



Water Storage Tank Inspection Report Terms of Reference: ACI 201.1R-08, Guide for Conducting a Visual Inspection of Concrete in Service Client/Operator: Cascadia Water Client Representative: Inspection Date: 02/23/2022 Culley Lehman Tank ID Number: "Big Tank" Tank Location: Ridge View Drive, Sequim, WA **ROV Pilot: Troy Gessner** ROV System Type & Number: VR Pro 4 #J10030 **ROV Accessory Equipment: Manipulator** Tank Construction: Weld **Bolted Steel** Composite Concre ed te X Steel Tank Type: Partially buried Tank Dimensions: N/A Tank Capacity: N/A concrete bunker General Description: Cast in place concrete box reservoir located in a residential neighborhood Safe Roof Access? Yes, roof elevation 3'-4' Safe Vehicle Access? Yes, safe access to large parking area adjacent to reservoir Access Hatch Type and Size: Describe Visible External Anomalies: Visual evidence of water leakage on reservoir external walls General Safety Observations: **General Condition Comments: Concrete Tanks** Internal Ladder None **Internal Surface Condition** Cracking: Significant diagonal cracking with ¼" observed gaps noted on internal support wall. Significant diagonal cracking with ¼" observed gaps noted at internal corners of concrete box structure. Moderate D-cracks noted on internal surfaces of external support walls with plant roots observed growing through the cracks. Additional Distress Indicators: None noted Textural Features: None noted **Rust Staining:** None noted Erosion: None noted Other Observations: General Condition: Joint Sealant/Filler: **Observed Anomalies:** See Attached Map of Anomaly Locations From ACI 201.1R-08, sec. 2.1.2.4, "Diagonal Crack"- in a flexural **Definitions:** member, an inclined crack, caused by shear stress, usually at approximately 45 degrees to the axis; or a crack in a slab, not

