

**Woodard, Marina (UTC)**

---

**From:** Faulkenberry, Mike [mike.faulkenberry@avistacorp.com]  
**Sent:** Friday, January 23, 2009 1:22 PM  
**To:** Woodard, Marina (UTC)  
**Subject:** Avista Utilities Reportable Incident, December 27, 2008  
**Attachments:** Document.pdf

<<Document.pdf>>

Marina:

Attached is a written report for an Avista Reportable Incident.

Mike Faulkenberry, P.E.  
Chief Gas Engineer, Avista Utilities  
Office Phone (509) 495-8499  
Cell Phone (509) 990-2386  
[mike.faulkenberry@avistacorp.com](mailto:mike.faulkenberry@avistacorp.com)



1411 E. Mission St.  
PO Box 3727  
Spokane, WA 99220-3727

RECEIVED *vrd*  
JAN 23 2009 *ema.1*  
WUTC  
Pipeline Safety Division

January 23, 2009

Ms. Anne Soiza  
Director of Pipeline Safety  
Washington Utilities and Transportation Commission  
P.O. Box 47250  
Olympia, WA. 98504-7250

Re: December 27<sup>th</sup>, 2008 Telephonic report, Avista Utilities

Dear Ms. Soiza,

This written response addresses the telephonic recorded message report Terry Barry of my staff made to the incident reporting hot line at 02:11 on December 27, 2008. This incident was assigned to Al Jones of your staff. Enclosed also is a copy of Form RSPA F 7100.1, Incident Report – Gas Distribution System, as submitted to the U.S. Department of Transportation. Additional information requested by Al Jones and David Lykken regarding this incident will be submitted at a later date under separate cover.

At approximately 22:15 on December 26, 2008, Avista Dispatch received a report of a structure fire and explosion at 206 N. Birch St. in Odessa, WA, Lincoln County. Avista personnel were dispatched at 22:17 and arrived at approximately 23:45. The leak was investigated, located, and secured by squeezing at 07:00 on December 27, 2008.

On December 26, 2008, a natural gas explosion occurred in a detached garage structure. Two individuals were injured directly by this incident, Roger Reyes, with severe burns requiring hospitalization and Cassandra McClure, requiring out-patient care. A third individual, Donald Hart, may have indirect personal injuries related to being evacuated from a neighboring residence. In addition, there is property damage to the garage and several vehicles, and possibly a dog. It appears that escaping natural gas migrated beneath frozen soil to the area of a garage



where it was ignited from an ignition source, suspected to be a cigarette. The building involved was not served with natural gas.

Avista personnel performed odorometer readings and a leak investigation and determined that gas was present in the surrounding soil. The two-inch diameter Aldyl PE gas main in the alley was found to have a crack as the result of suspected rock impingement. The damaged section of main was cut out and the remaining pipe was capped and abandoned in place. The system was operating at 40 psig at the time and has a 60 psig MAOP.

Several other structures and vehicles in the immediate area sustained damages. As outstanding claims against Avista exist, estimated costs are unavailable at this time, but are in excess of \$50,000.

Respectfully yours

A handwritten signature in black ink, appearing to read "Micheal J. Faulkenberry". The signature is fluid and cursive, with a large loop at the end.

Micheal J. Faulkenberry  
Chief Gas Engineer

Cc: Engineering Correspondence File  
Randy Chandler

Enclosure

U.S. Department of Transportation  
Research and Special Programs  
Administration

**INCIDENT REPORT - GAS DISTRIBUTION SYSTEM**

Report Date Jun 20, 2009  
No. 2009R2617-3728  
(DOT Use Only)

**INSTRUCTIONS**

**Important:** Please read the separate instructions for completing this form before you begin. They clarify the information requested and provide specific examples. If you do not have a copy of the instructions, you can obtain one from the Office of Pipeline Safety Web Page at .

**PART A - GENERAL REPORT INFORMATION**

Check  Original Report  Supplemental Report  Final Report

**1. Operator Name and Address**

- a. Operator's 5-digit Identification Number 31232
- b. If Operator does not own the pipeline, enter Owner's 5-digit Identification Number \_\_\_\_\_
- c. Name of Operator AVISTA CORP
- d. Operator street address E. 1411 MISSION AVE
- e. Operator address SPOKANE SPOKANE WA 99220  
City, County or Parish, State and Zip Code

**2. Time and date of the incident**

2215 hr 12/26/2008 month day year

**3. Incident Location**

- a. 206 N. BIRCH ST  
Street or nearest street or road
- b. ODESSA LINCOLN  
City and County or Parish
- c. WA 99159  
State and Zip Code
- d. Latitude: 47.33 Longitude: -118  
(if not available, see instructions for how to provide specific location)
- e. Class location description  
 Class 1  Class 2  Class 3  Class 4
- f. Incident on Federal Land  Yes  No

**4. Type of leak or rupture**

- Leak  Pinhole  Connection Failure (complete sec. F5)
  - Puncture, diameter or cross section (inches) \_\_\_\_\_
- Rupture (if applicable):
  - Circumferential - Separation
  - Longitudinal
    - Tear/ Crack, length (inches) \_\_\_\_\_
    - Propagation Length, total, both sides (feet) \_\_\_\_\_
- N/A
- Other: ROCK IMPINGEMENT CRACK

**5. Consequences (check and complete all that apply)**

- a.  Fatality Total number of people: 0  
Employees: 0 General Public: 0  
Non-employee Contractors: 0
- b.  Injury requiring inpatient hospitalization  
Total number of people: 1  
Employees: 0 General Public: 1  
Non-employee Contractors: 0
- c.  Property damage/ loss (estimated) Total \$ 55200  
Gas loss \$ 200 Operator damage \$ 5000  
Public private property damage \$ 50000
- d.  Gas ignited  Explosion  No Explosion
- e.  Gas did not ignite  Explosion  No Explosion
- f.  Evacuation (general public only) 5 people  
Evacuation Reason:  
 Unknown  
 Emergency worker or public official ordered, precautionary  
 Threat to the public  
 Company policy
- 6. Elapsed time until area was made safe:  
8 hr. 45 min.
- 7. Telephone Report  
893436 12/27/2008  
NRC Report Number month day year
- 8. a. Estimated pressure at point and time of incident:  
40 PSIG
- b. Max. allowable operating pressure (MAOP): 60 PSIG
- c. MAOP established by:  
 Test Pressure 90 psig  
 49 CFR § 192. 619 (a)(3)

**PART B - PREPARER AND AUTHORIZED SIGNATURE**

MIKE FAULKENBERRY 5094958499  
(type or print) Preparer's Name and Title Area Code and Telephone Number

MIKE.FAULKENBERRY@AVISTACORP.COM \_\_\_\_\_  
Preparer's E-mail Address Area Code and Facsimile Number

\_\_\_\_\_  
Authorized Signature (type or print) Name and Title Date Area Code and Telephone Number

**PART C - ORIGIN OF THE INCIDENT**

1. Incident occurred on  
 Main     Meter Set  
 Service Line     Other: \_\_\_\_\_  
 Pressure Limiting and Regulating Facility

2. Failure occurred on  
 Body of pipe     Pipe Seam  
 Joint     Component  
 Other: \_\_\_\_\_

3. Material involved (pipe, fitting, or other component)  
 Steel  
 Cast Wrought Iron  
 Polyethylene Plastic (complete all items that apply in a-c)  
 Other Plastic (complete all items that apply in a-c)  
Plastic failure was:  a. ductile     b. brittle     c. joint failure  
 Other material: \_\_\_\_\_

4. Year the pipe or component which failed was installed: 1981

**PART D - MATERIAL SPECIFICATION (if applicable)**

1. Nominal pipe size (NPS) \_\_\_\_\_ 2 \_\_\_\_\_ in.  
2. Wall thickness \_\_\_\_\_ .22 \_\_\_\_\_ in.  
3. Specification \_\_\_\_\_ PE 2406 \_\_\_\_\_ SMYS  
4. Seam type \_\_\_\_\_  
5. Valve type \_\_\_\_\_  
6. Pipe or valve manufactured by \_\_\_\_\_ UPONOR \_\_\_\_\_ in year 1981

**PART E - ENVIRONMENT**

1. Area of incident  
 In open ditch  
 Under pavement  
 Under ground  
 Inside under building  
 Other: \_\_\_\_\_

2. Depth of cover: 35 \_\_\_\_\_ inches

**PART F - APPARENT CAUSE**    *Important: There are 25 numbered causes in this section. Check the box to the left of the primary cause of the incident. Check one circle in each of the supplemental items to the right of or below the cause you indicate. See the instructions for this form for guidance.*

**F1 - CORROSION**

*If either F1 (1) External Corrosion, or F1 (2) Internal Corrosion is checked, complete all subparts a - e.*

1.  External Corrosion

a. Pipe Coating  
 Bare  
 Coated  
 Unknown

b. Visual Examination  
 Localized Pitting  
 General Corrosion  
 Other: \_\_\_\_\_

c. Cause of Corrosion  
 Galvanic     Stray Current  
 Improper Cathodic Protection  
 Microbiological  
 Other: \_\_\_\_\_

2.  Internal Corrosion

d. Was corroded part of pipeline considered to be under cathodic protection prior to discovering incident?  
 No     Yes     Unknown    Year Protection Started: \_\_\_\_\_

e. Was pipe previously damaged in the area of corrosion?  
 No     Yes     Unknown    How long prior to incident: \_\_\_\_\_ years \_\_\_\_\_ months

**F2 - NATURAL FORCES**

3.  Earth Movement    ⇒     Earthquake     Subsidence     Landslide     Other: \_\_\_\_\_  
4.  Lightning  
5.  Heavy Rains Floods    ⇒     Washouts     Flotation     Mudslide     Scouring     Other: \_\_\_\_\_  
6.  Temperature    ⇒     Thermal stress     Frost heave     Frozen components     Other: \_\_\_\_\_  
7.  High Winds

**F3 - EXCAVATION**

8.  Operator Excavation Damage (including their contractors)/ Not Third Party.

9.  Third Party Excavation Damage (complete a-d)

a. Excavator group  
 General Public     Government     Excavator other than Operator subcontractor

b. Type:  Road Work     Pipeline     Water     Electric     Sewer     Phone/ Cable/Fiber     Landowner     Railroad  
 Building Construction     Other: \_\_\_\_\_

c. Did operator get prior notification of excavation activity?  
 No     Yes:    Date received: \_\_\_\_\_

d. Was pipeline marked?  
 No     Yes (If Yes, check applicable items i - iv)  
i. Temporary markings:     Flags     Slakes     Paint  
ii. Permanent markings:     Yes     No  
iii. Marks were (check one)     Accurate     Not Accurate  
iv. Were marks made within required time?     Yes     No

**F4 - OTHER OUTSIDE FORCE DAMAGE**

10.  Fire/Explosion as primary cause of failure    ⇒    Fire Explosion cause:  Man made     Natural    Describe in Part G  
11.  Car, truck or other vehicle not relating to excavation activity damaging pipe  
12.  Rupture of Previously Damaged Pipe  
13.  Vandalism

**F5 - MATERIAL OR WELDS**

**Material**

14.  Body of Pipe     Dent     Gouge     Wrinkle Bend     Arc Burn     Other: ROCK IMPINGEMENT CRACK
15.  Component     Valve     Fitting     Vessel     Extruded Outlet     Other: \_\_\_\_\_
16.  Joint     Gasket     O-Ring     Threads     Fusion     Other: \_\_\_\_\_
- Weld**
17.  Sulf     Pipe     Fabrication     Other: \_\_\_\_\_
18.  Fillet     Branch     Hot Tap     Fitting     Repair Sleeve     Other: \_\_\_\_\_
19.  Pipe Seam     LF ERW     DSAW     Seamless     Flash Weld     Other: \_\_\_\_\_  
 HF ERW     SAW     Spiral

Complete a-f if you indicate any cause in part F5.



- a. Type of failure:  
 Construction Defect =  Poor Workmanship     Procedure not followed     Poor Construction Procedures  
 Material Defect
- b. Was failure due to pipe damage sustained in transportation to the construction or fabrication site?     Yes     No
- c. Was part which leaked pressure tested before incident occurred?     Yes, complete d-f, if known     No
- d. Date of test: 8/11/1981
- e. Time held at test pressure: \_\_\_\_\_ hr.
- f. Estimated test pressure at point of incident: \_\_\_\_\_ 90 \_\_\_\_\_ PSIG

**F6 - EQUIPMENT OR OPERATIONS**

20.  Malfunction of Control /Relief Equipment     Valve     Instrumentation     Pressure Regulator     Other: \_\_\_\_\_
21.  Threads Stripped, Broken Pipe Coupling     Nipples     Valve Threads     Mechanical Couplings     Other: \_\_\_\_\_
22.  Leaking Seals
23.  Incorrect Operation
- a. Type:     Inadequate Procedures     Inadequate Safety Practices     Failure to Follow Procedures     Other: \_\_\_\_\_
- b. Number of employees involved in incident who failed post-incident drug test: \_\_\_\_\_ Alcohol test: \_\_\_\_\_
- c. Was person involved in incident qualified per OQ rule?     Yes     No    d. Hours on duty for person involved: \_\_\_\_\_

**F7 - OTHER**

24.  Miscellaneous, describe: \_\_\_\_\_
25.  Unknown  
 Investigation Complete     Still Under Investigation (submit a supplemental report when investigation is complete)

**PART G - NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTING TO THE EVENT** (Attach additional sheets as necessary)

ROCK IMPINGEMENT APPEARS TO HAVE CAUSED CRACK IN P.E. PIPE WALL. SNOW AND FROST IN GROUND CAUSED GAS TO MIGRATE TO NEARBY STRUCTURE. GAS ACCUMULATED IN UNDERGROUND AREA OF STRUCTURE AFTER PASSING THROUGH CRACK IN WALL. ONE RESIDENT STATED THAT HE ENTERED GARAGE STRUCTURE AND LIT A CIGARETTE WHICH IS ASSUMED TO BE THE IGNITION SOURCE.