

Field Data Collection
(2011 Standard Inspection)

Company: Kinder Morgan Canada Inc.
Trans Mountain Pipeline (Puget Sound) LLC

Unit: Trans Mountain Pipeline (Puget Sound) LLC

Pipe-to-Soil Potential Readings, Rectifiers, and Mainline Valves (MLV)

Date	Location	Pipe (Volts) Power On	Pipe (Volts) Power Off	Casing (Volts)	Comments
8/24/2011	<u>Mainline Valve (MLV) MU-14 north of Nooksak River on Sumas to Laurel segment</u> Rectifier R-68 MU-14 valve stem	-1.640	-1.223		The MLV was inspected & partially operated by Rick Axelson and was fine. Rectifier DC output: 16.14 V; 4.8A Potential readings were acceptable.
8/24/2011	<u>Mainline Valve (MLV) MU-15 south of Nooksak River on Sumas to Laurel segment</u>				This block valve station has a check valve and both valves were inspected and were fine.
8/24/2011	<u>North Pass Road CP test station MU 12.660</u>	-2.193		-0.594	The casing was not shorted.
8/24/2011	<u>MLV ML-6 on the Laurel to Ferndale segment next to I-5 Freeway.</u>				The MLV was inspected and was partially operated by Rick Axelson and was fine.
8/24/2011	<u>CP test site 1L-5.647</u> Next to I-5 Freeway	-1.434	N/A	-1.179	The casing vent was damaged by highway mowing crew and the space between the casing and carrier pipe was most likely partially filled with water. The operator intends to purge the water by injecting gel or wax.

8/24/2011	MLV ML-8 of the Laurel to Ferndale segment				This MLV and a check valve were inspected. The MLV was not partially operated as it would require a confined space entry permit.
8/24/2011	Northwest Drive, Bellingham CP test station UL 4.664	-1.974		-0.572	The casing was not shorted.
8/24/2011	<u>Ferndale Station</u> Tank rectifier R-87 Pipeline rectifier R-60 CP test site 1L-11.250 <u>Tank T-130</u> North side of chime South side of chime Buried half-cell at the center of the tank bottom plate				Rectifier DC output: 33.84 V; 0.13 A Rectifier DC output: 20.46 V; 4.98 A Potential reading was acceptable. Potential reading was acceptable. Potential reading was acceptable. Potential reading was acceptable.
8/24/2011	<u>Laurel Station</u> <u>Rectifier R-34 for pipeline</u> <u>Rectifier R-16 for tanks</u> <u>CP test station MU-20.595</u>				Rectifier DC output: 40.3 V; 4.8 A Rectifier DC output: 8.01 V; 4.89 A Potential readings were acceptable.
8/24/2011	<u>Breakout Tank T-170 at Laurel Station</u> Bottom plate chime South side North side				
		-3.200 -4.310	-2.876 -4.260	N/A N/A	Potential readings were acceptable.
8/24/2011	<u>Breakout Tank T-180</u>				

	at Laurel Station Bottom plate chime South side	-2.117	-0.970	N/A	Potential readings were acceptable.
8/25/2011	<u>Anacortes Meter Station</u> 16" line downstream of Shell Refinery custody valve 12" surge relief line to T-7 in Shell Refinery, test station UB-8.982 Rectifier R-76 Breakout tank T-7 inside Shell Refinery	-2.135	-0.900		The casing on reading was -1.369 V, and off reading was -0.914 V. A new anode was installed near the casing and somehow the casing was polarized. This casing will be removed next month when the city installs a new water line under the street.
		-1.290	-1.050	N/A	Potential readings were acceptable. Rectifier DC output: 23.15 V; 6.8 A T-7 was inspected and there was one probable violation concerning disbonded coating and potential atmospheric corrosion at the soil/air interface of the 12" surge relief line to the tank.
8/25/2011	<u>Burlington Scraper Trap Station Rectifier R-40</u> CP test station MU-47.883	-1.505	-0.950	N/A	Rectifier DC output: 8.96 V; 3.45 A Potential readings were acceptable.
8/25/2011	<u>MLV at MU-43</u>	-0.483	-0.406	N/A	The native potential was -0.340 volts. It did not meet the 100 mv shift criterion

					during this field inspection. The soil resistivity was high due to very dry soil. The pipe or valve was most likely shorted with electrical conduits or other components for the MOV. Post inspection notes: On September 8, 2011 the operator's technicians identified a 1/2" temperature probe as the source of the short. An insulating union has been ordered and will be installed within a week.
8/25/2011	<u>Quarry at Nulle Road CP test station MU-35.448</u>	-1.116	-0.290		The native potential was +0.11 established in 9/2009. The instant off reading met 100 mv shift criterion.
8/25/2011	<u>Nulle Road Rectifier R-59</u> <u>CP test station 34.777 At Nulle Road crossing</u>	-2.049	-1.135	-0.566	Rectifier DC output: 72.2 V; 5.1 A Potential readings were acceptable. Casing was not shorted.
8/25/2011	<u>Manley Road CP test sites</u> 1A-34.233 1A-34.196 1A-34.059 1A-33.916 1A-33.882	-1.594 -1.392 -1.579 -1.236 -1.127	-0.675 -0.469 -0.843 -0.380 -0.204	-0.407 N/A N/A N/A N/A	Most of the instant off potentials did not meet the -850 mv criterion. However, they did meet the 100 mv shift criterion.

	1A-33.813	-1.570	-0.650	N/A	
	1A-33.764	-1.132	-0.300	N/A	
	1A-33.397	-1.863	-1.145	N/A	
8/25/2011	<u>MLV at MU-27</u>				This MLV is located in a residential area in Bellingham and is about 10 feet deep. The valve was inspected.
8/25/2011	<u>Whatcom Creek check valve at MU-26</u>				This check valve is located near City of Bellingham's water treatment plant and was inspected.