Company-confidential per Protective Order in Docket UE-190882 Exhibit No. CLT-1CCTr Docket UE-190882/UE-190458 Witness: Charles L. Tack

BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION

In the Matter of the Investigation of	
AVISTA CORPORATION d/b/a AVISTA UTILITIES, PUGET SOUND ENERGY, and PACIFIC POWER & LIGHT COMPANY,	Docket UE-190882
Regarding the Prudency of Outage and Replacement Power Costs	
In the Matter of	
PACIFIC POWER & LIGHT COMPANY,	Docket UE-190458
2018 Power Cost Adjustment Mechanism	

PACIFIC POWER & LIGHT COMPANY

REDACTED – COMPANY-CONFIDENTIAL DIRECT TESTIMONY OF CHARLES L. TACK

TABLE OF CONTENTS

1	QUALIFICATIONS
2	PURPOSE OF TESTIMONY1
3	PACIFIC POWER'S INVOLVEMENT IN THE COLSTRIP PLANT2
4	THE RISE IN PARTICULATE MATTER LEVELS IN EARLY 20184
5	THE COLSTRIP OUTAGE
6	ROOT CAUSE ANALYSIS FOR THE COLSTRIP OUTAGE
7	MONTANA DEPARTMENT OF ENVIRONMENTAL QUALITY CONSENT DECREE 15
8	CONCLUSION
	ATTACHED EXHIBITS
	Exhibit No. CLT-2CCr—Selected Excerpts from the Colstrip Operating and Ownership Agreement (Company Confidential)
	Exhibit No. CLT-3Cr—Shared Units Weekly Status Report (Confidential)
	Exhibit No. CLT-4r—2017 MATS PM Data Results Slide
	Exhibit No. CLT-5CCr—Internal Email from Talen (Company Confidential)
	Exhibit No. CLT-6CCr—Description of Talen's activities to track MATS PM level after February 2018 (Company Confidential)
	Exhibit No. CLT-7CCr—Spreadsheet used by Talen to track alternate indicators (Company Confidential)
	Exhibit No. CLT-8r—E-mail notification to MDEQ
	Exhibit No. CLT-9CCr—Timeline of the Colstrip Outage (Company Confidential)
	Exhibit No. CLT-10CCr—Root Cause Analysis (Company Confidential)

Exhibit No. CLT-13—MDEQ Press Release

Exhibit No. CLT-11—MDEQ Consent Decree Stipulation

Exhibit No. CLT-12—MDEQ Penalty Assessment

1	Q.	Please state your name, business address, and present position with PacifiCorp.
2	A.	My name is Charles (Chuck) L. Tack and my business address is 1407 North Temple,
3		Salt Lake City, Utah 84116. I am currently employed as Managing Director of
4		Generation Support at PacifiCorp. I am testifying for PacifiCorp d/b/a Pacific Power
5		& Light Company (Pacific Power).
6		QUALIFICATIONS
7	Q.	Please describe your education and professional experience.
8	A.	I hold a Bachelor's degree in Civil Engineering from the University of Nebraska, a
9		Masters in Energy Business from the University of Tulsa, and am currently working
10		towards a Masters in Finance from the University of Utah. Before joining Pacific
11		Power, I held a Senior Reactor Operators License at Fort Calhoun Nuclear Station
12		and a Senior Reactor Operators Certification at Cooper Nuclear Station. I joined
13		Pacific Power in 2017 and worked in various engineering and operational (including
14		Shared Unit Director) positions before becoming Managing Director of Generation
15		Support in 2019.
16		PURPOSE OF TESTIMONY
17	Q.	What is the purpose of your testimony?
18	A.	Through this testimony, I will provide an explanation of the events leading up to the
19		Environmental Protection Agency (EPA) Mercury and Air Toxic Standards (MATS)
20		Particulate Matter (PM) outage at the Colstrip generating station, Pacific Power's
21		understanding of the actions that were taken prior to the outage, and the actions that
22		were taken after the outage occurred.

1		PACIFIC POWER'S INVOLVEMENT IN THE COLSTRIP PLANT
2	Q.	Please provide some background on the Colstrip plant.
3	A.	The Colstrip plant is a four unit coal-fired power plant located in Montana. The plant
4		is jointly-owned by various parties, of which Pacific Power is a 10 percent owner in
5		Unit 3 and Unit 4. It is my understanding that only the company's ownership of Unit
6		4 is included in the company's Washington rates. The operator, Talen Montana
7		(Talen), plans and carries out the daily operation of the facility.
8	Q.	Please explain how Pacific Power participates in the on-going operations of
9		Colstrip?
10	A.	Pacific Power has a representative on the Ownership and Operating (O&O)
11		Committee, through which the owners who are not involved in the day to day
12		operation of Colstrip are kept informed on matters related to the operation and
13		maintenance of the plant. Additionally, Pacific Power maintains on-going contact
14		with Talen on an as-needed basis to address any issues that may arise. As the plant
15		operator, Talen has authority to act as an agent for the owners and "
16		
17		»1
18	Q.	In 2018, what was your role in the on-going operations of Colstrip?
19	A.	Throughout 2018, I was Pacific Power's representative on the O&O Committee. ²
20		Through that role, I attended meetings (in person or via telephone) of the O&O

¹ Exhibit CLT-2CCr at Section 3(d). This Exhibit contains selected sections from the Colstrip Ownership and Operation Agreement. I am not an attorney, however, I have quoted and provided certain sections of this agreement to support my understanding of how operations work in practice.

agreement to support my understanding of how operations work in practice.

The O&O Committee is referred to as the "Project Committee" in the Colstrip Ownership and Operation Agreement, *See* Exhibit CLT-2CCr at Section at 17.

- 1 Committee and participated in the discussions on the Colstrip MATS PM outage as
- 2 Pacific Power's representative.
- 3 Q. How often did the O&O Committee meet in 2018?
- 4 A. The O&O Committee is required to meet on a quarterly basis, however, meetings
- 5 occur monthly.
- 6 Q. What was generally discussed at the O&O Committee meetings?
- 7 A. Generally, all the O&O Committee meetings followed the same format. Talen would
- 8 provide updates on the following areas: safety, fuels, environmental, generation/plant
- 9 performance, and financial. After the updates, we would move into executive session
- for further discussion on more sensitive matters. For example, this could include
- discussion of topics between owners, direction the owners would like to see the plant
- go, contract challenges with vendors, staffing changes, etc. During the regular part of
- the O&O Committee meeting, many representatives from different Talen departments
- (safety, operations, fuels, etc.) attend. In the executive session, these individuals
- leave the meeting.
- 16 Q. How do you assess the information that Talen provides you in these meetings on
- 17 plant operations?
- 18 A. I have spent a significant portion of my career in operations, first in nuclear power
- plants, then in support of PacifiCorp's thermal generation fleet (coal, natural gas, and
- 20 geothermal). As Talen discusses plant operations, I assess the information and
- 21 direction provided based on my experience. This information, which usually includes
- 22 many follow up questions, provides good context for me to filter and understand the
- issues. Additionally (when I feel an issue warrants more attention or do not think the

1		direction is appropriate), I reach out to our internal experts for back-up to ensure
2		alignment with Pacific Power's practices. It is my job as Pacific Power's
3		representative to critically assess and challenge the information provided by Talen.
4	Q.	How do you communicate and discuss decisions on operational issues with Pacific
5		Power's management?
6	A.	I am in regular contact with my boss, Dana Ralston, who is the Senior Vice Presiden
7		of Thermal Generation, Coal Generation, and Mining. Decisions and updates I feel are
8		applicable were documented in the Shared Units Weekly Status Report. ³
9		THE RISE IN PARTICULATE MATTER LEVELS IN EARLY 2018
10	Q.	Please explain how Talen tests for compliance with the PM levels in order to
11		comply with the Mercury Air Toxics Standards (MATS)?
12	A.	To obtain a source's PM emission rate, a probe is inserted into the exhaust stack and a
13		pump draws flue gas through a filter media. The stack testers follow a prescribed EPA
14		test method which allows them to determine stack PM emissions on a pound-per-hour
15		or pound-per-million British Thermal Unit (BTU) basis. Compliance with the MATS
16		PM limit for Colstrip is demonstrated by the daily weighted site-wide rolling 30-day
17		average PM emission rate of all four Colstrip Units as directed by the EPA.
18	Q.	When did Talen first inform you that the rising PM levels had triggered
19		increased monitoring?
20	A.	During an O&O Committee meeting on February 21, 2018, Talen informed
21		committee members that although the plant was still in compliance, there were
22		elevated MATS PM levels in the official compliance tests that had occurred on

Direct Testimony of Charles L. Tack

³ A redacted version of this report, containing only information pertaining to Colstrip is attached as Exhibit CLT-3Cr.

February 7, 2018 and February 9, 2018 for Units 3 and 4. Talen then discussed that
they were looking into the potential source of the elevated PM levels. As elevated
levels were not expected, Talen's approach was to investigate what could be causing
the elevated PM levels while monitoring alternate indicators. These alternate
indicators are not official compliance measurements but help provide additional
evidence of whether the PM was still within acceptable limits. Along with this, Talen
discussed that PM levels are impacted by many variables, so the results are not linear
and often increase or decrease quarterly. ⁴

Q. Did you have any additional conversations with Talen regarding the elevated PM levels?

Yes, after being informed of the elevated PM levels, I had multiple additional conversations with Talen's representatives regarding my concerns around the elevated PM levels. I asked for more specificity regarding the actions that were being taken to find the cause of the elevated PM levels and what alternate indicators they used to help ensure compliance was maintained in the interim between official compliance tests. Additionally, attached as Exhibit CLT-5CCr is an internal email from Talen, that was provided to Pacific Power after the outage was resolved.⁵ This email documents the actions that were taken in February in response to the elevated PM levels.

Direct Testimony of Charles L. Tack

A.

⁴ The significant variability in PM levels through 2017 is shown in Exhibit CLT-4r, which was a slide developed for a workshop with UTC Staff.

⁵ This was provided to Pacific Power after additional discussions with Talen in November of 2019.

1	Q.	What actions were being taken by Talen to find the cause of the elevated PM
2		levels?
3	A.	Through the additional conversations, Talen informed me that they were monitoring
4		and evaluating the following alternative indicators for PM levels:
5 6 7 8 9 10 11 12		 Opacity PM CEMS (Particulate Matter Continuous Emissions Monitoring System) Scrubber Performance Boiler Performance While the alternate indicators are not official compliance tests that are submitted to
13		the Montana Department of Environmental Quality (MDEQ), they provide other
14		important ways to measure PM levels that can be correlated to the official compliance
15		test. These indicators provide real time (not official compliance) data for plant
16		operations that help indicate whether PM levels are within the permitted limits. I
17		have attached a narrative description of each of these items as well as results for the
18		time period in question. Attached to this testimony is a document that shows Talen's
19		tracking of these metrics after the February compliance test. ⁶
20	Q.	Based on your experience in plant operations, how do you respond when a single
21		indicator is elevated, like the PM levels in early 2018?
22	A.	It is my experience that when a single indicator like the measurement of MATS PM
23		levels in a compliance test is elevated, you start examining and troubleshooting other
24		indicators to correlate with and validate those results. On-going monitoring,
25		operation evaluations, and extra attention are generally accepted operating practice in

⁶ Exhibit CLT-6CCr. This Exhibit was originally developed after the outage in response to questions from UTC Staff and provided to them after a workshop between PacifiCorp and the UTC Staff on September 20, 2019.

helping identify if the issue is real or a false positive. There are multiple components
and parameters throughout a power plant that, over the course of the year, may have
random negative anomalies or outlier results. Operators monitor multiple data points
(alternate indicators) to determine trends and gather as much information as available
(not just single points) to understand if a specific reading represents a real or random
issue. Many times an issue (real or false) can only be identified when the unit is
operating.

If the Operator immediately shuts down every time there is a concern of an elevated parameter, the unit would cycle significantly more, placing large amounts of stress on staff and existing equipment as well as negatively impacting any troubleshooting efforts. Information gained through troubleshooting is vital to operations, planned decisions can be made about taking a unit offline, maintenance needed, risk, valid / invalid results, and/or continuing to build a trend based on existing operations.

Q. Was there any follow-up on this issue in the O&O Committee meeting that occurred on March 21, 2019?

Yes. At the meeting, Talen discussed that they had not identified any items causing the elevated PM levels and that the alternate indicators they were monitoring and evaluating indicated PM levels should be within compliance limits. Talen was not concerned about an exceedance and discussed that they would continue to look for what caused the elevated PM in the February tests as well as continue monitoring alternate indicators of current PM levels. Exhibit CLT-7CCr is a spreadsheet that was used by Talen to track plant parameters (unofficial MATS PM results) while

A.

1		evaluating the impacts from troubleshooting efforts during this time period. This
2		spreadsheet was provided to PacifiCorp after the outage occurred in response to UTC
3		staff questions.
4	Q.	In early June, Talen gave notice to the MDEQ that the PM compliance testing
5		would be delayed for that month. Was this test delayed because of concerns
6		related to the elevated PM levels?
7	A.	No. As discussed in Exhibit CLT-8r, the test was moved due to market and load
8		conditions. Official MATS PM compliance testing requires that the plant be running
9		within 90-110 percent of rated capacity and representative of normal operating
10		conditions.
11		The
12		MDEQ requires at least a three-day notice to change a testing date.
13	Q.	What does it mean when a test is delayed because of market conditions?
14	A.	The unit has to be running within 90-110 percent of rated capacity and representative
15		of normal operating conditions. Due to the projected market conditions (economics
16		of energy prices), the tests were moved to later in the month. There are many
17		variables that impact market conditions, especially weather. Generally, temperatures
18		are higher in late June than early June which would likely mean that increased energy
19		demand in late June would cause the Colstrip units to run at the higher power levels
20		aligning with requirements for the compliance tests on those dates.
21	Q.	Was the delay of this test unusual, and would you expect Talen to consult the
22		other owners on a decision to delay this test?
23	A.	No. It is not unusual to adjust testing dates due to market conditions, equipment

1	issues, individual unit outages, or other variables. I would generally not expect the
2	operator to consult the other owners on a decision to delay this test.
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	



1		
2		
3		
4		
5		
6		
7		
8	Q.	Through the discovery process, some parties have raised questions about the
9		functionality of the coal conveyor or the coal sampler. Did the functionality of
10		these pieces of equipment have any effect on the outage?
11	A.	No. From my understanding of the causes of the outage and the rise in PM levels,
12		any issues with the coal sampler and the coal conveyor had minimal to no effect on
13		the cause of the outage. As I stated above, the coal that was delivered met the
14		contractual specifications.
15		THE COLSTRIP OUTAGE
16	Q.	When did Talen inform Pacific Power that there would be an outage at Colstrip?
17	A.	On June 27, 2018, Talen contacted all co-owners for an emergency meeting. At this
18		meeting, the owners were informed that Unit 3 and Unit 4 had failed the official
19		second quarter MATS PM compliance tests and the units would be coming offline
20		expeditiously to address the issue.

- 1 Q. Market prices were lower from February through May, should Talen have taken
- 2 steps for a planned outage in the early part of the year, and would that have
- 3 prevented a forced outage later in the year?
- official MATS PM compliance was met but with elevated levels. At that time the elevated PM level was a single data point and unexpected. Talen was confident they

As discussed above, in the first quarter of 2018, we were informed by Talen that

- would maintain compliance based on the alternate indicators they were monitoring as
- 8 well as plant parameters they were evaluating. From my discussions with Talen, they
- 9 did not believe they would fail the second quarter official PM test. If Talen would
- have provided any hint that they believed the units would fail official testing, Pacific
- Power would have told them our standard position is to immediately shut down the
- units and address the concern. Pacific Power's priority is to ensure that Colstrip
- meets safety, environmental and compliance requirements.
 - Q. What steps were taken after Units 3 and 4 were taken offline?
- 15 A. Talen continued testing, cleaning, analysis, and evaluations of individual variables to
- determine if they could find the source of the elevated PM levels. Along with this,
- Talen continued to use in-house experts and got outside experts involved to help
- investigate the cause of the elevated PM levels. Each week there was a plan to
- investigate new variables. Unit 3 was the lead with Unit 4 following—they would
- address items on the Unit, then bring the Unit up to power and perform an unofficial
- 21 MATS PM test to determine if they were passing or if the items addressed had any
- impact.

4

14

Α.

Q. Did Talen reach out to industry experts for assistance?

1

- 2 A. Yes. Talen reached out to Architect Engineering Consulting Operations
- Maintenance (AECOM) and Air Control Techniques (ACT) to consult and help
- 4 address the PM levels. AECOM are experts in coal fired pollution control
- 5 equipment. ACT are specialists in stack gas testing & analysis.
- 6 Q. Did Talen keep the owners informed of their actions?
- 7 A. Yes. Talen continued to keep the owners informed of the actions they were taking
- 8 throughout the outage. A couple weeks into the outage, daily phone calls were had
- 9 with the owners to discuss findings and direction.
- 10 Q. Did Pacific Power provide any assistance to Talen as the outage progressed?
- 11 A. Yes. A few weeks into the outage as the issues continued to be a challenge, Pacific
- Power offered to send our experienced engineers to provide assistance to Talen.
- Talen accepted, and two of Pacific Power's engineers traveled to Talen to support.
- Along with this, when Pacific Power was notified of the official compliance test
- failure in late June, internally multiple environmental engineers and generation
- support engineers were brought into discuss what we felt was the best approach
- forward. From there we monitored Colstrip's approach and provided informal
- feedback on ideas that might help.
- 19 Q. How long did the outage last?
- 20 A. In September of 2018, Units 3 and 4 passed the official MATS PM compliance test
- and were brought back online. Exhibit CLT-9CCr provides a timeline detailing the
- events that led up to and during the outage.

1	Q.	In your opinion, were the actions taken by Talen before and after the outage
2		consistent with prudent utility practice?
3	A.	Yes. Consistent with prudent utility practice, Talen recognized that although the
4		facility was in compliance during the February testing, they still required increased
5		attention and evaluation of the PM emissions. Talen monitored numerous alternate
6		indicators and conducted trouble-shooting to evaluate whether the higher PM levels
7		represented a trend or were an anomaly. These alternate indicators and evaluations
8		indicated a likelihood that the limits for the second quarter compliance test would not
9		be exceeded. However, when the official compliance test results failed (and did not
10		align with the alternate indicators), Talen expeditiously shut-down the units and
11		brought in outside experts to help find and address the cause of the higher PM levels.
12		It took several months of the combined efforts of Talen's staff and outside experts,
13		including staff from PacifiCorp, to find and address the causes of the higher PM
14		levels, indicating the complexity of the problem.
15		ROOT CAUSE ANALYSIS FOR THE COLSTRIP OUTAGE
16	Q.	Did the owners hire an independent firm to conduct a root cause analysis (RCA)
17		to determine the cause of the outage?
18	A.	Yes. Sologic was contracted to conduct an RCA to determine the cause of the
19		elevated PM levels and determine appropriate corrective steps.
20	Q.	What did Sologic determine in their RCA?
21	A.	Through their analysis, Sologic determined that the elevated PM levels were due to a
22		combination of factors including:
23 24		

1 2		
3		Each of these elements is explained in detail in the RCA which is attached to this
4		testimony as Exhibit CLT-10CCr. The RCA goes on to conclude, "
5		
6		
7		> 210
8	Q.	Please summarize the preventive/corrective action items described in the RCA
9		and indicated whether they have been implemented?
10	A.	The following actions are Recommended Solutions which have been implemented or
11		are in progress:
12		
13		
14		
15		
16		
17		
18		
19		
20		•
21		

¹⁰ Exhibit CLT-10CCr at 4.
11 Exhibit CLT-10CCr at 5.
12 Exhibit CLT-10CCr at 5.
13 Exhibit CLT-10CCr at 5.

1		
2		
3		14
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		MONTANA DEPARTMENT OF ENVIRONMENTAL QUALITY CONSENT
16		DECREE
17	Q.	Was the MDEQ informed of the failure of the PM test in late June of 2018?
18	A.	Yes. The MDEQ was promptly informed after the failure of the PM test in June of
19		2018.
20	Q.	Did the MDEQ conduct an investigation of the violation of the MATS PM levels
21		at Colstrip?
22	A.	Yes. MDEQ conducted an investigation, and Talen has worked cooperatively with

¹⁴ Exhibit CLT-10CCr at 5.

1		MDEQ through the investigation which resulted in a penalty assessment and a
2		consent decree which was filed in Montana district court on November 25, 2019. The
3		consent decree and penalty assessment are attached as Exhibit CLT-11 and Exhibit
4		CLT-12.
5	Q.	What was the penalty assessed by MDEQ?
6	A.	Talen has agreed to a penalty of \$450,000 for air quality emissions and reporting
7		violations at the Colstrip generating station. ¹⁵ The penalty amount includes a
8		payment of \$112,500 to MDEQ as well as funding two supplemental environmental
9		projects to benefit local communities.
10	Q.	Did the Penalty Assessment include an evaluation of the events leading up to the
11		outage?
12	A.	Yes. The MDEQ determined that Talen took extensive measures to investigate
13		elevated PM levels after February 2018 testing and that those investigations indicated
14		the units were in compliance:
15 16 17 18 19 20 21 22 23 24 25		While the individual unit emission rates have experienced increases and decreases over the years, the weighted average PM emission rate had a slight upward trend, indicating a shrinking compliance margin over time. The PM test from the first quarter 2018 showed a decrease in PM emissions for Unit 1; however, Units 2, 3 and 4 all showed increases in PM emissions to their highest reported weighted average since MATS took effect in 2016. The results yielded a weighted average emission rate equal to the permit limit of 0.030 lb/MMBtu, 16 prompting Talen to investigate possible reasons for the elevated PM emissions. Talen reviewed indicators in the CAM plan, 17 reviewed operations and maintenance, scrubber plumb bob delta P, 18 opacity and PM CEMS 19 data and found no indicators of abnormal operations and no causes of higher PM
26		emissions. ²⁰

Exhibit CLT-13, MDEQ Press Release on Consent Decree.
 Pounds per million BTU.
 Continuous Assurance Monitoring Plan.

¹⁸ The scrubber delta p investigations looked at how adjusting a "bob" to control turbulence at an inlet impacted PM levels.

 ¹⁹ Continuous Emissions Monitoring System.
 ²⁰ Exhibit CLT-12, page 2.

1 The consent decree and penalty calculation do not make any finding that Talen failed

to take any operational measures that would have prevented the elevated PM levels.

Q. Can you provide an explanation of the reporting violations that were assessed by

4 MDEQ?

2

3

7

10

11

14

15

16

17

19

21

5 A. MDEQ assessed an administrative reporting violation against Talen for an inaccurate

6 compliance certification. Talen submitted a required semi-annual compliance

certification after the June compliance testing that inaccurately stated the units had

8 been in continual compliance. Talen had submitted a report that included

9 documentation and disclosure of the noncompliance, and had also reported it verbally

to MDEQ. However, the compliance certification was not accurate as submitted due

to an administrative error. After MDEQ notified Talen of the improper certification,

Talen submitted a corrected compliance certificate.²¹

13 Q. Did the MDEQ identify any corrective actions that should be taken?

A. Yes. However, no new or different operating requirements were identified. Instead,

MDEQ required some additional reporting and monitoring to confirm on-going

compliance. As part of MDEQ Enforcement Action requirements, MDEQ requires

Talen to conduct additional monthly monitoring to ensure PM levels remained below

the limits. MDEQ also required updates to Talen's testing protocols to ensure

accurate testing. MDEQ also required Talen to submit a report to confirm that

scrubbers on the units were operating as required by the permit.²²

Q. Has Talen implemented these corrective actions?

22 A. Yes. Talen is conducting the additional monthly testing. Talen acted proactively in

²¹ See Exhibit CLT-12.

²² Exhibit CLT-13.

December of 2018 (after discussions with MDEQ), and started monthly testing of
MATS PM levels. The other actions will be performed as required per the official
MDEQ Enforcement Action.

4 CONCLUSION

5 Q. Please summarize your testimony.

6 Beginning in February of 2018, Talen saw elevated MATS PM levels. As a result, A. 7 Talen began taking actions (generally accepted operation practices) to determine the 8 cause of the elevated MATS PM levels by tracking alternate indicators that would 9 correlate to the MATS PM levels. These alternate indicators supported the 10 conclusion that MATS PM levels would pass the next official test. However, the PM 11 levels did not pass the next official test. This caused Units 3 and 4 to enter into a 12 forced outage. Through the outage, Talen took numerous actions that individually 13 decreased the MATS PM results until official compliance was met. After consulting numerous engineers, consultants, including Pacific Power's experts, a single root 14 15 cause was not found. The RCA stated that there were four causes that likely in 16 combination caused the event. These four causes have driven numerous corrective 17 actions to ensure that this sort of outage does not occur again.

18 Q. Does this conclude your direct testimony?

19 A. Yes.