
### Cause of 7/12/17 Outage

- Occurred during maintenance event that was part of bigger project to upgrade West's emergency voice switches at
  Englewood and Miami from REDACTED switches to REDACTED Servers REDACTED
- Switch upgrade project was conducted over the course of a year from late 2016 to late 2017; traffic selectively migrated in segments according to detailed project plan
- As part of the migration of a portion of the WA traffic on 7/12/17, West exported the database with all of the trunk group information from our old switch to our new switch
- During the insertion phase of the database transfer, a machine error resulted in Ingress Trunk Group (ITG) flags not uploading correctly to the database for the new switch for a small portion of the migrating trunk groups
- The West Emergency Call Management Center (ECMC) (Selective Router) uses the ITG field to determine where and who a call originated from and what default PSAP is associated with the attendant trunk group. Without the ITG field, the ECMC rejects the call and returns a cause code 34 to the Originating Service Provider (OSP) indicating that the trunk is unavailable and the call should be rerouted



### Washington 9-1-1 Network Diagram

### West Safety Services Network Diagram





### Mitigating Factors

- Project aim was to provide "modern, adequate, sufficient and efficient" appliances/service by keeping switching "facilities . . . in good condition and repair" via switch upgrade
- All calls reached the ECMC/Selective Router during the outage
- Pre-validation steps showed no errors in database export and transfer (included audit of ITG tags)
- Call failure alarms worked as designed and identified lack of ITG tags
- Prompt response by West Internal fault management process triggered; NOC-to-NOC communication between West and CenturyLink; busied migrated trunks to force OSPs to alternate final route and manually reviewed and corrected the data extract
- Returned appropriate cause code 34 to OSPs for forward routing to redundant Miami switch
- Followed detailed project plan designed to limit potential for disruption by migrating voice traffic in small segments over short periods of time during the middle of the night
- Partial outage small number of WA trunks affected and Englewood switch not hard down
- Only known disruption during entire switch upgrade project over course of a year



### **Corrective Action**

- Updated Method Of Procedure (MOP) by adding manual, post-data load validation step
- Pre-notification of maintenance events to CenturyLink regardless of severity level or disruption potential
- Upgraded physical resources of provisioning server and restricted user access to reduce potential for unforeseen resource absorption



Description of Traffic Migration Project: REDACTED

Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS



Normal 9-1-1 Call Flow REDACTED

Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS



Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS

Normal 9-1-1 Call Flow REDACTED



REDACTED

Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS



REDACTED

Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS



Exh. RM-2C Docket No. UT-190209 Witness: RANDOM MILLS

### Data Entry Flow During Switch Upgrade Project

