SUPPLEMENTAL SCC QUESTIONNAIRE GAS TRANSMISSION OR LIQUID PIPELINE

- 1. Pipeline Safety Advisory Bulletin ADB-03-05 October 8, 2003
 - Review Bulletin with operator, if operator is not familiar with.
 - Reference also Baker Stress Corrosion Cracking Study at: http://primis.phmsa.dot.gov/gasimp/docs/SCC Report-Final Report with Database.pdf

Comments:

TransCanada is well aware of the SCC threat to pipelines. TransCanada has identified SCC as a threat of concern to the GTN pipelines.

- 2. Has the pipeline system ever experienced SCC (in service, out of service, leak, non-leak)?
 - Type of SCC?
 Clasical high pH
 Non-classical low or near neutral pH
 - What are the known risk indicators that may have contributed to the SCC?

Comments:

From discussion with GTN operational staff, there has not been any reported occurrence of SCC. The GTN A-Line is at risk as per ASME B311.8S (age of pipe > 10 years, operating stress > 60%, coating other than FBE, etc.

3. Does the operator have a written program in place to evaluate the pipeline system for the presence of SCC? If no, have operator explain. If operator has not considered SCC as a possible safety risk, go to #10.

Comments:

TransCanada is currently finalizing a SCCDA Plan which will be forwarded to PHMSA upon completion.

4. Has/does the operator evaluate the pipeline system for the presence of SCC risk indicators?

Comments:

Yes, TransCanada completed a risk assessment of the entire pipeline system, not just the HCA's.

SUPPLEMENTAL SCC QUESTIONNAIRE GAS TRANSMISSION OR LIQUID PIPELINE

5. Has the operator identified pipeline segments that are susceptible to SCC?

Comments:

Yes, mostly on the A-Line has been identified as SCC susceptible.

6. If conditions for SCC are present, are written inspection, examination and evaluation procedures in place?

Comments:

TransCanada is finalizing a SCCDA plan which will cover the procedures referenced in question 3, above.

7. Does the operator have written remediation measures in place for addressing SCC when discovered?

Comments:

Yes, TransCanada has a procedure, 'Repair of Pipeline Defects and Imperfections'.

- 8. What preventive measures has the operator taken to prevent recurrence of SCC?
 - Modeling?
 - Crack growth rate?
 - Comparing pipe/environ./cp data vs. established factors?
 - Other?
 - Hydrotest program?
 - Intelligent pigging program?
 - Pipe re-coating?
 - Operational changes?
 - Inspection program?
 - Other?

Comments:

TransCanada is about to being quantify the SCC threats on the A-Line. Plans are in place to complete the SCCDA plan which will ultimately result in inspections at susceptible sites.

SUPPLEMENTAL SCC QUESTIONNAIRE GAS TRANSMISSION OR LIQUID PIPELINE

9. Does the operator incorporate the risk assessment of SCC into a comprehensive risk management program?

Comments:

TransCanada utilizes a quantitative risk assessment process (PRIME) to model the threat of SCC.

Continue below for those operators who have not considered SCC as a possible safety risk.

10. Does the operator know of pipeline and right of way conditions that would match the risk indicators for either classical or non-classical SCC? See typical risk indicators below.

Comments:

Yes, the SCCDA plan includes reference to these risk indicators. As indicated, above, the A-Line is recognized as a threat of SCC.

High pH SCC Potential Risk Indicators

- Known SCC history (failure, non-failure, in service, and during testing)
- Pipeline and Coating Characteristics
- Steel grades X-52, X-60, X-65, X-70, and possibly X-42
 - Age \geq 10 years
 - Operating stress > 60% SMYS
 - Pipe temperature >100 deg. F (typically < 20 miles d/s of compression)
 - Damaged pipe coating
- Soil Characteristics
 - Soil pH range: 8.5 to 11
 - Alkaline carbonate/bicarbonate solution in the soil
 - Elevated soil temperature contributing to elevated pipe temperature
- Polarized cathodic potential range: -600 to -750 mV, Cu/CuSO4

Low or Near-Neutral pH SCC Potential Risk Indicators

- Known SCC history (failure, non-failure, in service, and during testing)
- Pipeline and Coating Characteristics
- Steel grades X-52, X-60, X-65, X-70, and possibly X-42
 - Age \geq 10 years
 - Frequently associated with metallurgical features, such as mechanical damage, longitudinal seams, etc.
 - Protective coatings that may be susceptible to disbondment

SUPPLEMENTAL SCC QUESTIONNAIRE GAS TRANSMISSION OR LIQUID PIPELINE

- Any coating other than correctly applied fusion bonded epoxy, field applied epoxies, or coal tar urethane . . .
- Coal tar
- Asphalt enamels
- Tapes
- Others
- Soil Characteristics
 - Soil pH range: 4 to 8
 - Dissolved CO2 and carbonate chemicals present in soil
 - Organic decay
 - Soil leaching (in rice fields, for example)
- "Normal" cathodic protection readings (disbonded coating shields the pipe from cp current)