

Wildfire Resiliency Fall Update Washington Utilities and Transportation


Commission Open Meeting

David Howell, Director of Operations

November 21, 2023

Guiding Principles

Promote public and worker safety around the impacts of wildfire



Minimize service disruptions caused by wildfires and other extreme weather events





Presentation Agenda

Avista Wildfire Resiliency








2023 Fire Season Review





2023 Washington Wildfire Conditions

Washington Drought Conditions




ught & Dryness Categories	% of WA
D0 – Abnormally Dry	19.2%
D1 – Moderate Drought	36.5%
D2 – Severe Drought	26.2%
D3 – Extreme Drought	9.8%
D4 – Exceptional Drought	0.0%
Total Area in Drought (D1–D	72.6%
	D0 – Abnormally Dry D1 – Moderate Drought D2 – Severe Drought D3 – Extreme Drought D4 – Exceptional Drought





2023 Washington Wildfires




2023 Avista Wildfire Events





Regional Fire and Operational Summary








Evaluating Risk During Fire Season

Snapshot: Fire Risk Scores for Four Feeders We Moved Into Elevated Protection Modes

- ✓ Correlation between the Dashboard predictions and actual outcomes was strong
- ✓ Timing of moving to elevated protection was aligned with actual fire activity







Noxon-Pine Creek 230 kV – July 8th












- About 1 acre
- Pole fire
- Burned trees and brush
- Fire resistant mesh protected pole, only repairs required





Ritzville, WA - July 17th








Scenes from the Ritzville fire






Benewah-Pine Creek 115 kV – July 29th



- Fire about 20 feet in diameter
- Right outside Plummer Substation
- Broken transmission crossarm
- No public structures damaged
- Burned brush
- Quick response by fire department





Examples of damaged crossarms





Shawnee-Sunset 115 kV – August 3rd



- About 1 acre in size
- Outside Spangle Substation
- Damaged 1 transmission structure
- No public structures damaged
- Burned brush



Damage on Shawnee-Sunset










Gray Fire – Medical Lake, WA - August 18th



- 10,085 Acres
- Cause under investigation
- 250+ homes lost
- 1 fatality
- 255 distribution poles lost

The restoration process involved 150 Avista employees, 13 crews, 50 Veg. Management Contractors. We lost 255 poles and 1,692 customers had outages.




Scenes from the Gray fire





Hospital Fire - Orofino, ID - August 29th





- 53 Acres
- Unknown Cause
- Destroyed 6 homes & multiple outbuildings
- Destroyed 1 transmission H-Frame
- Damaged Avista's Orofino Substation





Scenes from the Hospital fire





Communications






Community Outreach





- 90,422 Customers Reached
- 16 Counties in Tier 2 and 3
- 640 Public Safety Partners & Key Community Leaders
- Multi-Language Communications

2023 Telephone Town Hall Meetings






Avista's Named Communities

• 46% of Avista's Washington Customers:

- Highly Impacted Communities
- Vulnerable Populations


- Communication
- Outreach
- Support





Reaching Our Most Vulnerable Customers

- Identifying vulnerable customers
- Partnering with external agencies
- Special outreach to Tribes
- Pro-active outreach
- Employee Community Response Team
- Rapid-acquisition customer lists
- Non-English outreach materials
- Mapping vulnerable customer locations







External Partner Outreach

- Cross-training
- Local Emergency Management
- Partnering with first responders
 - Local
 - State
- Fire Weather Dashboard sharing
- Imbedding with fire critical incident response
- Fuel Reduction Partnerships Program
- Coordination with peer utilities



Tabletop Exercise Wildfire Scenario

- Included External Partners
- Valuable Lessons:
 - Learned each other's "language"
 - Strengthened relationships
 - Value of embedding Avista with fire incident response





Wildfire Related Grants






Grid Hardening

Applied for two grants:

- \$129 million: Convert 25% of planned overhead grid hardening to underground
- \$70 million: Reinforce existing
 overhead lines








Wildfire Identification Cameras

PanoAl Camera Installations

• Early Detection = Expedited Response







AVISTA




Wildfire Insurance





Insurance Update



Jurisdiction	Insurance Balancing Account Mechanism
Washington	Yes
Idaho	Yes






2023 Recap





Avista's Wildfire Resiliency Plan Status








2023 Accomplishments

- Implemented Fire Safety Mode Successfully
- Expedited Response covers nearly 100% of our service territory
- Developed & Tested Formalized Wildfire EOP
- Enhanced & Improved Customer Outreach
- Updates to WUI Map
- Enhanced Fire Weather Dashboard
- Public Safety Power Shutoffs: Initiated Planning
- Safe Tree Program Expanded Systemwide





Plans for 2024





Vegetation Management Challenges

Scaling the vegetation management risk tree program to complete 100% risk inspection annually is a bigger lift than anticipated.

> • Competitive Labor Markets for Contractors

• Forest Health Issues

• Incorporating New Technologies

• Customer Access for Vegetation Work

These pictures are of the same group of trees, four months apart, after a beetle infestation.





Public Safety Power Shutoffs

Utility	Enhanced Protection System?	Public Safety Power Shutoffs
Avista	Yes	Developing
APS - Arizona	Yes	Yes
Idaho Power	Yes	Yes
Northwestern	Yes	Developing
NV Energy	Yes	Yes
PG&E	Yes	Yes
PGE - Portland	Yes	Yes
PacifiCorp	Yes	Yes
Puget (PSE)	Yes	Developing







Enhanced Grid Hardening

Base Grid Hardening

Undergrounding Covered Conductor



Feeder Miles
2,747
1,700
3,200








Grid Hardening

Operations & Response

Avista Wildfire Resiliency egetation Momt.

Operations & Emergency Response





- All fire safety mode capable feeders "opted-in" to fire safety mode by default
- Reduce trigger point for initiating enhanced protection
- Non-fire safety mode feeders to be operated at "extreme" protection levels when wildfire conditions exist
- Public Safety Power Shutoffs as a tool





Questions



