7/17/24, 9:27 AM

FMCSA - Inspection Platform

DRIVER/VEHICLE EXAMINATION REPORT



Washington State Patrol

UTC

PO Box 42614

Ołympia, WA 98504-2614 Phone: (360) 596-3815 Email/Web: www.wsp.wa.gov Report Number: WAU586000051

Inspection Date: 07/17/2024

Start: 09:06 AM PDT End: 09:31 AM PDT

Inspection Level: V HM Inspection Type: None

BAKER BUS SKI AND SNOWBOARD CLUB

6903 BOURNE ST **DEMING, WA, 98244** USDOT#: 3772398 MC/MX#:

State#: Phone#: 3605993115

Fax#:

Driver: Licenses State# Date of Birth#

CoDriver: License#

State# Date of Birth# Location: BELLINGHAM WA

MilePost:

Highway: 714 Lakeway Dr County: WHATCOM

Shipper: Bill of Lading:

Origin: BELLINGHAM, WA, US Destination: BELLINGHAM, WA, US

Cargo: Empty Bus

VEHICLE IDENTIFICATION

VIN GVWR Mileage CVSA# CVSAIssued# OOS Sticker Unit Type Make Year State Plate # **Equipment ID** 1GBJG316191148562 VN CHEV 2009 WA CBZ0201 12,300 1

BRAKE MEASUREMENTS

Steer Axle Yes Νo Chamber Disc Disc Right N/A N/A Axle 2 Left N/A N/A

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	oos	Citation #	Verify	Violations Discovered
390.21TC	390.21T(c)	С	N		N	Improper size/location/color of required CMV marking(s): Not Marked with DOT prior to DOT number. No UTC charter number
393.60C	393.60(c)	1	N		N	Windshield - Damaged or Discolored: Windshield has crack from left side to right side and bottom to mid windshield in center of windshield.
393.9A-LBL	393,9(a)	1	N		N	Lighting - Backup lamp inoperative: Left and right back-up lights are inoperable.

Facility:

Special Checks:

No Data for Special Checks.

VIOLATIONS WERE REPAIRED

Signature Of Repairer X: _

I CERTIFY THAT ALL MECHANICAL

Date:

Copy Received By: 3772398 WA WAU586000051