


Letter of Transmittal

To: Mr. Dana Bayuk
Oregon DEQ, Northwest Region
700 NE Multnomah Street, Suite 600
Portland, Oregon 97232-4100

From: Mr. Rob Ede 
Hahn and Associates, Inc.
robe@hahnenv.com

Date: July 24, 2019

Regarding: Transmittal of Downhole Video (Thumb Drive)

Hahn and Associates, Inc., is providing the following documents:

Copies	Description
1	Thumb Drive Containing: Downhole Video of Old Gasco Supply Well (Mult 802) recorded on July 8, 2019 (filename "OSW_070819.mp4")
Notes:	<ol style="list-style-type: none">1) The video depth counter was inadvertently reset to depth = 0 feet at actual depth equals 200 feet below the top of casing during the camera trip down-hole.2) The depth interval of 13.6 feet to 27.3 feet below top of casing (during the trip down-hole) was inadvertently not recorded. This interval was successfully recorded on the trip up-hole (see -186.4 feet to -172.7 feet on depth counter).3) The tar on the inside of the 12-inch casing (from the top of casing down) occurred during decommissioning activities resulting from retrieval and clean-out of the 8-inch casing while temporarily clamped within the top of the borehole prior to cutting/removal.

Copied recipients:

Mr. Bob Wyatt, NW Natural
Ms. Patty Dost, Pearl Legal Group, PC
Ms. Jen Mott, Anchor QEA, LLC