

Cascade Natural Gas Corporation Pipeline Replacement Program Plan June 2019

Docket No. UG-120715

Table of Contents

I.	Introduction	2
	Cascade's Distribution Integrity Management Program (DIMP)	
III.	Cascade's Transmission Integrity Management Program (TIMP)	3
IV.	Integrity Management Analysis and Quantification	3
V.	Identification of Pipelines for Replacement	4
VI.	Obtaining New Information	4
VII.	Cascade's PRP Plan Progress	5
VIII.	Early Vintage Steel Pipe (EVSP)	5
IX.	Public Interest	. 10

I. Introduction

On December 31, 2012, the Washington Utilities and Transportation Commission (WUTC) issued a policy statement, in Docket UG-120715, for the accelerated replacement of natural gas pipeline facilities with elevated risk. This policy statement requires each gas company requesting a special pipe replacement cost recovery mechanism (CRM) to file with the Commission a pipe replacement program plan containing the following elements:

- 1. A "master" plan for addressing all pipes with an elevated risk of failure
- 2. A two-year plan that specifically identifies the goals for the upcoming two-year period
- 3. A plan for identifying the location of pipe that presents elevated risk of failure

In accordance with this policy statement, Cascade Natural Gas Corporation (Cascade) has previously submitted pipeline replacement program (PRP) plans, beginning in 2013, for pipe that poses an elevated risk of failure. Through Cascade's Distribution Integrity Management Program (DIMP) and Transmission Integrity Management Program (TIMP), Cascade continually analyzes the performance of its gas distribution systems and through a detailed analysis indicate certain categories of Cascade's gas system which present an elevated risk of failure. These categories are included as part of Cascade's PRP plan.

II. Cascade's Distribution Integrity Management Program (DIMP)

The requirement for Cascade to have a DIMP became effective on February 12, 2010. Operators were given until August 2, 2011, to write and implement a DIMP that demonstrates an understanding of the distribution system design and material characteristics; describes the operating conditions and environment; provides the maintenance and operating history; identifies existing and potential threats; evaluates and rank risks; identifies and implements measures to address risks; measures program performance; monitors results; evaluates effectiveness; and periodically assesses and improves the plan. The threats that are identified and evaluated in DIMP include:

- Corrosion
- Natural Forces
- Excavation Damage

- Other Outside Force Damage
- Material, Weld, or Joint Failure
- Equipment Failure
- Incorrect Operation
- Missing Data
- Other Forces unique to a particular area on the system

Cascade's DIMP Plan describes these risks and steps in greater detail. Cascade's DIMP Plan is on file with the WUTC's Pipeline Safety Division.

III. Cascade's Transmission Integrity Management Program (TIMP)

PHMSA rules required Cascade to create and implement a TIMP by December 17, 2004. The purpose of TIMP is to identify, prioritize, assess, evaluate, repair, and validate the integrity of transmission pipelines that could, in the event of a leak or failure, affect High Consequence Areas (HCAs). The threats that are identified and evaluated in TIMP include:

- Corrosion (External, Internal, Stress Corrosion Cracking)
- Material
- Construction
- Equipment
- Excavation Damage
- Incorrect Operations
- Vandalism
- Weather and Outside Forces
- Cyclical Fatigue

Cascade's TIMP Plan describes these risks and steps in greater detail. Cascade's TIMP Plan is on file with the WUTC's Pipeline Safety Division.

IV. Integrity Management Analysis and Quantification

As part of Cascade's DIMP and TIMP Plans, a risk analysis has been created and is maintained. Information collected as part of DIMP and TIMP are inputted into the risk analysis, where it is analyzed to find areas of concern and trends. This allows Cascade to quantify the risk associated with each pipeline based on factors that are pertinent to this PRP Plan. Cascade's DIMP and TIMP contains a more detailed explanation of this process.

V. Identification of Pipelines for Replacement

DIMP and TIMP risk analysis results and SME input are used to identify the locations of pipelines that should be addressed in the PRP Plan.

For pipelines identified by DIMP, samples of the DIMP risk analysis for the areas identified in the PRP Plan are included in Appendix A. Once replacement locations are identified, specific projects within these areas are planned and prioritized based on coordination with district and on-site personnel considered to be Subject Matter Experts (SMEs). This helps ensure the replacement of pipeline segments with an elevated risk within the identified areas.

VI. Obtaining New Information

Cascade obtains new information for their DIMP and TIMP risk analysis and PRP Plan through the following methods:

- 1. Observing trending DIMP and TIMP are analyzed on a yearly basis. The analysis includes reviewing leak information, failure analysis, and system condition data to identify trends. The analysis provides insight into the risks associated with pipe identified as having an elevated risk of failure that are included in the PRP plan.
- 2. New information is gathered through normal activities. Gathering new information from forms or other methods used to collect information related to the physical attributes and/or operating and maintenance activities. Integrating newly collected information into DIMP and TIMP.
- 3. Subject Matter Expert (SME) panel meetings SME panel meetings are held on an appropriate basis. Information from the panel meetings are used to validate the DIMP and TIMP risk analysis and new information is inputted into the DIMP and TIMP risk analysis.
- 4. Updating risk analysis Cascade's DIMP and TIMP risk analysis is updated annually. Results of the risk analysis are used to prioritize pipeline replacement projects.
- 5. Continuous improvement The assessment, prioritization, and mitigation of system risks continue to be refined as new and additional risk knowledge is incorporated into DIMP and TIMP through normal O&M and DIMP and TIMP activities. Activities related to DIMP and TIMP could include gathering data, conducting targeted inspections and assessments, and

completing remediation and replacement work associated with integrity management driven programs.

Based on new information that is obtained, the Master Plan may be modified appropriately to further accelerate or decelerate the pipe replacement schedule. Additionally, Cascade is actively monitoring system threats and performance and may identify additional pipeline segments that have an elevated risk of failure. If any changes are made to the PRP plan, Cascade will submit the changes to the WUTC as required by the policy statement.

VII. Cascade's PRP Plan Progress

The following table summarizes the miles of main replaced under the replacement programs according to the Master Plan since 2013.

Table 1. Summary of Replacement Programs from 2013-2018

Year	Miles of Main
2013	3.0
2014	4.8
2015	5.9
2016	11.9
2017	16.1
2018	19.3
Total	61.0

VIII. Early Vintage Steel Pipe (EVSP)

Master Plan

This Master Plan will serve as the guide that Cascade will use to determine which pipelines should be addressed as part of the PRP plan. This Master Plan will describe the possible risks that can be associated with Early Vintage Steel Pipe (EVSP).

Risk Assessment

Cascade has identified an increased risk of failure on different subsets of early vintage steel pipe (EVSP). EVSP is steel mains, service lines, and associated fittings installed earlier than 1/1/1970. These pipeline segments present an increased risk of failure due to aging and/or obsolete pipelines.

The primary risks on EVSP include external corrosion, material, weld, or joint failure, equipment failure, and missing data. External corrosion on EVSP is

attributed to bare, disbonded, damaged or poorly performing pipe coatings, poor soil and backfill conditions, ineffective cathodic protection, and other factors. Material, weld, or joint failure on EVSP is typically associated with issues with pipe welds made during installation (lack of weld standards and welder qualification), vintage acetylene gas welds, or pipe and fitting material leaks. Equipment failures on EVSP are normally contributed to leaks at main to service connections were Orings have failed, mechanical couplings and fittings, and on other aging equipment installed when the pipe was originally installed. EVSP also has increased risk associated with pipe with unknown attributes or missing data, which includes unknown physical infrastructure (i.e. pipe material, pipe specifications, construction information) and historical information (i.e. corrosion control records, maintenance records, leak records).

Ongoing analysis of EVSP continues to show this pipe has a greater likelihood to leak, have corrosion, and/or substandard pipe conditions. These segments of main and their associated service piping have an elevated risk of failure as validated by DIMP and TIMP risk analysis. The different subsets of EVSP include:

Pre-CNG

Cascade operates pipeline segments that are classified as Pre-CNG pipe segments. Pre-CNG pipe segments are distribution systems that were constructed to distribute manufactured gas or natural gas. These pipelines were originally installed, owned, operated, and maintained by others prior to 1955. Cascade acquired many of these systems in the late 1950s and throughout the 1960s. The condition of the Pre-CNG pipe is typically bare steel or coal tar wrapped. This pipe is of concern since it is over 60 years old and operated with no or inadequate cathodic protection until the early 1970s, leaving the pipe suspect to elevated corrosion risk. Pre-CNG pipe also has elevated risks associated with missing data with not fully knowing the physical infrastructure and historical information of the Pre-CNG pipe. The extent of this pipe varies throughout Cascade's and depends on the history of the system and how it was acquired by Cascade. The total miles of Pre-CNG in Washington is shown in Table 2 below.

Table 2. Total Miles of Pre-CNG in Washington

Total Miles of Pre-CNG Distribution Main	145.03 *
Total Miles of Pre-CNG Transmission Main	2.91

^{*} Includes 144.97 miles with missing or unknown install date.

DIMP maps showing the 2013 and 2018 DIMP risk analysis for Longview/Kelso, Anacortes, and Shelton pipe replacement projects are shown in Appendix B. Through Pre-CNG pipe replacement projects Cascade has removed approximately 65 miles of Pre-CNG pipe as of the end of 2018.

FISH

Cascade operates pipeline segments that are classified as FISH pipe segments. FISH pipe segments are distribution systems that were installed by Fish Service & Management Corporation in the 1950's through the early 1960's. FISH pipe is normally coal tar wrapped. FISH pipe is of concern since it is around 60 years old and may have operated with no or inadequate cathodic protection until the early 1970s, leaving the pipe suspect to elevated corrosion risk. FISH pipe also tends to have an elevated likelihood to have leaks associated with material and welds. The extent of this pipe varies throughout Cascade's system and depends on the history of the system and how Cascade built out the system in the late 1950's and early 1960's. The total miles of FISH in Washington is shown in Table 3 below.

Table 3. Total Miles of FISH in Washington

Total Miles of FISH Distribution Main	205.99 *
Total Miles of FISH Transmission Main	0.00

^{*} Includes 115.03 miles with missing or unknown install date.

Pre-1970

Cascade operates pipeline segments installed earlier than 1/1/1970 that are not classified as either Pre-CNG or FISH. These pipeline segments were originally installed by either Cascade employees or other contractors hired by Cascade. These pipeline segments are typically coal tar wrapped. This pipe is of concern due to its overall age may have had no or inadequate cathodic protection until the early 1970s, leaving the pipe suspect to corrosion risk. This pipe also has a elevated weld failure risk associated with leaks on vintage metal arc welds and acetylene gas welds. The total miles of Pre-1970 in Washington is shown in Table 4 below.

Table 4. Total Mile of Pre-1970 in Washington

Total Miles of Pre-1970 Distribution Main	1177.58 *
Total Miles of Pre-1970 Transmission Main	93.58

^{*} Includes 242.83 miles with missing or unknown install date.

EVSP Replacement Program Plan

Cascade is actively replacing EVSP that poses an elevated risk of failure. Cascade will continue monitoring the performance of EVSP through DIMP and TIMP, and appropriately update the replacement schedule and timeframe as necessary. For pipe currently not identified as having an elevated risk of failure, Cascade will continue to incorporate new risk knowledge and evaluate whether this population warrants replacement under PRP in the future.

Two-Year Plan

The two-year plan is to continue replacing EVSP according to the Master Plan. The following table shows the planned replacement miles of EVSP for the next two years. Cascade's two-year plan has been divided into two separate time periods. The time periods and the work that are proposed for each are listed below.

November 1, 2018 – October 31, 2019 Capital Replacement Projects							
PROJECT	DISTRICT	TYPE OF PIPE TO BE REPLACED					
ANACORTES IP EVSP REPLACEMENT, PHASE 7	MT. VERNON	EVSP (PRE-CNG, FISH)					
LONGVIEW IP EVSP REPLACEMENT, PHASE 8	LONGVIEW	EVSP (PRE-CNG)					
KELSO IP EVSP REPLACEMENT, PHASE 2	LONGVIEW	EVSP (PRE-CNG)					
KELSO IP EVSP GRADE ST. REPLACEMENT	LONGVIEW	EVSP (PRE-CNG)					
SHELTON IP EVSP REPLACEMENT, PHASE 3	ABERDEEN	EVSP (PRE-CNG)					
WALLA WALLA IP EVSP 9 TH AVE MILL CREEK REPLACEMENT	WALLA WALLA	EVSP (FISH)					
12" LONGVIEW KELSO HP DISTRIBUTION EVSP REPLACEMENT, PHASE 3	LONGVIEW	EVSP (PRE-CNG) *					
4" OTHELLO HP EVSP REPLACEMENT	WENATCHEE	EVSP (PRE-1970) *					
6" ANACORTES HP DISTRIBUTION EVSP REPLACEMENT, PHASE 2	MT. VERNON	EVSP (FISH) *					
BELLINGHAM IP EVSP. ALLEYWAY REPLACEMENTS	BELLINGHAM	EVSP (FISH, PRE-1970)					
LYNDEN IP EVSP ALLEYWAY REPLACEMENTS	BELLINGHAM	EVSP (PRE-CNG)					

^{*} PIPELINE SEGMENT IDENTIFIED IN SETTLEMENT AGREEMENT DOCKET PG-150120.

November 1, 2019 – October 31, 2020 Capital Replacement Projects							
PROJECT	DISTRICT	TYPE OF PIPE TO BE REPLACED					
ANACORTES IP EVSP REPLACEMENT, PHASE 8	MT. VERNON	EVSP (PRE-CNG, FISH)					
LONGVIEW IP EVSP REPLACEMENT, PHASE 9	LONGVIEW	EVSP (PRE-CNG)					
KELSO IP EVSP REPLACEMENT, PHASE 3	LONGVIEW	EVSP (PRE-CNG)					
SHELTON IP EVSP REPLACEMENT, PHASE 4	ABERDEEN	EVSP (PRE-CNG)					
2" NOOKSACK HP DISTRIBUTION EVSP REPLACEMENT	BELLINGHAM	EVSP (PRE-1970) *					
3" ZILLAH HP EVSP REPLACEMENT	YAKIMA	EVSP (FISH) *					
4" ARLINGTON HP EVSP REPLACEMENT	MT. VERNON	EVSP (FISH) *					
8" BREMERTON HP EVSP REPLACEMENT	BREMERTON	EVSP (PRE-1970) *					
12" LONGVIEW KELSO HP DISTRIBUTION EVSP REPLACEMENT, PHASE 4	LONGVIEW	EVSP (PRE-CNG) *					
6" ANACORTES HP DISTRIBUTION EVSP REPLACEMENT, PHASE 3	MT. VERNON	EVSP (FISH) *					
8" MARCH POINT TRANSMISSION EVSP REPLACEMENT, PHASE 2	MT. VERNON	EVSP (PRE-1970) *					
8" YAKIMA HP EVSP REPLACEMENT	YAKIMA	EVSP (FISH) *					

^{*} PIPELINE SEGMENT IDENTIFIED IN SETTLEMENT AGREEMENT DOCKET PG-150120.

The projects listed in these tentative schedules are based on the best information available at this time. As more information becomes available and risk analysis is updated, the prioritization of the projects may change. DIMP output for replacement projects is shown in Appendix A.

Summary of the previous two-year plan from November 1, 2016 – October 31, 2018 is shown in Appendix C.

Identification Plan

The location of EVSP that presents an elevated risk of failure is continually monitored by reviewing system information that includes leak repairs, active leaks, and exposed pipe condition reports. In conjunction with reviewing system performance data, the geographic information system (GIS) and risk analysis is

being utilized to proactively identify any new areas that may present an elevated risk of failure.

IX. Public Interest

The pipe replacement plans for the portion of Cascade's gas distribution system that pose an elevated risk of failure included in this PRP plan have been developed considering many factors. These factors include:

- Improving the safety of the distribution system by replacing pipe based on the relative level of risk presented for each material and location.
- Minimizing the replacement costs by maximizing efficiencies and productivity.
- Minimizing the impacts to municipalities and the general public.

APPENDIX A DIMP MODEL OUTPUT

Areas in red represent highest risk areas.

WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation


2" NOOKSACK HP DISTRIBUTION EVSP REPLACEMENT



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation


3" ZILLAH HP EVSP REPLACEMENT



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation

4" ARLINGTON HP EVSP REPLACEMENT






WGS_1984_Web_Mercator_Auxiliary_Sphere


© Cascade Natural Gas Corporation

4" OTHELLO HP EVSP REPLACEMENT



© Cascade Natural Gas Corporation


6" ANACORTES HP DISTRIBUTION EVSP REPLACEMENT, PHASE 2 & 3



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation


8" BREMERTON HP EVSP REPLACEMENT



WGS_1984_Web_Mercator_Auxiliary_Sphere


© Cascade Natural Gas Corporation

8" MARCH POINT TRANSMISSION EVSP REPLACEMENT, PHASE 2



© Cascade Natural Gas Corporation


8" YAKIMA HP EVSP REPLACEMENT



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation


12" LONGVIEW KELSO HP DISTRIBUTION EVSP REPLACEMENT, PHASE 3



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation

12" LONGVIEW KELSO HP DISTRIBUTION EVSP REPLACEMENT, PHASE 4




FIELD LOCATES ARE REQUIRED FOR LOCATION OF UTILITY FACILITIES


EVSP (PRE-CNG)

© Cascade Natural Gas Corporation


ANACORTES IP EVSP REPLACEMENT, PHASE 7



ANACORTES IP EVSP REPLACEMENT, PHASE 8




BELLINGHAM IP EVSP. ALLEYWAY REPLACEMENTS



© Cascade Natural Gas Corporation

KELSO IP EVSP GRADE ST. REPLACEMENT






WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation

KELSO IP EVSP REPLACEMENT, PHASE 2 & 3






WGS_1984_Web_Mercator_Auxiliary_Sphere


© Cascade Natural Gas Corporation

LONGVIEW IP EVSP REPLACEMENT, PHASE 8 & 9



© Cascade Natural Gas Corporation


LYNDEN IP EVSP ALLEYWAY REPLACEMENTS



WGS_1984_Web_Mercator_Auxiliary_Sphere

© Cascade Natural Gas Corporation

SHELTON IP EVSP REPLACEMENT, PHASE 3 & 4



FIELD LOCATES ARE REQUIRED FOR LOCATION OF UTILITY FACILITIES

EVSP (PRE-CNG)

WGS_1984_Web_Mercator_Auxiliary_Sphere


© Cascade Natural Gas Corporation


WALLA WALLA IP EVSP 9TH AVE MILL CREEK REPLACEMENT





APPENDIX B KELSO/LONGVIEW, ANACORTES, SHELTON DIMP MODEL OUTPUT













APPENDIX C PREVIOUS TWO-YEAR PLAN SUMMARY

NOVEMBER 1, 2016 – OCTOBER 31, 2017

FUNDING PROJECT(S)	PROJECT	DISTRICT	PROJECT DESCRIPTION	IN-SERVICE DATE		REPLACED MILEAGE	NEW MILEAGE		REPLACED MILEAGE	NEW MILEAGE
200687	CRM RPL ANACORTES BARE STEEL PHASE V	MT. VERNON	BARE STEEL/PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	12/6/2016, 10/4/2017	2" STL	3.90	0	2" PE	0	4.01
200686	CRM RPL LONGVIEW BARE STEEL PHASE VI	LONGVIEW	BARE STEEL/PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	10/24/2017, 10/30/2017	2/6" STL	7.32	1.15	2/4/6" PE	0	6.17
306982	CRM VANCE CREEK EXPOSURE REPLACE	ABERDEEN	EXPOSED PIPE (CORROSION) IN ADDITION TO MODERATE (ORANGE) RISK IN DIMP	10/27/2016	8" STL	0.26	0.26			
306983	CRM CAMP CREEK EXPOSURE REPLACEMENT	ABERDEEN	EXPOSED PIPE (CORROSION) IN ADDITION TO MODERATE (ORANGE) RISK IN DIMP	10/28/2016	8" STL	0.25	0.26			
306986	CRM 3" BURLINGTON HP LINE REPL	MT. VERNON	PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	5/23/2017	4" STL	1.01 (3")	0.90 (4")			
302663	CRM BELLINGHAM BRIDGE CROSSINGS RMV	BELLINGHAM	PRE-CNG PIPE - IDENTIFIED HIGH (RED) & MODERATE (ORANGE) RISK IN DIMP	2017 TIME	PERIOE SCHEDU	MPLETED IN 1 DUE TO PER LED TO BE CO OCTOBER 31	MITTING AND COMPLETED	ND RIG	HT OF WAY DENOVEMBER	DELAYS.
307212	CRM KELSO GRADE ST BRIDGE RELOCATE	LONGVIEW	EXPOSED PIPE SUSCEPTIBLE TO CORROSION RISK - MODERATE (ORANGE)	PROJECT NOT COMPLETED IN THE NOVEMBER 1, 2016 - OCTOBER 31, 2017 TIME PERIOD DUE TO DELAYS OBTAINING ARMY CORP OF ENGINEERS PERMIT TO CROSS COWEEMAN RIVER. PROJECT SCHEDULED TO BE COMPLETED IN THE NOVEMBER 1, 2017 - OCTOBER 31, 2018 TIME PERIOD.						
309001	2 IN STEEL IP BORE BELFAIR PL	KENNEWICK	MODERATE (ORANGE) RISK IN DIMP	1/6/2017	2" STL	0.04	0.05			
312041	CRM 6" NOB HILL REPLACEMENT	YAKIMA	IDENTIFIED HIGH (RED) RISK IN DIMP	6/8/2017	6" STL	0.01	0.01			
312043	KENNEWICK RR CROSS NEAR KAMIAKIN	KENNEWICK	MODERATE (ORANGE) RISK IN DIMP	8/1/2017	2" STL	0.08	0.12	2" PE	0	0.18
300346	CRM RPL; 12" STL HP, KELSO	LONGVIEW	HIGH (RED) RISK IN DIMP	12/19/2017	12" STL	0.77	0.63			
300363	CRM SHELTON PIPE REPLACEMENT	ABERDEEN	PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	9/18/2017	2/3" STL	2.06	0	2/4" PE	0	2.14
315641	VANCE CREEK REPLACEMENT (#2)	ABERDEEN	EXPOSED PIPE (CORROSION) IN ADDITION TO MODERATE (ORANGE) RISK IN DIMP	12/8/2016	8" STL	0.24	0.24			
315731	RPL 2" STL MN - BELLINGHAM	BELLINGHAM	IDENTIFIED MODERATE (ORANGE) RISK IN DIMP,	5/30/2017	2" STL	0.13	0.10	2" PE	0	0.09

PROJECT CANCELLED OR DELAYED FROM PLAN PERIOD PROJECT CARRIED OVER FROM PREVIOUS YEAR PROJECT ADDED TO PIPE REPLACEMENT PLAN

NOVEMBER 1, 2017 – OCTOBER 31, 2018

FUNDING PROJECT(S)	PROJECT	DISTRICT	PROJECT DESCRIPTION	IN-SERVICE DATE		REPLACED MILEAGE	NEW MILEAGE		REPLACED MILEAGE	NEW MILEAGE
200687 316687 316689 316690 316691	ANACORTES BARE STEEL PHASE 5/6	MT. VERNON	BARE STEEL/PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	3/21/2018 (Phase 5) 7/24/2018 (Phase 6)	2/4" STL	3.73	0	2/4" PE	0	2.85
200686	CRM RPL LONGVIEW BARE STEEL PHASE 7	LONGVIEW	BARE STEEL/PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP			NCELED FOR TO ADDRES				
316568	12" STL HP REPLACEMENT, KELSO PHASE 2	LONGVIEW	PRE-CNG PIPE - HIGH (RED) RISK IN DIMP	9/11/2018	12" STL	0.85	0.90			
300363 316766 316767 316768	SHELTON PIPE REPLACEMENT PHASE 2	ABERDEEN	PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	7/9/2018	2/4" STL	2.33	0	2/4" PE	0	2.52
303140	CRM YAKIMA PIPE REPLACEMENT PHASE 1	YAKIMA	IDENTIFIED HIGH (RED) RISK IN DIMP			NCELED FOR TO ADDRES				
302594 316775 316777 316778 316787	KELSO BARE STEEL PHASE 1	LONGVIEW	BARE STEEL/PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	8/13/2018 9/17/2018 8/29/2018	2/4" STL	6.92	0	2/4" PE	0	<mark>7.15</mark>
316323	7" STL IP REPLACEMENT, RICHLAND	KENNEWICK	PRE-CNG PIPE - IDENTIFIED HIGH (RED) RISK IN DIMP	3/21/2018	7" STL	0.23	0	6" PE	0	0.25
<mark>302663</mark>	8" STL HP, RETIRE BRIDGE CROSSINGS	BELLINGHAM	PRE-CNG PIPE - IDENTIFIED HIGH (RED) & MODERATE (ORANGE) RISK IN DIMP	12/14/2018	8" STL	0.36			=	
307212	2" STL IP GRADE ST BRIDGE REPLACEMENT	LONGVIEW	EXPOSED PIPE SUSCEPTIBLE TO CORROSION RISK - MODERATE (ORANGE)	2017 TII ENGIN	ME PER EERS P	MPLETED IN TAILOR DUE TO DEPENDENT TO CRUE COMPLETED 31, 2018	ELAYS OBT	TAINING EMAN VEMBE	G ARMY COR RIVER. PROJ	RP OF IECT
316036 316713	8" STL HP REPLACEMENT, ANACORTES PH 1	MT. VERNON	FISH PIPE WITH HIGH - MODERATE RISK IN DIMP	5/21/2018	8" STL	0.89	0.94	2" STL	0"	0.43
316037	6"/8" STL HP REPLACEMENT, MOSES LAKE	WENATCHEE	PRE-CNG TRANSMISSION PIPELINE	12/28/2018	8" STL	3.12	3.13	•		<u>.</u>
316319	2" STL IP COAL CR SLOUGH REPLACEMENT	LONGVIEW	EXPOSED PIPE SUSCEPTIBLE TO HIGHER CORROSION RISK, PIPE IS POORLY COATED AND SUPPORTED	8/30/2018	2" STL	0.06	0.06	•		
314964	8" HP RPL, MARCH POINT TRANSMISSION LINE	MOUNT VERNON	PRE-CODE TRANSMISSION MAIN, HISTORY OF CORROSION	10/30/2018	8" STL	0.76	0.79	•		•

PROJECT CANCELLED FROM PLAN YEAR
PROJECT CARRIED OVER FROM PREVIOUS YEAR
PROJECT ADDED TO PIPE REPLACEMENT PLAN