Exhibit "B"

Field Data Collection

(2008 Standard Inspection)

Company: TransCanada Gas Transmission Northwest (GTN)

Unit: Wallula District Inspector: Al Jones/UTC

Pipe-to-soil potential readings and other items

Please note: The A and B pipelines are 36 and 42 inch diameter, respectively.

		Pipe	Casing	
Date	Location	(Volts DC)	(Volts DC)	Comments
10/7/08	B-Line, MP 206.8	-0.880 on	-0.258	All CP potential were taken by Darin
	Snake River at Hwy 261	-0.775 off		Pema, GTN field technician.
10/7/08	B-Line, MP 207.0	-0.900 on	-0.227	
	Abandoned RR Xing	-0.782 off		
10/7/08	A-Line, MP 206.7	-0.861	-0.207	
	Snake River Grain			
	Elevator			
10/7/08	A-Line, MP 206.8	-0.807 on	-0.298	
	Hwy 261 Xing	-0.701 off		
10/7/08	A-Line, MP 207.0	-0.872 on	-0.219	
	RR Xing	-0.758 off		
10/7/08	Starbuck Rectifier on	76.9 Vdc		Note: Positive wire to the deep well
	Fletcher Rd.	2.52 Amps		needs to be labeled per PHMSA
		C-4, F-5		Notice.
10/7/08	A-Line, MP 211.8	-1.058 on		
	Lyons Ferry Rd.	-0.895 off		
10/7/08	B-Line, MP 211.8	-1.073 on		
	Lyons Ferry Rd.	-0.902 off		
10/7/08	Starbuck Compressor			Anode Beds at Circuit:
	Station # 7			#1: 60.46v, 3.7 Amps
	MP 212.5	28.04 v,		#2: 28.04v, 3.6 Amps
	Rectifier for anode flex	3.6 Amps		#3: 26.15v, 4.5 Amps
	beds placed along the			#4: 20.18v, 4.6 Amps
	station piping.			#5: 49.25v, 4.2 Amps
				Note: Positive wire to the ground beds
				needs to be labeled per PHMSA
				Notice.
10/7/08	Starbuck Compressor	-1.414 on		P/S at Security Fencing -0.274vDC
	Station # 7	-0.979 off		
	Discharge Piping			
	MP 212.5			

D :	·	Pipe	Casing	
Date	Location	(Volts DC)	(Volts DC)	Comments
10/7/08	Starbuck Compressor Station #7 Rectifier for anode flex beds placed along the pipelines.	7.24 v, 5.7 Amps C-1, F-2		Anode Flex at Bed: #22: 1.7mv #23: 1.9mv #24: 1.5mv #25: 0.4mv Note: Positive wire to the deep well needs to be labeled per PHMSA Notice.
10/7/08	Starbuck Compressor Station #7 Two Rolls-Royce Turbines: Avon at12,500hp and RB-211 at 39,000hp.			Tested five gas sensors and seven fire eyes in Buildings B & C. Note: Vent fan at the SE corner of Building C did not operate during gas sensor test. Tested the discharge pressure sensor (PT-5) with a 911psig MAOP and 935 psig Overpressure Protection.
10/8/08	Welch Road, MP 220.9 A-Line B-Line	-1.684v on -1.524v on	,	pag a verpressure i resserva
10/8/08	Welch Road, MP 220.9 NORTH Rectifier for anode flex beds placed along the pipelines.	10.09 v 22.4 Amps C-1, F-3		Anode Flex at Bed: #43: 2.0mv #44: 2.3mv #45: 2.0mv #46: 1.7mv #47: 3.3mv #48: 3.1mv #49: 2.6mv #50: 2.6mv #51: 2.8mv Note: Positive wire to the Anode bed needs to be labeled per PHMSA Notice.
10/8/08	Welch Road, MP 220.9 SOUTH Rectifier for anode flex beds placed along the pipelines.	10.17v 15.6 Amps C-1, F-3		Anode Flex at Beds: #52: 3.0mv #53: 2.6mv #54: 2.6mv #55: 2.3mv #56: 2.5mv #57: 2.6mv Note: Positive wire to the Anode bed

Date	Location	Pipe (Volts DC)	Casing (Volts DC)	Comments
				needs to be labeled per PHMSA Notice.
10/8/08	Greenville Rd. MP 229.9 NORTH Rectifier for anode flex beds placed along the pipelines.	9.93v 14.4Amps C-1, F-3		Notice. Anode Flex at Beds: #74: 1.9mv #75: 0.0 #76: 2.1mv #77: 3.6mv #78: 0.0 #79: 1.4mv #80: 1.5mv #81: 1.7mv #82: 1.9mv #83: 1.9mv Note: Positive wire to the Anode bed
10/8/08	Greenville Rd. MP 229.9			needs to be labeled per PHMSA Notice.
	SOUTH Rectifier for anode flex beds placed along the pipelines.	9.93v 17.6Amps C-1, F-3		Anode Flex at Beds: #84: 2.4mv #85: 2.1mv #86: 2.4mv #87: 2.3mv #88: 2.3mv #89: 2.1mv #90: 2.1mv #91: 2.2mv Note: Positive wire to the Anode bed needs to be labeled per PHMSA Notice.
10/8/08	Main Line Valve 7-1	-1.22v		Operated valve by Neil Isley GTN field technician.
10/8/08	Eureka Flats Rectifier A-Line B-Line	41.88 v 0.8 Amps C-1,F-2 -0.764 -0.806	-0.196	
10/8/08	MP 238.3 A-Line B-Line	-0.800 -0.862		
10/8/08	MP 241.6 A-Line B-Line	-0.814 -0.837		
10/8/08	Main Line Valve 7-2 MP 241.9	-0.840		Operated valve by Neil Isley GTN field technician.

		Pipe	Casing	
Date	Location	(Volts DC)	(Volts DC)	Comments
		 		
10/8/08	Britton Rd Rectifier	14.3	 	The rectifier has not been working
	MP 244.8	0 Amps		since September 8, 2008. The
				pipeline is approximately 300ft
	A-Line	-0.740		distance from the rectifier and
	B-Line	-0.803		adjacent to a plowed wheat field. The
				wire connecting the pipeline to the
				rectifier indicated as an open circuit
				continuity, likely problem is a broken
····				wire.
10/8/08	Dodd Rd Rectifier			
	MP 248.4		-0.240	
	A-Line	-0.822	n/a	
40/0/00	B-Line	-0.854		
10/8/08	Chevron Pipeline Xing MP 254.3			
	A-Line	-0.888		
	Chevron Pipeline	-1.947		
	B-Line	-0.747	,	
10/0/00	Chevron Pipeline	-1.84		
10/8/08	Hatch Grade Rd Rectifier	75.7v		
	MP 257.4	2.25Amps		
	A-Line	C-4,F-5 -1.254		
	B-Line	-1.254		
10/8/08	Wallula Compressor	-1.243	<u></u>	Darin Pema and Neil Isley, GTN field
10/0/00	Station #8 has			technicians tested the gas sensors and
	Three Turbines including:			fire eyes at Building "C" near the
	Rolls-Royce Avon			Rolls-Royce Avon turbine. The gas
	at12,500hp, and two			lines to the sensors were not purged of
	Solar Titans at 19,500hp			gas between tests as required by
	each.			company procedure.
10/8/08	Wallula Compressor			Anode Beds at Circuit:
10,0,00	Station #8			#1: 2.44v, 0.0 Amps Off since 9/3/08
	Plant Rectifier			#2: 26.5v, 11.4 Amps
				#3: 21.4v, 13.1 Amps
- · · · - · · · · · · · · · · · · · · ·				#4: 17.1v, 13.1 Amps
				