# **WUCC Complaint Form**

## **Requester Information**

Your Name:		Your Company:	
Scot Wayne Hattenburg		M&L Construction Inc.	
Your Phone Number:		Your Email:	
15099914129		scot@MLNORTHWEST.COM	
Your Address:			
Po Box 6311			4103 e dalke ave
Your City:	Your State:		Your Zip:
spokane	WA		99217
Was a locate requested from the call center? O Yes O No			
Ticket Number:		Ticket Date:	
22296526		07/08/2022	

## **Violation Information**

Alleged Violation/Damage:			
$\bigcirc$ RCW 19.122.030 Must call for marking two (2) full business days prior to digging.			
Other 19.122.030			
Section of Law Violated:		Alleged Violation I	Date:
mis located the gas line by 1	0'	07/07/2022	
Address of alleged violation:			
3423 e 33rd Ave Spokane Wa			
City of Alleged Violation:	State of Alleged Vi	olation:	Zip of Alleged Violation:
Spokane	Washington		99223

Basic Description:

We cored the asphalt and used a suck truck to try and find a gas line.... when we spent 2 hours looking for the gas line Brandon Howell called Ray from Avista who came out and located the gas line 10' away.

### Alleged Violator

Company Name:			
Avista Utilities/ELM			
Company Phone Number:		Company Email:	
8002279187		Darrel.Moss@avistacorp.com	
Company Address:			
Company City:	Company State:		Company Zip:
Spokane	Washington		99252
Names of Employees on Site:			
scot hattenburg, brandon ho	owell		

#### Other

Additional Information:

please see additional documentation supplied dropbox link			

By submitting this form I acknowledge that the statements that I alleged are true and accurate to the best of my knowledge.

#### Washington One Call

Ticket number	22296526	Type/header	2 FULL BUSINESS D	AYS IX
Original call date	07/05/22 04:31 pm			
Work to begin date	07/08/22 07:00 am			
Expiration date	08/19/22 04:30 pm			
Excavator information				
Company name	M&L CONSTRUCTION INC	Type of excavator	CONTRACTOR	
Contact name	STEPHANIE HATTENBURG	Phone	509-991-4129	
Best time				
Alt. contact		Phone		
Address	4111 DALKE AVE SPOKANE, WA 99217-6520	Fax phone		
Email address	stephanie@mlconstruction.com			
Excavation information				
Type of work	BORE TO INSTALL FIBER COND	UIT		
Directional drilling	Yes			
Type(s) of excavation equipment	Directional Drilling, Vacuum Equip	ment		
Work being done for	VERIZON			
Location information				
State	WA	County	SPOKANE	
Place	SPOKANE			
Address/street	3607 E 33RD AVE			
Intersecting street	S FREYA ST			
Location of work	MARK 50 FEET EITHER SIDE OF	THE ROUTE MARKED IN W	/HITE PAINT. LOCATE	ROW TO ROW
Remarks	AREA MARKED IN WHITE PAINT			
<b>NW Lat</b> 47.6247119	Lon -117.3636731	SE Lat 47.6243992	<b>Lon</b> -1	17.3572557
Members notified				
District Company name	Marking concern	ns Customer service	Repair	Status
AVSP101 AVISTA	888-728-9343	800-227-9187	800-227-9187	Clear, No Utility Owned
				Facility in Excavation Area
AVSP201 AVISTA	888-728-9343	800-227-9187	800-227-9187	Marked, Complete
AVSP301 AVISTA	888-728-9343	800-227-9187	800-227-9187	Marked, Complete
MCI06 MCI	800-289-3427	972-656-1233	972-656-1233	Does not report
SPOKAN02 CITY OF SPOKANE W	ATER DEPT 509-625-7800	509-625-7800	509-625-7800	Does not report

3124 3144 3154 204 3216 3314 3328	3408 3428 3528	3622 3708 3728
3111 3141 3157 3203 3223 3323	3411 3427 2924 3525	2919 2921 3623 3707 3723 2925 <b>P 30TH AVP</b>
3128 3144 5204 3224 3314 3127 3145 5203 3223 3313 3329	3414     3514     3328       3411     3427     3916       3521     3521	3604     3624     3708     3724       3607     3703     3717
3 18 3 46 3105 3228 3308 324   3117 3141 3149 3217 3307 3323	3416 3508 3522   403 3507 3523	3606     3520     3710     3728       3607     3623     3723
3118 3144   3117 3143	3414     3428     3512       3409     3423     3518     3522	604 3618 3706 3728 3617 3707 3727.
3108 3120 3138 3152 202 3228 3312 3328   3115 3133 3153 207 3223 3307 3319	3402 3426 3518   342 3509 3523	3604 3628 3724   3603 3623 3711 3727   P 34TH AVE 3727
	3402 3426 3518	604     3628     3724       8503     3623     3711     3727
3115 3133 3153 3207 3223 3307 3319   3108 3144 3152 4204 3218 3304 3328	3402 3426 3518 342 3309 3523 E 34TH-35TH ALY	604 3628 3724   8603 3623 3711 3727   93614 3704 3726   3607 3709

5000	
From:	Proszek, Tyler <tyler.proszek@avistacorp.com></tyler.proszek@avistacorp.com>
Sent:	Monday, July 25, 2022 1:02 PM
To:	scot@mlnorthwest.com
Cc:	Schultz, Brian
Subject:	3423 E 33rd Ave Spokane Mislocate
•	

Scot,

scot

Thank you for your time to talk today about the locating issue on 33<sup>rd</sup> Ave in Spokane last Friday (7/22). As I said in our phone call, there was a locating issue that resulted in locate marks being off 13ft due to locator error. Your crew was able to reach Jay Aragon with Avista when they had trouble potholing the gas service. Jay found the line and had ELM come back on site to confirm the marks to be inaccurate and agreed that the new location was correct. ELM also double checked the remainder of the dig area to make sure there were no additional errors. ELM management spoke with the original locator and performed retraining, stressing the importance of following proper locating procedures and committed to doing follow-up audits on the technician. Please let me know if I can be of help with this matter going forward.

Thank you.

**Tyler Proszek**, Damage Prevention Program Administrator 2406 N Dollar Rd MSC-6, Spokane Valley, WA, 99212 **Office** 509.495.8688 | **Cell** 509.290.3544





CONFIDENTIALITY NOTICE: The contents of this email message and any attachments are intended solely for the addressee(s) and may contain confidential and/or privileged information and may be legally protected from disclosure. If you are not the intended recipient of this message or an agent of the intended recipient, or if this message has been addressed to you in error, please immediately alert the sender by reply email and then delete this message and any attachments.

## Daily Report - Ray & 31st, 33rd - SPK2201DMKB (22-U353) Date: 7/21/2022

### Diary

Brandon Howell (113)

## Ģ

8:13 AM, Clear, 71°F, 41.98% Humidity, 5.4 MPH Winds

Note	Transaction Tags
Mob to job have. Have Brandon start vaccing down to pot holes. Open cut rd	
to set up drill. Took awhile to get asphalt out of ground to start drilling. Called	
up ELM for a mis located gas line we potholed. The mark was 10' off locate	
Ray from ELM came out and located it right than had him double check other	
locates on rest of job. Had Brandon and Jacob start coring out more	
potholes toward Ray until we free up some top hats. Drilled out 280' until we	

can pot hole the rest of the shot. Clean up make safe for weekend.



No notes found



No notes found











No notes found



No notes found



No notes found

No notes found

No notes found

No notes found gas was here



No notes found

gas not here,
core hole, vac truck,
gravel utilibond, and
restore core hole 3
hours labor



Å

Z

No notes found

Form PDF

No notes found

2

Gas line not located in the tolerance zone. It was approx 10' away.

