Optional Field Data Collection Form for Liquid Inspection

Page:	1	of	1	
-------	---	----	---	--

NOTES - FIELD INSPECTION

Company:	McChord Pipeline	Date(s): May 17-19, 2010
Unit:	OPID # 31049	

	Line Size, in.	Field Readings				- -
Line & Location		CP, volts		Rectifier		
		P/S	Casing	Volts	Amps	Remarks
Sta. 0+00 McChord Tanks	6	-1.080				Good coating with some atmospheric corrosion at pipe supports.
Sta. 21+97 N. Side Creek	6	-1.822				
Sta. 212+50 114 th & Park Ave	6	-1.968	-0.271			
93 rd St. & 24 th Ave.	6			15.0	2.3	Tap Settings: Coarse 1, Fine 3 Output data is typical for the past three years.
Main Line Valve South of Pacific Hwy						Valve is located below grade in a vault with secured manhole lid.
Piping at US Oil Pump Station						Pipe sections were replaced and need coating to protect from atmospheric corrosion.
			· · · · · ·			
	-					