

APPENDIX 2

Example of Leak Work Order
Leak Work Order 10
(Leak L9604014)

Madrone Park Leak Work Order

Date Printed: 03/19/2002

SECTION 1:	Project	L9604014 10	Complete on or Before	04/01/2002	AREA:	211
House 1/2 Street					PLAT MAP:	189074
3339 E FORD PL						
Originally Reported Date: 09/19/1996			Source: Outside Consultant			

SECTION 2 - LEAKAGE: Grade ~~B2~~ Repair or Re-evaluation

Leak History: CP Area? Repl. Planned? Original Leak Grade C

Leak Origin: N-Service Survey - NonCP: Bus & NonBus. Dist. Method Detected A-Instrument

Prev. Loc/Cgi: 10% GAS AT NW-CURB OPP EBL LSCHRE 10/11/01

MAR 28 2002
CORLA ANN SHEA

Field Response Data: ! Grade Found 0 ! Grade Left: 0 Excavation Only:

! Response Type: J2 >Pipe: >Material _____ >Size _____

! Response Co: C >Facility: >Type _____ >Yr Inst _____

! Responder Name: B. GORDON >Below Grade? Yes No CP Reads _____ psp

! Arrived Date: 3/27/02 !Time 11:50 * >Leak: >Component _____ >Cause _____

! Finished Date: 3/27/02 !Time 12:00 * Recheck? Yes No Date ____/____/____

Repair Type: _____ #Qty _____ Followup? Yes No Date ____/____/____

+ Pressure Test By: _____ +Date ____/____/____ +Hrs ____ Min ____ at ____ psi - +Type _____

+ - Required for Response Type R(Repair) & Repair Type D(Replace)

! Loc Cgi Reads Remaining / Comments: 0% GAS or LEL READS FOUND AT NW CURB OPP EBL

! - Required for all Work Orders. * - Use 24 Hour Clock # - Required for Response Type R(Repair). > - Required for all Repair Type A-G&S.

