



UTILITIES AND TRANSPORTATION
COMMISSION

Assignment Report Motor Carrier Safety

New Entrant? Yes No Was a CR conducted between 6-18 months after the permit was issued? Yes No

1. Investigator(s): Mathew Perkinson 2. Assignment No.: 116095

3. Current Date: 6/10/2016 4. Date of Activity: 6/10/2016

5. Carrier Name: Centrum d/b/a Centrum Foundation

6. Company ID: 17656 7. Industry Code: 232 8. USDOT #: 2892865

9. Carrier is: Intrastate Yes No Intra and Interstate

10. Destination Check

11. Compliance Review

12. Part B Violations

13. Vehicle Inspection Data

	Van 9-15	Carrier Type	Carrier Type	Carrier Type	Carrier Type	Carrier Type	Carrier Type	Carrier Type
Inspections	5							
Defective Vehicles	5							
OOS Vehicles	0							
Level	7							

14. Vehicle Inspection Violations

	VAN 9-15	Vehicle Type	Vehicle Type	Vehicle Type	Vehicle Type	Vehicle Type
Comments:						
Emergency Equipment, Exits	No fire extinguisher or Reflectors/Triangles (all five vehicles)					
Other	No driveshaft protection (all five vehicles)					
Violation Type						

15. Driver Inspection Violations

16. Relevant Carrier History:

Carrier is a new entrant planning to charge a small fee to transport its customers from ferry terminals to its facility in Port Angeles. All vehicles are non-CDL.

Assignment Report
Motor Carrier Safety

17. Findings:

Five Level 7 inspections were performed. All of the vehicles are 12 passenger 2015 Nissan vans. It was determined that each vehicle did not have emergency equipment or driveshaft protection. No CVSA decals were issued per level 7 guidelines. The inspections conformed to level 5 CVSA inspection standards. CFR Parts 382, 383, 387, 390, 391, 392, 393, 395, and 396 were discussed in detail. Centrum was provided a paper and USB copy of the commission's safety guide.

18. Recommended Safety Action: Yes No

19. Is this carrier considered a high risk carrier as a result of this activity? Yes No

- Carrier accident ratio is higher than aggregate ratio.
- Carrier had an out-of-service ratio 25% higher at the last vehicle inspection.
- Carrier had a defect ratio 75% or higher at the last vehicle inspection.
- Carrier received more than one conditional or unsatisfactory safety investigation rating in more than one of the last four safety investigations (or less than four if four are not completed).
- Other (please explain):

20. Additional Comments:

Please close and issue authority.

Investigator's Signature: Mathew Perkinson Date: 6/10/2016

OFFICE USE ONLY

Initial Review By: John Gault Date: 6/14/16

Initial Reviewer's Recommendation: Agree with recommendation to forward to licensing. Close & file

Final Review By: DPRAU Date: 6/15/16

Final Reviewer's Recommendation: Agree with recommendation. Close & file.

Forward to licensing - allow to issue permit.

Assignment Report
Motor Carrier Safety

Internal Processing	
Date Closed:	6/15/16 By: L. Ehardt
Company Name:	Centrum d/b/a Centrum Foundation
Assignment #:	116095 Staff Assigned: Perkinson