

Assignment Report Motor Carrier Safety

| Upload? Yes No - Reason for Not Uplo | ading:Intrastate |
|--|--|
| 1. Investigator(s): Rick Smith | 2. Assignment No.:112134 |
| 3. Current Date: 6/25/2013 | 4. Date of Activity: <u>-6/21/2013</u> |
| 5. Carrier Name: JJ Limousine Services Inc. | |
| 6. Permit: Pending 7. New Entrant da | ate of authority: |
| 8. MOTCAR No.: 10. Industry Code: | 9. Carrier is: |
| 11. USDOT No.: 2060747 | 12. MC No.: 000000 |
| 13. Destination Check Copy of the Destination Check Safety Plan Number of Buses/Motor Coaches inspected: 7- Number of vehicle inspections: Level 1 Any special emphasis placed on the destination Describe Special Emphasis What might we do differently to increase our s | 15 passenger 16+ passenger Level 2 Level 5 Level 5 Level 5 |
| 14. Safety Complaint | |
| Attach a copy of the Individual Safety Com What activity did staff complete for this safety Compliance review Technical assistance Number of vehicle inspections: Level 1 Unannounced terminal visit Other (please explain): | complaint: |
| 15. New Entrant – Charter, Auto Transportat. | ion |
| Is this carrier referred by FMCSA, operating in Is this carrier based in another state, requesting Is this carrier based in Washington, requesting | tra and interstate: |

for-

| 16. New Entrant-HHG |
|---|
| ■ Is this carrier referred by FMCSA, operating intra and interstate: Yes No |
| ■ Is this carrier based in another state, requesting intrastate authority: ☐ Yes ☐ No |
| ■ Is this carrier based in Washington, requesting intrastate authority: ☐ Yes ☐ No |
| • Did staff complete the following: |
| ♦ Inspect all vehicles between three and eighteen months? |
| Number of vehicle inspections: Level 1 Level 2 Level 5 |
| ♦ Conduct a SI/SA between three and eighteen months? ☐ Yes ☐ No ☐ SI ☐ SA |
| ♦ Conduct technical assistance within three months? |
| |
| |
| 17. CSA Investigation |
| Full Investigation |
| Focused Investigation |
| Basic is for: Passenger Carrier HHG Carrier Solid Waste Carrier |
| Basic Threshold Percentile is; |
| Unsafe Driving % |
| Fatigued Driving (HOS)% |
| Crash % |
| Driver Fitness% |
| Drug/Alcohol % |
| Vehicle Maintenance % |
| Venicle Mannenance |
| |
| 18. Individual Safety Plan Only: |
| |
| What activity did staff complete for this safety complaint? |
| Attach a copy of the Individual Carrier Safety Plan. |
| Safety Investigation |
| Technical assistance |
| Number of vehicle inspections: Level 1 Level 2 Level 5 |
| Unannounced terminal visit |
| U Other (please explain): |
| |
| |
| |
| 19. Safety Investigation: |
| Safety Audit: |
| ■ SI Rating: ☐ Satisfactory ☐ Unsatisfactory ☐ Conditional |
| ■ SA Rating: ☐ Pass ☐ Fail |
| Number of vehicles operated: |
| Number of drivers operated: |
| Total miles for prior year: |
| Recordable accidents for prior year: |
| Accident Ratio: n/a |

Revised 9-16-2011 2

20. Part B Violations:

| Part | Violations | Part | Violations | Part | Violations |
|--------|------------|------|------------|------|------------|
| 382/40 | | 383 | , | 387 | |
| 390 | | 391 | | 392 | |
| 395 | | 396 | | 397 | |
| • | | | | | |

| | MC | MB 1-15 | MB 16+ | SB 1-8 | SB 9-15 | SB 16+ | VAN 1-8 | VAN 9-15 | TRK | TT | TRA |
|-----------------------|----|------------|-----------|--------|---------|--------|---------|----------|-----|----|-----|
| Inspections | | 2 | | | | | | | | | |
| Defective Vehicles | | 0 | | | | | | | | | |
| OOS Vehicles | | 0 | | | | | | | | | |
| Level | | 5 | | | | | | | | | |

| | MC | MB 1-15 | MB 16+ | SB 1-8 | SB 9-15 | SB 16+ | VAN 1-8 | VAN 9-15 | TRK | TT | TRA |
|---------------------------|--|------------|-----------|--------|---------|----------|---------|--------------|--|--------------|----------|
| Brakes | IVIC | 1-13 | 10. | 3D 1-0 | | 35 101 | VALUE-0 | 7-13 | IKK | | IKA |
| Steering | | | | | | | | + | | · · · · · · | |
| Lights | | | | | | | | † | | | |
| Tires, wheels, rims | | | | | | | | | - | | |
| Horn | | Ì | | | | | | | | | |
| Windshield and Wipers | | | | | | | | | | | |
| Mirrors | | | | | | | 1 | | | | |
| Emergency Equip, Exits | | | | | | | | | | | |
| Coupling Devices | | | | | | | | | | | |
| Frame | | - | | | | | | | | | |
| Suspension | | | | | | | | † | 1 | | |
| Exhaust | | | | | | <u> </u> | | <u> </u> | | | |
| Other | | | | | | | | | 1 | | |
| Comment: | | | 1 | | 1 | | | | | I | <u> </u> |

| 23. Direct inspection violation | tion Violations: |
|-----------------------------------|------------------|
|-----------------------------------|------------------|

| Medical Card | Medical Waiver | Hours of Service | Drivers License |
|--------------|----------------|------------------|-----------------|
| - | | | |
| Comment: | | | |

Revised 9-16-2011 3

24. **Relevant Carrier History:** This carrier is requesting intrastate charter-excursion authority and has not had a prior review.

25. **Findings:** Two buses, a 38 passenger and 22 passenger vehicles for this carrier were offered and fully inspected. Both passed a CVSA level-5 inspection with no safety defects discovered.

This carrier in 2011 filed for authority and received a vehicle inspection. A safety presentation was provided at that time to the company owner and president Jeet Sidhu. The authority and application was later cancelled by UTC.

UTC had since that date received information this carrier was providing for-hire charter services with one of their vehicles involved in a crash. UTC contacted the carrier and advised them of the need to resubmit an authority application. Prior to a personal visit with the carrier on 6/21/2013, I was briefed by a UTC compliance investigator and received information the carrier had been using an internet web site to advertise several vehicles for-hire charter service, yet only two were currently listed in the carrier's new authority application.

I met with company President Jeet Sidhu at the carrier's terminal on 6/21/2013 and showed him the web site advertisement asking for an explanation. Mr. Sidhu said he had in the past outsourced some new business to a person he knew as Victor, but could not recall this Victors business name. He also leased Victor some of his personal vehicles, but has recently sold these vehicles to unknown buyers. He has also stopped the practice of outsourcing after selling the vehicles showing on the web page. Two limousines are still in his offered business services, but these vehicles are only limousines with no outside advertising showing on the vehicle and holding under 8 passengers. These particular vehicles are regulated by the department of licensing and not UTC.

The vehicles Mr. Sidhu has recently sold; 7 passenger town car, 14 passenger Van, 30 passenger bus, 26 passenger bus, 26 passenger bus, 20 passenger bus, and a 20 passenger bus. He still owns a 14 passenger Lincoln town car as a limousine only. He could not provide more detailed information on each of these vehicles during my visit.

The two vehicles Mr. Sidhu offered for inspection was a 38 passenger 2007 Chevy bus and a 22 passenger 2005 Hummer Bus. Both vehicles received a level 5 CVSA inspection and passed with no defects discovered. Please inspection documents attached with this report.

Providing safety training to Mr. Sidhu, he recalled my earlier training in 2011 and was very knowledgeable and specific while reciting appropriate regulatory law as applied to his business. He currently has employed the service of Alliance One in Bellevue as his drug and alcohol consortium due to the size of his vehicle requiring CDL drivers. Although he did not have his insurance document with him at the bus inspection site a short distance from his office. He told me he had current insurance on file in the amount of \$5,000.000 CSL limit. This is the minimum amount the carrier is required to carry for a vehicle carrying more than 15 passengers.

A UTC safety manual was provided for further study and future reference.

| 26. Recommended Action: | |
|--|--|
| No further action. | |
| Notify the company in writing of the finding | s by providing a copy of the safety investigation, |
| vehicle inspection report, safety audit or other | her similar document. |
| | plan in response to the 15-day letter requirement. |
| Recheck – Safety Investigation (Date: |) |
| Revisit to recheck a specific issue (Date: | |
| Send the company a compliance letter. Requi | |
| Issue administrative penalties in the amount of | |
| Issue a complaint. | |
| Stop company operations. | |
| | |
| 27. Is this carrier considered a high risk carrier as | a result of this activity? |
| Carrier accident ratio is higher than aggreg | |
| Carrier had an out-of-service ratio 25% or | higher at the last vehicle inspection. |
| Carrier had a defect ratio 75% or higher at | the last vehicle inspection. |
| Carrier received more than one conditional | or unsatisfactory safety investigation rating in |
| more than one of the last four safety investigati | ons (or less than four if four are not completed). |
| Other (please explain): | |
| | |
| | |
| 28. Additional Comments: Carrier is seemingly well | managed with appropriately maintained vehicles to |
| provide the passenger services as being requested. I red | commend authority be issued. |
| | |
| | |
| | Mike, Copy at report to Tina please. Betty already has the compliance — |
| Investigator's Signature: Richard Smith | Mike, |
| | & resert to |
| Initial Review By: | Copa and I B Hy - |
| | Two steast. Derry |
| Reviewer's Recommendation: | 1 Le constace _ |
| | a ready has The |
| | |
| 1 | file. |
| Final Pavian Pau | 4 (|
| Final Review By: Fra II | Thanks |
| Davis-1-12 | Thenks |
| Reviewer's Recommendation: | Contract Con |
| 1 - | |
| Agrie with reconnectations | |
| | |
| ok to issue authority. | |
| gre ecopo issue aumenting. | |

| OFFICE USE ONLY | |
|-------------------------------|----------|
| Date Closed: By: Mike Dollson | |
| Company Name: II Lin osine | <u>-</u> |
| Assignment #: (3)4 | _ |
| Staff Assigned: | _ |
| | |

| 26. Recommended Action: | , |
|---|--|
| No further action. | |
| Notify the company in writing of the findings | by providing a copy of the safety investigation, |
| vehicle inspection report, safety audit or other | |
| | plan in response to the 15-day letter requirement. |
| Recheck – Safety Investigation (Date: |) |
| Revisit to recheck a specific issue (Date: | |
| Send the company a compliance letter. Require | |
| Issue administrative penalties in the amount of | |
| Issue a complaint. | . Ψ |
| Stop company operations. | |
| Stop company operations. | |
| 27 In this courier considered a high wish courier on a | morally of this patients. |
| 27. Is this carrier considered a high risk carrier as a | <u> </u> |
| Carrier accident ratio is higher than aggregate | |
| Carrier had an out-of-service ratio 25% or hi | |
| Carrier had a defect ratio 75% or higher at the | |
| | or unsatisfactory safety investigation rating in |
| more than one of the last four safety investigation | |
| Other (please explain): | |
| | |
| | |
| 28. Additional Comments: Carrier is seemingly well n | |
| provide the passenger services as being requested. I reco | ommend authority be issued. |
| | |
| | |
| | |
| Investigator's Signature: Richard Smith | |
| | |
| Initial Review By: | Date: |
| | |
| Reviewer's Recommendation: | |
| | |
| | |
| | |
| 2 = 1 | 1 1 |
| Final Review By: Trall | Date: 6/25/13 |
| | |
| Reviewer's Recommendation: | |
| 100 TOWN OF B 10000 IMMORAL MOIN | |
| 1/200 | |
| Hyprie with recommendations | |
| | |
| XX OK to issue authority. | |
| ye come winer ing. | |