WUTC DOCKET: U-180680 EXHIBIT: DTA-16 ADMIT I W/D REJECT E Exhibit DTA-16 Docket U-180680

Exhibit DTA-16

Picture Diagram of Anderson Landing Incident

TESTIMONY OF

D. Timothy Arnold

In Opposition to the Multiparty Settlement Stipulation on Behalf of IBEW 77

site for some background. The maple at the end of the bridge is the one that caused the damage, it all three wire groups 117' to the east of the trans. pole. The primary broke leaving a 60 to 70 foot abandoned transformer, a down guy that splits the angle, and is about 1.5 feet out of plumb to the green , and the com is the black. The pole to the West is a 45' class 5 BAXCO 1957 set 6'4" has an off of it, it is approximately 3-4 feet out of plumb to the south /south west. I used photgraphs from the East. The primary was hanging energized off this pole approximately a foot off the earth. The breaking The pole to the east is an angle pole on a long span with a guy and an underground riser remnant to the west still energized. The neutral and com were forced to the earth neither one neutral in the primary position is approx. 37' off the earth, the com approx 26'. The tree went through fell at a 45 degree angle to the conductors and is approximately 115 feet in length. have used a red and yellow dotted line to represent the energized 7200 volt line, the neutral red and

Exhibit DTA-16 Docket U-180680 Page 1

0

electrocuted. I then returned to Asplundh, and did an opening conference with Asplundh, PSE Ryan Blood, Larry Mort, WAVE Broadband, Ray and Daryn and brief interview with the Asplundh crew. time and then went and talked to the WAVE supervisors who were collecting information on their employee Lance Piatt who was Blood PSE Corporate Safey their corporate attorney from Seattle were huddled in a group discussing the incident. I introduced myself and the attorney cleared, tagged and they had Francis Floyd asked me to hold off on opening untill he had more time to discuss some details. I said I would give them a little This contact incident hapen

installed grounds, the line is fused 65T. The Asplundh crew along with several supervisors and

contact. The Asplundh trimmer heard the arcing and saw him on fire, the foreman called 911 and then they used non conductive pruning poles to pull the were assessing the job a Wave employee came by to energized primary all the way to the mud. The energized #4acsr did break, and a section of line approximately 60 feet from the double dead end pole to left arm was amputated at the bicep, he was on a ventilator but appeared to be in stable condition. able to walk the injured to the tree, put him on a pack board and get him to the ambulance. He was air flighted to Harborview in Seattle, at last report the man out of the area. Emergency response was then at the site but would not cross the large downed maple as the line was still energized. They were their work zone, he left but came back, they again asked him to leave, which he did, but again he came back and then went to the pole, where he made the west, lay on the earth and burned, the cut out did not open. An Asplundh crew had been dispatched to remove a tree from the com. cable, while they The incident: Sunday afternoon a maple tree had blown down and pulled the communication cable, the neutral which was in the primary position, and the assess their storm damage. The Asplundh crew asked the Wave employee to move his truck out of

