Olympic Water and Sewer, Inc

70 Breaker Lane Port Ludlow, WA 98365 (360) 437-2101

October 28, 2011

RE: Status Report, UW-110436

BACKGROUND

On March 24, 2011 the subject docket was approved by the Washington Utilities and Transportation Commission granting deferral of certain costs associated with drilling Well No. 17 and the investigation and remediation of soil contamination discovered while drilling.

The order requires Olympic Water and Sewer, Inc. (OWSI) to report the status of the investigation and remediation and associated costs. A detail of the deferred costs can be found in a companion Excel worksheet filed along with this response. **The total project costs to date are \$144,292**

The detailed background leading to this Petition can be found in Docket UW-101543.

CHRONOLOGY OF HYDROCARBON DISCOVERY AND ACTION STEPS

On April 21, 2009, after advancing to a 50' depth, the driller noticed a hydrocarbon odor coming from the boring. Drilling ceased and Jefferson County Health and Department of Ecology (Ecology) were immediately notified. The 50' depth is significant in that there is a confining layer at that location where perched groundwater sits.

Activities since the discovery:

- OWSI, through legal counsel, is working with a former property owner to share in the cost of site investigation and remediation.
- Port Ludlow Associates, OWSI's parent company, contacted our insurance carriers to investigate any potential existing coverage. No coverage for this type of an event has been identified.
- On September 2, 2009, Ecology informed us that the site had been added to their database of Confirmed or Suspected Contaminated Sites and assigned ID #62223345.
- On October 12, 2010 Ecology informed us of their intent to contract with Jefferson County Health to conduct a site hazard assessment of the site and OWSI worked cooperatively with Jefferson County during that process.
- OWSI contracted with a consulting environmental firm to conduct an evaluation of the extent of the contamination on the site. The Site Characterization is complete and the findings documented in Site Characterization Report, Olympic Water & Sewer, Inc Property, SLR International Corp (SLR), December 17, 2010.

Olympic Water and Sewer, Inc. UW-110436 October 28, 2011

SITE INVESTIGATION FINDINGS

The site characterization work consisted of installing four monitoring wells to a depth of approximately 50' (refer to attached map "Groundwater Monitoring Well Locations") and conducting soil sampling of the borings as well as sampling and analyzing the perched groundwater. The wells were initially attempted with a hollow-stem auger rig and were largely unsuccessful because of the presence of cobbles, with 37' being the deepest that the boring could be advanced. This necessitated mobilizing an air-rotary drill rig to bore to the target 50' depth.

The conclusions of this investigation were:

- The northerly gasoline UST area is the source of the hydrocarbon contaminated perched groundwater.
- There is widely varying vertical geology for a small site with confining layers occurring at different depths in the monitoring well borings.
- The gasoline did not migrate straight down to the perched groundwater zone, but rather took a path of both lateral and vertical movement.
- Monitoring well MW-1 is adjacent to the source and contains groundwater contamination above Model Toxic Control Act (MTCA) cleanup levels.
- Monitoring well MW-2 is approximately 55' southwest of MW-1 and contains groundwater contamination above MTCA cleanup levels.
- Monitoring well MW-3 is approximately 140' southwest of MW-1 and 40 feet south of the Well 17 boring. It showed no signs of contamination and appears to be beyond the southerly extent of the contamination.
- Monitoring well MW-4 is 65' north of MW-1 (between the source of contamination and Well 2) and showed no signs of contamination and appears to be beyond the northerly extent of the contamination.
- Additional VOC sampling at Well 2 in April 2009 and April 2010 confirms that it is still unaffected by the contamination.

ADDITIONAL INVESTIGATION

In April 2011 further investigation of the was undertaken as follows:

- In order to delineate the western extent of contamination and the potential for offsite migration of hydrocarbon contaminated groundwater, a gulley located in the western part of the site was investigated for evidence of seepage. A sample of the intermittent stream in the gully was analyzed. The results showed that the sample did not contain any analyte concentrations greater than Maximum Reportable Limits (MRL).
- To delineate the eastern extent of the gasoline-impacted perched groundwater, a groundwater monitoring well (designated MW-5) was drilled and installed at the east property line of the site. There was no evidence of petroleum hydrocarbons in the boring.

Olympic Water and Sewer, Inc. UW-110436 October 28, 2011

- Three soil borings were advanced and sampled to further delineate the area of gasoline-impacted soil near the garage building. These borings were also proposed to serve as withdrawal points for pilot-testing the effectiveness of Soil Vapor Extraction (SVE) as a remediation method. The day after installation of these wells, both of the points contained over 15 feet of groundwater. This indicated the discovery of an additional shallow perched water table that was not encountered in any of the previous numerous borings on the site. This made the points unsuitable for their intended use.
- The groundwater levels in the SVE points were monitored through the summer months for potential subsidence so that pilot-testing could proceed. No significant lowering of groundwater levels has been observed.

NEXT STEPS (REMAINING ISSUES TO BE RESOLVED)

We are currently arranging a meeting between OWSI's consultant and the third-party consultant to assess and agree on an alternative pilot-test option. Our intent is to agree on an alternative, secure a cost-sharing agreement on the alternative, and conduct pilot-testing by the end of 2011, thus bringing closure to the investigation phase of the project. Whether or not this timeline can be realized depends on the outcome of the upcoming meeting.

PAYMENTS FROM THIRD-PARTIES

- OWSI has an agreement with a former property owner to cost-share certain investigation work on a 50/50 basis. This agreement applies only to the investigation of the source and extent of hydrocarbon investigation up to, and including pilot testing of a remediation alternative (yet to be performed). It does not include any costs related to the drilling of Well 17 or technical consultation provided by SLR directly to OWSI. Decisions on attempts at further cost recovery will not be made until the investigation phase of the project is completed.
- OWSI, through its parent company, Port Ludlow Associates, contacted insurance carriers for Port Ludlow Associates to investigate any potential existing coverage. No coverage for this type of an event has been identified.

Larry Smith President

Olympic Water and Sewer, Inc.

OLYMPIC WATER AND SEWER, INC WELL 17 AND FUEL CONTAMENATION COST TRACKING UW-110436

Sammary of Worksheet by Task:
Well No. 17 Drilling
Legal
Initial Site Characterization
Additional Investigation
Technical Support
Total

32,794 25,840 39,432 37,657 8,569

Total 2011 Investigation Project Total to Date	186 4-0502-020 Investigation 186 4-0500-0500 Investigation	Acci. Cl. Acci. Class No. Cl. Acci. Class No. Cl. Acci. Class No. Cl. Acci. Class No. Cl. Drilling 186 4.0520.6055 Well No. 17 Drilling Total Well No. 17 Drilling Costs 136 4.0520.6000 Investigation 136 4.0520.6200 Investigation 137 4.0520.6200 Investigation 138 4.0520.6200 Investigation
	SIR Counting Canadia Law Group Canadia Law Goop SIR Counting	Vendor Vendor Use HDR, R&W Cascadia Law Geop Ca
	Technical Support Legal Revisional Investigation Additional Investigation Technical Support Legal Legal	Description Well 17 Cerniture Conts Well 17 Delling Conts Well 17 Delling Conts Well 17 Delling Conts Well 17 Delling Conts Legal Le
53,966,04 144,291.95	1,023.25 250.00 337.50 3,083.23 71,250 2,075.00 1,078.25 1,038.27 1,058.25 1,1576.25 1	
53,966.04 144,291.95	1,032.25 250.00 337.50 3,083.23 712.50 2,075.00 1,088.75 1,088.75 1,088.75 1,268.78 7,268.78 1,158.75 1,158.75 1,158.75 1,158.75 1,158.75 1,158.75 1,158.75 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25 1,168.25	Carl Basis 1, 14,955.00 17,799.00 17,799.00 10,223.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 10,627.75 11,725 11,725 11,725 11,725 11,525
	2011 2011 3 2011 3 2011 3 2011 3 2011 3 2011 3 2011 4 2011 5 2011 7 2011 7 2011 9 2011 9 2011	Acquired Wr. Month Wr. Mon
	200 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Recent R
	7 7.93 7 7.93 7 2.50 7 2.50 7 8.50 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Monthly Interest Ror 2009 \$1 11521 813.48 \$1 137.94 1,105.54 \$254.15 1,917.02 \$4 79.23 \$5 1.21 \$6 6.10 \$6 6.20 \$6 5.23 \$6 5.23 \$6 5.23 \$6 5.23 \$7 12.15 \$6 6.40 \$7 12.25 \$7 12.25 \$8 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 13.73 \$9 1.21 \$9 20.87
		2,672,04 2,672,
ļ		## ACC. Hearnst ## 12-23-1-10 2,208.00 2,758.85 4,962.86 950.81 662.26 104.86 104.86 204.96 204.96 204.86 204.96 204.86 204.96 204.86 204.96 204.86 204.96 204.86 204.96 204.86 2
1,961.88 8,262.11	7,93 5,81 7,85 71,85 71,85 71,85 71,86 72,85 73,86 74,86 74,	Rev 2611 Thurs 2-30 1,045-90 1,241-48 2,267-38 2,267-38 713.11 713.11 713.11 74.55 11.77 54.93 27.46 47.08 78.47 58.85 117.58
1,961.88 13,979.15	7,93 5,81 7,85 71,69 16,57 64,33 33,44 32,20 70,60 70,	Ap. Junes i L. 1653 92 L. 1,653 92 L. 1,553 92 L. 1,553 92 L. 1,553 93 L. 1,553 93 L. 1,553 93 L. 1,553 93 L. 1,553 94 L. 1,55
55,927,92 158,271.10	1,031.18 255.81 255.81 345.35 3,154.95 3,154.95 3,154.95 1,1070.95 1,1070.95 1,1070.95 1,1070.95 1,1070.95 1,1070.95 2,822.66 2,457.45 7,862.63 274.26 2,818.74 772.16 914.64 1,772.51	Total Cost + line rest 17,435,44 20,695,79 38,131,22 11,887,57 11,095,56 11,095,56 11,095,56 11,095,56 11,095,56 11,095,56 11,095,56 11,095,98 11,095,98 12,041,06 12,965,98 12,041,06 14,865,98 12,041,06 14,865,98 14,965,98 14,965,98 15,865,98 16
(19,574.77) (55,394.88)		Tax Benefit (3.5%) (6.102.40) (7.245.53) (12.455.53) (4.150.63) (4.150.63) (4.150.63) (4.250.53) (2.650.63) (4.250.53) (2.650.63) (4.150.63) (4.150.63) (4.150.73) (2.150.73) (2.150.73) (2.150.73) (3.150.73) (4

Page 1