

08/31/2023 11:54:57
Terminal ID No.: 75822232



Credit Sale

Transaction #: 5
Card Type: Visa
Account: *****0378
Entry: Chip
Amount: USD\$2,611.47
Ref. Number: 324318173389
Global UID: 0821618162202308311154579959
Auth. Code: 031718
Batch #: 586
Response: APPROVAL 031718
Mode: Issuer
AID: A0000000031010 -4041
APPLAB: VISA CREDIT -4041
CUSTOMER COPY

Movers
th 2Nd Ave
VA 98203
-4041
-4041
ricammoversllc.com

Fleet Service
8215 Broadway
Everett, WA 98203
425-610-4662
Fax: 425-353-4799
Service@FleetService.com
www.FleetService.com

Plate WA C59276Z
Description 2005 International 4300 Base L6 7.6L 466CID
VIN 1HTMMAAL15H167600
Odometer 129,357

Invoice Date 8/31/2023 11:55 AM

Inspection

Diagnoses - Air Brake System

Customer states loses air pressure when off and compressor runs constant
Labor
Technician: Mitch Huffine / Service Advisor: Matt Adkison

\$0.00 *S

-- Technician Notes from AutoVitals SmartFlow --

Air system will not reach or hold proper pressure, found air leak from park brake valve. small hairline fracture on valve body and intermittently when above 110 PSI but has a larger leak at park brake release handle. Tested air compressor and found compressor to be getting weak. Drained air tanks to check for presence of water found excessive presence of water and oil in tank. After three air up and drain Cycles tanks are finally clear enough. At this time recommend replacement of air compressor assembly, air governor assembly, park brake release valve/ Dash valve and perform Air Dryer service including time to remove air dryer assembly and clean oil residue out if necessary. Once repair is performed retest system for proper operation

Sub \$0.00

***FS Courtesy Inspection**

Peace of Mind inspection report
Technician: Brandon Radcliff / Service Advisor: Matt Adkison

\$0.00 *S

Sub \$0.00

Service

Air Compressor, Governor, Dash Valve

Install Compressor, Dash Valve, and Governor
Technician: Damon Cruz / Service Advisor: Matt Adkison

\$1,011.00 *S

Governor	1 Unit	\$146.58 / Unit	\$146.58 ES
Air Compressor	1 Unit	\$1,509.68 / Unit	\$1,509.68 ES
Dash valve	1 Unit	\$265.39 / Unit	\$265.39 ES
Freight - Ground	1 Unit	\$139.77 / Unit	\$139.77 *S
		Sub	\$3,072.42

Brake System Repairs

Visually inspect brake lining without removing wheels, test drive and determine if squeak is an issue. Inspected and found that the Right Rear Slack adjuster is broken, the front drums are warped, and the Brake Relay Valve is operating incorrectly. Brake linings are in good condition. Replaced front Brake drums, Replaced Right Rear Slack Adjuster, and replaced Brake Relay Valve. Road test OK, Brakes are operating normally at this time.

Replace warped front brake drums \$143.60 *S

Technician: Damon Cruz / Service Advisor: Matt Adkison

Brake Drum Steer Axle 2 Unit \$413.72 / Unit \$827.44 ES

Replace Right Rear Slack Adjuster \$269.25 *S

Technician: Damon Cruz / Service Advisor: Matt Adkison

Slack Adjuster - RR 1 Unit \$228.89 / Unit \$228.89 ES