

TR-121921
BNSF Railway Company's Response to Penalty Assessment
and Request for Hearing

EXHIBIT A

DEFECT(S) TO BE CORRECTED

USDOT #:	084915M		
Street/Road:	Massey Rd	RCW/WAC:	WAC 480-62-225
Railroad Milepost:	119.34	Inspection Date:	11/26/2012
Defect Type:	Crossing surface	Notification Date:	12/21/2012
Defect Detail: The plane of the crossing is not level with the roadway, resulting in a rough crossing surface.			
Defect Comments: Drop off of asphalt about 2 inches on east side, more pronounced through west side. This may require coordination with the road authority.			

Responsible party to enter either date:

Correction was completed on:

(Date)

Correction will be completed by:

(Date)