

TRIANGLE CHARTER SERVICE LLC

U.S. DOT#: 1767297 Address: 408 E RIO VISTA AVENUE BURLINGTON, WA 98233 Number of Vehicles: 7 Number of Drivers: 6 Number of Inspections: 9

Safety Rating & OOS

Rates (As of 09/01/2015 updated daily from <u>SAFER</u>)

SATISFACTORY (Rating Date: 02/20/2015)

Out of Service Rates

Туре	00S %	National Avg %
Vehicle	12.5	20.7
Driver	0.0	5.5
Hazmat		4.5

Licensing and Insurance

(As of 09/01/2015 updated hourly from L&I)

Active For-Hire Authority							
Туре	Yes/No MC#/MX#						
Property	No						
Passenger	No						
Household Goods	No						
Broker	No						

U.S. DOT# 1767297 has no current for-hire operating authority with FMCSA.



Denotes this carrier exceeds the FMCSA intervention <u>threshold</u> relative to its safety event grouping based upon roadside data and/or has been cited with one or more serious violations within the past 12 months during an investigation. Therefore, this carrier may be prioritized for an intervention action and roadside inspection.

BASIC: Vehicle Maintenance



On-Road Performance

Measure: 7.26 **?** Percentile: 67%

Scale 0 to 100; 0 indicates the best safety performance.




Safety Measurement System - Vehicle Maint. BASIC (U.S. DOT# 1767297)

67% of motor carriers in the same safety event group have better on-road performance than this motor carrier.

Investigation Results


No Serious Violations Discovered



	Feb 20 2015	Mar 27 2015	Apr 24 2015	May 22 2015	Jun 19 2015	Jul 24 2015
Status	Active	Active	Active	Active	Active	Active
BASIC Trends Version	3.0.2	3.0.2	3.0.2	3.0.2	3.0.2	3.0.2
Overall Performance						
On-Road Performance	Less than 5 vehicle inspections with violations	66%	67%			
Investigation Results						
On-Road Performance Detail						
Measure	8.40	8.40	8.40	8.40	7.26	7.26
Safety Event Group	5-10 relevant vehicle inspections	5-10 relevant vehicle inspections	5-10 relevant vehicle inspections			
Vehicle Inspections Inspections	5	5	5	5	8	8
with Vehicle						


https://ai.fmcsa.dot.gov/SMS/Carrier/1767297/BASIC/VehicleMaint.aspx?print=true

9/2/2015		Safety Measurement S	ystem - Vehicle Maint. BAS	IC (U.S. DOT# 1767297)		
Maint. Violations	4	4	4	4	6	6
without Vehicle Maint. Violations	1	1	1	1	2	2
Vehicle Maint. Violations	12	12	12	12	18	18



INSPECTION RESULTS

The graph below displays the number of inspections that the carrier has received for a selected period of time, with or without violations for this BASIC. <u>Expand</u> for more information.



VIOLATION SUMMARY

Vehicle Maint. Violations: 18

Violations	Description	#	# 00S	Violation Severity
		Violations	Violations	Weight
393.45(b)(2)	Failing to secure brake hose/tubing against mechanical damage	2	0	4
393.45(d)	Brake connections with leaks/constrictions	2	0	4
393.203	Cab/body parts requirements violations	1	0	2
393.207(a)	Axle positioning parts defective/missing	1	1	7
393.209(e)	Power steering violations	1	0	6
393.30	Improper battery installation	1	0	3
393.47(e)	Clamp/Roto-Chamber type brake(s) out of adjustment	1	0	4
202 F2/b)	Automatic brake adjuster CMV manufactured on or after	1	0	Δ
393.53(b)	10/20/1994 - air brake	T		4
202 (2(0)	No or inadequate bus emergency exit marking - Bus manufactured	1	0	1
393.62(e)	on or after 9/1/1973	T	0	Ţ
393.78	Windshield wipers inoperative/defective	1	0	1
393.83(d)	Improper exhaust - bus (diesel)	1	0	1
393.83(h)	Exhaust system not securely fastened	1	0	1
396.3A1B	Brakes (general)	1	0	4
396.3A1DSCBCenter Bearing (Carrier Bearing) Cracked / Loose / Broken / Missing			0	3
396.5(b)	Oil and/or grease leak	1	0	3
396.5B-HLIW	Hubs - Oil and/or Grease Leaking from hub - inner wheel	1	0	2

INSPECTION HISTORY

Vehicle Inspections: 8

0/2/2015			Safety	Measurement System -	Vehicle Maint. BA	SIC (U.S. DOT# 176	7297)			
	I	Report			Vehicle		Measure =			
							Sum of the Total Weight (TotW)			
							Sum of	the Time We	ight (TiW)	
							Severity	Time	Total	
<u>Inspectio</u>	on Date	Number	State	Plate Number	Plate State	Туре	Weight (SW)	Weight (TiW)	Weight (TotW)	
6/17/2	2015	WAU007000016	WA	C65632B	WA	Motor Coach	0	3	0	
6/14/2		WAW106002775	WA	C65634B	WA	Bus	9	3	27	
		B Brakes (general)					4			
Violation:) Oil and/or grease	leak				3			
Violation:		HLIW Hubs - Oil an		ease Leaking fror	n hub - inner v	vheel	2			
		m of Violation Weig	-				9			
6/14/2		WAW706005799	WA	C65633B	WA	Motor Coach	9	3	27	
Violation:		Windshield wipers i				Motor couch	1		21	
Violation:		e) Clamp/Roto-Cha	•		ofadiustment		4			
Violation:		b) Automatic brake			-		4			
violation.	air brak		aujust			110/20/1554	7			
		n of Violation Weig	ht => Ir	spection Severit	ww.eight (SW)		9			
9/10/2		WAW703002601	WA	AAC2824	WA WA	Motor Coach	0	2	0	
9/10/2		WAW703002602	WA	B43899S	WA	Motor Coach	19	2	38	
Violation:		(e) Power steering			VVA		6	Z	30	
Violation:		b)(2) Failing to secu			ainst mochan	ical damago	4			
Violation:		d) Brake connectio			-	ical ualliage	4			
Violation:		d) Improper exhaus			/15		1			
Violation:		h) Exhaust system					1			
Violation:		mproper battery ir					3			
violation.		m of Violation Weig			Woight (SW)		19			
9/10/2		WAW709002363	WA	ALJ4703	WA	Motor Coach	6	2	12	
		b)(2) Failing to secu					4	2	12	
Violation:		Cab/body parts re			gamst methan	Ical uallage	4			
violation.		m of Violation Weig	· ·		Woight (SW)		6			
9/10/2		WAW709002364			WA	Motor Coach	1	2	2	
Violation:		e) No or inadequat					1	Z	Z	
violation.		9/1/1973	e bus e	mergency exit ma	arking - Dus ma		T			
9/10/2		WAW703002603	WA	B40738W	WA	Motor Coach	16	2	32	
Violation:		DSCB Center Beari					3	Z	JZ	
violation:			ng (Car	ner Dearing) Cra	ckeu / Loose /	DIOKEII/	3			
Violation:	Missing		T narte	dofoctivo/missing			7 + 2 (OOS)			
Violation: 393.207(a) Axle positioning parts defective/missing (OOS) Violation: 393.45(d) Brake connections with leaks/constrictions						4				
Sum of Violation Weight => Inspection Severity Weight						16				
	Sui	0								
		Only the :	1000 m	ost recent inspec	tions are incl	uded in this prir	nt view.			
					Sum of me	easure weights	60	19	138	
			120		DEDEGE		Tot\// 11	20		
$\begin{array}{rcl} \text{PERFORMANCE} & \frac{\text{TotW}}{\text{TiW}} = \frac{138}{19} = 7.26 \end{array}$					PERFOR		_	$\frac{38}{2} = 7.2$	6	
MEASU	IRE LAS	r tiw [–]	19	1.20	MEASUR	RETHIS	TiW 1	9 - 1.2	0	
MONTH As of				MONTH	As of					
MONT					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					

*** The sum of all violation severity weights (violation weight + out-of-service) for this inspection has been capped at 30.

INVESTIGATION RESULTS

Vehicle Maint. Serious Violations: 0

This carrier has no Vehicle Maintenance serious violations to display.

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: 10/10/2014 (Compliance Review) Total Inspections: 9 Total Inspections without Violations used in SMS: 3 Total Inspections with Violations used in SMS: 6 Total Crashes* : 2

*Crashes listed represent a motor carrier's involvement in <u>reportable</u> <u>crashes</u>, regardless of the carrier's or driver's role in the crash. <u>Continue for details</u>.

Carrier Registration

Subject to Passenger Threshold

Penalties History

(Six years as of 09/01/2015 updated daily from <u>FMCSA</u>)

No penalties found

USE OF SMS DATA/INFORMATION

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A 🕰 symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <u>http://safer.fmCSA.dot.gov</u> and motor carrier licensing and insurance status are available at <u>http://li-public.fmCSA.dot.gov/</u>.