

# EXHIBIT LIST

Docket No. PG-041624

NUMBER	WITNESS	A/R	DATE	DESCRIPTION
1		A	9/28/05	Revised Settlement Agreement (9/22/05)
2		A	9/28/05	Revised Narrative Supporting Settlement Agreement
3				
4				
5				
6				
7				
8				
9				
10				
11	<b>Staff witness Graham E.C. Bell, Ph.D.</b>	A	9/28/05	Testimony filed July 21, 2005 (GECB-1T)
12		A	9/28/05	Graham Bell Curriculum Vitae (GECB-2)
13		A	9/28/05	Schematic of Corrosion Cell Illustrated by a Flashlight Battery (GECB-3)
14		A	9/28/05	Schematic of Galvanic Cathodic Protection System (GECB-4)
15		A	9/28/05	Schematic of Impressed Current Cathodic Protection System (GECB-5)
16		A	9/28/05	Overview of Photo of Leak Location taken by WUTC Staff September 3, 2004 (No. DCS 00052) (GECB-6)
17		A	9/28/05	Close-up of Photo of Leak Location taken by WUTC Staff September 3, 2004 (No. DCS 00051) (GECB-7)
18		A	9/28/05	Letter from Kevin C. Garrity, PE of CC Technologies to Charles Gordon, Gordon Murray Tilden LLP, dated February 28, 2005 (GECB-8)
19		A	9/28/05	CC Technologies "Laboratory-based Evaluation of Failed Service Line, Final Report, F4434-01G" dated February 18, 2005 (GECB-9)
20		A	9/28/05	Puget Sound Energy, "Puget Sound Energy Pipe Segment Integrity Study in the Vicinity of the Vasa Park Rectifier," dated June 21, 2005 (GECB-10)

# EXHIBIT LIST

Docket No. PG-041624

NUMBER	WITNESS	A/R	DATE	DESCRIPTION
21		A	9/28/05	PSE Response to WUTC Data Request No. 65 (32 pages) (GECB-11)
22		A	9/28/05	M.J. Schiff & Associates, Inc. Letter Report Entitled, "Soil Corrosivity Study, Bellevue Incident," to Kim West, WUTC, dated March 17, 2005 (GECB-12)
23		A	9/28/05	Letter From Kevin C. Garrity, PE of CC Technologies to Steven Secrist, Puget Sound Energy, "Puget Sound Energy, Summary of Findings – Soil Survey – Spirit Ridge Subdivision" (F44345-01G), dated June 15, 2005 (GECB-13)
24		A	9/28/05	CC Technologies, "Summary Report – Failed Service Line, Bellevue, Washington, Final Report, G4434-21G," Prepared for Gordon Murray Tilden LLP, dated February 28, 2005 (GECB-14)
25		A	9/28/05	M.J. Schiff & Associates, Inc., "Report Reviewing CC Technologies Laboratory-based Evaluation of Failed Service Line Final Report, F4434-01G (dated February 18, 2005)" authored by Graham E.C. Bell, Ph.D., P.E., dated July 18, 2005 (GECG-15)
26		A	9/28/05	Letter From Kevin C. Garrity, PE of CC Technologies to Steven Secrist, Puget Sound Energy, "Spirit Ridge – Summary of Field Inspection of Seventy-five (75) and Metallurgical Analysis of Six (6) Service Risers – Spirit Ridge Subdivision (F4434-01G)," dated June 15, 2005 (GECB-16)
27		A	9/28/05	M.J. Schiff & Associates, Inc., "Report Reviewing CC Technologies' "Spirit Ridge – Summary of Field Inspection of Seventy-five (75) and Metallurgical Analysis of Six (6) Service Risers – Spirit ridge Subdivision (F4434-01G) (GECG-17)
28		A	9/28/05	M.J. Schiff & Associates, Inc., "Report Reviewing Puget Sound Energy, Inc.'s "Puget Sound Energy Pipe Segment Integrity Study in the Vicinity of the Vasa Park Rectifier," dated June 21, 2005, authored by Graham E.C. Bell, PhD, PE and John French, PE, dated July 18, 2005 (GECG-18)
29-100				
Not Used				

# EXHIBIT LIST

Docket No. PG-041624

NUMBER	WITNESS	A/R	DATE	DESCRIPTION
101	<b>Staff Witness Kuan-Shi Chu</b>	A	9/28/05	Testimony filed July 21, 2005 (KSC-1T)
102		A	9/28/05	Bellevue Fire Department Documents: Fire Investigation Report and Incident Report (KSC-2)
103		A	9/28/05	Chronology (KSC-3)
104		A	9/28/05	Photographs of the Schmitz house after the explosion (KSC-4)
105		A	9/28/05	Summary of Staff visits to Bellevue Area Related to Investigation in Docket No. PG-041624 (KSC-5)
106		A	9/28/05	Photograph of service line in the area of the leak, showing the drain from the sink in the basement and the corrugated drain (KSC-6)
107		A	9/28/05	Photographs of the service line showing the two holes (KSC-7)
108		A	9/28/05	Map of the area designed to be served by the Vasa Park rectifier; the area affected by the cross-wiring condition; and the area covered by the coating survey (KSC-8)
109		A	9/28/05	Same as KCS-8, smaller area (KSC-9)
110		A	9/28/05	PSE's response to Staff Data Request No. 88 (KSC-10)
111		A	9/28/05	Photographs of the Vasa Park rectifier from across the street and close-up, with cover removed (KSC-11)
112		A	9/28/05	Photographs of the Vasa Park rectifier wiring terminals (KSC-12)
113		A	9/28/05	PSE's response to Staff Data Request No. 77 (KSC-13)
114		A	9/28/05	PSE's response to Staff Data Request No. 71 (KSC-14)
115		A	9/28/05	PSE's response to Staff Data Request No. 76 (KSC-15)
116		A	9/28/05	PSE's response to Staff Data Request No. 50 (KSC-16)
117		A	9/28/05	Analog Volt Meter (KSC-17)
118		A	9/28/05	PSE's response to Staff Data Request No. 85 (PSE-18)
119		A	9/28/05	Photograph of the Vasa Park rectifier showing how the cover is attached (KSC-19)
120 – 150 Not Used				

# EXHIBIT LIST

Docket No. PG-041624

NUMBER	WITNESS	A/R	DATE	DESCRIPTION
151	<b>Staff Witness</b> <b>Alan E. Rathbun</b>	A	9/28/05	Testimony filed July 21, 2005 (AER-1T)
152		A	9/28/05	List of Staff Recommendations for Repairs, Changes or Other Improvements PSE Should Make (AER-2)
153				
154				
155				
156				
157				
158				
159				
160				