

UTC Rail Safety Program - Assignment Details - For Assignment 2017.0113

Assigned To	Johnston, Bob (UTC)	Railroad	BNSF Railway Company
Assignment Type	Accident Investigation - Crossing	Rail Line	2
Assignment Date	2/7/2017	Main Branch	B
Assignment Due	4/17/2017		
Assignment Completed		Complaint	No
Inspection Count	1	Complaint Made By	
Accompanied By	Cal Stocking		

Description:

Grade crossing incident that resulted in one fatality and one injury at a private crossing north of Stanwood, railroad milepost 58.5. USDOT number 084720A, Bellingham Subdivision, on September 27, 2016.

Comments:

TR-141105

Detail

USDOT#	UTC #	Name	City (In Limits)	County	Last Inspection
084720A	2B58.55	Crossing - 31718 Pioneer Hwy-Private		Snohomish	2/24/2016

actual xing is
084723V