Case 16-055

PSE Complaint No. 11

Requestor:

Erika Hunter
Damage Prevention Program Manager
Puget Sound Energy
P.O. Box 97034, EST-11W
Bellevue, WA 98009-9734
Erika.Hunter@pse.com
425-456-2854

Alleged violator:

Ben Tanielian Employees: Kevin TT & E, LLC 26910 92nd Ave NW Stanwood, WA 98292

Date: 12/01/2016

Location: 16001 1st Ave NE, Duvall WA

Violation: Digging without locates; RCW 19.122.30 (1), (2) and (5); Failure to notify facility operator

about damage to an underground utility 19.122.050 (1); Removal of temporary marking for

underground utilities prior to its intended use 19.122.075

Summary:

On December 1st Damage Prevention Field Representative, Roger Arrington, observed excavation taking place at 16001 1st Ave NE, Duvall WA. TT & E LLC was conducting excavation for foundation work without having obtained locates in violation of RCW.19.122.30 (1), (2), (5). Roger stopped the work and the TT & E employee, Kevin, said he had contacted the owner, Benjamin Tanielian to confirm locates had been called for, however, www.managetickets.com show that no tickets had been called in for that address. Kevin said Ben had confirmed that they had not called for locates and was also told that there were no utilities on the lot. He also said that he was told by the developer that calling 811 was unnecessary because they had as-built drawings. Roger explained that this was incorrect and prior to any excavation, locates for all utilities must be marked. While on site Roger noted that there was an electrical utility that had been damaged. Kevin told Roger he believed the line was dead. Neither Kevin, nor any other TT & E employee had reported the broken utility to PSE or the one call notification center, a violation of 19.122.050 (1). Roger then called our Electrical First Responder, Gary Houser, to the scene to check the utility. The power utility was confirmed as live. Roger also uncovered a gas stub marker that TT&E had dug over the top of which is a violation of 19.122.075 (Removal of temporary marking for underground utilities prior to its intended use). Roger exposed the marker by hand. Roger then took pictures of the work and left. PSE's Damage Prevention Program Manager, Erika Hunter, later on the

same day, also spoke with the owner Ben. He stated a second time that the line was not live. Erika called him a second time to confirm that the electrical facility was connected to a street light that had been installed and was live and ask that he communicate information about how to be safe around a broken utility as it was an endangerment to the safety, life and health, of the public as well as his employees and PSE employees responding to the scene. He said that he would do so.

There were no address markers at the house. We obtained the address from the ticket request Ben submitted later that day and compared it with our pictures to the plat map provided by the city of Duvall.








REPORT OF DAMAGE TO ELECTRIC FACILITIES PREPARED FOR LEGAL COUNSEL

			DATE OF REPORT		
LOCATION OF INCIDENT: STREET	BIRD ST & 1ST AVE N	E	CITY DUVALL	COUNTY KING	
TYPE OF INCIDENT	☑ UNDERGROUND DAY		OVERHEAD DAMAGE	☐ PERSONAL INJURY	(DESCRIBE)
INVESTIGATING AGENCY	ACCIDENT INVESTIGATED YES NO NAME & BADGE NO. OF IN	OTHER	PATROL SHERIFF O.		
DAMAGING PARTY		STATE	_ STREET PH	IONE NUMBER 425-754-7731	
IF AUTOMOBILE OR TRUCK	NAME	STATE	STATESTREETZIPDDB		
LOCATE# WAS IT LOCATABLE? WAS FACILITY MARK WERE MARKS MAINT NAME OF LOCATOR LOCATOR COMMENT	P IF N WEI ED? NO WEI AINED? WAI REPRESENTATIVE TS	O, WHY NOT? RE MARKS CORRECT?	G IN IF NO, HOW FAR OFF		_
OTHER COMMENTS					
COMPLETED BY (PLE		TITLE SVCMAN	SIGNATURE		DATE 20161201
RIGHT-OF-WAY WHERE TYPE OF EXCAVATION I TYPE OF WORK PERFO DID EXCAVATOR INCUR	EQUIPMENT: RMED:	PUBLIC-CITY STREET DID THE DAMA	FACILITY AFFECTED: TYPE OF EXCAVATOR GE CAUSE AN INTERRUPTION OF	ŧ	

	NAME		STREET		
WITNESSES	CITY	STATE	ZIP PHONE	NUMBER	
WIINEGGEG	NAME				
	CITY	STATE	ZIP PHONE	NUMBER	
COMPANY					
EMPLOYEES OR SERVICE			HEADQUARTERS		
	NAME		HEADQUARTERS		
PROVIDER AT SCENE ON					
SCENE ON					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					
SCENE ON INCIDENT					

Electrical facility that was damaged.









Gas Stub Marker that had been damaged and covered







Washington One Call

2 FULL BUSINESS DAYS

Ticket No: 16383151
Original Call Date: 12/01/16 10:23 am
Work to Begin Date: 12/06/16 12:00 am

TICKET ACTIONS

CALLER INFORMATION

Company Name: Contact Name: Alt. Contact:

TT BEN TANIELIAN NONE Phone: 425-754-7731 Phone: 425-754-7731 Fax Phone: 360-629-7477

 Caller Address:
 26910 92 AVE NORTH WEST STANWOOD,WA 97292

 Email Address:
 BTANIELIAN@GMAIL.COM

DIG SITE INFORMATION

Type of Work: FOUNDATION Work Being Done For: STAVORS

DIG SITE LOCATION

County: KING Address: 16005 WA DUVALL Place:

1ST AVE NE NE BIRD ST

Lon: -121.9852781 Lon: -121.9836473

