Puget Sound Energy, Inc. P.O. Box 90868 Bellevue. WA 98009-0868 RECEIVED TRANS

July 10, 2006

Carole Washburn Washington Utilities and Transportation Commission PO Box 47250 Olympia, WA 98504-7250

Attention: Alan Rathbun

RE: Docket PG-040210 Puget Sound Energy – 2004 Standard Inspection for Thurston & Lewis Counties; Processes for Inspecting and Remediating Atmospheric Corrosion

Dear Mr. Rathbun:

PSE had committed in a letter dated October 4, 2005 to provide copies of processes for inspecting and remediating atmospheric corrosion on locations that are difficult to access due to location. Attached please find a copy of these processes.

PSE plans to review these processes with Staff during their follow-up inspection which is scheduled for later this month. If Staff has any questions in the interim, please feel free to contact me at 425-462-3957.

Sincerely,

/Jim Hogan

Manager, Standards and Compliance

Enclosure

cc: Kimberly Harris

Karl Karzmar


Sue McLain

Booga Gilbertson

Duane Henderson

En la

Process Flow: Atmospheric Corrosion at Hard-to-Reach Locations (HRLs) - 6/30/06



FACILITIES (Gate Stations

HRL is Forwarded to SMP for Follow-

Development of Solution,

SMP Coordinates

SC&P Returns to Site,

60

Completes AC

(3<u>0</u>

Necessary, and Initiates

Inspection, and Updates Records

Solution

Arranges Funding it

Up Action

PRESSURE CONTROL

30

(20)

Regulating Station, etc.):
SC&P Identifies HRL