

Avista Utilities
1411 East Mission PO Box 3727
Spokane, Washington 99220-3727
Telephone 509-489-0500
Toll Free 800-727-9170

RECEIVED
NOV 07 2005
WASH. UT. & TR. COMM

FILE
PG-051569



November 3, 2005

Mr. Alan Rathbun
Pipeline Safety Director
Washington Utilities and Transportation Commission
PO Box 47250
Olympia, WA 98504-7250

Attn: Mr. Joe Subsits

Dear Mr. Subsits,

Enclosed please find a copy of the pressure chart for the hydrostatic test performed on the South Hill Feeder after its construction in 1992. Additionally, I have included the contractor foreman's notes indicating details of the test.


Please call if you have any further questions.

Respectfully yours,

A handwritten signature in cursive script that reads "Kris Busko".

Kris Busko, P.E.
Gas Distribution Engineer
509-495-8767

RMS
TA



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000
METER 1051
CHART PUT ON 10:35 AM
LOCATION 65TH & FREYA
REMARKS 11-7-88 92
W.O. 9909
53-540 GAS
RE-ARRANGED
TAKEN OFF 10:35 AM

MADE IN U.S.A.

6 AM

5

4

3

2

1

MIDNIGHT

11

NOON

1

2

3

4

5

6 PM

7

8

9

Hydrostatic Test 11-7th & 8-1992

SOUTH END GAS REINFORCEMENT - U.O. 9909

TESTED FOR - WASHINGTON WATER POWER

TESTED BY - DAUCO SERVICES INC.

FOOTAGE TESTED 58,968'

TEST PRESSURE 9.00 PSI

TEST MEDIUM WATER

LENGTH OF TEST 24 HRS

TEST ON 10:35 AM 11-7-1992

TEST OFF 10:35 AM 11-8-1992

TEST PRESSURE LOST 3 LBS DURING
THE NIGHT DUE TO DROP IN TEMPERATURE

Bob McCoy