

Exhibit No. ____ HC (GB-4HC)

Docket UT-081393

Witness: Glenn Blackmon

REDACTED VERSION

BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION

**Verizon Select Services, Inc.; MCI metro
Access Transmission Services, LLC; MCI
Communications Services, Inc.;
Teleconnect Long Distance Services and
Systems Co. d/b/a Telecom USA; and TTI
National, Inc.,**

Complainants,

v.

United Telephone Co. of the Northwest,

Respondent.

DOCKET UT-081393

EXHIBIT TO TESTIMONY OF

Glenn Blackmon

**STAFF OF
WASHINGTON UTILITIES AND
TRANSPORTATION COMMISSION**

Sample of Customer Locations

June 5, 2009

REDACTED VERSION

** Redacted Version **

Row	Element Number	Wire Center	Service Address	Service Grade	Investment (Circuit+Outside Plant)	Embedded Route Distance to CO (ft.)	Modeled Route Distance To CO (ft.)	Google Maps Road Distance (ft.)
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								

Notes (by Row):

- [1] Service address matches Lat/Long geocode.
- [2] Service address matches Lat/Long geocode.
- [3] Service address is much closer to CO than Lat/Long geocode.
- [4] Service address is much closer to highway than Lat/Long geocode.
- [5] Service address matches Lat/Long geocode, but modeled routing is excess length.
- [6] Service address matches Lat/Long geocode.
- [7] Service address does not match Lat/Long geocode, appears to be closer to Bickleton CO.
- [8] Service address apparently should be "Ecine Dr." Matches Lat/Long geocode.
- [9] Service address matches Lat/Long geocode.
- [10] Unable to locate service address, Lat/Long geocode is 13 miles from indicated highway.

Sources:

Embarq response to Staff DR#34.
 2007 v.2.0.1 LoopDesign.mdb
 Google Maps