



1. Investigator(s): Richard Smith 2. Assignment No.: 113005 3. Current Date: 1/16/13 4. Date of Activity: 1/11/13 5. Carrier Name: Two Small Men with Big Hearts Corp. 6. Permit: THG-064094 7. New Entrant date of authority: 12/09/2010	
5. Carrier Name:Two Small Men with Big Hearts Corp.	
6. Permit: <u>THG-064094</u> 7. New Entrant date of authority: <u>12/09/2010</u>	
8. MOTCAR No.: 9. Carrier is: Intrastate Only Interstate Only Interstate Only Interstate	
11. USDOT No.: 2080773 12. MC No.:	
 13. □ Destination Check □ Copy of the Destination Check Safety Plan is attached. ■ Number of Buses/Motor Coaches inspected: 7-15 passenger	
14. Safety Complaint Attach a copy of the Individual Safety Complaint Plan. What activity did staff complete for this safety complaint: Compliance review Technical assistance Number of vehicle inspections: Level 1 Level 2 Level 5 Unannounced terminal visit Other (please explain):	
15. ■ New Entrant – Charter, Auto Transportation Is this carrier referred by FMCSA, operating intra and interstate: ■ Yes ■ No Is this carrier based in another state, requesting intrastate authority: ■ Yes ■ No Is this carrier based in Washington, requesting intrastate authority: ■ Yes ■ No Did staff complete the following: Inspect all vehicles between three and nine months? ■ Yes ■ No Number of vehicle inspections: Level 1 ■ Level 2 ■ Level 5	

1

16. New Entrant-HHG
■ Is this carrier referred by FMCSA, operating intra and interstate: Yes No
■ Is this carrier based in another state, requesting intrastate authority: ☐ Yes ☐ No
■ Is this carrier based in Washington, requesting intrastate authority: Yes No
Did staff complete the following:
◆ Inspect all vehicles between three and eighteen months? Yes □ No
Number of vehicle inspections: Level 1 Level 5
♦ Conduct a SI/SA between three and eighteen months? ☐ Yes ☐ No ☐ SI ☐ SA
◆ Conduct technical assistance within three months?
17. CSA Investigation
Full Investigation
Focused Investigation
Basic is for: Passenger Carrier HHG Carrier Solid Waste Carrier
Basic Threshold Percentile is;
Unsafe Driving %
Fatigued Driving (HOS)%
Crash %
Driver Fitness %
Drug/Alcohol%
Vehicle Maintenance %
18. Individual Safety Plan Only:
What activity did staff complete for this safety complaint?
Attach a copy of the Individual Carrier Safety Plan.
Safety Investigation
Technical assistance
Number of vehicle inspections: Level 1 Level 2 Level 5
Unannounced terminal visit
Other (please explain):
19. Safety Investigation:
Safety Audit:
■ SI Rating: Satisfactory Unsatisfactory Conditional
SA Rating: Pass Fail
Number of vehicles operated: 2
Number of drivers operated: 2
Total miles for prior year:
Recordable accidents for prior year:0
Recordable accidents for prior year.

Revised 9-16-2011 2

20. **Part B Violations:**

Part .	Violations	Part	Violations	Part	Violations
382/40		383		387	
390		391		392	
395		396	2	397	

		MB	MB								
	MC	1-15	16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Inspections									2		
Defective									0		
Vehicles									١		
OOS									0		
Vehicles											
Level									5		

22. Vehicle Inspection Violations:

•	MG	NG	MG	MB	MB	CD 1.0	CD 0 15	GD 46	******	VAN		-	
	MC	1-15	16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	9-15	TRK	TT	TRA		
Brakes			•				1						
Steering													
Lights							,						
Tires, wheels, rims			·										
Horn											,		
Windshield and Wipers													
Mirrors													
Emergency Equip, Exits													
Coupling Devices													
Frame													
Suspension			·										
Exhaust													
Other								1	1				

23. Driver Inspection Violations:

Medical Card	Medical Waiver	Hours of Service	Drivers License
Comment:			

Revised 9-16-2011 3

Carrier received a conditional rating during an earlier compliance review as result of numerous violations.
25. Findings: This compliance review recheck determined the carrier has corrected all problems originally discovered and is doing a good job with safety management procedures and filing. Carrier received a satisfactory safety rating in this CR.
26. Recommended Action: No further action. Notify the company in writing of the findings by providing a copy of the safety investigation, vehicle inspection report, safety audit or other similar document. Require the company to submit a compliance plan in response to the 15-day letter requirement Recheck − Safety Investigation (Date:
27. Is this carrier considered a high risk carrier as a result of this activity? Carrier accident ratio is higher than aggregate ratio. Carrier had an out-of-service ratio 25% or higher at the last vehicle inspection. Carrier had a defect ratio 75% or higher at the last vehicle inspection. Carrier received more than one conditional or unsatisfactory safety investigation rating in more than one of the last four safety investigations (or less than four if four are not completed). Other (please explain):
28. Additional Comments: Carrier should be considered for permanent authority. Close and file.
Investigator's Signature: Richard Smith
Initial Review By: Date:
Paviawar's Pacommandation

Revised 9-16-2011 4

Final Review By: Date: 117/13
Reviewer's Recommendation:
AGREE WITH RECOMMENDATIONS OR to ISSUE prin authority.
or to issue prin authorite.
OFFICE USE ONLY
Date Closed: 1/16/2013 By: Carolyn Caruso
Company Name: Two Men With Small Hearts
Assignment #: 113005
Staff Assigned: Richard Smith

WA Utilities and Transportation Commission

US DOT#

Legal: TWO SMALL MEN WITH BIG HEARTS CORP

2080773 Operating (DBA):

MC/MX #: 000000

State #: HG064094

Federal Tax ID:68-0681490 (EIN)

Review Type: Compliance Review (CR)

Scope:

Principal Office

Location of Review/Audit: Company facility in the U. S.

Territory:

Operation Types Interstate Intrastate Carrier:

> Shipper: Cargo Tank:

Non-HM N/A

Non-HM N/A

Business: Corporation

Gross Revenue: \$57,960.00

for year ending: 12/31/2012

Company Physical Address:

803 Rainier Ave S Seattle, WA 98144

Contact Name:

David Dickson

Phone numbers: (1) 206-624-4327

N/A

(2) 206-660-0658

Fax 604-543-0445

E-Mail Address:

twosmallmen@qwestoffice.net

Company Mailing Address:

803 Rainier Ave S Seattle, WA 98144

Carrier Classification

Authorized for Hire

Private Property

Cargo Classification

Household Goods

Does carrier transport placardable quantities of HM?

Is an HM Permit required?

No N/A

Driver Information

Inter Intra 2 < 100 Miles: 0 >= 100 Miles: O 0 Average trip leased drivers/month: 0

Total Drivers: 2

CDL Drivers: 0

Equipment

Truck

Owned Term Leased Trip Leased 2

Owned Term Leased Trip Leased

Power units used in the U.S.: 2

Percentage of time used in the U.S.: 100



U.S. DOT #: 2080773

State #: HG064094

Review Date: 01/16/2013

Part A

Questions about this report or the Motor Carrier Safety or Hazardous Materials regulations may be addressed to:

This report will be used to assess your safety compliance.

Person(s) Interviewed

Name: David Dickson Name: Glen Buckler

Title: General Manager Title: Owner-President

Page 2 of 2



U.S. DOT#: 2080773

State #: HG064094

Review Date: 01/16/2013

Part B'Violations

1 STATE	Primary: 396.3(b)(2)	Di	scovered	Checked	Drivers/ In Violation	Vehicles Checked
	CFR Equivalent: 396.3(b)(2)	ļ	1	1	1	1
performed. Example	e a means of indicating the nature and due on the nature and due of the nature and due o	date of the various	inspection a	and maintenar	nce operations	to be
2 STATE	Primary: 396.17(a)	Di	scovered	Checked	Drivers/ In Violation	Vehicles Checked
Description	CFR Equivalent: 396.17(a)		1	1	11	1
Example Unit #14 not in Safety Fitness Total Mi	nercial motor vehicle not periodically inspect nspected annually after purchased for use in Rating Information: les Operated 7,200 able Accidents 0	n commerce.		OOS Vehic nicle Inspecto OS Vehicle (N	ed (CR): 1	
	able Accidents/Million Miles 0.00	Number		Inspected (N		
Your proposed	safety rating is :	Rating Fac	tors	-	Cute Critica	al
	, ,	Factor	1:	S	0 0)
		Factor	2:	S	0 0)
	SATISFACTORY	Factor	3:	S	0 0	
		Factor	4:	S	0 0)
	•	Factor	5:	N	0 0)
		Factor	6:	S		

Corrective actions must be taken for any violations (deficiencies) identified on Part B of this report.





U.S. DOT #: 2080773

State #: HG064094

Review Date: 01/16/2013

Part C

Reason for Review: Compliance Review Compliance Monitoring Planned Action:

Parts Reviewed Certification:

398 172 173 177 178 180 325 382 383 387 390 391 392 393 395 396 397 399 171

Prior Reviews

Prior Prosecutions

Unsat/Unfit Information

Is the motor carrier of passengers subject to the safety fitness procedures contained in 49 CFR part 385 subpart A, AND does it transport passengers in a commercial motor vehicle?

Does carrier transport placardable quantities of hazardous materials?

Unsat/Unfit rule:

Corporate Contact: David Dickson

Follow-up - 60-Day Rule for conditional Special Study Information:

Corporate Contact Title: General Manager

Remarks:

PART C

Two Small Men with Big Hearts Corp.

Mr. David Dickson, safety manager was contacted at the carrier's new terminal located at 803 Rainier Avenue S. Seattle, WA 98144 on Janiary 15-16, 2013 for the purpose of conducting a compliance review (CR). Mr. Dickson had personally attended the Utilities and Transportation Commission's (UTC) Household Goods (HHG) safety training April 26, 2011 and again October 12, 2011.

REASON FOR INVESTIGATION:

A full compliance review is required for Washington intrastate HHG carriers between three and 18 months after receiving provisional authority to operate for-hire in commerce in the state of Washington. Designated management for HHG Carriers are also required to attend one HHG safety class during their provisional authority period and before having a full CR completed or being granted permanent authority.

SCOPE OF INVESTIGATION:

A full intrastate compliance investigation was conducted while adhering to policies of the Federal Motor Carrier Safety Administration (FMCSA) international sampling recommendations. This carrier has two intrastate driver's requiring the review of 60 records of duty status records and 60 daily vehicle inspection reports. This carrier has two 24 ft straight trucks and two small vans under 10001 GVWR. The van trucks are not regulated by UTC due to being under the minimum GVWR of 10,001lbs for designation of a commercial motor vehicle. One of the 24 ft trucks was currently out of service leaving only unit #14 operating for HHG transportation and subject to UTC inspection.a 2007 Ford 11 passenger van was recently purchased in January 2012 and was being used without first having an annual inspection conducted by a DOT qualified mechanic. The only other violation discovered was that Mr. Boast did not have a plan for maintenance due dates. He told me he just decided to have the oil checked and other components of his vehicles inspected every 3 to 5,000 miles. This he was informed did not meet the requirements of the law. He immediately implemented a written plan to resolve this issue.

CARRIER OPERATION DESCRIPTION:

This carrier operates two 14,000 GVWR van trucks and currently employs two drivers as an intrastate only carrier. All files



U.S. DOT #: 2080773

State #: HG064094

Review Date: 01/16/2013

Part C

for this carrier are well maintained and filed in sequential order as if following the procedural sections of the UTC manual, Your Guide to Achieving a Satisfactory Safety Record". Even though Mr. Dickson had numerous questions that resulted in a full safety training be provided to him by the end the review, his safety interest was obvious.

The carriers gross operating revenue was \$57,960.00 for the last fiscal year ending on 12/31/2012. UTC records indicate that Mr. Dickson is responsible for all safety management.

PRE-INVESTIGATION:

The carrier was requested to produce the following information at least 48 hours before this compliance review was scheduled:

- * Financial responsibility
- * Crash information
- * Driver qualification files
- * Hours of service records
- * Inspection, repair and maintenance records including annual (periodic) inspections
- * Controlled substance and alcohol testing records, if applicable
- * Commercial driver's license information, if applicable
- * Medical certification credentials

DRIVER LICENSE CHECK:

Washington State Dept. of Licensing was used to verify driver's license as being current and valid since the two drivers for this carrier are not required a CDL.

INVESTIGATION:

The company now maintains good supporting documents consisting of daily trip records, inspection reports, and other data. Mr. Dickson is responsible for all documents and records located at the carrier's principal place of business. Files are maintained by trip or date depending upon the type of record.

In conducting this compliance review I examined records pertaining to CFR 49, Parts 382, 383, 387, 390, 391, 392, 393, 395, and 396 as adopted by the UTC in WAC 480-30-999. The following violations were discovered;

396.17(a), Using a commercial motor vehicle not periodically inspected, one violation. 396.3(b)(2), Not having a maintenance due dates plan.

Mr. Dickson immediately implemented new procedures to resolve each of the violations discovered and assured that being highly interested in maintaining a safe operation, he will stay on top of regulatory require, requirements for his business. His plans are to hire more drivers and purchase additional vehicles before the end of this year. The new vehicles he has hopes to obtain will require CDL operators. This program will require numerous changes to his current procedures and safety training was provided to ready him and his company for requirements of these major changes.

The carrier is insured with Zurich American Insurance under policy BAP 9337637 For 750,000.

The carrier's safety rating is satisfactory.

Upload Authorized:

Authorized by:

Uploaded:

Yes

No

Yes

Ɗate:/- /ົ - ໃ∞ງ] Failure Code:

Verified by:

Date:

No



U.S. DOT #: 2080773

State #: HG064094

Review Date: 01/16/2013

Part B Requirements and/or Recommendations

- IF YOU WANT A COPY OF YOUR INTRASTATE CARRIER PROFILE, CONTACT MS. CAROLYN CARUSO @ 360-664-1244.
- 2. If you have any questions concerning this report,, please contact the Washington Utilities & Transportation Commission @ UTC PO BOX 47250 OLYMPIA, WA 98504 ATTN: RICK SMITH 360-664-1236
- 3. "Under the Administrative Procedure Act (RCW 34.05) (Laws of 2009, ch. 358), the commission will waive any fines, civil penalties, or administrative sanctions for first-time paperwork violations by a small business, with certain exceptions. One of those exceptions provides that any violation of a substantially similar paperwork requirement (as described in Part B on this form) may result in the imposition of a fine, civil penalty or other administrative sanction. The company will not be entitled to a second waiver of penalties for "first-time" paperwork violations."
- 4. THIS COMPLIANCE REVIEW WILL RESULT IN AN INTRASTATE SAFETY RATING. TO OBTAIN A COPY OF THIS RATING, CONTACT CAROLYN CARUSO AT 360-664-1244.
- 5. Copies of the regulations, forms, interpretations, and manuals are available from a variety of sources. Check the FMCSA website for a current list of suppliers. www.fmcsa.dot.gov/safety-security/eta/index.htm
- **6.** Ensure that all drivers are fully and properly qualified before operating in interstate commerce. Maintain a complete file as required for each driver, documenting the qualification process.
- 7. Require all drivers to prepare complete and accurate records of duty status for each day, and to submit them within 13 days. Maintain all duty status records on file, with all supporting documents, for at least 6 months.
- 8. Ensure that all documents supporting records of duty status (such as toll, fuel repair and other on-the-road expense receipts, as well as invoices, bills of lading, dispatch records, etc.) are kept on file for at least 6 months.
- **9.** Establish a systematic maintenance records program for all vehicles. Maintain a complete file for each subject vehicle, recording all repair, maintenance and inspection operations performed.
- 10. Keep all driver vehicle inspection reports, signed, certified, and reviewed as required on file for at least 90 days.
- 11. This review will result in a Safety Rating.

