



Zella West <safetycommitteewaucc@gmail.com>

Complaint Form - WUCC Website

13023

sendmail@washington-ucc.org <sendmail@washington-ucc.org>
 To: safetycommitteewaucc@gmail.com
 Cc: jared@wearedifnt.com

Mon, Nov 4, 2013 at 9:02 AM

Aaron Donat just filed a complaint from washington-ucc.org

Requester Information

Name: Aaron Donat
Company: Tesoro Logistics Northwest Pipeline, LLC
Phone: (801) 913-0691
Address: 475 W 900 N
City: Salt Lake City
Zipcode: 84084
Email: adonat.contractor@tsocorp.com
Requested A Ticket: False

Violation Information

Violation: RCW 19.122.030
Law Violated: Did not call in a dig ticket.
Basic Description:

Property owner was digging a 3' deep trench with a trencher and did not call in a dig ticket. Property owner was contacted and refuses to call in any dig tickets while digging near our 8" refined petroleum products line. After we asked him to stop trenching and advised we would need to come and excavate our line to check for damage he excavated our line on his own without a dig ticket. Property owner will not cooperate in anyway and continues to threaten the pipeline stating he will dig it up and remove it himself.

Violation Address: 35030 W Hwy 12, Burbank, WA
Violation Date: 10/22/2013

Violation Information

Violator Company: Randy Buchanan
Violator Phone: (509) 521-4299
Violator Address: 35030 W Hwy. 12
Violator City: Burbank
Violator Zipcode: 99323
Violator Email: none@wontshareit.com
Violator Employees:

Other Information

Additional Information:

Mr. Buchanan was sent a letter by David Lykken and Anna Gill, however, he is still threatening to dig up our line without calling in a dig ticket and refuses to notify when he is tilling his field as required by law.



Washington State Dig Law Safety Committee
A Standing Committee of Washington Utilities Coordinating Council
COMMUNICATION – COOPERATION -
COORDINATION
5808 A Summitview PMB 227 • Yakima, WA 98908

December 6, 2013

Committee Members
Represent:

Local Government

Natural Gas Utility

Contractors

Excavators

Electric Utility

Consumer – Owned Utility

Pipeline Utility

Insurance Industry

**Utilities and Transportation
Commission**

**Telecommunications
Company**

Three At – Large Positions

Aaron Donat
Tesoro Logistics Northwest Pipeline, LLC
475 W 900 N
Salt Lake City, UT 84084

Re: Complaint Case Number: 13023

Dear Mr. Donat,

The Washington Dig Law Safety Committee has received your request to review an alleged violation of RCW 19.122.030.

Randy Buchanan has been notified of this request via mail with return receipt.

Your review will be held January 16, 2013 at the Utilities and Transportation Commission Office (directions enclosed), starting at 10:00 am. *This will be a 40 minute meeting only, 20 minutes for each side to thoroughly explain your case.*

Please provide ten (10) copies of any color documentation you feel will support your case to the Administrative Assistant at least ten (10) days prior to the hearing.

As this is an informal process, no legal representation is permitted as part of this proceeding.

If you have any questions, please contact me at (509) 966-0272 or safetycommitteewaucc@gmail.com

Sincerely,

Chelsie Rehfield
Chelsie Rehfield (on behalf of the Safety Committee)
Administrative Assistant
Washington Utilities Coordinating Council



Washington State Dig Law Safety Committee

A Standing Committee of Washington Utilities Coordinating Council

COMMUNICATION – COOPERATION -
COORDINATION

5808 A Summitview PMB 227 • Yakima, WA 98908

December 6, 2013

Randy Buchanan
35030 W Hwy. 12
Burbank, WA 99323

Re: Case Number: 13023

Dear Randy Buchanan,

The Washington Dig Law Safety Committee has received a complaint from Tesoro Logistics Northwest Pipeline, LLC. alleging you, Randy Buchanan violated Washington Law, RCW 19.122.030 (copy of complaint attached).

In accordance with the law, you are requested to attend a meeting to review the alleged violation(s). At this meeting, be prepared to thoroughly explain your side with comments and supporting color documentation. This complaint review is NOT an adjudication process. It is an attempt to prevent damage and injury caused by violations of the Washington dig law, by hearing both sides, confirming what occurred, and then recommending action(s) that will help prevent future violations. If the Safety Committee determines you likely committed a violation, it may recommend remedial action which may include a monetary penalty, training, education, or some combination thereof.

Your review will be held January 16, 2013 at the Utilities and Transportation Commission Office (directions enclosed), starting at 10:00am. *This will be a 40 minute meeting only, 20 minutes for each side.*

Please provide ten (10) copies of any documentation you feel will support your case to Administrative Assistant at least ten (10) days prior to the hearing.

As this is an informal process, no legal representation is permitted as part of this proceeding.

If you have any questions, please contact me at (509) 966-0272 or safetycommitteewuacc@gmail.com

Sincerely,
Chelsie Rehfield
Chelsie Rehfield (on behalf of Safety Committee)
Administrative Assistant
Washington Utilities Coordinating Council

www.washington-ucc.org

Committee Members
Represent:

Local Government

Natural Gas Utility

Contractors

Excavators

Electric Utility

Consumer – Owned Utility

Pipeline Utility

Insurance Industry

Utilities and Transportation
Commission

Telecommunications
Company

Three At – Large Positions



No.: LFM015-01
 TITLE: Foreign Line Crossing Report
 1/24/11 REV. No.: 3

Project Name/Number: MP 561.813		One-Call Number: None	
Report By: Yantzee Everett		Date Report Completed: 10/24/2013	Crossing Installation Date: 10/21/2013
Company: Randy Buchanan			
Pipeline Segment Name: South Line # 2 Line			
Location: <input type="checkbox"/> Alaska <input type="checkbox"/> Hawaii <input type="checkbox"/> North Dakota/Montana <input type="checkbox"/> N. California <input type="checkbox"/> S. California <input type="checkbox"/> Utah <input type="checkbox"/> Other <u>Washington</u>			
This Report is <input checked="" type="checkbox"/> New <input type="checkbox"/> Revised		Line Diameter: 6"	<input checked="" type="checkbox"/> Trunk <input type="checkbox"/> Gathering
Mile Post: 561.813		State: WA	County: Walla Walla
<input type="checkbox"/> NW <input type="checkbox"/> NE <input type="checkbox"/> SW <input type="checkbox"/> SE		Section: 27	Township: <input checked="" type="checkbox"/> N <input type="checkbox"/> S
Engineering Station # (ESN) at Crossing: 29663+77		Latitude (decimal degrees): 46.1458546	Longitude (decimal degrees): -118.9242839
Reference Feature used to Calculate ESN of Crossing: <input type="checkbox"/> Valve <input type="checkbox"/> Casing <input checked="" type="checkbox"/> Bend <input type="checkbox"/> Centerline of Named Road <input type="checkbox"/> Other			
Reference Feature Name/Description: <u>Bend</u>			
ESN: 29648+77		Latitude (decimal degrees): 46.143346	Longitude (decimal degrees): -118.919463
Distance (Feet) from Crossing to Reference Feature: 1500'		Direction from Reference Feature: <input type="checkbox"/> Up Stream <input checked="" type="checkbox"/> Down Stream	
Type of Crossing: <input type="checkbox"/> Pipeline <input type="checkbox"/> Sewer Line <input type="checkbox"/> Telecom <input checked="" type="checkbox"/> Water Line <input type="checkbox"/> Electrical <input type="checkbox"/> Other			
Method of Crossing: <input type="checkbox"/> Directional Drill or Bore <input checked="" type="checkbox"/> Open Cut <input type="checkbox"/> Other			
Was a TESORO Line Exposed? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, attach form LFM017-01 Inspection & Repair Report			
Over or Under TESORO Line? <input checked="" type="checkbox"/> Over <input type="checkbox"/> Under		Line Clearance (Feet-Inches): 16"	
Material of Foreign Crossing: <input type="checkbox"/> Steel <input type="checkbox"/> Concrete-Pressure <input type="checkbox"/> Cable <input checked="" type="checkbox"/> Plastic <input type="checkbox"/> Concrete-Gravity <input type="checkbox"/> Ductile/Cast Iron <input type="checkbox"/> Other			
Foreign Crossing Coated? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Foreign Crossing Cased? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Nominal Diameter of Foreign Crossing (Inches): 2"		Intersection Angle: 45 Degrees	
Test Station Installed? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, fill out and submit form LFM028-04 Test Station Datasheet			
Bonded to Foreign Crossing? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, fill out and submit form LFM028-04 Test Station Datasheet			
Field Sketch:			
<p>The field sketch consists of two diagrams. The left diagram shows a cross-section of the ground level with a hatched top line. Below it, a horizontal line represents the 'FOREIGN' line. Below that, a circle represents the 'TESORO' line. Below the TESORO line, another horizontal line represents another 'FOREIGN' line. Vertical dimension lines are labeled A, B, and C. A=47", B=16", and C=.</p> <p>The right diagram shows a top-down view of the TESORO line crossing the foreign line. The TESORO line is a horizontal cylinder with an arrow pointing right. The foreign line is a diagonal line crossing the TESORO line. The intersection angle is labeled as 45 degrees.</p>			
FIELD RESPONSE/LOCATE INFORMATION Check box if Not Applicable <input type="checkbox"/>			
Individual Contacted: <input type="checkbox"/> Contractor <input checked="" type="checkbox"/> Owner <input type="checkbox"/> Other			
Foreign Line Owner Name: Randy Buchanan		Foreign Line Owner Telephone Number: 509-547-4900, 509-521-4299	
Foreign Line Owner Address: 35032 W Highway 2		State: WA Zip: 99323	
City: Burbank			
Foreign Line Contractor Representative Name:		Foreign Line Contractor Telephone Number:	
Foreign Line Contractor Company Name:			
Address:			
City:		State: Zip:	
Investigation Due To: <input checked="" type="checkbox"/> Air Patrol <input checked="" type="checkbox"/> Vehicle Patrol <input type="checkbox"/> Stigate One Call <input type="checkbox"/> Other			
Line Sheet Number for Crossing (optional):		Land Works Tract/Line List Number (optional):	
Comments: This Foreign Line Crossing had no One Call Ticket associated with the work that was performed. Tesoro's Air Patrol called in the encroachment to the Maintenance Coordinator who in turn notified the Facility inspector for further follow up.			
(Attach One-Call Report & Photo)			

