



Completed Activity

Report Motor Carrier Safety

	∑ No	
1. Investigator(s):	Richard Smith	2. Assignment No.:112161
3. Current Date: ——	10-05-2012	4. Date of Activity:10-05-2012
5. Carrier Name:	Eli Enterprises Inc dba City	Limo.
6. Permit: N/A	7. If new entrant, date	e of temporary authority
8. MOTCAR No.: _	<u> </u>	9. Carrier is: Intrastate Only Interstate Only
10. Industry Code:	232	Both Intra and Interstate
11. DOT No.:	2346130	12. MC No.:
 Number of vehic 	le inspections: Level 1 ——	er # of 16+ passenger Level 5 Level 5 Level 5 stination check and the results:
■ What might we d	o differently to increase our su	access at the next destination check:
■ What might we d	o differently to increase our su	access at the next destination check:



 15. New Entrant – Charter, Auto Transportation Is this carrier referred by FMCSA, operating intra and interstate: Yes No Is this carrier based in another state, requesting intrastate authority: Yes No Is this carrier based in Washington, requesting intrastate authority: Yes No Did staff complete the following: Inspect all vehicles between three and nine months? Yes No Number of vehicle inspections: Level 1 Level 2 Level 53 Conduct a CR/SA between three and nine months? Yes No
16. ☐ New Entrant— HHG ■ Is this carrier referred by FMCSA, operating intra and interstate: ☐ Yes ☐ No ■ Is this carrier based in another state, requesting intrastate authority: ☐ Yes ☐ No ■ Is this carrier based in Washington, requesting intrastate authority: ☐ Yes ☐ No ■ Did staff complete the following: ■ Inspect all vehicles between three and eighteen months? ☐ Yes ☐ No Number of vehicle inspections: Level 1 ☐ Level 2 ☐ Level 5 ■ Conduct a CR/SA between three and eighteen months? ☐ Yes ☐ No ☐ CR ☐ SA ■ Conduct technical assistance within three months? ☐ Yes ☐ No
17.
18. Compliance Review Data: Safety Rating: Satisfactory Unsatisfactory Number of vehicles operated: Number of drivers operated: Total miles for prior year: Recordable accidents for prior year: Accident Ratio:

Revised 11-03-09 2

10		D	т	X 7: -	lations:
19.	!!	rart	Ŋ	V 10.	iations:

Part	Violations	Part	Violations	Part	Violations
382/40		383		387	
390		391		392	
395		396		397	

	MC	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Inspections								1			
Defective Vehicles								0			
OOS Vehicles								0			
Location		1						Term.			
Level				1				5			

	МС	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Brakes							_				
Steering							,				
Lights											
Tires, wheels, rims											
Horn					l						
Windshield and Wipers											
Mirrors	1										
Emergency Equip, Exits											
Coupling Devices											
Frame											
Suspension											
Exhaust											
Other	1 -										

22. Driver Inspection Violations	:		
Medical Card	Medical Waiver	Hours of Service	Drivers License

Revised 11-03-09 3

23. Relevant carrier history, if any: New Entrant vehicle inspections for authority.
24. Findings: One 2006 Lincoln Van capable of holding 9 passengers was fully inspected using CVSA inspection level 5 standards and found to be free of any defects or violations. A CVSA decal was issued to the vehicle. I met with safety manager and company owner Eli Darland and provided extensive education and technical assistance consisting of 3.2 hours. I issued to Mr. Sarver the UTC manual "Your Guide to Achieving a Satisfactory Safety Record". Each page of the manual was reviewed with Mr. Sarver.
25. Recommended Action: No further action. Notify the company in writing of the findings by providing a copy of the CR, vehicle inspection report, safety audit or other similar document. Require the company to submit a compliance plan in response to the 15-day letter requirement. Recheck − Compliance review (Date:) Revisit to recheck a specific issue (Date:) Describe:
Send the company a compliance letter. Require a response: Yes No Issue administrative penalties in the amount of \$ Issue a complaint. Stop company operations.
26. Is this carrier considered a high risk carrier as a result of this activity? Carrier accident ratio is higher than aggregate ratio. Carrier had an out-of-service ratio 25% or higher at the last vehicle inspection. Carrier had a defect ratio 75% or higher at the last vehicle inspection. Carrier received more than one conditional or unsatisfactory compliance review rating in more than one of the last four compliance reviews (or less than four if four are not completed). Other (please explain):
27. Additional Comments: I recommend authority be granted to this carrier. Mr. Darland was a very good student during my ETA and said his primary business concern was safety for his passengers and the general public. Close and file.
Investigator's signature: Richard Smith
Initial review by: Date: 10[8(12
Reviewer's recommendation: AGREE WITH RECOMMENDATION
A OK to 1554p authority.
Final review by: Date:
Reviewer's recommendation:

Revised 11-03-09

Date closed:		
Date closed:	By:	
cc:		
Company name	Assignment #	
Staff Assigned		

Revised 11-03-09

Special Project	112161

UNIFORM DRIVER/VEHICLE INSPECTION REPORT

1312642

PERSONNE		DIST / DET	E\/E · 1	2	3	1	5	1.5
T-5	80	HQ	L. V L L . 1 _	2	. J <u></u>	- , ¬		<u></u>
			ERAL		HAZAF	RDOUS I	MATER	IALS
DATE							***************	
10.	512	TIME (MILITARY) BEGUN :	FINISHED :	9 / /	CLASS / DIVISIO			
OCATION	: SR/MP		SCALEHOUSE NO	CNTY CODE REPORTAL	BLE QTY? Y	N HAZA	RDOUS WA	STE? Y N
	and the second			1 . — 1				TANKS? Y N
				RRIER				
ARRIER N	AME (Inclue D	BA when applicable)						
7	1 -	FILTER A	RISES TNC	Olo or	معدد از ایسی	<u>~</u>		
DDRESS		- M 1 - R 11	LIDED THE	, 300/m (<u>J</u>)	<u> </u>	<u> </u>		
1	7810	< C 7 3 S	2× = = 17	1				
ITY _	-0/1	<u> </u>	STATE ZIP CODE	INTERSTATE	DOT NO.	-	ICC NO.	
15.	Houns	3	STATE ZIP CODE WA 9400A	YES (NO)	234/4/	170		
	7000			IVER	1521.00	· · · · · · ·		
RIVER NA	ME			ICENSE NO.			STATE	EXP. YEAR
		No. of the second						
ATE OF B	ĪRĪH .	MED CERT	Y N SHIPPER NAME	<u> </u>		SHIP	PING NO.	
		1	Y N	<u> </u>	*	ļ		
/		Liver		uel F	00	1 /		
EGISTER	D OWNED NA	ME/ADDRESS .	VEI	HICLE	/ / / /	2- - 3	PBT RA	ATE
,		f.			44		""	
		as abou	- I					
UNIT		YEAR/MAKE	CO. UNIT NO.		LICENSE NO.	/ VIN NO.		STATE
1	VM	2006 Lin	1c 1	139243	39 u			
2		T6440		121FM	28 WX6	1637	9/2	الرئون
3		75 - 70		12.	1 9 W. 2 X W2	1 1	<u> </u>	
			· · · · · · · · · · · · · · · · · · ·					
4				[
	1	2 3	4 5 6	7 8 9	10	11 12	2	
FRO	ТИС	FINA	1216				\dashv	
		11/100						
	>rn		VIOLATIONS					Unit #s
	CFR		VIULATIUNS	•	D 1	2 3	4	O/S Complied
							1 1	
		No	Villetuns					
			3.73787			 	-	-:
		 	Contract of the second of the			 	-	
						ļ		
						1		
-								
						 		
				-		 		
								
				. s *				
			-	· ———				
				<u> </u>		 -		-
VB		LIAUT C	11117	Terror :		NOIC NO		
VSA DEC	ALS UNIT 1	ONIT 2	UNIT 3	UNIT 4		NOIC NO.		
/ 	116/	. /]	DRIVER SIGNATURE		-	L . — .		
		nay not be operated unt	ulo/s	1)	•			
		oted above are repaired by not drive until in com						
2-1	3							
3000-150	-160 R (2/99) .	<u> </u>		-			