	ssignment Report Motor Carrier Safety
Upload? 🗌 Yes 🛛 No - Reason For Not Uploading: New Er	atrant
1. Investigator(s):Ray Gardner J577_	2. Assignment No.: 114001
3. Current Date:January 21, 2014	4. Date of Activity: January 13, 2014
5. Carrier Name:DMC Transportation LLCRaz Transportation	tion
6. Permit: 7. New Entrant date of authority:	
8. MOTCAR No.: 7620 9. Carrier is: 10. Industry Code: 232	 Intrastate Only Interstate Only Intra and Interstate
11. USDOT No.: 24260 % 4 12. M	C No.:
 Copy of the Destination Check Safety Plan is attached. Number of Buses/Motor Coaches inspected: 7-15 passenger Number of vehicle inspections: Level 1 Level 2 Any special emphasis placed on the destination check [] Yes Describe Special Emphasis What might we do differently to increase our success at the ne 	Level 3 Level 5 [] No
 14. Safety Complaint Attach a copy of the Individual Safety Complaint Plan. What activity did staff complete for this safety complaint: Compliance review Technical assistance Number of vehicle inspections: Level 1 Level Unannounced terminal visit Other (please explain): 	2 Level 5
 15. New Entrant - Charter, Auto Transportation Is this carrier referred by FMCSA, operating intra and intersta Is this carrier based in another state, requesting intrastate author Is this carrier based in Washington, requesting intrastate author Did staff complete the following: Inspect all vehicles between three and nine months? Number of vehicle inspections: Level 1 Level 2 Conduct a SI/SA between three and nine months? 	ority: 🛛 Yes 🗌 No

16. New Entrant– HHG	
• Is this carrier referred by FMCSA, operating intra and interstate:	🔲 Yes 🔲 No
• Is this carrier based in another state, requesting intrastate authority:	🗌 Yes 🗌 No
• Is this carrier based in Washington, requesting intrastate authority:	Yes No
 Did staff complete the following: 	
Inspect all vehicles between three and eighteen months?	Yes No
Number of vehicle inspections: Level 1 Level 2 Le	vel 5
♦ Conduct a SI/SA between three and eighteen months?] No 🗌 SI 🗌 SA
♦ Conduct technical assistance within three months?] No

17. CSA Investigation	 	•
Full Investigation		
Focused Investigation	 · .	
Basic is for: Passenger Carrier HHG Carrier Solid Waste Carrier		
Basic Threshold Percentile is;		
Unsafe Driving%		
Fatigued Driving (HOS)%		
Crash%		
Driver Fitness%		
Drug/Alcohol%		
Vehicle Maintenance%		

18. 🗌 Individual Safety Plan Only:	
What activity did staff complete for this safety complaint?	
Attach a copy of the Individual Carrier Safety Plan.	
Safety Investigation	н
Technical assistance	
Number of vehicle inspections: Level 1 Level 2 Level 5	

Unannounced terminal visit Other (please explain):

19	. Safety Investigation:
	Safety Audit:
	SI Rating: Satisfactory Unsatisfactory Conditional
	SA Rating: Pass Fail
•	Number of vehicles operated:
=	Number of drivers operated:
	Total miles for prior year:
-	Recordable accidents for prior year:
	Accident Ratio:

20. **Part B Violations:**

Part	Violations	Part	Violations	Part	Violations
382/40		383		387	
390		391		392	
395		396		397	
					·

21. 🛛 Vehicle Inspection Data:

	мс	MB 1-15	MB 16+	SB 1-8	SB 9-15	SB 16+	VAN 1-8	VAN 9-15	TRK	TT	TRA
Inspections	8										
Defective Vehicles	2										
OOS Vehicles	1										
Level	5										

22. Xehicle Inspection Violations:

			· · · · ·			
					· · · · · · · · · · · · · · · · · · ·	
	· · · · · =					
1						×
						· · ·

23. Driver Inspection Violations:

Medical Card	Medical Waiver	Hours of Service	Drivers License
Comment:			· · · · · · · · · · · · · · · · · · ·

24. Relevant Carrier History:

This a carrier that has been in the UTC system before with different owners. The carrier has a new owner but does have the same maintenance manager and maintenance people in the shop.

25. Findings:

Eight coaches that were being offered for service were inspected. The coaches were inspected using the criteria set forth in CVSA for a level 5 CVSA safety inspection. Six of the coaches were found to have no violations. One of the coaches had one brake out of adjustment which was adjusted during the course of the inspection. One coach was placed out of service for a fuel leak and a broken engine mount hanger. The seven coaches that passed were given CVSA decals.

26. Recommended Action:

- \boxtimes No further action.
 - Notify the company in writing of the findings by providing a copy of the safety investigation, vehicle inspection report, safety audit or other similar document.
 - Require the company to submit a compliance plan in response to the 15-day letter requirement.
- Recheck Safety Investigation (Date: _____)
- Revisit to recheck a specific issue (Date: _____)

Send the company a compliance letter. Require a response: 🗌 Yes 🗌 No

Issue administrative penalties in the amount of \$

Ray

- Issue a complaint.
- Stop company operations.

27. Is this carrier considered a high risk carrier as a result of this activity?

- Carrier accident ratio is higher than aggregate ratio.
- Carrier had an out-of-service ratio 25% or higher at the last vehicle inspection.

Carrier had a defect ratio 75% or higher at the last vehicle inspection.

Carrier received more than one conditional or unsatisfactory safety investigation rating in

more than one of the last four safety investigations (or less than four if four are not completed).

Other (please explain):

28. Additional Comments: I would recommend that this carrier granted authority from the UTC to operate as a for hire Charter Carrier

Investigator's Signature:

Initial Review By:	Date:
Reviewer's Recommendation:	
Final Review By: Proet	Date: 129/14
Reviewer's Recommendation:	
OK to issue authority	
	· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·
OFFICE US	E ONLY
Date Closed: 129/2014	By: Lindsay Martin
Company Name: DANC Transport	
Assignment #: 114001	·
Staff Assigned: <u>Ray Gardner</u>	

Revised 9-16-2011

5