

UTC Rail Safety Program - Assignment Details - For Assignment 2017.0257

| | | | |
|----------------------|-----------------------------------|-------------------|----------------------|
| Assigned To | Stocking, Calvin (UTC) | Railroad | BNSF Railway Company |
| Assignment Type | Accident Investigation - Crossing | Rail Line | 2 |
| Assignment Date | 3/23/2017 | Main Branch | B |
| Assignment Due | 6/30/2017 | | |
| Assignment Completed | | Complaint | No |
| Inspection Count | 1 | Complaint Made By | |
| Accompanied By | Bob Johnston | | |

Description:

Investigate fatality incident that occurred at Greenleaf Avenue in Burlington, USDOT 084764A, RR MP 71.8. Incident occurred on November 20, 2016. LH did not request a death certificate because most of the information is contained in the police report. If you need the death certificate, please contact LH and she will request.

Comments:

14 x 6

Detail

| USDOT# | UTC # | Name | City (In Limits) | County | Last Inspection |
|---------|---------|-----------------------------|------------------|--------|-----------------|
| 084764A | 2B71.90 | Crossing - Greenleaf Avenue | Burlington | Skagit | 7/29/2015 |

EOS = 084764A

1. Ben

Arms/Gates - one lane lights.


MP 71.9

Greenleaf Ave

Station 30' from first track

NO EW SIGN

3 tracks



USA