

INSPECTIONS - ACTIVE RR BRIDGES - LS 37, MP 1,673.50 THRU 1,674.00

3/25/2008

Line Seg	MP Name	Bridge Description	Feature Interesected	Lgth (ft)	Ht (ft)	Year Built	SUPVR CENTER	INSP TYPE	INSP START DATE
37	1673.50	2-40',25'DPG	CHUMSTICK CRK,RD	106	25	1928	14931	AN	9/19/2007
								RT	2/20/2007
								AN	10/20/2006
								RT	4/20/2006
								AN	10/18/2005
								RT	9/8/2005
								RT	10/29/2004
								AN	4/22/2004
								RT	10/2/2003
								AN	4/16/2003
								RT	11/14/2002
								RT	8/29/2002
								AN	5/8/2002
								SP	4/8/2002
								RT	4/8/2002
								RT	11/1/2001
								SP	11/1/2001
								RT	7/26/2001
								SP	5/11/2001
								RT	5/11/2001
								AN	3/8/2001
								RT	8/24/2000
								SP	8/24/2000
								AN	4/26/2000
								SP	2/1/2000
								RT	11/17/1999

ALL BRIDGE EXCEPTIONS ON L.S. 37 - BTWN MP 1,673.50 & MP 1,674.00

L.S.	MP NAME	S F X	EXCEPTION ID	COMPONENT	EXCEPTION	EXCEPTION REMARKS	PRIORITY	STATUS	OPEN DATE	ENTERED DATE	ENTERED BY
37	1673.500		0224123219914698	NUMBER SIGN	MISSING		MTC	CLOS	11/17/1999	11/17/1999	Denny D Loveland
			5001120980214698	CHANNEL	EXCESSIVE VEGETATIO	Trees almost into lower stringers of br.	MTC	CLOS	4/8/2002	4/8/2002	Denny D Loveland
			4723122410214698	WALK	DEBRIS	ballast on walk- place toe-boards to keep ballast from falling on	INFO	CLOS	8/29/2002	8/29/2002	Denny D Loveland
			1919122410214698	WALK	NON STANDARD	12' dropoff West end of walk--place ecology blocks and ballast b	MTC	OPEN	8/29/2002	8/29/2002	Denny D Loveland