

Trunk Group Detail WAC 480-120-401 (3)										
TGID	CLLI-A	CLLI-Z	DIR	TRF TYPE	TRKS	% BLK ABH	% BLK PEAK	PBH	ACTION TAKEN	
GW011288	EVRTWAXA03T	SLLKWAXADS1	77	AFDT	432	0.64	45.95	17	Blocking due to abnormal weather, heavy snowfalls, no augument required	
GW012075	EVRTWAXA03T	SMSHWAXADS1	77	AFDT	360	0.85	47.88	10	Blocking due to abnormal weather, heavy snowfalls, no augument required	
GW023827	EVRTWAXA03T	HLLKWAXXDS0	77	AFDT	480	.61	11.78	10	Blocking due to abnormal weather, heavy snowfalls, no augument required	
GW033328	RDMDWAXADS1	SMSHWAXADS1	77	DFOG	72	1.53	80.78	11	Blocking due to abnormal weather, heavy snowfalls, no augument required	
GW033873	BOTHWAXBDS1	LKSTWAXADS1	77	DFIE	48	2.14	50	12	ABN 2 hours blocking 12/30 only, no other overflows, no augument required	
GW069871	WNWCWABADS0	WNWCWAXX01T	77	AFTU	192	4.59	27.76	10	Blocked calls due to under-trunked. Carrier has been notified.	
GW073981	MTVRWAXX05T	STTNWAHODS9	77	AFDT	48	3.58	96.42	10	Hi level blkgr on 12/1 between 15:00-20:00 and on 12/29 between 0900-100 due to trouble at LVC carrier.	
GW084470	EVRTWAAPSP1	EVRTWAXA03T	77	AFDT	120	3.03	43.53	10	Blocking due to abnormal weather, heavy snowfalls, Carrier controlled	
Trunk Group Detail WAC 480-120-401 (5)										
TGID	CLLI-A	CLLI-Z	DIR	TRF TYPE	TRKS	% BLK ABH	% BLK PEAK	PBH	ACTION TAKEN	
GW085027	EVRTWAXA03T	EVRTWAXF9MD	77	DFTD	96	10	100	15	Company appears to be out of business, awaiting credit auditor's findings.	