

**BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION**

**Docket No. \_\_\_\_\_  
Puget Sound Energy, Inc.  
Greenwood Incident**

**WUTC STAFF DATA REQUEST NO. 06**

**RECEIVED**

**MAY 16 2016**

State of Washington  
UTC  
Pipeline Safety Program

**WUTC STAFF DATA REQUEST NO. 06:**

Please provide Atm Corrosion Survey.

**Response:**

The most recent atmospheric corrosion survey for 8411 Greenwood Ave N was performed on 7/17/15 and no indication of atmospheric corrosion was indicated.

**WUTC STAFF SUPPLEMENTAL #1 TO DATA REQUEST NO. 06:**

Need actual atmospheric corrosion survey forms, maps and notes back to 2002. Related to this is DR #26.

**Response:**

Documentation of these surveys has evolved over the years and currently Atmospheric Corrosion inspections are conducted during leak surveys (See DR 04 Leak Survey maps).

The table below provides the Atmospheric Corrosion inspection data from 2002-2016 for 8411 Greenwood. Post 2009 results are only captured for Atmospheric Corrosion greater than Level 2.

<b>Program</b>	<b>Address</b>	<b>Completion Date</b>	<b>Description</b>	<b>Corrosion Rating</b>
Meter Reading	8411 GREENWOOD AVE N	7/22/2004	ATMOSPHERIC CORROSION	2
Meter Reading	8411 GREENWOOD AVE N	6/11/2007	ATMOSPHERIC CORROSION	2