

March 27, 2006

Washington Utilities & Transportation Commission 1300 S. Evergreen Park Drive SW Olympia, WA 98504-7250

Attention: Carole Washburn, Executive Secretary

RE: Report on Net Cost of Removing Customer's facilities

As Ordered in Docket No. UE-001734

Please find enclosed PacifiCorp's report for the period January 1, 2005 through December 31, 2005, in accordance with the Commission's Order in Docket No. UE-001734. This report details the Company's net cost of removing facilities when a customer requests permanent disconnection of service when the Company's facilities to provide service are not likely to be reused at that location, and their removal is necessary for safety and operational reasons.

If you have any questions or required further information, please call me at (503) 331-4446.

Sincerely,

Rob Stewart, Tariff Consultant Customer and Regulatory Liaison

**Enclosures** 

## WUTC Docket No. UE-001734 Net Removal Cost Report January 1 - December 31, 2005

7/11/2005	12/31/2004	5/11/2005	4/14/2005	Date
Scott Williams	Dennis Ledford	Everett Knudson	Doug Majerus	Customer Name
Irrigation	Irrigation	Residential	Commercial	Type of Servic
Remove poles and wires out of backyards. Developer built subdivison under Pacific's existing overhead facilities. CREA installed facilities to serve new lots. Job also included improvement of some facilities	Remove overhead facilities so developer can build 20 lot subdivision. CREA will serve new lots.	Remove overhead service so CREA can serve out of underground transfomer just installed next door	Developer req. facilities removed so he can build 175 lot subdivision	Type of Service Nature of Request
\$3,013 d	\$2,027	\$360	\$2,656	Actual Removal Cost
\$407	\$0	\$0	\$0	Actual Salvage Value*
Remove 1-10kva overhead transformer, 1-3phase cutout arm, 2 cutouts, 30' pole, 35' pole 342' #4 quad secondary cable. Install cutout and 18" cutout arm. Flagging included in job.	Remove 35' pole, crossarms and associated hardware, remove 1 span 7.2kv primary and 2 spans openwire secondary. Deadend remaining primary and install down guy and anchor.	Remove overhead service	Removal of primary riser assembly, pad mount transformer and 1/0 triplex underground service.	Description of Facilities Removed
DWAL/2006/C/DM9/2638104	DWAL/2005/C/DM9/2563655	WALDULM	DWAL/2005/C/DM9/2619714 and order #1005620	Accounts Used to Book Transactions

<sup>\*</sup> Actual salvage Value is Salvage less net book value. Items that can be re-used are returned to inventory. Those that can not be reused are sold for scrap.

Page 1 of 1