Halstead, Lori (UTC)

From: Sent:	Service, Interruption Desk <serviceinterruptiondesk@bnsf.com> Wednesday, September 28, 2016 12:50 AM</serviceinterruptiondesk@bnsf.com>	
To:	OPR DL (SI Desk Use ONLY) North Region Incident; Desk, CNS; CSESDesk; Ha S; Clark, Daniel P; Wootton, Jared T; Moyer, Jason; Surina, Mike I; Halstead, Lc Melonas, Gus S; Wallace, Courtney	
Subject:	092716 RNWE812126I-SemiTruck, Stanwood, WA	
Follow Up Flag: Flag Status:	Follow up Flagged	

One non-employee fatality at a private crossing.

BNSF Fort Worth - Network Operations Center - INCIDENT REPORT

	8.33					D-Code:	1	169273
Date:	092716	Time:	2017-CT	MP:	58.5	Divn:	Northwest	t
Time & Date Last Revised:								
Subdivision: Bellingham State:					Washington	County:	County: Snohomish	
Line Se	gment:	Superior Walter	Sua phre	50				
Neares	t Station:	The second second		Seed Are	North Stanwood, WA			
Neares	t Major Terr	ninal (dista	ance/directi	13 miles South	13 miles South of Burlington, WA			
Weathe	er Condition	s (Temp, w	<mark>rind, precipi</mark>	58*, fair, winds	58*, fair, winds WNW at 7 mph			

Injuries or Fatalities?	1 vehicle occupant fatality and 1 occupant injury (Harbor View Hospital)	Employee?	No	
Name:		Craft:		

Symbol:	R-MWE8121-26I				If Yard Job, is it Remote Control Operation (RCO)?					
Lead Locos:	BNSF 2620, BNSF 2359, BNSF 2349				49 L-E		-T-F:	28-39-5131	L-4852'	
DP Locos:					Dir		ection:	South	36126.0	
Did Lead locomotive have Ditch Lites?			Yes		Were Ditch Lite	's operating?			Yes	
Speed:	Maximum			m Au	Authorized Speed: 60 MPH					
Train Crew's	Origin / Des	tination:	mimosign	08	Burlington, WA / Burlington, WA					100000000000000000000000000000000000000
Conductor:	BC Pratt	a triple of	Enginee	er:	MR	Olson	Other:		B Heigert	are the relay
Prior Rest			Prior Re	est		0.00	Prior Rest		A SAME AND THE	
On Duty Time/Date: 1700-CT/092716			1950 (55)	On Duty Location: Burlington, WA						
Crew Interviewed by: Division Trainmaste				er Elg	jin H	awkins	4743	Y 190 5 -		Company of Section
Event Recorde	Work Request for camera downloads sent to Everett Mechanical.									

Locomotives	video e	equipped?								
Lead Locos	Y/N		Y/N		Y/N		Y/N		Y/N	Y/N
BNSF 2620	Υ	BNSF 2359	N	BNSF 2349	Υ	Marie Marie de M	g 100,000 m	The second section of		3-44
						1. 1		The desired		

Crossing Name:	Private crossing			T Number:	084720A 084723V		
Equipped with:	None		Fur	nctioning?		(A)	
Vehicle Direction:	Southeast	Vehicle Description:	Tra	ctor Trailer	A me	and the second second	
Law Enforcement Ag	jency:	Snohomish Sheriff's Office - Depu Jeffrey Minor, Case #2016-15290		Citations ?		1 10 10 10 10 1	

Cars, Amount: No Release (Y/N): **Haz Material?** Commodity: **Derailed Locomotives / Cars:** Init. Number: Line: Position (upright?): **Contents:** Disposition: No Heavy equipment ordered: Equipment Equip. Equipment Released: ETA: Arrived: Main Estimated Actual 0215-CT/28 Yes **Blocked?** Reopen: Reopen: **Estimated Damages and Costs: Track** Track, Track Structures, and Roadbed Damages. Pending \$ Signal 0 "Other" Adjacent buildings, other private property, etc. 0 \$ Car damage, incl. flat cars but excluding their \$ 0 **Car Damages** trailers/containers and contents. **Locomotive Damages** \$ Pending 0 FRA Reportable Subtotal 2016 FRA Reportable \$10,500 \$ Rerailing & clearing expenses only. Do not include 0 \$ **Contractor Expense** environmental cleanup, air monitoring, etc. Source is usually Damage Prevention/LARS. This 0 **Estimated Lading Recovery Costs** figure includes trucking charges and site remediation charges. 0 **Prelim. Lading Loss Estimates** Railcar/Trailer/Container **Contents ONLY** \$ Excludes contents. 0 **Trailer/Container Damages** (Mktg-Equip Mtce Team - Evita Murdock) 0 \$ **Not FRA Reportable Subtotal** 0 **Estimated Grand Total** (FRA Reportable Subtotal + Not FRA Reportable Subtotal) \$ Cause Code: M-505 Description: Under active investigation Cause: Which Car / Locomotive, etc.? **Brief Narrative of Incident:** 2031-CT/27 Initial report from Chief DS Jeffrey Schubert: R NWE8121 26 has struck a Semi Trailer Truck at MP 58.5 North of Stanwood. Delays to Amtk 517-27 & Amtk 516-27 are expected. 2048-CT/27 Update from Tina in ROCC: Snohomish Sheriff's Office confirms 1 fatality and 1 injuries to non-crew. 0230-CT/28 Initial report from Chief DS Jeffrey Schubert: There is one confirmed fatality and another individual with injuries thought to be somewhat severe transported to hospital, unknown if injuries are life threatening. The crew reported no injuries. There is damage to the lead unit. Track released at 0215CT-28. Post Accident Testing (FRA): Did this incident meet FRA Post Accident Testing criteria? No If the incident analysis indicates the need for FRA Testing, Contact MEH Dept so they can work with the field officer in charge of the testing to insure proper process is followed. (817) 352-1648 during normal business hours. (817) 352-1613 After hours, weekends and holidays. If no answer, then page Dustin Foster or Chris Kowalkowski via Blackberry Yes Did the AGST agree with the above analysis? Was the Mgr. Dispatching Practices and Rules notified? Yes Was the Shipping Box checked prior to use/shipment?

Notifications:

Was the train crew tested?

Was the Dispatcher tested?

Were the vials checked to insure they have not expired?

Which BNSF Mgr took crew for test?

Which BNSF Mgr took Dispr for test?

Time:	Entity:	Person Notified:	Reminders:
2017-CT	Service Interruption:	DDM from DS 81	Include who notified SID.
2017-CT	Resource Operations:	Tina	The first transport of the first fir
2126-CT	Cust. Solutions: 593-4670	All listed. Outlook msg and copy of this report.	Notify them of all derailments, collisions, or shipment damages.
	Outlook Mail: Desk, CNS Cust. Support: 234-1135	cins reporti	A STATE OF THE STA
	Outlook Mail: CSESDesk		Cust Support works 5pm-5am on weekdays and all shifts weekends.
2020-CT	Trainmaster:	Elgin Hawkins. Outlook msg and copy of this report.	Get ETA, check Cell number.
	Road Foreman Engines:		
2035-CT	Signal Desk: 593 - 5998	Sal	Signal Logs, TWD Logs.
2034-CT	M/W Desk: 593-6823/1	Marty	Last track inspn, last B-9 inspn.
2033-CT	Mechanical Desk:	Ron	Emergency car desk 593-9128
2031-CT	Corridor Supt:	Daniel Clark. Outlook msg and copy of this report.	AWES-GROWING
2024-CT	GST/AGST:	Darren Whitten. Outlook msg and copy of this report.	must car
	Divn Supt Operations:		
2031-CT	Divn General Manager:	Jared Wootton. Outlook msg and copy of this report,	
2031-CT	Divn GDT:	Jason Moyer. Outlook msg and copy of this report.	Section and removated TO \$505
2039-CT	Manager Dispatching Practices & Rules: 352-1312	Mike	Tape recordings, including SID and ROC, when appropriate.
2031-CT	Superintendent Operating Practices (All have Blackberry) The following group list is for the following departments: Safety, Law, Rules, Transportation Support, Rules and field Support, Corporate Relations, Government Affairs, and	Mike Surina. Outlook msg and copy of this report.	California, L.A. Chicago Red River Kansas Montana Heartland Northwest Powder River North Powder River South Southwest Twin Cities Page for the following events: 1. Major derailments or train collisions which are expected to exceed 16 hours or \$1,000,000 in damages. 2. Derailments or collisions with evacuations,
	Evidence Preservation Major event group page list (Not MIP) Also page Region VP. (It is located with the SID Locomotive group lists)		explosions, or involving crude oil trains. 3. Major Hazardous Incidents 4. Employee Fatalities, life threatening injuries, or amputations.
	Conference Calls:		If Conf Call is being established: (1) Notify: NOC Mechanical Desk (2) Notify: NOC M/W Desk (3) Notify: ROC
,	Hazardous Incidents: Contact East/West On-call mgrs. If California, notify CUPA.		Page for all Hazardous Incidents: Pat Brady, Piper, Justin, Reid, Clay D, Howard Horn, David C Clark, John D. Lovenburg, Allen Stegman, Laura Fiffick
	ChemTrec (USA) 800-424-9300 CanuTec (Canada)	* ½	Call whenever Haz Matl car involved in derailment or damaged; whether leaking or not.
	1-888-226-8832 or 613-996-6666		Run TSS: WBCOPY & HAZ & EXCR

2059-CT	NRC: (#1) 800 – 424 – 8802 (Initial SID Analysis) Reasons for notifying them now include for significant violence or threats of violence against people or property (02-07-01). NRC: (#2) 800 – 424 – 8802	Kevin Williams Rpt #1160176	Obtain their Report Number and name of person who took the report. This block is for the Initial SID analysis. If initially "not reportable" and later becomes "reportable," use next block.
2025-CT 2056-CT 2030-CT	State:	report to: LHalstead@utc.wa.gov Updated WEO with report of 1 fatality	WEO), Beth - Rpt #16-3607. Copy of this y and 1 injury to non-crew Commission, David Pratt (voice msg)
2030-C1	California - CUPA	washington officies & fransportation	Commission, David Pratt (Voice msg)
	Foreign Railroad:		
C	"Go Team" 1. Alpha Page Mark Schulze. 2. Alpha Page team on duty.		Contact the "Team" that's on duty. If approp., also notify Mark Schulze. (To see Team on duty, go to n/SID/SIDBOTH/GOTEAM).
2038-CT	Passenger Svcs: 352-2606	Claire	If incident involves passenger train route, email copy of report to Rich Wessler , Tamora Noel.
2126-CT	State Corporate Relations:	Melonas and Wallace. Outlook msg and copy of this report.	Notify of all significant Incidents: Gus Melonas and Courtney Wallace: BC, ID, OR, WA Matt Jones: MT, ID Ross Lane: MT, WY Joe Faust: AL, AR, LA, MS, TN, TX Lena Kent: AZ, CA Amy McBeth: MB, MN, ND, SD, WI Andy Williams: KS, MO, NE, IL, KY, IA Joe Sloan: CO, OK, NM, UT, NV
	Energy Desk:		Notify Energy desk of any crude oil train derailments: OPR DL Energy Desk managers or call 817-8670021