

**BEFORE THE WASHINGTON
UTILITIES & TRANSPORTATION COMMISSION**

WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION,

Complainant,

v.

PUGET SOUND ENERGY

Respondent.

DOCKET NOS. UE-190529 and UG-190530 (*Consolidated*)

CARLA A. COLAMONICI ON BEHALF OF PUBLIC COUNSEL UNIT

EXHIBIT CAC-4

Puget Sound Energy Response to Public Counsel Data Request Nos. 93, 96, and 178

November 22, 2019

BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION

**Dockets UE-190529 & UG-190530
Puget Sound Energy
2019 General Rate Case**

PUBLIC COUNSEL DATA REQUEST NO. 093:

Re: Water Heater Rental Program.

Please provide an updated response to Staff's informal data request No. 001 from the Water Heater Rental Program Collaborative. Provide a list of the make, model, and the date of installation of all water heaters currently used by PSE customers participating in the water heater rental program. Please include any repairs and replacements to leased equipment. Please provide the list in Excel in the following format and provide an update to include information through August 23, 2019.

Customer #	Installation Date	Make and Model	Repair	Replacement
1				
2				
3				

Response:

Please see Attachment A to Puget Sound Energy's ("PSE") Response to Public Counsel Data Request No. 093 for a MS Excel spreadsheet showing all water heaters currently used by PSE customers participating in the water heater rental program.

ATTACHMENT A to PSE's Response to PUBLIC COUNSEL Data Request No. 093

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1	01/06/2010	LTN040G	LOCHINVAR	0
2	10/08/1993	FSG40	AO SMITH	1
3	11/01/2000	41XR40	RHEEM	0
4	05/29/2002	FSG40	AO SMITH	0
5	04/10/1995	FGR30	AO SMITH	0
6	05/06/2002	FSG40	AO SMITH	0
7	08/17/2009	LTN040G	LOCHINVAR	0
8	07/16/2011	M45036FBN	BRADFORD-WHITE	1
9	04/18/2005	GVC50	A. O. SMITH	0
10	08/27/2007	LTN040G	LOCHINVAR	0
11	08/25/2010	LTN040GEF	LOCHINVAR	0
12	03/08/1999	FGR50	AO SMITH	0
13	06/21/2011	MI5036FBN	BRADFORD-WHITE	1
14	11/03/2010	21VR40	RHEEM	1
15	07/31/2008	LTN040GEF	LOCHINVAR	0
16	02/12/2011	21VR40	RHEEM	2
17	03/30/2009	LTN050GEF	LOCHINVAR	0
18	05/30/2007	LSN041G	LOCHINVAR	2
19	03/18/2005	XVR40	A. O. SMITH	0
20	05/03/2005	LTN050	LOCHINVAR	0
21	03/09/2012	M45036FBN	BRADFORD-WHITE	0
22	01/22/2007	LTN040G	LOCHINVAR	0
23	07/15/2002	FSG40	AO SMITH	0
24	12/13/2002	PGR30	AO SMITH	0
25	12/10/2007	LTN050GEF	LOCHINVAR	0
26	05/21/2003	PGR50	AO SMITH	0
27	11/26/2007	LTN050GEF	LOCHINVAR	0
28	12/14/2009	PRX50	STATE	2
29	12/04/2005	LTN051G	LOCHINVAR	0
30	05/17/2001	FSG50	AO SMITH	0
31	07/31/2012	M45036FBN	BRADFORD-WHITE	0
32	09/26/2001	FSG50	AO SMITH	0
33	02/07/2001	41V50	RHEEM	0
34	06/23/2003	FSG50	AO SMITH	0
35	03/02/2009	LTN050GEF	LOCHINVAR	0
36	11/06/2002	FSGL40	AO SMITH	0
37	02/13/2007	FSG50	AO SMITH	0
38	04/14/1988	FSG50	AO SMITH	0
39	10/29/2000	41XR40	RHEEM	0
40	12/13/1988	FSG50	AO SMITH	0
41	04/09/2003	FSG50	AO SMITH	0
42	11/23/2011	MI5036FBN	BRADFORD-WHITE	0
43	08/21/1998	FGR50	AO SMITH	1
44	06/28/1999	FSG50	AO SMITH	0
45	05/17/2006	LTN050G	LOCHINVAR	0
46	10/16/2006	PR650X0DS	STATE	0
47	04/14/2011	41VR50	RHEEM	0
48	02/20/2005	XVR50	A. O. SMITH	0
49	09/13/2006	PR650	STATE	0
50	12/27/2008	LTN050GEF	LOCHINVAR	0
51	03/17/2000	FSG50	AO SMITH	0
52	05/27/2000	41XR50	RHEEM	0
53	03/21/2012	M45036FBN	BRADFORD-WHITE	0
54	12/07/2011	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
55	09/27/1997	41XR50	RHEEM	0
56	04/30/2003	FSG50	AO SMITH	1
57	11/03/2006	LTN050G	LOCHINVAR	0
58	06/05/2009	LTN050GEF	LOCHINVAR	1
59	01/11/2002	PGR50	AO SMITH	0
60	06/01/2011	22DV50F	RHEEM	0
61	08/29/2005	LTN050G	LOCHINVAR	0
62	10/19/2004	PGR50	AO SMITH	0
63	02/04/2004	FCV50	AO SMITH	0
64	05/25/1988	FSG50	AO SMITH	0
65	04/13/2005	GVC50	A. O. SMITH	0
66	09/23/1988	PRX50	STATE	0
67	11/02/1970	PGX40	AO SMITH	0
68	06/20/2007	LTN050G	LOCHINVAR	1
69	08/25/2010	GVC50	A. O. SMITH	0
70	05/18/2000	21V506	RHEEM	0
71	06/22/2005	LTN050	LOCHINVAR	0
72	01/19/2005	GVC50	A. O. SMITH	0
73	05/24/1995	PR502T	RUUD	0
74	07/31/2009	LSN041G	LOCHINVAR	0
75	12/01/1970	A71DUMMY	UNKNOWN AT CONVERSION	0
76	03/22/1994	FGR50	AO SMITH	1
77	04/16/2007	LTN050G	LOCHINVAR	0
78	06/28/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
79	11/03/2005	LTN040G	LOCHINVAR	0
80	10/19/2008	LTN050GEF	LOCHINVAR	0
81	02/19/2008	LTN050GEF	LOCHINVAR	0
82	11/10/2005	LTN050GEF	LOCHINVAR	1
83	01/01/2006	LTN050G	LOCHINVAR	0
84	04/18/2003	PGR50	AO SMITH	2
85	01/09/2003	FSG40	AO SMITH	0
86	12/13/2010	21VR50	RHEEM	0
87	04/01/1971	PGX40	AO SMITH	0
88	10/12/2000	21V506	RHEEM	0
89	05/18/1997	FSG50	AO SMITH	0
90	04/20/2001	FSG40	AO SMITH	0
91	10/09/2007	G75125	RUUD/RHEEM	0
92	04/11/2007	LTN040G	LOCHINVAR	0
93	10/15/2012	MI40T6FBN	BRADFORD-WHITE	1
94	06/24/2010	LSN041G	LOCHINVAR	1
95	03/31/2011	PH199119	PHOENIX	1
96	07/25/2012	M45036FBN	BRADFORD-WHITE	0
97	03/07/1997	PGR40	AO SMITH	0
98	07/28/2012	MI40T6FBN	BRADFORD-WHITE	0
99	07/04/1998	FGR40	AO SMITH	0
100	01/27/2010	LTN050GEF	LOCHINVAR	0
101	07/08/2000	FSG50	AO SMITH	0
102	12/06/2007	LTN040G	LOCHINVAR	0
103	03/29/2003	FSGL40	AO SMITH	0
104	11/21/2011	G75125	RUUD/RHEEM	0
105	08/14/2008	RM5063	RHEEM	0
106	04/17/2003	BTC198	AO SMITH	0
107	01/28/2009	LTN050GEF	LOCHINVAR	0
108	09/10/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
109	10/09/1992	P506	RUUD	0
110	12/16/2010	21V502	RHEEM	2
111	01/23/2004	XTN040	LOCHINVAR	0
112	09/03/2008	FSG30	AO SMITH	2
113	03/31/2000	FSG40	AO SMITH	0
114	03/23/2009	LTN050GEF	LOCHINVAR	0
115	06/27/2005	LTN050	LOCHINVAR	2
116	09/29/2003	PGR50	AO SMITH	0
117	01/10/2009	LTN040GEF	LOCHINVAR	0
118	09/22/2004	GVC50	A. O. SMITH	1
119	11/17/1988	FSG40	AO SMITH	0
120	03/21/1995	PR407	RUUD	0
121	10/04/2011	M440T6FBN	BRADFORD-WHITE	0
122	03/25/2002	PGR50	AO SMITH	0
123	06/13/2012	MI403S6FBN	BRADFORD-WHITE	0
124	06/29/2009	LTN050GEF	LOCHINVAR	0
125	09/12/2011	M45036FBN	BRADFORD-WHITE	0
126	10/01/1968	FSGL40	AO SMITH	0
127	11/21/1997	FSG40	AO SMITH	1
128	11/27/1995	PR502T	RUUD	0
129	12/11/2009	LSN041G	LOCHINVAR	0
130	07/22/2003	FSG40	AO SMITH	0
131	12/21/2001	41XR50	RHEEM	0
132	10/09/2001	FSGL40	AO SMITH	0
133	05/17/2005	LTN050	LOCHINVAR	1
134	01/13/2001	41V40	RHEEM	0
135	01/03/2002	FSG40	AO SMITH	0
136	08/01/1966	E71DUMMY	UNKNOWN AT CONVERSION	0
137	05/11/2007	XSN040	LOCHINVAR	0
138	08/18/1999	FSG50	AO SMITH	1
139	03/24/2009	LTN040GEF	LOCHINVAR	0
140	08/17/2012	MI40T6FBN	BRADFORD-WHITE	0
141	07/21/2008	LTN040GEF	LOCHINVAR	2
142	06/09/2000	FSG30	AO SMITH	0
143	02/01/1965	PGX30	AO SMITH	0
144	09/17/2007	LTN050GEF	LOCHINVAR	0
145	05/29/2001	41XR40	RHEEM	0
146	10/27/1995	FGR30	AO SMITH	0
147	07/12/2007	LTN040G	LOCHINVAR	0
148	12/26/2003	FCV50	AO SMITH	0
149	04/05/2001	FSG50	AO SMITH	0
150	02/07/2005	GVC40	A. O. SMITH	2
151	05/30/2003	FSG40	AO SMITH	0
152	03/18/2008	LTN040GEF	LOCHINVAR	0
153	02/18/1997	G91200	RUUD/RHEEM	1
154	05/04/1998	FGR50	AO SMITH	0
155	09/18/1998	41VR50	RHEEM	0
156	07/17/2002	FSG40	AO SMITH	0
157	04/05/2000	PGR40	AO SMITH	0
158	11/04/2008	LTN040GEF	LOCHINVAR	0
159	09/20/2012	G91200	RUUD/RHEEM	0
160	10/28/2011	MI403S6FBN	BRADFORD-WHITE	0
161	04/06/2004	FCV40	AO SMITH	0
162	07/01/1966	PGX40	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
163	02/07/2013	M45036FBN	BRADFORD-WHITE	0
164	03/27/2009	LTN050GEF	LOCHINVAR	0
165	12/17/2009	LTN050GEF	LOCHINVAR	1
166	03/21/2002	FSG40	AO SMITH	0
167	12/04/2012	M45036FBN	BRADFORD-WHITE	1
168	11/18/2009	LSN041G	LOCHINVAR	0
169	07/09/2004	GVC40	A. O. SMITH	0
170	12/22/2001	G75125	RUUD/RHEEM	1
171	03/14/2012	M440T6FBN	BRADFORD-WHITE	1
172	03/07/2003	PGR40	AO SMITH	0
173	01/23/2007	LSN041G	LOCHINVAR	0
174	11/08/2004	GVC40	A. O. SMITH	0
175	05/03/2000	FSG40	AO SMITH	0
176	09/20/2011	M45036FBN	BRADFORD-WHITE	0
177	06/20/2001	FSG40	AO SMITH	0
178	11/08/2012	LTN040GEF	LOCHINVAR	0
179	08/24/2001	FSGL40	AO SMITH	0
180	10/16/2008	LTN040G	LOCHINVAR	0
181	07/03/2010	LTN040G	LOCHINVAR	0
182	03/27/2007	LTN050G	LOCHINVAR	0
183	09/12/2012	M440T6FBN	BRADFORD-WHITE	0
184	07/23/2003	FSG30	AO SMITH	0
185	06/09/2011	41VR40	RHEEM	0
186	08/12/2010	LTN050GEF	LOCHINVAR	0
187	12/02/1993	FGR50	AO SMITH	0
188	03/10/1999	21V407	RHEEM	0
189	01/18/2011	LTN040GEF	LOCHINVAR	0
190	01/03/1999	FSGL40	AO SMITH	0
191	06/03/2009	LTN050GEF	LOCHINVAR	0
192	12/21/2004	GVC30	AOSMITH	1
193	05/26/2012	G91200	RUUD/RHEEM	3
194	11/06/2002	PGR50	AO SMITH	0
195	05/22/2007	G75125	RUUD/RHEEM	0
196	01/11/1999	PHR50	RUUD	0
197	03/06/1998	G67114	RHEEM	0
198	10/17/2011	M440T6FBN	BRADFORD-WHITE	0
199	04/10/2001	FSG40	AO SMITH	0
200	05/23/2009	LTN050GEF	LOCHINVAR	0
201	06/28/2012	G91200	RUUD/RHEEM	1
202	01/29/2013	E71DUMMY	UNKNOWN AT CONVERSION	0
203	01/15/1999	FSG50	AO SMITH	0
204	08/25/1999	FSG50	AO SMITH	0
205	06/03/2009	LTN040GEF	LOCHINVAR	0
206	01/26/2010	LTN050GEF	LOCHINVAR	0
207	08/01/1964	PGX30	AO AMITH	0
208	02/06/2012	M440T6FBN	BRADFORD-WHITE	0
209	01/22/2004	PVR40	AO SMITH	0
210	09/30/1999	G72DUMMY	AO SMITH	0
211	10/22/2010	21VR40	RHEEM	0
212	10/19/2011	M45036FBN	BRADFORD-WHITE	0
213	02/06/2004	PVR40	AO SMITH	1
214	06/19/2004	GVC40	A. O. SMITH	0
215	11/03/2000	FSG40	AO SMITH	1
216	08/11/1994	PGR30	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
217	05/26/2011	41VR50	RHEEM	2
218	11/08/2000	FSG40	AO SMITH	0
219	02/22/2013	MI5036FBN	BRADFORD-WHITE	1
220	06/30/2009	LTN030G	AO SMITH	1
221	01/06/2010	LTN040GEF	LOCHINVAR	0
222	02/07/2008	LTN040G	LOCHINVAR	1
223	03/10/2008	LTN040GEF	LOCHINVAR	0
224	01/18/2013	MI40T6FBN	BRADFORD-WHITE	0
225	12/08/2011	M440T6FBN	BRADFORD-WHITE	0
226	07/19/1993	FSG40	AO SMITH	0
227	03/26/2002	FSG30	AO SMITH	0
228	08/11/2009	LSN041G	LOCHINVAR	0
229	08/23/2002	FSG50	AO SMITH	0
230	12/26/2007	LTN040GEF	LOCHINVAR	1
231	03/14/2010	LTN040GEF	LOCHINVAR	0
232	08/24/2012	M45036FBN	BRADFORD-WHITE	0
233	08/16/2001	FSG40	AO SMITH	0
234	02/15/2013	M45036FBN	BRADFORD-WHITE	0
235	03/06/2009	LTN050GEF	LOCHINVAR	0
236	10/04/2009	LTN050GEF	LOCHINVAR	0
237	03/04/2010	LTN040GEF	LOCHINVAR	0
238	01/18/2001	FSGL40	AO SMITH	0
239	05/01/1967	PGXL40	AO SMITH	0
240	06/27/2006	LTN050G	LOCHINVAR	1
241	10/01/1967	KGA40	AO SMITH	0
242	05/06/2011	21VR40	RHEEM	0
243	05/17/2008	LTN050GEF	LOCHINVAR	0
244	06/09/2003	FSG50	AO SMITH	0
245	05/15/2006	LTN040G	LOCHINVAR	0
246	01/19/2004	FCV30	AO SMITH	0
247	07/13/1998	G72DUMMY	AO SMITH	0
248	02/13/2001	FSG40	AO SMITH	0
249	05/25/2011	21VR40	RHEEM	0
250	01/02/2011	21VR40	RHEEM	0
251	12/14/2009	LTN040GEF	LOCHINVAR	2
252	07/05/2005	LSN041G	LOCHINVAR	0
253	12/13/2001	PGR50	AO SMITH	0
254	01/21/2011	42VR50	RHEEM	0
255	07/17/2009	LTN050G	LOCHINVAR	1
256	05/16/2008	LTN050GEF	LOCHINVAR	0
257	12/08/1997	G67114	RHEEM	0
258	04/06/1998	FSG30	AO SMITH	0
259	11/21/2003	FCV40	AO SMITH	0
260	07/16/2001	41VR50	RHEEM	0
261	09/01/2011	M45036FBN	BRADFORD-WHITE	1
262	09/12/2002	FSGL40	AO SMITH	0
263	11/26/2002	BTR154	AO SMITH	0
264	04/10/2001	41XR40	RHEEM	0
265	01/08/1996	PGR50	AO SMITH	0
266	01/11/2005	GVC30	AOSMITH	0
267	11/15/2012	MI403S6FBN	BRADFORD-WHITE	0
268	02/16/2009	LTN040GEF	LOCHINVAR	0
269	10/18/1998	FSG40	AO SMITH	0
270	02/01/1981	KGA30	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
271	04/25/2011	FSG30	AO SMITH	0
272	09/08/1997	FSG30	AO SMITH	1
273	02/08/2007	LTN050G	LOCHINVAR	0
274	04/06/1988	21V506	RHEEM	0
275	03/18/1999	FGR50	AO SMITH	0
276	01/14/2005	GVC30	AOSMITH	2
277	03/29/2012	MI403S6FBN	BRADFORD-WHITE	0
278	03/23/2006	LTN050G	LOCHINVAR	0
279	11/06/2001	FSG40	AO SMITH	0
280	08/06/2010	LTN040GEF	LOCHINVAR	0
281	05/21/2001	41XR50	RHEEM	0
282	01/29/2001	FSG30	AO SMITH	0
283	10/18/2012	M45036FBN	BRADFORD-WHITE	0
284	01/26/2012	MI5036FBN	BRADFORD-WHITE	0
285	04/09/2008	LTN040GEF	LOCHINVAR	1
286	09/03/2011	P230F	RUUD	0
287	08/19/2004	GVC40	A. O. SMITH	0
288	08/14/2003	FSG30	AO SMITH	0
289	03/26/2001	21V407	RHEEM	0
290	05/29/1998	FSG30	AO SMITH	0
291	04/08/2005	XVR50	A. O. SMITH	1
292	10/04/2010	LTN040GEF	LOCHINVAR	0
293	03/27/2012	MI403S6FBN	BRADFORD-WHITE	1
294	02/19/2012	MI5036FBN	BRADFORD-WHITE	0
295	05/25/2005	LTN050	LOCHINVAR	0
296	06/15/2011	M45036FBN	BRADFORD-WHITE	0
297	09/05/2008	LTN040GEF	LOCHINVAR	0
298	03/11/2010	LSN041G	LOCHINVAR	2
299	01/20/2009	ETN076	LOCHINVAR	0
300	04/24/2001	FSG40	AO SMITH	0
301	10/13/2008	LTN040GEF	LOCHINVAR	0
302	11/09/2007	LTN040G	LOCHINVAR	1
303	01/11/2005	GVR50	AO SMITH	0
304	01/01/1960	A71DUMMY	UNKNOWN AT CONVERSION	0
305	03/19/2008	LTN040	LOCHINVAR	0
306	06/05/2003	FGR40	AO SMITH	0
307	10/27/2004	GVC50	A. O. SMITH	2
308	07/24/1969	A71DUMMY	UNKNOWN AT CONVERSION	0
309	10/26/2004	42XR50	RHEEM	0
310	05/03/2005	LSN041G	LOCHINVAR	1
311	06/01/2007	LTN040GEF	LOCHINVAR	0
312	06/19/2007	LSN041G	LOCHINVAR	0
313	11/10/2004	XVR40	A. O. SMITH	0
314	10/28/2011	FSGL40	AO SMITH	0
315	03/17/2011	42VR50	RHEEM	0
316	02/23/2006	LTN050G	LOCHINVAR	1
317	05/10/2005	GVC40	A. O. SMITH	0
318	10/20/2009	ETN076	LOCHINVAR	1
319	08/11/2010	22DV50F	RHEEM	0
320	10/05/2010	41V50	RHEEM	0
321	10/01/2001	41V40S	RHEEM	0
322	06/12/1996	PR407	RUUD	1
323	11/14/2007	LTN040GEF	LOCHINVAR	0
324	01/29/2001	41XR40	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
325	02/17/2012	MI5036FBN	BRADFORD-WHITE	0
326	11/14/2008	LTN040G	LOCHINVAR	0
327	10/01/2008	LTN050GEF	LOCHINVAR	0
328	02/04/2011	LTN050GEF	LOCHINVAR	0
329	09/12/2002	FSGL40	AO SMITH	0
330	08/30/2010	LTN030G	AO SMITH	0
331	06/20/2012	M45036FBN	BRADFORD-WHITE	0
332	04/03/2009	LTN040GEF	LOCHINVAR	0
333	02/29/2000	FSG50	AO SMITH	0
334	08/26/1997	RFD91200	RUUD	2
335	06/29/2012	P230F	RUUD	0
336	02/10/2000	FSG40	AO SMITH	0
337	06/21/2012	P230F	RUUD	1
338	02/04/2000	G91200	RUUD/RHEEM	0
339	01/06/2009	LSN041G	LOCHINVAR	0
340	12/17/2012	MI403S6FBN	BRADFORD-WHITE	0
341	06/15/2010	LTN040G	LOCHINVAR	0
342	08/06/1996	FGR50	AO SMITH	0
343	09/14/2010	ETN076	LOCHINVAR	0
344	03/01/2004	41VR50	RHEEM	0
345	08/03/1993	FSGL40	AO SMITH	0
346	09/04/2002	PGR40	AO SMITH	0
347	02/13/2012	G91200	RUUD/RHEEM	0
348	03/09/2000	41XR40	RHEEM	0
349	05/05/2003	41V50S	RHEEM	0
350	02/16/2007	LTN040G	LOCHINVAR	1
351	11/04/2011	MI40T6FBN	BRADFORD-WHITE	0
352	02/01/2012	G82156	RUUD/RHEEM	0
353	08/29/1999	41V40S	RHEEM	0
354	08/08/2009	FSG50	AO SMITH	0
355	12/16/2008	LTN040GEF	LOCHINVAR	0
356	09/22/2001	FSG50	AO SMITH	0
357	11/04/2011	FSG40	AO SMITH	0
358	02/22/1977	RM5063	RHEEM	0
359	10/05/2008	LTN050GEF	LOCHINVAR	2
360	12/07/2006	FGR50	AO SMITH	0
361	05/27/1991	FSGL40	AO SMITH	0
362	06/30/2002	PGR50	AO SMITH	0
363	08/07/2001	FSG30	AO SMITH	0
364	05/03/1997	G72DUMMY	AO SMITH	0
365	08/29/2002	PGR50	AO SMITH	0
366	12/20/2005	GVC50	A. O. SMITH	0
367	12/12/1984	41XR50	RHEEM	0
368	07/08/2010	LTN040GEF	LOCHINVAR	0
369	03/31/2008	LTN040	LOCHINVAR	1
370	01/01/1960	G82156	RUUD/RHEEM	0
371	10/23/2012	LTN050	LOCHINVAR	0
372	01/07/2009	PH199119	PHOENIX	1
373	02/06/2004	XTN050	LOCHINVAR	0
374	10/03/2007	LTN040G	LOCHINVAR	0
375	03/21/2007	LTN040G	LOCHINVAR	0
376	06/02/2005	LTN050	LOCHINVAR	0
377	04/01/1965	PGX30	AO SMITH	0
378	07/03/2008	LTN040G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
379	01/11/2006	LTN050GEF	LOCHINVAR	0
380	02/02/2007	LTN040G	LOCHINVAR	0
381	10/04/1999	FSG40	AO SMITH	1
382	01/24/2011	21VR50	RHEEM	0
383	03/07/2008	LTN050	LOCHINVAR	0
384	03/17/2006	LTN050G	LOCHINVAR	0
385	02/10/2004	FSG30	AO SMITH	0
386	12/01/2012	G75125	RUUD/RHEEM	0
387	05/10/2004	G91200	RUUD/RHEEM	2
388	03/24/2001	21V506	RHEEM	0
389	02/26/2013	G91200	RUUD/RHEEM	0
390	08/15/2004	GVC40	A. O. SMITH	0
391	06/25/1999	G82156	RUUD/RHEEM	0
392	09/05/2002	FSG40	AO SMITH	1
393	11/04/2005	LTN050GEF	LOCHINVAR	0
394	03/30/1996	FGR40	AO SMITH	0
395	03/03/1995	G76200	RUUD/RHEEM	0
396	03/03/1995	G76200	RUUD/RHEEM	0
397	12/15/2009	LSN041G	LOCHINVAR	0
398	11/28/2012	M45036FBN	BRADFORD-WHITE	0
399	01/12/2010	LTN050GEF	LOCHINVAR	0
400	08/18/2010	G82156	RUUD/RHEEM	0
401	04/28/2010	LTN050GEF	LOCHINVAR	0
402	03/31/2010	RF82156	RUUD	0
403	11/15/2001	41XR50	RHEEM	0
404	05/29/2008	LSN041G	LOCHINVAR	1
405	04/18/2008	LSN041	LOCHINVAR	0
406	10/31/2007	LSN041G	LOCHINVAR	0
407	05/27/2008	LTN050GEF	LOCHINVAR	0
408	08/01/1971	PGX40	AO SMITH	0
409	12/22/2006	LSN041G	LOCHINVAR	0
410	10/23/2009	LTN040GEF	LOCHINVAR	0
411	05/14/2002	PGR40	AO SMITH	0
412	04/21/2007	LTN050G	LOCHINVAR	0
413	08/20/2008	PH199119	PHOENIX	0
414	04/19/2000	41V40S	RHEEM	0
415	10/09/2012	MI40T6FBN	BRADFORD-WHITE	0
416	09/01/2011	M440T6FBN	BRADFORD-WHITE	1
417	04/11/2012	M45036FBN	BRADFORD-WHITE	0
418	07/20/2009	LSN041G	LOCHINVAR	0
419	12/26/2007	LTN050G	LOCHINVAR	0
420	12/06/1996	G76200	RUUD/RHEEM	0
421	11/08/2006	LSN041G	LOCHINVAR	0
422	12/19/2001	G91200	RUUD/RHEEM	1
423	09/29/2012	M440T6FBN	BRADFORD-WHITE	0
424	01/20/2010	41VR50	RHEEM	0
425	10/01/2002	FSG50	AO SMITH	0
426	09/28/2012	M45036FBN	BRADFORD-WHITE	1
427	08/08/2000	PHR40	RUUD	0
428	04/19/2004	FCV50	AO SMITH	0
429	06/04/1965	PGX30	AO SMITH	0
430	03/27/2003	FSG50	AO SMITH	0
431	05/11/2007	XVR50	A. O. SMITH	0
432	12/04/2010	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
433	11/30/2006	LSN041G	LOCHINVAR	0
434	05/24/2001	FSG40	AO SMITH	0
435	02/17/2007	LTN040G	LOCHINVAR	1
436	10/08/2009	FGR50	AO SMITH	0
437	01/05/2006	LTN040G	LOCHINVAR	1
438	06/30/2005	LTN040	LOCHINVAR	1
439	06/30/2008	LTN050GEF	LOCHINVAR	0
440	02/17/2000	41V50	RHEEM	0
441	10/04/2010	ETN076	LOCHINVAR	0
442	07/26/2001	21V407	RHEEM	0
443	03/17/2005	GVC40	A. O. SMITH	0
444	06/01/2004	GCVL40	A. O. SMITH	0
445	07/09/2001	PGR50	AO SMITH	0
446	08/16/2012	MI40T6FBN	BRADFORD-WHITE	0
447	01/26/2001	FSG50	AO SMITH	0
448	02/26/2009	41VR50	RHEEM	1
449	02/20/1994	PGR40	AO SMITH	0
450	04/25/2003	FGR40	AO SMITH	0
451	10/06/2011	22V30F	RHEEM	0
452	07/24/2000	PGR50	AO SMITH	0
453	06/13/2008	LSN041G	LOCHINVAR	0
454	05/21/2006	LTN040G	LOCHINVAR	0
455	05/21/2009	LTN050G	LOCHINVAR	0
456	07/24/2010	LTN050GEF	LOCHINVAR	0
457	01/19/2010	LTN040G	LOCHINVAR	0
458	04/22/2006	LTN050G	LOCHINVAR	0
459	08/06/2004	G75125	RUUD/RHEEM	0
460	03/21/2007	XTN050	LOCHINVAR	0
461	06/28/2011	MI403S6FBN	BRADFORD-WHITE	1
462	04/15/2011	21VR40	RHEEM	0
463	07/29/2008	LTN050G	LOCHINVAR	0
464	07/27/2010	LSN041G	LOCHINVAR	0
465	08/31/2005	LTN040	LOCHINVAR	0
466	03/20/2009	LTN050GEF	LOCHINVAR	0
467	02/07/2007	LTN040G	LOCHINVAR	0
468	03/31/2008	LTN040GEF	LOCHINVAR	0
469	09/11/2001	FSG50	AO SMITH	0
470	01/02/2013	G75125	RUUD/RHEEM	0
471	11/29/2007	LTN050GEF	LOCHINVAR	1
472	07/10/2012	M45036FBN	BRADFORD-WHITE	0
473	01/23/1998	FSG40	AO SMITH	3
474	05/01/2009	LTN040GEF	LOCHINVAR	0
475	01/18/2007	LTN040GEF	LOCHINVAR	2
476	10/16/2009	FSG50	AO SMITH	1
477	05/18/2010	FSG30	AO SMITH	0
478	06/12/2009	G75125	RUUD/RHEEM	0
479	12/22/2005	LTN040GEF	LOCHINVAR	0
480	06/29/2005	LSN041G	LOCHINVAR	0
481	06/09/2008	LTN040GEF	LOCHINVAR	0
482	10/02/2011	M440T6FBN	BRADFORD-WHITE	0
483	05/01/1996	FGR40	AO SMITH	0
484	11/08/2011	M45036FBN	BRADFORD-WHITE	0
485	05/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	0
486	10/15/2009	LTN040GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
487	08/03/2010	LTN040GEF	LOCHINVAR	0
488	06/10/2009	LTN040G	LOCHINVAR	0
489	02/02/2012	M45036FBN	BRADFORD-WHITE	0
490	03/22/2012	M45036FBN	BRADFORD-WHITE	1
491	06/12/2000	G72DUMMY	AO SMITH	0
492	10/27/2001	21V407	RHEEM	0
493	02/11/2009	LTN050GEF	LOCHINVAR	1
494	05/14/1997	FSGL40	AO SMITH	0
495	10/18/2011	MI5036FBN	BRADFORD-WHITE	4
496	04/11/2001	PGR50	AO SMITH	0
497	06/12/2000	FSGL40	AO SMITH	0
498	08/13/2010	LTN050G	LOCHINVAR	0
499	01/27/2009	LTN040GEF	LOCHINVAR	0
500	03/02/2007	G75125	RUUD/RHEEM	0
501	06/16/2011	G91200	RUUD/RHEEM	1
502	06/04/2005	LTN050	LOCHINVAR	0
503	07/22/2010	LTN040G	LOCHINVAR	0
504	03/11/2012	MI5036FBN	BRADFORD-WHITE	1
505	05/25/2011	21VR50	RHEEM	0
506	06/29/1996	FSGL40	AO SMITH	0
507	02/16/2002	FSGL40	AO SMITH	0
508	12/20/2006	LTN050GEF	LOCHINVAR	0
509	11/26/2002	PGR50	AO SMITH	0
510	06/06/2005	LTN050G	LOCHINVAR	0
511	09/24/1997	PGR50	AO SMITH	0
512	08/31/1998	FSG40	AO SMITH	0
513	01/15/2008	PH199119	PHOENIX	1
514	10/10/1996	PGR50	AO SMITH	0
515	08/21/2008	LTN040GEF	LOCHINVAR	0
516	07/17/2003	FSG40	AO SMITH	0
517	10/06/1992	FSG40	AO SMITH	0
518	05/01/2009	LTN050GEF	LOCHINVAR	0
519	07/12/2011	LTN050G	LOCHINVAR	0
520	11/30/2011	MI403S6FBN	BRADFORD-WHITE	1
521	11/16/2000	FSGL40	AO SMITH	1
522	09/22/2006	LTN040G	LOCHINVAR	1
523	02/15/2005	LTN040	LOCHINVAR	0
524	07/08/2011	21V506	RHEEM	0
525	04/15/2012	G91200	RUUD/RHEEM	0
526	06/04/2003	FSG50	AO SMITH	0
527	01/01/1986	P506	RUUD	0
528	03/04/2013	MI50L6FBN	BRADFORD-WHITE	0
529	09/24/2009	LTN050GEF	LOCHINVAR	0
530	09/26/2011	MI40T6FBN	BRADFORD-WHITE	0
531	08/30/2011	MI403S6FBN	BRADFORD-WHITE	0
532	08/22/2012	RF82156	RUUD	1
533	11/13/1989	FSG40	AO SMITH	0
534	12/08/2005	LTN040G	LOCHINVAR	0
535	09/22/2011	M45036FBN	BRADFORD-WHITE	0
536	11/29/2000	FSG40	AO SMITH	0
537	10/20/2009	LTN040GEF	LOCHINVAR	0
538	08/27/1999	FGR40	AO SMITH	0
539	01/20/1999	41VR50	RHEEM	0
540	09/14/1998	G76200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
541	02/15/2006	LTN040GEF	LOCHINVAR	0
542	11/08/2007	LTN050GEF	LOCHINVAR	0
543	06/17/2010	LTN040GEF	LOCHINVAR	0
544	09/15/2001	FSG30	AO SMITH	0
545	02/18/2004	FSGL40	AO SMITH	0
546	10/18/2009	PRV50NODS	STATE	2
547	03/26/2002	FSG30	AO SMITH	1
548	03/04/2013	MI40T6FBN	BRADFORD-WHITE	0
549	05/04/2009	LTN040GEF	LOCHINVAR	0
550	02/15/2012	M45036FBN	BRADFORD-WHITE	0
551	08/20/2004	FCV50	AO SMITH	0
552	02/10/1996	PR407	RUUD	0
553	12/20/2012	MI5036FBN	BRADFORD-WHITE	0
554	01/05/2008	LTN040G	LOCHINVAR	0
555	01/27/2009	LTN040G	LOCHINVAR	0
556	08/11/2000	FSG50	AO SMITH	0
557	02/15/2002	FSG40	AO SMITH	0
558	01/01/1973	PGX40	AO SMITH	0
559	03/04/2004	FCV50	AO SMITH	0
560	01/25/2010	LTN050GEF	LOCHINVAR	0
561	10/26/2001	FSG40	AO SMITH	0
562	12/21/2004	GVC40	A. O. SMITH	3
563	02/23/2005	GVC40	A. O. SMITH	0
564	01/31/2002	H72DUMMY	AO SMITH	0
565	05/10/2011	42VR50	RHEEM	0
566	08/15/2007	LTN050GEF	LOCHINVAR	1
567	04/26/2012	M45036FBN	BRADFORD-WHITE	0
568	09/10/1997	PGR50	AO SMITH	0
569	03/11/2005	GCVL40	A. O. SMITH	0
570	06/15/2006	G76200	RUUD/RHEEM	0
571	02/10/2009	FSG30	AO SMITH	0
572	01/19/2001	41VR40	RHEEM	0
573	12/18/2007	LTN050G	LOCHINVAR	0
574	08/22/2012	G82156	RUUD/RHEEM	0
575	03/01/1980	FSG50	AO SMITH	0
576	03/31/1997	PGR40	AO SMITH	0
577	10/27/2006	LTN050G	LOCHINVAR	0
578	03/22/1999	41VR40	RHEEM	0
579	05/25/2004	FCV40	AO SMITH	0
580	07/27/1999	FSG40	AO SMITH	0
581	08/27/2005	LTN050	LOCHINVAR	1
582	09/14/2012	MI5036FBN	BRADFORD-WHITE	0
583	10/31/2012	MI40T6FBN	BRADFORD-WHITE	0
584	11/20/2002	FSG50	AO SMITH	0
585	11/27/2012	M440T6FBN	BRADFORD-WHITE	1
586	05/21/2011	21VR40	RHEEM	0
587	02/25/2013	MI403S6FBN	BRADFORD-WHITE	0
588	08/17/2011	M45036FBN	BRADFORD-WHITE	0
589	03/15/2007	LTN050GEF	LOCHINVAR	0
590	09/19/2003	FSG30	AO SMITH	0
591	04/19/2009	LSN041G	LOCHINVAR	0
592	05/01/1966	A71	UNKNOWN	0
593	06/27/1989	FSG50	AO SMITH	0
594	10/26/2005	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
595	08/19/2007	LTN040GEF	LOCHINVAR	0
596	04/16/2004	41V40	RHEEM	0
597	02/06/2000	41XR40	RHEEM	0
598	02/27/2007	LTN050G	LOCHINVAR	0
599	02/18/2008	LTN050GEF	LOCHINVAR	1
600	09/22/2005	LTN050	LOCHINVAR	0
601	05/21/2009	LTN050G	LOCHINVAR	0
602	02/01/1971	PGX50	AO SMITH	0
603	05/09/2011	21VR40	RHEEM	0
604	01/28/1999	41VR50	RHEEM	0
605	06/16/2009	LTN050GEF	LOCHINVAR	0
606	03/07/2001	PGR50	AO SMITH	0
607	10/30/2006	LTN040G	LOCHINVAR	0
608	03/18/2011	21V506	RHEEM	0
609	08/22/2007	LTN050GEF	LOCHINVAR	0
610	11/05/2010	42VR50	RHEEM	0
611	10/21/2011	MI40T6FBN	BRADFORD-WHITE	0
612	03/23/2009	LSN041G	LOCHINVAR	0
613	05/15/2005	LTN050	LOCHINVAR	2
614	01/27/1999	FSG30	AO SMITH	0
615	08/21/2001	PGR50	AO SMITH	0
616	08/19/2010	LTN050GEF	LOCHINVAR	0
617	04/13/2009	LTN050G	LOCHINVAR	0
618	09/06/2006	LTN050G	LOCHINVAR	0
619	01/26/1991	P506	RUUD	1
620	02/10/2011	22V30F	RHEEM	1
621	04/01/2003	PGR40	AO SMITH	0
622	05/01/1971	PGX40	AO SMITH	1
623	06/21/2002	PGR50	AO SMITH	0
624	01/31/2002	FSG50	AO SMITH	0
625	12/15/2006	LTN050G	LOCHINVAR	0
626	12/06/2004	XVR50	A. O. SMITH	0
627	02/27/2000	41XR50	RHEEM	0
628	08/20/2012	M45036FBN	BRADFORD-WHITE	1
629	03/26/2001	41XR50	RHEEM	0
630	02/16/2001	41VR40	RHEEM	0
631	02/09/2011	41VR40	RHEEM	0
632	11/21/2011	MI5036FBN	BRADFORD-WHITE	0
633	04/16/2003	FSG40	AO SMITH	0
634	03/12/2009	PH199119	PHOENIX	0
635	09/06/2010	LSN041G	LOCHINVAR	0
636	06/06/2008	LTN040GEF	LOCHINVAR	0
637	09/13/2006	LTN040GEF	Lochinvar	1
638	05/30/1991	FSG40	AO SMITH	0
639	11/29/2012	MI403S6FBN	BRADFORD-WHITE	0
640	08/12/1998	FGR40	AO SMITH	0
641	10/09/2003	PGR40	AO SMITH	0
642	04/19/2001	FSGL40	AO SMITH	0
643	12/27/2001	FSG40	AO SMITH	0
644	11/03/2011	MI40T6FBN	BRADFORD-WHITE	0
645	09/13/2006	LTN040GEF	L	0
646	07/17/2008	LTN040GEF	LOCHINVAR	2
647	10/17/2001	PGR50	AO SMITH	0
648	03/20/2001	FSG40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
649	03/03/2009	PH199119	PHOENIX	1
650	11/03/2009	LTN050GEF	LOCHINVAR	1
651	04/01/1967	PGX50	AO SMITH	0
652	01/14/2011	LTN040GEF	LOCHINVAR	0
653	03/03/2009	PH199119	PHOENIX	0
654	06/18/2005	LTN050	LOCHINVAR	0
655	02/21/2003	FSGL40	AO SMITH	0
656	02/10/2012	MI403S6FBN	BRADFORD-WHITE	0
657	03/05/2010	LTN040GEF	LOCHINVAR	0
658	11/11/2005	LTN050G	LOCHINVAR	0
659	10/20/2011	M440T6FBN	BRADFORD-WHITE	1
660	06/29/2011	M440T6FBN	BRADFORD-WHITE	0
661	01/14/2005	LTN050	LOCHINVAR	0
662	06/10/2009	LTN040GEF	LOCHINVAR	0
663	04/14/1997	21VR502T	RHEEM	1
664	07/28/2012	M45036FBN	BRADFORD-WHITE	0
665	02/24/2003	FSGL40	AO SMITH	1
666	04/06/2011	42VR50	RHEEM	0
667	06/09/2004	XSN040	LOCHINVAR	0
668	09/16/2005	LTN040	LOCHINVAR	0
669	05/28/2009	LSN041G	LOCHINVAR	0
670	07/12/1974	F72DUMMY	AO SMITH	0
671	07/12/1974	F72DUMMY	AO SMITH	0
672	07/08/2011	MI403S6FBN	BRADFORD-WHITE	2
673	03/01/1971	PGX40	AO SMITH	0
674	12/10/1991	FSG30	AO SMITH	0
675	04/04/2001	41XR50	RHEEM	0
676	09/28/1993	FSG40	AO SMITH	0
677	12/19/2011	M440T6FBN	BRADFORD-WHITE	1
678	09/26/2006	G82156	RUUD/RHEEM	0
679	06/07/1983	KGA50	AO SMITH	0
680	10/04/2001	PGR50	AO SMITH	0
681	04/21/2011	21VR40	RHEEM	0
682	10/06/2004	XVR50	A. O. SMITH	0
683	01/16/1998	21V407	RHEEM	0
684	03/22/2001	FSG40	AO SMITH	0
685	12/10/2008	G82156	RUUD/RHEEM	0
686	12/13/2012	M2XR504T6FBN	Bradford White	1
687	04/06/2012	MI5036FBN	BRADFORD-WHITE	0
688	06/26/2006	LTN050G	LOCHINVAR	0
689	02/28/2008	LTN050GEF	LOCHINVAR	0
690	11/23/2005	LTN040G	LOCHINVAR	0
691	06/13/2012	MI403S6FBN	BRADFORD-WHITE	0
692	07/19/2012	MI40T6FBN	BRADFORD-WHITE	0
693	08/01/1974	KGL40	AO SMITH	1
694	12/01/1998	21V506	RHEEM	0
695	07/25/2007	LTN050GEF	LOCHINVAR	0
696	02/20/2009	LTN050GEF	LOCHINVAR	0
697	05/26/2004	XTN050	LOCHINVAR	0
698	02/02/2010	LTN040GEF	LOCHINVAR	0
699	01/03/2012	MI403S6FBN	BRADFORD-WHITE	0
700	05/27/1998	FSG40	AO SMITH	0
701	06/20/1994	PGR40	AO SMITH	0
702	06/02/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
703	10/28/2003	FCVL40	AO SMITH	0
704	01/18/1999	FSG50	AO SMITH	0
705	12/29/1999	41V40S	RHEEM	0
706	05/13/2011	41VR50	RHEEM	0
707	05/15/2000	41XR50	RHEEM	0
708	07/11/2001	FSG40	AO SMITH	0
709	10/01/1976	KGA50	AO SMITH	0
710	02/07/2001	41VR50	RHEEM	0
711	05/13/2010	LTN050G	LOCHINVAR	0
712	09/22/2000	41V40S	RHEEM	1
713	09/11/2003	FSGL40	AO SMITH	0
714	09/06/2012	M440T6FBN	BRADFORD-WHITE	0
715	07/08/2008	LTN050G	LOCHINVAR	0
716	12/01/2008	LTN050GEF	LOCHINVAR	2
717	05/11/2001	FSGL40	AO SMITH	3
718	02/11/2008	LTN050G	LOCHINVAR	1
719	02/26/2013	M440T6FBN	BRADFORD-WHITE	1
720	06/06/2009	LSN041G	LOCHINVAR	3
721	03/30/2002	FSG50	AO SMITH	0
722	05/11/2001	FSGL40	AO SMITH	0
723	08/18/1977	KGA40	AO SMITH	0
724	12/21/2012	FSGL40	AO SMITH	0
725	11/05/2007	LTN040G	LOCHINVAR	1
726	08/16/2011	MI403S6FBN	BRADFORD-WHITE	0
727	03/18/2002	FSGL40	AO SMITH	0
728	08/15/2000	FSGL40	AO SMITH	0
729	05/02/2011	21VR40	RHEEM	0
730	04/15/2004	PRX50	STATE	0
731	04/23/1997	P506	RUUD	0
732	02/10/2009	KGL40	AO SMITH	0
733	12/02/2000	41XR50	RHEEM	0
734	07/23/2008	LTN050GEF	LOCHINVAR	0
735	05/27/1975	KGA50	AO SMITH	0
736	07/13/2010	LTN050GEF	LOCHINVAR	0
737	03/28/2005	GCVL40	A. O. SMITH	0
738	04/09/2011	21VR50	RHEEM	0
739	08/04/2010	21VR50	RHEEM	0
740	03/17/2012	MI5036FBN	BRADFORD-WHITE	1
741	05/18/2010	LTN050GEF	LOCHINVAR	0
742	06/22/2002	PGR40	AO SMITH	0
743	12/19/1997	PGR50	AO SMITH	0
744	12/31/2009	LTN040GEF	LOCHINVAR	0
745	06/26/2006	PGR50	AO SMITH	0
746	11/30/2007	LTN050GEF	LOCHINVAR	0
747	08/23/2003	FSG40	AO SMITH	0
748	11/24/2012	M45036FBN	BRADFORD-WHITE	0
749	11/18/1997	FSG50	AO SMITH	0
750	04/23/2004	XVR40	A. O. SMITH	0
751	04/01/2002	FSG50	AO SMITH	0
752	12/14/2010	LTN040G	LOCHINVAR	0
753	03/21/2007	LTN040G	LOCHINVAR	0
754	12/21/2005	GVC50	A. O. SMITH	0
755	09/02/1996	FGR50	AO SMITH	0
756	11/19/2010	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
757	10/19/1994	G72DUMMY	AO SMITH	0
758	10/04/2010	21VR50	RHEEM	0
759	09/04/2008	LTN050GEF	LOCHINVAR	0
760	10/02/2008	LTN050GEF	LOCHINVAR	0
761	05/28/2003	FSG50	AO SMITH	0
762	01/31/2012	M45036FBN	BRADFORD-WHITE	0
763	02/08/2003	FSG30	AO SMITH	1
764	05/21/2010	LTN050GEF	LOCHINVAR	1
765	02/02/2012	PH2DV50F	RUUD	0
766	10/13/2006	LTN040G	LOCHINVAR	0
767	03/04/2013	M440T6FBN	BRADFORD-WHITE	0
768	03/30/2011	42VR50	RHEEM	0
769	02/04/2009	LTN050GEF	LOCHINVAR	0
770	07/27/2009	LSN041G	LOCHINVAR	1
771	12/20/1973	RM5063	RHEEM	0
772	10/13/2001	PGR40	AO SMITH	0
773	03/23/2012	MI5036FBN	BRADFORD-WHITE	0
774	10/08/2007	LTN040G	LOCHINVAR	0
775	05/09/2012	M45036FBN	BRADFORD-WHITE	0
776	03/21/1995	PR407	RUUD	0
777	03/24/2005	GVC40	A. O. SMITH	0
778	03/17/1997	PGR40	AO SMITH	1
779	03/22/2005	XVR50	A. O. SMITH	0
780	04/11/2009	LTN040G	LOCHINVAR	0
781	04/08/1985	FSG50	AO SMITH	0
782	10/08/2009	LTN050G	LOCHINVAR	0
783	05/31/1999	FSG50	AO SMITH	0
784	10/15/2002	PGR50	AO SMITH	0
785	02/04/2010	LTN050GEF	LOCHINVAR	0
786	05/17/2005	XSN040	LOCHINVAR	0
787	02/12/2004	FCVL40	AO SMITH	0
788	12/22/2005	LTN040G	LOCHINVAR	0
789	12/31/2005	LTN050G	LOCHINVAR	0
790	08/31/2010	21V502	RHEEM	0
791	01/11/2012	M45036FBN	BRADFORD-WHITE	0
792	02/21/1989	FSGL40	AO SMITH	0
793	12/31/2008	LTN050GEF	LOCHINVAR	0
794	06/04/2001	FSGL40	AO SMITH	0
795	08/31/2010	LSN041G	LOCHINVAR	0
796	03/17/2004	PVR50	AO SMITH	0
797	05/29/2008	LTN050GEF	LOCHINVAR	0
798	02/03/2006	LTN050G	LOCHINVAR	0
799	07/28/2006	LTN050G	LOCHINVAR	0
800	09/13/1999	FSGL40	AO SMITH	0
801	10/03/1997	PGR50	AO SMITH	0
802	11/16/2007	LTN050GEF	LOCHINVAR	0
803	09/29/2008	LTN050GEF	LOCHINVAR	0
804	08/02/2008	LTN040GEF	LOCHINVAR	0
805	01/15/2009	LTN050GEF	LOCHINVAR	1
806	08/24/2004	GVR50	AO SMITH	0
807	02/06/2010	LTN050GEF	LOCHINVAR	0
808	01/24/2013	M45036FBN	BRADFORD-WHITE	3
809	12/11/2000	41XR40	RHEEM	1
810	06/17/1999	41VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
811	10/20/2008	LTN050GEF	LOCHINVAR	1
812	02/03/2009	LTN050GEF	LOCHINVAR	0
813	05/18/2009	LTN040GEF	LOCHINVAR	1
814	03/22/2001	PGR50	AO SMITH	1
815	02/20/2001	FSG40	AO SMITH	0
816	07/01/2005	LTN050G	LOCHINVAR	0
817	01/28/2005	FSG40	AO SMITH	0
818	07/23/2004	GCVL40	A. O. SMITH	0
819	06/25/2012	MI403S6FBN	BRADFORD-WHITE	0
820	02/22/2007	LTN040G	LOCHINVAR	0
821	04/17/2001	FSGL40	AO SMITH	0
822	06/27/2005	LTN050	LOCHINVAR	0
823	01/17/2008	LTN050GEF	LOCHINVAR	0
824	03/16/2007	LTN040GEF	LOCHINVAR	1
825	06/23/2010	LTN050G	LOCHINVAR	0
826	06/01/2010	LTN050GEF	LOCHINVAR	0
827	05/03/1998	FSGL40	AO SMITH	0
828	06/19/2001	FSG40	AO SMITH	0
829	12/22/2010	LTN040G	LOCHINVAR	1
830	10/18/1994	FGR40	AO SMITH	0
831	02/25/2009	LTN050G	LOCHINVAR	1
832	12/28/1994	G82156	RUUD/RHEEM	0
833	02/13/2007	P506	RUUD	0
834	03/08/2007	LTN050G	LOCHINVAR	0
835	09/08/2002	FSG50	AO SMITH	0
836	07/03/2001	FSG50	AO SMITH	0
837	03/02/2010	LTN040GEF	LOCHINVAR	0
838	11/03/2002	PGR50	AO SMITH	0
839	09/13/2011	M45036FBN	BRADFORD-WHITE	4
840	10/23/2003	FSG40	AO SMITH	0
841	07/08/2002	FSG40	AO SMITH	0
842	03/26/1999	FSG40	AO SMITH	0
843	11/12/2012	G91200	RUUD/RHEEM	1
844	11/10/2008	LTN050GEF	LOCHINVAR	0
845	11/09/1996	PGR50	AO SMITH	0
846	03/31/2012	M440T6FBN	BRADFORD-WHITE	1
847	04/01/2004	FCV50	AO SMITH	0
848	07/10/2012	MI5036FBN	BRADFORD-WHITE	0
849	10/01/1977	RH3063	RUUD	0
850	06/25/2007	LTN050G	LOCHINVAR	0
851	03/27/2010	G75125	RUUD/RHEEM	2
852	03/12/2012	M440T6FBN	BRADFORD-WHITE	0
853	11/10/2010	LTN040G	LOCHINVAR	0
854	02/20/2004	FCV40	AO SMITH	1
855	12/26/2008	LTN040	LOCHINVAR	1
856	01/19/2013	MI40T6FBN	BRADFORD-WHITE	0
857	08/22/2011	MI5036FBN	BRADFORD-WHITE	0
858	12/11/2004	G72DUMMY	AO SMITH	1
859	03/03/2008	LTN050GEF	LOCHINVAR	0
860	02/08/2006	LTN040G	LOCHINVAR	0
861	07/07/2008	42VR50	RHEEM	0
862	01/22/2007	LTN050G	LOCHINVAR	0
863	04/26/2008	LTN050	LOCHINVAR	0
864	05/22/2009	LTN050GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
865	03/10/2009	LTN050GEF	LOCHINVAR	0
866	07/21/2005	LSN041G	LOCHINVAR	0
867	01/08/2004	PVR40	AO SMITH	0
868	03/27/2009	LTN040GEF	LOCHINVAR	0
869	12/30/2008	LSN041G	LOCHINVAR	3
870	10/11/2008	LTN050GEF	LOCHINVAR	0
871	01/31/2002	G75125	RUUD/RHEEM	0
872	01/05/2001	FSG50	AO SMITH	0
873	04/07/2006	LTN040G	LOCHINVAR	1
874	02/23/2006	LTN050G	LOCHINVAR	0
875	04/09/2009	LTN050G	LOCHINVAR	0
876	12/03/2011	MI50L6FBN	BRADFORD-WHITE	0
877	04/14/1999	FSGL40	AO SMITH	0
878	03/06/2004	FCV40	AO SMITH	0
879	11/26/2005	LTN040	LOCHINVAR	0
880	05/14/2001	PGR50	AO SMITH	0
881	09/02/2008	LTN050GEF	LOCHINVAR	1
882	11/04/2006	LTN050G	LOCHINVAR	0
883	02/20/2012	MI40T6FBN	BRADFORD-WHITE	0
884	12/19/2011	MI40T6FBN	BRADFORD-WHITE	0
885	07/05/2007	LTN050GEF	LOCHINVAR	0
886	09/28/2007	LTN050G	LOCHINVAR	0
887	06/12/2005	LTN040	LOCHINVAR	2
888	01/06/2005	GVC40	A. O. SMITH	0
889	01/23/2012	G82156	RUUD/RHEEM	3
890	12/13/2002	PGR50	AO SMITH	0
891	06/06/2012	FSG50	AO SMITH	1
892	08/12/2009	LTN050GEF	LOCHINVAR	0
893	04/27/2001	PGR50	AO SMITH	1
894	11/12/1992	FSG50	AO SMITH	0
895	01/29/2002	FSGL40	AO SMITH	1
896	10/05/2009	LTN050GEF	LOCHINVAR	0
897	08/06/1999	FGR50	AO SMITH	0
898	03/04/2003	FSG50	AO SMITH	0
899	03/22/2001	FSG40	AO SMITH	0
900	01/31/2009	LTN040G	LOCHINVAR	0
901	01/25/2013	MI403S6FBN	BRADFORD-WHITE	0
902	04/19/2009	LTN050GEF	LOCHINVAR	0
903	01/27/2011	42VR50	RHEEM	0
904	08/04/2008	PH199119	PHOENIX	0
905	08/11/1997	PGR50	AO SMITH	0
906	11/20/2001	FSG30	AO SMITH	1
907	03/09/2000	FSGL40	AO SMITH	0
908	02/22/2008	LSN041	LOCHINVAR	1
909	10/23/2012	MI50L6FBN	BRADFORD-WHITE	0
910	11/08/2012	M45036FBN	BRADFORD-WHITE	1
911	10/03/2002	PGR50	AO SMITH	1
912	09/01/2012	MI403S6FBN	BRADFORD-WHITE	0
913	10/19/2011	MI403S6FBN	BRADFORD-WHITE	0
914	10/31/2007	FSG30	AO SMITH	0
915	01/11/2010	LTN040GEF	LOCHINVAR	0
916	04/29/2004	PVR50	AO SMITH	0
917	11/13/2010	21VR50	RHEEM	1
918	12/01/2006	LTN030G	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
919	03/09/2012	PH250SF	RUUD	0
920	07/08/2010	FSG40	AO SMITH	1
921	12/28/2009	LTN040GEF	LOCHINVAR	0
922	01/26/2011	42VR50	RHEEM	0
923	05/21/2001	PGR50	AO SMITH	0
924	07/21/1997	FGR50	AO SMITH	0
925	06/10/2007	LSN041G	LOCHINVAR	1
926	01/07/2011	LTN040G	LOCHINVAR	1
927	04/11/2008	LTN050GEF	LOCHINVAR	0
928	12/02/2010	LTN040GEF	LOCHINVAR	0
929	09/08/2011	M45036FBN	BRADFORD-WHITE	0
930	11/07/2007	LSN041G	LOCHINVAR	0
931	11/19/1998	FSG30	AO SMITH	0
932	09/13/2001	G91200	RUUD/RHEEM	1
933	03/09/2011	21VR50	RHEEM	0
934	05/10/2012	MI40T6FBN	BRADFORD-WHITE	0
935	07/11/2004	GVC50	A. O. SMITH	0
936	08/09/2008	LTN040GEF	LOCHINVAR	0
937	05/01/2009	LTN050GEF	LOCHINVAR	1
938	05/06/2006	LTN050G	LOCHINVAR	0
939	06/01/2010	LTN050G	LOCHINVAR	1
940	01/09/1999	PGR40	AO SMITH	0
941	04/11/2008	LTN050GEF	LOCHINVAR	2
942	04/04/2011	21VR40	RHEEM	0
943	12/10/2012	MI50L6FBN	BRADFORD-WHITE	2
944	04/05/2012	M45036FBN	BRADFORD-WHITE	0
945	12/28/2009	LTN050GEF	LOCHINVAR	0
946	02/01/1994	PGR50	AO SMITH	0
947	01/09/2012	M440T6FBN	BRADFORD-WHITE	0
948	10/26/1999	FSGL40	AO SMITH	0
949	02/10/2004	XTN050	LOCHINVAR	0
950	12/09/2008	LTN040GEF	LOCHINVAR	0
951	09/21/2006	LTN050G	LOCHINVAR	0
952	08/19/2008	LTN050GEF	LOCHINVAR	1
953	11/01/1975	KGA50	AO SMITH	0
954	06/04/1998	FSG40	AO SMITH	0
955	07/11/2006	LTN040G	LOCHINVAR	0
956	04/16/2007	LTN040G	LOCHINVAR	0
957	06/14/1999	FSG50	AO SMITH	0
958	01/23/2007	LTN050G	LOCHINVAR	1
959	04/02/2005	FCV40	AO SMITH	0
960	02/24/2011	41VR40	RHEEM	0
961	04/09/1998	G67114	RHEEM	0
962	09/20/2012	MI5036FBN	BRADFORD-WHITE	0
963	03/12/2008	LTN050	LOCHINVAR	0
964	07/14/2011	M440T6FBN	BRADFORD-WHITE	0
965	07/16/2003	FSG50	AO SMITH	1
966	06/15/2006	LTN050G	LOCHINVAR	0
967	10/11/1997	21V407	RHEEM	0
968	09/11/2006	G91200	RUUD/RHEEM	1
969	11/24/1992	BTR199	AO SMITH	0
970	02/13/2005	GVC40	A. O. SMITH	0
971	05/05/1993	FSG30	AO SMITH	0
972	07/19/2011	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
973	12/08/2003	G75125	RUUD/RHEEM	0
974	12/19/1991	FSG30	AO SMITH	0
975	09/02/2004	GVC50	A. O. SMITH	0
976	04/12/2002	FSG40	AO SMITH	0
977	01/19/2005	LTN050	LOCHINVAR	0
978	02/07/2011	42VR50	RHEEM	1
979	12/20/1973	PGXL30	AO SMITH	0
980	06/08/1998	FGR40	AO SMITH	0
981	11/12/2007	LSN041G	LOCHINVAR	0
982	01/13/1999	I72DUMMY	AO SMITH	0
983	07/13/2002	41XR50	RHEEM	0
984	10/17/2012	MI40T6FBN	BRADFORD-WHITE	0
985	12/10/2003	G76200	RUUD/RHEEM	0
986	10/20/1999	P506	RUUD	0
987	02/27/2006	G75125	RUUD/RHEEM	0
988	12/10/2003	G76200	RUUD/RHEEM	0
989	06/28/1989	FSG50	AO SMITH	0
990	06/22/1999	FSG50	AO SMITH	0
991	11/06/2000	FSG40	AO SMITH	0
992	03/18/1996	PGR40	AO SMITH	0
993	02/04/2006	FSGL30	AO SMITH	0
994	01/19/2010	LTN050GEF	LOCHINVAR	0
995	02/18/2005	XVR50	A. O. SMITH	0
996	09/07/2012	MI403S6FBN	BRADFORD-WHITE	0
997	12/28/2009	LTN040GEF	LOCHINVAR	0
998	06/27/2001	FSG50	AO SMITH	0
999	12/28/2009	FGR30	AO SMITH	0
1000	03/13/2007	LTN050GEF	LOCHINVAR	1
1001	08/27/2008	LTN050GEF	LOCHINVAR	0
1002	12/28/2009	FSG30	AO SMITH	1
1003	12/28/2009	PGX30	AO SMITH	0
1004	12/17/2012	FSGL40	AO SMITH	0
1005	12/28/2006	LTN050G	LOCHINVAR	0
1006	04/10/2004	XTN050	LOCHINVAR	0
1007	07/28/1987	G72DUMMY	AO SMITH	0
1008	06/20/1998	FGR50	AO SMITH	0
1009	12/14/2006	LTN040G	LOCHINVAR	0
1010	07/31/2006	LTN050G	LOCHINVAR	0
1011	12/03/2009	LSN041G	LOCHINVAR	0
1012	08/01/1967	PGX40	AO SMITH	0
1013	02/12/2003	FSGL40	AO SMITH	0
1014	02/25/1999	FSG50	AO SMITH	0
1015	11/17/1998	FSG50	AO SMITH	0
1016	12/17/2011	M440T6FBN	BRADFORD-WHITE	0
1017	11/10/1999	PGR50	AO SMITH	1
1018	02/12/2013	MI40T6FBN	BRADFORD-WHITE	0
1019	02/23/2013	M45036FBN	BRADFORD-WHITE	0
1020	12/06/2010	21VR40	RHEEM	1
1021	07/15/2009	LTN050GEF	LOCHINVAR	0
1022	06/15/2010	PR502T	RUUD	0
1023	09/21/2000	G75125	RUUD/RHEEM	0
1024	07/08/2003	FSG40	AO SMITH	0
1025	09/20/2010	LSN041G	LOCHINVAR	0
1026	11/14/2003	PVR40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1027	04/26/2004	FCV40	AO SMITH	0
1028	01/04/2002	FSG40	AO SMITH	0
1029	02/17/2009	LTN040GEF	LOCHINVAR	0
1030	01/03/2008	G91200	RUUD/RHEEM	0
1031	01/29/2004	XTN040	LOCHINVAR	0
1032	03/26/1996	PGR40	AO SMITH	0
1033	01/14/2005	XTN050	LOCHINVAR	0
1034	01/10/1996	PR502T	RUUD	0
1035	12/27/2011	G76200	RUUD/RHEEM	0
1036	08/15/2007	FGR50	AO SMITH	0
1037	03/07/2008	LTN050GEF	LOCHINVAR	0
1038	10/24/2005	LTN050G	LOCHINVAR	0
1039	07/24/2010	LTN040GEF	LOCHINVAR	1
1040	08/03/2009	LTN050G	LOCHINVAR	1
1041	01/12/1999	FSG40	AO SMITH	0
1042	11/05/2009	LSN041G	LOCHINVAR	1
1043	12/13/2001	PGR50	AO SMITH	0
1044	12/13/2012	MI403S6FBN	BRADFORD-WHITE	0
1045	02/14/2006	LTN040G	LOCHINVAR	0
1046	11/29/2001	FSG50	AO SMITH	0
1047	07/23/2012	MI40T6FBN	BRADFORD-WHITE	0
1048	02/10/2006	LTN040G	LOCHINVAR	1
1049	03/03/2011	21VR40	RHEEM	1
1050	08/09/2004	XTN050	LOCHINVAR	0
1051	11/19/2009	LTN050GEF	LOCHINVAR	0
1052	12/18/2007	LSN041G	LOCHINVAR	0
1053	02/07/2007	LTN040GEF	LOCHINVAR	1
1054	11/27/2000	PGR50	AO SMITH	0
1055	07/12/2010	PGR50	AO SMITH	0
1056	06/01/2001	21V402S	RHEEM	0
1057	05/04/2006	LTN040G	LOCHINVAR	1
1058	11/15/2012	MI5036FBN	BRADFORD-WHITE	0
1059	11/02/1998	FSG50	AO SMITH	0
1060	01/18/2008	LTN040G	LOCHINVAR	0
1061	04/25/1997	FSG40	AO SMITH	1
1062	07/14/2008	LSN041G	LOCHINVAR	0
1063	01/13/2006	LTN050G	LOCHINVAR	0
1064	10/04/2012	M45036FBN	BRADFORD-WHITE	0
1065	08/14/2006	LSN041G	LOCHINVAR	0
1066	01/12/2009	G75125	RUUD/RHEEM	0
1067	04/28/2003	PGR50	AO SMITH	0
1068	04/11/2005	GVC40	A. O. SMITH	0
1069	05/24/2004	RF67120	RUUD	0
1070	10/13/2011	MI40T6FBN	BRADFORD WHITE	1
1071	06/09/2008	LTN040GEF	LOCHINVAR	0
1072	08/15/1979	RH3063	RUUD	0
1073	04/12/1994	G76200	RUUD/RHEEM	1
1074	03/07/2006	LTN050G	LOCHINVAR	1
1075	04/09/1997	FSGL40	AO SMITH	0
1076	07/24/2007	P506	RUUD	0
1077	11/17/2005	LTN050G	LOCHINVAR	0
1078	08/18/2004	GVC50	A. O. SMITH	3
1079	11/04/1986	RM5063	RHEEM	1
1080	01/17/2008	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1081	12/24/2008	FSG30	AO SMITH	0
1082	10/27/2008	LTN050GEF	LOCHINVAR	0
1083	05/24/2005	GVC30	AOSMITH	0
1084	09/21/2004	XVR50	A. O. SMITH	0
1085	05/30/2012	MI403S6FBN	BRADFORD-WHITE	0
1086	04/18/1999	41VR50	RHEEM	0
1087	07/17/2002	FSG40	AO SMITH	0
1088	04/08/2002	FSG50	AO SMITH	0
1089	10/30/2012	M440T6FBN	BRADFORD-WHITE	0
1090	08/15/2003	FSG40	AO SMITH	0
1091	02/09/2013	PH2DV50F	RUUD	0
1092	01/08/2011	42VR50	RHEEM	0
1093	04/17/2002	FSG50	AO SMITH	0
1094	09/18/2012	G82156	RUUD/RHEEM	0
1095	05/04/1999	FSG50	AO SMITH	0
1096	11/03/2005	LTN050GEF	LOCHINVAR	1
1097	02/08/2002	FSG40	AO SMITH	0
1098	01/22/1999	FGR40	AO SMITH	0
1099	11/06/2012	M440T6FBN	BRADFORD-WHITE	0
1100	01/27/2011	42VR50	RHEEM	1
1101	03/06/2006	LSN041G	LOCHINVAR	0
1102	06/10/2011	42VR5040F	RHEEM	0
1103	06/02/2006	LTN050GEF	LOCHINVAR	1
1104	05/08/1995	FGR50	AO SMITH	0
1105	01/16/2008	LTN050GEF	LOCHINVAR	0
1106	10/02/2001	PGR40	AO SMITH	0
1107	08/03/2012	M45036FBN	BRADFORD-WHITE	0
1108	11/14/2007	LTN050GEF	LOCHINVAR	0
1109	07/29/2009	LTN050GEF	LOCHINVAR	1
1110	04/10/2012	M45036FBN	BRADFORD-WHITE	0
1111	11/11/2005	LTN050GEF	LOCHINVAR	0
1112	02/28/2001	41V50	RHEEM	0
1113	07/09/2010	LTN040G	LOCHINVAR	0
1114	04/25/2011	41VR50	RHEEM	0
1115	09/22/2005	LTN050G	LOCHINVAR	0
1116	07/15/2011	MI40T6FBN	BRADFORD-WHITE	2
1117	10/02/2007	LTN050GEF	LOCHINVAR	1
1118	07/26/2007	LTN050GEF	LOCHINVAR	0
1119	02/28/2009	LTN050GEF	LOCHINVAR	0
1120	04/24/1992	FSG50	AO SMITH	0
1121	06/15/2012	M45036FBN	BRADFORD-WHITE	0
1122	02/02/1999	FSGL40	AO SMITH	0
1123	08/17/1999	FSG40	AO SMITH	0
1124	03/19/1986	PGD30	AO SMITH	0
1125	12/31/1992	FSG40	AO SMITH	0
1126	06/08/2010	LTN050G	LOCHINVAR	0
1127	01/11/2001	41VR50	RHEEM	0
1128	07/10/2004	GCVL40	A. O. SMITH	0
1129	01/16/2004	FCVL40	AO SMITH	3
1130	12/01/1976	KGA40	AO SMITH	1
1131	12/05/2006	41V50	RHEEM	0
1132	03/19/2004	41XR40	RHEEM	0
1133	10/14/2008	LTN050GEF	LOCHINVAR	0
1134	01/16/2013	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1135	12/13/2002	G75125	RUUD/RHEEM	0
1136	01/06/2009	LTN040GEF	LOCHINVAR	0
1137	04/11/2011	42VR50	RHEEM	2
1138	01/01/1978	PGC50	AO SMITH	0
1139	04/09/1988	FSG40	AO SMITH	0
1140	11/24/2007	LTN040G	LOCHINVAR	0
1141	03/21/1989	FSG40	AO SMITH	0
1142	07/27/2004	GVC50	A. O. SMITH	0
1143	01/04/2010	LTN040GEF	LOCHINVAR	0
1144	04/11/2003	FSGL30	AO SMITH	0
1145	08/15/2007	LTN040GEF	LOCHINVAR	1
1146	10/29/2012	MI40T6FBN	BRADFORD-WHITE	0
1147	02/28/2007	LTN050G	LOCHINVAR	0
1148	09/12/1988	RF67120	RUUD	0
1149	03/03/2001	41XR40	RHEEM	0
1150	08/27/2010	LTN050GEF	LOCHINVAR	0
1151	04/17/2012	MI403S6FBN	BRADFORD-WHITE	0
1152	12/12/2012	M440T6FBN	BRADFORD-WHITE	1
1153	05/01/1989	G72DUMMY	AO SMITH	0
1154	05/16/2006	LTN040G	LOCHINVAR	1
1155	07/29/2003	FSG40	AO SMITH	0
1156	02/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	0
1157	10/01/2009	LSN041G	LOCHINVAR	0
1158	11/02/2012	MI403S6FBN	BRADFORD-WHITE	0
1159	08/24/2009	LTN040GEF	LOCHINVAR	1
1160	03/03/1999	41V40	RHEEM	0
1161	10/09/2011	MI40T6FBN	BRADFORD-WHITE	0
1162	12/15/2009	ETN076	LOCHINVAR	0
1163	08/18/1998	FSG40	AO SMITH	0
1164	11/15/2010	21VR40	RHEEM	1
1165	02/05/2013	41XR40	RHEEM	0
1166	10/03/2007	LTN050GEF	LOCHINVAR	0
1167	01/13/2006	LTN040G	LOCHINVAR	0
1168	02/07/2007	LTN050G	LOCHINVAR	0
1169	08/17/2010	LTN050G	LOCHINVAR	1
1170	12/20/2011	MI403S6FBN	BRADFORD-WHITE	0
1171	03/15/2006	LTN040G	LOCHINVAR	0
1172	09/01/2004	GVC50	A. O. SMITH	1
1173	08/02/2010	LTN050GEF	LOCHINVAR	0
1174	03/30/2003	21V407	RHEEM	0
1175	03/25/2002	PGR50	AO SMITH	0
1176	02/01/1978	PGCL40	AO SMITH	1
1177	01/06/2011	21VR40	RHEEM	0
1178	10/26/2002	FSG50	AO SMITH	0
1179	08/20/2004	GVC40	A. O. SMITH	3
1180	01/24/2007	PGR50	AO SMITH	0
1181	02/01/1978	KGA30	AO SMITH	0
1182	12/29/2008	LTN040GEF	LOCHINVAR	0
1183	07/08/2011	MI40T6FBN	BRADFORD-WHITE	0
1184	09/11/2003	PVR50	AO SMITH	0
1185	02/23/2001	21V407	RHEEM	0
1186	04/11/1977	A71DUMMY	UNKNOWN AT CONVERSION	0
1187	12/21/2010	42VR50	RHEEM	0
1188	01/20/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1189	07/01/2008	LTN040GEF	LOCHINVAR	0
1190	01/06/2004	PVR50	AO SMITH	0
1191	02/27/2007	G91200	RUUD/RHEEM	0
1192	01/02/1998	PGR50	AO SMITH	2
1193	07/15/1991	FSGL40	AO SMITH	0
1194	05/14/2002	FSG30	AO SMITH	0
1195	02/11/2007	LSN041G	LOCHINVAR	0
1196	11/02/2009	LTN050GEF	LOCHINVAR	0
1197	09/21/2011	MI5036FBN	BRADFORD-WHITE	0
1198	07/30/2007	LTN040GEF	LOCHINVAR	1
1199	10/17/2006	LSN041G	LOCHINVAR	0
1200	06/28/2012	M45036FBN	BRADFORD-WHITE	1
1201	01/19/2013	M45036FBN	BRADFORD-WHITE	0
1202	12/21/2012	MI5036FBN	BRADFORD-WHITE	2
1203	06/20/2006	LTN050G	LOCHINVAR	0
1204	05/05/2003	FSG40	AO SMITH	0
1205	01/07/1999	FSGL40	AO SMITH	0
1206	10/30/2003	PGR50	AO SMITH	0
1207	01/25/2006	GVC50	A. O. SMITH	0
1208	08/24/2007	G82156	RUUD/RHEEM	0
1209	09/02/1989	FSG40	AO SMITH	0
1210	07/12/2005	LTN050	LOCHINVAR	0
1211	01/31/2000	G82156	RUUD/RHEEM	0
1212	02/25/1998	G91200	RUUD/RHEEM	0
1213	02/02/2005	FSG30	AO SMITH	0
1214	06/12/2001	FSG50	AO SMITH	0
1215	07/07/2012	G91200	RUUD/RHEEM	0
1216	06/12/2008	LTN040GEF	LOCHINVAR	0
1217	12/27/1988	FSG40	AO SMITH	0
1218	04/29/2006	LTN050GEF	LOCHINVAR	0
1219	01/15/2010	ETN076	LOCHINVAR	0
1220	05/31/2006	LTN050G	LOCHINVAR	0
1221	12/06/2002	FSG50	AO SMITH	1
1222	03/23/2010	G75125	RUUD/RHEEM	0
1223	08/10/1999	FSG30	AO SMITH	0
1224	02/05/2001	41V50S	RHEEM	0
1225	08/30/2005	LTN040	LOCHINVAR	0
1226	07/27/2005	LTN050	LOCHINVAR	0
1227	09/20/2008	LTN050GEF	LOCHINVAR	0
1228	03/04/2003	FSG40	AO SMITH	0
1229	11/28/2012	MI75S6FBN	BRADFORD-WHITE	1
1230	12/20/1991	FSG50	AO SMITH	0
1231	11/20/2009	LTN050GEF	LOCHINVAR	0
1232	08/27/2012	MI403S6FBN	BRADFORD-WHITE	0
1233	07/14/2010	LTN040GEF	LOCHINVAR	0
1234	05/02/1998	FGR50	AO SMITH	0
1235	12/30/2009	PGX50	AO SMITH	0
1236	11/16/1983	KGA50	AO SMITH	0
1237	03/22/2005	GVC40	A. O. SMITH	0
1238	11/01/2009	LTN050GEF	LOCHINVAR	0
1239	10/19/2006	LTN050G	LOCHINVAR	0
1240	11/29/1999	PGR50	AO SMITH	0
1241	02/28/2012	M440T6FBN	BRADFORD-WHITE	0
1242	04/23/2012	P230F	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1243	01/08/1998	FSGL40	AO SMITH	0
1244	04/12/2008	LTN050GEF	LOCHINVAR	0
1245	04/10/2006	LTN040G	LOCHINVAR	0
1246	03/15/2013	MI403S6FBN	Bradford - White	0
1247	07/06/2004	GVC40	A. O. SMITH	0
1248	12/18/2007	PH199119	PHOENIX	1
1249	04/14/2006	LTN030G	AO SMITH	0
1250	12/31/2007	LSN041G	LOCHINVAR	0
1251	06/01/1994	PGR30	AO SMITH	1
1252	04/14/2010	G75125	RUUD/RHEEM	0
1253	05/02/2008	LSN041G	LOCHINVAR	2
1254	05/01/1965	PGX40	AO SMITH	1
1255	08/20/1999	PHR50	RUUD	0
1256	08/27/2006	LTN050G	LOCHINVAR	0
1257	02/14/2012	MI5036FBN	BRADFORD-WHITE	0
1258	11/01/2007	LTN050GEF	LOCHINVAR	0
1259	07/16/2008	LTN040GEF	LOCHINVAR	0
1260	10/15/2002	FSG40	AO SMITH	0
1261	08/31/2011	MI5036FBN	BRADFORD-WHITE	0
1262	06/03/2007	LTN050GEF	LOCHINVAR	0
1263	12/14/2001	FSGL40	AO SMITH	0
1264	02/25/2008	LTN040GEF	LOCHINVAR	0
1265	10/20/2006	LTN040GEF	LOCHINVAR	2
1266	12/28/2009	21V502	RHEEM	0
1267	07/27/1999	41VR40	RHEEM	0
1268	05/10/2011	21VR40	RHEEM	0
1269	06/01/1977	KGL40	AO SMITH	0
1270	04/29/2008	LTN050GEF	LOCHINVAR	0
1271	07/29/2010	LTN050GEF	LOCHINVAR	1
1272	08/01/2006	LSN041G	LOCHINVAR	0
1273	04/04/2011	42VR50	RHEEM	0
1274	03/29/2004	BT80112	AO SMITH	0
1275	04/01/2004	GVC50	A. O. SMITH	0
1276	04/10/2007	LSN041G	LOCHINVAR	0
1277	01/23/2001	FSG50	AO SMITH	0
1278	08/26/2007	LSN041G	LOCHINVAR	0
1279	08/17/2011	M45036FBN	BRADFORD-WHITE	0
1280	10/24/2012	M45036FBN	BRADFORD-WHITE	0
1281	05/14/2004	XTN040	LOCHINVAR	0
1282	06/06/2010	LTN051G	LOCHINVAR	1
1283	02/27/2009	LTN050GEF	LOCHINVAR	0
1284	02/03/2000	PGR50	AO SMITH	0
1285	03/10/1997	FSGL40	AO SMITH	0
1286	04/16/2004	GVC50	A. O. SMITH	0
1287	07/23/2012	M45036FBN	BRADFORD-WHITE	0
1288	10/21/2003	PVR50	AO SMITH	0
1289	04/30/2001	PGR50	AO SMITH	0
1290	05/30/2009	LTN050GEF	LOCHINVAR	0
1291	10/14/2009	LTN040G	LOCHINVAR	2
1292	11/13/2008	LTN050GEF	LOCHINVAR	0
1293	02/01/2012	MI5036FBN	BRADFORD-WHITE	0
1294	10/14/2009	FSG30	AO SMITH	0
1295	01/24/2009	LTN050GEF	LOCHINVAR	0
1296	01/07/2010	41V40S	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1297	10/18/2002	FSG30	AO SMITH	1
1298	03/08/1990	FSG40	AO SMITH	0
1299	12/03/2003	FCV40	AO SMITH	0
1300	05/25/1995	PGR40	AO SMITH	0
1301	08/13/2002	FSG40	AO SMITH	0
1302	10/26/2012	M45036FBN	BRADFORD-WHITE	0
1303	12/05/2007	LTN050GEF	LOCHINVAR	0
1304	07/23/2011	M45036FBN	BRADFORD-WHITE	1
1305	10/12/2011	MI40T6FBN	BRADFORD-WHITE	0
1306	07/01/1978	PGC50	AO SMITH	0
1307	07/30/2006	LTN040G	LOCHINVAR	0
1308	11/22/2002	G76200	RUUD/RHEEM	3
1309	02/01/1973	PGX50	AO SMITH	1
1310	11/30/2011	G76200	RUUD/RHEEM	1
1311	03/13/1996	H72DUMMY	AO SMITH	0
1312	09/05/2004	GVC50	A. O. SMITH	0
1313	03/09/2009	21VR40	RHEEM	0
1314	08/23/2011	G91200	RUUD/RHEEM	1
1315	05/29/2012	P230F	RUUD	0
1316	06/09/2005	LTN050	LOCHINVAR	0
1317	08/05/2003	FSG30	AO SMITH	0
1318	09/17/2012	MI403S6FBN	BRADFORD-WHITE	1
1319	01/10/2011	21VR50	RHEEM	1
1320	08/17/1999	FSG40	AO SMITH	0
1321	09/29/2012	G82156	RUUD/RHEEM	0
1322	01/04/2002	FSG50	AO SMITH	0
1323	03/28/2009	G82156	RUUD/RHEEM	0
1324	10/17/2008	RM5063	RUUD	0
1325	03/18/2009	LTN050GEF	LOCHINVAR	0
1326	10/18/2002	FSG50	AO SMITH	0
1327	10/01/1975	PGD30	AO SMITH	0
1328	11/24/2001	FSG50	AO SMITH	0
1329	12/29/2006	LTN050G	LOCHINVAR	0
1330	05/04/2010	LTN050G	LOCHINVAR	0
1331	08/11/2000	41XR50	RHEEM	1
1332	01/31/2006	LTN040G	LOCHINVAR	0
1333	04/08/2005	FCV40	AO SMITH	0
1334	02/06/2009	LTN050G	LOCHINVAR	0
1335	12/08/2004	GVC40	A. O. SMITH	0
1336	03/07/2005	GVC50	A. O. SMITH	0
1337	02/18/2012	M45036FBN	BRADFORD-WHITE	0
1338	06/23/2012	PH199119	PHOENIX	0
1339	09/22/2005	LTN050G	LOCHINVAR	0
1340	10/29/2012	MI5036FBN	BRADFORD-WHITE	0
1341	05/22/2005	LTN050	LOCHINVAR	0
1342	09/21/2012	F72DUMMY	UNKNOWN AT CONVERSION	0
1343	01/05/2009	LTN040GEF	LOCHINVAR	0
1344	02/24/2006	FSG50	AO SMITH	0
1345	02/01/1966	PGX50	AO SMITH	1
1346	01/25/1994	H72DUMMY	AO SMITH	0
1347	09/14/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
1348	09/02/2009	LTN050GEF	LOCHINVAR	0
1349	06/26/1998	FSG40	AO SMITH	0
1350	04/12/2012	M440T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1351	12/06/2007	LTN040GEF	LOCHINVAR	0
1352	03/30/2009	LSN041G	LOCHINVAR	0
1353	08/25/2003	FCV50	AO SMITH	0
1354	09/04/2008	LTN040GEF	LOCHINVAR	0
1355	07/19/1999	21V506	RHEEM	0
1356	03/05/2012	PGX40	AO SMITH	0
1357	03/21/2012	M45036FBN	BRADFORD-WHITE	0
1358	04/21/2009	LTN050GEF	LOCHINVAR	0
1359	12/07/2007	LTN050GEF	LOCHINVAR	0
1360	02/07/2008	LTN050	LOCHINVAR	0
1361	09/13/2001	PGR50	AO SMITH	1
1362	12/01/1975	KGL40	AO SMITH	0
1363	06/02/2012	M45036FBN	BRADFORD-WHITE	0
1364	06/12/2000	FSGL40	AO SMITH	0
1365	08/08/2012	M45036FBN	BRADFORD-WHITE	1
1366	10/19/2003	PGR40	AO SMITH	0
1367	11/30/2011	G76200	RUUD/RHEEM	1
1368	04/17/2008	LTN050GEF	LOCHINVAR	0
1369	09/29/2005	LTN040G	LOCHINVAR	0
1370	10/05/1998	PGR50	AO SMITH	0
1371	10/16/2012	M45036FBN	BRADFORD-WHITE	0
1372	05/27/1998	41VR40	RHEEM	0
1373	11/08/2010	21VR40	RHEEM	0
1374	09/12/2000	41V40S	RHEEM	0
1375	10/20/2005	LTN050G	LOCHINVAR	1
1376	12/11/2000	41XR50	RHEEM	0
1377	04/27/2011	21VR50	RHEEM	0
1378	07/08/1997	21V506	RHEEM	0
1379	04/17/2012	MI50L6FBN	BRADFORD-WHITE	2
1380	03/21/2006	LTN040G	LOCHINVAR	0
1381	10/29/2009	LTN040GEF	LOCHINVAR	0
1382	10/12/2006	LTN050G	LOCHINVAR	0
1383	01/01/1960	G72DUMMY	UNKNOWN AT CONVERSION	1
1384	07/31/2002	PGR50	AO SMITH	0
1385	11/01/1978	KGA40	AO SMITH	0
1386	01/08/2009	LTN040GEF	LOCHINVAR	1
1387	11/29/2005	G82156	RUUD/RHEEM	1
1388	03/13/2005	XVR50	A. O. SMITH	1
1389	04/13/2008	LTN040	LOCHINVAR	0
1390	01/03/2007	LTN050G	LOCHINVAR	0
1391	04/27/2005	GVC50	A. O. SMITH	0
1392	08/07/1997	41VR40	RHEEM	0
1393	12/28/1999	41XR50	RHEEM	0
1394	08/31/2007	LTN040GEF	LOCHINVAR	0
1395	08/31/2005	GVC50	A. O. SMITH	0
1396	03/23/2005	ETN076	LOCHINVAR	0
1397	10/10/2005	LTN050	LOCHINVAR	1
1398	08/11/2008	LTN050GEF	LOCHINVAR	0
1399	10/27/2011	MI40T6FBN	BRADFORD-WHITE	0
1400	11/07/2000	21V506	RHEEM	1
1401	02/19/2013	MI403S6FBN	BRADFORD-WHITE	0
1402	01/05/2005	LSN041G	LOCHINVAR	0
1403	03/02/1999	41VR50	RHEEM	1
1404	03/07/2013	MI403S6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1405	05/19/2010	LTN050GEF	LOCHINVAR	2
1406	05/01/1973	A71DUMMY	UNKNOWN AT CONVERSION	0
1407	12/21/1999	FSGL40	AO SMITH	0
1408	09/27/2012	M440T6FBN	BRADFORD-WHITE	0
1409	08/31/2000	41XR40	RHEEM	0
1410	08/26/2011	M45036FBN	BRADFORD-WHITE	0
1411	03/01/2004	XTN040	LOCHINVAR	0
1412	11/10/2004	XVR50	A. O. SMITH	1
1413	08/31/2007	LTN040G	LOCHINVAR	0
1414	09/02/2011	M440T6FBN	BRADFORD-WHITE	0
1415	01/05/1996	FSGL40	AO SMITH	0
1416	04/06/2005	GVC40	A. O. SMITH	0
1417	04/04/2008	LSN041	LOCHINVAR	0
1418	12/26/2003	PGR50	AO SMITH	0
1419	12/15/2009	LTN050GEF	LOCHINVAR	0
1420	04/20/2005	GVC40	A. O. SMITH	0
1421	11/17/2008	LSN041G	LOCHINVAR	0
1422	04/23/2007	LTN040G	LOCHINVAR	2
1423	12/27/1988	FSGL40	AO SMITH	1
1424	08/18/2006	LSN041G	LOCHINVAR	0
1425	02/02/2007	G91200	RUUD/RHEEM	1
1426	04/11/2012	MI5036FBN	BRADFORD-WHITE	2
1427	09/10/2007	G91200	RUUD/RHEEM	0
1428	10/13/2005	LTN050G	LOCHINVAR	0
1429	05/29/2002	PGR50	AO SMITH	0
1430	11/12/2012	M45036FBN	BRADFORD-WHITE	0
1431	09/05/2008	P506	RUUD	0
1432	01/17/2001	41VR40	RHEEM	0
1433	05/27/2003	FSG40	AO SMITH	1
1434	12/20/1993	FSGL40	AO SMITH	0
1435	09/29/1999	FSG50	AO SMITH	0
1436	09/03/2008	LTN050GEF	LOCHINVAR	0
1437	01/05/2002	PGR50	AO SMITH	0
1438	04/25/2000	PHR50	RUUD	0
1439	08/18/2006	LTN040G	LOCHINVAR	0
1440	04/23/2010	G82156	RUUD/RHEEM	0
1441	01/29/2004	XTN040	LOCHINVAR	0
1442	10/29/2002	FSG50	AO SMITH	0
1443	04/06/2001	FSG50	AO SMITH	0
1444	12/28/2012	MI5036FBN	BRADFORD-WHITE	1
1445	09/25/1999	41VR40	RHEEM	1
1446	10/01/1972	PGX50	AO SMITH	0
1447	01/11/2010	LSN041G	LOCHINVAR	0
1448	03/11/2008	LTN050	LOCHINVAR	0
1449	11/25/2008	LTN040G	LOCHINVAR	0
1450	06/06/2005	LTN050	LOCHINVAR	0
1451	01/09/2010	LTN050GEF	LOCHINVAR	0
1452	07/10/2001	FSG40	AO SMITH	0
1453	08/27/2009	LTN040GEF	LOCHINVAR	0
1454	01/13/2011	42VR50	RHEEM	0
1455	11/26/2008	LTN050GEF	LOCHINVAR	1
1456	10/06/2003	FCV40	AO SMITH	2
1457	08/13/2004	21V502	RHEEM	1
1458	04/14/2011	21VR50	RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1459	12/23/2002	PGR50	AO SMITH	0
1460	12/13/2007	LTN050G	LOCHINVAR	0
1461	10/08/2010	LTN040GEF	LOCHINVAR	0
1462	05/12/2004	GVC50	A. O. SMITH	0
1463	01/23/2013	M45036FBN	BRADFORD-WHITE	0
1464	01/11/2012	MI5036FBN	BRADFORD-WHITE	2
1465	09/10/2004	GVC40	A. O. SMITH	1
1466	07/26/2010	21VR50	RHEEM	0
1467	09/24/2007	LTN050GEF	LOCHINVAR	0
1468	12/11/2009	LTN050GEF	LOCHINVAR	0
1469	09/01/1978	PGC40	AO SMITH	0
1470	06/23/1993	FSGL40	AO SMITH	0
1471	04/13/2004	GVC40	A. O. SMITH	0
1472	03/16/2009	G91200	RUUD/RHEEM	1
1473	09/06/2001	PGR50	AO SMITH	0
1474	03/03/2003	FSGL40	AO SMITH	0
1475	07/16/2005	LTN040	LOCHINVAR	1
1476	07/28/2005	LTN050	LOCHINVAR	0
1477	03/08/2000	41XR50	RHEEM	0
1478	12/13/2008	LTN050GEF	LOCHINVAR	0
1479	04/24/2007	LTN040GEF	LOCHINVAR	3
1480	08/16/2008	G75125	RUUD/RHEEM	0
1481	01/17/2007	G91200	RUUD/RHEEM	0
1482	01/11/1999	FGR40	AO SMITH	0
1483	11/20/2007	GVC30	AOSMITH	0
1484	02/25/2005	GVC50	A. O. SMITH	4
1485	07/01/1973	PGX40	AO SMITH	0
1486	03/16/2004	GVC50	A. O. SMITH	0
1487	09/12/2002	PGR50	AO SMITH	0
1488	01/30/2004	PVR50	AO SMITH	1
1489	01/14/2010	LTN050GEF	LOCHINVAR	0
1490	07/22/2002	PGR40	AO SMITH	1
1491	05/03/2007	LTN040G	LOCHINVAR	0
1492	04/26/2006	LTN050G	LOCHINVAR	0
1493	01/28/2009	LTN050GEF	LOCHINVAR	4
1494	09/03/1999	41VR50	RHEEM	0
1495	03/28/2006	LTN050G	LOCHINVAR	0
1496	10/21/2000	PGR50	AO SMITH	0
1497	05/22/2009	LSN041G	LOCHINVAR	0
1498	10/01/1996	FGR50	AO SMITH	0
1499	04/19/2012	MI40T6FBN	BRADFORD-WHITE	1
1500	07/18/2012	G91200	RUUD/RHEEM	0
1501	08/22/2007	LTN050GEF	LOCHINVAR	1
1502	03/17/2006	LTN050GEF	LOCHINVAR	0
1503	09/26/2002	FSGL40	AO SMITH	0
1504	04/26/2010	LTN040G	LOCHINVAR	0
1505	07/23/1998	FGR40	AO SMITH	0
1506	10/10/2005	LTN040GEF	LOCHINVAR	0
1507	03/06/2013	MI403S6FBN	BRADFORD-WHITE	0
1508	01/18/2005	XVR40	A. O. SMITH	0
1509	03/26/2007	LSN041G	LOCHINVAR	0
1510	03/22/2002	FSG40	AO SMITH	0
1511	02/23/2011	22V40SF	RHEEM	0
1512	04/04/2005	GVC40	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1513	05/12/1992	FSG40	AO SMITH	0
1514	06/12/2008	LTN050GEF	LOCHINVAR	1
1515	10/18/2004	GVC50	A. O. SMITH	0
1516	02/24/2011	42VR50	RHEEM	0
1517	11/07/2007	LSN041G	LOCHINVAR	1
1518	10/01/1976	KGA40	AO SMITH	0
1519	06/04/2011	41VR40	RHEEM	0
1520	01/21/2000	PGR50	AO SMITH	0
1521	12/17/2012	MI40T6FBN	BRADFORD-WHITE	0
1522	09/12/2002	FSG50	AO SMITH	0
1523	06/01/1971	E71DUMMY	UNKNOWN AT CONVERSION	0
1524	10/23/1999	FSG30	AO SMITH	0
1525	02/27/2009	LTN050GEF	LOCHINVAR	0
1526	12/16/2009	LTN040G	LOCHINVAR	0
1527	10/16/2008	LTN040G	LOCHINVAR	0
1528	12/02/2000	FSGL40	AO SMITH	0
1529	05/18/2001	41V50	RHEEM	0
1530	08/05/2011	M440T6FBN	BRADFORD-WHITE	0
1531	06/24/1998	G91200	RUUD/RHEEM	0
1532	05/28/2000	41XR40	RHEEM	1
1533	11/02/1999	PGR50	AO SMITH	0
1534	11/14/1978	RH3063	RUUD	0
1535	09/28/2007	LTN050GEF	LOCHINVAR	0
1536	11/18/2009	LTN040GEF	LOCHINVAR	1
1537	04/28/1995	PHR50	RUUD	0
1538	12/13/2002	FSGL40	AO SMITH	0
1539	11/17/1978	G76200	RUUD/RHEEM	0
1540	04/07/2008	LTN040	LOCHINVAR	1
1541	10/31/2011	M45036FBN	BRADFORD-WHITE	2
1542	11/30/2012	M45036FBN	BRADFORD-WHITE	0
1543	12/24/2012	MI403S6FBN	BRADFORD-WHITE	0
1544	05/28/1999	FGR50	AO SMITH	0
1545	09/14/2006	LTN050G	LOCHINVAR	0
1546	02/13/2009	PGXL40	AO SMITH	0
1547	08/10/2006	LSN041G	LOCHINVAR	0
1548	09/02/2008	LTN050G	LOCHINVAR	0
1549	06/15/2007	LSN041G	LOCHINVAR	0
1550	06/11/2010	LTN050GEF	LOCHINVAR	0
1551	05/04/2001	FSG50	AO SMITH	0
1552	09/22/2008	PH199119	PHOENIX	2
1553	02/28/2000	FSG40	AO SMITH	1
1554	06/09/2006	LSN041G	LOCHINVAR	0
1555	10/23/2005	LTN040G	LOCHINVAR	0
1556	01/18/2011	42VR50	RHEEM	0
1557	06/27/1995	FGR40	AO SMITH	0
1558	05/27/2004	G91200	RUUD/RHEEM	1
1559	08/17/1993	P506	RUUD	0
1560	03/10/2009	LTN040GEF	LOCHINVAR	0
1561	01/11/1997	FGR30	AO SMITH	1
1562	03/06/2011	21VR50	RHEEM	0
1563	07/02/2009	LTN040GEF	LOCHINVAR	0
1564	08/08/2007	LTN040G	LOCHINVAR	1
1565	03/10/2002	G91200	RUUD/RHEEM	0
1566	06/05/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1567	06/04/2011	21VR50	RHEEM	0
1568	02/25/2008	LTN050GEF	LOCHINVAR	0
1569	03/07/1994	RF92200	RUUD	0
1570	01/30/2009	LTN050G	LOCHINVAR	0
1571	02/18/1999	FSG40	AO SMITH	0
1572	06/17/2008	LSN041G	LOCHINVAR	0
1573	02/19/1999	FSG40	AO SMITH	0
1574	12/18/2012	L72DUMMY	UNKNOWN AT CONVERSION	0
1575	03/15/2006	LTN050G	LOCHINVAR	0
1576	09/18/2002	PGR50	AO SMITH	0
1577	02/17/1989	FSG40	AO SMITH	0
1578	03/15/2011	21VR40	RHEEM	0
1579	02/26/2000	FSG40	AO SMITH	0
1580	11/01/2011	M45036FBN	BRADFORD-WHITE	0
1581	07/15/2011	M440T6FBN	BRADFORD-WHITE	0
1582	03/18/2008	LTN050GEF	LOCHINVAR	0
1583	09/14/2011	M45036FBN	BRADFORD-WHITE	0
1584	08/22/2010	LTN040GEF	LOCHINVAR	0
1585	01/06/2009	LTN040GEF	LOCHINVAR	0
1586	06/01/1999	G91200	RUUD/RHEEM	0
1587	06/14/2005	LTN050	LOCHINVAR	0
1588	07/24/2008	LTN050G	LOCHINVAR	0
1589	10/01/2003	FSG40	AO SMITH	0
1590	04/18/2009	LTN040GEF	LOCHINVAR	0
1591	01/31/1997	FSGL40	AO SMITH	0
1592	08/01/2002	FSG40	AO SMITH	0
1593	03/12/1997	FGR40	AO SMITH	0
1594	09/28/2012	M440T6FBN	BRADFORD-WHITE	0
1595	11/17/2008	LTN040GEF	LOCHINVAR	0
1596	03/16/1999	21V407	RHEEM	0
1597	05/23/1997	FGR50	AO SMITH	0
1598	05/31/2008	LTN050G	LOCHINVAR	3
1599	06/01/1964	G67114	RUUD	0
1600	06/17/2010	LTN040GEF	LOCHINVAR	0
1601	05/10/2006	LTN050G	LOCHINVAR	1
1602	11/28/2007	LTN050G	LOCHINVAR	0
1603	02/27/1995	FGR40	AO SMITH	0
1604	07/01/2003	PGR40	AO SMITH	0
1605	10/10/2001	FSG40	AO SMITH	0
1606	12/12/2007	LTN050GEF	LOCHINVAR	0
1607	02/17/2007	41V50	RHEEM	0
1608	06/25/2012	MI50L6FBN	BRADFORD-WHITE	1
1609	04/17/2012	M45036FBN	BRADFORD-WHITE	0
1610	12/28/2001	41XR50	RHEEM	0
1611	05/26/2012	MI40T6FBN	BRADFORD-WHITE	0
1612	12/13/2010	LTN050G	LOCHINVAR	0
1613	07/04/1998	FSG40	AO SMITH	0
1614	02/14/2011	22DV50F	RHEEM	0
1615	03/26/1999	G82156	RUUD/RHEEM	0
1616	06/17/2001	PGR40	AO SMITH	0
1617	08/31/2012	MI40T6FBN	BRADFORD-WHITE	1
1618	09/06/2001	FSGL40	AO SMITH	0
1619	07/31/1996	G67114	RHEEM	0
1620	06/09/2005	ETN076	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1621	02/19/2008	LTN050	LOCHINVAR	0
1622	05/28/1996	FGR40	AO SMITH	0
1623	09/13/2010	LTN040GEF	LOCHINVAR	0
1624	09/08/2009	LTN050GEF	LOCHINVAR	0
1625	10/01/2006	LTN050GEF	LOCHINVAR	0
1626	06/25/2010	LTN050GEF	LOCHINVAR	0
1627	11/15/2005	LTN050GEF	LOCHINVAR	0
1628	11/15/2008	LTN050GEF	LOCHINVAR	0
1629	03/27/1991	FSGL40	AO SMITH	0
1630	02/02/2009	LTN050GEF	LOCHINVAR	0
1631	02/20/2003	FSG30	AO SMITH	0
1632	03/24/2009	LTN040GEF	LOCHINVAR	0
1633	09/16/2002	FSGL40	AO SMITH	0
1634	08/06/2007	LTN050GEF	LOCHINVAR	0
1635	09/16/2000	41XR50	RHEEM	0
1636	03/27/2009	LSN041G	LOCHINVAR	0
1637	12/06/2011	MI403S6FBN	BRADFORD-WHITE	0
1638	08/04/2007	LTN040GEF	LOCHINVAR	0
1639	08/06/2007	LTN040GEF	LOCHINVAR	0
1640	09/09/2008	P506	RUUD	0
1641	03/13/2007	LSN041G	LOCHINVAR	0
1642	10/17/2004	GCVL40	A. O. SMITH	0
1643	05/31/2002	FSG50	AO SMITH	0
1644	02/16/2007	LTN050G	LOCHINVAR	0
1645	05/17/1978	RM5063	RHEEM	0
1646	07/03/2000	41XR50	RHEEM	1
1647	06/18/2002	FSG40	AO SMITH	0
1648	09/23/1994	FSGL40	AO SMITH	0
1649	12/03/2004	GVC50	A. O. SMITH	0
1650	04/21/2003	PGR50	AO SMITH	0
1651	10/06/2012	M45036FBN	BRADFORD-WHITE	0
1652	10/10/2007	LTN050GEF	LOCHINVAR	0
1653	08/17/2004	XVR50	A. O. SMITH	0
1654	03/08/2009	LTN050GEF	LOCHINVAR	0
1655	10/29/2012	G82156	RUUD/RHEEM	1
1656	04/06/2001	41V50	RHEEM	1
1657	02/25/2010	G76200	RUUD/RHEEM	3
1658	11/27/2001	FSGL40	AO SMITH	0
1659	01/14/2009	21VR40	RHEEM	0
1660	08/19/2008	LTN040GEF	LOCHINVAR	0
1661	12/10/2009	LSN041G	LOCHINVAR	0
1662	05/02/2004	GVC40	A. O. SMITH	0
1663	12/19/2011	MI5036FBN	BRADFORD-WHITE	0
1664	08/27/2008	ETN076	LOCHINVAR	1
1665	07/03/2012	MI40T6FBN	BRADFORD-WHITE	0
1666	10/03/2003	PVR40	AO SMITH	0
1667	11/04/2010	42VR50	RHEEM	0
1668	02/26/2004	XTN050	LOCHINVAR	0
1669	05/03/2000	FSG50	AO SMITH	0
1670	06/01/1967	PGX50	AO SMITH	1
1671	03/18/2010	LTN040GEF	LOCHINVAR	1
1672	06/14/2002	PRX50	STATE	0
1673	05/20/1992	H72DUMMY	AO SMITH	0
1674	05/03/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1675	12/08/2011	M45036FBN	BRADFORD-WHITE	1
1676	09/21/1998	FGR40	AO SMITH	0
1677	10/28/2010	PVR50	AO SMITH	2
1678	02/05/2008	LTN040	LOCHINVAR	0
1679	07/21/1994	FGR40	AO SMITH	1
1680	10/31/2012	M45036FBN	BRADFORD-WHITE	0
1681	04/27/2011	21VR40	RHEEM	0
1682	05/28/2012	P230F	RUUD	0
1683	09/21/2007	ETN065	LOCHINVAR	0
1684	05/26/2005	LTN040	LOCHINVAR	0
1685	09/26/2012	MI5036FBN	BRADFORD-WHITE	0
1686	04/11/1995	21V506	RHEEM	0
1687	02/11/2002	FSG40	AO SMITH	0
1688	04/12/2002	FSG40	AO SMITH	0
1689	06/05/2007	LSN041G	LOCHINVAR	0
1690	01/01/2009	LTN040GEF	LOCHINVAR	0
1691	04/12/2002	PGR50	AO SMITH	0
1692	07/22/2004	42V6050	RHEEM	0
1693	07/25/2011	MI40T6FBN	BRADFORD-WHITE	0
1694	10/03/2009	LTN050GEF	LOCHINVAR	0
1695	02/03/2010	LTN050GEF	LOCHINVAR	0
1696	03/02/2000	PGR50	AO SMITH	0
1697	04/23/2007	XSN040GEF	LOCHINVAR	0
1698	10/09/2000	41XR50	RHEEM	0
1699	01/12/2010	LTN040G	LOCHINVAR	0
1700	06/14/2006	LTN050G	LOCHINVAR	0
1701	01/24/2013	MI403S6FBN	BRADFORD-WHITE	0
1702	02/02/2011	42VR50	RHEEM	0
1703	07/14/2006	G91200	RUUD/RHEEM	0
1704	09/17/2004	XVR50	A. O. SMITH	0
1705	09/28/2004	LTN040	LOCHINVAR	0
1706	05/05/2010	G76200	RUUD/RHEEM	2
1707	12/12/2011	MI5036FBN	BRADFORD-WHITE	0
1708	07/14/2006	G91200	RUUD/RHEEM	1
1709	05/01/2001	FSG50	AO SMITH	0
1710	05/05/2010	G76200	RUUD/RHEEM	0
1711	11/14/1997	21V402S	RHEEM	0
1712	06/25/2007	LTN050G	LOCHINVAR	0
1713	01/04/2005	LSN041G	LOCHINVAR	0
1714	03/10/2006	LTN050G	LOCHINVAR	0
1715	04/13/1998	PGR40	AO SMITH	0
1716	12/11/1999	FSG40	AO SMITH	0
1717	10/27/2012	M45036FBN	BRADFORD-WHITE	0
1718	10/06/1997	FGR50	AO SMITH	0
1719	08/29/1997	PGR40	AO SMITH	0
1720	04/09/2007	LTN050G	LOCHINVAR	0
1721	01/15/2002	FSG40	AO SMITH	0
1722	10/20/2011	PH250SF	RUUD	0
1723	02/07/2013	MI40T6FBN	BRADFORD-WHITE	0
1724	02/18/2005	XVR50	A. O. SMITH	0
1725	02/21/2001	FSG50	AO SMITH	0
1726	07/23/2010	LTN040GEF	LOCHINVAR	0
1727	05/27/2005	LTN050G	LOCHINVAR	0
1728	08/30/1994	RF67120	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1729	05/23/1997	FSG40	AO SMITH	1
1730	09/29/2000	FSGL40	AO SMITH	0
1731	05/02/2002	41XR50	RHEEM	0
1732	05/01/1979	RM5063	RUUD	0
1733	01/02/2013	M440T6FBN	BRADFORD-WHITE	0
1734	01/05/2011	G91200	RUUD/RHEEM	0
1735	10/23/2011	MI403S6FBN	BRADFORD-WHITE	0
1736	02/19/1999	41VR50	RHEEM	0
1737	08/29/2002	FSG50	AO SMITH	0
1738	01/14/2009	LTN050GEF	LOCHINVAR	0
1739	05/04/2009	LSN041G	LOCHINVAR	0
1740	11/29/2004	XVR50	A. O. SMITH	0
1741	07/01/2005	LTN050GEF	LOCHINVAR	0
1742	01/18/1996	PR502T	RUUD	1
1743	09/28/2001	41XR50	RHEEM	0
1744	10/16/2008	LTN050GEF	LOCHINVAR	0
1745	12/27/2001	FSG40	AO SMITH	0
1746	11/03/2002	FSG50	AO SMITH	0
1747	04/26/2012	MI403S6FBN	BRADFORD-WHITE	0
1748	04/01/2011	41VR40	RHEEM	0
1749	12/23/1997	PGR50	AO SMITH	0
1750	10/01/1994	PGR50	AO SMITH	0
1751	11/04/2008	LTN050GEF	LOCHINVAR	1
1752	02/14/2008	LTN050	LOCHINVAR	0
1753	11/27/2004	XVR50	A. O. SMITH	1
1754	08/31/2007	LTN050G	LOCHINVAR	0
1755	03/31/2011	41VR50	RHEEM	0
1756	03/16/2004	XTN040	LOCHINVAR	0
1757	01/25/2008	LTN050GEF	LOCHINVAR	0
1758	06/29/2011	MI403S6FBN	BRADFORD-WHITE	3
1759	01/03/2011	LTN040G	LOCHINVAR	0
1760	04/05/2007	LTN050GEF	LOCHINVAR	0
1761	12/30/1992	FSG50	AO SMITH	0
1762	11/23/2011	PR502T	RUUD	0
1763	07/01/2011	MI5036FBN	BRADFORD-WHITE	0
1764	06/01/2012	M45036FBN	BRADFORD-WHITE	1
1765	10/01/2003	FSG40	AO SMITH	0
1766	04/17/2007	LTN050G	LOCHINVAR	0
1767	05/24/2005	LTN040	LOCHINVAR	0
1768	08/30/2004	G75125	RUUD/RHEEM	0
1769	05/26/2000	PGR50	AO SMITH	0
1770	04/26/1996	G75125	RUUD/RHEEM	0
1771	02/13/2006	LTN040GEF	LOCHINVAR	0
1772	10/01/1968	A71DUMMY	UNKNOWN AT CONVERSION	0
1773	05/21/1998	FGR50	AO SMITH	0
1774	09/16/1999	FSG40	AO SMITH	0
1775	07/08/2006	LTN050GEF	LOCHINVAR	0
1776	03/28/2003	FSGL40	AO SMITH	0
1777	01/14/2009	21VR40	RHEEM	0
1778	08/17/2001	FSG40	AO SMITH	0
1779	10/23/2003	FCV50	AO SMITH	0
1780	09/18/2001	FSG50	AO SMITH	0
1781	02/18/1999	41V50	RHEEM	0
1782	07/10/2012	G82156	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1783	12/26/1996	PGR40	AO SMITH	0
1784	07/10/2012	G82156	RUUD/RHEEM	0
1785	08/02/2006	LSN041G	LOCHINVAR	1
1786	11/02/2010	21VR50	RHEEM	0
1787	03/13/2009	LTN050GEF	LOCHINVAR	0
1788	06/20/2011	M45036FBN	BRADFORD-WHITE	0
1789	09/24/2008	PHR40	RUUD	0
1790	02/19/2007	LTN040G	LOCHINVAR	0
1791	01/10/2008	LTN050GEF	LOCHINVAR	0
1792	10/08/2005	LTN050GEF	LOCHINVAR	0
1793	10/08/2009	LTN040GEF	LOCHINVAR	0
1794	12/10/1999	PGR50	AO SMITH	0
1795	10/11/1999	FSGL40	AO SMITH	0
1796	02/27/2007	FSG40	AO SMITH	0
1797	01/02/2002	FSG50	AO SMITH	0
1798	12/15/2006	GCVL40	A. O. SMITH	0
1799	12/11/2009	LTN030G	AO SMITH	0
1800	10/30/2003	PGR40	AO SMITH	0
1801	10/11/2005	LTN050	LOCHINVAR	1
1802	02/24/2007	LTN050G	LOCHINVAR	0
1803	07/07/2010	LTN050GEF	LOCHINVAR	0
1804	01/05/2010	LTN040G	LOCHINVAR	1
1805	06/14/2012	MI403S6FBN	BRADFORD-WHITE	0
1806	10/16/2002	PRX50	STATE	2
1807	12/29/2006	LTN050G	LOCHINVAR	0
1808	04/21/2006	LTN040G	LOCHINVAR	0
1809	11/20/2003	PGR50	AO SMITH	0
1810	03/16/2010	LSN041G	LOCHINVAR	0
1811	09/01/1981	H72DUMMY	AO SMITH	0
1812	07/21/1994	FGR40	AO SMITH	1
1813	09/06/2006	LTN050G	LOCHINVAR	1
1814	09/05/2012	M440T6FBN	BRADFORD-WHITE	0
1815	12/07/2007	LTN040	LOCHINVAR	3
1816	09/13/2005	LTN040	LOCHINVAR	0
1817	03/28/2002	FSGL40	AO SMITH	0
1818	12/04/2008	LTN050GEF	LOCHINVAR	1
1819	03/09/1998	PGR40	AO SMITH	0
1820	06/22/2011	G75125	RUUD/RHEEM	5
1821	09/02/2010	LTN050GEF	LOCHINVAR	0
1822	12/23/2006	LSN041G	LOCHINVAR	0
1823	01/31/2012	MI40T6FBN	BRADFORD-WHITE	1
1824	02/17/1998	G67114	RHEEM	0
1825	12/23/2003	PGR50	AO SMITH	0
1826	11/03/2008	LTN040GEF	LOCHINVAR	1
1827	02/15/2011	LTN040GEF	LOCHINVAR	0
1828	08/17/2007	TNR200100	LOCHINVAR	0
1829	03/21/1998	PGR50	AO SMITH	0
1830	09/30/2010	LTN040GEF	LOCHINVAR	0
1831	08/16/2012	MI40T6FBN	BRADFORD-WHITE	0
1832	02/20/2010	LTN050GEF	LOCHINVAR	0
1833	05/27/2009	LTN050GEF	LOCHINVAR	0
1834	09/12/2006	LTN040GEF	LOCHINVAR	0
1835	01/23/2013	M440T6FBN	BRADFORD-WHITE	0
1836	10/31/2006	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1837	02/21/2006	LTN040G	LOCHINVAR	1
1838	08/02/2010	LTN050GEF	LOCHINVAR	0
1839	09/16/2009	LTN040GEF	LOCHINVAR	0
1840	05/05/2008	LTN050GEF	LOCHINVAR	0
1841	08/01/1964	PGX30	AO SMITH	0
1842	02/01/2013	M45036FBN	BRADFORD-WHITE	0
1843	11/29/2010	LTN040GEF	LOCHINVAR	0
1844	09/13/2012	MI403S6FBN	BRADFORD-WHITE	0
1845	08/27/2007	LSN041G	LOCHINVAR	0
1846	06/29/2007	LSN041G	LOCHINVAR	0
1847	02/22/2006	LTN050G	LOCHINVAR	0
1848	09/16/2010	LTN040GEF	LOCHINVAR	0
1849	08/05/2009	42VR50	RHEEM	0
1850	09/04/1996	FGR50	AO SMITH	0
1851	08/23/2011	M45036FBN	BRADFORD-WHITE	0
1852	03/15/2005	GCVL40	A. O. SMITH	0
1853	04/25/2011	41VR50	RHEEM	0
1854	03/12/2008	LTN050	LOCHINVAR	0
1855	05/07/2010	LTN050GEF	LOCHINVAR	0
1856	11/06/2006	LTN050G	LOCHINVAR	0
1857	03/25/2002	FSGL40	AO SMITH	0
1858	01/20/2013	G91200	RUUD/RHEEM	0
1859	08/02/2004	P506	RUUD	0
1860	10/10/2007	LTN040G	LOCHINVAR	0
1861	09/17/1996	PGR40	AO SMITH	0
1862	08/11/1998	FGR40	AO SMITH	0
1863	04/02/2007	LTN050G	LOCHINVAR	0
1864	07/31/2006	LSN041G	LOCHINVAR	0
1865	06/14/2012	FCV50	AO SMITH	0
1866	04/23/2012	M45036FBN	BRADFORD-WHITE	0
1867	07/08/2002	FSG50	AO SMITH	0
1868	04/13/2011	21VR40	RHEEM	1
1869	01/05/2011	41VR40	RHEEM	0
1870	04/26/2000	FSG40	AO SMITH	0
1871	06/08/1992	FSG50	AO SMITH	0
1872	05/25/2006	LTN040G	LOCHINVAR	1
1873	02/06/2010	LTN050GEF	LOCHINVAR	0
1874	05/09/2008	LTN050GEF	LOCHINVAR	0
1875	05/27/2005	LTN050	LOCHINVAR	0
1876	04/21/2010	LSN041G	LOCHINVAR	0
1877	04/08/2003	PGR50	AO SMITH	0
1878	12/30/2008	LSN041G	LOCHINVAR	0
1879	09/10/1999	PHR50	RUUD	0
1880	10/30/2009	LTN040GEF	LOCHINVAR	0
1881	05/10/2012	PH2DV50F	RUUD	0
1882	10/30/2000	FSG40	AO SMITH	0
1883	06/07/2002	G82156	RUUD/RHEEM	1
1884	11/27/2001	G75125	RUUD/RHEEM	0
1885	08/03/2006	LTN040G	LOCHINVAR	0
1886	05/11/2000	FSG40	AO SMITH	0
1887	01/08/2003	41V50S	RHEEM	0
1888	06/19/2004	FCV40	AO SMITH	0
1889	11/12/2002	FSG40	AO SMITH	0
1890	06/13/2012	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1891	12/21/2002	FSGL40	AO SMITH	2
1892	01/11/2001	41XR50	RHEEM	0
1893	09/17/1999	41VR50	RHEEM	0
1894	07/01/1978	PGC50	AO SMITH	0
1895	05/29/2004	XVR50	A. O. SMITH	0
1896	01/21/2002	FSG30	AO SMITH	0
1897	10/02/2000	FSGL40	AO SMITH	0
1898	05/10/2012	MI5036FBN	BRADFORD-WHITE	1
1899	01/08/2004	21V506	RHEEM	1
1900	05/07/2009	G82156	RUUD/RHEEM	1
1901	03/05/2008	LTN040	LOCHINVAR	0
1902	11/27/2012	M45036FBN	BRADFORD-WHITE	0
1903	12/27/2005	LTN040G	LOCHINVAR	0
1904	12/22/2005	LTN040GEF	LOCHINVAR	1
1905	04/01/2005	GVC50	A. O. SMITH	0
1906	05/05/1997	PGR50	AO SMITH	0
1907	03/04/2002	PGR40	AO SMITH	0
1908	05/25/1994	PGR50	AO SMITH	0
1909	10/22/1986	G76200	RUUD/RHEEM	0
1910	07/12/2007	LTN040G	LOCHINVAR	2
1911	07/23/2003	FSG40	AO SMITH	0
1912	10/03/2007	LTN040G	LOCHINVAR	0
1913	04/12/1999	FGR50	AO SMITH	0
1914	12/10/2005	LTN050G	LOCHINVAR	0
1915	09/08/2011	M440T6FBN	BRADFORD-WHITE	0
1916	03/06/2003	FSG40	AO SMITH	0
1917	05/03/2012	M45036FBN	BRADFORD-WHITE	0
1918	06/02/2010	LTN040GEF	LOCHINVAR	0
1919	06/12/2007	LSN041G	LOCHINVAR	0
1920	07/26/2007	LTN050GEF	LOCHINVAR	0
1921	09/02/1999	41VR40	RHEEM	0
1922	01/22/2013	MI40T6FBN	BRADFORD-WHITE	0
1923	12/05/2008	LTN040G	LOCHINVAR	0
1924	06/16/2010	LTN040GEF	LOCHINVAR	0
1925	07/17/2000	PHR40	RUUD	0
1926	12/01/2012	M45036FBN	BRADFORD-WHITE	0
1927	08/24/2012	G91200	RUUD/RHEEM	0
1928	08/27/2003	PGR40	AO SMITH	0
1929	09/17/2002	PGR50	AO SMITH	0
1930	02/02/2012	M45036FBN	BRADFORD-WHITE	2
1931	12/10/2007	LTN040G	LOCHINVAR	0
1932	03/28/2008	LTN040GEF	LOCHINVAR	0
1933	12/04/2012	G82156	RUUD/RHEEM	0
1934	07/09/2012	MI5036FBN	BRADFORD-WHITE	0
1935	07/11/1997	PGR50	AO SMITH	0
1936	10/15/2004	GCVL40	A. O. SMITH	1
1937	03/05/2013	M45036FBN	BRADFORD-WHITE	0
1938	09/17/2001	FSG40	AO SMITH	0
1939	01/15/2003	H72DUMMY	AO SMITH	0
1940	11/25/1997	FGR40	AO SMITH	0
1941	11/08/2008	LSN041G	LOCHINVAR	0
1942	04/28/2009	LTN050GEF	LOCHINVAR	1
1943	03/21/2005	GVC50	A. O. SMITH	0
1944	08/18/2008	P506	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1945	12/24/2001	FSG40	AO SMITH	0
1946	01/10/2011	42XR50	RHEEM	0
1947	12/01/2005	LTN040G	LOCHINVAR	0
1948	07/08/2011	42VR50	RHEEM	1
1949	01/22/2007	LTN050G	LOCHINVAR	0
1950	03/11/2003	PGR50	AO SMITH	0
1951	09/14/1991	21V502	RHEEM	0
1952	11/01/1974	PGX50	AO SMITH	0
1953	12/30/1974	PGX40	AO SMITH	1
1954	07/15/2008	LTN050GEF	LOCHINVAR	0
1955	12/07/2010	LTN040GEF	LOCHINVAR	0
1956	12/29/2008	LTN040GEF	LOCHINVAR	0
1957	08/02/2008	LTN040GEF	LOCHINVAR	0
1958	01/12/2006	LSN041G	LOCHINVAR	3
1959	06/07/1996	FGR50	AO SMITH	0
1960	02/14/2012	MI5036FBN	BRADFORD-WHITE	0
1961	10/11/2001	FSG30	AO SMITH	0
1962	07/30/2009	LTN050GEF	LOCHINVAR	0
1963	02/22/2008	LTN050GEF	LOCHINVAR	0
1964	04/03/2008	LTN050GEF	LOCHINVAR	0
1965	06/19/2003	FSG50	AO SMITH	0
1966	05/05/2006	SBF100199NES	STATE	0
1967	01/01/2006	LTN050G	LOCHINVAR	1
1968	08/16/2000	FSG40	AO SMITH	0
1969	03/13/2013	M45036FBN	BRADFORD-WHITE	1
1970	01/03/2008	LTN050GEF	LOCHINVAR	0
1971	11/17/2011	FGR50	AO SMITH	0
1972	01/26/1998	FSG50	AO SMITH	0
1973	06/09/2011	21VR40	RHEEM	0
1974	06/11/2010	LTN050GEF	LOCHINVAR	0
1975	10/24/1974	PGXL40	AO SMITH	0
1976	03/04/2005	GVC50	A. O. SMITH	0
1977	05/31/1997	PGR40	AO SMITH	0
1978	03/11/1997	21VR40	RHEEM	0
1979	03/04/1999	FSG40	AO SMITH	0
1980	12/13/2001	FSG50	AO SMITH	0
1981	10/30/2009	LTN050GEF	LOCHINVAR	0
1982	11/11/2008	G91200	RUUD/RHEEM	0
1983	02/09/2002	FSG40	AO SMITH	0
1984	01/09/2009	LTN040G	LOCHINVAR	0
1985	12/11/2009	21V407	RHEEM	3
1986	08/24/2005	G82156	RUUD/RHEEM	0
1987	11/23/2001	PGR50	AO SMITH	0
1988	09/01/1978	RH3063	RUUD	0
1989	07/24/2001	FSG40	AO SMITH	0
1990	09/04/2007	LTN040GEF	LOCHINVAR	1
1991	01/23/2007	LTN050G	LOCHINVAR	0
1992	04/20/1999	FGR50	AO SMITH	0
1993	09/30/1970	PGX50	AO SMITH	0
1994	04/27/2005	LTN050	LOCHINVAR	0
1995	02/11/2011	21VR50	RHEEM	0
1996	08/29/1999	FGR40	AO SMITH	0
1997	02/01/2008	LTN050GEF	LOCHINVAR	0
1998	06/09/2007	LTN050GEF	LOCHINVAR	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
1999	12/11/2010	21VR40	RHEEM	1
2000	10/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	1
2001	12/12/2011	M45036FBN	BRADFORD-WHITE	1
2002	07/05/2011	MI40T6FBN	BRADFORD-WHITE	0
2003	06/29/1993	FSG40	AO SMITH	0
2004	10/16/2001	FSG40	AO SMITH	1
2005	09/10/2004	FSG40	AO SMITH	1
2006	07/06/2009	LTN050GEF	LOCHINVAR	0
2007	10/12/2007	LSN041G	LOCHINVAR	0
2008	10/03/2001	FSG40	AO SMITH	0
2009	06/22/2001	G75125	RUUD/RHEEM	2
2010	02/12/2001	41V40S	RHEEM	0
2011	07/01/1969	PGX40	AO SMITH	0
2012	12/14/2007	LSN041G	LOCHINVAR	0
2013	09/18/2006	LTN040G	LOCHINVAR	1
2014	08/14/2001	FSG40	AO SMITH	0
2015	07/12/2010	LTN050GEF	LOCHINVAR	0
2016	08/29/1997	41VR50	RHEEM	0
2017	08/15/2008	LTN040GEF	LOCHINVAR	0
2018	08/05/2003	PVR40	AO SMITH	1
2019	12/28/2004	GCVL40	A. O. SMITH	0
2020	05/27/2008	LTN050G	LOCHINVAR	0
2021	03/30/2007	XSN040	LOCHINVAR	0
2022	01/11/2005	GVC40	A. O. SMITH	0
2023	05/03/2011	41VR50	RHEEM	0
2024	08/19/2010	LTN040GEF	LOCHINVAR	0
2025	10/05/1992	FSG50	AO SMITH	0
2026	04/13/2004	XVR40	A. O. SMITH	0
2027	02/18/2005	LTN050	LOCHINVAR	1
2028	10/29/2007	LTN040G	LOCHINVAR	0
2029	08/30/2011	MI5036FBN	BRADFORD-WHITE	1
2030	05/16/2010	LTN040GEF	LOCHINVAR	0
2031	08/11/2003	FSGL40	AO SMITH	0
2032	03/19/2009	LTN050GEF	LOCHINVAR	0
2033	04/14/2001	41V50	RHEEM	0
2034	04/28/2012	M45036FBN	BRADFORD-WHITE	0
2035	12/12/2009	LTN050G	LOCHINVAR	1
2036	01/16/2009	FGR50	AO SMITH	0
2037	09/03/1992	RF67120	RUUD	1
2038	06/20/2000	FSG40	AO SMITH	0
2039	10/22/2009	LTN050GEF	LOCHINVAR	0
2040	04/23/2004	XSN040	LOCHINVAR	0
2041	05/02/2011	21VR40	RHEEM	0
2042	03/08/2005	XVR40	A. O. SMITH	0
2043	05/26/2010	LSN041G	LOCHINVAR	0
2044	01/17/2007	LTN040	LOCHINVAR	0
2045	04/12/2006	LTN050G	LOCHINVAR	0
2046	09/15/2010	ETN076	LOCHINVAR	1
2047	05/31/2000	FSGL30	AO SMITH	0
2048	11/23/2012	M45036FBN	BRADFORD-WHITE	0
2049	07/01/2011	M45036FBN	BRADFORD-WHITE	0
2050	11/20/2001	FSG30	AO SMITH	1
2051	12/06/1990	FSG40	AO SMITH	0
2052	11/21/2001	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2053	09/07/2006	LTN040G	LOCHINVAR	0
2054	06/06/2002	FSG40	AO SMITH	1
2055	06/12/2012	MI403S6FBN	BRADFORD-WHITE	3
2056	11/02/2012	M440T6FBN	BRADFORD-WHITE	0
2057	12/16/1991	FSG40	AO SMITH	0
2058	12/18/2001	FSGL40	AO SMITH	0
2059	04/07/2010	41V50	RHEEM	4
2060	10/18/2004	FSG40	AO SMITH	2
2061	11/25/2008	LTN050GEF	LOCHINVAR	0
2062	01/17/2007	A71	UNKNOWN	0
2063	07/23/2002	FSG50	AO SMITH	0
2064	09/11/2001	PGR50	AO SMITH	0
2065	04/01/2008	LTN050GEF	LOCHINVAR	0
2066	01/12/2011	21VR50	RHEEM	0
2067	02/28/1990	FSG30	AO SMITH	0
2068	07/06/2010	LTN050GEF	LOCHINVAR	1
2069	02/06/2003	FSG50	AO SMITH	0
2070	11/19/2008	LTN050GEF	LOCHINVAR	3
2071	06/30/2008	LSN041G	LOCHINVAR	0
2072	08/23/2012	M45036FBN	BRADFORD-WHITE	0
2073	11/08/1991	RF82156	RUUD	0
2074	01/22/2008	LTN040GEF	LOCHINVAR	1
2075	06/09/2008	LTN040G	LOCHINVAR	0
2076	05/22/2011	21V506	RHEEM	0
2077	06/21/2001	G75125	RUUD/RHEEM	0
2078	10/19/2001	FSG50	AO SMITH	0
2079	05/07/2012	P230F	RUUD	0
2080	08/11/1999	P402	RUUD	0
2081	03/26/2007	LTN050G	LOCHINVAR	3
2082	12/27/2008	LTN050GEF	LOCHINVAR	0
2083	03/18/2009	LTN040GEF	LOCHINVAR	0
2084	05/21/2006	LTN050G	LOCHINVAR	1
2085	03/20/2012	MI403S6FBN	BRADFORD-WHITE	0
2086	08/10/2012	M45036FBN	BRADFORD-WHITE	0
2087	02/14/2010	LTN040GEF	LOCHINVAR	0
2088	05/01/2006	LTN040G	LOCHINVAR	0
2089	04/26/2012	M45036FBN	BRADFORD-WHITE	0
2090	12/29/1999	41V50	RHEEM	0
2091	08/01/1969	A71DUMMY	UNKNOWN AT CONVERSION	0
2092	04/27/2006	LTN050G	LOCHINVAR	0
2093	05/28/1991	21V502	RHEEM	0
2094	12/04/2002	PGR50	AO SMITH	0
2095	07/14/2008	LTN050GEF	LOCHINVAR	0
2096	06/20/2009	LTN040G	LOCHINVAR	1
2097	10/23/2007	LTN040G	LOCHINVAR	0
2098	07/13/2004	G91200	RUUD/RHEEM	1
2099	03/30/2012	M45036FBN	BRADFORD-WHITE	0
2100	05/21/2002	FSG40	AO SMITH	0
2101	07/31/2000	41XR40	RHEEM	0
2102	01/10/2009	LTN040G	LOCHINVAR	2
2103	02/06/2012	M45036FBN	BRADFORD-WHITE	2
2104	03/06/2000	FSG30	AO SMITH	0
2105	12/12/2009	LTN050GEF	LOCHINVAR	0
2106	12/14/2001	FSG50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2107	06/04/2007	FSG50	AO SMITH	0
2108	04/17/2001	PGR50	AO SMITH	1
2109	03/10/2009	LTN050GEF	LOCHINVAR	0
2110	10/22/2008	FSG40	AO SMITH	1
2111	04/01/1969	PGX50	AO SMITH	0
2112	09/21/2006	LTN050G	LOCHINVAR	0
2113	11/27/2012	MI5036FBN	BRADFORD-WHITE	0
2114	10/14/2005	KGA50	AO SMITH	0
2115	07/27/2012	MI5036FBN	BRADFORD-WHITE	0
2116	05/05/1975	KGA50	AO SMITH	0
2117	06/27/1989	FSG50	AO SMITH	0
2118	01/14/2010	FGR30	AO SMITH	0
2119	12/22/1999	FSG40	AO SMITH	0
2120	10/15/2007	LTN040G	LOCHINVAR	1
2121	04/21/2006	LTN050G	LOCHINVAR	0
2122	09/12/2011	M440T6FBN	BRADFORD-WHITE	1
2123	05/12/2010	LSN041G	LOCHINVAR	0
2124	11/04/2010	LTN040G	LOCHINVAR	0
2125	04/08/2002	FSG40	AO SMITH	0
2126	05/01/1975	PGX40	AO SMITH	0
2127	03/06/2000	FSG50	AO SMITH	0
2128	10/28/2011	MI403S6FBN	BRADFORD-WHITE	1
2129	02/28/2000	FSG30	AO SMITH	4
2130	03/17/2009	LTN050GEF	LOCHINVAR	0
2131	03/01/2007	LTN040GEF	LOCHINVAR	0
2132	05/28/2003	G91200	RUUD/RHEEM	0
2133	07/16/2008	LTN050GEF	LOCHINVAR	2
2134	04/17/2001	FSG40	AO SMITH	0
2135	01/28/2004	XTN050	LOCHINVAR	1
2136	11/04/2010	LTN040G	LOCHINVAR	0
2137	06/24/2003	21V407	RHEEM	0
2138	02/26/2008	LTN040	LOCHINVAR	0
2139	03/27/2012	PH2DV50F	RUUD	0
2140	07/12/2000	FSG40	AO SMITH	0
2141	02/02/2001	FSG40	AO SMITH	0
2142	05/09/1992	FSG40	AO SMITH	0
2143	05/24/2008	LTN040G	LOCHINVAR	0
2144	02/17/2010	G91200	RUUD/RHEEM	1
2145	07/11/2001	FSG50	AO SMITH	0
2146	04/06/2011	21VR50	RHEEM	1
2147	06/06/2008	LTN040GEF	LOCHINVAR	0
2148	03/27/1995	PHR50	RUUD	0
2149	02/07/2011	FCV40	AO SMITH	0
2150	11/14/1995	41XR40	RHEEM	0
2151	06/10/2012	M440T6FBN	BRADFORD-WHITE	0
2152	01/31/1989	FSG50	AO SMITH	0
2153	10/08/1999	41XR40	RHEEM	0
2154	02/22/2007	LTN040GEF	LOCHINVAR	0
2155	04/11/2008	LTN040GEF	LOCHINVAR	0
2156	06/24/2007	LTN040GEF	LOCHINVAR	0
2157	12/27/2000	FSGL40	AO SMITH	0
2158	12/08/1986	FSG50	AO SMITH	0
2159	05/04/2002	FSG50	AO SMITH	0
2160	09/04/2010	G82156	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2161	10/01/1969	PGX40	AO SMITH	0
2162	09/09/2010	G82156	RUUD/RHEEM	0
2163	06/17/2002	PGR50	AO SMITH	0
2164	01/26/1994	FGR40	AO SMITH	0
2165	09/09/2010	G82156	RUUD/RHEEM	0
2166	08/06/2001	FSG40	AO SMITH	0
2167	12/02/2012	M45036FBN	BRADFORD-WHITE	1
2168	04/11/2011	42VR50	RHEEM	0
2169	10/29/1999	41V40S	RHEEM	0
2170	01/31/2006	LTN050GEF	LOCHINVAR	2
2171	01/09/2008	LTN050GEF	LOCHINVAR	0
2172	02/09/2004	XTN050	LOCHINVAR	0
2173	10/16/2006	LTN050GEF	LOCHINVAR	0
2174	08/01/2006	LTN040G	LOCHINVAR	0
2175	03/20/2008	LTN050	LOCHINVAR	0
2176	03/01/2001	41VR50	RHEEM	0
2177	10/01/1967	A71DUMMY	UNKNOWN AT CONVERSION	0
2178	05/26/2004	XTN050	LOCHINVAR	0
2179	12/16/2010	21VR50	RHEEM	0
2180	03/09/2007	LTN050G	LOCHINVAR	0
2181	01/09/2009	LSN041G	LOCHINVAR	3
2182	03/08/2007	LTN050G	LOCHINVAR	0
2183	09/05/2008	LSN041G	LOCHINVAR	0
2184	07/01/2002	41V50	RHEEM	0
2185	05/26/1999	G91200	RUUD/RHEEM	0
2186	12/17/2008	LSN041G	LOCHINVAR	0
2187	10/03/2006	LTN050GEF	LOCHINVAR	0
2188	08/17/1992	FSG50	AO SMITH	0
2189	05/26/1999	G91200	RUUD/RHEEM	0
2190	05/06/2009	LTN040GEF	LOCHINVAR	0
2191	05/29/2002	PGR40	AO SMITH	0
2192	10/11/2011	G75125	RUUD/RHEEM	0
2193	09/10/2008	LTN050GEF	LOCHINVAR	1
2194	04/20/2011	21VR50	RHEEM	0
2195	02/20/2007	LTN050G	LOCHINVAR	0
2196	08/21/2006	LTN040	LOCHINVAR	0
2197	08/05/2004	GCVL40	A. O. SMITH	0
2198	04/18/1968	PGX50	AO SMITH	0
2199	03/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	0
2200	09/04/1992	FSG40	AO SMITH	0
2201	07/19/2012	M45036FBN	BRADFORD-WHITE	0
2202	04/23/2012	G91200	RUUD/RHEEM	0
2203	09/01/1966	PGL40	AO SMITH	0
2204	05/21/2001	PGR50	AO SMITH	0
2205	04/01/1967	PGXL40	AO SMITH	0
2206	11/20/1995	FGR30	AO SMITH	3
2207	06/06/2012	MI403S6FBN	BRADFORD-WHITE	0
2208	07/07/2012	G75125	RUUD/RHEEM	0
2209	01/16/2003	FSG50	AO SMITH	0
2210	08/24/2004	XVR40	A. O. SMITH	0
2211	09/06/2005	LTN040G	LOCHINVAR	0
2212	04/08/2004	GVC40	A. O. SMITH	1
2213	01/28/1997	FSG40	AO SMITH	0
2214	10/26/2012	PH199119	PHOENIX	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2215	07/20/2000	41XR40	RHEEM	0
2216	10/24/2003	FSG40	AO SMITH	0
2217	05/18/2002	FSG50	AO SMITH	0
2218	10/02/2009	LTN040G	LOCHINVAR	0
2219	01/25/2008	LTN050GEF	LOCHINVAR	0
2220	11/21/2002	FSG40	AO SMITH	0
2221	06/06/2002	PGR50	AO SMITH	0
2222	12/02/2002	FSGL40	AO SMITH	0
2223	09/19/2001	FSG30	AO SMITH	0
2224	03/14/2011	G91200	RUUD/RHEEM	0
2225	09/10/2012	M45036FBN	BRADFORD-WHITE	0
2226	02/27/2004	FCV40	AO SMITH	0
2227	08/01/1970	PGX50	AO SMITH	1
2228	01/13/1999	FSGL40	AO SMITH	0
2229	04/06/2005	XVR50	A. O. SMITH	0
2230	10/27/2005	G82156	RUUD/RHEEM	1
2231	01/15/2010	LTN040G	LOCHINVAR	0
2232	05/03/2011	21VR50	RHEEM	0
2233	07/31/2006	LTN050G	LOCHINVAR	0
2234	04/09/2007	LTN050G	LOCHINVAR	0
2235	07/12/2004	XTN050	LOCHINVAR	0
2236	12/26/2009	LTN050G	LOCHINVAR	0
2237	01/14/2011	21VR50	RHEEM	0
2238	11/04/2002	FSG40	AO SMITH	1
2239	06/21/2012	MI5036FBN	BRADFORD-WHITE	0
2240	06/11/2001	PGR50	AO SMITH	0
2241	12/30/2008	LTN050GEF	LOCHINVAR	0
2242	04/04/2007	XSN040	LOCHINVAR	0
2243	09/12/2000	FSG50	AO SMITH	0
2244	03/07/2011	21VR40	RHEEM	2
2245	12/12/1995	FGR40	AO SMITH	0
2246	12/23/2005	GVC50	A. O. SMITH	0
2247	05/13/2005	FSG30	AO SMITH	0
2248	09/24/2001	PGR40	AO SMITH	0
2249	09/26/2003	FSG40	AO SMITH	0
2250	04/05/2002	PGR50	AO SMITH	0
2251	01/04/2000	FSG40	AO SMITH	0
2252	05/23/2007	LTN040G	LOCHINVAR	0
2253	07/06/1995	PR502T	RUUD	0
2254	09/07/1999	FSGL40	AO SMITH	0
2255	01/04/2011	41VR40	RHEEM	0
2256	08/01/2009	LSN041G	LOCHINVAR	1
2257	08/02/2010	PGR50	AO SMITH	0
2258	12/03/1998	21VR40	RHEEM	0
2259	01/01/1970	PGX50	AO SMITH	0
2260	12/27/1997	PGR50	AO SMITH	0
2261	12/22/1999	FSG40	AO SMITH	0
2262	11/12/2009	LTN050GEF	LOCHINVAR	1
2263	03/22/2002	FSG50	AO SMITH	0
2264	12/09/2005	LTN050G	LOCHINVAR	0
2265	04/26/2012	M440T6FBN	BRADFORD-WHITE	0
2266	10/01/1996	FGR40	AO SMITH	0
2267	02/01/1997	PGR40	AO SMITH	0
2268	06/21/2001	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2269	09/06/2007	LTN050GEF	LOCHINVAR	0
2270	12/14/2007	LTN050G	LOCHINVAR	0
2271	04/12/2011	21VR40	RHEEM	0
2272	08/15/2011	MI403S6FBN	BRADFORD-WHITE	1
2273	12/10/2009	LTN050G	LOCHINVAR	0
2274	02/27/2012	MI40T6FBN	BRADFORD-WHITE	1
2275	08/04/2004	XTN040	LOCHINVAR	1
2276	11/27/2000	41V40S	RHEEM	0
2277	04/06/2006	LSN041G	LOCHINVAR	0
2278	04/18/2001	PGR50	AO SMITH	0
2279	02/03/2002	PGR50	AO SMITH	0
2280	10/23/2002	FSG40	AO SMITH	0
2281	07/03/2006	LTN050G	LOCHINVAR	0
2282	09/09/2011	PH19980	PHOENIX	1
2283	03/11/2003	G75125	RUUD/RHEEM	4
2284	08/04/2012	M45036FBN	BRADFORD-WHITE	0
2285	06/24/2003	FSG40	AO SMITH	0
2286	06/08/1999	FSGL40	AO SMITH	0
2287	09/01/1975	KGA40	AO SMITH	0
2288	11/06/2003	FCV40	AO SMITH	0
2289	04/15/2005	GVC40	A. O. SMITH	0
2290	01/01/1960	A71DUMMY	UNKNOWN AT CONVERSION	0
2291	05/11/2007	LTN050G	LOCHINVAR	0
2292	01/02/2009	LSN041G	LOCHINVAR	0
2293	06/15/2009	LTN050GEF	LOCHINVAR	1
2294	04/22/2011	21VR40	RHEEM	0
2295	01/21/2012	M45036FBN	BRADFORD-WHITE	0
2296	06/06/2003	PGR50	AO SMITH	0
2297	10/03/2007	LTN040GEF	LOCHINVAR	0
2298	03/30/2002	FSGL40	AO SMITH	0
2299	04/12/2011	21VR50	RHEEM	0
2300	02/22/2002	FSG40	AO SMITH	0
2301	08/01/2012	P230F	Ruud	0
2302	04/28/2009	LSN041G	LOCHINVAR	0
2303	05/26/2006	LTN040G	LOCHINVAR	0
2304	01/22/2009	LTN050GEF	LOCHINVAR	0
2305	03/06/2005	GVC40	A. O. SMITH	0
2306	07/27/2006	LTN050G	LOCHINVAR	0
2307	06/23/1996	FGR50	AO SMITH	0
2308	10/09/2009	LTN050GEF	LOCHINVAR	0
2309	11/05/2009	LTN040G	LOCHINVAR	0
2310	02/28/2010	LSN041G	LOCHINVAR	0
2311	08/17/2009	LTN040G	LOCHINVAR	0
2312	04/21/2004	GVC40	A. O. SMITH	0
2313	07/14/2008	LTN050GEF	LOCHINVAR	0
2314	03/04/2008	LTN040	LOCHINVAR	0
2315	03/01/1979	FSG50	AO SMITH	1
2316	10/12/2004	XVR50	A. O. SMITH	1
2317	03/17/1999	FGR50	AO SMITH	0
2318	11/21/2009	LTN050GEF	LOCHINVAR	0
2319	11/22/2002	FGR50	AO SMITH	0
2320	09/24/2003	41XR50	RHEEM	0
2321	11/19/1982	G76200	RUUD/RHEEM	0
2322	04/12/2005	XVR50	A. O. SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2323	09/28/2010	41VR50	RHEEM	0
2324	09/25/2006	LTN040G	LOCHINVAR	0
2325	08/17/2006	LTN050G	LOCHINVAR	0
2326	06/17/2008	LTN050GEF	LOCHINVAR	1
2327	08/12/2009	LTN050GEF	LOCHINVAR	0
2328	06/05/2006	LTN050G	LOCHINVAR	2
2329	07/12/2012	MI40T6FBN	BRADFORD-WHITE	1
2330	09/01/2005	LTN050GEF	LOCHINVAR	0
2331	11/01/2010	21VR50	RHEEM	0
2332	11/23/2011	M440T6FBN	BRADFORD-WHITE	0
2333	02/07/2003	FSG30	AO SMITH	0
2334	03/25/2003	FSG40	AO SMITH	0
2335	05/19/2008	LTN050GEF	LOCHINVAR	0
2336	06/24/2009	LTN050GEF	LOCHINVAR	0
2337	08/14/2007	LTN040G	LOCHINVAR	0
2338	05/04/1999	FSG40	AO SMITH	0
2339	01/22/2001	FSG40	AO SMITH	0
2340	11/01/1970	PGX40	AO SMITH	0
2341	12/21/2001	FSG50	AO SMITH	0
2342	10/01/1975	KGA40	AO SMITH	0
2343	08/14/2001	FSGL40	AO SMITH	0
2344	05/03/1999	FGR50	AO SMITH	0
2345	01/19/2012	M45036FBN	BRADFORD-WHITE	0
2346	12/18/2001	FSG40	AO SMITH	1
2347	02/01/1976	KGA40	AO SMITH	0
2348	08/18/1997	PGR50	AO SMITH	0
2349	03/31/2006	LTN050G	LOCHINVAR	0
2350	04/06/2009	LTN040GEF	LOCHINVAR	0
2351	02/09/2001	PGR50	AO SMITH	0
2352	12/26/2006	LSN041G	LOCHINVAR	0
2353	02/19/2013	FGR40	AO SMITH	2
2354	07/20/2011	MI5036FBN	BRADFORD-WHITE	1
2355	10/10/1997	PGR40	AO SMITH	0
2356	12/01/1975	KGA50	AO SMITH	0
2357	07/16/2001	FSG40	AO SMITH	0
2358	07/21/2001	FSG50	AO SMITH	0
2359	12/24/2007	LTN050G	LOCHINVAR	0
2360	11/25/1997	41V40	RHEEM	0
2361	05/05/2010	LTN040GEF	LOCHINVAR	0
2362	10/08/2009	LTN050GEF	LOCHINVAR	0
2363	03/29/2005	XVR50	A. O. SMITH	1
2364	08/16/2010	41V50	RHEEM	0
2365	07/25/2009	LTN050GEF	LOCHINVAR	0
2366	04/07/2005	GCVL40	A. O. SMITH	0
2367	07/02/1997	FGR30	AO SMITH	1
2368	03/01/1995	L72DUMMY	AO SMITH	0
2369	07/30/2008	LTN050GEF	LOCHINVAR	0
2370	01/30/1994	F72DUMMY	AO SMITH	0
2371	11/07/1999	PHR40	RUUD	0
2372	11/01/1995	L72DUMMY	AO SMITH	0
2373	04/03/2000	BTR154	AO SMITH	0
2374	10/19/2000	FSG40	AO SMITH	0
2375	01/17/2000	FSG50	AO SMITH	0
2376	12/29/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2377	08/12/2003	FSG40	AO SMITH	0
2378	07/25/1991	FSG40	AO SMITH	0
2379	07/29/2001	FSGL40	AO SMITH	0
2380	09/24/1987	G91200	RUUD/RHEEM	0
2381	05/18/2000	41XR50	RHEEM	0
2382	10/29/2004	XVR40	A. O. SMITH	0
2383	01/20/2012	M45036FBN	BRADFORD-WHITE	0
2384	06/23/2006	LTN050G	LOCHINVAR	0
2385	05/23/2003	G76200	RUUD/RHEEM	6
2386	03/28/2013	MI403S6FBN	BRADFORD WHITE	0
2387	08/16/2005	LTN050G	LOCHINVAR	0
2388	09/30/2009	LTN050GEF	LOCHINVAR	0
2389	04/29/1998	PGR40	AO SMITH	0
2390	05/25/2003	PGR50	AO SMITH	0
2391	08/10/2012	MI5036FBN	BRADFORD-WHITE	0
2392	09/28/2009	LSN041G	LOCHINVAR	0
2393	10/28/2002	FSGL40	AO SMITH	0
2394	10/14/2009	LTN050G	LOCHINVAR	1
2395	05/02/2008	LTN050G	LOCHINVAR	0
2396	09/24/2003	PGR50	AO SMITH	0
2397	11/01/2008	LSN041G	LOCHINVAR	1
2398	02/02/1993	RF67120	RUUD	0
2399	04/01/1971	A71DUMMY	UNKNOWN AT CONVERSION	0
2400	02/11/1986	E71DUMMY	AO SMITH	0
2401	12/01/1979	FSGL40	AO SMITH	0
2402	10/12/1999	FSGL40	AO SMITH	0
2403	10/13/2009	LTN050GEF	LOCHINVAR	0
2404	05/21/2012	41VR50	RHEEM	0
2405	01/01/1976	KGL40	AO SMITH	0
2406	08/03/1995	BTC197	AO SMITH	1
2407	03/08/2012	MI403S6FBN	BRADFORD-WHITE	0
2408	03/27/2012	M45036FBN	BRADFORD-WHITE	0
2409	06/22/2009	LTN050GEF	LOCHINVAR	0
2410	08/23/2006	LTN040G	LOCHINVAR	1
2411	10/14/2011	M440T6FBN	BRADFORD-WHITE	0
2412	08/22/2008	LTN050GEF	LOCHINVAR	1
2413	12/11/2000	41XR40	RHEEM	0
2414	11/16/2011	M440T6FBN	BRADFORD-WHITE	0
2415	01/01/1980	FSG40	AO SMITH	0
2416	02/01/2013	MI5036FBN	BRADFORD-WHITE	1
2417	10/29/2009	LTN050GEF	LOCHINVAR	0
2418	02/14/2002	FSG40	AO SMITH	0
2419	07/07/1995	PHR50	RUUD	0
2420	11/19/2011	MI5036FBN	BRADFORD-WHITE	0
2421	12/15/2002	FSG40	AO SMITH	0
2422	08/11/2005	41VR50	RHEEM	0
2423	09/07/2001	PGR50	AO SMITH	0
2424	11/22/2002	PGR40	AO SMITH	0
2425	05/30/2007	LTN050GEF	LOCHINVAR	0
2426	08/18/1992	FSG50	AO SMITH	0
2427	04/26/2012	M45036FBN	BRADFORD-WHITE	0
2428	11/01/2010	21VR50	RHEEM	0
2429	03/19/2009	LTN040GEF	LOCHINVAR	0
2430	04/16/2007	LTN040G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2431	07/30/2007	LTN040GEF	LOCHINVAR	0
2432	05/16/2011	41VR40	RHEEM	0
2433	09/24/2003	PGR50	AO SMITH	0
2434	10/05/2011	M45036FBN	BRADFORD-WHITE	0
2435	07/11/2008	LTN040GEF	LOCHINVAR	0
2436	02/28/2011	21VR50	RHEEM	0
2437	10/01/1974	RH3063	RUUD	0
2438	03/09/2011	42VR50	RHEEM	0
2439	01/23/2006	LTN050G	LOCHINVAR	0
2440	02/11/2013	G76200	RUUD/RHEEM	1
2441	10/20/2009	LTN050GEF	LOCHINVAR	0
2442	10/01/2012	M440T6FBN	BRADFORD-WHITE	0
2443	10/27/1993	FSG40	AO SMITH	0
2444	10/23/2004	GVC40	A. O. SMITH	0
2445	03/12/2009	PH199119	PHOENIX	1
2446	09/17/2011	M45036FBN	BRADFORD-WHITE	0
2447	07/22/2012	MI40T6FBN	BRADFORD-WHITE	0
2448	01/24/1997	PGR40	AO SMITH	1
2449	04/06/2009	LSN041G	LOCHINVAR	1
2450	08/30/2003	PGR50	AO SMITH	0
2451	05/16/2006	LTN040G	LOCHINVAR	1
2452	08/19/2010	LSN041G	LOCHINVAR	0
2453	08/10/2010	LSN041G	LOCHINVAR	0
2454	11/12/2010	21VR40	RHEEM	0
2455	09/16/2003	FSG40	AO SMITH	0
2456	05/08/2012	G76200	RUUD/RHEEM	0
2457	12/23/2009	LTN040G	LOCHINVAR	0
2458	10/12/2005	FSG30	AO SMITH	0
2459	03/09/2001	PGR50	AO SMITH	0
2460	06/23/2006	LTN040G	LOCHINVAR	0
2461	09/19/2000	41XR40	RHEEM	1
2462	06/23/2009	G91200	RUUD/RHEEM	0
2463	06/11/2010	LTN050GEF	LOCHINVAR	0
2464	05/26/2007	LTN050GEF	LOCHINVAR	0
2465	03/01/1980	FSG50	AO SMITH	0
2466	03/28/2001	PGR50	AO SMITH	0
2467	05/16/1999	FGR40	AO SMITH	0
2468	09/30/1995	RF67120	RUUD	0
2469	12/22/2011	M440T6FBN	BRADFORD-WHITE	0
2470	10/29/2003	PVR40	AO SMITH	0
2471	10/17/2006	G82156	RUUD/RHEEM	6
2472	11/15/2007	LTN050GEF	LOCHINVAR	0
2473	05/18/2009	LTN050GEF	LOCHINVAR	0
2474	07/19/2001	FSG40	AO SMITH	0
2475	07/17/2004	XTN050	LOCHINVAR	0
2476	05/18/2009	LTN050GEF	LOCHINVAR	0
2477	06/21/2011	M45036FBN	BRADFORD-WHITE	0
2478	11/08/2011	MI403S6FBN	BRADFORD-WHITE	1
2479	11/11/2002	FSG50	AO SMITH	1
2480	12/24/1998	G67114	RHEEM	0
2481	08/13/2012	MI5036FBN	BRADFORD-WHITE	0
2482	01/30/2012	MI403S6FBN	BRADFORD-WHITE	0
2483	06/25/2011	MI40T6FBN	BRADFORD-WHITE	1
2484	12/29/2011	MI5036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2485	12/12/2007	LTN050GEF	LOCHINVAR	0
2486	03/02/2006	LTN040G	LOCHINVAR	0
2487	05/18/2011	41VR40	RHEEM	0
2488	12/24/2005	LTN050GEF	LOCHINVAR	0
2489	05/10/2003	41XR40	RHEEM	0
2490	07/18/2000	41V40	RHEEM	0
2491	12/08/2008	LTN040G	LOCHINVAR	1
2492	05/16/2002	FSGL40	AO SMITH	0
2493	08/21/2010	LSN041G	LOCHINVAR	0
2494	03/03/2009	LTN040G	LOCHINVAR	0
2495	12/29/2006	LTN050G	LOCHINVAR	1
2496	10/08/2007	LTN040G	LOCHINVAR	0
2497	10/26/1999	FSG30	AO SMITH	0
2498	11/09/2001	FSG40	AO SMITH	0
2499	03/08/2002	FSGL40	AO SMITH	0
2500	10/04/1999	FSGL30	AO SMITH	0
2501	10/20/2009	FSG50	AO SMITH	0
2502	12/13/2008	LTN050GEF	LOCHINVAR	0
2503	07/25/2001	PGR50	AO SMITH	0
2504	01/31/2008	LTN050G	LOCHINVAR	0
2505	01/02/2002	PGR40	AO SMITH	0
2506	11/30/2009	LTN040GEF	LOCHINVAR	0
2507	04/10/2001	PGR50	AO SMITH	0
2508	04/09/2002	PGR50	AO SMITH	0
2509	11/23/1988	FSG40	AO SMITH	0
2510	11/09/2001	21V407	RHEEM	0
2511	07/06/2010	LTN040GEF	LOCHINVAR	1
2512	11/05/2005	FSG30	AO SMITH	0
2513	01/17/1987	FSG50	AO SMITH	0
2514	08/30/2012	M45036FBN	BRADFORD-WHITE	0
2515	07/19/2001	FSG40	AO SMITH	0
2516	11/28/2000	FSG40	AO SMITH	0
2517	07/24/2005	LSN041G	LOCHINVAR	0
2518	05/17/2011	21VR40	RHEEM	1
2519	09/08/1992	FSG50	AO SMITH	0
2520	05/01/2008	LTN050GEF	LOCHINVAR	0
2521	01/25/2008	LTN050GEF	LOCHINVAR	0
2522	03/03/2003	FSG40	AO SMITH	0
2523	01/27/2009	LTN050GEF	LOCHINVAR	0
2524	10/30/2012	M45036FBN	BRADFORD-WHITE	0
2525	05/19/1997	PGR50	AO SMITH	0
2526	11/27/2008	LSN041G	LOCHINVAR	0
2527	03/10/1999	SSV119199	VOYAGER	1
2528	03/18/2009	LTN050GEF	LOCHINVAR	0
2529	06/01/2009	LTN040G	LOCHINVAR	0
2530	03/11/1999	FSG50	AO SMITH	0
2531	05/02/2011	41VR50	RHEEM	0
2532	01/31/2013	MI5036FBN	BRADFORD-WHITE	0
2533	08/22/1999	41VR50	RHEEM	2
2534	02/15/2002	FSG40	AO SMITH	0
2535	01/01/1973	PGX40	AO SMITH	0
2536	12/30/2005	LSN041G	LOCHINVAR	0
2537	11/01/1970	PGX50	AO SMITH	0
2538	02/22/2013	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2539	03/19/1973	PGD30	AO SMITH	0
2540	12/03/2012	M45036FBN	BRADFORD-WHITE	0
2541	07/25/2007	LTN040GEF	LOCHINVAR	0
2542	05/25/2007	XSN040	LOCHINVAR	1
2543	08/27/2003	PGR50	AO SMITH	0
2544	04/01/1999	G67114	RHEEM	0
2545	03/14/2011	21VR50	RHEEM	0
2546	06/13/2008	LTN050GEF	LOCHINVAR	0
2547	08/24/1991	FSG50	AO SMITH	0
2548	02/10/2013	M45036FBN	BRADFORD-WHITE	1
2549	03/25/2013	MI5036FBN	Bradford-White	3
2550	11/01/1988	FSG50	AO SMITH	0
2551	12/27/2006	LTN050G	LOCHINVAR	0
2552	08/08/2005	LTN050GEF	LOCHINVAR	0
2553	11/12/2008	LTN050GEF	LOCHINVAR	1
2554	02/26/2002	PGR50	AO SMITH	0
2555	12/14/2009	LTN040GEF	LOCHINVAR	0
2556	04/17/2010	LSN041G	LOCHINVAR	0
2557	12/02/2011	MI40T6FBN	BRADFORD-WHITE	1
2558	07/31/2000	FGR40	AO SMITH	0
2559	06/24/2007	LTN040G	LOCHINVAR	0
2560	11/10/2009	LTN040G	LOCHINVAR	0
2561	09/18/2008	LTN050G	LOCHINVAR	0
2562	03/12/2007	LTN050G	LOCHINVAR	0
2563	04/02/2008	LTN050	LOCHINVAR	0
2564	06/02/2011	41VR50	RHEEM	0
2565	12/08/1993	PGR40	AO SMITH	0
2566	10/24/2004	XVR40	A. O. SMITH	0
2567	05/15/2009	LTN050GEF	LOCHINVAR	0
2568	11/19/2012	MI5036FBN	BRADFORD-WHITE	0
2569	11/02/2006	LTN050G	LOCHINVAR	0
2570	08/22/2002	PGR50	AO SMITH	0
2571	04/17/1996	G91200	RUUD/RHEEM	0
2572	04/03/2009	G91200	RUUD/RHEEM	0
2573	10/10/1997	G75125	RUUD/RHEEM	0
2574	02/02/2003	FSGL40	AO SMITH	0
2575	12/08/2010	LTN040GEF	LOCHINVAR	1
2576	07/21/1999	FSG30	AO SMITH	1
2577	06/04/1999	G75125	RUUD/RHEEM	1
2578	12/26/2007	FSG30	AO SMITH	2
2579	10/26/2010	41XR50	RHEEM	0
2580	10/25/2011	M440T6FBN	BRADFORD-WHITE	0
2581	12/17/2009	LSN041G	LOCHINVAR	0
2582	02/08/2012	M440T6FBN	BRADFORD-WHITE	0
2583	01/05/2013	MI40T6FBN	BRADFORD-WHITE	2
2584	11/19/2002	FSG40	AO SMITH	0
2585	12/14/2011	M45036FBN	BRADFORD-WHITE	0
2586	01/04/2010	LTN050GEF	LOCHINVAR	0
2587	12/08/1987	BTR199	AO SMITH	0
2588	02/19/2002	FSG50	AO SMITH	0
2589	02/02/2007	LTN040G	LOCHINVAR	0
2590	05/27/2003	21V506	RHEEM	0
2591	06/17/2010	LTN050G	LOCHINVAR	0
2592	05/19/2007	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2593	10/17/2002	FSG30	AO SMITH	0
2594	02/27/2004	PGR40	AO SMITH	0
2595	11/24/2009	LTN040GEF	LOCHINVAR	0
2596	02/01/1979	G72DUMMY	AO SMITH	0
2597	03/17/2003	FSG40	AO SMITH	0
2598	02/08/2008	LTN050GEF	LOCHINVAR	0
2599	12/29/2007	LSN041G	LOCHINVAR	0
2600	07/01/1997	FGR30	AO SMITH	2
2601	04/08/2005	GVC50	A. O. SMITH	0
2602	05/02/2001	FSG30	AO SMITH	1
2603	03/15/1994	21V506	RHEEM	0
2604	10/24/2008	LTN050GEF	LOCHINVAR	0
2605	01/26/2009	LTN050GEF	LOCHINVAR	0
2606	04/27/2011	41VR50	RHEEM	0
2607	02/01/1999	FSG30	AO SMITH	4
2608	03/16/2007	LTN050G	LOCHINVAR	0
2609	03/10/2009	LTN040GEF	LOCHINVAR	0
2610	02/21/2002	FSGL40	AO SMITH	0
2611	07/03/2003	PGR40	AO SMITH	0
2612	04/13/2006	PGR50	AO SMITH	0
2613	07/09/2012	MI5036FBN	BRADFORD-WHITE	0
2614	03/22/2004	GCVL40	A. O. SMITH	0
2615	11/02/2006	LTN050G	LOCHINVAR	0
2616	12/19/2009	LTN040GEF	LOCHINVAR	0
2617	05/02/2008	LTN050GEF	LOCHINVAR	0
2618	09/01/1976	KGA50	AO SMITH	0
2619	02/22/2006	LTN050G	LOCHINVAR	1
2620	08/24/1997	FGR50	AO SMITH	0
2621	05/02/2006	LTN040G	LOCHINVAR	0
2622	11/13/2008	LTN040GEF	LOCHINVAR	0
2623	10/10/2011	MI5036FBN	BRADFORD-WHITE	0
2624	10/17/2002	PGR50	AO SMITH	0
2625	07/24/2003	FSG50	AO SMITH	1
2626	03/06/2007	PRV50NODS	STATE	0
2627	03/13/2002	PGR50	AO SMITH	0
2628	05/29/2004	GVC50	A. O. SMITH	1
2629	12/04/2007	LTN050GEF	LOCHINVAR	0
2630	10/16/2010	SBF100199NES	STATE	2
2631	07/01/1985	RF67120	RUUD	0
2632	08/15/2007	LTN050GEF	LOCHINVAR	0
2633	12/12/2009	LTN050G	LOCHINVAR	0
2634	05/28/2002	FSG50	AO SMITH	0
2635	06/06/1999	FSG50	AO SMITH	0
2636	04/05/2011	22DV50F	RHEEM	0
2637	06/07/2007	LTN050G	LOCHINVAR	0
2638	11/06/2012	M45036FBN	BRADFORD-WHITE	0
2639	06/17/1996	FGR50	AO SMITH	0
2640	07/26/2009	LTN040GEF	LOCHINVAR	0
2641	06/17/2010	G82156	RUUD/RHEEM	0
2642	02/12/2013	G82156	RUUD/RHEEM	0
2643	12/21/2005	GVC50	A. O. SMITH	0
2644	07/28/2008	22DV50C	RHEEM	0
2645	09/22/2006	PR640	STATE	0
2646	06/25/2009	LSN041G	LOCHINVAR	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2647	03/04/2011	21VR50	RHEEM	0
2648	01/15/2003	PRX50	STATE	0
2649	03/09/2000	FSG50	AO SMITH	0
2650	04/01/2007	LSN041G	LOCHINVAR	0
2651	07/21/2011	M45036FBN	BRADFORD-WHITE	0
2652	05/12/2006	LTN050G	LOCHINVAR	1
2653	11/18/2012	MI5036FBN	BRADFORD-WHITE	0
2654	09/11/2009	LTN050GEF	LOCHINVAR	1
2655	11/15/2011	M45036FBN	BRADFORD-WHITE	0
2656	01/29/2009	LTN050GEF	LOCHINVAR	0
2657	03/21/2012	M440T6FBN	BRADFORD-WHITE	0
2658	02/19/1998	FGR50	AO SMITH	0
2659	05/18/2007	G82156	RUUD/RHEEM	0
2660	09/12/2002	FSG50	AO SMITH	0
2661	01/07/2002	FSG30	AO SMITH	0
2662	09/29/1971	G91200	RUUD/RHEEM	0
2663	07/28/2011	MI403S6FBN	BRADFORD-WHITE	0
2664	12/19/2001	FSGL40	AO SMITH	0
2665	12/02/2002	FSG50	AO SMITH	0
2666	11/15/2006	LTN040G	LOCHINVAR	0
2667	03/04/2005	GVC40	A. O. SMITH	2
2668	12/19/2001	FSGL30	AO SMITH	0
2669	04/07/2009	LTN050GEF	LOCHINVAR	0
2670	06/19/2000	FSGL40	AO SMITH	0
2671	06/04/2008	LTN040GEF	LOCHINVAR	0
2672	09/10/2009	LTN050GEF	LOCHINVAR	0
2673	08/06/2003	FCV50	AO SMITH	0
2674	08/11/2005	LTN050	LOCHINVAR	1
2675	04/10/2009	LTN050GEF	LOCHINVAR	0
2676	11/04/2006	LTN050G	LOCHINVAR	0
2677	08/20/1997	FSGL40	AO SMITH	0
2678	09/20/2011	M45036FBN	BRADFORD-WHITE	0
2679	04/30/2003	PGR50	AO SMITH	0
2680	08/01/2012	MI403S6FBN	BRADFORD-WHITE	1
2681	08/24/2010	LTN050	LOCHINVAR	0
2682	08/31/2012	MI5036FBN	BRADFORD-WHITE	0
2683	06/01/1980	KGA40	AO SMITH	0
2684	02/06/2001	G91200	RUUD/RHEEM	0
2685	12/19/2007	LTN050GEF	LOCHINVAR	0
2686	05/17/1996	PGR50	AO SMITH	0
2687	10/02/1997	FSGL40	AO SMITH	0
2688	04/21/2009	LTN050GEF	LOCHINVAR	0
2689	02/04/2010	LSN041G	LOCHINVAR	0
2690	07/16/2002	PGR50	AO SMITH	0
2691	12/20/2004	GCVL40	A. O. SMITH	0
2692	11/16/2005	LSN041G	LOCHINVAR	0
2693	07/23/2010	41V50	RHEEM	0
2694	11/05/2007	LTN050GEF	LOCHINVAR	0
2695	01/13/2000	FSG40	AO SMITH	0
2696	10/19/1983	FSG50	AO SMITH	0
2697	12/22/2011	M45036FBN	BRADFORD-WHITE	0
2698	10/05/1984	F72DUMMY	AO SMITH	0
2699	06/09/1998	FGR50	AO SMITH	0
2700	04/06/2007	G75125	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2701	07/29/1996	PGR40	AO SMITH	0
2702	12/13/2006	LTN050G	LOCHINVAR	0
2703	02/10/2009	LTN040GEF	LOCHINVAR	0
2704	11/17/2008	LTN050GEF	LOCHINVAR	0
2705	04/10/1998	41V50	RHEEM	0
2706	07/09/2009	L72DUMMY	AO SMITH	0
2707	03/30/1998	FGR50	AO SMITH	0
2708	05/23/2005	LTN050	LOCHINVAR	0
2709	05/29/1997	G76200	RUUD/RHEEM	0
2710	11/13/2000	FSG40	AO SMITH	0
2711	10/31/2011	MI5036FBN	BRADFORD-WHITE	0
2712	10/07/2010	42VR50	RHEEM	0
2713	01/16/2013	MI5036FBN	BRADFORD-WHITE	0
2714	08/30/2012	M440T6FBN	BRADFORD-WHITE	0
2715	09/28/2010	21VR-50	RHEEM	1
2716	12/03/2007	LTN050GEF	LOCHINVAR	0
2717	11/01/2008	ETN076	LOCHINVAR	1
2718	02/26/2009	LTN050GEF	LOCHINVAR	1
2719	07/18/2012	M45036FBN	BRADFORD-WHITE	1
2720	12/08/2011	M45036FBN	BRADFORD-WHITE	0
2721	10/05/1983	KGA30	AO SMITH	0
2722	02/02/2012	MI40T6FBN	BRADFORD-WHITE	0
2723	07/19/2000	FSG50	AO SMITH	0
2724	08/10/1997	PRX40	STATE	0
2725	11/04/1982	KGA30	AO SMITH	0
2726	03/29/2007	LTN050G	LOCHINVAR	0
2727	05/10/2008	LTN050GEF	LOCHINVAR	0
2728	11/04/1982	KGA30	AO SMITH	0
2729	05/19/2011	PGR50	AO SMITH	0
2730	10/10/2001	FSG40	AO SMITH	0
2731	11/10/2005	LTN050G	LOCHINVAR	0
2732	05/02/2006	FSG30	AO SMITH	0
2733	02/28/2013	I72DUMMY	UNKNOWN AT CONVERSION	0
2734	07/03/1995	PHR50	RUUD	0
2735	09/16/2004	GCVL40	A. O. SMITH	0
2736	06/17/2005	LSN041G	LOCHINVAR	0
2737	02/22/1999	P506	RUUD	0
2738	08/25/2009	LTN050GEF	LOCHINVAR	0
2739	07/03/2003	PVR50	AO SMITH	0
2740	12/26/2006	LTN050G	LOCHINVAR	0
2741	11/04/1982	BW50	BRADFORD-WHITE	0
2742	03/14/2012	M45036FBN	BRADFORD-WHITE	5
2743	05/09/2003	41V40S	RHEEM	0
2744	02/09/2006	LTN040G	LOCHINVAR	0
2745	02/15/2006	LTN050G	LOCHINVAR	1
2746	09/24/2011	MI40T6FBN	BRADFORD-WHITE	0
2747	01/01/1997	FSGL40	AO SMITH	0
2748	11/29/2012	MI403S6FBN	BRADFORD-WHITE	0
2749	08/28/2002	FSGL40	AO SMITH	0
2750	04/26/2001	FSGL40	AO SMITH	0
2751	06/05/2012	MI5036FBN	BRADFORD-WHITE	0
2752	03/13/1984	FSG50	AO SMITH	0
2753	03/12/2004	FCVL40	AO SMITH	0
2754	01/01/2002	FSG30	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2755	11/30/2004	GVC50	A. O. SMITH	0
2756	07/16/2012	MI403S6FBN	BRADFORD-WHITE	0
2757	10/09/2000	FSG40	AO SMITH	0
2758	08/21/2007	LTN050GEF	LOCHINVAR	0
2759	10/06/2010	LTN040	LOCHINVAR	0
2760	04/12/2002	PGR50	AO SMITH	1
2761	07/14/2010	LTN050GEF	LOCHINVAR	0
2762	09/26/2011	G76200	RUUD/RHEEM	1
2763	08/04/2009	LTN050GEF	LOCHINVAR	0
2764	12/03/2012	G91200	RUUD/RHEEM	0
2765	03/05/2013	G91200	RUUD/RHEEM	0
2766	01/20/2006	PR640	STATE	0
2767	01/01/1996	FSG30	AO SMITH	0
2768	03/05/2013	MI5036FBN	BRADFORD-WHITE	0
2769	01/01/1996	FSG30	AO SMITH	0
2770	12/03/2012	G91200	RUUD/RHEEM	0
2771	01/26/2006	PGXL30	AO SMITH	1
2772	07/07/2005	GVC40	A. O. SMITH	1
2773	01/13/2012	M45036FBN	BRADFORD-WHITE	0
2774	03/10/2011	SBD100199NES	STATE	0
2775	03/29/2008	FSG30	AO SMITH	0
2776	08/21/2003	FCV50	AO SMITH	0
2777	07/13/2012	M45036FBN	BRADFORD-WHITE	1
2778	06/09/2005	LTN050	LOCHINVAR	0
2779	10/24/2008	FSG30	AO SMITH	0
2780	03/10/2011	SBD100199NES	STATE	0
2781	09/30/1999	FSG50	AO SMITH	0
2782	11/01/2000	G75125	RUUD/RHEEM	0
2783	06/18/2003	FSG50	AO SMITH	0
2784	05/23/2005	LTN050	LOCHINVAR	0
2785	07/21/2007	LTN050GEF	LOCHINVAR	0
2786	11/02/2010	42VR50	RHEEM	0
2787	04/09/2009	LTN040G	LOCHINVAR	0
2788	09/12/2001	FSG50	AO SMITH	0
2789	02/18/2000	41XR50	RHEEM	0
2790	06/17/2008	LTN050GEF	LOCHINVAR	0
2791	09/21/2010	42VR50	RHEEM	0
2792	06/18/2007	LTN030G	AO SMITH	0
2793	09/19/2003	PVR40	AO SMITH	1
2794	03/19/2004	GVC50	A. O. SMITH	0
2795	04/07/2012	M45036FBN	BRADFORD-WHITE	0
2796	11/09/2009	LTN050GEF	LOCHINVAR	0
2797	05/07/2003	41V50	RHEEM	0
2798	01/07/2011	LTN040G	LOCHINVAR	0
2799	11/17/2008	LTN050GEF	LOCHINVAR	0
2800	12/06/2010	21VR40	RHEEM	0
2801	11/03/2000	21V407	RHEEM	0
2802	01/12/2012	M45036FBN	BRADFORD-WHITE	0
2803	02/19/2004	PVR40	AO SMITH	0
2804	06/09/2008	LTN040GEF	LOCHINVAR	0
2805	03/18/2013	FGR50	AO SMITH	0
2806	01/01/1998	PRV50NORT	STATE	0
2807	11/03/2005	LTN050GEF	LOCHINVAR	0
2808	05/21/2001	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2809	06/25/1984	FSG50	AO SMITH	0
2810	12/03/2008	LTN050GEF	LOCHINVAR	0
2811	01/01/1993	FSG30	AO SMITH	0
2812	03/11/2003	FSG40	AO SMITH	0
2813	05/16/1997	PGR50	AO SMITH	0
2814	08/06/2003	FCV50	AO SMITH	0
2815	10/02/2009	LTN050GEF	LOCHINVAR	0
2816	05/15/1996	H72DUMMY	AO SMITH	0
2817	12/21/2006	LTN050GEF	LOCHINVAR	0
2818	03/07/1984	FSG50	AO SMITH	0
2819	01/01/1997	PRV50NORT	STATE	0
2820	06/28/2004	XTN040	LOCHINVAR	0
2821	01/01/1982	FSG40	AO SMITH	0
2822	09/19/2012	G91200	RUUD/RHEEM	3
2823	01/01/2003	FSG30	AO SMITH	0
2824	05/08/2010	LTN050G	LOCHINVAR	0
2825	08/11/2003	FSGL40	AO SMITH	0
2826	06/10/2006	LTN050G	LOCHINVAR	0
2827	11/12/1998	FGR40	AO SMITH	0
2828	09/13/2000	41V40S	RHEEM	0
2829	11/07/1983	FSGL40	AO SMITH	0
2830	01/01/2003	FSG30	AO SMITH	0
2831	12/17/2001	PGR50	AO SMITH	0
2832	01/24/2002	FSG50	AO SMITH	0
2833	09/22/2012	MI50L6FBN	BRADFORD-WHITE	0
2834	05/05/2011	41VR50	RHEEM	0
2835	05/13/2003	PGR50	AO SMITH	0
2836	08/17/2004	GCVL40	A. O. SMITH	0
2837	04/07/2006	LTN040G	LOCHINVAR	0
2838	04/17/2001	FSG50	AO SMITH	0
2839	03/06/2011	42VR50	RHEEM	1
2840	09/20/2007	LTN050GEF	LOCHINVAR	0
2841	06/08/2007	LTN050G	LOCHINVAR	1
2842	12/16/2008	KGA30	AO SMITH	0
2843	09/08/2004	XTN050	LOCHINVAR	0
2844	04/09/2008	G75125	RUUD/RHEEM	0
2845	07/07/2011	M45036FBN	BRADFORD-WHITE	0
2846	11/22/1999	FSGL40	AO SMITH	0
2847	11/20/2002	FSG50	AO SMITH	1
2848	01/20/2009	LTN040GEF	LOCHINVAR	0
2849	04/11/2001	PGR50	AO SMITH	0
2850	10/12/2004	XVR50	A. O. SMITH	0
2851	12/04/1979	FSG50	AO SMITH	0
2852	12/08/2010	42VR50	RHEEM	1
2853	11/01/1979	FSG50	AO SMITH	0
2854	11/26/2003	PVR50	AO SMITH	0
2855	05/23/1983	21V502	RHEEM	0
2856	12/03/2002	FSG50	AO SMITH	0
2857	12/20/2012	MI5036FBN	BRADFORD-WHITE	0
2858	08/04/2008	G91200	RUUD/RHEEM	2
2859	04/26/2007	LTN050GEF	LOCHINVAR	1
2860	03/01/2001	21V407	RHEEM	0
2861	09/26/2012	MI50L6FBN	BRADFORD-WHITE	0
2862	08/04/2008	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2863	10/10/2000	41XR50	RHEEM	0
2864	10/17/1983	FSG50	AO SMITH	0
2865	12/19/2006	FSGL40	AO SMITH	2
2866	05/12/2004	FSG50	AO SMITH	0
2867	10/10/2006	LTN050GEF	LOCHINVAR	0
2868	07/03/2003	FSG40	AO SMITH	0
2869	10/25/2003	FCVL40	AO SMITH	0
2870	07/08/2003	PGR40	AO SMITH	0
2871	09/13/2011	M45036FBN	BRADFORD-WHITE	0
2872	06/24/1998	FGR50	AO SMITH	0
2873	02/18/1997	FSGL40	AO SMITH	0
2874	10/10/2008	LSN041G	LOCHINVAR	0
2875	01/17/1999	41V50	RHEEM	0
2876	06/16/1998	FSG40	AO SMITH	0
2877	12/12/2005	LSN041G	LOCHINVAR	0
2878	07/19/2001	G91200	RUUD/RHEEM	0
2879	07/11/1999	PHR50	RUUD	0
2880	10/31/2010	21VR40	RHEEM	0
2881	12/01/1982	FSG40	AO SMITH	0
2882	04/02/2009	LTN040GEF	LOCHINVAR	0
2883	06/29/2004	GVC40	A. O. SMITH	1
2884	03/29/2003	FSG50	AO SMITH	0
2885	11/07/2002	PGR50	AO SMITH	0
2886	05/04/2007	LTN050G	LOCHINVAR	0
2887	11/17/2005	LTN040G	LOCHINVAR	0
2888	11/09/2003	PGR50	AO SMITH	0
2889	10/03/2008	LTN050G	LOCHINVAR	0
2890	04/28/1998	FSG40	AO SMITH	0
2891	12/28/2007	LTN050GEF	LOCHINVAR	0
2892	10/11/2008	LTN050GEF	LOCHINVAR	0
2893	04/25/2008	LTN050GEF	LOCHINVAR	1
2894	11/22/2000	41XR50	RHEEM	0
2895	11/09/2010	21VR50	RHEEM	0
2896	03/08/1999	FSGL40	AO SMITH	0
2897	10/16/2009	LTN050GEF	LOCHINVAR	0
2898	02/05/2002	FSG40	AO SMITH	0
2899	01/05/2004	FCVL40	AO SMITH	0
2900	06/03/2011	41VR50	RHEEM	0
2901	08/10/2001	FSG40	AO SMITH	0
2902	11/27/1993	FSGL40	AO SMITH	0
2903	09/08/2010	LTN050GEF	LOCHINVAR	0
2904	08/01/1982	FSG50	AO SMITH	0
2905	05/06/2002	FSGL40	AO SMITH	0
2906	10/16/2007	LSN041G	LOCHINVAR	0
2907	09/29/1996	FSGL40	AO SMITH	0
2908	01/29/1999	FGR50	AO SMITH	0
2909	05/29/1999	FSG50	AO SMITH	0
2910	03/11/2003	FSG50	AO SMITH	0
2911	06/21/2001	FSG50	AO SMITH	1
2912	09/23/2011	M45036FBN	BRADFORD-WHITE	0
2913	01/01/1982	RF67120	RUUD	0
2914	07/24/2004	XVR50	A. O. SMITH	0
2915	07/02/2001	FSG50	AO SMITH	0
2916	06/14/2010	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2917	01/01/2012	M45036FBN	BRADFORD-WHITE	1
2918	12/23/1982	21V407	RHEEM	0
2919	07/23/2009	LTN050GEF	LOCHINVAR	0
2920	10/13/1997	FSG30	AO SMITH	0
2921	07/06/2009	LTN040GEF	LOCHINVAR	0
2922	05/15/2006	LTN050G	LOCHINVAR	0
2923	11/12/1997	FSG30	AO SMITH	0
2924	05/30/2006	LTN040G	LOCHINVAR	0
2925	10/14/2011	M-I-5036FBN	BRADFORD-WHITE	0
2926	01/27/2007	LTN040G	LOCHINVAR	1
2927	11/14/2012	M2XR504T6FBN	BRADFORD WHITE	3
2928	12/10/2007	LTN050G	LOCHINVAR	0
2929	10/29/2009	LTN050GEF	LOCHINVAR	0
2930	10/07/2006	LTN051G	LOCHINVAR	0
2931	03/23/2009	LTN040GEF	LOCHINVAR	2
2932	01/21/2006	LTN050G	LOCHINVAR	0
2933	01/29/2011	42VR50	RHEEM	0
2934	11/19/1999	PHR50	RUUD	0
2935	11/11/2009	FGR50	AO SMITH	0
2936	07/16/2011	M45036FBN	BRADFORD-WHITE	1
2937	03/01/2001	H72DUMMY	AO SMITH	0
2938	02/03/2004	PVR50	AO SMITH	1
2939	03/06/2006	LTN040G	LOCHINVAR	0
2940	06/28/1984	FSG50	AO SMITH	0
2941	02/02/2009	LTN050GEF	LOCHINVAR	0
2942	02/17/2004	XTN050	LOCHINVAR	0
2943	10/01/2007	LTN050G	LOCHINVAR	0
2944	03/03/2007	LTN050G	LOCHINVAR	0
2945	04/06/2010	LTN050GEF	LOCHINVAR	0
2946	12/20/2005	LSN041G	LOCHINVAR	0
2947	02/28/2013	M45036FBN	BRADFORD-WHITE	0
2948	10/30/1990	21V502	RHEEM	0
2949	09/10/2003	FSGL40	AO SMITH	0
2950	08/16/2011	M45036FBN	BRADFORD-WHITE	1
2951	07/09/2010	LTN040	LOCHINVAR	0
2952	06/28/1984	RM5063	RUUD	0
2953	10/01/1999	FGR50	AO SMITH	0
2954	11/05/2010	42VR50	RHEEM	0
2955	10/08/2009	FGR50	AO SMITH	0
2956	05/26/1999	FGR50	AO SMITH	0
2957	05/02/2003	FSG50	AO SMITH	0
2958	05/14/2007	LTN050G	LOCHINVAR	0
2959	04/29/2010	LTN040GEF	LOCHINVAR	0
2960	07/19/2007	LSN041G	LOCHINVAR	1
2961	05/28/1998	FGR50	AO SMITH	1
2962	05/13/2005	LTN050	LOCHINVAR	1
2963	01/11/1996	PGR50	AO SMITH	0
2964	02/07/2009	21VR40	RHEEM	0
2965	01/25/2013	M45036FBN	BRADFORD-WHITE	0
2966	02/12/1999	41VR50	RHEEM	0
2967	01/27/2000	FSG40	AO SMITH	0
2968	08/05/2008	LTN050GEF	LOCHINVAR	0
2969	01/04/2007	41V50	RHEEM	0
2970	07/21/2012	MI5036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
2971	12/28/2004	41V50	RHEEM	0
2972	06/18/2008	LSN041G	LOCHINVAR	0
2973	03/29/2012	P230F	RUUD	0
2974	08/21/2012	M45036FBN	BRADFORD-WHITE	1
2975	09/10/2001	FSGL40	AO SMITH	1
2976	11/19/1997	PGR50	AO SMITH	0
2977	08/20/2002	G91200	RUUD/RHEEM	2
2978	02/10/2010	LTN040G	LOCHINVAR	0
2979	12/27/1999	21V407	RHEEM	1
2980	05/17/1999	FSG50	AO SMITH	0
2981	03/29/2012	P230F	RUUD	1
2982	06/12/2012	G91200	RUUD/RHEEM	1
2983	10/02/2000	41XR50	RHEEM	0
2984	10/22/2002	FSG40	AO SMITH	1
2985	06/15/1999	G91200	RUUD/RHEEM	1
2986	09/17/2012	G91200	RUUD/RHEEM	0
2987	05/04/2009	LTN050GEF	LOCHINVAR	0
2988	01/25/2012	MI5036FBN	BRADFORD-WHITE	0
2989	06/22/2010	LSN041G	LOCHINVAR	0
2990	07/20/2005	LTN050	LOCHINVAR	0
2991	03/05/2009	LTN050GEF	LOCHINVAR	1
2992	07/10/2010	LTN050GEF	LOCHINVAR	0
2993	06/22/2010	LSN041G	LOCHINVAR	0
2994	03/15/1995	BTC197	AO SMITH	1
2995	10/07/2011	MI5036FBN	BRADFORD-WHITE	0
2996	10/05/2009	LSN041G	LOCHINVAR	0
2997	03/23/2000	FSG50	AO SMITH	0
2998	05/01/2012	M45036FBN	BRADFORD-WHITE	0
2999	03/26/1999	FSG40	AO SMITH	0
3000	10/02/2009	LSN041G	LOCHINVAR	0
3001	11/29/2011	M440T6FBN	BRADFORD-WHITE	0
3002	12/03/1997	PGR40	AO SMITH	0
3003	06/01/2009	LTN050GEF	LOCHINVAR	0
3004	09/01/2010	LTN050GEF	LOCHINVAR	0
3005	04/03/2009	LTN050GEF	LOCHINVAR	0
3006	07/27/2010	PH199119	PHOENIX	1
3007	06/15/2011	G91200	RUUD/RHEEM	0
3008	06/01/2009	PR502T	RUUD	0
3009	03/26/2004	FCV50	AO SMITH	0
3010	12/14/1999	PGR50	AO SMITH	0
3011	07/27/2010	PH199119	PHOENIX	0
3012	02/24/2003	PGR50	AO SMITH	1
3013	05/15/2002	FSG50	AO SMITH	0
3014	06/02/2000	PGR50	AO SMITH	0
3015	03/15/2012	M440T6FBN	BRADFORD-WHITE	1
3016	01/07/2004	PRX40	STATE	0
3017	11/08/1996	G67114	RHEEM	0
3018	08/16/1983	21V407	RHEEM	0
3019	08/05/2010	LTN050GEF	LOCHINVAR	1
3020	12/31/2008	ETN076	LOCHINVAR	0
3021	08/09/2003	FCV50	AO SMITH	2
3022	04/18/1995	PHR50	RUUD	0
3023	03/27/1997	PGR50	AO SMITH	0
3024	11/08/2007	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3025	01/31/1998	FGR40	AO SMITH	0
3026	10/11/2001	FSG50	AO SMITH	0
3027	12/15/1995	PR502T	RUUD	0
3028	09/23/1997	PGR50	AO SMITH	0
3029	07/18/2011	MI40T6FBN	BRADFORD-WHITE	1
3030	01/13/2009	FSGL40	AO SMITH	0
3031	03/01/2010	G91200	RUUD/RHEEM	2
3032	01/18/2005	FSG50	AO SMITH	0
3033	04/25/2011	21VR40	RHEEM	0
3034	02/28/2008	22DV50C	RHEEM	0
3035	07/23/2001	FSG40	AO SMITH	0
3036	06/08/2012	M45036FBN	BRADFORD-WHITE	0
3037	03/26/1999	41VR40	RHEEM	0
3038	03/21/2012	PGR50	AO SMITH	1
3039	04/13/1996	PGR50	AO SMITH	0
3040	07/16/2001	PGR50	AO SMITH	0
3041	08/23/2009	LTN050GEF	LOCHINVAR	0
3042	10/31/2006	LTN040G	LOCHINVAR	0
3043	03/09/2001	FSG50	AO SMITH	0
3044	11/01/1980	B71	UNKNOWN	0
3045	07/02/1997	PGR50	AO SMITH	0
3046	02/04/1982	RM5063	RUUD	0
3047	03/04/2003	FSG40	AO SMITH	0
3048	04/03/2001	41XR50	RHEEM	0
3049	04/06/2010	LTN050GEF	LOCHINVAR	0
3050	11/06/2007	LTN050GEF	LOCHINVAR	0
3051	01/20/2003	FSG50	AO SMITH	0
3052	10/11/2010	G75125	RUUD/RHEEM	1
3053	09/28/2010	42VR50	RHEEM	0
3054	07/18/2005	LTN050	LOCHINVAR	0
3055	04/21/2006	LTN050G	LOCHINVAR	0
3056	11/18/2011	MI5036FBN	BRADFORD-WHITE	0
3057	02/29/2008	LTN050GEF	LOCHINVAR	0
3058	08/30/2001	PGR40	AO SMITH	0
3059	02/26/2011	21VR50	RHEEM	0
3060	09/17/2002	PGR50	AO SMITH	0
3061	08/02/2007	LTN040GEF	LOCHINVAR	0
3062	03/22/2010	21VR40	RHEEM	1
3063	08/08/2008	FSG50	AO SMITH	0
3064	02/26/1996	PRV40NODS	STATE	1
3065	02/06/2012	MI5036FBN	BRADFORD-WHITE	0
3066	12/21/2010	21VR40	RHEEM	0
3067	05/29/2007	LTN050GEF	LOCHINVAR	0
3068	05/09/2007	LSN041G	LOCHINVAR	0
3069	02/01/1982	FSG50	AO SMITH	0
3070	07/19/2011	M45036FBN	BRADFORD-WHITE	1
3071	07/21/2010	LTN050GEF	LOCHINVAR	0
3072	05/17/2006	LTN050G	LOCHINVAR	0
3073	02/28/2001	41VR40	RHEEM	0
3074	01/03/2012	M45036FBN	BRADFORD-WHITE	0
3075	01/16/2010	LTN050GEF	LOCHINVAR	0
3076	03/20/1997	FSG50	AO SMITH	0
3077	07/15/2009	LTN050GEF	LOCHINVAR	0
3078	11/18/1998	41VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3079	10/01/1981	FSG50	AO SMITH	0
3080	01/20/2010	LTN050GEF	LOCHINVAR	0
3081	06/13/2008	LTN050GEF	LOCHINVAR	0
3082	12/28/2000	G75125	RUUD/RHEEM	5
3083	04/28/1999	FSG50	AO SMITH	0
3084	10/24/2005	LTN050G	LOCHINVAR	0
3085	02/23/2006	LTN040G	LOCHINVAR	0
3086	02/04/2010	LTN050GEF	LOCHINVAR	0
3087	12/22/2009	LTN050GEF	LOCHINVAR	0
3088	05/15/2002	PGR50	AO SMITH	0
3089	09/11/2002	41XR50	RHEEM	3
3090	12/29/2000	PGR50	AO SMITH	0
3091	08/24/2010	LTN050	LOCHINVAR	0
3092	09/11/2002	41XR50	RHEEM	1
3093	02/02/2013	G75125	RUUD/RHEEM	3
3094	01/22/2008	LTN040GEF	LOCHINVAR	0
3095	06/05/2003	FSG50	AO SMITH	0
3096	02/14/1994	PGR50	AO SMITH	0
3097	07/25/2002	BTR198	AO SMITH	1
3098	02/11/1999	FGR50	AO SMITH	0
3099	01/24/2013	G91200	RUUD/RHEEM	0
3100	02/27/2002	FSG50	AO SMITH	0
3101	07/23/2002	BTR198	AO SMITH	0
3102	08/03/1998	G67114	RHEEM	0
3103	06/08/2009	LTN050GEF	LOCHINVAR	1
3104	09/22/2008	LTN040GEF	LOCHINVAR	1
3105	11/12/2011	MI5036FBN	BRADFORD-WHITE	0
3106	02/10/2012	G91200	RUUD/RHEEM	1
3107	02/18/1999	FGR50	AO SMITH	0
3108	10/03/2002	FSG50	AO SMITH	0
3109	10/18/2007	LTN050GEF	LOCHINVAR	0
3110	08/16/1996	FSGL40	AO SMITH	0
3111	09/26/2008	LSN041G	LOCHINVAR	0
3112	11/24/2008	LTN050GEF	LOCHINVAR	2
3113	07/09/2006	LTN050G	LOCHINVAR	0
3114	03/10/2005	GVC50	A. O. SMITH	1
3115	11/01/1980	FSG50	AO SMITH	0
3116	01/14/2003	FSG50	AO SMITH	0
3117	07/10/2012	MI5036FBN	BRADFORD-WHITE	0
3118	02/28/2013	M45036FBN	BRADFORD-WHITE	0
3119	01/28/2011	42VR50	RHEEM	1
3120	07/17/2008	LTN050GEF	LOCHINVAR	2
3121	06/14/2004	XVR50	A. O. SMITH	0
3122	03/06/1995	FSGL40	AO SMITH	0
3123	02/01/2003	PGR40	AO SMITH	0
3124	02/16/2010	LSN041G	LOCHINVAR	0
3125	10/14/2012	MI403S6FBN	BRADFORD-WHITE	0
3126	01/03/1998	PGR50	AO SMITH	0
3127	07/10/2002	BTR198	AO SMITH	3
3128	04/08/2012	M45036FBN	BRADFORD-WHITE	0
3129	04/07/2009	22DV50C	RHEEM	0
3130	01/11/2002	G91200	RUUD/RHEEM	2
3131	05/27/2005	XSN040	LOCHINVAR	2
3132	06/30/2010	G75125	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3133	11/29/1995	PGR50	AO SMITH	0
3134	03/15/2007	LTN050G	LOCHINVAR	0
3135	11/21/2006	LTN050G	LOCHINVAR	0
3136	03/15/2011	21VR50	RHEEM	1
3137	04/17/2012	M45036FBN	BRADFORD-WHITE	0
3138	09/23/2005	LTN050	LOCHINVAR	0
3139	04/13/2001	G75125	RUUD/RHEEM	1
3140	04/07/1998	FSG50	AO SMITH	0
3141	08/11/2004	GVC50	A. O. SMITH	0
3142	10/18/2010	42VR50	RHEEM	0
3143	07/27/2010	LTN050G	LOCHINVAR	1
3144	08/17/1998	G67114	RHEEM	1
3145	04/02/2004	FCV50	AO SMITH	0
3146	12/29/2009	PR502T	RUUD	1
3147	04/04/2006	LTN050G	LOCHINVAR	0
3148	06/21/2005	GCVL40	A. O. SMITH	0
3149	10/17/2000	41XR50	RHEEM	0
3150	07/07/1998	FGR50	AO SMITH	0
3151	01/02/2009	LTN050G	LOCHINVAR	1
3152	10/21/2003	FCV50	AO SMITH	0
3153	04/25/1998	FGR50	AO SMITH	0
3154	05/02/2006	LTN040G	LOCHINVAR	0
3155	11/03/2009	LTN050GEF	LOCHINVAR	0
3156	07/28/2010	41VR50	RHEEM	0
3157	02/11/2002	FSG40	AO SMITH	0
3158	12/01/2010	21VR50	RHEEM	0
3159	04/11/2000	41V40S	RHEEM	0
3160	12/13/2001	FSG50	AO SMITH	1
3161	03/03/2010	LTN050GEF	LOCHINVAR	0
3162	12/10/1998	FGR50	AO SMITH	0
3163	08/24/2004	XTN050	LOCHINVAR	0
3164	01/10/2003	PGR50	AO SMITH	0
3165	11/26/2007	LTN050GEF	LOCHINVAR	0
3166	02/03/2006	LTN051G	LOCHINVAR	0
3167	08/01/2009	LTN050GEF	LOCHINVAR	0
3168	12/18/2001	PGR50	AO SMITH	0
3169	05/02/2007	LTN050G	LOCHINVAR	0
3170	10/16/1996	PGR50	AO SMITH	0
3171	08/26/2003	FSG50	AO SMITH	0
3172	11/19/2008	LTN050GEF	LOCHINVAR	0
3173	05/08/2005	LTN050	LOCHINVAR	4
3174	07/03/2006	LTN050G	LOCHINVAR	0
3175	03/22/2011	21VR40	RHEEM	0
3176	01/22/2008	LTN050GEF	LOCHINVAR	0
3177	01/21/1986	PH30	RUUD	0
3178	05/18/2008	LTN050GEF	LOCHINVAR	0
3179	05/16/2005	LTN050	LOCHINVAR	0
3180	01/09/2007	LTN050G	LOCHINVAR	1
3181	11/18/2004	XVR50	A. O. SMITH	0
3182	06/02/2012	MI5036FBN	BRADFORD-WHITE	0
3183	10/09/1999	41VR50	RHEEM	0
3184	11/20/2009	LTN050GEF	LOCHINVAR	0
3185	02/17/2004	FCV50	AO SMITH	0
3186	11/27/1984	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3187	03/05/2011	42VR50	RHEEM	0
3188	10/12/2010	41VR50	RHEEM	0
3189	08/19/2011	MI403S6FBN	BRADFORD-WHITE	0
3190	02/10/2012	MI5036FBN	BRADFORD-WHITE	0
3191	07/12/1997	PGR50	AO SMITH	0
3192	09/06/2012	SBF100199NES	STATE	0
3193	10/09/2003	FSG50	AO SMITH	0
3194	10/14/2010	G75125	RUUD/RHEEM	2
3195	06/15/1983	FSG40	AO SMITH	0
3196	03/12/2011	G91200	RUUD/RHEEM	4
3197	03/10/2006	LTN050G	LOCHINVAR	1
3198	03/27/2002	FSG50	AO SMITH	0
3199	02/02/2009	LTN040GEF	LOCHINVAR	0
3200	01/21/2009	LTN050GEF	LOCHINVAR	0
3201	09/14/1998	FSGL40	AO SMITH	1
3202	08/31/2007	G82156	RUUD/RHEEM	0
3203	03/18/2003	PGR50	AO SMITH	1
3204	03/09/1998	FGR50	AO SMITH	0
3205	06/22/2001	POWERMISER 9	KENMORE	1
3206	03/16/2009	LSN041G	LOCHINVAR	0
3207	04/29/2011	21VR50	RHEEM	0
3208	04/06/2011	G75125	RUUD/RHEEM	0
3209	09/14/2012	M45036FBN	BRADFORD-WHITE	0
3210	07/29/2002	FSG40	AO SMITH	0
3211	06/26/2008	LTN050GEF	LOCHINVAR	1
3212	10/30/1998	G72DUMMY	AO SMITH	0
3213	11/16/2009	LTN050GEF	LOCHINVAR	0
3214	03/28/2005	XVR50	A. O. SMITH	2
3215	09/26/2008	LTN050GEF	LOCHINVAR	0
3216	11/11/2004	FSG50	AO SMITH	0
3217	04/12/2012	MI40T6FBN	BRADFORD-WHITE	0
3218	06/25/2005	LTN040	LOCHINVAR	0
3219	11/22/2010	42VR50	RHEEM	0
3220	02/18/2011	22DV50F	RHEEM	0
3221	01/13/2004	FCVL40	AO SMITH	0
3222	07/06/2001	FSG50	AO SMITH	0
3223	09/09/2008	LTN050G	LOCHINVAR	0
3224	09/11/2001	FSG50	AO SMITH	0
3225	03/04/1997	FSG50	AO SMITH	0
3226	11/12/2001	PGR50	AO SMITH	0
3227	03/12/2012	MI40T6FBN	BRADFORD-WHITE	1
3228	12/01/1985	FSG50	AO SMITH	0
3229	02/07/2011	21VR50	RHEEM	0
3230	11/21/2001	PGR50	AO SMITH	1
3231	09/20/2001	PGR50	AO SMITH	1
3232	05/09/2000	FSG50	AO SMITH	0
3233	10/08/2008	LTN050GEF	LOCHINVAR	0
3234	07/30/2011	MI403S6FBN	BRADFORD-WHITE	1
3235	05/19/2011	21VR50	RHEEM	1
3236	01/19/1999	FSG50	AO SMITH	0
3237	04/26/2006	LTN050G	LOCHINVAR	2
3238	09/27/1985	FSG50	AO SMITH	0
3239	12/10/2005	PR640	STATE	0
3240	01/30/2009	LTN050GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3241	04/23/1986	FSG50	AO SMITH	0
3242	11/23/1985	FSG50	AO SMITH	0
3243	04/18/2005	GVC50	A. O. SMITH	0
3244	02/05/2011	22DV50F	RHEEM	0
3245	02/27/2007	LTN050GEF	LOCHINVAR	0
3246	02/13/2009	LTN050GEF	LOCHINVAR	0
3247	02/01/2012	PH2DV50F	RUUD	0
3248	10/10/2012	G91200	RUUD/RHEEM	0
3249	07/31/2003	PRV50NODS	STATE	0
3250	07/19/2009	41V50	RHEEM	0
3251	04/12/2012	M45036FBN	BRADFORD-WHITE	0
3252	08/08/2009	LTN050GEF	LOCHINVAR	1
3253	12/02/2006	LTN050G	LOCHINVAR	0
3254	11/14/2011	MI5036FBN	BRADFORD-WHITE	0
3255	03/29/2001	FSG50	AO SMITH	0
3256	02/19/2009	22DV50F	RHEEM	0
3257	09/16/1999	FGR40	AO SMITH	0
3258	01/20/1998	41VR50	RHEEM	0
3259	09/23/2011	M45036FBN	BRADFORD-WHITE	1
3260	08/19/2008	LTN050G	LOCHINVAR	0
3261	05/02/2008	22DV50C	RHEEM	0
3262	02/28/2006	LTN050G	LOCHINVAR	4
3263	12/19/2006	LTN050GEF	LOCHINVAR	0
3264	05/20/2002	FSG40	AO SMITH	1
3265	05/11/2007	LTN050G	LOCHINVAR	0
3266	10/26/2001	PGR50	AO SMITH	1
3267	07/07/2000	FSGL40	AO SMITH	0
3268	10/21/2005	LTN050G	LOCHINVAR	0
3269	09/12/2012	M45036FBN	BRADFORD-WHITE	2
3270	10/17/1994	PGR40	AO SMITH	0
3271	11/16/1983	FSGL40	AO SMITH	0
3272	08/06/2010	LTN050G	LOCHINVAR	1
3273	02/12/2004	XTN050	LOCHINVAR	0
3274	06/10/2011	21VR40	RHEEM	0
3275	07/27/2002	PGR50	AO SMITH	0
3276	08/05/2003	FCVL40	AO SMITH	0
3277	12/11/2007	LTN040G	LOCHINVAR	0
3278	01/23/2011	42VR50	RHEEM	0
3279	05/15/2003	FSGL40	AO SMITH	0
3280	08/06/2009	LTN050G	LOCHINVAR	2
3281	03/05/2011	21VR40	RHEEM	0
3282	09/08/1982	FSGL40	AO SMITH	0
3283	12/08/1994	H72DUMMY	AO SMITH	0
3284	10/17/1997	41VR50	RHEEM	0
3285	03/09/2011	21VR40	RHEEM	0
3286	11/25/2011	M45036FBN	BRADFORD-WHITE	1
3287	10/06/2005	LTN040G	LOCHINVAR	0
3288	11/29/2006	LTN050G	LOCHINVAR	0
3289	04/22/2009	LTN040GEF	LOCHINVAR	0
3290	12/07/2010	42VR50	RHEEM	0
3291	02/14/2012	M45036FBN	BRADFORD-WHITE	1
3292	12/15/2006	LTN050G	LOCHINVAR	0
3293	02/20/2002	PGR50	AO SMITH	0
3294	11/13/2007	LTN050GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3295	08/22/2012	G82156	RUUD/RHEEM	1
3296	08/17/2007	LTN050GEF	LOCHINVAR	0
3297	06/26/2000	FSG50	AO SMITH	0
3298	12/18/1998	FSG50	AO SMITH	0
3299	04/26/2005	LTN050	LOCHINVAR	0
3300	01/11/2002	FSG50	AO SMITH	0
3301	06/24/2010	LTN050G	LOCHINVAR	0
3302	05/18/2010	22DV50C	RHEEM	0
3303	03/02/2011	42VR50	RHEEM	0
3304	11/18/2011	MI403S6FBN	BRADFORD-WHITE	0
3305	09/05/2006	PR650	STATE	0
3306	10/08/2012	MI403S6FBN	BRADFORD-WHITE	1
3307	07/05/2011	M45036FBN	BRADFORD-WHITE	1
3308	03/03/2009	FSGL40	AO SMITH	0
3309	11/07/2008	LTN050GEF	LOCHINVAR	0
3310	10/23/2007	PR650	STATE	0
3311	02/20/2007	LTN050G	LOCHINVAR	1
3312	05/02/2000	FSG40	AO SMITH	0
3313	11/18/1997	FSG40	AO SMITH	0
3314	05/19/2005	LTN040	LOCHINVAR	1
3315	11/06/2012	G91200	RUUD/RHEEM	4
3316	03/03/2008	21DV50	RHEEM	0
3317	11/16/2005	LSN041G	LOCHINVAR	0
3318	09/04/1998	41VR50	RHEEM	0
3319	07/08/2002	FSG50	AO SMITH	0
3320	01/31/2012	M45036FBN	BRADFORD-WHITE	2
3321	02/21/2013	M45036FBN	BRADFORD-WHITE	0
3322	01/16/1985	FSG40	AO SMITH	0
3323	02/25/2009	LTN050GEF	LOCHINVAR	0
3324	01/26/2004	FCV50	AO SMITH	0
3325	06/01/2003	FSG50	AO SMITH	0
3326	08/30/2000	41V40S	RHEEM	0
3327	12/12/2003	PVR50	AO SMITH	0
3328	09/24/2009	LTN040GEF	LOCHINVAR	0
3329	08/30/1999	FSG50	AO SMITH	0
3330	08/31/2010	21V502	RHEEM	0
3331	06/21/2001	PGR50	AO SMITH	0
3332	01/12/2009	LTN050GEF	LOCHINVAR	0
3333	06/25/2003	FSGL40	AO SMITH	0
3334	03/05/2001	FSG50	AO SMITH	1
3335	06/06/2002	FSG50	AO SMITH	0
3336	05/08/2008	LTN050GEF	LOCHINVAR	1
3337	09/28/2010	21VR50	RHEEM	0
3338	06/12/2001	FSG50	AO SMITH	0
3339	12/20/2002	41V40S	RHEEM	0
3340	03/10/2010	LTN050GEF	LOCHINVAR	0
3341	04/12/2005	GCVL40	A. O. SMITH	0
3342	10/12/2011	MI40T6FBN	BRADFORD-WHITE	1
3343	03/05/2011	42VR50	RHEEM	0
3344	02/24/2005	GCVL40	A. O. SMITH	0
3345	08/07/2012	M45036FBN	BRADFORD-WHITE	0
3346	05/02/2003	FSG50	AO SMITH	0
3347	12/18/2009	LTN040GEF	LOCHINVAR	0
3348	03/21/2008	LTN040	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3349	01/12/2012	MI403S6FBN	BRADFORD-WHITE	0
3350	11/02/2009	LTN050GEF	LOCHINVAR	0
3351	09/14/2012	MI40T6FBN	BRADFORD-WHITE	0
3352	11/23/2010	21VR50	RHEEM	0
3353	04/11/1988	SBF75120NE	STATE	0
3354	01/24/2013	MI403S6FBN	BRADFORD-WHITE	0
3355	08/20/2011	42V50SF	RHEEM	0
3356	12/01/2009	LTN050GEF	LOCHINVAR	0
3357	02/10/2006	LTN040G	LOCHINVAR	1
3358	10/14/1998	FSG40	AO SMITH	0
3359	09/15/2009	LTN040G	LOCHINVAR	3
3360	10/03/2006	LTN050G	LOCHINVAR	0
3361	10/03/2007	LTN050GEF	LOCHINVAR	0
3362	12/09/1999	G75125	RUUD/RHEEM	1
3363	04/12/2011	41VR50	RHEEM	0
3364	07/18/2006	LTN050G	LOCHINVAR	0
3365	09/09/2011	MI5036FBN	BRADFORD-WHITE	0
3366	03/31/2011	21VR50	RHEEM	0
3367	04/19/2000	FSG50	AO SMITH	1
3368	12/03/2002	41XR50	RHEEM	0
3369	05/03/2006	LTN040GEF	LOCHINVAR	0
3370	12/23/2004	GVC50	A. O. SMITH	0
3371	09/18/2012	M45036FBN	BRADFORD-WHITE	0
3372	03/19/1998	FSG50	AO SMITH	0
3373	04/08/2011	22DV50F	RHEEM	1
3374	07/28/2011	MI5036FBN	BRADFORD-WHITE	0
3375	03/31/2008	22DV50C	RHEEM	0
3376	02/03/1999	FGR50	AO SMITH	0
3377	03/03/1991	PRX50	STATE	0
3378	05/25/2010	LTN050GEF	LOCHINVAR	0
3379	12/11/2005	LTN050GEF	LOCHINVAR	0
3380	09/14/2009	21V502	RHEEM	0
3381	02/07/2003	21V506	RHEEM	0
3382	08/30/2007	LTN050G	LOCHINVAR	0
3383	12/06/1985	FSG50	AO SMITH	0
3384	03/19/2001	FSG50	AO SMITH	0
3385	08/26/2009	G76200	RUUD/RHEEM	1
3386	12/21/2011	M45036FBN	BRADFORD-WHITE	0
3387	05/22/2008	LTN050GEF	LOCHINVAR	0
3388	04/18/2001	PRX50	STATE	0
3389	03/22/2012	M45036FBN	BRADFORD-WHITE	0
3390	05/07/2009	LTN050GEF	LOCHINVAR	0
3391	10/26/2009	LTN050GEF	LOCHINVAR	0
3392	01/18/2007	LSN041G	LOCHINVAR	0
3393	12/14/2007	LTN050GEF	LOCHINVAR	0
3394	10/19/2011	DS150S6FBN	BRADFORD-WHITE	0
3395	04/24/2007	LTN040G	LOCHINVAR	0
3396	10/14/2010	22DV50C	RHEEM	0
3397	04/15/2006	LTN050G	LOCHINVAR	0
3398	06/10/2009	LTN050GEF	LOCHINVAR	0
3399	03/06/2009	LTN050GEF	LOCHINVAR	0
3400	03/20/2007	LTN050G	LOCHINVAR	0
3401	11/09/2012	MI5036FBN	BRADFORD-WHITE	0
3402	07/01/1998	FSG50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3403	10/03/2006	G91200	RUUD/RHEEM	0
3404	06/19/2007	LTN050G	LOCHINVAR	0
3405	07/03/1997	21V407	RHEEM	1
3406	11/26/2010	42VR50	RHEEM	0
3407	08/17/2004	XVR50	A. O. SMITH	2
3408	04/23/1999	FSGL30	AO SMITH	0
3409	08/17/2010	LTN050GEF	LOCHINVAR	2
3410	06/11/2010	LTN040GEF	LOCHINVAR	0
3411	01/18/2002	G82156	RUUD/RHEEM	1
3412	04/11/2008	LTN050GEF	LOCHINVAR	2
3413	01/13/2009	LTN040GEF	LOCHINVAR	0
3414	09/01/1982	P402	RUUD	0
3415	07/16/2012	M45036FBN	BRADFORD-WHITE	0
3416	04/25/2012	41XR50	RHEEM	0
3417	05/15/2001	FGR40	AO SMITH	0
3418	01/05/2012	MI50L6FBN	BRADFORD-WHITE	0
3419	05/30/2007	LTN040GEF	LOCHINVAR	0
3420	12/01/1984	FSG50	AO SMITH	0
3421	05/16/1994	PR502T	RUUD	0
3422	04/28/2008	PH199119	PHOENIX	1
3423	01/14/1997	RF67120	RUUD	0
3424	12/09/2009	LTN050GEF	LOCHINVAR	0
3425	01/29/2004	XTN050	LOCHINVAR	0
3426	12/14/1983	FSG50	AO SMITH	0
3427	05/03/2006	LTN040G	LOCHINVAR	0
3428	02/15/2005	FGR40	AO SMITH	2
3429	09/25/2007	LSN041G	LOCHINVAR	1
3430	11/02/2012	M45036FBN	BRADFORD-WHITE	0
3431	03/17/2008	LSN041	LOCHINVAR	0
3432	07/20/2004	XTN050	LOCHINVAR	0
3433	10/24/2012	M45036FBN	BRADFORD-WHITE	0
3434	09/01/1983	FSG50	AO SMITH	0
3435	08/17/2012	M45036FBN	BRADFORD-WHITE	0
3436	02/19/2013	G91200	RUUD/RHEEM	0
3437	02/21/2013	G91200	RUUD/RHEEM	0
3438	08/31/2007	LTN050GEF	LOCHINVAR	0
3439	05/02/2005	LTN050	LOCHINVAR	0
3440	07/23/2001	PGR50	AO SMITH	0
3441	02/07/2003	FSG50	AO SMITH	0
3442	09/17/1998	BTR198	AO SMITH	0
3443	12/27/2005	LTN050GEF	LOCHINVAR	1
3444	08/17/2000	FGR30	AO SMITH	0
3445	01/27/2011	42VR50	RHEEM	0
3446	12/03/2010	21VR40	RHEEM	0
3447	10/30/2009	PRX40	STATE	0
3448	07/20/2010	22DV50C	RHEEM	1
3449	07/22/2003	FSG40	AO SMITH	0
3450	06/03/2009	LTN050G	LOCHINVAR	0
3451	06/23/2010	LTN050GEF	LOCHINVAR	0
3452	09/05/2008	LTN050GEF	LOCHINVAR	0
3453	10/27/2006	LTN040G	LOCHINVAR	0
3454	06/08/2006	LTN050G	LOCHINVAR	0
3455	04/11/2012	PH2DV50F	RUUD	0
3456	01/25/2013	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3457	04/06/2009	LTN050GEF	LOCHINVAR	0
3458	12/18/2007	LTN040G	LOCHINVAR	1
3459	08/02/2011	MI5036FBN	BRADFORD-WHITE	0
3460	02/08/2002	PGR50	AO SMITH	0
3461	11/06/2010	21VR50	RHEEM	1
3462	08/06/2009	LTN050GEF	LOCHINVAR	0
3463	12/24/2002	FSG50	AO SMITH	0
3464	12/26/2012	M45036FBN	BRADFORD-WHITE	0
3465	02/01/2007	41V50	RHEEM	0
3466	06/26/2012	M45036FBN	BRADFORD-WHITE	0
3467	11/27/2006	LTN050G	LOCHINVAR	0
3468	01/23/2012	MI50L6FBN	BRADFORD-WHITE	0
3469	10/26/1999	FSG40	AO SMITH	0
3470	01/10/2004	FSG50	AO SMITH	0
3471	04/05/2010	PGR50	AO SMITH	0
3472	04/19/2004	PR650	STATE	0
3473	07/27/2007	LTN050GEF	LOCHINVAR	0
3474	11/28/2004	GVC50	A. O. SMITH	0
3475	10/23/2007	LTN050GEF	LOCHINVAR	1
3476	05/01/2009	22DV50C	RHEEM	0
3477	09/04/2009	LTN050GEF	LOCHINVAR	1
3478	01/08/1996	BTC197	AO SMITH	0
3479	01/17/2009	LTN050GEF	LOCHINVAR	0
3480	10/25/2007	LTN050GEF	LOCHINVAR	0
3481	05/03/2006	LSN041	LOCHINVAR	0
3482	01/08/1996	BTC197	AO SMITH	0
3483	07/22/2011	M440T6FBN	BRADFORD-WHITE	0
3484	12/28/1992	FSG50	AO SMITH	0
3485	04/02/2012	MI5036FBN	BRADFORD-WHITE	0
3486	12/10/2001	PGR50	AO SMITH	0
3487	11/08/2010	21VR50	RHEEM	0
3488	08/10/2006	LSN041G	LOCHINVAR	0
3489	10/09/2007	LTN050G	LOCHINVAR	0
3490	11/26/2008	LTN050GEF	LOCHINVAR	0
3491	07/30/2012	M45036FBN	BRADFORD-WHITE	0
3492	12/07/2004	GVC30	AOSMITH	0
3493	08/11/2007	LTN040GEF	LOCHINVAR	1
3494	06/30/1997	PGR40	AO SMITH	0
3495	07/13/2002	PGR40	AO SMITH	0
3496	04/20/2000	PHR50	RUUD	0
3497	08/25/2000	FSG40	AO SMITH	0
3498	01/22/2007	LTN050G	LOCHINVAR	0
3499	04/07/2003	PGR50	AO SMITH	0
3500	01/03/2010	FGR50	AO SMITH	0
3501	10/23/2001	PGR50	AO SMITH	1
3502	02/12/2002	FSG40	AO SMITH	0
3503	03/30/2010	LTN050GEF	LOCHINVAR	0
3504	10/25/2001	PGR50	AO SMITH	0
3505	05/22/2000	G75125	RUUD/RHEEM	0
3506	07/05/2012	M45036FBN	BRADFORD-WHITE	0
3507	10/10/2008	LTN050GEF	LOCHINVAR	0
3508	09/29/1996	RF67120	RUUD	0
3509	07/10/2004	GVC50	A. O. SMITH	0
3510	12/16/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3511	05/11/2012	MI403S6FBN	BRADFORD-WHITE	0
3512	05/14/2003	PGR50	AO SMITH	1
3513	01/27/2000	FGR40	AO SMITH	0
3514	03/17/2008	LSN041	LOCHINVAR	0
3515	01/06/2007	LTN040G	LOCHINVAR	1
3516	01/27/2009	LTN050GEF	LOCHINVAR	2
3517	07/10/2009	LTN050GEF	LOCHINVAR	0
3518	05/07/2004	XVR50	A. O. SMITH	1
3519	04/01/2002	PGR50	AO SMITH	0
3520	04/26/2001	FSGL40	AO SMITH	0
3521	10/21/2008	LTN050GEF	LOCHINVAR	0
3522	07/20/2001	41XR50	RHEEM	1
3523	08/31/2011	SBF100199NES	STATE	1
3524	12/12/2007	LTN050G	LOCHINVAR	0
3525	03/02/2010	G91200	RUUD/RHEEM	2
3526	12/04/2009	LTN050GEF	LOCHINVAR	0
3527	12/14/2012	MI5036FBN	BRADFORD-WHITE	2
3528	02/18/2012	M45036FBN	BRADFORD-WHITE	0
3529	02/06/2012	PH2DV50F	RUUD	0
3530	03/17/2006	LTN050G	LOCHINVAR	0
3531	03/01/2010	LTN050G	LOCHINVAR	0
3532	12/13/2010	21VR50	RHEEM	0
3533	01/25/1985	FSG50	AO SMITH	0
3534	07/28/2010	LSN041G	LOCHINVAR	0
3535	03/23/2008	LTN050GEF	LOCHINVAR	0
3536	03/29/2011	21VR40	RHEEM	0
3537	09/20/2005	LTN040G	LOCHINVAR	0
3538	03/01/2004	G75125	RUUD/RHEEM	0
3539	04/05/2005	XVR50	A. O. SMITH	0
3540	01/20/1997	PGR50	AO SMITH	0
3541	11/15/2009	LSN041G	LOCHINVAR	0
3542	01/02/2002	FSGL40	AO SMITH	0
3543	06/08/2010	LTN050G	LOCHINVAR	0
3544	04/22/1986	FSG50	AO SMITH	0
3545	09/15/2009	22DV50F	RHEEM	2
3546	07/25/1985	FSG50	AO SMITH	0
3547	02/20/2007	LTN050G	LOCHINVAR	0
3548	10/04/2001	FSG40	AO SMITH	0
3549	02/24/2010	22DV50C	RHEEM	0
3550	05/16/2006	LTN050G	LOCHINVAR	0
3551	05/02/2000	G75125	RUUD/RHEEM	0
3552	04/17/2009	LTN050GEF	LOCHINVAR	0
3553	01/06/2005	GVC50	A. O. SMITH	0
3554	05/30/2000	PGR50	AO SMITH	0
3555	01/30/2006	LSN041G	LOCHINVAR	1
3556	01/27/2006	LTN050G	LOCHINVAR	0
3557	01/27/2009	22DV50C	RHEEM	0
3558	04/10/2002	FSG40	AO SMITH	0
3559	12/26/2007	LTN050GEF	LOCHINVAR	0
3560	03/12/2013	MI5036FBN	BRADFORD-WHITE	1
3561	02/11/2008	LTN050GEF	LOCHINVAR	0
3562	07/14/1998	41VR50	RHEEM	0
3563	06/25/2009	LTN040G	LOCHINVAR	0
3564	01/23/2012	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3565	06/15/2004	XTN050	LOCHINVAR	0
3566	08/30/2010	FSG40	AO SMITH	0
3567	02/03/2009	22DV50C	RHEEM	0
3568	06/21/2005	LTN050	LOCHINVAR	0
3569	04/18/1986	FSG50	AO SMITH	0
3570	04/28/2010	LTN040GEF	LOCHINVAR	1
3571	09/26/2001	PGR50	AO SMITH	0
3572	02/09/2007	LTN050G	LOCHINVAR	0
3573	10/21/2005	LTN040G	LOCHINVAR	2
3574	10/25/2007	LTN050	LOCHINVAR	0
3575	09/07/2000	BTR197	AO SMITH	0
3576	01/23/1995	PR502T	RUUD	1
3577	04/25/1985	PH30	RUUD	1
3578	06/02/2001	FSG40	AO SMITH	0
3579	07/27/2009	LTN050GEF	LOCHINVAR	0
3580	08/11/2011	M45036FBN	BRADFORD-WHITE	1
3581	06/23/2008	22DV50F	RHEEM	0
3582	12/27/2012	PH2DV50F	RUUD	0
3583	09/28/2006	PR650	STATE	0
3584	01/02/2002	PGR50	AO SMITH	1
3585	05/26/2011	21V506	RHEEM	0
3586	11/12/2011	G75125	RUUD/RHEEM	0
3587	03/08/2001	PGR50	AO SMITH	0
3588	08/11/2007	LTN050G	LOCHINVAR	3
3589	10/14/1998	FGR50	AO SMITH	1
3590	04/20/2000	21V506	RHEEM	0
3591	05/01/2010	LTN050GEF	LOCHINVAR	1
3592	10/30/1999	41XR50	RHEEM	0
3593	09/19/2008	LTN050GEF	LOCHINVAR	0
3594	08/16/2002	PGR50	AO SMITH	0
3595	11/14/2003	FCV50	AO SMITH	0
3596	06/24/2008	LTN050GEF	LOCHINVAR	0
3597	11/26/2001	41XR50	RHEEM	0
3598	11/29/2009	LTN050GEF	LOCHINVAR	1
3599	10/02/2007	LTN050GEF	LOCHINVAR	0
3600	07/21/2010	22DV50C	RHEEM	0
3601	07/21/1999	FSG50	AO SMITH	0
3602	10/09/2006	LTN050G	LOCHINVAR	0
3603	11/15/2007	LSN041G	LOCHINVAR	0
3604	02/28/2005	PRX50	STATE	0
3605	09/11/2001	FSG50	AO SMITH	0
3606	03/07/2006	LTN040G	LOCHINVAR	1
3607	04/18/1986	RM5063	RUUD	1
3608	08/05/2011	M45036FBN	BRADFORD-WHITE	1
3609	09/30/1985	FSG50	AO SMITH	0
3610	06/27/2006	LTN040G	LOCHINVAR	0
3611	10/20/2007	LTN050G	LOCHINVAR	0
3612	01/02/2004	XTN050	LOCHINVAR	0
3613	04/25/2002	FSG50	AO SMITH	1
3614	12/05/2008	LTN050GEF	LOCHINVAR	0
3615	09/11/2000	41XR50	RHEEM	0
3616	12/05/2012	MI50L6FBN	BRADFORD-WHITE	1
3617	12/16/2008	22DV50C	RHEEM	0
3618	04/18/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3619	03/27/1984	FSG50	AO SMITH	0
3620	10/03/2003	G75125	RUUD/RHEEM	0
3621	06/12/2006	LSN041G	LOCHINVAR	0
3622	02/08/2013	MI5036FBN	BRADFORD-WHITE	0
3623	07/07/2009	LTN040GEF	LOCHINVAR	0
3624	08/25/1999	PGR50	AO SMITH	0
3625	03/17/2012	M45036FBN	BRADFORD-WHITE	1
3626	12/08/2009	LTN050GEF	LOCHINVAR	0
3627	07/28/1999	G75125	RUUD/RHEEM	2
3628	06/29/2007	LTN050G	LOCHINVAR	0
3629	08/29/2003	G75125	RUUD/RHEEM	0
3630	09/08/2000	41XR50	RHEEM	1
3631	01/22/2003	FSG50	AO SMITH	0
3632	07/18/2002	FSG30	AO SMITH	0
3633	01/11/2012	M45036FBN	BRADFORD-WHITE	0
3634	04/03/2008	LTN050GEF	LOCHINVAR	0
3635	08/12/2011	MI5036FBN	BRADFORD-WHITE	0
3636	07/03/1997	PGR50	AO SMITH	0
3637	09/04/2002	FSG40	AO SMITH	1
3638	11/01/1993	FSG50	AO SMITH	0
3639	10/07/2010	42VR50	RHEEM	0
3640	01/13/1996	PGR50	AO SMITH	0
3641	05/18/1999	G91200	RUUD/RHEEM	0
3642	03/06/1999	41VR40	RHEEM	0
3643	11/29/1993	21V502	RHEEM	0
3644	04/21/1997	PGR40	AO SMITH	0
3645	05/28/2009	LTN050GEF	LOCHINVAR	0
3646	08/13/2012	MI403S6FBN	BRADFORD-WHITE	0
3647	01/20/2010	LTN050G	LOCHINVAR	0
3648	12/23/2003	G82156	RUUD/RHEEM	0
3649	03/11/1996	PGR50	AO SMITH	0
3650	04/21/2008	LTN040GEF	LOCHINVAR	0
3651	12/03/2004	GVC50	A. O. SMITH	0
3652	04/11/2002	FSG50	AO SMITH	0
3653	01/28/2007	LTN050G	LOCHINVAR	0
3654	09/09/2007	G82156	RUUD/RHEEM	0
3655	05/11/2006	LTN050G	LOCHINVAR	0
3656	05/06/2011	41V50S	RHEEM	0
3657	02/22/2003	FSG50	AO SMITH	0
3658	06/23/2005	LTN050	LOCHINVAR	0
3659	11/18/1986	FSG50	AO SMITH	0
3660	01/28/2012	MI75S6FBN	BRADFORD-WHITE	3
3661	10/10/1985	FSG50	AO SMITH	0
3662	08/02/2012	MI403S6FBN	BRADFORD-WHITE	0
3663	02/11/2005	XVR50	A. O. SMITH	0
3664	06/28/1993	21V502	RHEEM	0
3665	03/01/2011	42VR50	RHEEM	2
3666	10/14/2004	GDVS50	AOSMITH	0
3667	11/19/2009	LTN050GEF	LOCHINVAR	0
3668	10/03/2000	41XR40	RHEEM	0
3669	01/09/2006	LSN041G	LOCHINVAR	0
3670	10/14/2010	42VR50	RHEEM	1
3671	03/10/2004	PRX50	STATE	0
3672	05/22/2000	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3673	07/18/2001	PRX50	STATE	0
3674	11/14/2011	PH2DV50F	RUUD	0
3675	02/12/2003	PRX50	STATE	0
3676	08/29/2005	LTN050GEF	LOCHINVAR	0
3677	01/01/2011	22DV50F	RHEEM	0
3678	02/11/2011	22DV50F	RHEEM	0
3679	12/18/2012	DS150S6FBN	BRADFORD-WHITE	0
3680	03/11/2000	PRV50NODS	STATE	0
3681	06/24/2010	22DV50C	RHEEM	0
3682	10/26/2006	LTN050G	LOCHINVAR	0
3683	09/22/2010	41V50	RHEEM	0
3684	10/17/2007	PR650	STATE	0
3685	02/27/2008	LTN050	LOCHINVAR	1
3686	02/01/2004	FCVL40	AO SMITH	0
3687	12/13/1999	FGR50	AO SMITH	0
3688	06/29/2004	FSG30	AO SMITH	0
3689	08/30/2012	G82156	RUUD/RHEEM	3
3690	10/16/1999	PGR50	AO SMITH	0
3691	06/08/2011	H72DUMMY	AO SMITH	0
3692	09/09/2011	MI5036FBN	BRADFORD-WHITE	1
3693	09/07/2007	LTN050GEF	LOCHINVAR	0
3694	10/12/2006	GVC50	A. O. SMITH	0
3695	05/10/2012	M45036FBN	BRADFORD-WHITE	0
3696	12/05/2007	LTN050GEF	LOCHINVAR	0
3697	01/10/2000	FSG40	AO SMITH	0
3698	08/11/2008	PR640	STATE	0
3699	11/20/2001	41XR40	RHEEM	0
3700	02/15/2011	21VR50	RHEEM	0
3701	11/17/2008	LTN040GEF	LOCHINVAR	1
3702	02/13/2004	FCV40	AO SMITH	0
3703	06/17/2011	MI50L6FBN	BRADFORD-WHITE	0
3704	01/31/2006	LTN050G	LOCHINVAR	0
3705	01/22/2013	G91200	RUUD/RHEEM	0
3706	07/31/2003	FSGL40	AO SMITH	0
3707	11/22/2004	PRX40	STATE	0
3708	10/26/2001	PGR50	AO SMITH	1
3709	04/20/2006	LTN050G	LOCHINVAR	0
3710	07/01/2010	LTN040G	LOCHINVAR	0
3711	01/25/1997	PR502T	RUUD	0
3712	07/26/2007	LTN050GEF	LOCHINVAR	0
3713	09/17/2001	FSG50	AO SMITH	0
3714	05/17/2005	XSN040	LOCHINVAR	0
3715	07/01/2012	G75125	RUUD/RHEEM	1
3716	06/20/2000	FSG50	AO SMITH	0
3717	07/15/2003	FSG50	AO SMITH	0
3718	09/23/2003	FSGL40	AO SMITH	2
3719	06/29/2005	LTN050	LOCHINVAR	2
3720	11/22/2005	LTN050G	LOCHINVAR	0
3721	01/11/2006	LSN041G	LOCHINVAR	0
3722	12/16/2008	LTN050GEF	LOCHINVAR	1
3723	09/15/2006	LTN050G	LOCHINVAR	0
3724	09/10/2004	XTN050	LOCHINVAR	0
3725	12/12/2012	MI5036FBN	BRADFORD-WHITE	0
3726	01/03/2013	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3727	03/22/2004	XTN040	LOCHINVAR	0
3728	10/15/2010	42VR50	RHEEM	0
3729	04/05/2003	FSG40	AO SMITH	0
3730	11/11/2008	LTN050G	LOCHINVAR	0
3731	03/04/2005	GVC40	A. O. SMITH	1
3732	01/11/2005	GVC50	A. O. SMITH	0
3733	06/13/2011	MI5036FBN	BRADFORD-WHITE	0
3734	08/02/2006	LSN041G	LOCHINVAR	0
3735	10/08/2011	M45036FBN	BRADFORD-WHITE	0
3736	08/26/2011	M45036FBN	BRADFORD-WHITE	0
3737	08/10/2009	G82156	RUUD/RHEEM	0
3738	02/02/2010	ETN076	LOCHINVAR	0
3739	02/16/2010	G75125	RUUD/RHEEM	0
3740	05/25/2011	42VR5040F	RHEEM	0
3741	11/11/2007	LTN050GEF	LOCHINVAR	1
3742	04/24/2007	LTN050G	LOCHINVAR	0
3743	10/03/2011	MI5036FBN	BRADFORD-WHITE	0
3744	11/16/1999	21V506	RHEEM	0
3745	07/16/2004	GVC50	A. O. SMITH	0
3746	01/22/2009	LSN041G	LOCHINVAR	0
3747	01/26/2009	LTN050GEF	LOCHINVAR	0
3748	01/02/1986	FSG50	AO SMITH	0
3749	08/27/2007	LTN050G	LOCHINVAR	0
3750	03/25/2009	LTN050GEF	LOCHINVAR	0
3751	06/23/2009	G91200	RUUD/RHEEM	0
3752	02/13/2013	MI5036FBN	BRADFORD-WHITE	0
3753	10/21/2007	LTN050GEF	LOCHINVAR	0
3754	01/28/2013	MI403S6FBN	BRADFORD-WHITE	0
3755	06/28/2000	FSG50	AO SMITH	0
3756	12/21/2009	PR650	STATE	0
3757	02/24/2006	LTN050G	LOCHINVAR	0
3758	11/24/2012	DS150S6FBN	BRADFORD-WHITE	0
3759	10/22/2001	PGR50	AO SMITH	0
3760	04/26/2007	LTN050G	LOCHINVAR	1
3761	04/30/1986	FSGL40	AO SMITH	2
3762	06/30/2009	LTN050GEF	LOCHINVAR	0
3763	04/06/2006	LTN050G	LOCHINVAR	0
3764	10/17/2005	LTN050G	LOCHINVAR	0
3765	03/06/2013	M45036FBN	BRADFORD-WHITE	0
3766	11/01/2004	RM5063	RUUD	2
3767	11/17/2009	LTN040GEF	LOCHINVAR	0
3768	06/30/2008	LTN050GEF	LOCHINVAR	0
3769	04/16/2007	LTN050G	LOCHINVAR	0
3770	01/24/2013	M45036FBN	BRADFORD-WHITE	0
3771	08/28/2004	GVC30	AOSMITH	0
3772	01/15/2008	LTN050GEF	LOCHINVAR	1
3773	08/09/2004	FSGL40	AO SMITH	0
3774	04/11/2000	PR640	STATE	0
3775	11/07/2003	FCV40	AO SMITH	0
3776	02/21/2008	PR640	STATE	1
3777	09/22/2002	FSG50	AO SMITH	0
3778	03/03/2000	PR650	STATE	0
3779	11/05/2007	LTN050GEF	LOCHINVAR	0
3780	05/05/2005	LTN050G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3781	12/07/2011	M45036FBN	BRADFORD-WHITE	1
3782	05/29/2007	LTN050GEF	LOCHINVAR	0
3783	05/12/2012	M45036FBN	BRADFORD-WHITE	0
3784	06/08/2002	FSG40	AO SMITH	0
3785	12/16/2011	P506	RUUD	0
3786	02/13/2013	PH2DV50F	RUUD	0
3787	08/03/2005	PR650	STATE	0
3788	03/01/2005	GVC40	A. O. SMITH	0
3789	12/12/2005	PR650	STATE	0
3790	09/20/2010	21VR50	RHEEM	0
3791	05/04/2001	FSG50	AO SMITH	0
3792	05/04/2007	LTN050GEF	LOCHINVAR	0
3793	02/13/2002	PGR50	AO SMITH	0
3794	11/16/2008	LTN050GEF	LOCHINVAR	0
3795	07/02/2004	XVR50	A. O. SMITH	1
3796	11/05/2011	M45036FBN	BRADFORD-WHITE	0
3797	07/16/2005	PR650	STATE	0
3798	11/03/2006	LTN050G	LOCHINVAR	0
3799	03/14/2007	LTN040G	LOCHINVAR	0
3800	11/20/2006	LTN051G	LOCHINVAR	0
3801	02/14/2002	FSG40	AO SMITH	0
3802	06/13/2008	LTN050GEF	LOCHINVAR	0
3803	02/11/2011	22DV50F	RHEEM	0
3804	07/24/2003	FSG50	AO SMITH	0
3805	08/16/1996	PGR50	AO SMITH	0
3806	09/23/2011	M45036FBN	BRADFORD-WHITE	0
3807	06/10/2003	FDV50	AO SMITH	0
3808	05/04/2011	41VR50	RHEEM	0
3809	07/29/2010	LTN050GEF	LOCHINVAR	0
3810	03/21/2007	LTN050G	LOCHINVAR	1
3811	12/14/2005	LTN050G	LOCHINVAR	0
3812	12/08/2008	LTN050GEF	LOCHINVAR	0
3813	11/08/2001	PRX50	STATE	1
3814	05/17/2007	LTN050G	LOCHINVAR	0
3815	03/02/2010	LTN050GEF	LOCHINVAR	0
3816	04/11/2006	FSG50	AO SMITH	1
3817	06/14/2006	PR650	STATE	0
3818	08/19/2004	XSN040	LOCHINVAR	0
3819	06/28/2012	MI50L6FBN	BRADFORD-WHITE	0
3820	09/13/2011	MI5036FBN	BRADFORD-WHITE	0
3821	01/05/2006	LTN050G	LOCHINVAR	0
3822	07/16/2012	M45036FBN	BRADFORD-WHITE	1
3823	06/02/1987	PRV30	STATE	0
3824	02/24/2009	LTN050G	LOCHINVAR	0
3825	02/08/2008	LTN050GEF	LOCHINVAR	0
3826	08/29/2009	G76200	RUUD/RHEEM	0
3827	04/16/2010	LTN050GEF	LOCHINVAR	0
3828	11/26/2012	G75125	RUUD/RHEEM	0
3829	12/22/2000	PRX50	STATE	0
3830	05/21/1997	P506	RUUD	0
3831	07/07/1983	FSG50	AO SMITH	0
3832	02/01/2011	42VR5040F	RHEEM	0
3833	12/02/2008	LTN050GEF	LOCHINVAR	0
3834	07/18/2003	FSG40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3835	02/03/2005	FSG50	AO SMITH	0
3836	12/04/2006	LTN050G	LOCHINVAR	1
3837	04/30/2003	PGR50	AO SMITH	0
3838	11/16/2006	LTN050G	LOCHINVAR	0
3839	09/29/2011	LTN050G	LOCHINVAR	0
3840	02/09/2000	FSGL40	AO SMITH	0
3841	09/19/1998	G82156	RUUD/RHEEM	1
3842	05/28/2001	41V40S	RHEEM	0
3843	12/20/1984	FSG50	AO SMITH	0
3844	01/29/2007	LTN050G	LOCHINVAR	0
3845	10/04/2008	LTN050GEF	LOCHINVAR	0
3846	06/01/2012	MI40T6FBN	BRADFORD-WHITE	0
3847	03/27/2007	XSN040	LOCHINVAR	1
3848	11/04/2001	PGR40	AO SMITH	0
3849	11/29/2001	FSG50	AO SMITH	0
3850	07/22/2001	41V50	RHEEM	0
3851	02/06/2007	LTN050G	LOCHINVAR	0
3852	03/02/2006	LTN050G	LOCHINVAR	1
3853	11/23/2002	PGR50	AO SMITH	0
3854	05/21/2002	FSGL40	AO SMITH	0
3855	08/12/2006	LTN040G	LOCHINVAR	1
3856	08/27/2001	FSG50	AO SMITH	0
3857	02/25/2009	PH199119	PHOENIX	1
3858	02/11/2009	LTN050GEF	LOCHINVAR	0
3859	12/30/1998	21V506	RHEEM	0
3860	05/12/2001	41V50	RHEEM	0
3861	01/08/1992	P502	RUUD	0
3862	01/17/2011	42VR50	RHEEM	2
3863	03/09/2007	GVC40	A. O. SMITH	0
3864	02/21/2012	MI40T6FBN	BRADFORD-WHITE	0
3865	03/29/1984	KGA50	AO SMITH	0
3866	11/07/2010	21VR40	RHEEM	0
3867	08/05/2009	LTN050GEF	LOCHINVAR	0
3868	05/10/1999	FSGL40	AO SMITH	0
3869	01/13/2004	PVR50	AO SMITH	1
3870	08/21/2008	LTN050GEF	LOCHINVAR	4
3871	01/07/2008	LTN050GEF	LOCHINVAR	0
3872	01/02/2004	FCV50	AO SMITH	0
3873	12/07/2012	M440T6FBN	BRADFORD-WHITE	0
3874	02/23/2001	FSG50	AO SMITH	0
3875	10/20/2009	LTN050G	LOCHINVAR	0
3876	11/07/2012	G91200	RUUD/RHEEM	1
3877	01/08/2010	LTN050GEF	LOCHINVAR	1
3878	01/16/2008	LTN050G	LOCHINVAR	0
3879	05/31/2006	LTN050G	LOCHINVAR	0
3880	03/30/2004	GVC50	A. O. SMITH	0
3881	03/16/2011	41VR50	RHEEM	0
3882	01/26/2011	LTN040G	LOCHINVAR	0
3883	02/22/2005	LTN050	LOCHINVAR	0
3884	02/26/2008	LTN050GEF	LOCHINVAR	1
3885	05/19/2010	LSN041G	LOCHINVAR	0
3886	08/02/2011	M45036FBN	BRADFORD-WHITE	2
3887	07/26/2001	FSG50	AO SMITH	0
3888	01/05/2010	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3889	03/06/2008	LTN050GEF	LOCHINVAR	0
3890	05/27/2003	PGR50	AO SMITH	0
3891	07/26/2012	DS150S6FBN	BRADFORD-WHITE	3
3892	02/09/2013	M45036FBN	BRADFORD-WHITE	0
3893	07/21/2012	M45036FBN	BRADFORD-WHITE	0
3894	01/31/2009	22DV50F	RHEEM	0
3895	06/12/2011	22DV50F	RHEEM	0
3896	02/22/2012	M440T6FBN	BRADFORD-WHITE	0
3897	03/26/2011	41VR50	RHEEM	0
3898	04/17/2012	M45036FBN	BRADFORD-WHITE	0
3899	10/19/2001	FSG50	AO SMITH	2
3900	08/24/2009	LTN050GEF	LOCHINVAR	0
3901	09/10/2007	PR650	STATE	0
3902	02/07/2007	LTN040G	LOCHINVAR	0
3903	05/11/2012	M45036FBN	BRADFORD-WHITE	0
3904	11/27/1998	BTC197	AO SMITH	0
3905	01/11/2013	M45036FBN	BRADFORD-WHITE	0
3906	12/24/2002	FSG50	AO SMITH	0
3907	01/23/2009	LTN050GEF	LOCHINVAR	0
3908	12/01/1999	FGR50	AO SMITH	0
3909	02/24/2011	42VR50	RHEEM	0
3910	08/28/2001	FSG50	AO SMITH	0
3911	11/01/1999	FSG40	AO SMITH	0
3912	12/20/2002	PGR50	AO SMITH	0
3913	02/26/1994	E71DUMMY	AO SMITH	0
3914	04/04/2006	LTN050G	LOCHINVAR	0
3915	10/11/2006	LTN050G	LOCHINVAR	0
3916	04/13/2006	LSN041	LOCHINVAR	2
3917	09/27/1982	21V502	RHEEM	0
3918	09/16/2005	LTN040	LOCHINVAR	0
3919	03/29/1984	KGA50	AO SMITH	0
3920	01/03/2004	PGR40	AO SMITH	0
3921	01/27/2006	LTN050G	LOCHINVAR	1
3922	11/17/1998	FSGL40	AO SMITH	0
3923	12/17/1984	RM5063	RUUD	0
3924	02/21/2002	FSG50	AO SMITH	0
3925	07/13/2009	LTN050G	LOCHINVAR	0
3926	10/27/1995	PHR50	RUUD	0
3927	05/05/2003	FSG50	AO SMITH	0
3928	03/20/2002	PGR50	AO SMITH	0
3929	12/06/2010	42VR50	RHEEM	0
3930	06/06/2001	PRX50	STATE	0
3931	01/31/2003	FSG40	AO SMITH	1
3932	06/07/2011	42VR50	RHEEM	0
3933	08/01/1997	PGR40	AO SMITH	0
3934	03/29/1997	FGR40	AO SMITH	1
3935	09/16/2005	LTN040GEF	LOCHINVAR	0
3936	04/27/2009	LTN050GEF	LOCHINVAR	0
3937	03/03/2003	PGR50	AO SMITH	0
3938	08/04/2002	41XR50	RHEEM	0
3939	07/30/2009	LSN041G	LOCHINVAR	0
3940	07/12/2010	LTN050GEF	LOCHINVAR	0
3941	09/06/2012	MI5036FBN	BRADFORD-WHITE	0
3942	01/03/1997	H72DUMMY	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3943	11/13/2001	FSG50	AO SMITH	0
3944	12/07/2007	LTN040G	LOCHINVAR	0
3945	11/26/2007	ETN076	LOCHINVAR	0
3946	09/13/1996	FGR50	AO SMITH	1
3947	08/01/2008	PH199119	PHOENIX	2
3948	01/08/2008	LSN041G	LOCHINVAR	1
3949	03/14/2012	MI40T6FBN	BRADFORD-WHITE	0
3950	03/13/2009	21VR40	RHEEM	0
3951	08/25/2008	G82156	RUUD/RHEEM	0
3952	09/08/2008	LTN040G	LOCHINVAR	2
3953	01/25/2012	MI403S6FBN	BRADFORD-WHITE	0
3954	11/29/2007	PRX50	STATE	0
3955	06/17/1987	FSG50	AO SMITH	0
3956	01/29/2013	MI5036FBN	BRADFORD-WHITE	0
3957	08/06/2011	M45036FBN	BRADFORD-WHITE	1
3958	06/24/2004	XVR50	A. O. SMITH	0
3959	05/06/2000	41VR40	RHEEM	0
3960	09/15/2003	PRX50	STATE	0
3961	07/28/2005	LTN050	LOCHINVAR	0
3962	02/21/2008	PR650	STATE	0
3963	12/20/2005	LTN050GEF	LOCHINVAR	0
3964	11/18/1986	FSG50	AO SMITH	0
3965	05/17/2000	41XR50	RHEEM	0
3966	06/08/1999	G75125	RUUD/RHEEM	0
3967	06/29/2011	22DV50F	RHEEM	0
3968	07/14/2008	LTN050GEF	LOCHINVAR	0
3969	10/20/2009	LTN050GEF	LOCHINVAR	0
3970	12/04/2009	G91200	RUUD/RHEEM	0
3971	05/07/2004	PVR50	AO SMITH	0
3972	11/24/1996	FSG50	AO SMITH	0
3973	09/28/2004	LTN050G	LOCHINVAR	0
3974	12/11/2003	PVR50	AO SMITH	0
3975	11/29/2001	PRX50	STATE	0
3976	04/20/2011	21VR40	RHEEM	0
3977	02/28/2006	ETN076	LOCHINVAR	0
3978	09/09/2009	LTN050GEF	LOCHINVAR	0
3979	11/18/2003	41XR50	RHEEM	0
3980	12/31/2009	LTN050GEF	LOCHINVAR	1
3981	01/29/2007	LTN040GEF	LOCHINVAR	0
3982	05/01/1987	FSG50	AO SMITH	0
3983	02/23/2001	PRX50	STATE	1
3984	11/09/2005	LTN040G	LOCHINVAR	1
3985	12/02/2011	MI5036FBN	BRADFORD-WHITE	0
3986	09/20/2010	21VR50	RHEEM	0
3987	11/29/2005	LTN050G	LOCHINVAR	0
3988	02/25/2011	21VR50	RHEEM	0
3989	04/20/2011	22DV50F	RHEEM	0
3990	10/06/2000	41V40S	RHEEM	0
3991	09/25/1986	FSG50	AO SMITH	0
3992	02/02/2013	MI5036FBN	BRADFORD-WHITE	0
3993	06/04/2001	41XR50	RHEEM	0
3994	04/25/1998	FSGL40	AO SMITH	0
3995	08/18/2009	LTN050GEF	LOCHINVAR	3
3996	09/26/2006	ETN076	LOCHINVAR	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
3997	01/04/2008	LTN050G	LOCHINVAR	0
3998	11/24/2008	LTN050GEF	LOCHINVAR	0
3999	03/06/2010	LTN050GEF	LOCHINVAR	0
4000	06/28/2011	G91200	RUUD/RHEEM	0
4001	05/16/2002	BTR154	AO SMITH	0
4002	07/29/1997	FGR50	AO SMITH	0
4003	08/16/1998	FGR50	AO SMITH	0
4004	02/06/2013	M45036FBN	BRADFORD-WHITE	0
4005	11/11/1985	FSG50	AO SMITH	0
4006	04/30/2003	FSG50	AO SMITH	0
4007	12/29/2003	PRX50	STATE	0
4008	06/05/2010	LTN050GEF	LOCHINVAR	0
4009	04/29/2010	LTN050GEF	LOCHINVAR	0
4010	02/03/2006	LTN050G	LOCHINVAR	0
4011	06/26/2002	FSG30	AO SMITH	0
4012	12/06/2006	LTN050G	LOCHINVAR	1
4013	09/20/2007	LTN050GEF	LOCHINVAR	1
4014	02/09/2000	41V50	RHEEM	0
4015	07/16/2003	FSG50	AO SMITH	1
4016	08/11/2001	PGR50	AO SMITH	0
4017	04/25/2005	LTN050	LOCHINVAR	0
4018	10/10/2002	PRX50	STATE	0
4019	11/13/2002	FSGL40	AO SMITH	0
4020	09/28/2012	G82156	RUUD/RHEEM	1
4021	08/21/2007	LTN050GEF	LOCHINVAR	0
4022	11/16/2010	42VR50	RHEEM	0
4023	03/30/2000	FSG30	AO SMITH	0
4024	01/06/2009	LTN050GEF	LOCHINVAR	0
4025	06/14/2011	M45036FBN	BRADFORD-WHITE	0
4026	06/23/2006	LTN050G	LOCHINVAR	0
4027	01/14/1997	PGR50	AO SMITH	0
4028	02/10/2005	GVC50	A. O. SMITH	1
4029	08/20/1985	G91200	RUUD/RHEEM	0
4030	07/16/2010	LTN050GEF	LOCHINVAR	0
4031	11/11/2011	M45036FBN	BRADFORD-WHITE	0
4032	02/20/2009	LTN050G	LOCHINVAR	0
4033	03/09/2007	LTN050G	LOCHINVAR	0
4034	09/15/2003	FSG50	AO SMITH	0
4035	11/09/2012	M45036FBN	BRADFORD-WHITE	0
4036	04/26/2005	LTN050	LOCHINVAR	0
4037	06/05/2008	LTN050GEF	LOCHINVAR	1
4038	08/20/1996	PGR50	AO SMITH	0
4039	10/16/1998	PGR50	AO SMITH	0
4040	12/05/2011	PH250SF	RUUD	0
4041	01/06/2010	G75125	RUUD/RHEEM	0
4042	11/26/2007	LTN040G	LOCHINVAR	0
4043	04/05/2002	PGR50	AO SMITH	0
4044	03/24/2005	XVR50	A. O. SMITH	0
4045	11/03/2000	FSG50	AO SMITH	0
4046	11/10/2004	GVC50	A. O. SMITH	1
4047	02/27/1987	FSG50	AO SMITH	0
4048	01/20/2003	FSG50	AO SMITH	0
4049	11/10/1986	FSG50	AO SMITH	0
4050	03/26/2002	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4051	10/09/2002	21V506	RHEEM	0
4052	01/30/2012	M45036FBN	BRADFORD-WHITE	1
4053	11/19/2009	LTN050GEF	LOCHINVAR	0
4054	08/04/2008	LTN050G	LOCHINVAR	0
4055	12/30/2006	LTN050G	LOCHINVAR	0
4056	11/19/2008	LTN050GEF	LOCHINVAR	2
4057	03/03/1998	FGR50	AO SMITH	0
4058	01/06/2001	41XR50	RHEEM	0
4059	04/27/2007	LTN050G	LOCHINVAR	0
4060	02/04/2008	21DV50	RHEEM	2
4061	01/29/2003	FSG50	AO SMITH	0
4062	10/09/2009	LTN050GEF	LOCHINVAR	0
4063	01/27/2012	MI5036FBN	BRADFORD-WHITE	0
4064	02/07/2008	LTN050GEF	LOCHINVAR	0
4065	10/18/2011	M45036FBN	BRADFORD-WHITE	0
4066	04/15/1987	FSG50	AO SMITH	0
4067	07/13/2010	LTN050	LOCHINVAR	1
4068	08/14/2001	PGR50	AO SMITH	0
4069	05/29/2003	PGR50	AO SMITH	0
4070	03/27/2009	LTN050GEF	LOCHINVAR	1
4071	04/07/2010	22DV50C	RHEEM	0
4072	08/10/2009	42XR50	RHEEM	0
4073	04/04/2011	42VR50	RHEEM	1
4074	07/31/2008	LTN050GEF	LOCHINVAR	0
4075	07/19/1995	FGR50	AO SMITH	0
4076	08/23/1999	FGR50	AO SMITH	0
4077	01/12/2011	42VR50	RHEEM	0
4078	05/11/1999	FGR50	AO SMITH	0
4079	12/17/2010	22DV50F	RHEEM	0
4080	03/02/2010	LTN050GEF	LOCHINVAR	0
4081	12/20/1986	FSG50	AO SMITH	1
4082	11/13/2007	PR650	STATE	0
4083	08/08/1995	PR502T	RUUD	0
4084	11/28/2012	MI5036FBN	BRADFORD-WHITE	0
4085	11/10/2008	22DV50C	RHEEM	0
4086	02/15/2006	PR640	STATE	0
4087	12/04/2007	PRV50NODS	STATE	0
4088	03/21/2007	PR650	STATE	0
4089	06/18/1987	PRX50	STATE	0
4090	06/16/2003	FSG50	AO SMITH	0
4091	03/27/2011	21VR40	RHEEM	0
4092	01/13/2006	LTN050G	LOCHINVAR	0
4093	01/01/2009	22DV50F	RHEEM	0
4094	10/17/2003	PGR50	AO SMITH	0
4095	10/19/2005	LTN050G	LOCHINVAR	0
4096	04/29/1986	FSG50	AO SMITH	0
4097	06/23/2008	LTN050GEF	LOCHINVAR	0
4098	07/03/2006	LTN040G	LOCHINVAR	0
4099	03/20/2002	PGR50	AO SMITH	0
4100	05/23/2007	LTN050G	LOCHINVAR	0
4101	01/16/2006	LTN050GEF	LOCHINVAR	1
4102	03/08/1986	FSG50	AO SMITH	0
4103	02/20/2012	MI5036FBN	BRADFORD-WHITE	0
4104	06/27/2005	PR650	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4105	04/08/2005	SBF100199NES	STATE	1
4106	11/23/2005	FSGL40	AO SMITH	0
4107	12/30/2010	42VR50	RHEEM	0
4108	12/17/1985	FSGL40	AO SMITH	0
4109	03/20/1986	FSG50	AO SMITH	0
4110	01/18/2009	LTN050GEF	LOCHINVAR	0
4111	08/03/2007	LTN050GEF	LOCHINVAR	1
4112	02/28/2008	LTN050	LOCHINVAR	0
4113	11/10/2005	FGR50	AO SMITH	0
4114	08/18/2007	LTN040GEF	LOCHINVAR	0
4115	09/28/1999	FSG50	AO SMITH	0
4116	10/11/2010	41VR50	RHEEM	0
4117	03/24/2004	XTN050	LOCHINVAR	0
4118	06/15/2007	LTN050G	LOCHINVAR	0
4119	09/20/2010	42VR50	RHEEM	0
4120	12/24/2009	LTN050G	LOCHINVAR	0
4121	06/29/2007	LTN050	LOCHINVAR	0
4122	06/11/1997	G76200	RUUD/RHEEM	0
4123	05/15/2009	LTN040GEF	LOCHINVAR	1
4124	08/09/2007	LTN050G	LOCHINVAR	0
4125	06/12/2010	LTN050G	LOCHINVAR	0
4126	04/11/2011	21VR40	RHEEM	0
4127	02/26/1996	G76200	RUUD/RHEEM	0
4128	02/25/2004	PVR50	AO SMITH	0
4129	09/11/2003	PGR50	AO SMITH	1
4130	05/15/1996	BTC197	AO SMITH	0
4131	12/09/2009	LTN040G	LOCHINVAR	0
4132	11/08/2003	PVR50	AO SMITH	0
4133	08/11/2005	LTN050GEF	LOCHINVAR	0
4134	10/09/2008	LTN050GEF	LOCHINVAR	0
4135	05/24/2002	PGR50	AO SMITH	1
4136	07/20/2010	LTN050G	LOCHINVAR	0
4137	11/08/2002	FSG50	AO SMITH	0
4138	09/27/2001	FSG50	AO SMITH	0
4139	11/01/2012	FGR50	AO SMITH	0
4140	09/09/2010	LTN050GEF	LOCHINVAR	0
4141	09/22/2010	42VR50	RHEEM	0
4142	01/02/2008	LTN040G	LOCHINVAR	0
4143	12/12/2005	LTN050G	LOCHINVAR	0
4144	01/14/2003	G75125	RUUD/RHEEM	0
4145	11/09/2001	FSG40	AO SMITH	0
4146	08/21/2003	FCV50	AO SMITH	0
4147	03/05/2012	MI5036FBN	BRADFORD-WHITE	0
4148	11/25/2011	M45036FBN	BRADFORD-WHITE	0
4149	11/28/2005	LTN040GEF	LOCHINVAR	0
4150	07/20/2010	LTN050G	LOCHINVAR	0
4151	02/06/2010	LTN040GEF	LOCHINVAR	1
4152	06/03/2009	22DV50C	RHEEM	0
4153	02/01/1973	PGX50	AO SMITH	0
4154	08/29/2012	FGR50	AO SMITH	0
4155	04/10/2007	LTN050G	LOCHINVAR	1
4156	09/22/2002	PGR50	AO SMITH	0
4157	11/30/2006	LTN050G	LOCHINVAR	0
4158	09/13/2000	41XR40	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4159	09/12/2001	PGR50	AO SMITH	0
4160	09/11/2003	FSG50	AO SMITH	0
4161	10/11/2010	LTN040G	LOCHINVAR	0
4162	09/23/2008	LTN050GEF	LOCHINVAR	0
4163	10/26/2008	LTN040GEF	LOCHINVAR	0
4164	06/18/2008	PH199119	PHOENIX	0
4165	05/16/2007	LTN050G	LOCHINVAR	0
4166	05/14/2003	21V506	RHEEM	0
4167	04/26/2002	PGR50	AO SMITH	0
4168	02/21/2012	MI403S6FBN	BRADFORD-WHITE	0
4169	07/15/2009	22DV50C	RHEEM	1
4170	10/24/2012	M45036FBN	BRADFORD-WHITE	0
4171	09/14/2009	21V502	RHEEM	0
4172	01/23/2012	MI40T6FBN	BRADFORD-WHITE	0
4173	07/05/2012	M45036FBN	BRADFORD-WHITE	0
4174	12/20/1985	FSG50	AO SMITH	0
4175	02/06/2005	XTN050	LOCHINVAR	0
4176	04/12/2011	22DV50F	RHEEM	0
4177	10/29/2004	PRX50	STATE	0
4178	02/01/2012	G91200	RUUD/RHEEM	4
4179	04/27/2009	LTN050GEF	LOCHINVAR	0
4180	03/08/1999	FGR50	AO SMITH	0
4181	10/12/2012	M45036FBN	BRADFORD-WHITE	0
4182	02/21/2011	42VR50	RHEEM	0
4183	07/13/2002	FSG50	AO SMITH	0
4184	11/13/2007	LTN040G	LOCHINVAR	0
4185	12/11/2008	LTN050GEF	LOCHINVAR	0
4186	09/13/2006	LTN050GEF	LOCHINVAR	0
4187	03/04/1998	FGR50	AO SMITH	0
4188	02/02/2007	LTN050G	LOCHINVAR	0
4189	09/08/1999	PGR50	AO SMITH	0
4190	01/08/2001	21V407	RHEEM	0
4191	01/08/2002	FSG50	AO SMITH	0
4192	09/15/2006	LTN050G	LOCHINVAR	0
4193	11/25/2002	FSG50	AO SMITH	0
4194	09/22/1999	PR650	STATE	0
4195	06/13/1994	FGR50	AO SMITH	0
4196	08/29/2005	PR650	STATE	0
4197	12/17/2009	LTN050GEF	LOCHINVAR	0
4198	03/10/2007	LTN050G	LOCHINVAR	0
4199	08/31/2010	41V50	RHEEM	0
4200	11/30/2011	MI5036FBN	BRADFORD-WHITE	0
4201	12/18/1985	FSG50	AO SMITH	0
4202	03/22/2005	GVC50	A. O. SMITH	0
4203	03/13/2013	MI5036FBN	Bradford - White	1
4204	07/16/2012	M45036FBN	BRADFORD-WHITE	1
4205	02/25/1986	FSG50	AO SMITH	0
4206	05/14/1985	FSG50	AO SMITH	0
4207	07/21/2012	M45036FBN	BRADFORD-WHITE	0
4208	05/24/2001	41XR50	RHEEM	0
4209	07/19/2000	41XR50	RHEEM	0
4210	11/05/2010	42VR50	RHEEM	0
4211	08/29/1997	FSG50	AO SMITH	1
4212	04/10/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4213	06/25/1999	FGR50	AO SMITH	0
4214	07/25/2012	MI5036FBN	BRADFORD-WHITE	1
4215	05/19/2006	PR650	STATE	0
4216	03/23/2012	M45036FBN	BRADFORD-WHITE	2
4217	07/13/2011	42VR50	RHEEM	0
4218	11/21/2012	MI5036FBN	BRADFORD-WHITE	0
4219	08/17/2007	LTN050GEF	LOCHINVAR	1
4220	11/22/2011	MI5036FBN	BRADFORD-WHITE	0
4221	10/01/2001	FSG50	AO SMITH	0
4222	08/09/2012	PH2DV50F	RUUD	0
4223	02/29/2008	LTN050GEF	LOCHINVAR	0
4224	07/30/2003	PRX50	STATE	0
4225	10/13/2006	LTN050G	LOCHINVAR	0
4226	10/04/2006	LTN050GEF	LOCHINVAR	0
4227	09/07/2010	22DV50C	RHEEM	0
4228	07/06/2009	LTN050GEF	LOCHINVAR	1
4229	12/24/2007	PR650X0DS	STATE	0
4230	11/03/2005	LTN050G	LOCHINVAR	1
4231	10/13/2000	FSG50	AO SMITH	0
4232	01/18/1999	PR650	STATE	0
4233	10/21/2002	PRX50	STATE	0
4234	09/30/2011	MI5036FBN	BRADFORD-WHITE	0
4235	05/17/2011	41VR50	RHEEM	0
4236	02/05/2010	LTN050GEF	LOCHINVAR	0
4237	03/16/2007	LTN050G	LOCHINVAR	0
4238	03/04/2005	PRX50	STATE	1
4239	06/28/2008	LTN050GEF	LOCHINVAR	0
4240	09/02/2008	LTN050GEF	LOCHINVAR	0
4241	01/26/2005	GVR50	AO SMITH	0
4242	04/19/2006	LTN050G	LOCHINVAR	0
4243	06/14/2007	LTN050GEF	LOCHINVAR	1
4244	09/30/2008	22DV50C	RHEEM	0
4245	05/12/2004	GVC50	A. O. SMITH	1
4246	06/22/2006	LTN050G	LOCHINVAR	0
4247	08/28/1997	FSG50	AO SMITH	0
4248	07/12/1995	PR502T	RUUD	0
4249	06/30/2007	LTN050G	LOCHINVAR	0
4250	02/07/2002	PGR50	AO SMITH	0
4251	07/29/1987	PRV50NODS	STATE	0
4252	11/24/2004	GVC50	A. O. SMITH	0
4253	03/24/1987	FSG50	AO SMITH	0
4254	05/11/2007	LTN040G	LOCHINVAR	0
4255	12/09/2010	G91200	RUUD/RHEEM	0
4256	09/24/2009	G82156	RUUD/RHEEM	0
4257	06/18/2008	PH199119	PHOENIX	0
4258	01/13/1984	FSG50	AO SMITH	0
4259	07/06/2002	PGR40	AO SMITH	0
4260	01/24/2000	PGR50	AO SMITH	0
4261	06/10/1999	FSG50	AO SMITH	0
4262	03/23/2005	GVC50	A. O. SMITH	0
4263	08/23/2011	M45036FBN	BRADFORD-WHITE	1
4264	02/06/2008	LTN050GEF	LOCHINVAR	2
4265	09/10/1998	21V506	RHEEM	0
4266	02/21/2003	FSGL40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4267	03/20/2001	FSG50	AO SMITH	0
4268	03/02/2011	21VR50	RHEEM	1
4269	06/03/1993	21V506	RHEEM	0
4270	07/19/2005	LTN050	LOCHINVAR	0
4271	02/01/1983	FSG50	AO SMITH	0
4272	11/01/1995	PGR50	AO SMITH	0
4273	06/30/2005	LTN040	LOCHINVAR	0
4274	08/19/2002	FSG40	AO SMITH	0
4275	10/26/2004	LTN050	LOCHINVAR	0
4276	03/23/2001	BTR154	AO SMITH	0
4277	07/25/2002	PGR50	AO SMITH	0
4278	08/13/2012	MI40T6FBN	BRADFORD-WHITE	1
4279	03/08/2000	FGR50	AO SMITH	0
4280	02/14/2008	LSN041G	LOCHINVAR	0
4281	09/06/2000	FSG40	AO SMITH	0
4282	05/12/2011	41VR50	RHEEM	1
4283	10/05/1999	FSG40	AO SMITH	0
4284	05/14/2011	21VR50	RHEEM	0
4285	04/20/2012	M45036FBN	BRADFORD-WHITE	3
4286	04/13/1999	FSG50	AO SMITH	0
4287	01/28/2013	M45036FBN	BRADFORD-WHITE	1
4288	06/30/2008	LTN050GEF	LOCHINVAR	0
4289	12/18/1997	FSGL40	AO SMITH	0
4290	10/30/2008	LTN050G	LOCHINVAR	2
4291	07/11/2000	P40S	RUUD	0
4292	12/09/2001	FSG50	AO SMITH	0
4293	11/20/1995	FSG50	AO SMITH	0
4294	09/25/2009	LTN040G	LOCHINVAR	1
4295	06/23/2010	LSN041G	LOCHINVAR	0
4296	09/22/2008	G75125	RUUD/RHEEM	0
4297	12/04/2004	LTN050G	LOCHINVAR	0
4298	05/28/2008	LTN050GEF	LOCHINVAR	0
4299	12/23/2009	LTN050GEF	LOCHINVAR	0
4300	12/28/2006	FSG50	AO SMITH	0
4301	01/23/2013	MI403S6FBN	BRADFORD-WHITE	0
4302	01/27/2012	M440T6FBN	BRADFORD-WHITE	0
4303	01/30/2002	FSG50	AO SMITH	0
4304	01/26/1996	PRX50	STATE	0
4305	09/15/2011	M45036FBN	BRADFORD-WHITE	0
4306	08/15/1999	FSG40	AO SMITH	0
4307	05/06/2011	41VR50	RHEEM	1
4308	12/02/2010	42VR50	RHEEM	0
4309	01/27/2000	41XR40	RHEEM	0
4310	05/13/2002	PGR50	AO SMITH	0
4311	11/03/2008	LTN040GEF	LOCHINVAR	0
4312	06/11/1986	FSG50	AO SMITH	0
4313	07/16/2011	MI40T6FBN	BRADFORD-WHITE	0
4314	03/05/2010	LTN050GEF	LOCHINVAR	1
4315	03/10/2005	GVC50	A. O. SMITH	1
4316	01/28/2013	MI5036FBN	BRADFORD-WHITE	0
4317	06/16/2010	LTN050GEF	LOCHINVAR	0
4318	11/22/2008	LTN050GEF	LOCHINVAR	1
4319	04/09/1999	FGR50	AO SMITH	0
4320	07/10/2008	22DV50F	Rheem	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4321	04/05/2007	LTN050G	LOCHINVAR	0
4322	08/04/2009	LTN050GEF	LOCHINVAR	0
4323	08/08/2000	PGR50	AO SMITH	0
4324	02/25/2005	GCVL40	A. O. SMITH	0
4325	12/21/2004	H72DUMMY	AO SMITH	0
4326	09/29/2003	PGR50	AO SMITH	1
4327	12/30/2006	PR650	STATE	0
4328	08/07/2008	LTN050GEF	LOCHINVAR	2
4329	03/26/2012	M45036FBN	BRADFORD-WHITE	0
4330	03/10/1986	FSG50	AO SMITH	0
4331	02/09/1997	FGR50	AO SMITH	0
4332	03/09/2008	LTN050GEF	LOCHINVAR	0
4333	06/07/2002	PGR50	AO SMITH	0
4334	11/07/2004	XVR50	A. O. SMITH	0
4335	01/23/2006	GVC50	A. O. SMITH	0
4336	02/26/2010	LTN050GEF	LOCHINVAR	1
4337	08/19/2003	PGR50	AO SMITH	0
4338	10/24/1997	FSG50	AO SMITH	0
4339	12/29/2001	FSG50	AO SMITH	0
4340	01/08/2011	42VR50	RHEEM	0
4341	04/13/1987	FSG50	AO SMITH	0
4342	09/06/2012	MI5036FBN	BRADFORD-WHITE	1
4343	09/16/2009	LTN050GEF	LOCHINVAR	0
4344	05/13/2009	LTN050G	LOCHINVAR	0
4345	06/19/2006	PRV40NODS	STATE	0
4346	11/05/2004	GVC50	A. O. SMITH	0
4347	03/11/1999	FSG30	AO SMITH	0
4348	09/02/2002	PRX40	STATE	0
4349	10/10/2003	FSG50	AO SMITH	1
4350	12/21/2012	M45036FBN	BRADFORD-WHITE	0
4351	04/22/1987	FSG50	AO SMITH	0
4352	07/14/2003	PRX50	STATE	0
4353	01/05/2011	42VR50	RHEEM	0
4354	05/25/2005	LTN050G	LOCHINVAR	0
4355	08/17/2001	G75125	RUUD/RHEEM	0
4356	08/24/2010	LTN050GEF	LOCHINVAR	0
4357	10/04/2001	PGR50	AO SMITH	0
4358	04/07/2009	LTN050G	LOCHINVAR	0
4359	04/24/2002	PGR50	AO SMITH	3
4360	04/21/2012	M45036FBN	BRADFORD-WHITE	0
4361	07/14/2000	BTR154	AO SMITH	0
4362	12/09/2011	FSG50	AO SMITH	0
4363	12/15/1986	BTR199	AO SMITH	0
4364	12/12/2012	M45036FBN	BRADFORD-WHITE	0
4365	09/14/1987	E71DUMMY	AO SMITH	0
4366	05/12/2010	21V506	RHEEM	0
4367	01/31/2011	42VR50	RHEEM	0
4368	11/21/1999	41VR50	RHEEM	0
4369	11/26/2004	GCVL40	A. O. SMITH	0
4370	08/14/2007	LTN050GEF	LOCHINVAR	0
4371	09/07/2011	MI403S6FBN	BRADFORD-WHITE	0
4372	05/18/1995	RFD82156	RUUD	0
4373	01/22/2013	M45036FBN	BRADFORD-WHITE	2
4374	01/31/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4375	11/19/1999	FSG50	AO SMITH	0
4376	09/29/2000	PGR50	AO SMITH	0
4377	04/08/2009	LTN050GEF	LOCHINVAR	0
4378	09/23/2005	LTN050G	LOCHINVAR	0
4379	12/09/2001	FSG50	AO SMITH	0
4380	12/14/2012	MI403S6FBN	BRADFORD-WHITE	0
4381	10/06/2011	M45036FBN	BRADFORD-WHITE	0
4382	09/23/2005	PR650	STATE	0
4383	05/23/2011	42VR50	RHEEM	0
4384	01/17/2012	PRX50	STATE	1
4385	02/14/2010	LTN050GEF	LOCHINVAR	2
4386	05/14/2009	LTN050GEF	LOCHINVAR	0
4387	02/11/2009	LTN040GEF	LOCHINVAR	0
4388	05/08/2012	G91200	RUUD/RHEEM	0
4389	02/26/2009	LSN041G	LOCHINVAR	2
4390	05/18/1994	41XR40	RHEEM	0
4391	02/26/2009	LSN041G	LOCHINVAR	0
4392	01/22/2001	H72DUMMY	AO SMITH	0
4393	05/17/2006	LTN050GEF	LOCHINVAR	0
4394	10/22/1998	FSG50	AO SMITH	0
4395	05/02/2002	FSG50	AO SMITH	0
4396	12/08/1999	PGR50	AO SMITH	0
4397	04/05/2011	41VR50	RHEEM	0
4398	07/17/2005	LTN050	LOCHINVAR	0
4399	08/18/2009	LTN050GEF	LOCHINVAR	0
4400	08/31/2010	LTN040G	LOCHINVAR	1
4401	12/30/2003	FCV50	AO SMITH	0
4402	12/28/2001	21V407	RHEEM	1
4403	02/25/2011	21VR50	RHEEM	1
4404	10/17/2002	FSG40	AO SMITH	0
4405	11/11/2005	LTN040G	LOCHINVAR	0
4406	09/30/2011	MI5036FBN	BRADFORD-WHITE	1
4407	11/09/2012	M45036FBN	BRADFORD-WHITE	0
4408	02/01/1971	A71DUMMY	UNKNOWN AT CONVERSION	0
4409	03/04/1983	FSG50	AO SMITH	1
4410	09/13/2010	LTN040GEF	LOCHINVAR	0
4411	01/03/1999	41VR50	RHEEM	1
4412	02/23/2004	PVR50	AO SMITH	0
4413	10/14/2009	G75125	RUUD/RHEEM	1
4414	09/24/2012	M45036FBN	BRADFORD-WHITE	0
4415	12/26/2003	FSG30	AO SMITH	0
4416	07/03/2008	LTN050G	LOCHINVAR	1
4417	07/21/2009	LTN050GEF	LOCHINVAR	0
4418	11/13/2006	LTN050GEF	LOCHINVAR	0
4419	03/21/1988	FSG50	AO SMITH	0
4420	05/03/2008	LTN050GEF	LOCHINVAR	0
4421	12/07/2012	PH2DV50F	RUUD	1
4422	08/14/1997	FGR50	AO SMITH	0
4423	11/08/2011	M45036FBN	BRADFORD-WHITE	0
4424	11/03/2011	PH2DV50F	RUUD	0
4425	08/09/2012	MI5036FBN	BRADFORD-WHITE	0
4426	03/22/2010	LTN050GEF	LOCHINVAR	0
4427	01/09/2003	FSG40	AO SMITH	0
4428	04/16/2010	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4429	12/02/1996	P506	RUUD	0
4430	11/30/2008	LTN050GEF	LOCHINVAR	0
4431	02/20/2007	LTN050G	LOCHINVAR	0
4432	05/25/2006	LTN050G	LOCHINVAR	0
4433	11/19/2007	LTN050GEF	LOCHINVAR	0
4434	02/08/2011	21VR50	RHEEM	1
4435	09/08/2009	LTN040GEF	LOCHINVAR	0
4436	08/15/2011	M45036FBN	BRADFORD-WHITE	0
4437	09/24/1987	FSG50	AO SMITH	0
4438	06/16/2003	G91200	RUUD/RHEEM	3
4439	04/12/1988	FSG50	AO SMITH	0
4440	08/17/1998	FSG50	AO SMITH	0
4441	10/18/1999	41VR50	RHEEM	0
4442	01/03/2008	LTN050G	LOCHINVAR	0
4443	10/09/2001	PRX50	STATE	0
4444	06/07/2003	PGR50	AO SMITH	0
4445	03/11/2009	LTN040GEF	LOCHINVAR	0
4446	01/28/2007	LTN050G	LOCHINVAR	1
4447	05/30/2005	LTN050	LOCHINVAR	0
4448	05/05/2011	G82156	RUUD/RHEEM	0
4449	08/22/2005	XSN040	LOCHINVAR	2
4450	12/26/2012	M45036FBN	BRADFORD-WHITE	0
4451	12/08/2010	42VR50	RHEEM	1
4452	07/10/2009	LTN050G	LOCHINVAR	0
4453	12/13/2010	G75125	RUUD/RHEEM	0
4454	11/14/2011	MI5036FBN	BRADFORD-WHITE	0
4455	04/04/1986	FSG50	AO SMITH	0
4456	08/27/2008	22DV50C	RHEEM	0
4457	06/25/2012	XTN050	LOCHINVAR	0
4458	05/14/2002	FSGL40	AO SMITH	0
4459	08/12/2010	LTN050G	LOCHINVAR	0
4460	07/11/1998	PRV50NODS	STATE	0
4461	04/20/2004	GCVL40	A. O. SMITH	0
4462	06/28/2004	XVR50	A. O. SMITH	1
4463	08/10/2009	LTN050GEF	LOCHINVAR	1
4464	05/08/1996	FGR50	AO SMITH	0
4465	02/23/2009	LTN050GEF	LOCHINVAR	0
4466	01/10/2000	PGR50	AO SMITH	0
4467	12/23/2008	LTN050GEF	LOCHINVAR	0
4468	09/25/1997	FSG50	AO SMITH	0
4469	08/16/1990	SBF100199NES	STATE	0
4470	01/30/2008	LTN050GEF	LOCHINVAR	1
4471	08/25/2005	LTN050G	LOCHINVAR	0
4472	08/06/2007	LTN050G	LOCHINVAR	0
4473	11/04/1985	FSG50	AO SMITH	1
4474	01/06/1986	RF67120	RUUD	0
4475	10/12/2011	M45036FBN	BRADFORD-WHITE	0
4476	05/24/2001	FSG50	AO SMITH	0
4477	01/05/2010	LTN050GEF	LOCHINVAR	0
4478	10/07/2001	41VR50	RHEEM	1
4479	12/05/2008	LSN041G	LOCHINVAR	0
4480	10/26/2005	LTN050GEF	LOCHINVAR	0
4481	02/28/1986	FSGL40	AO SMITH	0
4482	03/22/2012	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4483	11/18/1985	21V502	RHEEM	0
4484	01/02/2008	LTN050G	LOCHINVAR	0
4485	05/30/2011	22DV50F	RHEEM	3
4486	01/09/2002	PGR50	AO SMITH	0
4487	06/06/2000	FSG50	AO SMITH	0
4488	04/09/2003	FSG50	AO SMITH	2
4489	02/12/2009	PH199119	PHOENIX	1
4490	02/16/2013	MI403S6FBN	BRADFORD-WHITE	0
4491	01/13/2006	LTN050G	LOCHINVAR	0
4492	02/12/2009	PH199119	PHOENIX	0
4493	04/20/2005	GVC50	A. O. SMITH	1
4494	06/10/2002	PGR50	AO SMITH	0
4495	06/21/2005	G82156	RUUD/RHEEM	0
4496	12/08/1997	FGR50	AO SMITH	0
4497	10/05/1998	FGR50	AO SMITH	0
4498	10/19/2009	LTN050GEF	LOCHINVAR	0
4499	01/10/2009	LTN050GEF	LOCHINVAR	0
4500	04/30/2012	M45036FBN	BRADFORD-WHITE	0
4501	12/05/2000	FSG50	AO SMITH	0
4502	07/06/1998	PGR50	AO SMITH	0
4503	09/06/2011	PH2DV50F	RUUD	0
4504	07/18/2001	PGR50	AO SMITH	1
4505	06/09/2003	PRX40	STATE	0
4506	11/29/1994	PR502T	RUUD	0
4507	02/10/2012	M45036FBN	BRADFORD-WHITE	0
4508	03/02/2012	DS150S6FBN	BRADFORD-WHITE	0
4509	05/07/2012	PH2DV50F	RUUD	0
4510	09/13/2006	LTN050G	LOCHINVAR	0
4511	05/19/2006	PR650	STATE	1
4512	05/22/2012	MI5036FBN	BRADFORD-WHITE	0
4513	12/24/2000	41V40	RHEEM	0
4514	05/01/2004	PRX50	STATE	1
4515	03/30/2005	GVC50	A. O. SMITH	1
4516	03/23/1987	FSG50	AO SMITH	0
4517	02/06/2012	MI5036FBN	BRADFORD-WHITE	1
4518	05/04/2006	LTN050G	LOCHINVAR	0
4519	06/24/1986	FSG50	AO SMITH	0
4520	08/02/2007	LTN050GEF	LOCHINVAR	0
4521	09/19/1999	PHR50	RUUD	0
4522	08/31/2001	FSG50	AO SMITH	0
4523	10/31/1986	FSG50	AO SMITH	0
4524	11/14/1994	PR502T	RUUD	0
4525	01/29/2008	LSN041G	LOCHINVAR	1
4526	03/07/2007	LTN040G	LOCHINVAR	0
4527	02/02/2011	21VR50	RHEEM	0
4528	07/22/2003	FSGL40	AO SMITH	0
4529	08/24/1987	FSG50	AO SMITH	0
4530	12/24/2004	XVR50	A. O. SMITH	0
4531	06/15/2005	LTN050	LOCHINVAR	0
4532	05/02/1994	PHR50	RUUD	0
4533	04/30/2007	LTN050G	LOCHINVAR	0
4534	08/29/1986	FSG50	AO SMITH	0
4535	04/29/2002	FSG50	AO SMITH	1
4536	11/02/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4537	08/21/2012	MI5036FBN	BRADFORD-WHITE	1
4538	05/09/2006	LTN050G	LOCHINVAR	0
4539	02/20/2007	LTN050G	LOCHINVAR	1
4540	09/29/2011	MI5036FBN	BRADFORD-WHITE	0
4541	05/02/2012	M45036FBN	BRADFORD-WHITE	1
4542	03/05/2003	PGR50	AO SMITH	0
4543	09/02/1997	PGR40	AO SMITH	0
4544	10/11/2002	PGR50	AO SMITH	0
4545	05/19/2011	41VR50	RHEEM	0
4546	02/18/2000	FSG40	AO SMITH	1
4547	07/25/2005	LTN050G	LOCHINVAR	2
4548	05/11/2010	LTN050GEF	LOCHINVAR	0
4549	05/26/2009	LTN050GEF	LOCHINVAR	0
4550	11/15/2005	LTN040G	LOCHINVAR	0
4551	05/05/2007	LTN040GEF	LOCHINVAR	0
4552	09/20/2011	G75125	RUUD/RHEEM	0
4553	02/23/2007	PGX50	AO SMITH	0
4554	10/18/2011	M45036FBN	BRADFORD-WHITE	0
4555	11/25/1995	PGR50	AO SMITH	0
4556	03/28/2002	FSG50	AO SMITH	0
4557	03/16/2006	LTN050G	LOCHINVAR	0
4558	07/03/2000	FSGL40	AO SMITH	0
4559	01/04/2011	21VR40	RHEEM	0
4560	08/14/1996	FSGL40	AO SMITH	0
4561	04/20/2007	LTN050GEF	LOCHINVAR	0
4562	04/24/2009	LTN040GEF	LOCHINVAR	1
4563	11/11/2008	LTN050GEF	LOCHINVAR	0
4564	10/03/2002	PGR50	AO SMITH	0
4565	08/12/2010	G91200	RUUD/RHEEM	0
4566	10/23/2000	PGR50	AO SMITH	0
4567	10/01/1993	FSG50	AO SMITH	0
4568	08/23/2007	LTN040GEF	LOCHINVAR	1
4569	07/10/2008	LTN050G	LOCHINVAR	2
4570	10/08/2012	G75125	RUUD/RHEEM	2
4571	09/28/1984	FSG50	AO SMITH	0
4572	08/01/2007	G75125	RUUD/RHEEM	0
4573	03/09/2007	LTN050G	LOCHINVAR	1
4574	12/11/2007	LTN040G	LOCHINVAR	2
4575	07/19/2006	LTN050G	LOCHINVAR	0
4576	02/08/2006	LTN050G	LOCHINVAR	0
4577	08/13/2001	PGR50	AO SMITH	0
4578	12/29/1995	FGR50	AO SMITH	0
4579	08/30/1999	41VR50	RHEEM	0
4580	10/08/2008	LTN040GEF	LOCHINVAR	0
4581	03/02/2010	LTN050GEF	LOCHINVAR	1
4582	10/20/2008	LTN050GEF	LOCHINVAR	2
4583	02/16/2012	G82156	RUUD/RHEEM	1
4584	01/15/2009	21VR40	RHEEM	0
4585	10/20/2010	21VR50	RHEEM	0
4586	07/10/2007	LTN051G	LOCHINVAR	1
4587	07/14/2005	LSN041G	LOCHINVAR	0
4588	04/25/2001	41V50	RHEEM	1
4589	01/01/2011	21VR50	RHEEM	0
4590	09/24/2009	LSN041G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4591	06/24/2010	LTN050GEF	LOCHINVAR	1
4592	10/27/2003	PVR50	AO SMITH	0
4593	05/01/2009	RM5063	RUUD	0
4594	06/16/2006	LTN050G	LOCHINVAR	0
4595	07/26/2003	FSG50	AO SMITH	0
4596	02/11/2013	M45036FBN	BRADFORD-WHITE	0
4597	03/15/2012	M45036FBN	BRADFORD-WHITE	0
4598	04/13/2007	PR650X0DS	STATE	0
4599	12/07/2009	LTN050G	LOCHINVAR	0
4600	12/12/2001	FSG50	AO SMITH	0
4601	08/31/2003	FSGL40	AO SMITH	0
4602	07/26/2006	LTN050G	LOCHINVAR	1
4603	07/28/1993	FSG50	AO SMITH	0
4604	08/31/2011	M45036FBN	BRADFORD-WHITE	0
4605	03/10/2007	PR650	STATE	0
4606	09/05/2008	LTN040G	LOCHINVAR	1
4607	08/09/2010	LTN050G	LOCHINVAR	0
4608	01/27/2010	LTN050G	LOCHINVAR	0
4609	12/30/2008	LTN050GEF	LOCHINVAR	0
4610	10/09/1997	PGR50	AO SMITH	0
4611	05/08/1986	F72DUMMY	AO SMITH	0
4612	12/14/2012	M440T6FBN	BRADFORD-WHITE	0
4613	02/22/2013	M45036FBN	BRADFORD-WHITE	0
4614	03/30/2002	PGR50	AO SMITH	0
4615	01/27/2013	M45036FBN	BRADFORD-WHITE	0
4616	04/14/2006	LTN050GEF	LOCHINVAR	0
4617	07/06/2008	LTN050GEF	LOCHINVAR	0
4618	03/07/1985	FSG50	AO SMITH	0
4619	11/17/2006	PR650	STATE	0
4620	12/01/1995	RF67120	RUUD	0
4621	08/30/1985	FSG50	AO SMITH	0
4622	02/12/2002	FSG50	AO SMITH	0
4623	05/14/2001	FSG40	AO SMITH	0
4624	10/27/2009	LSN041G	LOCHINVAR	0
4625	01/11/2011	LTN040G	LOCHINVAR	0
4626	06/08/2008	LTN050GEF	LOCHINVAR	0
4627	09/06/2012	M45036FBN	BRADFORD-WHITE	0
4628	06/20/2008	LTN050G	LOCHINVAR	2
4629	11/13/2008	LTN050GEF	LOCHINVAR	0
4630	01/03/2000	PHR50	RUUD	0
4631	09/05/2012	M45036FBN	BRADFORD-WHITE	0
4632	06/09/2009	22DV50C	RHEEM	0
4633	10/20/1999	FGR50	AO SMITH	0
4634	04/28/2011	P506	RUUD	1
4635	04/14/2008	LTN050GEF	LOCHINVAR	0
4636	01/09/2004	PVR50	AO SMITH	0
4637	11/08/2001	FSG50	AO SMITH	0
4638	11/25/2008	LTN050GEF	LOCHINVAR	0
4639	04/25/2011	41VR50	RHEEM	1
4640	12/19/2012	MI5036FBN	BRADFORD-WHITE	0
4641	05/23/2003	FSG50	AO SMITH	0
4642	11/17/2005	LTN050G	LOCHINVAR	0
4643	09/17/2007	LTN050GEF	LOCHINVAR	0
4644	12/16/2010	22DV50F	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4645	03/12/2009	22DV50C	RHEEM	0
4646	08/28/2006	42VR50	RHEEM	2
4647	01/30/1995	PR502T	RUUD	0
4648	06/08/2010	22DV50C	RHEEM	1
4649	10/13/2006	LTN050G	LOCHINVAR	0
4650	12/08/2008	LTN050GEF	LOCHINVAR	1
4651	02/19/2009	LTN050GEF	LOCHINVAR	0
4652	05/15/1988	FSG50	AO SMITH	0
4653	07/25/2005	LTN050	LOCHINVAR	1
4654	12/15/2005	LTN050G	LOCHINVAR	0
4655	04/26/2002	41V40S	RHEEM	0
4656	05/10/2010	LTN050G	LOCHINVAR	1
4657	06/19/2007	LTN051G	LOCHINVAR	0
4658	07/23/2007	PR650X0DS	STATE	0
4659	09/17/2010	21V502	RHEEM	0
4660	10/27/2009	LTN050GEF	LOCHINVAR	0
4661	05/12/2009	LTN050GEF	LOCHINVAR	0
4662	06/28/2011	M45036FBN	BRADFORD-WHITE	0
4663	05/02/2007	LTN050GEF	LOCHINVAR	0
4664	04/17/2004	PRX50	STATE	0
4665	12/01/2011	MI5036FBN	BRADFORD-WHITE	1
4666	08/15/2006	LTN050GEF	LOCHINVAR	0
4667	12/19/2007	LTN050GEF	LOCHINVAR	0
4668	09/28/2011	MI40T6FBN	BRADFORD-WHITE	0
4669	06/25/2011	MI5036FBN	BRADFORD-WHITE	0
4670	02/11/2013	PH2DV50F	RUUD	0
4671	03/18/2006	LTN050GEF	LOCHINVAR	0
4672	04/23/2007	LTN050G	LOCHINVAR	0
4673	02/04/2009	22DV50C	RHEEM	0
4674	07/31/2009	LTN050GEF	LOCHINVAR	0
4675	04/01/2001	41XR50	RHEEM	0
4676	11/23/1998	41VR50	RHEEM	0
4677	01/11/2007	LTN050GEF	LOCHINVAR	0
4678	04/20/2004	G75125	RUUD/RHEEM	0
4679	07/18/2008	22DV50F	RHEEM	0
4680	12/20/2007	LTN050GEF	LOCHINVAR	0
4681	11/09/2004	GVC50	A. O. SMITH	0
4682	01/07/2005	LTN050G	LOCHINVAR	0
4683	05/27/2006	PR650	STATE	1
4684	09/07/2007	LSN041G	Lochinvar	1
4685	01/03/2000	G91200	RUUD/RHEEM	0
4686	06/13/1996	PGR40	AO SMITH	0
4687	09/06/2011	M440T6FBN	BRADFORD-WHITE	0
4688	10/19/2004	GVC50	A. O. SMITH	0
4689	11/05/2004	XVR50	A. O. SMITH	0
4690	12/21/2007	PR650	STATE	0
4691	10/30/1995	FGR50	AO SMITH	0
4692	01/14/2000	FSG50	AO SMITH	0
4693	02/26/2007	LTN050G	LOCHINVAR	0
4694	03/26/1986	FSG50	AO SMITH	0
4695	12/08/2005	LTN050G	LOCHINVAR	1
4696	02/10/2010	PGR40	AO SMITH	0
4697	10/04/2012	MI5036FBN	BRADFORD-WHITE	0
4698	10/30/2001	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4699	04/07/2007	LTN050G	LOCHINVAR	0
4700	02/23/2011	42VR50	RHEEM	1
4701	09/14/1995	PR502T	RUUD	0
4702	11/02/2009	LTN050GEF	LOCHINVAR	1
4703	12/14/2006	LTN050G	LOCHINVAR	0
4704	02/27/2008	LTN050GEF	LOCHINVAR	0
4705	01/17/2013	M45036FBN	BRADFORD-WHITE	0
4706	10/18/1996	P506	RUUD	0
4707	03/27/1999	PHR50	RUUD	0
4708	10/03/2010	21V502	RHEEM	0
4709	11/07/2012	G75125	RUUD/RHEEM	5
4710	11/17/2006	FSG50	AO SMITH	0
4711	01/09/2009	22DV50F	RHEEM	0
4712	09/01/1998	41VR50	RHEEM	0
4713	02/20/2007	LTN050G	LOCHINVAR	0
4714	03/02/2011	41VR40	RHEEM	2
4715	11/12/2010	21VR50	RHEEM	0
4716	01/20/2006	LTN050GEF	LOCHINVAR	0
4717	08/05/2002	PGR50	AO SMITH	1
4718	11/21/1999	PRV40NODS	STATE	0
4719	12/17/2005	LTN050G	LOCHINVAR	0
4720	11/13/2012	MI403S6FBN	BRADFORD-WHITE	0
4721	01/03/1986	FSG50	AO SMITH	1
4722	05/23/2007	LTN050GEF	LOCHINVAR	0
4723	04/16/2004	PRX40	STATE	0
4724	05/13/1982	P40S	RUUD	0
4725	08/31/2009	LTN050G	LOCHINVAR	1
4726	02/12/2001	41VR50	RHEEM	0
4727	08/25/2012	MI50L6FBN	BRADFORD-WHITE	0
4728	05/24/2002	FSG50	AO SMITH	0
4729	08/07/2006	LTN040G	LOCHINVAR	0
4730	06/24/2007	LTN040GEF	LOCHINVAR	0
4731	04/23/2004	FCV50	AO SMITH	1
4732	07/01/2009	LTN050GEF	LOCHINVAR	0
4733	05/23/2011	21VR50	RHEEM	0
4734	12/19/2012	MI5036FBN	BRADFORD-WHITE	0
4735	03/11/2011	42VR50	RHEEM	1
4736	07/06/2005	LTN040	LOCHINVAR	0
4737	09/09/2003	FSGL40	AO SMITH	0
4738	04/03/2008	LTN050GEF	LOCHINVAR	0
4739	05/27/2008	LTN050GEF	LOCHINVAR	0
4740	11/10/2009	LTN050GEF	LOCHINVAR	0
4741	12/23/1993	PGR50	AO SMITH	0
4742	12/14/2005	LTN050G	LOCHINVAR	0
4743	01/09/2009	LTN050GEF	LOCHINVAR	1
4744	11/18/2007	LTN040G	LOCHINVAR	1
4745	03/12/2008	LTN050	LOCHINVAR	0
4746	07/21/1999	PHR50	RUUD	0
4747	01/04/2005	GVC40	A. O. SMITH	0
4748	10/22/1999	PGR50	AO SMITH	0
4749	10/19/2009	LSN041G	LOCHINVAR	1
4750	04/06/2000	G91200	RUUD/RHEEM	0
4751	10/03/2007	LTN050GEF	LOCHINVAR	0
4752	03/08/2011	21VR40	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4753	11/09/2010	42VR50	RHEEM	0
4754	04/25/2006	LTN040G	LOCHINVAR	0
4755	01/04/2000	FSG40	AO SMITH	0
4756	04/06/2000	G91200	RUUD/RHEEM	0
4757	03/08/2011	21VR40	RHEEM	0
4758	05/09/2007	LTN050GEF	LOCHINVAR	0
4759	04/03/2001	FSG50	AO SMITH	0
4760	03/09/2003	PRX50	STATE	0
4761	12/03/2011	MI5036FBN	BRADFORD-WHITE	0
4762	11/19/2008	LTN040GEF	LOCHINVAR	0
4763	02/02/2003	FSG50	AO SMITH	0
4764	08/12/2011	MI403S6FBN	BRADFORD-WHITE	0
4765	02/16/2001	FSG50	AO SMITH	0
4766	12/23/2011	M45036FBN	BRADFORD-WHITE	0
4767	12/01/1971	PGX30	AO AMITH	0
4768	10/02/2006	LTN050G	LOCHINVAR	0
4769	04/13/2001	41XR50	RHEEM	0
4770	03/24/2010	LTN050GEF	LOCHINVAR	0
4771	08/05/2009	LTN050GEF	LOCHINVAR	0
4772	01/20/2000	PGR50	AO SMITH	0
4773	06/29/2011	M45036FBN	BRADFORD-WHITE	0
4774	04/26/2008	LTN050GEF	LOCHINVAR	0
4775	02/27/2010	LTN050GEF	LOCHINVAR	1
4776	08/10/2007	LTN050G	LOCHINVAR	0
4777	12/05/2005	LTN050GEF	LOCHINVAR	0
4778	11/01/1999	FSG50	AO SMITH	0
4779	09/19/2006	LTN050G	LOCHINVAR	0
4780	08/01/2007	LTN050GEF	LOCHINVAR	0
4781	04/27/1987	P506	RUUD	0
4782	12/06/2008	LTN050GEF	LOCHINVAR	0
4783	04/03/2003	FSG50	AO SMITH	0
4784	12/29/2008	22DV50C	RHEEM	0
4785	03/29/2012	M45036FBN	BRADFORD-WHITE	0
4786	08/26/2010	LTN040G	LOCHINVAR	0
4787	02/08/2006	LTN050G	LOCHINVAR	0
4788	10/09/2006	PR640	STATE	2
4789	08/24/2006	LTN050G	LOCHINVAR	0
4790	02/29/2008	LTN050	LOCHINVAR	1
4791	11/02/2007	PR650	STATE	0
4792	12/22/2004	PRX50	STATE	0
4793	01/13/2012	M440T6FBN	BRADFORD-WHITE	0
4794	12/16/2008	LTN050GEF	LOCHINVAR	2
4795	04/07/2011	42VR50	RHEEM	0
4796	11/13/2001	PGR50	AO SMITH	0
4797	08/12/2005	LTN050GEF	LOCHINVAR	0
4798	08/13/1998	21V407	RHEEM	0
4799	05/14/2009	LTN050G	LOCHINVAR	0
4800	03/07/2005	GVC50	A. O. SMITH	0
4801	01/13/2010	22DV50C	RHEEM	0
4802	08/26/1995	FGR50	AO SMITH	0
4803	05/17/2010	LTN050GEF	LOCHINVAR	0
4804	06/23/2004	XVR50	A. O. SMITH	0
4805	04/25/2000	PGR50	AO SMITH	0
4806	11/05/2007	LTN040G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4807	04/24/2007	LTN050G	LOCHINVAR	0
4808	05/29/1995	BTC197	AO SMITH	0
4809	12/13/2006	LTN050GEF	LOCHINVAR	0
4810	01/09/2009	41V50	RHEEM	0
4811	03/04/2009	LTN050GEF	LOCHINVAR	1
4812	04/24/2007	LTN050G	LOCHINVAR	0
4813	12/15/2007	LTN050GEF	LOCHINVAR	0
4814	01/10/2008	FSG50	AO SMITH	0
4815	07/17/2001	PRX50	STATE	0
4816	07/01/1988	FSG50	AO SMITH	0
4817	07/17/2012	PH199119	PHOENIX	0
4818	12/15/1999	PGR50	AO SMITH	0
4819	12/09/2003	FCV50	AO SMITH	0
4820	11/17/1999	FSG50	AO SMITH	0
4821	01/08/2008	LTN050GEF	LOCHINVAR	0
4822	11/08/2007	LTN050GEF	LOCHINVAR	2
4823	01/24/2011	22V50F1	RHEEM	0
4824	04/24/1995	FGR50	AO SMITH	0
4825	05/06/2004	XVR50	A. O. SMITH	1
4826	03/27/2012	MI5036FBN	BRADFORD-WHITE	0
4827	07/08/2008	22DV50C	RHEEM	0
4828	03/21/2012	MI5036FBN	BRADFORD-WHITE	0
4829	05/10/2001	PRV50NODS	STATE	0
4830	12/27/1995	FGR50	AO SMITH	0
4831	10/13/2006	LTN050G	LOCHINVAR	0
4832	03/11/2013	MI5036FBN	BRADFORD WHITE	0
4833	11/28/2011	M45036FBN	BRADFORD-WHITE	0
4834	11/29/1997	RFD91200	RUUD	0
4835	09/26/2001	41XR50	RHEEM	0
4836	04/14/2010	LTN050G	LOCHINVAR	0
4837	02/15/2007	LTN050GEF	LOCHINVAR	1
4838	06/26/2009	LTN050G	LOCHINVAR	1
4839	06/07/2001	PRX50	STATE	0
4840	05/09/2006	LTN050G	LOCHINVAR	0
4841	07/14/2009	LTN050GEF	LOCHINVAR	0
4842	03/25/1988	21V506	RHEEM	0
4843	05/10/1988	FSG50	AO SMITH	0
4844	10/06/2009	PGR50	AO SMITH	0
4845	05/17/2010	LTN050G	LOCHINVAR	0
4846	03/06/1998	PRV50NODS	STATE	0
4847	03/17/2000	41XR50	RHEEM	0
4848	06/24/1988	FSG50	AO SMITH	0
4849	01/26/2003	PGR50	AO SMITH	1
4850	09/22/1987	RF67120	RUUD	0
4851	07/09/2004	XTN050	LOCHINVAR	0
4852	02/09/2009	LTN040GEF	LOCHINVAR	1
4853	08/01/2006	LTN050GEF	LOCHINVAR	0
4854	12/07/1998	PHR50	RUUD	0
4855	05/20/2010	22DV50C	RHEEM	2
4856	06/10/1988	FSG50	AO SMITH	0
4857	11/08/2004	XVR50	A. O. SMITH	0
4858	08/01/2000	PRV50NODS	STATE	0
4859	03/02/2009	LTN050GEF	LOCHINVAR	0
4860	11/01/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4861	05/03/2007	LTN040G	LOCHINVAR	0
4862	02/13/2012	MI5036FBN	BRADFORD-WHITE	1
4863	01/31/2002	FSG50	AO SMITH	0
4864	09/03/2004	GVC50	A. O. SMITH	0
4865	07/25/2005	LTN040	LOCHINVAR	0
4866	09/25/2001	FSG40	AO SMITH	0
4867	07/23/2007	LTN050GEF	LOCHINVAR	1
4868	10/15/2011	MI5036FBN	BRADFORD-WHITE	0
4869	03/28/2011	22DV50F	RHEEM	0
4870	04/19/2005	GVC50	A. O. SMITH	0
4871	10/01/2009	LTN050GEF	LOCHINVAR	0
4872	11/02/1998	FSG40	AO SMITH	0
4873	03/13/1985	FSG50	AO SMITH	0
4874	05/17/2007	LTN050G	LOCHINVAR	0
4875	08/29/2005	LTN050G	LOCHINVAR	0
4876	10/16/2010	PRV50NODS	STATE	0
4877	04/08/2012	MI40T6FBN	BRADFORD-WHITE	1
4878	08/21/2000	41XR50	RHEEM	0
4879	01/05/1996	PGR50	AO SMITH	1
4880	10/19/2005	LTN050G	LOCHINVAR	0
4881	01/19/2011	22DV50F	RHEEM	0
4882	10/02/2007	LTN050GEF	LOCHINVAR	0
4883	05/15/1999	FSG50	AO SMITH	0
4884	05/08/1985	RM50632	RUUD	0
4885	12/22/2006	LTN050G	LOCHINVAR	0
4886	06/13/2009	LTN050GEF	LOCHINVAR	0
4887	11/26/2007	LTN050G	LOCHINVAR	0
4888	04/28/2011	21VR50	RHEEM	0
4889	03/13/2007	LTN050GEF	LOCHINVAR	0
4890	11/27/2009	22DV50C	RHEEM	0
4891	04/24/2004	FSG50	AO SMITH	0
4892	05/19/1986	P506	RUUD	0
4893	01/07/2011	42VR50	RHEEM	1
4894	02/22/2012	M45036FBN	BRADFORD-WHITE	0
4895	05/06/2011	41VR50	RHEEM	0
4896	03/11/2002	FSG50	AO SMITH	0
4897	01/12/2012	FGR50	AO SMITH	0
4898	12/28/2012	MI40T6FBN	BRADFORD-WHITE	0
4899	04/04/2007	LTN050G	LOCHINVAR	0
4900	08/15/2000	41XR50	RHEEM	0
4901	11/17/2009	LTN050GEF	LOCHINVAR	0
4902	09/12/2009	LTN050GEF	LOCHINVAR	0
4903	07/01/2009	LTN050GEF	LOCHINVAR	0
4904	12/11/2008	LTN050GEF	LOCHINVAR	0
4905	04/06/2010	LTN050GEF	LOCHINVAR	0
4906	11/03/2005	LTN050G	LOCHINVAR	0
4907	05/05/2008	LTN050GEF	LOCHINVAR	1
4908	10/25/2009	22DV50C	RHEEM	0
4909	10/01/2007	LTN050GEF	LOCHINVAR	0
4910	10/18/2010	42VR50	RHEEM	0
4911	08/17/1987	FSG50	AO SMITH	0
4912	04/23/2004	GVC50	A. O. SMITH	0
4913	05/10/2006	LTN050G	LOCHINVAR	0
4914	12/12/2012	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4915	01/18/2013	PH2DV50F	RUUD	0
4916	04/11/2012	PH2DV50F	RUUD	0
4917	03/09/2010	LTN050G	LOCHINVAR	0
4918	07/12/2009	LTN050GEF	LOCHINVAR	0
4919	10/25/2009	LTN050GEF	LOCHINVAR	0
4920	11/16/2005	LTN050G	LOCHINVAR	0
4921	03/22/2003	PGR50	AO SMITH	0
4922	12/14/2012	M45036FBN	BRADFORD-WHITE	0
4923	11/07/1986	FSG40	AO SMITH	0
4924	01/03/2012	PH2DV50F	RUUD	2
4925	02/12/2010	LTN050GEF	LOCHINVAR	0
4926	04/25/2002	FSG50	AO SMITH	0
4927	03/13/2001	FSG50	AO SMITH	0
4928	02/09/2001	41V40	RHEEM	0
4929	06/08/2009	LTN040GEF	LOCHINVAR	0
4930	10/13/2008	LTN050GEF	LOCHINVAR	0
4931	05/29/1999	21V506	RHEEM	0
4932	01/31/2006	LTN050GEF	LOCHINVAR	0
4933	05/23/2006	GVC40	A. O. SMITH	0
4934	03/30/2001	PGR50	AO SMITH	1
4935	04/03/2006	LSN041G	LOCHINVAR	0
4936	08/17/2007	LTN050GEF	LOCHINVAR	0
4937	10/18/2011	M45036FBN	BRADFORD-WHITE	0
4938	05/27/2008	LTN050GEF	LOCHINVAR	0
4939	08/05/2003	PRX50	STATE	1
4940	10/05/1998	FGR50	AO SMITH	0
4941	07/22/2008	LTN050GEF	LOCHINVAR	1
4942	06/27/2011	G75125	RUUD/RHEEM	2
4943	05/01/2007	LTN050GEF	LOCHINVAR	0
4944	11/02/2000	41VR50	RHEEM	0
4945	01/05/2009	LTN050GEF	LOCHINVAR	1
4946	12/20/1999	41XR50	RHEEM	0
4947	01/05/2008	LTN050GEF	LOCHINVAR	0
4948	04/22/2005	G75125	RUUD/RHEEM	1
4949	10/15/2002	PGR50	AO SMITH	0
4950	08/28/1998	21V402S	RHEEM	0
4951	08/08/1983	FSGL40	AO SMITH	0
4952	10/05/2000	41XR50	RHEEM	0
4953	03/27/2009	LTN050GEF	LOCHINVAR	0
4954	02/22/2006	LTN050G	LOCHINVAR	0
4955	05/15/2007	LTN040G	LOCHINVAR	0
4956	04/08/2004	GVC40	A. O. SMITH	0
4957	01/09/2009	LSN041G	LOCHINVAR	0
4958	12/13/2011	M45036FBN	BRADFORD-WHITE	0
4959	05/19/2008	LTN050GEF	LOCHINVAR	0
4960	04/09/2002	FSG30	AO SMITH	0
4961	10/27/2003	FSG50	AO SMITH	0
4962	05/14/2007	LTN050G	LOCHINVAR	0
4963	03/09/1992	FSG40	AO SMITH	0
4964	10/22/2010	41VR50	RHEEM	1
4965	03/22/2005	GVC50	A. O. SMITH	0
4966	05/25/2007	LTN050GEF	LOCHINVAR	0
4967	01/24/2011	MI40T6FBN	BRADFORD-WHITE	0
4968	10/28/2012	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
4969	12/27/1984	FSG50	AO SMITH	0
4970	02/28/2002	PGR50	AO SMITH	0
4971	10/12/2010	LTN040G	LOCHINVAR	0
4972	08/18/2009	LTN050G	LOCHINVAR	0
4973	09/13/2008	LTN050GEF	LOCHINVAR	0
4974	05/24/2005	LTN050	LOCHINVAR	0
4975	03/03/1997	21V402S	RHEEM	0
4976	02/07/2006	LTN050G	LOCHINVAR	0
4977	07/13/2011	M45036FBN	BRADFORD-WHITE	1
4978	12/07/2007	LTN050G	LOCHINVAR	0
4979	07/10/2012	M45036FBN	BRADFORD-WHITE	0
4980	10/04/2005	LSN041G	LOCHINVAR	0
4981	11/11/2002	FSG50	AO SMITH	0
4982	03/23/2001	G91200	RUUD/RHEEM	1
4983	05/18/2005	LTN050	LOCHINVAR	0
4984	04/07/2008	LTN050GEF	LOCHINVAR	0
4985	04/28/2010	ETN076	LOCHINVAR	3
4986	08/12/2002	PGR50	AO SMITH	0
4987	04/28/2008	LTN050GEF	LOCHINVAR	0
4988	08/28/2002	PGR50	AO SMITH	0
4989	07/23/2006	G91200	RUUD/RHEEM	0
4990	03/03/2003	G91200	RUUD/RHEEM	2
4991	07/23/2006	LSN041G	LOCHINVAR	0
4992	12/30/2004	PRX50	STATE	0
4993	05/20/2011	21VR40	RHEEM	3
4994	09/15/2001	FSGL40	AO SMITH	0
4995	11/24/1999	FGR40	AO SMITH	0
4996	03/26/2010	22DV50C	RHEEM	0
4997	02/19/2004	PVR50	AO SMITH	0
4998	09/09/2004	GVC50	A. O. SMITH	1
4999	01/09/2012	MI5036FBN	BRADFORD-WHITE	0
5000	06/12/2008	LTN050G	LOCHINVAR	0
5001	12/02/1987	FSG50	AO SMITH	0
5002	02/24/2005	GVC50	A. O. SMITH	0
5003	04/03/2007	LTN050G	LOCHINVAR	1
5004	08/12/1988	FSG50	AO SMITH	0
5005	05/16/2002	PGR50	AO SMITH	0
5006	09/07/2011	M45036FBN	BRADFORD-WHITE	0
5007	07/19/2007	LTN050G	LOCHINVAR	0
5008	02/17/1988	RF82156	RUUD	0
5009	10/15/2001	FSG40	AO SMITH	0
5010	10/11/2004	PRX50	STATE	0
5011	11/30/2005	LTN050GEF	LOCHINVAR	0
5012	10/23/2010	21DV50	RHEEM	0
5013	04/17/2004	PRX50	STATE	0
5014	11/07/2001	G75125	RUUD/RHEEM	1
5015	05/20/2011	21VR50	RHEEM	0
5016	02/08/2012	PH2DV50F	RUUD	1
5017	10/08/1987	FSG50	AO SMITH	0
5018	10/27/2008	LTN050GEF	LOCHINVAR	0
5019	01/09/2005	PRX40	STATE	0
5020	10/25/2010	21VR50	RHEEM	0
5021	03/08/2001	PGR50	AO SMITH	0
5022	08/03/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5023	07/27/1999	G91200	RUUD/RHEEM	0
5024	11/28/2005	LTN050G	LOCHINVAR	0
5025	06/30/2007	LSN041G	LOCHINVAR	0
5026	02/01/2013	MI5036FBN	BRADFORD-WHITE	0
5027	06/30/2002	PGR50	AO SMITH	0
5028	03/05/2009	LTN040GEF	LOCHINVAR	0
5029	10/09/1985	FSG50	AO SMITH	0
5030	08/06/2008	LTN050GEF	LOCHINVAR	0
5031	08/23/1998	41V50	RHEEM	0
5032	02/26/2011	21VR50	RHEEM	0
5033	04/04/2011	22DV50F	RHEEM	0
5034	11/05/2003	PGR50	AO SMITH	0
5035	07/20/2003	G91200	RUUD/RHEEM	1
5036	11/09/2007	PR650	STATE	2
5037	12/18/2006	LSN041G	LOCHINVAR	0
5038	08/11/2003	PRX50	STATE	2
5039	05/11/2010	22DV50F	RHEEM	2
5040	07/13/2010	LTN050GEF	LOCHINVAR	1
5041	10/13/2008	LTN050GEF	LOCHINVAR	1
5042	04/30/2009	LTN050GEF	LOCHINVAR	0
5043	03/20/2002	PGR50	AO SMITH	2
5044	05/23/2001	FSG50	AO SMITH	0
5045	05/31/1985	FSG50	AO SMITH	0
5046	09/25/2008	LTN050GEF	LOCHINVAR	2
5047	01/05/2003	G91200	RUUD/RHEEM	1
5048	06/21/2010	LTN050GEF	LOCHINVAR	1
5049	09/30/2009	LTN050GEF	LOCHINVAR	0
5050	03/01/2013	MI403S6FBN	BRADFORD WHITE	0
5051	09/06/2012	M45036FBN	BRADFORD-WHITE	0
5052	08/17/2006	LTN050GEF	LOCHINVAR	0
5053	03/30/2005	GVC50	A. O. SMITH	0
5054	03/01/2013	FSGL40	AO SMITH	0
5055	01/20/2011	41VR50	RHEEM	0
5056	06/17/2003	PR650	STATE	0
5057	12/19/2003	41XR50	RHEEM	0
5058	10/01/2004	LTN050G	LOCHINVAR	0
5059	03/10/2008	LTN050GEF	LOCHINVAR	0
5060	05/20/2005	LTN040GEF	LOCHINVAR	0
5061	04/21/2011	41VR50	RHEEM	0
5062	03/13/2002	FSG50	AO SMITH	0
5063	05/31/2000	PGR50	AO SMITH	0
5064	05/25/1999	21V506	RHEEM	0
5065	12/28/2007	PR640XODS	STATE	0
5066	12/14/2010	21VR50	RHEEM	0
5067	05/03/2002	PGR50	AO SMITH	0
5068	06/10/2003	FSG50	AO SMITH	0
5069	01/07/2002	FSG50	AO SMITH	0
5070	11/28/2011	MI5036FBN	BRADFORD-WHITE	0
5071	11/12/2009	LTN050GEF	LOCHINVAR	0
5072	07/01/2001	PGR50	AO SMITH	0
5073	04/20/2003	FSG50	AO SMITH	0
5074	01/17/2007	LTN050G	LOCHINVAR	0
5075	07/05/2003	PVR50	AO SMITH	0
5076	01/10/2002	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5077	05/30/2008	LSN041G	LOCHINVAR	0
5078	04/16/2012	M2XR504T6FBN	BRADFORD WHITE	0
5079	12/28/2001	41XR50	RHEEM	0
5080	11/23/1998	21V506	RHEEM	0
5081	10/07/2008	PGR50	AO SMITH	0
5082	08/20/2003	PRX50	STATE	0
5083	04/05/2006	LTN040G	LOCHINVAR	0
5084	06/15/2009	LTN050GEF	LOCHINVAR	0
5085	01/25/2002	FSG50	AO SMITH	0
5086	07/07/2004	GVC40	A. O. SMITH	0
5087	12/01/2011	M45036FBN	BRADFORD-WHITE	0
5088	06/17/2003	FSG50	AO SMITH	0
5089	12/09/1998	PR502T	RUUD	0
5090	05/22/2003	PRV50NODS	STATE	0
5091	03/06/2006	LTN051G	LOCHINVAR	0
5092	11/15/2012	PH2DV50F	RUUD	0
5093	03/04/2009	LTN050GEF	LOCHINVAR	0
5094	02/14/2011	22V50F1	RHEEM	0
5095	10/01/2011	M45036FBN	BRADFORD-WHITE	0
5096	09/15/2005	LTN050G	LOCHINVAR	0
5097	01/27/2004	FSG50	AO SMITH	1
5098	11/16/2012	MI5036FBN	BRADFORD-WHITE	0
5099	06/22/2011	MI5036FBN	BRADFORD-WHITE	0
5100	10/01/1996	PGR50	AO SMITH	0
5101	04/14/1997	FGR50	AO SMITH	0
5102	03/17/1987	FSG50	AO SMITH	0
5103	10/25/2002	PRX50	STATE	0
5104	04/24/2008	LTN050GEF	LOCHINVAR	0
5105	10/18/2005	LTN050G	LOCHINVAR	0
5106	12/08/2008	LTN050GEF	LOCHINVAR	1
5107	09/08/1999	41VR50	RHEEM	1
5108	08/11/2000	PRX50	STATE	1
5109	06/20/2008	LTN050GEF	LOCHINVAR	0
5110	11/30/2004	GVC40	A. O. SMITH	1
5111	07/19/2006	LTN050G	LOCHINVAR	0
5112	07/01/2003	PGR50	AO SMITH	0
5113	06/17/2005	LTN050	LOCHINVAR	0
5114	02/29/2012	M45036FBN	BRADFORD-WHITE	0
5115	08/22/1993	FSG50	AO SMITH	0
5116	01/12/2005	XVR50	A. O. SMITH	0
5117	02/13/2001	FSG50	AO SMITH	2
5118	02/27/2012	M45036FBN	BRADFORD-WHITE	1
5119	09/29/2008	G82156	RUUD/RHEEM	0
5120	08/30/2000	41XR50	RHEEM	0
5121	10/29/2011	FSG50	AO SMITH	0
5122	07/02/2001	FSG40	AO SMITH	0
5123	07/31/2004	XTN050	LOCHINVAR	0
5124	07/08/2006	LTN050G	LOCHINVAR	0
5125	05/23/2011	41VR50	RHEEM	0
5126	09/21/2006	LSN041G	LOCHINVAR	0
5127	01/11/1984	KGA50	AO SMITH	0
5128	03/31/2002	FSGL40	AO SMITH	1
5129	10/24/2009	LTN050GEF	LOCHINVAR	0
5130	04/03/2007	41V50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5131	08/26/2009	LTN050GEF	LOCHINVAR	0
5132	02/08/2010	LSN041G	LOCHINVAR	0
5133	04/04/2007	LTN040G	LOCHINVAR	0
5134	03/01/1983	FSG50	AO SMITH	0
5135	02/05/2002	FSGL40	AO SMITH	0
5136	07/02/1998	PRV40NODS	STATE	0
5137	01/02/1991	FSG50	AO SMITH	0
5138	08/09/1999	FGR50	AO SMITH	0
5139	10/20/2011	M45036FBN	BRADFORD-WHITE	0
5140	01/18/2008	LTN040GEF	LOCHINVAR	0
5141	10/30/2000	PGR50	AO SMITH	0
5142	10/11/2012	M440T6FBN	BRADFORD-WHITE	1
5143	07/01/2002	21V506	RHEEM	1
5144	08/23/2006	LTN040G	LOCHINVAR	0
5145	04/03/2012	M440T6FBN	BRADFORD-WHITE	0
5146	02/17/2006	LTN050G	LOCHINVAR	0
5147	08/18/2010	42VR50	RHEEM	0
5148	03/11/1997	PGR50	AO SMITH	0
5149	05/13/2008	LTN050G	LOCHINVAR	0
5150	02/21/2012	M45036FBN	BRADFORD-WHITE	0
5151	06/16/2005	LTN050	LOCHINVAR	0
5152	11/10/2005	LTN050G	LOCHINVAR	0
5153	10/26/2009	LSN041G	LOCHINVAR	0
5154	10/11/2011	PGR50	AO SMITH	1
5155	12/06/2002	PRX40	STATE	0
5156	01/22/2006	LTN050GEF	LOCHINVAR	0
5157	03/16/2004	PRX50	STATE	1
5158	05/25/2006	LTN040G	LOCHINVAR	0
5159	08/15/2005	LTN050G	LOCHINVAR	0
5160	04/07/2009	LTN050GEF	LOCHINVAR	0
5161	11/14/2008	LTN050GEF	LOCHINVAR	1
5162	02/29/2012	PH2DV50F	RUUD	0
5163	12/06/1985	FSG50	AO SMITH	0
5164	09/16/1999	FSGL40	AO SMITH	0
5165	08/26/2010	21VR50	RHEEM	0
5166	06/25/2006	LTN040G	LOCHINVAR	0
5167	12/06/1985	FSG50	AO SMITH	0
5168	02/10/2003	FSGL40	AO SMITH	0
5169	08/25/2011	MI5036FBN	BRADFORD-WHITE	0
5170	04/03/2001	41V50	RHEEM	0
5171	11/05/2001	PGR50	AO SMITH	0
5172	12/08/2005	LTN050GEF	LOCHINVAR	1
5173	07/19/2004	XVR50	A. O. SMITH	0
5174	01/11/2006	LTN050	LOCHINVAR	1
5175	04/23/2011	21DV50	RHEEM	0
5176	07/27/2009	LTN050G	LOCHINVAR	0
5177	11/12/2008	LTN050GEF	LOCHINVAR	0
5178	03/10/2009	LTN050G	LOCHINVAR	0
5179	12/16/2010	22DV50F	RHEEM	0
5180	04/10/2003	41V50	RHEEM	0
5181	10/24/2005	LTN040G	LOCHINVAR	0
5182	01/23/2009	LTN050GEF	LOCHINVAR	0
5183	03/07/2006	LTN050GEF	LOCHINVAR	0
5184	10/27/2006	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5185	06/07/1985	FSGL40	AO SMITH	0
5186	09/17/2008	LTN050GEF	LOCHINVAR	0
5187	03/12/1985	FSG50	AO SMITH	0
5188	03/13/2000	21V506	RHEEM	0
5189	04/02/1985	FSG50	AO SMITH	0
5190	06/13/2004	XSN040	LOCHINVAR	1
5191	01/15/2009	LTN050GEF	LOCHINVAR	0
5192	06/20/2011	M45036FBN	BRADFORD-WHITE	0
5193	12/14/2009	LTN050G	LOCHINVAR	1
5194	01/06/2005	GVR50	AO SMITH	0
5195	04/04/2003	PRX50	STATE	1
5196	06/13/2003	FSGL40	AO SMITH	0
5197	09/14/2004	GVC50	A. O. SMITH	0
5198	10/06/2010	42VR50	RHEEM	0
5199	09/11/2012	MI5036FBN	BRADFORD-WHITE	1
5200	10/19/2010	LSN041G	LOCHINVAR	0
5201	11/23/2009	LTN050GEF	LOCHINVAR	1
5202	04/03/2009	LTN050GEF	LOCHINVAR	0
5203	03/26/2003	FSG40	AO SMITH	0
5204	03/25/2010	LTN050GEF	LOCHINVAR	0
5205	08/01/2012	PH2DV50F	RUUD	0
5206	11/14/1997	FSGL40	AO SMITH	0
5207	06/03/1988	FSG50	AO SMITH	0
5208	06/01/2010	LTN050G	LOCHINVAR	0
5209	10/06/1998	FSG40	AO SMITH	0
5210	03/23/2007	FSG50	AO SMITH	0
5211	10/25/2004	LTN050	LOCHINVAR	0
5212	12/27/2001	41V50	RHEEM	0
5213	04/27/1988	FSG50	AO SMITH	0
5214	11/11/2009	LTN050GEF	LOCHINVAR	0
5215	08/09/1988	FSG50	AO SMITH	0
5216	06/09/2009	LTN050GEF	LOCHINVAR	1
5217	05/10/2005	FSG50	AO SMITH	1
5218	02/24/2010	22DV50C	RHEEM	0
5219	04/07/2011	22DV50F	RHEEM	0
5220	11/06/2006	LTN050GEF	LOCHINVAR	0
5221	02/02/2007	LTN050G	LOCHINVAR	0
5222	04/22/2011	22DV50F	RHEEM	0
5223	08/19/2008	LTN050GEF	LOCHINVAR	0
5224	09/13/2000	FGR50	AO SMITH	1
5225	09/01/2007	LTN050GEF	LOCHINVAR	0
5226	03/09/1996	FSGL40	AO SMITH	0
5227	09/19/2011	M45036FBN	BRADFORD-WHITE	0
5228	04/03/2002	PRX50	STATE	0
5229	02/13/2004	FSG50	AO SMITH	0
5230	03/24/2012	M45036FBN	BRADFORD-WHITE	2
5231	07/10/2002	PRX50	STATE	0
5232	04/25/2001	PGR50	AO SMITH	0
5233	09/08/1998	FSG40	AO SMITH	0
5234	07/25/2004	GVC50	A. O. SMITH	0
5235	12/27/2007	LTN050GEF	LOCHINVAR	1
5236	03/13/2008	42XR50	RHEEM	1
5237	11/10/2004	GVC50	A. O. SMITH	0
5238	10/23/2012	G91200	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5239	12/23/2011	M45036FBN	BRADFORD-WHITE	0
5240	07/13/2011	M45036FBN	BRADFORD-WHITE	1
5241	01/17/2013	PH2DV50F	RUUD	0
5242	07/17/2008	LTN040GEF	LOCHINVAR	0
5243	05/04/2010	LTN051G	LOCHINVAR	0
5244	08/24/2004	GVC50	A. O. SMITH	0
5245	09/17/1997	PGR40	AO SMITH	0
5246	09/08/2009	LTN050GEF	LOCHINVAR	0
5247	03/09/2007	XTN050	LOCHINVAR	0
5248	01/07/2009	22DV50C	RHEEM	0
5249	04/14/2007	LTN050GEF	LOCHINVAR	0
5250	04/16/2004	XVR50	A. O. SMITH	0
5251	01/04/2001	FSG50	AO SMITH	0
5252	01/21/2013	M45036FBN	BRADFORD-WHITE	0
5253	03/24/2009	22DV50C	RHEEM	0
5254	12/20/2011	M45036FBN	BRADFORD-WHITE	0
5255	11/26/2012	M45036FBN	BRADFORD-WHITE	0
5256	09/22/1998	FSG50	AO SMITH	0
5257	02/15/2013	M45036FBN	BRADFORD-WHITE	0
5258	08/30/1985	H72DUMMY	AO SMITH	0
5259	03/30/1999	FGR50	AO SMITH	0
5260	09/10/2009	22DV50C	RHEEM	0
5261	12/30/1992	FSG50	AO SMITH	0
5262	04/21/2010	LTN040GEF	LOCHINVAR	0
5263	05/06/1985	FSG50	AO SMITH	0
5264	05/30/2008	LTN050GEF	LOCHINVAR	0
5265	11/23/2011	M45036FBN	BRADFORD-WHITE	0
5266	02/24/2009	LTN050GEF	LOCHINVAR	0
5267	03/05/2007	GVC40	A. O. SMITH	1
5268	10/20/2012	M45036FBN	BRADFORD-WHITE	0
5269	02/06/2012	M440T6FBN	BRADFORD-WHITE	0
5270	03/10/2003	PGR50	AO SMITH	0
5271	04/30/2012	MI5036FBN	BRADFORD-WHITE	1
5272	04/11/2012	M45036FBN	BRADFORD-WHITE	1
5273	07/26/2004	GDVS50	AOSMITH	0
5274	06/26/2008	LTN050GEF	LOCHINVAR	1
5275	06/14/2012	M45036FBN	BRADFORD-WHITE	0
5276	08/17/2011	PH2DV50F	RUUD	0
5277	11/01/1985	FSG50	AO SMITH	0
5278	09/13/2012	MI40T6FBN	BRADFORD-WHITE	0
5279	04/01/2004	GCVL40	A. O. SMITH	0
5280	11/22/1999	PGR50	AO SMITH	0
5281	04/03/2006	LTN050G	LOCHINVAR	0
5282	05/30/2002	PGR50	AO SMITH	1
5283	04/30/2009	41V50	RHEEM	0
5284	09/27/2001	FSG50	AO SMITH	0
5285	09/08/2000	41XR50	RHEEM	0
5286	04/24/2005	PRX50	STATE	0
5287	07/10/1999	PRV50NODS	STATE	1
5288	01/12/2005	LTN050	LOCHINVAR	0
5289	01/12/2004	PVR50	AO SMITH	0
5290	01/14/2011	21VR50	RHEEM	1
5291	10/26/2001	FSG50	AO SMITH	0
5292	05/25/2000	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5293	02/06/2009	22DV50F	RHEEM	3
5294	09/23/2009	LTN050GEF	LOCHINVAR	0
5295	07/30/2011	M45036FBN	BRADFORD-WHITE	1
5296	11/04/2008	22DV50C	RHEEM	0
5297	03/18/1987	FSG50	AO SMITH	0
5298	03/22/2006	LTN050G	LOCHINVAR	0
5299	03/07/2013	MI5036FBN	BRADFORD-WHITE	0
5300	12/27/2012	M45036FBN	BRADFORD-WHITE	0
5301	10/05/2011	M440T6FBN	BRADFORD-WHITE	0
5302	01/27/2006	LTN050G	LOCHINVAR	1
5303	08/15/1999	41VR50	RHEEM	0
5304	09/20/2000	41XR50	RHEEM	0
5305	12/10/1998	FGR50	AO SMITH	0
5306	01/05/2006	PR650	STATE	0
5307	02/12/1987	FSG50	AO SMITH	0
5308	02/23/2009	FSG30	AO SMITH	0
5309	03/04/2010	LTN050GEF	LOCHINVAR	0
5310	11/26/2007	G82156	RUUD/RHEEM	0
5311	03/20/2008	22DV50C	RHEEM	0
5312	04/01/2003	FSGL40	AO SMITH	0
5313	03/18/2008	LTN050GEF	LOCHINVAR	0
5314	05/26/2009	LTN050GEF	LOCHINVAR	0
5315	04/28/2009	LTN040G	LOCHINVAR	0
5316	02/26/2007	LTN050G	LOCHINVAR	0
5317	05/21/2002	FSG50	AO SMITH	0
5318	06/27/2012	MI40T6FBN	BRADFORD-WHITE	0
5319	06/10/2008	LTN050GEF	LOCHINVAR	0
5320	10/25/2002	PGR50	AO SMITH	0
5321	05/26/1998	FSG50	AO SMITH	0
5322	07/22/2004	GDVS50	AOSMITH	0
5323	12/13/2000	41VR50	RHEEM	0
5324	09/03/1996	FSGL40	AO SMITH	1
5325	04/06/2005	FCVL40	AO SMITH	0
5326	08/04/2009	LTN050GEF	LOCHINVAR	0
5327	03/08/2011	41VR40	RHEEM	0
5328	11/27/1998	PHR50	RUUD	0
5329	05/06/2001	41XR50	RHEEM	0
5330	11/29/2002	FSG50	AO SMITH	1
5331	09/04/2007	LTN050GEF	LOCHINVAR	0
5332	02/16/2010	LTN050GEF	LOCHINVAR	0
5333	08/28/2008	LTN050GEF	LOCHINVAR	0
5334	07/25/1997	FSGL40	AO SMITH	1
5335	06/26/2009	LTN040GEF	LOCHINVAR	2
5336	07/30/2007	LTN050GEF	LOCHINVAR	0
5337	03/14/2000	FSGL40	AO SMITH	0
5338	02/14/2006	LTN050G	LOCHINVAR	0
5339	08/23/2006	LTN040G	LOCHINVAR	0
5340	09/27/2002	FSG50	AO SMITH	0
5341	07/01/2011	22DV50F	RHEEM	1
5342	09/17/2007	LTN050GEF	LOCHINVAR	0
5343	02/07/1997	FGR40	AO SMITH	0
5344	02/13/2013	M45036FBN	BRADFORD-WHITE	0
5345	06/07/1999	FSG50	AO SMITH	1
5346	08/07/1995	41XR40	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5347	09/02/1997	FSG50	AO SMITH	0
5348	10/23/1995	41XR40	RHEEM	0
5349	06/03/1992	E71DUMMY	AO SMITH	0
5350	06/09/2006	LTN050G	LOCHINVAR	2
5351	05/13/2002	PGR40	AO SMITH	0
5352	07/23/2010	G91200	RUUD/RHEEM	3
5353	03/02/2007	LTN050G	LOCHINVAR	0
5354	02/12/2010	LTN050GEF	LOCHINVAR	0
5355	11/22/2006	LTN050G	LOCHINVAR	0
5356	05/16/2002	PGR50	AO SMITH	0
5357	02/07/2003	PGR50	AO SMITH	0
5358	09/23/1997	FGR50	AO SMITH	0
5359	09/10/1997	FGR50	AO SMITH	1
5360	04/05/2004	PVR50	AO SMITH	0
5361	02/14/1999	FSG50	AO SMITH	0
5362	07/03/2006	LTN050G	LOCHINVAR	0
5363	01/17/2012	MI5036FBN	BRADFORD-WHITE	0
5364	03/10/2005	GVC50	A. O. SMITH	0
5365	08/17/2012	MI403S6FBN	BRADFORD-WHITE	0
5366	10/23/2012	G76200	RUUD/RHEEM	0
5367	04/06/2009	LTN050GEF	LOCHINVAR	0
5368	10/15/2007	LTN050G	LOCHINVAR	0
5369	07/18/2008	LTN050GEF	LOCHINVAR	0
5370	11/18/2008	LTN050GEF	LOCHINVAR	0
5371	06/05/2001	FSG50	AO SMITH	0
5372	08/17/2004	GVC50	A. O. SMITH	0
5373	12/17/1987	FSG50	AO SMITH	0
5374	03/16/2006	LTN050G	LOCHINVAR	0
5375	10/07/2011	M45036FBN	BRADFORD-WHITE	0
5376	03/24/2008	LTN050GEF	LOCHINVAR	0
5377	03/08/1988	FSG50	AO SMITH	0
5378	09/21/2005	LTN050GEF	LOCHINVAR	0
5379	04/22/2002	PGR50	AO SMITH	1
5380	08/28/2007	G91200	RUUD/RHEEM	0
5381	05/08/2006	LTN050GEF	LOCHINVAR	0
5382	02/04/1988	FSG50	AO SMITH	0
5383	03/14/2008	LTN050GEF	LOCHINVAR	1
5384	02/09/2011	22DV50F	RHEEM	0
5385	11/07/2001	PGR50	AO SMITH	0
5386	01/27/2011	42VR50	RHEEM	0
5387	05/24/2009	LTN050G	LOCHINVAR	0
5388	02/27/1999	41VR50	RHEEM	0
5389	04/20/2006	LTN040G	LOCHINVAR	0
5390	05/15/2003	FSG50	AO SMITH	0
5391	05/09/2005	LTN050	LOCHINVAR	1
5392	03/06/2007	LTN050GEF	LOCHINVAR	1
5393	02/17/2010	21V502	RHEEM	0
5394	03/02/2013	M45036FBN	BRADFORD-WHITE	0
5395	12/08/2008	LTN050GEF	LOCHINVAR	0
5396	01/21/2002	41VR50	RHEEM	0
5397	11/21/2008	LTN050G	LOCHINVAR	0
5398	11/10/2006	LSN041G	LOCHINVAR	1
5399	04/09/2012	MI5036FBN	BRADFORD-WHITE	0
5400	08/08/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5401	09/10/2007	LTN050G	LOCHINVAR	0
5402	02/02/1988	FSG50	AO SMITH	0
5403	10/18/2010	42VR50	RHEEM	0
5404	10/17/2007	LTN050G	LOCHINVAR	0
5405	03/25/2000	41XR50	RHEEM	0
5406	01/27/2010	LTN050GEF	LOCHINVAR	0
5407	08/18/2005	LTN050	LOCHINVAR	0
5408	09/20/2007	LTN050GEF	LOCHINVAR	0
5409	09/28/2009	LTN050GEF	LOCHINVAR	0
5410	09/20/2010	41VR50	RHEEM	0
5411	06/03/1988	FSGL30	AO SMITH	0
5412	02/14/2006	LTN050GEF	LOCHINVAR	0
5413	12/16/1985	FSG40	AO SMITH	0
5414	03/20/2001	41V50	RHEEM	0
5415	10/29/2005	PR650	STATE	0
5416	06/17/2002	FSG50	AO SMITH	1
5417	12/06/1999	PHR50	RUUD	0
5418	01/23/2007	LTN050G	LOCHINVAR	0
5419	11/17/2008	LTN050GEF	LOCHINVAR	0
5420	06/03/2005	LTN050GEF	LOCHINVAR	1
5421	04/14/2011	PGR50	AO SMITH	0
5422	01/21/2006	LSN041G	LOCHINVAR	0
5423	06/27/2000	FSG40	AO SMITH	0
5424	11/16/2010	21DV50	RHEEM	0
5425	10/09/2005	LTN050G	LOCHINVAR	0
5426	06/22/2006	LSN041G	LOCHINVAR	0
5427	11/01/2003	FCV50	AO SMITH	0
5428	12/07/1999	PGR50	AO SMITH	0
5429	03/22/2004	FCV50	AO SMITH	0
5430	12/23/2009	LTN050G	LOCHINVAR	0
5431	01/16/2001	FSG40	AO SMITH	0
5432	10/16/2002	FSG50	AO SMITH	0
5433	04/30/2004	PRX40	STATE	1
5434	09/10/2005	GVC50	A. O. SMITH	0
5435	05/13/1986	PRV50NODS	STATE	0
5436	02/03/2001	41XR40	RHEEM	1
5437	03/14/1999	FGR50	AO SMITH	0
5438	05/15/2012	MI403S6FBN	BRADFORD-WHITE	0
5439	06/02/2012	M45036FBN	BRADFORD-WHITE	0
5440	03/02/2013	MI5036FBN	BRADFORD-WHITE	0
5441	03/17/2009	LTN040G	LOCHINVAR	0
5442	02/15/2011	42VR5040F	RHEEM	0
5443	03/03/2008	LTN050GEF	LOCHINVAR	0
5444	04/29/2009	LTN050G	LOCHINVAR	0
5445	11/28/2012	M45036FBN	BRADFORD-WHITE	0
5446	06/17/2005	LTN050	LOCHINVAR	0
5447	07/05/2006	PR640	STATE	1
5448	05/11/1994	PRV40NODS	STATE	0
5449	02/29/2008	LTN050GEF	LOCHINVAR	0
5450	01/10/2002	FSG50	AO SMITH	0
5451	05/02/2011	41VR50	RHEEM	0
5452	02/09/1996	PRX50	STATE	0
5453	06/29/2001	PGR50	AO SMITH	0
5454	04/22/1997	FSG40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5455	10/21/2002	PGR50	AO SMITH	0
5456	04/12/2005	GVC50	A. O. SMITH	0
5457	04/26/2012	MI5036FBN	BRADFORD-WHITE	1
5458	07/08/2010	LTN050GEF	LOCHINVAR	0
5459	07/01/1986	G72DUMMY	UNKNOWN AT CONVERSION	0
5460	09/25/1997	41VR50	RHEEM	0
5461	02/19/2012	PH2DV50F	RUUD	0
5462	12/20/2011	MI5036FBN	BRADFORD-WHITE	0
5463	07/04/2005	LTN050G	LOCHINVAR	0
5464	02/17/2008	LTN050	LOCHINVAR	0
5465	08/16/2010	21V502	RHEEM	0
5466	06/23/2004	GVC50	A. O. SMITH	1
5467	06/01/2010	LTN050GEF	LOCHINVAR	0
5468	02/27/2007	LTN050G	LOCHINVAR	0
5469	10/24/2000	PGR50	AO SMITH	0
5470	02/12/2008	LSN041G	LOCHINVAR	0
5471	10/12/2005	LSN041G	LOCHINVAR	0
5472	01/12/2011	42VR50	RHEEM	1
5473	10/31/2002	FSG40	AO SMITH	0
5474	05/20/2010	LTN050G	LOCHINVAR	0
5475	03/14/2013	M440T6FBN	BRADFORD-WHITE	0
5476	09/28/2011	22DV50F	RHEEM	0
5477	07/08/2008	LTN050GEF	LOCHINVAR	0
5478	09/10/2008	LTN050GEF	LOCHINVAR	0
5479	01/21/2006	LTN050GEF	LOCHINVAR	0
5480	08/06/2011	M45036FBN	BRADFORD-WHITE	0
5481	01/30/2013	MI403S6FBN	BRADFORD-WHITE	2
5482	06/21/2010	22DV50F	RHEEM	2
5483	12/27/2008	LTN050GEF	LOCHINVAR	1
5484	01/27/2004	PVR50	AO SMITH	1
5485	01/18/2003	FSG40	AO SMITH	1
5486	11/07/1986	FSG50	AO SMITH	0
5487	12/10/2007	LTN050GEF	LOCHINVAR	0
5488	09/01/2007	LTN040G	LOCHINVAR	0
5489	07/21/2010	21DV50	RHEEM	0
5490	08/08/2001	PRX50	STATE	0
5491	05/18/2009	LTN050GEF	LOCHINVAR	0
5492	04/29/2009	LTN050GEF	LOCHINVAR	0
5493	09/19/2005	PR650	STATE	0
5494	04/15/2005	FCV40	AO SMITH	0
5495	05/07/2004	CPN199100	LOCHINVAR	0
5496	03/12/2007	LTN050G	LOCHINVAR	0
5497	06/29/2012	M45036FBN	BRADFORD-WHITE	0
5498	05/28/2002	PGR50	AO SMITH	0
5499	12/27/2010	41VR50	RHEEM	0
5500	11/04/1992	P506	RUUD	0
5501	10/19/2012	MI50L6FBN	BRADFORD-WHITE	0
5502	08/28/2011	M45036FBN	BRADFORD-WHITE	0
5503	04/07/2005	GCVL40	A. O. SMITH	0
5504	02/11/2008	LTN040G	LOCHINVAR	0
5505	08/29/2003	G82156	RUUD/RHEEM	1
5506	01/26/2009	LSN041G	LOCHINVAR	0
5507	11/19/2007	LTN050GEF	LOCHINVAR	0
5508	04/19/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5509	05/01/2001	FSG50	AO SMITH	0
5510	06/22/2004	GCVL40	A. O. SMITH	0
5511	01/20/2000	41XR40	RHEEM	0
5512	08/07/2000	G76200	RUUD/RHEEM	6
5513	10/08/2011	M45036FBN	BRADFORD-WHITE	1
5514	04/12/2010	LTN040G	LOCHINVAR	0
5515	12/29/2011	G91200	RUUD/RHEEM	0
5516	10/04/2007	LTN050GEF	LOCHINVAR	0
5517	03/28/1996	PGR40	AO SMITH	0
5518	08/04/2007	LTN050GEF	LOCHINVAR	0
5519	07/21/2010	LSN041	LOCHINVAR	0
5520	10/13/2000	FSG50	AO SMITH	0
5521	10/23/2009	PGX50	AO SMITH	0
5522	11/23/2011	M45036FBN	BRADFORD-WHITE	0
5523	06/14/2010	LTN050GEF	LOCHINVAR	0
5524	08/08/2011	MI50L6FBN	BRADFORD-WHITE	0
5525	11/27/2001	41XR50	RHEEM	0
5526	07/21/2000	FSG40	AO SMITH	1
5527	01/24/2001	FSG30	AO SMITH	0
5528	11/13/2003	FSGL30	AO SMITH	1
5529	04/04/2000	FSG50	AO SMITH	0
5530	08/03/2010	LTN050GEF	LOCHINVAR	1
5531	09/13/1983	FSG50	AO SMITH	0
5532	01/07/2002	PGR50	AO SMITH	0
5533	10/26/2007	LSN041G	LOCHINVAR	0
5534	04/10/2006	LTN040G	LOCHINVAR	0
5535	07/01/1986	G72DUMMY	UNKNOWN AT CONVERSION	0
5536	02/22/2007	LTN050G	LOCHINVAR	0
5537	08/17/2009	LTN050G	LOCHINVAR	0
5538	05/30/2012	M45036FBN	BRADFORD-WHITE	0
5539	11/27/2012	MI40T6FBN	BRADFORD-WHITE	0
5540	03/15/1985	FSG50	AO SMITH	0
5541	01/11/2006	LTN051G	LOCHINVAR	0
5542	08/29/2008	LTN050GEF	LOCHINVAR	0
5543	04/26/2002	PRX50	STATE	0
5544	06/21/2006	CPN13585FS	LOCHINVAR	3
5545	01/14/2010	LTN050GEF	LOCHINVAR	1
5546	12/28/2004	LTN050	LOCHINVAR	0
5547	04/26/1996	PGR50	AO SMITH	0
5548	09/14/2005	LTN050G	LOCHINVAR	1
5549	10/17/2010	21VR50	RHEEM	1
5550	07/21/2005	LSN041G	LOCHINVAR	0
5551	09/30/2005	LTN050G	LOCHINVAR	0
5552	10/08/2008	LTN050GEF	LOCHINVAR	0
5553	06/13/2012	PH2DV50F	RUUD	0
5554	04/04/1986	FSG50	AO SMITH	0
5555	05/19/1998	FSG40	AO SMITH	0
5556	11/30/2009	LTN050GEF	LOCHINVAR	0
5557	12/20/2005	LTN050G	LOCHINVAR	0
5558	12/15/2008	LTN050GEF	LOCHINVAR	0
5559	10/29/1988	FSG50	AO SMITH	0
5560	07/15/2010	LTN050GEF	LOCHINVAR	0
5561	04/03/2008	LTN050GEF	LOCHINVAR	0
5562	01/20/2011	21VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5563	06/11/2009	LTN040GEF	LOCHINVAR	2
5564	11/09/2002	FSG50	AO SMITH	0
5565	04/26/2004	PVR50	AO SMITH	0
5566	08/18/2000	FSG50	AO SMITH	0
5567	02/17/2004	FCV40	AO SMITH	0
5568	12/19/2011	MI50L6FBN	BRADFORD-WHITE	0
5569	04/12/2001	PGR50	AO SMITH	0
5570	01/30/2006	LTN040G	LOCHINVAR	0
5571	12/06/1999	PR650	STATE	0
5572	02/06/2006	LSN041G	LOCHINVAR	0
5573	01/20/2009	LTN050GEF	LOCHINVAR	1
5574	09/11/2002	FSG50	AO SMITH	0
5575	11/12/2003	FSGL40	AO SMITH	0
5576	04/16/2008	LTN050GEF	LOCHINVAR	1
5577	02/19/2011	21VR50	RHEEM	0
5578	02/18/2011	42VR50	RHEEM	0
5579	01/07/2002	PGR50	AO SMITH	0
5580	10/30/2007	LTN050GEF	LOCHINVAR	0
5581	10/10/2002	PGR50	AO SMITH	0
5582	10/20/2003	FCV50	AO SMITH	0
5583	11/03/2006	LTN050G	LOCHINVAR	0
5584	02/18/2009	22DV50C	RHEEM	0
5585	08/21/2003	PR650	STATE	0
5586	08/23/2010	LTN050GEF	LOCHINVAR	0
5587	09/19/2003	21V506	RHEEM	0
5588	07/16/2012	PH2DV50F	RUUD	0
5589	12/21/2009	LTN050GEF	LOCHINVAR	0
5590	09/08/2012	MI40T6FBN	BRADFORD-WHITE	1
5591	06/20/2005	LTN050	LOCHINVAR	1
5592	07/15/2009	LTN050G	LOCHINVAR	0
5593	09/01/1988	FSG50	AO SMITH	0
5594	01/08/2012	MI5036FBN	BRADFORD-WHITE	0
5595	04/05/2008	LTN050GEF	LOCHINVAR	1
5596	10/27/2002	FSG50	AO SMITH	0
5597	02/21/1998	FSG50	AO SMITH	0
5598	05/13/2004	FSGT50	AO SMITH	0
5599	03/22/2011	P506	RUUD	0
5600	03/06/2013	MI5036FBN	BRADFORD-WHITE	1
5601	03/20/1999	FGR50	AO SMITH	0
5602	12/03/2002	PRX50	STATE	0
5603	10/21/1987	H72DUMMY	AO SMITH	0
5604	04/29/2009	LTN050G	LOCHINVAR	0
5605	09/20/1988	FSG50	AO SMITH	0
5606	07/06/1999	FSG50	AO SMITH	0
5607	04/02/2007	LTN050G	LOCHINVAR	0
5608	08/30/2006	LTN040G	LOCHINVAR	0
5609	07/18/2006	LTN050G	LOCHINVAR	1
5610	04/01/2006	LTN050GEF	LOCHINVAR	0
5611	07/09/2011	22DV50F	RHEEM	0
5612	12/15/2006	LTN050G	LOCHINVAR	0
5613	01/15/2006	LTN040G	LOCHINVAR	0
5614	12/17/2010	21VR50	RHEEM	0
5615	05/22/2000	BTR120	AO SMITH	0
5616	03/25/2008	LTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5617	05/21/2000	41XR50	RHEEM	0
5618	01/27/2000	G75125	RUUD/RHEEM	0
5619	06/04/2001	FSG50	AO SMITH	0
5620	02/16/2010	LTN050GEF	LOCHINVAR	0
5621	08/18/2004	GVC50	A. O. SMITH	0
5622	02/17/2010	LSN041G	LOCHINVAR	0
5623	06/14/2006	LTN050G	LOCHINVAR	0
5624	06/18/2008	LTN040G	LOCHINVAR	1
5625	07/27/2005	LTN050GEF	LOCHINVAR	0
5626	12/27/1999	41XR50	RHEEM	0
5627	03/08/2005	GVC40	A. O. SMITH	0
5628	12/26/2003	PRX50	STATE	0
5629	09/17/2002	FSG50	AO SMITH	0
5630	12/31/2008	LTN050	LOCHINVAR	0
5631	08/25/2008	22DV50F	RHEEM	0
5632	01/12/2004	PRX50	STATE	2
5633	06/23/2011	MI5036FBN	BRADFORD-WHITE	0
5634	12/10/2003	PGR50	AO SMITH	1
5635	08/20/2010	21VR50	RHEEM	0
5636	04/28/2006	LTN050	LOCHINVAR	0
5637	04/16/2008	LTN050GEF	LOCHINVAR	0
5638	05/01/2001	PRX50	STATE	0
5639	09/09/2002	PGR50	AO SMITH	1
5640	02/12/2013	MI403S6FBN	BRADFORD-WHITE	0
5641	03/18/2004	PRX50	STATE	0
5642	07/24/1996	G76200	RUUD/RHEEM	1
5643	11/12/2002	PGR50	AO SMITH	0
5644	04/29/2008	LTN050GEF	LOCHINVAR	0
5645	08/23/2006	LTN050G	LOCHINVAR	2
5646	01/26/2010	FSG50	AO SMITH	0
5647	06/22/2011	M45036FBN	BRADFORD-WHITE	0
5648	10/30/2003	FCV50	AO SMITH	0
5649	12/01/2003	G82156	RUUD/RHEEM	1
5650	01/07/2009	22DV50C	RHEEM	0
5651	12/11/2008	G91200	RUUD/RHEEM	1
5652	01/14/2010	LTN050GEF	LOCHINVAR	0
5653	12/12/2012	M45036FBN	BRADFORD-WHITE	0
5654	12/25/2011	MI5036FBN	BRADFORD-WHITE	0
5655	02/06/2001	PRV50NODS	STATE	0
5656	12/29/1997	PGR50	AO SMITH	0
5657	01/05/2001	41XR50	RHEEM	0
5658	03/12/2009	LTN050G	LOCHINVAR	0
5659	11/12/2009	22DV50C	RHEEM	0
5660	07/19/2006	LTN050G	LOCHINVAR	0
5661	01/26/2007	LTN050G	LOCHINVAR	0
5662	11/21/2000	PRX50	STATE	0
5663	02/02/2009	LTN050GEF	LOCHINVAR	0
5664	02/12/2013	PH2DV50F	RUUD	0
5665	10/01/2002	41XR50	RHEEM	0
5666	10/06/2010	42VR50	RHEEM	0
5667	12/28/2004	XVR50	A. O. SMITH	0
5668	11/17/2005	LTN050G	LOCHINVAR	1
5669	12/14/2001	FSG50	AO SMITH	1
5670	10/03/2006	G82156	RUUD/RHEEM	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5671	09/24/2002	FSG50	AO SMITH	0
5672	12/05/2005	LTN050	LOCHINVAR	0
5673	01/04/2007	LTN050GEF	LOCHINVAR	0
5674	01/17/2008	LTN050GEF	LOCHINVAR	0
5675	08/03/2000	41XR50	RHEEM	0
5676	03/28/2011	21VR40	RHEEM	0
5677	09/16/2010	21V502	RHEEM	0
5678	03/10/2011	21VR40	RHEEM	0
5679	06/13/2010	LTN050GEF	LOCHINVAR	0
5680	11/06/2006	PR650	STATE	0
5681	11/07/2012	M45036FBN	BRADFORD-WHITE	3
5682	05/20/2003	PGR50	AO SMITH	0
5683	09/15/2002	FSG30	AO SMITH	0
5684	01/21/2008	LTN050GEF	LOCHINVAR	1
5685	05/24/1999	FSG50	AO SMITH	0
5686	05/07/1985	FSG50	AO SMITH	1
5687	06/17/2004	GVC50	A. O. SMITH	0
5688	12/01/2008	22DV50C	RHEEM	0
5689	02/24/2009	LTN050GEF	LOCHINVAR	1
5690	04/13/2010	LTN050GEF	LOCHINVAR	0
5691	06/29/2008	LTN050GEF	LOCHINVAR	0
5692	05/23/2007	XSN040	LOCHINVAR	0
5693	11/25/1997	PGR50	AO SMITH	0
5694	06/25/2010	LTN050G	LOCHINVAR	0
5695	04/09/2000	PRX50	STATE	0
5696	05/27/2011	21VR40	RHEEM	0
5697	02/04/2005	XTN050	LOCHINVAR	1
5698	09/20/1988	FSG50	AO SMITH	0
5699	09/28/2011	MI5036FBN	BRADFORD-WHITE	0
5700	10/03/2005	LTN050G	LOCHINVAR	0
5701	01/20/2005	GVR50	AO SMITH	0
5702	03/12/2009	LTN050GEF	LOCHINVAR	0
5703	12/22/2010	21VR50	RHEEM	0
5704	07/17/1986	FSG50	AO SMITH	0
5705	04/26/2002	FSG50	AO SMITH	0
5706	09/05/2001	FSG50	AO SMITH	0
5707	05/21/2007	LTN050GEF	LOCHINVAR	0
5708	01/03/2011	21VR50	RHEEM	1
5709	11/12/2007	LTN050G	LOCHINVAR	0
5710	01/14/2010	LTN050GEF	LOCHINVAR	0
5711	08/24/1998	FSG50	AO SMITH	1
5712	09/10/2009	21VR50	RHEEM	0
5713	03/01/2001	41XR50	RHEEM	0
5714	04/08/2005	XVR50	A. O. SMITH	0
5715	08/22/2005	LTN050G	LOCHINVAR	0
5716	06/05/2006	LTN050G	LOCHINVAR	1
5717	03/16/2009	LSN041G	LOCHINVAR	0
5718	02/13/2012	MI75S6FBN	BRADFORD-WHITE	2
5719	05/13/2010	LTN050G	LOCHINVAR	0
5720	04/03/2002	FSG50	AO SMITH	0
5721	03/27/1996	RF67120	RUUD	0
5722	01/16/1984	FSG40	AO SMITH	0
5723	10/13/2005	LTN050GEF	LOCHINVAR	0
5724	11/09/2009	LTN040GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5725	01/03/2003	PGR50	AO SMITH	0
5726	02/07/2012	G82156	RUUD/RHEEM	0
5727	02/03/2006	LTN040G	LOCHINVAR	0
5728	02/21/2009	LTN050G	LOCHINVAR	0
5729	02/21/2003	FSG40	AO SMITH	0
5730	05/29/2007	G91200	RUUD/RHEEM	0
5731	04/25/2005	SBF100199NES	STATE	0
5732	06/13/2011	M45036FBN	BRADFORD-WHITE	0
5733	07/06/2012	M45036FBN	BRADFORD-WHITE	0
5734	01/21/2010	LTN050GEF	LOCHINVAR	0
5735	06/07/2000	G75125	RUUD/RHEEM	0
5736	08/24/2009	LTN050GEF	LOCHINVAR	2
5737	04/29/1998	FGR50	AO SMITH	0
5738	07/29/2010	41V50	RHEEM	0
5739	02/13/1985	FSG50	AO SMITH	0
5740	07/28/2010	21V502	RHEEM	0
5741	11/16/2004	42V6050	RHEEM	0
5742	06/30/2011	MI5036FBN	BRADFORD-WHITE	0
5743	08/01/2012	P230F	RUUD	1
5744	07/14/2005	LTN050	LOCHINVAR	0
5745	05/14/2002	PGR50	AO SMITH	0
5746	10/30/1996	PGR50	AO SMITH	0
5747	02/25/2002	FSG50	AO SMITH	1
5748	01/27/2003	FSG50	AO SMITH	0
5749	08/20/2002	FSG50	AO SMITH	0
5750	02/01/2008	LTN050GEF	LOCHINVAR	0
5751	11/10/2005	LTN050G	LOCHINVAR	0
5752	04/23/2004	XSN040	LOCHINVAR	0
5753	10/16/2006	PR650	STATE	0
5754	05/07/2009	LTN050G	LOCHINVAR	0
5755	12/08/2007	21V506	RHEEM	0
5756	04/22/2005	LTN050	LOCHINVAR	0
5757	10/18/2002	PRX50	STATE	1
5758	02/06/2013	M45036FBN	BRADFORD-WHITE	0
5759	04/11/1991	FSG50	AO SMITH	0
5760	07/21/2008	PR650	STATE	1
5761	08/15/2005	LTN050G	LOCHINVAR	0
5762	05/26/2006	PR650	STATE	0
5763	11/30/1987	PRV50NODS	STATE	0
5764	05/31/2005	G91200	RUUD/RHEEM	0
5765	11/09/2012	MI5036FBN	BRADFORD-WHITE	0
5766	02/20/2007	LTN050GEF	LOCHINVAR	0
5767	10/23/2012	PH2DV50F	RUUD	0
5768	01/06/2001	PR650	STATE	0
5769	10/28/2009	22DV50C	RHEEM	0
5770	05/24/2010	LTN040GEF	LOCHINVAR	0
5771	11/19/1987	FSG50	AO SMITH	0
5772	07/31/2010	PH199119	PHOENIX	11
5773	06/06/1988	FSG50	AO SMITH	0
5774	06/13/2011	22DV50F	RHEEM	0
5775	12/05/2007	LTN050GEF	LOCHINVAR	0
5776	07/03/2004	GVC50	A. O. SMITH	1
5777	04/06/2007	LTN050G	LOCHINVAR	0
5778	12/01/2010	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5779	03/01/1988	FSG50	AO SMITH	0
5780	11/01/2006	LTN050G	LOCHINVAR	0
5781	05/21/2007	LTN050GEF	LOCHINVAR	0
5782	07/10/2006	LTN050G	LOCHINVAR	1
5783	06/03/1988	G67114	RHEEM	0
5784	04/08/2008	LTN050GEF	LOCHINVAR	0
5785	02/17/2012	MI5036FBN	BRADFORD-WHITE	0
5786	07/31/2007	LTN050GEF	LOCHINVAR	0
5787	10/15/2002	FSG50	AO SMITH	0
5788	12/14/2001	PGR50	AO SMITH	0
5789	11/18/1985	FSG50	AO SMITH	0
5790	01/04/2001	41V50	RHEEM	0
5791	09/30/2011	PH250SF	RUUD	0
5792	10/19/2006	LTN050GEF	LOCHINVAR	0
5793	10/08/2010	21VR50	RHEEM	0
5794	03/04/2012	MI5036FBN	BRADFORD-WHITE	0
5795	10/31/2008	PR640	STATE	0
5796	01/06/1998	FSG30	AO SMITH	0
5797	12/19/2002	PRX50	STATE	0
5798	09/22/2011	M45036FBN	BRADFORD-WHITE	0
5799	08/13/1997	SBF100199NES	STATE	0
5800	06/20/2008	LTN050GEF	LOCHINVAR	0
5801	01/12/1999	PR650	STATE	0
5802	03/01/2005	XVR50	A. O. SMITH	0
5803	01/10/1986	PRX50	STATE	0
5804	07/09/2011	22DV50F	RHEEM	0
5805	01/28/2013	MI50L6FBN	BRADFORD-WHITE	2
5806	02/12/2013	MI5036FBN	BRADFORD-WHITE	0
5807	09/07/2008	22DV50C	RHEEM	0
5808	08/29/2012	MI5036FBN	BRADFORD-WHITE	1
5809	07/21/2012	FSG50	AO SMITH	1
5810	11/22/2005	LTN050GEF	LOCHINVAR	0
5811	10/03/2012	M45036FBN	BRADFORD-WHITE	0
5812	01/25/2012	PR502T	RUUD	0
5813	09/10/2008	ETN076	LOCHINVAR	0
5814	06/24/1985	FSG40	AO SMITH	0
5815	02/14/2007	LTN050G	LOCHINVAR	0
5816	01/29/2011	LTN040GEF	LOCHINVAR	0
5817	11/16/2006	LTN051G	LOCHINVAR	0
5818	10/04/2006	SBF100199NES	STATE	0
5819	06/04/2009	LTN050GEF	LOCHINVAR	0
5820	09/19/2011	PH2DV50F	RUUD	1
5821	01/18/2009	22DV50F	RHEEM	1
5822	10/20/2009	LTN050GEF	LOCHINVAR	0
5823	11/09/2010	41VR50	RHEEM	0
5824	03/11/2003	PRX50	STATE	1
5825	12/30/2011	M45036FBN	BRADFORD-WHITE	0
5826	07/26/2002	G82156	RUUD/RHEEM	1
5827	11/06/2001	PGR50	AO SMITH	0
5828	09/28/2001	PGR50	AO SMITH	0
5829	03/09/2007	LTN050GEF	LOCHINVAR	0
5830	11/18/2010	41VR50	RHEEM	0
5831	11/03/2009	G82156	RUUD/RHEEM	0
5832	02/12/2002	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5833	09/03/2008	22DV50F	RHEEM	2
5834	03/09/2007	LTN040G	LOCHINVAR	0
5835	06/29/2006	LTN040G	LOCHINVAR	0
5836	04/18/2002	PGR50	AO SMITH	0
5837	09/25/2009	LTN050GEF	LOCHINVAR	0
5838	01/16/2003	FCV50	AO SMITH	0
5839	01/16/2000	FSG30	AO SMITH	0
5840	02/03/2006	LTN050G	LOCHINVAR	0
5841	04/24/2003	PGR50	AO SMITH	0
5842	08/11/1987	21V506	RHEEM	0
5843	09/28/2005	LTN050G	LOCHINVAR	0
5844	12/19/2005	LTN040G	LOCHINVAR	0
5845	01/25/1999	FSGL40	AO SMITH	0
5846	11/20/2001	FSG50	AO SMITH	0
5847	08/06/2004	XVR50	A. O. SMITH	0
5848	12/02/1998	FSG50	AO SMITH	0
5849	04/29/2005	PRX50	STATE	0
5850	04/30/1997	PGR50	AO SMITH	0
5851	06/05/2009	LSN041G	LOCHINVAR	0
5852	12/08/2010	42VR50	RHEEM	0
5853	08/27/2004	XTN050	LOCHINVAR	0
5854	09/22/2004	FSG50	AO SMITH	0
5855	11/28/2012	M45036FBN	BRADFORD-WHITE	0
5856	09/19/2008	LTN050G	LOCHINVAR	0
5857	06/19/2008	LTN050G	LOCHINVAR	0
5858	07/13/2010	FSGL40	AO SMITH	0
5859	06/09/2012	M45036FBN	BRADFORD-WHITE	0
5860	08/18/2004	21V506	RHEEM	0
5861	07/14/2008	LTN050GEF	LOCHINVAR	0
5862	11/16/2009	22DV50C	RHEEM	0
5863	06/07/2006	LTN050G	LOCHINVAR	0
5864	01/14/2008	LTN050G	LOCHINVAR	0
5865	08/21/1987	FSG50	AO SMITH	0
5866	05/30/2011	22DV50F	RHEEM	0
5867	07/07/1995	PGR50	AO SMITH	0
5868	07/21/2010	LTN050GEF	LOCHINVAR	0
5869	11/17/2010	22DV50F	RHEEM	0
5870	03/22/2007	FSG30	AO SMITH	0
5871	10/14/2009	FGR30	AO SMITH	0
5872	08/04/2010	LTN050GEF	LOCHINVAR	0
5873	08/10/2011	MI403S6FBN	BRADFORD-WHITE	0
5874	07/17/2012	P230F	RUUD	0
5875	03/15/2004	FCVL40	AO SMITH	0
5876	01/19/2009	LTN050GEF	LOCHINVAR	0
5877	01/30/1997	FGR50	AO SMITH	0
5878	12/05/2007	LTN050GEF	LOCHINVAR	1
5879	08/18/2005	LTN050	LOCHINVAR	0
5880	05/01/1981	FSG40	AO SMITH	0
5881	11/29/2006	LTN050G	LOCHINVAR	0
5882	01/30/1997	FGR50	AO SMITH	0
5883	01/03/2002	41XR50	RHEEM	0
5884	06/13/2011	M45036FBN	BRADFORD-WHITE	0
5885	06/13/2007	XSN040	LOCHINVAR	2
5886	02/23/2013	G75125	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5887	05/04/2011	21VR50	RHEEM	0
5888	08/03/2011	G75125	RUUD/RHEEM	1
5889	12/10/1996	FGR40	AO SMITH	0
5890	05/15/2009	LTN040G	LOCHINVAR	0
5891	09/06/1994	PHR50	RUUD	0
5892	10/22/2001	PGR50	AO SMITH	0
5893	09/30/1992	21V407	RHEEM	0
5894	08/14/2006	G91200	RUUD/RHEEM	0
5895	07/06/1998	PHR50	RUUD	0
5896	12/31/2005	G75125	RUUD/RHEEM	0
5897	06/21/2011	M45036FBN	BRADFORD-WHITE	0
5898	11/01/1997	FSGL40	AO SMITH	0
5899	12/06/2001	PGR50	AO SMITH	0
5900	01/16/2009	LTN050GEF	LOCHINVAR	1
5901	05/10/1984	FSG50	AO SMITH	0
5902	04/14/1998	FSGL40	AO SMITH	0
5903	03/10/2008	LTN040GEF	LOCHINVAR	0
5904	03/07/2002	FSG40	AO SMITH	0
5905	10/21/2005	LTN050G	LOCHINVAR	0
5906	09/13/2000	FSG50	AO SMITH	0
5907	08/25/2008	PH199119	PHOENIX	0
5908	05/19/2005	LTN050	LOCHINVAR	1
5909	01/31/2010	22DV50C	RHEEM	0
5910	09/18/2007	LTN050GEF	LOCHINVAR	0
5911	07/18/2005	PR640	STATE	0
5912	01/08/2009	LTN050GEF	LOCHINVAR	0
5913	04/20/2006	LTN050G	LOCHINVAR	0
5914	01/08/2008	LTN050GEF	LOCHINVAR	1
5915	03/26/2002	PGR50	AO SMITH	0
5916	09/16/2010	21VR50	RHEEM	0
5917	04/30/2001	FSG50	AO SMITH	0
5918	12/27/2001	41XR50	RHEEM	0
5919	05/14/2007	LTN050GEF	LOCHINVAR	0
5920	08/13/1996	RM5063	RUUD	0
5921	08/22/2008	LTN050GEF	LOCHINVAR	0
5922	11/18/2004	GVC50	A. O. SMITH	0
5923	01/19/2007	LTN050G	LOCHINVAR	0
5924	09/19/2008	LTN050GEF	LOCHINVAR	2
5925	11/08/2012	M45036FBN	BRADFORD-WHITE	1
5926	09/29/1988	FSG50	AO SMITH	0
5927	04/08/2009	LTN050GEF	LOCHINVAR	0
5928	04/08/1985	FSG50	AO SMITH	0
5929	09/09/2008	FGR50	AO SMITH	0
5930	04/16/2001	FSGL40	AO SMITH	0
5931	10/22/2009	LTN050GEF	LOCHINVAR	0
5932	03/21/2005	GVC50	A. O. SMITH	0
5933	09/20/2011	M45036FBN	BRADFORD-WHITE	1
5934	01/05/2007	LTN050G	LOCHINVAR	0
5935	11/01/2005	LTN050GEF	LOCHINVAR	0
5936	01/24/2011	41VR50	RHEEM	2
5937	11/18/2012	FSG50	AO SMITH	0
5938	10/26/2006	LTN050G	LOCHINVAR	0
5939	04/11/1997	PR502T	RUUD	0
5940	07/18/2006	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5941	05/23/2005	LTN050	LOCHINVAR	0
5942	12/27/1988	PRV50NODS	STATE	0
5943	09/10/2010	21DV50	RHEEM	0
5944	01/07/2010	LTN050GEF	LOCHINVAR	1
5945	09/20/1988	FSG50	AO SMITH	1
5946	01/11/2001	PRX50	STATE	0
5947	06/05/2012	MI5036FBN	BRADFORD-WHITE	2
5948	10/22/2008	LTN050GEF	LOCHINVAR	0
5949	04/08/2002	G75125	RUUD/RHEEM	0
5950	11/20/2007	LTN050G	LOCHINVAR	0
5951	06/04/2008	22DV50C	RHEEM	0
5952	10/12/2012	MI50L6FBN	BRADFORD-WHITE	0
5953	09/13/2005	LSN041G	LOCHINVAR	0
5954	01/15/1999	PHR50	RUUD	0
5955	11/05/2003	FCV50	AO SMITH	1
5956	06/03/2009	LTN050GEF	LOCHINVAR	0
5957	03/24/2004	FCV50	AO SMITH	0
5958	04/12/2012	MI5036FBN	BRADFORD-WHITE	3
5959	11/18/2004	GVC50	A. O. SMITH	0
5960	12/28/1998	21VR50	RHEEM	0
5961	06/14/2012	PH2DV50F	RUUD	0
5962	07/23/2010	22DV50C	RHEEM	1
5963	12/15/2011	MI50L6FBN	BRADFORD-WHITE	2
5964	02/08/1989	FSG50	AO SMITH	0
5965	07/24/2003	FSG50	AO SMITH	0
5966	12/21/2005	LTN050G	LOCHINVAR	0
5967	09/09/2006	LTN050G	LOCHINVAR	0
5968	11/16/2007	LTN050GEF	LOCHINVAR	0
5969	11/05/2010	21DV50	RHEEM	0
5970	12/30/2002	PRX50	STATE	0
5971	03/26/2012	M45036FBN	BRADFORD-WHITE	0
5972	07/09/2007	LTN050GEF	LOCHINVAR	0
5973	03/25/2000	41XR50	RHEEM	0
5974	04/20/2009	22DV50F	RHEEM	0
5975	10/13/2005	LTN050	LOCHINVAR	0
5976	03/01/2012	MI5036FBN	BRADFORD-WHITE	1
5977	12/05/2006	LTN050G	LOCHINVAR	0
5978	10/24/2012	MI5036FBN	BRADFORD-WHITE	0
5979	05/20/1999	FGR50	AO SMITH	0
5980	02/13/2013	M45036FBN	BRADFORD-WHITE	0
5981	04/14/1988	FSG50	AO SMITH	0
5982	07/24/2008	LTN050GEF	LOCHINVAR	0
5983	01/17/2006	LTN050GEF	LOCHINVAR	0
5984	03/13/2007	LTN050G	LOCHINVAR	0
5985	09/22/2010	42VR50	RHEEM	0
5986	04/16/2010	LTN050G	LOCHINVAR	0
5987	10/05/2006	GVC50	A. O. SMITH	1
5988	08/31/2007	G82156	RUUD/RHEEM	0
5989	03/06/2011	42VR50	RHEEM	0
5990	05/20/2010	LTN050GEF	LOCHINVAR	1
5991	07/17/2007	LTN050GEF	LOCHINVAR	0
5992	02/29/1988	FSG50	AO SMITH	0
5993	12/06/2000	21V407	RHEEM	0
5994	10/05/2006	GVC50	A. O. SMITH	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
5995	03/05/2012	M45036FBN	BRADFORD-WHITE	0
5996	10/28/2010	42VR50	RHEEM	0
5997	02/13/2007	G82156	RUUD/RHEEM	1
5998	03/06/2009	LTN050GEF	LOCHINVAR	0
5999	11/04/2010	G72DUMMY	AO SMITH	1
6000	10/04/2007	LTN040G	LOCHINVAR	0
6001	06/16/1997	FSGL40	AO SMITH	0
6002	04/24/2007	LTN050G	LOCHINVAR	0
6003	07/12/2008	LSN041G	LOCHINVAR	0
6004	10/21/2008	LTN050GEF	LOCHINVAR	0
6005	10/04/2003	PGR50	AO SMITH	0
6006	07/20/2010	LTN050	LOCHINVAR	1
6007	02/15/1994	FGR50	AO SMITH	0
6008	04/05/2011	21VR40	RHEEM	0
6009	11/04/2004	XVR40	A. O. SMITH	2
6010	07/27/2008	LTN050GEF	LOCHINVAR	0
6011	10/21/1997	FGR50	AO SMITH	0
6012	10/25/2012	G100200	RUUD/RHEEM	1
6013	06/01/1984	FSG50	AO SMITH	0
6014	10/05/2006	PR650	STATE	0
6015	03/10/2006	LTN050G	LOCHINVAR	0
6016	06/17/2009	LTN050GEF	LOCHINVAR	0
6017	10/29/2001	G82156	RUUD/RHEEM	1
6018	09/24/2002	PGR50	AO SMITH	0
6019	03/03/2003	G91200	RUUD/RHEEM	3
6020	04/02/2009	LTN040GEF	LOCHINVAR	0
6021	12/18/1984	FSG50	AO SMITH	0
6022	10/17/2000	PGR50	AO SMITH	0
6023	05/23/2004	G91200	RUUD/RHEEM	0
6024	03/09/2007	LTN040G	LOCHINVAR	0
6025	07/20/2001	PGR50	AO SMITH	0
6026	12/09/2002	H72DUMMY	AO SMITH	0
6027	11/05/2007	LTN040G	LOCHINVAR	0
6028	04/01/2000	41XR40	RHEEM	0
6029	09/01/2001	FSG50	AO SMITH	0
6030	02/01/2007	LTN050G	LOCHINVAR	0
6031	08/17/2009	LTN050GEF	LOCHINVAR	0
6032	10/03/2007	PR640XODS	STATE	0
6033	04/14/2000	FSG40	AO SMITH	0
6034	08/22/2006	LTN050G	LOCHINVAR	0
6035	10/13/2003	21DV50	RHEEM	1
6036	06/22/1987	FSG50	AO SMITH	0
6037	01/07/2013	PH2DV50F	RUUD	0
6038	11/05/2008	LTN050G	LOCHINVAR	1
6039	08/08/2012	M45036FBN	BRADFORD-WHITE	0
6040	03/20/2009	LTN050GEF	LOCHINVAR	0
6041	12/05/2002	FSG50	AO SMITH	0
6042	06/07/2005	LTN050GEF	LOCHINVAR	0
6043	07/07/2011	22DV50F	RHEEM	0
6044	04/10/2010	LTN050GEF	LOCHINVAR	0
6045	03/17/2005	GVC50	A. O. SMITH	1
6046	12/20/2005	GVC50	A. O. SMITH	0
6047	03/27/1993	FSG50	AO SMITH	0
6048	02/08/2010	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6049	10/05/2005	LTN040G	LOCHINVAR	0
6050	05/23/2010	22DV50C	RHEEM	2
6051	08/03/2007	LTN050G	LOCHINVAR	0
6052	10/31/2003	PRX50	STATE	1
6053	01/25/2002	FSG50	AO SMITH	0
6054	12/10/2012	MI5036FBN	BRADFORD-WHITE	0
6055	02/07/2012	MI5036FBN	BRADFORD-WHITE	0
6056	07/31/2003	PGR50	AO SMITH	1
6057	01/27/2011	42VR50	RHEEM	0
6058	12/20/2006	LTN050G	LOCHINVAR	0
6059	12/16/2001	FSG50	AO SMITH	0
6060	06/24/2009	LTN050GEF	LOCHINVAR	0
6061	02/26/2009	LTN050GEF	LOCHINVAR	0
6062	04/25/2002	PRX50	STATE	0
6063	11/20/2007	LTN050GEF	LOCHINVAR	0
6064	08/02/2010	LTN050	LOCHINVAR	0
6065	05/29/2003	FSG50	AO SMITH	0
6066	12/19/2001	FSG50	AO SMITH	0
6067	02/15/2013	M45036FBN	BRADFORD-WHITE	1
6068	09/08/2003	PVR50	AO SMITH	0
6069	08/22/2002	FSG50	AO SMITH	0
6070	08/02/2003	PGR50	AO SMITH	0
6071	02/15/2013	PH2DV50F	RUUD	0
6072	02/05/2009	LTN050GEF	LOCHINVAR	0
6073	05/14/2011	22DV50F	RHEEM	1
6074	08/20/2007	PR650	STATE	0
6075	05/04/1999	FSG50	AO SMITH	0
6076	01/08/2010	LTN050GEF	LOCHINVAR	0
6077	03/01/2001	41XR50	RHEEM	1
6078	06/17/1987	FSG50	AO SMITH	0
6079	07/07/2007	LTN050GEF	LOCHINVAR	0
6080	08/13/2009	LTN040GEF	LOCHINVAR	0
6081	05/31/2001	21V506	RHEEM	0
6082	08/05/2009	22DV50C	RHEEM	0
6083	07/18/2000	P506	RUUD	1
6084	03/07/2011	22DV50F	RHEEM	0
6085	08/01/2007	LTN050GEF	LOCHINVAR	0
6086	01/12/2004	PRX50	STATE	0
6087	10/16/2002	PGR50	AO SMITH	1
6088	10/16/2002	PGR50	AO SMITH	0
6089	11/04/1999	G82156	RUUD/RHEEM	0
6090	07/12/2007	LTN050GEF	LOCHINVAR	1
6091	11/23/2009	LSN041G	LOCHINVAR	0
6092	05/28/2008	LTN050GEF	LOCHINVAR	0
6093	04/18/1995	FGR50	AO SMITH	0
6094	10/20/1988	PRV50NODS	STATE	0
6095	04/10/1985	FSG50	AO SMITH	0
6096	10/06/2009	LTN050GEF	LOCHINVAR	0
6097	06/30/2003	FSG50	AO SMITH	0
6098	06/05/1985	FSG50	AO SMITH	0
6099	12/14/2010	41VR40	RHEEM	0
6100	02/05/2011	42V5065F	RHEEM	1
6101	01/15/2007	PR650X0DS	STATE	0
6102	11/19/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6103	05/16/2007	PR650X0DS	STATE	1
6104	04/05/2010	LTN050GEF	LOCHINVAR	0
6105	10/13/1988	FSG50	AO SMITH	0
6106	10/23/2012	M45036FBN	BRADFORD-WHITE	0
6107	01/07/2010	22DV50F	RHEEM	1
6108	02/06/2002	PGR40	AO SMITH	0
6109	01/20/2009	LTN050GEF	LOCHINVAR	1
6110	11/12/2008	LTN050GEF	LOCHINVAR	0
6111	11/26/2007	LTN050G	LOCHINVAR	0
6112	12/14/2010	21VR50	RHEEM	0
6113	10/26/2010	21DV50	RHEEM	0
6114	01/15/2005	GVR50	AO SMITH	0
6115	10/07/1988	FSG50	AO SMITH	0
6116	03/31/2003	FSG50	AO SMITH	0
6117	12/10/2009	LTN050GEF	LOCHINVAR	0
6118	03/07/1995	PHR50	RUUD	0
6119	08/29/2007	LTN050G	LOCHINVAR	0
6120	12/19/2006	LTN050G	LOCHINVAR	0
6121	01/04/2001	41XR50	RHEEM	0
6122	08/01/2006	LTN050G	LOCHINVAR	0
6123	09/16/1999	FSG50	AO SMITH	0
6124	04/13/2007	LTN040GEF	LOCHINVAR	1
6125	05/12/2010	LTN050GEF	LOCHINVAR	0
6126	02/05/2004	XTN050	LOCHINVAR	0
6127	03/10/2006	LTN050G	LOCHINVAR	1
6128	05/30/2007	LTN050GEF	LOCHINVAR	0
6129	11/03/2011	MI5036FBN	BRADFORD-WHITE	3
6130	07/20/2010	LTN050G	LOCHINVAR	0
6131	01/25/2000	G75125	RUUD/RHEEM	0
6132	06/19/2002	PGR50	AO SMITH	0
6133	09/14/2012	MI5036FBN	BRADFORD-WHITE	0
6134	06/27/2007	LTN050G	LOCHINVAR	0
6135	02/10/2005	PRX50	STATE	1
6136	08/30/2006	LTN050G	LOCHINVAR	0
6137	03/06/1998	FSG50	AO SMITH	0
6138	01/25/2006	LTN050G	LOCHINVAR	0
6139	03/14/2012	P230F	RUUD	0
6140	12/11/1987	SBF100199NES	STATE	0
6141	09/01/2011	PH2DV50F	RUUD	0
6142	05/14/2006	LTN051G	LOCHINVAR	0
6143	08/06/2001	PGR50	AO SMITH	0
6144	10/14/2005	G75125	RUUD/RHEEM	1
6145	01/28/1988	FSG50	AO SMITH	0
6146	02/20/2013	M45036FBN	BRADFORD-WHITE	0
6147	03/31/2010	LTN050GEF	LOCHINVAR	0
6148	06/15/2000	FSG50	AO SMITH	0
6149	01/16/2009	22DV50C	RHEEM	1
6150	01/11/2013	D71DUMMY	UNKNOWN AT CONVERSION	0
6151	08/23/2004	PRX50	STATE	0
6152	11/09/2005	LTN050G	LOCHINVAR	0
6153	08/09/2005	LTN050G	LOCHINVAR	0
6154	02/23/2010	LTN040G	LOCHINVAR	0
6155	04/30/1999	PRV50NODS	STATE	0
6156	01/23/2003	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6157	07/09/2010	G82156	RUUD/RHEEM	2
6158	09/18/2001	FSG50	AO SMITH	0
6159	05/06/1997	FGR50	AO SMITH	0
6160	10/08/2008	LTN050GEF	LOCHINVAR	0
6161	01/04/2013	MI5036FBN	BRADFORD-WHITE	1
6162	01/21/2005	GDVS50	AOSMITH	0
6163	08/08/2000	41XR50	RHEEM	0
6164	04/20/2010	LTN050GEF	LOCHINVAR	0
6165	02/04/2011	21VR50	RHEEM	0
6166	04/09/2010	22DV50C	RHEEM	1
6167	03/13/2008	22DV50C	RHEEM	1
6168	03/18/2011	42VR50	RHEEM	0
6169	12/29/2012	PH2DV50F	RUUD	0
6170	04/20/2010	LTN050GEF	LOCHINVAR	0
6171	02/13/2012	M45036FBN	BRADFORD-WHITE	0
6172	03/03/2008	LSN041G	LOCHINVAR	1
6173	11/28/2012	M45036FBN	BRADFORD-WHITE	0
6174	09/17/2012	MI5036FBN	BRADFORD-WHITE	0
6175	04/14/1987	FSG50	AO SMITH	0
6176	05/19/2003	PRX50	STATE	0
6177	06/19/2008	PR640	STATE	0
6178	01/09/2004	FCVL40	AO SMITH	0
6179	12/03/2008	LTN050G	LOCHINVAR	0
6180	01/15/2004	XTN050	LOCHINVAR	1
6181	04/10/1987	RF82156	RUUD	1
6182	11/16/2007	LTN050GEF	LOCHINVAR	0
6183	04/21/2004	PVR50	AO SMITH	0
6184	04/20/2007	LTN050G	LOCHINVAR	0
6185	04/26/1996	FGR50	AO SMITH	0
6186	03/23/2001	41XR50	RHEEM	0
6187	04/10/1987	RF67120	RUUD	0
6188	04/04/2011	42VR50	RHEEM	0
6189	02/25/2012	M45036FBN	BRADFORD-WHITE	0
6190	04/10/2009	LTN050GEF	LOCHINVAR	2
6191	02/08/2005	GVR50	AO SMITH	0
6192	11/11/1986	FSG40	AO SMITH	0
6193	03/15/2003	FSG50	AO SMITH	0
6194	10/25/2012	FGR50	AO SMITH	0
6195	03/07/1994	FGR50	AO SMITH	0
6196	12/08/2011	MI5036FBN	BRADFORD-WHITE	0
6197	12/15/2009	LTN050GEF	LOCHINVAR	0
6198	11/14/1995	PHR50	RUUD	0
6199	03/17/2008	LTN050GEF	LOCHINVAR	0
6200	10/08/1997	41VR50	RHEEM	0
6201	11/09/2012	PH2DV50F	RUUD	0
6202	08/19/2004	GVC40	A. O. SMITH	0
6203	06/23/1996	PGR50	AO SMITH	0
6204	06/18/2002	FSG50	AO SMITH	0
6205	10/19/2005	LTN050G	LOCHINVAR	0
6206	12/09/2002	PRX50	STATE	0
6207	12/29/2008	LTN050GEF	LOCHINVAR	0
6208	11/29/2010	21DV50	RHEEM	2
6209	03/26/2010	LTN050G	LOCHINVAR	0
6210	05/01/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6211	12/27/2008	G76200	RUUD/RHEEM	0
6212	08/15/2005	LTN050G	LOCHINVAR	0
6213	02/07/2013	MI5036FBN	BRADFORD-WHITE	0
6214	07/01/2009	LTN050GEF	LOCHINVAR	0
6215	03/21/1997	PRX50	STATE	0
6216	11/24/2010	42VR50	RHEEM	1
6217	12/24/1986	P506	RUUD	0
6218	02/14/2007	PR650	STATE	1
6219	09/25/2005	LTN050	LOCHINVAR	0
6220	03/28/2005	GVC50	A. O. SMITH	1
6221	06/27/2000	P502	RUUD	0
6222	11/14/2006	LTN050G	LOCHINVAR	0
6223	05/19/2003	FSG40	AO SMITH	0
6224	07/23/2012	M45036FBN	BRADFORD-WHITE	1
6225	10/11/2011	LSN041G	LOCHINVAR	1
6226	05/21/2007	LTN050	LOCHINVAR	0
6227	04/12/1983	FSG50	AO SMITH	1
6228	07/23/2010	LSN041G	LOCHINVAR	0
6229	04/23/2012	MI403S6FBN	BRADFORD-WHITE	0
6230	08/18/2003	PGR40	AO SMITH	0
6231	06/16/2007	LTN040GEF	LOCHINVAR	0
6232	12/01/2010	42VR50	RHEEM	0
6233	02/15/2010	LTN050GEF	LOCHINVAR	1
6234	03/29/1984	FSG50	AO SMITH	0
6235	02/17/2012	MI5036FBN	BRADFORD-WHITE	0
6236	01/22/2008	LTN050GEF	LOCHINVAR	0
6237	03/21/2011	42VR50	RHEEM	0
6238	07/24/1991	FSG50	AO SMITH	0
6239	08/26/2011	PH2DV50F	RUUD	0
6240	07/07/2005	LTN050	LOCHINVAR	0
6241	06/12/2002	FSG50	AO SMITH	0
6242	01/24/1996	FGR50	AO SMITH	0
6243	04/12/1983	RM5063	RUUD	0
6244	04/16/1997	FSG50	AO SMITH	0
6245	08/15/2005	LSN041G	LOCHINVAR	0
6246	03/30/2010	LTN050GEF	LOCHINVAR	0
6247	03/12/1985	FSG50	AO SMITH	1
6248	11/20/1999	PGR50	AO SMITH	0
6249	05/01/2001	PGR50	AO SMITH	0
6250	02/18/2005	LTN050	LOCHINVAR	0
6251	07/12/2007	LSN041G	LOCHINVAR	2
6252	12/19/2001	G91200	RUUD/RHEEM	0
6253	05/21/2009	LTN050GEF	LOCHINVAR	0
6254	02/08/2003	PGR50	AO SMITH	0
6255	07/15/2009	LSN041G	LOCHINVAR	0
6256	10/25/2006	LTN050G	LOCHINVAR	0
6257	03/04/2002	FSG50	AO SMITH	0
6258	08/25/1999	G72DUMMY	AO SMITH	0
6259	03/08/2011	42VR50	RHEEM	0
6260	12/07/1988	FSG50	AO SMITH	0
6261	04/02/2004	GVC50	A. O. SMITH	2
6262	11/09/1999	PGR50	AO SMITH	0
6263	06/28/2002	FSG50	AO SMITH	0
6264	08/05/2009	22DV50C	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6265	10/25/2004	XVR50	A. O. SMITH	0
6266	08/17/1988	FSG50	AO SMITH	0
6267	04/01/2004	PRX50	STATE	0
6268	01/15/2000	41V50	RHEEM	1
6269	01/13/2009	LTN040GEF	LOCHINVAR	0
6270	03/22/2002	FSGL40	AO SMITH	0
6271	03/26/2011	21VR50	RHEEM	0
6272	04/07/2008	LTN050GEF	LOCHINVAR	0
6273	10/06/1988	FSGL40	AO SMITH	0
6274	05/09/2011	42VR50	RHEEM	1
6275	10/12/2005	LTN051G	LOCHINVAR	0
6276	12/24/2005	GVC50	A. O. SMITH	1
6277	11/23/2004	XVR50	A. O. SMITH	1
6278	02/12/2013	DS140S6FBN	BRADFORD-WHITE	1
6279	09/18/2009	22DV50C	RHEEM	1
6280	02/17/2009	LTN050GEF	LOCHINVAR	0
6281	10/20/2011	D71	UNKNOWN	0
6282	01/02/2001	PGR50	AO SMITH	0
6283	07/06/2004	PRX50	STATE	0
6284	12/31/2008	LTN050GEF	LOCHINVAR	1
6285	10/24/2001	PRX50	STATE	0
6286	01/07/1989	FSG50	AO SMITH	0
6287	09/08/2003	PVR50	AO SMITH	0
6288	12/26/2003	FCV50	AO SMITH	0
6289	07/18/2011	MI5036FBN	BRADFORD-WHITE	0
6290	02/03/2009	LTN050GEF	LOCHINVAR	1
6291	02/03/1999	41VR50	RHEEM	0
6292	02/23/2009	LTN050GEF	LOCHINVAR	0
6293	08/13/2008	LTN050GEF	LOCHINVAR	0
6294	07/30/2004	XSN040	LOCHINVAR	0
6295	08/28/2009	LSN041G	LOCHINVAR	0
6296	10/07/2006	LTN040G	LOCHINVAR	0
6297	10/15/2009	LTN040GEF	LOCHINVAR	0
6298	01/28/2008	LTN050GEF	LOCHINVAR	0
6299	10/10/2000	41VR50	RHEEM	0
6300	11/27/2012	M45036FBN	BRADFORD-WHITE	1
6301	03/05/2009	LTN050GEF	LOCHINVAR	0
6302	08/12/2008	LTN050GEF	LOCHINVAR	0
6303	11/06/2011	MI5036FBN	BRADFORD-WHITE	0
6304	03/20/2012	MI5036FBN	BRADFORD-WHITE	0
6305	12/19/2003	PRX50	STATE	1
6306	10/22/2007	PR650	STATE	1
6307	02/14/2013	M45036FBN	BRADFORD-WHITE	0
6308	10/03/2009	LTN050GEF	LOCHINVAR	0
6309	01/08/2004	PVR50	AO SMITH	1
6310	01/05/2007	PR650	STATE	0
6311	06/26/2001	41V50	RHEEM	0
6312	08/18/2007	PRX50	STATE	0
6313	08/21/2002	PRX50	STATE	0
6314	10/31/2008	LTN050GEF	LOCHINVAR	0
6315	10/23/1987	FSG50	AO SMITH	0
6316	11/27/2007	LTN050G	LOCHINVAR	0
6317	06/03/2009	LTN050GEF	LOCHINVAR	0
6318	04/27/2004	XTN040	LOCHINVAR	3

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6319	11/12/2003	41XR50	RHEEM	0
6320	05/16/2011	21VR50	RHEEM	0
6321	04/20/2012	M45036FBN	BRADFORD-WHITE	0
6322	01/28/2000	PR650	STATE	0
6323	09/23/2006	PR650	STATE	0
6324	12/03/2005	LTN050GEF	LOCHINVAR	0
6325	11/22/2008	LTN050GEF	LOCHINVAR	0
6326	08/02/2000	41XR50	RHEEM	0
6327	07/11/1988	FSG50	AO SMITH	0
6328	06/07/2007	LTN050GEF	LOCHINVAR	1
6329	03/08/2007	LTN050G	LOCHINVAR	0
6330	07/07/2003	FSG40	AO SMITH	0
6331	04/10/2002	PGR50	AO SMITH	0
6332	01/07/2007	LTN050G	LOCHINVAR	0
6333	01/14/2002	PGR50	AO SMITH	0
6334	12/27/2010	21VR50	RHEEM	0
6335	03/06/2001	41V50	RHEEM	0
6336	11/14/2011	M45036FBN	BRADFORD-WHITE	0
6337	12/09/2002	PRX50	STATE	0
6338	01/16/2002	FSG50	AO SMITH	0
6339	11/16/2012	FSG50	AO SMITH	1
6340	05/02/2007	LTN050GEF	LOCHINVAR	0
6341	12/17/2005	LTN050G	LOCHINVAR	0
6342	02/06/2003	PGR50	AO SMITH	0
6343	01/17/2003	PGR50	AO SMITH	0
6344	02/18/2009	LTN040G	LOCHINVAR	0
6345	05/01/2009	22DV50C	RHEEM	0
6346	08/17/2010	22DV50C	RHEEM	0
6347	10/05/2006	LTN050G	LOCHINVAR	0
6348	02/26/2011	21VR40	RHEEM	0
6349	10/17/2006	LTN050GEF	LOCHINVAR	0
6350	03/16/1988	FSGL40	AO SMITH	0
6351	04/20/2005	PR650	STATE	0
6352	09/21/2011	M45036FBN	BRADFORD-WHITE	0
6353	02/01/2001	41V50	RHEEM	1
6354	03/16/1988	FSGL30	AO SMITH	0
6355	06/21/2012	D71	UNKNOWN	2
6356	03/08/2007	LTN050G	LOCHINVAR	0
6357	05/29/2001	G91200	RUUD/RHEEM	1
6358	04/20/1983	FSGL40	AO SMITH	0
6359	10/27/2012	MI403S6FBN	BRADFORD-WHITE	0
6360	08/15/2012	MI5036FBN	BRADFORD-WHITE	0
6361	07/13/1996	BTR154	AO SMITH	0
6362	01/12/2010	LTN050GEF	LOCHINVAR	0
6363	09/08/2010	LSN041G	LOCHINVAR	0
6364	05/18/2006	LTN050G	LOCHINVAR	0
6365	09/30/2000	FSG50	AO SMITH	0
6366	02/02/2001	FSG50	AO SMITH	0
6367	05/05/2009	LTN050GEF	LOCHINVAR	0
6368	02/12/2013	M45036FBN	BRADFORD-WHITE	0
6369	08/06/1998	FSGL40	AO SMITH	0
6370	02/25/1991	21V506	RHEEM	0
6371	03/14/1991	F72DUMMY	AO SMITH	1
6372	07/26/2011	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6373	12/20/2000	FSG50	AO SMITH	0
6374	07/20/2007	LTN050GEF	LOCHINVAR	0
6375	05/03/2012	M45036FBN	BRADFORD-WHITE	0
6376	12/23/1991	F72DUMMY	AO SMITH	0
6377	08/19/2003	FCV40	AO SMITH	0
6378	01/28/1992	21V502	RHEEM	1
6379	12/15/2009	LTN040G	LOCHINVAR	0
6380	02/14/1985	FSG50	AO SMITH	0
6381	10/31/1984	FSG50	AO SMITH	0
6382	01/22/2009	LTN050GEF	LOCHINVAR	1
6383	12/04/2006	LSN041G	LOCHINVAR	0
6384	03/06/2009	LTN050GEF	LOCHINVAR	2
6385	04/29/2010	LTN050GEF	LOCHINVAR	0
6386	01/10/2006	LTN050G	LOCHINVAR	0
6387	01/10/2004	PRX50	STATE	0
6388	12/22/1998	PHR40	RUUD	0
6389	12/12/2002	PRX50	STATE	0
6390	02/28/2002	PGR50	AO SMITH	0
6391	08/01/2011	M45036FBN	BRADFORD-WHITE	0
6392	12/27/2006	LTN050G	LOCHINVAR	1
6393	08/17/1999	FSG50	AO SMITH	0
6394	11/19/2004	XVR50	A. O. SMITH	0
6395	03/23/2010	LTN050GEF	LOCHINVAR	0
6396	10/13/2009	LTN050GEF	LOCHINVAR	0
6397	06/15/2008	22DV50C	RHEEM	0
6398	10/17/2008	LTN050GEF	LOCHINVAR	0
6399	03/01/2001	41XR50	RHEEM	0
6400	08/09/1997	PGR50	AO SMITH	0
6401	05/19/1987	21V502	RHEEM	0
6402	02/17/2008	LTN050	LOCHINVAR	0
6403	03/20/2009	22DV50C	RHEEM	1
6404	06/24/2004	GVC50	A. O. SMITH	0
6405	11/28/1995	41XR40	RHEEM	0
6406	08/26/2008	LTN050G	LOCHINVAR	0
6407	04/15/2009	LTN030G	AO SMITH	1
6408	06/10/2002	PGR50	AO SMITH	0
6409	08/20/1996	PGR50	AO SMITH	0
6410	10/26/2010	42VR50	RHEEM	1
6411	08/13/2012	M45036FBN	BRADFORD-WHITE	0
6412	03/28/2006	LTN050G	LOCHINVAR	0
6413	12/24/2008	LTN050G	LOCHINVAR	0
6414	03/23/1997	PGR50	AO SMITH	0
6415	02/10/2004	FCV50	AO SMITH	0
6416	12/17/2001	PGR50	AO SMITH	0
6417	01/28/2010	22DV50C	RHEEM	0
6418	03/14/2010	LTN050GEF	LOCHINVAR	0
6419	08/05/2011	22DV50F	RHEEM	0
6420	09/25/2012	M45036FBN	BRADFORD-WHITE	2
6421	01/05/2007	LTN050G	LOCHINVAR	0
6422	02/03/2007	LSN041G	LOCHINVAR	0
6423	02/02/2001	PGR50	AO SMITH	0
6424	06/16/2010	LTN050GEF	LOCHINVAR	0
6425	10/20/2008	LTN050GEF	LOCHINVAR	1
6426	06/03/2002	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6427	08/23/2007	LTN050GEF	LOCHINVAR	0
6428	08/13/2002	PGR50	AO SMITH	1
6429	01/07/2002	PGR50	AO SMITH	0
6430	07/05/2000	21V506	RHEEM	0
6431	07/08/2008	LTN050GEF	LOCHINVAR	0
6432	06/17/2008	22DV5038	RHEEM	0
6433	12/12/2008	LTN050GEF	LOCHINVAR	0
6434	01/23/2006	LTN050G	LOCHINVAR	2
6435	01/21/1988	FSG50	AO SMITH	0
6436	07/12/1996	FSG50	AO SMITH	0
6437	03/14/2001	FSG50	AO SMITH	0
6438	03/16/1988	FSGL30	AO SMITH	0
6439	01/03/2002	PRX50	STATE	0
6440	02/01/2013	M45036FBN	BRADFORD-WHITE	3
6441	11/09/2005	PR650	STATE	0
6442	12/23/1987	FSG40	AO SMITH	0
6443	06/29/1988	RF82156	RUUD	0
6444	12/02/1996	PRX50	STATE	0
6445	07/23/2004	PVR50	AO SMITH	0
6446	09/24/1987	FSG50	AO SMITH	0
6447	01/04/2008	LTN040GEF	LOCHINVAR	0
6448	09/09/1988	FSG50	AO SMITH	1
6449	12/07/2001	PGR50	AO SMITH	0
6450	01/30/2013	MI5036FBN	BRADFORD-WHITE	1
6451	08/11/2004	GVC50	A. O. SMITH	1
6452	06/02/2008	G91200	RUUD/RHEEM	0
6453	01/31/2006	PR650	STATE	0
6454	09/14/2005	LTN050GEF	LOCHINVAR	0
6455	05/17/2012	PH2DV50F	RUUD	0
6456	12/28/1995	PRX40	STATE	0
6457	08/11/2001	FSG50	AO SMITH	0
6458	12/17/2004	PRX50	STATE	0
6459	10/18/2007	PR640	STATE	0
6460	01/22/2003	FSG50	AO SMITH	0
6461	12/14/2012	M45036FBN	BRADFORD-WHITE	1
6462	04/29/1988	PRX50	STATE	0
6463	01/20/2004	FSGL40	AO SMITH	0
6464	02/23/2007	LTN050G	LOCHINVAR	0
6465	07/12/2007	G82156	RUUD/RHEEM	2
6466	05/14/2006	PR650	STATE	0
6467	10/17/2012	FSG50	AO SMITH	0
6468	12/09/2009	22DV50F	RHEEM	0
6469	07/25/2002	PRX50	STATE	0
6470	07/12/2007	G82156	RUUD/RHEEM	1
6471	12/06/2011	MI5036FBN	BRADFORD-WHITE	5
6472	11/26/2011	MI403S6FBN	BRADFORD-WHITE	0
6473	06/17/2004	FSG50	AO SMITH	0
6474	01/07/2008	LTN050GEF	LOCHINVAR	0
6475	01/29/2009	LTN050G	LOCHINVAR	0
6476	09/15/2005	LTN050	LOCHINVAR	1
6477	12/12/2000	41VR50	RHEEM	0
6478	11/06/2000	PGR50	AO SMITH	0
6479	02/25/1988	P506	RUUD	0
6480	07/08/1997	PRV50NODS	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6481	06/19/1997	PGR50	AO SMITH	0
6482	01/01/1985	FSG50	AO SMITH	0
6483	11/12/2009	LTN050G	LOCHINVAR	0
6484	02/07/2003	BTC198	AO SMITH	0
6485	10/02/2008	LTN040GEF	LOCHINVAR	0
6486	04/27/2006	LSN041	LOCHINVAR	1
6487	08/12/2002	FSG50	AO SMITH	0
6488	02/08/2002	FSG50	AO SMITH	0
6489	05/09/2012	MI5036FBN	BRADFORD-WHITE	0
6490	01/12/2000	FSGL40	AO SMITH	0
6491	01/12/2006	LTN050G	LOCHINVAR	0
6492	04/21/2011	41VR40	RHEEM	0
6493	05/02/2012	M45036FBN	BRADFORD-WHITE	0
6494	09/22/2007	LTN050G	LOCHINVAR	0
6495	12/19/2007	LTN040G	LOCHINVAR	0
6496	01/03/2008	G82156	RUUD/RHEEM	0
6497	12/21/2012	M45036FBN	BRADFORD-WHITE	0
6498	04/02/2007	LTN050G	LOCHINVAR	0
6499	08/02/2003	FSG50	AO SMITH	0
6500	11/18/2007	LTN050GEF	LOCHINVAR	0
6501	09/21/1983	KGA40	AO SMITH	0
6502	03/17/2006	LTN050GEF	LOCHINVAR	0
6503	07/05/2005	LTN050G	LOCHINVAR	0
6504	01/14/2002	PGR50	AO SMITH	0
6505	10/19/2004	GVC40	A. O. SMITH	0
6506	07/21/2008	LTN050GEF	LOCHINVAR	0
6507	09/22/2011	M45036FBN	BRADFORD-WHITE	0
6508	10/25/2009	LTN050G	LOCHINVAR	0
6509	12/10/2002	PGR50	AO SMITH	0
6510	09/20/2002	FSG50	AO SMITH	0
6511	06/23/2006	LSN041G	LOCHINVAR	0
6512	07/13/1995	PR502T	RUUD	0
6513	01/24/2013	M45036FBN	BRADFORD-WHITE	1
6514	12/24/2001	FSGL40	AO SMITH	0
6515	02/12/2001	FGR50	AO SMITH	0
6516	07/30/2012	MI5036FBN	BRADFORD-WHITE	0
6517	06/27/2002	FSG40	AO SMITH	0
6518	07/27/1987	FSG50	AO SMITH	0
6519	10/16/2010	42VR50	RHEEM	0
6520	08/31/2012	M45036FBN	BRADFORD-WHITE	0
6521	12/23/2003	FSG50	AO SMITH	0
6522	05/27/2003	FSG50	AO SMITH	0
6523	12/15/2001	PGR50	AO SMITH	0
6524	03/09/2006	LTN050G	LOCHINVAR	0
6525	03/21/2001	PGR50	AO SMITH	0
6526	04/13/2007	LTN050G	LOCHINVAR	0
6527	09/23/1998	FSG50	AO SMITH	0
6528	11/18/2006	PR650	STATE	0
6529	01/11/2011	42VR50	RHEEM	0
6530	04/20/2002	PGR50	AO SMITH	0
6531	04/05/2002	FSG50	AO SMITH	0
6532	06/24/2008	22DV50C	RHEEM	0
6533	10/18/2007	LTN050GEF	LOCHINVAR	0
6534	05/04/2009	22DV50C	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6535	08/15/2012	M45036FBN	BRADFORD-WHITE	0
6536	01/30/2005	PRX50	STATE	0
6537	08/29/1997	FSG50	AO SMITH	0
6538	08/13/2003	PGR50	AO SMITH	1
6539	01/11/2008	LTN050GEF	LOCHINVAR	0
6540	01/27/2006	LTN051G	LOCHINVAR	0
6541	08/01/2012	MI50L6FBN	BRADFORD-WHITE	0
6542	12/15/2003	FCV50	AO SMITH	0
6543	09/18/2007	LSN041G	LOCHINVAR	0
6544	06/26/2009	LTN050GEF	LOCHINVAR	2
6545	09/17/2003	FCV50	AO SMITH	0
6546	03/18/2000	41V50	RHEEM	0
6547	04/03/2000	PGR50	AO SMITH	0
6548	07/19/2007	LTN050GEF	LOCHINVAR	1
6549	10/10/2009	LTN050GEF	LOCHINVAR	0
6550	12/23/1999	FSG50	AO SMITH	0
6551	08/22/2012	M45036FBN	BRADFORD-WHITE	0
6552	11/19/2009	LTN050GEF	LOCHINVAR	0
6553	10/19/2007	LTN050G	LOCHINVAR	0
6554	08/14/1998	41VR50	RHEEM	0
6555	11/04/2010	21DV50	RHEEM	1
6556	03/11/2011	42VR50	RHEEM	0
6557	02/19/1996	FGR50	AO SMITH	0
6558	10/05/2000	41XR40	RHEEM	1
6559	07/27/2010	LTN050G	LOCHINVAR	0
6560	07/17/2007	LTN050G	LOCHINVAR	0
6561	04/13/2004	XVR50	A. O. SMITH	0
6562	02/28/2013	M45036FBN	BRADFORD-WHITE	0
6563	02/21/2004	FCV50	AO SMITH	0
6564	07/17/2006	LTN050GEF	LOCHINVAR	0
6565	08/24/2012	MI5036FBN	BRADFORD-WHITE	1
6566	01/18/2007	LTN050G	LOCHINVAR	0
6567	02/20/1987	FSG50	AO SMITH	0
6568	03/18/2006	PR650X0DS	STATE	0
6569	10/07/2001	41VR40	RHEEM	1
6570	08/04/2012	M45036FBN	BRADFORD-WHITE	0
6571	01/05/2012	M45036FBN	BRADFORD-WHITE	0
6572	02/05/2011	G82156	RUUD/RHEEM	1
6573	06/06/2007	LTN050G	LOCHINVAR	0
6574	09/09/1988	FSG50	AO SMITH	0
6575	01/15/2013	M45036FBN	BRADFORD-WHITE	0
6576	03/27/2008	LTN050GEF	LOCHINVAR	0
6577	11/02/1988	FSG50	AO SMITH	0
6578	02/03/2011	42VR50	RHEEM	0
6579	07/06/2006	LTN040G	LOCHINVAR	0
6580	03/08/2004	PRX50	STATE	0
6581	01/09/2001	FSG50	AO SMITH	0
6582	02/05/2007	LSN041	LOCHINVAR	0
6583	11/30/2006	FSG50	AO SMITH	0
6584	11/17/1997	FSG50	AO SMITH	1
6585	10/07/2000	PRV50NODS	STATE	1
6586	11/29/2004	GVC50	A. O. SMITH	0
6587	08/18/2004	GVC50	A. O. SMITH	0
6588	03/13/2006	PR650	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6589	08/18/2004	GVC50	A. O. SMITH	0
6590	01/01/2004	PRV50NODS	STATE	0
6591	10/12/1988	P506	RUUD	0
6592	04/29/2008	LTN050G	LOCHINVAR	1
6593	03/02/2001	41XR50	RHEEM	0
6594	01/23/2004	PRX50	STATE	0
6595	10/25/1988	PRV50NODS	STATE	0
6596	12/19/2010	21VR50	RHEEM	0
6597	12/22/1988	FSG50	AO SMITH	0
6598	05/17/2012	M45036FBN	BRADFORD-WHITE	0
6599	04/10/2000	FSG50	AO SMITH	0
6600	02/14/2010	22DV50C	RHEEM	0
6601	02/08/2010	LTN050GEF	LOCHINVAR	0
6602	01/05/2011	42VR50	RHEEM	0
6603	05/24/2000	PGR50	AO SMITH	0
6604	01/15/2008	LSN041G	LOCHINVAR	0
6605	02/01/2011	42VR50	RHEEM	0
6606	03/13/2000	FSG50	AO SMITH	0
6607	09/14/2006	PR650X0DS	STATE	0
6608	05/05/2000	41XR50	RHEEM	0
6609	08/10/1997	PGR50	AO SMITH	0
6610	02/09/2007	LTN050G	LOCHINVAR	0
6611	01/29/2009	LTN050GEF	LOCHINVAR	0
6612	02/26/2009	LTN050GEF	LOCHINVAR	1
6613	08/30/2002	FSG50	AO SMITH	0
6614	01/30/2006	LSN041G	LOCHINVAR	0
6615	10/28/2011	MI5036FBN	BRADFORD-WHITE	0
6616	08/16/1997	FSGL40	AO SMITH	0
6617	01/25/1984	FSG50	AO SMITH	0
6618	09/16/2010	21VR50	RHEEM	0
6619	02/23/2006	LTN050GEF	LOCHINVAR	0
6620	05/30/1998	41VR50	RHEEM	0
6621	06/07/2004	XVR50	A. O. SMITH	1
6622	05/04/2005	LTN050GEF	LOCHINVAR	0
6623	10/17/1997	PGR50	AO SMITH	0
6624	08/31/2007	LTN050GEF	LOCHINVAR	0
6625	04/02/1998	FGR50	AO SMITH	0
6626	03/01/1977	KGA40	AO SMITH	0
6627	04/11/2007	LTN040G	LOCHINVAR	0
6628	01/31/1984	FSG50	AO SMITH	0
6629	02/12/2013	G76200	RUUD/RHEEM	0
6630	10/28/2009	LTN040G	LOCHINVAR	0
6631	06/27/2011	M45036FBN	BRADFORD-WHITE	0
6632	01/08/2009	LTN040G	LOCHINVAR	0
6633	05/18/2004	GVC40	A. O. SMITH	0
6634	11/13/2003	SBF100199NES	STATE	0
6635	04/30/2009	LSN041G	LOCHINVAR	0
6636	06/18/2012	G91200	RUUD/RHEEM	0
6637	01/31/2008	LTN050GEF	LOCHINVAR	0
6638	08/22/2010	21VR50	RHEEM	0
6639	05/06/2009	LTN040GEF	LOCHINVAR	0
6640	10/25/2005	LTN040G	LOCHINVAR	0
6641	08/24/2005	PR640	STATE	0
6642	06/17/2009	LTN040G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6643	01/01/1985	FSG50	AO SMITH	0
6644	01/09/2010	LTN050GEF	LOCHINVAR	0
6645	04/06/2006	LTN050G	LOCHINVAR	0
6646	07/17/2000	PRX50	STATE	0
6647	07/11/2007	LTN050GEF	LOCHINVAR	1
6648	05/23/2003	PGR50	AO SMITH	1
6649	06/08/2012	M45036FBN	BRADFORD-WHITE	1
6650	10/06/2007	LTN050GEF	LOCHINVAR	0
6651	03/16/2005	PRX50	STATE	0
6652	01/17/2004	FCV40	AO SMITH	0
6653	01/12/2012	M45036FBN	BRADFORD-WHITE	0
6654	03/08/2005	GVC50	A. O. SMITH	0
6655	09/02/2003	PRX50	STATE	0
6656	05/25/2011	21VR50	RHEEM	0
6657	01/17/2004	FCVL40	AO SMITH	0
6658	10/15/2001	FSG50	AO SMITH	0
6659	10/10/2009	LTN050GEF	LOCHINVAR	0
6660	06/29/2009	LTN050GEF	LOCHINVAR	0
6661	12/11/2008	LTN050GEF	LOCHINVAR	0
6662	12/26/2006	LTN050G	LOCHINVAR	1
6663	10/25/2007	LTN050G	LOCHINVAR	1
6664	11/04/2008	LTN050GEF	LOCHINVAR	1
6665	11/24/2009	LTN050GEF	LOCHINVAR	1
6666	06/17/1999	G75125	RUUD/RHEEM	2
6667	10/18/2005	LTN050G	LOCHINVAR	2
6668	08/31/2006	LTN050G	LOCHINVAR	0
6669	07/14/1988	FSG50	AO SMITH	0
6670	07/24/1999	FSG50	AO SMITH	0
6671	12/17/2009	LTN050GEF	LOCHINVAR	0
6672	01/31/2011	41VR50	RHEEM	0
6673	01/02/2007	LTN050G	LOCHINVAR	0
6674	08/15/2001	FSGL40	AO SMITH	0
6675	05/23/2006	LTN050G	LOCHINVAR	0
6676	05/01/1999	FSG50	AO SMITH	0
6677	01/06/1988	21V506	RHEEM	0
6678	05/08/2004	GVC50	A. O. SMITH	0
6679	12/20/2012	MI50L6FBN	BRADFORD-WHITE	0
6680	08/19/1988	FSG50	AO SMITH	0
6681	06/05/2006	LSN041G	LOCHINVAR	0
6682	06/18/2002	FSG50	AO SMITH	0
6683	06/08/2000	PGR50	AO SMITH	1
6684	09/26/1988	P506	RUUD	0
6685	04/28/2005	LTN050	LOCHINVAR	0
6686	07/27/2010	LTN050	LOCHINVAR	0
6687	09/18/2007	LTN050G	LOCHINVAR	0
6688	11/15/2002	PRX40	STATE	0
6689	02/12/2001	PGR50	AO SMITH	0
6690	07/08/2010	21DV50	RHEEM	0
6691	04/28/2008	LTN050	LOCHINVAR	0
6692	03/27/2007	LTN050G	LOCHINVAR	0
6693	04/22/2003	FSG50	AO SMITH	2
6694	09/17/2012	MI5036FBN	BRADFORD-WHITE	1
6695	12/27/2006	LTN050G	LOCHINVAR	1
6696	12/17/1986	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6697	04/21/2012	PH2DV50F	RUUD	0
6698	01/18/2006	GVC50	A. O. SMITH	0
6699	12/17/2008	LSN041G	LOCHINVAR	0
6700	01/30/2009	LTN050GEF	LOCHINVAR	0
6701	12/26/1995	FGR50	AO SMITH	0
6702	10/05/1999	PRV50NODS	STATE	0
6703	04/03/2006	LTN050G	LOCHINVAR	0
6704	02/29/2012	M45036FBN	BRADFORD-WHITE	0
6705	11/14/2012	M440T6FBN	BRADFORD-WHITE	0
6706	12/29/2009	LTN050G	LOCHINVAR	0
6707	03/07/2005	PR640	STATE	0
6708	09/07/1993	G91200	RUUD/RHEEM	0
6709	02/09/2012	M440T6FBN	BRADFORD-WHITE	0
6710	10/30/1997	PGR50	AO SMITH	0
6711	03/09/2009	LTN050GEF	LOCHINVAR	0
6712	06/27/2002	PRX50	STATE	0
6713	05/10/2011	41VR50	RHEEM	0
6714	04/17/2002	PGR50	AO SMITH	0
6715	04/15/2005	PRX50	STATE	1
6716	02/10/2012	MI403S6FBN	BRADFORD-WHITE	1
6717	02/13/2004	FSGL40	AO SMITH	1
6718	07/14/2008	LTN050GEF	LOCHINVAR	0
6719	02/11/2002	PRX50	STATE	0
6720	04/04/2011	22DV50F	RHEEM	0
6721	09/08/1986	FSG50	AO SMITH	0
6722	10/30/2008	P506	RUUD	1
6723	09/30/1998	G91200	RUUD/RHEEM	0
6724	02/02/2007	LTN050G	LOCHINVAR	0
6725	09/01/2004	GVC50	A. O. SMITH	1
6726	11/09/2004	GVC40	A. O. SMITH	0
6727	10/10/2011	PH2DV50F	RUUD	0
6728	07/28/2011	MI5036FBN	BRADFORD-WHITE	1
6729	04/30/2011	22DV50F	RHEEM	0
6730	12/01/2010	LSN041G	LOCHINVAR	0
6731	04/29/1999	FGR50	AO SMITH	0
6732	08/19/1987	FSG50	AO SMITH	0
6733	10/13/2010	LSN041G	LOCHINVAR	0
6734	04/10/2012	M45036FBN	BRADFORD-WHITE	0
6735	08/02/2012	MI403S6FBN	BRADFORD-WHITE	1
6736	08/31/2005	SSV50	STATE	0
6737	02/09/2009	LTN050GEF	LOCHINVAR	0
6738	07/27/2004	XTN040	LOCHINVAR	0
6739	12/09/2003	PGR50	AO SMITH	0
6740	04/16/2009	LTN050G	LOCHINVAR	0
6741	11/03/2012	MI5036FBN	BRADFORD-WHITE	0
6742	12/12/2005	LTN050G	LOCHINVAR	0
6743	10/20/2001	FSG50	AO SMITH	0
6744	11/26/2011	MI5036FBN	BRADFORD-WHITE	0
6745	02/07/2012	M45036FBN	BRADFORD-WHITE	0
6746	11/21/2002	21V506	RHEEM	0
6747	01/06/2011	22DV50F	RHEEM	0
6748	03/18/2006	LSN041G	LOCHINVAR	0
6749	05/23/2005	42VR506	RHEEM	0
6750	02/14/1989	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6751	07/29/2009	LTN050GEF	LOCHINVAR	0
6752	08/17/2009	LTN050GEF	LOCHINVAR	0
6753	10/19/2000	41XR50	RHEEM	0
6754	06/27/2008	LTN050GEF	LOCHINVAR	0
6755	10/20/2006	LTN050GEF	LOCHINVAR	0
6756	02/11/2004	21V502	RHEEM	0
6757	11/01/2010	21VR50	RHEEM	0
6758	01/31/2011	22DV50F	RHEEM	0
6759	09/21/2010	42VR50	RHEEM	0
6760	01/28/2009	LTN050GEF	LOCHINVAR	0
6761	04/03/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
6762	01/16/1997	G82156	RUUD/RHEEM	2
6763	07/14/2004	XTN050	LOCHINVAR	0
6764	05/12/2007	LTN050GEF	LOCHINVAR	0
6765	08/08/2001	FSG50	AO SMITH	0
6766	04/30/1999	FGR50	AO SMITH	0
6767	12/20/2011	M45036FBN	BRADFORD-WHITE	0
6768	10/31/2011	PGR50	AO SMITH	0
6769	02/25/2013	MI403S6FBN	BRADFORD-WHITE	0
6770	06/25/2004	GVC50	A. O. SMITH	0
6771	12/11/2001	PRX50	STATE	0
6772	08/31/2011	M45036FBN	BRADFORD-WHITE	2
6773	11/27/2010	21VR50	RHEEM	1
6774	03/02/2011	42VR50	RHEEM	0
6775	07/31/2005	LTN050G	LOCHINVAR	1
6776	04/10/2010	LTN050GEF	LOCHINVAR	0
6777	10/15/1988	FSG50	AO SMITH	0
6778	04/05/2002	PGR50	AO SMITH	1
6779	08/31/2011	M440T6FBN	BRADFORD-WHITE	0
6780	11/15/1988	P506	RUUD	0
6781	09/20/2008	22DV50C	RHEEM	0
6782	08/02/2007	LTN050GEF	LOCHINVAR	0
6783	10/11/1988	BTR120	AO SMITH	0
6784	11/25/2003	PRX50	STATE	0
6785	12/26/2012	MI5036FBN	BRADFORD-WHITE	0
6786	12/18/1998	41XR50	RHEEM	0
6787	04/16/2010	22DV50C	RHEEM	0
6788	08/21/2009	22V50F1	RHEEM	3
6789	04/15/2005	P506	RUUD	0
6790	01/26/2011	42VR50	RHEEM	0
6791	04/01/2002	FSG50	AO SMITH	1
6792	05/22/2002	PGR50	AO SMITH	0
6793	05/05/2009	22DV50C	RHEEM	0
6794	01/16/1997	FGR50	AO SMITH	0
6795	02/09/2007	LTN050G	LOCHINVAR	0
6796	06/13/2007	LTN050G	LOCHINVAR	0
6797	06/22/2006	LTN050G	LOCHINVAR	1
6798	02/13/2013	G75125	RUUD/RHEEM	6
6799	03/18/2009	LTN050GEF	LOCHINVAR	0
6800	03/12/2001	FSG40	AO SMITH	2
6801	04/21/2005	GVC50	A. O. SMITH	0
6802	11/23/2009	G75125	RUUD/RHEEM	0
6803	06/30/2008	LTN050GEF	LOCHINVAR	0
6804	12/15/2003	PVR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6805	01/09/1998	FGR50	AO SMITH	0
6806	07/20/2006	PR650X0DS	STATE	0
6807	01/19/2009	LTN050GEF	LOCHINVAR	0
6808	06/22/2005	LTN050	LOCHINVAR	0
6809	03/05/2002	FSG40	AO SMITH	0
6810	09/17/2005	LTN040G	LOCHINVAR	1
6811	11/15/2000	PGR50	AO SMITH	0
6812	01/08/2013	M45036FBN	BRADFORD-WHITE	1
6813	07/18/2003	21V407	RHEEM	0
6814	08/04/1977	PGC50	AO SMITH	0
6815	05/22/1997	FSGL40	AO SMITH	0
6816	03/04/2006	LTN040G	LOCHINVAR	0
6817	09/12/2005	GCVL40	A. O. SMITH	0
6818	01/14/2010	LTN050G	LOCHINVAR	0
6819	03/31/2011	42VR50	RHEEM	0
6820	09/05/2008	LTN050GEF	LOCHINVAR	0
6821	02/04/2008	LTN040G	LOCHINVAR	0
6822	04/13/2010	LTN050GEF	LOCHINVAR	0
6823	11/15/2001	41XR50	RHEEM	0
6824	12/04/2004	GVC50	A. O. SMITH	0
6825	10/12/2006	LTN050GEF	LOCHINVAR	0
6826	11/21/2005	LTN050G	LOCHINVAR	0
6827	07/24/1998	FGR50	AO SMITH	0
6828	12/28/2007	LTN050GEF	LOCHINVAR	0
6829	06/01/2011	42VR50	RHEEM	1
6830	10/24/2011	M45036FBN	BRADFORD-WHITE	0
6831	12/10/2001	FSGL40	AO SMITH	0
6832	01/04/2010	LTN050G	LOCHINVAR	0
6833	07/05/2005	PR650	STATE	0
6834	11/27/2002	PGR50	AO SMITH	0
6835	01/16/2000	21V506	RHEEM	0
6836	07/17/2009	LTN050G	LOCHINVAR	0
6837	09/30/2006	LTN050G	LOCHINVAR	0
6838	06/15/2006	LTN050G	LOCHINVAR	0
6839	11/19/1987	FSG50	AO SMITH	0
6840	04/20/2012	PH2DV50F	RUUD	0
6841	12/11/2007	LTN050GEF	LOCHINVAR	0
6842	03/07/2003	PRX50	STATE	0
6843	02/09/1988	FSG50	AO SMITH	0
6844	02/11/1988	FSG50	AO SMITH	0
6845	09/16/2008	22DV50C	RHEEM	0
6846	01/20/1996	PR502T	RUUD	0
6847	01/04/2013	M45036FBN	BRADFORD-WHITE	0
6848	04/01/2000	FGR50	AO SMITH	0
6849	06/30/1988	FSG50	AO SMITH	0
6850	02/08/2012	M45036FBN	BRADFORD-WHITE	0
6851	03/01/2010	LTN050GEF	LOCHINVAR	0
6852	11/13/1997	PGR50	AO SMITH	0
6853	01/04/2013	LTN051G	UNKNOWN AT CONVERSION	0
6854	01/29/2013	M45036FBN	BRADFORD-WHITE	0
6855	03/21/1988	FSG50	AO SMITH	0
6856	12/11/2002	FSG40	AO SMITH	0
6857	05/17/2007	LTN050G	LOCHINVAR	0
6858	12/09/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6859	12/04/2006	PR650	STATE	0
6860	10/16/2009	LTN050GEF	LOCHINVAR	0
6861	09/24/2010	FSG50	AO SMITH	0
6862	10/15/2006	LTN050GEF	LOCHINVAR	0
6863	08/10/2004	GVC50	A. O. SMITH	0
6864	05/06/2009	LTN050GEF	LOCHINVAR	1
6865	10/09/2000	PRX50	STATE	0
6866	01/05/2004	XTN050	LOCHINVAR	0
6867	09/07/2008	LTN050GEF	LOCHINVAR	0
6868	09/03/2009	LTN050GEF	LOCHINVAR	0
6869	10/06/2008	LTN050GEF	LOCHINVAR	0
6870	06/20/2009	LTN050GEF	LOCHINVAR	0
6871	10/28/2005	LTN050G	LOCHINVAR	0
6872	09/13/2012	M45036FBN	BRADFORD-WHITE	0
6873	04/09/2008	LTN050GEF	LOCHINVAR	0
6874	11/07/2010	21DV50	RHEEM	0
6875	04/26/2004	PRX50	STATE	0
6876	12/27/2001	FSG50	AO SMITH	0
6877	05/04/1999	FGR50	AO SMITH	0
6878	10/26/2011	PH2DV50F	RUUD	0
6879	04/02/2001	PGR50	AO SMITH	0
6880	01/05/2002	PGR50	AO SMITH	0
6881	09/20/2005	LTN050G	LOCHINVAR	0
6882	08/07/1987	FSG50	AO SMITH	0
6883	07/02/1986	FSG40	AO SMITH	0
6884	02/12/2009	LTN050GEF	LOCHINVAR	0
6885	07/31/2002	FSGL40	AO SMITH	0
6886	11/30/2010	42VR50	RHEEM	0
6887	08/02/2012	MI403S6FBN	BRADFORD-WHITE	1
6888	01/30/2000	G75125	RUUD/RHEEM	1
6889	02/02/2002	FSG50	AO SMITH	0
6890	04/26/2011	42VR5040F	RHEEM	0
6891	12/04/1998	FSG50	AO SMITH	0
6892	05/28/1987	21V506	RHEEM	0
6893	04/06/2007	LSN041G	LOCHINVAR	0
6894	01/04/2011	M440T6FBN	BRADFORD-WHITE	0
6895	12/20/2006	LTN050G	LOCHINVAR	0
6896	09/30/2009	LTN050GEF	LOCHINVAR	0
6897	07/20/2010	LTN050GEF	LOCHINVAR	0
6898	10/23/2001	FSG50	AO SMITH	0
6899	09/14/2009	LTN050GEF	LOCHINVAR	0
6900	07/18/1986	FSG50	AO SMITH	0
6901	10/07/2004	LTN050G	LOCHINVAR	0
6902	03/08/2011	42VR50	RHEEM	0
6903	11/23/2007	LTN050GEF	LOCHINVAR	0
6904	09/28/2011	M440T6FBN	BRADFORD-WHITE	0
6905	05/09/1995	PR502T	RUUD	0
6906	05/26/2004	GVC50	A. O. SMITH	0
6907	07/15/2003	FSG50	AO SMITH	0
6908	12/31/2001	PGR50	AO SMITH	0
6909	01/22/2007	LTN050G	LOCHINVAR	0
6910	06/03/2002	FSG50	AO SMITH	0
6911	05/11/2010	LTN050GEF	LOCHINVAR	0
6912	08/22/2000	41XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6913	04/26/1998	PGR50	AO SMITH	0
6914	04/27/2005	LTN050	LOCHINVAR	0
6915	05/19/2007	LSN041G	LOCHINVAR	0
6916	02/28/2012	PH2DV50F	RUUD	0
6917	01/05/2000	FSG50	AO SMITH	0
6918	04/21/2008	22DV50C	RHEEM	0
6919	04/27/2000	PGR50	AO SMITH	0
6920	05/12/2006	LSN041G	LOCHINVAR	0
6921	01/04/2011	21VR50	RHEEM	0
6922	12/07/1998	FGR50	AO SMITH	0
6923	12/02/1993	P506	RUUD	1
6924	06/07/2007	LTN050GEF	LOCHINVAR	0
6925	08/06/1984	21V502	RHEEM	0
6926	12/19/1994	PR502T	RUUD	0
6927	02/14/2000	FSG50	AO SMITH	0
6928	06/06/2005	LTN050	LOCHINVAR	0
6929	06/05/1999	41VR40	RHEEM	0
6930	05/14/2011	21VR40	RHEEM	0
6931	10/26/1997	G91200	RUUD/RHEEM	0
6932	05/26/2012	MI5036FBN	BRADFORD-WHITE	0
6933	03/13/2007	LTN040G	LOCHINVAR	1
6934	08/30/2010	21V502	RHEEM	0
6935	06/12/2001	PGR50	AO SMITH	0
6936	06/11/2010	LTN050G	LOCHINVAR	1
6937	05/25/2007	LTN050GEF	LOCHINVAR	0
6938	01/12/2009	LTN050GEF	LOCHINVAR	0
6939	07/18/2005	LTN050	LOCHINVAR	0
6940	09/22/1989	SBF100199NES	STATE	0
6941	08/01/1978	PGC50	AO SMITH	0
6942	09/25/2001	G91200	RUUD/RHEEM	0
6943	06/02/2001	G91200	RUUD/RHEEM	0
6944	09/07/2012	M45036FBN	BRADFORD-WHITE	1
6945	04/01/1998	PGR50	AO SMITH	0
6946	12/31/2012	MI5036FBN	BRADFORD-WHITE	0
6947	02/11/2011	42VR50	RHEEM	1
6948	12/01/1981	G76200	RUUD/RHEEM	0
6949	02/24/2012	MI5036FBN	BRADFORD-WHITE	0
6950	11/06/2003	PRX50	STATE	0
6951	07/31/2003	41XR50	RHEEM	0
6952	04/01/2010	22DV50C	RHEEM	0
6953	12/09/2010	42VR50	RHEEM	0
6954	06/21/2010	LTN050GEF	LOCHINVAR	1
6955	05/02/2001	PGR50	AO SMITH	0
6956	06/18/2008	LTN050GEF	LOCHINVAR	0
6957	01/31/2004	PRX50	STATE	0
6958	12/11/1987	P506	RUUD	0
6959	06/23/2004	GVC50	A. O. SMITH	1
6960	07/14/2006	LTN040G	LOCHINVAR	0
6961	08/06/2002	FSG50	AO SMITH	0
6962	10/10/2001	PGR50	AO SMITH	0
6963	11/05/2008	LTN050GEF	LOCHINVAR	0
6964	08/29/2011	PH2DV50F	RUUD	0
6965	02/02/2010	LTN050GEF	LOCHINVAR	1
6966	04/08/1998	FGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
6967	05/29/2003	FSG50	AO SMITH	0
6968	05/24/2012	M45036FBN	BRADFORD-WHITE	0
6969	10/27/2005	LTN050G	LOCHINVAR	0
6970	04/21/2012	BT80	AO SMITH	0
6971	09/29/1987	FSG50	AO SMITH	0
6972	08/08/2003	FSGL40	AO SMITH	0
6973	07/18/2010	22DV50C	RHEEM	0
6974	11/15/2006	LTN050GEF	LOCHINVAR	0
6975	02/11/2004	PRX50	STATE	0
6976	01/02/2005	GVC50	A. O. SMITH	0
6977	09/06/2009	LTN050GEF	LOCHINVAR	1
6978	01/02/2004	PRX50	STATE	0
6979	07/13/2007	PR650	STATE	0
6980	07/09/2009	LTN050GEF	LOCHINVAR	0
6981	02/21/2008	LTN050GEF	LOCHINVAR	0
6982	01/19/2007	PR650X0DS	STATE	0
6983	01/28/2006	LTN050G	LOCHINVAR	1
6984	03/15/2005	PRX50	STATE	0
6985	04/22/2011	41VR50	RHEEM	0
6986	04/15/2002	PGR50	AO SMITH	0
6987	12/17/2004	LTN050	LOCHINVAR	0
6988	11/20/2008	LTN050GEF	LOCHINVAR	0
6989	07/01/1988	FSG50	AO SMITH	0
6990	09/09/2010	LTN040GEF	LOCHINVAR	0
6991	09/24/2012	MI5036FBN	BRADFORD-WHITE	0
6992	10/14/2009	LTN050GEF	LOCHINVAR	0
6993	01/26/2010	LTN050GEF	LOCHINVAR	0
6994	08/27/2010	21VR50	RHEEM	0
6995	04/18/2005	GVC50	A. O. SMITH	0
6996	11/20/2002	21V506	RHEEM	0
6997	06/09/2007	LTN050GEF	LOCHINVAR	0
6998	09/17/2008	LTN040GEF	LOCHINVAR	0
6999	07/14/2008	22DV50F	RHEEM	0
7000	02/15/2007	LTN040G	LOCHINVAR	0
7001	02/08/2012	M45036FBN	BRADFORD-WHITE	0
7002	03/23/2001	FSG40	AO SMITH	0
7003	10/17/2002	PGR50	AO SMITH	0
7004	01/14/2009	LTN050G	LOCHINVAR	0
7005	03/23/2012	G75125	RUUD/RHEEM	0
7006	09/13/2006	LTN050GEF	LOCHINVAR	1
7007	02/29/2012	MI5036FBN	BRADFORD-WHITE	0
7008	01/07/2011	21VR50	RHEEM	1
7009	06/27/2008	LTN050GEF	LOCHINVAR	0
7010	12/11/2007	PR650X0DS	STATE	0
7011	08/06/1986	FSG50	AO SMITH	0
7012	03/19/2004	GVC50	A. O. SMITH	0
7013	03/07/2013	PH2DV50F	RUUD	0
7014	03/06/1997	PGR50	AO SMITH	0
7015	03/08/1997	PGR50	AO SMITH	0
7016	12/28/2009	FGR50	AO SMITH	0
7017	02/04/2003	FSG50	AO SMITH	1
7018	03/18/2004	XTN050	LOCHINVAR	0
7019	04/21/1995	PRX40	STATE	0
7020	03/23/2004	41XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7021	04/18/2012	PH250SF	RUUD	1
7022	10/12/2000	PGR50	AO SMITH	0
7023	11/04/2010	42VR50	RHEEM	0
7024	05/09/2011	21VR40	RHEEM	0
7025	03/24/2004	PR650	STATE	0
7026	10/18/2009	22DV50F	RHEEM	0
7027	09/16/2012	PH2DV50F	RUUD	0
7028	01/03/2011	21VR50	RHEEM	1
7029	06/08/2004	XVR50	A. O. SMITH	0
7030	05/20/1987	P505	RUUD	0
7031	11/20/2006	LTN051G	LOCHINVAR	0
7032	12/21/2001	FSG50	AO SMITH	0
7033	11/28/2005	LTN050G	LOCHINVAR	0
7034	12/28/2011	M440T6FBN	BRADFORD-WHITE	0
7035	11/13/2008	LTN050GEF	LOCHINVAR	0
7036	04/26/2012	M45036FBN	BRADFORD-WHITE	0
7037	03/04/2011	21VR50	RHEEM	0
7038	04/28/2005	LTN050	LOCHINVAR	0
7039	04/02/2012	MI5036FBN	BRADFORD-WHITE	0
7040	09/30/1988	FSGL40	AO SMITH	0
7041	10/10/2011	M440T6FBN	BRADFORD-WHITE	0
7042	11/23/2011	M45036FBN	BRADFORD-WHITE	1
7043	02/15/2004	PRX40	STATE	0
7044	09/14/2000	FSG50	AO SMITH	0
7045	08/14/2009	LTN050GEF	LOCHINVAR	0
7046	03/17/2008	LTN050	LOCHINVAR	0
7047	10/03/2003	FSG50	AO SMITH	1
7048	02/21/2007	PR650	STATE	0
7049	02/28/1989	FSG50	AO SMITH	0
7050	08/05/2009	LTN050GEF	LOCHINVAR	0
7051	08/17/2000	PRX50	STATE	0
7052	12/27/2002	PGR50	AO SMITH	0
7053	03/19/2004	PRX50	STATE	0
7054	03/27/2006	LTN050G	LOCHINVAR	1
7055	10/01/2001	FSG40	AO SMITH	0
7056	04/15/2009	LTN050GEF	LOCHINVAR	0
7057	08/07/2007	LTN050GEF	LOCHINVAR	0
7058	10/11/2007	LTN050GEF	LOCHINVAR	0
7059	09/20/2005	LTN050	LOCHINVAR	0
7060	04/05/2003	PRX50	STATE	0
7061	06/29/2012	M45036FBN	BRADFORD-WHITE	0
7062	12/21/2012	MI403S6FBN	BRADFORD-WHITE	0
7063	06/16/2006	PR640	STATE	0
7064	12/21/2012	MI403S6FBN	BRADFORD-WHITE	0
7065	08/18/2000	PRX50	STATE	0
7066	06/16/2006	LTN050G	LOCHINVAR	0
7067	03/15/2010	LTN050GEF	LOCHINVAR	0
7068	04/21/2006	LTN050G	LOCHINVAR	0
7069	05/21/2010	LTN050GEF	LOCHINVAR	0
7070	10/21/2008	LTN050GEF	LOCHINVAR	0
7071	07/01/2003	PRX50	STATE	0
7072	09/18/2003	FSG50	AO SMITH	0
7073	06/22/2006	PR650	STATE	0
7074	08/12/1988	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7075	07/31/2009	LTN040GEF	LOCHINVAR	0
7076	03/24/2008	22DV50F	RHEEM	2
7077	03/17/2009	LTN050GEF	LOCHINVAR	2
7078	03/08/2004	FCVL40	AO SMITH	0
7079	03/19/2004	GVC50	A. O. SMITH	0
7080	09/19/1988	FSGL40	AO SMITH	0
7081	07/25/2011	MI5036FBN	BRADFORD-WHITE	0
7082	04/06/2009	22DV50F	RHEEM	0
7083	12/19/1988	FSG50	AO SMITH	0
7084	03/01/2011	21VR50	RHEEM	0
7085	11/28/2007	PR650	STATE	0
7086	01/27/2004	41VR50	RHEEM	0
7087	03/20/2007	LTN050G	LOCHINVAR	0
7088	03/06/2002	PGR50	AO SMITH	0
7089	06/25/2001	PGR50	AO SMITH	0
7090	07/27/2012	MI5036FBN	BRADFORD-WHITE	0
7091	01/21/2003	PGR50	AO SMITH	0
7092	06/01/1982	P502	RUUD	0
7093	05/21/2009	LSN041G	LOCHINVAR	0
7094	05/16/2008	LTN050GEF	LOCHINVAR	0
7095	07/17/2001	41VR50	RHEEM	0
7096	02/22/2001	PGR50	AO SMITH	0
7097	02/27/2007	LTN050G	LOCHINVAR	0
7098	01/05/2007	LTN050G	LOCHINVAR	0
7099	05/22/2005	GCVL40	A. O. SMITH	0
7100	02/19/2004	FCV50	AO SMITH	0
7101	06/08/2011	42VR5040F	RHEEM	0
7102	06/20/2002	FSG40	AO SMITH	0
7103	06/29/2012	M45036FBN	BRADFORD-WHITE	0
7104	07/20/2006	LSN041G	LOCHINVAR	0
7105	04/27/2011	21VR50	RHEEM	0
7106	07/26/2007	LSN041G	LOCHINVAR	0
7107	01/30/1996	PRX40	STATE	0
7108	11/14/2006	LTN040G	LOCHINVAR	0
7109	05/09/1983	P40S	RUUD	0
7110	01/14/1985	FSG50	AO SMITH	0
7111	03/19/2008	G91200	RUUD/RHEEM	0
7112	10/15/2009	LTN040GEF	LOCHINVAR	0
7113	09/03/2008	LTN050GEF	LOCHINVAR	0
7114	11/24/1999	PGR50	AO SMITH	0
7115	07/04/2003	41XR50	RHEEM	0
7116	04/17/2012	M45036FBN	BRADFORD-WHITE	0
7117	10/20/2012	M45036FBN	BRADFORD-WHITE	1
7118	05/19/2009	LTN050GEF	LOCHINVAR	0
7119	10/17/2007	P506	RUUD	0
7120	10/03/2005	LTN050G	LOCHINVAR	0
7121	10/17/2003	FSG50	AO SMITH	0
7122	01/14/2004	XTN050	LOCHINVAR	0
7123	12/24/2008	G75125	RUUD/RHEEM	0
7124	05/21/2008	LTN050GEF	LOCHINVAR	0
7125	07/24/2008	LTN050GEF	LOCHINVAR	0
7126	11/23/2004	GVC40	A. O. SMITH	0
7127	07/02/2004	GVC50	A. O. SMITH	0
7128	01/18/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7129	01/14/2010	LTN050	LOCHINVAR	0
7130	08/01/2008	LTN050GEF	LOCHINVAR	1
7131	01/01/1979	FSG50	AO SMITH	0
7132	02/26/2007	PGR50	AO SMITH	0
7133	10/15/2008	LTN050GEF	LOCHINVAR	0
7134	09/29/2005	PR650	STATE	1
7135	05/22/2008	LTN050GEF	LOCHINVAR	0
7136	06/30/2011	22DV50F	RHEEM	0
7137	03/13/2001	FSG50	AO SMITH	0
7138	04/10/2003	PGR50	AO SMITH	0
7139	02/04/2009	LTN050GEF	LOCHINVAR	0
7140	10/27/2008	LTN051G	LOCHINVAR	0
7141	10/16/2010	PRV50NODS	STATE	0
7142	01/29/2010	LTN040G	LOCHINVAR	0
7143	11/14/2001	FSGL40	AO SMITH	0
7144	06/11/2003	FDV50T	AO SMITH	0
7145	09/06/2006	LTN050GEF	LOCHINVAR	1
7146	12/07/1998	FGR50	AO SMITH	0
7147	03/03/2004	FSG40	AO SMITH	0
7148	07/21/2004	XVR50	A. O. SMITH	0
7149	08/04/2009	G82156	RUUD/RHEEM	0
7150	12/24/2003	21V506	RHEEM	1
7151	07/28/2005	LTN050	LOCHINVAR	0
7152	08/25/2001	41V50	RHEEM	1
7153	09/16/2007	LTN050GEF	LOCHINVAR	0
7154	05/19/2010	LTN050GEF	LOCHINVAR	0
7155	11/16/1994	PR502T	RUUD	0
7156	01/15/2005	PRX50	STATE	1
7157	09/15/2009	LTN050GEF	LOCHINVAR	0
7158	12/20/2005	LTN050GEF	LOCHINVAR	0
7159	09/06/2006	LTN050GEF	LOCHINVAR	1
7160	05/15/2012	MI5036FBN	BRADFORD-WHITE	0
7161	06/01/2001	PGR50	AO SMITH	0
7162	12/10/2012	MI5036FBN	BRADFORD-WHITE	1
7163	12/29/2007	LTN050GEF	LOCHINVAR	0
7164	01/13/2003	FSG50	AO SMITH	0
7165	09/05/2001	PGR50	AO SMITH	0
7166	06/29/2010	LTN050G	LOCHINVAR	0
7167	01/21/1988	FSG50	AO SMITH	0
7168	04/11/2011	21VR50	RHEEM	0
7169	01/25/2001	41V40S	RHEEM	0
7170	05/14/2012	MI5036FBN	BRADFORD-WHITE	0
7171	01/21/1988	FSG50	AO SMITH	0
7172	05/04/2002	FSG50	AO SMITH	0
7173	04/24/2007	LTN050G	LOCHINVAR	0
7174	12/19/2004	XVR50	A. O. SMITH	0
7175	11/03/2008	LTN040GEF	LOCHINVAR	0
7176	06/02/2008	LTN050GEF	LOCHINVAR	0
7177	01/13/2007	LTN050G	LOCHINVAR	0
7178	12/17/2005	LTN050GEF	LOCHINVAR	0
7179	09/23/2003	FSG50	AO SMITH	0
7180	10/28/2007	LTN050G	LOCHINVAR	0
7181	03/27/2002	FSG40	AO SMITH	0
7182	04/09/1997	FGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7183	04/04/2011	22DV50F	RHEEM	0
7184	08/10/2009	LTN050GEF	LOCHINVAR	0
7185	05/25/2006	LTN050G	LOCHINVAR	1
7186	07/02/2010	LTN040	LOCHINVAR	1
7187	02/02/2011	42VR50	RHEEM	0
7188	02/14/1997	PRX50	STATE	0
7189	10/29/2008	LTN050G	LOCHINVAR	2
7190	08/15/2012	PH2DV50F	RUUD	0
7191	07/30/2010	LSN041G	LOCHINVAR	0
7192	04/19/2011	21VR40	RHEEM	1
7193	07/07/2000	PGR50	AO SMITH	0
7194	07/08/2008	LTN050GEF	LOCHINVAR	0
7195	02/13/2012	MI5036FBN	BRADFORD-WHITE	1
7196	02/28/2008	LTN050GEF	LOCHINVAR	0
7197	03/29/2006	LTN050G	LOCHINVAR	0
7198	05/13/2002	FSG50	AO SMITH	0
7199	01/30/2006	LTN050G	LOCHINVAR	0
7200	12/01/2009	LTN050GEF	LOCHINVAR	0
7201	03/11/1987	21V502	RHEEM	0
7202	01/04/2002	PGR50	AO SMITH	0
7203	06/03/2005	PRX50	STATE	0
7204	03/04/2013	PH2DV50F	RUUD	0
7205	12/26/2003	XTN050	LOCHINVAR	2
7206	07/24/2001	PGR40	AO SMITH	1
7207	06/02/2007	XSN040GEF	LOCHINVAR	0
7208	08/03/2009	22DV50F	RHEEM	0
7209	12/22/2012	M45036FBN	BRADFORD-WHITE	0
7210	04/14/2001	41V40S	RHEEM	1
7211	05/18/1998	FGR50	AO SMITH	0
7212	10/19/2008	41XR50	RHEEM	0
7213	01/19/2011	42VR50	RHEEM	0
7214	12/15/2009	LTN050GEF	LOCHINVAR	0
7215	03/03/2000	FSGL40	AO SMITH	0
7216	08/25/2011	M45036FBN	BRADFORD-WHITE	1
7217	07/26/2010	LTN050GEF	LOCHINVAR	0
7218	04/20/2011	41VR50	RHEEM	0
7219	07/16/2008	LSN041G	LOCHINVAR	0
7220	02/05/2007	LTN050G	LOCHINVAR	0
7221	03/07/2003	FSG50	AO SMITH	0
7222	06/06/2011	41VR50	RHEEM	0
7223	07/20/2012	M45036FBN	BRADFORD-WHITE	0
7224	08/15/2002	FSG50	AO SMITH	0
7225	03/31/2001	PGR40	AO SMITH	0
7226	02/22/2001	FGR50	AO SMITH	1
7227	08/19/2008	LTN050GEF	LOCHINVAR	0
7228	03/05/2010	LTN050GEF	LOCHINVAR	0
7229	08/02/2012	MI5036FBN	BRADFORD-WHITE	0
7230	12/30/2011	M45036FBN	BRADFORD-WHITE	0
7231	02/15/2008	LTN050	LOCHINVAR	0
7232	10/14/2005	LTN050G	LOCHINVAR	0
7233	08/23/2002	FSG50	AO SMITH	0
7234	02/16/2005	XVR50	A. O. SMITH	0
7235	12/28/2004	GVC50	A. O. SMITH	0
7236	09/12/2012	PH2DV50F	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7237	12/19/2003	PVR50	AO SMITH	0
7238	10/11/2011	FSG50	AO SMITH	2
7239	01/10/2003	41XR50	RHEEM	0
7240	11/12/2007	LTN040	LOCHINVAR	0
7241	12/05/2008	LSN041G	LOCHINVAR	0
7242	07/16/2012	MI5036FBN	BRADFORD-WHITE	2
7243	05/03/1989	FSG50	AO SMITH	0
7244	09/18/2001	PRX50	STATE	0
7245	05/05/2010	LTN050GEF	LOCHINVAR	0
7246	11/13/2012	M45036FBN	BRADFORD-WHITE	0
7247	02/09/2006	LTN050G	LOCHINVAR	0
7248	01/08/2009	LTN050GEF	LOCHINVAR	0
7249	10/14/2011	PH2DV50F	RUUD	0
7250	02/27/2002	FSG50	AO SMITH	0
7251	04/17/2003	PGR50	AO SMITH	0
7252	09/30/2006	G82156	RUUD/RHEEM	1
7253	01/27/2005	XVR50	A. O. SMITH	0
7254	01/17/2007	LTN050G	LOCHINVAR	1
7255	04/20/2012	MI50L6FBN	BRADFORD-WHITE	0
7256	08/18/2005	LTN050G	LOCHINVAR	0
7257	02/24/2005	GVC50	A. O. SMITH	2
7258	11/21/2003	PVR50	AO SMITH	0
7259	05/05/2010	LTN050GEF	LOCHINVAR	1
7260	05/30/2012	PH2DV50F	RUUD	1
7261	10/18/2003	PRX50	STATE	0
7262	09/16/2005	LSN041G	LOCHINVAR	0
7263	03/20/2002	FSG50	AO SMITH	0
7264	05/03/2006	LTN050G	LOCHINVAR	0
7265	09/04/2008	LTN050GEF	LOCHINVAR	0
7266	12/09/2004	PRX50	STATE	0
7267	11/24/2008	LTN051G	LOCHINVAR	0
7268	12/19/1989	FSG50	AO SMITH	0
7269	05/23/2008	LTN040GEF	LOCHINVAR	0
7270	02/25/2005	XVR50	A. O. SMITH	0
7271	02/02/2001	FSG50	AO SMITH	0
7272	03/07/2011	42V5065F	RHEEM	0
7273	01/28/2013	M45036FBN	BRADFORD-WHITE	0
7274	05/08/2010	LTN050GEF	LOCHINVAR	0
7275	10/12/2002	FSG50	AO SMITH	0
7276	05/28/2003	PGR50	AO SMITH	0
7277	07/17/2012	PH2DV50F	RUUD	0
7278	09/30/2007	LTN050GEF	LOCHINVAR	0
7279	01/21/2003	PRX50	STATE	0
7280	09/09/1999	PR650	STATE	0
7281	03/23/2010	21DV50	RHEEM	1
7282	01/11/2010	LTN050GEF	LOCHINVAR	1
7283	06/15/2010	LTN050G	LOCHINVAR	0
7284	06/30/2012	M440T6FBN	BRADFORD-WHITE	1
7285	01/10/2009	LTN050GEF	LOCHINVAR	0
7286	03/13/2012	M45036FBN	BRADFORD-WHITE	0
7287	09/19/2008	LTN050GEF	LOCHINVAR	0
7288	02/29/2012	MI5036FBN	BRADFORD-WHITE	0
7289	03/16/2009	LTN050GEF	LOCHINVAR	0
7290	04/29/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7291	09/24/1997	FSG50	AO SMITH	0
7292	07/31/2012	MI5036FBN	BRADFORD-WHITE	0
7293	06/08/2001	FSGL40	AO SMITH	0
7294	06/23/2008	LTN050G	LOCHINVAR	0
7295	08/31/2007	LTN050G	LOCHINVAR	0
7296	11/09/2005	LTN050G	LOCHINVAR	0
7297	08/18/2009	22DV50C	RHEEM	1
7298	11/27/1998	PR650	STATE	0
7299	01/27/2012	M45036FBN	BRADFORD-WHITE	0
7300	01/25/2005	FSGL40	AO SMITH	0
7301	01/20/2009	41V50	RHEEM	0
7302	08/22/2003	PVR50	AO SMITH	0
7303	11/14/2005	LTN050G	LOCHINVAR	1
7304	02/25/2012	M45036FBN	BRADFORD-WHITE	0
7305	02/28/2000	FSG50	AO SMITH	0
7306	12/30/2011	MI5036FBN	BRADFORD-WHITE	0
7307	07/31/2012	MI5036FBN	BRADFORD-WHITE	0
7308	05/01/1999	FSG50	AO SMITH	0
7309	12/13/1988	FSG50	AO SMITH	0
7310	01/17/2007	LTN040G	LOCHINVAR	0
7311	03/21/2008	LSN041	LOCHINVAR	1
7312	09/01/2010	41V50	RHEEM	0
7313	10/06/2005	LTN050	LOCHINVAR	0
7314	12/13/2012	M45036FBN	BRADFORD-WHITE	0
7315	12/24/2011	MI5036FBN	BRADFORD-WHITE	2
7316	01/10/2006	LTN050G	LOCHINVAR	0
7317	11/07/1988	BTR120	AO SMITH	0
7318	10/04/2004	GCVL40	A. O. SMITH	1
7319	02/27/2004	PRX50	STATE	1
7320	03/22/2004	PVR50	AO SMITH	0
7321	04/17/2012	MI5036FBN	BRADFORD-WHITE	0
7322	10/05/1999	FSG50	AO SMITH	0
7323	01/14/2006	LTN050G	LOCHINVAR	1
7324	12/10/2009	LSN041G	LOCHINVAR	0
7325	11/21/2001	FSG50	AO SMITH	0
7326	05/13/2004	FSG40	AO SMITH	0
7327	01/06/2003	PGR50	AO SMITH	0
7328	04/12/2001	41V50	RHEEM	0
7329	03/26/2010	22DV50F	RHEEM	0
7330	08/13/2002	FSG50	AO SMITH	0
7331	10/02/2006	LTN050G	LOCHINVAR	0
7332	07/23/2009	LTN040GEF	LOCHINVAR	1
7333	03/30/2005	XVR40	A. O. SMITH	0
7334	12/15/2012	MI5036FBN	BRADFORD-WHITE	0
7335	06/17/1988	FSG50	AO SMITH	1
7336	06/21/2010	LTN050GEF	LOCHINVAR	0
7337	07/08/2005	LTN050	LOCHINVAR	0
7338	04/03/2003	PGR50	AO SMITH	0
7339	06/10/2011	22DV50F	RHEEM	1
7340	01/13/2011	42VR50	RHEEM	1
7341	08/27/2001	41XR50	RHEEM	1
7342	01/15/2004	FCV50	AO SMITH	0
7343	02/23/2007	LTN050G	LOCHINVAR	1
7344	01/23/2007	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7345	07/19/2004	PRX50	STATE	0
7346	05/14/1999	FGR50	AO SMITH	1
7347	01/14/2011	42VR50	RHEEM	0
7348	10/20/2012	G76200	RUUD/RHEEM	1
7349	05/25/2012	PH2DV50F	RUUD	0
7350	01/20/2007	LTN050G	LOCHINVAR	0
7351	01/08/2001	FSG50	AO SMITH	0
7352	11/24/2006	G76200	RUUD/RHEEM	0
7353	08/10/2001	PRX50	STATE	0
7354	12/27/1999	FSG50	AO SMITH	0
7355	03/16/2009	22DV50C	RHEEM	0
7356	02/26/1999	FGR50	AO SMITH	0
7357	05/07/1999	41VR50	RHEEM	1
7358	03/22/2011	LTN040	LOCHINVAR	1
7359	06/04/2004	GVC50	A. O. SMITH	0
7360	10/09/2006	LTN050G	LOCHINVAR	0
7361	08/29/2006	G75125	RUUD/RHEEM	0
7362	04/07/2008	PRX50	STATE	0
7363	08/17/2012	M45036FBN	BRADFORD-WHITE	0
7364	11/28/2011	PH2DV50F	RUUD	0
7365	09/13/2012	PH2DV50F	RUUD	0
7366	07/03/2005	LTN050	LOCHINVAR	0
7367	12/08/2010	41XR50	RHEEM	0
7368	06/27/2001	PRX50	STATE	0
7369	02/16/2007	LTN050G	LOCHINVAR	0
7370	01/02/1987	21V502	RHEEM	0
7371	02/23/2012	PH250SF	RUUD	0
7372	12/03/2004	GVC50	A. O. SMITH	0
7373	06/24/1987	FSG50	AO SMITH	0
7374	05/19/1987	FSG50	AO SMITH	0
7375	08/29/2003	FCV40	AO SMITH	0
7376	04/19/2002	PGR50	AO SMITH	0
7377	04/11/2002	PGR50	AO SMITH	2
7378	05/03/2004	41XR50	RHEEM	1
7379	12/11/2012	MI5036FBN	BRADFORD-WHITE	0
7380	09/26/2000	PGR50	AO SMITH	0
7381	11/23/1997	FGR50	AO SMITH	0
7382	01/12/2009	LTN050GEF	LOCHINVAR	1
7383	08/14/2005	LTN050GEF	LOCHINVAR	0
7384	09/15/2010	LTN040GEF	LOCHINVAR	0
7385	03/21/2004	FSG50	AO SMITH	0
7386	09/28/2010	42VR50	RHEEM	2
7387	01/12/2009	LTN050G	LOCHINVAR	1
7388	05/03/2011	21VR50	RHEEM	0
7389	12/14/2006	LTN050G	LOCHINVAR	0
7390	12/02/1987	FSG50	AO SMITH	0
7391	05/26/2006	LTN050G	LOCHINVAR	0
7392	01/04/2011	41VR40	RHEEM	0
7393	08/17/2012	M45036FBN	BRADFORD-WHITE	0
7394	08/17/1987	PRX50	STATE	0
7395	10/05/2000	PGR50	AO SMITH	1
7396	05/09/2005	P506	RUUD	0
7397	07/26/2012	M45036FBN	BRADFORD-WHITE	0
7398	01/17/1995	PHR50	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7399	11/20/2009	LTN050GEF	LOCHINVAR	0
7400	02/07/2003	21V506	RHEEM	0
7401	08/27/2007	PR650	STATE	0
7402	09/12/1986	FSG50	AO SMITH	0
7403	03/20/2012	M45036FBN	BRADFORD-WHITE	0
7404	01/27/2011	42V50SF	RHEEM	2
7405	11/15/1988	FSG50	AO SMITH	0
7406	12/28/2007	LTN050GEF	LOCHINVAR	0
7407	02/19/2008	LTN050G	LOCHINVAR	1
7408	09/15/2008	LTN050GEF	LOCHINVAR	0
7409	12/15/2008	LTN050GEF	LOCHINVAR	0
7410	02/15/2011	21VR50	RHEEM	0
7411	12/18/2008	LTN050GEF	LOCHINVAR	0
7412	09/21/2011	MI5036FBN	BRADFORD-WHITE	0
7413	09/04/1998	FGR50	AO SMITH	1
7414	07/15/1988	FSG50	AO SMITH	0
7415	08/27/2000	FSG50	AO SMITH	0
7416	04/14/1999	PRV40NODS	STATE	0
7417	12/19/2000	41XR50	RHEEM	0
7418	10/23/1987	FSG50	AO SMITH	0
7419	11/30/2010	21VR40	RHEEM	3
7420	12/02/2008	22DV50C	RHEEM	0
7421	11/18/2005	LTN050G	LOCHINVAR	0
7422	09/24/2001	FSG50	AO SMITH	0
7423	10/01/2003	PRX50	STATE	0
7424	09/21/2007	LTN050GEF	LOCHINVAR	0
7425	12/14/2001	PGR50	AO SMITH	1
7426	08/21/2001	PRX50	STATE	0
7427	01/21/2000	PGR50	AO SMITH	0
7428	08/29/2012	PH2DV50F	RUUD	0
7429	07/22/2005	LTN050	LOCHINVAR	0
7430	08/08/1997	FSG50	AO SMITH	0
7431	06/30/2001	PRX50	STATE	0
7432	10/21/2008	LTN050GEF	LOCHINVAR	0
7433	10/11/2005	PR650	STATE	0
7434	12/23/2011	MI5036FBN	BRADFORD-WHITE	0
7435	04/09/2011	21VR50	RHEEM	0
7436	12/20/2005	LTN050G	LOCHINVAR	0
7437	10/01/2004	42XR50	RHEEM	0
7438	09/04/2004	GCVL40	A. O. SMITH	0
7439	01/19/2013	M45036FBN	BRADFORD-WHITE	0
7440	08/16/2001	PGR50	AO SMITH	0
7441	12/07/2009	LSN041G	LOCHINVAR	0
7442	01/08/1996	FGR50	AO SMITH	0
7443	04/06/1988	FSG50	AO SMITH	0
7444	12/23/2002	PGR50	AO SMITH	0
7445	01/21/2011	G91200	RUUD/RHEEM	0
7446	08/12/2009	LTN050GEF	LOCHINVAR	0
7447	05/22/2006	LTN050G	LOCHINVAR	0
7448	12/04/2007	LSN041G	LOCHINVAR	1
7449	01/03/2012	MI5036FBN	BRADFORD-WHITE	0
7450	11/30/2001	PGR50	AO SMITH	0
7451	10/08/2002	FSG50	AO SMITH	0
7452	08/27/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7453	08/28/2009	LTN050GEF	LOCHINVAR	0
7454	05/21/2008	LTN050GEF	LOCHINVAR	0
7455	11/21/2007	LTN050G	LOCHINVAR	1
7456	11/09/2009	LTN050G	LOCHINVAR	0
7457	01/07/2002	FSG50	AO SMITH	0
7458	08/07/2008	LTN050GEF	LOCHINVAR	0
7459	01/01/1987	FSG50	AO SMITH	0
7460	01/12/2007	LTN040G	LOCHINVAR	1
7461	05/19/2008	22DV50C	RHEEM	0
7462	06/10/2009	LTN050GEF	LOCHINVAR	0
7463	01/20/2010	LTN050GEF	LOCHINVAR	0
7464	11/09/2010	21VR50	RHEEM	0
7465	01/15/2013	PH2DV50F	RUUD	1
7466	06/30/2009	LTN050GEF	LOCHINVAR	0
7467	02/07/2013	MI5036FBN	BRADFORD-WHITE	0
7468	01/15/2013	MI5036FBN	BRADFORD-WHITE	0
7469	06/13/2006	LTN050G	LOCHINVAR	0
7470	12/19/1995	PGR50	AO SMITH	0
7471	01/07/2002	21V407	RHEEM	0
7472	10/19/2009	22DV50C	RHEEM	0
7473	07/06/2010	LTN050G	LOCHINVAR	0
7474	07/20/2012	M45036FBN	BRADFORD-WHITE	0
7475	01/28/2009	LTN050GEF	LOCHINVAR	0
7476	01/10/2003	PR650	STATE	0
7477	10/18/2004	GVC50	A. O. SMITH	1
7478	01/14/2008	LTN040GEF	LOCHINVAR	1
7479	10/20/2007	LTN050GEF	LOCHINVAR	0
7480	03/06/2006	LTN050G	LOCHINVAR	0
7481	04/19/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
7482	02/09/2012	M45036FBN	BRADFORD-WHITE	0
7483	09/09/1986	FSG50	AO SMITH	0
7484	09/09/2009	PH199119	PHOENIX	0
7485	03/20/1998	PRV50NODS	STATE	1
7486	06/16/2003	FSG40	AO SMITH	0
7487	12/02/2010	42VR50	RHEEM	0
7488	07/05/2005	LTN050	LOCHINVAR	0
7489	01/04/1999	41VR50	RHEEM	0
7490	02/28/2012	M45036FBN	BRADFORD-WHITE	0
7491	10/21/2012	PH2DV50F	RUUD	0
7492	11/27/1997	PGR50	AO SMITH	0
7493	09/01/2011	M45036FBN	BRADFORD-WHITE	0
7494	04/23/2008	LTN050GEF	LOCHINVAR	0
7495	07/09/2001	FSG50	AO SMITH	0
7496	04/09/2007	LTN050G	LOCHINVAR	0
7497	11/21/1988	PRX50	STATE	0
7498	11/17/2008	LTN050GEF	LOCHINVAR	0
7499	12/30/1988	FSG50	AO SMITH	0
7500	12/16/2009	LTN050GEF	LOCHINVAR	2
7501	10/19/2000	21V506	RHEEM	0
7502	10/27/2004	GVC50	A. O. SMITH	1
7503	02/14/2003	FSG50	AO SMITH	0
7504	05/20/2009	LTN051G	LOCHINVAR	0
7505	11/09/2004	GVC50	A. O. SMITH	1
7506	08/13/2012	PRX50	STATE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7507	09/15/2006	PR650	STATE	0
7508	02/01/2011	21VR50	RHEEM	0
7509	12/21/2012	M440T6FBN	BRADFORD-WHITE	3
7510	12/08/2012	B71	UNKNOWN	0
7511	01/11/2000	FSGL40	AO SMITH	0
7512	04/26/2005	PRX50	STATE	0
7513	06/04/2010	LTN050GEF	LOCHINVAR	2
7514	01/23/2004	XTN050	LOCHINVAR	0
7515	10/06/2006	LTN050GEF	LOCHINVAR	0
7516	12/15/2011	PH19980	PHOENIX	1
7517	05/26/2009	22DV50F	RHEEM	0
7518	11/21/2000	FSG50	AO SMITH	1
7519	04/19/2012	M45036FBN	BRADFORD-WHITE	0
7520	12/19/2009	LTN050GEF	LOCHINVAR	0
7521	05/28/2010	22DV50C	RHEEM	2
7522	10/10/2003	FCV50	AO SMITH	0
7523	03/17/2001	PR650	STATE	0
7524	08/15/2007	PR650	STATE	0
7525	02/07/2000	PRX50	STATE	0
7526	11/04/2011	M45036FBN	BRADFORD-WHITE	0
7527	08/26/2011	MI403S6FBN	BRADFORD-WHITE	1
7528	09/07/1988	FSG50	AO SMITH	0
7529	08/19/2008	LTN050GEF	LOCHINVAR	0
7530	05/15/2003	FSG40	AO SMITH	0
7531	10/07/1988	FSG50	AO SMITH	0
7532	03/14/2007	LTN050G	LOCHINVAR	0
7533	04/17/2006	PR650	STATE	0
7534	07/18/2011	M45036FBN	BRADFORD-WHITE	0
7535	07/26/2012	M45036FBN	BRADFORD-WHITE	1
7536	07/06/1999	PRV50NODS	STATE	0
7537	12/27/2010	22DV50F	RHEEM	0
7538	09/18/2009	22DV50C	RHEEM	0
7539	06/05/2001	FSG50	AO SMITH	0
7540	11/09/2009	22DV50C	RHEEM	0
7541	04/09/2010	G91200	RUUD/RHEEM	0
7542	02/22/1995	BTC197	AO SMITH	0
7543	01/02/2008	LTN050G	LOCHINVAR	1
7544	02/10/2011	22DV50F	RHEEM	0
7545	11/27/2007	LTN040G	LOCHINVAR	0
7546	07/19/1999	G91200	RUUD/RHEEM	0
7547	10/12/2011	MI5036FBN	BRADFORD-WHITE	0
7548	02/02/2007	LTN050G	LOCHINVAR	0
7549	12/06/2006	LTN050GEF	LOCHINVAR	1
7550	03/13/2001	41XR50	RHEEM	0
7551	01/16/2001	41V50	RHEEM	0
7552	04/13/2004	PRX50	STATE	1
7553	05/02/2008	LTN050GEF	LOCHINVAR	0
7554	07/20/2005	LTN050	LOCHINVAR	1
7555	03/04/2005	PR640	STATE	0
7556	09/01/2011	M45036FBN	BRADFORD-WHITE	0
7557	08/12/2005	LTN050G	LOCHINVAR	0
7558	01/10/2005	XVR50	A. O. SMITH	0
7559	08/28/2012	PH2DV50F	RUUD	0
7560	08/21/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7561	04/05/2010	PGR50	AO SMITH	0
7562	08/19/1987	FSG50	AO SMITH	0
7563	03/11/2005	GVC50	A. O. SMITH	0
7564	09/09/2009	LTN050GEF	LOCHINVAR	0
7565	07/19/2001	G91200	RUUD/RHEEM	1
7566	09/17/2007	LTN050GEF	LOCHINVAR	0
7567	04/24/1987	FSG50	AO SMITH	0
7568	01/02/2008	LTN050GEF	LOCHINVAR	0
7569	05/04/2001	FSG40	AO SMITH	0
7570	01/03/2001	41V50	RHEEM	0
7571	07/05/2009	LTN051G	LOCHINVAR	0
7572	07/23/2004	GVC50	A. O. SMITH	0
7573	02/15/2011	22DV50F	RHEEM	0
7574	01/06/2010	22DV50C	RHEEM	0
7575	04/28/2003	PGR50	AO SMITH	0
7576	12/21/2004	PRX50	STATE	0
7577	12/04/2009	LTN050GEF	LOCHINVAR	0
7578	05/17/1998	FGR50	AO SMITH	0
7579	03/08/1988	FSG50	AO SMITH	0
7580	07/18/2005	LSN041G	LOCHINVAR	0
7581	08/31/2007	LTN050GEF	LOCHINVAR	0
7582	11/01/2000	FSG50	AO SMITH	0
7583	07/15/2002	PGR50	AO SMITH	0
7584	06/26/2012	M45036FBN	BRADFORD-WHITE	0
7585	01/25/2006	LTN050G	LOCHINVAR	0
7586	02/11/2012	M45036FBN	BRADFORD-WHITE	0
7587	10/05/2011	MI5036FBN	BRADFORD-WHITE	0
7588	10/04/2011	M45036FBN	BRADFORD-WHITE	0
7589	01/20/2003	PGR50	AO SMITH	0
7590	02/13/2009	LTN050GEF	LOCHINVAR	0
7591	01/30/2009	LTN040G	LOCHINVAR	2
7592	01/28/2011	22V50F1	RHEEM	0
7593	08/13/2012	PH2DV50F	RUUD	1
7594	08/07/2010	LTN050GEF	LOCHINVAR	0
7595	06/09/2009	LTN050GEF	LOCHINVAR	0
7596	11/15/2005	LTN050GEF	LOCHINVAR	0
7597	05/26/1988	FSG50	AO SMITH	0
7598	12/14/2003	FCV50	AO SMITH	1
7599	07/21/2010	LTN050G	LOCHINVAR	0
7600	07/19/2011	M45036FBN	BRADFORD-WHITE	0
7601	05/14/2012	MI5036FBN	BRADFORD-WHITE	0
7602	07/01/2004	GVC50	A. O. SMITH	0
7603	12/31/1996	PRV50NODS	STATE	0
7604	12/31/2008	22DV50F	RHEEM	0
7605	05/20/2010	LTN050GEF	LOCHINVAR	0
7606	12/01/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
7607	08/31/2012	PH2DV50F	RUUD	0
7608	08/02/2012	MI5036FBN	BRADFORD-WHITE	0
7609	05/16/2003	FSG50	AO SMITH	0
7610	01/25/2008	LTN051G	LOCHINVAR	0
7611	03/18/2008	LTN050GEF	LOCHINVAR	0
7612	02/10/2010	LTN050GEF	LOCHINVAR	0
7613	03/30/2007	LTN050G	LOCHINVAR	0
7614	05/13/2008	22DV50F	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7615	03/04/2009	LSN041G	LOCHINVAR	0
7616	07/29/2004	PRX50	STATE	1
7617	06/25/2008	22DV50C	RHEEM	0
7618	02/06/2006	LTN050G	LOCHINVAR	1
7619	08/29/2005	XSN040GEF	LOCHINVAR	0
7620	02/09/2005	GVC50	A. O. SMITH	0
7621	08/26/2010	42VR50	RHEEM	0
7622	10/27/2010	21DV50	RHEEM	0
7623	10/11/2012	MI403S6FBN	BRADFORD-WHITE	0
7624	11/18/1988	FSG50	AO SMITH	0
7625	10/26/2008	LTN040GEF	LOCHINVAR	0
7626	10/13/1988	FSG50	AO SMITH	0
7627	04/19/2005	XVR50	A. O. SMITH	0
7628	12/04/1989	FSG50	AO SMITH	0
7629	01/08/2011	22DV50F	RHEEM	0
7630	01/03/1999	41VR50	RHEEM	1
7631	06/17/2002	PRX50	STATE	1
7632	08/24/2004	PRX50	STATE	0
7633	10/21/2002	FSG50	AO SMITH	0
7634	02/20/2004	FCVL40	AO SMITH	0
7635	01/02/1999	41V50S	RHEEM	1
7636	08/13/2011	MI5036FBN	BRADFORD-WHITE	0
7637	08/10/2005	LTN050G	LOCHINVAR	0
7638	07/15/2003	PGR50	AO SMITH	0
7639	03/16/2007	LTN050G	LOCHINVAR	0
7640	01/22/1996	RF67120	RUUD	0
7641	03/29/2002	FSG50	AO SMITH	0
7642	07/19/2011	MI5036FBN	BRADFORD-WHITE	1
7643	03/22/2007	PR650X0DS	STATE	0
7644	04/29/1999	FGR50	AO SMITH	0
7645	02/23/2012	MI5036FBN	BRADFORD-WHITE	0
7646	03/23/2011	42VR50	RHEEM	0
7647	07/26/2005	LTN050G	LOCHINVAR	0
7648	08/25/1988	PRV50NODS	STATE	0
7649	03/27/2008	LTN050GEF	LOCHINVAR	1
7650	03/31/2010	LTN050GEF	LOCHINVAR	0
7651	02/08/1989	FSG50	AO SMITH	0
7652	10/27/1988	FSG50	AO SMITH	0
7653	01/15/2003	PRX50	STATE	0
7654	02/27/2008	LTN050GEF	LOCHINVAR	0
7655	12/10/2001	41XR50	RHEEM	0
7656	01/06/2007	PR650	STATE	0
7657	11/07/2006	LTN050G	LOCHINVAR	0
7658	09/15/2003	FCVL40	AO SMITH	0
7659	08/09/2005	PR650	STATE	0
7660	11/15/2002	FSG50	AO SMITH	0
7661	05/25/2007	LTN050G	LOCHINVAR	0
7662	11/02/2011	M45036FBN	BRADFORD-WHITE	0
7663	09/17/2001	PRX50	STATE	0
7664	03/04/2008	LTN050	LOCHINVAR	2
7665	11/09/1987	FSG50	AO SMITH	0
7666	04/06/2010	LTN050GEF	LOCHINVAR	0
7667	12/22/2001	41V40S	RHEEM	0
7668	10/03/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7669	08/27/1987	PRX50	STATE	0
7670	05/19/2005	LTN050	LOCHINVAR	1
7671	08/18/2012	M45036FBN	BRADFORD-WHITE	0
7672	04/01/2011	41VR50	RHEEM	0
7673	04/03/2012	41VR50	RHEEM	0
7674	02/05/2013	MI5036FBN	BRADFORD-WHITE	0
7675	07/07/2008	LSN041G	LOCHINVAR	0
7676	01/24/2011	22DV50F	RHEEM	0
7677	05/06/1999	FSG50	AO SMITH	0
7678	04/13/2007	LTN050G	LOCHINVAR	0
7679	03/30/2009	LTN050GEF	LOCHINVAR	0
7680	08/23/2006	LTN050G	LOCHINVAR	0
7681	07/17/2007	LTN050GEF	LOCHINVAR	0
7682	09/25/1986	FSGL40	AO SMITH	0
7683	02/10/2007	LTN050GEF	LOCHINVAR	0
7684	12/23/2008	LTN050GEF	LOCHINVAR	0
7685	10/01/2004	GCVL40	A. O. SMITH	0
7686	03/09/2011	42VR50	RHEEM	0
7687	02/22/2012	D71	UNKNOWN	0
7688	12/19/2007	PR650X0DS	STATE	0
7689	07/24/1986	FSG50	AO SMITH	0
7690	06/20/2011	M45036FBN	BRADFORD-WHITE	0
7691	11/25/2002	PGR50	AO SMITH	0
7692	07/27/2011	M45036FBN	BRADFORD-WHITE	0
7693	02/01/2007	GVC50	A. O. SMITH	0
7694	08/25/2001	PGR50	AO SMITH	0
7695	10/12/2009	LTN050GEF	LOCHINVAR	0
7696	02/18/2011	22DV50F	RHEEM	0
7697	03/05/2009	LTN050GEF	LOCHINVAR	0
7698	01/10/2013	PH2DV50F	RUUD	0
7699	03/01/2001	41XR50	RHEEM	0
7700	11/25/2005	FSG50	AO SMITH	1
7701	02/15/2011	21VR50	RHEEM	0
7702	01/26/2004	PVR50	AO SMITH	0
7703	10/18/2011	M45036FBN	BRADFORD-WHITE	0
7704	08/26/2008	LTN050GEF	LOCHINVAR	0
7705	04/04/1988	FSG50	AO SMITH	0
7706	08/29/2008	LTN050GEF	LOCHINVAR	0
7707	10/04/1988	FSG50	AO SMITH	0
7708	04/03/2006	LTN050G	LOCHINVAR	0
7709	06/21/2006	LTN050G	LOCHINVAR	1
7710	07/08/2009	LTN050G	LOCHINVAR	0
7711	03/31/2005	GVC50	A. O. SMITH	0
7712	06/16/1997	PGR50	AO SMITH	0
7713	07/14/2012	MI5036FBN	BRADFORD-WHITE	0
7714	09/08/2010	41VR50	RHEEM	0
7715	12/04/2007	LTN050GEF	LOCHINVAR	0
7716	03/01/1988	FSG50	AO SMITH	0
7717	11/19/2010	41VR50	RHEEM	0
7718	11/16/2001	FSG50	AO SMITH	0
7719	07/24/2007	LTN040G	LOCHINVAR	0
7720	02/06/2003	FSG50	AO SMITH	0
7721	05/03/2011	41VR50	RHEEM	0
7722	01/07/2009	LTN040GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7723	10/30/1987	P506	RUUD	0
7724	01/30/2009	LTN050GEF	LOCHINVAR	0
7725	03/07/2012	PH2DV50F	RUUD	1
7726	03/02/2012	M45036FBN	BRADFORD-WHITE	0
7727	01/07/2001	PRX50	STATE	0
7728	03/23/2007	LTN050G	LOCHINVAR	0
7729	01/04/2011	42VR50	RHEEM	0
7730	03/14/2011	42VR50	RHEEM	0
7731	05/19/2012	MI403S6FBN	BRADFORD-WHITE	0
7732	06/10/2008	LTN050G	LOCHINVAR	0
7733	12/26/2005	PR650	STATE	0
7734	04/16/2008	LTN050GEF	LOCHINVAR	0
7735	04/26/2007	42VR50	RHEEM	0
7736	08/22/2002	PRX50	STATE	0
7737	11/09/2012	M45036FBN	BRADFORD-WHITE	0
7738	10/05/1987	FSG50	AO SMITH	0
7739	03/23/2001	41XR50	RHEEM	0
7740	03/16/2011	21VR50	RHEEM	0
7741	01/18/2002	41XR50	RHEEM	0
7742	02/21/2008	LTN050G	LOCHINVAR	0
7743	05/25/2010	LTN050G	LOCHINVAR	0
7744	02/28/2006	FGR50	AO SMITH	0
7745	05/28/2005	LTN040	LOCHINVAR	0
7746	09/09/2008	LTN050GEF	LOCHINVAR	0
7747	12/16/2005	LTN050G	LOCHINVAR	0
7748	11/12/2003	G82156	RUUD/RHEEM	1
7749	11/22/2010	21DV50	RHEEM	0
7750	02/01/1998	PRV50NODS	STATE	0
7751	01/19/2002	FSG50	AO SMITH	1
7752	11/17/2006	PR650	STATE	0
7753	09/27/2004	PRX50	STATE	0
7754	01/31/2011	PGR50	AO SMITH	0
7755	08/17/2006	LTN050G	LOCHINVAR	0
7756	08/04/2011	M45036FBN	BRADFORD-WHITE	0
7757	02/05/2008	LSN041G	LOCHINVAR	0
7758	01/19/2011	21VR50	RHEEM	0
7759	08/23/2000	41XR50	RHEEM	0
7760	02/23/2005	LTN050	LOCHINVAR	0
7761	02/01/2007	LTN040G	LOCHINVAR	0
7762	02/01/2013	MI5036FBN	BRADFORD-WHITE	0
7763	01/17/2002	FSG50	AO SMITH	0
7764	07/01/2003	PGR50	AO SMITH	2
7765	09/27/2002	FSG50	AO SMITH	0
7766	02/02/1987	FSG50	AO SMITH	0
7767	09/06/2002	FSG50	AO SMITH	0
7768	04/21/2012	PH2DV50F	RUUD	0
7769	07/06/1997	PRX50	STATE	0
7770	02/01/2000	41XR50	RHEEM	0
7771	05/22/1987	FSG50	AO SMITH	0
7772	09/11/1987	FSG50	AO SMITH	0
7773	04/29/2004	PRX50	STATE	0
7774	11/19/2009	LTN050GEF	LOCHINVAR	0
7775	03/06/2003	PGR50	AO SMITH	0
7776	07/14/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7777	04/23/2004	XTN050	LOCHINVAR	0
7778	07/05/2010	LTN050G	LOCHINVAR	1
7779	05/23/2006	LTN050G	LOCHINVAR	0
7780	04/23/2012	M45036FBN	BRADFORD-WHITE	1
7781	01/22/2009	LTN050GEF	LOCHINVAR	0
7782	08/02/2007	LTN050GEF	LOCHINVAR	1
7783	02/23/2013	M45036FBN	BRADFORD-WHITE	0
7784	04/28/2011	22DV50F	RHEEM	0
7785	06/08/2010	LTN050GEF	LOCHINVAR	0
7786	04/23/2012	M45036FBN	BRADFORD-WHITE	0
7787	08/27/2001	PGR50	AO SMITH	0
7788	09/01/1998	PR650	STATE	0
7789	08/17/1998	PRV50NODS	STATE	0
7790	05/18/2001	FSGL40	AO SMITH	0
7791	05/08/2012	M45036FBN	BRADFORD-WHITE	2
7792	01/07/1999	FSG40	AO SMITH	0
7793	04/12/2006	LTN050G	LOCHINVAR	0
7794	10/31/2007	LTN050GEF	LOCHINVAR	0
7795	04/16/1987	FSG50	AO SMITH	0
7796	02/25/2002	FSG50	AO SMITH	0
7797	12/06/1999	PGR50	AO SMITH	0
7798	09/03/2010	LTN040GEF	LOCHINVAR	0
7799	05/26/2002	PRX50	STATE	0
7800	02/26/2008	LTN050	LOCHINVAR	0
7801	06/02/2011	42VR50	RHEEM	0
7802	04/15/2011	21VR40	RHEEM	0
7803	11/07/2012	M45036FBN	BRADFORD-WHITE	0
7804	05/12/2009	22DV50C	RHEEM	1
7805	08/20/2001	PGR50	AO SMITH	0
7806	01/12/2006	LTN050GEF	LOCHINVAR	0
7807	12/02/2006	LTN050G	LOCHINVAR	0
7808	07/24/1998	21V402S	RHEEM	0
7809	01/29/2000	PRX50	STATE	0
7810	10/11/2005	PR650	STATE	0
7811	10/13/2007	LTN040	LOCHINVAR	3
7812	03/27/2010	LTN040G	LOCHINVAR	0
7813	11/30/1988	FSG50	AO SMITH	0
7814	03/09/1997	FGR50	AO SMITH	0
7815	02/24/2006	LTN050GEF	LOCHINVAR	0
7816	03/01/2005	PRX50	STATE	1
7817	07/16/2009	LTN050GEF	LOCHINVAR	0
7818	09/27/1988	FSG50	AO SMITH	0
7819	12/31/2012	MI5036FBN	BRADFORD-WHITE	0
7820	12/10/2006	LTN050G	LOCHINVAR	0
7821	06/29/2001	FSG50	AO SMITH	0
7822	02/05/1999	FGR50	AO SMITH	0
7823	04/04/2011	22DV50F	RHEEM	1
7824	01/03/2013	M45036FBN	BRADFORD-WHITE	0
7825	11/28/2009	LTN050GEF	LOCHINVAR	0
7826	07/20/2002	21DV50	RHEEM	0
7827	11/30/1988	PRX50	STATE	0
7828	10/27/1988	FSG50	AO SMITH	0
7829	01/09/2004	FCV50	AO SMITH	0
7830	11/17/2010	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7831	11/07/2012	M45036FBN	BRADFORD-WHITE	2
7832	10/25/2012	MI50L6FBN	BRADFORD-WHITE	0
7833	11/06/2006	LTN050G	LOCHINVAR	0
7834	03/13/1989	FSG50	AO SMITH	0
7835	01/10/2007	LTN050G	LOCHINVAR	0
7836	03/23/2006	PRX50	STATE	0
7837	01/04/2006	LTN050G	LOCHINVAR	0
7838	02/28/2005	PRX40	STATE	0
7839	05/08/2007	LTN050G	LOCHINVAR	0
7840	01/02/2008	LTN050GEF	LOCHINVAR	0
7841	02/10/1998	PRV50NODS	STATE	0
7842	07/05/2010	PRX50	STATE	1
7843	05/05/2011	21VR50	RHEEM	1
7844	11/14/2001	FSG50	AO SMITH	0
7845	10/13/2008	LTN050GEF	LOCHINVAR	0
7846	12/01/2000	41V50	RHEEM	1
7847	04/19/2002	FSG50	AO SMITH	0
7848	12/18/2005	LTN050GEF	LOCHINVAR	2
7849	12/20/1988	FSG50	AO SMITH	0
7850	10/06/2006	LTN050G	LOCHINVAR	0
7851	08/31/2004	XVR50	A. O. SMITH	0
7852	06/28/2010	LTN050GEF	LOCHINVAR	1
7853	02/16/2012	MI5036FBN	BRADFORD-WHITE	0
7854	03/09/2004	PVR50	AO SMITH	0
7855	03/07/2006	LTN050G	LOCHINVAR	0
7856	10/17/1998	FGR50	AO SMITH	0
7857	08/17/2011	42V5065F	RHEEM	0
7858	02/25/2008	LTN050GEF	LOCHINVAR	0
7859	02/23/2009	22DV50C	RHEEM	0
7860	07/05/2007	LTN050GEF	LOCHINVAR	0
7861	06/21/2004	GVC50	A. O. SMITH	0
7862	02/06/2008	LTN050GEF	LOCHINVAR	0
7863	09/30/1987	FSG50	AO SMITH	1
7864	05/02/2011	22V50F1	RHEEM	0
7865	03/02/2010	G91200	RUUD/RHEEM	0
7866	06/20/2003	FSG50	AO SMITH	0
7867	12/15/2009	LTN050GEF	LOCHINVAR	0
7868	04/09/2002	PGR50	AO SMITH	0
7869	06/24/2010	LTN040G	LOCHINVAR	1
7870	10/10/2002	BTR198	AO SMITH	0
7871	12/15/2009	LTN050GEF	LOCHINVAR	0
7872	10/18/1988	FSG50	AO SMITH	0
7873	08/16/2010	G75125	RUUD/RHEEM	1
7874	08/26/2007	LTN050GEF	LOCHINVAR	0
7875	11/14/2001	FSG50	AO SMITH	1
7876	07/17/2012	MI5036FBN	BRADFORD-WHITE	0
7877	05/13/2008	LTN050GEF	LOCHINVAR	0
7878	01/25/2010	LTN050GEF	LOCHINVAR	0
7879	08/16/2010	G75125	RUUD/RHEEM	0
7880	01/27/1988	FSG50	AO SMITH	0
7881	01/04/1988	FSG50	AO SMITH	0
7882	03/09/1988	FSG50	AO SMITH	0
7883	03/12/2000	FSG50	AO SMITH	0
7884	07/22/2011	M440T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7885	01/21/2011	42VR50	RHEEM	0
7886	03/07/2007	LTN050G	LOCHINVAR	0
7887	04/23/2009	LTN050GEF	LOCHINVAR	1
7888	08/07/2009	LTN050GEF	LOCHINVAR	0
7889	11/05/2009	LTN050GEF	LOCHINVAR	0
7890	05/27/2009	LTN050GEF	LOCHINVAR	1
7891	01/11/2012	MI5036FBN	BRADFORD-WHITE	2
7892	07/22/2011	M440T6FBN	BRADFORD-WHITE	0
7893	09/15/2010	PRX40	STATE	2
7894	08/17/1988	FSG50	AO SMITH	0
7895	12/28/2009	FSGL40	AO SMITH	0
7896	05/09/2011	41VR50	RHEEM	0
7897	10/24/2004	XVR50	A. O. SMITH	0
7898	12/30/2004	GVC50	A. O. SMITH	1
7899	06/04/2010	LTN050GEF	LOCHINVAR	1
7900	01/16/1998	41VR50	RHEEM	0
7901	12/10/2008	22DV50C	RHEEM	0
7902	04/25/2005	LTN050	LOCHINVAR	1
7903	03/24/2006	LSN041	LOCHINVAR	0
7904	12/29/2008	LTN050GEF	LOCHINVAR	0
7905	12/30/2008	22DV50C	RHEEM	0
7906	12/01/2009	22DV50F	RHEEM	0
7907	01/31/2007	GVC50	A. O. SMITH	0
7908	10/15/2004	PRX50	STATE	0
7909	10/19/2007	LTN050G	LOCHINVAR	0
7910	05/31/2006	PRX50	STATE	0
7911	09/23/1997	41V50	RHEEM	0
7912	07/25/2007	LTN050GEF	LOCHINVAR	0
7913	09/07/1999	FSG50	AO SMITH	0
7914	08/14/2009	LTN050GEF	LOCHINVAR	0
7915	01/09/1998	PRV50NODS	STATE	2
7916	01/28/2011	42XR50	RHEEM	0
7917	01/24/2011	22DV50F	RHEEM	0
7918	09/03/2008	LTN050GEF	LOCHINVAR	0
7919	01/21/2004	XTN050	LOCHINVAR	0
7920	01/20/2008	LTN050GEF	LOCHINVAR	0
7921	05/30/2010	22DV50F	RHEEM	1
7922	04/05/2002	FSG40	AO SMITH	0
7923	03/24/2011	22DV50F	RHEEM	0
7924	04/25/2012	M45036FBN	BRADFORD-WHITE	0
7925	07/28/2004	XTN050	LOCHINVAR	2
7926	12/28/2004	GCVL40	A. O. SMITH	0
7927	07/08/2011	M45036FBN	BRADFORD-WHITE	2
7928	10/13/2008	LTN050GEF	LOCHINVAR	0
7929	05/20/2004	GVC50	A. O. SMITH	0
7930	07/06/2005	LTN050	LOCHINVAR	0
7931	03/16/2007	LTN050G	LOCHINVAR	3
7932	02/22/2007	LTN050G	LOCHINVAR	1
7933	07/16/2006	LTN050G	LOCHINVAR	0
7934	12/23/2008	22DV50C	RHEEM	0
7935	04/03/1998	FGR40	AO SMITH	0
7936	12/20/2012	M45036FBN	BRADFORD-WHITE	0
7937	02/24/2004	GVC50	A. O. SMITH	0
7938	06/10/2011	22DV50F	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7939	12/31/2007	LTN050GEF	LOCHINVAR	0
7940	09/17/2012	PH2DV50F	RUUD	1
7941	01/01/2005	P506	RUUD	0
7942	12/07/2009	22DV50C	RHEEM	0
7943	10/10/2008	LTN050GEF	LOCHINVAR	0
7944	11/20/2008	LTN050GEF	LOCHINVAR	0
7945	09/25/2003	21DV50	RHEEM	0
7946	06/21/2007	LTN051G	LOCHINVAR	0
7947	08/07/2002	PRX50	STATE	1
7948	06/02/1989	21V506	RHEEM	0
7949	03/21/2004	XTN050	LOCHINVAR	0
7950	05/09/2012	M45036FBN	BRADFORD-WHITE	0
7951	03/15/2006	LTN050G	LOCHINVAR	0
7952	01/03/2011	41XR50	RHEEM	0
7953	10/19/1989	FSG50	AO SMITH	0
7954	01/02/2009	LTN050GEF	LOCHINVAR	0
7955	02/21/2004	FCV50	AO SMITH	0
7956	12/09/2005	G75125	RUUD/RHEEM	0
7957	10/28/2001	21V506	RHEEM	0
7958	01/24/2003	FSG50	AO SMITH	0
7959	06/30/1989	PRX50	STATE	0
7960	04/15/2005	XVR50	A. O. SMITH	0
7961	11/26/2007	G82156	RUUD/RHEEM	0
7962	03/13/2012	DS150S6FBN	BRADFORD-WHITE	0
7963	12/03/2005	LTN050G	LOCHINVAR	0
7964	08/28/1989	21V506	RHEEM	0
7965	02/06/2005	XVR50	A. O. SMITH	2
7966	06/20/1998	FGR40	AO SMITH	0
7967	11/10/2009	LTN050GEF	LOCHINVAR	0
7968	12/08/2000	41XR50	RHEEM	0
7969	10/27/2010	22DV50F	RHEEM	0
7970	01/13/2001	41XR50	RHEEM	0
7971	12/28/2009	LTN050GEF	LOCHINVAR	0
7972	12/10/2007	LTN050G	LOCHINVAR	0
7973	01/02/2009	22DV50C	RHEEM	1
7974	01/10/2000	FGR40	AO SMITH	1
7975	01/05/2001	PGR50	AO SMITH	0
7976	08/13/2000	41XR50	RHEEM	0
7977	03/08/2001	PGR50	AO SMITH	0
7978	10/10/2012	MI5036FBN	BRADFORD-WHITE	0
7979	05/03/2007	LTN050G	LOCHINVAR	1
7980	07/05/2001	PGR50	AO SMITH	0
7981	08/21/2002	PGR50	AO SMITH	0
7982	09/28/2005	LTN050G	LOCHINVAR	0
7983	12/02/1988	FSG50	AO SMITH	0
7984	05/29/2009	22DV50C	RHEEM	0
7985	01/28/2008	LTN050GEF	LOCHINVAR	0
7986	12/29/2005	PR650	STATE	0
7987	08/28/1989	FSG50	AO SMITH	0
7988	06/20/2000	FSG50	AO SMITH	0
7989	02/04/2007	LSN041G	LOCHINVAR	0
7990	05/26/2012	M45036FBN	BRADFORD-WHITE	2
7991	08/14/2012	MI5036FBN	BRADFORD-WHITE	1
7992	11/11/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
7993	06/20/2003	PRX50	STATE	0
7994	04/23/2006	LTN050G	LOCHINVAR	0
7995	12/12/2000	G82156	RUUD/RHEEM	0
7996	07/22/2002	FSG50	AO SMITH	0
7997	10/18/2007	LTN050GEF	LOCHINVAR	0
7998	04/05/2010	22DV50C	RHEEM	0
7999	01/03/2003	PGR50	AO SMITH	0
8000	07/23/2009	LTN050GEF	LOCHINVAR	0
8001	08/12/2002	PRX50	STATE	0
8002	09/14/2009	LTN050GEF	LOCHINVAR	0
8003	01/27/2007	GVC50	A. O. SMITH	0
8004	03/13/2013	PH2DV50F	RUUD	0
8005	05/24/2002	G75125	RUUD/RHEEM	2
8006	05/24/2012	M45036FBN	BRADFORD-WHITE	0
8007	10/13/2005	LTN050	LOCHINVAR	0
8008	01/16/2009	LTN050GEF	LOCHINVAR	0
8009	04/09/2010	22DV50C	RHEEM	0
8010	11/11/1988	FSG40	AO SMITH	0
8011	12/07/1998	FSG50	AO SMITH	1
8012	11/08/1988	FSG50	AO SMITH	0
8013	06/09/2006	LTN050G	LOCHINVAR	0
8014	05/10/2006	LTN050G	LOCHINVAR	0
8015	10/10/2008	LTN050G	LOCHINVAR	0
8016	09/25/2006	LTN050G	LOCHINVAR	0
8017	03/10/2003	FSGL40	AO SMITH	0
8018	01/23/2009	LTN050GEF	LOCHINVAR	0
8019	11/19/2012	M45036FBN	BRADFORD-WHITE	0
8020	04/21/2011	41VR50	RHEEM	0
8021	01/15/2010	LTN050GEF	LOCHINVAR	0
8022	03/28/2008	G91200	RUUD/RHEEM	1
8023	05/12/2011	21VR50	RHEEM	0
8024	03/02/2001	41XR50	RHEEM	0
8025	10/31/2011	MI5036FBN	BRADFORD-WHITE	0
8026	02/04/2013	M45036FBN	BRADFORD-WHITE	1
8027	10/06/2008	LTN050GEF	LOCHINVAR	0
8028	10/24/1988	P506	RUUD	0
8029	01/03/2007	LTN050G	LOCHINVAR	0
8030	11/21/1998	PR650	STATE	0
8031	10/20/1988	FSGL40	AO SMITH	1
8032	02/05/2009	LTN050GEF	LOCHINVAR	0
8033	12/11/2001	PR650	STATE	0
8034	09/21/2001	FSG50	AO SMITH	0
8035	01/12/1995	BTC197	AO SMITH	0
8036	07/19/2003	41XR40	RHEEM	0
8037	04/29/2002	FSG50	AO SMITH	0
8038	06/10/2003	FSG50	AO SMITH	0
8039	03/16/2009	FGR50	AO SMITH	0
8040	08/28/2006	LTN050GEF	LOCHINVAR	0
8041	12/03/1987	FSG50	AO SMITH	0
8042	06/18/2010	22DV50C	RHEEM	0
8043	08/06/2012	G76200	RUUD/RHEEM	1
8044	12/10/2009	LTN050GEF	LOCHINVAR	0
8045	12/23/2006	LTN050G	LOCHINVAR	0
8046	03/26/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8047	10/28/1998	PGR50	AO SMITH	0
8048	06/25/2000	PR650	STATE	0
8049	10/25/2005	LTN050G	LOCHINVAR	0
8050	08/03/2001	PGR50	AO SMITH	0
8051	09/28/2009	22DV50C	RHEEM	0
8052	07/08/2006	LTN050G	LOCHINVAR	2
8053	11/15/2008	LSN041G	LOCHINVAR	0
8054	06/10/2010	LTN050GEF	LOCHINVAR	0
8055	05/12/2004	XTN050	LOCHINVAR	0
8056	06/22/2005	LTN050	LOCHINVAR	0
8057	07/17/2007	LTN050GEF	LOCHINVAR	0
8058	10/17/2011	PR650	STATE	0
8059	09/10/2008	LTN050GEF	LOCHINVAR	2
8060	11/06/1987	FSG50	AO SMITH	0
8061	01/10/2013	G75125	RUUD/RHEEM	0
8062	12/19/2011	PH2DV50F	RUUD	0
8063	05/13/2010	LTN050GEF	LOCHINVAR	1
8064	08/21/2012	PH2DV50F	RUUD	0
8065	09/21/2010	21V502	RHEEM	1
8066	07/20/2009	22DV50C	RHEEM	0
8067	02/13/2009	LTN050GEF	LOCHINVAR	0
8068	06/15/2007	LTN050G	LOCHINVAR	0
8069	02/02/2006	G75125	RUUD/RHEEM	0
8070	11/12/2001	FSG50	AO SMITH	0
8071	09/08/2011	M45036FBN	BRADFORD-WHITE	1
8072	01/05/2007	PR650	STATE	0
8073	11/14/2007	LTN050GEF	LOCHINVAR	0
8074	02/19/2008	LTN040GEF	LOCHINVAR	0
8075	02/04/2010	22DV50C	RHEEM	0
8076	03/18/2002	FSG50	AO SMITH	0
8077	05/05/2003	PGR50	AO SMITH	0
8078	12/27/2006	LTN050G	LOCHINVAR	0
8079	11/16/1999	PGR50	AO SMITH	0
8080	08/12/2011	M45036FBN	BRADFORD-WHITE	0
8081	09/23/2004	GVC50	A. O. SMITH	0
8082	07/25/2012	MI5036FBN	BRADFORD-WHITE	0
8083	02/12/2003	FSG40	AO SMITH	0
8084	08/13/2009	LTN050GEF	LOCHINVAR	0
8085	03/28/2008	LTN050GEF	LOCHINVAR	0
8086	06/26/1997	FSG50	AO SMITH	0
8087	05/18/2007	LTN050GEF	LOCHINVAR	0
8088	10/28/2010	41VR50	RHEEM	0
8089	04/09/2009	FSG50	AO SMITH	0
8090	11/13/2000	FSG40	AO SMITH	0
8091	12/04/2001	FSG50	AO SMITH	0
8092	03/01/2012	M45036FBN	BRADFORD-WHITE	0
8093	04/06/2012	M45036FBN	BRADFORD-WHITE	0
8094	01/31/2005	XTN050	LOCHINVAR	0
8095	12/15/2006	LTN050G	LOCHINVAR	0
8096	04/15/2008	LTN050	LOCHINVAR	0
8097	06/22/2012	PH250SF	RUUD	0
8098	01/18/2000	FSG50	AO SMITH	0
8099	11/13/2006	FSG50	AO SMITH	0
8100	08/15/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8101	12/21/2009	LTN040G	LOCHINVAR	0
8102	01/15/2007	LTN050G	LOCHINVAR	0
8103	12/29/2006	LTN050G	LOCHINVAR	0
8104	09/13/2005	LTN040	LOCHINVAR	0
8105	06/02/2008	LTN050G	LOCHINVAR	0
8106	12/09/2003	FSGL40	AO SMITH	0
8107	10/06/2009	PR640	STATE	0
8108	01/30/2004	PVR50	AO SMITH	0
8109	07/31/2007	LTN050GEF	LOCHINVAR	0
8110	02/16/2011	42VR50	RHEEM	1
8111	02/14/2011	22DV50F	RHEEM	0
8112	04/08/2011	21VR50	RHEEM	0
8113	09/20/2011	MI5036FBN	BRADFORD-WHITE	0
8114	09/01/2010	LTN050G	LOCHINVAR	0
8115	03/05/2003	FSG40	AO SMITH	0
8116	11/22/2006	LTN050G	LOCHINVAR	0
8117	09/27/2011	MI5036FBN	BRADFORD-WHITE	0
8118	03/21/2011	42VR50	RHEEM	0
8119	09/17/2012	MI403S6FBN	BRADFORD-WHITE	0
8120	04/09/2012	MI40T6FBN	BRADFORD-WHITE	4
8121	01/12/2002	FSG50	AO SMITH	0
8122	03/02/2011	21DV50	RHEEM	1
8123	01/07/1987	FSG50	AO SMITH	0
8124	10/30/1995	PGR50	AO SMITH	0
8125	07/25/2002	41XR50	RHEEM	0
8126	12/21/2010	22DV50F	RHEEM	0
8127	11/10/2009	LTN050G	LOCHINVAR	2
8128	01/03/2003	PGR50	AO SMITH	0
8129	03/15/1991	FSG50	AO SMITH	0
8130	10/19/2011	M440T6FBN	BRADFORD-WHITE	0
8131	09/25/2001	PGR50	AO SMITH	0
8132	02/16/2011	42VR50	RHEEM	0
8133	03/03/2011	21VR50	RHEEM	0
8134	02/03/2003	PGR50	AO SMITH	0
8135	12/30/2004	LTN050G	LOCHINVAR	0
8136	08/14/2007	LTN050GEF	LOCHINVAR	0
8137	12/29/2003	XTN050	LOCHINVAR	0
8138	10/20/2005	LTN050G	LOCHINVAR	0
8139	09/14/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
8140	12/21/2007	LTN050GEF	LOCHINVAR	0
8141	06/17/2004	XVR50	A. O. SMITH	1
8142	02/12/2004	XTN040	LOCHINVAR	1
8143	12/17/2010	22DV50F	RHEEM	0
8144	06/23/1989	FSG50	AO SMITH	0
8145	12/23/2001	FSG40	AO SMITH	0
8146	08/22/2004	PRX50	STATE	0
8147	11/26/2001	PRX50	STATE	0
8148	08/21/2001	41XR50	RHEEM	1
8149	11/24/2009	21V502	RHEEM	0
8150	05/11/2010	LTN050GEF	LOCHINVAR	1
8151	01/02/2002	PGR50	AO SMITH	0
8152	05/31/1989	FSG50	AO SMITH	0
8153	01/04/2007	LTN050G	LOCHINVAR	3
8154	03/13/2006	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8155	02/16/2006	PR650	STATE	0
8156	09/20/2011	M45036FBN	BRADFORD-WHITE	0
8157	05/01/2010	22DV50C	RHEEM	0
8158	09/23/1998	FSGL40	AO SMITH	0
8159	04/26/2007	LTN050G	LOCHINVAR	0
8160	04/19/2006	PR650	STATE	0
8161	06/03/2009	LTN050GEF	LOCHINVAR	0
8162	07/26/2012	M45036FBN	BRADFORD-WHITE	0
8163	08/13/2007	LTN050G	LOCHINVAR	0
8164	09/12/2003	G82156	RUUD/RHEEM	0
8165	09/11/2009	22DV50F	RHEEM	0
8166	09/01/2009	22DV50C	RHEEM	0
8167	06/12/2003	FSGL40	AO SMITH	0
8168	09/30/2004	LTN050	LOCHINVAR	0
8169	05/26/2010	LTN050GEF	LOCHINVAR	0
8170	08/29/2007	LTN050GEF	LOCHINVAR	0
8171	12/21/2010	42V5065F	RHEEM	1
8172	08/08/2011	PH2DV50F	RUUD	0
8173	02/16/2013	MI403S6FBN	BRADFORD-WHITE	0
8174	07/30/2008	PRV50NODS	STATE	0
8175	11/29/2001	PRX50	STATE	0
8176	10/23/2003	FCV50	AO SMITH	0
8177	09/07/2007	LTN050GEF	LOCHINVAR	0
8178	08/06/2008	LTN050GEF	LOCHINVAR	0
8179	08/15/1988	21V502	RHEEM	0
8180	11/17/2011	42V50SF	RHEEM	0
8181	11/11/2011	MI403S6FBN	BRADFORD-WHITE	2
8182	04/25/2005	LTN050G	LOCHINVAR	0
8183	09/13/2007	LTN050GEF	LOCHINVAR	1
8184	08/25/2004	GVC50	A. O. SMITH	0
8185	08/15/1988	PRX50	STATE	0
8186	06/05/2007	LTN050GEF	LOCHINVAR	0
8187	03/18/2002	PGR50	AO SMITH	0
8188	05/31/2005	LTN050	LOCHINVAR	0
8189	07/30/2001	PGR50	AO SMITH	0
8190	04/25/2008	LTN050GEF	LOCHINVAR	0
8191	04/07/2007	LTN050G	LOCHINVAR	0
8192	10/30/2006	PR650	STATE	0
8193	11/09/2004	GVC50	A. O. SMITH	0
8194	04/02/2007	LTN050G	LOCHINVAR	0
8195	03/21/2003	FSG50	AO SMITH	1
8196	09/15/2008	LTN050GEF	LOCHINVAR	0
8197	07/06/2012	P230F	RUUD	1
8198	12/31/2012	MI5036FBN	BRADFORD-WHITE	0
8199	01/20/2010	LTN050GEF	LOCHINVAR	0
8200	06/24/2008	22DV50F	RHEEM	1
8201	02/07/2005	GVC50	A. O. SMITH	0
8202	10/14/2011	PRX50	STATE	1
8203	12/08/2008	22DV50C	RHEEM	0
8204	01/07/2004	PR650	STATE	1
8205	06/07/2012	PH2DV50F	RUUD	1
8206	01/06/1997	RF67120	RUUD	0
8207	07/10/2006	LTN051G	LOCHINVAR	1
8208	03/26/2009	22DV50C	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8209	10/26/2012	MI5036FBN	BRADFORD-WHITE	0
8210	11/06/2008	LTN050	LOCHINVAR	0
8211	10/10/2011	MI40T6FBN	BRADFORD-WHITE	0
8212	01/15/2003	PGR50	AO SMITH	0
8213	10/27/2005	LTN050GEF	LOCHINVAR	0
8214	07/01/1988	FSG50	AO SMITH	0
8215	05/28/2006	LTN050G	LOCHINVAR	0
8216	02/23/2003	FSG50	AO SMITH	0
8217	12/28/2011	MI40T6FBN	BRADFORD-WHITE	0
8218	05/12/2008	LTN050GEF	LOCHINVAR	0
8219	10/19/2010	42VR50	RHEEM	1
8220	02/18/2001	FSG50	AO SMITH	0
8221	11/05/2009	PR502T	RUUD	0
8222	06/10/2011	42VR50	RHEEM	0
8223	12/05/1986	FSG50	AO SMITH	0
8224	08/20/2001	PGR50	AO SMITH	0
8225	08/21/2002	PGR50	AO SMITH	1
8226	10/24/2011	G82156	RUUD/RHEEM	0
8227	03/20/2006	PR650	STATE	0
8228	03/27/2012	PH2DV50F	RUUD	0
8229	08/08/2005	LTN051	LOCHINVAR	0
8230	01/29/2008	LTN050GEF	LOCHINVAR	0
8231	10/24/2011	G82156	RUUD/RHEEM	0
8232	09/29/2007	LTN050GEF	LOCHINVAR	0
8233	01/24/2009	22DV50F	RHEEM	0
8234	10/14/2009	LTN050GEF	LOCHINVAR	0
8235	06/18/1999	FSG50	AO SMITH	0
8236	11/15/2012	MI5036FBN	BRADFORD-WHITE	0
8237	05/08/2006	PR650	STATE	0
8238	02/17/2003	PRX40	STATE	0
8239	11/10/1986	FSG50	AO SMITH	0
8240	05/25/2005	LTN050	LOCHINVAR	0
8241	08/14/2000	PRX50	STATE	0
8242	02/28/1998	PGR50	AO SMITH	0
8243	04/09/2012	M45036FBN	BRADFORD-WHITE	0
8244	04/29/2005	LTN050	LOCHINVAR	0
8245	04/26/1987	FSG50	AO SMITH	0
8246	09/23/2010	42VR50	RHEEM	0
8247	05/09/2005	GVC50	A. O. SMITH	0
8248	05/18/2007	PR650	STATE	1
8249	04/24/1987	FSG50	AO SMITH	0
8250	01/28/2002	FSG50	AO SMITH	0
8251	04/02/2009	LTN050GEF	LOCHINVAR	0
8252	10/06/2008	LTN050GEF	LOCHINVAR	0
8253	01/30/2009	LTN050GEF	LOCHINVAR	0
8254	06/05/2008	22DV50C	RHEEM	0
8255	03/03/2000	FSG50	AO SMITH	0
8256	09/22/1999	FGR50	AO SMITH	0
8257	04/30/2007	LTN050G	LOCHINVAR	0
8258	07/07/2011	MI5036FBN	BRADFORD-WHITE	0
8259	04/14/2010	LTN050GEF	LOCHINVAR	0
8260	07/13/2005	LTN050	LOCHINVAR	0
8261	04/27/2007	LTN050G	LOCHINVAR	0
8262	07/18/2002	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8263	02/26/1996	FSG50	AO SMITH	0
8264	05/13/1998	PGR50	AO SMITH	0
8265	01/26/2011	42VR5040F	RHEEM	0
8266	12/21/2010	42VR50	RHEEM	0
8267	01/24/2013	M45036FBN	BRADFORD-WHITE	0
8268	08/14/2004	G75125	RUUD/RHEEM	0
8269	07/07/2010	PRX50	STATE	0
8270	05/04/2011	22DV50F	RHEEM	0
8271	04/06/2007	PR650	STATE	0
8272	02/08/2007	LTN050G	LOCHINVAR	0
8273	10/10/2008	PR640	STATE	0
8274	06/02/2003	FSG50	AO SMITH	0
8275	01/27/2012	M45036FBN	BRADFORD-WHITE	0
8276	02/20/2010	22DV50F	RHEEM	0
8277	03/09/2009	LTN050GEF	LOCHINVAR	1
8278	01/16/2010	LTN051G	LOCHINVAR	0
8279	07/14/2011	M45036FBN	BRADFORD-WHITE	0
8280	06/03/1999	FSG50	AO SMITH	0
8281	12/03/2001	PGR50	AO SMITH	0
8282	01/05/2004	XTN050	LOCHINVAR	1
8283	06/12/1989	FSG50	AO SMITH	0
8284	03/22/2010	LTN050G	LOCHINVAR	0
8285	06/22/1989	P502	RUUD	0
8286	02/14/2013	D71DUMMY	UNKNOWN AT CONVERSION	0
8287	03/18/2004	GVC50	A. O. SMITH	1
8288	12/10/2011	MI5036FBN	BRADFORD-WHITE	0
8289	08/03/2005	PR650	STATE	0
8290	06/17/2008	LTN050GEF	LOCHINVAR	0
8291	07/23/2009	LTN050GEF	LOCHINVAR	1
8292	09/19/2011	MI5036FBN	BRADFORD-WHITE	0
8293	05/28/2011	41VR50	RHEEM	0
8294	11/08/2011	MI5036FBN	BRADFORD-WHITE	0
8295	06/15/2004	GVC50	A. O. SMITH	0
8296	01/06/2007	PR650	STATE	2
8297	07/10/2008	LTN050GEF	LOCHINVAR	0
8298	07/26/2006	LTN050G	LOCHINVAR	0
8299	07/26/2011	MI5036FBN	BRADFORD-WHITE	1
8300	01/10/2012	M45036FBN	BRADFORD-WHITE	0
8301	11/22/2011	M45036FBN	BRADFORD-WHITE	0
8302	09/20/2008	LTN050GEF	LOCHINVAR	0
8303	08/04/2006	P506	RUUD	0
8304	09/11/1989	FSG50	AO SMITH	0
8305	06/16/2012	PRX50	STATE	0
8306	05/09/2011	21VR50	RHEEM	0
8307	03/14/2007	LTN050G	LOCHINVAR	0
8308	10/18/2006	PR650	STATE	1
8309	03/22/2001	FSG50	AO SMITH	1
8310	02/12/2013	MI5036FBN	BRADFORD-WHITE	0
8311	07/09/2009	LTN050GEF	LOCHINVAR	0
8312	09/10/2011	M45036FBN	BRADFORD-WHITE	1
8313	07/08/2002	PRX50	STATE	0
8314	03/09/1988	FSG40	AO SMITH	0
8315	04/22/2011	41VR50	RHEEM	0
8316	02/28/2007	G91200	RUUD/RHEEM	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8317	09/22/2009	22DV50C	RHEEM	1
8318	03/04/2003	PGR50	AO SMITH	0
8319	04/28/2006	LTN050G	LOCHINVAR	0
8320	11/16/2012	PRX50	STATE	0
8321	06/27/2010	22DV50C	RHEEM	0
8322	01/27/2006	LTN050G	LOCHINVAR	0
8323	02/24/2004	XTN050	LOCHINVAR	0
8324	09/21/2004	GVC50	A. O. SMITH	1
8325	07/23/2007	LTN050GEF	LOCHINVAR	0
8326	05/01/2006	LTN050G	LOCHINVAR	0
8327	09/14/2005	LTN050G	LOCHINVAR	0
8328	12/22/2012	M45036FBN	BRADFORD-WHITE	0
8329	09/21/2006	LTN050GEF	LOCHINVAR	0
8330	05/10/2010	G91200	RUUD/RHEEM	0
8331	10/20/2008	LTN050GEF	LOCHINVAR	0
8332	09/07/2006	LTN050G	LOCHINVAR	0
8333	12/16/2005	GVC50	A. O. SMITH	0
8334	01/05/2007	PR650	STATE	1
8335	06/20/2001	G91200	RUUD/RHEEM	0
8336	08/30/2004	XTN040	LOCHINVAR	0
8337	09/21/2008	LTN050GEF	LOCHINVAR	0
8338	08/01/2005	LTN050	LOCHINVAR	0
8339	01/05/2007	PR640	STATE	0
8340	07/01/1999	FSGL40	AO SMITH	0
8341	07/26/2012	DS150S6FBN	BRADFORD-WHITE	0
8342	07/07/1988	FSG50	AO SMITH	0
8343	02/16/2007	PR650X0DS	STATE	0
8344	12/12/2011	M45036FBN	BRADFORD-WHITE	0
8345	08/01/2005	LTN050GEF	LOCHINVAR	0
8346	12/11/2008	LTN050GEF	LOCHINVAR	2
8347	10/01/1996	PGR50	AO SMITH	0
8348	07/12/2011	M45036FBN	BRADFORD-WHITE	1
8349	10/23/2003	FCV50	AO SMITH	0
8350	01/15/2008	LSN041	LOCHINVAR	0
8351	01/06/2012	MI50L6FBN	BRADFORD-WHITE	1
8352	05/18/2009	LTN050GEF	LOCHINVAR	0
8353	12/28/1998	21VR50	RHEEM	0
8354	12/09/1996	PRV50NODS	STATE	0
8355	09/26/2003	41XR50	RHEEM	0
8356	03/08/2012	M45036FBN	BRADFORD-WHITE	0
8357	07/23/2009	LTN050GEF	LOCHINVAR	0
8358	06/11/2009	LSN041G	LOCHINVAR	0
8359	07/20/2000	41XR50	RHEEM	0
8360	04/25/1997	G72DUMMY	AO SMITH	0
8361	10/17/2000	41XR50	RHEEM	0
8362	11/04/1986	FSG50	AO SMITH	0
8363	04/08/2008	ETN076	LOCHINVAR	2
8364	10/24/2003	41XR50	RHEEM	1
8365	01/26/1995	PHR50	RUUD	0
8366	04/20/2012	MI5036FBN	BRADFORD-WHITE	3
8367	09/14/1994	FSGL40	AO SMITH	0
8368	02/14/2012	M440T6FBN	BRADFORD-WHITE	0
8369	11/25/1998	FSG50	AO SMITH	1
8370	10/22/2001	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8371	02/16/2002	PGR50	AO SMITH	0
8372	08/12/2009	22DV50C	RHEEM	0
8373	01/07/2010	22DV50C	RHEEM	1
8374	07/02/2000	PGR50	AO SMITH	0
8375	09/10/1997	PGR50	AO SMITH	0
8376	01/05/2004	PVR50	AO SMITH	0
8377	03/03/2006	PR650X0DS	STATE	0
8378	08/27/2010	42VR50	RHEEM	2
8379	08/14/2007	LTN050G	LOCHINVAR	0
8380	01/13/2005	PRX40	STATE	0
8381	01/27/2010	22DV50F	RHEEM	0
8382	04/29/2005	LTN050	LOCHINVAR	0
8383	05/12/1997	PGR50	AO SMITH	0
8384	11/05/2009	22DV50F	RHEEM	0
8385	11/30/2012	MI50L6FBN	BRADFORD-WHITE	0
8386	05/23/2000	PGR50	AO SMITH	0
8387	07/25/2000	41XR50	RHEEM	0
8388	09/11/2003	FCV50	AO SMITH	0
8389	12/05/1986	PRX50	STATE	0
8390	06/05/1998	FGR50	AO SMITH	0
8391	10/19/1997	PHR50	RUUD	0
8392	01/15/2013	MI5036FBN	BRADFORD-WHITE	0
8393	07/01/1987	PRV50NODS	STATE	0
8394	01/30/2012	MI5036FBN	BRADFORD-WHITE	1
8395	12/15/2007	LTN050GEF	LOCHINVAR	1
8396	07/11/2011	M45036FBN	BRADFORD-WHITE	1
8397	12/30/2011	M45036FBN	BRADFORD-WHITE	0
8398	02/09/2010	LTN050GEF	LOCHINVAR	0
8399	01/22/2003	PRX40	STATE	0
8400	01/15/1987	FSG50	AO SMITH	0
8401	01/28/2013	DS150S6FBN	BRADFORD-WHITE	0
8402	05/07/2009	LTN050GEF	LOCHINVAR	0
8403	02/04/2009	LTN050G	LOCHINVAR	1
8404	04/28/2010	SBF100199NET	STATE	0
8405	05/29/2007	LTN040G	LOCHINVAR	0
8406	02/06/2002	41V50	RHEEM	0
8407	11/20/2008	22DV50C	RHEEM	0
8408	01/23/1989	PRV50NODS	STATE	0
8409	04/24/2009	LTN050GEF	LOCHINVAR	0
8410	02/17/2006	LTN050	LOCHINVAR	0
8411	08/26/1989	RF82156	RUUD	1
8412	08/26/2004	XTN050	LOCHINVAR	0
8413	02/27/2012	M45036FBN	BRADFORD-WHITE	0
8414	07/26/2007	PR640	STATE	0
8415	05/02/2012	MI5036FBN	BRADFORD-WHITE	0
8416	11/14/2012	M45036FBN	BRADFORD-WHITE	0
8417	06/06/2012	PH2DV50F	RUUD	0
8418	08/21/2011	M45036FBN	BRADFORD-WHITE	0
8419	07/15/1989	D74DUMMY	AO SMITH	0
8420	03/10/2001	41XR50	RHEEM	0
8421	11/16/2009	22DV50C	RHEEM	0
8422	04/10/2008	LTN050GEF	LOCHINVAR	0
8423	11/30/2000	PGR50	AO SMITH	0
8424	12/21/1989	FSG50	AO SMITH	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8425	03/11/2004	PRX50	STATE	0
8426	02/05/2011	42VR50	RHEEM	0
8427	11/09/2006	LTN040G	LOCHINVAR	0
8428	07/06/2004	41XR50	RHEEM	0
8429	10/09/2005	LTN050	LOCHINVAR	0
8430	04/29/2004	FCV50	AO SMITH	0
8431	08/21/2012	M2XR504T6FBN	BRADFORD-WHITE	0
8432	03/16/2005	PRX40	STATE	0
8433	07/17/2009	22DV50F	RHEEM	0
8434	04/16/2002	PR650	STATE	0
8435	10/11/2005	LTN050	LOCHINVAR	1
8436	06/05/2009	LTN050G	LOCHINVAR	0
8437	09/08/2005	LTN040	LOCHINVAR	1
8438	04/05/2010	LTN050GEF	LOCHINVAR	0
8439	05/11/2006	LTN050GEF	LOCHINVAR	0
8440	05/29/2010	LTN050GEF	LOCHINVAR	0
8441	06/02/2011	21VR50	RHEEM	0
8442	11/09/2006	LTN050G	LOCHINVAR	0
8443	01/10/2003	FSG50	AO SMITH	0
8444	03/09/2012	MI5036FBN	BRADFORD-WHITE	0
8445	07/12/1989	FSG50	AO SMITH	0
8446	02/16/1989	FSG50	AO SMITH	1
8447	01/28/2007	FSGL40	AO SMITH	0
8448	06/13/2000	41V40S	RHEEM	0
8449	06/27/2010	LTN050G	LOCHINVAR	0
8450	01/02/2009	22DV50C	RHEEM	0
8451	08/11/1997	PGR50	AO SMITH	0
8452	09/14/2011	M45036FBN	BRADFORD-WHITE	0
8453	11/21/2007	PR650	STATE	0
8454	06/14/2006	LTN050G	LOCHINVAR	0
8455	03/02/2004	FCV50	AO SMITH	1
8456	01/29/2007	FSGL40	AO SMITH	0
8457	09/27/2002	PRX50	STATE	0
8458	02/03/2006	LTN050G	LOCHINVAR	0
8459	06/12/2008	LTN050GEF	LOCHINVAR	0
8460	12/27/2002	PGR50	AO SMITH	0
8461	12/03/2001	FSG50	AO SMITH	1
8462	06/10/2008	22DV50C	RHEEM	0
8463	04/26/2006	LTN050G	LOCHINVAR	0
8464	12/28/1987	FSG50	AO SMITH	0
8465	01/16/2000	41XR50	RHEEM	0
8466	06/08/2005	XSN040	LOCHINVAR	0
8467	06/04/2003	PGR50	AO SMITH	0
8468	01/29/2007	LTN050G	LOCHINVAR	0
8469	09/19/1992	FSG30	AO SMITH	0
8470	12/12/2012	PH2DV50F	RUUD	0
8471	10/08/2012	MI5036FBN	BRADFORD-WHITE	0
8472	05/24/2007	LTN040G	LOCHINVAR	1
8473	11/30/2010	42VR50	RHEEM	0
8474	04/21/2004	XTN050	LOCHINVAR	0
8475	04/25/2009	LTN050GEF	LOCHINVAR	1
8476	12/28/2012	DS150S6FBN	BRADFORD-WHITE	0
8477	11/26/2008	LTN050GEF	LOCHINVAR	0
8478	08/02/2002	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8479	01/31/2011	42VR50	RHEEM	1
8480	04/20/2002	PRX50	STATE	0
8481	06/02/1994	P506	RUUD	0
8482	05/22/2000	PRX50	STATE	0
8483	10/14/2005	LTN050G	LOCHINVAR	0
8484	05/13/2002	PRX50	STATE	0
8485	01/28/2013	M45036FBN	BRADFORD-WHITE	2
8486	05/13/1988	FSG40	AO SMITH	0
8487	02/07/2007	PR650X0DS	STATE	0
8488	08/03/2006	LTN050G	LOCHINVAR	0
8489	08/05/2008	PRV50NODS	STATE	1
8490	07/23/2004	FCV40	AO SMITH	0
8491	03/02/2013	M45036FBN	BRADFORD-WHITE	1
8492	05/04/2007	LTN040G	LOCHINVAR	0
8493	02/24/1987	21V407	RHEEM	0
8494	10/04/2011	M45036FBN	BRADFORD-WHITE	0
8495	12/03/2008	LTN050GEF	LOCHINVAR	0
8496	06/01/2004	GVC50	A. O. SMITH	1
8497	06/01/2012	M45036FBN	BRADFORD-WHITE	0
8498	08/24/2004	GVC50	A. O. SMITH	1
8499	03/04/1987	PRX50	STATE	0
8500	04/16/2007	LSN041G	LOCHINVAR	0
8501	10/18/2005	LTN050G	LOCHINVAR	0
8502	05/13/2012	PH2DV50F	RUUD	0
8503	11/07/2011	M45036FBN	BRADFORD-WHITE	0
8504	03/03/2011	22DV50F	RHEEM	0
8505	01/15/2000	FSGL40	AO SMITH	0
8506	04/29/2008	LTN050	LOCHINVAR	0
8507	11/30/2009	22DV50C	RHEEM	0
8508	06/20/2005	LTN050	LOCHINVAR	0
8509	05/20/2004	CPN199100	LOCHINVAR	2
8510	08/30/2000	FSG40	AO SMITH	0
8511	06/14/2012	M45036FBN	BRADFORD-WHITE	0
8512	08/01/1986	P506	RUUD	0
8513	09/09/2011	42VR50	RHEEM	1
8514	02/26/2003	PGR50	AO SMITH	0
8515	06/08/2001	PRX50	STATE	0
8516	07/15/2004	XTN050	LOCHINVAR	0
8517	06/25/2002	FSG50	AO SMITH	0
8518	12/23/2008	LTN050GEF	LOCHINVAR	0
8519	02/02/2008	LTN050GEF	LOCHINVAR	0
8520	08/09/2012	M440T6FBN	BRADFORD-WHITE	0
8521	06/06/2004	GCVL40	A. O. SMITH	0
8522	12/10/1999	PGR50	AO SMITH	2
8523	04/28/2006	LTN050G	LOCHINVAR	0
8524	07/09/2004	XVR50	A. O. SMITH	0
8525	10/21/1987	FSG50	AO SMITH	0
8526	02/26/2011	21VR50	RHEEM	1
8527	09/07/2001	PR650	STATE	0
8528	06/08/2002	FSG50	AO SMITH	0
8529	08/31/2009	LTN050GEF	LOCHINVAR	0
8530	01/02/2006	LTN040G	LOCHINVAR	0
8531	11/30/2005	LTN050G	LOCHINVAR	0
8532	08/15/2007	LTN050G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8533	12/14/2002	FSG50	AO SMITH	0
8534	08/08/2007	LTN050GEF	LOCHINVAR	0
8535	11/16/2011	MI403S6FBN	BRADFORD-WHITE	0
8536	11/13/2012	G76200	RUUD/RHEEM	0
8537	02/09/2009	LTN050G	LOCHINVAR	0
8538	05/01/2012	PH2DV50F	RUUD	0
8539	01/17/2007	LTN050G	LOCHINVAR	0
8540	01/09/2004	41VR50	RHEEM	3
8541	08/09/2011	G91200	RUUD/RHEEM	0
8542	12/15/1989	FSG50	AO SMITH	0
8543	08/30/2002	21V506	RHEEM	0
8544	02/18/2005	LTN050G	LOCHINVAR	0
8545	06/16/2011	M45036FBN	BRADFORD-WHITE	0
8546	02/26/2013	G91200	RUUD/RHEEM	0
8547	03/17/1989	P506	RUUD	0
8548	06/05/2006	PR650	STATE	0
8549	02/16/2006	LTN050G	LOCHINVAR	0
8550	03/17/2011	42VR50	RHEEM	0
8551	12/07/2005	LTN050G	LOCHINVAR	0
8552	08/23/2000	41XR50	RHEEM	0
8553	02/25/1999	FGR50	AO SMITH	0
8554	12/21/2005	LTN051G	LOCHINVAR	0
8555	06/20/1989	FSG40	AO SMITH	0
8556	09/20/2005	LTN040	LOCHINVAR	0
8557	02/07/2001	41XR50	RHEEM	0
8558	02/25/2002	PGR50	AO SMITH	0
8559	06/24/2004	GVC50	A. O. SMITH	1
8560	06/01/2009	22DV50C	RHEEM	0
8561	10/22/2001	PGR50	AO SMITH	0
8562	05/13/2005	LTN050	LOCHINVAR	0
8563	08/29/1989	FSG50	AO SMITH	0
8564	12/28/1988	FSG40	AO SMITH	0
8565	01/10/2013	MI5036FBN	BRADFORD-WHITE	0
8566	01/22/2003	PRX50	STATE	2
8567	01/27/2007	21DV50	RHEEM	0
8568	03/17/2008	LTN050GEF	LOCHINVAR	0
8569	10/16/2005	LTN050G	LOCHINVAR	0
8570	03/03/2011	42VR50	RHEEM	0
8571	07/12/1989	PRX50	STATE	0
8572	03/26/2005	GVC50	A. O. SMITH	0
8573	07/20/2012	MI5036FBN	BRADFORD-WHITE	0
8574	10/27/1995	FGR50	AO SMITH	0
8575	10/13/1989	FSG50	AO SMITH	0
8576	05/05/2010	22DV50C	RHEEM	0
8577	02/08/2012	M45036FBN	BRADFORD-WHITE	0
8578	01/01/2000	FSGL40	AO SMITH	0
8579	01/17/2005	GVR50	AO SMITH	1
8580	11/07/2007	PR640	STATE	0
8581	07/13/2012	M45036FBN	BRADFORD-WHITE	0
8582	05/24/1990	FSGL40	AO SMITH	0
8583	05/15/2004	XTN050	LOCHINVAR	0
8584	07/07/1998	PRV50NODS	STATE	0
8585	10/21/2009	LTN040GEF	LOCHINVAR	0
8586	06/16/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8587	11/07/2007	PR640	STATE	0
8588	02/23/2012	M45036FBN	BRADFORD-WHITE	0
8589	01/15/1990	21V506	RHEEM	0
8590	05/14/2012	MI5036FBN	BRADFORD-WHITE	0
8591	02/07/2012	M45036FBN	BRADFORD-WHITE	0
8592	04/27/2008	B71DUMMY	UNKNOWN AT CONVERSION	0
8593	07/26/2004	XTN050	LOCHINVAR	0
8594	01/16/2007	LTN051G	LOCHINVAR	1
8595	04/08/2003	PRX50	STATE	1
8596	10/01/1992	FSG50	AO SMITH	0
8597	04/06/2012	M45036FBN	BRADFORD-WHITE	0
8598	01/22/1993	FSG50	AO SMITH	1
8599	01/17/2007	41V50	RHEEM	0
8600	11/11/2004	GVC50	A. O. SMITH	0
8601	10/31/2008	LTN050GEF	LOCHINVAR	0
8602	01/26/2007	LTN050G	LOCHINVAR	0
8603	12/13/2005	LTN050GEF	LOCHINVAR	0
8604	12/10/2003	FCV50	AO SMITH	0
8605	04/09/2009	LTN050GEF	LOCHINVAR	0
8606	11/30/2010	42VR50	RHEEM	0
8607	04/03/2001	PGR50	AO SMITH	1
8608	07/30/2007	PR650	STATE	0
8609	01/02/2012	LTN050GEF	LOCHINVAR	1
8610	11/12/2005	LTN050G	LOCHINVAR	0
8611	03/12/2013	M45036FBN	BRADFORD-WHITE	0
8612	07/14/1999	FSG50	AO SMITH	0
8613	07/08/2010	LTN051G	LOCHINVAR	2
8614	07/27/2009	LTN050GEF	LOCHINVAR	1
8615	04/06/2010	LTN050GEF	LOCHINVAR	0
8616	06/28/2011	42V5065F	RHEEM	0
8617	06/21/2004	GVC40	A. O. SMITH	0
8618	07/17/2007	LTN050GEF	LOCHINVAR	0
8619	01/05/2011	42VR50	RHEEM	0
8620	01/07/2009	LSN041G	LOCHINVAR	0
8621	12/29/2005	LTN040G	LOCHINVAR	1
8622	05/12/2003	PGR50	AO SMITH	0
8623	04/21/2012	M45036FBN	BRADFORD-WHITE	0
8624	03/12/1997	BTC197	AO SMITH	0
8625	08/05/2008	LTN050GEF	LOCHINVAR	0
8626	09/02/2008	LTN050GEF	LOCHINVAR	1
8627	01/10/1999	G91200	RUUD/RHEEM	0
8628	08/02/2007	PR650	STATE	0
8629	07/25/2005	LTN050	LOCHINVAR	0
8630	12/22/1987	FSG50	AO SMITH	0
8631	01/10/2008	LTN050GEF	LOCHINVAR	0
8632	02/06/2008	PR650X0DS	STATE	1
8633	01/04/2001	PRX50	STATE	1
8634	04/12/1988	FSG50	AO SMITH	0
8635	06/25/2006	LTN050G	LOCHINVAR	0
8636	04/16/2008	G75125	RUUD/RHEEM	2
8637	12/10/1996	FSG50	AO SMITH	0
8638	10/07/1988	P506	RUUD	0
8639	03/03/1988	PH30	RUUD	0
8640	06/20/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8641	07/08/2010	LTN050G	LOCHINVAR	0
8642	04/03/2001	41XR50	RHEEM	0
8643	08/26/1988	FSG50	AO SMITH	0
8644	01/13/2004	FCV50	AO SMITH	0
8645	11/22/2011	PH2DV50F	RUUD	0
8646	12/16/2003	PRX50	STATE	0
8647	01/17/2011	42VR50	RHEEM	0
8648	07/01/2005	LTN050	LOCHINVAR	0
8649	04/14/2009	LSN041G	LOCHINVAR	0
8650	12/01/2007	PR650X0DS	STATE	2
8651	07/09/1988	FSG50	AO SMITH	0
8652	01/07/2011	PH2DV50F	RUUD	1
8653	08/24/1999	PHR50	RUUD	0
8654	10/16/2008	LTN050GEF	LOCHINVAR	0
8655	03/12/2013	M45036FBN	Bradford-White	0
8656	03/30/2004	FCV50	AO SMITH	0
8657	02/17/2010	LTN050GEF	LOCHINVAR	0
8658	02/04/1988	PRV50NODS	STATE	0
8659	03/15/2012	M45036FBN	BRADFORD-WHITE	0
8660	11/03/2007	FSGL40	AO SMITH	0
8661	09/22/2004	GVC50	A. O. SMITH	0
8662	04/21/2011	41VR50	RHEEM	0
8663	12/07/2001	PRX50	STATE	0
8664	05/11/2007	LTN050GEF	LOCHINVAR	0
8665	10/10/2001	PGR50	AO SMITH	0
8666	01/13/2012	MI5036FBN	BRADFORD-WHITE	0
8667	11/15/2003	G76200	RUUD/RHEEM	2
8668	12/05/2004	FSG50	AO SMITH	0
8669	11/02/2009	LTN051G	LOCHINVAR	0
8670	12/05/2007	LTN050GEF	LOCHINVAR	1
8671	01/09/2002	FSG50	AO SMITH	0
8672	10/19/2009	LTN050G	LOCHINVAR	0
8673	04/20/1990	FSG50	AO SMITH	0
8674	05/14/2000	41XR50	RHEEM	0
8675	01/06/1996	PGR50	AO SMITH	0
8676	08/23/2012	H72DUMMY	UNKNOWN AT CONVERSION	5
8677	11/02/2004	GVC50	A. O. SMITH	0
8678	11/22/2002	FSG50	AO SMITH	0
8679	09/21/2009	LTN051G	LOCHINVAR	0
8680	02/23/2009	LTN050GEF	LOCHINVAR	0
8681	02/16/2007	LTN050G	LOCHINVAR	0
8682	11/02/2004	GVC50	A. O. SMITH	0
8683	04/23/2002	PGR50	AO SMITH	0
8684	01/28/2008	PR650X0DS	STATE	0
8685	09/02/2009	LTN050GEF	LOCHINVAR	1
8686	10/09/2012	MI403S6FBN	BRADFORD-WHITE	0
8687	12/28/2001	PR650	STATE	0
8688	07/26/2001	PGR40	AO SMITH	1
8689	05/03/2011	21VR50	RHEEM	0
8690	05/13/2011	41VR50	RHEEM	0
8691	11/23/2002	PGR50	AO SMITH	0
8692	03/10/2011	22DV50F	RHEEM	0
8693	07/15/2009	22DV50F	RHEEM	0
8694	01/29/2013	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8695	09/18/2008	LTN050GEF	LOCHINVAR	0
8696	03/26/2003	FSGT50	AO SMITH	0
8697	06/19/2008	LTN050GEF	LOCHINVAR	0
8698	01/31/2006	LTN050GEF	LOCHINVAR	0
8699	10/11/2003	41V50S	RHEEM	0
8700	01/07/2012	M45036FBN	BRADFORD-WHITE	0
8701	10/20/2003	41XR50	RHEEM	0
8702	12/15/1996	FGR50	AO SMITH	0
8703	07/25/2011	M45036FBN	BRADFORD-WHITE	0
8704	03/22/2010	LTN050GEF	LOCHINVAR	0
8705	05/13/2009	22DV50C	RHEEM	0
8706	09/23/2009	21VR50	RHEEM	0
8707	05/03/1990	FSG50	AO SMITH	0
8708	06/14/2000	FSGL40	AO SMITH	0
8709	10/17/2011	PH2DV50F	RUUD	0
8710	01/23/2004	XTN050	LOCHINVAR	1
8711	09/20/2011	PH2DV50F	RUUD	0
8712	06/08/2010	LTN050GEF	LOCHINVAR	0
8713	12/25/2011	M45036FBN	BRADFORD-WHITE	0
8714	03/08/2013	PH2DV50F	RUUD	0
8715	12/05/2000	G91200	RUUD/RHEEM	0
8716	12/09/1988	FSG50	AO SMITH	0
8717	05/21/2010	LTN051G	LOCHINVAR	0
8718	01/24/1989	P506	RUUD	0
8719	07/15/1997	RFD91200	RUUD	0
8720	11/03/2003	PVR40	AO SMITH	0
8721	08/07/2006	PR650	STATE	0
8722	11/27/2007	PR650X0DS	STATE	0
8723	08/07/2004	GVC50	A. O. SMITH	0
8724	07/16/2009	LTN050GEF	LOCHINVAR	0
8725	10/23/2003	FSG50	AO SMITH	0
8726	03/08/1989	FSG50	AO SMITH	0
8727	04/02/2003	PGR50	AO SMITH	0
8728	09/05/1997	FSG50	AO SMITH	0
8729	03/27/2001	PRV50NODS	STATE	0
8730	03/06/2000	FSG50	AO SMITH	0
8731	09/04/2009	LTN050GEF	LOCHINVAR	0
8732	01/10/2003	PGR50	AO SMITH	0
8733	05/02/2006	LTN050G	LOCHINVAR	0
8734	05/29/2012	MI5036FBN	BRADFORD-WHITE	0
8735	03/10/2009	LTN050GEF	LOCHINVAR	0
8736	03/03/1989	FSG50	AO SMITH	0
8737	03/18/2009	LTN050GEF	LOCHINVAR	0
8738	05/08/1989	P506	RUUD	0
8739	04/07/2001	PRX50	STATE	1
8740	06/03/2002	PGR50	AO SMITH	0
8741	02/22/1999	FSG50	AO SMITH	0
8742	01/05/2007	LTN050G	LOCHINVAR	1
8743	12/22/1997	41VR50	RHEEM	0
8744	02/22/2000	FSG50	AO SMITH	0
8745	04/09/2010	LTN050GEF	LOCHINVAR	0
8746	06/01/2004	PRX50	STATE	0
8747	05/03/2011	21VR40	RHEEM	0
8748	01/28/1999	41VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8749	06/03/2003	FSGL40	AO SMITH	3
8750	07/02/2010	LTN051G	LOCHINVAR	0
8751	08/14/2007	LTN050G	LOCHINVAR	1
8752	08/08/2003	FSG50	AO SMITH	0
8753	07/27/2012	M440T6FBN	BRADFORD-WHITE	0
8754	02/04/2010	22DV50F	RHEEM	0
8755	04/28/2011	21VR40	RHEEM	1
8756	07/18/2012	MI5036FBN	BRADFORD-WHITE	0
8757	12/27/2007	LTN050G	LOCHINVAR	0
8758	11/22/2005	LTN050G	LOCHINVAR	0
8759	01/19/2005	G76200	RUUD/RHEEM	0
8760	09/15/2008	LTN050GEF	LOCHINVAR	0
8761	11/01/2003	41V50	RHEEM	1
8762	11/29/1995	G91200	RUUD/RHEEM	1
8763	05/25/2007	LTN050GEF	LOCHINVAR	0
8764	03/03/2012	MI5036FBN	BRADFORD-WHITE	1
8765	09/16/2003	PVR50	AO SMITH	0
8766	08/23/2011	G76200	RUUD/RHEEM	0
8767	01/29/1999	PR650	STATE	0
8768	12/30/2006	LSN041G	LOCHINVAR	0
8769	09/04/2007	LTN050GEF	LOCHINVAR	0
8770	03/02/1987	FSG50	AO SMITH	1
8771	10/15/2001	PRX50	STATE	0
8772	11/25/2009	LTN050GEF	LOCHINVAR	1
8773	04/29/2004	PGR50	AO SMITH	2
8774	02/05/2013	G75125	RUUD/RHEEM	3
8775	01/13/2009	FGR50	AO SMITH	0
8776	05/27/1998	41VR50	RHEEM	0
8777	04/30/2009	LTN050GEF	LOCHINVAR	0
8778	08/16/2006	LTN040G	LOCHINVAR	0
8779	09/16/1998	FSG50	AO SMITH	0
8780	04/17/2012	DS150S6FBN	BRADFORD-WHITE	0
8781	04/16/2004	41XR50	RHEEM	0
8782	07/21/1997	FGR50	AO SMITH	1
8783	11/10/2004	GVC40	A. O. SMITH	0
8784	01/04/2012	M45036FBN	BRADFORD-WHITE	0
8785	03/01/2010	LTN050GEF	LOCHINVAR	0
8786	10/08/2006	PR650	STATE	0
8787	03/25/2006	LTN050G	LOCHINVAR	0
8788	10/23/2008	22DV50C	RHEEM	0
8789	04/11/2003	FSG40	AO SMITH	0
8790	06/01/1987	PRV50NODS	STATE	0
8791	03/30/2002	PGR50	AO SMITH	0
8792	02/17/2003	PGR50	AO SMITH	0
8793	05/03/2005	42VR506	RHEEM	0
8794	03/16/2010	LTN050GEF	LOCHINVAR	0
8795	09/28/2001	41XR50	RHEEM	0
8796	05/28/1987	FSG50	AO SMITH	0
8797	04/21/1987	FSG40	AO SMITH	0
8798	05/01/2002	41V50	RHEEM	0
8799	07/02/1999	41VR40	RHEEM	0
8800	07/15/2007	LTN050G	LOCHINVAR	0
8801	11/25/2011	M45036FBN	BRADFORD-WHITE	0
8802	08/16/2010	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8803	05/02/2004	SBF100199NES	STATE	0
8804	01/10/2012	PH2DV50F	RUUD	0
8805	07/17/2006	PR640	STATE	0
8806	01/02/1998	41VR50	RHEEM	0
8807	05/30/2006	LTN040G	LOCHINVAR	0
8808	08/16/2011	MI5036FBN	BRADFORD-WHITE	0
8809	11/23/2001	PGR50	AO SMITH	0
8810	07/06/2009	LTN050GEF	LOCHINVAR	0
8811	10/18/2002	FSG50	AO SMITH	0
8812	05/18/2007	LTN050GEF	LOCHINVAR	0
8813	08/26/2009	LTN040GEF	LOCHINVAR	0
8814	08/29/2006	LTN050G	LOCHINVAR	0
8815	02/25/2010	22DV50C	RHEEM	0
8816	02/01/2013	MI5036FBN	BRADFORD-WHITE	0
8817	06/08/2012	PH2DV50F	RUUD	1
8818	08/11/2010	LTN050GEF	LOCHINVAR	1
8819	04/26/1991	FSG50	AO SMITH	0
8820	01/09/2002	FSG40	AO SMITH	0
8821	12/18/2007	PR650	STATE	1
8822	02/18/2009	LTN051G	LOCHINVAR	0
8823	04/25/2000	41XR50	RHEEM	0
8824	01/28/2009	LSN041G	LOCHINVAR	0
8825	09/27/2001	PGR50	AO SMITH	0
8826	01/28/1999	41VR50	RHEEM	0
8827	12/23/2009	G91200	RUUD/RHEEM	0
8828	01/27/2010	LTN050G	LOCHINVAR	0
8829	05/14/2006	LTN050G	LOCHINVAR	0
8830	08/25/2004	GCVL40	A. O. SMITH	0
8831	09/15/2011	PH2DV50F	RUUD	0
8832	08/04/2010	21DV50	RHEEM	0
8833	04/10/2012	MI403S6FBN	BRADFORD-WHITE	1
8834	06/05/2009	LSN041G	LOCHINVAR	0
8835	12/16/2009	LTN050GEF	LOCHINVAR	0
8836	12/08/2012	MI5036FBN	BRADFORD-WHITE	0
8837	07/01/1988	FSG50	AO SMITH	0
8838	01/13/2003	FSG50	AO SMITH	0
8839	11/02/2009	LTN051G	LOCHINVAR	0
8840	08/05/2005	LTN050G	LOCHINVAR	0
8841	04/23/1999	FSG50	AO SMITH	0
8842	12/30/2006	LTN050G	LOCHINVAR	0
8843	01/26/2010	LTN050GEF	LOCHINVAR	0
8844	02/24/2013	M45036FBN	BRADFORD-WHITE	0
8845	01/06/2007	LTN050G	LOCHINVAR	0
8846	04/22/2000	FSG40	AO SMITH	0
8847	02/12/2009	22DV50F	RHEEM	0
8848	11/05/2003	21V407	RHEEM	0
8849	06/30/1988	FSG50	AO SMITH	0
8850	10/05/2000	PGR50	AO SMITH	0
8851	02/21/2001	FSG50	AO SMITH	0
8852	02/16/2012	M45036FBN	BRADFORD-WHITE	0
8853	08/27/2000	41XR50	RHEEM	0
8854	06/28/1988	FSG50	AO SMITH	0
8855	05/29/2009	LTN050GEF	LOCHINVAR	0
8856	04/04/2012	PH2DV50F	RUUD	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8857	12/02/2005	LTN050G	LOCHINVAR	0
8858	12/19/2008	LTN050GEF	LOCHINVAR	0
8859	04/13/2002	PGR50	AO SMITH	0
8860	11/26/2003	FCV50	AO SMITH	0
8861	05/24/2012	MI40T6FBN	BRADFORD-WHITE	0
8862	10/19/2007	PR650	STATE	1
8863	03/18/2012	M45036FBN	BRADFORD-WHITE	1
8864	06/06/1988	PRX50	STATE	0
8865	03/16/2010	22DV50F	RHEEM	0
8866	02/04/2002	41VR50	RHEEM	0
8867	03/28/2005	PRX50	STATE	0
8868	09/12/2011	M45036FBN	BRADFORD-WHITE	0
8869	07/15/1988	FSG50	AO SMITH	0
8870	01/10/2011	G91200	RUUD/RHEEM	0
8871	01/27/2006	LTN050G	LOCHINVAR	0
8872	04/20/2011	41VR50	RHEEM	0
8873	01/22/2013	M45036FBN	BRADFORD-WHITE	0
8874	05/30/2009	22DV50C	RHEEM	1
8875	11/24/2009	LTN050G	LOCHINVAR	3
8876	11/23/2005	PR650	STATE	0
8877	07/08/2003	21V506	RHEEM	0
8878	03/30/2012	M45036FBN	BRADFORD-WHITE	1
8879	03/03/2008	LTN050GEF	LOCHINVAR	0
8880	02/14/2001	FSG50	AO SMITH	0
8881	01/04/2006	FSG50	AO SMITH	0
8882	11/21/1996	RF67120	RUUD	0
8883	02/05/2010	LTN040GEF	LOCHINVAR	0
8884	10/01/2009	LTN050GEF	LOCHINVAR	0
8885	04/20/2009	LTN050GEF	LOCHINVAR	0
8886	09/04/1997	FGR50	AO SMITH	0
8887	11/20/2002	PGR50	AO SMITH	0
8888	03/10/2004	21DV50	RHEEM	0
8889	10/16/2009	LTN050GEF	LOCHINVAR	0
8890	02/11/2005	XVR50	A. O. SMITH	1
8891	08/14/2009	LSN041G	LOCHINVAR	1
8892	09/15/2009	GDVS40	AOSMITH	0
8893	05/30/1990	PRV50NODS	STATE	0
8894	01/12/2013	MI5036FBN	BRADFORD-WHITE	0
8895	07/29/2009	LTN050GEF	LOCHINVAR	0
8896	11/03/2012	MI75S6FBN	BRADFORD-WHITE	3
8897	11/18/2008	LTN050GEF	LOCHINVAR	3
8898	11/14/2009	22DV50F	RHEEM	0
8899	12/02/2004	GVC50	A. O. SMITH	1
8900	02/21/1995	FGR50	AO SMITH	0
8901	02/24/1999	FGR50	AO SMITH	0
8902	12/02/2005	LTN050G	LOCHINVAR	0
8903	05/19/2009	LTN051G	LOCHINVAR	0
8904	08/22/2012	MI5036FBN	BRADFORD-WHITE	0
8905	05/27/2007	PR650	STATE	0
8906	10/01/2005	LTN050G	LOCHINVAR	0
8907	01/15/2001	PGR50	AO SMITH	0
8908	02/02/2001	41V40	RHEEM	0
8909	03/30/2007	LTN050G	LOCHINVAR	1
8910	01/14/2008	PR650	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8911	07/01/2003	21DV50	RHEEM	1
8912	04/25/2012	PH2DV50F	RUUD	0
8913	07/02/2001	PRX50	STATE	0
8914	05/25/2007	ETN076	LOCHINVAR	1
8915	01/19/2005	PRX50	STATE	0
8916	06/29/2001	PRX50	STATE	0
8917	01/08/1990	PR407	RUUD	0
8918	04/28/2012	MI5036FBN	BRADFORD-WHITE	2
8919	03/13/2002	PRX50	STATE	0
8920	06/15/2005	PR650	STATE	0
8921	01/13/2009	22DV50C	RHEEM	0
8922	08/01/2005	LTN050G	LOCHINVAR	1
8923	10/16/2010	22DV50F	RHEEM	0
8924	09/06/2005	PR650	STATE	0
8925	08/13/2007	LSN041G	LOCHINVAR	0
8926	07/08/2004	GVC50	A. O. SMITH	0
8927	09/11/1989	21DV50	RHEEM	0
8928	09/22/2000	FSG50	AO SMITH	0
8929	01/17/2008	LTN050G	LOCHINVAR	1
8930	04/13/2005	PHR50	RUUD	0
8931	05/20/2008	LTN050GEF	LOCHINVAR	0
8932	06/12/2002	FSG50	AO SMITH	0
8933	01/14/2011	42VR50	RHEEM	0
8934	09/27/1989	21V502	RHEEM	0
8935	05/12/2010	LTN050GEF	LOCHINVAR	0
8936	12/29/1999	FGR50	AO SMITH	0
8937	10/23/1989	FSG50	AO SMITH	0
8938	02/08/2003	PRX50	STATE	0
8939	04/30/2008	LTN050GEF	LOCHINVAR	0
8940	12/01/2007	LTN050GEF	LOCHINVAR	0
8941	03/27/2002	FSG50	AO SMITH	0
8942	06/27/2009	LTN040GEF	LOCHINVAR	1
8943	01/11/2007	LTN050G	LOCHINVAR	0
8944	02/12/2011	21VR50	RHEEM	0
8945	08/07/2007	LTN040G	LOCHINVAR	0
8946	12/14/2005	LTN050G	LOCHINVAR	0
8947	08/05/2004	PRX50	STATE	0
8948	12/18/2006	LTN050G	LOCHINVAR	0
8949	02/29/2012	M45036FBN	BRADFORD-WHITE	1
8950	09/29/2009	22DV50C	RHEEM	1
8951	01/28/2005	GDVS50	AOSMITH	0
8952	09/25/2001	PGR50	AO SMITH	0
8953	03/11/2002	PRX50	STATE	0
8954	09/28/1989	FSG50	AO SMITH	0
8955	03/03/2006	LTN050G	LOCHINVAR	0
8956	08/10/2011	M45036FBN	BRADFORD-WHITE	0
8957	05/15/2002	PGR50	AO SMITH	0
8958	02/25/2011	42VR50	RHEEM	0
8959	07/02/2012	M45036FBN	BRADFORD-WHITE	0
8960	04/12/1989	P506	RUUD	0
8961	11/17/2003	PGR50	AO SMITH	0
8962	04/14/2008	21DV50	RHEEM	0
8963	05/09/2011	21VR50	RHEEM	0
8964	10/06/2011	MI5036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
8965	03/27/2001	PGR50	AO SMITH	0
8966	04/05/2006	LTN050G	LOCHINVAR	0
8967	03/26/2012	G75125	RUUD/RHEEM	1
8968	06/02/2011	21VR50	RHEEM	0
8969	02/04/2013	G72DUMMY	UNKNOWN AT CONVERSION	0
8970	11/20/1998	PRX50	STATE	0
8971	08/30/2005	LTN050GEF	LOCHINVAR	0
8972	11/26/2010	42VR50	RHEEM	0
8973	11/17/2001	FSG50	AO SMITH	0
8974	05/23/2005	GVC50	A. O. SMITH	0
8975	10/15/1996	FGR50	AO SMITH	0
8976	03/16/2006	LTN050G	LOCHINVAR	1
8977	07/17/1989	FSG50	AO SMITH	0
8978	08/01/2012	MI5036FBN	BRADFORD-WHITE	0
8979	06/03/2005	LTN050	LOCHINVAR	0
8980	11/05/2012	G76200	RUUD/RHEEM	0
8981	06/17/2002	PGR50	AO SMITH	1
8982	02/03/1995	PR502T	RUUD	0
8983	02/16/2000	FSG50	AO SMITH	0
8984	05/23/2012	DS150S6FBN	BRADFORD-WHITE	0
8985	09/10/2009	LTN050GEF	LOCHINVAR	0
8986	03/02/2001	PGR50	AO SMITH	0
8987	06/09/2012	MI5036FBN	BRADFORD-WHITE	0
8988	12/20/2011	M45036FBN	BRADFORD-WHITE	1
8989	05/29/2006	PR650	STATE	1
8990	01/14/2005	PRX50	STATE	0
8991	01/18/2006	LTN050GEF	LOCHINVAR	0
8992	05/09/2002	FSG40	AO SMITH	0
8993	03/03/2008	LTN050GEF	LOCHINVAR	0
8994	08/18/1987	FSG50	AO SMITH	0
8995	01/15/1987	FSG50	AO SMITH	0
8996	01/16/1997	PGR50	AO SMITH	0
8997	12/20/2010	21VR40	RHEEM	0
8998	01/17/2012	M45036FBN	BRADFORD-WHITE	1
8999	01/05/2012	PH2DV50F	RUUD	1
9000	12/26/1986	G76200	RUUD/RHEEM	0
9001	01/08/2004	XTN050	LOCHINVAR	2
9002	04/14/2004	GVC50	A. O. SMITH	1
9003	03/22/2006	PR650X0DS	STATE	0
9004	06/22/2009	22DV50C	RHEEM	0
9005	03/03/2001	41V50	RHEEM	0
9006	05/21/2007	LTN050GEF	LOCHINVAR	0
9007	01/10/2006	LTN050G	LOCHINVAR	0
9008	05/02/1997	FGR50	AO SMITH	1
9009	04/20/1987	FSG50	AO SMITH	0
9010	05/30/2012	MI5036FBN	BRADFORD-WHITE	0
9011	03/31/2011	21VR40	RHEEM	0
9012	12/23/1999	FGR50	AO SMITH	0
9013	09/03/2008	PH199119	PHOENIX	0
9014	04/19/2010	LTN050GEF	LOCHINVAR	0
9015	06/02/2003	PGR50	AO SMITH	0
9016	12/14/2009	LTN050GEF	LOCHINVAR	0
9017	03/15/2011	21VR50	RHEEM	1
9018	12/08/2010	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9019	07/05/2011	MI40T6FBN	BRADFORD-WHITE	1
9020	06/21/2006	LTN050G	LOCHINVAR	0
9021	05/07/2010	LTN050GEF	LOCHINVAR	0
9022	01/17/2011	21VR50	RHEEM	0
9023	09/24/1987	P506	RUUD	0
9024	05/02/2000	PGR50	AO SMITH	0
9025	12/14/1998	FGR50	AO SMITH	0
9026	03/01/2002	PRX40	STATE	0
9027	07/11/2012	G91200	RUUD/RHEEM	0
9028	11/29/2006	LTN050G	LOCHINVAR	0
9029	01/20/2005	LTN050	LOCHINVAR	0
9030	09/24/1987	P506	RUUD	0
9031	02/14/1990	FGR50	AO SMITH	0
9032	06/15/2000	G76200	RUUD/RHEEM	0
9033	10/13/2002	PGR50	AO SMITH	0
9034	09/18/2007	LTN051G	LOCHINVAR	3
9035	10/27/2008	LTN040GEF	LOCHINVAR	0
9036	02/06/2013	MI5036FBN	BRADFORD-WHITE	0
9037	06/21/2008	LTN050G	LOCHINVAR	1
9038	04/10/2004	XVR50	A. O. SMITH	0
9039	10/12/2004	PRX50	STATE	0
9040	05/06/2006	PR650	STATE	0
9041	04/19/2010	22DV50C	RHEEM	0
9042	06/28/2012	MI403S6FBN	BRADFORD-WHITE	0
9043	05/20/1996	I72DUMMY	AO SMITH	0
9044	08/16/2003	PGR50	AO SMITH	0
9045	08/10/1990	FSG50	AO SMITH	1
9046	01/27/2009	LTN050GEF	LOCHINVAR	0
9047	05/04/1990	FSG50	AO SMITH	0
9048	10/03/1989	P506	RUUD	0
9049	12/09/2005	B71DUMMY	AMERICAN	0
9050	04/22/1997	FSG50	AO SMITH	0
9051	08/28/2012	PH2DV50F	RUUD	0
9052	10/20/2010	42VR50	RHEEM	1
9053	07/21/2004	PRX50	STATE	0
9054	03/26/2009	LTN050GEF	LOCHINVAR	0
9055	09/04/2003	PGR50	AO SMITH	1
9056	07/09/1999	41VR50	RHEEM	0
9057	07/05/2010	22DV50C	RHEEM	0
9058	06/09/2009	LTN050GEF	LOCHINVAR	0
9059	02/05/2003	PRX50	STATE	0
9060	04/21/2009	LTN050GEF	LOCHINVAR	0
9061	08/28/2012	M45036FBN	BRADFORD-WHITE	0
9062	10/11/2011	MI5036FBN	BRADFORD-WHITE	1
9063	05/23/2009	LTN050GEF	LOCHINVAR	0
9064	06/11/2003	PGR50	AO SMITH	1
9065	02/22/1990	P506	RUUD	0
9066	02/23/2009	LTN050GEF	LOCHINVAR	0
9067	05/24/2012	M45036FBN	BRADFORD-WHITE	1
9068	12/21/2009	LTN050GEF	LOCHINVAR	0
9069	11/23/2010	21VR50	RHEEM	0
9070	12/07/2011	MI403S6FBN	BRADFORD-WHITE	0
9071	08/31/2009	LTN050GEF	LOCHINVAR	0
9072	08/13/2001	FSG50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9073	06/30/2009	LTN050G	LOCHINVAR	0
9074	03/15/2000	PRV50NODS	STATE	0
9075	05/15/2007	PR640	STATE	0
9076	03/03/2010	LTN050GEF	LOCHINVAR	0
9077	12/09/1987	FSG50	AO SMITH	0
9078	11/19/1987	FSG50	AO SMITH	0
9079	10/14/2003	PRX50	STATE	0
9080	08/23/2006	LTN050G	LOCHINVAR	0
9081	02/19/1988	FSG50	AO SMITH	0
9082	02/19/1999	FGR50	AO SMITH	0
9083	03/03/2001	41XR50	RHEEM	0
9084	08/04/1988	FSG50	AO SMITH	0
9085	10/08/2007	LTN050G	LOCHINVAR	0
9086	10/29/2009	LTN050GEF	LOCHINVAR	0
9087	04/18/2002	FSG50	AO SMITH	0
9088	01/12/2012	M45036FBN	BRADFORD-WHITE	0
9089	01/23/2007	LTN050G	LOCHINVAR	1
9090	07/09/2010	22DV50C	RHEEM	4
9091	02/03/2009	LTN050GEF	LOCHINVAR	0
9092	12/11/1987	PRX50	STATE	0
9093	11/02/2010	22DV50F	RHEEM	0
9094	06/02/1999	G91200	RUUD/RHEEM	0
9095	10/10/2005	LTN050	LOCHINVAR	0
9096	10/07/2006	LTN050GEF	LOCHINVAR	0
9097	04/09/1988	FSG50	AO SMITH	0
9098	08/03/2007	LTN050GEF	LOCHINVAR	0
9099	06/12/2010	LTN050GEF	LOCHINVAR	0
9100	03/26/2007	LTN050G	LOCHINVAR	0
9101	08/18/2011	M45036FBN	BRADFORD-WHITE	0
9102	01/25/2012	LTN051G	LOCHINVAR	1
9103	11/10/2009	LTN050GEF	LOCHINVAR	0
9104	09/14/2005	LTN050	LOCHINVAR	0
9105	01/31/2000	FSG50	AO SMITH	0
9106	02/26/2009	LTN050GEF	LOCHINVAR	1
9107	02/20/2004	PRX40	STATE	0
9108	10/03/2011	M45036FBN	BRADFORD-WHITE	1
9109	09/24/2010	42VR50	RHEEM	0
9110	05/15/2007	LTN050G	LOCHINVAR	1
9111	04/01/2002	PGR50	AO SMITH	0
9112	03/16/2007	LTN050G	LOCHINVAR	0
9113	03/08/2006	LTN050G	LOCHINVAR	0
9114	03/16/2008	LTN050GEF	LOCHINVAR	1
9115	11/05/2009	LSN041G	LOCHINVAR	0
9116	07/24/2008	LTN050GEF	LOCHINVAR	0
9117	10/20/2006	LTN050GEF	LOCHINVAR	1
9118	11/27/2001	FSGL40	AO SMITH	0
9119	08/17/2004	PVR50	AO SMITH	1
9120	10/13/2012	PH2DV50F	RUUD	0
9121	08/17/2000	FSG50	AO SMITH	0
9122	09/21/2011	M45036FBN	BRADFORD-WHITE	0
9123	09/20/2010	21VR50	RHEEM	0
9124	08/15/2011	42V50SF	RHEEM	0
9125	06/24/2008	22DV50F	RHEEM	0
9126	12/11/2001	FSGL40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9127	07/24/2009	LTN050GEF	LOCHINVAR	0
9128	02/28/2011	42V5065F	RHEEM	0
9129	08/25/2009	LTN050GEF	LOCHINVAR	0
9130	01/26/1989	FSG50	AO SMITH	0
9131	01/31/2005	XVR50	A. O. SMITH	0
9132	01/27/2013	MI5036FBN	BRADFORD-WHITE	0
9133	07/20/2009	22DV50F	RHEEM	0
9134	02/17/2010	22DV50C	RHEEM	0
9135	01/26/1989	FSG50	AO SMITH	0
9136	08/03/2005	LTN050	LOCHINVAR	1
9137	01/29/2005	GDVS50	AOSMITH	1
9138	09/07/2006	LTN050G	LOCHINVAR	0
9139	12/28/2004	LTN050	LOCHINVAR	0
9140	05/08/2007	LTN050GEF	LOCHINVAR	0
9141	07/30/2007	LTN050GEF	LOCHINVAR	0
9142	09/08/2003	PVR50	AO SMITH	0
9143	03/28/2007	ETN065	LOCHINVAR	0
9144	06/11/2001	PGR50	AO SMITH	0
9145	07/29/2002	PRX50	STATE	0
9146	07/11/2000	FSG30	AO SMITH	0
9147	12/06/1988	FSG50	AO SMITH	0
9148	02/20/2008	LTN050G	LOCHINVAR	0
9149	10/12/2007	LTN050GEF	LOCHINVAR	0
9150	03/21/2011	42VR50	RHEEM	0
9151	10/10/2001	PGR50	AO SMITH	0
9152	01/17/2013	M45036FBN	BRADFORD-WHITE	2
9153	03/18/2007	GVC50	A. O. SMITH	0
9154	06/12/2008	21DV50	RHEEM	1
9155	04/28/2005	LTN050	LOCHINVAR	0
9156	11/24/2006	LTN050G	LOCHINVAR	0
9157	03/10/2004	FSGL40	AO SMITH	0
9158	02/10/2003	FSG50	AO SMITH	0
9159	08/06/2002	FSG50	AO SMITH	0
9160	04/08/2004	XTN050	LOCHINVAR	0
9161	06/10/2009	LTN050GEF	LOCHINVAR	0
9162	09/18/1997	PGR50	AO SMITH	1
9163	01/06/2009	22DV50C	RHEEM	0
9164	03/02/2011	42VR50	RHEEM	0
9165	07/31/2012	M45036FBN	BRADFORD-WHITE	0
9166	04/22/2012	M45036FBN	BRADFORD-WHITE	0
9167	05/21/2000	41XR50	RHEEM	0
9168	12/29/2004	PR640	STATE	0
9169	08/25/2010	LTN050GEF	LOCHINVAR	0
9170	09/26/2008	LTN050GEF	LOCHINVAR	1
9171	06/13/2006	PR650	STATE	0
9172	12/22/2005	PR650	STATE	0
9173	05/15/1996	FSG50	AO SMITH	0
9174	04/10/2008	PR640	STATE	0
9175	05/01/1990	PH30	RUUD	1
9176	03/08/2006	LTN050G	LOCHINVAR	1
9177	12/02/2011	M45036FBN	BRADFORD-WHITE	0
9178	05/30/1990	H72DUMMY	AO SMITH	0
9179	12/01/1990	FSG50	AO SMITH	0
9180	07/23/2009	22DV50F	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9181	07/05/2012	M45036FBN	BRADFORD-WHITE	1
9182	11/15/1990	FSGL40	AO SMITH	0
9183	08/07/2006	PR650	STATE	0
9184	12/15/1998	G91200	RUUD/RHEEM	0
9185	08/07/2009	LTN050GEF	LOCHINVAR	2
9186	06/22/2009	22DV50F	RHEEM	1
9187	04/21/1994	PR502T	RUUD	0
9188	08/03/2009	LTN050GEF	LOCHINVAR	0
9189	09/26/2011	MI5036FBN	BRADFORD-WHITE	0
9190	02/28/2000	41XR50	RHEEM	0
9191	11/20/2001	PGR50	AO SMITH	0
9192	07/28/2009	22DV50C	RHEEM	2
9193	06/12/1990	BTR120	AO SMITH	0
9194	02/14/2006	LTN050G	LOCHINVAR	0
9195	08/21/2001	PRX50	STATE	0
9196	02/25/2007	FGR50	AO SMITH	1
9197	07/20/1990	P506	RUUD	0
9198	03/19/2011	22DV50F	RHEEM	1
9199	07/27/2004	GVC50	A. O. SMITH	0
9200	10/09/2006	LTN050G	LOCHINVAR	0
9201	11/26/2010	42VR50	RHEEM	0
9202	03/15/2002	FSG50	AO SMITH	0
9203	12/20/1990	PRV40NODS	STATE	1
9204	10/25/1989	FSG50	AO SMITH	0
9205	04/07/2008	LTN040	LOCHINVAR	0
9206	11/14/1990	PRV50NODS	STATE	0
9207	03/07/2011	21VR50	RHEEM	1
9208	10/15/2007	LTN050G	LOCHINVAR	0
9209	04/18/2007	LSN041G	LOCHINVAR	1
9210	10/06/1999	P506	RUUD	0
9211	11/03/2006	LTN050G	LOCHINVAR	0
9212	04/07/2006	ETN076	LOCHINVAR	3
9213	09/26/2001	FSG50	AO SMITH	0
9214	03/07/2000	FSG50	AO SMITH	0
9215	08/18/2004	PRX50	STATE	1
9216	05/28/1999	PRV50NODS	STATE	0
9217	05/30/2007	LTN050G	LOCHINVAR	0
9218	02/20/2008	LTN050	LOCHINVAR	1
9219	05/10/2002	FSG40	AO SMITH	0
9220	08/09/2010	LTN050	LOCHINVAR	1
9221	10/28/2011	M45036FBN	BRADFORD-WHITE	0
9222	09/10/2009	LTN050GEF	LOCHINVAR	0
9223	03/11/2011	42VR50	RHEEM	0
9224	06/21/2007	LSN041G	LOCHINVAR	0
9225	02/17/2012	G100200	RUUD/RHEEM	0
9226	02/20/2003	PGR50	AO SMITH	0
9227	07/31/2009	22DV50C	RHEEM	0
9228	07/23/2006	LTN050G	LOCHINVAR	0
9229	05/23/2011	41VR50	RHEEM	1
9230	02/11/2004	PRX50	STATE	1
9231	09/09/1986	FSG50	AO SMITH	0
9232	08/12/2008	LSN041G	LOCHINVAR	0
9233	10/03/2011	DS150S6FBN	BRADFORD-WHITE	0
9234	06/29/2006	PR650	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9235	10/16/2012	M45036FBN	BRADFORD-WHITE	1
9236	09/18/2002	PRX50	STATE	0
9237	09/18/1998	FGR50	AO SMITH	0
9238	12/30/2010	42VR50	RHEEM	0
9239	11/02/2004	GVC50	A. O. SMITH	0
9240	04/13/2012	M45036FBN	BRADFORD-WHITE	0
9241	10/11/2012	MI5036FBN	BRADFORD-WHITE	0
9242	10/02/2005	LTN050G	LOCHINVAR	1
9243	12/14/2001	FGR40	AO SMITH	1
9244	09/15/2008	LTN050GEF	LOCHINVAR	0
9245	01/28/2010	LTN050GEF	LOCHINVAR	0
9246	05/31/2011	22DV50F	RHEEM	0
9247	10/05/1998	PRV50NODS	STATE	0
9248	12/16/2002	FSG40	AO SMITH	0
9249	09/09/2004	GVC40	A. O. SMITH	1
9250	07/28/2012	MI5036FBN	BRADFORD-WHITE	0
9251	09/11/2006	LTN050G	LOCHINVAR	0
9252	08/20/2009	LTN050G	LOCHINVAR	0
9253	01/31/2003	FSG40	AO SMITH	0
9254	11/03/2003	PVR50	AO SMITH	0
9255	05/14/2007	LTN040GEF	LOCHINVAR	1
9256	02/06/2010	LTN050G	LOCHINVAR	0
9257	11/13/2007	LTN051G	LOCHINVAR	2
9258	05/04/2006	PR650	STATE	0
9259	06/14/2000	G91200	RUUD/RHEEM	0
9260	08/14/2009	FSGL40	AO SMITH	0
9261	01/15/2013	M45036FBN	BRADFORD-WHITE	0
9262	01/25/1991	B71DUMMY	AMERICAN	0
9263	02/22/1991	21V506	RHEEM	0
9264	07/15/2005	LTN050	LOCHINVAR	0
9265	02/13/1990	PRX50	STATE	0
9266	09/18/1989	FSG50	AO SMITH	0
9267	07/07/2012	M45036FBN	BRADFORD-WHITE	0
9268	07/20/1990	FSG50	AO SMITH	0
9269	10/22/2012	FGR50	AO SMITH	1
9270	02/19/1990	PRX50	STATE	0
9271	04/28/1990	PRV50NODS	STATE	0
9272	02/12/2010	22DV50C	RHEEM	2
9273	03/01/2004	21DV50	RHEEM	0
9274	04/15/2009	22DV50F	RHEEM	0
9275	05/01/2001	PRX50	STATE	0
9276	10/30/1995	PHR50	RUUD	0
9277	10/19/2009	22DV50C	RHEEM	0
9278	04/18/2003	PGR50	AO SMITH	0
9279	08/09/2011	42V5065F	RHEEM	0
9280	11/12/2012	MI5036FBN	BRADFORD-WHITE	0
9281	06/10/2004	GVC50	A. O. SMITH	0
9282	10/20/2009	LTN050GEF	LOCHINVAR	0
9283	12/17/2003	G75125	RUUD/RHEEM	0
9284	11/30/2006	LTN050GEF	LOCHINVAR	0
9285	09/06/2011	PH2DV50F	RUUD	0
9286	10/19/2009	G75125	RUUD/RHEEM	0
9287	04/06/2004	PVR50	AO SMITH	0
9288	09/09/2010	22DV50C	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9289	06/28/2001	PGR50	AO SMITH	0
9290	04/02/2001	41XR50	RHEEM	0
9291	03/02/2012	PH2DV50F	RUUD	1
9292	07/09/2007	LTN050GEF	LOCHINVAR	0
9293	08/08/2007	LTN050GEF	LOCHINVAR	0
9294	07/09/2012	PH2DV50F	RUUD	0
9295	01/27/2008	LTN050GEF	LOCHINVAR	0
9296	08/08/2006	LTN050G	LOCHINVAR	0
9297	07/12/2011	M45036FBN	BRADFORD-WHITE	0
9298	04/08/2009	22DV50F	RHEEM	0
9299	08/06/1999	FSG50	AO SMITH	0
9300	02/08/2005	LTN050	LOCHINVAR	0
9301	02/13/2013	MI5036FBN	BRADFORD-WHITE	2
9302	03/17/2006	PR650X0DS	STATE	0
9303	10/17/2002	FSG40	AO SMITH	0
9304	07/02/2007	LTN050GEF	LOCHINVAR	0
9305	06/16/2011	M45036FBN	BRADFORD-WHITE	0
9306	09/25/2006	LTN050G	LOCHINVAR	0
9307	07/13/2009	LTN050GEF	LOCHINVAR	0
9308	07/07/2007	LTN050G	LOCHINVAR	0
9309	03/16/1989	FSG50	AO SMITH	0
9310	11/30/2005	LTN050G	LOCHINVAR	1
9311	01/26/2009	LTN050G	LOCHINVAR	0
9312	08/09/2004	PRX40	STATE	0
9313	10/27/2010	21DV50	RHEEM	1
9314	10/25/2012	DS150S6FBN	BRADFORD-WHITE	0
9315	03/24/2007	LTN050G	LOCHINVAR	0
9316	04/30/2003	PGR50	AO SMITH	0
9317	04/05/2006	LTN050G	LOCHINVAR	0
9318	12/23/2001	PRX40	STATE	0
9319	02/17/2008	LTN050	LOCHINVAR	0
9320	01/08/2010	22DV50F	RHEEM	0
9321	06/17/2003	PRX50	STATE	0
9322	07/06/2006	PR650	STATE	0
9323	12/23/2004	PRX50	STATE	0
9324	04/25/2008	LTN050GEF	LOCHINVAR	0
9325	08/03/2004	XVR50	A. O. SMITH	1
9326	06/09/2008	LTN040GEF	LOCHINVAR	0
9327	05/08/2009	LTN050GEF	LOCHINVAR	0
9328	08/05/1999	G91200	RUUD/RHEEM	0
9329	05/15/2008	LTN050GEF	LOCHINVAR	0
9330	05/13/2002	PGR50	AO SMITH	0
9331	10/22/2004	GCVL40	A. O. SMITH	0
9332	03/23/2012	M45036FBN	BRADFORD-WHITE	0
9333	12/04/1987	FSG50	AO SMITH	0
9334	08/16/2008	G91200	RUUD/RHEEM	0
9335	03/23/2011	21VR50	RHEEM	0
9336	08/23/2012	M45036FBN	BRADFORD-WHITE	1
9337	08/20/2007	LSN041G	LOCHINVAR	0
9338	07/30/2007	G76200	RUUD/RHEEM	0
9339	02/11/1988	FSG50	AO SMITH	0
9340	12/22/2005	GVC50	A. O. SMITH	1
9341	06/15/1988	FSG50	AO SMITH	0
9342	03/04/2004	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9343	11/23/2005	PR650	STATE	0
9344	02/02/2012	MI5036FBN	BRADFORD-WHITE	1
9345	09/08/2008	LTN050G	LOCHINVAR	0
9346	02/23/2005	LTN050	LOCHINVAR	1
9347	05/28/2009	LTN050GEF	LOCHINVAR	0
9348	08/28/2002	FSG50	AO SMITH	0
9349	07/31/1989	FSG50	AO SMITH	0
9350	10/02/2008	LTN050GEF	LOCHINVAR	0
9351	12/19/2004	PRX50	STATE	1
9352	07/21/2010	G75125	RUUD/RHEEM	0
9353	05/28/2010	LTN050G	LOCHINVAR	0
9354	08/10/1989	21V506	RHEEM	0
9355	06/14/2011	MI40T6FBN	BRADFORD-WHITE	0
9356	03/14/2002	21V506	RHEEM	0
9357	06/21/2000	G75125	RUUD/RHEEM	0
9358	05/04/2010	LTN050GEF	LOCHINVAR	0
9359	12/23/2008	LTN050GEF	LOCHINVAR	0
9360	04/17/1989	FSG50	AO SMITH	0
9361	09/12/2007	LTN050GEF	LOCHINVAR	0
9362	02/27/2005	PRX50	STATE	0
9363	09/24/2004	42XR50	RHEEM	0
9364	06/30/2003	G72DUMMY	AO SMITH	0
9365	03/17/2003	PRX50	STATE	0
9366	02/16/2009	LTN050GEF	LOCHINVAR	0
9367	05/20/2010	LTN050GEF	LOCHINVAR	2
9368	07/10/2009	LTN050GEF	LOCHINVAR	0
9369	07/06/2004	42VR506	RHEEM	1
9370	07/31/2003	PGR40	AO SMITH	0
9371	04/10/2000	FSG50	AO SMITH	0
9372	07/20/2004	GVC50	A. O. SMITH	0
9373	02/26/2007	LTN050G	LOCHINVAR	2
9374	02/01/2011	21VR50	RHEEM	0
9375	08/22/2003	PGR50	AO SMITH	0
9376	04/21/2006	PR650	STATE	0
9377	01/20/2004	XTN050	LOCHINVAR	1
9378	02/16/1989	FSG50	AO SMITH	0
9379	01/28/2003	PRX50	STATE	0
9380	08/30/2008	LTN050GEF	LOCHINVAR	1
9381	12/02/2008	22DV50C	RHEEM	0
9382	10/26/2012	M45036FBN	BRADFORD-WHITE	2
9383	02/27/1990	FSG50	AO SMITH	0
9384	02/06/2012	MI5036FBN	BRADFORD-WHITE	0
9385	05/31/2006	LTN050	LOCHINVAR	0
9386	06/18/1999	41VR50	RHEEM	0
9387	09/12/1989	FSG50	AO SMITH	0
9388	02/07/2007	LTN050G	LOCHINVAR	0
9389	08/17/2012	PH2DV50F	RUUD	0
9390	08/06/2001	P506	RUUD	0
9391	04/14/2004	XVR50	A. O. SMITH	0
9392	09/19/2002	PGR50	AO SMITH	0
9393	04/04/2010	LTN050GEF	LOCHINVAR	0
9394	12/20/2008	LTN051G	LOCHINVAR	0
9395	07/22/2009	LTN050G	LOCHINVAR	0
9396	11/23/2001	41XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9397	05/02/2004	GVC50	A. O. SMITH	0
9398	10/18/2009	LTN050GEF	LOCHINVAR	0
9399	12/19/2005	LTN050G	LOCHINVAR	2
9400	08/12/2010	LTN050GEF	LOCHINVAR	0
9401	07/05/2011	MI403S6FBN	BRADFORD-WHITE	1
9402	05/04/2010	22DV50C	RHEEM	0
9403	08/03/2004	PRX50	STATE	0
9404	03/26/1990	P506	RUUD	0
9405	11/13/1989	21V506	RHEEM	0
9406	07/25/2005	LSN041G	LOCHINVAR	0
9407	09/10/2011	M45036FBN	BRADFORD-WHITE	0
9408	02/19/2008	PR650	STATE	0
9409	06/15/1990	G82156	RUUD/RHEEM	0
9410	09/11/2010	21V502	RHEEM	0
9411	02/02/2007	PR650	STATE	1
9412	06/15/1990	G82156	RUUD/RHEEM	0
9413	10/20/1999	FSGL40	AO SMITH	0
9414	09/06/1995	PR502T	RUUD	0
9415	04/23/2001	41V40S	RHEEM	0
9416	12/13/2000	FSG50	AO SMITH	0
9417	02/04/2004	XTN050	LOCHINVAR	0
9418	07/04/1998	PGR50	AO SMITH	0
9419	09/03/2010	41V50	RHEEM	0
9420	10/09/2010	21VR50	RHEEM	0
9421	09/15/2012	M440T6FBN	BRADFORD-WHITE	0
9422	01/08/2002	FSGL40	AO SMITH	0
9423	09/30/2008	22DV50C	RHEEM	0
9424	03/26/1999	41VR50	RHEEM	0
9425	04/10/2009	LTN040GEF	LOCHINVAR	0
9426	02/07/2012	PH2DV50F	RUUD	1
9427	10/05/2002	PGR50	AO SMITH	0
9428	05/01/2011	41VR50	RHEEM	0
9429	03/11/2009	41V50	RHEEM	1
9430	12/13/2011	MI403S6FBN	BRADFORD-WHITE	0
9431	04/23/2009	LTN050GEF	LOCHINVAR	0
9432	07/20/2009	LTN050GEF	LOCHINVAR	0
9433	02/04/1987	FSG50	AO SMITH	0
9434	12/03/2009	22DV50F	RHEEM	1
9435	01/05/2010	LTN040GEF	LOCHINVAR	0
9436	07/14/1987	FSG50	AO SMITH	0
9437	10/09/2009	21VR50	RHEEM	0
9438	02/10/1999	FGR50	AO SMITH	0
9439	05/09/2006	LSN041G	LOCHINVAR	1
9440	08/26/1999	FGR50	AO SMITH	0
9441	04/26/2005	LTN050	LOCHINVAR	0
9442	08/02/1999	FSG50	AO SMITH	0
9443	05/16/2008	LTN050GEF	LOCHINVAR	0
9444	03/02/2009	LTN050GEF	LOCHINVAR	0
9445	08/21/1987	FSG50	AO SMITH	0
9446	09/02/2009	LTN050GEF	LOCHINVAR	0
9447	02/13/2009	LTN051G	LOCHINVAR	1
9448	11/04/2009	LTN051G	LOCHINVAR	0
9449	07/19/2012	M45036FBN	BRADFORD-WHITE	0
9450	02/26/2006	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9451	09/06/2000	PRX50	STATE	0
9452	04/12/2007	LTN050G	LOCHINVAR	0
9453	09/06/2007	PR650	STATE	1
9454	10/26/2004	GCVL40	A. O. SMITH	1
9455	04/10/2003	PR650	STATE	0
9456	09/11/2006	LTN050G	LOCHINVAR	0
9457	06/13/2007	FGR50	AO SMITH	0
9458	01/30/2003	PRX50	STATE	0
9459	06/06/2002	PGR50	AO SMITH	0
9460	05/18/2012	MI5036FBN	BRADFORD-WHITE	1
9461	09/12/2003	PRX50	STATE	0
9462	08/10/2004	XVR50	A. O. SMITH	0
9463	06/18/2007	LTN050G	LOCHINVAR	0
9464	10/06/2005	PR650X0DS	STATE	0
9465	03/10/2004	PVR50	AO SMITH	0
9466	06/08/2010	LTN050G	LOCHINVAR	0
9467	07/21/1999	FGR40	AO SMITH	0
9468	07/01/2005	PR650	STATE	0
9469	03/29/2011	42VR50	RHEEM	1
9470	06/11/2001	FSGL40	AO SMITH	0
9471	04/28/1997	PGR50	AO SMITH	0
9472	11/10/2008	LTN050GEF	LOCHINVAR	0
9473	01/29/2010	LTN050GEF	LOCHINVAR	2
9474	12/21/2011	M45036FBN	BRADFORD-WHITE	0
9475	04/23/2001	41V40S	RHEEM	0
9476	06/27/2011	MI5036FBN	BRADFORD-WHITE	0
9477	04/03/2002	FSG50	AO SMITH	0
9478	12/15/2005	LTN050G	LOCHINVAR	1
9479	04/11/2006	LTN050G	LOCHINVAR	0
9480	03/27/2009	LTN050GEF	LOCHINVAR	0
9481	07/06/1990	PRV50NODS	STATE	1
9482	07/14/2008	42VR50	RHEEM	0
9483	01/19/2004	PVR50	AO SMITH	0
9484	08/23/2003	FVR50	AO SMITH	2
9485	03/12/2009	LTN050GEF	LOCHINVAR	1
9486	12/02/1997	FGR40	AO SMITH	0
9487	01/26/2003	FSGL40	AO SMITH	0
9488	03/31/2000	PGR50	AO SMITH	0
9489	11/04/2004	GVC50	A. O. SMITH	0
9490	05/23/2002	FSG50	AO SMITH	0
9491	06/15/2004	GVC50	A. O. SMITH	0
9492	03/01/2001	41V50	RHEEM	0
9493	08/17/1999	FGR50	AO SMITH	0
9494	06/06/2005	LTN050	LOCHINVAR	1
9495	09/11/2011	PH2DV50F	RUUD	0
9496	01/27/2007	GVC50	A. O. SMITH	0
9497	04/14/2011	21VR50	RHEEM	0
9498	12/06/2004	FSG50	AO SMITH	0
9499	09/13/2010	21V502	RHEEM	0
9500	05/05/2001	FSG40	AO SMITH	0
9501	06/18/2012	M45036FBN	BRADFORD-WHITE	0
9502	11/13/1990	FSG50	AO SMITH	0
9503	05/27/2009	LTN050GEF	LOCHINVAR	0
9504	08/06/2003	FCV50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9505	11/24/2007	LTN050GEF	LOCHINVAR	0
9506	03/24/1999	FGR50	AO SMITH	0
9507	10/26/1999	41XR50	RHEEM	0
9508	11/20/2009	LTN051G	LOCHINVAR	0
9509	12/11/2010	41VR50	RHEEM	0
9510	02/24/2004	PVR50	AO SMITH	0
9511	04/20/2009	PRV50NODS	STATE	0
9512	11/01/1990	P506	RUUD	0
9513	02/06/1995	PR407	RUUD	0
9514	05/03/2003	21DV50	RHEEM	0
9515	04/20/2009	LTN050G	LOCHINVAR	0
9516	09/10/1990	FSGL40	AO SMITH	0
9517	02/24/2006	LTN050G	LOCHINVAR	0
9518	06/16/2000	PGR50	AO SMITH	0
9519	12/10/1998	FSG50	AO SMITH	0
9520	01/02/2007	LTN050G	LOCHINVAR	0
9521	03/23/2011	21VR40	RHEEM	0
9522	09/01/2006	LTN050GEF	LOCHINVAR	2
9523	01/14/2007	LTN050G	LOCHINVAR	0
9524	03/07/2011	42VR50	RHEEM	0
9525	04/28/1989	FSG50	AO SMITH	0
9526	01/31/1989	FSG50	AO SMITH	0
9527	06/28/2010	LTN050G	LOCHINVAR	1
9528	01/17/2011	21DV50	RHEEM	0
9529	06/27/1989	FSG50	AO SMITH	0
9530	11/09/2007	LTN050GEF	LOCHINVAR	0
9531	01/22/2013	M45036FBN	BRADFORD-WHITE	0
9532	07/16/2001	G91200	RUUD/RHEEM	0
9533	03/24/2012	M45036FBN	BRADFORD-WHITE	0
9534	02/15/2008	LTN050	LOCHINVAR	0
9535	11/11/2004	42XR50	RHEEM	0
9536	10/03/2012	MI5036FBN	BRADFORD-WHITE	0
9537	03/05/2013	M45036FBN	BRADFORD-WHITE	0
9538	02/01/2006	LTN050G	LOCHINVAR	0
9539	10/13/2011	MI5036FBN	BRADFORD-WHITE	0
9540	10/09/2006	LTN050G	LOCHINVAR	1
9541	01/19/2006	LTN050GEF	LOCHINVAR	0
9542	06/24/2002	FSG50	AO SMITH	0
9543	02/28/2007	LTN050G	LOCHINVAR	0
9544	09/10/1999	FSGL40	AO SMITH	0
9545	01/21/2010	LTN040GEF	LOCHINVAR	0
9546	11/16/2005	LTN050G	LOCHINVAR	0
9547	06/03/2002	FSG50	AO SMITH	0
9548	03/26/2012	FSG50	AO SMITH	0
9549	08/03/1989	FSG50	AO SMITH	0
9550	03/16/2005	GVC50	A. O. SMITH	0
9551	09/30/2005	LTN050G	LOCHINVAR	0
9552	01/31/2007	LTN040G	LOCHINVAR	0
9553	11/08/1988	FSG50	AO SMITH	0
9554	01/30/2012	MI5036FBN	BRADFORD-WHITE	0
9555	10/30/2001	FSGL40	AO SMITH	0
9556	03/21/2005	PRX50	STATE	0
9557	04/04/2007	LTN050G	LOCHINVAR	0
9558	12/23/2005	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9559	05/07/2009	LTN050GEF	LOCHINVAR	1
9560	08/10/2012	PH2DV50F	RUUD	0
9561	09/11/2001	FSG50	AO SMITH	0
9562	08/25/2006	LTN050G	LOCHINVAR	0
9563	05/15/1998	41VR50	RHEEM	0
9564	02/15/2008	LTN050G	LOCHINVAR	0
9565	03/04/2012	M45036FBN	BRADFORD-WHITE	0
9566	07/07/2004	XTN050	LOCHINVAR	0
9567	09/19/2005	LTN050GEF	LOCHINVAR	0
9568	04/12/2007	LTN050GEF	LOCHINVAR	0
9569	07/27/1988	FSG50	AO SMITH	0
9570	02/03/2012	M45036FBN	BRADFORD-WHITE	0
9571	08/11/2005	PR650	STATE	0
9572	12/02/2011	M45036FBN	BRADFORD-WHITE	0
9573	11/07/2002	PGR50	AO SMITH	0
9574	04/03/2009	22DV50F	RHEEM	0
9575	02/10/2011	22DV50F	RHEEM	0
9576	08/05/2003	PRX50	STATE	0
9577	01/24/2007	PR650X0DS	STATE	0
9578	09/18/2004	XVR50	A. O. SMITH	0
9579	02/27/2006	LTN040G	LOCHINVAR	0
9580	02/07/2009	LTN050GEF	LOCHINVAR	0
9581	10/15/2001	PGR50	AO SMITH	0
9582	11/10/2005	LTN050G	LOCHINVAR	0
9583	08/05/2000	41XR50	RHEEM	0
9584	04/11/1996	41XR40	RHEEM	0
9585	04/24/2002	PGR50	AO SMITH	0
9586	07/20/1988	FSGL40	AO SMITH	0
9587	05/19/1988	FSG50	AO SMITH	0
9588	06/29/1988	PRX50	STATE	0
9589	05/04/2012	MI5036FBN	BRADFORD-WHITE	0
9590	01/11/2008	PR650X0DS	STATE	1
9591	07/28/2012	MI5036FBN	BRADFORD-WHITE	0
9592	09/12/2011	MI5036FBN	BRADFORD-WHITE	0
9593	06/09/2009	LTN030G	AO SMITH	1
9594	12/15/2009	LTN050GEF	LOCHINVAR	4
9595	06/14/2005	LTN050	LOCHINVAR	0
9596	09/29/2000	FSG50	AO SMITH	0
9597	01/10/2009	PRX50	STATE	0
9598	04/22/2011	41VR50	RHEEM	0
9599	07/20/2011	M45036FBN	BRADFORD-WHITE	0
9600	12/07/2007	PR650	STATE	1
9601	01/06/2007	LTN050G	LOCHINVAR	0
9602	04/05/2010	LTN050GEF	LOCHINVAR	0
9603	12/26/2007	LTN050GEF	LOCHINVAR	0
9604	03/19/2009	LTN050GEF	LOCHINVAR	0
9605	03/16/2010	LTN050GEF	LOCHINVAR	0
9606	02/24/2006	LTN050G	LOCHINVAR	0
9607	09/08/2004	GVC50	A. O. SMITH	1
9608	11/22/2010	21DV50	RHEEM	0
9609	04/01/2005	PVR50	AO SMITH	0
9610	09/19/2012	MI5036FBN	BRADFORD-WHITE	0
9611	08/02/2010	LTN050GEF	LOCHINVAR	0
9612	06/18/1990	FSG40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9613	07/01/2004	GVC50	A. O. SMITH	0
9614	05/30/1996	FGR50	AO SMITH	0
9615	12/19/2011	M45036FBN	BRADFORD-WHITE	0
9616	09/07/2007	LTN050G	LOCHINVAR	0
9617	03/23/2002	FSG50	AO SMITH	0
9618	11/09/2010	41VR40	RHEEM	0
9619	12/08/1989	PRV50NODS	STATE	1
9620	03/23/2012	MI5036FBN	BRADFORD-WHITE	0
9621	08/14/1998	G72DUMMY	AO SMITH	0
9622	03/11/2003	PGR50	AO SMITH	2
9623	06/01/2010	LTN051G	LOCHINVAR	0
9624	08/13/2009	PRV50NODS	STATE	0
9625	02/27/2012	M45036FBN	BRADFORD-WHITE	0
9626	12/27/2005	LTN050G	LOCHINVAR	2
9627	03/02/2010	22DV50F	RHEEM	0
9628	01/05/2009	LTN050GEF	LOCHINVAR	1
9629	03/02/2012	M45036FBN	BRADFORD-WHITE	0
9630	04/04/1991	B71DUMMY	AMERICAN	0
9631	10/08/2009	LTN051G	LOCHINVAR	0
9632	12/28/2005	LTN050	LOCHINVAR	0
9633	03/05/2001	PRX50	STATE	0
9634	06/17/2008	22DV50C	RHEEM	0
9635	04/03/1991	B71DUMMY	AMERICAN	0
9636	01/02/2009	LTN050G	LOCHINVAR	0
9637	09/07/1989	PRV50NODS	STATE	0
9638	02/26/2000	41XR50	RHEEM	0
9639	03/08/2003	FSG50	AO SMITH	0
9640	08/10/1999	FGR50	AO SMITH	0
9641	11/22/2002	PRX50	STATE	0
9642	11/15/2012	PH2DV50F	RUUD	1
9643	02/21/2003	FSG50	AO SMITH	0
9644	10/21/2008	LTN050GEF	LOCHINVAR	1
9645	10/20/2002	FSG50	AO SMITH	0
9646	07/25/2007	LTN050GEF	LOCHINVAR	0
9647	07/01/2004	GVC50	A. O. SMITH	0
9648	11/18/2002	PRX50	STATE	0
9649	03/25/2003	FSG50	AO SMITH	0
9650	02/15/2004	XTN040	LOCHINVAR	2
9651	10/10/2011	MI5036FBN	BRADFORD-WHITE	0
9652	05/11/1997	PGR50	AO SMITH	0
9653	12/30/2010	21V502	RHEEM	0
9654	05/27/2010	LTN050GEF	LOCHINVAR	0
9655	11/30/2007	LSN041G	LOCHINVAR	0
9656	02/25/2002	PGR50	AO SMITH	0
9657	06/12/2007	LTN040GEF	LOCHINVAR	0
9658	12/12/1990	PRV50NODS	STATE	0
9659	03/02/2009	LTN050G	LOCHINVAR	0
9660	01/15/2011	42VR50	RHEEM	0
9661	01/27/2005	GVR50	AO SMITH	1
9662	10/24/2011	PH2DV50F	RUUD	0
9663	06/23/2003	PRX50	STATE	1
9664	07/20/2012	MI5036FBN	BRADFORD-WHITE	1
9665	01/22/2011	LTN040G	LOCHINVAR	0
9666	03/15/2011	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9667	04/19/2012	MI5036FBN	BRADFORD-WHITE	0
9668	02/07/2011	42VR50	RHEEM	0
9669	04/14/2008	LTN050GEF	LOCHINVAR	0
9670	01/27/1987	PRX50	STATE	0
9671	06/25/2010	LTN040GEF	LOCHINVAR	1
9672	06/26/2000	41XR50	RHEEM	1
9673	06/24/1999	FSG50	AO SMITH	0
9674	10/11/2010	42VR50	RHEEM	1
9675	11/29/2012	M45036FBN	BRADFORD-WHITE	0
9676	07/20/2007	LTN050GEF	LOCHINVAR	0
9677	04/17/2003	PGR50	AO SMITH	0
9678	02/26/2001	PR650	STATE	0
9679	08/05/2009	LTN050GEF	LOCHINVAR	0
9680	06/28/2010	LTN050GEF	LOCHINVAR	0
9681	09/15/2006	LTN050G	LOCHINVAR	0
9682	09/29/1987	FSGL40	AO SMITH	0
9683	01/16/1987	FSG50	AO SMITH	1
9684	12/27/2011	M45036FBN	BRADFORD-WHITE	0
9685	08/03/2005	LTN050	LOCHINVAR	0
9686	10/14/2000	41XR50	RHEEM	0
9687	01/12/2013	M45036FBN	BRADFORD-WHITE	0
9688	12/31/2007	LTN050GEF	LOCHINVAR	0
9689	01/16/2013	MI5036FBN	BRADFORD-WHITE	0
9690	05/03/2005	PR640	STATE	3
9691	08/11/2006	LTN050G	LOCHINVAR	0
9692	09/23/2008	LTN050G	LOCHINVAR	1
9693	11/08/2001	21V506	RHEEM	1
9694	10/01/2004	XVR50	A. O. SMITH	0
9695	03/05/2008	LTN050	LOCHINVAR	0
9696	04/30/1987	FGR50	AO SMITH	0
9697	04/11/2010	LTN050G	LOCHINVAR	0
9698	08/15/2008	22DV50F	RHEEM	1
9699	06/16/2008	LTN050GEF	LOCHINVAR	0
9700	10/27/2006	PHR50	RUUD	0
9701	10/28/2011	MI5036FBN	BRADFORD-WHITE	0
9702	01/07/2009	LTN050GEF	LOCHINVAR	0
9703	12/13/1999	41VR50	RHEEM	1
9704	01/02/2001	PRX50	STATE	0
9705	12/01/2008	LTN050GEF	LOCHINVAR	0
9706	09/11/2010	42VR50	RHEEM	0
9707	11/12/2011	M440T6FBN	BRADFORD-WHITE	1
9708	08/20/1998	FSG40	AO SMITH	0
9709	12/02/2011	MI5036FBN	BRADFORD-WHITE	1
9710	11/21/2006	PR650	STATE	0
9711	11/22/2002	21V506	RHEEM	2
9712	11/16/2010	42VR50	RHEEM	1
9713	03/06/2002	PGR50	AO SMITH	1
9714	09/16/2009	LTN050GEF	LOCHINVAR	0
9715	05/13/2007	LTN050G	LOCHINVAR	0
9716	11/24/2006	LTN050G	LOCHINVAR	0
9717	08/14/2001	PGR50	AO SMITH	0
9718	10/08/2010	41VR50	RHEEM	0
9719	12/27/2007	LTN050GEF	LOCHINVAR	0
9720	08/11/2005	LTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9721	03/14/2012	M45036FBN	BRADFORD-WHITE	0
9722	01/04/2002	PGR40	AO SMITH	0
9723	11/30/2012	MI403S6FBN	BRADFORD-WHITE	0
9724	03/14/2013	M45036FBN	BRADFORD-WHITE	0
9725	01/30/2010	22DV50C	RHEEM	0
9726	04/14/2008	LTN050GEF	LOCHINVAR	0
9727	09/27/1999	PRV50NODS	STATE	0
9728	02/01/1990	PRX50	STATE	0
9729	06/14/2003	PRX50	STATE	0
9730	01/30/2010	22DV50C	RHEEM	0
9731	09/08/2005	PR650	STATE	0
9732	04/07/2011	ETN076	LOCHINVAR	2
9733	12/27/2007	PR650X0DS	STATE	0
9734	11/18/2008	LTN050GEF	LOCHINVAR	0
9735	12/05/2005	LTN050G	LOCHINVAR	0
9736	03/12/2004	FCV50	AO SMITH	0
9737	04/28/2012	M45036FBN	BRADFORD-WHITE	0
9738	03/11/2002	FSG50	AO SMITH	0
9739	08/22/2008	LTN050GEF	LOCHINVAR	0
9740	12/02/2008	FSG50	AO SMITH	0
9741	05/25/2010	G91200	RUUD/RHEEM	0
9742	08/01/2008	LTN050GEF	LOCHINVAR	0
9743	12/14/2010	42VR50	RHEEM	3
9744	07/19/2011	M45036FBN	BRADFORD-WHITE	0
9745	11/08/2000	H72DUMMY	AO SMITH	0
9746	03/28/2007	PR650	STATE	1
9747	03/19/2008	LTN050GEF	LOCHINVAR	0
9748	07/17/2011	MI5036FBN	BRADFORD-WHITE	0
9749	11/05/2005	LTN040GEF	LOCHINVAR	0
9750	02/28/2013	M45036FBN	BRADFORD-WHITE	4
9751	05/19/2003	FSG50	AO SMITH	0
9752	03/10/2006	XSN0401GEF	LOCHINVAR	0
9753	02/04/2012	PH2DV50F	RUUD	0
9754	05/01/2006	LTN050G	LOCHINVAR	1
9755	03/01/2006	PR650	STATE	0
9756	11/09/2012	M45036FBN	BRADFORD-WHITE	0
9757	12/14/1988	FSG50	AO SMITH	0
9758	04/01/2009	22DV50C	RHEEM	0
9759	09/15/2009	LTN050GEF	LOCHINVAR	0
9760	09/28/2005	LTN050G	LOCHINVAR	0
9761	10/27/2011	M45036FBN	BRADFORD-WHITE	0
9762	03/12/2012	MI5036FBN	BRADFORD-WHITE	1
9763	09/01/1999	FGR40	AO SMITH	0
9764	11/18/2010	42VR50	RHEEM	0
9765	01/26/2012	G75125	RUUD/RHEEM	0
9766	07/26/2007	FSGL40	AO SMITH	0
9767	04/05/1999	FSG50	AO SMITH	0
9768	05/20/2006	PR650	STATE	0
9769	01/24/2012	M45036FBN	BRADFORD-WHITE	1
9770	07/30/2009	LTN051G	LOCHINVAR	0
9771	05/05/1989	PRV50NODS	STATE	0
9772	02/01/2010	LTN050GEF	LOCHINVAR	0
9773	03/17/1989	FSG50	AO SMITH	0
9774	12/30/2011	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9775	12/08/2001	41VR40	RHEEM	0
9776	10/07/1998	41XR50	RHEEM	0
9777	07/05/2009	LTN050GEF	LOCHINVAR	0
9778	10/31/2008	LTN050GEF	LOCHINVAR	0
9779	07/21/1989	FSG50	AO SMITH	1
9780	03/29/2010	LTN050GEF	LOCHINVAR	0
9781	09/26/2006	LTN050G	LOCHINVAR	1
9782	01/27/2011	22DV50F	RHEEM	0
9783	01/12/1998	PRV50NODS	STATE	1
9784	12/26/2008	22DV50F	RHEEM	0
9785	11/09/2009	LTN050GEF	LOCHINVAR	0
9786	05/11/2005	LTN050	LOCHINVAR	0
9787	04/08/1989	FSG50	AO SMITH	0
9788	06/28/1989	RF82156	RUUD	0
9789	07/27/2012	PH2DV50F	RUUD	0
9790	10/25/2004	GVC50	A. O. SMITH	1
9791	04/12/2004	GVC50	A. O. SMITH	0
9792	08/14/1989	FSG40	AO SMITH	0
9793	10/04/1989	FSG40	AO SMITH	0
9794	05/18/2005	PR650	STATE	1
9795	05/27/2012	M45036FBN	BRADFORD-WHITE	0
9796	01/13/2006	LTN050G	LOCHINVAR	1
9797	02/01/2008	LTN050GEF	LOCHINVAR	0
9798	08/21/2012	MI5036FBN	BRADFORD-WHITE	0
9799	06/13/2002	FSG50	AO SMITH	0
9800	03/07/2002	PGR50	AO SMITH	0
9801	10/05/2005	LTN050G	LOCHINVAR	0
9802	04/22/2003	FSG50	AO SMITH	0
9803	08/28/2010	LTN050GEF	LOCHINVAR	2
9804	06/04/2003	FSG50	AO SMITH	1
9805	03/14/2009	LTN050G	LOCHINVAR	0
9806	09/04/2001	PRX50	STATE	0
9807	03/11/2009	LTN050G	LOCHINVAR	0
9808	04/22/2003	FSG50	AO SMITH	0
9809	10/04/2009	LTN040GEF	LOCHINVAR	0
9810	05/04/2009	LTN050GEF	LOCHINVAR	1
9811	02/15/2007	LTN050G	LOCHINVAR	0
9812	12/02/2008	22DV50C	RHEEM	0
9813	08/14/2003	FSG40	AO SMITH	0
9814	04/13/2011	22V50F1	RHEEM	0
9815	10/19/2007	LTN050G	LOCHINVAR	0
9816	06/20/2006	LTN050G	LOCHINVAR	0
9817	02/20/1989	FSG50	AO SMITH	0
9818	03/11/2006	LTN050G	LOCHINVAR	0
9819	12/18/2001	41V50	RHEEM	0
9820	11/07/2011	MI5036FBN	BRADFORD-WHITE	1
9821	03/26/2004	PRX50	STATE	2
9822	06/15/2006	LTN050G	LOCHINVAR	0
9823	11/29/2008	LTN050GEF	LOCHINVAR	0
9824	01/14/1998	FGR50	AO SMITH	0
9825	08/13/2002	PGR50	AO SMITH	0
9826	04/02/2012	MI5036FBN	BRADFORD-WHITE	1
9827	03/28/1988	FSG50	AO SMITH	0
9828	10/08/2002	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9829	02/10/2004	PRX50	STATE	1
9830	06/29/2000	FSGL40	AO SMITH	0
9831	09/20/2007	LTN050G	LOCHINVAR	0
9832	12/01/2008	LTN050GEF	LOCHINVAR	0
9833	02/05/2002	PGR50	AO SMITH	0
9834	09/11/2002	PGR50	AO SMITH	0
9835	01/23/2012	DS150S6FBN	BRADFORD-WHITE	0
9836	04/14/1988	FSG50	AO SMITH	0
9837	08/29/2007	LSN041G	LOCHINVAR	1
9838	08/09/2004	PRX50	STATE	0
9839	06/01/2004	PRX50	STATE	0
9840	07/28/2001	PRX50	STATE	0
9841	05/10/2009	LTN050GEF	LOCHINVAR	0
9842	10/26/2012	PH2DV50F	RUUD	0
9843	06/21/2005	LTN050	LOCHINVAR	0
9844	10/13/2011	MI403S6FBN	BRADFORD-WHITE	1
9845	05/12/1988	FSG50	AO SMITH	0
9846	12/15/2008	LTN050GEF	LOCHINVAR	0
9847	02/04/1988	P505	RUUD	0
9848	04/20/1999	PGR50	AO SMITH	0
9849	03/14/2008	LTN040GEF	LOCHINVAR	0
9850	05/01/1999	FSG50	AO SMITH	0
9851	10/13/2006	XVR50	A. O. SMITH	2
9852	11/28/2007	PR650	STATE	0
9853	05/25/2004	GVC50	A. O. SMITH	0
9854	05/25/2007	LTN050GEF	LOCHINVAR	0
9855	03/31/2012	MI5036FBN	BRADFORD-WHITE	0
9856	01/23/1991	BTC197	AO SMITH	0
9857	12/05/1987	FSG50	AO SMITH	0
9858	10/23/2011	M45036FBN	BRADFORD-WHITE	0
9859	01/30/2012	M45036FBN	BRADFORD-WHITE	0
9860	12/10/2007	LTN050GEF	LOCHINVAR	0
9861	04/09/2003	PRX50	STATE	0
9862	03/26/1998	H72DUMMY	AO SMITH	0
9863	11/28/1989	FSG50	AO SMITH	0
9864	06/30/2008	LTN051G	LOCHINVAR	0
9865	07/15/2009	PGR50	AO SMITH	0
9866	03/31/2001	PGR50	AO SMITH	0
9867	06/21/2008	LTN050GEF	LOCHINVAR	0
9868	03/31/2006	LTN050G	LOCHINVAR	0
9869	11/13/2001	PGR50	AO SMITH	0
9870	04/26/2006	LTN050G	LOCHINVAR	0
9871	12/06/2008	LTN050G	LOCHINVAR	0
9872	08/15/2010	22DV50C	RHEEM	0
9873	11/26/2007	LTN050GEF	LOCHINVAR	0
9874	03/14/2008	LTN050GEF	LOCHINVAR	0
9875	10/16/2007	LTN050G	LOCHINVAR	1
9876	01/28/2008	LTN050G	LOCHINVAR	0
9877	10/14/2011	M45036FBN	BRADFORD-WHITE	1
9878	12/23/1999	41XR50	RHEEM	0
9879	01/03/1995	PRV50NODS	STATE	0
9880	02/05/1990	FSG50	AO SMITH	0
9881	02/09/1990	PRV50NODS	STATE	0
9882	04/22/2005	LTN040	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9883	07/13/2004	GVC40	A. O. SMITH	1
9884	10/14/2011	M45036FBN	BRADFORD WHITE	0
9885	12/07/2009	LTN050GEF	LOCHINVAR	0
9886	07/30/2007	LTN050GEF	LOCHINVAR	0
9887	01/03/2000	FSG50	AO SMITH	1
9888	06/16/2008	LTN050GEF	LOCHINVAR	0
9889	11/05/1990	21V502	RHEEM	1
9890	04/12/2000	FSGL40	AO SMITH	1
9891	10/25/2006	PR650	STATE	0
9892	02/20/2010	LTN050GEF	LOCHINVAR	0
9893	12/28/1989	21V502	RHEEM	0
9894	12/03/2007	LTN050GEF	LOCHINVAR	0
9895	09/10/2000	41XR50	RHEEM	0
9896	01/16/2000	41XR50	RHEEM	0
9897	02/19/2010	LTN050GEF	LOCHINVAR	4
9898	02/19/2002	PGR50	AO SMITH	0
9899	11/19/2004	GVC40	A. O. SMITH	0
9900	11/04/2011	M45036FBN	BRADFORD-WHITE	0
9901	10/29/1990	PRX50	STATE	0
9902	06/22/2010	22DV50C	RHEEM	1
9903	01/14/2012	M45036FBN	BRADFORD-WHITE	0
9904	06/26/2006	LTN050G	LOCHINVAR	0
9905	02/23/2006	LTN050G	LOCHINVAR	0
9906	10/02/2012	M45036FBN	BRADFORD-WHITE	0
9907	11/30/1998	FSG50	AO SMITH	0
9908	12/17/2002	PGR50	AO SMITH	0
9909	01/30/2006	LTN050G	LOCHINVAR	1
9910	01/25/2000	FSG50	AO SMITH	0
9911	12/31/2008	LTN050GEF	LOCHINVAR	0
9912	02/29/2008	21DV50	RHEEM	1
9913	12/15/1986	21V506	RHEEM	0
9914	08/14/1998	FGR50	AO SMITH	0
9915	07/08/2007	LSN041G	LOCHINVAR	0
9916	12/30/2009	LTN050G	LOCHINVAR	0
9917	06/07/2008	LTN050GEF	LOCHINVAR	0
9918	10/10/2012	M45036FBN	BRADFORD-WHITE	0
9919	09/07/2005	LTN050G	LOCHINVAR	0
9920	09/02/2004	GVC40	A. O. SMITH	1
9921	10/11/2001	FSG50	AO SMITH	0
9922	12/27/2010	21VR50	RHEEM	0
9923	11/21/1986	P506	RUUD	0
9924	01/16/2013	DS150S6FBN	BRADFORD-WHITE	0
9925	09/16/2010	22DV50C	RHEEM	4
9926	09/09/2009	PGR50	AO SMITH	0
9927	06/17/2012	M45036FBN	BRADFORD-WHITE	0
9928	02/22/2002	FSG50	AO SMITH	0
9929	08/10/2010	LTN050GEF	LOCHINVAR	0
9930	12/26/2007	LTN050GEF	LOCHINVAR	0
9931	03/22/2005	GVC50	A. O. SMITH	0
9932	08/31/2011	G91200	RUUD/RHEEM	0
9933	12/12/1996	PGR50	AO SMITH	0
9934	06/02/2006	LTN050G	LOCHINVAR	0
9935	11/24/2008	PR640	STATE	0
9936	02/12/1992	21DV50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9937	11/08/2006	LTN040G	LOCHINVAR	0
9938	01/30/1998	FGR40	AO SMITH	0
9939	09/20/2012	M45036FBN	BRADFORD-WHITE	1
9940	10/05/2002	PRX40	STATE	0
9941	04/19/2007	PR650X0DS	STATE	0
9942	09/12/2002	FSG50	AO SMITH	0
9943	01/17/1990	PRX50	STATE	0
9944	02/14/2008	FSG40	AO SMITH	0
9945	07/03/2002	FSG50	AO SMITH	0
9946	02/13/2012	M45036FBN	BRADFORD-WHITE	2
9947	01/07/2011	22DV50F	RHEEM	0
9948	06/10/2001	FSGL40	AO SMITH	0
9949	06/03/2008	LTN050GEF	LOCHINVAR	0
9950	04/24/2008	LTN050GEF	LOCHINVAR	0
9951	04/21/2006	PR650	STATE	1
9952	01/26/2006	LTN050GEF	LOCHINVAR	0
9953	10/14/2009	LTN050GEF	LOCHINVAR	0
9954	06/21/2004	GVC50	A. O. SMITH	0
9955	11/27/2006	PRV50NODS	STATE	0
9956	03/11/2010	21DV50	RHEEM	1
9957	04/09/2007	LTN051G	LOCHINVAR	0
9958	05/29/2009	LTN050GEF	LOCHINVAR	0
9959	02/16/2006	LTN050G	LOCHINVAR	0
9960	11/30/2006	LTN051G	LOCHINVAR	1
9961	02/26/2009	22DV50F	RHEEM	0
9962	03/20/2010	LTN050GEF	LOCHINVAR	0
9963	06/20/2005	XSN0401GEF	LOCHINVAR	0
9964	03/08/2004	XTN050	LOCHINVAR	0
9965	06/28/2004	PRX50	STATE	0
9966	01/02/2013	F72DUMMY	UNKNOWN AT CONVERSION	0
9967	01/23/2002	FSG50	AO SMITH	0
9968	08/08/2001	PRX50	STATE	0
9969	10/04/2003	PGR50	AO SMITH	1
9970	02/13/1990	P505	RUUD	0
9971	06/23/2011	MI5036FBN	BRADFORD-WHITE	0
9972	01/15/2003	FSG50	AO SMITH	0
9973	10/02/2006	LTN050G	LOCHINVAR	0
9974	02/16/2005	PRX50	STATE	0
9975	04/11/2011	22DV50F	RHEEM	0
9976	09/26/2012	MI5036FBN	BRADFORD-WHITE	0
9977	01/12/2004	XTN050	LOCHINVAR	0
9978	02/10/2005	GCVL40	A. O. SMITH	0
9979	02/06/2013	MI5036FBN	BRADFORD-WHITE	0
9980	10/16/2001	FSG50	AO SMITH	0
9981	05/02/2005	LTN050	LOCHINVAR	0
9982	09/12/2002	PGR50	AO SMITH	0
9983	04/13/2007	LTN050G	LOCHINVAR	0
9984	01/09/2009	LTN050GEF	LOCHINVAR	0
9985	06/05/2008	LTN040GEF	LOCHINVAR	0
9986	08/18/2012	PH2DV50F	RUUD	2
9987	10/12/2006	PR650	STATE	0
9988	01/09/2009	LTN050GEF	LOCHINVAR	0
9989	07/07/1989	FSG50	AO SMITH	0
9990	10/11/1989	21V506	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
9991	09/08/1989	FSGL40	AO SMITH	0
9992	09/03/2001	PGR50	AO SMITH	0
9993	01/20/2012	MI5036FBN	BRADFORD-WHITE	5
9994	10/08/2003	PVR50	AO SMITH	0
9995	05/19/2008	LTN051G	LOCHINVAR	0
9996	09/20/2006	PR650X0DS	STATE	0
9997	02/24/2000	41XR50	RHEEM	0
9998	11/21/2012	M45036FBN	BRADFORD-WHITE	0
9999	02/14/2011	22DV50F	RHEEM	0
10000	06/02/2004	PGR50	AO SMITH	0
10001	10/26/2009	LTN050GEF	LOCHINVAR	0
10002	09/20/2010	LTN050GEF	LOCHINVAR	0
10003	01/16/2013	DS140S6FBN	BRADFORD-WHITE	0
10004	02/12/1999	FSG40	AO SMITH	0
10005	07/18/2005	LTN050	LOCHINVAR	0
10006	10/25/1989	P506	RUUD	0
10007	03/24/2011	22DV50F	RHEEM	0
10008	07/20/2012	G91200	RUUD/RHEEM	1
10009	06/28/2005	LTN050	LOCHINVAR	2
10010	03/01/2007	LTN050G	LOCHINVAR	0
10011	09/17/2009	LTN050GEF	LOCHINVAR	0
10012	06/07/2008	LTN050G	LOCHINVAR	1
10013	08/07/2004	GVC50	A. O. SMITH	0
10014	04/16/2010	LTN050G	LOCHINVAR	0
10015	12/27/1999	PHR50	RUUD	0
10016	03/16/2013	MI5036FBN	Bradford-White	0
10017	05/20/2011	21VR50	RHEEM	0
10018	08/17/2007	LSN041G	LOCHINVAR	0
10019	09/19/2011	PH2DV50F	RUUD	0
10020	02/28/2000	PGR50	AO SMITH	0
10021	10/11/2004	PRX50	STATE	0
10022	09/27/2010	41VR50	RHEEM	0
10023	11/14/2007	LTN050GEF	LOCHINVAR	0
10024	11/16/2012	M45036FBN	BRADFORD-WHITE	1
10025	03/17/2011	42VR50	RHEEM	1
10026	02/27/2008	PR650X0DS	STATE	0
10027	08/24/2005	LTN050	LOCHINVAR	0
10028	04/27/2011	22DV50F	RHEEM	0
10029	10/23/1989	FSG50	AO SMITH	0
10030	04/14/1999	21V506	RHEEM	0
10031	12/08/2008	LTN050GEF	LOCHINVAR	0
10032	04/01/1998	FSG50	AO SMITH	0
10033	11/08/2010	GVC50	A. O. SMITH	0
10034	03/13/2008	PRV50NODS	STATE	1
10035	01/14/2002	PRX50	STATE	0
10036	04/07/1988	FSG50	AO SMITH	0
10037	02/24/1995	PHR50	RUUD	0
10038	11/08/1999	PGR50	AO SMITH	0
10039	11/18/2009	22DV50C	RHEEM	0
10040	05/07/2009	LTN050GEF	LOCHINVAR	0
10041	09/17/2012	G75125	RUUD/RHEEM	0
10042	03/24/2012	MI5036FBN	BRADFORD-WHITE	0
10043	01/16/2009	LSN041G	LOCHINVAR	0
10044	01/14/2005	LTN040GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10045	02/19/2005	LTN050	LOCHINVAR	0
10046	11/18/2005	LTN050GEF	LOCHINVAR	1
10047	03/01/2011	22DV50F	RHEEM	0
10048	09/27/1999	FSG40	AO SMITH	0
10049	04/16/2004	FCV50	AO SMITH	0
10050	08/01/1988	FSGL40	AO SMITH	0
10051	07/13/1997	FSGL40	AO SMITH	0
10052	09/23/1998	41V50S	RHEEM	0
10053	02/23/1996	PGR50	AO SMITH	0
10054	07/11/2007	LTN050GEF	LOCHINVAR	0
10055	08/12/2011	PH2DV50F	RUUD	0
10056	09/20/2006	LTN050G	LOCHINVAR	0
10057	01/21/2002	PRX50	STATE	0
10058	08/24/1988	FSG50	AO SMITH	0
10059	07/08/2008	21V506	RHEEM	0
10060	11/29/2005	LTN050GEF	LOCHINVAR	1
10061	03/21/2006	PR650	STATE	0
10062	06/15/2005	LTN050	LOCHINVAR	1
10063	01/08/2008	PR650	STATE	0
10064	04/29/2003	PRX50	STATE	0
10065	12/28/2010	21VR50	RHEEM	1
10066	10/09/1999	FSG50	AO SMITH	0
10067	06/13/2002	PGR50	AO SMITH	1
10068	12/10/1987	FSG50	AO SMITH	0
10069	07/06/2007	LTN050GEF	LOCHINVAR	1
10070	04/18/2012	MI5036FBN	BRADFORD-WHITE	0
10071	09/24/2001	PGR40	AO SMITH	0
10072	09/08/2004	XVR50	A. O. SMITH	0
10073	12/09/2009	LTN050GEF	LOCHINVAR	0
10074	06/02/2005	LTN050	LOCHINVAR	0
10075	04/26/2006	PR650	STATE	1
10076	04/05/2008	22DV50C	RHEEM	0
10077	03/22/2010	LTN050G	LOCHINVAR	0
10078	08/19/2011	MI5036FBN	BRADFORD-WHITE	0
10079	06/11/2011	F72DUMMY	UNKNOWN AT CONVERSION	2
10080	05/21/2003	FSG50	AO SMITH	0
10081	06/19/2001	21DV50	RHEEM	1
10082	09/29/2008	LTN050GEF	LOCHINVAR	0
10083	10/19/1990	PRV50NODS	STATE	0
10084	10/20/1998	FSG50	AO SMITH	0
10085	12/17/2009	LTN050GEF	LOCHINVAR	0
10086	08/02/2011	21V506	RHEEM	0
10087	03/26/2012	MI5036FBN	BRADFORD-WHITE	0
10088	10/29/2004	GVC50	A. O. SMITH	0
10089	10/20/2007	LTN050GEF	LOCHINVAR	0
10090	02/25/2005	21V506	RHEEM	0
10091	03/30/2001	FSGL40	AO SMITH	0
10092	06/06/1990	FSG50	AO SMITH	0
10093	06/23/2004	PRX50	STATE	0
10094	03/24/2010	LTN050GEF	LOCHINVAR	0
10095	05/02/2001	21V506	RHEEM	0
10096	09/16/2006	PR650	STATE	0
10097	07/27/2010	LTN050G	LOCHINVAR	0
10098	07/31/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10099	09/15/2003	PRX50	STATE	0
10100	07/25/2001	FSG50	AO SMITH	0
10101	07/04/2009	LTN050G	LOCHINVAR	0
10102	04/12/1990	FSG50	AO SMITH	0
10103	05/23/2005	LTN050	LOCHINVAR	0
10104	08/22/2011	M440T6FBN	BRADFORD-WHITE	0
10105	09/23/2006	PR650	STATE	0
10106	10/19/2012	G91200	RUUD/RHEEM	1
10107	10/30/1996	FGR50	AO SMITH	0
10108	12/01/2008	LTN050GEF	LOCHINVAR	1
10109	05/08/2012	M45036FBN	BRADFORD-WHITE	0
10110	09/10/2008	42VR50	RHEEM	0
10111	11/06/2007	LTN050GEF	LOCHINVAR	0
10112	05/28/1997	FSG40	AO SMITH	0
10113	03/16/2009	LTN050G	LOCHINVAR	0
10114	10/11/2005	PR650	STATE	0
10115	10/15/2011	MI5036FBN	BRADFORD-WHITE	0
10116	03/28/2012	M45036FBN	BRADFORD-WHITE	0
10117	02/04/2012	PH2DV50F	RUUD	1
10118	07/26/1990	FSGL30	AO SMITH	0
10119	10/23/2003	G76200	RUUD/RHEEM	0
10120	09/21/2005	LTN050G	LOCHINVAR	0
10121	05/24/2007	LTN050GEF	LOCHINVAR	0
10122	06/09/2008	LTN050G	LOCHINVAR	0
10123	11/27/1990	BT155	AO SMITH	1
10124	09/21/2011	M45036FBN	BRADFORD-WHITE	1
10125	04/10/2008	22DV50C	RHEEM	1
10126	10/21/2006	LTN050GEF	LOCHINVAR	1
10127	12/17/2011	PH2DV50F	RUUD	2
10128	12/21/2011	M45036FBN	BRADFORD-WHITE	0
10129	02/19/2007	LTN050G	LOCHINVAR	1
10130	12/22/2006	PR650X0DS	STATE	0
10131	06/06/2001	PRX50	STATE	0
10132	06/24/1999	FGR50	AO SMITH	0
10133	02/09/1991	RF67120	RUUD	0
10134	01/21/1991	D74DUMMY	AO SMITH	0
10135	01/29/2013	MI5036FBN	BRADFORD-WHITE	0
10136	01/22/2013	M45036FBN	BRADFORD-WHITE	0
10137	03/11/2009	LTN040GEF	LOCHINVAR	0
10138	04/21/2012	PH2DV50F	RUUD	0
10139	01/02/2001	41VR50	RHEEM	0
10140	07/16/2001	FSG50	AO SMITH	0
10141	09/25/2007	LTN050G	LOCHINVAR	0
10142	03/03/2006	21V506	RHEEM	0
10143	03/08/2002	FSG50	AO SMITH	0
10144	06/27/2005	LTN050	LOCHINVAR	0
10145	09/01/2011	PH2DV50F	RUUD	0
10146	11/11/2004	GVC50	A. O. SMITH	0
10147	07/30/2005	LTN050	LOCHINVAR	0
10148	05/08/2003	PGR50	AO SMITH	0
10149	05/11/2011	41VR50	RHEEM	1
10150	06/06/2009	21DV50	RHEEM	0
10151	01/12/2009	LTN050GEF	LOCHINVAR	1
10152	05/11/2011	21VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10153	03/09/2012	MI5036FBN	BRADFORD-WHITE	0
10154	12/22/2001	FSG50	AO SMITH	0
10155	01/29/2002	PR650	STATE	0
10156	02/15/2010	LTN050GEF	LOCHINVAR	1
10157	06/09/2009	22DV50F	RHEEM	0
10158	03/09/2012	MI5036FBN	BRADFORD-WHITE	0
10159	09/11/2000	FSGL40	AO SMITH	0
10160	05/26/2011	22DV50F	RHEEM	0
10161	01/13/2010	LTN050GEF	LOCHINVAR	0
10162	12/11/2006	LTN050GEF	LOCHINVAR	0
10163	06/22/1989	P506	RUUD	0
10164	10/24/2011	PH2DV50F	Rheem/Ruud	1
10165	03/29/2011	21VR50	RHEEM	0
10166	10/30/2010	41VR50	RHEEM	0
10167	01/13/2006	LTN050G	LOCHINVAR	1
10168	07/25/1989	FSG50	AO SMITH	0
10169	02/21/2012	41XR50	RHEEM	1
10170	04/30/2004	XTN050	LOCHINVAR	0
10171	03/01/2002	PGR50	AO SMITH	0
10172	04/10/2007	LTN050G	LOCHINVAR	0
10173	04/14/2008	LTN050	LOCHINVAR	0
10174	11/30/2011	M45036FBN	BRADFORD-WHITE	0
10175	04/28/2004	GVC50	A. O. SMITH	0
10176	06/04/2012	MI5036FBN	BRADFORD-WHITE	1
10177	10/01/2011	M45036FBN	BRADFORD-WHITE	0
10178	05/13/2002	PRX50	STATE	0
10179	02/22/2013	MI5036FBN	BRADFORD-WHITE	0
10180	03/19/2010	LTN050GEF	LOCHINVAR	0
10181	07/09/2012	MI40T6FBN	BRADFORD-WHITE	1
10182	12/23/1988	PRX50	STATE	0
10183	02/26/2011	42V5065F	RHEEM	1
10184	06/20/1989	PRV50NODS	STATE	0
10185	06/04/2005	PR650	STATE	0
10186	01/28/2002	FSG50	AO SMITH	0
10187	12/04/2001	PGR50	AO SMITH	0
10188	03/30/2009	22DV50F	RHEEM	2
10189	03/29/1989	21V502	RHEEM	0
10190	05/28/2001	41VR50	RHEEM	0
10191	05/11/2006	PR650	STATE	0
10192	10/25/2009	LTN050GEF	LOCHINVAR	1
10193	11/16/1989	FSG50	AO SMITH	0
10194	06/26/2008	LTN050G	LOCHINVAR	0
10195	01/23/2009	22DV50C	RHEEM	0
10196	11/26/1999	PR650	STATE	0
10197	01/21/1991	P506	RUUD	1
10198	08/17/2005	LTN050	LOCHINVAR	1
10199	12/17/2004	FSG50	AO SMITH	0
10200	04/24/1998	FSG50	AO SMITH	0
10201	04/27/2010	LTN050GEF	LOCHINVAR	0
10202	02/22/2011	21VR50	RHEEM	0
10203	08/05/2010	LTN050GEF	LOCHINVAR	0
10204	01/06/2002	PRX50	STATE	0
10205	11/09/2010	42VR50	RHEEM	0
10206	03/08/2005	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10207	05/29/2010	LTN050GEF	LOCHINVAR	0
10208	05/14/2007	LTN051G	LOCHINVAR	0
10209	07/27/2007	LTN050GEF	LOCHINVAR	0
10210	10/24/2005	LTN040G	LOCHINVAR	0
10211	05/03/2007	LTN050GEF	LOCHINVAR	0
10212	10/10/2005	LTN050GEF	LOCHINVAR	0
10213	06/29/2012	M45036FBN	BRADFORD-WHITE	0
10214	11/09/2005	PR650	STATE	0
10215	05/06/2010	LTN050GEF	LOCHINVAR	0
10216	10/15/2007	LTN050G	LOCHINVAR	0
10217	09/11/2003	41V40S	RHEEM	0
10218	03/11/2002	21V506	RHEEM	0
10219	02/07/2005	LTN050	LOCHINVAR	0
10220	03/30/2011	22DV50F	RHEEM	0
10221	06/26/1999	FSG50	AO SMITH	0
10222	05/18/2010	LTN050GEF	LOCHINVAR	0
10223	07/01/2007	LTN051G	LOCHINVAR	0
10224	11/05/2012	M45036FBN	BRADFORD-WHITE	0
10225	03/27/2012	MI5036FBN	BRADFORD-WHITE	0
10226	01/18/1990	21V506	RHEEM	0
10227	11/03/2006	LTN050G	LOCHINVAR	0
10228	08/26/2009	22DV50C	RHEEM	0
10229	09/18/1989	FSG50	AO SMITH	0
10230	07/30/1990	PRV50NODS	STATE	0
10231	01/29/1998	PGR50	AO SMITH	1
10232	04/13/1999	FSG50	AO SMITH	0
10233	08/04/2003	PRX50	STATE	2
10234	12/20/2009	41V50	RHEEM	1
10235	11/20/2012	MI5036FBN	BRADFORD-WHITE	0
10236	11/16/2005	LTN050G	LOCHINVAR	0
10237	06/29/1999	41XR50	RHEEM	0
10238	03/07/2011	22DV50F	RHEEM	0
10239	06/07/1988	FSG50	AO SMITH	0
10240	01/23/2007	LTN051G	LOCHINVAR	0
10241	11/29/2010	21VR50	RHEEM	0
10242	10/15/2010	41VR50	RHEEM	0
10243	11/25/2011	M45036FBN	BRADFORD-WHITE	2
10244	12/18/2002	PRX50	STATE	0
10245	10/16/2006	PR650	STATE	0
10246	02/21/2013	M45036FBN	BRADFORD-WHITE	0
10247	03/29/2006	LTN050G	LOCHINVAR	0
10248	12/27/2006	LTN050G	LOCHINVAR	0
10249	09/08/2011	MI5036FBN	BRADFORD-WHITE	1
10250	05/08/2009	LTN050GEF	LOCHINVAR	0
10251	12/29/2008	LTN050GEF	LOCHINVAR	0
10252	12/05/2001	FSG50	AO SMITH	0
10253	04/19/2006	G75125	RUUD/RHEEM	0
10254	09/29/2005	PR650	STATE	0
10255	07/07/2000	FSG40	AO SMITH	0
10256	12/10/2009	LTN050GEF	LOCHINVAR	0
10257	02/02/2001	PGR50	AO SMITH	0
10258	03/13/2001	G75125	RUUD/RHEEM	0
10259	11/06/2001	PGR50	AO SMITH	0
10260	03/01/2002	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10261	08/23/2005	LTN050G	LOCHINVAR	0
10262	11/17/2010	22DV50F	RHEEM	0
10263	10/26/2012	PH2DV50F	RUUD	0
10264	10/07/2011	PH2DV50F	RUUD	0
10265	01/16/2007	LTN050G	LOCHINVAR	0
10266	06/29/2010	LTN050GEF	LOCHINVAR	0
10267	11/10/2009	LTN050GEF	LOCHINVAR	0
10268	09/10/2012	MI5036FBN	BRADFORD-WHITE	0
10269	04/13/1988	FSG50	AO SMITH	0
10270	12/10/2007	LTN050GEF	LOCHINVAR	0
10271	08/29/2008	LTN050GEF	LOCHINVAR	0
10272	01/15/2001	PGR50	AO SMITH	0
10273	02/26/2007	LTN050G	LOCHINVAR	0
10274	08/31/1999	PGR50	AO SMITH	0
10275	10/03/2007	PR650	STATE	0
10276	12/18/2000	PGR50	AO SMITH	0
10277	02/11/2005	GVC50	A. O. SMITH	0
10278	02/02/2013	M45036FBN	BRADFORD-WHITE	0
10279	03/01/2012	MI5036FBN	BRADFORD-WHITE	3
10280	08/28/2006	PR650	STATE	1
10281	11/02/2007	LTN050GEF	LOCHINVAR	0
10282	08/17/2007	LTN050GEF	LOCHINVAR	1
10283	08/09/2005	LTN050G	LOCHINVAR	0
10284	10/11/1990	FSGL40	AO SMITH	0
10285	10/15/2009	LTN050G	LOCHINVAR	0
10286	09/21/2006	LTN050G	LOCHINVAR	0
10287	03/21/2007	XSN040	LOCHINVAR	0
10288	01/29/2013	PH2DV50F	RUUD	1
10289	06/21/2006	LTN051G	LOCHINVAR	3
10290	08/26/1997	41VR50	RHEEM	0
10291	03/30/1999	PGR50	AO SMITH	0
10292	07/03/2001	FSG50	AO SMITH	0
10293	07/01/2002	FSG50	AO SMITH	1
10294	02/20/2006	LSN041G	LOCHINVAR	0
10295	03/27/2003	FSG50	AO SMITH	0
10296	03/14/2005	P506	RUUD	0
10297	01/09/2007	41V50	RHEEM	0
10298	08/11/2009	LTN050GEF	LOCHINVAR	2
10299	01/27/2012	PH2DV50F	RUUD	0
10300	08/08/2011	MI5036FBN	BRADFORD-WHITE	1
10301	04/26/2003	PGR50	AO SMITH	0
10302	09/17/2004	PRX50	STATE	1
10303	08/10/1999	FSG50	AO SMITH	1
10304	05/04/2006	LTN050G	LOCHINVAR	0
10305	05/17/2010	22DV50F	RHEEM	0
10306	02/24/2012	D71	UNKNOWN	0
10307	08/10/2007	LTN050G	LOCHINVAR	0
10308	04/02/1998	FSG50	AO SMITH	0
10309	04/30/2008	22DV50C	RHEEM	0
10310	03/19/2012	MI5036FBN	BRADFORD-WHITE	0
10311	02/15/1990	PRV40NODS	STATE	0
10312	03/05/2008	LTN050GEF	LOCHINVAR	0
10313	04/09/2007	LTN050G	LOCHINVAR	0
10314	05/29/2001	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10315	09/15/2012	PH2DV50F	RUUD	0
10316	08/18/2004	XVR50	A. O. SMITH	0
10317	05/13/2002	PRX50	STATE	0
10318	02/15/1990	PRV40NODS	STATE	0
10319	12/18/2001	PGR50	AO SMITH	0
10320	05/18/2010	22DV50C	RHEEM	1
10321	08/10/2011	42VR50	RHEEM	1
10322	09/06/2006	LSN041G	LOCHINVAR	0
10323	05/02/1990	PRV50NODS	STATE	0
10324	07/13/1999	FGR50	AO SMITH	1
10325	01/14/2008	LTN050G	LOCHINVAR	0
10326	03/07/2009	LTN050GEF	LOCHINVAR	0
10327	02/14/2006	LTN050G	LOCHINVAR	0
10328	02/19/2001	41XR50	RHEEM	0
10329	06/17/2005	21V506	RHEEM	0
10330	12/08/1989	FSG50	AO SMITH	0
10331	08/12/2005	G91200	RUUD/RHEEM	0
10332	02/17/2005	GVC50	A. O. SMITH	0
10333	10/26/1998	FSG50	AO SMITH	0
10334	10/13/2011	M45036FBN	BRADFORD-WHITE	0
10335	05/24/2007	LTN050GEF	LOCHINVAR	0
10336	03/05/2009	LTN040GEF	LOCHINVAR	0
10337	02/14/2008	LTN051G	LOCHINVAR	0
10338	11/16/2001	FSG40	AO SMITH	0
10339	11/05/2010	21VR50	RHEEM	0
10340	04/19/2011	41VR50	RHEEM	0
10341	12/01/2009	LSN041G	LOCHINVAR	0
10342	06/23/2012	M440T6FBN	BRADFORD-WHITE	0
10343	01/05/2001	G75125	RUUD/RHEEM	1
10344	08/18/2008	LTN050GEF	LOCHINVAR	0
10345	09/01/2007	LTN050GEF	LOCHINVAR	0
10346	07/24/2012	M440T6FBN	BRADFORD-WHITE	0
10347	08/05/2010	LTN050GEF	LOCHINVAR	0
10348	04/09/2010	LTN050GEF	LOCHINVAR	0
10349	03/01/2013	MI5036FBN	BRADFORD-WHITE	1
10350	06/17/2008	LTN050GEF	LOCHINVAR	0
10351	12/20/2001	G91200	RUUD/RHEEM	2
10352	03/06/2005	PRX40	STATE	0
10353	01/30/2009	LTN040GEF	LOCHINVAR	0
10354	08/23/1989	FSG50	AO SMITH	0
10355	10/16/2009	LTN050GEF	LOCHINVAR	0
10356	09/07/2011	M45036FBN	BRADFORD-WHITE	0
10357	11/29/2012	MI5036FBN	BRADFORD-WHITE	1
10358	07/10/2004	PRX50	STATE	0
10359	07/28/2011	M45036FBN	BRADFORD-WHITE	2
10360	05/28/2002	PGR50	AO SMITH	0
10361	07/06/2006	PR650	STATE	1
10362	02/27/1989	FSG40	AO SMITH	0
10363	04/04/2002	PRX50	STATE	0
10364	01/31/2000	PGR50	AO SMITH	0
10365	11/11/2010	XVR50	A. O. SMITH	0
10366	10/13/2004	LTN050	LOCHINVAR	0
10367	08/09/2011	M45036FBN	BRADFORD-WHITE	0
10368	03/07/1989	P506	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10369	03/10/2006	PR650	STATE	0
10370	03/20/2006	21DV50	RHEEM	0
10371	04/11/2003	FSG50	AO SMITH	0
10372	09/16/2009	21V502	RHEEM	0
10373	11/08/2000	FSG50	AO SMITH	0
10374	06/06/2006	LTN050G	LOCHINVAR	0
10375	05/05/2011	41VR50	RHEEM	0
10376	03/19/2001	PRX50	STATE	0
10377	11/14/2005	PR650	STATE	0
10378	03/03/2012	PH2DV50F	RUUD	0
10379	07/05/2007	LTN050GEF	LOCHINVAR	0
10380	01/21/2004	FCV50	AO SMITH	1
10381	10/23/2008	LTN050GEF	LOCHINVAR	0
10382	02/11/2013	M45036FBN	BRADFORD-WHITE	0
10383	05/14/2003	21V506	RHEEM	0
10384	01/21/2013	M45036FBN	BRADFORD-WHITE	1
10385	02/19/2011	42VR50	RHEEM	0
10386	03/21/2011	21VR50	RHEEM	0
10387	05/25/1997	PRV50NODS	STATE	0
10388	05/12/2012	MI403S6FBN	BRADFORD-WHITE	0
10389	10/20/2011	PH250SF	RUUD	1
10390	11/13/1999	41XR50	RHEEM	0
10391	02/13/2007	LSN041G	LOCHINVAR	1
10392	08/16/2000	21V506	RHEEM	0
10393	07/28/2010	LTN050GEF	LOCHINVAR	0
10394	08/16/2001	PGR40	AO SMITH	0
10395	02/26/1990	PRX50	STATE	0
10396	08/28/2003	PRX50	STATE	0
10397	02/06/2007	LTN050G	LOCHINVAR	0
10398	09/04/2001	PGR50	AO SMITH	0
10399	07/17/2008	LTN050GEF	LOCHINVAR	1
10400	12/24/2012	MI50L6FBN	BRADFORD-WHITE	0
10401	10/12/2000	41XR50	RHEEM	0
10402	04/25/2005	LTN050G	LOCHINVAR	0
10403	06/09/2012	FSG50	AO SMITH	0
10404	02/23/2000	FSG40	AO SMITH	0
10405	11/19/2009	21VR50	RHEEM	1
10406	01/11/1990	P506	RUUD	0
10407	11/03/2000	PR650	STATE	0
10408	12/28/1994	PGR50	AO SMITH	0
10409	09/28/2011	M45036FBN	BRADFORD-WHITE	1
10410	01/02/1995	PRX50	STATE	0
10411	07/15/2008	LTN050GEF	LOCHINVAR	1
10412	10/31/2012	MI5036FBN	BRADFORD-WHITE	0
10413	07/09/2007	PR650X0DS	STATE	0
10414	05/30/2012	G91200	RUUD/RHEEM	0
10415	07/20/2012	M45036FBN	BRADFORD-WHITE	0
10416	02/04/2011	42VR50	RHEEM	0
10417	03/20/2002	PRX50	STATE	0
10418	04/07/2007	PR650	STATE	0
10419	02/18/1988	FSG50	AO SMITH	0
10420	08/24/2000	PHR50	RUUD	0
10421	10/05/2012	PH2DV50F	RUUD	0
10422	02/12/2008	G75125	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10423	10/26/2004	GCVL40	A. O. SMITH	0
10424	12/03/2010	42VR50	RHEEM	0
10425	06/12/2009	LTN050G	LOCHINVAR	0
10426	01/07/2011	42VR50	RHEEM	0
10427	10/31/2005	LTN050G	LOCHINVAR	0
10428	12/13/2012	MI5036FBN	BRADFORD-WHITE	0
10429	11/09/2011	FSG50	AO SMITH	0
10430	04/04/2012	PH2DV50F	RUUD	0
10431	11/01/2007	LTN050GEF	LOCHINVAR	0
10432	04/01/1988	21V502	RHEEM	0
10433	05/02/1988	PRX50	STATE	0
10434	06/11/2012	MI5036FBN	BRADFORD-WHITE	0
10435	08/18/2005	LTN050	LOCHINVAR	0
10436	10/18/2007	LTN050GEF	LOCHINVAR	0
10437	11/13/2009	PRX40	STATE	2
10438	01/14/2005	XVR50	A. O. SMITH	0
10439	02/25/2013	PH2DV50F	RUUD	0
10440	02/21/2003	41XR50	RHEEM	0
10441	07/29/1988	FSG50	AO SMITH	0
10442	09/02/2001	FSG50	AO SMITH	0
10443	10/27/2012	MI5036FBN	BRADFORD-WHITE	0
10444	01/10/1997	PRV50NODS	STATE	0
10445	05/21/2002	FSG50	AO SMITH	0
10446	05/16/1988	FSG50	AO SMITH	0
10447	06/26/2002	PGR50	AO SMITH	0
10448	09/17/2010	LSN041G	LOCHINVAR	1
10449	05/02/2005	PR640	STATE	0
10450	07/24/2012	M45036FBN	BRADFORD-WHITE	0
10451	01/14/2013	M45036FBN	BRADFORD-WHITE	0
10452	02/21/2008	LTN050	LOCHINVAR	0
10453	08/31/2003	FSG50	AO SMITH	0
10454	03/18/2007	XTN050	LOCHINVAR	0
10455	06/13/2003	PGR50	AO SMITH	0
10456	06/10/2008	LTN050GEF	LOCHINVAR	0
10457	04/09/2011	G91200	RUUD/RHEEM	1
10458	09/17/1990	FSG50	AO SMITH	0
10459	12/08/2006	LTN050G	LOCHINVAR	0
10460	05/30/2010	LTN050GEF	LOCHINVAR	0
10461	02/19/2009	G91200	RUUD/RHEEM	0
10462	09/03/2009	LTN050GEF	LOCHINVAR	0
10463	03/16/2011	42VR50	RHEEM	0
10464	01/21/2005	XTN050	LOCHINVAR	0
10465	11/01/2005	LTN050G	LOCHINVAR	0
10466	03/22/2003	PGR50	AO SMITH	0
10467	01/17/2011	22DV50F	RHEEM	0
10468	05/16/2000	FSG40	AO SMITH	0
10469	04/01/2002	FSG50	AO SMITH	0
10470	11/27/2012	MI5036FBN	BRADFORD-WHITE	0
10471	02/16/2007	LTN050G	LOCHINVAR	0
10472	10/19/1997	P502	RUUD	0
10473	11/30/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
10474	10/11/2000	FSG40	AO SMITH	0
10475	06/25/2012	PH2DV50F	RUUD	0
10476	01/10/2002	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10477	09/28/2001	FSGL40	AO SMITH	0
10478	01/29/1991	FSG50	AO SMITH	1
10479	09/23/2011	DS150S6FBN	BRADFORD-WHITE	0
10480	09/24/2007	LTN050GEF	LOCHINVAR	0
10481	05/23/2006	LTN050G	LOCHINVAR	0
10482	05/25/2005	PR650	STATE	0
10483	05/19/2001	41V50	RHEEM	0
10484	04/10/2002	PRX50	STATE	1
10485	04/14/1995	FGR50	AO SMITH	0
10486	01/04/2013	PH2DV50F	RUUD	0
10487	08/01/1990	SBF100199NES	STATE	0
10488	06/15/2008	FSG50	AO SMITH	0
10489	01/31/2012	M45036FBN	BRADFORD-WHITE	0
10490	01/05/2009	LTN050GEF	LOCHINVAR	0
10491	03/08/2005	FSG50	AO SMITH	0
10492	08/01/1990	SBF100199NES	STATE	0
10493	01/10/2002	41XR50	RHEEM	1
10494	11/01/2004	GVC50	A. O. SMITH	0
10495	10/05/2009	LTN050GEF	LOCHINVAR	0
10496	03/07/1989	P506	RUUD	0
10497	03/16/2009	22DV50F	RHEEM	0
10498	10/27/2008	LTN050GEF	LOCHINVAR	1
10499	02/16/2005	PRX50	STATE	0
10500	04/03/2010	22DV50C	RHEEM	0
10501	04/09/2008	FSG50	AO SMITH	0
10502	04/09/2004	GVC50	A. O. SMITH	1
10503	07/11/2011	22DV50F	RHEEM	0
10504	05/29/2011	21VR50	RHEEM	0
10505	03/05/2005	XVR50	A. O. SMITH	0
10506	06/25/2011	M45036FBN	BRADFORD-WHITE	0
10507	09/18/2002	PGR50	AO SMITH	0
10508	12/07/2012	PH2DV50F	RUUD	0
10509	08/17/1999	G75125	RUUD/RHEEM	0
10510	10/28/2004	PRX50	STATE	0
10511	10/27/2010	21VR40	RHEEM	0
10512	06/04/2004	PRX50	STATE	0
10513	09/26/2005	LTN050GEF	LOCHINVAR	0
10514	07/13/2001	PR650	STATE	0
10515	04/07/2003	41V50	RHEEM	0
10516	10/09/2009	LTN050GEF	LOCHINVAR	0
10517	07/28/2006	LTN050G	LOCHINVAR	0
10518	04/03/2012	MI50L6FBN	BRADFORD-WHITE	0
10519	04/14/2010	LTN050GEF	LOCHINVAR	1
10520	11/28/1989	FSG50	AO SMITH	0
10521	06/10/2008	22DV50F	RHEEM	0
10522	02/13/2007	LTN050G	LOCHINVAR	0
10523	12/31/2008	LTN050GEF	LOCHINVAR	0
10524	07/31/2001	PGR50	AO SMITH	0
10525	08/16/2011	M45036FBN	BRADFORD-WHITE	0
10526	10/25/2012	MI5036FBN	BRADFORD-WHITE	0
10527	12/07/2000	FSGL40	AO SMITH	0
10528	07/23/2011	MI5036FBN	BRADFORD-WHITE	0
10529	06/29/2011	MI5036FBN	BRADFORD-WHITE	4
10530	03/01/2006	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10531	12/08/2003	FCV50	AO SMITH	0
10532	06/29/2010	22DV50F	RHEEM	0
10533	03/23/1990	B71DUMMY	AMERICAN	0
10534	01/03/2000	41V50	RHEEM	0
10535	12/10/2011	G67114	RHEEM	0
10536	06/26/1990	FSG50	AO SMITH	0
10537	09/18/2009	LTN050GEF	LOCHINVAR	0
10538	03/23/2010	41V50	RHEEM	0
10539	09/10/2011	PH2DV50F	RUUD	0
10540	12/14/2005	LTN050G	LOCHINVAR	0
10541	06/23/2001	21V506	RHEEM	0
10542	07/24/2012	MI40T6FBN	BRADFORD-WHITE	3
10543	12/24/2001	PGR50	AO SMITH	0
10544	02/14/2005	GVC50	A. O. SMITH	0
10545	09/20/1989	FSG40	AO SMITH	0
10546	06/19/2008	LTN050G	LOCHINVAR	0
10547	03/02/2006	LTN050GEF	LOCHINVAR	0
10548	05/10/1999	PR650	STATE	0
10549	02/10/2001	PRX50	STATE	0
10550	10/24/1990	FSG50	AO SMITH	0
10551	11/11/2004	XVR50	A. O. SMITH	1
10552	12/01/2005	LTN050G	LOCHINVAR	0
10553	07/25/2002	FSG50	AO SMITH	0
10554	12/18/2000	PRX50	STATE	0
10555	10/11/2010	21VR50	RHEEM	0
10556	06/14/2012	PH2DV50F	RUUD	0
10557	06/26/2002	FSG50	AO SMITH	0
10558	11/10/2004	GVC50	A. O. SMITH	1
10559	06/30/2002	PGR50	AO SMITH	0
10560	11/20/2012	FSG50	AO SMITH	0
10561	10/25/2010	21VR50	RHEEM	0
10562	03/29/1990	P506	RUUD	0
10563	06/29/2010	LTN050G	LOCHINVAR	0
10564	09/29/2008	LTN050GEF	LOCHINVAR	1
10565	12/31/2008	LTN050GEF	LOCHINVAR	1
10566	07/07/2006	FSGL30	AO SMITH	0
10567	12/19/2012	MI5036FBN	BRADFORD-WHITE	1
10568	10/06/1987	FSG50	AO SMITH	0
10569	08/13/2010	LSN041G	LOCHINVAR	0
10570	06/30/2009	LTN050GEF	LOCHINVAR	0
10571	07/07/2006	PH30	RUUD	0
10572	08/10/2001	PGR50	AO SMITH	0
10573	08/25/2009	22DV50F	RHEEM	0
10574	03/14/2011	21VR50	RHEEM	0
10575	07/14/1997	FSG50	AO SMITH	0
10576	12/08/1987	FSG50	AO SMITH	0
10577	06/12/2007	LTN050GEF	LOCHINVAR	0
10578	02/23/2012	M45036FBN	BRADFORD-WHITE	0
10579	06/21/1988	P506	RUUD	1
10580	12/19/2009	FGR50	AO SMITH	0
10581	12/24/1999	PHR50	RUUD	0
10582	06/07/2003	FSG50	AO SMITH	0
10583	11/11/2006	LTN050G	LOCHINVAR	0
10584	05/11/2009	22DV50C	RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10585	08/13/2007	LTN050GEF	LOCHINVAR	0
10586	01/04/2006	LTN050G	LOCHINVAR	0
10587	05/05/2007	PR650	STATE	1
10588	01/13/1988	21V502	RHEEM	0
10589	01/16/2009	LTN050GEF	LOCHINVAR	2
10590	05/30/2010	21DV50	RHEEM	0
10591	10/20/2010	41VR50	RHEEM	0
10592	05/25/1988	FSG50	AO SMITH	0
10593	01/13/1988	FSG50	AO SMITH	1
10594	08/24/1988	FSG50	AO SMITH	0
10595	01/05/2006	PR650	STATE	0
10596	08/22/2000	FSG50	AO SMITH	0
10597	05/23/2011	LTN040G	LOCHINVAR	0
10598	10/10/2008	LTN050G	LOCHINVAR	0
10599	03/17/1988	FSG50	AO SMITH	0
10600	10/22/1987	FSG50	AO SMITH	0
10601	08/31/2005	GVC50	A. O. SMITH	0
10602	11/01/2006	LTN050GEF	LOCHINVAR	0
10603	06/30/2004	GVC40	A. O. SMITH	0
10604	06/07/2010	LSN041G	LOCHINVAR	0
10605	11/09/2007	LTN050GEF	LOCHINVAR	0
10606	01/20/2012	M45036FBN	BRADFORD-WHITE	0
10607	05/12/2003	PGR50	AO SMITH	0
10608	08/16/2012	M45036FBN	BRADFORD-WHITE	0
10609	01/13/2008	LSN041G	LOCHINVAR	0
10610	04/01/2003	PGR50	AO SMITH	0
10611	05/05/2012	M45036FBN	BRADFORD-WHITE	0
10612	08/06/2010	LTN050GEF	LOCHINVAR	0
10613	08/12/1996	21DV50	RHEEM	0
10614	06/04/2001	PGR50	AO SMITH	0
10615	04/13/2011	21VR50	RHEEM	0
10616	08/25/2005	PR640	STATE	0
10617	01/16/2013	G91200	RUUD/RHEEM	1
10618	11/22/2009	LTN050GEF	LOCHINVAR	0
10619	01/16/2013	G91200	RUUD/RHEEM	0
10620	03/26/2007	LTN050G	LOCHINVAR	0
10621	08/24/2012	PH2DV50F	RUUD	1
10622	04/06/2004	PVR50	AO SMITH	0
10623	10/28/2004	XVR50	A. O. SMITH	0
10624	02/14/2011	42VR50	RHEEM	0
10625	03/28/2011	42VR50	RHEEM	0
10626	06/06/1991	FSG50	AO SMITH	0
10627	04/03/2006	PR650	STATE	0
10628	02/07/2013	M45036FBN	BRADFORD-WHITE	0
10629	04/15/1999	FGR50	AO SMITH	0
10630	02/17/2009	LTN050GEF	LOCHINVAR	0
10631	07/19/2010	LTN050GEF	LOCHINVAR	0
10632	08/28/2009	LTN040G	LOCHINVAR	3
10633	12/28/2012	MI5036FBN	BRADFORD-WHITE	0
10634	07/25/2009	LTN050GEF	LOCHINVAR	0
10635	11/25/2008	LTN050GEF	LOCHINVAR	0
10636	12/20/2000	FSG40	AO SMITH	0
10637	06/23/2006	PR650	STATE	1
10638	11/23/2003	PVR40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10639	01/06/2010	LTN050G	LOCHINVAR	0
10640	05/01/2009	22DV50C	RHEEM	0
10641	01/18/2000	FSGL40	AO SMITH	0
10642	10/23/2007	LTN050	LOCHINVAR	0
10643	03/11/1991	PRV50NODS	STATE	0
10644	02/28/2009	LTN050GEF	LOCHINVAR	0
10645	11/20/2003	PRX50	STATE	0
10646	11/12/2003	FCV50	AO SMITH	1
10647	10/03/2005	LTN050	LOCHINVAR	1
10648	07/05/2005	LTN040	LOCHINVAR	0
10649	08/01/2008	LTN050GEF	LOCHINVAR	0
10650	01/18/2007	LTN050G	LOCHINVAR	0
10651	05/13/2002	PGR50	AO SMITH	0
10652	11/11/1991	21V502	RHEEM	0
10653	11/10/2006	PR650X0DS	STATE	0
10654	09/14/2012	41VR50	RHEEM	0
10655	01/26/2001	41XR50	RHEEM	1
10656	08/01/2000	41XR50	RHEEM	0
10657	11/08/2011	PH2DV50F	RUUD	0
10658	01/25/2006	PR650	STATE	0
10659	03/27/2004	PRX50	STATE	0
10660	11/18/2009	LTN050GEF	LOCHINVAR	0
10661	08/20/1990	P506	RUUD	0
10662	03/21/2008	22DV50F	RHEEM	0
10663	11/12/2009	LTN050GEF	LOCHINVAR	0
10664	03/21/2008	22DV50F	RHEEM	0
10665	01/08/2009	LTN040GEF	LOCHINVAR	1
10666	02/14/2008	PR650	STATE	0
10667	03/01/2011	42VR50	RHEEM	0
10668	09/26/2001	PGR50	AO SMITH	0
10669	06/25/2012	PH2DV50F	RUUD	0
10670	01/17/1990	FSG50	AO SMITH	0
10671	05/07/1990	FSG50	AO SMITH	0
10672	05/22/1990	PH30	RUUD	0
10673	12/01/1999	21V506	RHEEM	0
10674	01/23/2009	LTN040GEF	LOCHINVAR	1
10675	03/13/2008	LTN050GEF	LOCHINVAR	0
10676	12/12/2010	22DV50F	RHEEM	0
10677	12/14/2000	41XR50	RHEEM	0
10678	10/19/2005	LTN050	LOCHINVAR	0
10679	02/18/2011	21VR50	RHEEM	0
10680	09/08/2005	LTN050	LOCHINVAR	0
10681	01/08/1991	P506	RUUD	0
10682	11/30/1990	FSG50	AO SMITH	0
10683	04/19/2004	FCV50	AO SMITH	0
10684	11/05/2012	M2XR504T6FBN	UNKNOWN AT CONVERSION	0
10685	09/27/2010	21VR40	RHEEM	0
10686	06/21/2006	PR650	STATE	0
10687	09/22/1990	FSG50	AO SMITH	0
10688	12/10/1999	FSG50	AO SMITH	0
10689	08/07/2009	LTN050GEF	LOCHINVAR	0
10690	06/03/2009	LTN050GEF	LOCHINVAR	0
10691	07/06/2010	LTN051G	LOCHINVAR	0
10692	05/15/2001	FSG50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10693	03/16/2013	PH2DV50F	RUUD	0
10694	11/21/2012	M45036FBN	BRADFORD-WHITE	1
10695	10/11/1997	PGR50	AO SMITH	0
10696	11/03/1990	P506	RUUD	1
10697	02/05/2008	LTN050G	LOCHINVAR	1
10698	08/15/2012	MI50L6FBN	BRADFORD-WHITE	1
10699	08/22/1989	P506	RUUD	0
10700	02/13/2013	M45036FBN	BRADFORD-WHITE	1
10701	07/27/2010	LTN050	LOCHINVAR	0
10702	05/14/2005	LTN040	LOCHINVAR	0
10703	02/20/2008	21DV50	RHEEM	0
10704	07/28/2000	PHR50	RUUD	0
10705	01/19/2008	LTN050G	LOCHINVAR	0
10706	04/21/1994	FGR50	AO SMITH	0
10707	11/21/2001	FSG40	AO SMITH	0
10708	01/14/2013	M45036FBN	BRADFORD-WHITE	0
10709	02/10/2009	LTN050GEF	LOCHINVAR	2
10710	10/17/1989	FSG40	AO SMITH	0
10711	03/05/1997	FGR50	AO SMITH	0
10712	01/11/1989	FSG50	AO SMITH	0
10713	06/07/2010	LTN050GEF	LOCHINVAR	0
10714	07/07/2005	21V506	RHEEM	0
10715	11/04/1997	PGR50	AO SMITH	0
10716	12/14/1988	FSG50	AO SMITH	0
10717	01/06/2001	PRX50	STATE	1
10718	07/19/2012	21DV50	RHEEM	0
10719	03/13/2001	PRX50	STATE	0
10720	01/10/1989	FSG50	AO SMITH	0
10721	11/03/2012	M45036FBN	BRADFORD-WHITE	1
10722	06/02/2007	PR650X0DS	STATE	0
10723	05/26/2007	LTN050GEF	LOCHINVAR	0
10724	03/23/2002	FSG50	AO SMITH	0
10725	02/19/2003	41XR50	RHEEM	0
10726	04/13/2009	LTN050G	LOCHINVAR	0
10727	07/27/2009	22DV50F	RHEEM	0
10728	03/12/2003	FSG50	AO SMITH	0
10729	02/06/2013	MI5036FBN	BRADFORD-WHITE	0
10730	04/08/1995	FGR40	AO SMITH	0
10731	11/23/2010	21DV50	RHEEM	0
10732	06/02/2008	LTN050GEF	LOCHINVAR	1
10733	02/05/2003	FSG50	AO SMITH	1
10734	11/22/2000	PRV50NODS	STATE	0
10735	04/17/2006	LTN051G	LOCHINVAR	0
10736	03/03/2011	G91200	RUUD/RHEEM	3
10737	11/17/2005	LTN050G	LOCHINVAR	0
10738	11/28/2009	LTN050GEF	LOCHINVAR	0
10739	01/21/2009	22DV50F	RHEEM	1
10740	04/18/2006	LTN050G	LOCHINVAR	0
10741	02/11/2008	G91200	RUUD/RHEEM	0
10742	08/30/2005	GVC50	A. O. SMITH	0
10743	10/15/2007	LTN050GEF	LOCHINVAR	0
10744	01/19/2001	PGR50	AO SMITH	1
10745	09/01/2005	LTN050GEF	LOCHINVAR	0
10746	07/19/2000	41XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10747	07/14/2006	LTN050G	LOCHINVAR	0
10748	10/24/2009	LTN050GEF	LOCHINVAR	0
10749	03/30/2012	MI403S6FBN	BRADFORD-WHITE	1
10750	01/16/1999	FSG50	AO SMITH	0
10751	01/31/2002	FSG50	AO SMITH	0
10752	08/24/1999	FSG50	AO SMITH	1
10753	01/05/2001	PGR50	AO SMITH	0
10754	03/08/2011	22DV50F	RHEEM	1
10755	02/22/1988	PRX50	STATE	0
10756	07/22/2007	LTN050GEF	LOCHINVAR	1
10757	01/18/1988	FSG50	AO SMITH	0
10758	12/04/2009	LTN050GEF	LOCHINVAR	1
10759	07/19/2005	PR650	STATE	0
10760	04/26/2003	PRX50	STATE	0
10761	05/14/2009	LTN050GEF	LOCHINVAR	0
10762	07/26/2002	PRX50	STATE	0
10763	02/08/1988	FSG50	AO SMITH	0
10764	08/11/2003	PGR50	AO SMITH	0
10765	03/26/2008	LTN050GEF	LOCHINVAR	0
10766	01/13/1988	FSG50	AO SMITH	0
10767	06/12/2009	22DV50F	RHEEM	1
10768	07/19/1988	FSG40	AO SMITH	0
10769	11/10/2005	LTN050G	LOCHINVAR	2
10770	05/03/2012	PRX50	STATE	0
10771	03/30/1992	BW50	BRADFORD-WHITE	0
10772	03/26/2011	41VR40	RHEEM	0
10773	10/03/2008	LTN050GEF	LOCHINVAR	0
10774	03/20/2013	MI5036FBN	Bradford-White	0
10775	05/22/1992	FSG50	AO SMITH	0
10776	04/15/2009	22DV50C	RHEEM	0
10777	03/09/2004	XVR50	A. O. SMITH	0
10778	05/15/2012	M45036FBN	BRADFORD-WHITE	0
10779	10/28/2012	G82156	RUUD/RHEEM	3
10780	04/21/2008	22DV50C	RHEEM	0
10781	12/16/2009	LTN051G	LOCHINVAR	0
10782	05/07/2007	LTN050GEF	LOCHINVAR	0
10783	04/23/2012	M45036FBN	BRADFORD-WHITE	1
10784	02/12/2010	LTN050G	LOCHINVAR	0
10785	06/03/2011	42VR5040F	RHEEM	6
10786	02/01/2008	PR650X0DS	STATE	0
10787	10/25/2007	LTN050GEF	LOCHINVAR	0
10788	10/23/2006	LTN050G	LOCHINVAR	0
10789	12/20/1989	FSG50	AO SMITH	0
10790	08/14/2003	FSG50	AO SMITH	0
10791	01/08/2005	PRX50	STATE	0
10792	02/11/2002	PGR50	AO SMITH	0
10793	04/18/2003	FSG50	AO SMITH	0
10794	04/14/2006	FSG50	AO SMITH	0
10795	10/09/1995	FSG40	AO SMITH	0
10796	05/28/2003	FSG50	AO SMITH	0
10797	01/02/1991	FSG50	AO SMITH	0
10798	07/19/2000	PRX50	STATE	0
10799	12/31/2005	PR650	STATE	0
10800	12/13/2004	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10801	11/29/2012	G82156	RUUD/RHEEM	3
10802	09/26/2006	LTN040GEF	LOCHINVAR	0
10803	08/05/2008	LSN041G	LOCHINVAR	0
10804	02/27/2002	PGR50	AO SMITH	0
10805	02/16/2012	MI5036FBN	BRADFORD-WHITE	0
10806	01/25/2011	21VR50	RHEEM	1
10807	11/06/2003	21V506	RHEEM	0
10808	04/07/2008	LTN050GEF	LOCHINVAR	6
10809	04/29/2004	PRX50	STATE	0
10810	10/31/1998	FGR40	AO SMITH	0
10811	07/15/2010	LTN051G	LOCHINVAR	0
10812	02/16/2010	LTN050GEF	LOCHINVAR	0
10813	07/31/2004	PRX50	STATE	0
10814	01/07/2008	LTN050GEF	LOCHINVAR	0
10815	05/11/1990	PRV50NODS	STATE	0
10816	09/27/1998	FSG50	AO SMITH	0
10817	07/08/2010	LTN050G	LOCHINVAR	0
10818	05/07/2001	PGR50	AO SMITH	1
10819	02/19/1991	FSG50	AO SMITH	0
10820	07/02/1990	PRV50NODS	STATE	0
10821	12/23/2000	FSG50	AO SMITH	0
10822	04/03/2003	PGR50	AO SMITH	0
10823	05/30/2010	LTN050GEF	LOCHINVAR	0
10824	09/01/2010	21VR50	RHEEM	0
10825	06/16/2006	LSN041G	LOCHINVAR	0
10826	04/13/2012	M440T6FBN	BRADFORD-WHITE	0
10827	12/13/2006	LTN050G	LOCHINVAR	0
10828	02/20/2004	FCV50	AO SMITH	0
10829	01/11/2011	22DV50F	RHEEM	1
10830	04/02/2003	FSG50	AO SMITH	1
10831	05/16/2005	42VR506	RHEEM	0
10832	04/30/2008	LTN050GEF	LOCHINVAR	0
10833	07/06/2001	PRX50	STATE	1
10834	03/04/2002	FSG50	AO SMITH	0
10835	01/14/1998	FGR40	AO SMITH	0
10836	03/26/1991	FSG50	AO SMITH	0
10837	01/09/2007	LTN050G	LOCHINVAR	0
10838	10/22/2009	LTN051G	LOCHINVAR	0
10839	02/10/2011	42VR50	RHEEM	1
10840	10/21/2012	M45036FBN	BRADFORD-WHITE	0
10841	05/18/2004	XTN050	LOCHINVAR	0
10842	12/11/2006	LTN050G	LOCHINVAR	0
10843	06/04/2010	22DV50C	RHEEM	2
10844	09/04/1991	21V502	RHEEM	0
10845	01/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
10846	06/13/2006	LTN050G	LOCHINVAR	0
10847	03/04/2003	21DV50	RHEEM	0
10848	02/21/2008	G75125	RUUD/RHEEM	0
10849	07/14/2005	PR650	STATE	1
10850	06/10/2008	LTN050GEF	LOCHINVAR	2
10851	05/15/2009	P506	RUUD	0
10852	03/22/1991	B71DUMMY	AMERICAN	0
10853	06/13/1991	P506	RUUD	0
10854	01/28/2013	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10855	12/03/1999	41XR50	RHEEM	0
10856	04/28/2010	22DV50C	RHEEM	0
10857	12/07/2003	FCV50	AO SMITH	0
10858	02/13/2009	LTN050GEF	LOCHINVAR	0
10859	03/25/2008	LTN050GEF	LOCHINVAR	0
10860	01/03/1991	FSG50	AO SMITH	0
10861	09/23/2008	LTN050GEF	LOCHINVAR	0
10862	09/18/2002	21V506	RHEEM	0
10863	09/20/1991	FSG50	AO SMITH	0
10864	03/26/2001	PGR50	AO SMITH	0
10865	04/02/2007	LTN050G	LOCHINVAR	0
10866	09/15/2011	M45036FBN	BRADFORD-WHITE	1
10867	04/18/2001	PR650	STATE	0
10868	03/08/1999	FGR50	AO SMITH	0
10869	12/22/2004	PRX50	STATE	0
10870	11/27/1989	FSG50	AO SMITH	0
10871	01/31/2009	41V40	RHEEM	0
10872	08/02/2004	PRX50	STATE	0
10873	07/12/2000	21V402S	RHEEM	0
10874	11/27/1989	FSG50	AO SMITH	0
10875	03/26/2009	LTN050GEF	LOCHINVAR	1
10876	05/13/2010	LTN050G	LOCHINVAR	0
10877	02/01/2010	LTN050GEF	LOCHINVAR	0
10878	04/14/1989	FSG50	AO SMITH	0
10879	09/03/2003	H72DUMMY	AO SMITH	0
10880	09/28/2012	MI5036FBN	BRADFORD-WHITE	0
10881	07/26/2011	42VR50	RHEEM	0
10882	05/10/2011	G91200	RUUD/RHEEM	1
10883	10/22/2010	41VR50	RHEEM	0
10884	09/28/1989	FSG50	AO SMITH	0
10885	03/23/2005	GVC50	A. O. SMITH	0
10886	06/25/2001	PGR50	AO SMITH	1
10887	09/27/2005	LTN050G	LOCHINVAR	0
10888	12/10/2004	PRX50	STATE	0
10889	04/21/1989	PRV50NODS	STATE	0
10890	06/23/2008	PGR50	AO SMITH	0
10891	06/02/2011	42V5065F	RHEEM	0
10892	11/21/2009	LTN050GEF	LOCHINVAR	0
10893	05/06/2009	LTN050G	LOCHINVAR	1
10894	01/07/2006	LTN050GEF	LOCHINVAR	0
10895	02/10/2012	M45036FBN	BRADFORD-WHITE	0
10896	06/28/1989	FSG50	AO SMITH	0
10897	12/07/2010	42VR50	RHEEM	0
10898	12/11/2009	LTN050GEF	LOCHINVAR	0
10899	02/04/2009	PH199119	PHOENIX	0
10900	01/23/2001	FSG50	AO SMITH	0
10901	10/12/1989	B71DUMMY	AMERICAN	0
10902	02/04/2009	PH199119	PHOENIX	1
10903	10/03/2012	MI5036FBN	BRADFORD-WHITE	0
10904	03/23/2011	42V5065F	RHEEM	0
10905	05/03/2005	PRX50	STATE	0
10906	08/25/2003	FCV40	AO SMITH	0
10907	06/09/2006	LTN050G	LOCHINVAR	1
10908	06/12/2010	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10909	08/11/1989	FSG50	AO SMITH	0
10910	09/17/2003	41XR50	RHEEM	0
10911	05/13/1999	FSG40	AO SMITH	0
10912	06/26/2008	LTN050GEF	LOCHINVAR	0
10913	11/28/2000	FSG50	AO SMITH	0
10914	01/04/2006	LTN050G	LOCHINVAR	0
10915	06/16/2008	LTN050GEF	LOCHINVAR	0
10916	05/10/2001	PGR50	AO SMITH	0
10917	09/08/2001	FSG50	AO SMITH	0
10918	05/14/2009	LTN050GEF	LOCHINVAR	0
10919	06/27/2007	LTN051G	LOCHINVAR	0
10920	09/02/2010	LTN050	LOCHINVAR	0
10921	05/11/2004	PRX50	STATE	0
10922	04/12/2007	LTN051G	LOCHINVAR	0
10923	03/09/2010	LTN050GEF	LOCHINVAR	0
10924	01/17/2008	LTN050G	LOCHINVAR	1
10925	06/26/2012	M45036FBN	BRADFORD-WHITE	0
10926	07/29/2010	21DV50	RHEEM	1
10927	05/07/2008	LTN050GEF	LOCHINVAR	0
10928	05/17/2004	GVC50	A. O. SMITH	1
10929	08/07/2006	LTN050G	LOCHINVAR	0
10930	06/09/2007	LTN050GEF	LOCHINVAR	0
10931	05/22/2004	G91200	RUUD/RHEEM	0
10932	11/13/1999	41XR50	RHEEM	0
10933	05/19/2003	PGR50	AO SMITH	0
10934	04/02/2006	21DV50	RHEEM	0
10935	10/09/2009	22DV50C	RHEEM	4
10936	06/29/2005	PR650	STATE	0
10937	04/03/2007	LTN050G	LOCHINVAR	0
10938	06/01/2007	G75125	RUUD/RHEEM	1
10939	12/22/2010	42VR50	RHEEM	0
10940	05/23/2012	MI5036FBN	BRADFORD-WHITE	0
10941	04/19/2005	GVC50	A. O. SMITH	0
10942	06/01/2001	PGR50	AO SMITH	0
10943	12/01/2009	22DV50F	RHEEM	1
10944	12/18/2012	MI5036FBN	BRADFORD-WHITE	0
10945	10/12/2010	21VR50	RHEEM	0
10946	07/23/2003	PGR50	AO SMITH	0
10947	04/03/2007	LTN050G	LOCHINVAR	0
10948	11/20/2001	PGR50	AO SMITH	0
10949	09/13/2011	MI5036FBN	BRADFORD-WHITE	2
10950	02/24/2012	PH2DV50F	RUUD	0
10951	10/04/2009	22DV50C	RHEEM	0
10952	06/15/1998	FSG50	AO SMITH	0
10953	11/08/2010	FGR50	AO SMITH	0
10954	10/18/2004	GVC50	A. O. SMITH	0
10955	03/07/2002	FSG50	AO SMITH	0
10956	09/07/1990	FSG50	AO SMITH	0
10957	01/24/2009	LTN050GEF	LOCHINVAR	0
10958	03/04/2013	M45036FBN	BRADFORD-WHITE	0
10959	04/27/2004	21V506	RHEEM	0
10960	10/13/2005	LTN050	LOCHINVAR	0
10961	04/12/2010	22DV50F	RHEEM	0
10962	09/06/2011	DS150S6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
10963	12/29/2000	FSG50	AO SMITH	0
10964	09/14/2004	21DV50	RHEEM	0
10965	07/23/2008	22DV50C	RHEEM	1
10966	05/04/1990	FSG50	AO SMITH	0
10967	06/25/2007	LTN050G	LOCHINVAR	1
10968	03/07/1996	PGR50	AO SMITH	0
10969	07/16/2008	LTN050GEF	LOCHINVAR	0
10970	11/16/1990	21V506	RHEEM	0
10971	03/08/2000	FSG50	AO SMITH	1
10972	09/22/1989	FSG50	AO SMITH	0
10973	01/27/2007	PR650X0DS	STATE	0
10974	07/27/2001	PGR50	AO SMITH	0
10975	04/22/2005	PR650	STATE	0
10976	07/13/2012	PH2DV50F	RUUD	0
10977	01/12/1990	FSG40	AO SMITH	0
10978	01/31/2004	PRX50	STATE	0
10979	09/18/2005	LTN050G	LOCHINVAR	0
10980	11/08/1990	FSG50	AO SMITH	0
10981	12/13/2001	PRX50	STATE	0
10982	03/13/2006	PR650X0DS	STATE	0
10983	08/17/2009	G91200	RUUD/RHEEM	2
10984	03/09/2012	MI5036FBN	BRADFORD-WHITE	0
10985	08/27/2005	LTN050GEF	LOCHINVAR	0
10986	07/16/2006	PR650	STATE	0
10987	10/19/2012	G91200	RUUD/RHEEM	0
10988	08/16/2010	41VR50	RHEEM	0
10989	06/02/2006	CPN13585FS	LOCHINVAR	0
10990	05/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	1
10991	03/14/2008	LTN050	LOCHINVAR	0
10992	11/16/2010	21VR50	RHEEM	0
10993	04/03/2012	PH2DV50F	RUUD	0
10994	01/11/2003	PGR50	AO SMITH	0
10995	06/03/2005	LTN040	LOCHINVAR	0
10996	07/23/2009	LTN050GEF	LOCHINVAR	1
10997	06/16/2009	LTN050GEF	LOCHINVAR	0
10998	05/04/1989	21V502	RHEEM	0
10999	12/26/2001	PGR50	AO SMITH	0
11000	11/01/2011	MI5036FBN	BRADFORD-WHITE	0
11001	02/08/1989	FSG50	AO SMITH	0
11002	06/28/2010	LTN050GEF	LOCHINVAR	0
11003	07/14/2010	LTN050GEF	LOCHINVAR	0
11004	11/16/2004	GVC50	A. O. SMITH	0
11005	02/10/1999	21V506	RHEEM	0
11006	06/30/1989	FSG40	AO SMITH	0
11007	09/18/2012	PH2DV50F	RUUD	0
11008	08/31/2005	GVC50	A. O. SMITH	0
11009	12/24/2007	LTN050GEF	LOCHINVAR	0
11010	10/18/2004	GVC50	A. O. SMITH	0
11011	05/10/2005	XSN0401GEF	LOCHINVAR	0
11012	05/10/2005	XSN0401GEF	LOCHINVAR	0
11013	03/23/1998	FGR50	AO SMITH	0
11014	11/11/2010	42VR50	RHEEM	0
11015	01/07/2002	FSGL40	AO SMITH	0
11016	09/29/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11017	09/14/2010	42VR50	RHEEM	2
11018	04/03/2008	22DV50C	RHEEM	0
11019	12/01/2011	MI5036FBN	BRADFORD-WHITE	0
11020	02/15/2012	M45036FBN	BRADFORD-WHITE	0
11021	08/24/2007	PR650	STATE	0
11022	11/24/2004	GVC50	A. O. SMITH	1
11023	10/28/2012	PH2DV50F	RUUD	1
11024	08/20/2001	FSG50	AO SMITH	0
11025	09/16/2010	LTN050GEF	LOCHINVAR	0
11026	08/17/2009	LTN050GEF	LOCHINVAR	0
11027	06/16/2011	M45036FBN	BRADFORD-WHITE	0
11028	02/24/2004	B71DUMMY	UNKNOWN AT CONVERSION	0
11029	03/10/2009	22DV50C	RHEEM	1
11030	12/22/2002	21DV50	RHEEM	0
11031	06/22/2002	PRX50	STATE	0
11032	10/07/2004	PRX50	STATE	0
11033	08/30/2006	LTN050G	LOCHINVAR	0
11034	12/01/2008	LSN041G	LOCHINVAR	0
11035	08/21/2008	22DV50F	RHEEM	0
11036	12/31/2007	PR650X0DS	STATE	0
11037	02/03/2006	F72DUMMY	AO SMITH	0
11038	06/26/2007	EPN150085	LOCHINVAR	0
11039	05/05/1997	FSG50	AO SMITH	0
11040	05/22/2012	MI5036FBN	BRADFORD-WHITE	0
11041	09/08/2012	M45036FBN	BRADFORD-WHITE	0
11042	06/12/2012	M440T6FBN	BRADFORD-WHITE	4
11043	08/25/2012	MI40T6FBN	BRADFORD-WHITE	1
11044	06/09/2000	41XR50	RHEEM	0
11045	09/06/2007	LTN050GEF	LOCHINVAR	0
11046	10/15/1991	PRV50NODS	STATE	0
11047	12/02/2010	42VR50	RHEEM	0
11048	12/01/2012	PH2DV50F	RUUD	0
11049	08/25/2012	MI40T6FBN	BRADFORD-WHITE	0
11050	03/16/2006	21V506	RHEEM	0
11051	01/04/2003	PRX50	STATE	0
11052	12/01/2009	LTN040GEF	LOCHINVAR	0
11053	02/15/2012	DS150S6FBN	BRADFORD-WHITE	0
11054	07/03/2000	41VR40	RHEEM	0
11055	03/12/2012	PH2DV50F	RUUD	0
11056	06/18/2012	PH2DV50F	RUUD	0
11057	03/21/2002	FSG50	AO SMITH	0
11058	07/03/2008	LTN050G	LOCHINVAR	0
11059	03/29/1991	B71DUMMY	AMERICAN	0
11060	03/05/1999	PR650	STATE	0
11061	03/12/2002	FSG50	AO SMITH	0
11062	06/16/2008	22DV5038	RHEEM	0
11063	02/12/1992	21V502	RHEEM	0
11064	03/31/2000	FSG50	AO SMITH	0
11065	03/06/2002	FSG50	AO SMITH	0
11066	08/16/2011	FGC40	AO SMITH	0
11067	09/11/1991	FSG50	AO SMITH	0
11068	01/23/2013	M45036FBN	BRADFORD-WHITE	0
11069	09/29/2003	FSG50	AO SMITH	0
11070	11/26/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11071	06/28/2011	M45036FBN	BRADFORD-WHITE	0
11072	08/08/2008	LTN051G	LOCHINVAR	0
11073	02/26/2011	21DV50	RHEEM	0
11074	10/26/2004	GVC50	A. O. SMITH	0
11075	10/10/2007	LTN050G	LOCHINVAR	1
11076	12/14/1989	FSG50	AO SMITH	0
11077	06/26/2009	22DV50F	RHEEM	0
11078	06/26/2009	LTN050GEF	LOCHINVAR	0
11079	01/29/2001	FGR50	AO SMITH	0
11080	05/19/2012	MI403S6FBN	BRADFORD-WHITE	2
11081	01/30/2002	FSG50	AO SMITH	0
11082	03/10/2009	LTN050GEF	LOCHINVAR	0
11083	10/13/2000	FSG50	AO SMITH	0
11084	02/05/2008	LTN040G	LOCHINVAR	1
11085	02/16/2005	GDVS50	AOSMITH	1
11086	02/07/1990	PRV50NODS	STATE	0
11087	06/23/2008	22DV50C	RHEEM	1
11088	09/10/2001	FSG40	AO SMITH	0
11089	05/17/2001	PGR50	AO SMITH	0
11090	02/18/2003	PRX50	STATE	1
11091	02/26/2011	42VR50	RHEEM	0
11092	12/06/2004	GVC50	A. O. SMITH	0
11093	01/26/2008	G91200	RUUD/RHEEM	0
11094	11/07/1991	P502	RUUD	0
11095	12/29/2006	LTN050G	LOCHINVAR	1
11096	10/06/2004	LTN050	LOCHINVAR	0
11097	03/01/2001	41V50	RHEEM	0
11098	12/14/2007	LTN050GEF	LOCHINVAR	0
11099	09/17/2011	M45036FBN	BRADFORD-WHITE	0
11100	03/24/2011	42VR50	RHEEM	0
11101	01/29/2013	MI5036FBN	BRADFORD-WHITE	0
11102	12/02/2008	22DV50C	RHEEM	0
11103	10/26/1996	FGR50	AO SMITH	0
11104	07/03/1990	RF92200	RUUD	0
11105	07/15/2008	22DV50C	RHEEM	0
11106	05/06/2004	GVC50	A. O. SMITH	0
11107	07/31/2007	LTN050GEF	LOCHINVAR	1
11108	02/07/2000	BTR154	AO SMITH	0
11109	01/30/2004	41VR50	RHEEM	1
11110	03/12/1997	21V407	RHEEM	0
11111	02/10/2009	LTN050GEF	LOCHINVAR	0
11112	02/05/2009	LTN050GEF	LOCHINVAR	0
11113	06/24/2002	FSG50	AO SMITH	0
11114	05/24/2011	41VR50	RHEEM	0
11115	12/05/2008	LTN050GEF	LOCHINVAR	0
11116	06/12/2003	41VR40	RHEEM	0
11117	06/30/2008	LTN050GEF	LOCHINVAR	0
11118	02/23/2001	PGR50	AO SMITH	0
11119	03/04/2011	21VR50	RHEEM	0
11120	04/24/2006	LTN050G	LOCHINVAR	0
11121	05/21/2009	LTN050GEF	LOCHINVAR	0
11122	09/05/2003	PRX50	STATE	0
11123	10/16/1998	FSG50	AO SMITH	0
11124	11/07/2001	41V50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11125	12/10/2008	22DV50C	RHEEM	0
11126	12/19/2003	41V50S	RHEEM	1
11127	01/28/2003	PGR50	AO SMITH	0
11128	01/24/1991	BTR199	AO SMITH	0
11129	11/12/2008	LTN051G	LOCHINVAR	0
11130	01/22/2003	FSG50	AO SMITH	0
11131	09/18/2008	LTN050GEF	LOCHINVAR	0
11132	02/26/2010	22DV50F	RHEEM	0
11133	08/31/2007	PR650X0DS	STATE	4
11134	02/20/2010	LTN050	LOCHINVAR	0
11135	10/30/2007	LTN040	LOCHINVAR	0
11136	03/17/1999	41VR50	RHEEM	0
11137	01/25/2011	FSG40	AO SMITH	0
11138	03/16/1990	FSG50	AO SMITH	0
11139	02/26/2011	G75125	RUUD/RHEEM	0
11140	01/16/1990	PRX50	STATE	0
11141	11/27/2007	LTN050G	LOCHINVAR	0
11142	02/13/2008	LTN050GEF	LOCHINVAR	1
11143	07/25/2009	22DV50C	RHEEM	0
11144	12/07/2004	XVR50	A. O. SMITH	0
11145	05/22/2006	LTN050G	LOCHINVAR	2
11146	07/17/1990	FSG50	AO SMITH	0
11147	02/20/2007	LTN050GEF	LOCHINVAR	0
11148	09/05/1990	PRX50	STATE	0
11149	02/06/2003	H72DUMMY	AO SMITH	0
11150	08/08/2005	PR650	STATE	0
11151	04/18/2007	PR650X0DS	STATE	0
11152	12/04/1989	21V506	RHEEM	0
11153	06/11/1990	FSG50	AO SMITH	0
11154	03/06/1992	P506	RUUD	0
11155	08/23/2011	MI5036FBN	BRADFORD-WHITE	0
11156	01/08/2005	GVC50	A. O. SMITH	0
11157	08/23/2004	41V50S	RHEEM	0
11158	09/04/2009	LTN050GEF	LOCHINVAR	0
11159	12/02/2005	LTN050G	LOCHINVAR	0
11160	12/02/2008	22DV50C	RHEEM	0
11161	11/10/2008	22DV50C	RHEEM	1
11162	05/26/2004	GVC50	A. O. SMITH	0
11163	09/10/2009	22DV50F	RHEEM	1
11164	08/28/2008	LSN041G	LOCHINVAR	0
11165	05/12/1989	FSG50	AO SMITH	0
11166	07/02/1989	FSG40	AO SMITH	0
11167	07/18/2001	FSG50	AO SMITH	0
11168	08/07/2007	LTN050G	LOCHINVAR	0
11169	03/02/2012	PH250SF	RUUD	0
11170	08/04/2004	XVR50	A. O. SMITH	0
11171	10/04/2005	LTN040G	LOCHINVAR	1
11172	12/27/1997	PGR50	AO SMITH	1
11173	10/30/2007	LTN050GEF	LOCHINVAR	0
11174	04/16/2006	LSN041	LOCHINVAR	0
11175	07/19/2008	LTN050G	LOCHINVAR	0
11176	06/17/1994	FGR50	AO SMITH	0
11177	11/14/2008	22DV50C	RHEEM	0
11178	12/06/1996	H72DUMMY	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11179	12/06/2003	21V506	RHEEM	0
11180	08/10/2007	LTN050G	LOCHINVAR	0
11181	12/28/1989	PRV50NODS	STATE	0
11182	12/28/2012	MI50L6FBN	BRADFORD-WHITE	0
11183	02/05/2008	LTN050GEF	LOCHINVAR	0
11184	04/11/1989	FSG50	AO SMITH	0
11185	04/04/2011	22DV50F	RHEEM	0
11186	01/12/2002	41XR50	RHEEM	0
11187	07/25/2009	LTN050GEF	LOCHINVAR	0
11188	01/24/2013	MI5036FBN	BRADFORD-WHITE	0
11189	07/08/1997	PGR50	AO SMITH	0
11190	01/21/2009	LTN050GEF	LOCHINVAR	0
11191	12/29/1998	21VR50	RHEEM	0
11192	08/15/2011	MI403S6FBN	BRADFORD-WHITE	0
11193	03/24/2001	PRX50	STATE	0
11194	04/30/2009	LTN050GEF	LOCHINVAR	0
11195	11/30/2005	LTN050GEF	LOCHINVAR	1
11196	09/19/2005	LTN050G	LOCHINVAR	0
11197	04/09/2011	21VR50	RHEEM	0
11198	05/29/2002	PGR50	AO SMITH	0
11199	01/27/2004	FCV50	AO SMITH	1
11200	08/01/2011	M45036FBN	BRADFORD-WHITE	0
11201	09/14/2010	42V5065F	RHEEM	1
11202	02/19/2008	LTN050GEF	LOCHINVAR	0
11203	12/31/2012	M45036FBN	BRADFORD-WHITE	0
11204	07/10/2012	M45036FBN	BRADFORD-WHITE	0
11205	05/06/1999	PRV50NODS	STATE	0
11206	03/02/2003	PGR50	AO SMITH	0
11207	05/07/2012	PH2DV50F	RUUD	0
11208	03/16/1999	41VR50	RHEEM	0
11209	05/10/2007	LTN050G	LOCHINVAR	0
11210	08/01/2012	FSG50	AO SMITH	0
11211	05/20/2010	21DV50	RHEEM	0
11212	08/22/2011	M45036FBN	BRADFORD-WHITE	0
11213	03/09/2011	22DV50F	RHEEM	0
11214	03/21/1994	PRX50	STATE	0
11215	06/06/2012	MI5036FBN	BRADFORD-WHITE	0
11216	08/09/1989	FSG50	AO SMITH	0
11217	03/05/2000	FSGL40	AO SMITH	0
11218	01/04/2010	22DV50F	RHEEM	0
11219	02/09/2007	LTN051G	LOCHINVAR	1
11220	07/08/2007	LTN050GEF	LOCHINVAR	0
11221	05/23/2002	21DV50	RHEEM	0
11222	03/25/2010	PRX50	STATE	0
11223	03/13/2006	LSN041G	LOCHINVAR	0
11224	11/20/1999	FSGL40	AO SMITH	0
11225	07/26/2010	LTN051G	LOCHINVAR	0
11226	12/19/1991	P506	RUUD	0
11227	02/28/2012	MI5036FBN	BRADFORD-WHITE	0
11228	06/10/1999	FGR50	AO SMITH	0
11229	06/18/1991	FSG50	AO SMITH	0
11230	07/12/2005	LTN050	LOCHINVAR	0
11231	09/15/2008	22DV50F	RHEEM	0
11232	10/16/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11233	12/14/2005	PR640	STATE	0
11234	10/31/1991	P506	RUUD	0
11235	04/02/2004	PR650	STATE	0
11236	03/14/2001	FSG40	AO SMITH	0
11237	02/11/1991	P506	RUUD	0
11238	10/23/2009	LTN051G	LOCHINVAR	0
11239	02/22/2007	LTN050G	LOCHINVAR	2
11240	11/25/1991	21V502	RHEEM	0
11241	09/07/2011	PH2DV50F	RUUD	0
11242	12/09/2008	41V50S	RHEEM	0
11243	07/25/2002	PGR50	AO SMITH	0
11244	11/17/2007	LTN050GEF	LOCHINVAR	0
11245	12/07/2011	M45036FBN	BRADFORD-WHITE	3
11246	02/02/2013	M45036FBN	BRADFORD-WHITE	0
11247	05/26/2003	FSG50	AO SMITH	0
11248	10/06/2012	PH2DV50F	RUUD	0
11249	04/21/2007	PR650	STATE	0
11250	02/19/2011	22V40SF	RHEEM	0
11251	11/16/2010	42VR50	RHEEM	0
11252	04/10/2008	22DV50C	RHEEM	0
11253	06/27/1991	21V502	RHEEM	0
11254	10/04/1991	FSG50	AO SMITH	0
11255	10/22/2003	41V50	RHEEM	0
11256	09/13/2000	PRV50NODS	STATE	0
11257	01/24/1992	PRV50NODS	STATE	0
11258	02/29/2012	M45036FBN	BRADFORD-WHITE	0
11259	09/05/2001	FSG40	AO SMITH	0
11260	03/01/2006	LTN050G	LOCHINVAR	4
11261	07/18/2011	MI5036FBN	BRADFORD-WHITE	1
11262	06/21/2012	PH2DV50F	RUUD	0
11263	05/02/2008	LTN050GEF	LOCHINVAR	0
11264	08/17/2010	21V502	RHEEM	0
11265	10/09/2001	FSG50	AO SMITH	0
11266	03/22/2001	FSG30	AO SMITH	0
11267	02/24/2005	GVC50	A. O. SMITH	0
11268	04/29/2001	41XR50	RHEEM	0
11269	05/17/1991	P506	RUUD	0
11270	08/10/2004	41V50	RHEEM	0
11271	08/08/2012	MI5036FBN	BRADFORD-WHITE	1
11272	02/07/2012	MI5036FBN	BRADFORD-WHITE	0
11273	12/30/2008	P502	RUUD	0
11274	07/02/2002	PRX50	STATE	0
11275	08/02/2001	PGR50	AO SMITH	1
11276	01/22/1991	P506	RUUD	0
11277	02/09/2007	TNR200100	LOCHINVAR	0
11278	04/06/1990	FSG50	AO SMITH	0
11279	03/07/2013	MI5036FBN	BRADFORD-WHITE	0
11280	06/02/2012	M45036FBN	BRADFORD-WHITE	0
11281	02/02/2005	GVC50	A. O. SMITH	1
11282	02/09/2007	TNR200100	LOCHINVAR	0
11283	03/23/2007	LTN050G	LOCHINVAR	0
11284	11/23/1999	FSG50	AO SMITH	1
11285	11/15/2002	G82156	RUUD/RHEEM	2
11286	01/18/2013	G82156	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11287	08/24/2008	22DV50F	RHEEM	0
11288	03/13/2012	MI5036FBN	BRADFORD-WHITE	0
11289	04/03/2012	M45036FBN	BRADFORD-WHITE	0
11290	04/14/2006	21DV50	RHEEM	2
11291	01/18/2013	G82156	RUUD/RHEEM	1
11292	08/08/1999	FGR50	AO SMITH	0
11293	08/01/2011	MI40T6FBN	BRADFORD-WHITE	0
11294	08/13/2012	MI50L6FBN	BRADFORD-WHITE	0
11295	12/03/2008	LTN050GEF	LOCHINVAR	0
11296	09/21/1990	FSG50	AO SMITH	0
11297	01/23/2006	LTN050G	LOCHINVAR	0
11298	01/24/2000	FSG50	AO SMITH	0
11299	02/27/2008	LTN050GEF	LOCHINVAR	0
11300	03/04/2007	LTN050G	LOCHINVAR	0
11301	01/15/1991	P506	RUUD	0
11302	01/03/2003	PGR50	AO SMITH	0
11303	05/23/2008	LTN050GEF	LOCHINVAR	1
11304	09/25/2006	PRV50NODS	STATE	0
11305	01/16/2004	XTN050	LOCHINVAR	0
11306	09/18/2002	PGR50	AO SMITH	0
11307	10/22/2002	FSG50	AO SMITH	0
11308	07/27/2008	LTN050GEF	LOCHINVAR	0
11309	03/02/2010	LTN050GEF	LOCHINVAR	0
11310	10/03/2005	LTN051G	LOCHINVAR	0
11311	03/23/1990	P506	RUUD	0
11312	09/22/2005	LTN050G	LOCHINVAR	0
11313	06/29/2011	21V506	RHEEM	2
11314	06/05/1990	PRV50NODS	STATE	0
11315	02/03/2009	LTN050GEF	LOCHINVAR	0
11316	05/26/2000	PR650	STATE	0
11317	08/28/2008	PRV50NODS	STATE	0
11318	10/06/2000	FSGL40	AO SMITH	0
11319	11/10/2012	M440T6FBN	BRADFORD-WHITE	0
11320	06/06/2003	PGR50	AO SMITH	0
11321	08/28/2008	22DV50C	RHEEM	0
11322	06/08/2005	ETN076	LOCHINVAR	0
11323	07/28/2006	FSG50	AO SMITH	0
11324	10/13/2012	G75125	RUUD/RHEEM	0
11325	06/08/2009	LTN050GEF	LOCHINVAR	0
11326	02/16/2001	PRX50	STATE	0
11327	05/22/2007	LTN050G	LOCHINVAR	0
11328	06/03/2010	22DV50C	RHEEM	2
11329	08/10/2009	G76200	RUUD/RHEEM	1
11330	10/26/2009	LTN040GEF	LOCHINVAR	0
11331	03/02/1993	21V502	RHEEM	0
11332	03/21/2005	42XR50	RHEEM	0
11333	12/27/2002	PGR50	AO SMITH	0
11334	06/02/2012	MI5036FBN	BRADFORD-WHITE	0
11335	02/09/2012	PH2DV50F	RUUD	0
11336	07/16/2007	LTN050G	LOCHINVAR	0
11337	03/20/2009	LTN050GEF	LOCHINVAR	1
11338	11/02/2007	LTN050GEF	LOCHINVAR	0
11339	06/10/2006	LTN050G	LOCHINVAR	1
11340	11/27/2007	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11341	11/16/2011	M45036FBN	BRADFORD-WHITE	3
11342	02/24/2002	PGR50	AO SMITH	0
11343	09/29/1992	FSG50	AO SMITH	0
11344	11/11/2010	21V502	RHEEM	0
11345	08/21/2004	XVR40	A. O. SMITH	2
11346	10/06/2005	LTN050G	LOCHINVAR	0
11347	06/20/2012	M440T6FBN	BRADFORD-WHITE	0
11348	12/04/1992	21V506	RHEEM	0
11349	10/04/2011	MI5036FBN	BRADFORD-WHITE	1
11350	04/11/2011	41VR50	RHEEM	0
11351	09/08/1992	PRV50NORT	STATE	0
11352	07/08/2006	LTN050G	LOCHINVAR	0
11353	02/07/2005	XVR50	A. O. SMITH	1
11354	06/10/1993	21V502	RHEEM	0
11355	11/06/2011	PH250SF	RUUD	0
11356	04/04/2002	FSG50	AO SMITH	0
11357	06/04/2007	LTN050GEF	LOCHINVAR	0
11358	06/11/1993	21V502	RHEEM	0
11359	02/24/2005	PRX50	STATE	0
11360	02/23/2001	G91200	RUUD/RHEEM	0
11361	04/08/1992	PRX50	STATE	0
11362	03/24/2011	41VR40	RHEEM	0
11363	09/26/2011	M45036FBN	BRADFORD-WHITE	0
11364	03/30/2009	22DV50C	RHEEM	0
11365	07/28/1992	21V502	RHEEM	0
11366	01/06/2006	LTN050G	LOCHINVAR	0
11367	04/13/2007	LTN050G	LOCHINVAR	0
11368	01/14/2003	41V50	RHEEM	0
11369	05/07/2012	PH2DV50F	RUUD	0
11370	07/06/2006	LTN050G	LOCHINVAR	0
11371	02/03/2003	PGR40	AO SMITH	0
11372	11/08/2011	M45036FBN	BRADFORD-WHITE	0
11373	11/28/2009	LSN041G	LOCHINVAR	0
11374	12/21/1988	FSG50	AO SMITH	0
11375	11/28/2011	PH2DV50F	RUUD	0
11376	11/04/2012	PH2DV50F	RUUD	0
11377	12/17/2009	LTN050GEF	LOCHINVAR	0
11378	09/11/2009	LTN050GEF	LOCHINVAR	0
11379	02/02/2010	LTN050GEF	LOCHINVAR	0
11380	06/26/2009	LTN050GEF	LOCHINVAR	0
11381	07/06/2005	LTN050	LOCHINVAR	5
11382	07/29/2011	MI50L6FBN	BRADFORD-WHITE	0
11383	09/29/2012	M45036FBN	BRADFORD-WHITE	0
11384	07/26/2008	LTN050GEF	LOCHINVAR	0
11385	10/31/2000	G75125	RUUD/RHEEM	1
11386	08/20/1992	FSG50	AO SMITH	0
11387	09/18/1990	PRV50NODS	STATE	0
11388	07/14/2006	LTN050G	LOCHINVAR	0
11389	09/22/2003	PR650	STATE	0
11390	08/24/2012	MI5036FBN	BRADFORD-WHITE	1
11391	04/23/2000	41V50	RHEEM	2
11392	01/02/2004	PRX50	STATE	1
11393	02/17/2007	LTN050G	LOCHINVAR	1
11394	02/13/2007	42VR50	RHEEM	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11395	03/30/2012	M2XR504T6FBN	Bradford White	0
11396	06/27/2007	LTN050G	LOCHINVAR	0
11397	03/20/2001	FSG50	AO SMITH	1
11398	02/13/2007	P506	RUUD	2
11399	07/23/2012	F72DUMMY	UNKNOWN AT CONVERSION	1
11400	12/10/2009	LSN041G	LOCHINVAR	0
11401	01/11/2011	22DV50F	RHEEM	2
11402	02/15/2007	LTN051G	LOCHINVAR	1
11403	11/12/2005	LTN050G	LOCHINVAR	1
11404	01/10/2005	GVC50	A. O. SMITH	0
11405	12/20/2010	21V502	RHEEM	1
11406	05/15/2007	LTN050GEF	LOCHINVAR	0
11407	01/24/1990	PRV50NODS	STATE	1
11408	12/12/2007	LTN050GEF	LOCHINVAR	0
11409	01/30/2009	LTN050GEF	LOCHINVAR	0
11410	01/04/2001	FSG50	AO SMITH	0
11411	12/26/2008	LTN050GEF	LOCHINVAR	0
11412	06/30/1989	PRV50NORT	STATE	0
11413	01/31/1989	FSG50	AO SMITH	0
11414	02/16/2007	LTN050GEF	LOCHINVAR	0
11415	11/14/2003	PVR50	AO SMITH	4
11416	08/05/1989	FSG50	AO SMITH	0
11417	04/22/2002	PGR50	AO SMITH	0
11418	11/19/2012	MI5036FBN	BRADFORD-WHITE	0
11419	04/05/2012	M45036FBN	BRADFORD-WHITE	0
11420	02/05/2010	LTN050GEF	LOCHINVAR	0
11421	11/27/2000	PGR50	AO SMITH	0
11422	02/11/2010	LTN050GEF	LOCHINVAR	0
11423	05/28/2002	FSGL40	AO SMITH	0
11424	02/28/2006	LTN050G	LOCHINVAR	0
11425	05/23/1989	FSG50	AO SMITH	0
11426	06/28/1989	FSG40	AO SMITH	0
11427	01/09/2002	PGR50	AO SMITH	0
11428	02/12/2008	PR650	STATE	0
11429	04/13/1989	FSG50	AO SMITH	0
11430	03/18/1989	FSG40	AO SMITH	0
11431	03/10/2007	LTN050G	LOCHINVAR	0
11432	04/29/2002	FSG50	AO SMITH	1
11433	01/21/2013	MI5036FBN	BRADFORD-WHITE	0
11434	02/20/2013	MI5036FBN	BRADFORD-WHITE	1
11435	09/11/2007	LTN050GEF	LOCHINVAR	1
11436	05/31/1989	FSGL40	AO SMITH	0
11437	09/11/2000	41XR50	RHEEM	0
11438	01/28/2003	FSG50	AO SMITH	0
11439	03/25/2013	M2XR504T6FBN	BRADFORD WHITE	0
11440	09/01/2005	FSGL40	AO SMITH	0
11441	11/10/2005	LTN050G	LOCHINVAR	0
11442	06/29/2011	22DV50F	RHEEM	2
11443	12/15/2009	LTN050G	LOCHINVAR	0
11444	09/29/2009	LTN050GEF	LOCHINVAR	0
11445	03/04/2011	22DV50F	RHEEM	0
11446	01/08/2010	LSN041G	LOCHINVAR	1
11447	10/29/2009	H72DUMMY	AO SMITH	0
11448	01/04/2000	PRV50NODS	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11449	06/08/2004	GVC50	A. O. SMITH	0
11450	02/28/1989	FSG50	AO SMITH	0
11451	07/24/2003	FSG50	AO SMITH	0
11452	07/10/2003	21V506	RHEEM	0
11453	04/13/2012	PH2DV50F	RUUD	0
11454	09/25/2008	22DV50F	RHEEM	0
11455	07/16/2005	LTN050	LOCHINVAR	0
11456	03/27/1992	21DV50	RHEEM	0
11457	03/19/2009	22DV50F	RHEEM	0
11458	02/21/2013	M45036FBN	BRADFORD-WHITE	0
11459	11/06/1991	FSG50	AO SMITH	0
11460	11/29/2004	GCVL40	A. O. SMITH	0
11461	08/15/2000	PRX50	STATE	0
11462	12/03/2012	M45036FBN	BRADFORD-WHITE	1
11463	08/31/2010	41VR50	RHEEM	0
11464	12/11/1999	21V506	RHEEM	1
11465	09/10/2012	MI40T6FBN	BRADFORD-WHITE	0
11466	01/25/2013	MI5036FBN	BRADFORD-WHITE	1
11467	07/09/2012	M45036FBN	BRADFORD-WHITE	0
11468	06/30/1991	FSG50	AO SMITH	1
11469	12/02/2010	21VR50	RHEEM	0
11470	12/10/1990	PRV50NORT	STATE	1
11471	07/10/2007	PR650	STATE	0
11472	03/24/2008	LTN050GEF	LOCHINVAR	0
11473	12/10/1990	PRV50NORT	STATE	0
11474	09/08/2006	LTN051G	LOCHINVAR	0
11475	02/14/2012	MI5036FBN	BRADFORD-WHITE	0
11476	03/21/2005	LTN050	LOCHINVAR	0
11477	07/23/2009	LTN050G	LOCHINVAR	1
11478	08/26/2011	M440T6FBN	BRADFORD-WHITE	0
11479	03/18/1991	P502	RUUD	0
11480	12/21/2012	M45036FBN	BRADFORD-WHITE	0
11481	09/23/2010	41VR50	RHEEM	0
11482	11/09/2006	PR650	STATE	0
11483	12/29/2007	PR650	STATE	1
11484	07/03/1991	FSG50	AO SMITH	0
11485	03/06/2009	22DV50C	RHEEM	0
11486	10/05/2002	PGR50	AO SMITH	0
11487	12/29/2007	PR650	STATE	0
11488	11/19/2010	42VR50	RHEEM	0
11489	07/24/2006	21DV50	RHEEM	1
11490	08/08/2008	LTN050G	LOCHINVAR	0
11491	01/17/2008	LTN050GEF	LOCHINVAR	1
11492	12/20/2010	21V502	RHEEM	0
11493	11/03/2003	G91200	RUUD/RHEEM	0
11494	04/21/2004	XTN050	LOCHINVAR	0
11495	10/06/2009	LTN050GEF	LOCHINVAR	0
11496	01/02/1996	PR502T	RUUD	0
11497	09/24/2010	21VR50	RHEEM	2
11498	03/02/2009	FGR50	AO SMITH	0
11499	04/16/2003	FSGT50	AO SMITH	0
11500	08/17/2009	LTN050G	LOCHINVAR	0
11501	06/17/2005	LTN050	LOCHINVAR	0
11502	03/30/1990	B71DUMMY	AMERICAN	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11503	08/06/2012	M45036FBN	BRADFORD-WHITE	0
11504	05/26/2009	LTN050GEF	LOCHINVAR	0
11505	04/04/2011	22DV50F	RHEEM	4
11506	02/05/2010	LTN050GEF	LOCHINVAR	0
11507	02/05/2007	LTN050G	LOCHINVAR	0
11508	11/18/2009	LTN050GEF	LOCHINVAR	0
11509	12/04/2002	PGR50	AO SMITH	0
11510	06/29/2009	LTN050GEF	LOCHINVAR	0
11511	09/27/2002	FSG40	AO SMITH	0
11512	04/02/2008	LTN050GEF	LOCHINVAR	2
11513	08/10/2011	21DV50	RHEEM	0
11514	09/20/2002	PRX50	STATE	0
11515	03/22/2006	PR650	STATE	0
11516	11/08/1990	PRV50NODS	STATE	0
11517	01/14/2009	LTN050GEF	LOCHINVAR	0
11518	01/31/2013	M440T6FBN	BRADFORD-WHITE	1
11519	10/06/2004	PRX50	STATE	0
11520	08/17/2007	PR650	STATE	0
11521	04/08/1998	21V506	RHEEM	0
11522	05/01/2002	PRX50	STATE	1
11523	11/12/2003	41XR50	RHEEM	0
11524	02/03/2013	MI5036FBN	BRADFORD-WHITE	0
11525	09/18/2010	41VR50	RHEEM	5
11526	02/14/2000	PHR50	RUUD	0
11527	05/20/2012	M45036FBN	BRADFORD-WHITE	0
11528	10/11/2001	FSG50	AO SMITH	0
11529	06/01/1990	PRV50NODS	STATE	0
11530	10/14/1998	FGR40	AO SMITH	0
11531	06/06/2007	21V506	RHEEM	2
11532	04/07/2011	21VR50	RHEEM	0
11533	09/01/2012	PH2DV50F	RUUD	0
11534	06/28/2011	M45036FBN	BRADFORD-WHITE	0
11535	09/01/1989	FSG50	AO SMITH	0
11536	10/25/2003	FCV50	AO SMITH	0
11537	02/28/2013	M45036FBN	BRADFORD-WHITE	0
11538	09/13/2007	PR650	STATE	0
11539	07/07/2009	PRX50	STATE	0
11540	04/27/2000	FSG50	AO SMITH	0
11541	01/07/2002	PGR50	AO SMITH	0
11542	04/08/1999	FGR50	AO SMITH	0
11543	05/17/1989	FSG50	AO SMITH	0
11544	07/08/2008	42VR50	RHEEM	0
11545	02/23/1989	21V506	RHEEM	0
11546	09/27/2001	G91200	RUUD/RHEEM	1
11547	11/05/2007	LTN050G	LOCHINVAR	0
11548	08/30/2011	M45036FBN	BRADFORD-WHITE	0
11549	11/21/2011	M45036FBN	BRADFORD-WHITE	0
11550	10/26/1989	FSG50	AO SMITH	0
11551	06/26/1998	G91200	RUUD/RHEEM	4
11552	12/15/2008	LTN050G	LOCHINVAR	0
11553	01/09/2003	SBF100199NES	STATE	0
11554	07/22/2005	LTN050	LOCHINVAR	0
11555	03/29/1989	FSG50	AO SMITH	0
11556	03/10/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11557	10/17/2005	LTN050G	LOCHINVAR	2
11558	12/22/2009	LTN050GEF	LOCHINVAR	0
11559	02/25/2013	PH2DV50F	RUUD	0
11560	01/09/2003	SBF100199NES	STATE	0
11561	11/27/2010	LTN040GEF	LOCHINVAR	1
11562	03/28/2003	PGR50	AO SMITH	0
11563	10/15/2007	PRX50	STATE	0
11564	01/31/1989	FSG30	AO SMITH	0
11565	11/29/2003	21DV50	RHEEM	0
11566	04/18/2006	PR650	STATE	0
11567	10/07/2005	LTN050G	LOCHINVAR	0
11568	04/04/2003	FSG50	AO SMITH	0
11569	09/05/2003	FCV50	AO SMITH	0
11570	01/23/1989	FSG50	AO SMITH	0
11571	02/25/2006	LTN050G	LOCHINVAR	0
11572	02/12/2004	FCV50	AO SMITH	0
11573	02/03/1989	FSG50	AO SMITH	0
11574	12/29/1989	F72DUMMY	AO SMITH	0
11575	03/24/2008	21DV50	RHEEM	0
11576	02/20/2012	M45036FBN	BRADFORD-WHITE	0
11577	03/25/2009	LTN050GEF	LOCHINVAR	0
11578	06/22/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
11579	07/11/1997	FGR40	AO SMITH	0
11580	05/10/1989	FSG50	AO SMITH	0
11581	05/30/2011	22V40SF	RHEEM	0
11582	06/25/2004	XTN050	LOCHINVAR	0
11583	12/03/2005	LTN050G	LOCHINVAR	0
11584	11/18/1992	P502	RUUD	0
11585	09/17/1999	PR650	STATE	0
11586	09/16/1992	FSG50	AO SMITH	0
11587	07/03/2005	FSG40	AO SMITH	0
11588	11/26/2001	FSG50	AO SMITH	0
11589	12/15/2006	LTN050G	LOCHINVAR	0
11590	10/10/2003	PGR50	AO SMITH	0
11591	07/12/2004	G91200	RUUD/RHEEM	2
11592	02/22/2005	XTN050	LOCHINVAR	0
11593	02/11/2005	XTN050	LOCHINVAR	0
11594	11/06/2011	M45036FBN	BRADFORD-WHITE	0
11595	02/21/2001	FSG50	AO SMITH	0
11596	04/17/2009	LTN050GEF	LOCHINVAR	1
11597	02/08/2008	LTN051	LOCHINVAR	0
11598	05/22/2010	22DV50C	RHEEM	0
11599	01/26/2007	LTN050G	LOCHINVAR	0
11600	11/07/2012	MI5036FBN	BRADFORD-WHITE	0
11601	04/28/2009	LTN050G	LOCHINVAR	0
11602	12/21/2010	21VR50	RHEEM	0
11603	03/06/2008	PR650	STATE	0
11604	02/10/2005	GVC40	A. O. SMITH	0
11605	01/22/1993	PRV50NODS	STATE	0
11606	02/23/2008	LTN050	LOCHINVAR	0
11607	10/31/2002	BTR199	AO SMITH	0
11608	08/30/2006	LSN041G	LOCHINVAR	0
11609	10/30/2012	M2XR504T6FBN	BRADFORD-WHITE	6
11610	06/30/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11611	11/09/1992	P506	RUUD	0
11612	01/15/2011	22DV50F	RHEEM	1
11613	04/27/2009	G75125	RUUD/RHEEM	0
11614	03/21/2001	PGR50	AO SMITH	2
11615	06/19/2004	GVC50	A. O. SMITH	0
11616	09/14/2008	LTN050GEF	LOCHINVAR	0
11617	06/09/2006	PR650	STATE	0
11618	06/19/2008	LTN050GEF	LOCHINVAR	0
11619	08/07/1992	RF67120	RUUD	0
11620	01/16/2009	LTN050GEF	LOCHINVAR	1
11621	12/01/2010	21VR50	RHEEM	0
11622	12/10/2012	M2XR504T6FBN	BRADFORD WHITE	1
11623	05/14/2008	LTN050GEF	LOCHINVAR	1
11624	10/30/2012	MI5036FBN	BRADFORD-WHITE	0
11625	04/02/2009	LTN050G	LOCHINVAR	0
11626	05/16/2005	LTN050	LOCHINVAR	0
11627	10/06/2003	PVR50	AO SMITH	0
11628	03/16/2009	LTN050G	LOCHINVAR	0
11629	04/15/2008	22DV50C	RHEEM	0
11630	12/06/2010	21V506	RHEEM	0
11631	12/16/2005	LTN050GEF	LOCHINVAR	1
11632	02/23/2012	G91200	RUUD/RHEEM	3
11633	08/04/2006	LTN050G	LOCHINVAR	0
11634	02/23/2006	LTN050G	LOCHINVAR	0
11635	11/29/2011	G91200	RUUD/RHEEM	0
11636	04/12/1990	B71DUMMY	AMERICAN	0
11637	01/03/2001	PRX50	STATE	0
11638	12/26/2008	LTN050G	LOCHINVAR	0
11639	12/18/2006	PR650	STATE	0
11640	05/25/2008	LTN050GEF	LOCHINVAR	0
11641	06/09/2009	21V502	RHEEM	0
11642	04/27/1990	P506	RUUD	0
11643	07/29/2004	XTN050	LOCHINVAR	0
11644	01/21/1991	PRX50	STATE	1
11645	02/10/2012	M45036FBN	BRADFORD-WHITE	0
11646	01/03/2011	21VR50	RHEEM	1
11647	12/04/2003	PRX50	STATE	0
11648	10/15/2008	LTN051G	LOCHINVAR	0
11649	03/16/2009	LTN050GEF	LOCHINVAR	0
11650	03/06/2012	M45036FBN	BRADFORD-WHITE	0
11651	04/23/2007	LTN051G	LOCHINVAR	1
11652	10/20/2004	LTN050G	LOCHINVAR	0
11653	06/01/1999	FSG50	AO SMITH	0
11654	03/19/2009	LTN050GEF	LOCHINVAR	0
11655	10/23/2003	FSG30	AO SMITH	0
11656	09/15/2011	M45036FBN	BRADFORD-WHITE	0
11657	07/26/2008	LTN050GEF	LOCHINVAR	0
11658	05/21/2003	PGR50	AO SMITH	0
11659	01/22/1990	FSG50	AO SMITH	0
11660	12/16/2008	LTN050GEF	LOCHINVAR	0
11661	04/10/2000	FSG50	AO SMITH	0
11662	02/23/2009	LTN050GEF	LOCHINVAR	1
11663	07/02/2005	G91200	RUUD/RHEEM	0
11664	06/24/2010	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11665	09/17/1990	P506	RUUD	0
11666	10/08/2009	22DV50C	RHEEM	0
11667	10/05/2001	PGR40	AO SMITH	0
11668	02/24/1999	G91200	RUUD/RHEEM	0
11669	04/18/2011	21VR40	RHEEM	0
11670	06/23/2009	LTN050GEF	LOCHINVAR	1
11671	05/06/2011	21VR50	RHEEM	0
11672	05/20/2010	LTN050GEF	LOCHINVAR	0
11673	08/22/1990	PRV50NORT	STATE	0
11674	05/24/2009	LTN050GEF	LOCHINVAR	0
11675	11/30/2007	PR650X0DS	STATE	1
11676	10/30/1990	FSG50	AO SMITH	0
11677	05/07/2010	22DV50C	RHEEM	0
11678	12/20/2005	GVC50	A. O. SMITH	0
11679	01/09/2010	LTN050GEF	LOCHINVAR	0
11680	07/04/2005	LSN041G	LOCHINVAR	0
11681	06/16/2006	LTN050G	LOCHINVAR	0
11682	12/12/1991	P506	RUUD	0
11683	08/17/2002	FSG50	AO SMITH	0
11684	07/08/1991	FSG50	AO SMITH	0
11685	07/25/2003	FSG50	AO SMITH	0
11686	11/13/2008	LTN050G	LOCHINVAR	0
11687	02/14/2007	LTN050G	LOCHINVAR	0
11688	12/16/2008	LTN050GEF	LOCHINVAR	1
11689	05/06/2009	G91200	RUUD/RHEEM	2
11690	11/16/2008	LTN050G	LOCHINVAR	0
11691	07/31/1991	FSG50	AO SMITH	0
11692	10/22/2001	PGR50	AO SMITH	0
11693	02/23/2007	P506	RUUD	1
11694	09/18/1991	P502	RUUD	0
11695	10/11/2011	M45036FBN	BRADFORD-WHITE	0
11696	11/13/2008	LTN050G	LOCHINVAR	0
11697	03/23/1991	G67114	RHEEM	0
11698	07/27/2008	22DV50C	RHEEM	1
11699	12/07/1998	G91200	RUUD/RHEEM	0
11700	06/28/1991	F72DUMMY	AO SMITH	2
11701	11/07/2010	41VR50	RHEEM	0
11702	01/29/2008	LTN050	LOCHINVAR	0
11703	10/15/1991	RF92200	RUUD	0
11704	06/08/2006	PR650	STATE	1
11705	01/29/2001	PRX50	STATE	1
11706	10/25/2012	M45036FBN	BRADFORD-WHITE	1
11707	06/04/2008	LTN050G	LOCHINVAR	0
11708	05/22/1991	41XR50	RHEEM	0
11709	02/05/2011	42VR50	RHEEM	0
11710	08/08/1991	P506	RUUD	0
11711	07/22/2002	21V506	RHEEM	0
11712	11/29/1999	FSG50	AO SMITH	0
11713	11/06/2009	P502	RUUD	0
11714	01/05/2012	PH2DV50F	RUUD	0
11715	05/15/2012	M2XR504T6FBN	Bradford White	2
11716	09/29/2007	FSG50	AO SMITH	0
11717	02/23/2007	FSGL40	AO SMITH	0
11718	01/31/2000	PGR50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11719	03/15/2006	PR650	STATE	0
11720	11/08/2007	LTN050GEF	LOCHINVAR	0
11721	10/31/2010	21DV50	RHEEM	0
11722	03/08/2011	42VR50	RHEEM	1
11723	07/17/2009	LTN040GEF	LOCHINVAR	0
11724	10/27/2000	PGR50	AO SMITH	0
11725	06/19/2010	LTN050GEF	LOCHINVAR	0
11726	02/26/2004	PVR50	AO SMITH	0
11727	08/04/2007	LTN050GEF	LOCHINVAR	0
11728	07/01/2003	PRX50	STATE	0
11729	06/16/2006	PR650X0DS	STATE	0
11730	07/20/1998	FSG50	AO SMITH	0
11731	03/08/2012	MI403S6FBN	BRADFORD-WHITE	1
11732	06/11/2001	FSG50	AO SMITH	0
11733	12/31/2004	LTN050	LOCHINVAR	0
11734	12/14/2011	M45036FBN	BRADFORD-WHITE	1
11735	01/26/2005	GVC50	A. O. SMITH	0
11736	08/26/2008	LTN050G	LOCHINVAR	0
11737	11/17/2011	41VR50	RHEEM	1
11738	02/06/2002	FSG50	AO SMITH	0
11739	03/31/2003	FSGL40	AO SMITH	0
11740	01/17/2012	PH2DV50F	RUUD	0
11741	01/06/2011	G75125	RUUD/RHEEM	0
11742	05/18/1990	P506	RUUD	0
11743	06/05/1998	FSG50	AO SMITH	0
11744	04/12/2006	LTN050G	LOCHINVAR	0
11745	05/10/1999	FSG50	AO SMITH	0
11746	03/05/2012	PH2DV50F	RUUD	0
11747	02/15/2006	PR650	STATE	0
11748	03/02/2011	22DV50F	RHEEM	0
11749	04/12/1999	FSG50	AO SMITH	0
11750	10/24/2012	MI50L6FBN	BRADFORD-WHITE	0
11751	02/02/2009	LTN050GEF	LOCHINVAR	1
11752	04/10/2001	G91200	RUUD/RHEEM	0
11753	03/08/2011	21VR50	RHEEM	0
11754	12/12/2011	MI5036FBN	BRADFORD-WHITE	0
11755	12/27/2009	21V502	RHEEM	2
11756	10/15/2012	M45036FBN	BRADFORD-WHITE	0
11757	03/28/2002	FSG50	AO SMITH	0
11758	09/27/2011	M45036FBN	BRADFORD-WHITE	0
11759	01/05/1990	PRX50	STATE	0
11760	04/23/2007	LTN040GEF	LOCHINVAR	0
11761	12/05/2008	LTN050GEF	LOCHINVAR	0
11762	05/18/1990	PRX50	STATE	0
11763	11/22/2006	LTN050G	LOCHINVAR	0
11764	11/20/1998	41XR50	RHEEM	0
11765	06/13/2007	LTN050G	LOCHINVAR	0
11766	03/13/2006	LTN050G	LOCHINVAR	0
11767	04/23/1996	PHR50	RUUD	0
11768	11/28/2008	22DV50F	RHEEM	0
11769	05/31/2012	MI40T6FBN	BRADFORD-WHITE	0
11770	05/22/2001	PGR50	AO SMITH	0
11771	11/25/2011	MI40T6FBN	BRADFORD-WHITE	0
11772	03/03/2001	41VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11773	11/05/2007	LTN050GEF	LOCHINVAR	0
11774	10/27/2008	LTN050GEF	LOCHINVAR	0
11775	07/11/2001	PGR50	AO SMITH	0
11776	07/16/2008	LTN050G	LOCHINVAR	0
11777	02/17/2010	LSN041G	LOCHINVAR	0
11778	06/10/2003	G82156	RUUD/RHEEM	2
11779	01/07/2000	PRX50	STATE	0
11780	07/21/2009	LTN050GEF	LOCHINVAR	0
11781	02/18/2008	22DV50C	RHEEM	0
11782	06/05/2006	LTN050G	LOCHINVAR	0
11783	03/07/2001	FSG40	AO SMITH	0
11784	06/05/2007	XVR50	A. O. SMITH	0
11785	06/29/2000	PGR50	AO SMITH	0
11786	06/05/2006	LTN050G	LOCHINVAR	0
11787	02/08/2007	PR650X0DS	STATE	0
11788	06/09/2004	PRX50	STATE	0
11789	12/20/2010	22DV50F	RHEEM	0
11790	04/17/1989	FSG50	AO SMITH	0
11791	06/12/2006	LTN050G	LOCHINVAR	0
11792	05/09/2012	PH2DV50F	RUUD	0
11793	04/26/2005	LTN050	LOCHINVAR	0
11794	08/16/2000	PGR50	AO SMITH	0
11795	07/20/2009	LTN040G	LOCHINVAR	0
11796	10/24/1989	FSG50	AO SMITH	0
11797	08/02/2011	M45036FBN	BRADFORD-WHITE	0
11798	02/20/2008	LTN050GEF	LOCHINVAR	1
11799	01/05/2000	PGR50	AO SMITH	0
11800	08/29/2012	MI5036FBN	BRADFORD-WHITE	0
11801	12/23/2010	22DV50F	RHEEM	0
11802	03/09/2005	GVC50	A. O. SMITH	0
11803	09/13/2011	41XR50	RHEEM	0
11804	12/31/2007	LTN050G	LOCHINVAR	0
11805	03/09/2005	XVR50	A. O. SMITH	0
11806	12/16/2011	MI50L6FBN	BRADFORD-WHITE	0
11807	06/27/2011	MI403S6FBN	BRADFORD-WHITE	0
11808	06/19/2012	M45036FBN	BRADFORD-WHITE	1
11809	03/13/1989	P506	RUUD	0
11810	12/06/2006	LTN050G	LOCHINVAR	0
11811	08/20/2008	LTN050G	LOCHINVAR	1
11812	05/19/2005	LTN050	LOCHINVAR	0
11813	03/04/2005	GVC50	A. O. SMITH	0
11814	05/12/2011	41VR50	RHEEM	0
11815	08/10/2006	PR650X0DS	STATE	0
11816	04/17/2010	LTN050GEF	LOCHINVAR	0
11817	09/04/2002	PGR50	AO SMITH	0
11818	01/09/2006	LTN050	LOCHINVAR	0
11819	01/25/1993	FSG50	AO SMITH	0
11820	07/13/2010	LTN050G	LOCHINVAR	0
11821	03/31/2010	LTN050GEF	LOCHINVAR	0
11822	10/05/1992	P506	RUUD	0
11823	03/30/2007	LTN050G	LOCHINVAR	0
11824	05/13/1992	FSG40	AO SMITH	0
11825	05/16/2012	MI403S6FBN	BRADFORD-WHITE	0
11826	02/07/2003	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11827	05/08/2012	M45036FBN	BRADFORD-WHITE	0
11828	01/22/2007	LTN050G	LOCHINVAR	0
11829	04/30/1992	41V50	RHEEM	0
11830	05/05/2003	FSG40	AO SMITH	1
11831	05/30/2008	LTN040G	LOCHINVAR	0
11832	01/15/2002	PGR50	AO SMITH	0
11833	08/05/1992	FSG50	AO SMITH	1
11834	08/14/2003	PRX50	STATE	0
11835	02/27/2003	FSG50	AO SMITH	0
11836	06/19/2011	22DV50F	RHEEM	0
11837	06/26/2012	MI5036FBN	BRADFORD-WHITE	1
11838	09/15/2002	FSG50	AO SMITH	0
11839	02/27/2008	LTN050GEF	LOCHINVAR	1
11840	08/06/2008	LTN050GEF	LOCHINVAR	0
11841	07/26/2010	21V502	RHEEM	1
11842	12/28/2009	LTN050G	LOCHINVAR	0
11843	09/09/2002	21V506	RHEEM	0
11844	05/29/2008	LSN041G	LOCHINVAR	0
11845	02/06/2013	PH2DV50F	RUUD	0
11846	09/15/2005	LTN050	LOCHINVAR	0
11847	11/28/2008	LTN050GEF	LOCHINVAR	0
11848	06/19/2008	LTN050GEF	LOCHINVAR	0
11849	12/22/2010	42VR50	RHEEM	0
11850	12/02/1992	P506	RUUD	0
11851	08/25/2009	LTN040G	LOCHINVAR	0
11852	10/14/2009	LSN041G	LOCHINVAR	0
11853	10/01/1992	FSG50	AO SMITH	0
11854	06/12/2012	MI5036FBN	BRADFORD-WHITE	0
11855	08/14/1998	FGR50	AO SMITH	0
11856	04/25/2008	41V50	RHEEM	0
11857	06/09/2008	LTN050GEF	LOCHINVAR	0
11858	02/15/1990	21V506	RHEEM	0
11859	03/24/2004	PRX50	STATE	0
11860	10/13/2005	LTN050	LOCHINVAR	0
11861	03/28/2001	PGR50	AO SMITH	0
11862	12/02/2000	41XR50	RHEEM	0
11863	12/01/1993	FGR50	AO SMITH	0
11864	02/02/2012	M45036FBN	BRADFORD-WHITE	0
11865	07/30/2003	PRX50	STATE	0
11866	07/27/2006	LTN050GEF	LOCHINVAR	0
11867	12/20/2007	LTN050GEF	LOCHINVAR	3
11868	12/18/2001	PRX50	STATE	0
11869	03/02/2009	22DV50C	RHEEM	0
11870	12/22/2004	C71	UNKNOWN	0
11871	03/21/2006	LTN050G	LOCHINVAR	0
11872	12/30/1999	FGR50	AO SMITH	0
11873	10/10/1990	P506	RUUD	0
11874	12/03/2004	LTN050G	LOCHINVAR	0
11875	02/12/1990	P505	RUUD	0
11876	04/20/2010	LTN050GEF	LOCHINVAR	0
11877	08/07/2008	22DV50C	RHEEM	0
11878	02/22/2012	M45036FBN	BRADFORD-WHITE	1
11879	03/26/2003	PGR50	AO SMITH	0
11880	05/01/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11881	03/06/1991	B71DUMMY	AMERICAN	0
11882	04/02/2011	21VR50	RHEEM	0
11883	01/10/2005	GVC50	A. O. SMITH	1
11884	08/02/2002	FSG50	AO SMITH	0
11885	09/03/2007	LSN041G	LOCHINVAR	0
11886	03/10/1990	PRX40	STATE	0
11887	02/29/2008	LTN050GEF	LOCHINVAR	0
11888	03/06/1990	PRV50NODS	STATE	0
11889	06/20/2006	PR650	STATE	0
11890	04/26/2008	LTN050GEF	LOCHINVAR	0
11891	01/06/2006	PR650	STATE	0
11892	12/18/2006	LTN051G	LOCHINVAR	3
11893	07/14/2008	22DV50C	RHEEM	3
11894	06/09/2008	LTN050G	LOCHINVAR	0
11895	09/30/2003	PGR50	AO SMITH	0
11896	09/26/2012	M45036FBN	BRADFORD-WHITE	0
11897	02/24/2007	LTN050G	LOCHINVAR	0
11898	03/07/2006	LTN050G	LOCHINVAR	0
11899	09/17/1999	41VR50	RHEEM	0
11900	03/15/2006	LTN050G	LOCHINVAR	0
11901	08/28/2001	FSG50	AO SMITH	0
11902	09/18/1991	FSG50	AO SMITH	0
11903	10/06/2008	LTN050G	LOCHINVAR	1
11904	09/03/2008	LTN050GEF	LOCHINVAR	0
11905	07/23/2011	M45036FBN	BRADFORD-WHITE	0
11906	04/09/2008	LTN050GEF	LOCHINVAR	0
11907	12/11/2001	PGR50	AO SMITH	0
11908	01/07/2002	L72DUMMY	AO SMITH	0
11909	05/27/2001	PRX50	STATE	0
11910	04/25/2008	LTN050GEF	LOCHINVAR	0
11911	08/24/2011	G91200	RUUD/RHEEM	0
11912	08/13/2012	M45036FBN	BRADFORD-WHITE	0
11913	04/13/2005	GVC50	A. O. SMITH	0
11914	01/14/2003	FSG40	AO SMITH	0
11915	05/23/1991	FSG50	AO SMITH	0
11916	07/23/2010	LTN050GEF	LOCHINVAR	0
11917	04/06/2010	LTN050GEF	LOCHINVAR	0
11918	09/27/2007	PR650X0DS	STATE	1
11919	08/21/2012	MI5036FBN	BRADFORD-WHITE	0
11920	07/01/2010	LTN040G	LOCHINVAR	0
11921	04/06/2012	DS140S6FBN	BRADFORD-WHITE	2
11922	08/19/1991	RF92200	RUUD	0
11923	12/05/2007	LTN050G	LOCHINVAR	0
11924	12/13/2005	LTN050G	LOCHINVAR	0
11925	05/08/2006	LTN051G	LOCHINVAR	0
11926	05/01/2012	MI50L6FBN	BRADFORD-WHITE	0
11927	12/06/2007	LTN050GEF	LOCHINVAR	0
11928	02/03/2003	PRX50	STATE	0
11929	09/16/2010	21VR50	RHEEM	0
11930	02/18/2000	PGR50	AO SMITH	0
11931	10/11/2012	DS140S6FBN	BRADFORD-WHITE	0
11932	02/04/2002	PGR50	AO SMITH	0
11933	06/14/2002	21DV50	RHEEM	0
11934	09/14/2007	LTN050GEF	LOCHINVAR	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11935	03/06/2004	PRX50	STATE	0
11936	12/16/2009	LTN050GEF	LOCHINVAR	0
11937	10/09/2005	LTN050G	LOCHINVAR	0
11938	11/04/2002	PRX50	STATE	0
11939	09/13/2007	LTN050GEF	LOCHINVAR	1
11940	07/29/2011	PH2DV50F	RUUD	0
11941	11/23/1994	FGR50	AO SMITH	0
11942	01/16/2012	MI5036FBN	BRADFORD-WHITE	0
11943	03/12/1999	FGR50	AO SMITH	0
11944	12/21/2006	PR650	STATE	0
11945	08/18/2010	LTN050G	LOCHINVAR	0
11946	05/04/1998	FSG50	AO SMITH	0
11947	10/20/2008	LTN050G	LOCHINVAR	0
11948	02/26/2013	M45036FBN	BRADFORD-WHITE	0
11949	10/07/2010	21V506	RHEEM	0
11950	06/28/2005	G76200	RUUD/RHEEM	0
11951	12/11/2007	LTN040G	LOCHINVAR	0
11952	01/19/2009	22DV50F	RHEEM	0
11953	12/19/2011	LTN040G	LOCHINVAR	1
11954	02/26/2001	PGR50	AO SMITH	0
11955	06/04/2000	41XR50	RHEEM	0
11956	10/23/2001	FSG50	AO SMITH	0
11957	12/26/2004	PRX50	STATE	1
11958	07/03/1990	FSG50	AO SMITH	0
11959	07/29/2007	LTN050G	LOCHINVAR	2
11960	11/01/2010	21VR50	RHEEM	0
11961	08/26/2008	LTN050GEF	LOCHINVAR	0
11962	02/07/2013	PH2DV50F	RUUD	0
11963	09/24/2008	42VR50	RHEEM	0
11964	10/31/2005	LTN050G	LOCHINVAR	0
11965	11/03/2011	PH2DV50F	RUUD	0
11966	04/15/1997	FGR50	AO SMITH	0
11967	10/15/2009	LTN040G	LOCHINVAR	0
11968	06/18/2012	M45036FBN	BRADFORD-WHITE	0
11969	07/04/2010	LTN050G	LOCHINVAR	0
11970	01/09/2000	41VR50	RHEEM	0
11971	09/12/2008	LTN050GEF	LOCHINVAR	0
11972	05/28/1999	FSG50	AO SMITH	0
11973	08/15/2012	MI5036FBN	BRADFORD-WHITE	0
11974	05/01/2004	GVC50	A. O. SMITH	1
11975	12/26/2009	LTN050G	LOCHINVAR	0
11976	08/26/2007	LTN050G	LOCHINVAR	1
11977	02/02/2007	LTN050G	LOCHINVAR	0
11978	10/12/2005	LTN050GEF	LOCHINVAR	0
11979	01/29/2007	G75125	RUUD/RHEEM	0
11980	12/28/2005	GVC50	A. O. SMITH	0
11981	10/08/2007	PR650	STATE	0
11982	04/13/2010	LTN050GEF	LOCHINVAR	0
11983	11/21/1990	PRV50NODS	STATE	1
11984	04/05/1990	P506	RUUD	0
11985	07/01/2010	D71DUMMY	UNKNOWN AT CONVERSION	0
11986	01/09/1998	FGR50	AO SMITH	0
11987	10/28/2002	G82156	RUUD/RHEEM	0
11988	11/30/2010	21VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
11989	11/05/2012	M45036FBN	BRADFORD-WHITE	0
11990	06/26/1990	FSG50	AO SMITH	0
11991	08/08/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
11992	10/12/2012	PH2DV50F	RUUD	0
11993	04/21/2005	LTN050	LOCHINVAR	0
11994	10/19/2011	M45036FBN	BRADFORD-WHITE	0
11995	07/31/1989	FSG50	AO SMITH	1
11996	01/05/2008	PR650	STATE	0
11997	04/18/1989	PRX50	STATE	0
11998	10/28/1999	PGR50	AO SMITH	0
11999	08/08/1989	FSG50	AO SMITH	0
12000	12/14/2000	21V506	RHEEM	0
12001	11/09/2006	PR650	STATE	0
12002	03/08/2010	LTN050GEF	LOCHINVAR	0
12003	08/07/1997	PRV50NODS	STATE	0
12004	09/06/2001	PGR50	AO SMITH	0
12005	01/17/1989	PRX50	STATE	0
12006	01/23/2006	PR650	STATE	0
12007	08/25/2009	G91200	RUUD/RHEEM	0
12008	10/26/2001	G75125	RUUD/RHEEM	1
12009	03/31/2010	LTN050GEF	LOCHINVAR	0
12010	01/09/2013	M45036FBN	BRADFORD-WHITE	0
12011	02/06/2010	LTN040GEF	LOCHINVAR	0
12012	01/24/2005	GVC50	A. O. SMITH	0
12013	02/10/2006	LTN050G	LOCHINVAR	0
12014	07/21/2007	LTN050G	LOCHINVAR	0
12015	08/06/2010	LTN050GEF	LOCHINVAR	0
12016	01/06/2009	22DV50C	RHEEM	0
12017	10/29/2008	LTN050GEF	LOCHINVAR	0
12018	01/08/2002	PGR50	AO SMITH	0
12019	03/22/2008	LTN050GEF	LOCHINVAR	0
12020	04/04/2006	LTN050G	LOCHINVAR	0
12021	03/10/2011	22DV50F	RHEEM	0
12022	11/17/2010	22DV50F	RHEEM	1
12023	06/14/1989	FSG50	AO SMITH	0
12024	10/26/2006	PR650	STATE	1
12025	06/25/2007	LTN050G	LOCHINVAR	1
12026	03/05/1989	FSG50	AO SMITH	0
12027	12/16/2008	LTN050GEF	LOCHINVAR	0
12028	02/14/2003	PGR50	AO SMITH	0
12029	03/30/2009	LTN050G	LOCHINVAR	0
12030	08/30/1989	FSG50	AO SMITH	0
12031	11/18/2006	LTN050G	LOCHINVAR	0
12032	04/08/1989	FSG50	AO SMITH	0
12033	05/08/1989	FSG50	AO SMITH	0
12034	11/24/2011	MI5036FBN	BRADFORD-WHITE	0
12035	01/11/2004	FSG50	AO SMITH	0
12036	02/16/2007	PR650X0DS	STATE	0
12037	12/11/2009	LTN050GEF	LOCHINVAR	0
12038	03/09/2006	LTN050G	LOCHINVAR	1
12039	10/10/2003	FSG50	AO SMITH	0
12040	08/12/2008	22DV50F	RHEEM	0
12041	07/18/2006	LTN050G	LOCHINVAR	0
12042	01/25/2007	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12043	12/23/2010	21V506	RHEEM	2
12044	05/05/2009	LTN050GEF	LOCHINVAR	0
12045	03/19/2003	FSG50	AO SMITH	0
12046	11/06/2009	LTN050GEF	LOCHINVAR	0
12047	03/01/2010	LSN041G	LOCHINVAR	1
12048	05/01/1992	21V502	RHEEM	0
12049	06/10/2005	GVC50	A. O. SMITH	0
12050	07/31/1992	FSG50	AO SMITH	1
12051	03/31/2008	22DV50C	RHEEM	0
12052	11/03/2010	21VR50	RHEEM	1
12053	09/24/2007	LTN050GEF	LOCHINVAR	0
12054	08/05/1992	21V502	RHEEM	1
12055	01/17/2009	LTN050GEF	LOCHINVAR	0
12056	12/30/1992	21V502	RHEEM	0
12057	03/16/2006	LTN050GEF	LOCHINVAR	0
12058	05/07/2009	LTN040	LOCHINVAR	0
12059	01/15/2008	LSN041G	LOCHINVAR	4
12060	11/30/2007	LTN050GEF	LOCHINVAR	0
12061	09/12/2011	M45036FBN	BRADFORD-WHITE	0
12062	11/22/2002	FSG50	AO SMITH	0
12063	01/11/2007	SBF100199NES	STATE	0
12064	06/19/2006	LTN050G	LOCHINVAR	0
12065	03/04/2002	PGR50	AO SMITH	0
12066	11/28/2012	MI5036FBN	BRADFORD-WHITE	0
12067	04/20/2011	21VR50	RHEEM	0
12068	12/01/2012	MI403S6FBN	BRADFORD-WHITE	1
12069	06/18/2007	G91200	RUUD/RHEEM	9
12070	02/03/1993	FSG40	AO SMITH	0
12071	05/12/2012	M45036FBN	BRADFORD-WHITE	0
12072	09/24/2005	LTN051	LOCHINVAR	0
12073	05/07/2002	PRX50	STATE	1
12074	04/23/2008	LTN050GEF	LOCHINVAR	0
12075	10/17/2009	LTN050G	LOCHINVAR	0
12076	11/17/2010	21VR50	RHEEM	1
12077	10/27/2006	LTN051G	LOCHINVAR	0
12078	06/28/2007	LSN041G	LOCHINVAR	0
12079	02/01/2002	FSG50	AO SMITH	0
12080	01/25/2011	21VR50	RHEEM	0
12081	03/11/2002	FSGL40	AO SMITH	0
12082	04/04/2006	PR650	STATE	0
12083	07/09/2010	LTN050G	LOCHINVAR	0
12084	05/02/2011	21VR50	RHEEM	0
12085	03/19/2005	XVR50	A. O. SMITH	0
12086	07/06/2012	PH2DV50F	RUUD	1
12087	05/13/2011	21VR40	RHEEM	0
12088	05/23/2002	21DV50	RHEEM	0
12089	01/06/2012	M45036FBN	BRADFORD-WHITE	0
12090	10/25/2005	LTN050G	LOCHINVAR	1
12091	03/27/1991	P506	RUUD	0
12092	01/23/2003	PRX50	STATE	0
12093	12/15/2005	LTN051G	LOCHINVAR	0
12094	04/28/2011	42VR50	RHEEM	0
12095	08/22/2000	PRX50	STATE	0
12096	06/01/2007	LTN040GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12097	10/29/2012	PH2DV50F	RUUD	0
12098	01/04/1991	21V506	RHEEM	1
12099	05/31/2006	LTN050G	LOCHINVAR	0
12100	01/23/2006	LTN050GEF	LOCHINVAR	0
12101	08/02/2011	MI403S6FBN	BRADFORD-WHITE	0
12102	01/04/1991	21V506	RHEEM	0
12103	09/01/2010	22DV50C	RHEEM	0
12104	02/08/1991	FSG50	AO SMITH	0
12105	01/20/2003	FSG50	AO SMITH	1
12106	01/13/2013	MI50L6FBN	BRADFORD-WHITE	0
12107	04/02/1991	FSG50	AO SMITH	0
12108	03/25/2005	LTN050G	LOCHINVAR	2
12109	05/29/1991	FSG50	AO SMITH	0
12110	07/17/2007	PR650	STATE	0
12111	11/29/2006	LTN050G	LOCHINVAR	0
12112	05/07/2005	LTN050	LOCHINVAR	0
12113	12/26/2007	22DV50C	RHEEM	1
12114	02/26/2004	FCV50	AO SMITH	0
12115	02/05/1991	BTR120	AO SMITH	0
12116	01/25/2002	FSGL40	AO SMITH	0
12117	03/10/2006	LTN050G	LOCHINVAR	0
12118	02/27/2002	PGR50	AO SMITH	0
12119	03/17/2009	LTN050GEF	LOCHINVAR	0
12120	03/07/2007	PR650	STATE	0
12121	12/13/2007	G82156	RUUD/RHEEM	0
12122	05/08/2007	LTN050GEF	LOCHINVAR	0
12123	01/28/2011	42VR50	RHEEM	0
12124	02/27/2012	MI40T6FBN	BRADFORD-WHITE	0
12125	12/05/2003	PVR50	AO SMITH	0
12126	08/15/2011	M45036FBN	BRADFORD-WHITE	2
12127	02/12/1991	PRX50	STATE	0
12128	02/14/1990	FSG50	AO SMITH	0
12129	01/11/2010	LTN050GEF	LOCHINVAR	1
12130	12/06/2007	LTN050GEF	LOCHINVAR	0
12131	06/20/2006	LTN050G	LOCHINVAR	0
12132	09/16/2002	FSG40	AO SMITH	0
12133	11/08/2011	PH2DV50F	RUUD	0
12134	12/27/2004	GVC50	A. O. SMITH	2
12135	02/10/2010	21V502	RHEEM	0
12136	01/03/2002	PRX50	STATE	0
12137	01/25/2006	LTN050G	LOCHINVAR	0
12138	06/04/1998	FGR50	AO SMITH	0
12139	11/28/2003	PRX50	STATE	0
12140	03/06/1990	PH30	RUUD	0
12141	03/09/2011	21VR40	RHEEM	0
12142	03/25/2005	GVC50	A. O. SMITH	0
12143	08/29/2006	LTN050G	LOCHINVAR	0
12144	07/21/2012	MI75S6FBN	BRADFORD-WHITE	1
12145	07/07/2008	LTN050GEF	LOCHINVAR	1
12146	07/30/2011	MI5036FBN	BRADFORD-WHITE	0
12147	11/26/2008	22DV50C	RHEEM	0
12148	05/07/2007	LTN050G	LOCHINVAR	0
12149	09/13/2000	PRV50NODS	STATE	0
12150	01/11/2003	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12151	12/26/2007	LTN050GEF	LOCHINVAR	1
12152	03/31/2006	LTN040G	LOCHINVAR	0
12153	11/15/2012	MI403S6FBN	BRADFORD-WHITE	0
12154	02/26/1990	21V506	RHEEM	0
12155	12/10/2004	LTN050G	LOCHINVAR	0
12156	05/12/2004	XVR50	A. O. SMITH	0
12157	12/22/2005	GVC50	A. O. SMITH	2
12158	01/05/1990	FSG50	AO SMITH	0
12159	09/26/1999	41XR40	RHEEM	0
12160	03/18/2008	22DV50C	RHEEM	0
12161	03/30/2011	22DV50F	RHEEM	0
12162	01/26/2011	21VR40	RHEEM	0
12163	12/10/2010	21VR50	RHEEM	0
12164	06/24/2008	LTN050GEF	LOCHINVAR	0
12165	07/15/2000	41XR50	RHEEM	1
12166	01/19/2005	LTN040	LOCHINVAR	0
12167	03/25/2002	PRX50	STATE	4
12168	09/10/2010	PVR50	AO SMITH	0
12169	11/02/1989	FSG50	AO SMITH	0
12170	03/24/2006	PR650	STATE	0
12171	12/07/2010	21VR50	RHEEM	0
12172	02/13/2006	LTN051G	LOCHINVAR	0
12173	06/25/2001	PGR50	AO SMITH	0
12174	03/09/2004	21V506	RHEEM	0
12175	09/30/1999	41V50S	RHEEM	0
12176	02/27/2004	PRX50	STATE	0
12177	06/19/2007	PR650	STATE	0
12178	03/17/2008	22DV50C	RHEEM	0
12179	11/22/2005	LTN050G	LOCHINVAR	0
12180	11/16/2002	PRX40	STATE	1
12181	11/15/2001	PGR50	AO SMITH	0
12182	02/12/2002	FSGL40	AO SMITH	0
12183	08/06/2007	LTN051G	LOCHINVAR	0
12184	03/01/2005	41VR50	RHEEM	0
12185	05/16/2001	21V506	RHEEM	1
12186	10/18/2011	M45036FBN	BRADFORD-WHITE	0
12187	02/15/2001	41XR50	RHEEM	0
12188	01/02/2006	41VR50	RHEEM	1
12189	02/24/2005	21DV50	RHEEM	0
12190	07/07/2007	LTN050G	LOCHINVAR	0
12191	08/08/1989	FSG50	AO SMITH	0
12192	07/24/1998	FGR50	AO SMITH	0
12193	09/07/2007	LTN050GEF	LOCHINVAR	1
12194	05/16/2002	FSG50	AO SMITH	0
12195	08/17/2005	LTN050GEF	LOCHINVAR	0
12196	09/11/2009	LTN050GEF	LOCHINVAR	0
12197	10/28/2011	DS150S6FBN	BRADFORD-WHITE	1
12198	02/27/2001	41XR50	RHEEM	0
12199	04/07/1995	PR502T	RUUD	0
12200	11/11/2012	PRV50NODS	STATE	0
12201	01/30/1996	FGR50	AO SMITH	0
12202	10/11/1998	FGR50	AO SMITH	0
12203	07/30/2012	PH2DV50F	RUUD	2
12204	04/30/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12205	06/29/2009	22DV50C	RHEEM	0
12206	02/13/2010	LTN050GEF	LOCHINVAR	0
12207	05/17/2005	LTN040	LOCHINVAR	0
12208	11/20/2003	PVR50	AO SMITH	2
12209	10/30/2000	PGR50	AO SMITH	0
12210	10/04/2002	FSG50	AO SMITH	0
12211	02/25/2009	LTN050G	LOCHINVAR	0
12212	04/19/2002	PGR50	AO SMITH	0
12213	12/16/2010	42VR50	RHEEM	0
12214	09/08/2009	21DV50	RHEEM	0
12215	10/23/1990	FSG50	AO SMITH	0
12216	07/30/2007	LTN050G	LOCHINVAR	1
12217	12/26/2004	XVR50	A. O. SMITH	0
12218	02/04/2006	PR650	STATE	0
12219	05/02/1999	41VR50	RHEEM	0
12220	09/24/2009	LTN050GEF	LOCHINVAR	0
12221	03/29/1990	PRV50NODS	STATE	0
12222	04/14/2007	LTN050G	LOCHINVAR	0
12223	03/05/2013	M45036FBN	BRADFORD-WHITE	1
12224	01/26/2009	LTN050GEF	LOCHINVAR	0
12225	01/18/2006	PR650X0DS	STATE	0
12226	06/25/2000	41XR50	RHEEM	0
12227	05/22/2009	LTN050GEF	LOCHINVAR	0
12228	09/27/2002	PGR50	AO SMITH	0
12229	12/10/2007	LTN050GEF	LOCHINVAR	0
12230	10/11/2003	PGR50	AO SMITH	0
12231	07/02/2005	PR650	STATE	0
12232	10/01/2012	MI5036FBN	BRADFORD-WHITE	1
12233	01/27/2006	LTN050G	LOCHINVAR	0
12234	03/26/2008	21DV50	RHEEM	0
12235	03/09/1990	FSG50	AO SMITH	0
12236	02/27/2013	M45036FBN	BRADFORD-WHITE	0
12237	03/24/2006	LTN050GEF	LOCHINVAR	1
12238	02/26/2007	LTN050G	LOCHINVAR	0
12239	03/01/2005	PRX50	STATE	0
12240	01/23/2007	LTN050G	LOCHINVAR	1
12241	02/01/2008	21DV50	RHEEM	0
12242	08/15/1991	FSG50	AO SMITH	0
12243	10/12/2002	PGR50	AO SMITH	0
12244	02/15/1991	FSG50	AO SMITH	0
12245	04/11/2008	LTN050GEF	LOCHINVAR	3
12246	02/03/2000	21V506	RHEEM	1
12247	12/10/2007	LTN050G	LOCHINVAR	0
12248	10/23/2000	PGR50	AO SMITH	0
12249	03/13/1997	FSG50	AO SMITH	0
12250	11/16/1990	FSG40	AO SMITH	0
12251	10/08/2011	D71DUMMY	UNKNOWN AT CONVERSION	0
12252	01/10/2004	21DV50	RHEEM	0
12253	04/17/2012	MI5036FBN	BRADFORD-WHITE	0
12254	07/06/2006	LTN050G	LOCHINVAR	0
12255	04/12/2004	PRX50	STATE	0
12256	01/20/2009	LTN050GEF	LOCHINVAR	1
12257	10/25/2012	MI5036FBN	BRADFORD-WHITE	0
12258	08/02/2010	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12259	09/30/2009	LTN050GEF	LOCHINVAR	0
12260	10/06/2005	LTN050G	LOCHINVAR	0
12261	07/31/2008	LTN050GEF	LOCHINVAR	0
12262	01/27/2005	GDVS50	AOSMITH	0
12263	06/20/2009	LTN050GEF	LOCHINVAR	0
12264	11/24/2008	LTN050GEF	LOCHINVAR	0
12265	02/17/2006	PR650	STATE	0
12266	11/06/2008	LTN050GEF	LOCHINVAR	0
12267	03/02/2006	LTN050G	LOCHINVAR	0
12268	09/14/2004	GVC50	A. O. SMITH	0
12269	08/27/1998	PHR50	RUUD	0
12270	05/15/2005	LTN050	LOCHINVAR	0
12271	12/06/2006	PR650	STATE	0
12272	11/12/2010	42VR50	RHEEM	0
12273	07/21/2001	21V407	RHEEM	0
12274	01/27/1992	P506	RUUD	0
12275	01/15/1991	FSG50	AO SMITH	0
12276	03/01/2002	PGR50	AO SMITH	0
12277	04/01/2008	22DV50C	RHEEM	0
12278	09/03/2002	PGR50	AO SMITH	0
12279	05/23/1991	21V502	RHEEM	0
12280	10/19/2007	ETN076	LOCHINVAR	0
12281	08/11/2010	LTN050G	LOCHINVAR	1
12282	02/08/1991	FSG40	AO SMITH	0
12283	04/16/2011	42VR50	RHEEM	0
12284	07/05/2011	22DV50F	RHEEM	0
12285	05/23/2007	LTN050G	LOCHINVAR	0
12286	02/25/1992	PRX50	STATE	0
12287	06/30/1992	PRX40	STATE	0
12288	05/27/2011	41VR50	RHEEM	0
12289	08/01/2011	22DV50F	RHEEM	0
12290	09/29/2006	LTN050G	LOCHINVAR	0
12291	03/19/2012	MI5036FBN	BRADFORD-WHITE	0
12292	05/16/2011	21VR50	RHEEM	0
12293	02/02/2004	G82156	RUUD/RHEEM	1
12294	03/21/2002	PGR50	AO SMITH	1
12295	08/26/2012	MI5036FBN	BRADFORD-WHITE	0
12296	07/19/2007	LTN050GEF	LOCHINVAR	0
12297	12/07/2010	42VR50	RHEEM	0
12298	02/07/2013	MI5036FBN	BRADFORD-WHITE	0
12299	01/29/2009	LTN040GEF	LOCHINVAR	0
12300	12/20/2007	LTN051G	LOCHINVAR	0
12301	05/06/2007	PR650	STATE	0
12302	10/01/2009	LTN040GEF	LOCHINVAR	0
12303	05/02/2012	M45036FBN	BRADFORD-WHITE	0
12304	04/18/2012	PH2DV50F	RUUD	2
12305	12/03/2008	LTN050GEF	LOCHINVAR	0
12306	02/22/2003	FSG50	AO SMITH	0
12307	06/08/2010	G75125	RUUD/RHEEM	0
12308	04/24/2004	XTN050	LOCHINVAR	0
12309	12/03/2006	FSG50	AO SMITH	0
12310	04/01/2010	LTN030G	AO SMITH	0
12311	10/05/1992	RF67120	RUUD	0
12312	10/27/2005	LTN050GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12313	01/25/2011	G91200	RUUD/RHEEM	2
12314	12/23/1992	FSGL40	AO SMITH	0
12315	10/07/1992	PRX50	STATE	0
12316	02/02/2006	PR640	STATE	0
12317	08/03/2007	LTN050GEF	LOCHINVAR	0
12318	03/11/1992	G82156	RUUD/RHEEM	0
12319	05/23/2008	LTN051G	LOCHINVAR	0
12320	07/26/2003	FSG50	AO SMITH	0
12321	05/22/1992	21V502	RHEEM	0
12322	11/01/2004	PRX50	STATE	1
12323	06/23/2010	LTN050G	LOCHINVAR	0
12324	02/16/2010	LTN050GEF	LOCHINVAR	0
12325	06/07/2005	21V506	RHEEM	0
12326	12/03/1992	FSG50	AO SMITH	0
12327	07/15/2004	XVR50	A. O. SMITH	1
12328	01/15/1992	FSG50	AO SMITH	0
12329	01/21/2010	LTN050GEF	LOCHINVAR	0
12330	03/02/2001	PGR50	AO SMITH	0
12331	03/28/2001	FSG40	AO SMITH	0
12332	01/13/2004	PVR50	AO SMITH	0
12333	03/16/1997	FGR50	AO SMITH	0
12334	07/18/2008	LTN050GEF	LOCHINVAR	0
12335	04/29/2010	LTN051G	LOCHINVAR	0
12336	12/05/2005	LTN050G	LOCHINVAR	1
12337	02/28/2012	MI5036FBN	BRADFORD-WHITE	0
12338	10/26/2010	21V506	RHEEM	2
12339	04/07/2012	PH2DV50F	RUUD	0
12340	03/18/1993	FSG50	AO SMITH	0
12341	09/18/2004	21V506	RHEEM	0
12342	07/15/2010	22V50F1	RHEEM	1
12343	01/25/2008	LTN050GEF	LOCHINVAR	1
12344	05/22/1997	FGR50	AO SMITH	0
12345	06/14/2007	LTN050GEF	LOCHINVAR	0
12346	04/20/1990	PRV50NODS	STATE	0
12347	03/28/2005	21V506	RHEEM	0
12348	07/10/2000	FSG50	AO SMITH	0
12349	10/19/1990	FSGL40	AO SMITH	0
12350	10/21/2011	MI40T6FBN	BRADFORD-WHITE	5
12351	10/19/2011	M45036FBN	BRADFORD-WHITE	0
12352	01/26/2009	LTN040G	LOCHINVAR	0
12353	04/15/1999	FSG50	AO SMITH	0
12354	01/14/2008	LTN050G	LOCHINVAR	0
12355	04/06/2001	41XR50	RHEEM	0
12356	07/17/2010	LSN041G	LOCHINVAR	0
12357	08/03/2012	MI40T6FBN	BRADFORD-WHITE	0
12358	11/07/2003	PRX50	STATE	0
12359	02/26/2010	LTN050GEF	LOCHINVAR	0
12360	06/03/2011	41VR50	RHEEM	0
12361	11/10/2006	LTN050G	LOCHINVAR	0
12362	10/21/1999	41XR50	RHEEM	0
12363	08/13/2010	LTN050GEF	LOCHINVAR	0
12364	05/17/2000	41XR50	RHEEM	0
12365	10/29/2000	41XR50	RHEEM	0
12366	12/22/2004	42XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12367	03/02/2010	LTN050GEF	LOCHINVAR	0
12368	02/22/2007	LTN050G	LOCHINVAR	0
12369	08/28/2007	LTN050GEF	LOCHINVAR	1
12370	01/05/2008	LTN050GEF	LOCHINVAR	0
12371	01/04/2012	M45036FBN	BRADFORD-WHITE	0
12372	09/06/2011	MI40T6FBN	BRADFORD-WHITE	0
12373	06/04/2010	LTN050G	LOCHINVAR	0
12374	05/19/2003	PRX50	STATE	0
12375	03/10/2005	XVR50	A. O. SMITH	0
12376	08/29/2011	M45036FBN	BRADFORD-WHITE	1
12377	12/31/2006	P506	RUUD	0
12378	11/02/2005	H72DUMMY	AO SMITH	0
12379	01/17/2007	LTN050G	LOCHINVAR	0
12380	04/21/2004	XTN050	LOCHINVAR	0
12381	12/06/1989	P505	RUUD	0
12382	03/15/2007	LTN050G	LOCHINVAR	0
12383	05/08/1989	FSG50	AO SMITH	0
12384	01/24/2003	21DV50	RHEEM	1
12385	06/09/2000	G75125	RUUD/RHEEM	0
12386	01/15/2008	LTN050GEF	LOCHINVAR	1
12387	06/16/2005	LTN050	LOCHINVAR	0
12388	08/21/2004	42XR50	RHEEM	0
12389	08/27/2008	LTN050GEF	LOCHINVAR	0
12390	07/31/2009	22DV50C	RHEEM	0
12391	02/11/2012	G91200	RUUD/RHEEM	1
12392	12/22/2007	LTN050GEF	LOCHINVAR	0
12393	07/15/2005	G75125	RUUD/RHEEM	0
12394	04/10/2005	PRX50	STATE	0
12395	05/24/2010	D74DUMMY	AO SMITH	1
12396	10/28/2005	LTN050G	LOCHINVAR	0
12397	03/28/2003	21DV50	RHEEM	0
12398	10/28/1993	P506	RUUD	0
12399	12/28/2012	MI5036FBN	BRADFORD-WHITE	0
12400	11/13/2000	FSG50	AO SMITH	0
12401	08/16/1989	FSG50	AO SMITH	0
12402	11/03/2012	M45036FBN	BRADFORD-WHITE	0
12403	12/09/1997	PGR50	AO SMITH	0
12404	01/16/2009	LTN050GEF	LOCHINVAR	0
12405	05/22/2007	LTN050GEF	LOCHINVAR	0
12406	03/09/2007	LTN050G	LOCHINVAR	0
12407	10/27/2005	LTN050G	LOCHINVAR	0
12408	10/31/2008	PRV50NODS	STATE	0
12409	01/31/1990	FSG50	AO SMITH	0
12410	07/11/1995	PHR50	RUUD	0
12411	02/25/2005	21DV50	RHEEM	0
12412	07/14/2008	42VR50	RHEEM	0
12413	01/23/1990	FSG50	AO SMITH	0
12414	09/06/2011	42V5065F	RHEEM	0
12415	02/21/2007	LTN050G	LOCHINVAR	0
12416	11/24/2010	42VR50	RHEEM	0
12417	05/20/2011	FSG50	AO SMITH	0
12418	11/07/2001	41VR50	RHEEM	0
12419	05/22/2009	22DV50C	RHEEM	0
12420	05/05/2008	22DV50C	RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12421	06/22/2010	LTN050GEF	LOCHINVAR	0
12422	01/15/1990	21V506	RHEEM	0
12423	04/28/2008	LTN051	LOCHINVAR	0
12424	01/28/1999	41VR50	RHEEM	0
12425	02/20/2008	LTN040	LOCHINVAR	0
12426	09/14/2009	21V502	RHEEM	0
12427	01/22/1990	21V506	RHEEM	0
12428	09/14/2010	21V502	RHEEM	0
12429	04/08/2011	22DV50F	RHEEM	0
12430	10/28/1996	FSG50	AO SMITH	0
12431	09/27/2001	PRX50	STATE	0
12432	10/02/2002	PGR50	AO SMITH	0
12433	11/10/2007	LTN050G	LOCHINVAR	0
12434	06/19/2002	PGR50	AO SMITH	0
12435	02/25/2008	21DV50	RHEEM	2
12436	06/06/1997	FSG50	AO SMITH	0
12437	12/27/2004	G75125	RUUD/RHEEM	0
12438	01/13/2000	FSGL40	AO SMITH	0
12439	11/13/2008	LTN050GEF	LOCHINVAR	0
12440	04/13/2009	LTN050GEF	LOCHINVAR	1
12441	07/06/2006	PR650	STATE	0
12442	09/17/2002	21V506	RHEEM	0
12443	03/10/1993	FSG40	AO SMITH	0
12444	05/26/2009	LTN050GEF	LOCHINVAR	0
12445	05/11/2011	42VR50	RHEEM	0
12446	06/01/2011	41VR50	RHEEM	0
12447	11/15/2005	LTN050G	LOCHINVAR	0
12448	03/10/1993	FSG50	AO SMITH	0
12449	01/06/2011	42VR50	RHEEM	1
12450	02/05/1999	42VR50	RHEEM	0
12451	04/03/2000	FSG50	AO SMITH	0
12452	04/11/2006	PR650	STATE	0
12453	07/06/2000	PRX50	STATE	0
12454	08/23/1999	PRV50NODS	STATE	0
12455	04/11/2007	PR650	STATE	2
12456	05/25/2012	MI5036FBN	BRADFORD-WHITE	0
12457	01/12/2002	FSG40	AO SMITH	0
12458	01/07/2009	LTN050G	LOCHINVAR	0
12459	11/17/2009	G82156	RUUD/RHEEM	0
12460	08/02/2005	LTN050G	LOCHINVAR	0
12461	02/03/2012	M45036FBN	BRADFORD-WHITE	1
12462	08/21/2002	PRX50	STATE	0
12463	11/14/2000	41VR50	RHEEM	0
12464	02/23/2012	M45036FBN	BRADFORD-WHITE	0
12465	12/13/1991	FSG50	AO SMITH	0
12466	11/09/1992	21V502	RHEEM	0
12467	03/07/2006	LTN050G	LOCHINVAR	0
12468	02/13/1992	FSG50	AO SMITH	0
12469	03/26/2007	LTN040GEF	LOCHINVAR	0
12470	08/21/2008	LTN050GEF	LOCHINVAR	0
12471	05/09/2002	FSGL40	AO SMITH	0
12472	09/12/2002	41V40S	RHEEM	1
12473	03/21/2009	ETN076	LOCHINVAR	0
12474	02/16/2005	GVR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12475	04/10/2007	PR650X0DS	STATE	0
12476	05/23/2012	MI5036FBN	BRADFORD-WHITE	2
12477	02/09/2012	M45036FBN	BRADFORD-WHITE	0
12478	01/25/2007	PR650X0DS	STATE	0
12479	02/03/1993	FSG50	AO SMITH	0
12480	04/16/2004	PVR50	AO SMITH	0
12481	09/07/1993	21V506	RHEEM	0
12482	06/02/2008	22DV50C	RHEEM	0
12483	02/11/2001	41XR50	RHEEM	0
12484	11/27/2000	41V50	RHEEM	0
12485	10/15/2003	21DV50	RHEEM	1
12486	01/18/2000	FSG40	AO SMITH	0
12487	07/15/2007	GVC50	A. O. SMITH	0
12488	08/31/2011	M45036FBN	BRADFORD-WHITE	2
12489	11/19/1998	FGR40	AO SMITH	0
12490	12/10/2005	LTN050GEF	LOCHINVAR	0
12491	05/22/2003	G91200	RUUD/RHEEM	1
12492	04/25/2000	PGR50	AO SMITH	1
12493	10/30/1991	FSG50	AO SMITH	0
12494	07/22/2009	LTN051G	LOCHINVAR	1
12495	08/04/2009	LTN051G	LOCHINVAR	0
12496	11/24/2010	42VR50	RHEEM	0
12497	04/26/2010	LTN050GEF	LOCHINVAR	0
12498	04/15/2009	LTN050G	LOCHINVAR	0
12499	07/12/2005	PR650	STATE	0
12500	01/29/2001	FSG50	AO SMITH	0
12501	03/07/2011	22DV50F	RHEEM	0
12502	03/22/2002	PGR50	AO SMITH	0
12503	11/16/2012	M45036FBN	BRADFORD-WHITE	0
12504	04/15/1991	P506	RUUD	0
12505	12/12/1991	FSG50	AO SMITH	0
12506	08/06/2012	MI5036FBN	BRADFORD-WHITE	0
12507	07/02/2007	LTN050G	LOCHINVAR	0
12508	03/16/2005	G91200	RUUD/RHEEM	1
12509	09/12/2001	FSG50	AO SMITH	0
12510	01/18/2002	FSG40	AO SMITH	0
12511	10/10/2012	M45036FBN	BRADFORD-WHITE	1
12512	07/01/2010	41V50	RHEEM	1
12513	01/18/2010	LTN050GEF	LOCHINVAR	0
12514	01/07/2008	LTN050GEF	LOCHINVAR	0
12515	04/19/2005	GCVL40	A. O. SMITH	0
12516	09/02/2012	M45036FBN	BRADFORD-WHITE	0
12517	10/05/2004	GVC50	A. O. SMITH	0
12518	02/03/2005	PRX50	STATE	0
12519	10/09/2008	22DV50C	RHEEM	0
12520	09/03/2003	PRX50	STATE	1
12521	10/01/2010	LSN041G	LOCHINVAR	0
12522	09/03/2010	41VR50	RHEEM	0
12523	09/12/2000	41V40S	RHEEM	0
12524	04/01/2009	LTN050G	LOCHINVAR	0
12525	04/07/2005	PRX50	STATE	0
12526	05/29/2012	MI5036FBN	BRADFORD-WHITE	0
12527	11/25/1990	FSG50	AO SMITH	0
12528	10/23/2000	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12529	09/09/2006	LTN050G	LOCHINVAR	0
12530	01/25/2007	PR650	STATE	1
12531	10/24/2011	MI5036FBN	BRADFORD-WHITE	0
12532	04/08/2003	21V506	RHEEM	0
12533	10/25/1993	FSG50	AO SMITH	0
12534	03/01/2004	PVR50	AO SMITH	1
12535	02/21/1991	FSG50	AO SMITH	0
12536	10/10/2011	PH2DV50F	RUUD	0
12537	04/24/2008	LTN050GEF	LOCHINVAR	0
12538	08/21/2009	LTN050GEF	LOCHINVAR	0
12539	01/23/2002	FSGL40	AO SMITH	1
12540	05/13/2003	G91200	RUUD/RHEEM	1
12541	08/08/1998	G91200	RUUD/RHEEM	1
12542	09/19/2005	XSN040GEF	LOCHINVAR	0
12543	09/20/2002	FSG50	AO SMITH	0
12544	01/03/2011	42VR5040F	RHEEM	0
12545	03/22/1990	FSG50	AO SMITH	0
12546	01/03/2002	FSG50	AO SMITH	0
12547	09/13/2001	PGR50	AO SMITH	0
12548	04/21/2001	21V506	RHEEM	0
12549	12/16/2010	21VR50	RHEEM	0
12550	10/16/2008	LTN050GEF	LOCHINVAR	0
12551	01/08/2000	FSG50	AO SMITH	1
12552	06/08/2009	LTN050GEF	LOCHINVAR	0
12553	12/08/2011	M45036FBN	BRADFORD-WHITE	0
12554	02/14/2006	PR650	STATE	0
12555	01/09/2013	P230F	RUUD	0
12556	03/18/2005	42VR506	RHEEM	0
12557	03/05/2011	22DV50F	RHEEM	0
12558	07/02/2009	LTN050GEF	LOCHINVAR	0
12559	10/14/2009	LTN040GEF	LOCHINVAR	0
12560	09/08/2010	22DV50F	RHEEM	1
12561	01/09/2009	LTN050GEF	LOCHINVAR	0
12562	01/04/2007	LTN050G	LOCHINVAR	0
12563	12/03/2008	LTN050G	LOCHINVAR	0
12564	09/02/2004	GDVS50	AOSMITH	0
12565	04/12/2012	22DV50F	RHEEM	0
12566	02/02/2007	G91200	RUUD/RHEEM	1
12567	03/23/2012	MI75S6FBN	BRADFORD-WHITE	0
12568	06/26/2002	FSG50	AO SMITH	0
12569	02/12/2009	22DV50C	RHEEM	0
12570	10/14/2011	M45036FBN	BRADFORD-WHITE	0
12571	11/17/2009	LTN050GEF	LOCHINVAR	0
12572	12/21/2009	LTN040GEF	LOCHINVAR	0
12573	09/18/2004	GVC40	A. O. SMITH	2
12574	04/23/2001	FSG40	AO SMITH	0
12575	12/13/2009	LTN050GEF	LOCHINVAR	0
12576	01/26/2013	MI403S6FBN	BRADFORD-WHITE	0
12577	02/28/2012	M45036FBN	BRADFORD-WHITE	1
12578	02/12/2009	LTN051G	LOCHINVAR	0
12579	05/08/2000	PGR50	AO SMITH	0
12580	08/03/2007	LTN050GEF	LOCHINVAR	0
12581	05/10/1996	PGR50	AO SMITH	0
12582	02/05/2011	42VR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12583	08/05/2009	22DV50F	RHEEM	0
12584	11/06/2010	FSG50	AO SMITH	0
12585	08/31/2012	MI5036FBN	BRADFORD-WHITE	0
12586	02/28/2011	42VR50	RHEEM	0
12587	08/28/2000	41XR50	RHEEM	0
12588	04/20/2004	FSG50	AO SMITH	1
12589	12/10/2012	PH2DV50F	RUUD	0
12590	04/26/2005	LTN050	LOCHINVAR	0
12591	09/03/2008	LTN050GEF	LOCHINVAR	0
12592	04/10/2008	LTN051G	LOCHINVAR	4
12593	04/08/2009	LTN050GEF	LOCHINVAR	0
12594	09/22/2011	MI40T6FBN	BRADFORD-WHITE	0
12595	07/13/2006	LTN050G	LOCHINVAR	0
12596	11/16/2006	LTN050G	LOCHINVAR	0
12597	06/05/1989	FSG50	AO SMITH	0
12598	09/25/1999	FSG50	AO SMITH	0
12599	08/21/2001	FSG50	AO SMITH	0
12600	09/06/2000	PGR50	AO SMITH	0
12601	10/27/2010	21VR50	RHEEM	0
12602	11/03/2005	LTN050G	LOCHINVAR	0
12603	02/08/1989	F72DUMMY	AO SMITH	0
12604	07/11/1989	FSG50	AO SMITH	0
12605	10/12/2012	M45036FBN	BRADFORD-WHITE	1
12606	09/24/2008	LTN050G	LOCHINVAR	0
12607	05/05/2005	LTN050	LOCHINVAR	1
12608	09/05/2008	LTN050GEF	LOCHINVAR	0
12609	06/03/2011	H72DUMMY	AO SMITH	0
12610	10/31/2002	PRX50	STATE	0
12611	02/12/2007	LTN050G	LOCHINVAR	0
12612	09/28/2012	MI5036FBN	BRADFORD-WHITE	0
12613	10/02/2007	LTN050GEF	LOCHINVAR	1
12614	06/25/2010	LTN050G	LOCHINVAR	0
12615	10/19/2010	21VR50	RHEEM	0
12616	02/13/2009	22DV50F	RHEEM	0
12617	11/07/1996	PGR40	AO SMITH	0
12618	11/20/2006	FSG50	AO SMITH	0
12619	11/27/2002	FSG50	AO SMITH	0
12620	05/17/2006	LTN051G	LOCHINVAR	0
12621	11/14/2011	MI5036FBN	BRADFORD-WHITE	0
12622	12/02/1991	PRX50	STATE	0
12623	04/08/2006	LTN050G	LOCHINVAR	0
12624	09/30/2010	41VR50	RHEEM	1
12625	05/23/2000	41XR50	RHEEM	0
12626	04/15/2002	FSG50	AO SMITH	0
12627	01/23/2008	PR650	STATE	1
12628	09/05/2004	GVC50	A. O. SMITH	0
12629	01/09/2013	MI50L6FBN	BRADFORD-WHITE	0
12630	06/19/1992	FSG40	AO SMITH	0
12631	02/27/2013	M45036FBN	BRADFORD-WHITE	0
12632	01/09/1992	G67114	RHEEM	0
12633	01/20/2010	LTN050GEF	LOCHINVAR	0
12634	03/11/2002	FSG50	AO SMITH	0
12635	04/01/2002	PGR50	AO SMITH	0
12636	04/15/2004	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12637	01/08/2001	PRX40	STATE	0
12638	12/03/2012	PH2DV50F	RUUD	0
12639	10/17/2012	MI5036FBN	BRADFORD-WHITE	0
12640	08/29/2000	PGR50	AO SMITH	0
12641	04/20/2003	FSG50	AO SMITH	0
12642	06/10/2008	LTN050GEF	LOCHINVAR	1
12643	03/28/2005	PRX50	STATE	1
12644	06/23/2012	MI5036FBN	BRADFORD-WHITE	0
12645	10/24/2006	LTN050GEF	LOCHINVAR	0
12646	10/26/2007	LTN050GEF	LOCHINVAR	0
12647	07/02/2008	LTN050GEF	LOCHINVAR	1
12648	12/30/2008	22DV50C	RHEEM	0
12649	01/12/2004	XTN050	LOCHINVAR	0
12650	12/30/2004	PRX50	STATE	0
12651	06/03/2010	LTN050G	LOCHINVAR	0
12652	06/23/2010	22DV50F	RHEEM	1
12653	10/25/2011	MI5036FBN	BRADFORD-WHITE	0
12654	08/28/2009	LTN050GEF	LOCHINVAR	0
12655	06/07/2010	LTN050G	LOCHINVAR	0
12656	12/02/2005	LTN050G	LOCHINVAR	0
12657	08/06/1992	21V502	RHEEM	0
12658	01/31/2013	M2XR504T6FBN	BRADFORD-WHITE	0
12659	12/01/2009	LTN050GEF	LOCHINVAR	0
12660	04/02/2012	M45036FBN	BRADFORD-WHITE	0
12661	09/16/2011	M45036FBN	BRADFORD-WHITE	0
12662	01/21/2004	PRX50	STATE	1
12663	06/02/2000	PGR50	AO SMITH	0
12664	04/10/2006	LTN050G	LOCHINVAR	0
12665	08/05/2003	FSG50	AO SMITH	0
12666	07/10/2009	LTN050GEF	LOCHINVAR	0
12667	11/23/2004	GCVL40	A. O. SMITH	0
12668	05/08/2008	LTN051G	LOCHINVAR	0
12669	07/09/2012	MI403S6FBN	BRADFORD-WHITE	0
12670	08/09/2010	LSN041G	LOCHINVAR	0
12671	04/27/1999	21V506	RHEEM	0
12672	12/05/2008	LTN050G	LOCHINVAR	0
12673	02/09/1998	41V40S	RHEEM	0
12674	02/24/2012	PH2DV50F	RUUD	0
12675	06/21/2010	LTN050GEF	LOCHINVAR	0
12676	01/13/2008	LTN050GEF	LOCHINVAR	0
12677	01/14/2003	21DV50	RHEEM	0
12678	11/04/2010	21VR50	RHEEM	0
12679	10/06/2005	LTN050GEF	LOCHINVAR	0
12680	06/06/2006	LTN050GEF	LOCHINVAR	0
12681	03/07/2008	LTN050GEF	LOCHINVAR	0
12682	03/22/2006	LTN050G	LOCHINVAR	0
12683	03/23/2001	FSGL40	AO SMITH	0
12684	12/29/2008	LTN050GEF	LOCHINVAR	0
12685	01/26/2013	M45036FBN	BRADFORD-WHITE	0
12686	07/08/2009	LTN050GEF	LOCHINVAR	0
12687	01/20/2010	LTN050G	LOCHINVAR	0
12688	01/13/2006	LTN050G	LOCHINVAR	0
12689	07/31/1991	FSGL40	AO SMITH	0
12690	02/20/1991	BTR120	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12691	11/24/2001	FGR50	AO SMITH	0
12692	12/05/2002	PGR50	AO SMITH	0
12693	11/01/2010	21VR50	RHEEM	0
12694	09/08/2004	GVC50	A. O. SMITH	2
12695	11/18/2006	LTN050G	LOCHINVAR	0
12696	06/19/2008	LTN050GEF	LOCHINVAR	0
12697	10/05/2007	LTN050GEF	LOCHINVAR	0
12698	05/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
12699	02/16/2012	MI5036FBN	BRADFORD-WHITE	0
12700	08/27/2009	LTN040G	LOCHINVAR	1
12701	04/23/2007	LTN050G	LOCHINVAR	0
12702	01/08/2010	LTN050GEF	LOCHINVAR	0
12703	05/29/2000	PHR50	RUUD	1
12704	01/06/2006	LTN050G	LOCHINVAR	0
12705	11/12/2004	PRX50	STATE	0
12706	11/25/1991	FSG50	AO SMITH	0
12707	12/21/2011	MI5036FBN	BRADFORD-WHITE	0
12708	10/05/1989	FSG50	AO SMITH	0
12709	05/19/2002	PGR50	AO SMITH	0
12710	10/15/2008	22DV50C	RHEEM	0
12711	02/07/2004	FCV50	AO SMITH	0
12712	09/08/2004	XVR50	A. O. SMITH	2
12713	05/29/1997	21VR502T	RHEEM	1
12714	05/05/2005	LTN050	LOCHINVAR	0
12715	02/15/2008	LTN050	LOCHINVAR	0
12716	11/16/2010	42VR50	RHEEM	0
12717	12/12/2012	PH2DV50F	RUUD	0
12718	07/16/2001	FSG50	AO SMITH	0
12719	07/09/2010	LTN050G	LOCHINVAR	1
12720	01/20/2012	PH2DV50F	RUUD	0
12721	05/26/2004	GVC50	A. O. SMITH	0
12722	03/23/2010	FSG50	AO SMITH	0
12723	03/26/2001	41XR50	RHEEM	0
12724	09/27/2007	LTN050GEF	LOCHINVAR	0
12725	12/27/2010	42VR50	RHEEM	0
12726	11/28/2005	LTN050G	LOCHINVAR	0
12727	01/08/2002	PGR50	AO SMITH	0
12728	08/30/2006	LTN050G	LOCHINVAR	0
12729	05/24/2002	G91200	RUUD/RHEEM	0
12730	07/07/2004	FSG50	AO SMITH	0
12731	12/15/2008	LTN050GEF	LOCHINVAR	0
12732	01/24/2013	D71DUMMY	UNKNOWN AT CONVERSION	0
12733	01/14/2013	G75125	RUUD/RHEEM	0
12734	08/01/1989	FSG50	AO SMITH	0
12735	09/29/1989	FSG50	AO SMITH	0
12736	10/12/2000	FSG50	AO SMITH	0
12737	11/27/2004	GVC50	A. O. SMITH	0
12738	10/04/2007	LTN050GEF	LOCHINVAR	0
12739	11/06/2007	PR640	STATE	0
12740	09/14/2001	21V506	RHEEM	0
12741	04/22/1998	FGR50	AO SMITH	0
12742	07/02/2003	FSGL40	AO SMITH	0
12743	10/25/2006	LSN041G	LOCHINVAR	0
12744	12/01/2006	LSN041G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12745	03/07/2012	MI5036FBN	BRADFORD-WHITE	0
12746	06/13/1989	FSG50	AO SMITH	0
12747	11/27/2003	PRX50	STATE	0
12748	04/25/2002	PRX50	STATE	0
12749	10/11/2004	XVR50	A. O. SMITH	0
12750	01/07/2009	22DV50F	RHEEM	1
12751	01/27/2005	GVC50	A. O. SMITH	0
12752	10/12/2011	MI5036FBN	Bradford-White	0
12753	08/09/1989	21V506	RHEEM	0
12754	06/17/2011	MI5036FBN	BRADFORD-WHITE	0
12755	11/17/2011	PH2DV50F	RUUD	0
12756	08/05/2003	41V50S	RHEEM	0
12757	01/26/2011	21VR50	RHEEM	0
12758	12/13/2005	LTN050GEF	LOCHINVAR	0
12759	10/31/2008	LTN050GEF	LOCHINVAR	0
12760	07/18/2004	XTN050	LOCHINVAR	0
12761	09/12/2012	M45036FBN	BRADFORD-WHITE	2
12762	02/15/2010	LTN050GEF	LOCHINVAR	0
12763	02/05/2008	PR650	STATE	0
12764	03/08/2004	PRX50	STATE	0
12765	06/12/2007	LTN050G	LOCHINVAR	0
12766	08/06/2008	LSN041G	LOCHINVAR	0
12767	07/29/2009	LTN050GEF	LOCHINVAR	0
12768	10/05/2009	LTN050GEF	LOCHINVAR	0
12769	03/25/2006	LTN050G	LOCHINVAR	0
12770	11/22/2004	GVC40	A. O. SMITH	2
12771	03/24/2008	LTN050	LOCHINVAR	0
12772	11/20/2012	DS140S6FBN	BRADFORD-WHITE	1
12773	02/15/2010	22DV50C	RHEEM	0
12774	12/29/1992	P506	RUUD	0
12775	12/26/2002	FSG50	AO SMITH	0
12776	02/22/2006	PR650	STATE	0
12777	12/29/1992	P506	RUUD	0
12778	02/06/2009	22DV50F	RHEEM	0
12779	05/09/2007	FSG30	AO SMITH	0
12780	12/26/2008	22DV50C	RHEEM	0
12781	12/19/2001	PGR50	AO SMITH	0
12782	01/19/1993	FSG50	AO SMITH	0
12783	06/22/2001	FSG50	AO SMITH	0
12784	10/07/2011	MI5036FBN	BRADFORD-WHITE	0
12785	10/30/2011	M45036FBN	BRADFORD-WHITE	1
12786	05/19/2008	LTN050GEF	LOCHINVAR	1
12787	07/19/2000	PHR40	RUUD	0
12788	06/17/2009	LTN050GEF	LOCHINVAR	0
12789	06/17/1992	FSG50	AO SMITH	0
12790	08/20/2009	22DV50C	RHEEM	1
12791	08/10/2011	M45036FBN	BRADFORD-WHITE	0
12792	03/04/2008	PR650X0DS	STATE	0
12793	07/23/1998	G67114	RHEEM	1
12794	09/27/2004	PRX50	STATE	0
12795	10/18/2001	G75125	RUUD/RHEEM	1
12796	02/06/2013	PH2DV50F	RUUD	0
12797	11/18/2004	21V506	RHEEM	0
12798	12/29/1992	PRV50NODS	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12799	05/08/2009	LTN050GEF	LOCHINVAR	0
12800	10/08/2006	PR650	STATE	0
12801	01/25/2004	XTN050	LOCHINVAR	0
12802	03/19/2013	M45036FBN	BRADFORD-WHITE	0
12803	10/16/2008	LTN050GEF	LOCHINVAR	0
12804	11/13/1992	FSG50	AO SMITH	1
12805	02/05/2003	PRX40	STATE	0
12806	06/02/2012	MI40T6FBN	BRADFORD-WHITE	0
12807	04/07/2011	42VR50	RHEEM	1
12808	05/17/2012	MI5036FBN	BRADFORD-WHITE	0
12809	09/06/2009	21VR50	RHEEM	1
12810	05/15/2005	LTN050G	LOCHINVAR	0
12811	03/08/2002	FSG50	AO SMITH	0
12812	09/24/1999	PHR50	RUUD	0
12813	11/08/1990	BTR197	AO SMITH	0
12814	05/12/2010	LTN050GEF	LOCHINVAR	0
12815	01/29/2003	PRX50	STATE	0
12816	08/25/2006	LTN050G	LOCHINVAR	0
12817	05/14/2012	MI5036FBN	BRADFORD-WHITE	0
12818	01/30/1999	FSG40	AO SMITH	1
12819	04/19/2012	M45036FBN	BRADFORD-WHITE	0
12820	02/01/2010	22DV50C	RHEEM	1
12821	08/03/2009	LTN050GEF	LOCHINVAR	2
12822	01/05/2009	PGR30	AO SMITH	0
12823	03/08/2007	LTN050G	LOCHINVAR	0
12824	08/23/2012	H72DUMMY	UNKNOWN AT CONVERSION	1
12825	12/05/2012	FSG50	AO SMITH	0
12826	10/13/2007	PR650	STATE	1
12827	12/10/2008	LTN050GEF	LOCHINVAR	0
12828	12/10/2002	PRX50	STATE	0
12829	09/27/1991	PH30	RUUD	1
12830	05/01/2002	FSGL40	AO SMITH	0
12831	07/15/1991	B71DUMMY	AMERICAN	0
12832	02/07/2008	PR650	STATE	0
12833	10/10/1991	SBT5065NE	AO SMITH	0
12834	07/26/2011	MI5036FBN	BRADFORD-WHITE	0
12835	01/26/2006	LTN050G	LOCHINVAR	0
12836	11/15/1999	PGR50	AO SMITH	0
12837	02/03/2011	21DV50	RHEEM	0
12838	01/11/2008	LTN050GEF	LOCHINVAR	0
12839	12/13/2001	PRX50	STATE	0
12840	09/22/2008	LTN050GEF	LOCHINVAR	0
12841	03/21/2001	G75125	RUUD/RHEEM	0
12842	10/26/2004	GDVS50	AOSMITH	0
12843	05/18/2001	21V506	RHEEM	0
12844	02/29/2012	PH2DV50F	RUUD	0
12845	03/28/2006	21DV50	RHEEM	0
12846	06/04/2003	41V50S	RHEEM	1
12847	03/22/2009	22DV50C	RHEEM	0
12848	06/06/2005	PR650	STATE	0
12849	08/11/1989	FSG50	AO SMITH	0
12850	12/30/2005	LTN050GEF	LOCHINVAR	0
12851	11/05/2010	21VR50	RHEEM	0
12852	08/29/2007	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12853	08/02/2004	SBF100199NES	STATE	0
12854	04/07/2011	41VR50	RHEEM	0
12855	09/24/2004	GVC40	A. O. SMITH	0
12856	10/23/2003	21V506	RHEEM	0
12857	10/11/2011	42V5065F	RHEEM	0
12858	02/01/2007	GVC50	A. O. SMITH	0
12859	01/31/2005	GVR50	AO SMITH	0
12860	02/07/1989	PRX50	STATE	0
12861	04/05/1989	FSG50	AO SMITH	0
12862	03/26/2012	M45036FBN	BRADFORD-WHITE	0
12863	05/29/2008	22DV50C	RHEEM	0
12864	03/19/2007	XTN050	LOCHINVAR	0
12865	08/25/2006	LTN050G	LOCHINVAR	1
12866	08/21/1989	P506	RUUD	0
12867	09/14/1997	PRV50NODS	STATE	0
12868	11/28/1998	BTC197	AO SMITH	0
12869	12/30/2004	GVC50	A. O. SMITH	0
12870	01/16/2009	LTN050GEF	LOCHINVAR	0
12871	02/08/2013	PH2DV50F	RUUD	0
12872	08/03/2006	LTN050G	LOCHINVAR	0
12873	06/04/2007	LTN050GEF	LOCHINVAR	0
12874	02/20/2013	M45036FBN	BRADFORD-WHITE	0
12875	05/22/2002	PRX50	STATE	0
12876	05/10/2010	G91200	RUUD/RHEEM	0
12877	01/26/2009	LTN050GEF	LOCHINVAR	0
12878	09/23/1999	FGR50	AO SMITH	0
12879	05/29/2003	FSG50	AO SMITH	0
12880	06/19/2001	G91200	RUUD/RHEEM	0
12881	10/23/2001	FSG50	AO SMITH	0
12882	09/25/2006	LTN050G	LOCHINVAR	0
12883	12/22/2002	PRX50	STATE	0
12884	10/22/2003	41XR50	RHEEM	0
12885	04/01/2010	LTN050GEF	LOCHINVAR	0
12886	02/22/1989	FSG50	AO SMITH	0
12887	02/26/1998	PRV40NODS	STATE	0
12888	06/14/2007	LSN041G	LOCHINVAR	0
12889	02/04/2013	MI5036FBN	BRADFORD-WHITE	0
12890	05/18/2004	XVR50	Lochinvar	1
12891	11/26/2002	PRX50	STATE	0
12892	06/22/2009	LTN050GEF	LOCHINVAR	0
12893	11/04/1999	PGR50	AO SMITH	0
12894	11/26/1998	FSG50	AO SMITH	0
12895	05/11/2012	P230F	RUUD	0
12896	08/14/1992	FSG50	AO SMITH	0
12897	10/21/2011	PRV50NODS	STATE	0
12898	04/07/1992	FSG50	AO SMITH	0
12899	12/10/1992	FSGL40	AO SMITH	0
12900	08/21/2004	42XR50	RHEEM	0
12901	12/06/2006	LTN050G	LOCHINVAR	0
12902	04/09/2007	G82156	RUUD/RHEEM	0
12903	09/19/2003	PGR50	AO SMITH	0
12904	10/15/2004	PRX40	STATE	0
12905	01/16/2013	MI5036FBN	BRADFORD-WHITE	1
12906	03/06/2005	XVR50	A. O. SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12907	06/12/2007	LTN050G	LOCHINVAR	0
12908	09/06/2007	LTN050G	LOCHINVAR	0
12909	02/19/2008	22DV50C	RHEEM	0
12910	12/01/2010	42VR50	RHEEM	0
12911	11/12/2009	21DV50	RHEEM	0
12912	10/02/2003	PVR50	AO SMITH	0
12913	04/02/1996	L72DUMMY	AO SMITH	1
12914	02/22/2006	LTN050G	LOCHINVAR	0
12915	10/08/2010	42VR50	RHEEM	0
12916	10/05/2004	PRX50	STATE	0
12917	01/26/2005	GVC40	A. O. SMITH	0
12918	04/09/2004	PRX50	STATE	0
12919	05/14/1992	21V506	RHEEM	0
12920	05/22/2012	MI403S6FBN	BRADFORD-WHITE	0
12921	03/31/2004	GVC40	A. O. SMITH	0
12922	01/30/1992	PRX50	STATE	0
12923	03/22/2009	LTN050GEF	LOCHINVAR	0
12924	01/01/2010	LTN050G	LOCHINVAR	0
12925	03/12/2012	MI5036FBN	BRADFORD-WHITE	2
12926	12/19/2005	PR650	STATE	0
12927	12/12/2009	LTN050GEF	LOCHINVAR	0
12928	03/22/2000	PGR50	AO SMITH	0
12929	08/06/2001	41V50	RHEEM	0
12930	03/24/1992	PRV50NODS	STATE	0
12931	02/23/2001	21V506	RHEEM	0
12932	10/19/2011	MI403S6FBN	BRADFORD-WHITE	1
12933	03/07/1992	FSG50	AO SMITH	0
12934	09/10/2007	LTN050GEF	LOCHINVAR	0
12935	05/16/2006	LTN050G	LOCHINVAR	0
12936	06/21/2010	22DV50C	RHEEM	0
12937	01/20/2012	M45036FBN	BRADFORD-WHITE	0
12938	09/10/2007	LTN050GEF	LOCHINVAR	0
12939	01/21/2009	LTN040GEF	LOCHINVAR	0
12940	03/05/2013	M45036FBN	BRADFORD-WHITE	0
12941	04/19/2011	21VR50	RHEEM	1
12942	02/27/2013	M45036FBN	BRADFORD-WHITE	0
12943	04/11/2008	LTN050GEF	LOCHINVAR	0
12944	05/29/2005	LTN050	LOCHINVAR	0
12945	03/30/2012	M45036FBN	BRADFORD-WHITE	0
12946	04/05/2009	22DV50C	RHEEM	0
12947	05/30/2008	LTN050GEF	LOCHINVAR	0
12948	09/10/2007	LTN050GEF	LOCHINVAR	0
12949	07/16/2008	P506	RUUD	1
12950	08/05/1991	B71DUMMY	AMERICAN	0
12951	05/05/2003	PGR50	AO SMITH	0
12952	09/29/2009	21V502	RHEEM	1
12953	07/18/2001	PGR50	AO SMITH	0
12954	01/08/1991	B71DUMMY	AMERICAN	0
12955	06/18/2010	LTN050G	LOCHINVAR	0
12956	06/19/2012	MI40T6FBN	BRADFORD-WHITE	0
12957	11/21/1991	FSG50	AO SMITH	0
12958	05/15/2007	LTN051G	LOCHINVAR	0
12959	04/03/1991	P506	RUUD	0
12960	03/08/2009	LTN050G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
12961	12/09/2005	G75125	RUUD/RHEEM	2
12962	10/07/2001	FSG50	AO SMITH	0
12963	09/19/2008	LTN050GEF	LOCHINVAR	0
12964	01/06/2007	LTN050G	LOCHINVAR	0
12965	08/02/2012	G75125	RUUD/RHEEM	0
12966	06/25/1991	FSG50	AO SMITH	0
12967	03/28/2012	M45036FBN	BRADFORD-WHITE	0
12968	02/27/1998	G67114	RHEEM	0
12969	05/26/2005	LTN050	LOCHINVAR	1
12970	03/31/2007	PR650	STATE	0
12971	01/02/2007	B71DUMMY	AMERICAN	0
12972	06/02/2005	XSN040	LOCHINVAR	1
12973	05/16/1999	41XR50	RHEEM	0
12974	09/26/2004	PRX50	STATE	0
12975	02/01/2013	M45036FBN	BRADFORD-WHITE	0
12976	07/07/2009	LTN050GEF	LOCHINVAR	1
12977	05/03/1999	FGR50	AO SMITH	0
12978	10/21/2007	LTN050G	LOCHINVAR	0
12979	07/13/2009	G75125	RUUD/RHEEM	0
12980	07/07/2008	22DV50C	RHEEM	0
12981	10/31/2010	LTN040G	LOCHINVAR	0
12982	05/30/2007	LTN050GEF	LOCHINVAR	0
12983	08/17/2004	XVR50	A. O. SMITH	1
12984	01/04/2011	42VR50	RHEEM	0
12985	11/08/2004	GVC50	A. O. SMITH	0
12986	11/17/2010	22DV50F	RHEEM	0
12987	03/17/2000	PGR50	AO SMITH	0
12988	08/04/2011	M45036FBN	BRADFORD-WHITE	0
12989	11/29/1989	FSG50	AO SMITH	0
12990	05/24/2000	FSG50	AO SMITH	0
12991	08/14/2008	21V506	RHEEM	0
12992	01/03/2003	FSG50	AO SMITH	0
12993	12/27/1997	PRV50NODS	STATE	0
12994	03/07/1989	H72DUMMY	AO SMITH	0
12995	05/01/2003	FSGL40	AO SMITH	1
12996	01/27/2013	M45036FBN	BRADFORD-WHITE	2
12997	10/30/2007	LTN050G	LOCHINVAR	1
12998	08/18/2009	LTN050GEF	LOCHINVAR	0
12999	12/13/2001	FSG50	AO SMITH	0
13000	04/29/2008	22DV50C	RHEEM	0
13001	03/10/2011	22DV50F	RHEEM	0
13002	02/17/2009	LTN050GEF	LOCHINVAR	0
13003	12/15/1988	FSG50	AO SMITH	0
13004	05/09/2006	LTN050G	LOCHINVAR	0
13005	01/11/2010	LTN050GEF	LOCHINVAR	0
13006	06/21/1998	FSG50	AO SMITH	0
13007	01/18/2001	FSG40	AO SMITH	0
13008	02/16/1989	FSG50	AO SMITH	0
13009	06/18/2010	LTN050G	LOCHINVAR	0
13010	01/20/2010	22DV50F	RHEEM	0
13011	04/23/2003	FSG50	AO SMITH	0
13012	09/25/1989	FSG50	AO SMITH	0
13013	02/25/2009	22DV50C	RHEEM	0
13014	06/04/2006	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13015	09/25/2000	FSG50	AO SMITH	0
13016	08/09/2003	PVR50	AO SMITH	2
13017	03/08/2007	LTN050G	LOCHINVAR	0
13018	05/25/2011	41VR50	RHEEM	0
13019	09/16/2003	FCVL40	AO SMITH	0
13020	06/28/2004	XVR50	A. O. SMITH	0
13021	10/29/1993	PRX50	STATE	0
13022	01/08/2001	FSG50	AO SMITH	0
13023	12/22/2011	M45036FBN	BRADFORD-WHITE	0
13024	06/13/2007	LTN050G	LOCHINVAR	0
13025	07/27/2006	LSN041G	LOCHINVAR	0
13026	06/18/2012	PH2DV50F	RUUD	0
13027	07/01/2008	22DV5038	RHEEM	0
13028	03/30/2004	PRX50	STATE	1
13029	06/09/2008	LTN050GEF	LOCHINVAR	0
13030	05/11/2006	PR650	STATE	0
13031	08/02/1989	PRV50NODS	STATE	0
13032	05/28/2005	LTN050	LOCHINVAR	0
13033	02/24/2010	LTN051G	LOCHINVAR	1
13034	02/13/2002	FSG40	AO SMITH	0
13035	07/13/2009	G75125	RUUD/RHEEM	1
13036	02/25/2010	LTN050GEF	LOCHINVAR	0
13037	02/03/2004	PRX50	STATE	0
13038	11/26/1991	FSG50	AO SMITH	0
13039	01/10/2011	21V502	RHEEM	0
13040	03/02/2011	42VR50	RHEEM	0
13041	11/28/2000	PRX50	STATE	1
13042	06/08/2007	LTN050GEF	LOCHINVAR	0
13043	04/26/2001	FSG50	AO SMITH	0
13044	01/13/2002	FSG50	AO SMITH	0
13045	03/27/2004	41XR50	RHEEM	1
13046	10/14/2010	41VR50	RHEEM	2
13047	10/08/2003	PGR50	AO SMITH	0
13048	08/11/2005	LTN050G	LOCHINVAR	0
13049	07/06/2004	GVC50	A. O. SMITH	0
13050	01/17/1991	BTR199	AO SMITH	0
13051	10/28/2009	LTN050GEF	LOCHINVAR	1
13052	04/25/2003	G82156	RUUD/RHEEM	0
13053	04/06/2011	21VR50	RHEEM	0
13054	01/17/1991	FSGL40	AO SMITH	0
13055	09/26/2004	PRX40	STATE	0
13056	04/03/2002	PRX50	STATE	0
13057	03/11/2005	GVC50	A. O. SMITH	0
13058	01/17/1991	FSGL40	AO SMITH	0
13059	01/20/1999	21DV50	RHEEM	0
13060	02/26/2011	42VR50	RHEEM	0
13061	12/19/2012	M45036FBN	BRADFORD-WHITE	0
13062	10/06/2005	LTN050G	LOCHINVAR	0
13063	11/16/2001	PGR50	AO SMITH	0
13064	04/14/2004	GVC50	A. O. SMITH	0
13065	09/24/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
13066	05/23/1991	P506	RUUD	0
13067	05/20/2002	FSG50	AO SMITH	0
13068	10/09/1991	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13069	11/17/2000	41XR50	RHEEM	0
13070	02/26/2007	PR650X0DS	STATE	0
13071	02/05/2010	41XR50	RHEEM	0
13072	11/12/2004	FSG50	AO SMITH	0
13073	10/10/2001	FSG40	AO SMITH	0
13074	10/25/1991	F72DUMMY	AO SMITH	0
13075	03/29/1999	FSG40	AO SMITH	0
13076	01/23/2011	41VR50	RHEEM	1
13077	05/23/2007	LTN050GEF	LOCHINVAR	2
13078	01/03/2008	P506	RUUD	1
13079	09/09/2007	LTN050GEF	LOCHINVAR	0
13080	01/05/2001	41XR50	RHEEM	1
13081	09/09/2010	41VR50	RHEEM	1
13082	06/02/2007	LTN050GEF	LOCHINVAR	2
13083	03/15/2002	FSG50	AO SMITH	0
13084	11/03/1992	FSG50	AO SMITH	0
13085	05/21/2005	LTN040	LOCHINVAR	0
13086	04/17/1993	P506	RUUD	0
13087	04/03/2009	22DV50C	RHEEM	0
13088	03/04/2010	LTN050G	LOCHINVAR	0
13089	04/12/2002	FSGL40	AO SMITH	0
13090	01/30/2010	LTN050GEF	LOCHINVAR	0
13091	10/28/2002	FSG50	AO SMITH	0
13092	03/23/1992	FSGL40	AO SMITH	0
13093	02/22/2011	42VR50	RHEEM	0
13094	10/09/2012	PH2DV50F	RUUD	0
13095	10/08/2005	LTN050G	LOCHINVAR	0
13096	12/29/1992	21V506	RHEEM	0
13097	05/08/2007	LTN051G	LOCHINVAR	0
13098	12/16/2007	LTN050GEF	LOCHINVAR	0
13099	02/27/2004	PVR50	AO SMITH	0
13100	09/24/2007	LTN050G	LOCHINVAR	1
13101	12/13/2006	LTN040G	LOCHINVAR	0
13102	11/21/2002	BTR120	AO SMITH	1
13103	10/16/1992	F72DUMMY	AO SMITH	0
13104	02/11/1992	FSG50	AO SMITH	0
13105	09/02/2010	LTN050GEF	LOCHINVAR	0
13106	03/18/1999	FGR50	AO SMITH	0
13107	12/16/1992	FSG40	AO SMITH	0
13108	06/12/2006	LTN050G	LOCHINVAR	0
13109	02/07/2007	LTN050G	LOCHINVAR	0
13110	10/31/2008	LSN041G	LOCHINVAR	0
13111	11/10/2010	21VR50	RHEEM	0
13112	06/02/2005	PR650	STATE	0
13113	03/02/2012	M45036FBN	BRADFORD-WHITE	0
13114	12/11/1992	FSG50	AO SMITH	0
13115	07/27/2009	22DV50C	RHEEM	2
13116	05/18/2009	22DV50C	RHEEM	0
13117	05/12/2009	LTN050GEF	LOCHINVAR	0
13118	01/23/2002	FSG50	AO SMITH	0
13119	08/12/2011	PH2DV50F	RUUD	3
13120	05/30/2005	LTN050	LOCHINVAR	2
13121	12/11/2007	LTN050GEF	LOCHINVAR	0
13122	10/19/1992	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13123	12/29/2006	PR650	STATE	1
13124	07/09/2008	LTN050GEF	LOCHINVAR	1
13125	12/29/1992	FSG50	AO SMITH	0
13126	08/03/2009	G82156	RUUD/RHEEM	0
13127	10/21/1992	FSG50	AO SMITH	0
13128	10/02/2009	LTN050GEF	LOCHINVAR	1
13129	04/21/2011	21VR50	RHEEM	0
13130	01/02/2009	LSN041G	LOCHINVAR	0
13131	07/17/2007	LTN050GEF	LOCHINVAR	0
13132	10/01/2002	21V506	RHEEM	0
13133	09/05/1999	PRV50NODS	STATE	0
13134	07/10/2006	PR650	STATE	0
13135	09/27/2005	LTN050GEF	LOCHINVAR	0
13136	12/26/1988	FSG50	AO SMITH	0
13137	10/21/2009	FSG50	AO SMITH	0
13138	02/19/2004	PRX50	STATE	0
13139	04/03/1989	FSG50	AO SMITH	0
13140	06/26/1989	P506	RUUD	0
13141	10/08/2001	PGR50	AO SMITH	2
13142	07/02/2004	GVC50	A. O. SMITH	0
13143	07/14/2011	PH2DV50F	RUUD	0
13144	09/10/2010	42VR50	RHEEM	0
13145	08/22/2008	LTN050GEF	LOCHINVAR	2
13146	03/13/2003	PRX50	STATE	0
13147	07/22/2009	LTN050GEF	LOCHINVAR	0
13148	03/04/2004	GVC50	A. O. SMITH	0
13149	01/09/2004	XTN050	LOCHINVAR	0
13150	11/08/2010	42VR50	RHEEM	0
13151	08/12/1997	PGR50	AO SMITH	1
13152	02/26/2009	LTN050GEF	LOCHINVAR	0
13153	12/21/2001	PRX50	STATE	0
13154	07/11/2006	LTN050G	LOCHINVAR	0
13155	07/13/2004	XVR50	A. O. SMITH	0
13156	01/30/2006	LTN050G	LOCHINVAR	0
13157	07/20/2009	G91200	RUUD/RHEEM	1
13158	02/11/2011	22DV50F	RHEEM	2
13159	09/08/2009	21V502	RHEEM	0
13160	01/17/2007	LTN050G	LOCHINVAR	0
13161	10/04/2001	FSGL40	AO SMITH	0
13162	09/02/2009	22DV50C	RHEEM	0
13163	01/11/2006	LTN050G	LOCHINVAR	0
13164	03/10/2009	LTN050G	LOCHINVAR	0
13165	09/26/2008	LTN050G	LOCHINVAR	0
13166	05/02/2000	PHR50	RUUD	0
13167	01/28/2005	LTN050	LOCHINVAR	1
13168	05/24/2010	LTN050GEF	LOCHINVAR	0
13169	06/01/2009	LTN050GEF	LOCHINVAR	0
13170	06/26/2012	M45036FBN	BRADFORD-WHITE	0
13171	10/25/1991	F72DUMMY	AO SMITH	0
13172	08/16/2006	LTN050G	LOCHINVAR	0
13173	01/06/2007	LTN050G	LOCHINVAR	0
13174	08/15/2008	22DV50F	RHEEM	0
13175	10/10/1991	FSG50	AO SMITH	0
13176	03/19/2004	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13177	02/04/1991	FSG50	AO SMITH	0
13178	11/14/2006	LTN050GEF	LOCHINVAR	0
13179	08/09/2012	G91200	RUUD/RHEEM	0
13180	11/13/2006	G91200	RUUD/RHEEM	1
13181	09/25/2001	FSG50	AO SMITH	1
13182	10/25/1991	F72DUMMY	AO SMITH	0
13183	01/24/2011	21DV50	RHEEM	0
13184	03/25/2002	PGR50	AO SMITH	0
13185	04/18/2009	LTN050GEF	LOCHINVAR	1
13186	10/25/1991	F72DUMMY	AO SMITH	0
13187	04/11/2006	LTN050	LOCHINVAR	0
13188	01/26/2011	42VR50	RHEEM	0
13189	05/14/1991	FSG50	AO SMITH	0
13190	06/19/2008	LTN050GEF	LOCHINVAR	0
13191	03/21/2003	G75125	RUUD/RHEEM	0
13192	06/09/2012	MI40T6FBN	BRADFORD-WHITE	0
13193	04/30/2003	PGR50	AO SMITH	1
13194	06/16/2005	LTN040	LOCHINVAR	0
13195	02/08/2005	GDVS50	AOSMITH	0
13196	09/11/2002	PRX50	STATE	0
13197	01/12/2007	LTN040G	LOCHINVAR	0
13198	05/25/2006	LTN050G	LOCHINVAR	0
13199	04/03/2009	LTN050GEF	LOCHINVAR	0
13200	10/27/2011	M440T6FBN	BRADFORD-WHITE	1
13201	12/02/2008	LTN050GEF	LOCHINVAR	0
13202	03/23/2011	21VR50	RHEEM	0
13203	06/07/2007	LTN050GEF	LOCHINVAR	0
13204	11/21/2001	FSG40	AO SMITH	0
13205	06/15/2011	MI5036FBN	BRADFORD-WHITE	0
13206	07/24/2004	GVC40	A. O. SMITH	0
13207	12/02/2009	LTN050G	LOCHINVAR	0
13208	06/14/1991	FSG50	AO SMITH	0
13209	07/12/2010	21VR50	RHEEM	0
13210	07/24/2007	LTN050G	LOCHINVAR	0
13211	02/04/2010	LTN050GEF	LOCHINVAR	0
13212	03/31/2003	FSG50	AO SMITH	0
13213	09/14/2012	MI5036FBN	BRADFORD-WHITE	0
13214	08/25/2004	GVR50	AO SMITH	0
13215	07/02/2001	FSG50	AO SMITH	0
13216	07/22/2009	LTN050GEF	LOCHINVAR	0
13217	09/16/2004	XTN050	LOCHINVAR	0
13218	07/26/2010	LTN050	LOCHINVAR	0
13219	01/11/1989	PRX50	STATE	0
13220	04/21/2012	MI403S6FBN	BRADFORD-WHITE	0
13221	08/08/2009	LTN050GEF	LOCHINVAR	0
13222	04/15/2003	PR650	STATE	0
13223	11/08/2005	LTN050G	LOCHINVAR	0
13224	08/31/2010	42V5065F	RHEEM	0
13225	04/23/1996	PR502T	RUUD	0
13226	08/03/1989	FSGL40	AO SMITH	0
13227	04/12/2008	LTN040GEF	LOCHINVAR	0
13228	04/26/2006	LTN050G	LOCHINVAR	0
13229	12/27/2004	GVC50	A. O. SMITH	0
13230	12/15/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13231	03/23/2001	PGR50	AO SMITH	0
13232	03/19/2004	XTN050	LOCHINVAR	0
13233	11/22/2004	XTN050	LOCHINVAR	0
13234	03/24/2005	XVR50	A. O. SMITH	0
13235	05/27/2006	LTN050G	LOCHINVAR	0
13236	08/02/2004	XTN050	LOCHINVAR	0
13237	04/20/2010	22DV50F	RHEEM	0
13238	05/12/2005	LTN050	LOCHINVAR	0
13239	09/13/1989	FSG50	AO SMITH	0
13240	01/02/2010	22DV50F	RHEEM	1
13241	10/14/2008	LTN050GEF	LOCHINVAR	0
13242	05/06/2010	LTN050GEF	LOCHINVAR	1
13243	12/09/2010	42V5065F	RHEEM	0
13244	01/18/2000	41VR40	RHEEM	0
13245	01/12/2013	DS150S6FBN	BRADFORD-WHITE	0
13246	04/24/2012	MI5036FBN	BRADFORD-WHITE	0
13247	12/28/2006	LTN050G	LOCHINVAR	0
13248	08/27/2010	21V502	RHEEM	0
13249	12/06/2001	PGR50	AO SMITH	0
13250	12/12/2004	GVC50	A. O. SMITH	0
13251	12/01/2007	LTN050GEF	LOCHINVAR	1
13252	07/05/2000	21V506	RHEEM	0
13253	12/21/2000	41V50	RHEEM	0
13254	12/14/2009	LTN050GEF	LOCHINVAR	2
13255	12/08/1999	PGR50	AO SMITH	0
13256	01/02/2004	PRX50	STATE	0
13257	08/18/1992	P506	RUUD	0
13258	06/17/1992	P506	RUUD	0
13259	01/22/2009	LTN050GEF	LOCHINVAR	1
13260	12/13/2005	LTN050G	LOCHINVAR	0
13261	02/25/2009	LTN050GEF	LOCHINVAR	1
13262	09/23/2010	42VR50	RHEEM	0
13263	04/20/2004	GVC50	A. O. SMITH	0
13264	09/02/1992	FSG50	AO SMITH	0
13265	05/30/2006	LTN050G	LOCHINVAR	0
13266	03/24/1994	21VR50	RHEEM	0
13267	11/23/2009	LTN050GEF	LOCHINVAR	3
13268	06/24/1992	21V502	RHEEM	0
13269	03/07/2010	LTN050GEF	LOCHINVAR	0
13270	10/20/2011	MI5036FBN	BRADFORD-WHITE	0
13271	01/07/2003	FSG40	AO SMITH	0
13272	01/16/2013	MI5036FBN	BRADFORD-WHITE	4
13273	01/09/2008	LTN050G	LOCHINVAR	0
13274	05/15/2006	PR650	STATE	0
13275	10/29/2008	LTN050GEF	LOCHINVAR	0
13276	10/20/1992	FSG50	AO SMITH	1
13277	10/29/2008	LTN050GEF	LOCHINVAR	0
13278	05/13/2011	21VR50	RHEEM	0
13279	01/30/2009	LTN050G	LOCHINVAR	0
13280	05/23/2008	LTN050GEF	LOCHINVAR	0
13281	04/02/1992	21V502	RHEEM	0
13282	02/26/2003	BTR198	AO SMITH	0
13283	03/01/2008	LTN050GEF	LOCHINVAR	0
13284	04/17/2006	LTN050G	LOCHINVAR	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13285	03/24/2006	LTN050GEF	LOCHINVAR	0
13286	10/08/2008	22DV50F	RHEEM	0
13287	08/10/2010	LTN050G	LOCHINVAR	0
13288	06/27/2011	MI5036FBN	BRADFORD-WHITE	3
13289	07/15/2011	MI40T6FBN	BRADFORD-WHITE	0
13290	12/04/2007	PR650	STATE	0
13291	07/22/2009	LTN050GEF	LOCHINVAR	0
13292	02/08/2008	LSN041	LOCHINVAR	0
13293	09/25/2012	MI5036FBN	BRADFORD-WHITE	1
13294	02/13/2004	XTN050	LOCHINVAR	0
13295	02/02/2007	GVC50	A. O. SMITH	0
13296	01/13/1993	FSG50	AO SMITH	0
13297	03/03/2000	PGR50	AO SMITH	0
13298	09/30/2011	MI5036FBN	BRADFORD-WHITE	0
13299	10/14/2011	M45036FBN	BRADFORD-WHITE	1
13300	07/17/2007	LTN050GEF	LOCHINVAR	0
13301	04/14/2010	FGR50	AO SMITH	1
13302	08/29/2002	PRX50	STATE	1
13303	08/20/1992	FSG50	AO SMITH	0
13304	07/29/2012	MI5036FBN	BRADFORD-WHITE	0
13305	04/29/2002	PRX50	STATE	0
13306	10/14/2004	GVC50	A. O. SMITH	0
13307	04/16/2002	G75125	RUUD/RHEEM	0
13308	09/06/1989	PRX50	STATE	0
13309	06/23/2004	PRX50	STATE	0
13310	03/05/2004	XTN050	LOCHINVAR	0
13311	12/27/2005	GVC50	A. O. SMITH	1
13312	07/20/1994	FGR50	AO SMITH	0
13313	03/26/1999	FSG50	AO SMITH	0
13314	11/01/2003	41XR50	RHEEM	0
13315	07/14/2000	PGR50	AO SMITH	0
13316	10/05/2009	LTN050GEF	LOCHINVAR	2
13317	12/23/2004	PGR50	AO SMITH	0
13318	10/18/2012	PH2DV50F	RUUD	0
13319	10/06/2000	PRV40NODS	STATE	1
13320	11/11/2003	PVR50	AO SMITH	0
13321	02/24/2003	PRX40	STATE	0
13322	04/24/2001	FSG40	AO SMITH	0
13323	10/03/2012	G100200	RUUD/RHEEM	3
13324	03/24/2010	LTN050GEF	LOCHINVAR	0
13325	09/05/1989	FSG50	AO SMITH	1
13326	12/17/2003	FCV50	AO SMITH	0
13327	07/11/2012	M45036FBN	BRADFORD-WHITE	0
13328	08/30/2007	LTN050GEF	LOCHINVAR	1
13329	04/05/2011	21VR50	RHEEM	0
13330	10/13/2005	LTN050	LOCHINVAR	0
13331	01/03/2005	GVC50	A. O. SMITH	0
13332	11/13/2002	BTR120	AO SMITH	0
13333	03/07/2008	21DV50	RHEEM	1
13334	07/09/2007	PR650	STATE	0
13335	01/15/2009	22DV50C	RHEEM	0
13336	03/09/1989	FSGL40	AO SMITH	0
13337	02/09/2011	21VR50	RHEEM	0
13338	01/18/2002	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13339	05/27/2008	LTN051G	LOCHINVAR	0
13340	07/27/2009	LTN050GEF	LOCHINVAR	0
13341	10/22/2010	LTN040G	LOCHINVAR	0
13342	11/28/2011	G91200	RUUD/RHEEM	0
13343	05/02/2011	21VR50	RHEEM	0
13344	03/05/2009	LTN050GEF	LOCHINVAR	0
13345	09/10/2010	41VR50	RHEEM	1
13346	09/29/1999	FGR50	AO SMITH	0
13347	12/20/2009	LTN050G	LOCHINVAR	0
13348	03/05/2001	FSG50	AO SMITH	0
13349	04/18/2007	LTN050G	LOCHINVAR	0
13350	01/04/2008	PR650	STATE	0
13351	09/25/2008	22DV50F	RHEEM	0
13352	04/18/2011	21VR40	RHEEM	0
13353	02/14/2012	PRX50	STATE	0
13354	06/27/2011	MI50L6FBN	BRADFORD-WHITE	0
13355	02/02/2005	GDVS50	AOSMITH	0
13356	02/15/2005	GVC50	A. O. SMITH	0
13357	06/06/2011	21VR50	RHEEM	0
13358	05/31/2009	LTN050GEF	LOCHINVAR	0
13359	10/12/2002	PGR40	AO SMITH	0
13360	01/28/2005	GVC50	A. O. SMITH	0
13361	01/14/2010	LSN041G	LOCHINVAR	0
13362	04/22/2011	22DV50F	RHEEM	0
13363	08/25/2003	FSGL40	AO SMITH	1
13364	06/06/2006	LTN050G	LOCHINVAR	1
13365	02/01/2006	LTN050G	LOCHINVAR	0
13366	07/26/2005	LTN050G	LOCHINVAR	0
13367	04/01/2004	XVR50	A. O. SMITH	0
13368	10/14/2008	LTN050GEF	LOCHINVAR	0
13369	12/16/1992	21DV50	RHEEM	1
13370	07/09/2007	PR650	STATE	0
13371	11/12/2002	FSG50	AO SMITH	0
13372	08/05/2011	M45036FBN	BRADFORD-WHITE	0
13373	04/25/2011	22DV50F	RHEEM	0
13374	08/28/2009	LTN050GEF	LOCHINVAR	0
13375	06/30/2010	LTN050G	LOCHINVAR	0
13376	02/10/2005	21V506	RHEEM	0
13377	07/10/2012	M45036FBN	BRADFORD-WHITE	0
13378	01/06/2006	LTN051G	LOCHINVAR	0
13379	02/21/2012	MI75S6FBN	BRADFORD-WHITE	1
13380	11/13/2001	PGR50	AO SMITH	0
13381	06/24/2004	XTN050	LOCHINVAR	0
13382	01/14/2011	PRX50	STATE	0
13383	06/24/2004	PRX50	STATE	0
13384	10/08/2007	PR650X0DS	STATE	0
13385	09/26/2000	BTR154	AO SMITH	0
13386	12/24/2007	LTN050G	LOCHINVAR	0
13387	03/04/2013	M45036FBN	BRADFORD-WHITE	0
13388	08/08/2005	LTN050G	LOCHINVAR	0
13389	02/27/2009	22DV50C	RHEEM	0
13390	07/07/2006	LTN050G	LOCHINVAR	0
13391	03/28/2005	GVC50	A. O. SMITH	0
13392	07/21/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13393	10/21/1992	H72DUMMY	AO SMITH	0
13394	11/08/2005	PR650	STATE	0
13395	08/28/2010	22DV50C	RHEEM	1
13396	08/02/2011	22DV50F	RHEEM	0
13397	04/22/1993	RF82156	RUUD	0
13398	01/27/2009	LTN050GEF	LOCHINVAR	1
13399	07/09/2007	LTN050GEF	LOCHINVAR	0
13400	12/04/2002	21V407	RHEEM	0
13401	01/02/2003	FSG50	AO SMITH	0
13402	03/06/2007	PR650X0DS	STATE	0
13403	06/12/1992	FSG50	AO SMITH	0
13404	01/25/2002	PGR50	AO SMITH	0
13405	12/30/2002	PRX50	STATE	0
13406	09/28/2004	21V502	RHEEM	1
13407	09/01/2011	MI5036FBN	BRADFORD-WHITE	1
13408	05/14/2007	PR650X0DS	STATE	0
13409	02/17/1992	21V502	RHEEM	0
13410	06/22/2011	MI403S6FBN	BRADFORD-WHITE	0
13411	12/08/2011	M45036FBN	BRADFORD-WHITE	0
13412	02/10/2011	42V50SF	RHEEM	1
13413	04/30/1991	21V502	RHEEM	1
13414	07/26/2007	LTN050GEF	LOCHINVAR	0
13415	07/12/2006	PRV50NODS	STATE	1
13416	02/25/1991	FSG50	AO SMITH	0
13417	05/07/2009	PRX50	STATE	0
13418	04/13/2010	LTN050GEF	LOCHINVAR	0
13419	08/12/2012	PH2DV50F	RUUD	0
13420	01/20/2010	ETN076	LOCHINVAR	0
13421	03/20/2009	LTN050GEF	LOCHINVAR	0
13422	11/16/2007	LTN050GEF	LOCHINVAR	0
13423	04/10/2009	LTN050GEF	LOCHINVAR	0
13424	06/24/2004	21V506	RHEEM	0
13425	10/29/2006	PR650	STATE	0
13426	08/30/2006	PR650	STATE	1
13427	01/24/2011	42VR50	RHEEM	0
13428	03/12/2008	LTN050	LOCHINVAR	1
13429	06/04/2003	FDV50	AO SMITH	0
13430	10/31/1991	BTR120	AO SMITH	0
13431	10/04/1991	21V502	RHEEM	0
13432	05/25/2012	MI5036FBN	BRADFORD-WHITE	0
13433	02/07/2012	MI5036FBN	BRADFORD-WHITE	1
13434	06/03/2008	LTN050GEF	LOCHINVAR	0
13435	10/14/2011	M45036FBN	BRADFORD-WHITE	0
13436	12/08/2011	M45036FBN	BRADFORD-WHITE	0
13437	04/29/2005	LTN050	LOCHINVAR	1
13438	08/07/2012	PH2DV50F	RUUD	1
13439	03/11/2006	LTN050G	LOCHINVAR	1
13440	12/18/2003	PRX50	STATE	0
13441	02/24/2004	FCV50	AO SMITH	1
13442	10/09/2001	PGR50	AO SMITH	0
13443	02/21/2006	LTN050G	LOCHINVAR	0
13444	11/29/2012	MI50L6FBN	BRADFORD-WHITE	0
13445	04/28/2001	PRX50	STATE	1
13446	05/10/1991	P506	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13447	11/22/1989	FSG50	AO SMITH	0
13448	06/27/2005	ETN076	LOCHINVAR	1
13449	02/13/2004	41V50	RHEEM	0
13450	12/02/2011	PH2DV50F	RUUD	0
13451	01/09/1989	FSG50	AO SMITH	1
13452	01/23/2008	LTN050GEF	LOCHINVAR	0
13453	08/26/2010	PRX50	STATE	0
13454	06/01/2000	PRX50	STATE	0
13455	06/05/2009	22DV50F	RHEEM	0
13456	06/11/2008	LTN050GEF	LOCHINVAR	0
13457	08/25/2003	PRX50	STATE	0
13458	11/30/2007	LTN050GEF	LOCHINVAR	0
13459	07/26/2012	M45036FBN	BRADFORD-WHITE	0
13460	01/03/2006	22DV5038	RHEEM	0
13461	04/03/2008	22DV50C	RHEEM	0
13462	07/11/1989	FSG50	AO SMITH	0
13463	12/09/2003	FCV50	AO SMITH	0
13464	09/10/2001	41XR50	RHEEM	0
13465	02/04/2008	LTN050GEF	LOCHINVAR	0
13466	09/05/2006	PR650	STATE	0
13467	12/26/2006	LTN050G	LOCHINVAR	1
13468	08/26/2012	G91200	RUUD/RHEEM	2
13469	04/13/2007	LTN040G	LOCHINVAR	1
13470	05/20/2011	22DV50F	RHEEM	0
13471	07/26/2011	M45036FBN	BRADFORD-WHITE	1
13472	05/21/1996	PRX50	STATE	0
13473	03/18/2005	PVR50	AO SMITH	0
13474	10/14/2009	LTN050GEF	LOCHINVAR	0
13475	05/19/2003	PGR50	AO SMITH	0
13476	11/18/2005	LTN050G	LOCHINVAR	0
13477	05/09/2005	GDVS50	AOSMITH	0
13478	07/26/2010	FSG50	AO SMITH	0
13479	02/13/2008	LTN050G	LOCHINVAR	0
13480	06/30/2010	22DV50C	RHEEM	0
13481	03/12/2003	FSG50	AO SMITH	0
13482	02/18/2002	PGR50	AO SMITH	0
13483	12/23/2001	PGR50	AO SMITH	0
13484	09/08/2008	LTN051G	LOCHINVAR	0
13485	10/31/2008	LTN050GEF	LOCHINVAR	0
13486	07/10/2008	22DV50F	RHEEM	0
13487	11/06/2012	MI5036FBN	BRADFORD-WHITE	0
13488	10/17/2003	FSG50	AO SMITH	0
13489	03/23/2001	PR650	STATE	0
13490	07/30/2003	PRX50	STATE	0
13491	06/05/2007	LTN050G	LOCHINVAR	0
13492	01/30/2007	LTN050G	LOCHINVAR	1
13493	02/07/2009	LTN050GEF	LOCHINVAR	0
13494	09/23/2011	M45036FBN	BRADFORD-WHITE	2
13495	01/28/2002	21V506	RHEEM	0
13496	09/24/2010	42VR50	RHEEM	0
13497	09/26/2007	LTN050GEF	LOCHINVAR	0
13498	01/09/2009	LTN050GEF	LOCHINVAR	0
13499	12/04/2006	PRV50NORT	STATE	0
13500	06/28/2010	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13501	02/03/1998	PRX50	STATE	0
13502	12/26/2012	PH2DV50F	RUUD	0
13503	04/04/2005	GVC50	A. O. SMITH	1
13504	06/07/2007	LTN050GEF	LOCHINVAR	0
13505	11/13/2008	22DV50C	RHEEM	0
13506	02/24/1992	FSG50	AO SMITH	0
13507	10/06/2011	FSG50	AO SMITH	0
13508	06/10/2011	22DV50F	RHEEM	0
13509	07/30/2004	PRX50	STATE	0
13510	01/24/2000	21V506	RHEEM	0
13511	02/06/2007	LTN050G	LOCHINVAR	0
13512	07/28/2002	PRX50	STATE	0
13513	11/09/2009	LTN050GEF	LOCHINVAR	0
13514	04/16/2012	PH2DV50F	RUUD	0
13515	12/18/2003	PRX50	STATE	0
13516	10/14/2003	FCV50	AO SMITH	0
13517	09/17/1992	FSG50	AO SMITH	0
13518	12/12/2001	FSG50	AO SMITH	0
13519	09/07/2005	LTN050G	LOCHINVAR	0
13520	12/08/2003	PRX50	STATE	0
13521	06/10/1992	FSG50	AO SMITH	0
13522	09/27/2010	41VR50	RHEEM	0
13523	12/07/2011	DS150S6FBN	BRADFORD-WHITE	1
13524	10/19/2008	LSN041G	LOCHINVAR	1
13525	11/24/2012	M45036FBN	BRADFORD-WHITE	0
13526	02/23/2001	G91200	RUUD/RHEEM	2
13527	10/29/2004	GVC50	A. O. SMITH	1
13528	04/19/2009	22DV50C	RHEEM	0
13529	09/01/2006	LTN050GEF	LOCHINVAR	0
13530	10/11/2005	LTN050GEF	LOCHINVAR	1
13531	05/22/2012	PH2DV50F	RUUD	0
13532	08/04/2004	GVC50	A. O. SMITH	0
13533	04/01/2006	22DV50C	RHEEM	0
13534	03/28/2007	XSN040	LOCHINVAR	0
13535	05/20/2006	LTN050G	LOCHINVAR	0
13536	10/28/2000	PRX50	STATE	0
13537	04/25/2001	FSG50	AO SMITH	0
13538	07/13/2007	LTN050GEF	LOCHINVAR	0
13539	04/12/2002	FSG50	AO SMITH	0
13540	03/17/2005	XSN040	LOCHINVAR	1
13541	05/04/2004	XVR50	A. O. SMITH	0
13542	02/08/2002	PGR50	AO SMITH	1
13543	02/03/2009	LTN050GEF	LOCHINVAR	0
13544	11/01/2012	MI40T6FBN	BRADFORD-WHITE	0
13545	04/02/2007	LTN050G	LOCHINVAR	0
13546	01/28/2006	PR650	STATE	0
13547	07/30/1999	FGR50	AO SMITH	0
13548	07/11/2003	PGR50	AO SMITH	0
13549	06/02/2012	M45036FBN	BRADFORD-WHITE	0
13550	01/11/2011	42VR50	RHEEM	0
13551	12/12/2004	GCVL40	A. O. SMITH	0
13552	01/05/2005	GVC40	A. O. SMITH	0
13553	10/01/2008	LTN050G	LOCHINVAR	0
13554	05/07/2012	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13555	09/29/2006	LTN051G	LOCHINVAR	0
13556	06/12/2002	21V506	RHEEM	0
13557	01/19/2010	LTN050GEF	LOCHINVAR	0
13558	12/08/2009	LSN041G	LOCHINVAR	0
13559	03/14/2008	LTN050	LOCHINVAR	0
13560	11/11/2002	BTR120	AO SMITH	0
13561	02/19/2000	FSG50	AO SMITH	0
13562	05/11/2009	LTN050GEF	LOCHINVAR	0
13563	11/02/2012	M45036FBN	BRADFORD-WHITE	1
13564	02/06/2006	LTN050GEF	LOCHINVAR	0
13565	03/16/1993	FSG50	AO SMITH	0
13566	07/11/2006	LTN050G	LOCHINVAR	0
13567	05/18/2006	PR650	STATE	0
13568	07/25/2002	PGR50	AO SMITH	0
13569	08/30/2010	G82156	RUUD/RHEEM	1
13570	12/28/2012	MI403S6FBN	BRADFORD-WHITE	0
13571	11/01/2001	PRX50	STATE	0
13572	07/19/2011	M45036FBN	BRADFORD-WHITE	0
13573	04/25/2003	FSG50	AO SMITH	0
13574	01/28/2004	PRX50	STATE	0
13575	09/17/2009	LTN050GEF	LOCHINVAR	0
13576	03/23/1998	FGR50	AO SMITH	0
13577	11/14/1989	21V506	RHEEM	0
13578	12/27/2011	FSG50	AO SMITH	0
13579	07/30/2002	FSG50	AO SMITH	0
13580	07/31/2009	LTN050GEF	LOCHINVAR	0
13581	05/19/2012	MI5036FBN	BRADFORD-WHITE	0
13582	07/14/2005	LTN050	LOCHINVAR	0
13583	12/08/2009	LTN050GEF	LOCHINVAR	0
13584	11/21/2012	PH2DV50F	RUUD	0
13585	08/16/2011	M45036FBN	BRADFORD-WHITE	2
13586	09/22/2009	LTN050GEF	LOCHINVAR	0
13587	10/11/2012	MI403S6FBN	BRADFORD-WHITE	0
13588	03/08/2007	LTN050G	LOCHINVAR	0
13589	05/04/2008	22DV50C	RHEEM	0
13590	07/27/2005	LTN050	LOCHINVAR	0
13591	03/11/2002	G91200	RUUD/RHEEM	1
13592	10/18/2010	41VR50	RHEEM	0
13593	05/07/2008	LTN050GEF	LOCHINVAR	1
13594	08/23/1999	PR650	STATE	0
13595	12/12/2009	LTN050GEF	LOCHINVAR	0
13596	03/11/2002	G91200	RUUD/RHEEM	0
13597	08/01/2008	LTN050GEF	LOCHINVAR	0
13598	04/16/2011	41VR50	RHEEM	2
13599	02/15/2001	PRX50	STATE	0
13600	01/24/2007	LTN050G	LOCHINVAR	0
13601	06/29/2010	LTN051G	LOCHINVAR	0
13602	12/26/2008	22DV50C	RHEEM	0
13603	10/11/2006	LTN050G	LOCHINVAR	0
13604	11/08/2000	41XR50	RHEEM	0
13605	01/08/2002	PGR50	AO SMITH	0
13606	10/06/1995	FSG50	AO SMITH	1
13607	11/01/2002	FSG50	AO SMITH	2
13608	01/15/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13609	11/11/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
13610	06/04/2008	LTN050GEF	LOCHINVAR	0
13611	09/15/2009	LSN041G	LOCHINVAR	0
13612	05/18/2012	MI5036FBN	BRADFORD-WHITE	0
13613	03/09/2009	LTN050GEF	LOCHINVAR	0
13614	04/08/2010	LTN050GEF	LOCHINVAR	0
13615	06/15/2011	22DV50F	RHEEM	0
13616	01/04/1994	FGR50	AO SMITH	0
13617	04/05/2008	LTN050GEF	LOCHINVAR	0
13618	06/21/2004	XVR50	A. O. SMITH	1
13619	11/29/2011	M440T6FBN	BRADFORD-WHITE	0
13620	08/23/1989	P506	RUUD	0
13621	08/16/2011	MI40T6FBN	BRADFORD-WHITE	0
13622	04/22/1999	PHR50	RUUD	0
13623	01/04/2007	LTN050G	LOCHINVAR	0
13624	07/05/2004	GVC50	A. O. SMITH	1
13625	08/31/1999	FSG50	AO SMITH	0
13626	06/20/2011	22DV50F	RHEEM	0
13627	12/10/2009	LTN050GEF	LOCHINVAR	0
13628	09/25/2004	GVC50	A. O. SMITH	0
13629	03/06/1991	PRV50NODS	STATE	0
13630	06/30/2010	LTN050GEF	LOCHINVAR	0
13631	09/17/2012	DS150S6FBN	BRADFORD-WHITE	2
13632	11/28/1998	PR650	STATE	0
13633	03/12/2002	21V506	RHEEM	0
13634	11/28/2005	LTN050G	LOCHINVAR	3
13635	11/23/2005	BTR154	AO SMITH	0
13636	08/11/2005	FSG40	AO SMITH	0
13637	08/21/1991	PRX50	STATE	0
13638	10/31/2005	BTR154	AO SMITH	0
13639	09/18/2007	LTN050GEF	LOCHINVAR	0
13640	01/05/1992	PRV50NODS	STATE	0
13641	11/27/2006	LSN041G	LOCHINVAR	1
13642	04/10/1991	FSG40	AO SMITH	0
13643	11/30/2001	PGR50	AO SMITH	0
13644	01/24/1992	P506	RUUD	0
13645	07/29/1991	21V407	RHEEM	0
13646	01/13/2002	FSG50	AO SMITH	0
13647	01/07/2009	22DV50F	RHEEM	0
13648	10/30/1991	FSG50	AO SMITH	0
13649	02/04/2002	PGR50	AO SMITH	1
13650	08/03/2011	M45036FBN	BRADFORD-WHITE	0
13651	02/17/2006	PR650X0DS	STATE	1
13652	04/04/2005	G75125	RUUD/RHEEM	0
13653	01/25/2006	LTN040G	LOCHINVAR	1
13654	10/08/2001	PGR50	AO SMITH	0
13655	02/09/2006	LTN050G	LOCHINVAR	0
13656	07/02/2010	LTN050G	LOCHINVAR	1
13657	01/15/1991	P506	RUUD	0
13658	01/27/2013	MI5036FBN	BRADFORD-WHITE	0
13659	11/22/2004	XVR50	A. O. SMITH	0
13660	08/15/2008	LTN051G	LOCHINVAR	0
13661	02/06/1999	FGR50	AO SMITH	0
13662	12/10/2004	LTN050	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13663	12/13/2007	LTN050GEF	LOCHINVAR	0
13664	10/01/1998	FSG50	AO SMITH	0
13665	07/05/2012	M440T6FBN	BRADFORD-WHITE	0
13666	09/13/2001	PRX50	STATE	0
13667	12/30/2011	M440T6FBN	BRADFORD-WHITE	1
13668	11/19/2010	42VR50	RHEEM	0
13669	01/21/2010	LTN050GEF	LOCHINVAR	0
13670	05/17/1991	B71DUMMY	AMERICAN	1
13671	07/31/2012	M45036FBN	BRADFORD-WHITE	0
13672	11/15/2010	21VR50	RHEEM	0
13673	01/31/2006	G91200	RUUD/RHEEM	1
13674	09/10/1992	FSG50	AO SMITH	0
13675	04/01/2009	PH199119	PHOENIX	0
13676	10/27/2005	G76200	RUUD/RHEEM	0
13677	10/15/2005	PR650	STATE	0
13678	04/01/2009	PH199119	PHOENIX	0
13679	10/29/1992	P502	RUUD	0
13680	03/21/2006	G91200	RUUD/RHEEM	0
13681	09/12/2011	G76200	RUUD/RHEEM	1
13682	04/01/2009	PH199119	PHOENIX	0
13683	09/16/2010	21V502	RHEEM	0
13684	12/01/2010	21VR50	RHEEM	0
13685	11/10/1992	PRV50NORT	STATE	0
13686	08/02/2005	PR650	STATE	0
13687	01/23/2009	LTN051G	LOCHINVAR	1
13688	03/11/2005	GVC50	A. O. SMITH	0
13689	04/23/2012	MI403S6FBN	BRADFORD-WHITE	0
13690	12/23/1992	21V502	RHEEM	0
13691	01/23/2002	PRX50	STATE	0
13692	04/23/2012	MI403S6FBN	BRADFORD-WHITE	0
13693	03/30/2006	LTN050GEF	LOCHINVAR	1
13694	03/22/2008	LTN050GEF	LOCHINVAR	0
13695	03/09/2003	G75125	RUUD/RHEEM	1
13696	08/17/2009	LTN050GEF	LOCHINVAR	0
13697	12/15/2012	PH2DV50F	RUUD	0
13698	03/09/1993	P502	RUUD	0
13699	02/02/2010	LTN050GEF	LOCHINVAR	0
13700	05/08/1992	21V502	RHEEM	0
13701	03/13/2013	M45036FBN	BRADFORD-WHITE	0
13702	08/31/2006	LTN050GEF	LOCHINVAR	0
13703	12/19/2011	MI5036FBN	BRADFORD-WHITE	0
13704	01/28/2002	FSG50	AO SMITH	1
13705	01/24/2007	PR650X0DS	STATE	0
13706	12/27/2004	GVC50	A. O. SMITH	0
13707	10/27/1999	PRX50	STATE	0
13708	07/17/2003	FGR50	AO SMITH	0
13709	12/01/2003	PVR50	AO SMITH	0
13710	03/06/1989	21V506	RHEEM	0
13711	02/03/2001	41XR50	RHEEM	0
13712	07/16/2003	FSG50	AO SMITH	0
13713	11/11/2000	41XR50	RHEEM	0
13714	06/02/2006	LTN050G	LOCHINVAR	0
13715	02/04/2009	22DV50C	RHEEM	1
13716	06/26/1999	PR650	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13717	11/20/2006	LTN050GEF	LOCHINVAR	0
13718	12/03/2008	LTN050GEF	LOCHINVAR	1
13719	12/24/2009	LTN050GEF	LOCHINVAR	0
13720	09/18/1998	FGR50	AO SMITH	0
13721	06/28/2001	41XR50	RHEEM	0
13722	11/11/2011	M45036FBN	BRADFORD-WHITE	1
13723	04/11/2007	LTN050G	LOCHINVAR	0
13724	05/25/1989	FSGL40	AO SMITH	1
13725	12/17/2003	PRX50	STATE	0
13726	12/23/2009	LTN050G	LOCHINVAR	0
13727	09/28/2011	PH2DV50F	RUUD	0
13728	09/09/2011	42VR50	RHEEM	0
13729	08/31/1989	FSG40	AO SMITH	0
13730	08/18/2010	PGR50	AO SMITH	0
13731	11/12/2012	MI5036FBN	BRADFORD-WHITE	0
13732	01/31/2005	GCVL40	A. O. SMITH	1
13733	06/22/2001	FSG50	AO SMITH	0
13734	02/25/2009	LTN050GEF	LOCHINVAR	0
13735	09/15/2005	LTN050GEF	LOCHINVAR	0
13736	04/09/2010	LTN050GEF	LOCHINVAR	0
13737	05/15/1989	FSG50	AO SMITH	0
13738	08/07/2009	LTN050GEF	LOCHINVAR	0
13739	07/25/2012	G82156	RUUD/RHEEM	1
13740	08/14/1989	FSG50	AO SMITH	0
13741	01/08/2008	LTN050G	LOCHINVAR	0
13742	01/29/2010	LTN050GEF	LOCHINVAR	0
13743	07/25/2012	G82156	RUUD/RHEEM	0
13744	01/05/2009	LTN050GEF	LOCHINVAR	0
13745	01/26/2011	22DV50F	RHEEM	0
13746	06/03/2011	41VR50	RHEEM	0
13747	11/19/2001	PGR50	AO SMITH	0
13748	07/11/2008	LTN050GEF	LOCHINVAR	0
13749	04/22/2011	22DV50F	RHEEM	0
13750	01/30/2001	PGR50	AO SMITH	2
13751	06/24/1998	PGR50	AO SMITH	0
13752	05/20/2009	LTN050GEF	LOCHINVAR	0
13753	03/18/2013	41VR50	RHEEM	0
13754	03/07/2008	LTN050GEF	LOCHINVAR	0
13755	01/23/2010	LTN050GEF	LOCHINVAR	0
13756	02/28/2013	PH2DV50F	RUUD	0
13757	06/02/2010	LTN050GEF	LOCHINVAR	0
13758	09/28/2005	PRX50	STATE	1
13759	03/23/2009	LTN050G	LOCHINVAR	1
13760	02/15/2013	MI5036FBN	BRADFORD-WHITE	0
13761	10/16/2007	LTN050GEF	LOCHINVAR	0
13762	12/29/2006	41V50	RHEEM	0
13763	03/07/2008	LTN050	LOCHINVAR	0
13764	11/05/2007	21V402S	RHEEM	0
13765	02/17/2009	LTN050GEF	LOCHINVAR	0
13766	03/09/1991	PRV50NODS	STATE	1
13767	02/14/2012	MI5036FBN	BRADFORD-WHITE	0
13768	06/18/2009	LSN041G	LOCHINVAR	0
13769	10/15/2008	LTN050GEF	LOCHINVAR	0
13770	07/05/2008	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13771	09/05/1991	FSG50	AO SMITH	0
13772	10/22/2001	PGR50	AO SMITH	0
13773	04/28/2006	LTN050G	LOCHINVAR	0
13774	09/26/2005	LTN050GEF	LOCHINVAR	0
13775	02/12/2008	PR650	STATE	0
13776	01/14/2003	PGR50	AO SMITH	0
13777	10/30/2003	41V50S	RHEEM	0
13778	10/28/2003	PGR50	AO SMITH	0
13779	11/13/2008	LTN050G	LOCHINVAR	0
13780	08/02/2002	FSG50	AO SMITH	0
13781	09/27/2005	LTN050	LOCHINVAR	0
13782	05/17/2010	LTN050G	LOCHINVAR	0
13783	08/06/1991	FSG50	AO SMITH	0
13784	06/14/2004	PRX50	STATE	0
13785	10/30/2009	LTN050GEF	LOCHINVAR	0
13786	09/05/2007	LSN041G	LOCHINVAR	0
13787	07/21/2011	M45036FBN	BRADFORD-WHITE	0
13788	09/30/2012	PH2DV50F	RUUD	0
13789	11/30/2004	GVC50	A. O. SMITH	0
13790	01/13/2006	LTN051G	LOCHINVAR	0
13791	05/19/2006	LTN050G	LOCHINVAR	0
13792	01/25/2012	M45036FBN	BRADFORD-WHITE	0
13793	11/12/2010	21VR50	RHEEM	1
13794	10/14/2005	PR650	STATE	0
13795	08/11/2007	LTN050G	LOCHINVAR	0
13796	03/05/1991	FSG50	AO SMITH	0
13797	02/05/2010	22DV50C	RHEEM	0
13798	12/08/2009	LTN050GEF	LOCHINVAR	0
13799	01/04/2013	MI5036FBN	BRADFORD-WHITE	0
13800	04/12/2008	LTN050GEF	LOCHINVAR	0
13801	04/09/2011	21VR50	RHEEM	0
13802	10/30/1992	FSG50	AO SMITH	0
13803	10/09/2001	PGR50	AO SMITH	0
13804	07/02/1992	FSG50	AO SMITH	0
13805	07/17/2009	22DV50C	RHEEM	0
13806	09/23/2000	FSG50	AO SMITH	0
13807	07/10/1992	P502	RUUD	0
13808	06/10/2003	FSG40	AO SMITH	1
13809	03/28/2002	PGR50	AO SMITH	0
13810	10/12/2007	LTN050GEF	LOCHINVAR	0
13811	11/04/2005	LTN050G	LOCHINVAR	1
13812	02/09/2012	M45036FBN	BRADFORD-WHITE	0
13813	10/28/1992	FSG50	AO SMITH	0
13814	05/05/2007	LTN050GEF	LOCHINVAR	0
13815	01/08/2002	21V506	RHEEM	1
13816	11/01/2006	LTN050G	LOCHINVAR	0
13817	03/10/2005	41XR50	RHEEM	0
13818	08/28/2006	PR650	STATE	0
13819	11/09/2002	PGR50	AO SMITH	0
13820	02/11/2013	MI50L6FBN	BRADFORD-WHITE	0
13821	08/01/2008	22DV50C	RHEEM	0
13822	08/04/2007	LTN040GEF	LOCHINVAR	0
13823	07/14/1993	21V502	RHEEM	0
13824	08/03/1992	FSGL40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13825	03/20/2006	PR650	STATE	0
13826	12/03/2012	G91200	RUUD/RHEEM	3
13827	02/05/2010	LTN050GEF	LOCHINVAR	0
13828	08/01/2009	LTN050GEF	LOCHINVAR	1
13829	09/24/2012	M45036FBN	BRADFORD-WHITE	0
13830	07/07/2004	GVC50	A. O. SMITH	1
13831	11/05/2002	PGR50	AO SMITH	0
13832	01/25/2011	21VR50	RHEEM	0
13833	11/02/2002	FSG50	AO SMITH	0
13834	05/21/2010	LTN050GEF	LOCHINVAR	0
13835	01/02/2013	M45036FBN	BRADFORD-WHITE	0
13836	10/01/1992	FSG50	AO SMITH	0
13837	06/26/2011	M45036FBN	BRADFORD-WHITE	2
13838	07/22/2002	PGR50	AO SMITH	1
13839	12/15/2010	G75125	RUUD/RHEEM	0
13840	04/23/2008	LTN050	LOCHINVAR	0
13841	06/08/2001	FSG50	AO SMITH	0
13842	09/20/2010	21DV50	RHEEM	1
13843	02/19/2007	LTN050GEF	LOCHINVAR	0
13844	11/12/2008	LTN050GEF	LOCHINVAR	0
13845	03/25/2011	21VR50	RHEEM	0
13846	11/08/2003	41V50	RHEEM	0
13847	06/29/2007	LTN050G	LOCHINVAR	0
13848	05/08/2001	FSG40	AO SMITH	0
13849	12/30/1996	PR502T	RUUD	0
13850	11/28/1997	PGR50	AO SMITH	0
13851	08/04/2010	LTN050GEF	LOCHINVAR	1
13852	01/25/2000	FSG50	AO SMITH	0
13853	09/19/2011	M45036FBN	BRADFORD-WHITE	1
13854	05/09/2008	LTN050GEF	LOCHINVAR	0
13855	12/18/1999	PHR50	RUUD	0
13856	11/01/2002	FSG50	AO SMITH	0
13857	06/24/2010	FCV50	AO SMITH	1
13858	10/29/2007	LTN050G	LOCHINVAR	0
13859	09/26/2008	LTN050GEF	LOCHINVAR	0
13860	03/27/2009	LTN050GEF	LOCHINVAR	0
13861	07/11/2011	MI50L6FBN	BRADFORD-WHITE	0
13862	06/28/1989	P506	RUUD	0
13863	01/19/2006	PR650	STATE	0
13864	02/28/2011	42VR50	RHEEM	0
13865	10/16/2012	41XR50	RHEEM	1
13866	02/03/2006	PR650X0DS	STATE	0
13867	07/09/2001	FSG50	AO SMITH	0
13868	03/01/2002	FSG50	AO SMITH	1
13869	01/31/2008	LTN050G	LOCHINVAR	0
13870	11/11/2010	21VR50	RHEEM	0
13871	06/18/2008	LTN050GEF	LOCHINVAR	0
13872	09/25/2007	PR650	STATE	0
13873	06/19/2008	LTN040G	LOCHINVAR	2
13874	08/18/2005	LSN041G	LOCHINVAR	1
13875	09/22/2006	LTN050G	LOCHINVAR	0
13876	08/29/2003	21V506	RHEEM	0
13877	10/18/1989	21V506	RHEEM	0
13878	09/23/2008	LTN051G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13879	10/10/2006	PR650X0DS	STATE	0
13880	03/29/2002	FSG50	AO SMITH	0
13881	07/24/1989	FSG50	AO SMITH	0
13882	05/09/2003	PGR50	AO SMITH	0
13883	10/18/2000	41XR50	RHEEM	0
13884	07/14/2008	22DV50C	RHEEM	0
13885	01/27/2009	22DV50C	RHEEM	0
13886	09/15/2004	GVC50	A. O. SMITH	1
13887	12/22/2004	GVC50	A. O. SMITH	0
13888	04/24/2012	41VR50	RHEEM	0
13889	11/05/2001	PRX50	STATE	0
13890	07/17/2007	LTN040GEF	LOCHINVAR	0
13891	09/10/2012	MI5036FBN	BRADFORD-WHITE	0
13892	12/27/2012	MI5036FBN	BRADFORD-WHITE	0
13893	06/03/2011	21VR40	RHEEM	0
13894	01/26/2006	LTN050G	LOCHINVAR	0
13895	08/16/2011	MI5036FBN	BRADFORD-WHITE	0
13896	08/12/2004	41V50	RHEEM	0
13897	06/19/2009	LTN050GEF	LOCHINVAR	0
13898	09/27/2005	LTN050G	LOCHINVAR	0
13899	05/13/2010	22DV50C	RHEEM	0
13900	03/28/2013	FSG50	AO SMITH	1
13901	12/06/2004	XVR50	A. O. SMITH	1
13902	05/08/2003	PRX50	STATE	0
13903	01/25/2010	LTN050G	LOCHINVAR	0
13904	05/17/1991	21V502	RHEEM	0
13905	12/09/2008	LTN050GEF	LOCHINVAR	1
13906	03/14/2011	21VR40	RHEEM	0
13907	09/20/2010	21V502	RHEEM	0
13908	10/03/2009	LTN051G	LOCHINVAR	0
13909	01/07/2010	LTN050GEF	LOCHINVAR	0
13910	07/09/1991	21V502	RHEEM	0
13911	06/02/2005	LTN050	LOCHINVAR	0
13912	11/14/1998	41VR50	RHEEM	0
13913	08/30/1991	FSG40	AO SMITH	0
13914	09/20/2001	PGR50	AO SMITH	0
13915	07/05/2006	LTN050G	LOCHINVAR	0
13916	02/06/1991	PRV50NODS	STATE	0
13917	04/11/2003	FSG50	AO SMITH	0
13918	09/29/1999	41XR50	RHEEM	0
13919	08/30/1991	FSG40	AO SMITH	0
13920	12/30/1999	FSG50	AO SMITH	1
13921	06/26/2003	FSG40	AO SMITH	0
13922	04/08/2003	G75125	RUUD/RHEEM	0
13923	11/14/2011	M45036FBN	BRADFORD-WHITE	0
13924	04/07/2006	LTN050G	LOCHINVAR	0
13925	06/17/2011	22DV50F	RHEEM	0
13926	04/08/2003	G75125	RUUD/RHEEM	0
13927	01/08/2003	PRX50	STATE	0
13928	08/17/2012	M45036FBN	BRADFORD-WHITE	0
13929	05/17/2011	41VR50	RHEEM	0
13930	06/01/2008	LTN050GEF	LOCHINVAR	0
13931	03/23/2001	G75125	RUUD/RHEEM	3
13932	09/20/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13933	11/02/2011	M45036FBN	BRADFORD-WHITE	0
13934	12/12/1990	RF67120	RUUD	0
13935	01/28/2012	M440T6FBN	BRADFORD-WHITE	0
13936	05/09/2003	CPN13585FS	LOCHINVAR	0
13937	03/15/2006	PR650X0DS	STATE	0
13938	04/04/2002	PGR50	AO SMITH	0
13939	10/08/2011	M45036FBN	BRADFORD-WHITE	0
13940	08/07/2011	42VR50	RHEEM	0
13941	07/10/2008	42VR5040	RHEEM	0
13942	10/13/2009	22DV50C	RHEEM	0
13943	04/02/1996	RF67120	RUUD	1
13944	10/29/2009	FSG50	AO SMITH	0
13945	01/09/2008	LTN050	LOCHINVAR	0
13946	06/17/2007	LTN050G	LOCHINVAR	0
13947	08/20/2009	22DV50C	RHEEM	0
13948	01/15/2003	FSGT50	AO SMITH	0
13949	07/29/2005	PRX50	STATE	0
13950	11/19/2008	LTN050GEF	LOCHINVAR	0
13951	05/23/2005	LTN050	LOCHINVAR	1
13952	07/08/2009	22DV50C	RHEEM	0
13953	07/04/2009	22DV50C	RHEEM	1
13954	12/04/2007	LTN050G	LOCHINVAR	0
13955	10/24/2012	MI50L6FBN	BRADFORD-WHITE	1
13956	08/15/2007	LTN050G	LOCHINVAR	0
13957	06/15/2012	D71	UNKNOWN	0
13958	02/17/2012	MI5036FBN	BRADFORD-WHITE	0
13959	06/11/2007	LTN050G	LOCHINVAR	0
13960	02/17/2011	22V50F1	RHEEM	0
13961	03/23/1993	21DV50	RHEEM	0
13962	11/06/2008	LTN040GEF	LOCHINVAR	1
13963	11/26/2007	LTN040G	LOCHINVAR	0
13964	10/22/2003	FCV50	AO SMITH	0
13965	07/19/2004	PRX50	STATE	0
13966	04/14/2011	22DV50F	RHEEM	0
13967	03/08/2003	PRX50	STATE	0
13968	05/19/1992	FSG50	AO SMITH	0
13969	12/10/2008	LSN041G	LOCHINVAR	0
13970	11/23/2005	PR650	STATE	0
13971	12/18/2005	GVC50	A. O. SMITH	0
13972	08/12/2011	MI5036FBN	BRADFORD-WHITE	0
13973	12/31/2003	FCVL40	AO SMITH	0
13974	01/04/1993	PRV40NODS	STATE	0
13975	03/16/2011	22DV50F	RHEEM	1
13976	02/06/1992	PRV50NODS	STATE	0
13977	01/04/1993	PRX50	STATE	0
13978	03/25/2013	DS150S6FBN	Bradford - White	0
13979	09/10/1992	P502	RUUD	0
13980	01/26/2011	21DV50	RHEEM	1
13981	07/06/2004	PRX50	STATE	0
13982	10/02/2008	LSN041G	LOCHINVAR	0
13983	11/27/2011	M45036FBN	BRADFORD-WHITE	1
13984	10/30/2008	LTN050G	LOCHINVAR	1
13985	07/25/1991	FSG50	AO SMITH	0
13986	07/21/2003	FSG50	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
13987	07/17/2001	PRX50	STATE	0
13988	07/19/2008	LTN050GEF	LOCHINVAR	0
13989	06/07/2007	LTN050GEF	LOCHINVAR	0
13990	01/15/2013	MI40T6FBN	BRADFORD-WHITE	1
13991	01/31/1991	FSG50	AO SMITH	0
13992	10/15/1991	21V506	RHEEM	0
13993	11/25/2011	MI5036FBN	BRADFORD-WHITE	0
13994	09/27/1991	FSGL40	AO SMITH	0
13995	02/26/2003	PRX50	STATE	0
13996	11/24/2010	42VR50	RHEEM	0
13997	09/13/2005	LTN050G	LOCHINVAR	0
13998	01/13/2011	21DV50	RHEEM	0
13999	10/20/2009	LTN050GEF	LOCHINVAR	3
14000	08/16/2011	M45036FBN	BRADFORD-WHITE	4
14001	05/01/2006	LTN050GEF	LOCHINVAR	0
14002	11/14/2012	M45036FBN	BRADFORD-WHITE	0
14003	12/29/2000	41XR50	RHEEM	0
14004	04/06/2001	FSG50	AO SMITH	0
14005	05/04/2004	PRX50	STATE	0
14006	09/01/2006	PR640XODS	STATE	1
14007	02/24/2009	LTN050GEF	LOCHINVAR	0
14008	03/04/2013	M45036FBN	BRADFORD-WHITE	1
14009	01/28/2010	LTN050GEF	LOCHINVAR	0
14010	01/01/2006	PR650X0DS	STATE	0
14011	03/05/2000	PGR50	AO SMITH	0
14012	09/18/2006	FSG30	AO SMITH	0
14013	04/12/2007	LTN050GEF	LOCHINVAR	0
14014	10/24/2002	FSG50	AO SMITH	0
14015	08/24/2004	GVC50	A. O. SMITH	0
14016	04/23/2007	LTN050G	LOCHINVAR	0
14017	09/11/2012	MI5036FBN	BRADFORD-WHITE	0
14018	02/27/2006	LTN050G	LOCHINVAR	0
14019	08/24/2004	FCV50	AO SMITH	0
14020	01/09/2013	M45036FBN	BRADFORD-WHITE	0
14021	02/03/1992	PRV50NODS	STATE	0
14022	09/12/2011	MI5036FBN	BRADFORD-WHITE	0
14023	06/19/1991	FSG50	AO SMITH	0
14024	07/19/2000	PGR50	AO SMITH	0
14025	07/30/2011	M45036FBN	BRADFORD-WHITE	0
14026	01/06/1993	FSG50	AO SMITH	0
14027	09/07/2007	LTN050GEF	LOCHINVAR	1
14028	06/09/1992	PRX50	STATE	0
14029	05/21/2010	LTN050GEF	LOCHINVAR	0
14030	10/19/2007	PR650X0DS	STATE	0
14031	09/10/2001	FSG50	AO SMITH	0
14032	09/02/2008	22DV50C	RHEEM	1
14033	08/23/2006	LTN040G	LOCHINVAR	0
14034	07/13/2004	GVC50	A. O. SMITH	0
14035	03/27/2009	G82156	RUUD/RHEEM	0
14036	12/28/2007	LTN050GEF	LOCHINVAR	0
14037	01/24/2008	LTN050GEF	LOCHINVAR	0
14038	01/13/2006	LTN050	LOCHINVAR	0
14039	09/10/2009	21V502	RHEEM	0
14040	04/04/2008	LTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14041	09/24/2009	GDVS40	AOSMITH	0
14042	12/04/2001	FSG50	AO SMITH	0
14043	01/10/2001	FSG50	AO SMITH	0
14044	12/17/2003	PRX50	STATE	0
14045	02/04/2013	H72DUMMY	UNKNOWN AT CONVERSION	0
14046	11/28/2005	21DV50	RHEEM	0
14047	08/21/2009	LTN050GEF	LOCHINVAR	0
14048	12/23/2004	PRX50	STATE	1
14049	05/20/2010	LTN050GEF	LOCHINVAR	0
14050	01/03/1992	FSG50	AO SMITH	0
14051	12/17/2008	LTN051G	LOCHINVAR	0
14052	06/06/2006	G75125	RUUD/RHEEM	0
14053	01/14/2010	22DV50F	RHEEM	0
14054	07/28/2004	GVC40	A. O. SMITH	0
14055	03/07/2013	G75125	RUUD/RHEEM	0
14056	12/01/2000	G75125	RUUD/RHEEM	2
14057	05/14/2007	LTN050G	LOCHINVAR	1
14058	04/09/1992	FSG40	AO SMITH	0
14059	12/19/2008	LTN050G	LOCHINVAR	0
14060	04/07/2003	G91200	RUUD/RHEEM	0
14061	12/25/2010	21VR50	RHEEM	0
14062	10/07/2003	FSG50	AO SMITH	0
14063	09/08/2010	22DV50C	RHEEM	0
14064	08/26/1992	PRV50NODS	STATE	0
14065	12/13/2004	LTN040	LOCHINVAR	0
14066	03/27/2009	22DV50C	RHEEM	0
14067	05/11/2012	M45036FBN	BRADFORD-WHITE	0
14068	11/26/2005	LTN050G	LOCHINVAR	0
14069	11/16/2010	G91200	RUUD/RHEEM	0
14070	08/15/2006	LTN050G	LOCHINVAR	0
14071	03/08/2012	PH2DV50F	RUUD	0
14072	10/01/2009	LTN050GEF	LOCHINVAR	0
14073	08/16/2004	XVR50	A. O. SMITH	0
14074	11/11/2001	PRX50	STATE	0
14075	10/11/2011	M45036FBN	BRADFORD-WHITE	1
14076	01/10/2013	M45036FBN	BRADFORD-WHITE	0
14077	06/04/2008	LTN050GEF	LOCHINVAR	2
14078	07/03/2002	FSG50	AO SMITH	0
14079	11/01/1991	RF67120	RUUD	0
14080	10/22/2007	LTN050G	LOCHINVAR	0
14081	11/20/2012	FSG40	AO SMITH	1
14082	01/19/2010	LTN050GEF	LOCHINVAR	0
14083	12/08/2010	21VR50	RHEEM	0
14084	03/27/2009	LTN050GEF	LOCHINVAR	0
14085	11/20/2012	MI403S6FBN	BRADFORD-WHITE	0
14086	04/13/2010	LTN050GEF	LOCHINVAR	2
14087	04/05/2007	PR650	STATE	0
14088	02/20/2008	LTN040GEF	LOCHINVAR	1
14089	04/22/2011	21VR50	RHEEM	0
14090	06/07/2010	LTN050GEF	LOCHINVAR	0
14091	08/21/1997	FGR50	AO SMITH	0
14092	02/27/2013	MI5036FBN	BRADFORD-WHITE	1
14093	04/18/1991	PRX40	STATE	0
14094	12/18/2003	PRX40	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14095	03/21/1991	FSG50	AO SMITH	0
14096	01/28/2001	41XR50	RHEEM	0
14097	05/09/2002	FSG50	AO SMITH	0
14098	09/20/1998	FGR50	AO SMITH	0
14099	02/13/2001	PGR50	AO SMITH	0
14100	05/10/2012	21V502	RHEEM	0
14101	05/27/2010	LTN050GEF	LOCHINVAR	0
14102	10/06/2000	PRX50	STATE	0
14103	07/04/2004	PRX50	STATE	0
14104	05/29/2007	LTN050GEF	LOCHINVAR	0
14105	11/02/2006	LTN050G	LOCHINVAR	0
14106	04/21/2003	PGR50	AO SMITH	0
14107	08/02/2007	LTN050GEF	LOCHINVAR	0
14108	04/05/2003	FSG50	AO SMITH	1
14109	01/17/2001	21V506	RHEEM	0
14110	01/05/2010	LTN050GEF	LOCHINVAR	0
14111	12/04/2009	LTN050GEF	LOCHINVAR	0
14112	01/07/2011	42VR50	RHEEM	1
14113	08/05/2011	M45036FBN	BRADFORD-WHITE	0
14114	09/07/2010	41V50	RHEEM	0
14115	05/29/1991	P502	RUUD	0
14116	06/05/2009	22DV50F	RHEEM	0
14117	06/08/2009	LTN050GEF	LOCHINVAR	0
14118	01/25/2008	LTN050G	LOCHINVAR	0
14119	12/23/2000	FSG50	AO SMITH	0
14120	05/18/2009	FSG50	AO SMITH	0
14121	06/10/2004	PVR50	AO SMITH	0
14122	10/10/1991	FSG50	AO SMITH	0
14123	04/24/2004	PRX50	STATE	1
14124	06/18/2003	FSG50	AO SMITH	0
14125	09/17/1999	41XR50	RHEEM	0
14126	10/04/2011	G76200	RUUD/RHEEM	0
14127	04/15/2010	LTN050GEF	LOCHINVAR	0
14128	11/08/2006	LTN050G	LOCHINVAR	0
14129	07/12/2011	MI403S6FBN	BRADFORD-WHITE	0
14130	08/31/2004	GDVS50	AOSMITH	0
14131	09/20/2012	M440T6FBN	BRADFORD-WHITE	1
14132	08/11/1992	P502	RUUD	0
14133	02/02/2008	LTN050GEF	LOCHINVAR	0
14134	09/15/2012	M45036FBN	BRADFORD-WHITE	0
14135	07/02/2002	41V50	RHEEM	0
14136	08/11/1992	P502	RUUD	0
14137	12/24/2007	LTN050	LOCHINVAR	3
14138	02/22/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
14139	10/27/2004	PRX50	STATE	0
14140	10/29/2007	LTN050G	LOCHINVAR	0
14141	02/22/1999	G91200	RUUD/RHEEM	0
14142	10/26/2010	21VR50	RHEEM	0
14143	01/14/2011	21VR50	RHEEM	0
14144	09/02/1998	FGR50	AO SMITH	0
14145	11/01/2012	DS140S6FBN	BRADFORD-WHITE	0
14146	05/06/2004	PRX50	STATE	1
14147	08/11/2005	LTN050G	LOCHINVAR	0
14148	07/21/2009	LTN050GEF	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14149	01/12/2005	GVR50	AO SMITH	0
14150	06/30/2008	LTN050G	LOCHINVAR	0
14151	02/04/1992	FSG50	AO SMITH	0
14152	07/29/2008	LTN050GEF	LOCHINVAR	3
14153	05/28/2011	41VR50	RHEEM	1
14154	07/01/2010	LTN040GEF	LOCHINVAR	0
14155	01/18/2011	21DV50	RHEEM	0
14156	12/09/2011	MI403S6FBN	BRADFORD-WHITE	0
14157	12/28/2006	PR650	STATE	1
14158	06/24/2005	LTN050	LOCHINVAR	0
14159	11/03/2009	LTN050GEF	LOCHINVAR	1
14160	08/24/2004	XTN050	LOCHINVAR	0
14161	02/02/2010	22V50F1	RHEEM	0
14162	01/14/2008	LTN050GEF	LOCHINVAR	0
14163	09/27/2012	MI5036FBN	BRADFORD-WHITE	0
14164	03/30/2006	PR650	STATE	0
14165	02/26/2003	FSG50	AO SMITH	0
14166	11/06/2007	FSG50	AO SMITH	0
14167	07/22/2005	FCV40	AO SMITH	0
14168	10/18/2000	FSG50	AO SMITH	0
14169	05/05/2009	LTN050GEF	LOCHINVAR	0
14170	02/08/2013	MI5036FBN	BRADFORD-WHITE	0
14171	10/01/1991	FSG50	AO SMITH	1
14172	11/22/2004	GDVS50	AOSMITH	0
14173	12/18/2003	PRX50	STATE	0
14174	02/24/2010	LTN051G	LOCHINVAR	0
14175	02/13/2004	FSG50	AO SMITH	1
14176	04/19/2005	GVC50	A. O. SMITH	0
14177	06/09/2005	LTN050	LOCHINVAR	0
14178	03/17/2011	21VR40	RHEEM	1
14179	10/28/2009	22DV50C	RHEEM	0
14180	01/08/1999	41VR50	RHEEM	0
14181	05/18/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
14182	01/30/2007	GVC50	A. O. SMITH	0
14183	04/07/2010	LTN050G	LOCHINVAR	1
14184	07/05/1991	FSG50	AO SMITH	0
14185	11/26/2003	FCV50	AO SMITH	0
14186	06/16/1999	21V506	RHEEM	0
14187	09/12/1991	FSG50	AO SMITH	0
14188	09/12/2008	LTN050G	LOCHINVAR	0
14189	04/20/2006	LTN050G	LOCHINVAR	0
14190	10/22/2011	M45036FBN	BRADFORD-WHITE	0
14191	07/20/2012	MI5036FBN	BRADFORD-WHITE	0
14192	02/01/2005	PRX50	STATE	1
14193	07/24/2004	PRX50	STATE	0
14194	05/18/2004	FCV50	AO SMITH	1
14195	03/08/1991	P506	RUUD	0
14196	07/21/2005	LTN040	LOCHINVAR	0
14197	12/21/2011	M45036FBN	BRADFORD-WHITE	0
14198	03/12/2006	LTN050G	LOCHINVAR	0
14199	08/15/2007	LTN050GEF	LOCHINVAR	0
14200	02/17/2006	LTN050G	LOCHINVAR	0
14201	10/21/1991	FSG50	AO SMITH	0
14202	05/21/2010	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14203	03/24/2010	LTN040G	LOCHINVAR	1
14204	02/02/2012	M45036FBN	BRADFORD-WHITE	3
14205	05/10/1991	21V506	RHEEM	0
14206	02/17/1993	PRV50NODS	STATE	0
14207	10/30/1992	21V407	RHEEM	0
14208	08/14/2007	LSN041G	LOCHINVAR	0
14209	10/08/2001	PGR50	AO SMITH	0
14210	07/03/2008	LTN050GEF	LOCHINVAR	0
14211	02/08/2004	XTN050	LOCHINVAR	0
14212	09/03/2008	LTN050G	LOCHINVAR	0
14213	09/29/2009	22DV50C	RHEEM	1
14214	06/07/2006	PR650	STATE	0
14215	07/09/2012	MI5036FBN	BRADFORD-WHITE	0
14216	11/09/2009	LTN050GEF	LOCHINVAR	2
14217	05/19/2009	22DV50C	RHEEM	0
14218	08/05/1992	FSG50	AO SMITH	0
14219	01/31/1993	G67114	RHEEM	0
14220	10/04/2010	FSG50	AO SMITH	1
14221	03/14/2005	GVC50	A. O. SMITH	0
14222	02/11/2004	XTN050	LOCHINVAR	1
14223	02/18/1993	H72DUMMY	AO SMITH	1
14224	02/12/2002	FSG50	AO SMITH	0
14225	09/24/2003	FCVL40	AO SMITH	0
14226	05/03/2007	PR650	STATE	0
14227	02/19/2004	FSG50	AO SMITH	0
14228	06/08/2012	M45036FBN	BRADFORD-WHITE	1
14229	07/21/2001	PR650	STATE	0
14230	07/30/2010	22DV50F	RHEEM	0
14231	12/12/2008	ETN076	LOCHINVAR	4
14232	04/02/2011	42VR50	RHEEM	0
14233	08/02/2001	FSG50	AO SMITH	0
14234	10/14/2009	LTN050GEF	LOCHINVAR	0
14235	10/24/2007	LTN050G	LOCHINVAR	0
14236	07/26/2007	LTN051G	LOCHINVAR	0
14237	01/03/2012	M45036FBN	BRADFORD-WHITE	0
14238	07/20/2012	MI5036FBN	BRADFORD-WHITE	0
14239	07/08/2008	LTN050GEF	LOCHINVAR	0
14240	05/28/1992	PRV50NODS	STATE	0
14241	04/28/2012	PH2DV50F	RUUD	0
14242	11/06/2005	LTN050G	LOCHINVAR	0
14243	05/06/2005	GDVS50	AOSMITH	0
14244	08/08/2001	PGR50	AO SMITH	0
14245	08/24/2011	MI5036FBN	BRADFORD-WHITE	0
14246	08/16/2012	G91200	RUUD/RHEEM	0
14247	04/18/2005	GVC50	A. O. SMITH	0
14248	02/25/2005	21V506	RHEEM	0
14249	02/20/2007	LTN050GEF	LOCHINVAR	0
14250	03/21/2011	21VR50	RHEEM	0
14251	08/03/2010	22DV50F	RHEEM	0
14252	08/03/2001	FSG40	AO SMITH	0
14253	10/21/2002	FSG50	AO SMITH	0
14254	11/22/1991	FSG50	AO SMITH	0
14255	12/20/1997	PHR50	RUUD	1
14256	07/12/2004	GCVL40	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14257	09/03/2003	FCV50	AO SMITH	0
14258	01/28/1999	FSG50	AO SMITH	0
14259	08/06/2009	22DV50C	RHEEM	0
14260	10/03/2005	LTN050G	LOCHINVAR	0
14261	11/10/2006	LTN050G	LOCHINVAR	0
14262	12/01/2010	42VR50	RHEEM	0
14263	07/30/2004	PRX50	STATE	0
14264	09/04/1991	FSG50	AO SMITH	0
14265	03/02/2005	PRX50	STATE	0
14266	10/25/1991	FSG50	AO SMITH	0
14267	09/18/2001	PGR50	AO SMITH	1
14268	09/10/2010	LTN040GEF	LOCHINVAR	0
14269	08/23/2006	LTN050G	LOCHINVAR	0
14270	11/12/2005	LTN040G	LOCHINVAR	0
14271	07/17/2000	PGR50	AO SMITH	0
14272	06/01/2002	FSG50	AO SMITH	0
14273	08/12/1991	FSG50	AO SMITH	0
14274	01/04/2002	PGR50	AO SMITH	0
14275	02/18/1999	G76200	RUUD/RHEEM	0
14276	10/27/2010	42VR50	RHEEM	0
14277	05/21/2009	LTN050GEF	LOCHINVAR	0
14278	09/06/2012	PH2DV50F	RUUD	0
14279	02/24/2006	LTN050G	LOCHINVAR	0
14280	04/10/2002	PGR50	AO SMITH	0
14281	11/20/2004	GVC50	A. O. SMITH	0
14282	07/12/2011	M45036FBN	BRADFORD-WHITE	1
14283	08/19/2010	GVC50	A. O. SMITH	0
14284	07/24/1991	FSG50	AO SMITH	0
14285	06/11/2007	LTN050GEF	LOCHINVAR	0
14286	08/20/2004	XVR50	A. O. SMITH	0
14287	07/20/2009	22DV50C	RHEEM	0
14288	11/28/2012	GVC50	A. O. SMITH	0
14289	10/10/2005	LTN050GEF	LOCHINVAR	0
14290	06/17/2011	M45036FBN	BRADFORD-WHITE	0
14291	03/22/2010	LTN050GEF	LOCHINVAR	1
14292	01/04/2011	42VR50	RHEEM	0
14293	10/04/2003	PRX50	STATE	0
14294	01/28/2008	LTN050GEF	LOCHINVAR	0
14295	12/10/2012	M45036FBN	BRADFORD-WHITE	0
14296	12/11/2010	21DV50	RHEEM	0
14297	06/14/2003	FSG50	AO SMITH	0
14298	12/06/2011	M45036FBN	BRADFORD-WHITE	0
14299	05/29/2002	PRX50	STATE	0
14300	01/30/1993	H72DUMMY	AO SMITH	0
14301	09/13/2006	LTN040G	LOCHINVAR	0
14302	04/04/2006	LTN050GEF	LOCHINVAR	1
14303	07/11/2003	G91200	RUUD/RHEEM	0
14304	07/10/1992	PRV50NODS	STATE	0
14305	11/03/2005	LTN050GEF	LOCHINVAR	2
14306	02/29/2012	G91200	RUUD/RHEEM	0
14307	03/29/2005	XVR50	A. O. SMITH	1
14308	09/16/1992	FSG50	AO SMITH	1
14309	11/17/2004	GVC50	A. O. SMITH	2
14310	04/22/2003	21V506	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14311	07/17/2006	PR650	STATE	0
14312	09/01/2011	MI5036FBN	BRADFORD-WHITE	0
14313	05/23/2005	LTN050	LOCHINVAR	0
14314	11/20/2002	PGR50	AO SMITH	0
14315	10/08/1992	FSG40	AO SMITH	0
14316	08/20/2009	LTN050GEF	LOCHINVAR	0
14317	04/05/2012	M45036FBN	BRADFORD-WHITE	0
14318	09/24/2001	PRX50	STATE	0
14319	11/12/1992	FSG50	AO SMITH	0
14320	09/18/2010	LSN041G	LOCHINVAR	0
14321	05/01/2010	LSN041G	LOCHINVAR	0
14322	07/17/1992	P502	RUUD	0
14323	05/08/2005	LTN050	LOCHINVAR	0
14324	09/29/2005	LTN050G	LOCHINVAR	0
14325	08/18/2009	LTN050GEF	LOCHINVAR	0
14326	11/19/1992	FSGL40	AO SMITH	0
14327	01/18/2000	PHR40	RUUD	0
14328	05/29/2012	M45036FBN	BRADFORD-WHITE	0
14329	10/26/2001	PGR50	AO SMITH	0
14330	05/27/2005	LTN050	LOCHINVAR	0
14331	08/29/2001	PGR40	AO SMITH	0
14332	10/15/2007	LTN050GEF	LOCHINVAR	1
14333	05/06/2009	LTN050G	LOCHINVAR	0
14334	12/31/2005	PR650	STATE	2
14335	01/10/2005	GVC50	A. O. SMITH	0
14336	07/21/1992	FSGL40	AO SMITH	0
14337	04/06/2007	XSN040	LOCHINVAR	0
14338	10/04/2005	G75125	RUUD/RHEEM	0
14339	04/16/2008	LTN050GEF	LOCHINVAR	0
14340	06/11/2007	LTN050GEF	LOCHINVAR	0
14341	06/26/2012	PH2DV50F	RUUD	0
14342	10/04/2005	G75125	RUUD/RHEEM	0
14343	01/14/2012	M45036FBN	BRADFORD-WHITE	0
14344	12/20/2005	LTN050GEF	LOCHINVAR	0
14345	04/14/2009	LTN050GEF	LOCHINVAR	0
14346	10/14/2004	GDVS50	AOSMITH	0
14347	05/06/1993	P502	RUUD	0
14348	10/25/1991	FSG50	AO SMITH	0
14349	09/08/1998	FGR40	AO SMITH	0
14350	04/25/1991	P506	RUUD	0
14351	08/01/2012	M45036FBN	BRADFORD-WHITE	0
14352	09/22/2010	42VR50	RHEEM	0
14353	04/25/1991	P506	RUUD	0
14354	10/11/2003	PGR50	AO SMITH	1
14355	06/14/2003	PRX50	STATE	0
14356	09/12/2011	MI5036FBN	BRADFORD-WHITE	0
14357	07/30/2010	LSN041	LOCHINVAR	3
14358	05/06/2008	22DV50C	RHEEM	0
14359	08/07/2011	M45036FBN	BRADFORD-WHITE	4
14360	10/20/2006	LSN041G	LOCHINVAR	0
14361	11/01/1998	FGR50	AO SMITH	0
14362	02/07/2012	M45036FBN	BRADFORD-WHITE	0
14363	02/14/1998	PHR50	RUUD	0
14364	06/10/2010	22DV50C	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14365	03/28/1991	FSG50	AO SMITH	0
14366	02/24/2010	LTN050GEF	LOCHINVAR	0
14367	11/30/2002	PGR40	AO SMITH	0
14368	09/15/2008	22DV50C	RHEEM	0
14369	04/27/2011	G76200	RUUD/RHEEM	0
14370	03/26/2001	FSG50	AO SMITH	0
14371	08/12/1992	B71DUMMY	AMERICAN	0
14372	12/07/2007	LTN050G	LOCHINVAR	0
14373	02/22/1991	21V502	RHEEM	0
14374	03/12/2003	PRX50	STATE	0
14375	01/03/2000	PRX50	STATE	0
14376	08/24/2012	M45036FBN	BRADFORD-WHITE	0
14377	07/26/2011	MI5036FBN	BRADFORD-WHITE	0
14378	04/21/2005	PRX50	STATE	0
14379	03/11/2010	LSN041G	LOCHINVAR	1
14380	05/17/2008	LTN050GEF	LOCHINVAR	0
14381	09/09/2005	GVC50	A. O. SMITH	0
14382	05/01/2011	22DV50F	RHEEM	0
14383	03/20/2008	22DV50C	RHEEM	1
14384	06/11/1993	FSG50	AO SMITH	0
14385	04/25/2007	PR650X0DS	STATE	1
14386	10/12/1998	FGR50	AO SMITH	0
14387	11/16/2009	22DV50C	RHEEM	0
14388	08/02/2011	PH2DV50F	RUUD	0
14389	07/11/2007	LTN050GEF	LOCHINVAR	0
14390	05/15/2008	LTN050GEF	LOCHINVAR	0
14391	10/23/1991	PRV50NODS	STATE	0
14392	09/06/2011	M45036FBN	BRADFORD-WHITE	0
14393	08/04/2003	PVR50	AO SMITH	0
14394	03/17/2002	PGR50	AO SMITH	0
14395	09/25/2008	LTN050GEF	LOCHINVAR	0
14396	10/05/2011	M45036FBN	BRADFORD-WHITE	0
14397	04/10/2009	G76200	RUUD/RHEEM	0
14398	01/12/1993	FSG50	AO SMITH	0
14399	07/23/2004	GVC50	A. O. SMITH	0
14400	06/02/2010	LTN050GEF	LOCHINVAR	0
14401	09/24/2010	42VR50	RHEEM	0
14402	11/26/2002	PRX50	STATE	2
14403	02/19/2009	LTN050GEF	LOCHINVAR	0
14404	10/22/2008	LTN050GEF	LOCHINVAR	0
14405	05/28/1992	PRX40	STATE	0
14406	01/05/2009	LTN050GEF	LOCHINVAR	0
14407	12/12/2009	G75125	RUUD/RHEEM	0
14408	12/31/2003	G91200	RUUD/RHEEM	2
14409	12/03/2010	G82156	RUUD/RHEEM	1
14410	08/07/2007	LSN041G	LOCHINVAR	0
14411	03/27/2002	FSG50	AO SMITH	0
14412	06/06/2011	21VR50	RHEEM	0
14413	12/31/2003	G91200	RUUD/RHEEM	0
14414	01/02/2001	PGR50	AO SMITH	1
14415	01/05/2006	G82156	RUUD/RHEEM	0
14416	06/16/2003	41XR50	RHEEM	0
14417	03/08/1993	P506	RUUD	0
14418	05/28/1992	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14419	10/01/2012	M45036FBN	BRADFORD-WHITE	0
14420	03/03/1992	FSG50	AO SMITH	0
14421	10/03/2007	LTN051G	LOCHINVAR	0
14422	07/20/1992	RF67120	RUUD	0
14423	04/24/2012	MI50L6FBN	BRADFORD-WHITE	0
14424	02/22/2007	LTN051G	LOCHINVAR	0
14425	11/21/2012	P502	RUUD	0
14426	02/04/2001	21V506	RHEEM	0
14427	11/27/2005	LTN050GEF	LOCHINVAR	0
14428	07/09/2009	LTN050GEF	LOCHINVAR	0
14429	02/18/2005	XVR50	A. O. SMITH	1
14430	06/24/2002	FSGL40	AO SMITH	0
14431	12/15/2012	MI50L6FBN	BRADFORD-WHITE	1
14432	01/10/2006	LTN050G	LOCHINVAR	0
14433	11/26/2010	42VR50	RHEEM	0
14434	01/16/2002	FSG50	AO SMITH	0
14435	01/06/2011	21VR50	RHEEM	0
14436	04/02/2012	M45036FBN	BRADFORD-WHITE	0
14437	11/23/2005	LTN050G	LOCHINVAR	0
14438	05/11/2012	MI5036FBN	BRADFORD-WHITE	0
14439	01/26/2001	41XR40	RHEEM	0
14440	01/12/2005	GVC50	A. O. SMITH	0
14441	01/30/2011	22V50F1	RHEEM	0
14442	01/08/2004	PRX50	STATE	0
14443	04/28/2006	LTN051G	LOCHINVAR	0
14444	05/29/2010	21DV50	RHEEM	0
14445	11/17/1992	FSG50	AO SMITH	0
14446	12/11/1991	PH30	RUUD	0
14447	02/26/2011	42VR50	RHEEM	1
14448	03/27/2006	LTN050G	LOCHINVAR	0
14449	12/19/2008	LTN050G	LOCHINVAR	0
14450	04/22/1992	21V502	RHEEM	1
14451	12/22/1999	FSG50	AO SMITH	0
14452	12/23/2012	M45036FBN	BRADFORD-WHITE	0
14453	02/16/2009	22DV50C	RHEEM	0
14454	06/27/2008	LTN050GEF	LOCHINVAR	0
14455	09/13/2008	LTN050GEF	LOCHINVAR	0
14456	02/04/2013	D71DUMMY	UNKNOWN AT CONVERSION	0
14457	04/10/2009	G76200	RUUD/RHEEM	0
14458	09/30/2006	LSN041G	LOCHINVAR	0
14459	01/30/2006	LTN050G	LOCHINVAR	0
14460	04/01/2012	PH2DV50F	RUUD	0
14461	01/25/1991	P506	RUUD	0
14462	07/29/2008	22DV50C	RHEEM	0
14463	08/12/2011	M45036FBN	BRADFORD-WHITE	0
14464	07/03/2010	FSG50	AO SMITH	0
14465	08/25/2008	LTN050GEF	LOCHINVAR	0
14466	12/20/2010	42VR50	RHEEM	0
14467	01/07/2009	LTN050GEF	LOCHINVAR	0
14468	06/13/2003	FSG50	AO SMITH	0
14469	09/17/2006	LTN050G	LOCHINVAR	1
14470	01/09/2009	LSN041G	LOCHINVAR	0
14471	04/27/2011	41VR50	RHEEM	0
14472	08/30/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14473	01/26/1991	P506	RUUD	1
14474	09/26/2010	21VR50	RHEEM	0
14475	01/06/2001	41XR50	RHEEM	2
14476	05/20/2007	LTN050G	LOCHINVAR	0
14477	02/21/2007	PR650X0DS	STATE	0
14478	04/10/1991	PRV50NODS	STATE	0
14479	06/25/2012	MI5036FBN	BRADFORD-WHITE	1
14480	11/01/1990	41XR40	RHEEM	0
14481	01/27/2012	M45036FBN	BRADFORD-WHITE	0
14482	01/22/2007	LTN050G	LOCHINVAR	0
14483	02/02/2012	M45036FBN	BRADFORD-WHITE	0
14484	09/17/2012	M45036FBN	BRADFORD-WHITE	0
14485	08/19/2012	MI5036FBN	BRADFORD-WHITE	0
14486	06/21/2012	M45036FBN	BRADFORD-WHITE	0
14487	07/09/2010	21V502	RHEEM	0
14488	06/06/2001	FSG50	AO SMITH	0
14489	07/08/2010	22DV50C	RHEEM	1
14490	10/24/2006	LTN050G	LOCHINVAR	1
14491	03/04/2009	LTN050GEF	LOCHINVAR	0
14492	04/15/2004	PRX50	STATE	0
14493	04/30/2001	41XR50	RHEEM	0
14494	09/25/1996	FGR50	AO SMITH	0
14495	05/29/2008	LTN050GEF	LOCHINVAR	0
14496	08/27/2009	LTN050GEF	LOCHINVAR	0
14497	12/18/2012	PH2DV50F	RUUD	0
14498	09/21/2004	GVC50	A. O. SMITH	0
14499	04/02/2011	22DV50F	RHEEM	0
14500	01/03/2011	21VR50	RHEEM	0
14501	03/12/2008	22DV50C	RHEEM	0
14502	08/10/2009	LTN050GEF	LOCHINVAR	0
14503	11/05/1992	21V502	RHEEM	0
14504	05/20/1992	FSG50	AO SMITH	0
14505	08/27/2007	LTN051G	LOCHINVAR	0
14506	07/09/2008	LTN050GEF	LOCHINVAR	2
14507	12/18/2009	22DV50C	RHEEM	0
14508	12/16/2003	FCVL40	AO SMITH	3
14509	03/28/2003	FSG50	AO SMITH	1
14510	12/26/1992	21V502	RHEEM	0
14511	11/25/2003	FCV50	AO SMITH	0
14512	03/31/2011	22DV50F	RHEEM	0
14513	09/18/2011	MI403S6FBN	BRADFORD-WHITE	0
14514	06/06/2006	LTN050G	LOCHINVAR	0
14515	05/03/2004	G82156	RUUD/RHEEM	0
14516	08/01/2009	21V407	RHEEM	0
14517	09/16/2006	PR650	STATE	1
14518	01/28/2010	B71DUMMY	UNKNOWN AT CONVERSION	1
14519	08/01/2009	LTN040GEF	LOCHINVAR	0
14520	07/28/2004	GVC50	A. O. SMITH	0
14521	10/03/2008	LTN050GEF	LOCHINVAR	0
14522	01/10/2005	PR640	STATE	0
14523	09/17/2010	42VR50	RHEEM	2
14524	12/29/2008	LTN050G	LOCHINVAR	0
14525	12/09/2008	LTN040GEF	LOCHINVAR	0
14526	07/13/2009	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14527	10/03/2008	LTN050GEF	LOCHINVAR	0
14528	02/03/2013	M45036FBN	BRADFORD-WHITE	1
14529	08/01/2008	LTN050GEF	LOCHINVAR	0
14530	03/05/2008	LTN050	LOCHINVAR	1
14531	02/10/2010	LTN050GEF	LOCHINVAR	1
14532	06/26/1992	FSG50	AO SMITH	1
14533	05/07/2008	LTN050GEF	LOCHINVAR	0
14534	05/25/2011	42VR50	RHEEM	1
14535	05/20/2008	LTN050GEF	LOCHINVAR	1
14536	05/28/2003	FSG50	AO SMITH	0
14537	10/23/2011	M45036FBN	BRADFORD-WHITE	0
14538	03/08/2008	21DV50	RHEEM	0
14539	10/22/1999	PHR50	RUUD	0
14540	10/26/1993	P506	RUUD	0
14541	01/12/2008	LTN050G	LOCHINVAR	0
14542	01/10/1998	PHR50	RUUD	0
14543	09/18/2010	41VR50	RHEEM	0
14544	11/09/2009	LTN050GEF	LOCHINVAR	0
14545	07/02/2008	22DV50F	RHEEM	0
14546	10/25/2003	PRX50	STATE	0
14547	12/21/2010	21VR40	RHEEM	0
14548	01/02/1999	41VR40	RHEEM	0
14549	08/03/2007	LSN041G	LOCHINVAR	0
14550	09/10/2009	22DV50F	RHEEM	0
14551	11/27/2007	SBD100199NES	STATE	0
14552	07/07/2008	LTN050GEF	LOCHINVAR	0
14553	04/22/1996	FGR50	AO SMITH	0
14554	06/05/2007	PR650X0DS	STATE	0
14555	01/18/2006	LTN040G	LOCHINVAR	0
14556	12/10/2012	M45036FBN	BRADFORD-WHITE	0
14557	10/02/2003	G91200	RUUD/RHEEM	0
14558	05/23/2010	G91200	RUUD/RHEEM	0
14559	10/02/2003	G91200	RUUD/RHEEM	0
14560	05/16/1996	FGR50	AO SMITH	0
14561	08/28/2012	G91200	RUUD/RHEEM	0
14562	01/13/1998	21VR502T	RHEEM	0
14563	01/19/2005	G91200	RUUD/RHEEM	0
14564	01/14/2012	MI5036FBN	BRADFORD-WHITE	0
14565	01/06/2012	G91200	RUUD/RHEEM	1
14566	05/31/2012	G75125	RUUD/RHEEM	0
14567	05/28/2009	LTN050GEF	LOCHINVAR	0
14568	08/15/2000	G75125	RUUD/RHEEM	0
14569	09/30/1993	21V502	RHEEM	0
14570	12/07/1999	G76200	RUUD/RHEEM	0
14571	05/29/2008	LTN050G	LOCHINVAR	0
14572	01/23/2013	M45036FBN	BRADFORD-WHITE	0
14573	08/05/2009	LTN050GEF	LOCHINVAR	0
14574	02/21/2010	G91200	RUUD/RHEEM	2
14575	07/10/2007	LTN050G	LOCHINVAR	0
14576	01/07/1999	FGR40	AO SMITH	0
14577	04/25/2007	PR650X0DS	STATE	0
14578	04/23/2008	LTN040GEF	LOCHINVAR	0
14579	11/24/1999	PHR40	RUUD	0
14580	10/19/2007	PR650	STATE	3

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14581	11/26/1999	FGR50	AO SMITH	0
14582	02/05/1998	21V506	RHEEM	0
14583	01/19/2011	42VR50	RHEEM	1
14584	08/11/2009	LTN050G	LOCHINVAR	0
14585	09/09/1991	BTR197	AO SMITH	0
14586	12/05/1999	41XR50	RHEEM	0
14587	03/21/1991	RF67120	RUUD	0
14588	11/30/2012	M45036FBN	BRADFORD-WHITE	0
14589	08/08/2012	P230F	RUUD	0
14590	10/01/2009	22DV50C	RHEEM	0
14591	10/31/2005	LTN050GEF	LOCHINVAR	0
14592	10/07/1991	FSG50	AO SMITH	1
14593	11/13/2007	LSN041G	LOCHINVAR	0
14594	09/12/1991	FSG50	AO SMITH	0
14595	05/30/2007	LTN050GEF	LOCHINVAR	0
14596	12/12/2010	42VR50	RHEEM	0
14597	01/14/2005	PRX50	STATE	0
14598	02/25/2013	M45036FBN	BRADFORD-WHITE	0
14599	11/06/1991	PRX50	STATE	0
14600	01/17/2004	PRX50	STATE	0
14601	07/30/2003	PGR50	AO SMITH	0
14602	12/29/2004	GVC50	A. O. SMITH	0
14603	06/04/2012	PH250SF	RUUD	0
14604	01/08/2008	LTN050GEF	LOCHINVAR	0
14605	01/29/2004	PRX50	STATE	0
14606	06/02/2004	G75125	RUUD/RHEEM	1
14607	05/16/1997	FGR50	AO SMITH	0
14608	07/29/2012	PH2DV50F	RUUD	0
14609	05/13/2011	41VR50	RHEEM	0
14610	02/10/2007	LTN050GEF	LOCHINVAR	0
14611	09/21/2009	LTN050GEF	LOCHINVAR	0
14612	07/24/1991	FSGL40	AO SMITH	0
14613	07/24/2012	PH2DV50F	RUUD	0
14614	05/29/1991	B71DUMMY	AMERICAN	0
14615	10/15/2012	M45036FBN	BRADFORD-WHITE	1
14616	06/23/2009	LTN050GEF	LOCHINVAR	0
14617	07/18/2011	MI5036FBN	BRADFORD-WHITE	0
14618	01/16/1992	PRV50NODS	STATE	0
14619	08/31/2012	D71DUMMY	UNKNOWN AT CONVERSION	0
14620	06/27/1991	P506	RUUD	0
14621	07/25/2011	DH165TSFBN	BRADFORD-WHITE	1
14622	08/07/2006	LTN050G	LOCHINVAR	0
14623	05/09/2006	LTN050GEF	LOCHINVAR	0
14624	04/07/1993	P506	RUUD	0
14625	02/05/2009	LTN050GEF	LOCHINVAR	0
14626	10/26/1993	RF67120	RUUD	1
14627	03/22/2012	PH2DV50F	RUUD	1
14628	09/08/2007	LTN050G	LOCHINVAR	0
14629	06/22/2004	GVC50	A. O. SMITH	1
14630	04/09/1993	FSGL40	AO SMITH	0
14631	04/20/2012	M45036FBN	BRADFORD-WHITE	1
14632	12/06/2011	MI5036FBN	BRADFORD-WHITE	0
14633	07/02/2012	MI5036FBN	BRADFORD-WHITE	0
14634	07/26/2006	LTN050G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14635	04/14/1993	PRV50NODS	STATE	0
14636	07/18/2011	PRV50NODS	STATE	0
14637	03/10/2009	FSG50	AO SMITH	5
14638	10/23/2008	LTN050G	LOCHINVAR	1
14639	04/07/1993	FSGL40	AO SMITH	0
14640	01/13/2000	FGR40	AO SMITH	0
14641	08/30/2010	G82156	RUUD/RHEEM	1
14642	02/27/2013	G91200	RUUD/RHEEM	1
14643	07/21/2010	21V502	RHEEM	0
14644	08/30/2010	G82156	RUUD/RHEEM	0
14645	08/05/2008	22DV50F	RHEEM	1
14646	05/07/2009	I72DUMMY	RHEEM	4
14647	01/13/2006	LTN050G	LOCHINVAR	0
14648	09/24/2004	PRX50	STATE	1
14649	12/09/2010	42VR50	RHEEM	0
14650	02/17/1993	FSG50	AO SMITH	0
14651	12/19/2001	41V50	RHEEM	0
14652	10/22/1993	FGR50	AO SMITH	0
14653	02/04/2010	22DV50F	RHEEM	0
14654	05/06/2012	MI40T6FBN	BRADFORD-WHITE	0
14655	02/21/2007	LTN050G	LOCHINVAR	0
14656	06/15/2008	G91200	RUUD/RHEEM	0
14657	07/12/1996	FGR50	AO SMITH	0
14658	01/21/1999	PHR50	RUUD	0
14659	11/24/2012	M45036FBN	BRADFORD-WHITE	1
14660	11/10/2005	LTN051G	LOCHINVAR	0
14661	09/15/2011	M440T6FBN	BRADFORD-WHITE	0
14662	11/22/2012	MI403S6FBN	BRADFORD-WHITE	0
14663	11/30/2010	21VR50	RHEEM	1
14664	03/10/2009	LTN050GEF	LOCHINVAR	0
14665	02/29/2008	LSN041G	LOCHINVAR	0
14666	03/19/2002	G82156	RUUD/RHEEM	0
14667	02/26/2013	MI50L6FBN	BRADFORD-WHITE	0
14668	07/30/2009	LTN050GEF	LOCHINVAR	0
14669	05/12/2010	LTN050GEF	LOCHINVAR	0
14670	07/11/2008	LTN050G	LOCHINVAR	0
14671	04/21/2012	MI5036FBN	BRADFORD-WHITE	0
14672	12/16/1991	FSG40	AO SMITH	0
14673	06/04/2012	M45036FBN	BRADFORD-WHITE	0
14674	08/17/1992	FSG50	AO SMITH	0
14675	01/05/2004	FCV50	AO SMITH	0
14676	06/08/1992	FSGL40	AO SMITH	0
14677	02/18/2004	FCV50	AO SMITH	1
14678	09/18/2008	LTN050G	LOCHINVAR	0
14679	03/23/2008	LTN050	LOCHINVAR	0
14680	04/17/2008	LSN041G	LOCHINVAR	0
14681	08/28/2007	LTN050G	LOCHINVAR	1
14682	04/14/2010	G76200	RUUD/RHEEM	1
14683	05/26/2011	41VR50	RHEEM	0
14684	02/12/2008	G75125	RUUD/RHEEM	0
14685	08/25/2003	FSG50	AO SMITH	0
14686	02/03/1993	21V502	RHEEM	0
14687	02/27/2006	PRV50NODS	STATE	0
14688	06/19/2012	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14689	12/27/2009	LTN050G	LOCHINVAR	0
14690	07/20/2001	PRX50	STATE	0
14691	05/14/1992	FSG50	AO SMITH	0
14692	03/07/2008	LTN050GEF	LOCHINVAR	0
14693	09/21/1992	P502	RUUD	0
14694	05/04/2012	PH250SF	RUUD	0
14695	12/01/2005	LTN050G	LOCHINVAR	0
14696	08/05/2006	PR650	STATE	1
14697	11/06/2002	FSG50	AO SMITH	0
14698	11/03/2006	LTN050G	LOCHINVAR	0
14699	06/07/2007	LTN050GEF	LOCHINVAR	0
14700	11/24/2009	LTN050GEF	LOCHINVAR	0
14701	08/20/2012	MI50L6FBN	BRADFORD-WHITE	0
14702	04/15/2006	PR650	STATE	0
14703	01/02/2008	LTN050GEF	LOCHINVAR	0
14704	06/11/2004	XTN050	LOCHINVAR	0
14705	11/19/2002	41V40	RHEEM	0
14706	04/22/2002	FSG50	AO SMITH	0
14707	06/11/1992	PRX50	STATE	0
14708	12/15/2006	22DV50C	RHEEM	1
14709	12/04/2009	LTN051G	LOCHINVAR	0
14710	12/12/2007	LTN050GEF	LOCHINVAR	0
14711	12/20/2010	G75125	RUUD/RHEEM	0
14712	09/01/1998	PHR50	RUUD	0
14713	01/16/2009	LTN050GEF	LOCHINVAR	0
14714	10/22/1991	FSG40	AO SMITH	0
14715	05/10/2010	LTN040G	LOCHINVAR	1
14716	12/02/2002	FSGT50	AO SMITH	0
14717	02/01/1999	PR650	STATE	0
14718	09/07/2008	LTN050G	LOCHINVAR	0
14719	11/12/1991	B71DUMMY	AMERICAN	0
14720	11/22/2005	PRV50NODS	STATE	0
14721	08/22/2007	LTN050GEF	LOCHINVAR	0
14722	01/14/2013	MI50L6FBN	BRADFORD-WHITE	0
14723	06/20/2006	ETN076	LOCHINVAR	1
14724	11/19/2009	LTN050GEF	LOCHINVAR	0
14725	02/15/2005	XVR50	A. O. SMITH	0
14726	07/12/1991	FSG50	AO SMITH	0
14727	11/03/2004	GVC50	A. O. SMITH	0
14728	11/19/2009	LTN050GEF	LOCHINVAR	0
14729	03/18/1991	FSG50	AO SMITH	0
14730	02/22/2002	PGR50	AO SMITH	0
14731	09/07/2005	GVC50	A. O. SMITH	1
14732	05/25/1998	FSG50	AO SMITH	0
14733	04/23/1991	FSG50	AO SMITH	0
14734	11/07/2008	LTN050G	LOCHINVAR	1
14735	02/06/2010	LTN050GEF	LOCHINVAR	0
14736	12/13/2011	M45036FBN	BRADFORD-WHITE	0
14737	03/01/2007	G91200	RUUD/RHEEM	0
14738	06/15/2001	FSG40	AO SMITH	0
14739	07/09/2001	FSG40	AO SMITH	0
14740	11/01/1991	PRX50	STATE	0
14741	11/01/1991	FSG50	AO SMITH	0
14742	01/12/2010	22DV50F	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14743	07/03/2010	LTN050GEF	LOCHINVAR	0
14744	07/17/1991	P506	RUUD	0
14745	02/17/2010	21V502	RHEEM	0
14746	02/10/2005	GVC50	A. O. SMITH	0
14747	03/18/2010	LTN050GEF	LOCHINVAR	0
14748	06/17/2012	PH2DV50F	RUUD	0
14749	05/14/2008	G82156	RUUD/RHEEM	1
14750	05/20/2009	22DV50C	RHEEM	0
14751	05/18/2011	22DV50F	RHEEM	0
14752	07/22/2005	LTN050	LOCHINVAR	1
14753	12/06/1999	PR650	STATE	0
14754	12/02/1993	RF67120	RUUD	0
14755	04/20/2010	LTN050GEF	LOCHINVAR	0
14756	06/18/2010	LTN050GEF	LOCHINVAR	0
14757	01/18/1999	PRV40NODS	STATE	1
14758	07/18/1996	PR502T	RUUD	0
14759	12/07/1999	PHR50	RUUD	0
14760	07/03/2004	XVR50	A. O. SMITH	0
14761	07/30/1996	FGR50	AO SMITH	0
14762	02/18/2010	LTN050G	LOCHINVAR	1
14763	06/25/2007	LTN050G	LOCHINVAR	0
14764	02/11/1998	PHR50	RUUD	0
14765	01/10/2009	LTN050GEF	LOCHINVAR	0
14766	06/13/2012	M45036FBN	BRADFORD-WHITE	0
14767	01/10/2004	XTN040	LOCHINVAR	0
14768	02/13/1998	PHR50	RUUD	0
14769	11/28/2012	FSG40	AO SMITH	0
14770	01/03/2012	MI403S6FBN	BRADFORD-WHITE	1
14771	06/29/2009	LSN041G	LOCHINVAR	0
14772	07/31/2012	M440T6FBN	BRADFORD-WHITE	0
14773	12/06/2011	M45036FBN	BRADFORD-WHITE	0
14774	12/13/1999	41VR50	RHEEM	0
14775	08/29/2005	LTN050G	LOCHINVAR	0
14776	05/25/1993	P506	RUUD	0
14777	02/01/1999	41VR50	RHEEM	1
14778	08/20/2007	LTN050G	LOCHINVAR	0
14779	10/14/2002	BTR198	AO SMITH	0
14780	02/16/1998	FGR50	AO SMITH	0
14781	01/06/2012	M45036FBN	BRADFORD-WHITE	3
14782	05/01/2012	M45036FBN	BRADFORD-WHITE	0
14783	03/10/2004	G76200	RUUD/RHEEM	0
14784	07/12/2011	M440T6FBN	BRADFORD-WHITE	0
14785	11/28/2002	PRX50	STATE	0
14786	06/02/2008	G91200	RUUD/RHEEM	1
14787	06/14/2002	PGR50	AO SMITH	0
14788	08/22/2011	G91200	RUUD/RHEEM	0
14789	06/16/2008	22DV5038	RHEEM	0
14790	11/21/2003	PRX50	STATE	0
14791	02/20/2008	LTN050GEF	LOCHINVAR	0
14792	09/08/2001	FSG50	AO SMITH	0
14793	01/09/2003	PGR50	AO SMITH	0
14794	04/14/2008	SBF100199NES	STATE	0
14795	10/22/2008	22DV50F	RHEEM	0
14796	08/09/1992	21V502	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14797	06/14/2004	GVC50	AO SMITH	1
14798	07/02/2008	22DV50C	RHEEM	0
14799	08/06/2008	LTN050GEF	LOCHINVAR	1
14800	12/15/1999	BTR154	AO SMITH	0
14801	10/13/2011	M45036FBN	BRADFORD-WHITE	1
14802	09/04/2012	MI5036FBN	BRADFORD-WHITE	0
14803	08/20/2007	LTN050G	LOCHINVAR	0
14804	12/16/1999	FGR50	AO SMITH	0
14805	11/25/2008	LTN050GEF	LOCHINVAR	1
14806	08/25/2011	M45036FBN	BRADFORD-WHITE	0
14807	09/24/1992	PRV50NODS	STATE	0
14808	01/31/2007	LSN041G	LOCHINVAR	1
14809	11/17/2011	G91200	RUUD/RHEEM	2
14810	05/12/1992	P506	RUUD	0
14811	12/20/2003	FCVL40	AO SMITH	0
14812	06/04/2003	FSG40	AO SMITH	0
14813	05/11/2005	LTN050	LOCHINVAR	0
14814	11/17/2011	G91200	RUUD/RHEEM	0
14815	04/30/1992	21V506	RHEEM	0
14816	02/09/2010	LTN050GEF	LOCHINVAR	1
14817	09/19/2003	21V506	RHEEM	1
14818	06/09/2005	LTN040	LOCHINVAR	0
14819	10/14/1992	FSG50	AO SMITH	0
14820	05/10/2003	PGR50	AO SMITH	0
14821	07/26/2011	42V5065F	RHEEM	3
14822	12/20/2001	FSG50	AO SMITH	0
14823	10/10/2005	LTN050G	LOCHINVAR	0
14824	12/03/2011	M45036FBN	BRADFORD-WHITE	0
14825	05/12/2011	42V5065F	RHEEM	0
14826	07/13/2004	GVC50	A. O. SMITH	0
14827	09/08/2011	MI403S6FBN	BRADFORD-WHITE	0
14828	08/13/2003	FSG40	AO SMITH	0
14829	07/28/2011	G82156	RUUD/RHEEM	0
14830	09/11/1992	P506	RUUD	0
14831	01/13/2006	LTN051G	LOCHINVAR	0
14832	05/02/2008	LTN050	LOCHINVAR	0
14833	06/25/2012	MI5036FBN	BRADFORD-WHITE	0
14834	03/28/2012	M45036FBN	BRADFORD-WHITE	0
14835	09/30/2001	PGR50	AO SMITH	0
14836	08/28/2009	22DV50F	RHEEM	0
14837	04/20/2006	LTN050G	LOCHINVAR	0
14838	01/04/2010	22DV50F	RHEEM	0
14839	05/05/2003	PRX50	STATE	0
14840	06/07/2006	LTN050G	LOCHINVAR	0
14841	05/24/1999	FGR50	AO SMITH	0
14842	10/27/2012	M45036FBN	BRADFORD-WHITE	0
14843	12/30/2011	D71	UNKNOWN	0
14844	10/30/1997	PRV50NODS	STATE	0
14845	03/13/2008	LTN050GEF	LOCHINVAR	2
14846	10/21/1992	FSG50	AO SMITH	0
14847	12/12/2011	M45036FBN	BRADFORD-WHITE	1
14848	02/11/2012	M45036FBN	BRADFORD-WHITE	0
14849	02/20/1992	H72DUMMY	AO SMITH	0
14850	08/27/2003	PVR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14851	05/02/2007	PR650	STATE	0
14852	12/23/1991	FSG50	AO SMITH	0
14853	05/23/2007	PR650	STATE	0
14854	02/27/2004	FCV40	AO SMITH	0
14855	05/30/2008	22DV50C	RHEEM	2
14856	06/01/2005	LTN050G	LOCHINVAR	0
14857	04/10/2009	LTN050GEF	LOCHINVAR	0
14858	04/26/2001	FSG50	AO SMITH	0
14859	08/11/2011	MI5036FBN	BRADFORD-WHITE	0
14860	02/28/2013	H72DUMMY	UNKNOWN AT CONVERSION	0
14861	01/14/2012	G91200	RUUD/RHEEM	0
14862	01/12/1999	FGR50	AO SMITH	0
14863	09/06/2010	G91200	RUUD/RHEEM	1
14864	07/17/2012	M45036FBN	BRADFORD-WHITE	0
14865	12/30/1999	FGR40	AO SMITH	0
14866	07/28/2012	G91200	RUUD/RHEEM	0
14867	11/22/2005	PR650	STATE	1
14868	12/07/2007	PR650	STATE	0
14869	12/29/1992	21DV50	RHEEM	0
14870	11/09/2005	LTN050G	LOCHINVAR	0
14871	07/15/2011	G91200	RUUD/RHEEM	0
14872	04/22/2012	M45036FBN	BRADFORD-WHITE	0
14873	03/03/1998	FGR40	AO SMITH	0
14874	11/18/2011	MI5036FBN	BRADFORD-WHITE	0
14875	10/03/2002	FSG50	AO SMITH	0
14876	11/01/2006	LTN050G	LOCHINVAR	0
14877	09/23/2009	LTN050GEF	LOCHINVAR	0
14878	05/13/2008	22DV50F	RHEEM	0
14879	03/04/1998	FGR50	AO SMITH	0
14880	08/14/2001	FSG50	AO SMITH	1
14881	03/04/1993	FSGL40	AO SMITH	0
14882	09/03/2008	LTN050GEF	LOCHINVAR	0
14883	01/16/2011	42VR50	RHEEM	0
14884	06/05/2012	G82156	RUUD/RHEEM	1
14885	09/25/1996	FGR50	AO SMITH	0
14886	11/23/2009	LSN041G	LOCHINVAR	0
14887	02/05/2007	LTN050G	LOCHINVAR	0
14888	04/30/2004	G82156	RUUD/RHEEM	0
14889	04/30/2012	G82156	RUUD/RHEEM	0
14890	03/18/2000	PRV50NODS	STATE	0
14891	08/20/1996	FGR50	AO SMITH	0
14892	11/04/2009	LTN050G	LOCHINVAR	0
14893	04/30/2012	G82156	RUUD/RHEEM	0
14894	04/14/2008	SBD100199NES	STATE	3
14895	09/04/1996	FGR50	AO SMITH	0
14896	01/10/2012	G82156	RUUD/RHEEM	1
14897	05/20/2005	PR650	STATE	0
14898	09/28/2010	G91200	RUUD/RHEEM	2
14899	02/17/1999	PHR50	RUUD	0
14900	10/10/2006	LTN050G	LOCHINVAR	3
14901	11/28/2009	LTN050GEF	LOCHINVAR	0
14902	01/11/2013	PH2DV50F	RUUD	0
14903	06/28/2007	LTN050G	LOCHINVAR	3
14904	02/18/1999	G76200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14905	12/27/2005	PR640	STATE	0
14906	06/27/2007	LTN040G	LOCHINVAR	0
14907	09/30/2008	LTN050GEF	LOCHINVAR	0
14908	06/20/2010	LTN050GEF	LOCHINVAR	1
14909	04/01/2003	FSG50	AO SMITH	0
14910	06/02/2012	G91200	RUUD/RHEEM	0
14911	10/02/2009	LTN050G	LOCHINVAR	0
14912	03/03/2012	M45036FBN	BRADFORD-WHITE	0
14913	06/02/2010	22DV50C	RHEEM	1
14914	12/11/2006	LTN051G	LOCHINVAR	0
14915	09/20/1991	D74DUMMY	AO SMITH	0
14916	03/10/2010	LTN051G	LOCHINVAR	0
14917	02/16/2011	21VR40	RHEEM	1
14918	10/14/2003	PGR50	AO SMITH	0
14919	10/04/2010	G82156	RUUD/RHEEM	0
14920	09/29/2011	MI403S6FBN	BRADFORD-WHITE	2
14921	01/22/2007	LTN050G	LOCHINVAR	0
14922	02/11/1991	FSG50	AO SMITH	0
14923	07/28/2009	LTN050GEF	LOCHINVAR	0
14924	10/24/2002	FSG50	AO SMITH	0
14925	08/02/2005	LTN050	LOCHINVAR	0
14926	06/02/2005	LTN050	LOCHINVAR	0
14927	05/20/2011	22DV50F	RHEEM	0
14928	09/26/2010	41VR50	RHEEM	1
14929	11/16/2010	21V502	RHEEM	0
14930	03/11/2008	22DV50C	RHEEM	0
14931	04/22/2008	LTN050GEF	LOCHINVAR	1
14932	05/29/2004	21DV50	RHEEM	0
14933	07/27/2011	MI5036FBN	BRADFORD-WHITE	1
14934	10/06/2008	LTN050G	LOCHINVAR	0
14935	12/28/2007	LTN050GEF	LOCHINVAR	0
14936	08/12/2007	PR650	STATE	0
14937	04/25/2012	PH250SF	RUUD	1
14938	07/10/2002	FSG50	AO SMITH	0
14939	10/02/2005	PR650	STATE	0
14940	04/19/2010	LTN050G	LOCHINVAR	0
14941	05/13/2009	LTN050GEF	LOCHINVAR	0
14942	11/21/1991	G67114	RHEEM	1
14943	09/13/1991	P506	RUUD	0
14944	02/17/2009	LTN050GEF	LOCHINVAR	0
14945	09/21/2004	PRX50	STATE	0
14946	05/06/2008	22DV50C	RHEEM	0
14947	01/31/1991	FSG50	AO SMITH	0
14948	03/03/2006	LTN050G	LOCHINVAR	0
14949	05/08/2006	LSN041G	LOCHINVAR	0
14950	07/05/2006	LTN050G	LOCHINVAR	0
14951	07/24/2001	FSG50	AO SMITH	0
14952	10/04/2002	PRX50	STATE	0
14953	11/03/1993	FSGL40	AO SMITH	0
14954	10/21/2011	M45036FBN	BRADFORD-WHITE	2
14955	09/16/1996	FGR40	AO SMITH	0
14956	02/06/2010	22DV50F	RHEEM	0
14957	08/09/2001	41V50	RHEEM	0
14958	06/28/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
14959	10/21/2011	21V502	RHEEM	0
14960	09/17/1996	21VR502T	RHEEM	0
14961	02/21/2008	21DV50	RHEEM	0
14962	09/18/2010	21V502	RHEEM	0
14963	07/27/2004	GVC50	A. O. SMITH	0
14964	08/03/2012	M45036FBN	BRADFORD-WHITE	0
14965	03/11/2009	LTN050GEF	LOCHINVAR	0
14966	05/01/2007	LTN050G	LOCHINVAR	0
14967	10/08/2009	LTN050G	LOCHINVAR	0
14968	09/15/2012	MI5036FBN	BRADFORD-WHITE	0
14969	02/15/2010	22DV50F	RHEEM	0
14970	08/15/2008	LTN050GEF	LOCHINVAR	0
14971	03/29/2007	LTN050G	LOCHINVAR	0
14972	04/26/1994	RFD91200	RUUD	0
14973	02/09/1993	P502	RUUD	0
14974	03/25/2011	42VR50	RHEEM	0
14975	01/26/2005	ETN076	LOCHINVAR	0
14976	08/06/2009	LTN050GEF	LOCHINVAR	1
14977	03/25/1998	41VR50	RHEEM	0
14978	10/08/2008	LTN050GEF	LOCHINVAR	0
14979	02/08/2010	LTN040G	LOCHINVAR	0
14980	11/04/2010	21DV50	RHEEM	1
14981	10/13/2007	G75125	RUUD/RHEEM	0
14982	02/01/2008	LTN050GEF	LOCHINVAR	0
14983	04/28/2009	LTN040GEF	LOCHINVAR	0
14984	05/01/2005	LTN050	LOCHINVAR	0
14985	12/22/2000	G75125	RUUD/RHEEM	0
14986	08/28/2011	MI5036FBN	BRADFORD-WHITE	0
14987	01/13/2000	41VR40	RHEEM	0
14988	03/30/1998	FGR40	AO SMITH	1
14989	02/17/2011	22DV50F	RHEEM	0
14990	11/19/2009	LTN050GEF	LOCHINVAR	0
14991	01/12/2000	FGR50	AO SMITH	0
14992	02/19/2010	22DV50C	RHEEM	0
14993	03/16/1994	RFD91200	RUUD	0
14994	10/24/2010	42V75F	Rheem	1
14995	10/22/1996	PR502T	RUUD	0
14996	03/17/2009	LTN050GEF	LOCHINVAR	0
14997	07/19/2008	LSN041G	LOCHINVAR	0
14998	07/14/2010	LTN050GEF	LOCHINVAR	0
14999	10/04/1999	BTR120	AO SMITH	0
15000	02/11/2009	LTN050G	LOCHINVAR	1
15001	10/06/2006	PR650	STATE	0
15002	01/04/2006	LTN050	LOCHINVAR	0
15003	08/06/1992	FSG50	AO SMITH	0
15004	03/04/1993	GVF8533T	RUUD	0
15005	11/14/2006	PR650X0DS	STATE	0
15006	04/18/2006	PR650	STATE	0
15007	09/18/1992	FSG50	AO SMITH	0
15008	07/15/2003	PRX50	STATE	0
15009	03/16/2012	MI403S6FBN	BRADFORD-WHITE	0
15010	02/16/2005	GVC50	A. O. SMITH	0
15011	01/13/2004	XTN050	LOCHINVAR	0
15012	04/04/2002	PGR50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15013	10/24/2011	PH2DV50F	RUUD	0
15014	08/05/2008	LTN050GEF	LOCHINVAR	0
15015	02/23/2007	PR650	STATE	1
15016	01/20/2000	PHR50	RUUD	0
15017	12/17/2001	G91200	RUUD/RHEEM	0
15018	12/20/2011	G91200	RUUD/RHEEM	1
15019	11/11/1998	41XR50	RHEEM	0
15020	11/03/2011	41VR50	RHEEM	0
15021	12/06/2007	PR650	STATE	1
15022	06/23/2010	LTN040G	LOCHINVAR	0
15023	12/17/2001	G91200	RUUD/RHEEM	0
15024	12/20/1991	FSG40	AO SMITH	0
15025	08/12/2003	PRX50	STATE	0
15026	12/15/2012	M45036FBN	BRADFORD-WHITE	0
15027	12/17/2001	G91200	RUUD/RHEEM	0
15028	06/23/2010	LTN040G	LOCHINVAR	0
15029	11/29/2005	LTN051G	LOCHINVAR	0
15030	10/27/2002	FSG50	AO SMITH	0
15031	01/05/1999	FSG50	AO SMITH	0
15032	01/03/2009	LTN050GEF	LOCHINVAR	0
15033	12/30/1991	FSGL40	AO SMITH	0
15034	08/08/2008	LTN050GEF	LOCHINVAR	0
15035	05/18/2002	FSG50	AO SMITH	0
15036	05/16/2000	41XR50	RHEEM	0
15037	05/28/2008	LTN050GEF	LOCHINVAR	0
15038	05/07/2012	MI403S6FBN	BRADFORD-WHITE	1
15039	09/19/2008	LTN050GEF	LOCHINVAR	0
15040	07/30/1992	FSG50	AO SMITH	0
15041	02/27/2007	42V6050	RHEEM	2
15042	06/16/2009	LTN040GEF	LOCHINVAR	0
15043	10/15/2005	LTN050G	LOCHINVAR	0
15044	10/22/2012	MI5036FBN	BRADFORD-WHITE	0
15045	03/06/2012	MI5036FBN	BRADFORD-WHITE	0
15046	06/06/2005	PR650	STATE	0
15047	06/28/2003	PVR50	AO SMITH	1
15048	06/15/2007	LSN041G	LOCHINVAR	0
15049	02/06/2013	PH2DV50F	RUUD	0
15050	12/24/2010	42VR50	RHEEM	0
15051	01/31/1991	FSG50	AO SMITH	0
15052	04/21/2008	LTN050GEF	LOCHINVAR	0
15053	06/20/2008	G91200	RUUD/RHEEM	0
15054	02/28/1999	FGR50	AO SMITH	0
15055	05/18/1993	FSG50	AO SMITH	1
15056	08/22/2011	MI5036FBN	BRADFORD-WHITE	0
15057	06/08/2011	42VR5040F	RHEEM	1
15058	04/27/1993	FSG50	AO SMITH	0
15059	02/09/1994	FGR50	AO SMITH	0
15060	04/13/2003	G91200	RUUD/RHEEM	0
15061	07/12/1993	21V502	RHEEM	0
15062	10/13/2012	M45036FBN	BRADFORD-WHITE	0
15063	03/30/2009	22DV50F	RHEEM	0
15064	02/26/1993	P502	RUUD	0
15065	01/12/2011	22DV50F	RHEEM	0
15066	10/17/2002	PRX50	STATE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15067	09/15/2012	PH2DV50F	RUUD	0
15068	02/08/2011	42VR50	RHEEM	0
15069	01/18/2000	41XR40	RHEEM	1
15070	10/27/2009	21V502	RHEEM	2
15071	02/23/1999	41VR50	RHEEM	0
15072	03/03/2012	M45036FBN	BRADFORD-WHITE	1
15073	01/09/2013	MI50L6FBN	BRADFORD-WHITE	0
15074	02/25/2005	PRX50	STATE	0
15075	03/22/1993	21V506	RHEEM	0
15076	09/13/2012	M45036FBN	BRADFORD-WHITE	0
15077	12/10/2009	LTN050GEF	LOCHINVAR	0
15078	09/06/2005	LTN050	LOCHINVAR	0
15079	02/09/1993	FSG50	AO SMITH	0
15080	07/31/2008	LTN050GEF	LOCHINVAR	0
15081	03/14/2008	LTN040GEF	LOCHINVAR	1
15082	08/12/2010	LTN050GEF	LOCHINVAR	2
15083	04/24/1998	FGR50	AO SMITH	0
15084	11/14/2009	LTN050GEF	LOCHINVAR	0
15085	03/18/2008	LTN050	LOCHINVAR	1
15086	12/07/2009	LTN050GEF	LOCHINVAR	0
15087	02/01/2000	FGR50	AO SMITH	0
15088	03/05/1999	PHR50	RUUD	0
15089	09/20/2012	PH2DV50F	RUUD	1
15090	08/27/2010	LTN050GEF	LOCHINVAR	0
15091	06/25/2011	MI5036FBN	BRADFORD-WHITE	0
15092	01/15/2007	LTN050G	LOCHINVAR	0
15093	03/27/2003	PGR50	AO SMITH	0
15094	04/03/2009	LTN050GEF	LOCHINVAR	0
15095	03/27/2011	41VR50	RHEEM	0
15096	02/03/2000	PRV50NODS	STATE	0
15097	06/16/2010	LTN050GEF	LOCHINVAR	0
15098	05/05/2010	LTN050GEF	LOCHINVAR	0
15099	07/26/2005	21DV50	RHEEM	0
15100	10/17/2011	M45036FBN	BRADFORD-WHITE	1
15101	05/27/2009	LTN050GEF	LOCHINVAR	0
15102	04/01/1994	F72DUMMY	AO SMITH	0
15103	09/21/2010	41VR50	RHEEM	0
15104	01/12/2004	PVR50	AO SMITH	0
15105	04/01/1994	F72DUMMY	AO SMITH	0
15106	06/10/2000	FSG50	AO SMITH	0
15107	04/04/2008	LTN050GEF	LOCHINVAR	0
15108	10/31/1996	FGR50	AO SMITH	0
15109	02/04/2000	FGR50	AO SMITH	0
15110	10/28/2011	PH2DV50F	RUUD	0
15111	12/26/2009	LTN050GEF	LOCHINVAR	0
15112	08/26/2009	LTN050GEF	LOCHINVAR	0
15113	07/10/2009	LTN050GEF	LOCHINVAR	0
15114	09/29/2011	PH250SF	RUUD	0
15115	06/08/2006	LTN040G	LOCHINVAR	0
15116	03/10/1999	41VR50	RHEEM	0
15117	08/01/2006	LTN050GEF	LOCHINVAR	0
15118	06/17/2006	LTN050G	LOCHINVAR	0
15119	03/12/1999	41VR50	RHEEM	0
15120	09/27/2006	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15121	11/26/2008	LTN050GEF	LOCHINVAR	1
15122	05/04/2012	M45036FBN	BRADFORD-WHITE	0
15123	04/14/2009	LTN050GEF	LOCHINVAR	0
15124	11/11/2004	GVC50	A. O. SMITH	0
15125	01/30/2012	M45036FBN	BRADFORD-WHITE	0
15126	02/11/2000	PHR50	RUUD	0
15127	07/07/2008	LTN050G	LOCHINVAR	0
15128	10/27/2010	G91200	RUUD/RHEEM	17
15129	07/12/1993	FSG50	AO SMITH	0
15130	11/10/2008	SBF100199NES	STATE	0
15131	05/21/2003	PGR50	AO SMITH	0
15132	10/20/2008	SBF100199NES	STATE	0
15133	05/26/1993	FSG50	AO SMITH	0
15134	03/23/2011	42VR50	RHEEM	0
15135	01/08/2011	22DV50F	RHEEM	0
15136	10/20/2004	FSG30	AO SMITH	0
15137	06/22/1992	FSG50	AO SMITH	1
15138	10/30/2009	LTN050GEF	LOCHINVAR	0
15139	01/19/1993	21V502	RHEEM	0
15140	03/24/2012	M45036FBN	BRADFORD-WHITE	0
15141	12/21/2007	PR650X0DS	STATE	0
15142	07/09/1993	PRV50NODS	STATE	0
15143	06/19/2008	LTN050GEF	LOCHINVAR	0
15144	07/27/2012	M45036FBN	BRADFORD-WHITE	0
15145	11/14/2010	22DV50F	RHEEM	3
15146	02/05/2005	XVR40	A. O. SMITH	0
15147	10/24/2012	PH2DV50F	RUUD	0
15148	02/15/1993	FSG50	AO SMITH	0
15149	02/22/2012	M45036FBN	BRADFORD-WHITE	0
15150	11/11/2003	PRX50	STATE	0
15151	09/15/2007	LTN050GEF	LOCHINVAR	0
15152	10/25/2000	FSGL40	AO SMITH	0
15153	03/04/2008	22DV50C	RHEEM	0
15154	03/12/2000	41XR50	RHEEM	1
15155	01/21/2002	PRX50	STATE	1
15156	11/15/2004	GVC50	A. O. SMITH	0
15157	06/27/2009	LTN050G	LOCHINVAR	0
15158	02/13/2002	FSG50	AO SMITH	0
15159	08/31/2007	LTN050GEF	LOCHINVAR	0
15160	01/19/2005	GVR50	AO SMITH	1
15161	04/12/1993	PRV50NODS	STATE	0
15162	11/14/2002	FSG50	AO SMITH	0
15163	01/21/2009	B71DUMMY	UNKNOWN AT CONVERSION	0
15164	04/11/2012	M45036FBN	BRADFORD-WHITE	0
15165	07/30/1993	21DV50	RHEEM	0
15166	01/09/2006	LTN050G	LOCHINVAR	0
15167	11/20/2009	LTN050GEF	LOCHINVAR	0
15168	04/27/2009	LTN050GEF	LOCHINVAR	1
15169	12/26/2006	LTN050G	LOCHINVAR	0
15170	03/11/2011	21VR50	RHEEM	0
15171	03/11/2009	LTN050GEF	LOCHINVAR	0
15172	11/21/2002	PRX50	STATE	0
15173	07/09/2010	LTN050G	LOCHINVAR	0
15174	08/04/2010	LTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15175	07/07/2008	LTN050G	LOCHINVAR	0
15176	02/18/2006	LTN050G	LOCHINVAR	0
15177	11/19/2011	M45036FBN	BRADFORD-WHITE	0
15178	05/04/1998	PRV50NODS	STATE	0
15179	04/29/1993	H72DUMMY	AO SMITH	0
15180	08/02/2009	LTN050GEF	LOCHINVAR	0
15181	11/22/2002	FSG50	AO SMITH	0
15182	08/03/2006	FGR40	AO SMITH	0
15183	01/09/2002	PRX50	STATE	0
15184	04/15/1994	RFD91200	RUUD	0
15185	01/14/2005	XVR50	A. O. SMITH	0
15186	01/08/1997	PR502T	RUUD	0
15187	03/19/1999	FGR50	AO SMITH	2
15188	05/07/1998	41VR40	RHEEM	0
15189	01/28/2006	LTN050G	LOCHINVAR	0
15190	01/21/2012	MI75S6FBN	BRADFORD-WHITE	6
15191	12/21/2006	LTN040GEF	LOCHINVAR	0
15192	08/31/2007	G91200	RUUD/RHEEM	2
15193	01/18/2013	G75125	RUUD/RHEEM	0
15194	03/19/1998	FGR50	AO SMITH	0
15195	04/16/2010	LTN050GEF	LOCHINVAR	0
15196	02/18/2000	FGR50	AO SMITH	0
15197	02/05/2007	PR650X0DS	STATE	0
15198	07/30/2004	XTN050	LOCHINVAR	0
15199	05/05/1993	H72DUMMY	AO SMITH	0
15200	01/04/2005	LTN050	LOCHINVAR	0
15201	03/19/1998	FGR50	AO SMITH	0
15202	09/25/2003	PVR50	AO SMITH	0
15203	01/24/2001	41VR50	RHEEM	0
15204	03/10/2008	LTN050	LOCHINVAR	0
15205	01/09/2012	M45036FBN	BRADFORD-WHITE	0
15206	06/03/2012	M45036FBN	BRADFORD-WHITE	1
15207	04/30/2007	PR650	STATE	0
15208	02/23/2000	PR650	STATE	0
15209	08/07/2007	LTN050GEF	LOCHINVAR	1
15210	07/20/2009	G75125	RUUD/RHEEM	0
15211	05/26/2006	PR650	STATE	0
15212	02/23/2000	FGR40	AO SMITH	0
15213	02/08/2011	21VR50	RHEEM	1
15214	09/03/2010	LSN041G	LOCHINVAR	0
15215	02/25/2000	FGR40	AO SMITH	0
15216	03/11/2013	M2XR504T6FBN	BRADFORD WHITE	8
15217	11/17/2003	PVR50	AO SMITH	0
15218	08/04/2011	M45036FBN	BRADFORD-WHITE	0
15219	05/06/1994	FGR50	AO SMITH	0
15220	07/28/2009	LTN050GEF	LOCHINVAR	1
15221	02/25/2000	G91200	RUUD/RHEEM	0
15222	03/07/2008	LTN050GEF	LOCHINVAR	0
15223	07/07/2011	22DV50F	RHEEM	1
15224	03/06/2007	LTN050G	LOCHINVAR	0
15225	03/01/2000	41XR50	RHEEM	0
15226	07/15/1993	PRV50NODS	STATE	0
15227	05/04/2006	LTN050G	LOCHINVAR	0
15228	11/15/2010	FSG50	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15229	08/23/2003	PRX50	STATE	0
15230	04/06/2011	21VR40	RHEEM	0
15231	08/11/2006	LTN050G	LOCHINVAR	1
15232	05/22/2008	22DV50C	RHEEM	0
15233	03/31/2011	21VR40	RHEEM	0
15234	09/25/2009	LTN050GEF	LOCHINVAR	0
15235	03/17/2001	41XR50	RHEEM	0
15236	02/26/1993	FSG50	AO SMITH	0
15237	06/20/2007	LTN050G	LOCHINVAR	2
15238	11/07/2005	PR650	STATE	0
15239	01/24/2011	LTN040G	LOCHINVAR	0
15240	11/18/1992	FSG50	AO SMITH	0
15241	12/18/2001	PGR50	AO SMITH	0
15242	07/11/2006	PR650	STATE	0
15243	08/21/2010	41VR50	RHEEM	0
15244	03/24/1993	21V506	RHEEM	0
15245	08/23/2002	PGR50	AO SMITH	0
15246	04/06/2005	GVC50	A. O. SMITH	1
15247	07/20/2001	FSG50	AO SMITH	0
15248	01/10/1992	FSG50	AO SMITH	0
15249	01/10/2010	21V502	RHEEM	0
15250	04/06/2005	GVC50	A. O. SMITH	0
15251	10/14/2006	LSN041G	LOCHINVAR	0
15252	04/11/2006	PR650	STATE	0
15253	02/01/1993	FSG50	AO SMITH	0
15254	04/08/2003	PRX50	STATE	0
15255	11/08/2005	PR650	STATE	0
15256	03/19/2011	21VR50	RHEEM	3
15257	03/14/2012	P502	RUUD	0
15258	05/07/2007	LTN050G	LOCHINVAR	0
15259	05/28/2010	22DV50F	RHEEM	0
15260	08/11/1992	PRV50NODS	STATE	0
15261	11/26/2012	M45036FBN	BRADFORD-WHITE	0
15262	08/20/2011	M440T6FBN	BRADFORD-WHITE	0
15263	12/05/2012	MI75S6FBN	BRADFORD-WHITE	0
15264	10/29/2002	PRX50	STATE	0
15265	06/01/2009	LTN050GEF	LOCHINVAR	0
15266	10/22/2004	GCVL40	A. O. SMITH	0
15267	12/30/2002	G91200	RUUD/RHEEM	0
15268	12/01/2004	GDVS50	AOSMITH	1
15269	08/20/2006	LTN050G	LOCHINVAR	0
15270	03/17/2004	FCV50	AO SMITH	0
15271	01/19/2006	GVC50	A. O. SMITH	0
15272	03/26/2006	LTN050G	LOCHINVAR	0
15273	02/01/2007	LTN050G	LOCHINVAR	0
15274	09/25/2008	LTN040GEF	LOCHINVAR	0
15275	11/06/2009	LTN050GEF	LOCHINVAR	0
15276	11/19/2009	PH199119	PHOENIX	0
15277	01/14/2012	MI5036FBN	BRADFORD-WHITE	2
15278	08/20/2005	LTN050	LOCHINVAR	0
15279	11/19/2009	PH199119	PHOENIX	0
15280	01/05/2006	21DV50	RHEEM	0
15281	07/10/2007	LTN040GEF	LOCHINVAR	0
15282	06/02/2012	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15283	12/15/2011	PR407	RUUD	0
15284	03/26/1999	FGR40	AO SMITH	0
15285	05/06/2010	LTN050GEF	LOCHINVAR	1
15286	10/05/2011	M45036FBN	BRADFORD-WHITE	0
15287	03/20/2012	M45036FBN	BRADFORD-WHITE	1
15288	03/27/1999	PHR40	RUUD	0
15289	11/10/2009	LTN050GEF	LOCHINVAR	0
15290	10/04/2006	G82156	RUUD/RHEEM	0
15291	12/30/2009	22DV50F	RHEEM	0
15292	04/20/1999	PR650	STATE	0
15293	01/28/1997	FGR50	AO SMITH	0
15294	05/19/1994	F72DUMMY	AO SMITH	0
15295	08/08/2008	LTN050GEF	LOCHINVAR	0
15296	11/16/2007	LTN050GEF	LOCHINVAR	0
15297	04/01/2008	LTN050	LOCHINVAR	0
15298	01/13/2009	22DV50C	RHEEM	0
15299	08/24/2011	M45036FBN	BRADFORD-WHITE	0
15300	03/30/1999	41VR50	RHEEM	0
15301	03/18/1993	21V502	RHEEM	0
15302	05/19/1998	FGR50	AO SMITH	0
15303	04/22/2011	41VR50	RHEEM	0
15304	05/14/2004	G75125	RUUD/RHEEM	0
15305	12/30/2011	G82156	RUUD/RHEEM	0
15306	06/20/2006	LTN050G	LOCHINVAR	0
15307	05/14/2004	G75125	RUUD/RHEEM	0
15308	02/15/2000	PHR50	RUUD	0
15309	05/21/1998	FGR50	AO SMITH	0
15310	10/26/2009	LTN050GEF	LOCHINVAR	0
15311	10/25/2012	MI50L6FBN	BRADFORD-WHITE	1
15312	02/15/2008	LSN041	LOCHINVAR	0
15313	05/13/2004	PRX50	STATE	0
15314	03/09/2000	41XR50	RHEEM	0
15315	07/17/2009	LTN050GEF	LOCHINVAR	0
15316	10/09/2012	M45036FBN	BRADFORD-WHITE	0
15317	04/06/1999	21V407	RHEEM	0
15318	12/17/2004	G91200	RUUD/RHEEM	0
15319	09/20/2008	22DV50F	RHEEM	0
15320	10/03/2008	PH199119	PHOENIX	2
15321	02/03/2010	21V502	RHEEM	2
15322	08/01/2011	M45036FBN	BRADFORD-WHITE	0
15323	03/16/2006	G91200	RUUD/RHEEM	0
15324	02/11/1997	PRV50NODS	STATE	0
15325	11/09/2010	21DV50	RHEEM	2
15326	06/22/2011	M45036FBN	BRADFORD-WHITE	1
15327	03/02/2010	G91200	RUUD/RHEEM	2
15328	04/07/2008	LTN050	LOCHINVAR	0
15329	06/01/1998	41VR50	RHEEM	0
15330	01/10/2013	G91200	RUUD/RHEEM	0
15331	12/30/2012	FGR50	AO SMITH	0
15332	05/05/2006	LTN040GEF	LOCHINVAR	0
15333	04/01/2008	G75125	RUUD/RHEEM	1
15334	02/14/2013	M45036FBN	BRADFORD-WHITE	0
15335	07/17/2008	LTN050GEF	LOCHINVAR	1
15336	12/02/2004	GVC50	A. O. SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15337	10/25/2004	GVC50	A. O. SMITH	1
15338	06/21/2011	MI50L6FBN	BRADFORD-WHITE	0
15339	05/01/2012	MI5036FBN	BRADFORD-WHITE	0
15340	12/04/2008	22DV50F	RHEEM	0
15341	02/20/1997	PR502T	RUUD	0
15342	05/01/2010	LTN050GEF	LOCHINVAR	0
15343	12/15/2011	MI5036FBN	BRADFORD-WHITE	0
15344	05/02/2007	SBD100199NES	STATE	0
15345	06/18/2008	22DV50F	RHEEM	0
15346	02/04/2011	LTN040GEF	LOCHINVAR	0
15347	01/11/2013	M45036FBN	BRADFORD-WHITE	0
15348	02/27/1997	G67114	RHEEM	0
15349	12/29/2011	M45036FBN	BRADFORD-WHITE	0
15350	02/15/2008	PR650	STATE	0
15351	01/27/2009	LTN050GEF	LOCHINVAR	0
15352	12/17/2009	LTN050GEF	LOCHINVAR	0
15353	05/27/2009	22DV50F	RHEEM	2
15354	11/06/2009	22DV50F	RHEEM	0
15355	07/25/2008	LTN050GEF	LOCHINVAR	0
15356	07/21/2005	PR650	STATE	0
15357	03/18/2000	41XR50	RHEEM	0
15358	11/26/2003	FCV50	AO SMITH	0
15359	11/18/2011	PH2DV50F	RUUD	0
15360	09/12/2011	M45036FBN	BRADFORD-WHITE	0
15361	04/29/1999	41VR50	RHEEM	0
15362	09/05/2002	G91200	RUUD/RHEEM	1
15363	01/27/2006	LTN050G	LOCHINVAR	0
15364	10/05/2011	G91200	RUUD/RHEEM	1
15365	11/02/2007	LTN050GEF	LOCHINVAR	0
15366	07/20/2009	LTN050GEF	LOCHINVAR	0
15367	08/01/2002	FSG50	AO SMITH	0
15368	12/14/2005	PR650	STATE	0
15369	02/07/2006	PR650	STATE	0
15370	03/09/2010	LTN050GEF	LOCHINVAR	0
15371	04/06/2010	LTN050GEF	LOCHINVAR	0
15372	01/05/2004	XVR50	A. O. SMITH	0
15373	04/21/2008	22DV50C	RHEEM	1
15374	08/12/2000	41XR50	RHEEM	0
15375	07/16/1992	21V502	RHEEM	0
15376	11/21/2009	LTN051G	LOCHINVAR	0
15377	09/24/1993	FSG50	AO SMITH	0
15378	06/14/2011	G75125	RUUD/RHEEM	0
15379	03/25/2005	XVR50	A. O. SMITH	0
15380	06/28/2010	LTN050G	LOCHINVAR	0
15381	03/15/2006	LTN050G	LOCHINVAR	0
15382	10/24/2006	PR650	STATE	0
15383	04/27/2001	G82156	RUUD/RHEEM	1
15384	07/18/2006	G91200	RUUD/RHEEM	0
15385	01/07/2005	GDVS50	AOSMITH	0
15386	12/18/2006	LTN040G	LOCHINVAR	0
15387	11/20/1992	P502	RUUD	0
15388	04/16/2004	PVR50	AO SMITH	0
15389	02/19/2012	M45036FBN	BRADFORD-WHITE	0
15390	12/20/2004	LTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15391	12/11/2007	LTN050GEF	LOCHINVAR	1
15392	09/16/2002	PGR50	AO SMITH	0
15393	02/04/2009	FSGL40	AO SMITH	4
15394	10/10/2001	G91200	RUUD/RHEEM	1
15395	04/27/2006	G91200	RUUD/RHEEM	0
15396	07/06/2010	21DV50	RHEEM	2
15397	02/07/2006	ETN076	LOCHINVAR	0
15398	09/25/1992	FSG50	AO SMITH	0
15399	05/06/2010	LTN050GEF	LOCHINVAR	0
15400	03/14/2006	PR650	STATE	0
15401	02/16/2009	LTN050GEF	LOCHINVAR	1
15402	04/28/2003	FSG50	AO SMITH	0
15403	09/23/1992	SBF100199NET	STATE	0
15404	11/17/2005	LTN050GEF	LOCHINVAR	0
15405	06/01/1992	P502	RUUD	0
15406	03/02/2002	PRX50	STATE	0
15407	09/14/2010	G91200	RUUD/RHEEM	1
15408	03/18/2008	LTN050GEF	LOCHINVAR	0
15409	04/29/1999	41VR50	RHEEM	0
15410	01/11/2012	M45036FBN	BRADFORD-WHITE	0
15411	09/06/2006	G75125	RUUD/RHEEM	0
15412	03/22/2000	41XR50	RHEEM	0
15413	06/08/2001	PGR50	AO SMITH	0
15414	11/12/2011	M45036FBN	BRADFORD-WHITE	1
15415	07/17/2011	M440T6FBN	BRADFORD-WHITE	0
15416	05/10/1999	G91200	RUUD/RHEEM	0
15417	12/29/2009	LTN040GEF	LOCHINVAR	1
15418	05/23/2008	22DV50C	RHEEM	0
15419	03/20/1997	PR502T	RUUD	0
15420	04/21/2008	LTN050GEF	LOCHINVAR	0
15421	07/27/1994	FGR50	AO SMITH	0
15422	12/09/2011	M45036FBN	BRADFORD-WHITE	0
15423	03/27/2000	PHR50	RUUD	1
15424	10/24/2005	G75125	RUUD/RHEEM	0
15425	06/23/1998	G91200	RUUD/RHEEM	1
15426	01/10/2013	M45036FBN	BRADFORD-WHITE	0
15427	04/21/2008	PH199119	PHOENIX	2
15428	10/09/2012	M45036FBN	BRADFORD-WHITE	0
15429	05/18/2012	G91200	RUUD/RHEEM	0
15430	09/27/2011	PH250SF	RUUD	0
15431	01/14/2010	LTN040GEF	LOCHINVAR	1
15432	05/12/1999	FGR50	AO SMITH	0
15433	05/17/2010	LTN050GEF	LOCHINVAR	0
15434	05/26/1993	FSG50	AO SMITH	0
15435	11/18/2012	G91200	RUUD/RHEEM	0
15436	07/20/2012	M45036FBN	BRADFORD-WHITE	0
15437	05/10/1999	G75125	RUUD/RHEEM	1
15438	03/15/2000	41XR50	RHEEM	0
15439	03/23/1997	H72DUMMY	AO SMITH	1
15440	04/16/2010	LTN050GEF	LOCHINVAR	0
15441	01/26/2013	M440T6FBN	BRADFORD-WHITE	0
15442	09/24/2009	ETN076	LOCHINVAR	0
15443	07/19/2004	GVC40	A. O. SMITH	1
15444	04/16/2010	LTN050G	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15445	03/07/2007	LSN041G	LOCHINVAR	0
15446	10/12/2010	G75125	RUUD/RHEEM	0
15447	02/03/2011	22DV50F	RHEEM	0
15448	03/18/2010	LTN050G	LOCHINVAR	2
15449	02/02/2000	G75125	RUUD/RHEEM	0
15450	01/21/2010	LTN050G	LOCHINVAR	0
15451	03/11/2011	G75125	RUUD/RHEEM	2
15452	10/25/2010	42VR50	RHEEM	0
15453	08/17/1994	FGR50	AO SMITH	0
15454	01/21/2010	LTN050GEF	LOCHINVAR	0
15455	11/03/2011	M45036FBN	BRADFORD-WHITE	0
15456	02/28/2000	41XR50	RHEEM	1
15457	10/24/2010	41VR50	RHEEM	1
15458	01/13/2011	21VR50	RHEEM	0
15459	01/15/1992	21V502	RHEEM	0
15460	09/15/2008	LTN040GEF	LOCHINVAR	0
15461	12/23/2005	GVC50	A. O. SMITH	0
15462	12/02/2007	LTN050G	LOCHINVAR	0
15463	01/23/2013	MI5036FBN	BRADFORD-WHITE	0
15464	09/21/2011	MI5036FBN	BRADFORD-WHITE	0
15465	08/05/2011	PH2DV50F	RUUD	0
15466	07/10/2012	M45036FBN	BRADFORD-WHITE	0
15467	09/02/2011	MI5036FBN	BRADFORD-WHITE	0
15468	10/16/2009	21DV50	RHEEM	0
15469	11/15/2002	G82156	RUUD/RHEEM	0
15470	05/16/2001	PGR50	AO SMITH	0
15471	09/23/1992	FSG50	AO SMITH	0
15472	06/20/2012	PH2DV50F	RUUD	1
15473	02/27/2008	LTN050GEF	LOCHINVAR	2
15474	11/22/2005	LTN050G	LOCHINVAR	0
15475	05/14/2010	LSN041G	LOCHINVAR	1
15476	01/04/2007	LTN040G	LOCHINVAR	0
15477	07/20/2009	LTN050GEF	LOCHINVAR	1
15478	07/22/2011	M45036FBN	BRADFORD-WHITE	2
15479	03/09/2004	FCV40	AO SMITH	0
15480	02/19/2013	MI40T6FBN	BRADFORD-WHITE	0
15481	07/27/2006	LTN050G	LOCHINVAR	0
15482	07/09/2010	FCV50	AO SMITH	1
15483	05/08/1992	FSG50	AO SMITH	0
15484	06/03/2003	FSG50	AO SMITH	0
15485	12/22/2006	PR650X0DS	STATE	0
15486	05/05/2005	FSG50	AO SMITH	1
15487	12/28/2006	LTN050G	LOCHINVAR	0
15488	05/11/2001	PR650	STATE	0
15489	07/05/2004	GVC50	A. O. SMITH	0
15490	12/18/1992	21DV50	RHEEM	0
15491	03/07/2006	21V506	RHEEM	0
15492	08/17/2009	LTN050GEF	LOCHINVAR	0
15493	04/21/2002	FSGL40	AO SMITH	0
15494	06/27/2010	LTN050GEF	LOCHINVAR	0
15495	10/25/2001	FSG50	AO SMITH	0
15496	06/12/2005	21V502	RHEEM	0
15497	12/04/2002	PGR50	AO SMITH	0
15498	10/21/2004	G75125	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15499	03/18/2009	LTN050GEF	LOCHINVAR	1
15500	10/28/2003	PGR50	AO SMITH	0
15501	04/26/2005	LTN050GEF	LOCHINVAR	0
15502	03/15/2012	PH2DV50F	RUUD	0
15503	03/15/2001	FSG50	AO SMITH	0
15504	01/04/2004	PRX50	STATE	0
15505	11/05/2008	22DV50F	RHEEM	0
15506	06/23/1998	41VR50	RHEEM	0
15507	10/14/2011	M45036FBN	BRADFORD-WHITE	0
15508	06/18/2010	LTN050G	LOCHINVAR	0
15509	11/15/2010	21VR50	RHEEM	0
15510	02/12/2009	22DV50C	RHEEM	0
15511	06/23/1998	FGR50	AO SMITH	0
15512	11/04/2009	LTN050GEF	LOCHINVAR	0
15513	09/10/2008	22DV50F	RHEEM	0
15514	03/27/2010	LTN050GEF	LOCHINVAR	0
15515	06/27/2012	MI5036FBN	BRADFORD-WHITE	0
15516	05/14/1999	FGR50	AO SMITH	1
15517	03/26/2010	LTN050GEF	LOCHINVAR	0
15518	09/07/2011	MI5036FBN	BRADFORD-WHITE	0
15519	10/29/2009	PR650	STATE	0
15520	06/30/1998	41VR50	RHEEM	0
15521	08/30/2007	CPN199100	LOCHINVAR	5
15522	04/09/2008	LTN050GEF	LOCHINVAR	0
15523	04/02/1997	BTC197	AO SMITH	0
15524	08/28/2012	M45036FBN	BRADFORD-WHITE	0
15525	03/08/2013	MI5036FBN	BRADFORD-WHITE	0
15526	04/18/2000	PHR50	RUUD	1
15527	08/15/2012	M440T6FBN	BRADFORD-WHITE	0
15528	06/21/1998	41VR50	RHEEM	0
15529	09/20/2012	M2XR504T6FBN	Bradford White	1
15530	04/04/2000	PGR50	AO SMITH	0
15531	01/14/2005	GVC50	A. O. SMITH	0
15532	07/09/1998	FGR50	AO SMITH	0
15533	08/04/1994	FGR50	AO SMITH	0
15534	04/04/2006	PR650	STATE	0
15535	09/19/1998	FSG50	AO SMITH	0
15536	10/19/2012	G75125	RUUD/RHEEM	6
15537	11/29/1994	PRV50NODS	STATE	0
15538	12/15/2009	LTN040GEF	LOCHINVAR	3
15539	04/07/1997	21VR502T	RHEEM	0
15540	08/18/2011	M440T6FBN	BRADFORD-WHITE	0
15541	03/16/2009	22DV50F	RHEEM	0
15542	08/04/1993	21DV50	RHEEM	0
15543	08/19/2011	M45036FBN	BRADFORD-WHITE	0
15544	09/21/1994	FGR50	AO SMITH	0
15545	08/11/2005	LTN050	LOCHINVAR	0
15546	04/15/1997	FGR50	AO SMITH	0
15547	10/02/1994	FGR50	AO SMITH	0
15548	09/18/2012	MI50L6FBN	BRADFORD-WHITE	0
15549	01/08/2012	M45036FBN	BRADFORD-WHITE	0
15550	04/24/2000	PRX50	STATE	0
15551	02/16/2012	M45036FBN	BRADFORD-WHITE	0
15552	11/24/2007	PR650	STATE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15553	01/13/2006	LTN050	LOCHINVAR	0
15554	09/10/2008	LTN050GEF	LOCHINVAR	0
15555	03/08/2006	42VR5040	RHEEM	1
15556	04/28/2000	FGR50	AO SMITH	0
15557	05/20/1999	G91200	RUUD/RHEEM	0
15558	07/15/1998	FGR50	AO SMITH	0
15559	05/31/2011	42VR5040F	RHEEM	0
15560	03/06/2006	LTN050G	LOCHINVAR	0
15561	04/29/2011	G91200	RUUD/RHEEM	1
15562	09/17/2011	M440T6FBN	BRADFORD-WHITE	0
15563	12/09/2008	G75125	RUUD/RHEEM	0
15564	02/28/2005	GVC50	A. O. SMITH	0
15565	04/25/1997	PR407	RUUD	0
15566	04/28/1997	G91200	RUUD/RHEEM	0
15567	01/18/2009	PH13080	PHOENIX	2
15568	09/30/2010	41VR50	RHEEM	1
15569	11/07/2012	MI5036FBN	BRADFORD-WHITE	0
15570	01/21/2010	LTN050GEF	LOCHINVAR	0
15571	02/19/2001	G91200	RUUD/RHEEM	0
15572	05/02/2000	41XR40	RHEEM	0
15573	05/24/1999	41VR50	RHEEM	0
15574	10/05/2011	41V50	RHEEM	2
15575	08/18/2000	G91200	RUUD/RHEEM	0
15576	05/02/2000	FGR40	AO SMITH	0
15577	03/03/2009	22DV50F	RHEEM	1
15578	05/03/2000	G91200	RUUD/RHEEM	0
15579	01/28/2012	M45036FBN	BRADFORD-WHITE	0
15580	11/05/2011	M45036FBN	BRADFORD-WHITE	0
15581	10/27/2010	G91200	RUUD/RHEEM	2
15582	02/14/2002	PRX50	STATE	0
15583	05/26/2006	G82156	RUUD/RHEEM	0
15584	06/01/1999	FGR50	AO SMITH	0
15585	12/05/1994	FGR50	AO SMITH	0
15586	05/05/2000	FSG50	AO SMITH	0
15587	04/30/2010	G91200	RUUD/RHEEM	0
15588	02/03/2012	41VR50	RHEEM	0
15589	01/30/2009	LTN050GEF	LOCHINVAR	0
15590	02/22/2008	G91200	RUUD/RHEEM	0
15591	06/02/1999	FGR50	AO SMITH	0
15592	02/22/2008	G91200	RUUD/RHEEM	0
15593	04/22/2005	LTN050G	LOCHINVAR	0
15594	03/19/2003	FSG50	AO SMITH	0
15595	09/16/2007	PR650	STATE	0
15596	04/28/2001	PRX50	STATE	0
15597	06/02/2011	41VR50	RHEEM	0
15598	12/05/2011	MI5036FBN	BRADFORD-WHITE	0
15599	11/24/1992	FSG50	AO SMITH	0
15600	04/21/2009	LTN050GEF	LOCHINVAR	0
15601	07/24/1998	G82156	RUUD/RHEEM	0
15602	10/22/1994	PR407	RUUD	0
15603	05/08/2000	PHR50	RUUD	0
15604	10/18/2000	BTC197	AO SMITH	0
15605	02/09/2013	M45036FBN	BRADFORD-WHITE	0
15606	03/09/2011	I72DUMMY	AO SMITH	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15607	10/18/2000	BTC197	AO SMITH	0
15608	04/17/2012	G91200	RUUD/RHEEM	3
15609	05/02/2009	LTN050GEF	LOCHINVAR	0
15610	11/14/2012	M45036FBN	BRADFORD-WHITE	0
15611	12/15/1994	PR502T	RUUD	0
15612	07/15/2010	G67114	RHEEM	0
15613	05/10/2010	G75125	RUUD/RHEEM	1
15614	05/12/2000	FGR50	AO SMITH	0
15615	03/24/2003	FSG50	AO SMITH	0
15616	03/18/1993	H72DUMMY	AO SMITH	1
15617	08/08/2011	M45036FBN	BRADFORD-WHITE	1
15618	04/01/2004	G82156	RUUD/RHEEM	0
15619	01/13/2012	M45036FBN	BRADFORD-WHITE	1
15620	06/19/2000	G91200	RUUD/RHEEM	0
15621	03/16/2005	GVC50	A. O. SMITH	1
15622	08/03/1998	H72DUMMY	AO SMITH	0
15623	07/09/2011	M45036FBN	BRADFORD-WHITE	0
15624	07/10/2007	LTN050GEF	LOCHINVAR	0
15625	05/29/1999	FGR50	AO SMITH	0
15626	05/18/2012	M45036FBN	BRADFORD-WHITE	0
15627	01/12/1995	SBF100199NES	STATE	0
15628	07/07/2010	LTN050G	LOCHINVAR	0
15629	01/12/2008	LTN050GEF	LOCHINVAR	0
15630	04/11/2009	LTN040GEF	LOCHINVAR	0
15631	07/30/1998	G91200	RUUD/RHEEM	2
15632	09/19/2008	22DV50F	RHEEM	0
15633	01/24/2002	PGR50	AO SMITH	0
15634	10/09/2010	21VR50	RHEEM	0
15635	05/18/2000	41XR50	RHEEM	0
15636	09/08/2010	G76200	RUUD/RHEEM	0
15637	05/11/2002	41XR50	RHEEM	1
15638	07/05/2006	LTN050G	LOCHINVAR	0
15639	08/17/2009	LTN050GEF	LOCHINVAR	1
15640	01/22/2009	RF92200	RUUD	0
15641	07/29/2008	22DV50F	RHEEM	0
15642	05/03/2011	21VR50	RHEEM	0
15643	02/19/2013	PH2DV50F	RUUD	1
15644	05/24/2000	FGR40	AO SMITH	1
15645	05/21/1997	G82156	RUUD/RHEEM	0
15646	05/30/2000	G82156	RUUD/RHEEM	0
15647	11/28/2005	PR650	STATE	0
15648	10/13/2006	LTN040G	LOCHINVAR	0
15649	06/14/1999	41VR50	RHEEM	0
15650	08/25/2010	LTN050GEF	LOCHINVAR	0
15651	01/20/1995	PR502T	RUUD	0
15652	05/24/2000	41XR50	RHEEM	0
15653	01/15/2011	41VR50	RHEEM	0
15654	05/09/1997	PRV50NODS	STATE	0
15655	12/30/2005	LTN050G	LOCHINVAR	0
15656	08/10/1998	RF67120	RUUD	0
15657	11/04/2003	G75125	RUUD/RHEEM	0
15658	04/16/2003	PGR50	AO SMITH	0
15659	11/17/2005	PR650	STATE	0
15660	01/12/2010	LTN050GEF	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15661	06/18/1999	41VR50	RHEEM	0
15662	04/02/2008	PR650	STATE	0
15663	06/04/2009	G76200	RUUD/RHEEM	1
15664	10/31/2012	MI75S6FBN	BRADFORD-WHITE	0
15665	04/11/2007	LTN050G	LOCHINVAR	1
15666	03/01/2012	M45036FBN	BRADFORD-WHITE	1
15667	01/15/2008	LTN050GEF	LOCHINVAR	1
15668	06/04/2009	G76200	RUUD/RHEEM	0
15669	12/06/2008	LTN050GEF	LOCHINVAR	2
15670	10/14/2010	22DV50F	RHEEM	0
15671	01/06/2007	LTN050	LOCHINVAR	0
15672	07/28/2005	LTN050G	LOCHINVAR	0
15673	09/14/2011	M45036FBN	BRADFORD-WHITE	0
15674	12/28/2010	21VR50	RHEEM	0
15675	07/22/2004	PRX50	STATE	0
15676	05/30/2000	PHR50	RUUD	0
15677	06/10/2010	22DV50F	RHEEM	2
15678	06/09/1997	FGR50	AO SMITH	0
15679	12/14/2010	42VR50	RHEEM	1
15680	11/12/2006	PR650	STATE	0
15681	01/09/2013	G76200	RUUD/RHEEM	0
15682	05/24/2000	41XR50	RHEEM	0
15683	02/05/2003	BTR197	AO SMITH	0
15684	03/05/2008	PR640	STATE	0
15685	05/09/2008	LTN040GEF	LOCHINVAR	0
15686	02/20/2013	G76200	RUUD/RHEEM	0
15687	12/31/2004	PRX50	STATE	0
15688	07/14/1993	RF67120	RUUD	0
15689	08/31/2012	M45036FBN	BRADFORD-WHITE	0
15690	01/17/2013	MI403S6FBN	BRADFORD-WHITE	0
15691	11/09/2009	PH199119	PHOENIX	0
15692	05/14/2003	PGR50	AO SMITH	0
15693	02/03/2013	MI5036FBN	BRADFORD-WHITE	0
15694	03/31/1993	21V502	RHEEM	0
15695	11/17/2007	LTN050GEF	LOCHINVAR	0
15696	06/28/2011	MI50L6FBN	BRADFORD-WHITE	0
15697	10/12/2010	21V407	RHEEM	0
15698	05/26/2009	41V50	RHEEM	1
15699	02/08/2010	GVC50	A. O. SMITH	0
15700	01/25/2010	LTN050GEF	LOCHINVAR	0
15701	07/21/2007	LTN050GEF	LOCHINVAR	0
15702	06/15/1999	SSV119199	VOYAGER	2
15703	06/15/1999	SSV119199	VOYAGER	0
15704	09/28/2007	G75125	RUUD/RHEEM	1
15705	08/03/2010	LTN050GEF	LOCHINVAR	0
15706	08/26/1998	PHR50	RUUD	0
15707	11/01/2007	PH199119	PHOENIX	1
15708	06/11/2003	H72DUMMY	AO SMITH	0
15709	12/15/2007	LTN050GEF	LOCHINVAR	0
15710	06/12/2000	G76200	RUUD/RHEEM	1
15711	07/02/1993	RFD91200	RUUD	0
15712	11/03/2008	LTN050GEF	LOCHINVAR	0
15713	06/05/2012	M45036FBN	BRADFORD-WHITE	0
15714	06/06/2000	41XR50	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15715	03/28/1994	RF82156	RUUD	0
15716	01/30/2013	M45036FBN	BRADFORD-WHITE	1
15717	06/18/1997	21VR50	RHEEM	1
15718	04/18/2008	LTN040GEF	LOCHINVAR	0
15719	06/30/2010	22DV50F	RHEEM	0
15720	09/02/1998	G91200	RUUD/RHEEM	0
15721	01/27/2005	GVC50	A. O. SMITH	0
15722	03/14/2009	LTN050GEF	LOCHINVAR	0
15723	02/17/2003	41VR50	RHEEM	1
15724	06/26/1997	FGR50	AO SMITH	0
15725	05/14/2012	M45036FBN	BRADFORD-WHITE	0
15726	10/02/2012	MI5036FBN	BRADFORD-WHITE	1
15727	03/31/1995	FGR50	AO SMITH	0
15728	09/03/1998	BTR199	AO SMITH	0
15729	07/02/2007	PR650	STATE	0
15730	03/08/2013	MI5036FBN	BRADFORD-WHITE	0
15731	12/31/2009	LTN050GEF	LOCHINVAR	0
15732	06/21/2000	41XR40	RHEEM	0
15733	07/22/2005	LTN050	LOCHINVAR	0
15734	08/07/2012	MI40T6FBN	BRADFORD-WHITE	1
15735	11/02/2010	42VR50	RHEEM	1
15736	07/07/1997	G67114	RHEEM	0
15737	12/28/2007	LTN040GEF	LOCHINVAR	0
15738	04/26/2011	G91200	RUUD/RHEEM	0
15739	07/09/1993	RF82156	RUUD	0
15740	02/11/2011	G91200	RUUD/RHEEM	0
15741	01/06/2011	41VR40	RHEEM	0
15742	03/07/2005	GVC50	A. O. SMITH	1
15743	08/23/1999	PHR50	RUUD	1
15744	07/09/1993	P506	RUUD	0
15745	01/04/2006	LTN050GEF	LOCHINVAR	0
15746	07/08/1997	PR502T	RUUD	0
15747	12/18/2003	G76200	RUUD/RHEEM	0
15748	07/20/1999	PHR50	RUUD	0
15749	06/04/2012	G82156	RUUD/RHEEM	0
15750	07/15/1997	41VR50	RHEEM	0
15751	09/06/2009	LTN050GEF	LOCHINVAR	0
15752	02/14/2012	G91200	RUUD/RHEEM	1
15753	04/25/2011	22DV50F	RHEEM	0
15754	05/30/2007	G91200	RUUD/RHEEM	0
15755	11/17/2010	LTN040G	LOCHINVAR	0
15756	06/04/2010	22DV50C	RHEEM	0
15757	03/29/2010	LTN040GEF	LOCHINVAR	0
15758	07/19/2010	PGR50	AO SMITH	0
15759	07/20/1999	PHR40	RUUD	0
15760	03/30/2011	42VR50	RHEEM	0
15761	04/13/2007	LTN050G	LOCHINVAR	1
15762	11/02/2011	G91200	RUUD/RHEEM	1
15763	06/18/2008	LTN050GEF	LOCHINVAR	0
15764	06/08/2011	22DV50F	RHEEM	0
15765	07/23/1999	FGR50	AO SMITH	0
15766	10/02/1998	BTR199	AO SMITH	0
15767	05/06/1993	21V502	RHEEM	0
15768	07/01/2000	BTR154	AO SMITH	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15769	10/31/2007	PR650	STATE	0
15770	10/06/2007	G82156	RUUD/RHEEM	2
15771	02/24/2006	PH30	RUUD	0
15772	12/27/2010	LTN040GEF	LOCHINVAR	0
15773	11/30/2009	22DV50F	RHEEM	0
15774	11/04/2010	42VR50	RHEEM	0
15775	07/13/1993	P502	RUUD	0
15776	09/22/2012	FGR50	AO SMITH	0
15777	08/14/2008	42VR5040	RHEEM	0
15778	09/18/1998	41VR50	RHEEM	0
15779	12/27/2011	M45036FBN	BRADFORD-WHITE	0
15780	03/05/2011	LTN030G	AO SMITH	1
15781	03/14/2011	42VR50	RHEEM	0
15782	08/06/1997	FGR50	AO SMITH	0
15783	02/04/2008	LTN050GEF	LOCHINVAR	0
15784	09/21/1998	G91200	RUUD/RHEEM	0
15785	08/13/2008	FGR30	AO SMITH	0
15786	04/06/2005	FCV40	AO SMITH	0
15787	06/11/2012	MI403S6FBN	BRADFORD-WHITE	0
15788	06/06/2006	LTN040G	LOCHINVAR	1
15789	09/20/2007	FGR30	AO SMITH	0
15790	08/13/1997	BTC197	AO SMITH	0
15791	08/20/1999	PHR50	RUUD	0
15792	08/30/2010	LSN041G	LOCHINVAR	0
15793	03/25/2010	21DV50	RHEEM	0
15794	08/02/1999	FGR50	AO SMITH	0
15795	07/27/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15796	10/17/2009	LTN050GEF	LOCHINVAR	0
15797	10/27/2010	42VR50	RHEEM	0
15798	07/27/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15799	01/19/2011	21VR40	RHEEM	0
15800	03/31/2004	GVC50	A. O. SMITH	0
15801	09/21/1998	41VR50	RHEEM	0
15802	01/06/2010	LTN050G	LOCHINVAR	0
15803	05/15/1992	21V502	RHEEM	0
15804	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15805	05/11/2002	PGR40	AO SMITH	0
15806	11/01/1993	21V506	RHEEM	1
15807	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15808	12/28/2009	22DV50F	RHEEM	0
15809	06/30/2010	22DV50C	RHEEM	0
15810	10/08/2011	M45036FBN	BRADFORD-WHITE	0
15811	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15812	02/24/2008	LTN040	LOCHINVAR	0
15813	08/22/2006	PR650	STATE	1
15814	01/24/2011	P502	RUUD	0
15815	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15816	10/02/1998	FGR50	AO SMITH	0
15817	04/09/2008	LTN050	LOCHINVAR	0
15818	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15819	10/08/2004	G91200	RUUD/RHEEM	0
15820	10/08/2009	LTN050GEF	LOCHINVAR	1
15821	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15822	08/10/1999	PHR50	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15823	06/15/2012	M2XR504T6FBN	Bradford White	0
15824	02/13/2008	LSN041G	LOCHINVAR	0
15825	10/01/1998	41VR50	RHEEM	0
15826	06/15/2012	M2XR504T6FBN	Bradford White	0
15827	08/31/2012	M45036FBN	BRADFORD-WHITE	0
15828	10/07/2010	22DV50C	RHEEM	0
15829	05/22/2006	LTN050GEF	LOCHINVAR	0
15830	01/15/2008	LTN050GEF	LOCHINVAR	0
15831	06/15/2012	M2XR504T6FBN	Bradford White	1
15832	08/30/1997	41VR50	RHEEM	0
15833	12/05/2012	M45036FBN	BRADFORD-WHITE	0
15834	07/26/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15835	07/26/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15836	07/09/2003	BTR120	AO SMITH	1
15837	08/09/2010	LTN050GEF	LOCHINVAR	1
15838	03/31/2010	LTN040GEF	LOCHINVAR	0
15839	01/06/2010	LTN050G	LOCHINVAR	0
15840	04/13/2009	G75125	RUUD/RHEEM	0
15841	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15842	05/07/2006	LTN050G	LOCHINVAR	0
15843	09/14/2009	LTN050GEF	LOCHINVAR	0
15844	10/09/1998	PHR50	RUUD	0
15845	08/28/1999	PHR50	RUUD	0
15846	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15847	08/09/1993	P502	RUUD	0
15848	08/12/2008	LTN050GEF	LOCHINVAR	0
15849	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	0
15850	09/11/1997	PR502T	RUUD	0
15851	12/07/2005	LTN050GEF	LOCHINVAR	1
15852	08/03/2010	LTN050G	LOCHINVAR	0
15853	05/30/2006	G82156	RUUD/RHEEM	3
15854	08/21/1999	PHR50	RUUD	0
15855	08/10/1993	FSG50	AO SMITH	0
15856	01/14/2009	22DV50F	RHEEM	0
15857	10/09/1998	FGR50	AO SMITH	0
15858	10/03/2007	LTN050GEF	LOCHINVAR	0
15859	08/03/1995	L72DUMMY	AO SMITH	0
15860	08/27/1993	21V502	RHEEM	0
15861	09/17/1997	41VR50	RHEEM	0
15862	10/09/1998	41VR50	RHEEM	0
15863	06/11/2004	GCVL40	A. O. SMITH	1
15864	08/27/1999	PHR50	RUUD	0
15865	02/04/2002	PGR50	AO SMITH	1
15866	05/05/1995	FGR50	AO SMITH	0
15867	12/12/1997	PR502T	RUUD	0
15868	02/09/2007	LTN050	LOCHINVAR	0
15869	04/28/2008	22DV50F	RHEEM	1
15870	09/16/1997	PRV50NODS	STATE	0
15871	08/18/1999	41VR50	RHEEM	0
15872	03/22/2006	LSN041G	LOCHINVAR	0
15873	10/12/1998	PR650	STATE	0
15874	04/01/2009	FGR50	AO SMITH	0
15875	02/23/2009	LTN050GEF	LOCHINVAR	0
15876	09/18/1997	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15877	10/14/1998	PHR50	RUUD	0
15878	12/03/2008	LTN050GEF	LOCHINVAR	0
15879	11/01/2006	LTN050G	LOCHINVAR	0
15880	07/08/2008	22DV50C	RHEEM	0
15881	02/04/2010	G82156	RUUD/RHEEM	0
15882	03/11/2013	D71DUMMY	UNKNOWN AT CONVERSION	0
15883	08/27/2001	PR650	STATE	0
15884	08/12/2003	PGR50	AO SMITH	0
15885	05/26/2010	LTN050GEF	LOCHINVAR	0
15886	10/26/2010	21VR50	RHEEM	0
15887	03/31/2010	ETN076	LOCHINVAR	0
15888	02/21/2012	M45036FBN	BRADFORD-WHITE	0
15889	12/28/2012	M440T6FBN	BRADFORD-WHITE	0
15890	09/22/2008	LSN041G	LOCHINVAR	0
15891	08/17/2009	LTN050GEF	LOCHINVAR	0
15892	03/10/2012	M45036FBN	BRADFORD-WHITE	0
15893	07/22/2009	LTN050GEF	LOCHINVAR	0
15894	08/25/1999	FGR50	AO SMITH	0
15895	08/06/1993	FSG50	AO SMITH	0
15896	04/08/2005	FCV40	AO SMITH	0
15897	03/12/1993	G72DUMMY	AO SMITH	0
15898	10/30/1995	FGR40	AO SMITH	0
15899	04/19/2011	21VR40	RHEEM	0
15900	08/04/1993	P502	RUUD	0
15901	10/11/1999	BTH199	AO SMITH	1
15902	01/15/2012	MI5036FBN	BRADFORD-WHITE	0
15903	03/12/1993	FSG50	AO SMITH	0
15904	03/12/2006	LTN050G	LOCHINVAR	1
15905	01/03/2004	PRX50	STATE	0
15906	10/03/1997	I72DUMMY	AO SMITH	0
15907	02/12/2010	LTN050G	LOCHINVAR	0
15908	08/28/1999	PHR40	RUUD	0
15909	02/20/2003	FGR50	AO SMITH	1
15910	04/24/2012	PH2DV50F	RUUD	0
15911	10/27/1998	FGR40	AO SMITH	0
15912	11/10/2012	PH2DV50F	RUUD	0
15913	08/27/1999	H72DUMMY	AO SMITH	0
15914	10/25/2005	LTN050G	LOCHINVAR	0
15915	04/11/2011	42VR50	RHEEM	0
15916	02/26/1993	21V502	RHEEM	0
15917	08/05/1999	41VR50	RHEEM	0
15918	01/21/2010	PR650	STATE	0
15919	03/17/1993	P506	RUUD	0
15920	02/19/2008	G82156	RUUD/RHEEM	0
15921	01/03/2004	PVR50	AO SMITH	1
15922	11/11/2011	MI5036FBN	BRADFORD-WHITE	0
15923	10/25/2008	LSN041G	LOCHINVAR	0
15924	10/11/2009	MI40T6FBN	BRADFORD-WHITE	0
15925	05/30/2012	MI5036FBN	BRADFORD-WHITE	0
15926	03/19/2007	TNR200100	LOCHINVAR	0
15927	04/02/2007	LTN050G	LOCHINVAR	0
15928	01/19/2010	LTN050GEF	LOCHINVAR	1
15929	11/01/2012	PH2DV50F	RUUD	0
15930	09/07/1999	FGR40	AO SMITH	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15931	02/18/2009	LTN050GEF	LOCHINVAR	2
15932	01/04/2001	G82156	RUUD/RHEEM	0
15933	12/08/2010	21VR50	RHEEM	0
15934	01/23/2001	H72DUMMY	AO SMITH	0
15935	10/05/2006	PR650	STATE	0
15936	10/16/1997	41VR40	RHEEM	0
15937	01/14/2005	GVC50	A. O. SMITH	0
15938	09/09/1999	PHR50	RUUD	0
15939	11/06/1998	21V502	RHEEM	0
15940	09/28/2009	PRV50NODS	STATE	0
15941	05/29/2010	LTN050	LOCHINVAR	0
15942	04/05/2008	LTN050G	LOCHINVAR	0
15943	06/15/2012	M45036FBN	BRADFORD-WHITE	0
15944	06/25/2012	PH2DV50F	RUUD	2
15945	11/16/2010	42VR50	RHEEM	0
15946	07/14/2010	LTN050GEF	LOCHINVAR	0
15947	06/24/1993	FSG50	AO SMITH	0
15948	07/26/2012	G75125	RUUD/RHEEM	0
15949	01/04/2012	MI5036FBN	BRADFORD-WHITE	0
15950	07/09/2012	G91200	RUUD/RHEEM	2
15951	02/12/2009	22DV50F	RHEEM	1
15952	10/04/2011	G82156	RUUD/RHEEM	4
15953	05/04/2006	LTN050G	LOCHINVAR	0
15954	04/23/2009	LTN050GEF	LOCHINVAR	1
15955	06/29/2011	M45036FBN	BRADFORD-WHITE	0
15956	02/13/2004	H72DUMMY	AO SMITH	0
15957	01/16/2011	42VR50	RHEEM	0
15958	01/06/2011	21VR40	RHEEM	0
15959	02/13/2004	H72DUMMY	AO SMITH	0
15960	10/28/1997	FGR50	AO SMITH	0
15961	03/14/2011	21VR50	RHEEM	0
15962	06/23/1999	FGR50	AO SMITH	0
15963	07/14/2011	DS150S6FBN	BRADFORD-WHITE	0
15964	08/30/1993	21V502	RHEEM	0
15965	11/30/2004	GVC50	A. O. SMITH	0
15966	10/30/1995	PRV50NODS	STATE	0
15967	11/19/1998	BW50	BRADFORD-WHITE	0
15968	06/16/2008	LTN050GEF	LOCHINVAR	0
15969	08/22/2007	LTN050G	LOCHINVAR	0
15970	03/06/2012	M45036FBN	BRADFORD-WHITE	0
15971	11/19/1998	BW50	BRADFORD-WHITE	1
15972	09/08/2009	LTN050GEF	LOCHINVAR	0
15973	12/11/1995	BTC197	AO SMITH	0
15974	01/05/1994	FGR50	AO SMITH	0
15975	11/23/1998	FGR50	AO SMITH	0
15976	09/20/1999	FGR50	AO SMITH	0
15977	12/14/2006	LTN050G	LOCHINVAR	0
15978	03/01/2010	LTN050GEF	LOCHINVAR	0
15979	09/30/2004	G91200	RUUD/RHEEM	0
15980	05/30/2006	LTN050G	LOCHINVAR	2
15981	12/30/1998	SBF100199NET	STATE	0
15982	09/30/2004	G91200	RUUD/RHEEM	0
15983	10/01/2009	G82156	RUUD/RHEEM	0
15984	04/07/2006	LTN050G	LOCHINVAR	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
15985	12/09/2009	22DV50F	RHEEM	0
15986	08/04/2010	LTN050GEF	LOCHINVAR	3
15987	02/19/2011	21VR50	RHEEM	0
15988	09/22/1999	PHR50	RUUD	0
15989	01/07/2012	PH2DV50F	RUUD	0
15990	12/13/2010	LTN040GEF	LOCHINVAR	0
15991	04/10/2006	LTN050G	LOCHINVAR	0
15992	02/19/2013	M45036FBN	BRADFORD-WHITE	0
15993	03/18/2011	42VR50	RHEEM	1
15994	03/22/2008	PH199119	PHOENIX	0
15995	11/07/1997	41VR50	RHEEM	0
15996	12/11/2008	LTN050GEF	LOCHINVAR	0
15997	12/21/2012	MI5036FBN	BRADFORD-WHITE	0
15998	11/30/1998	SSV119199	VOYAGER	0
15999	04/14/2005	GVC50	A. O. SMITH	0
16000	01/09/2008	G91200	RUUD/RHEEM	0
16001	01/10/1994	FSG50	AO SMITH	0
16002	11/25/1998	41VR50	RHEEM	0
16003	02/23/2007	LTN050G	LOCHINVAR	0
16004	03/12/2012	M440T6FBN	BRADFORD-WHITE	0
16005	12/02/2010	22DV50F	RHEEM	1
16006	02/26/1993	FSG50	AO SMITH	0
16007	11/22/1997	FGR50	AO SMITH	0
16008	04/16/2012	G72DUMMY	AO SMITH	0
16009	01/27/2006	LTN040G	LOCHINVAR	0
16010	05/26/2012	MI5036FBN	BRADFORD-WHITE	0
16011	10/28/2004	G91200	RUUD/RHEEM	0
16012	10/02/2009	H72DUMMY	LOCHINVAR	2
16013	09/10/2012	MI5036FBN	BRADFORD-WHITE	1
16014	04/28/2011	41VR50	RHEEM	2
16015	07/14/2011	M45036FBN	BRADFORD-WHITE	3
16016	11/12/2012	MI50L6FBN	BRADFORD-WHITE	0
16017	10/06/1999	PHR50	RUUD	0
16018	05/22/2012	MI5036FBN	BRADFORD-WHITE	0
16019	12/16/2004	FGR50	AO SMITH	0
16020	06/07/2012	M45036FBN	BRADFORD-WHITE	0
16021	09/28/2009	22DV50C	RHEEM	1
16022	12/11/2009	LTN050GEF	LOCHINVAR	0
16023	03/28/2003	PGR50	AO SMITH	0
16024	09/30/1993	FSG50	AO SMITH	0
16025	10/01/2001	PGR50	AO SMITH	0
16026	05/22/2002	G75125	RUUD/RHEEM	0
16027	12/14/2010	22DV50F	RHEEM	0
16028	10/08/1999	PHR50	RUUD	0
16029	12/07/2004	PRX50	STATE	0
16030	11/30/1998	PR650	STATE	0
16031	12/05/1997	FGR50	AO SMITH	0
16032	07/12/2011	22DV50F	RHEEM	0
16033	10/08/1999	PR650	STATE	0
16034	12/06/1997	FGR50	AO SMITH	0
16035	06/03/2010	LTN050GEF	LOCHINVAR	0
16036	12/03/2010	42VR50	RHEEM	0
16037	11/27/1997	41VR50	RHEEM	0
16038	08/24/2007	FSG30	AO SMITH	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16039	07/14/2009	22DV50F	RHEEM	0
16040	02/23/2011	I72DUMMY	AO SMITH	0
16041	02/20/2013	M45036FBN	BRADFORD-WHITE	0
16042	10/18/2007	LTN050GEF	LOCHINVAR	0
16043	05/21/2011	22DV50F	RHEEM	0
16044	12/03/2009	LTN050GEF	LOCHINVAR	0
16045	01/05/2011	G82156	RUUD/RHEEM	0
16046	05/09/2007	PR650X0DS	STATE	0
16047	12/03/1998	41VR50	RHEEM	0
16048	09/10/2012	MI5036FBN	BRADFORD-WHITE	0
16049	07/07/2006	LTN050G	LOCHINVAR	0
16050	11/07/2011	PH2DV50F	RUUD	0
16051	07/30/2012	MI5036FBN	BRADFORD-WHITE	2
16052	05/17/2007	G91200	RUUD/RHEEM	0
16053	12/08/2008	LTN050GEF	LOCHINVAR	1
16054	03/13/2007	G91200	RUUD/RHEEM	0
16055	08/02/2012	M45036FBN	BRADFORD-WHITE	0
16056	11/22/2009	PRV50NODS	STATE	0
16057	12/26/2007	ETN076	LOCHINVAR	1
16058	10/29/1999	41VR50	RHEEM	0
16059	10/29/2009	22DV50F	RHEEM	0
16060	07/19/2010	22DV50F	RHEEM	0
16061	04/27/2007	LTN050G	LOCHINVAR	0
16062	02/21/2012	G91200	RUUD/RHEEM	1
16063	12/10/1997	FSGL40	AO SMITH	0
16064	10/13/2004	G91200	RUUD/RHEEM	2
16065	08/04/2007	PR650	STATE	0
16066	08/28/2010	LTN050GEF	LOCHINVAR	0
16067	09/01/1993	FSG50	AO SMITH	0
16068	07/04/2005	G91200	RUUD/RHEEM	0
16069	12/08/2011	PH2DV50F	RUUD	0
16070	10/25/1999	PHR50	RUUD	0
16071	10/17/2012	MI75S6FBN	BRADFORD-WHITE	0
16072	08/20/2012	M45036FBN	BRADFORD-WHITE	0
16073	06/09/2004	41VR50	RHEEM	0
16074	10/31/2005	LTN040G	LOCHINVAR	1
16075	12/01/1998	G67114	RHEEM	0
16076	12/11/2002	PGR50	AO SMITH	0
16077	11/21/1997	PRV50NODS	STATE	0
16078	03/12/2010	LTN050GEF	LOCHINVAR	0
16079	10/10/2011	G75125	RUUD/RHEEM	0
16080	02/23/1996	PR502T	RUUD	0
16081	10/29/1999	41XR50	RHEEM	0
16082	03/10/2012	FGR40	AO SMITH	0
16083	10/29/1999	PHR50	RUUD	0
16084	02/14/2010	LTN050GEF	LOCHINVAR	0
16085	03/17/1994	PRV50NODS	STATE	0
16086	12/12/1998	PRV40NODS	STATE	0
16087	11/15/2011	GVC50	A. O. SMITH	0
16088	05/02/2012	DS150S6FBN	BRADFORD-WHITE	0
16089	01/11/2011	41VR50	RHEEM	0
16090	04/12/2005	P506	RUUD	0
16091	11/27/2001	FSG50	AO SMITH	0
16092	07/08/2004	XTN050	LOCHINVAR	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16093	12/22/2010	G91200	RUUD/RHEEM	0
16094	04/24/2002	PRX50	STATE	0
16095	01/21/2005	G82156	RUUD/RHEEM	0
16096	03/16/2010	LTN050GEF	LOCHINVAR	0
16097	05/19/2005	LTN050	LOCHINVAR	0
16098	11/17/1999	PHR50	RUUD	0
16099	10/16/2009	LTN050GEF	LOCHINVAR	0
16100	04/13/1998	G91200	RUUD/RHEEM	1
16101	01/27/2010	LTN050GEF	LOCHINVAR	0
16102	10/19/2011	G91200	RUUD/RHEEM	0
16103	05/03/2012	MI5036FBN	BRADFORD-WHITE	0
16104	10/10/2011	PR650	STATE	0
16105	06/07/2007	LTN050G	LOCHINVAR	0
16106	09/17/1993	G76200	RUUD/RHEEM	0
16107	02/04/2009	LTN040GEF	LOCHINVAR	0
16108	11/12/1999	FGR40	AO SMITH	0
16109	09/17/1993	G76200	RUUD/RHEEM	0
16110	04/24/2006	LTN050G	LOCHINVAR	0
16111	04/14/2009	LTN050GEF	LOCHINVAR	0
16112	07/28/2009	LTN040GEF	LOCHINVAR	0
16113	07/02/2009	LTN050GEF	LOCHINVAR	0
16114	07/31/2009	LTN050GEF	LOCHINVAR	0
16115	01/06/1998	41VR40	RHEEM	0
16116	02/06/1998	PRV50NODS	STATE	0
16117	03/23/1993	PH30	RUUD	0
16118	05/01/2001	41V40S	RHEEM	0
16119	03/14/2011	42VR50	RHEEM	0
16120	01/27/2010	LTN050GEF	LOCHINVAR	0
16121	02/21/2007	LTN050G	LOCHINVAR	0
16122	08/24/2010	42VR50	RHEEM	0
16123	05/18/2006	LTN050GEF	LOCHINVAR	0
16124	09/28/2001	FSG50	AO SMITH	0
16125	04/08/2010	LTN050GEF	LOCHINVAR	0
16126	09/27/2010	FSG50	AO SMITH	0
16127	08/31/2004	G76200	RUUD/RHEEM	0
16128	08/31/2004	G76200	RUUD/RHEEM	1
16129	08/31/2004	G76200	RUUD/RHEEM	0
16130	01/08/2009	LTN050GEF	LOCHINVAR	0
16131	06/17/2010	21V502	RHEEM	0
16132	04/06/1993	FSG50	AO SMITH	0
16133	03/25/2013	ph2dv50f	ruud	0
16134	03/14/2013	ph2dv50f	ruud	0
16135	03/29/2013	mi5036fbn	bradford-white	0
16136	03/29/2013	M45036FBN	bradford-white	1
16137	03/30/2013	MI403S6FBN	Bradford-White	0
16138	03/13/2013	M45036FBn	Bradford-White	0
16139	03/19/2013	M45036FBN	Bradford-White	0
16140	03/13/2013	PH2DV50F	Ruud	0
16141	03/17/2013	MI5036FBN	bradford-white	0
16142	03/29/2013	MI40T6FBN	Bradfor-White	0
16143	03/18/2013	M45036FBN	Bradford-White	0
16144	03/20/2013	M45036FBN	Bradford-White	0
16145	03/18/2013	MI5036FBN	Bradford-White	0
16146	03/23/2013	MI403S6FBN	Bradford-White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16147	03/28/2013	M45036FBN	Bradford-White	0
16148	03/29/2013	MI5036FBN	Bradford-White	0
16149	03/15/2013	MI5036FBN	Bradford-White	0
16150	03/29/2013	M45036FBN	Bradford-White	0
16151	03/18/2013	M45036FBN	Bradford-White	0
16152	03/16/2013	M45036FBN	Bradford White	0
16153	03/15/2013	M2XR504T6FBN	Bradford White	0
16154	01/26/2013	M45036FBN	Bradford White	0
16155	02/03/2013	PH2DV50F	Ruud	3
16156	03/13/2013	MI40T6FBN	Bradford White	0
16157	03/27/2013	MI5036FBN	BRADFORD WHITE	0
16158	03/27/2013	MI5036FBN	BRADFORD WHITE	0
16159	03/17/2013	MI403S6FBN	Bradford-White	0
16160	03/27/2013	MI5036FBN	BRADFORD WHITE	0
16161	03/13/2013	FGR50	AO SMITH	0
16162	03/26/2013	PH2DV50F	RUUD	0
16163	03/23/2013	PH2DV50F	RUUD	0
16164	03/27/2013	M45036FBN	BRADFORD WHITE	0
16165	03/08/2013	M45036FBN	BRADFORD WHITE	0
16166	03/21/2013	MI5036FBN	Bradford-White	0
16167	03/14/2013	MI5036FBN	Bradford-White	0
16168	03/15/2013	MI403S6FBN	BRADFORD WHITE	1
16169	03/15/2013	MI5036FBN	BRADFORD WHITE	0
16170	03/15/2013	M2XR504T6FBN	BRADFORD WHITE	0
16171	03/18/2013	M45036FBN	Bradford-White	2
16172	03/30/2013	PH2DV50F	Ruud	0
16173	03/23/2013	MI403S6FBN	Bradford-White	0
16174	03/11/2013	MI5036FBN	Bradford-White	0
16175	03/12/2013	MI5036FBN	Bradford-White	0
16176	03/12/2013	M45036FBN	Bradford-White	0
16177	03/27/2013	M45036FBn	Bradford-White	0
16178	03/28/2013	MI5036FBN	Bradford-White	0
16179	03/18/2013	MI5036FBN	Bradford-White	0
16180	03/21/2013	MI50L6FBN	Bradford-White	0
16181	03/25/2013	M45036FBN	Bradford-White	0
16182	03/05/2013	MI40T6FBN	Bradford - White	0
16183	03/21/2013	M45036FBN	Bradford - White	0
16184	03/28/2013	MI5036FBN	Bradford - White	0
16185	03/22/2013	MI50L6FBN	Bradford White	0
16186	03/18/2013	M45036FBN	Bradford White	0
16187	03/19/2013	FSGL40	AO SMITH	0
16188	03/18/2013	LTN050G	LOCHINVAR	1
16189	03/09/2013	FSG50	AO SMITH	0
16190	03/27/2013	M45036FBN	Bradford White	0
16191	03/21/2013	MI40T6FBN	BRADFORD WHITE	0
16192	10/10/1980	DS20	ECON	0
16193	04/08/2013	G75125	RUUD	0
16194	04/05/2013	G91200	RUUD	0
16195	04/03/2013	MI50L6FBN	Bradford-White	0
16196	04/03/2013	MI5036FBN	Bradford-White	0
16197	04/02/2013	M45036FBN	Bradford-White	1
16198	04/02/2013	22DV50F	Rheem	0
16199	03/27/2013	PH2DV50F	Ruud	0
16200	04/09/2013	MI5036FBN	Bradford-White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16201	04/02/2013	M45036FBN	Bradford-White	0
16202	04/09/2013	M45036FBN	Bradford-White	0
16203	03/21/2013	MI5036FBN	Bradford-White	1
16204	04/03/2013	MI40T6FBN	Bradford-White	0
16205	04/03/2013	M45036FBN	Bradford-White	0
16206	04/04/2013	M45036FBN	Bradford-White	1
16207	04/05/2013	G82156	Rheem	0
16208	04/01/2013	DS150S6FBN	BRADFORD-WHITE	0
16209		M45036FBN	BRADFORD-WHITE	0
16210	04/02/2013	M45036FBN	BRADFORD-WHITE	0
16211	04/02/2013	MI5036FBN	BRADFORD-WHITE	0
16212	04/02/2013	MI5036FBN	BRADFORD-WHITE	1
16213	04/03/2013	MI403S6FBN	BRADFORD-WHITE	0
16214	03/28/2013	MI5036FBN	BRADFORD-WHITE	3
16215	04/25/2013	DS150S6FBN	Bradford-White	0
16216	01/24/2013	MI50L6FBN	BRADFORD-WHITE	0
16217	01/16/2013	G91200	RUUD/RHEEM	2
16218	04/17/2013	M45036FBN	Bradford-White	0
16219	03/25/2013	MI40T6FBN	Bradford-White	4
16220	04/30/2013	M45036FBN	Bradford-White	0
16221	04/30/2013	PH2DV50F	Ruud	0
16222	03/07/2013	G75125	RHEEM	2
16223	04/19/2013	MI5036FBN	BRADFORD WHITE	1
16224	03/26/2013	M45036FBN	Bradford White	0
16225	05/15/2013	M2XR504T6FBN	Bradford White	0
16226	03/28/2013	PH2DV50F	RHEEM	0
16227	03/23/2013	MI403S6FBN	Bradford White	1
16228	03/25/2013	MI5036FBN	Bradford White	0
16229	04/04/2013	MI5036FBN	BRADFORD-WHITE	0
16230	04/04/2013	MI403S6FBN	BRADFORD-WHITE	0
16231	04/04/2013	M45036FBN	BRADFORD-WHITE	0
16232	04/04/2013	MI5036FBN	BRADFORD-WHITE	0
16233	03/29/2013	MI5036FBN	Bradford White	0
16234	04/11/2013	MI5036FBN	BRADFORD WHITE	0
16235	04/11/2013	MI5036FBN	BRADFORD WHITE	1
16236	04/10/2013	M45036FBN	BRADFORD WHITE	0
16237	04/06/2013	M45036FBN	Bradford-White	0
16238	04/10/2013	M45036FBN	BRADFORD WHITE	0
16239	04/09/2013	MI5036FBN	BRADFORD WHITE	0
16240	04/09/2013	MI5036FBN	BRADFORD WHITE	0
16241	04/09/2013	M45036FBN	BRADFORD WHITE`	0
16242	04/01/2013	M45036FBN	BRADFORD WHITE	1
16243	04/03/2013	MI40T6FBN	BRADFORD WHITE	1
16244	04/02/2013	M45036FBN	BRADFORD WHITE	0
16245	04/03/2013	M45036FBN	BRADFORD WHITE	0
16246	03/20/2013	M45036FBN	BRADFORD WHITE	2
16247	04/08/2013	P230F	Ruud	0
16248	04/04/2013	M45036FBN	Bradford-White	0
16249	03/30/2013	MI40T6FBN	BRADFORD WHITE	0
16250	03/16/2013	MI40T6FBN	Bradford-White	0
16251	04/02/2013	MI5036FBN	Bradford-White	0
16252	03/25/2013	MI40T6FBN	BRADFORD WHITE	0
16253	04/03/2013	G91200	RUUD/RHEEM	3
16254	04/17/2013	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16255	04/14/2013	MI5036FBN	BRADFORD WHITE	0
16256	04/17/2013	MI5036FBN	BRADFORD WHITE	0
16257	04/16/2013	M45036FBN	BRADFORD WHITE	0
16258	04/05/2013	M45036FBN	BRADFORD WHITE	2
16259	03/11/2013	PH2DV50F	RUUD	1
16260	04/16/2013	M45036FBN	BRADFORD WHITE	0
16261	04/12/2013	MI40T6FBN	Bradford-White	1
16262	03/15/2013	M45036FBN	Bradford-White	1
16263	04/15/2013	G82156	RUUD/RHEEM	1
16264	04/23/2013	MI40T6FBN	BRADFORD-WHITE	0
16265	04/18/2013	MI5036FBN	BRADFORD-WHITE	0
16266	04/09/2013	M2XR504T6FBN	BRADFORD WHITE	0
16267	04/17/2013	PH2DV50F	RUUD	0
16268	04/17/2013	PH2DV50F	RUUD	1
16269	04/17/2013	M45036FBN	BRADFORD-WHITE	0
16270	04/18/2013	MI5036FBN	BRADFORD-WHITE	0
16271	04/13/2013	MI403S6FBN	Bradford-White	0
16272	04/19/2013	G76200	RUUD/RHEEM	0
16273	03/10/2013	MI5036FBN	BRADFORD-WHITE	1
16274		MI5036FBN	BRADFORD-WHITE	0
16275	04/16/2013	M45036FBN	BRADFORD-WHITE	1
16276	04/22/2013	MI5036FBN	BRADFORD-WHITE	0
16277	04/16/2013	M45036FBN	BRADFORD-WHITE	0
16278	04/24/2013	PH199119	PHOENIX	0
16279	04/27/2013	PH2DV50F	RUUD	0
16280	04/26/2013	G91200	RUUD	0
16281	04/23/2013	MI5036FBN	BRADFORD-WHITE	0
16282	04/25/2013	M45036FBN	BRADFORD-WHITE	0
16283	04/26/2013	M45036FBN	Bradford-White	0
16284	04/24/2013	M45036FBN	Bradford-White	0
16285	04/19/2013	M2XR504T6FBN	Bradford-White	0
16286	04/29/2013	G91200	Ruud	0
16287	04/21/2013	G91200	RUUD/RHEEM	0
16288	04/16/2013	M45036FBN	Bradford-White	1
16289	04/16/2013	MI5036FBN	Bradford-White	0
16290	05/14/2013	MI5036FBN	BRADFORD WHITE	0
16291	05/15/2013	MI5036FBN	BRADFORD WHITE	0
16292	05/09/2013	MI50L6FBN	BRADFORD WHITE	1
16293	05/15/2013	MI5036FBN	BRADFORD WHITE	0
16294	05/11/2013	M440T6FBN	BRADFORD WHITE	0
16295	04/17/2013	M45036FBN	Bradford-White	0
16296	04/14/2013	MI5036FBN	BRADFORD-WHITE	3
16297	04/29/2013	MI403S6FBN	BRADFORD-WHITE	0
16298	04/15/2013	G76200	RUUD/RHEEM	0
16299	04/25/2013	M45036FBN	BRADFORD-WHITE	0
16300	04/16/2013	MI5036FBN	BRADFORD-WHITE	0
16301	04/23/2013	M45036FBN	BRADFORD-WHITE	0
16302	04/25/2013	M45036FBN	BRADFORD-WHITE	0
16303	04/25/2013	MI50L6FBN	BRADFORD-WHITE	0
16304	04/22/2013	M45036FBN	BRADFORD-WHITE	0
16305	04/23/2013	DS140S6FBN	BRADFORD-WHITE	0
16306	05/11/2013	PH2DV50F	RUUD	0
16307	04/15/2013	MI5036FBN	BRADFORD-WHITE	0
16308	04/15/2013	PH2DV50F	Ruud	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16309	04/13/2013	PH2DV50F	Ruud	0
16310	04/14/2013	G82156	Ruud	1
16311	04/12/2013	MI40T6FBN	Bradford-White	0
16312	05/09/2013	M45036FBN	BRADFORD WHITE	0
16313	05/17/2013	M45036FBN	BRADFORD WHITE	0
16314	05/11/2013	G91200	RUUD	0
16315	02/15/2013	PH2DV50F	Ruud	0
16316	05/11/2013	M45036FBN	BRADFORD-WHITE	0
16317	04/23/2013	MI5036FBN	Bradford-White	0
16318	03/25/2013	G76200	Rheem	0
16319	05/15/2013	MI5036FBN	Bradford-White	0
16320	05/16/2013	PH2DV50F	Ruud	0
16321	04/09/2013	G75125	RHEEM	0
16322	05/03/2013	M45036FBN	BRADFORD WHITE	0
16323	05/02/2013	MI5036FBN	BRADFORD WHITE	0
16324	04/22/2013	MI5036FBN	Bradford-White	0
16325	04/17/2013	MI5036FBN	Bradford-White	0
16326	04/18/2013	MI40T6FBN	Bradford-White	0
16327	04/20/2013	M45036FBN	Bradford-White	0
16328	04/17/2013	MI5036FBN	Bradford-White	0
16329	04/12/2013	M45036FBn	Bradford-White	0
16330	04/18/2013	MI5036FBN	Bradford-White	0
16331	05/14/2013	MI5036FBN	Bradford-White	0
16332	04/17/2013	MI5036FBN	Bradford-White	0
16333	04/15/2013	MI40T6FBN	Bradford-White	0
16334	04/10/2013	MI50L6FBN	Bradford-White	3
16335	03/29/2013	M45036FBN	BRADFORD WHITE	0
16336	05/14/2013	MI40T6FBN	Bradford-White	0
16337	04/29/2013	MI5036FBN	BRADFORD-WHITE	1
16338	04/26/2013	MI5036FBN	BRADFORD-WHITE	1
16339	04/24/2013	MI5036FBN	BRADFORD-WHITE	1
16340	04/16/2013	MI5036FBN	Bradford-White	0
16341	05/13/2013	PH2DV50F	Ruud	1
16342	05/13/2013	PH2DV50F	Ruud	0
16343	02/26/2013	M45036FBN	Bradford-White	0
16344	03/22/2013	M45036FBN	Bradford-White	1
16345	04/23/2013	M2XR504T6FBN	BRADFORD WHITE	0
16346	05/13/2013	MI5036FBN	BRADFORD-WHITE	1
16347	05/05/2013	M45036FBN	BRADFORD WHITE	0
16348	05/06/2013	MI5036FBN	BRADFORD WHITE	1
16349	04/30/2013	M45036FBN	BRADFORD WHITE	0
16350	05/06/2013	M45036FBN	BRADFORD WHITE	1
16351	05/03/2013	MI5036FBN	Bradford-White	0
16352	05/04/2013	MI5036FBN	Bradford-White	0
16353	04/09/2013	G75125	Ruud	2
16354	05/08/2013	M45036FBN	Bradford-White	0
16355	04/25/2013	DS150S6FBN	Bradford-White	0
16356	05/02/2013	M45036FBN	Bradford-White	0
16357	04/20/2013	M45036FBN	Bradford-White	0
16358	05/02/2013	M45036FBN	Bradford-White	0
16359	05/06/2013	MI5036FBN	Bradford-White	1
16360	05/03/2013	M45036FBN	Bradford-White	0
16361	05/06/2013	M45036FBN	BRADFORD WHITE	1
16362	05/06/2013	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16363	05/01/2013	MI5036FBN	BRADFORD WHITE	4
16364	04/25/2013	M45036FBN	BRADFORD WHITE	0
16365	05/21/2013	MI5036FBN	Bradford-White	2
16366	05/17/2013	MI5036FBN	Bradford-White	1
16367	05/13/2013	DS150S6FBN	Bradford-White	0
16368	05/13/2013	M45036FBN	Bradford-White	0
16369	05/17/2013	MI50L6FBN	BRADFORD WHITE	0
16370	05/02/2013	MI5036FBN	BRADFORD WHITE	0
16371	05/09/2013	MI5036FBN	BRADFORD WHITE	0
16372	05/08/2013	MI5036FBN	BRADFORD WHITE	0
16373	05/15/2013	M440T6FBN	BRADFORD WHITE	0
16374	05/20/2013	M45036FBN	BRADFORD WHITE	0
16375	05/21/2013	G91200	RUUD/RHEEM	1
16376	05/23/2013	M45036FBN	BRADFORD WHITE	1
16377	05/23/2013	M45036FBN	BRADFORD WHITE	0
16378	05/22/2013	M45036FBN	BRADFORD WHITE	0
16379	05/17/2013	MI403S6FBN	BRADFORD WHITE	0
16380	05/21/2013	M45036FBN	BRADFORD WHITE	0
16381	05/01/2013	MI50L6FBN	Bradford-White	1
16382	05/13/2013	M45036FBN	Bradford-White	0
16383	05/08/2013	M45036FBN	BRADFORD WHITE	0
16384	05/17/2013	M45036FBN	Bradford-White	0
16385	05/10/2013	MI403S6FBN	BRADFORD-WHITE	0
16386	04/01/2013	MI403S6FBN	Bradford-White	1
16387	05/03/2013	M45036FBN	BRADFORD-WHITE	1
16388	05/01/2013	M45036FBN	Bradford-White	0
16389	05/06/2013	M45036FBN	BRADFORD-WHITE	0
16390	05/06/2013	M45036FBN	BRADFORD-WHITE	0
16391	05/09/2013	MI5036FBN	BRADFORD WHITE	1
16392	05/28/2013	MI50L6FBN	BRADFORD WHITE	0
16393	05/25/2013	MI403S6FBN	BRADFORD WHITE	0
16394	05/22/2013	MI5036FBN	BRADFORD WHITE	0
16395	05/23/2013	M45036FBN	BRADFORD WHITE	0
16396	05/23/2013	M45036FBN	BRADFORD WHITE	0
16397	05/29/2013	M45036FBN	BRADFORD WHITE	0
16398	05/29/2013	M45036FBN	BRADFORD WHITE	2
16399	05/25/2013	MI40T6FBN	BRADFORD WHITE	0
16400	05/28/2013	M45036FBN	BRADFORD WHITE	0
16401	05/01/2013	M45036FBN	Bradford-White	1
16402	05/22/2013	P230S30F	RUUD	0
16403	05/21/2013	M2XR504T6FBN	BRADFORD WHITE	1
16404	05/17/2013	MI5036FBN	BRADFORD WHITE	0
16405	05/17/2013	M45036FBN	BRADFORD WHITE	0
16406	05/22/2013	PH2DV50F	RUUD	0
16407	06/28/2013	MI403S6FBN	BRADFORD WHITE	0
16408	06/28/2013	MI403S6FBN	BRADFORD WHITE	0
16409	05/01/2013	G82156	RUUD/RHEEM	1
16410	05/30/2013	M45036FBN	BRADFORD WHITE	1
16411	06/10/2013	M45036FBN	BRADFORD WHITE	1
16412	05/30/2013	M45036FBN	BRADFORD WHITE	0
16413	06/04/2013	PH2DV50F	RUUD	0
16414	06/05/2013	M440T6FBN	BRADFORD WHITE	0
16415	05/25/2013	G82156	RHEEM	1
16416	06/04/2013	PH2DV50F	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16417	05/06/2013	MI5036FBN	BRADFORD-WHITE	0
16418	05/08/2013	MI403S6FBN	BRADFORD-WHITE	0
16419	05/20/2013	MI5036FBN	BRADFORD-WHITE	0
16420	05/17/2013	M45036FBN	BRADFORD-WHITE	1
16421	05/09/2013	M45036FBN	BRADFORD-WHITE	0
16422	05/11/2013	MI403S6FBN	BRADFORD-WHITE	0
16423	05/31/2013	MI5036FBN	BRADFORD WHITE	1
16424	06/07/2013	M45036FBN	BRADFORD WHITE	0
16425	06/03/2013	M45036FBN	BRADFORD WHITE	0
16426	05/08/2013	MI5036FBN	BRADFORD WHITE	2
16427	04/22/2013	PH199-80	PHOENIX	4
16428	05/24/2013	M45036FBN	Bradford-White	0
16429	05/25/2013	MI40T6FBN	Bradford-White	1
16430	05/22/2013	MI403S6FBN	Bradford-White	0
16431	05/10/2013	MI5036FBN	Bradford-White	0
16432	05/09/2013	M45036FBN	Bradford-White	1
16433	03/21/2013	G75125	RUUD	1
16434	05/18/2013	MI5036FBN	Bradford-White	0
16435	05/07/2013	PH19980	Phoenix	4
16436	04/26/2013	MI5036FBN	BRADFORD-WHITE	0
16437	05/03/2013	MI5036FBN	Bradford-White	1
16438	05/02/2013	MI5036FBN	Bradford-White	0
16439	05/18/2013	G91200	RUUD/RHEEM	0
16440	05/03/2013	G75125	RUUD/RHEEM	0
16441	05/23/2013	G91200	Ruud/Rheem	0
16442	05/24/2013	MI5036FBN	Bradford-White	1
16443	05/04/2013	M45036FBN	Bradford-White	0
16444	05/21/2013	MI5036FBN	Bradford White	0
16445	05/24/2013	DS150S6FBN	Bradford-White	0
16446	06/05/2013	PH2DV50F	Ruud/Rheem	1
16447	06/05/2013	MI403S6FBN	Bradford-White	0
16448	05/08/2013	M45036FBN	Bradford White	0
16449	05/20/2013	PH2DV50F	RUUD	0
16450	05/24/2013	G82156	RHEEM	0
16451	05/26/2013	MI5036FBN	Bradford-White	0
16452	06/12/2013	MI403S6FBN	BRADFORD WHITE	0
16453	06/11/2013	M430T6FBN	BRADFORD WHITE	0
16454	05/28/2013	M2XR504T6FBN	Bradford-White	0
16455		MI40T6FBN	Bradford-White	0
16456	06/01/2013	M45036FBN	Bradford-White	0
16457	06/06/2013	M45036FBN	Bradford-White	0
16458	06/05/2013	M45036FBN	BRADFORD WHITE	0
16459	06/26/2013	MI40T6FBN	BRADFORD WHITE	2
16460	06/18/2013	MI50L6FBN	BRADFORD WHITE	0
16461	06/20/2013	M440T6FBN	BRADFORD WHITE	0
16462	06/28/2013	PH2DV50F	RUUD	0
16463	06/21/2013	M45036FBN	BRADFORD WHITE	0
16464	06/21/2013	M45036FBN	BRADFORD WHITE	0
16465	06/13/2013	MI5036FBN	BRADFORD WHITE	0
16466	06/10/2013	MI5036FBN	BRADFORD WHITE	0
16467	06/21/2013	M45036FBN	BRADFORD WHITE	0
16468	05/16/2013	MI403S6FBN	BRADFORD WHITE	1
16469	05/24/2013	M45036FBN	Bradford-White	0
16470	05/25/2013	M45036FBN	Bradford-White	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16471	05/28/2013	PH2DV50F	RUUD	0
16472	06/05/2013	MI5036FBN	Bradford-White	0
16473	05/31/2013	P230F	RUUD	0
16474	06/11/2013	M440T6FBN	Bradford-White	0
16475	05/13/2013	MI5036FBN	BRADFORD WHITE	0
16476	05/20/2013	M45036FBN	BRADFORD WHITE	0
16477	06/11/2013	PH2DV50F	RUUD	0
16478	06/02/2013	MI403S6FBN	BRADFORD WHITE	0
16479	06/22/2013	M45036FBN	BRADFORD WHITE	0
16480	06/18/2013	MI5036FBN	BRADFORD WHITE	0
16481	06/12/2013	MI403S6FBN	BRADFORD WHITE	0
16482	06/26/2013	M45036FBN	BRADFORD WHITE	0
16483	06/08/2013	M45036FBN	Bradford White	0
16484	06/20/2013	M45036FBN	BRADFORD WHITE	0
16485	07/11/2013	MI40T6FBN	Bradford-White	0
16486	06/01/2013	MI5036FBN	Bradford-White	0
16487	06/18/2013	PH2DV50F	Ruud	0
16488	06/28/2013	PH2DV50F	Ruud	0
16489	06/11/2013	MI40T6FBN	Bradford-White	0
16490	06/05/2013	MI403S6FBN	Bradford-White	0
16491	06/26/2013	MI75S6FBN	Bradford-White	1
16492	06/17/2013	M45036Fbn	Bradford-White	0
16493	06/20/2013	G91200	RUUD/RHEEM	2
16494	06/03/2013	MI5036FBN	Bradford-White	0
16495	06/21/2013	M45036FBN	Bradford-White	0
16496	06/28/2013	MI5036FBN	BRADFORD WHITE	1
16497	06/28/2013	MI5036FBN	BRADFORD WHITE	0
16498	06/24/2013	P230F	RUUD	0
16499	06/26/2013	G91200	RHEEM	1
16500	07/03/2013	M45036FBN	BRADFORD WHITE	0
16501	07/02/2013	M45036FBN	Bradford-White	0
16502	07/03/2013	MI5036FBN	BRADFORD WHITE	1
16503	06/25/2013	MI5036FBN	BRADFORD-WHITE	0
16504	07/05/2013	PH2DV50F	RUUD	0
16505	06/21/2013	M45036FBN	BRADFORD WHITE	0
16506	07/02/2013	M45036FBN	Bradford-White	0
16507	06/30/2013	PH2DV50F	RUUD	2
16508	07/02/2013	M440T6FBN	BRADFORD WHITE	0
16509	06/28/2013	MI5036FBN	BRADFORD WHITE	0
16510	07/03/2013	M45036FBN	BRADFORD WHITE	0
16511	07/09/2013	M45036FBN	BRADFORD WHITE	1
16512	07/12/2013	MI5036FBN	BRADFORD WHITE	0
16513	07/15/2013	MI5036FBN	BRADFORD WHITE	0
16514	07/18/2013	M45036FBN	BRADFORD WHITE	0
16515	07/11/2013	MI40T6FBN	BRADFORD WHITE	0
16516	07/09/2013	M45036FBN	BRADFORD WHITE	0
16517	07/09/2013	M45036FBN	BRADFORD WHITE	0
16518	05/25/2013	MI403S6FBN	BRADFORD-WHITE	0
16519	06/03/2013	MI40T6FBN	Bradford-White	0
16520	06/26/2013	M45036FBN	Bradford-White	0
16521	06/19/2013	MI5036FBN	BRADFORD-WHITE	0
16522	05/31/2013	M45036FBN	BRADFORD-WHITE	0
16523	06/05/2013	MI5036FBN	BRADFORD-WHITE	0
16524	05/20/2013	MI5036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16525	06/11/2013	MI5036FBN	Bradford-White	0
16526	06/28/2013	MI40T6FBN	Bradford-White	0
16527	06/05/2013	MI40T6FBN	Bradford-White	0
16528	06/12/2013	PRV50NODS	STATE	0
16529	06/18/2013	M45036FBN	Bradford-White	0
16530	06/22/2013	MI5036FBN	Bradford-White	0
16531	06/25/2013	PH2DV50F	Ruud/Rheem	2
16532	06/11/2013	M45036FBN	BRADFORD-WHITE	0
16533	06/17/2013	MI5036FBN	Bradford-White	0
16534	06/25/2013	M45036FBN	Bradford-White	1
16535	06/12/2013	MI40T6FBN	BRADFORD-WHITE	0
16536	05/26/2013	M45036FBN	BRADFORD WHITE	0
16537	06/03/2013	P230F	RUUD	1
16538	06/05/2013	MI40T6FBN	BRADFORD WHITE	0
16539	06/24/2013	M45036FBN	BRADFORD WHITE	0
16540	05/25/2013	MI403S6FBN	BRADFORD WHITE	0
16541	05/30/2013	P230F	RUUD	0
16542	06/10/2013	M2XR504T6FBN	BRADFORD WHITE	0
16543	06/22/2013	PH2DV50F	RUUD	0
16544	06/21/2013	M45036FBN	BRADFORD-WHITE	0
16545	06/07/2013	MI5036FBN	BRADFORD-WHITE	0
16546	06/05/2013	MI5036FBN	Bradford-White	0
16547	06/27/2013	M440T6FBN	BRADFORD-WHITE	0
16548	06/27/2013	MI5036FBN	BRADFORD-WHITE	0
16549	06/25/2013	MI403S6FBN	BRADFORD-WHITE	0
16550	06/20/2013	MI5036FBN	BRADFORD-WHITE	0
16551	06/22/2013	PH2DV50F	RUUD	2
16552	06/06/2013	MI5036FBN	BRADFORD-WHITE	0
16553	06/06/2013	MI5036FBN	BRADFORD-WHITE	0
16554	06/05/2013	M440T6FBN	BRADFORD-WHITE	0
16555	06/03/2013	M45036FBN	BRADFORD-WHITE	0
16556	06/01/2013	M440T6FBN	BRADFORD-WHITE	0
16557	06/08/2013	MI5036FBN	BRADFORD-WHITE	0
16558	06/18/2013	M45036FBN	BRADFORD-WHITE	1
16559	06/19/2013	M45036FBN	BRADFORD-WHITE	1
16560	06/24/2013	PH2DV50F	RUUD	0
16561	06/28/2013	DS150S6FBN	BRADFORD-WHITE	0
16562	06/27/2013	M45036FBN	BRADFORD-WHITE	0
16563	06/25/2013	PH2DV50F	RUUD	0
16564	06/28/2013	M45036FBN	BRADFORD-WHITE	0
16565	06/11/2013	MI40T6FBN	BRADFORD-WHITE	0
16566	06/26/2013	M45036FBN	BRADFORD-WHITE	0
16567	06/27/2013	M45036FBN	BRADFORD-WHITE	0
16568	07/12/2013	PH2DV50F	Ruud	1
16569	06/13/2013	MI40T6FBN	BRADFORD-WHITE	0
16570	07/16/2013	G82156	RUUD/RHEEM	2
16571	07/01/2013	MI40T6FBN	Bradford-White	1
16572	06/17/2013	M45036FBN	BRADFORD-WHITE	0
16573	06/18/2013	PH2DV50F	RUUD	0
16574	06/24/2013	M45036FBN	BRADFORD-WHITE	0
16575	06/27/2013	M45036FBN	Bradford-White	0
16576	07/03/2013	PH2DV50F	Ruud/Rheem	0
16577	07/05/2013	MI5036FBN	Bradford-White	0
16578	07/02/2013	DS150S6FBN	Bradford-White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16579	07/10/2013	PH2DV50F	Ruud/Rheem	0
16580	07/11/2013	M45036FBN	Bradford-White	0
16581	07/20/2013	M45036FBN	Bradford-White	0
16582	07/16/2013	DS150S6FBN	Bradford-White	0
16583	07/15/2013	MI5036FBN	Bradford-White	0
16584	07/17/2013	MI5036FBN	Bradford-White	0
16585	07/19/2013	G75125	RUUD/RHEEM	0
16586	07/16/2013	MI5036FBN	BRADFORD-WHITE	0
16587	07/11/2013	M45036FBN	BRADFORD WHITE	0
16588	07/06/2013	MI40T6FBN	BRADFORD-WHITE	1
16589	07/19/2013	MI40T6FBN	BRADFORD WHITE	2
16590	07/11/2013	PH2DV50F	RUUD	1
16591	07/08/2013	M45036FBN	BRADFORD WHITE	0
16592	06/20/2013	G91200	RHEEM	3
16593	07/23/2013	PH2DV50F	RUUD	1
16594	07/19/2013	PH2DV50F	RUUD	0
16595	07/17/2013	M45036FBN	BRADFORD WHITE	0
16596	07/24/2013	MI403S6FBN	BRADFORD WHITE	0
16597	07/19/2013	G82156	RHEEM / RUUD	0
16598	06/28/2013	M45036FBN	BRADFORD WHITE	0
16599	07/15/2013	G91200	RUUD/RHEEM	0
16600	07/08/2013	M45036FBN	BRADFORD-WHITE	0
16601	07/15/2013	DS150S6FBN	BRADFORD-WHITE	0
16602	07/08/2013	FSG50	AO SMITH	2
16603	07/06/2013	M440T6FBN	BRADFORD-WHITE	0
16604	07/02/2013	MI40T6FBN	BRADFORD-WHITE	0
16605	06/22/2013	M45036FBN	BRADFORD-WHITE	0
16606	07/03/2013	MI403S6FBN	BRADFORD-WHITE	2
16607	06/28/2013	MI5036FBN	BRADFORD-WHITE	0
16608	07/02/2013	MI403S6FBN	BRADFORD-WHITE	0
16609	07/01/2013	MI5036FBN	BRADFORD-WHITE	0
16610	07/16/2013	MI5036FBN	Bradford-White	0
16611	07/10/2013	PH2DV50F	Ruud	0
16612	07/09/2013	MI5036FBN	Bradford-White	0
16613	07/24/2013	MI403S6FBN	BRADFORD WHITE	0
16614	07/19/2013	M45036FBN	BRADFORD WHITE	0
16615	07/07/2013	M45036FBN	BRADFORD WHITE	0
16616	07/09/2013	M45036FBN	BRADFORD WHITE	0
16617	07/01/2013	M440T6FBN	BRADFORD-WHITE	0
16618	07/20/2013	MI5036FBN	BRADFORD-WHITE	0
16619	07/10/2013	MI40T6FBN	BRADFORD WHITE	0
16620	07/06/2013	MI5036FBN	BRADFORD WHITE	0
16621	07/24/2013	M45036FBN	BRADFORD-WHITE	0
16622	07/17/2013	MI5036FBN	BRADFORD-WHITE	0
16623	07/12/2013	DS140S6FBN	BRADFORD-WHITE	0
16624	07/11/2013	MI5036FBN	BRADFORD-WHITE	0
16625	06/29/2013	MI50L6FBN	BRADFORD-WHITE	0
16626	07/15/2013	DS150S6FBN	BRADFORD-WHITE	0
16627	07/17/2013	M45036FBN	BRADFORD-WHITE	1
16628	07/11/2013	MI5036FBN	BRADFORD-WHITE	3
16629	07/28/2013	M45036FBN	BRADFORD-WHITE	0
16630	07/26/2013	M45036FBN	BRADFORD-WHITE	0
16631	07/17/2013	P230F	RUUD	0
16632	06/06/2013	MI50L6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16633	07/24/2013	P230S30F	RUUD	0
16634	07/24/2013	PH2DV50F	RUUD	0
16635	07/26/2013	MI40T6FBN	BRADFORD WHITE	0
16636	07/05/2013	MI5036FBN	Bradford-White	0
16637	07/16/2013	M440T6FBN	Bradford-White	2
16638	07/05/2013	MI5036FBN	Bradford-White	0
16639	07/15/2013	M440t6FBN	Bradford-White	0
16640	07/13/2013	MI5036FBN	BRADFORD-WHITE	2
16641	07/26/2013	MI403S6FBN	Bradford-White	1
16642	06/06/2013	MI50L6FBN	Bradford-White	0
16643	07/02/2013	M2XR504T6FBN	Bradford-White	1
16644	07/26/2013	PH2DV50F	RUUD	1
16645	07/26/2013	MI5036FBN	BRADFORD WHITE	0
16646	07/09/2013	M45036FBN	RHEEM	0
16647	07/31/2013	M45036FBN	Bradford-White	0
16648	07/30/2013	MI5036FBN	Bradford-White	0
16649	08/05/2013	MI403S6FBN	Bradford-White	0
16650	08/09/2013	M45036FBN	Bradford-White	1
16651	08/02/2013	MI5036FBN	Bradford-White	0
16652	08/05/2013	M440T6FBN	Bradford-White	0
16653	07/25/2013	M45036FBN	BRADFORD-WHITE	0
16654	07/25/2013	M45036FBN	BRADFORD-WHITE	0
16655	07/23/2013	M45036FBN	BRADFORD-WHITE	0
16656	07/27/2013	MI5036FBN	BRADFORD-WHITE	0
16657	07/24/2013	MI5036FBN	BRADFORD-WHITE	1
16658	07/18/2013	MI403S6FBN	BRADFORD-WHITE	0
16659	07/28/2013	MI40T6FBN	BRADFORD-WHITE	1
16660	07/22/2013	G91200	RUUD	0
16661	07/31/2013	M2XR504T6FBN	BRADFORD-WHITE	1
16662	07/31/2013	M45036FBN	BRADFORD-WHITE	0
16663	07/30/2013	M45036FBN	BRADFORD-WHITE	0
16664	07/27/2013	M45036FBN	BRADFORD-WHITE	1
16665	07/26/2013	M45036FBN	BRADFORD-WHITE	0
16666	07/12/2013	M45036FBN	BRADFORD-WHITE	0
16667	07/25/2013	MI75S6FBN	BRADFORD-WHITE	1
16668	06/14/2013	G76200	RUUD	0
16669	07/30/2013	MI403S6FBN	BRADFORD-WHITE	1
16670	07/24/2013	MI403S6FBN	BRADFORD-WHITE	0
16671	07/27/2013	MI5036FBN	BRADFORD-WHITE	2
16672	07/24/2013	M45036FBN	BRADFORD-WHITE	0
16673	07/26/2013	MI5036FBN	BRADFORD-WHITE	0
16674	07/30/2013	PR650	STATE	0
16675	09/03/2013	MI5036FBN	Bradford-White	0
16676	08/07/2013	PH2DV50F	RUUD	0
16677	07/30/2013	M45036FBN	Bradford-White	0
16678	08/10/2013	M45036FBN	BRADFORD WHITE	0
16679	08/04/2013	M45036FBN	Bradford-White	0
16680	08/07/2013	M45036FBN	Bradford-White	0
16681	07/25/2013	MI40T6FBN	BRADFORD WHITE	0
16682	07/31/2013	MI5036FBN	BRADFORD WHITE	1
16683	07/20/2013	M45036FBN	BRADFORD WHITE	0
16684	07/21/2013	PH2DV50F	RUUD	0
16685	08/01/2013	M45036FBN	BRADFORD WHITE	0
16686	08/06/2013	M45036FBn	Bradford-White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16687	08/06/2013	M45036FBN	Bradford-White	0
16688	08/04/2013	M45036FBN	BRADFORD WHITE	0
16689	08/06/2013	MI5036FBN	Bradford-White	0
16690	07/19/2013	M45036FBN	BRADFORD-WHITE	0
16691	08/09/2013	MI403S6FBN	BRADFORD WHITE	0
16692	08/15/2013	MI5036FBN	BRADFORD-WHITE	0
16693	08/15/2013	MI403S6FBN	BRADFORD-WHITE	0
16694	08/24/2013	M440T6FBN	Bradford-White	0
16695	08/15/2013	M440T6FBN	BRADFORD-WHITE	0
16696	08/16/2013	M45036FBN	BRADFORD-WHITE	0
16697	08/14/2013	M45036FBN	BRADFORD-WHITE	0
16698	08/15/2013	M45036FBN	BRADFORD-WHITE	0
16699	08/16/2013	PH2DV50F	RUUD	0
16700	08/25/2013	MI5036FBN	Bradford-White	0
16701	08/30/2013	M45036FBN	Bradford-White	0
16702	07/31/2013	M45036FBN	BRADFORD WHITE	0
16703	08/12/2013	PH2DV50F	Ruud	0
16704	08/05/2013	PH19980	PHOENIX	0
16705	08/12/2013	M45036FBN	Bradford-White	1
16706	08/25/2013	MI5036FBN	BRADFORD-WHITE	0
16707	08/28/2013	MI5036FBN	BRADFORD-WHITE	0
16708	07/08/2013	G82156	RHEEM	2
16709	08/13/2013	G75125	RHEEM	1
16710	08/24/2013	M45036FBN	BRADFORD-WHITE	1
16711	08/28/2013	MI5036FBN	Bradford-White	0
16712	08/27/2013	MI5036FBN	Bradford-White	0
16713	08/27/2013	M45036FBN	Bradford-White	0
16714	08/27/2013	PH2DV50F	Bradford-White	0
16715	08/23/2013	M45036FBN	Bradford-White	0
16716	08/23/2013	M45036FBN	Bradford-White	0
16717	08/26/2013	MI403S6FBN	Bradford-White	0
16718	08/27/2013	MI5036FBN	Bradford-White	1
16719	04/23/2013	M45036FBN	Bradford-White	0
16720	04/26/2013	MI403S6FBN	Bradford-White	0
16721	04/24/2013	MI403S6FBN	Bradford-White	0
16722	08/26/2013	DS140S6FBN	Bradford-White	0
16723	04/22/2013	PH13080	Phoenix	0
16724	08/30/2013	MI403S6FBN	Bradford-White	0
16725	08/29/2013	PH2DV50F	Ruud	0
16726	08/23/2013	MI5036FBN	Bradford-White	0
16727	08/04/2013	MI40T6FBN	Bradford-White	0
16728	08/01/2013	MI403S6FBN	BRADFORD WHITE	0
16729	08/07/2013	M45036FBN	BRADFORD WHITE	0
16730	08/03/2013	M45036FBN	BRADFORD WHITE	0
16731	07/30/2013	M45036FBN	BRADFORD WHITE	0
16732	08/08/2013	MI5036FBN	BRADFORD WHITE	0
16733	08/08/2013	M45036FBN	BRADFORD WHITE	0
16734	07/17/2013	M45036FBN	BRADFORD WHITE	0
16735	08/23/2013	M45036FBN	Bradford-White	0
16736	08/03/2013	PH2DV50F	RUUD	0
16737	08/16/2013	MI5036FBN	Bradford-White	0
16738	08/12/2013	M45036FBN	BRADFORD-WHITE	0
16739	08/06/2013	MI5036FBN	BRADFORD-WHITE	0
16740	08/30/2013	M45036FBN	Bradford-White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16741	08/29/2013	MI5036FBN	Bradford-White	0
16742	08/13/2013	M45036FBN	Bradford-White	0
16743	07/30/2013	PH2DV50F	Ruud	0
16744	08/01/2013	M15036FBN	Bradford-White	1
16745	08/23/2013	M45036FBN	Bradford-White	0
16746	08/16/2013	MI5036FBN	Bradford-White	1
16747	08/07/2013	DS150S6FBN	Bradford-White	0
16748	07/10/2013	PH2DV50F	RUUD	0
16749	04/20/2013	MI5036FBN	BRADFORD-WHITE	0
16750	04/28/2013	PH2DV50F	RUUD	0
16751	04/29/2013	MI5036FBN	BRADFORD WHITE	0
16752	08/29/2013	M45036FBN	Bradford-White	0
16753	08/29/2013	MI5036FBN	Bradford-White	0
16754	08/10/2013	M45036FBN	Bradford-White	0
16755	07/29/2013	P230F	Ruud	0
16756	08/27/2013	M440T6FBN	BRADFORD-WHITE	0
16757	08/21/2013	M45036FBN	BRADFORD-WHITE	0
16758	08/21/2013	MI403S6FBN	BRADFORD-WHITE	1
16759	08/21/2013	M45036FBN	BRADFORD-WHITE	0
16760	08/16/2013	MI5036FBN	BRADFORD-WHITE	3
16761	08/05/2013	M45036FBN	BRADFORD-WHITE	0
16762	08/22/2013	PH2DV50F	RUUD	0
16763	08/22/2013	MI50L6FBN	BRADFORD-WHITE	0
16764	08/16/2013	MI5036FBN	BRADFORD-WHITE	0
16765	08/19/2013	MI40T6FBN	BRADFORD-WHITE	0
16766	08/30/2013	MI403S6FBN	BRADFORD-WHITE	0
16767	08/26/2013	MI5036FBN	BRADFORD-WHITE	0
16768	08/24/2013	M45036FBN	BRADFORD-WHITE	0
16769	08/28/2013	M45036FBN	BRADFORD-WHITE	2
16770	08/20/2013	M45036FBN	BRADFORD-WHITE	0
16771	08/20/2013	M45036FBN	BRADFORD-WHITE	0
16772	08/20/2013	M45036FBN	BRADFORD-WHITE	0
16773	08/20/2013	MI5036FBN	BRADFORD-WHITE	0
16774	08/21/2013	M45036FBN	BRADFORD-WHITE	1
16775	08/21/2013	M45036FBN	BRADFORD-WHITE	0
16776	08/19/2013	M45036FBN	BRADFORD-WHITE	2
16777	08/14/2013	MI403S6FBN	BRADFORD-WHITE	0
16778	08/10/2013	MI40T6FBN	BRADFORD WHITE	0
16779	08/09/2013	M440T6FBN	BRADFORD WHITE	0
16780	08/09/2013	PH2DV50F	RUUD	0
16781	08/10/2013	M45036FBN	BRADFORD WHITE	0
16782	08/15/2013	M45036FBN	BRADFORD WHITE	1
16783	08/13/2013	MI403S6FBN	BRADFORD WHITE	0
16784	07/31/2013	M45036FBN	BRADFORD WHITE	0
16785	07/29/2013	M45036FBN	BRADFORD WHITE	1
16786	07/28/2013	MI5036FBN	BRADFORD WHITE	0
16787	07/31/2013	MI50L6FBN	BRADFORD WHITE	0
16788	08/01/2013	MI40T6FBN	BRADFORD WHITE	0
16789	08/01/2013	M45036FBN	BRADFORD WHITE	0
16790	08/04/2013	MI5036FBN	BRADFORD WHITE	0
16791	08/15/2013	MI5036FBN	Bradford-White	0
16792	09/09/2013	M45036FBN	Bradford White	0
16793	09/20/2013	MI5036FBN	BRADFORD-WHITE	0
16794	09/20/2013	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16795	09/19/2013	MI403S6FBN	BRADFORD-WHITE	0
16796	09/25/2013	MI5036FBN	BRADFORD-WHITE	0
16797	09/19/2013	M45036FBN	BRADFORD-WHITE	0
16798	09/27/2013	M45036FBN	BRADFORD-WHITE	0
16799	09/28/2013	M45036FBN	BRADFORD-WHITE	0
16800	09/25/2013	PH2DV50F	RUUD	0
16801	09/25/2013	M45036FBN	BRADFORD-WHITE	0
16802	09/24/2013	M45036FBN	BRADFORD-WHITE	3
16803	09/23/2013	M45036FBN	BRADFORD-WHITE	0
16804	09/23/2013	M45036FBN	BRADFORD-WHITE	0
16805	09/18/2013	MI40T6FBN	BRADFORD-WHITE	0
16806	08/12/2013	M2XR504T6FBN	Bradford-White	0
16807	08/07/2013	M440T6FBN	Bradford-White	0
16808	08/06/2013	MI5036FBN	Bradford-White	1
16809	09/14/2013	M45036FBN	Bradford-White	0
16810	08/25/2013	MI40T6FBN	BRADFORD WHITE	0
16811	09/11/2013	M45036FBN	BRADFORD WHITE	0
16812	09/04/2013	M45036FBN	BRADFORD WHITE	0
16813	09/06/2013	M440T6FBN	BRADFORD WHITE`	0
16814	08/21/2013	MI5036FBN	BRADFORD WHITE	0
16815	09/04/2013	PH2DV50F	RUUD	0
16816	09/13/2013	M45036FBN	BRADFORD WHITE	0
16817	09/13/2013	M45036FBN	BRADFORD WHITE	0
16818	09/06/2013	M45036FBN	BRADFORD WHITE	0
16819	09/24/2013	MI40T6FBN	BRADFORD WHITEQ	0
16820	09/24/2013	M45036FBN	BRADFORD WHITE	0
16821	09/21/2013	M2XR504T6FBN	BRADFORD WHITE	0
16822	09/09/2013	M45036FBN	BRADFORD WHITE	0
16823	09/24/2013	M45036FBN	BRADFORD WHITE	0
16824	09/23/2013	PH2DV50F	RUUD	1
16825	09/23/2013	M45036FBN	BRADFORD WHITE	0
16826	09/24/2013	MI403S6FBN	BRADFORD WHITE	0
16827	09/11/2013	G91200	RHEEM	0
16828	09/17/2013	G91200	RHEEM	0
16829	09/03/2013	G75125	RHEEM	0
16830	09/05/2013	MI75S6FBN	BRADFORD WHITE	4
16831	09/11/2013	MI5036FBN	BRADFORD WHITE	0
16832	09/10/2013	MI50L6FBN	BRADFORD WHITE	0
16833	09/09/2013	PH2DV50F	RUUD	0
16834	08/03/2013	MI40T6FBN	BRADFORD WHITE	0
16835	09/04/2013	M45036FBN	BRADFORD WHITE	1
16836	09/04/2013	MI5036FBN	BRADFORD WHITE	0
16837	09/06/2013	PH2DV50F	RUUD	0
16838	09/07/2013	MI403S6FBN	BRADFORD WHITE	0
16839	08/11/2013	M45036FBN	BRADFORD WHITE	1
16840	08/27/2013	M45036FBN	BRADFORD WHITE	0
16841	08/26/2013	MI403S6FBN	BRADFORD-WHITE	0
16842	09/14/2013	M45036FBN	BRADFORD-WHITE	0
16843	09/06/2013	MI403S6FBN	BRADFORD-WHITE	0
16844	09/12/2013	M45036FBN	BRADFORD-WHITE	0
16845	09/01/2013	M45036FBN	BRADFORD-WHITE	0
16846	09/12/2013	M440T6FBN	BRADFORD-WHITE	2
16847	09/14/2013	M45036FBN	BRADFORD-WHITE	0
16848	08/21/2013	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16849	09/18/2013	PH2DV50F	RUUD	0
16850	09/18/2013	MI5036FBN	BRADFORD-WHITE	0
16851	09/20/2013	MI403S6FBN	BRADFORD-WHITE	0
16852	09/20/2013	MI403S6FBN	BRADFORD-WHITE	0
16853	09/07/2013	MI5036FBN	BRADFORD WHITE	1
16854	09/10/2013	M440T6FBN	Bradford White	1
16855	09/02/2013	M45036FBN	Bradford White	0
16856	08/23/2013	M45036FBN	Bradford White	0
16857	09/13/2013	M45036FBN	Bradford White	0
16858	09/12/2013	M45036FBN	Bradford White	0
16859	08/24/2013	MI5036FBN	Bradford White	0
16860	09/14/2013	MI40T6FBN	Bradford White	0
16861	09/14/2013	M45036FBN	Bradford White	0
16862	09/04/2013	MI50L6FBN	Bradford White	0
16863	09/26/2013	M45036FBN	Bradford White	0
16864	09/26/2013	M45036FBN	Bradford White	0
16865	09/20/2013	G75125	RUUD/RHEEM	1
16866	09/15/2013	G82156	RUUD/RHEEM	2
16867	09/21/2013	MI75S6FBN	BRADFORD WHITE	2
16868	08/03/2013	PH2DV50F	Ruud	0
16869	09/21/2013	M45036FBN	Bradford White	1
16870	09/14/2013	PH2DV50F	Ruud	0
16871	09/13/2013	M45036FBN	Bradford White	0
16872	09/13/2013	MI5036FBN	BRADFORD-WHITE	0
16873	08/27/2013	DS150S6FBN	BRADFORD-WHITE	0
16874	09/11/2013	M45036FBN	BRADFORD-WHITE	0
16875	09/06/2013	PH2DV50F	RUUD	0
16876	09/12/2013	MI40T6FBN	BRADFORD-WHITE	0
16877	09/28/2013	M2XR504T6FBN	BRADFORD-WHITE	0
16878	08/12/2013	MI40T6FBN	BRADFORD-WHITE	1
16879	10/01/2013	MI75S6FBN	BRADFORD-WHITE	4
16880	10/04/2013	G91200	RHEEM/RUUD	0
16881	09/12/2013	MI5036FBN	BRADFORD-WHITE	0
16882	09/16/2013	M45036FBN	BRADFORD-WHITE	0
16883	09/11/2013	MI403S6FBN	BRADFORD-WHITE	0
16884	09/05/2013	MI5036FBN	BRADFORD-WHITE	0
16885	09/23/2013	M45036FBN	BRADFORD-WHITE	0
16886	09/17/2013	M45036FBN	BRADFORD-WHITE	0
16887	10/09/2013	M45036FBN	Bradford White	0
16888	10/15/2013	MI5036FBN	Bradford White	0
16889		MI5036FBN	Bradford White	0
16890	10/24/2013	G75125	Ruud	0
16891	10/07/2013	G75125	Ruud	1
16892	10/27/2013	MI5036FBN	Bradford White	0
16893	10/14/2013	MI5036FBN	Bradford White	1
16894	10/28/2013	MI40T6FBN	Bradford White	0
16895	10/28/2013	MI40T6FBN	Bradford White	0
16896	10/28/2013	MI40T6FBN	Bradford White	0
16897	09/26/2013	PH2DV50F	Ruud	0
16898	10/02/2013	M45036FBN	Bradford White	0
16899	10/17/2013	M440T6FBN	Bradford White	0
16900	10/29/2013	MI40T6FBN	Bradford White	0
16901	10/04/2013	M45036FBN	Bradford White	0
16902	10/12/2013	MI40T6FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16903	10/16/2013	MI403S6FBN	Bradford White	0
16904	10/31/2013	G75125	RUUD/RHEEM	2
16905	10/04/2013	MI40T6FBN	Bradford White	2
16906	09/16/2013	MI5036FBN	BRADFORD-WHITE	0
16907	08/25/2013	M45036FBN	BRADFORD-WHITE	0
16908	08/25/2013	MI5036FBN	BRADFORD-WHITE	0
16909	09/16/2013	PH2DV50F	RUUD	0
16910	10/03/2013	PH2DV50F	RUUD	0
16911	10/03/2013	M45036FBN	BRADFORD WHITE	0
16912	10/04/2013	M45036FBN	BRADFORD WHITE	0
16913	10/07/2013	MI40T6FBN	BRADFORD WHITE	0
16914	10/10/2013	MI403S6FBN	BRADFORD WHITE	0
16915	10/10/2013	M2XR504T6FBN	BRADFORD WHITE	0
16916	10/10/2013	M45036FBN	BRADFORD WHITE	0
16917	10/12/2013	PH2DV50F	RUUD	0
16918	10/07/2013	M45036FBN	BRADFORD WHITE	0
16919	09/27/2013	M440T6FBN	BRADFORD WHITE	0
16920	10/01/2013	MI5036FBN	BRADFORD WHITE	0
16921	09/30/2013	M440T6FBN	BRADFORD WHITE	0
16922	10/01/2013	M45036FBN	BRADFORD WHITE	0
16923	09/14/2013	M45036FBN	BRADFORD WHITE	0
16924	10/01/2013	M45036FBN	BRADFORD WHITE	0
16925	10/03/2013	MI5036FBN	Bradford White	0
16926	10/06/2013	M45036FBN	BRADFORD WHITE	0
16927	10/04/2013	M45036FBN	BRADFORD WHITE	0
16928	10/04/2013	P230F	RUUD	1
16929	09/11/2013	M45036FBN	BRADFORD WHITE	0
16930	10/02/2013	G75125	RUUD	0
16931	07/09/2013	M45036FBN	BRADFORD WHITE	0
16932	10/01/2013	M45036FBN	BRADFORD WHITE	0
16933	10/03/2013	M45036FBN	BRADFORD WHITE	0
16934	10/02/2013	DS140S6FBN	BRADFORD WHITE	0
16935	10/04/2013	M45036FBN	BRADFORD WHITE	0
16936	10/09/2013	M45036FBN	Bradford White	2
16937	09/04/2013	MI403S6FBN	BRADFORD-WHITE	0
16938	09/26/2013	MI5036FBN	BRADFORD-WHITE	0
16939	09/26/2013	M45036FBN	BRADFORD-WHITE	0
16940	08/26/2013	MI5036FBN	BRADFORD-WHITE	0
16941	09/06/2013	MI5036FBN	BRADFORD-WHITE	0
16942	08/28/2013	M440T6FBN	BRADFORD-WHITE	0
16943	09/29/2013	MI5036FBN	BRADFORD-WHITE	0
16944	09/14/2013	MI40T6FBN	BRADFORD-WHITE	0
16945	09/30/2013	M45036FBN	BRADFORD-WHITE	0
16946	10/18/2013	M45036FBN	BRADFORD WHITE	1
16947	10/16/2013	MI40T6FBN	BRADFORD WHITE	0
16948	10/08/2013	M45036FBN	BRADFORD WHITE	0
16949	09/16/2013	MI40T6FBN	BRADFORD WHITE	0
16950	10/19/2013	M45036FBN	BRADFORD WHITE	0
16951	10/18/2013	M45036FBN	BRADFORD WHITE	0
16952	10/17/2013	M45036FBN	BRADFORD WHITE	0
16953	10/19/2013	MI5036FBN	BRADFORD WHITE	0
16954	10/27/2013	MI403S6FBN	BRADFORD WHITE	0
16955	10/20/2013	PH2DV50F	RUUD	1
16956	10/23/2013	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
16957	10/19/2013	MI5036FBN	BRADFORD WHITE	0
16958	10/15/2013	M45036FBN	BRADFORD WHITE	0
16959	10/18/2013	M2XR504T6FBN	BRADFORD WHITE	0
16960	10/29/2013	M2XR504T6FBN	BRADFORD WHITE	0
16961	11/03/2013	MI5036FBN	Bradford White	0
16962	11/07/2013	MI5036FBN	Bradford White	0
16963	11/18/2013	FSG50	AO SMITH	0
16964		M45036FBN	Bradford White	0
16965	11/11/2013	PRV50NODS	STATE	0
16966	11/15/2013	MI5036FBN	Bradford White	1
16967	11/08/2013	MI50L6FBN	Bradford White	0
16968	10/21/2013	M45036FBN	Bradford White	0
16969	11/01/2013	MI50L6FBN	Bradford White	0
16970	11/02/2013	MI5036FBN	BRADFORD-WHITE	0
16971	11/15/2013	M45036FBN	Bradford White	0
16972	11/03/2013	M45036FBN	Bradford White	0
16973	11/18/2013	PH2DV50F	RUUD	0
16974	09/17/2013	MI5036FBN	Bradford White	0
16975	10/16/2013	MI5036FBN	Bradford White	0
16976	10/08/2013	M45036FBN	Bradford White	0
16977	10/10/2013	M45036FBN	Bradford White	0
16978	10/08/2013	M45036FBN	Bradford White	2
16979	10/03/2013	M45036FBN	Bradford White	0
16980	09/09/2013	M45036FBN	Bradford White	0
16981	10/15/2013	G91200	RUUD/RHEEM	0
16982	10/15/2013	G91200	RUUD/RHEEM	0
16983	10/20/2013	G82156	RUUD/RHEEM	1
16984	09/01/2013	MI40T6FBN	BRADFORD WHITE	0
16985	10/28/2013	M45036FBN	BRADFORD WHITE	0
16986	10/08/2013	M45036FBN	BRADFORD WHITE	0
16987	10/23/2013	M440T6FBN	BRADFORD WHITE	0
16988	10/20/2013	PH2DV50F	RUUD	0
16989	10/28/2013	MI40T6FBN	BRADFORD WHITE	0
16990	10/26/2013	M45036FBN	BRADFORD WHITE	0
16991	10/23/2013	M45036FBN	BRADFORD WHITE	1
16992	10/25/2013	MI5036FBN	BRADFORD WHITE	0
16993	10/29/2013	M45036FBN	BRADFORD WHITE	1
16994	10/31/2013	M45036FBN	BRADFORD WHITE	0
16995	10/17/2013	M45036FBN	BRADFORD WHITE	0
16996	10/31/2013	MI40T6FBN	BRADFORD WHITE	0
16997	10/29/2013	M45036FBN	BRADFORD WHITE`	0
16998	10/26/2013	M45036FBN	BRADFORD WHITE	0
16999	10/21/2013	MI5036FBN	BRADFORD WHITE	0
17000	10/06/2013	M45036FBN	BRADFORD WHITE	0
17001	09/17/2013	M2XR504T6FBN	BRADFORD-WHITE	1
17002	09/17/2013	M45036FBN	BRADFORD-WHITE	1
17003	09/24/2013	MI40T6FBN	BRADFORD-WHITE	0
17004	09/25/2013	M45036FBN	BRADFORD-WHITE	0
17005	09/04/2013	MI5036FBN	BRADFORD-WHITE	0
17006	09/24/2013	MI40T6FBN	BRADFORD-WHITE	0
17007	09/20/2013	P230F	RUUD	0
17008	09/10/2013	DS140S6FBN	BRADFORD-WHITE DIRECT VENT	0
17009	09/14/2013	MI40T6FBN	BRADFORD-WHITE	0
17010	09/17/2013	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17011	09/14/2013	MI5036FBN	BRADFORD-WHITE	0
17012	09/14/2013	MI5036FBN	BRADFORD-WHITE	0
17013	09/13/2013	M440T6FBN	BRADFORD-WHITE	0
17014	11/06/2013	M45036FBN	Bradford White	0
17015	10/23/2013	MI50L6FBN	Bradford White	0
17016	11/01/2013	M45036FBN	Bradford White	0
17017	11/04/2013	PH2DV50F	RUUD/RHEEM	0
17018	10/28/2013	M45036FBN	Bradford White	0
17019	11/02/2013	M2XR504T6FBN	Bradford White	0
17020	10/30/2013	MI403S6FBN	Bradford White	0
17021	11/07/2013	M45036FBN	Bradford White	0
17022	10/31/2013	M45036FBN	BRADFORD WHITE	0
17023	11/04/2013	MI403S6FBN	BRADFORD WHITE	1
17024	11/01/2013	MI40T6FBN	BRADFORD WHTIE	2
17025	11/02/2013	M45036FBN	BRADFORD WHITE	0
17026	10/26/2013	M45036FBN	BRADFORD WHITE	0
17027	11/05/2013	M440T6FBN	BRADFORD WHITE	0
17028	11/07/2013	M45036FBN	BRADFORD WHITE	0
17029	11/02/2013	M45036FBN	BRADFORD WHITE	0
17030	11/01/2013	MI403S6FBN	BRADFORD WHITE	0
17031	10/24/2013	G82156	RUUD	0
17032	11/14/2013	G76200	RUUD	1
17033	11/11/2013	G75125	RUUD	7
17034	01/16/2014	MI40T6FBN	BRADFORD-WHITE	0
17035	11/28/2013	MI40T6FBN	BRADFORD WHITE	0
17036	11/07/2013	MI5036FBN	Bradford White	1
17037	11/07/2013	PH2DV50F	RUUD	0
17038	11/04/2013	M45036FBN	Bradford White	0
17039	11/02/2013	M45036FBN	Bradford White	0
17040	11/01/2013	MI40T6FBN	Bradford White	0
17041	11/13/2013	M45036FBN	Bradford White	0
17042	11/12/2013	M45036FBN	Bradford White	0
17043	10/29/2013	MI50L6FBN	Bradford White	0
17044	11/13/2013	M2XR504T6FBN	Bradford White	0
17045	11/14/2013	MI5036FBN	Bradford White	0
17046	11/11/2013	PH2DV50F	RUUD/RHEEM	0
17047	11/11/2013	M45036FBN	Bradford White	0
17048	11/06/2013	MI5036FBN	Bradford White	0
17049	10/27/2013	M45036FBN	Bradford White	0
17050	11/01/2013	M45036FBN	Bradford White	0
17051	10/26/2013	M45036FBN	Bradford White	0
17052	11/01/2013	M45036FBN	Bradford White	0
17053	11/07/2013	MI403S6FBN	Bradford White	0
17054	11/01/2013	PH2DV50F	Bradford White	0
17055	11/19/2013	M45036FBN	Bradford White	0
17056	09/17/2013	M45036FBN	BRADFORD-WHITE	0
17057	09/14/2013	MI5036FBN	BRADFORD-WHITE	0
17058	09/12/2013	MI5036FBN	BRADFORD-WHITE	0
17059	09/12/2013	M45036FBN	BRADFORD-WHITE	0
17060	09/19/2013	MI40T6FBN	BRADFORD-WHITE	0
17061	09/19/2013	MI5036FBN	BRADFORD-WHITE	0
17062	09/19/2013	M45036FBN	BRADFORD-WHITE	0
17063	11/01/2013	M45036FBN	BRADFORD-WHITE	1
17064	10/13/2013	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17065	10/21/2013	M45036FBN	BRADFORD-WHITE	0
17066	10/29/2013	M45036FBN	BRADFORD-WHITE	0
17067	10/31/2013	M45036FBN	Bradford White	0
17068	10/29/2013	M45036FBN	BRADFORD-WHITE	0
17069	11/06/2013	MI40T6FBN	Bradford White	0
17070	11/11/2013	MI5036FBN	Bradford White	0
17071	11/14/2013	MI50L6FBN	Bradford White	0
17072	10/24/2013	MI403S6FBN	BRADFORD-WHITE	0
17073	10/29/2013	M45036FBN	BRADFORD-WHITE	0
17074	11/14/2013	M45036FBN	Bradford White	0
17075	10/23/2013	MI5036FBN	BRADFORD-WHITE	0
17076	10/30/2013	MI5036FBN	BRADFORD-WHITE	0
17077	11/08/2013	MI5036FBN	Bradford White	0
17078	10/23/2013	MI5036FBN	BRADFORD-WHITE	1
17079	10/28/2013	PH2DV50F	RUUD	0
17080	12/08/2013	PH2DV50F	RUUD	1
17081	11/14/2013	M45036FBN	BRADFORD WHITE	1
17082	11/25/2013	MI5036FBN	BRADFORD WHITE	0
17083	11/27/2013	DS140S6FBN	BRADFORD WHITE	1
17084	11/20/2013	M45036FBN	BRADFORD WHITE	0
17085	11/22/2013	M45036FBN	BRADFORD WHITE	0
17086	11/16/2013	M45036FBN	BRADFORD WHITE	1
17087	11/19/2013	MI5036FBN	BRADFORD WHITE	1
17088	11/23/2013	MI5036FBN	BRADFORD WHITE	0
17089	11/25/2013	M45036FBN	BRADFORD WHITE	0
17090	11/22/2013	M45036FBN	BRADFORD WHITE	0
17091	11/28/2013	PH2DV50F	RUUD	0
17092	11/27/2013	M45036FBN	BRADFORD WHITE	0
17093	11/04/2013	PH2DV50F	RUUD/RHEEM	0
17094	10/22/2013	M45036FBN	BRADFORD-WHITE	1
17095	10/23/2013	PH2DV50F	RUUD	0
17096	10/22/2013	MI5036FBN	BRADFORD-WHITE	1
17097	10/28/2013	MI403S6FBN	BRADFORD-WHITE	0
17098	10/31/2013	M45036FBN	BRADFORD-WHITE	0
17099	10/28/2013	MI403S6FBN	BRADFORD-WHITE	0
17100	10/24/2013	MI50L6FBN	BRADFORD-WHITE	0
17101	10/11/2013	MI5036FBN	BRADFORD-WHITE	0
17102	10/18/2013	M45036FBN	BRADFORD-WHITE	0
17103	10/18/2013	M45036FBN	BRADFORD-WHITE	0
17104	10/18/2013	M45036FBN	BRADFORD WHITE	1
17105	12/09/2013	PH2DV50F	RUUD	0
17106	12/06/2013	MI40T6FBN	BRADFORD WHITE	0
17107	10/21/2013	MI5036FBN	BRADFORD-WHITE	0
17108	10/20/2013	MI50L6FBN	BRADFORD-WHITE	0
17109	10/08/2013	MI5036FBN	BRADFORD-WHITE	0
17110	10/22/2013	PH2DV50F	RUUD	0
17111	10/21/2013	MI40T6FBN	BRADFORD-WHITE	2
17112	10/29/2013	PH2DV50F	RUUD	0
17113	10/23/2013	MI5036FBN	BRADFORD-WHITE	1
17114	10/28/2013	MI40T6FBN	BRADFORD-WHITE	0
17115	10/28/2013	MI5036FBN	BRADFORD-WHITE	0
17116	10/15/2013	M45036FBN	BRADFORD-WHITE	0
17117	10/16/2013	DS150S6FBN	BRADFORD-WHITE DIRECT VENT	1
17118	08/29/2013	MI50L6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17119	10/08/2013	M45036FBN	BRADFORD-WHITE	0
17120	10/15/2013	P230F	RUUD	0
17121	10/12/2013	M45036FBN	BRADFORD-WHITE	0
17122	12/21/2013	M45036FBN	BRADFORD WHITE	0
17123	12/20/2013	M45036FBN	BRADFORD WHITE	0
17124	12/26/2013	PH2DV50F	RUUD	1
17125	12/20/2013	MI403S6FBN	BRADFORD WHITE	0
17126	12/21/2013	MI5036FBN	BRADFORD WHITE	0
17127	12/13/2013	M45036FBN	BRADFORD WHITE	0
17128	12/11/2013	MI403S6FBN	BRADFORD WHITE	0
17129	12/02/2013	MI40T6FBN	BRADFORD WHITE	0
17130	12/12/2013	M45036FBN	BRADFORD WHITE	0
17131	10/07/2013	MI403S6FBN	BRADFORD-WHITE	0
17132	12/10/2013	M45036FBN	BRADFORD WHITE	1
17133	12/10/2013	MI5036FBN	BRADFORD WHITE	0
17134	12/11/2013	M45036FBN	BRADFORD WHITE	0
17135	10/07/2013	MI5036FBN	BRADFORD WHITE	0
17136	10/15/2013	PH2DV50F	RUUD	0
17137	08/15/2013	MI40T6FBN	BRADFORD WHITE	0
17138	09/30/2013	MI403S6FBN	BRADFORD WHITE	2
17139	10/11/2013	M45036FBN	BRADFORD WHITE	0
17140	10/17/2013	MI5036FBN	BRADFORD WHITE	0
17141	10/15/2013	MI5036FBN	BRADFORD WHITE	0
17142	11/26/2013	MI5036FBN	Bradford White	0
17143	10/10/2013	MI40T6FBN	BRADFORD WHITE	0
17144	11/29/2013	G91200	Ruud	0
17145	11/20/2013	G91200	RUUD/RHEEM	1
17146	11/20/2013	M45036FBN	Bradford White	0
17147	11/20/2013	MI40T6FBN	Bradford White	0
17148	11/20/2013	M45036FBN	Bradford White	0
17149	11/18/2013	MI5036FBN	Bradford White	1
17150	11/21/2013	M45036FBN	Bradford White	1
17151	11/26/2013	MI5036FBN	Bradford White	0
17152	12/02/2013	PH2DV50F	RUUD	0
17153	12/04/2013	M45036FBN	BRADFORD WHITEQ	0
17154	12/13/2013	M45036FBN	BRADFORD WHITE	0
17155	11/26/2013	DS150S6FBN	Bradford White	0
17156	12/13/2013	M45036FBN	BRADFORD WHITE	1
17157	11/19/2013	PH2DV50F	RUUD/RHEEM	0
17158	10/10/2013	P230F	RUUD/RHEEM	0
17159	12/10/2013	MI5036FBN	BRADFORD WHITE	1
17160	12/18/2013	MI403S6FBN	Bradford White	0
17161	11/18/2013	M45036FBN	Bradford White	0
17162	12/06/2013	MI5036FBN	Bradford White	0
17163	12/06/2013	FSG40	AO SMITH	0
17164	12/02/2013	MI5036FBN	Bradford White	1
17165	12/04/2013	PH2DV50F	RUUD/RHEEM	0
17166	11/26/2013	MI403S6FBN	Bradford White	0
17167	12/20/2013	M45036FBN	Bradford White	0
17168	12/03/2013	M45036FBN	Bradford White	0
17169	12/17/2013	M45036FBN	Bradford White	0
17170	12/17/2013	M2XR504T6FBN	Bradford White	1
17171	11/27/2013	MI5036FBN	Bradford White	1
17172	12/19/2013	MI5036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17173	12/08/2013	M45036FBN	Bradford White	0
17174	12/11/2013	M45036FBN	Bradford White	1
17175	10/25/2013	G82156	RUUD	5
17176	11/07/2013	MI75S6FBN	BRADFORD-WHITE	1
17177	11/03/2013	MI5036FBN	Bradford White	1
17178	11/06/2013	G91200	RUUD	0
17179	11/17/2013	G82156	RUUD	3
17180	11/16/2013	MI403S6FBN	BRADFORD-WHITE	0
17181	12/04/2013	MI5036FBN	Bradford White	0
17182	11/18/2013	M45036FBN	BRADFORD-WHITE	0
17183	11/05/2013	M45036FBN	BRADFORD-WHITE	1
17184	11/18/2013	MI5036FBN	BRADFORD-WHITE	0
17185	11/18/2013	MI403S6FBN	BRADFORD-WHITE	0
17186	12/24/2013	G82156	RUUD	1
17187	11/16/2013	MI5036FBN	BRADFORD-WHITE	0
17188	12/16/2013	M140T6FBN	BRADFORD WHTIE	0
17189	12/11/2013	M2XR504T6FBN	BRADFORD WHITE	0
17190	11/14/2013	M45036FBN	BRADFORD WHITE	0
17191	12/15/2013	M45036FBN	BRADFORD WHITE	0
17192	12/11/2013	M45036FBN	BRADFORD WHITE	0
17193	12/23/2013	M45036FBN	BRADFORD WHITE	0
17194	12/04/2013	MI5036FBN	BRADFORD WHITE	0
17195	10/29/2013	M45036FBN	BRADFORD-WHITE	0
17196	11/19/2013	M45036FBN	BRADFORD-WHITE	0
17197	11/12/2013	M45036FBN	BRADFORD-WHITE	0
17198	11/09/2013	M45036FBN	BRADFORD-WHTE	0
17199	11/11/2013	M45036FBN	BRADFORD-WHITE	0
17200	11/19/2013	M45036FBN	BRADFORD-WHITE	0
17201	11/15/2013	MI5036FBN	BRADFORD-WHITE	0
17202	11/21/2013	M45036FBN	BRADFORD-WHITE	0
17203	11/22/2013	M45036FBN	BRADFORD-WHITE	0
17204	11/23/2013	M45036FBN	BRADFORD-WHITE	0
17205	11/23/2013	MI5036FBN	BRADFORD-WHITE	1
17206	11/23/2013	MI40T6FBN	BRADFORD-WHITE	0
17207	11/25/2013	M45036FBN	BRADFORD-WHITE	1
17208	11/22/2013	M45036FBN	BRADFORD-WHITE	0
17209	11/25/2013	MI5036FBN	BRADFORD-WHITE	0
17210	12/20/2013	M45036FBN	Bradford White	0
17211	12/02/2013	M45036FBN	Bradford White	0
17212	12/27/2013	MI5036FBN	Bradford White	0
17213	12/20/2013	M45036FBN	Bradford White	0
17214	08/14/2013	M45036FBN	Bradford White	0
17215	12/07/2013	M45036FBN	Bradford White	0
17216	12/05/2013	MI5036FBN	Bradford White	0
17217	12/06/2013	M45036FBN	Bradford White	0
17218	12/04/2013	M45036FBN	Bradford White	0
17219	10/30/2013	M45036FBN	Bradford White	0
17220	11/27/2013	G76200	RUUD/RHEEM	0
17221	11/30/2013	M45036FBN	Bradford White	0
17222	11/27/2013	M45036FBN	Bradford White	1
17223	11/19/2013	M440T6FBN	Bradford White	0
17224	12/14/2013	MI5036FBN	BRADFORD WHITE	0
17225	12/27/2013	MI5036FBN	BRADFORD WHITE	0
17226	12/24/2013	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17227	12/30/2013	M45036FBN	BRADFORD WHITE	0
17228	12/07/2013	M45036FBN	BRADFORD WHITE	0
17229	12/13/2013	G82156	RUUD	0
17230	12/09/2013	G91200	RUUD	0
17231	12/09/2013	G91200	RUUD	2
17232	12/05/2013	PH199119	PHOENIX	1
17233	12/16/2013	G91200	RUUD	1
17234	12/14/2013	G82156	RUUD	0
17235	12/16/2013	G91200	RUUD	1
17236	12/06/2013	MI5036FBN	BRADFORD WHITE	0
17237	12/17/2013	MI5036FBN	BRADFORD WHITE	1
17238	12/28/2013	M45036FBN	BRADFORD WHITE	0
17239	11/26/2013	M45036FBN	Bradford White	0
17240	01/25/2014	M45036FBN	Bradford White	0
17241	12/12/2013	M45036FBN	Bradford White	0
17242	12/31/2013	PH2DV50F	Ruud	0
17243	12/03/2013	M45036FBN	Bradford White	0
17244	12/05/2013	M45036FBN	Bradford White	0
17245	12/06/2013	M45036FBN	BRADFORD-WHITE	1
17246	11/21/2013	M45036FBN	BRADFORD-WHITE	0
17247	11/19/2013	M45036FBN	BRADFORD-WHITE	0
17248	11/26/2013	MI5036FBN	BRADFORD-WHITE	1
17249	12/09/2013	PH2DV50F	RUUD	0
17250	12/11/2013	PH2DV50F	RUUD	0
17251	12/12/2013	MI5036FBN	BRADFORD-WHITE	0
17252	12/05/2013	M45036FBN	BRADFORD-WHITE	0
17253	12/09/2013	M45036FBN	BRADFORD-WHITE	0
17254	12/10/2013	M45036FBN	BRADFORD-WHITE	0
17255	12/09/2013	MI5036FBN	BRADFORD-WHITE	0
17256	12/06/2013	M45036FBN	BRADFORD-WHITE	0
17257	12/03/2013	MI5036FBN	BRADFORD-WHITE	1
17258	12/05/2013	MI40T6FBN	BRADFORD-WHITE	0
17259	11/26/2013	MI5036FBN	BRADFORD-WHITE	0
17260	11/26/2013	MI5036FBN	BRADFORD-WHITE	0
17261	12/30/2013	M45036FBN	BRADFORD WHITE	2
17262	12/30/2013	MI5036FBN	BRADFORD WHITE	0
17263	09/26/2013	MI5036FBN	BRADFORD WHITE	1
17264	01/03/2014	M45036FBN	BRADFORD WHITE	0
17265	12/26/2013	M45036FBN	BRADFORD WHITE	0
17266	12/24/2013	M45036FBN	BRADFORD WHITE	0
17267	01/04/2014	M45036FBN	BRADFORD WHITE	0
17268	10/29/2013	MI40T6FBN	BRADFORD WHITE	0
17269	12/10/2013	G82156	RUUD	6
17270	12/12/2013	G91200	RUUD	0
17271	01/06/2014	M45036FBN	BRADFORD WHITE	1
17272	01/08/2014	MI5036FBN	BRADFORD WHITE	0
17273	12/26/2013	MI40T6FBN	BRADFORD WHITE	0
17274	01/04/2014	PH2DV50F	RUUD	0
17275	01/08/2014	PH2DV50F	RUUD	1
17276	12/12/2013	G100200	RUUD	0
17277	12/06/2013	G91200	RUUD	0
17278	10/10/2013	PH2DV50F	RUUD	0
17279	06/26/2013	PH2DV50F	RUUD	1
17280	01/05/2014	M45036FBN	BRADFORD-WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17281	01/08/2014	G82156	RUUD/RHEEM	0
17282	01/08/2014	M45036FBN	BRADFORD-WHITE	1
17283	12/26/2013	M45036FBN	BRADFORD-WHITE	0
17284	12/23/2013	M2XR504T6FBN	BRADFORD-WHITE	0
17285	12/19/2013	MI5036FBN	BRADFORD-WHITE	0
17286	12/15/2013	M45036FBN	BRADFORD-WHITE	0
17287	12/29/2013	MI5036FBN	BRADFORD-WHITE	0
17288	01/03/2014	M45036FBN	Bradford White	0
17289	12/31/2013	M440T6FBN	Bradford White	0
17290	12/17/2013	M45036FBN	Bradford White	3
17291	12/26/2013	PH2DV50F	Bradford White	0
17292	01/02/2014	MI50L6FBN	Bradford White	0
17293	01/02/2014	MI5036FBN	Bradford White	0
17294	01/06/2014	MI40T6FBN	Bradford White	0
17295	12/29/2013	M2XR504T6FBN	Bradford White	6
17296	01/12/2014	G91200	RUUD/RHEEM	2
17297	01/13/2014	M45036FBN	Bradford White	0
17298	01/14/2014	PH2DV50F	RUUD/RHEEM	0
17299	01/14/2014	MI5036FBN	Bradford White	1
17300	01/20/2014	MI40T6FBN	BRADFORD WHITE	0
17301	01/21/2014	M45036FBN	BRADFORD WHITE	0
17302	01/27/2014	PROG5038NRU58DV	RUUD	1
17303	01/24/2014	MI5036FBN	BRADFORD WHITE	2
17304	01/20/2014	MI40T6FBN	BRADFORD WHITE	0
17305	01/23/2014	M45036FBN	BRADFORD WHITE	0
17306	12/19/2013	MI40T6FBN	Bradford White	0
17307	01/17/2014	MI40T6FBN	BRADFORD-WHITE	0
17308	11/18/2013	G91200	RUUD	3
17309	01/16/2014	M45036FBN	Bradford White	0
17310	01/24/2014	MI5036FBN	Bradford White	0
17311	12/04/2013	G82156	RUUD/RHEEM	3
17312	12/31/2013	M45036FBN	Bradford White	0
17313	01/19/2014	MI5036FBN	Bradford White	0
17314	01/17/2014	FGR50	AO SMITH	0
17315	01/26/2014	M45036FBN	Bradford White	0
17316	01/17/2014	M45036FBN	Bradford White	0
17317	01/30/2014	M45036FBN	Bradford White	0
17318	01/24/2014	M45036FBN	Bradford White	0
17319	01/19/2014	MI40T6FBN	BRADFORD-WHITE	0
17320	01/28/2014	MI40T6FBN	BRADFORD-WHITE	0
17321	12/17/2013	G91200	RUUD	0
17322	12/15/2013	M45036FBN	Bradford White	0
17323	12/14/2013	M45036FBN	BRADFORD-WHITE	0
17324	12/31/2013	M440T6FBN	Bradford White	0
17325	01/08/2014	MI5036FBN	BRADFORD-WHITE	1
17326	01/10/2014	PH2DV50F	RUUD/RHEEM	0
17327	12/19/2013	MI5036FBN	Bradford White	0
17328	12/06/2013	G75125	Bradford White	1
17329	12/15/2013	MI50L6FBN	Bradford White	0
17330	01/07/2014	M45036FBN	Bradford White	0
17331	01/02/2014	M45036FBN	Bradford White	0
17332	01/03/2014	MI5036FBN	Bradford White	0
17333	12/17/2013	MI40T6FBN	BRADFORD-WHITE	0
17334	01/03/2014	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17335	12/23/2013	MI5036FBN	Bradford White	0
17336	12/04/2013	P230F	RUUD	0
17337	11/06/2013	MI403S6FBN	BRADFORD-WHITE	1
17338	10/30/2013	MI403S6FBN	BRADFORD-WHITE	0
17339	10/30/2013	MI403S6FBN	BRADFORD-WHITE	0
17340	11/30/2013	M2XR504T6FBN	BRADFORD-WHITE	0
17341	12/07/2013	MI5036FBN	BRADFORD-WHITE	0
17342	01/09/2014	M45036FBN	Bradford White	0
17343	12/18/2013	MI5036FBN	Bradford White	0
17344	01/05/2014	MI40T6FBN	Bradford White	0
17345	01/09/2014	M45036FBN	Bradford White	0
17346	12/21/2013	M45036FBN	Bradford White	0
17347	12/27/2013	M45036FBN	BRADFORD-WHITE	3
17348	11/26/2013	MI40T6FBN	Bradford White	0
17349	12/22/2013	M45036FBN	BRADFORD-WHITE	0
17350	12/29/2013	PH2DV50F	RUUD	2
17351	12/29/2013	PH2DV50F	RUUD	1
17352	12/30/2013	PHR50	RUUD	0
17353	12/30/2013	MI40T6FBN	BRADFORD-WHITE	0
17354	12/16/2013	MI5036FBN	BRADFORD-WHITE	1
17355	12/31/2013	PH2DV50F	RUUD	0
17356	06/20/2013	G91200	RUUD	0
17357	12/20/2013	M45036FBN	Bradford White	0
17358	12/31/2013	M45036FBN	Bradford White	0
17359	12/31/2013	M45036FBN	Bradford White	0
17360	12/31/2013	M440T6FBN	Bradford White	0
17361	11/29/2013	M2XR504T6FBN	BRADFORD-WHITE	0
17362	12/02/2013	MI5036FBN	BRADFORD-WHITE	0
17363	12/02/2013	M45036FBN	BRADFORD-WHITE	0
17364	12/30/2013	M45036FBN	BRADFORD-WHITE	1
17365	11/05/2013	MI5036FBN	BRADFORD-WHITE	0
17366	12/11/2013	G91200	RUUD	0
17367	01/08/2014	P230F	RUUD	1
17368	01/04/2014	M45036FBN	BRADFORD-WHITE	0
17369	12/26/2013	M45036FBN	BRADFORD-WHITE	0
17370	01/10/2014	MI403S6FBN	BRADFORD-WHITE	2
17371	01/07/2014	MI50L6FBN	BRADFORD-WHITE	1
17372	01/06/2014	M45036FBN	BRADFORD-WHITE	0
17373	12/30/2013	MI5036FBN	BRADFORD-WHITE	0
17374	01/07/2014	G82156	RUUD	0
17375	01/02/2014	PH2DV50F	RUUD	0
17376	12/09/2013	MI50L6FBN	BRADFORD-WHITE	0
17377	05/28/2013	P230F	RUUD	1
17378	12/13/2013	M45036FBN	BRADFORD WHITE	0
17379	12/30/2013	M45036FBN	BRADFORD WHITE	0
17380	12/27/2013	MI5036FBN	BRADFORD WHITE	0
17381	12/28/2013	G82156	RUUD	1
17382	01/07/2014	RF82156	RUUD	0
17383	01/04/2014	MI50L6FBN	BRADFORD WHITE	1
17384	01/02/2014	PH2DV50F	RUUD	0
17385	12/30/2013	M45036FBN	BRADFORD WHITE	0
17386	01/06/2014	MI5036FBN	BRADFORD WHITE	1
17387	12/06/2013	G82156	RUUD	2
17388	01/10/2014	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17389	01/10/2014	PH2DV50F	RUUD	1
17390	01/15/2014	PH2DV50F	RUUD	0
17391	01/10/2014	PH2DV50F	RUUD	0
17392	01/06/2014	M45036FBN	BRADFORD WHITE	0
17393	12/26/2013	MI403S6FBN	BRADFORD WHITE	0
17394	12/13/2013	PH2DV50F	RUUD	1
17395	01/14/2014	MI403S6FBN	BRADFORD WHITE	0
17396	01/31/2014	M45036FBN	BRADFORD WHITE	0
17397	01/26/2014	MI5036FBN	BRADFORD WHITE	0
17398	01/30/2014	PH2DV50F	RUUD	0
17399	01/14/2014	M45036FBN	BRADFORD WHITE	0
17400	01/19/2014	MI40T6FBN	BRADFORD WHITE	0
17401	01/22/2014	PH199119	PHOENIX	3
17402	01/20/2014	M45036FBN	BRADFORD WHITE	1
17403	01/21/2014	M45036FBN	BRADFORD WHITE	3
17404	01/22/2014	M440T6FBN	BRADFORD WHITE	0
17405	01/23/2014	M45036FBN	BRADFORD WHITE	1
17406	01/24/2014	M45036FBN	BRADFORD WHITE	0
17407	01/16/2014	MI5036FBN	BRADFORD WHITE	0
17408	12/28/2013	MI5036FBN	BRADFORD-WHITE	0
17409	01/02/2014	G82156	RUUD	0
17410	01/15/2014	MI403S6FBN	BRADFORD-WHITE	0
17411	01/11/2014	M45036FBN	BRADFORD-WHITE	0
17412	01/09/2014	M45036FBN	BRADFORD-WHITE	0
17413	01/06/2014	G91200	RUUD	1
17414	01/07/2014	MI403S6FBN	BRADFORD-WHITE	0
17415	01/09/2014	MI40T6FBN	BRADFORD-WHITE	0
17416	01/16/2014	M45036FBN	BRADFORD-WHITE	1
17417	01/28/2014	PH2DV50F	RUUD	0
17418	01/29/2014	PH2DV50F	RUUD	0
17419	12/27/2013	M45036FBN	Bradford White	0
17420	01/23/2014	G91200	RUUD/RHEEM	0
17421	01/23/2014	M440T6FBN	Bradford White	4
17422	01/27/2014	PGR50	AO SMITH	0
17423	01/24/2014	M45036FBN	Bradford White	0
17424	02/01/2014	M45036FBN	BRADFORD WHITE	1
17425	02/01/2014	PROG5038NRU58DV	RUUD	1
17426	01/28/2014	MI5036FBN	BRADFORD WHITE	0
17427	02/04/2014	M45036FBN	BRADFORD WHITE	0
17428	02/06/2014	PH2DV50F	RUUD	1
17429	01/28/2014	MI5036FBN	BRADFORD-WHITE	0
17430	01/29/2014	M45036FBN	BRADFORD-WHITE	0
17431	01/21/2014	M45036FBN	BRADFORD-WHITE	0
17432	01/22/2014	M45036FBN	BRADFORD-WHITE	2
17433	01/17/2014	M45036FBN	BRADFORD-WHITE	0
17434	01/17/2014	M45036FBN	BRADFORD-WHITE	0
17435	02/04/2014	M45036FBN	BRADFORD WHITE	0
17436	02/11/2014	MI50L6FBN	BRADFORD WHITE	2
17437	02/08/2014	MI5036FBN	BRADFORD WHITE	0
17438	02/12/2014	M45036FBN	BRADFORD WHITE	0
17439	01/31/2014	PH2DV50F	RUUD	0
17440	01/27/2014	M45036FBN	BRADFORD WHITE	0
17441	02/12/2014	M45036FBN	BRADFORD WHITE	0
17442	02/07/2014	DS150S6FBN	BRADFORD WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17443	02/08/2014	PH2DV50F	RUUD	1
17444	02/06/2014	M45036FBN	BRADFORD WHITE	0
17445	02/06/2014	PH2DV50F	RUUD	0
17446	02/03/2014	MI5036FBN	BRADFORD WHITE	0
17447	02/03/2014	MI5036FBN	BRADFORD WHITE	0
17448	02/04/2014	MI40T6FBN	BRADFORD WHITE	0
17449	02/07/2014	MI5036FBN	BRADFORD WHITE	0
17450	02/07/2014	MI5036FBN	BRADFORD WHITE	0
17451	01/20/2014	PH2DV50F	RUUD	1
17452	01/29/2014	M45036FBN	BRADFORD WHITE	0
17453	01/21/2014	M440T6FBN	BRADFORD WHITE	0
17454	01/21/2014	MI5036FBN	BRADFORD-WHITE	0
17455	01/23/2014	M45036FBN	BRADFORD-WHITE	0
17456	01/23/2014	MI5036FBN	BRADFORD-WHITE	0
17457	01/22/2014	M45036FBN	Bradford White	0
17458	01/21/2014	PGR50	AO SMITH	0
17459	01/21/2014	MI40T6FBN	Bradford White	0
17460	01/21/2014	MI5036FBN	Bradford White	0
17461	02/10/2014	M45036FBN	Bradford White	0
17462	02/10/2014	PROG5038NRU58DV	Ruud/Rheem	0
17463	02/06/2014	MI75S6FBN	Bradford White	2
17464	02/12/2014	M45036FBN	Bradford White	0
17465	12/24/2013	M45036FBN	Bradford White	0
17466	02/14/2014	G91200	RUUD/RHEEM	0
17467	02/19/2014	MI5036FBN	Bradford White	0
17468	02/19/2014	M45036FBN	Bradford White	0
17469	02/18/2014	M45036FBN	Bradford White	0
17470	01/31/2014	G82156	Ruud/Rheem	0
17471	02/13/2014	M45036FBN	Bradford White	0
17472	01/27/2014	M2XR504T6FBN	BRADFORD-WHITE	0
17473	02/06/2014	G91200	RUUD	0
17474	02/06/2014	G91200	RUUD	1
17475	12/17/2013	MI5036FBN	BRADFORD-WHITE	0
17476	02/21/2014	M45036FBN	BRADFORD-WHITE	0
17477	02/20/2014	M45036FBN	BRADFORD-WHITE	0
17478	01/29/2014	G82156	RUUD	2
17479	02/19/2014	MI403S6FBN	BRADFORD-WHITE	1
17480	02/14/2014	MI50L6FBN	BRADFORD-WHITE	0
17481	01/31/2014	M45036FBN	BRADFORD WHITE	0
17482	02/19/2014	DS140S6FBN	BRADFORD WHITE	0
17483	02/13/2014	M45036FBN	BRADFORD WHITE	0
17484	01/30/2014	G82156	RUUD	0
17485	02/17/2014	M45036FBN	BRADFORD WHITE	0
17486	02/12/2014	MI5036FBN	BRADFORD WHITE	0
17487	01/28/2014	MI5036FBN	BRADFORD WHITE	0
17488	01/25/2014	MI40T6FBN	BRADFORD-WHITE	0
17489	01/28/2014	MI40T6FBN	BRADFORD-WHITE	0
17490	01/24/2014	M45036FBN	BRADFORD-WHITE	0
17491	01/28/2014	MI5036FBN	BRADFORD-WHITE	1
17492	01/22/2014	MI40T6FBN	BRADFORD-WHITE	0
17493	02/11/2014	M440T6FBN	BRADFORD-WHITE	0
17494	02/07/2014	M45036FBN	BRADFORD-WHITE	0
17495	02/05/2014	MI5036FBN	BRADFORD-WHITE	0
17496	01/31/2014	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17497	01/19/2014	MI5036FBN	BRADFORD-WHITE	0
17498	02/07/2014	PROG5038NRU58DV	RUUD	0
17499	02/08/2014	MI40T6FBN	BRADFORD-WHITE	0
17500	02/10/2014	MI40T6FBN	BRADFORD-WHITE	0
17501	02/07/2014	MI50L6FBN	BRADFORD-WHITE	0
17502	02/05/2014	M45036FBN	BRADFORD-WHITE	0
17503	02/17/2014	MI5036FBN	BRADFORD WHITE	2
17504	02/02/2014	MI5036FBN	BRADFORD WHITE	0
17505	02/17/2014	MI40T6FBN	BRADFORD WHITE	0
17506	02/21/2014	M45036FBN	BRADFORD WHITE	0
17507	02/24/2014	M45036FBN	BRADFORD WHITE	0
17508	02/26/2014	DS150S6FBN	BRADFORD WHITE	0
17509	02/11/2014	MI403S6FBN	BRADFORD WHITE	0
17510	02/25/2014	M45036FBN	BRADFORD WHTIE	0
17511	02/18/2014	PH2DV50F	RUUD	1
17512	02/11/2014	MI40T6FBN	BRADFORD WHITE	0
17513	02/03/2014	MI5036FBN	BRADFORD-WHITE	0
17514	01/31/2014	PH2DV50F	RUUD	0
17515	02/14/2014	MI5036FBN	Bradford White	0
17516	02/14/2014	M45036FBN	Bradford White	0
17517	01/30/2014	MI5036FBN	Bradford White	0
17518	02/25/2014	M45036FBN	Bradford White	0
17519	01/22/2014	MI5036FBN	Bradford White	0
17520	02/26/2014	M45036FBN	BRADFORD WHITE	0
17521	02/24/2014	MI40T6FBN	BRADFORD WHITE	0
17522	02/20/2014	PH2DV50F	RUUD	0
17523	02/24/2014	M45036FBN	BRADFORD WHITE	0
17524	02/13/2014	MI40T6FBN	BRADFORD WHITE	0
17525	02/21/2014	M45036FBN	BRADFORD WHTIE	0
17526	02/23/2014	M45036FBN	BRADFORD WHITE	0
17527	02/28/2014	G76200	RUUD	3
17528	02/28/2014	PROG5038NRU58	RUUD	0
17529	12/26/2013	G75125	RUUD	0
17530	02/25/2014	MI5036FBN	Bradford White	0
17531	02/20/2014	M45036FBN	Bradford White	0
17532	02/21/2014	M45036FBN	Bradford White	0
17533	02/26/2014	DS150S6FBN	Bradford White	0
17534	02/19/2014	M45036FBN	BRADFORD-WHITE	0
17535	02/18/2014	G91200	RUUD/RHEEM	0
17536	03/21/2013	M45036FBN	BRADFORD-WHITE	0
17537	01/22/2014	M45036FBN	Bradford White	0
17538	02/13/2014	MI5036FBN	Bradford White	0
17539	02/24/2014	M45036FBN	Bradford White	0
17540	02/13/2014	PH2DV50F	Ruud/Rheem	1
17541	02/25/2014	MI403S6FBN	Bradford White	0
17542	02/09/2014	PROG5038NRU58DV	Ruud/Rheem	0
17543	02/27/2014	M440T6FBN	Bradford White	1
17544	02/08/2014	MI5036FBN	BRADFORD-WHITE	1
17545	01/26/2014	MI5036FBN	BRADFORD-WHITE	0
17546	02/14/2014	PH2DV50F	RUUD	0
17547	02/25/2014	M45036FBN	BRADFORD-WHITE	1
17548	02/26/2014	MI50L6FBN	BRADFORD-WHITE	0
17549	02/17/2014	PH2DV50F	RUUD	0
17550	02/20/2014	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17551	02/13/2014	MI5036FBN	BRADFORD-WHITE	1
17552	02/15/2014	PH2DV50F	RUUD	0
17553	02/27/2014	M45036FBN	BRADFORD-WHITE	0
17554	02/06/2014	G91200	RUUD/RHEEM	2
17555	02/27/2014	M45036FBN	BRADFORD-WHITE	0
17556	02/25/2014	M45036FBN	BRADFORD-WHITE	0
17557	02/09/2014	MI5036FBN	BRADFORD-WHITE	0
17558	02/14/2014	M45036FBN	BRADFORD-WHITE	0
17559	02/18/2014	P230F	BRADFORD-WHITE	0
17560	02/13/2014	M45036FBN	BRADFORD-WHITE	0
17561	01/20/2014	G91200	RUUD	0
17562	02/28/2014	MI5036FBN	BRADFORD-WHITE	0
17563	03/05/2014	M45036FBN	BRADFORD-WHITE	0
17564	02/19/2014	MI40T6FBN	BRADFORD-WHITE	0
17565	03/04/2014	G91200	RUUD	0
17566	03/04/2014	G91200	RUUD	0
17567	03/03/2014	PROG5038NRU58	Ruud	0
17568	03/06/2014	PROG5038NRU58DV	RUUD	3
17569	03/05/2014	MI403S6FBN	BRADFORD-WHITE	0
17570	03/11/2014	M45036FBN	BRADFORD-WHITE	1
17571	02/25/2014	G91200	RUUD	0
17572	03/12/2014	M45036FBN	BRADFORD-WHITE	0
17573	03/13/2014	MI40T6FBN	BRADFORD-WHITE	0
17574	02/15/2014	MI5036FBN	BRADFORD-WHITE	0
17575	02/15/2014	MI5036FBN	BRADFORD-WHITE	1
17576	03/12/2014	MI5036FBN	Bradford White	0
17577	03/10/2014	M45036FBN	Bradford White	0
17578	03/11/2014	MI5036FBN	Bradford White	0
17579	03/08/2014	M440T6FBN	Bradford White	0
17580		MI403S6FBN	Bradford White	0
17581	03/07/2014	PH2DV50F	Ruud/Rheem	1
17582	03/17/2014	G91200	RUUD/RHEEM	0
17583	03/13/2014	M45036FBN	Bradford White	0
17584	03/16/2014	MI5036FBN	Bradford White	0
17585	03/07/2014	M45036FBN	Bradford White	0
17586	03/07/2014	M45036FBN	Bradford White	0
17587	03/15/2014	M45036FBN	Bradford White	0
17588	03/17/2014	M45036FBN	Bradford White	0
17589	03/01/2014	M45036FBN	BRADFORD WHITE	1
17590	03/01/2014	MI5036FBN	BRADFORD WHITE	0
17591	02/20/2014	M45036FBN	BRADFORD WHITE	3
17592	03/07/2014	MI75S6FBN	BRADFORD WHITE	1
17593	03/10/2014	M45036FBN	BRADFORD WHITE	0
17594	03/10/2014	MI5036FBN	BRADFORD WHITE	0
17595	03/07/2014	MI5036FBN	BRADFORD WHITE	0
17596	03/03/2014	MI5036FBN	BRADFORD WHITE	0
17597	03/07/2014	M45036FBN	BRADFORD WHITE	0
17598	03/12/2014	MI5036FBN	BRADFORD WHITE	0
17599	03/01/2014	G82156	RUUD	0
17600	03/04/2014	M45036FBN	BRADFORD WHITE	1
17601	02/28/2014	PH2DV50F	Ruud/Rheem	0
17602	03/02/2014	M45036FBN	Bradford White	0
17603	02/28/2014	M45036FBN	Bradford White	0
17604	03/19/2014	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17605	03/10/2014	MI5036FBN	BRADFORD-WHITE	0
17606	03/07/2014	M45036FBN	BRADFORD-WHITE	0
17607	03/07/2014	FSG40	AO SMITH	0
17608	03/10/2014	M45036FBN	BRADFORD-WHITE	2
17609	02/21/2014	MI75S6FBN	Bradford White	0
17610	03/07/2014	MI5036FBN	BRADFORD-WHITE	0
17611	03/13/2014	MI5036FBN	BRADFORD WHITE	1
17612	03/13/2014	G76200	RUUD	1
17613	03/20/2014	PH2DV50F	State	0
17614	03/03/2014	M45036FBN	Bradford White	0
17615	02/21/2014	PGX50	AO SMITH	1
17616	03/04/2014	DS140S6FBN	Bradford White	0
17617	03/03/2014	M45036FBN	Bradford White	0
17618	03/09/2014	M45036FBN	BRADFORD-WHITE	1
17619	03/14/2014	M45036FBN	BRADFORD-WHITE	0
17620	03/12/2014	MI5036FBN	BRADFORD WHITE	0
17621	03/02/2014	M45036FBN	BRADFORD WHITE	0
17622	02/23/2014	MI40T6FBN	BRADFORD WHITE	0
17623	03/18/2014	M45036FBN	BRADFORD WHITE	2
17624	03/20/2014	M440T6FBN	BRADFORD WHITE	0
17625	03/26/2014	MI40T6FBN	BRADFORD WHITE	0
17626	03/28/2014	PROG5038NRU58	RUUD	0
17627	03/20/2014	M45036FBN	BRADFORD WHITE	0
17628	03/20/2014	MI5036FBN	BRADFORD WHITE	0
17629	03/20/2014	M45036FBN	BRADFORD WHITE	0
17630	03/26/2014	M45036FBN	BRADFORD WHITE	0
17631	03/26/2014	MI5036FBN	BRADFORD WHITE	0
17632	03/25/2014	M45036FBN	BRADFORD WHITE	1
17633	03/26/2014	MI403S6FBN	BRADFORD WHITE	0
17634	03/21/2014	MI5036FBN	BRADFORD WHITE	1
17635	03/22/2014	PROG5038NRU58DV	RUUD	0
17636	03/19/2014	MI5036FBN	BRADFORD WHITE	0
17637	03/31/2014	M45036FBN	Bradford White	0
17638	03/18/2014	M45036FBN	Bradford White	0
17639	03/31/2014	PROG5038NRU58DV	Ruud/Rheem	0
17640	02/25/2014	M45036FBN	Bradford White	0
17641	03/29/2014	PH2DV50F	RHEEM	0
17642	03/31/2014	M45036FBN	Bradford White	5
17643	03/21/2014	G76200	Ruud/Rheem	0
17644	03/31/2014	M45036FBN	Bradford White	0
17645	04/01/2014	M45036FBN	Bradford White	0
17646	04/01/2014	M45036FBN	Bradford White	0
17647	06/19/2014	MI5036FBN	Bradford White	1
17648	03/31/2014	MI5036FBN	Bradford White	0
17649	03/25/2014	G91200	Ruud/Rheem	0
17650	03/21/2014	M45036FBN	Bradford White	0
17651	03/20/2014	M45036FBN	Bradford White	0
17652	04/03/2014	M45036FBN	Bradford White	0
17653	03/28/2014	M45036FBN	Bradford White	1
17654	03/25/2014	MI40T6FBN	Bradford White	0
17655	03/28/2014	M2XR504T6FBN	BRADFORD WHITE	0
17656	03/19/2014	MI40T6FBN	Bradford White	0
17657	03/23/2014	MI403S6FBN	Bradford White	0
17658	03/19/2014	G75125	Ruud/Rheem	9

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17659	03/22/2014	M440T6FBN	Bradford White	0
17660	03/17/2014	M45036FBN	Bradford White	0
17661	03/04/2014	PH2DV50F	Ruud/Rheem	0
17662	03/20/2014	M45036FBN	Bradford White	0
17663	03/18/2014	M45036FBN	Bradford White	0
17664	03/24/2014	M45036FBN	Bradford White	0
17665	03/25/2014	MI5036FBN	Bradford White	0
17666	03/17/2014	M440T6FBN	Bradford White	0
17667	04/14/2014	MI40T6FBN	Bradford White	0
17668	04/04/2014	M45036FBN	Bradford White	0
17669	04/09/2014	M45036FBN	Bradford White	0
17670	04/08/2014	M45036FBN	Bradford White	0
17671	04/08/2014	M45036FBN	Bradford White	0
17672	04/05/2014	M45036FBN	Bradford White	0
17673	04/04/2014	MI5036FBN	Bradford White	0
17674	03/08/2014	M45036FBN	BRADFORD-WHITE	0
17675	03/25/2014	M45036FBN	BRADFORD-WHITE	0
17676	03/25/2014	MI5036FBN	BRADFORD-WHITE	0
17677	03/21/2014	MI5036FBN	BRADFORD-WHITE	0
17678	03/19/2014	PH2DV50F	RUUD	0
17679	03/05/2014	M45036FBN	BRADFORD-WHITE	0
17680	03/29/2014	M45036FBN	BRADFORD WHITE	1
17681	03/31/2014	M45036FBN	BRADFORD WHITE	0
17682	02/10/2014	G91200	RUUD	0
17683	03/25/2014	MI5036FBN	BRADFORD WHITE	0
17684	03/24/2014	MI40T6FBN	BRADFORD WHITE	0
17685	03/31/2014	G75125	RUUD	1
17686	03/31/2014	PGR40	AO SMITH	0
17687	02/23/2014	G91200	RUUD	1
17688	03/31/2014	PROG5038NRU58	RUUD	2
17689	03/27/2014	M45036FBN	BRADFORD WHITE	0
17690	04/01/2014	G91200	RUUD	0
17691	03/01/2014	M45036FBN	BRADFORD WHITE	0
17692	04/04/2014	MI5036FBN	BRADFORD WHITE	0
17693	03/16/2014	M440T6FBN	BRADFORD WHITE	0
17694	04/01/2014	MI5036FBN	BRADFORD WHITE	2
17695	03/24/2014	G75125	RUUD/RHEEM	1
17696	03/24/2014	G75125	RUUD/RHEEM	2
17697	04/01/2014	M45036FBN	BRADFORD WHITE	0
17698	03/22/2014	G75125	RUUD	0
17699	04/06/2014	PROG5038NRU58	RUUD	0
17700	04/08/2014	MI5036FBN	BRADFORD WHITE	0
17701	03/28/2014	MI40T6FBN	BRADFORD WHITE	0
17702	04/08/2014	M45036FBN	BRADFORD WHITE	0
17703	04/09/2014	MI40T6FBN	BRADFORD WHITE	0
17704	04/09/2014	MI403S6FBN	BRADFORD WHITE	0
17705	04/11/2014	M45036FBN	BRADFORD WHITE	0
17706	04/12/2014	M45036FBN	BRADFORD WHITE	0
17707	04/10/2014	MI403S6FBN	BRADFORD WHITE	2
17708	04/09/2014	PH2DV50F	RUUD	0
17709	04/07/2014	M45036FBN	BRADFORD WHITE	0
17710	04/11/2014	M45036FBN	BRADFORD WHITE	0
17711	04/07/2014	M440T6FBN	BRADFORD WHITE	0
17712	04/12/2014	MI5036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17713	04/15/2014	PROG5038NRU58	RUUD	0
17714	03/22/2014	M45036FBN	BRADFORD-WHITE	0
17715	03/15/2014	MI40T6FBN	BRADFORD-WHITE	0
17716	03/26/2014	M45036FBN	BRADFORD-WHITE	0
17717	03/25/2014	MI403S6FBN	BRADFORD-WHITE	0
17718	03/20/2014	MI5036FBN	BRADFORD-WHITE	0
17719	03/20/2014	M45036FBN	BRADFORD-WHITE	0
17720	03/24/2014	M45036FBN	BRADFORD-WHITE	0
17721	03/21/2014	M45036FBN	BRADFORD-WHITE	0
17722	03/22/2014	G75125	RUUD	0
17723	04/04/2014	MI5036FBN	Bradford White	0
17724	04/07/2014	MI5036FBN	Bradford White	1
17725	04/02/2014	MI40T6FBN	BRADFORD WHITE	0
17726	03/19/2014	G75125	RUUD/RHEEM	1
17727	11/04/2013	MI75S6FBN	BRADFORD-WHITE	4
17728	03/25/2014	G91200	RUUD/RHEEM	1
17729	03/17/2014	M45036FBN	BRADFORD-WHITE	0
17730	03/24/2014	MI40T6FBN	BRADFORD-WHITE	0
17731	03/20/2014	MI5036FBN	BRADFORD-WHITE	0
17732	03/23/2014	MI403S6FBN	BRADFORD-WHITE	0
17733	03/06/2014	MI5036FBN	BRADFORD-WHITE	1
17734	03/31/2014	MI5036FBN	BRADFORD-WHITE	0
17735	03/24/2014	M45036FBN	BRADFORD-WHITE	4
17736	03/28/2014	G75125	RUUD/RHEEM	2
17737	03/25/2014	M45036FBN	BRADFORD-WHITE	1
17738	03/27/2014	MI40T6FBN	BRADFORD-WHITE	0
17739	03/28/2014	MI5036FBN	BRADFORD-WHITE	0
17740	03/30/2014	G91200	RUUD/RHEEM	0
17741	03/31/2014	PH2DV50F	RUUD	0
17742	03/31/2014	M45036FBN	BRADFORD-WHITE	0
17743	03/23/2014	G82156	RUUD/RHEEM	0
17744	04/01/2014	MI404T6FBN	BRADFORD-WHITE	0
17745	04/01/2014	MI5036FBN	BRADFORD-WHITE	0
17746	04/01/2014	M45036FBN	BRADFORD-WHITE	0
17747	04/01/2014	PROG5038NRU58DV	RUUD	0
17748	04/03/2014	M45036FBN	BRADFORD-WHITE	0
17749	03/18/2014	MI5036FBN	BRADFORD-WHITE	0
17750	03/28/2014	MI5036FBN	BRADFORD-WHITE	0
17751	04/14/2014	M45036FBN	Bradford White	1
17752	04/11/2014	MI5036FBN	Bradford White	1
17753	04/11/2014	M45036FBN	Bradford White	0
17754	03/28/2014	M45036FBN	Bradford White	0
17755	03/28/2014	M45036FBN	Bradford White	0
17756	04/14/2014	G91200	RUUD/RHEEM	0
17757	04/02/2014	G91200	RUUD/RHEEM	0
17758	04/09/2014	M45036FBN	Bradford White	0
17759	04/08/2014	PROG5038NRU58	Ruud/Rheem	1
17760	04/08/2014	M45036FBN	Bradford White	0
17761	04/08/2014	M2XR504T6FBN	Bradford White	0
17762	03/25/2014	G91200	RUUD	0
17763	03/30/2014	M45036FBN	BRADFORD-WHITE	0
17764	04/07/2014	DS150S6FBN	BRADFORD-WHITE	0
17765	04/10/2014	MI5036FBN	BRADFORD-WHITE	0
17766	04/10/2014	MI403S6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17767	04/14/2014	G82156	RUUD/RHEEM	0
17768	04/13/2014	PH2DV50F	RUUD	0
17769	04/12/2014	MI5036FBN	BRADFORD-WHITE	0
17770	04/19/2014	MI5036FBN	BRADFORD-WHITE	0
17771	04/20/2014	G91200	RUUD/RHEEM	1
17772	04/21/2014	MI5036FBN	BRADFORD-WHITE	1
17773	04/12/2014	M45036FBN	BRADFORD-WHITE	0
17774	04/23/2014	M2XR504T6FBN	BRADFORD-WHITE	0
17775	04/22/2014	G91200	RUUD/RHEEM	3
17776	01/09/2014	M45036FBN	BRADFORD-WHITE	0
17777	04/18/2014	M45036FBN	BRADFORD-WHITE	0
17778	04/13/2014	M45036FBN	BRADFORD-WHITE	0
17779	04/22/2014	G76200	RUUD/RHEEM	1
17780	04/26/2014	MI5036FBN	BRADFORD-WHITE	0
17781	04/15/2014	MI50L6FBN	BRADFORD-WHITE	0
17782	04/25/2014	M45036FBN	BRADFORD-WHITE	0
17783	04/20/2014	MI40T6FBN	BRADFORD-WHITE	0
17784	05/06/2014	PH199119	PHOENIX	0
17785	05/09/2014	MI403S6FBN	Bradford White	0
17786	05/09/2014	MI5036FBN	Bradford White	0
17787	05/06/2014	M45036FBN	Bradford White	0
17788	05/09/2014	MI5036FBN	Bradford White	0
17789	04/18/2014	G82156	RUUD/RHEEM	0
17790	04/16/2014	M45036FBN	Bradford White	0
17791	04/16/2014	M45036FBN	BRADFORD WHITE	0
17792	04/14/2014	M45036FBN	BRADFORD WHITE	0
17793	04/11/2014	MI5036FBN	BRADFORD WHITE	0
17794	04/21/2014	MI40T6FBN	BRADFORD WHITE	0
17795	04/17/2014	M440T6FBN	Bradford White	0
17796	04/17/2014	G75125	RUUD	0
17797	04/11/2014	M45036FBN	BRADFORD WHITE	1
17798	04/17/2014	M45036FBN	Bradford White	0
17799	04/23/2014	MI403S6FBN	BRADFORD WHITE	0
17800	04/09/2014	M45036FBN	BRADFORD WHITE	1
17801	11/16/2013	M45036FBN	BRADFORD WHITE	0
17802	04/21/2014	MI40T6FBN	BRADFORD WHITE	0
17803	04/22/2014	M440T6FBN	BRADFORD WHITE	0
17804	04/25/2014	M45036FBN	BRADFORD WHITE	0
17805	04/24/2014	PROG2932NRU63	RUUD	0
17806	04/17/2014	MI40T6FBN	BRADFORD WHITE	0
17807	04/28/2014	M45036FBN	BRADFORD WHITE	0
17808	04/27/2014	PROG5038NRU58	RUUD	0
17809	04/11/2014	PH19980	PHOENIX	1
17810	04/22/2014	M45036FBN	Bradford White	0
17811	04/14/2014	MI40T6FBN	BRADFORD-WHITE	0
17812	04/23/2014	M45036FBN	Bradford White	0
17813	04/22/2014	M45036FBN	Bradford White	0
17814	04/15/2014	M45036FBN	Bradford White	0
17815	04/21/2014	M45036FBN	Bradford White	0
17816	04/18/2014	M45036FBN	Bradford White	1
17817	03/29/2014	M45036FBN	Bradford White	0
17818	05/05/2014	MI5036FBN	Bradford White	0
17819	04/19/2014	PROG5038NRU58DV	Ruud/Rheem	0
17820	05/02/2014	G82156	RUUD	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17821	04/29/2014	M45036FBN	BRADFORD WHITE	0
17822	04/30/2014	M45036FBN	BRADFORD WHITE	0
17823	04/25/2014	M45036FBN	BRADFORD WHITE	0
17824	05/06/2014	MI403S6FBN	BRADFORD-WHITE	0
17825	04/21/2014	G91200	RUUD/RHEEM	0
17826	05/07/2014	M45036FBN	BRADFORD-WHITE	0
17827	05/03/2014	PROG5038NRU58	RHEEM/RUUD	0
17828	05/01/2014	M45036FBN	BRADFORD WHITE	0
17829	05/21/2014	PROG5038NRU58DV	Ruud/Rheem	0
17830	05/13/2014	M45036FBN	Bradford White	0
17831	05/11/2014	MI5036FBN	Bradford White	0
17832	05/04/2014	MI5036FBN	BRADFORD WHITE	0
17833	05/01/2014	MI403S6FBN	BRADFORD WHITE	0
17834	04/12/2014	P230F	RUUD	1
17835	05/02/2014	M45036FBN	BRADFORD WHITE	0
17836	05/01/2014	M45036FBN	BRADFORD WHITE	0
17837	04/30/2014	MI40T6FBN	BRADFORD-WHITE	0
17838	04/30/2014	P230F	RHEEM / RUUD	0
17839	05/06/2014	M440T6FBN	BRADFORD-WHITE	0
17840	05/08/2014	PROG5038NRU58	RUUD	0
17841	04/26/2014	MI40T6FBN	BRADFORD-WHITE	0
17842	05/09/2014	M45036FBN	BRADFORD-WHITE	1
17843	05/03/2014	MI40T6FBN	BRADFORD-WHITE	0
17844	05/08/2014	MI5036FBN	BRADFORD-WHITE	0
17845	05/08/2014	M45036FBN	BRADFORD-WHITE	0
17846	05/07/2014	M45036FBN	BRADFORD-WHITE	0
17847	05/12/2014	M45036FBN	BRADFORD-WHITE	0
17848	05/10/2014	MI5036FBN	BRADFORD-WHITE	0
17849	05/06/2014	M45036FBN	BRADFORD-WHITE	1
17850	05/13/2014	M45036FBN	BRADFORD-WHITE	0
17851	05/13/2014	M440T6FBN	BRADFORD-WHITE	0
17852	05/04/2014	MI5036FBN	BRADFORD-WHITE	0
17853	05/13/2014	M440T6FBN	BRADFORD-WHITE	0
17854	05/14/2013	MI403S6FBN	BRADFORD-WHITE	0
17855	05/14/2014	G76200	RUUD/RHEEM	0
17856	05/02/2014	M45036FBN	BRADFORD-WHITE	0
17857	05/08/2014	MI40T6FBN	BRADFORD-WHITE	0
17858	04/24/2014	PROG5038NRU58DV	Ruud/Rheem	0
17859	04/30/2014	MI40T6FBN	Bradford White	0
17860	04/30/2014	MI5036FBN	Bradford White	0
17861	04/23/2014	MI5036FBN	Bradford White	1
17862	04/23/2014	M2XR504T6FBN	Bradford White	0
17863	04/28/2014	M2XR504T6FBN	BRADFORD WHITE	0
17864	04/19/2014	M45036FBN	BRADFORD WHITE	0
17865	03/12/2014	G91200	RUUD/RHEEM	0
17866	04/07/2014	MI40T6FBN	BRADFORD WHITE	0
17867	05/03/2014	G91200	Ruud/Rheem	1
17868	04/20/2014	MI50L6FBN	Bradford White	0
17869	05/03/2014	MI5036FBN	AO SMITH	0
17870	05/01/2014	MI403S6FBN	Bradford White	0
17871	05/01/2014	M45036FBN	Bradford White	0
17872	05/01/2014	G91200	RUUD/RHEEM	0
17873	05/01/2014	M45036FBN	Bradford White	0
17874	04/30/2014	MI5036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17875	05/05/2014	M45036FBN	Bradford White	0
17876	04/23/2014	MI5036FBN	Bradford White	0
17877	05/08/2014	M45036FBN	Bradford White	0
17878	05/08/2014	M440T6FBN	Bradford White	0
17879	05/12/2014	G91200	RUUD/RHEEM	0
17880	05/02/2014	M45036FBN	BRADFORD WHITE	0
17881	05/05/2014	M45036FBN	BRADFORD WHITE	0
17882	05/02/2014	G91200	RUUD	1
17883	05/08/2014	MI5036FBN	BRADFORD WHITE	0
17884	05/06/2014	MI5036FBN	BRADFORD WHITE	0
17885	05/08/2014	MI5036FBN	BRADFORD WHITE	0
17886	05/11/2014	PROG5038NRU58	RUUD	2
17887	05/12/2014	PROG5038NRU58	RUUD	0
17888	05/13/2014	M45036FBN	BRADFORD WHITE	0
17889	05/12/2014	M45036FBN	BRADFORD WHITE	1
17890	05/15/2014	G82156	RUUD/RHEEM	4
17891	05/14/2014	PROG5038NRU58	Rheem/Ruud	0
17892	05/15/2014	M45036FBN	Bradford White	0
17893	05/05/2014	M45036FBN	Bradford White	0
17894	04/22/2014	G82156	Rheem/Ruud	0
17895	05/20/2014	MI40T6FBN	Bradford White	0
17896	04/22/2014	G82156	RUUD	0
17897	05/16/2014	MI5036FBN	BRADFORD-WHITE	1
17898	05/21/2014	G91200	RUUD	0
17899	05/21/2014	MI75S6FBN	BRADFORD-WHITE	0
17900	05/20/2014	MI40S6FBN	BRADFORD-WHITE	0
17901	05/20/2014	M45036FBN	BRADFORD-WHITE	0
17902	05/21/2014	MI40T6FBN	BRADFORD-WHITE	0
17903	05/19/2014	MI5036FBN	BRADFORD-WHITE	2
17904	05/21/2014	M45036FBN	Bradford White	1
17905	05/19/2014	MI5036FBN	Bradford White	0
17906	05/16/2014	G91200	Rheem/Ruud	0
17907	05/15/2014	M45036FBN	Bradford White	1
17908	05/14/2014	M45036FBN	Bradford White	0
17909	05/27/2014	G91200	RUUD/RHEEM	1
17910	05/14/2014	G76200	Rheem/Ruud	2
17911	05/20/2014	MI50L6FBN	Bradford White	0
17912	05/28/2014	MI5036FBN	Bradford White	0
17913	05/28/2014	M440T6FBN	Bradford White	0
17914	05/22/2014	MI5036FBN	Bradford White	0
17915	05/24/2014	M440T6FBN	Bradford White	0
17916	05/23/2014	M440T6FBN	Bradford White	0
17917	05/28/2014	G91200	RUUD	3
17918	05/14/2014	G91200	RUUD	0
17919	05/22/2014	PROG5038NRU58	RUUD	0
17920	05/28/2014	MI5036FBN	BRADFORD-WHITE	0
17921	05/11/2014	PH2DV50F	RUUD	0
17922	06/03/2014	M45036FBN	BRADFORD-WHITE	0
17923	06/02/2014	MI5036FBN	BRADFORD-WHITE	0
17924	06/05/2014	G82156	RUUD	0
17925	06/02/2014	M45036FBN	BRADFORD-WHITE	0
17926	05/20/2014	PROG5038NRU58	RUUD	0
17927	05/12/2014	PH2DV50F	Rheem/Ruud	0
17928	05/13/2014	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17929	05/11/2014	M45036FBN	BRADFORD-WHITE	1
17930	05/14/2014	M45036FBN	BRADFORD WHITE	0
17931	05/19/2014	M45036FBN	BRADFORD WHITE	0
17932	05/15/2014	PROG5038NRU58	RUUD	0
17933	05/15/2014	G76200	RUUD	0
17934	06/05/2014	M45036FBN	Bradford White	0
17935	05/13/2014	M45036FBN	Bradford White	0
17936	05/02/2014	MI5036FBN	Bradford White	0
17937	05/22/2014	M2XR504T6FBN	BRADFORD WHITE	0
17938	05/27/2014	M45036FBN	BRADFORD WHITE	0
17939	05/08/2014	M45036FBN	BRADFORD WHITE	0
17940	05/12/2014	G91200	RUUD	1
17941	05/22/2014	M45036FBN	BRADFORD WHITE	2
17942	05/27/2014	MI5036FBN	BRADFORD WHITE	0
17943	05/11/2014	PROG5038NRU58	RUUD	0
17944	05/28/2014	G100200	RUUD	0
17945	05/29/2014	DS140S6FBN	BRADFORD WHITE	0
17946	06/03/2014	MI5036FBN	BRADFORD WHITE	0
17947	06/03/2014	M45036FBN	BRADFORD WHITE	0
17948	05/31/2014	MI5036FBN	BRADFORD WHITE	0
17949	05/27/2014	M45036FBN	BRADFORD WHITE	0
17950	06/03/2014	M45036FBN	BRADFORD WHITE	0
17951	06/02/2014	M45036FBN	BRADFORD WHITE	0
17952	05/07/2014	MI5036FBN	BRADFORD WHITE	0
17953	06/05/2014	M45036FBN	Bradford White	0
17954	06/03/2014	MI5036FBN	Bradford White	0
17955	05/23/2014	M45036FBN	BRADFORD-WHITE	0
17956	05/22/2014	M45036FBN	BRADFORD-WHITE	0
17957	05/27/2014	DS140S6FBN	BRADFORD-WHITE	1
17958	05/19/2014	MI5036FBN	BRADFORD-WHITE	1
17959	06/02/2014	M45036FBN	Bradford White	0
17960	05/30/2014	M45036FBN	Bradford White	0
17961	05/22/2014	MI40T6FBN	Bradford White	0
17962	06/02/2014	MI403S6FBN	Bradford White	0
17963	06/05/2014	M45036FBN	Bradford White	0
17964	05/07/2014	MI5036FBN	Bradford White	1
17965	06/03/2014	G82156	Ruud/Rheem	0
17966	05/19/2014	G91200	RUUD/RHEEM	3
17967	05/31/2014	PH2DV50F	Ruud/Rheem	0
17968	06/06/2014	G91200	RUUD/RHEEM	0
17969	06/03/2014	MI403S6FBN	BRADFORD-WHITE	0
17970	06/01/2014	G91200	RUUD	0
17971	06/04/2014	M2XR504T6FBN	BRADFORD-WHITE	0
17972	05/21/2014	M440T6FBN	BRADFORD-WHITE	0
17973	06/05/2014	RF82156	Ruud/Rheem	0
17974	06/05/2014	M45036FBN	Bradford White	0
17975	06/04/2014	MI403S6FBN	Bradford White	0
17976	06/05/2014	M45036FBN	Bradford White	0
17977	05/31/2014	MI5036FBN	Bradford White	0
17978	06/11/2014	M45036FBN	Bradford White	1
17979	06/06/2014	MI5036FBN	BRADFORD WHITE	1
17980	05/24/2014	MI5036FBN	BRADFORD-WHITE	0
17981	04/15/2014	G82156	RUUD/RHEEM	0
17982	06/04/2014	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
17983	06/08/2014	MI5036FBN	BRADFORD-WHITE	0
17984	05/28/2014	M45036FBN	BRADFORD WHITE	0
17985	05/27/2014	M45036FBN	BRADFORD WHITE	0
17986	06/03/2014	PROG5038NRU58	RUUD	0
17987	06/02/2014	MI403S6FBN	BRADFORD WHITE	0
17988	06/10/2014	G75125	RUUD/RHEEM	4
17989	06/12/2014	M45036FBN	BRADFORD WHITE	0
17990	06/10/2014	MI403S6FBN	BRADFORD WHITE	0
17991	06/13/2014	G75125	RUUD/RHEEM	0
17992	06/10/2014	PROG5038NRU58DV	Bradford White	0
17993	06/12/2014	G100200	STATE	0
17994	05/27/2014	M2XR504T6FBN	Bradford White	0
17995	06/06/2014	PROG5038NRU58DV	Ruud/Rheem	0
17996	06/13/2014	M45036FBN	Bradford White	0
17997	06/12/2014	MI40T6FBN	Bradford White	0
17998	06/13/2014	M45036FBN	Bradford White	0
17999	06/02/2014	M440T6FBN	BRADFORD-WHITE	2
18000	06/12/2014	M45036FBN	BRADFORD WHITE	0
18001	06/05/2014	M45036FBN	BRADFORD-WHITE	0
18002	06/10/2014	M45036FBN	BRADFORD-WHITE	0
18003	06/13/2014	MI5036FBN	BRADFORD-WHITE	1
18004	06/18/2014	G91200	RUUD/RHEEM	0
18005	06/16/2014	PROG5038NRU58DV	Ruud/Rheem	1
18006	06/12/2014	MI5036FBN	BRADFORD-WHITE	0
18007	06/16/2014	M440T6FBN	Bradford White	0
18008	06/10/2014	MI40T6FBN	BRADFORD-WHITE	1
18009	06/19/2014	M45036FBN	Bradford White	0
18010	06/16/2014	MI5036FBN	BRADFORD-WHITE	0
18011	06/18/2014	MI5036FBN	BRADFORD-WHITE	0
18012	06/17/2014	M45036FBN	BRADFORD-WHITE	0
18013	06/18/2014	MI75S6FBN	BRADFORD-WHITE	0
18014	06/14/2014	M45036FBN	BRADFORD-WHITE	0
18015	06/17/2014	MI5036FBN	BRADFORD-WHITE	1
18016	06/13/2014	M45036FBN	BRADFORD-WHITE	0
18017	06/16/2014	MI5036FBN	BRADFORD-WHITE	0
18018	06/18/2014	MI5036FBN	Bradford White	0
18019	06/13/2014	MI50L6FBN	BRADFORD-WHITE	0
18020	06/14/2014	M45036FBN	Bradford White	0
18021	06/17/2014	G91200	Rheem/Ruud	0
18022	06/16/2014	MI5036FBN	Bradford White	1
18023	06/13/2014	MI5036FBN	BRADFORD-WHITE	0
18024	06/20/2014	G91200	RUUD/RHEEM	2
18025	06/02/2014	MI5036FBN	BRADFORD WHITE	0
18026	05/29/2014	MI5036FBN	BRADFORD WHITE	0
18027	06/19/2014	M45036FBN	BRADFORD WHITE	1
18028	06/19/2014	MI40T6FBN	BRADFORD WHITE	0
18029	06/19/2014	MI5036FBN	BRADFORD WHITE	0
18030	06/17/2014	MI5036FBN	BRADFORD WHITE	0
18031	06/18/2014	PROG5038NRU58	RUUD	1
18032	06/16/2014	M45036FBN	BRADFORD WHITE	0
18033	06/12/2014	MI5036FBN	BRADFORD WHITE	0
18034	06/24/2014	PROG2932NRU62	RUUD	0
18035	06/25/2014	MI5036FBN	BRADFORD WHITE	0
18036	06/10/2014	MI40T6FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18037	06/17/2014	M45036FBN	BRADFORD-WHITE	0
18038	06/21/2014	DS150S6FBN	BRADFORD WHITE	0
18039	06/26/2014	PROG5038NRU58	RUUD	0
18040	06/17/2014	M45036FBN	BRADFORD WHITE	1
18041	06/26/2014	M45036FBN	BRADFORD WHITE	1
18042	06/25/2014	MI5036FBN	BRADFORD WHITE	0
18043	06/15/2014	M45036FBN	BRADFORD WHITE	0
18044	06/21/2014	MI5036FBN	BRADFORD WHITE	0
18045	06/12/2014	PROG2932NRU62	RHEEM/RUUD	0
18046	06/28/2014	M440T6FBN	BRADFORD-WHITE	0
18047	06/27/2014	MI40T6FBN	BRADFORD-WHITE	0
18048	06/24/2014	MI40T6FBN	BRADFORD-WHITE	0
18049	06/23/2014	MI5036FBN	BRADFORD-WHITE	0
18050	05/17/2014	G91200	RUUD/RHEEM	0
18051	06/23/2014	PROG5038NRU58	RUUD / RHEEM	0
18052	06/26/2014	M45036FBN	BRADFORD-WHITE	0
18053	06/26/2014	M45036FBN	Bradford White	0
18054	06/23/2014	G82156	Rheem/Ruud	0
18055	06/24/2014	MI5036FBN	Bradford White	0
18056	06/26/2014	MI5036FBN	Bradford White	0
18057	06/21/2014	MI5036FBN	Bradford White	0
18058	06/24/2014	PROG5038NRU58	Rheem/Ruud	0
18059	06/26/2014	M45036FBN	Bradford White	0
18060	06/20/2014	M440T6FBN	Bradford White	0
18061	06/22/2014	G82156	RUUD/RHEEM	0
18062	06/21/2014	M45036FBN	Bradford White	1
18063	06/23/2014	MI5036FBN	BRADFORD-WHITE	0
18064	06/30/2014	M45036FBN	BRADFORD-WHITE	0
18065	06/28/2014	P230F	RUUD	0
18066	06/19/2014	M45036FBN	BRADFORD-WHITE	1
18067	06/24/2014	G91200	RUUD/RHEEM	0
18068	06/24/2014	MI403S6FBN	BRADFORD-WHITE	0
18069	06/25/2014	M45036FBN	BRADFORD-WHITE	0
18070	06/21/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18071	07/17/2014	MI5036FBN	BRADFORD-WHITE	0
18072	07/08/2014	M45036FBN	BRADFORD-WHITE	0
18073	07/08/2014	MI5036FBN	BRADFORD-WHITE	0
18074	07/07/2014	MI5036FBN	BRADFORD-WHITE	0
18075	07/07/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18076	07/22/2014	MI40T6FBN	Bradford White	0
18077	07/03/2014	MI5036FBN	Bradford White	0
18078	07/08/2014	MI5036FBN	Bradford White	0
18079	07/03/2014	M45036FBN	Bradford White	0
18080	07/03/2014	MI5036FBN	BRADFORD WHITE	0
18081	07/01/2014	G75125	RUUD	0
18082	07/01/2014	PROG5038NRU58	RUUD	1
18083	07/01/2014	PROG5038NRU58	RUUD	0
18084	07/07/2014	MI5036FBN	BRADFORD WHITE	1
18085	07/01/2014	MI5036FBN	BRADFORD WHITE	0
18086	07/03/2014	MI5036FBN	Bradford White	0
18087	07/15/2014	M45036FBN	Bradford White	0
18088	07/14/2014	M45036FBN	Bradford White	0
18089	07/17/2014	G91200	RUUD/RHEEM	1
18090	07/17/2014	M45036FBN	Bradford White	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18091	07/16/2014	M440T6FBN	Bradford White	0
18092	07/17/2014	MI40T6FBN	Bradford White	0
18093	07/19/2014	MI5036FBN	Bradford White	0
18094	07/21/2014	PROG5038NRU58	Rheem/Ruud	0
18095	07/17/2014	G91200	RUUD/RHEEM	0
18096	07/23/2014	MI75S6FBN	BRADFORD-WHITE	0
18097	07/05/2014	M45036FBN	BRADFORD-WHITE	0
18098	07/18/2014	M45036FBN	Bradford White	0
18099	07/23/2014	MI40T6FBN	Bradford White	0
18100	07/24/2014	MI403S6FBN	Bradford White	0
18101	07/22/2014	MI403S6FBN	BRADFORD-WHITE	0
18102	07/23/2014	M45036FBN	Bradford White	0
18103	07/27/2014	MI5036FBN	BRADFORD-WHITE	0
18104	07/22/2014	M440T6FBN	BRADFORD-WHITE	0
18105	07/28/2014	PROG5038NRU58	RUUD	0
18106	07/28/2014	PROG5038NRU58	RUUD	0
18107	07/26/2014	M440T6FBN	BRADFORD-WHITE	1
18108	07/28/2014	M45036FBN	BRADFORD-WHITE	0
18109	07/14/2014	MI403S6FBN	Bradford White	0
18110	07/25/2014	FSGL40	AO SMITH	0
18111	06/11/2014	MI5036FBN	BRADFORD-WHITE	0
18112	07/30/2014	M45036FBN	BRADFORD-WHITE	1
18113	07/26/2014	DS140S6FBN	BRADFORD-WHITE	0
18114	08/01/2014	M45036FBN	BRADFORD-WHITE	0
18115	08/14/2014	MI5036FBN	BRADFORD-WHITE	0
18116	07/22/2014	MI5036FBN	Bradford White	0
18117	07/28/2014	M45036FBN	Bradford White	0
18118	07/25/2014	M440T6FBN	Bradford White	1
18119	07/28/2014	M45036FBN	Bradford White	0
18120	07/31/2014	M45036FBN	Bradford White	0
18121	07/18/2014	MI75S6FBN	Bradford White	0
18122	06/29/2014	M440T6FBN	Bradford White	0
18123	07/01/2014	MI403S6FBN	Bradford White	0
18124	07/01/2014	PROG5038NRU58	Rheem/Ruud	0
18125	07/01/2014	PROG5038NRU58	Rheem/Ruud	0
18126	07/07/2014	M45036FBN	Bradford White	0
18127	07/09/2014	MI40T6FBN	Bradford White	0
18128	07/15/2014	G82156	RUUD/RHEEM	3
18129	07/07/2014	MI403S6FBN	Bradford White	0
18130	07/15/2014	M2XR504T6FBN	RHEEM	0
18131	07/08/2014	MI5036FBN	Bradford White	0
18132	07/09/2014	M45036FBN	Bradford White	0
18133	06/24/2014	MI50L6FBN	BRADFORD-WHITE	0
18134	07/10/2014	M45036FBN	Bradford White	0
18135	07/11/2014	MI5036FBN	Bradford White	0
18136	07/15/2014	MI403S6FBN	BRADFORD WHITE	0
18137	07/09/2014	M45036FBN	BRADFORD WHITE	0
18138	07/10/2014	M45036FBN	BRADFORD WHITE	0
18139	07/10/2014	MI5036FBN	BRADFORD WHITE	0
18140	07/15/2014	G76200	RUUD	3
18141	07/01/2014	PH13080	PHOENIX	5
18142	07/08/2014	M2XR504T6FBN	BRADFORD WHITE	0
18143	07/08/2014	MI40T6FBN	BRADFORD WHITE	0
18144	07/16/2014	PROG5038NRU58	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18145	07/02/2014	MI50L6FBN	BRADFORD-WHITE	0
18146	07/07/2014	M45036FBN	BRADFORD-WHITE	0
18147	06/14/2014	M45036FBN	BRADFORD-WHITE	0
18148	07/01/2014	MI5036FBN	BRADFORD-WHITE	0
18149	07/03/2014	M45036FBN	BRADFORD-WHITE	1
18150	07/01/2014	G75125	RUUD/RHEEM	0
18151	07/01/2014	MI40T6FBN	BRADFORD-WHITE	0
18152	06/14/2014	MI5036FBN	BRADFORD-WHITE	0
18153	07/02/2014	MI5036FBN	BRADFORD-WHITE	1
18154	07/05/2014	DS150S6FBN	BRADFORD-WHITE	0
18155	07/10/2014	M45036FBN	BRADFORD-WHITE	0
18156	07/15/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18157	07/14/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18158	07/17/2014	PROG5038NRU58	RUUD	1
18159	07/18/2014	MI5036FBN	BRADFORD WHITE	1
18160	07/15/2014	MI5036FBN	BRADFORD WHITE	0
18161	07/21/2014	G91200	RUUD	2
18162	07/23/2014	M45036FBN	BRADFORD WHITE	0
18163	07/23/2014	MI75S6FBN	BRADFORD WHITE	0
18164	07/23/2014	MI40T6FBN	BRADFORD WHITE	0
18165	07/17/2014	MI5036FBN	BRADFORD WHITE	0
18166	07/23/2014	M440T6FBN	BRADFORD WHITE	0
18167	07/20/2014	PROG5038NRU58	RUUD	0
18168	07/25/2014	MI5036FBN	BRADFORD WHITE	0
18169	07/08/2014	MI403S6FBN	BRADFORD WHITE	0
18170	07/25/2014	MI5036FBN	BRADFORD WHITE	0
18171	07/28/2014	MI5036FBN	BRADFORD WHITE	0
18172	07/28/2014	DS140S6FBN	BRADFORD WHITE	0
18173	07/09/2014	DS140S6FBN	BRADFORD-WHITE	0
18174	07/05/2014	MI5036FBN	BRADFORD-WHITE	0
18175	07/17/2014	G100200	RUUD	5
18176	07/16/2014	MI403S6FBN	BRADFORD-WHITE	0
18177	07/18/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18178	07/15/2014	M45036FBN	BRADFORD-WHITE	0
18179	07/21/2014	M45036FBN	BRADFORD-WHITE	0
18180	07/20/2014	M45036FBN	BRADFORD-WHITE	0
18181	07/21/2014	G91200	RUUD	0
18182	07/13/2014	MI5036FBN	BRADFORD-WHITE	0
18183	07/24/2014	MI40T6FBN	BRADFORD-WHITE	0
18184	07/30/2014	MI5036FBN	BRADFORD WHITE	0
18185	07/23/2014	MI5036FBN	BRADFORD WHITE	0
18186	07/28/2014	MI403S6FBN	BRADFORD WHITE	0
18187	07/28/2014	M45036FBN	BRADFORD WHITE	0
18188	07/31/2014	G75125	RUUD	0
18189	07/25/2014	M45036FBN	BRADFORD WHITE	0
18190	07/31/2014	MI5036FBN	BRADFORD WHITE	0
18191	08/05/2014	M45036FBN	BRADFORD WHITE	0
18192	08/01/2014	G82156	RUUD	0
18193	08/02/2014	M45036FBN	BRADFORD WHITE	0
18194	08/06/2014	M2XR504T6FBN	BRADFORD WHITE	0
18195	08/06/2014	G75125	RUUD	2
18196	07/31/2014	M45036FBN	BRADFORD WHITE	0
18197	08/05/2014	MI5036FBN	BRADFORD WHITE	3
18198	07/24/2014	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18199	08/05/2014	M45036FBN	BRADFORD WHITE	0
18200	08/01/2014	G75125	RUUD/RHEEM	0
18201	07/29/2014	M45036FBN	BRADFORD-WHITE	0
18202	08/04/2014	M45036FBN	BRADFORD-WHITE	0
18203	08/04/2014	MI40T6FBN	BRADFORD-WHITE	0
18204	08/04/2014	DS140S6FBN	BRADFORD-WHITE	2
18205	07/30/2014	M45036FBN	Bradford White	0
18206	07/30/2014	PROG5038NRU58DV	RUUD	0
18207	07/26/2014	MI5036FBN	Bradford White	0
18208	07/26/2014	MI5036FBN	BRADFORD-WHITE	0
18209	05/29/2014	G82156	Ruud/Rheem	0
18210	07/31/2014	MI40T6FBN	Bradford White	0
18211	07/30/2014	M45036FBN	Bradford White	0
18212	08/05/2014	FSG50	AO SMITH	0
18213	08/07/2014	MI5036FBN	Bradford White	0
18214	08/04/2014	M45036FBN	Bradford White	0
18215	06/28/2014	M45036FBN	Bradford White	0
18216	08/01/2014	PROG5038NRU58DV	Ruud/Rheem	0
18217	08/05/2014	MI5036FBN	Bradford White	0
18218	08/06/2014	MI40T6FBN	Bradford White	0
18219	07/05/2014	M45036FBN	Bradford White	0
18220	08/02/2014	PROG5038NRU58DV	Ruud/Rheem	0
18221	08/04/2014	MI40T6FBN	Bradford White	0
18222	08/08/2014	MI403S6FBN	Bradford White	0
18223	08/08/2014	MI403S6FBN	Bradford White	0
18224	08/11/2014	PROG5038NRU58DV	Ruud/Rheem	1
18225	08/09/2014	MI5036FBN	BRADFORD-WHITE	0
18226	08/11/2014	MI5036FBN	Bradford White	0
18227	08/04/2014	MI5036FBN	Bradford White	0
18228	08/12/2014	M45036FBN	BRADFORD-WHITE	0
18229	07/24/2014	M45036FBN	BRADFORD-WHITE	0
18230	08/07/2014	MI5036FBN	BRADFORD-WHITE	0
18231	08/11/2014	M45036FBN	BRADFORD-WHITE	0
18232	08/05/2014	M45036FBN	BRADFORD-WHITE	0
18233	08/08/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18234	07/08/2014	G82156	RUUD	1
18235	08/13/2014	MI5036FBN	BRADFORD WHITE	0
18236	07/31/2014	MI50L6FBN	BRADFORD WHITE	0
18237	08/05/2014	M45036FBN	BRADFORD WHITE	0
18238	08/01/2014	M45036FBN	BRADFORD WHITE	0
18239	08/05/2014	MI5036FBN	BRADFORD WHITE	0
18240	09/03/2014	PROG5038NRU58DV	Rheem	1
18241	08/12/2014	G82156	RUUD/RHEEM	1
18242	08/12/2014	M45036FBN	Bradford White	0
18243	08/17/2014	PROG5038NRU58DV	Rheem/Ruud	0
18244	08/14/2014	M45036FBN	BRADFORD WHITE	0
18245	08/14/2014	PROG5038NRU58DV	RUUD	1
18246	08/11/2014	M45036FBN	BRADFORD WHITE	1
18247	08/14/2014	M45036FBN	BRADFORD WHITE	0
18248	08/12/2014	M45036FBN	BRADFORD WHITE	0
18249	08/19/2014	M45036FBN	BRADFORD WHITE	0
18250	08/12/2014	MI40T6FBN	BRADFORD WHITE	0
18251	08/10/2014	MI40T6FBN	BRADFORD WHITE	0
18252	08/22/2014	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18253	08/21/2014	MI5036FBN	BRADFORD WHITE	0
18254	06/01/2014	MI5036FBN	BRADFORD WHITE	0
18255	08/19/2014	M440T6FBN	BRADFORD WHITE	1
18256	09/08/2014	M45036FBN	Bradford White	0
18257	08/15/2014	DS150S6FBN	BRADFORD-WHITE	0
18258	09/23/2014	MI5036FBN	Bradford White	0
18259	08/19/2014	M45036FBN	Bradford White	1
18260	08/27/2014	G82156	RUUD	1
18261	08/22/2014	MI5036FBN	BRADFORD WHITE	0
18262	08/12/2014	PROG5038NRU58DV	RUUD	3
18263	08/17/2014	M45036FBN	BRADFORD WHITE	0
18264	08/05/2014	M2XR504T6FBN	BRADFORD WHITE	0
18265	08/18/2014	G91200	RUUD	0
18266	07/21/2014	MI5036FBN	BRADFORD WHITE	0
18267	08/09/2014	PROG5038NRU58DV	RUUD	0
18268	08/25/2014	MI50L6FBN	BRADFORD WHITE	0
18269	08/22/2014	M45036FBN	BRADFORD WHITE	0
18270	08/19/2014	PROG5038NRU58	Rheem/Ruud	0
18271	08/14/2014	M440T6FBN	Bradford White	0
18272	08/25/2014	PROG5038NRU58	Rheem/Ruud	0
18273	08/22/2014	MI75S6FBN	Bradford White	0
18274	08/18/2014	M440T6FBN	Bradford White	0
18275	08/08/2014	MI403S6FBN	Bradford White	0
18276	08/15/2014	G91200	RUUD/RHEEM	0
18277	08/22/2014	M45036FBN	BRADFORD WHITE	0
18278	08/27/2014	MI5036FBN	BRADFORD WHITE	0
18279	08/28/2014	M45036FBN	BRADFORD WHITE	0
18280	08/31/2014	M45036FBN	BRADFORD WHITE	0
18281	08/20/2014	PROG5038NRU58DV	RUUD	0
18282	08/15/2014	G91200	RUUD	0
18283	08/08/2014	G91200	RUUD	0
18284	08/12/2014	M45036FBN	BRADFORD WHITE	0
18285	08/14/2014	G82156	RUUD	1
18286	09/04/2014	M45036FBN	BRADFORD WHITE	0
18287	09/04/2014	MI5036FBN	BRADFORD WHITE	0
18288	09/04/2014	MI5036FBN	BRADFORD WHITE	0
18289	09/03/2014	M45036FBN	BRADFORD WHITE	0
18290	08/12/2014	G82156	RUUD	0
18291	08/16/2014	PROG5038NRU58	RUUD	0
18292	09/08/2014	PROG5038NRU58DV	RUUD	0
18293	08/16/2014	MI40T6FBN	BRADFORD-WHITE	1
18294	08/13/2014	PROG5038NRU58DV	RUUD	0
18295	09/09/2014	M45036FBN	BRADFORD WHITE	0
18296	08/29/2014	M45036FBN	BRADFORD WHITE	0
18297	09/03/2014	MI5036FBN	BRADFORD WHITE	0
18298	09/04/2014	PROG5038NRU58DV	RUUD	0
18299	09/09/2014	PROG5038NRU58DV	RUUD	0
18300	09/12/2014	G91200	RUUD	0
18301	09/12/2014	PROG2932NRU62	RUUD	0
18302	08/15/2014	PROG5038NRU58	RUUD	1
18303	09/10/2014	MI5036FBN	BRADFORD WHITE	0
18304	09/09/2014	MI5036FBN	BRADFORD WHITE	0
18305	08/13/2014	MI5036FBN	BRADFORD-WHITE	0
18306	08/19/2014	M45036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18307	08/19/2014	MI5036FBN	BRADFORD-WHITE	0
18308	08/14/2014	PROG5038NRU58	RUUD	0
18309	08/12/2014	DS140S6FBN	BRADFORD-WHITE	0
18310	08/07/2014	M45036FBN	BRADFORD-WHITE	0
18311	08/12/2014	MI5036FBN	BRADFORD-WHITE	0
18312	08/05/2014	G91200	RUUD	1
18313	08/15/2014	MI50L6FBN	BRADFORD WHITE	0
18314	08/18/2014	MI403S6FBN	BRADFORD WHITE	0
18315	08/21/2014	MI40T6FBN	BRADFORD WHITE	0
18316	08/05/2014	MI50L6FBN	BRADFORD WHITE	0
18317	08/17/2014	M45036FBN	BRADFORD WHITE	0
18318	08/13/2014	M45036FBN	BRADFORD WHITE	0
18319	09/25/2014	M440T6FBN	Bradford White	0
18320	08/22/2014	M45036FBN	Bradford White	0
18321	08/20/2014	G91200	Rheem/Ruud	0
18322	07/14/2014	MI75S6FBN	Bradford White	0
18323	07/30/2014	MI75S6FBN	Bradford White	0
18324	08/25/2014	MI40T6FBN	Bradford White	1
18325	08/24/2014	M45036FBN	Bradford White	0
18326	08/26/2014	PROG5038NRU58DV	Rheem/Ruud	0
18327	08/22/2014	MI40T6FBN	BRADFORD-WHITE	0
18328	08/18/2014	M45036FBN	BRADFORD-WHITE	0
18329	08/27/2014	MI5036FBN	BRADFORD-WHITE	0
18330	08/28/2014	PROG5038NRU58DV	RUUD	0
18331	08/19/2014	MI5036FBN	BRADFORD-WHITE	0
18332	08/25/2014	M45036FBN	BRADFORD-WHITE	1
18333	08/19/2014	M45036FBN	BRADFORD-WHITE	0
18334	08/08/2014	G91200	RUUD/RHEEM	0
18335	09/02/2014	M45036FBN	BRADFORD-WHITE	0
18336	08/27/2014	M45036FBN	Bradford White	0
18337	08/27/2014	MI50L6FBN	Bradford White	0
18338	08/27/2014	M440T6FBN	Bradford White	0
18339	08/13/2014	PROG5038NRU58DV	Bradford White	0
18340	08/30/2014	G91200	RUUD/RHEEM	0
18341	08/27/2014	M45036FBN	Bradford White	0
18342	08/29/2014	M45036FBN	Bradford White	0
18343	08/29/2014	M45036FBN	Bradford White	0
18344	08/29/2014	M45036FBN	Bradford White	1
18345	08/26/2014	G75125	RUUD/RHEEM	3
18346	09/04/2014	M2XR504T6FBN	BRADFORD WHITE	0
18347	09/05/2014	G76200	RUUD/RHEEM	0
18348	09/05/2014	M45036FBN	BRADFORD WHITE	0
18349	09/06/2014	MI5036FBN	BRADFORD WHITE	0
18350	09/10/2014	M45036FBN	BRADFORD WHITE	0
18351	09/02/2014	G91200	RUUD/RHEEM	0
18352	09/07/2014	MI40T6FBN	BRADFORD WHITE	1
18353	08/21/2014	MI75S6FBN	BRADFORD WHITE	0
18354	09/01/2014	PROG5038NRU58DV	Rheem/Ruud	0
18355	09/01/2014	MI5036FBN	Bradford White	1
18356	08/28/2014	MI5036FBN	Bradford White	2
18357	08/28/2014	M45036FBN	Bradford White	0
18358	08/29/2014	PROG5038NRU58DV	RUUD	0
18359	08/29/2014	MI5036FBN	BRADFORD WHITE	0
18360	09/03/2014	PROG2932NRU62	Rheem/Ruud	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18361	09/05/2014	M45036FBN	Bradford White	0
18362	07/08/2014	G75125	RHEEM	2
18363	09/11/2014	PROG5038NRU58DV	RUUD/RHEEM	1
18364	09/10/2014	MI5036FBN	BRADFORD WHITE	0
18365	09/16/2014	MI5036FBN	BRADFORD WHITE	0
18366	09/04/2014	M45036FBN	BRADFORD WHITE	0
18367	09/14/2014	M45036FBN	BRADFORD WHITE	0
18368	09/13/2014	M45036FBN	BRADFORD WHITE	0
18369	09/02/2014	MI50L6FBN	BRADFORD WHITE	0
18370	09/10/2014	PROG5038NRU58DV	RUUD	0
18371	09/12/2014	MI5036FBN	BRADFORD WHITE	0
18372	09/13/2014	M2XR504T6FBN	BRADFORD WHITE	1
18373	09/18/2014	MI5036FBN	BRADFORD WHITE	0
18374	09/13/2014	MI5036FBN	BRADFORD WHITE	0
18375	09/10/2014	PROG5038NRU58DV	Rheem/Ruud	0
18376	09/02/2014	MI40T6FBN	Bradford White	2
18377	09/18/2014	M45036FBN	BRADFORD WHITE	1
18378	09/21/2014	MI5036FBN	BRADFORD WHITE	0
18379	09/19/2014	PROG5038NRU58DV	RUUD	0
18380	09/22/2014	G76200	RUUD	0
18381	09/23/2014	M45036FBN	BRADFORD WHITE	0
18382	09/24/2014	M45036FBN	BRADFORD WHITE	0
18383	09/12/2014	M45036FBN	BRADFORD WHITE	0
18384	09/16/2014	M45036FBN	BRADFORD WHITE	0
18385	09/06/2014	MI5036FBN	BRADFORD WHITE	1
18386	09/22/2014	MI5036FBN	BRADFORD WHITE	0
18387	08/13/2014	M45036FBN	Bradford White	0
18388	09/05/2014	M45036FBN	Bradford White	0
18389	09/10/2014	M440T6FBN	Bradford White	0
18390	09/15/2014	M45036FBN	Bradford White	0
18391	09/16/2014	XVR50	A. O. SMITH	0
18392	09/09/2014	MI5036FBN	Bradford White	0
18393	09/11/2014	PROG5038NRU58DV	Rheem/Ruud	0
18394	09/18/2014	M440T6FBN	Bradford White	0
18395	03/23/2007	LTN050G	LOCHINVAR	0
18396	10/07/2014	MI5036FBN	Bradford White	0
18397	08/27/2014	G91200	RUUD/RHEEM	2
18398	09/07/2014	MI5036FBN	Bradford White	0
18399	09/17/2014	M45036FBN	BRADFORD-WHITE	0
18400	09/18/2014	MI403S6FBN	BRADFORD-WHITE	1
18401	09/19/2014	MI5036FBN	BRADFORD WHITE	0
18402	09/20/2014	MI5036FBN	BRADFORD WHITE	0
18403	09/22/2014	PROG5038NRU58DV	RUUD	0
18404	09/22/2014	G75125	RUUD/RHEEM	4
18405	09/24/2014	M45036FBN	BRADFORD WHITE	0
18406	08/14/2014	M45036FBN	BRADFORD WHITE	0
18407	09/13/2014	MI5036FBN	BRADFORD WHITE	0
18408	09/08/2014	MI40T6FBN	BRADFORD WHITE	0
18409	09/12/2014	P506	BRADFORD WHITE	0
18410	09/16/2014	MI40T6FBN	BRADFORD WHITE	0
18411	09/16/2014	MI5036FBN	Bradford White	0
18412	09/25/2014	MI40T6FBN	BRADFORD WHITE	0
18413	09/25/2014	MI40T6FBN	BRADFORD WHITE	0
18414	09/03/2014	MI40T6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18415	09/12/2014	MI5036FBN	BRADFORD WHITE	0
18416	09/10/2014	MI40T6FBN	Bradford White	0
18417	09/19/2014	MI40T6FBN	Bradford White	1
18418	09/22/2014	PROG5038NRU58DV	Rheem/Ruud	0
18419	09/22/2014	M45036FBN	Bradford White	0
18420	09/23/2014	MI40T6FBN	Bradford White	0
18421	09/19/2014	G82156	RUUD/RHEEM	1
18422	09/25/2014	M45036FBN	BRADFORD WHITE	0
18423	09/28/2014	MI5036FBN	BRADFORD WHITE	0
18424	09/29/2014	MI5036FBN	BRADFORD WHITE	0
18425	09/27/2014	M440T6FBN	BRADFORD WHITE	0
18426	09/25/2014	M45036FBN	BRADFORD WHITE	0
18427	09/26/2014	MI5036FBN	BRADFORD WHITE	1
18428	09/29/2014	G75125	RUUD/RHEEM	2
18429	09/12/2014	M45036FBN	BRADFORD WHITE	0
18430	09/30/2014	M45036FBN	BRADFORD WHITE	1
18431	09/12/2014	M45036FBN	BRADFORD WHITE	0
18432	09/30/2014	PROG5038NRU58DV	RUUD/RHEEM	0
18433	10/03/2014	MI40T6FBN	BRADFORD WHITE	0
18434	09/29/2014	MI5036FBN	BRADFORD WHITE	0
18435	09/26/2014	M45036FBN	BRADFORD WHITE	1
18436	09/26/2014	M45036FBN	BRADFORD WHITE	0
18437	09/29/2014	M45036FBN	BRADFORD WHITE	0
18438	09/29/2014	MI50L6FBN	BRADFORD WHITE	0
18439	09/30/2014	M2XR504T6FBN	BRADFORD WHITE	0
18440	09/22/2014	M440T6FBN	BRADFORD WHITE	0
18441	09/09/2014	MI403S6FBN	BRADFORD WHITE	0
18442	10/01/2014	MI403S6FBN	BRADFORD WHITE	0
18443	09/18/2014	M2XR504T6FBN	BRADFORD WHITE	0
18444	10/03/2014	MI50L6FBN	BRADFORD WHITE	0
18445	10/10/2014	M45036FBN	Bradford White	0
18446	09/30/2014	PROG5038NRU58DV	Ruud/Rheem	0
18447	09/25/2014	G82156	Ruud/Rheem	1
18448	09/29/2014	PROG5038NRU58DV	Ruud/Rheem	1
18449	09/04/2014	MI75S6FBN	Bradford White	0
18450	09/04/2014	MI5036FBN	Bradford White	0
18451	09/04/2014	MI5036FBN	Bradford White	1
18452	09/26/2014	M45036FBN	Bradford White	0
18453	09/24/2014	M45036FBN	Bradford White	0
18454	09/24/2014	M2XR504T6FBN	Bradford White	0
18455	09/23/2014	MI5036FBN	BRADFORD WHITE	0
18456	10/06/2014	M45036FBN	BRADFORD WHITE	2
18457	09/28/2014	MI40T6FBN	BRADFORD WHITE	0
18458	10/09/2014	MI40T6FBN	BRADFORD WHITE	1
18459	10/03/2014	PROG5038NRU58DV	RUUD	0
18460	09/30/2014	MI403S6FBN	BRADFORD WHITE	0
18461	10/03/2014	MI5036FBN	BRADFORD WHITE	0
18462	10/02/2014	PROG5038NRU58DV	RUUD	0
18463	10/21/2014	MI5036FBN	Bradford White	0
18464	10/01/2014	MI5036FBN	Bradford White	0
18465	09/29/2014	M45036FBN	Bradford White	0
18466	10/07/2014	MI5036FBN	Bradford White	0
18467	10/07/2014	PROG5038NRU58DV	Ruud/Rheem	0
18468	09/27/2014	MI5036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18469	10/06/2014	MI40T6FBN	Bradford White	0
18470	10/01/2014	M440T6FBN	Bradford White	0
18471	09/27/2014	M440T6FBN	Bradford White	0
18472	10/22/2014	MI403S6FBN	BRADFORD-WHITE	0
18473	09/26/2014	M440T6FBN	BRADFORD WHITE	0
18474	10/01/2014	MI5036FBN	BRADFORD WHITE	0
18475	10/04/2014	M45036FBN	BRADFORD WHITE	0
18476	10/08/2014	PROG5038NRU58DV	RUUD/RHEEM	1
18477	09/30/2014	M45036FBN	BRADFORD WHITE	0
18478	09/13/2014	MI5036FBN	BRADFORD WHITE	0
18479	10/04/2014	M45036FBN	BRADFORD WHITE	0
18480	10/08/2014	MI5036FBN	BRADFORD WHITE	0
18481	10/14/2014	MI5036FBN	BRADFORD WHITE	0
18482	10/13/2014	G91200	RUUD	1
18483	09/28/2014	M2XR504T6FBN	BRADFORD WHITE	0
18484	10/01/2014	MI5036FBN	BRADFORD WHITE	0
18485	10/10/2014	MI5036FBN	BRADFORD WHITE	0
18486	10/09/2014	MI50L6FBN	BRADFORD WHITE	0
18487	10/08/2014	MI5036FBN	BRADFORD WHITE	0
18488	10/15/2014	MI5036FBN	BRADFORD WHITE	0
18489	10/15/2014	G91200	RUUD	1
18490	10/17/2014	MI403S6FBN	BRADFORD WHITE	0
18491	10/14/2014	MI50L6FBN	BRADFORD WHITE	0
18492	10/15/2014	MI5036FBN	BRADFORD WHITE	0
18493	10/17/2014	MI5036FBN	BRADFORD WHITE	1
18494	10/08/2014	MI5036FBN	Bradford White	0
18495	10/16/2014	G91200	RUUD/RHEEM	0
18496	09/18/2014	M45036FBN	Bradford White	0
18497	10/11/2014	PROG5038NRU58DV	Ruud/Rheem	0
18498	10/07/2014	M45036FBN	Bradford White	0
18499	10/01/2014	MI40T6FBN	Bradford White	0
18500	10/10/2014	MI40T6FBN	BRADFORD WHITE	0
18501	09/25/2014	M45036FBN	BRADFORD WHITE	0
18502	10/09/2014	PROG5038NRU58DV	RUUD RHEEM	0
18503	10/12/2014	M45036FBN	BRADFORD WHITE	0
18504	10/09/2014	M440T6FBN	BRADFORD WHITE	1
18505	10/13/2014	G82156	RUUD/RHEEM	0
18506	10/19/2014	MI403S6FBN	Bradford White	0
18507	10/16/2014	M45036FBN	Bradford White	0
18508	10/16/2014	MI5036FBN	Bradford White	0
18509	10/17/2014	M45036FBN	Bradford White	0
18510	10/15/2014	M45036FBN	Bradford White	0
18511	10/15/2014	MI40T6FBN	Bradford White	1
18512	10/19/2014	MI40T6FBN	Bradford White	1
18513	10/11/2014	PROG5038NRU58DV	Ruud/Rheem	0
18514	10/10/2014	MI5036FBN	BRADFORD WHITE	1
18515	10/16/2014	MI5036FBN	BRADFORD WHITE	0
18516	10/13/2014	MI5036FBN	BRADFORD WHITE	1
18517	10/07/2014	MI5036FBN	BRADFORD WHITE	0
18518	10/08/2014	M440T6FBN	BRADFORD WHITE	1
18519	10/12/2014	PROG2932NRU62	BRADFORD WHITE	0
18520	10/13/2014	M45036FBN	BRADFORD WHITE	0
18521	10/14/2014	M45036FBN	BRADFORD WHITE	0
18522	10/13/2014	PROG5038NRU58DV	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18523	10/20/2014	MI5036FBN	BRADFORD WHITE	0
18524	10/13/2014	M45036FBN	BRADFORD WHITE	0
18525	10/10/2014	MI5036FBN	BRADFORD WHITE	0
18526	10/16/2014	MI403S6FBN	Bradford White	0
18527	10/16/2014	MI5036FBN	Bradford White	0
18528	10/11/2014	M45036FBN	Bradford White	0
18529	09/24/2014	M440T6FBN	Bradford White	0
18530	10/02/2014	M45036FBN	Bradford White	2
18531	10/10/2014	M440T6FBN	Bradford White	0
18532	10/03/2014	M45036FBN	Bradford White	0
18533	10/17/2014	M45036FBN	BRADFORD WHITE	0
18534	10/19/2014	M45036FBN	BRADFORD WHITE	0
18535	10/15/2014	M2XR504T6FBN	BRADFORD WHITE	0
18536	10/14/2014	PROG5038NRU58DV	RHEEM / RUUD	0
18537	10/18/2014	G91200	RUUD/RHEEM	0
18538	10/14/2014	MI5036FBN	BRADFORD WHITE	0
18539	10/20/2014	M45036FBN	BRADFORD WHITE	0
18540	10/24/2014	PH2DV50F	RUUD	0
18541	10/27/2014	PROG2932NRU62	RHEEM RUUD	0
18542	10/23/2014	M45036FBN	BRADFORD WHITE	0
18543	09/30/2014	G91200	RUUD/RHEEM	2
18544	10/23/2014	MI40T6FBN	Bradford White	0
18545	10/28/2014	M45036FBN	Bradford White	0
18546	10/29/2014	M2XR504T6FBN	Bradford White	0
18547	10/24/2014	MI5036FBN	Bradford White	0
18548	10/24/2014	M45036FBN	Bradford White	0
18549	10/17/2014	M45036FBN	Bradford White	0
18550	10/25/2014	MI403S6FBN	Bradford White	0
18551	10/21/2014	MI403S6FBN	Bradford White	0
18552	10/20/2014	M45036FBN	Bradford White	0
18553	10/19/2014	M45036FBN	BRADFORD WHITE	1
18554	10/10/2014	PROG5038NRU58DV	BRADFORD WHITE	0
18555	10/24/2014	M45036FBN	BRADFORD WHITE	0
18556	10/24/2014	MI5036FBN	BRADFORD WHITE	0
18557	10/27/2014	MI5036FBN	BRADFORD WHITE	0
18558	10/23/2014	MI403S6FBN	BRADFORD WHITE	0
18559	10/29/2014	MI5036FBN	BRADFORD WHITE	0
18560	10/29/2014	M45036FBN	BRADFORD WHITE	1
18561	10/07/2014	M45036FBN	BRADFORD WHITE	0
18562	10/20/2014	MI5036FBN	BRADFORD WHITE	0
18563	10/22/2014	M45036FBN	BRADFORD WHITE	0
18564	10/22/2014	MI40T6FBN	BRADFORD WHITE	0
18565	10/23/2014	MI5036FBN	BRADFORD WHITE	0
18566	10/22/2014	M45036FBN	BRADFORD WHITE	0
18567	10/29/2014	MI5036FBN	BRADFORD WHITE	0
18568	10/21/2014	M45036FBN	BRADFORD WHITE	0
18569	10/03/2014	M45036FBN	BRADFORD WHITE	1
18570	10/16/2014	MI40T6FBN	BRADFORD-WHITE	0
18571	10/29/2014	M2XR504T6FBN	BRADFORD-WHITE	0
18572	10/28/2014	PROG5038NRU58DV	RUUD RHEEM	0
18573	10/21/2014	G75125	RUUD/RHEEM	0
18574	10/14/2014	MI5036FBN	Bradford White	2
18575	11/05/2014	M45036FBN	BRADFORD WHITE	0
18576	10/30/2014	MI5036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18577	11/07/2014	G91200	RUUD/RHEEM	0
18578	11/09/2014	MI5036FBN	Bradford White	0
18579	11/01/2014	MI403S6FBN	Bradford White	0
18580	10/27/2014	MI5036FBN	Bradford White	0
18581	10/30/2014	MI403S6FBN	BRADFORD WHITE	0
18582	10/31/2014	G76200	RUUD/RHEEM	0
18583	10/10/2014	G91200	RUUD/RHEEM	0
18584	10/29/2014	M45036FBN	BRADFORD WHITE	0
18585	10/09/2014	M45036FBN	BRADFORD WHITE	0
18586	10/31/2014	M45036FBN	BRADFORD WHITE	0
18587	10/28/2014	MI5036FBN	Bradford White	0
18588	10/27/2014	MI50L6FBN	Bradford White	0
18589	10/27/2014	M440T6FBN	Bradford White	0
18590	10/31/2014	MI403S6FBN	Bradford White	0
18591	10/30/2014	M45036FBN	Bradford White	1
18592	10/24/2014	MI40T6FBN	BRADFORD WHITE	0
18593	10/23/2014	MI5036FBN	BRADFORD WHITE	0
18594	11/03/2014	G75125	RUUD	1
18595	11/01/2014	PROG5038NRU58DV	RUUD	0
18596	11/04/2014	MI40T6FBN	BRADFORD WHITE	0
18597	11/07/2014	M45036FBN	BRADFORD WHITE	0
18598	11/07/2014	M45036FBN	BRADFORD WHITE	0
18599	11/06/2014	MI5036FBN	BRADFORD WHITE	0
18600	11/10/2014	MI403S6FBN	BRADFORD WHITE	0
18601	11/06/2014	MI50L6FBN	BRADFORD WHITE	0
18602	11/03/2014	M45036FBN	Bradford White	0
18603	11/17/2014	M45036FBN	Bradford White	0
18604	11/03/2014	MI5036FBN	Bradford White	0
18605	10/02/2014	MI5036FBN	Bradford White	0
18606	10/08/2014	MI5036FBN	Bradford White	0
18607	10/30/2014	M45036FBN	Bradford White	0
18608	11/13/2014	MI40T6FBN	Bradford White	0
18609	11/05/2014	M45036FBN	Bradford White	0
18610	11/23/2014	G76200	RUUD	1
18611	11/11/2014	M45036FBN	BRADFORD WHITE	0
18612	11/20/2014	M440T6FBN	BRADFORD WHITE	0
18613	11/21/2014	M440T6FBN	BRADFORD WHITE	0
18614	11/26/2014	MI5036FBN	BRADFORD WHITE	0
18615	11/25/2014	M45036FBN	BRADFORD WHITE	0
18616	11/13/2014	M440T6FBN	BRADFORD WHITE	0
18617	11/30/2014	M45036FBN	BRADFORD WHITE	0
18618	10/28/2014	M45036FBN	Bradford White	1
18619	10/22/2014	M45036FBN	BRADFORD WHITE	0
18620	10/15/2014	MI5036FBN	BRADFORD WHITE	0
18621	10/28/2014	PROG5038NRU58DV	RUUD / RHEEM	0
18622	10/21/2014	MI5036FBN	BRADFORD WHITE	0
18623	10/31/2014	MI5036FBN	BRADFORD WHITE	0
18624	12/01/2014	M45036FBN	Bradford White	0
18625	11/03/2014	M45036FBN	Bradford White	0
18626	10/30/2014	PROG5038NRU58	RUUD / RHEEM	0
18627	10/31/2014	M45036FBN	BRADFORD-WHITE	0
18628	10/24/2014	MI5036FBN	BRADFORD-WHITE	1
18629	10/29/2014	MI5036FBN	BRADFORD-WHITE	0
18630	10/28/2014	MI5036FBN	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18631	10/29/2014	MI5036FBN	BRADFORD WHITE	0
18632	10/30/2014	MI40T6FBN	BRADFORD-WHITE	0
18633	11/03/2014	M45036FBN	BRADFORD-WHITE	0
18634	11/03/2014	MI5036FBN	BRADFORD-WHITE	0
18635	11/01/2014	PROG5036NRU60DV	RHEEM/RUUD	0
18636	11/07/2014	M45036FBN	BRADFORD-WHITE	0
18637	10/20/2014	G91200	RUUD	0
18638	11/10/2014	M440T6FBN	BRADFORD WHITE	0
18639	11/11/2014	M45036FBN	BRADFORD WHITE	2
18640	11/01/2014	M45036FBN	BRADFORD WHITE	0
18641	11/20/2014	G75125	RUUD	3
18642	10/24/2014	M440T6FBN	BRADFORD WHITE	0
18643	11/17/2014	M45036FBN	BRADFORD WHITE	1
18644	11/04/2014	PROG5038NRU58DV	RUUD	0
18645	11/21/2014	PROG5038NRU58DV	RUUD	0
18646	11/10/2014	M45036FBN	Bradford White	0
18647	11/13/2014	P506	RUUD	0
18648	11/11/2014	M45036FBN	Bradford White	0
18649	11/11/2014	G75125	RUUD/RHEEM	0
18650	11/18/2014	M45036FBN	Bradford White	0
18651	11/17/2014	M45036FBN	Bradford White	0
18652	11/18/2014	M45036FBN	Bradford White	0
18653	11/15/2014	M45036FBN	Bradford White	0
18654	11/18/2014	MI5036FBN	Bradford White	0
18655	11/21/2014	MI5036FBN	Bradford White	0
18656	11/29/2014	M45036FBN	BRADFORD WHITE	0
18657	11/19/2014	MI5036FBN	BRADFORD WHITE	0
18658	11/21/2014	PROG5038NRU58DV	RUUD	0
18659	11/26/2014	M45036FBN	BRADFORD WHITE	0
18660	11/26/2014	MI5036FBN	BRADFORD WHITE	0
18661	11/22/2014	PROG5038NRU58DV	RUUD	0
18662	11/18/2014	M45036FBN	BRADFORD WHITE	0
18663	11/17/2014	MI40T6FBN	BRADFORD WHITE	0
18664	11/25/2014	P230S30F	RUUD	2
18665	12/02/2014	M45036FBN	BRADFORD WHITE	0
18666	11/14/2014	DS140S6FBN	Bradford White	0
18667	11/08/2014	PROG5038NRU58DV	Ruud/Rheem	0
18668	11/08/2014	M45036FBN	AMERICAN	0
18669	11/10/2014	M45036FBN	Bradford White	0
18670	11/13/2014	M45036FBN	Bradford White	0
18671	11/10/2014	M45036FBN	Bradford White	0
18672	11/21/2014	MI5036FBN	Bradford White	2
18673	11/16/2014	MI5036FBN	Bradford White	0
18674	11/17/2014	MI5036FBN	Bradford White	0
18675	11/17/2014	M440T6FBN	Bradford White	0
18676	11/08/2014	MI5036FBN	Bradford White	0
18677	11/09/2014	21VR50	RHEEM	0
18678	11/18/2014	M45036FBN	Bradford White	0
18679	11/20/2014	PROG5038NRU58DV	Ruud/Rheem	1
18680	11/20/2014	PROG5038NRU58DV	Ruud/Rheem	0
18681	11/19/2014	MI5036FBN	Bradford White	0
18682	11/20/2014	PROG5038NRU58DV	RUUD	1
18683	11/12/2014	MI40T6FBN	Bradford White	0
18684	11/07/2014	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18685	11/19/2014	MI40T6FBN	BRADFORD WHITE	0
18686	11/04/2014	M45036FBN	Bradford White	0
18687	11/07/2014	M45036FBN	Bradford White	0
18688	11/15/2014	M45036FBN	BRADFORD WHITE	0
18689	11/19/2014	PROG2932NRU62	RUUD	0
18690	11/05/2014	G91200	RUUD	0
18691	11/05/2014	G91200	RUUD	1
18692	11/14/2014	MI403S6FBN	BRADFORD WHITE	0
18693	11/21/2014	PROG5038NRU58DV	RUUD	0
18694	12/12/2014	M45036FBN	Bradford White	0
18695	11/12/2014	M45036FBN	Bradford White	0
18696	11/10/2014	PROG5038NRU58DV	Ruud/Rheem	0
18697	11/04/2014	M45036FBN	Ruud/Rheem	0
18698	11/28/2014	G91200	RUUD	0
18699	11/28/2014	PROG5038NRU58DV	RUUD	0
18700	11/26/2014	M45036FBN	BRADFORD WHITE	1
18701	11/28/2014	MI5036FBN	BRADFORD WHITE	0
18702	11/25/2014	MI5036FBN	BRADFORD WHITE	0
18703	11/25/2014	PROG5038NRU58DV	RUUD	1
18704	11/26/2014	G75125	RUUD	0
18705	12/03/2014	M45036FBN	BRADFORD WHITE	0
18706	12/01/2014	M45036FBN	BRADFORD WHITE	0
18707	11/29/2014	MI403S6FBN	BRADFORD WHITE	1
18708	12/04/2014	M45036FBN	BRADFORD WHITE	3
18709	11/30/2014	MI5036FBN	BRADFORD WHITE	1
18710	12/03/2014	M45036FBN	BRADFORD WHITE	0
18711	12/02/2014	PROG5038NRU58DV	RUUD	0
18712	12/01/2014	MI5036FBN	BRADFORD WHITE	0
18713	12/04/2014	MI40T6FBN	BRADFORD WHITE	0
18714	12/03/2014	MI40T6FBN	BRADFORD WHITE	0
18715	12/07/2014	M45036FBN	BRADFORD WHITE	0
18716	12/05/2014	M45036FBN	BRADFORD WHITE	0
18717	12/06/2014	M45036FBN	BRADFORD WHITE	0
18718	12/03/2014	MI403S6FBN	BRADFORD WHITE	0
18719	12/07/2014	MI5036FBN	BRADFORD WHITE	0
18720	12/05/2014	PROG5038NRU58DV	RUUD	0
18721	12/02/2014	MI5036FBN	BRADFORD WHITE	0
18722	11/25/2014	M2XR504T6FBN	Bradford White	2
18723	11/20/2014	MI50L6FBN	Bradford White	1
18724	11/30/2014	MI5036FBN	Bradford White	0
18725	11/20/2014	MI5036FBN	Bradford White	0
18726	11/20/2014	MI403S6FBN	Bradford White	0
18727	11/26/2014	G75125	Ruud/Rheem	0
18728	12/04/2014	M45036FBN	Bradford White	0
18729	12/03/2014	M45036FBN	Bradford White	0
18730	12/09/2014	MI5036FBN	Bradford White	0
18731	12/06/2014	PGR50	AO SMITH	0
18732	12/07/2014	M45036FBN	Bradford White	0
18733	12/08/2014	PROG5038NRU58DV	Ruud	0
18734	12/09/2014	MI40T6FBN	Bradford White	0
18735	12/13/2014	MI5036FBN	Bradford White	0
18736	12/01/2014	M45036FBN	Bradford White	1
18737	12/10/2014	P230S30F	Bradford White	0
18738	12/11/2014	PHR40	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18739	12/16/2014	MI5036FBN	Bradford White	0
18740	12/16/2014	MI403S6FBN	Bradford White	0
18741	11/22/2014	M440T6FBN	Bradford White	0
18742	11/24/2014	M45036FBN	Bradford White	0
18743	12/04/2014	MI5036FBN	BRADFORD WHITE	2
18744	12/10/2014	MI5036FBN	BRADFORD WHITE	0
18745	12/03/2014	MI5036FBN	BRADFORD WHITE	0
18746	12/05/2014	M45036FBN	Bradford White	0
18747	12/04/2014	MI5036FBN	BRADFORD WHITE	0
18748	12/03/2014	MI5036FBN	Bradford White	0
18749	11/05/2014	21DV50	RHEEM	0
18750	12/05/2014	M45036FBN	BRADFORD WHITE	0
18751	11/28/2014	M45036FBN	Bradford White	0
18752	12/02/2014	PROG5038nru58DV	Ruud	0
18753	12/01/2014	MI40T6FBN	Bradford White	0
18754	12/02/2014	PROG5038NRU58DV	Ruud	0
18755	11/25/2014	PROG5038NRU58DV	Ruud	0
18756	12/05/2014	M45036FBN	Bradford White	0
18757	12/07/2014	M45036FBN	Bradford White	0
18758	12/06/2014	MI5036FBN	BRADFORD WHITE	0
18759	12/12/2014	MI5036FBN	BRADFORD WHITE	0
18760	12/12/2014	M45036FBN	BRADFORD WHITE	0
18761	11/26/2014	MI5036FBN	BRADFORD WHITE	0
18762	12/10/2014	MI40T6FBN	BRADFORD WHITE	0
18763	12/12/2014	FSG50	AO SMITH	0
18764	12/17/2014	M45036FBN	BRADFORD WHITE	0
18765	12/15/2014	PROG5038NRU58DV	BRADFORD WHITE	0
18766	12/11/2014	G82156	RUUD	0
18767	12/08/2014	PROG5038NRU58DV	RUUD	0
18768	12/12/2014	M45036FBN	BRADFORD WHITE	0
18769	12/10/2014	M45036FBN	BRADFORD WHITE	0
18770	12/16/2014	MI5036FBN	BRADFORD WHITE	0
18771	01/07/2015	MI5036FBN	BRADFORD WHITE	0
18772	01/07/2015	MI5036FBN	BRADFORD WHITE	0
18773	01/02/2015	M45036FBN	BRADFORD WHITE	0
18774	01/05/2015	DS140S6FBN	BRADFORD WHITE	0
18775	01/06/2015	MI5036FBN	BRADFORD WHITE	1
18776	01/07/2015	M45036FBN	BRADFORD WHITE	0
18777	01/10/2015	G82156	RUUD/RHEEM	0
18778	01/07/2015	PROG5038NRU58DV	RUUD	0
18779	01/07/2015	M45036FBN	BRADFORD WHITE	1
18780	11/18/2014	G91200	RUUD	2
18781	12/01/2014	MI5036FBN	BRADFORD WHITE	0
18782	12/18/2014	MI5036FBN	BRADFORD WHITE	0
18783	12/11/2014	G91200	RUUD	1
18784	12/22/2014	M45036FBN	BRADFORD WHITE	0
18785	12/17/2014	MI5036FBN	BRADFORD WHITE	0
18786	12/19/2014	M45036FBN	BRADFORD WHITE	0
18787	12/03/2014	M45036FBN	BRADFORD WHITE	0
18788	12/02/2014	MI5036FBN	BRADFORD WHITE	0
18789	12/18/2014	MI403S6FBN	BRADFORD WHITE	0
18790	12/17/2014	DS140S6FBN	BRADFORD WHITE	2
18791	12/16/2014	MI5036FBN	BRADFORD WHITE	0
18792	12/29/2014	MI403S6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18793	12/26/2014	M45036FBN	BRADFORD WHITE	0
18794	12/30/2014	MI5036FBN	BRADFORD WHITE	0
18795	12/30/2014	MI5036FBN	BRADFORD WHITE	0
18796	12/26/2014	MI40T6FBN	BRADFORD WHITE	0
18797	12/28/2014	MI40T6FBN	BRADFORD WHITE	0
18798	01/01/2015	M45036FBN	BRADFORD WHITE	0
18799	01/01/2015	G91200	RUUD	0
18800	01/02/2015	MI5036FBN	BRADFORD WHITE	0
18801	01/04/2015	G75125	RUUD	0
18802	01/05/2015	M45036FBN	BRADFORD WHITE	0
18803	01/12/2015	M45036FBN	BRADFORD WHITE	0
18804	01/02/2015	MI403S6FBN	BRADFORD WHITE	2
18805	01/09/2015	MI5036FBN	BRADFORD WHITE	0
18806	12/15/2014	PROG5038NRU58DV	RUUD	0
18807	12/02/2014	PROG5038NRU58DV	Ruud	0
18808	12/10/2014	MI5036FBN	BRADFORD WHITE	0
18809	12/07/2014	PROG5038NRU58DV	RUUD	0
18810	12/10/2014	LTN040GEF	LOCHINVAR	0
18811	12/04/2014	PROG5038NRU58DV	Ruud	0
18812	12/06/2014	M45036FBN	Bradford White	0
18813	12/06/2014	M45036FBN	Bradford White	0
18814	12/10/2014	PROG5038NRU58DV	RUUD	0
18815	12/03/2014	MI5036FBN	Bradford White	0
18816	12/15/2014	MI5036FBN	Bradford White	0
18817	12/15/2014	M440T6FBN	Bradford White	0
18818	12/14/2014	PROG5038NRU58DV	Ruud	0
18819	12/17/2014	M45036FBN	Bradford White	0
18820	12/10/2014	M45036FBN	Bradford White	0
18821	12/08/2014	MI50L6FBN	Bradford White	0
18822	12/15/2014	M45036FBN	Bradford White	0
18823	12/14/2014	M45036FBN	Bradford White	0
18824	12/16/2014	M45036FBN	Bradford White	0
18825	12/23/2014	M45036FBN	Bradford White	0
18826	12/31/2014	MI403S6FBN	Bradford White	0
18827	12/31/2014	MI40T6FBN	Bradford White	3
18828	12/30/2014	M45036FBN	Bradford White	0
18829	12/30/2014	MI5036FBN	Bradford White	0
18830	12/30/2014	MI5036FBN	Bradford White	0
18831	12/30/2014	MI5036FBN	Bradford White	0
18832	12/29/2014	MI5036FBN	Bradford White	0
18833	12/30/2014	PROG5038NRU58DV	RUUD	1
18834	12/30/2014	PROG5038NRU58DV	RUUD	0
18835	12/23/2014	G75125	RUUD	1
18836	12/26/2014	M2XR504T6FBN	BRADFORD WHITE	1
18837	12/31/2014	M45036FBN	BRADFORD WHITE	0
18838	12/11/2014	PROG5038NRU58DV	RUUD	0
18839	12/12/2014	M45036FBN	BRADFORD WHITE	0
18840	12/10/2014	MI5036FBN	BRADFORD WHITE	0
18841	12/09/2014	M45036FBN	BRADFORD WHITE	0
18842	12/08/2014	M45036FBN	BRADFORD WHITE	0
18843	12/22/2014	M45036FBN	Bradford White	0
18844	12/23/2014	M45036FBN	Bradford White	1
18845	12/28/2014	MI5036FBN	Bradford White	0
18846	12/24/2014	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18847	12/26/2014	M45036FBN	Bradford White	0
18848	12/31/2014	MI5036FBN	Bradford White	0
18849	12/12/2014	M45036FBN	Bradford White	0
18850	12/29/2014	M45036FBN	BRADFORD WHITE	0
18851	12/27/2014	M45036FBN	BRADFORD WHITE	0
18852	12/17/2014	M45036FBN	BRADFORD WHITE	0
18853	12/26/2014	MI403S6FBN	BRADFORD WHITE	0
18854	12/23/2014	M45036FBN	BRADFORD WHITE	0
18855	12/31/2014	G91200	RUUD	0
18856	12/22/2014	G75125	RUUD/RHEEM	5
18857	12/16/2014	MI403S6FBN	BRADFORD-WHITE	0
18858	12/19/2014	M45036FBN	BRADFORD WHITE	0
18859	12/19/2014	MI5036FBN	BRADFORD WHITE	0
18860	12/01/2014	M2XR504T6FBN	BRADFORD WHITE	0
18861	12/16/2014	MI5036FBN	BRADFORD WHITE	0
18862	12/18/2014	M45036FBN	BRADFORD WHITE	0
18863	01/06/2015	M45036FBN	Bradford White	0
18864	01/09/2015	M45036FBN	Bradford White	0
18865	01/06/2015	G91200	Ruud	3
18866	12/27/2014	MI5036FBN	BRADFORD WHITE	1
18867	01/10/2015	PROG5038NRU58DV	RUUD	0
18868	12/24/2014	M45036FBN	BRADFORD WHITE	0
18869	01/07/2015	PROG5038NRU58DV	RUUD	0
18870	01/09/2015	PROG5038NRU58DV	RUUD	0
18871	01/07/2015	M45036FBN	BRADFORD WHITE	0
18872	01/06/2015	MI5036FBN	BRADFORD WHITE	1
18873	12/30/2014	DS150S6FBN	BRADFORD WHITE	2
18874	12/19/2014	M45036FBN	BRADFORD WHITE	0
18875	12/19/2014	MI5036FBN	BRADFORD WHITE	0
18876	01/08/2015	MI5036FBN	Bradford White	0
18877	01/05/2015	MI5036FBN	Bradford White	0
18878	01/09/2015	MI40T6FBN	Bradford White	2
18879	01/07/2015	PROG5038NRU58DV	Ruud	0
18880	01/07/2015	MI5036FBN	Bradford White	0
18881	12/28/2014	M45036FBN	Bradford White	0
18882	01/13/2015	G76200	Ruud	1
18883	01/03/2015	MI5036FBN	Bradford White	0
18884	01/07/2015	PROG5038NRU58DV	Ruud	0
18885	01/06/2015	MI5036FBN	Bradford White	0
18886	01/06/2015	MI50L6FBN	Bradford White	0
18887	01/12/2015	M45036FBN	Bradford White	0
18888	01/21/2015	M45036FBN	BRADFORD WHITE	0
18889	12/29/2014	PROG5038NRU58DV	Ruud/Rheem	1
18890	01/02/2015	M45036FBN	Bradford White	0
18891	01/05/2015	M440T6FBN	Bradford White	0
18892	01/09/2015	DS150S6FBN	Bradford White	0
18893	01/14/2015	M2XR504T6FBN	Bradford White	0
18894	01/15/2015	M45036FBN	BRADFORD WHITE	0
18895	01/05/2015	PROG5038NRU58DV	RUUD	0
18896	12/30/2014	M2XR504T6FBN	BRADFORD WHITE	0
18897	01/12/2015	PROG5038NRU58DV	RUUD	0
18898	01/12/2015	MI40T6FBN	BRADFORD WHITE	2
18899	01/15/2015	DS140S6FBN	BRADFORD WHITE	0
18900	01/12/2015	G75125	RUUD/RHEEM	9

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18901	01/16/2015	PROG5038NRU58DV	RUUD	0
18902	01/20/2015	MI5036FBN	Bradford White	0
18903	01/23/2015	M45036FBN	Bradford White	0
18904	01/20/2015	M45036FBN	Bradford White	0
18905	01/23/2015	MI403S6FBN	Bradford White	0
18906	01/24/2015	PROG5038NRU58DV	Ruud/Rheem	0
18907	01/26/2015	MI5036FBN	Bradford White	0
18908	01/27/2015	MI5036FBN	Bradford White	0
18909	01/27/2015	G76200	Ruud/Rheem	5
18910	01/23/2015	G76200	RUUD	0
18911	01/27/2015	M45036FBN	BRADFORD WHITE	0
18912	01/26/2015	MI40T6FBN	BRADFORD WHITE	0
18913	01/27/2015	M45036FBN	BRADFORD WH ITE	0
18914	01/27/2015	M45036FBN	BRADFORD WHITE	0
18915	01/21/2015	MI50L6FBN	BRADFORD WHITE	0
18916	01/26/2015	MI403S6FBN	BRADFORD WHITE	0
18917	01/24/2015	G82156	RUUD	0
18918	01/13/2015	MI40T6FBN	BRADFORD WHITE	0
18919	01/08/2015	M45036FBN	Bradford White	0
18920	01/08/2015	MI403S6FBN	Bradford White	0
18921	01/27/2015	G76200	RUUD	0
18922	01/26/2015	M45036FBN	BRADFORD WHITE	0
18923	01/26/2015	PROG5038NRU58DV	RUUD	1
18924	01/23/2015	P230S30F	RUUD	0
18925	01/29/2015	G91200	RUUD	0
18926	01/30/2015	P506	BRADFORD WHITE	0
18927	01/30/2015	M45036FBN	BRADFORD WHITE	0
18928	01/31/2015	M45036FBN	BRADFORD WHITE	3
18929	02/04/2015	MI5036FBN	BRADFORD WHITE	0
18930	01/30/2015	MI5036FBN	BRADFORD WHITE	0
18931	02/04/2015	M45036FBN	BRADFORD WHITE	0
18932	01/15/2015	M440T6FBN	BRADFORD WHITE	0
18933	01/26/2015	M45036FBN	BRADFORD WHITE	0
18934	02/11/2015	G91200	RUUD/RHEEM	0
18935	02/09/2015	MI5036FBN	BRADFORD WHITE	0
18936	02/17/2015	MI5036FBN	BRADFORD WHITE	0
18937	02/17/2015	M2XR504T6FBN	BRADFORD WHITE	0
18938	01/28/2015	G76200	RUUD	0
18939	02/09/2015	M2XR504T6FBN	BRADFORD WHITE	5
18940	02/18/2015	M45036FBN	BRADFORD WHITE	0
18941	01/31/2015	MI5036FBN	BRADFORD WHITE	0
18942	02/17/2015	MI5036FBN	BRADFORD WHITE	0
18943	02/25/2015	MI5036FBN	BRADFORD WHITE	0
18944	02/23/2015	MI5036FBN	BRADFORD WHITE	0
18945	02/23/2015	M45036FBN	BRADFORD WHITE	0
18946	02/26/2015	MI5036FBN	BRADFORD WHITE	0
18947	02/28/2015	MI40T6FBN	BRADFORD WHITE	0
18948	02/25/2015	PROG5038NRU58DV	RUUD / RHEEM	0
18949	02/26/2015	G76200	RUUD	3
18950	02/24/2015	M45036FBN	BRADFORD WHITE	0
18951	02/18/2015	MI40T6FBN	BRADFORD WHITE	0
18952	02/25/2015	MI5036FBN	BRADFORD WHITE	0
18953	03/02/2015	M45036FBN	BRADFORD WHITE	0
18954	03/02/2015	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
18955	01/05/2015	MI5036FBN	BRADFORD WHITE	0
18956	01/10/2015	MI5036FBN	BRADFORD WHITE	0
18957	01/11/2015	M45036FBN	BRADFORD WHITE	0
18958	01/07/2015	MI75S6FBN	BRADFORD WHITE	0
18959	01/13/2015	MI403S6FBN	BRADFORD WHITE	0
18960	01/13/2015	MI403S6FBN	BRADFORD WHITE	0
18961	01/02/2015	PROG5038NRU58DV	RUUD	1
18962	12/30/2014	MI5036FBN	BRADFORD WHITE	1
18963	01/05/2015	M45036FBN	BRADFORD WHITE	0
18964	01/03/2015	PROG5038NRU58DV	RUUD	0
18965	01/02/2015	MI403S6FBN	BRADFORD WHITE	0
18966	01/13/2015	MI5036FBN	BRADFORD WHITE	0
18967	01/14/2015	DS150S6FBN	BRADFORD WHITE	0
18968	01/15/2015	M45036FBN	BRADFORD WHITE	0
18969	12/31/2014	PROG5038NRU58DV	RUUD	0
18970	12/29/2014	M2XR504T6FBN	BRADFORD WHITE	0
18971	01/14/2015	M45036FBN	BRADFORD WHITE	0
18972	01/21/2015	M45036FBN	Bradford White	0
18973	01/21/2015	M45036FBN	Bradford White	1
18974	01/10/2015	M45036FBN	Bradford White	0
18975	01/15/2015	M2XR504T6FBN	Bradford White	0
18976	01/28/2015	M45036FBN	BRADFORD WHITE	0
18977	01/29/2015	M440T6FBN	BRADFORD WHITE	0
18978	02/03/2015	MI40T6FBN	AO SMITH	0
18979	02/03/2015	M45036FBN	Bradford White	0
18980	02/04/2015	PROG5038NRU58DV	RUUD	1
18981	02/16/2015	G91200	RUUD	0
18982	02/12/2015	M45036FBN	BRADFORD WHITE	0
18983	02/12/2015	M45036FBN	BRADFORD WHITE	1
18984	02/21/2015	M45036FBN	BRADFORD WHITE	0
18985	02/19/2015	MI5036FBN	BRADFORD WHITE	0
18986	02/18/2015	MI403S6FBN	BRADFORD WHITE	0
18987	02/18/2015	M440T6FBN	BRADFORD WHITE	0
18988	02/19/2015	MI5036FBN	BRADFORD WHITE	0
18989	02/22/2015	MI5036FBN	BRADFORD WHITE	0
18990	02/22/2015	MI5036FBN	BRADFORD WHITE	1
18991	02/24/2015	M45036FBN	BRADFORD WHITE	0
18992	02/20/2015	MI50L6FBN	Bradford White	2
18993	02/18/2015	MI5036FBN	Bradford White	0
18994	02/17/2015	MI5036FBN	Bradford White	1
18995	12/22/2014	MI5036FBN	Bradford White	0
18996	12/22/2014	M45036FBN	Bradford White	0
18997	01/16/2015	M45036FBN	Bradford White	0
18998	01/17/2015	MI5036FBN	Bradford White	0
18999	01/14/2015	MI5036FBN	Bradford White	0
19000	01/19/2015	MI5036FBN	Bradford White	0
19001	01/16/2015	PROG5038NRU58DV	RUUD	0
19002	01/16/2015	M45036FBN	BRADFORD WHITE	0
19003	01/17/2015	MI403S6FBN	BRADFORD WHITE	0
19004	01/20/2015	M45036FBN	BRADFORD WHITE	0
19005	12/17/2014	MI40T6FBN	BRADFORD WHITE	1
19006	01/05/2015	MI5036FBN	BRADFORD WHITE	0
19007	01/06/2015	MI5036FBN	BRADFORD WHITE	0
19008	01/14/2015	M440T6FBN	BRADFORD WHITE	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19009	01/20/2015	M440T6FBN	BRADFORD WHITE	0
19010	01/22/2015	MI5036FBN	BRADFORD WHITE	0
19011	01/15/2015	M45036FBN	BRADFORD WHITE	0
19012	01/19/2015	MI5036FBN	BRADFORD WHITE	0
19013	01/25/2015	PROG5038NRU58DV	RUUD	0
19014	12/16/2014	M45036FBN	BRADFORD WHITE	0
19015	01/27/2015	DS150S6FBN	BRADFORD WHITE	0
19016	01/27/2015	M45036FBN	BRADFORD WHITE	0
19017	01/22/2015	MI5036FBN	BRADFORD WHITE	0
19018	01/23/2015	M440T6FBN	BRADFORD WHITE	0
19019	01/23/2015	MI5036FBN	BRADFORD WHITE	1
19020	01/20/2015	MI5036FBN	BRADFORD WHITE	0
19021	01/14/2015	G75125	RUUD	10
19022	01/15/2015	MI40T6FBN	BRADFORD WHITE	0
19023	01/22/2015	M45036FBN	BRADFORD WHITE	0
19024	01/24/2015	PROG5038NRU58DV	Ruud/Rheem	0
19025	01/31/2015	PROG5038NRU58DV	RUUD	1
19026	01/31/2015	MI5036FBN	BRADFORD WHITE	1
19027	01/16/2015	M45036FBN	BRADFORD WHITE	0
19028	01/16/2015	M2XR504T6FBN	BRADFORD WHITE	0
19029	02/03/2015	M2XR504T6FBN	BRADFORD WHITE	0
19030	02/02/2015	PROG5038NRU58DV	RUUD	0
19031	01/24/2015	M45036FBN	BRADFORD WHITE	0
19032	01/01/2015	MI5036FBN	BRADFORD WHITE	0
19033	02/11/2015	MI75S6FBN	Bradford White	0
19034	02/16/2015	LTN050G	LOCHINVAR	0
19035	02/16/2015	M45036FBN	Bradford White	0
19036	02/11/2015	MI5036FBN	Bradford White	0
19037	02/13/2015	MI403S6FBN	Bradford White	0
19038	02/18/2015	PR650	STATE	0
19039	01/27/2015	LSN041G	LOCHINVAR	0
19040	02/17/2015	GVC50	A. O. SMITH	0
19041	02/04/2015	M45036FBN	BRADFORD WHITE	0
19042	01/29/2015	M45036FBN	BRADFORD WHITE	0
19043	01/26/2015	MI403S6FBN	BRADFORD WHITE	0
19044	02/02/2015	M45036FBN	BRADFORD WHITE	0
19045	02/05/2015	MI40T6FBN	BRADFORD WHITE	0
19046	02/06/2015	M45036FBN	BRADFORD WHITE	0
19047	01/29/2015	M45036FBN	BRADFORD WHITE	0
19048	01/29/2015	M45036FBN	BRADFORD WHITE	0
19049	02/05/2015	M45036FBN	BRADFORD WHITE	1
19050	02/05/2015	G82156	RUUD	0
19051	02/06/2015	M45036FBN	BRADFORD WHITE	0
19052	02/09/2015	M45036FBN	BRADFORD WHITE	0
19053	02/11/2015	M45036FBN	BRADFORD WHITE	0
19054	02/12/2015	MI40T6FBN	BRADFORD WHITE	0
19055	02/12/2015	MI5036FBN	BRADFORD WHITE	0
19056	02/13/2015	PROG5038NRU58DV	RHEEM RUUD	0
19057	01/28/2015	PH199119	PHOENIX	1
19058	01/23/2015	M2XR504T6FBN	BRADFORD WHITE	0
19059	01/28/2015	M45036FBN	BRADFORD WHITE	0
19060	01/29/2015	MI403S6FBN	BRADFORD WHITE	0
19061	01/31/2015	M45036FBN	BRADFORD WHITE	1
19062	01/30/2015	MI40T6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19063	01/31/2015	MI5036FBN	BRADFORD WHITE	0
19064	02/05/2015	G82156	Ruud/Rheem	1
19065	01/26/2015	G91200	Ruud/Rheem	2
19066	02/09/2015	M45036FBN	Bradford White	0
19067	02/09/2015	MI5036FBN	Bradford White	0
19068	02/11/2015	M45036FBN	Bradford White	0
19069	02/12/2015	G82156	RUUD/RHEEM	0
19070	02/08/2015	M45036FBN	Bradford White	0
19071	02/11/2015	MI75S6FBN	BRADFORD WHITE	0
19072	02/06/2015	M45036FBN	BRADFORD WHITE	0
19073	02/05/2015	M45036FBN	BRADFORD WHITE	0
19074	02/03/2015	MI5036FBN	BRADFORD WHITE	0
19075	02/08/2015	MI5036FBN	BRADFORD WHITE	0
19076	02/10/2015	M45036FBN	BRADFORD WHITE	0
19077	02/12/2015	PH19980	Phoenix	0
19078	02/09/2015	MI5036FBN	Bradford White	0
19079	02/18/2015	G91200	RUUD/RHEEM	0
19080	02/10/2015	PROG5038NRU58DV	Ruud/Rheem	0
19081	02/11/2015	M45036FBN	Bradford White	0
19082	02/18/2015	M440T6FBN	Bradford White	0
19083	02/19/2015	PROG5038NRU58DV	RUUD	0
19084	02/17/2015	MI40T6FBN	BRADFORD WHITE	1
19085	02/22/2015	MI5036FBN	BRADFORD WHITE	0
19086	02/18/2015	M440T6FBN	BRADFORD WHITE	1
19087	02/13/2015	M45036FBN	BRADFORD WHITE	0
19088	02/20/2015	MI5036FBN	BRADFORD WHITE	0
19089	02/24/2015	MI403S6FBN	BRADFORD WHITE	0
19090	02/20/2015	MI5036FBN	BRADFORD WHITE	0
19091	02/18/2015	PROG5038NRU58DV	RUUD	0
19092	02/16/2015	G91200	RUUD/RHEEM	0
19093	02/06/2015	PROG5038NRU58DV	RUUD/RHEEM	0
19094	02/14/2015	MI5036FBN	BRADFORD WHITE	0
19095	02/19/2015	M45036FBN	BRADFORD WHITE	0
19096	02/07/2015	M45036FBN	BRADFORD WHITE	0
19097	02/17/2015	PROG5038NRU58DV	RHEEM RUUD	0
19098	02/08/2015	MI75S6FBN	Bradford White	0
19099	02/22/2015	MI403S6FBN	Bradford White	0
19100	02/24/2015	MI5036FBN	Bradford White	0
19101	02/21/2015	PROG5038NRU58DV	Ruud/Rheem	0
19102	02/23/2015	MI5036FBN	Bradford White	0
19103	02/25/2015	MI75S6FBN	Bradford White	0
19104	02/22/2015	M45036FBN	Bradford White	0
19105	02/01/2015	MI5036FBN	Bradford White	0
19106	02/23/2015	M440T6FBN	Bradford White	0
19107	02/25/2015	M45036FBN	Bradford White	0
19108	02/27/2015	MI5036FBN	Bradford White	0
19109	02/26/2015	MI5036FBN	Bradford White	0
19110	02/20/2015	MI75S6FBN	Bradford White	0
19111	02/24/2015	M45036FBN	BRADFORD WHITE	0
19112	02/23/2015	M45036FBN	BRADFORD WHITE	0
19113	02/24/2015	MI5036FBN	BRADFORD WHITE	0
19114	02/27/2015	M440T6FBN	BRADFORD WHITE	0
19115	02/25/2015	M45036FBN	BRADFORD WHITE	0
19116	02/24/2015	MI5036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19117	02/21/2015	MI5036FBN	BRADFORD WHITE	0
19118	02/28/2015	M45036FBN	BRADFORD-WHITE	0
19119	02/24/2015	MI40T6FBN	BRADFORD WHITE	0
19120	02/11/2015	M2XR504T6FBN	BRADFORD WHITE	0
19121	02/25/2015	M440T6FBN	Bradford White	0
19122	02/24/2015	PROG5038NRU58DV	Ruud/Rheem	0
19123	02/24/2015	MI50L6FBN	Bradford White	0
19124	02/02/2015	M45036FBN	Bradford White	0
19125	03/05/2015	M45036FBN	Bradford White	0
19126	02/09/2015	M45036FBN	Bradford White	0
19127	02/18/2015	M440T6FBN	Bradford White	0
19128	02/23/2015	MI40T6FBN	BRADFORD WHITE	0
19129	03/02/2015	M45036FBN	BRADFORD WHITE	0
19130	03/03/2015	PROG5038NRU58DV	BRADFORD WHITE	0
19131	03/06/2015	M45036FBN	Bradford White	0
19132	03/06/2015	MI5036FBN	Bradford White	2
19133	03/10/2015	M45036FBN	Bradford White	0
19134	03/04/2015	PROG5038NRU58DV	Ruud/Rheem	0
19135	03/10/2015	M2XR504T6FBN	Bradford White	1
19136	03/09/2015	MI5036FBN	Bradford White	0
19137	03/06/2015	MI5036FBN	Bradford White	0
19138	03/02/2015	M2XR504T6FBN	Bradford White	0
19139	03/04/2015	MI5036FBN	Bradford White	0
19140	03/03/2015	PROG5038NRU58DV	Ruud/Rheem	1
19141	03/09/2015	MI40T6FBN	Bradford White	1
19142	03/06/2015	MI5036FBN	BRADFORD WHITE	0
19143	03/06/2015	M45036FBN	BRADFORD WHITE	0
19144	03/03/2015	M2XR504T6FBN	BRADFORD WHITE	0
19145	03/04/2015	M440T6FBN	BRADFORD WHITE	0
19146	03/10/2015	M45036FBN	BRADFORD WHITE	0
19147	03/05/2015	MI5036FBN	BRADFORD WHITE	0
19148	03/13/2015	MI5036FBN	Bradford White	0
19149	03/14/2015	M45036FBN	Bradford White	0
19150	03/12/2015	MI5036FBN	Bradford White	0
19151	02/27/2015	MI5036FBN	Bradford White	0
19152	03/17/2015	MI403S6FBN	Bradford White	0
19153	03/27/2015	MI40T6FBN	BRADFORD WHITE	0
19154	03/22/2015	MI403S6FBN	BRADFORD WHITE	0
19155	03/23/2015	M45036FBN	BRADFORD WHITE	0
19156	03/20/2015	PROG5038NRU58DV	BRADFORD WHITE	0
19157	03/20/2015	G75125	RUUD	0
19158	03/20/2015	M45036FBN	BRADFORD WHITE	0
19159	03/13/2015	M45036FBN	BRADFORD WHITE	0
19160	03/06/2015	MI403S6FBN	BRADFORD WHITE	2
19161	03/13/2015	MI5036FBN	Bradford White	0
19162	03/11/2013	M45036FBN	Bradford White	0
19163		PROG5038NRU58DV	RUUD	0
19164	02/21/2015	MI5036FBN	BRADFORD WHITE	0
19165	03/04/2015	M45036FBN	BRADFORD WHITE	0
19166	03/04/2015	MI5036FBN	BRADFORD WHITE	1
19167	03/06/2015	M440T6FBN	BRADFORD WHITE	0
19168	03/02/2015	MI403S6FBN	BRADFORD WHITE	0
19169	03/09/2015	M45036FBN	BRADFORD WHITE	1
19170	03/03/2015	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19171	03/03/2015	PROG5038NRU58DV	RUUD	0
19172	03/09/2015	M45036FBN	BRADFORD WHITE	1
19173	03/10/2015	M45036FBN	BRADFORD WHITE	0
19174	03/10/2015	M45036FBN	BRADFORD WHITE	0
19175	02/26/2015	PROG5038NRU58DV	RUUD	0
19176	03/09/2015	G91200	RUUD/RHEEM	0
19177	03/03/2015	M2XR504T6FBN	BRADFORD WHITE	1
19178	03/06/2015	M45036FBN	BRADFORD WHITE	0
19179	03/09/2015	PROG5038NRU58DV	RUUD	0
19180	03/10/2015	M45036FBN	BRADFORD WHITE	0
19181	03/10/2015	PROG5038NRU58DV	RUUD	0
19182	03/11/2015	MI5036FBN	BRADFORD WHITE	0
19183	03/11/2015	MI75S6FBN	BRADFORD WHITE	1
19184	03/09/2015	G91200	RUUD/RHEEM	0
19185	03/13/2015	M440T6FBN	BRADFORD WHITE	0
19186	03/11/2015	MI75S6FBN	BRADFORD WHITE	0
19187	03/12/2015	MI5036FBN	BRADFORD WHITE	0
19188	03/05/2015	M45036FBN	BRADFORD WHITE	0
19189	03/14/2015	G91200	RUUD/RHEEM	0
19190	03/13/2015	MI5036FBN	BRADFORD WHITE	0
19191	03/13/2015	M45036FBN	BRADFORD WHITE	0
19192	03/12/2015	MI5036FBN	BRADFORD WHITE	0
19193	03/11/2015	M45036FBN	BRADFORD WHITE	0
19194	02/27/2015	PROG5038NRU58DV	RUUD	0
19195	03/13/2015	MI40T6FBN	BRADFORD WHITE	0
19196	03/19/2015	MI40T6FBN	BRADFORD WHITE	0
19197	03/19/2015	G76200	RUUD	0
19198	03/10/2015	PROG5038NRU58DV	Ruud/Rheem	0
19199	03/09/2015	MI5036FBN	Bradford White	0
19200	03/18/2015	MI50L6FBN	BRADFORD WHITE	0
19201	03/16/2015	G82156	RUUD	0
19202	03/16/2015	MI5036FBN	BRADFORD WHITE	0
19203	03/10/2015	MI403S6FBN	BRADFORD WHITE	2
19204	03/18/2015	M45036FBN	Bradford White	0
19205	03/16/2015	MI5036FBN	Bradford White	0
19206	03/17/2015	M45036FBN	Bradford White	0
19207	03/07/2015	M45036FBN	Bradford White	0
19208	03/24/2015	M440T6FBN	BRADFORD WHITE	0
19209	03/16/2015	M45036FBN	BRADFORD WHITE	0
19210	03/24/2015	PROG5038NRU58DV	RUUD	0
19211	03/21/2015	M45036FBN	BRADFORD WHITE	0
19212	03/18/2015	MI5036FBN	Bradford White	0
19213	03/13/2015	MI5036FBN	BRADFORD WHITE	0
19214	03/18/2015	MI40T6FBN	BRADFORD WHITE	0
19215	03/14/2015	M45036FBN	BRADFORD WHITE	0
19216	03/13/2015	DS140S6FBN	BRADFORD WHITE	0
19217	03/13/2015	MI5036FBN	BRADFORD WHITE	0
19218	03/09/2015	M45036FBN	BRADFORD WHITE	0
19219	03/19/2015	M45036FBN	BRADFORD WHITE	0
19220	03/19/2015	MI5036FBN	BRADFORD WHITE	0
19221	03/27/2015	MI5036FBN	Bradford White	0
19222	03/26/2015	MI5036FBN	Bradford White	0
19223	03/26/2015	MI403S6FBN	Bradford White	0
19224	03/25/2015	M45036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19225	03/23/2015	M45036FBN	Bradford White	2
19226	03/27/2015	MI5036FBN	BRADFORD WHITE	0
19227	03/25/2015	M45036FBN	BRADFORD WHITE	0
19228	03/29/2015	M45036FBN	BRADFORD WHITE	0
19229	03/16/2015	MI5036FBN	BRADFORD WHITE	0
19230	04/02/2015	MI403S6FBN	BRADFORD WHITE	0
19231	04/02/2015	M45036FBN	BRADFORD WHITE	0
19232	03/31/2015	MI5036FBN	BRADFORD WHITE	0
19233	03/27/2015	MI5036FBN	BRADFORD WHITE	0
19234	03/30/2015	M45036FBN	BRADFORD WHITE	0
19235	03/30/2015	MI75S6FBN	BRADFORD WHITE	0
19236	03/20/2015	M45036FBN	BRADFORD WHITE	0
19237	03/28/2015	PROG5038NRU58DV	RUUD	0
19238	03/25/2015	PROG5038NRU58DV	Ruud/Rheem	0
19239	03/26/2015	G91200	Ruud/Rheem	5
19240	03/17/2015	MI5036FBN	Bradford White	0
19241	04/14/2015	MI40T6FBN	Bradford White	0
19242	03/31/2015	PROG5038NRU58DV	RUUD	0
19243	03/31/2015	PROG5038RU58DV	RUUD	0
19244	03/28/2015	MI5036FBN	BRADFORD WHITE	0
19245	03/30/2015	M45036FBN	BRADFORD WHITE	0
19246	03/27/2015	MI5036FBN	BRADFORD WHITE	0
19247	03/20/2015	G91200	RUUD	0
19248	04/08/2015	MI5036FBN	Bradford White	0
19249	04/02/2015	M45036FBN	Bradford White	0
19250	04/01/2015	MI5036FBN	Bradford White	0
19251	04/07/2015	MI5036FBN	Bradford White	0
19252	04/03/2015	M45036FBN	BRADFORD WHITE	0
19253	04/02/2015	PROG5038NRU58DV	RUUD	0
19254	04/01/2015	M45036FBN	BRADFORD WHITE	0
19255	04/02/2015	M45036FBN	BRADFORD WHITE	0
19256	04/02/2015	PROG5038NRU58DV	RUUD	0
19257	04/06/2015	M45036FBN	BRADFORD WHITE	1
19258	04/13/2015	MI5036FBN	BRADFORD WHITE	0
19259	04/07/2015	M440T6FBN	BRADFORD WHITE	0
19260	03/27/2015	PROG5038NRU58DV	Ruud/Rheem	0
19261	03/27/2015	PROG5038NRU58DV	Ruud/Rheem	0
19262	03/29/2015	MI5036FBN	Bradford White	0
19263	03/28/2015	M45036FBN	Bradford White	0
19264	03/30/2015	M45036FBN	Bradford White	0
19265	03/30/2015	M45036FBN	Bradford White	0
19266	03/30/2015	MI5036FBN	Bradford White	1
19267	03/31/2015	PROG5038NRU58DV	Ruud	0
19268	03/18/2015	MI403S6FBN	BRADFORD WHITE	0
19269	03/20/2015	M45036FBN	BRADFORD WHITE	1
19270	03/19/2015	M45036FBN	BRADFORD WHITE	2
19271	03/21/2015	M45036FBN	BRADFORD WHITE	0
19272	03/20/2015	M440T6FBN	BRADFORD WHITE	0
19273	03/20/2015	MI5036FBN	BRADFORD WHITE	0
19274	03/18/2015	M45036FBN	BRADFORD WHITE	0
19275	03/11/2015	MI403S6FBN	BRADFORD WHITE	0
19276	03/24/2015	PROG5038NRU58DV	RUUD	0
19277	03/20/2015	MI5036FBN	BRADFORD WHITE	0
19278	03/20/2015	MI5036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19279	03/23/2015	MI5036FBN	BRADFORD WHITE	0
19280	03/25/2015	MI5036FBN	Bradford White	0
19281	03/10/2015	M45036FBN	BRADFORD WHITE	0
19282	03/26/2015	G91200	RUUD	0
19283	03/17/2015	MI5036FBN	BRADFORD WHITE	0
19284	03/24/2015	MI5036FBN	BRADFORD WHITE	0
19285	03/26/2015	MI5036FBN	BRADFORD WHITE	0
19286	03/25/2015	M45036FBN	BRADFORD WHITE	0
19287	03/26/2015	M45036FBN	BRADFORD WHITE	0
19288	03/28/2015	M45036FBN	BRADFORD WHITE	1
19289	04/06/2015	MI403S6FBN	BRADFORD WHITE	0
19290	04/02/2015	PROG5038NRU58DV	RUUD	0
19291	03/27/2015	M45036FBN	BRADFORD WHITE	0
19292	03/27/2015	PROG5038NRU58DV	RUUD	0
19293	03/27/2015	M45036FBN	BRADFORD WHITE	0
19294	03/19/2015	MI5036FBN	BRADFORD WHITE	0
19295	03/19/2015	MI5036FBN	BRADFORD WHITE	0
19296	03/24/2015	MI403S6FBN	BRADFORD WHITE	0
19297	03/25/2015	MI5036FBN	BRADFORD WHITE	0
19298	03/25/2015	M45036FBN	BRADFORD WHITE	0
19299	03/26/2015	M45036FBN	BRADFORD WHITE	0
19300	03/23/2015	MI40T6FBN	BRADFORD WHITE	0
19301	04/08/2015	M45036FBN	BRADFORD WHITE	0
19302	04/17/2015	G91200	RUUD/RHEEM	1
19303	04/03/2015	MI403S6FBN	BRADFORD-WHITE	0
19304	04/08/2015	MI5036FBN	BRADFORD-WHITE	0
19305	04/02/2015	PROG5038NRU58DV	Ruud	0
19306	03/16/2015	M45036FBN	Bradford White	0
19307	04/01/2015	M45036FBN	Bradford White	0
19308	04/02/2015	MI5036FBN	Bradford White	0
19309	04/08/2015	MI50L6FBN	BRADFORD WHITE	0
19310	04/14/2015	M440T6FBN	Bradford White	1
19311	04/14/2015	M440T6FBN	BRADFORD WHITE	1
19312	04/08/2015	M440T6FBN	BRADFORD WHITE	0
19313	04/09/2015	MI5036FBN	BRADFORD WHITE	1
19314	04/03/2015	MI403S6FBN	Bradford White	1
19315	04/07/2015	M45036FBN	Bradford White	0
19316	04/16/2015	M440T6FBN	Bradford White	0
19317	04/16/2015	MI5036FBN	Bradford White	0
19318	04/16/2015	MI403S6FBN	Bradford White	0
19319	04/15/2015	M440T6FBN	Bradford White	0
19320	04/03/2015	M45036FBN	BRADFORD WHITE	0
19321	04/10/2015	M45036FBN	BRADFORD WHITE	0
19322	04/16/2015	M45036FBN	BRADFORD WHITE	0
19323	04/15/2015	PROG5038NRU58	RUUD	0
19324	04/16/2015	M2XR504T6FBN	BRADFORD WHITE	0
19325	04/11/2015	M45036FBN	BRADFORD WHITE	0
19326	04/10/2015	MI5036FBN	BRADFORD WHITE	0
19327	04/09/2015	M440T6FBN	BRADFORD WHITE	0
19328	04/09/2015	M440T6FBN	BRADFORD WHITE	0
19329	04/20/2015	M2XR504T6FBN	BRADFORD WHITE	0
19330	04/17/2015	M45036FBN	BRADFORD WHITE	0
19331	04/16/2015	M440T6FBN	BRADFORD WHITE	0
19332	04/20/2015	PROG5038NRU58	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19333	04/22/2015	M45036FBN	BRADFORD WHITE	0
19334	04/02/2015	M45036FBN	BRADFORD WHITE	0
19335	04/14/2015	MI5036FBN	BRADFORD WHITE	0
19336	04/15/2015	MI5036FBN	BRADFORD WHITE	0
19337	04/16/2015	PROG5038NRU58DV	RUUD	0
19338	04/04/2015	FSG50	AO SMITH	0
19339	04/08/2015	MI5036FBN	BRADFORD WHITE	0
19340	04/08/2015	MI40T6FBN	BRADFORD WHITE	0
19341	04/14/2015	PROG5038NRU60DV	RUUD	0
19342	04/13/2015	M45036FBN	BRADFORD WHITE	0
19343	03/24/2015	M45036FBN	BRADFORD WHITE	0
19344	04/21/2015	PROG5038NRU58DV	RUUD	0
19345	04/17/2015	M45036FBN	BRADFORD WHITE	0
19346	04/15/2015	MI5036FBN	Bradford White	0
19347	05/18/2015	M2XR504T6FBN	BRADFORD WHITE	0
19348	04/17/2015	M440T6FBN	Bradford White	0
19349	04/17/2015	M45036FBN	Bradford White	0
19350	04/15/2015	MI40T6FBN	Bradford White	0
19351	04/20/2015	FSG40	AO SMITH	0
19352	04/01/2015	MI40T6FBN	Bradford White	0
19353	04/03/2015	MI5036FBN	BRADFORD WHITE	0
19354	04/20/2015	PROG5038NRU60	RUUD	0
19355	04/01/2015	G75125	RUUD/RHEEM	0
19356	04/28/2015	MI40T6FBN	BRADFORD WHITE	1
19357	04/15/2015	DS140S6FBN	BRADFORD WHITE	1
19358	04/23/2015	PROG5038NRU58	RUUD	0
19359	04/22/2015	MI5036FBN	BRADFORD WHITE	0
19360	04/21/2015	MI50L6FBN	BRADFORD WHITE	0
19361	04/17/2015	MI5036FBN	BRADFORD WHITE	0
19362	05/04/2015	PROG5038NRU58DV	Ruud/Rheem	0
19363	05/05/2015	G75125	RUUD/RHEEM	0
19364	05/10/2015	G91200	RUUD/RHEEM	0
19365	04/29/2015	MI5036FBN	Bradford White	0
19366	04/24/2015	M45036FBN	Bradford White	0
19367	04/13/2015	M45036FBN	Bradford White	0
19368	04/16/2015	M45036FBN	BRADFORD WHITE	1
19369	04/15/2015	PROG5038NRU58DV	RUUD	0
19370	04/10/2015	MI5036FBN	BRADFORD WHITE	0
19371	04/17/2015	MI403S6FBN	BRADFORD WHITE	0
19372	03/26/2015	M45036FBN	BRADFORD WHITE	0
19373	03/25/2015	M45036FBN	Bradford White	1
19374	04/15/2015	M440T6FBN	Bradford White	0
19375	04/09/2015	M45036FBN	Bradford White	0
19376	04/21/2015	M45036FBN	BRADFORD WHITE	0
19377	04/16/2015	M45036FBN	BRADFORD WHITE	0
19378	04/20/2015	MI5036FBN	BRADFORD WHITE	1
19379	04/10/2015	MI5036FBN	BRADFORD WHITE	0
19380	04/15/2015	M45036FBN	BRADFORD WHITE	0
19381	04/13/2015	MI5036FBN	BRADFORD WHITE	0
19382	04/17/2015	M45036FBN	BRADFORD WHITE	0
19383	04/19/2015	G76200	RUUD	0
19384	04/15/2015	MI403S6FBN	BRADFORD WHITE	0
19385	04/09/2015	G91200	RUUD	0
19386	04/10/2015	G91200	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19387	04/13/2015	G91200	RUUD	1
19388	04/08/2015	G75125	RUUD	0
19389	04/23/2015	G91200	RUUD	0
19390	04/17/2015	M45036FBN	BRADFORD WHITE	2
19391	05/01/2015	MI5036FBN	BRADFORD WHITE	0
19392	05/04/2015	M45036FBN	BRADFORD WHITE	0
19393	04/29/2015	M440T6FBN	BRADFORD WHITE	2
19394	04/29/2015	MI403S6FBN	BRADFORD WHITE	0
19395	04/25/2015	MI5036FBN	BRADFORD WHITE	0
19396	04/29/2015	PH199119	PHOENIX	0
19397	04/29/2015	G91200	RUUD	0
19398	05/06/2015	MI5036FBN	BRADFORD WHITE	0
19399	05/06/2015	M45036FBN	BRADFORD WHITE	0
19400	05/07/2015	M45036FBN	BRADFORD WHITE	0
19401	05/04/2015	MI5036FBN	BRADFORD WHITE	0
19402	05/04/2015	MI5036FBN	BRADFORD WHITE	0
19403	05/01/2015	MI403S6FBN	BRADFORD WHITE	0
19404	05/05/2015	G82156	RUUD	0
19405	05/05/2015	G82156	RUUD	2
19406	05/11/2015	M45036FBN	BRADFORD WHITE	0
19407	05/06/2015	MI5036FBN	BRADFORD WHITE	0
19408	05/11/2015	G76200	RUUD	0
19409	04/26/2015	M45036FBN	Bradford White	0
19410	04/18/2015	M2XR504T6FBN	Bradford White	0
19411	03/28/2015	M2XR504T6FBN	Bradford White	1
19412	04/28/2015	M45036FBN	BRADFORD WHITE	0
19413	04/27/2015	PROG5038NRU58DV	RUUD	0
19414	04/22/2015	MI5036FBN	BRADFORD WHITE	1
19415	04/27/2015	M440T6FBN	BRADFORD WHITE	0
19416	04/20/2015	MI403S6FBN	BRADFORD WHITE	0
19417	04/21/2015	M45036FBN	BRADFORD WHITE	0
19418	04/22/2015	MI403S6FBN	BRADFORD WHITE	0
19419	04/26/2015	M45036FBN	BRADFORD WHITE	0
19420	04/25/2015	MI5036FBN	BRADFORD WHITE	1
19421	05/01/2015	M45036FBN	BRADFORD WHITE	0
19422	05/01/2015	M45036FBN	BRADFORD WHITE	0
19423	05/02/2015	M45036FBN	BRADFORD WHITE	0
19424	05/01/2015	M45036FBN	BRADFORD WHITE	0
19425	04/29/2015	PH13080	PHOENIX	0
19426	04/29/2015	PH199119	PHOENIX	0
19427	04/29/2015	G91200	RUUD/RHEEM	0
19428	05/08/2015	M45036FBN	BRADFORD WHITE	0
19429	04/13/2015	M45036FBN	Bradford White	0
19430	04/09/2015	G91200	RUUD/RHEEM	1
19431	05/05/2015	MI5036FBN	BRADFORD WHITE	1
19432	05/04/2015	MI5036FBN	BRADFORD WHITE	0
19433	04/20/2015	MI5036FBN	BRADFORD WHITE	4
19434	04/26/2015	G91200	RUUD	0
19435	04/22/2015	M2XR504T6FBN	BRADFORD WHITE	3
19436	04/24/2015	M45036FBN	BRADFORD WHITE	0
19437	05/18/2015	MI5036FBN	Bradford White	0
19438	05/14/2015	PROG5038NRU58DV	Ruud/Rheem	0
19439	05/16/2015	MI403S6FBN	Bradford White	1
19440	05/12/2015	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19441	05/19/2015	PROG5038NRU58DV	BRADFORD WHITE	0
19442	05/13/2015	MI5036FBN	BRADFORD WHITE	0
19443	05/01/2015	MI403S6FBN	BRADFORD WHITE	1
19444	05/06/2015	MI50L6FBN	BRADFORD WHITE	0
19445	05/19/2015	M2XR504T6FBN	BRADFORD WHITE	0
19446	05/20/2015	M45036FBN	BRADFORD WHITE	0
19447	06/02/2015	MI5036FBN	Bradford White	0
19448	05/22/2015	M45036FBN	Bradford White	0
19449	05/26/2015	M45036FBN	Bradford White	0
19450	05/29/2015	PROG5038NRU58DV	Ruud/Rheem	0
19451	05/22/2015	MI5036FBN	Bradford White	0
19452	06/03/2015	M45036FBN	Bradford White	0
19453	06/02/2015	MI5036FBN	Bradford White	0
19454	06/02/2015	MI5036FBN	Bradford White	0
19455	06/02/2015	M45036FBN	Bradford White	0
19456	06/05/2015	MI5036FBN	Bradford White	0
19457	06/04/2015	M45036FBN	Bradford White	0
19458	05/10/2015	M2XR504T6FBN	BRADFORD WHITE	0
19459	06/04/2015	M45036FBN	BRADFORD WHITE	0
19460	06/08/2015	M45036FBN	BRADFORD WHITE	1
19461	05/30/2015	M45036FBN	BRADFORD WHITE	0
19462	06/08/2015	MI403S6FBN	BRADFORD WHITE	0
19463	05/30/2015	M440T6FBN	BRADFORD WHITE	0
19464	12/16/2013	MI75S6FBN	BRADFORD WHITE	0
19465	05/02/2015	MI5036FBN	BRADFORD WHITE	2
19466	05/11/2015	M45036FBN	BRADFORD WHITE	1
19467	05/09/2015	M45036FBN	BRADFORD WHITE	0
19468	04/20/2015	MI40T6FBN	BRADFORD WHITE	0
19469	04/21/2015	MI5036FBN	Bradford White	0
19470	04/23/2015	G91200	Ruud/Rheem	0
19471	04/08/2015	G91200	Ruud/Rheem	0
19472	04/20/2015	M45036FBN	Bradford White	0
19473	04/16/2015	MI5036FBN	Bradford White	0
19474	04/24/2015	M45036FBN	Bradford White	0
19475	05/06/2015	M45036FBN	Bradford White	0
19476	05/06/2015	MI5036FBN	Bradford White	0
19477	05/07/2015	MI5036FBN	Bradford White	0
19478	05/12/2015	M45036FBN	Bradford White	0
19479	03/26/2015	PROG5038NRU58	Ruud/Rheem	0
19480	05/02/2015	MI75S6FBN	Bradford White	0
19481	04/27/2015	G75125	Ruud/Rheem	0
19482	05/01/2015	M45036FBN	Bradford White	0
19483	05/01/2015	PROG5038nru58DV	Ruud/Rheem	0
19484	05/01/2015	M45036FBN	Bradford White	0
19485	04/28/2015	PR502T	RUUD	0
19486	05/04/2015	PROG5038NRU58DV	Ruud/Rheem	0
19487	05/04/2015	MI5036FBN	Bradford White	0
19488	04/29/2015	MI5036FBN	Bradford White	0
19489	04/30/2015	MI5036FBN	Bradford White	0
19490	04/30/2015	M45036FBN	Bradford White	0
19491	05/11/2015	G91200	RHEEM	0
19492	05/20/2015	M45036FBN	BRADFORD WHITE	0
19493	05/13/2015	MI5036FBN	BRADFORD WHITE	0
19494	05/20/2015	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19495	05/21/2015	MI75S6FBN	BRADFORD WHITE	0
19496	05/15/2015	MI40T6FBN	Bradford White	0
19497	05/13/2015	PROG2932NRU62	Ruud/Rheem	0
19498	05/20/2015	M45036FBN	BRADFORD WHITE	1
19499	05/09/2015	MI40T6FBN	BRADFORD WHITE	0
19500	05/18/2015	M45036FBN	Bradford White	0
19501	05/12/2015	PROG2932NRU62	Ruud/Rheem	0
19502	05/18/2015	M45036FBN	BRADFORD WHITE	1
19503	05/14/2015	M45036FBN	BRADFORD WHITE	0
19504	05/14/2015	MI5036FBN	BRADFORD WHITE	0
19505	05/21/2015	M45036FBN	BRADFORD WHITE	0
19506	05/21/2015	M440T6FBN	BRADFORD WHITE	0
19507	05/14/2015	M45036FBN	BRADFORD WHITE	0
19508	05/19/2015	M45036FBN	BRADFORD WHITE	0
19509	05/20/2015	M45036FBN	BRADFORD WHITE	0
19510	05/16/2015	MI5036FBN	BRADFORD WHITE	0
19511	05/05/2015	M45036FBN	BRADFORD WHITE	0
19512	05/08/2015	M440T6FBN	BRADFORD WHITE	0
19513	05/11/2015	M45036FBN	BRADFORD WHITE	0
19514	05/05/2015	MI5036FBN	BRADFORD WHITE	0
19515	06/12/2015	M45036FBN	BRADFORD WHITE	0
19516	05/08/2015	M45036FBN	BRADFORD WHITE	1
19517	05/08/2015	MI40T6FBN	BRADFORD WHITE	0
19518	05/15/2015	MI5036FBN	BRADFORD WHITE	0
19519	05/14/2015	M45036FBN	BRADFORD WHITE	0
19520	05/28/2015	M45036FBN	BRADFORD WHITE	0
19521	05/30/2015	PROG5038NRU58DV	RUUD	1
19522	05/28/2015	MI5036FBN	BRADFORD WHITE	0
19523	05/19/2015	MI403S6FBN	BRADFORD WHITE	0
19524	05/28/2015	M45036FBN	BRADFORD WHITE	0
19525	05/22/2015	M45036FBN	BRADFORD WHITE	0
19526	05/24/2015	M45036FBN	BRADFORD WHITE	0
19527	05/24/2015	PROG5038NRU58DV	RUUD	0
19528	05/27/2015	M45036FBN	BRADFORD WHITE	0
19529	05/19/2015	MI403S6FBN	BRADFORD WHITE	0
19530	05/29/2015	G91200	RUUD/RHEEM	7
19531	05/29/2015	G91200	RUUD	0
19532	05/15/2015	M440T6FBN	BRADFORD WHITE	0
19533	06/02/2015	M45036FBN	BRADFORD WHITE	0
19534	06/02/2015	M45036FBN	BRADFORD WHITE	0
19535	06/01/2015	M2XR504T6FBN	BRADFORD WHITE	0
19536	06/01/2015	M45036FBN	BRADFORD WHITE	0
19537	05/22/2015	MI5036FBN	BRADFORD WHITE	1
19538	06/03/2015	M45036FBN	BRADFORD WHITE	1
19539	10/14/2014	G91200	RUUD	2
19540	04/30/2015	MI5036FBN	Bradford White	0
19541	05/08/2015	M45036FBN	Bradford White	0
19542	05/10/2015	M45036FBN	Bradford White	0
19543	05/11/2015	M45036FBN	Bradford White	0
19544	05/11/2015	MI40T6FBN	Bradford White	0
19545	05/15/2015	MI50L6FBN	Bradford White	0
19546	05/15/2015	MI5036FBN	Bradford White	0
19547	05/14/2015	MI40T6FBN	Bradford White	0
19548	05/18/2015	G76200	Ruud/Rheem	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19549	05/14/2015	M45036FBN	Bradford White	0
19550	05/21/2015	M45036FBN	Bradford White	1
19551	04/30/2015	MI5036FBN	Bradford White	0
19552	05/13/2015	MI40T6FBN	Bradford White	0
19553	05/27/2015	M45036FBN	Bradford White	0
19554	05/31/2015	G75125	RUUD/RHEEM	3
19555	05/29/2015	M45036FBN	Bradford White	0
19556	06/08/2015	MI403S6FBN	BRADFORD WHITE	0
19557	05/21/2015	MI40T6FBN	BRADFORD WHITE	1
19558	05/29/2015	PROG5038NRU58DV	RUUD	4
19559	05/28/2015	MI5036FBN	BRADFORD WHITE	0
19560	05/21/2015	MI403S6FBN	BRADFORD WHITE	0
19561	05/18/2015	MI40T6FBN	BRADFORD WHITE	0
19562	05/29/2015	M45036FBN	BRADFORD WHITE	1
19563	05/26/2015	M440T6FBN	Bradford White	0
19564	06/04/2015	M45036FBN	Bradford White	0
19565	02/29/2008	G91200	RUUD/RHEEM	2
19566	05/28/2015	MI403S6FBN	Bradford White	0
19567	05/26/2015	M45036FBN	Bradford White	1
19568	05/13/2015	PROG5038NRU58DV	Ruud/Rheem	0
19569	05/28/2015	MI5036FBN	Bradford White	0
19570	05/28/2015	PROG5038NRU58DV	Ruud/Rheem	0
19571	05/20/2015	MI50L6FBN	Bradford White	0
19572	05/22/2015	MI403S6FBN	Bradford White	3
19573	05/31/2015	MI40T6FBN	Bradford White	0
19574	06/01/2015	M45036FBN	Bradford White	1
19575	06/05/2015	MI5036FBN	Bradford White	0
19576	06/05/2015	MI5036FBN	Bradford White	0
19577	06/02/2015	M45036FBN	Bradford White	0
19578		MI40T6FBN	Bradford White	0
19579	04/14/2015	G82156	RUUD	0
19580	06/02/2015	MI40T6FBN	BRADFORD WHITE	0
19581	05/19/2015	MI5036FBN	BRADFORD WHITE	0
19582	06/03/2015	M45036FBN	BRADFORD WHITE	0
19583	06/03/2015	PROG5038NRU58DV	RUUD	0
19584	06/10/2015	FSG40	AO SMITH	0
19585	06/05/2015	MI403S6FBN	Bradford White	0
19586	06/12/2015	FSG40	AO SMITH	0
19587	06/16/2015	FSGL40	AO SMITH	0
19588	06/11/2015	LTN050GEF	LOCHINVAR	0
19589	06/05/2015	MI40T6FBN	Bradford White	0
19590	06/11/2015	M45036FBN	Bradford White	0
19591	06/11/2015	M45036FBN	Bradford White	0
19592	06/12/2015	MI5036FBN	Bradford White	0
19593	06/16/2015	M45036FBN	Bradford White	0
19594	06/11/2015	M45036FBN	Bradford White	0
19595	06/15/2015	M45036FBN	Bradford White	0
19596	06/11/2015	M45036FBN	Bradford White	0
19597	06/16/2015	M45036FBN	Bradford White	0
19598	05/26/2015	M45036FBN	BRADFORD WHITE	0
19599	05/27/2015	PROG5038NRU58DV	RUUD	0
19600	05/27/2015	G91200	RUUD	1
19601	05/15/2015	M45036FBN	Bradford White	0
19602	05/27/2015	G91200	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19603	06/03/2015	MI5036FBN	BRADFORD WHITE	0
19604	06/09/2015	MI5036FBN	BRADFORD WHITE	0
19605	05/29/2015	MI40T6FBN	BRADFORD WHITE	0
19606	05/30/2015	MI5036FBN	BRADFORD WHITE	0
19607	06/02/2015	MI5036FBN	BRADFORD WHITE	0
19608	06/09/2015	PROG5038NRU58DV	RUUD	0
19609	06/03/2015	MI403S6FBN	BRADFORD WHITE	0
19610	06/04/2015	MI40T6FBN	BRADFORD WHITE	0
19611	06/04/2015	M45036FBN	BRADFORD WHITE	0
19612	06/11/2015	PROG2932NRU62	RUUD	0
19613	05/29/2015	MI403S6FBN	BRADFORD WHITE	0
19614	06/26/2015	MI5036FBN	BRADFORD WHITE	0
19615	06/12/2015	MI5036FBN	Bradford White	0
19616	06/04/2015	MI5036FBN	Bradford White	0
19617	06/09/2015	MI5036FBN	Bradford White	0
19618	06/11/2015	MI5036FBN	Bradford White	0
19619	06/12/2015	PROG5038NRU58DV	Ruud/Rheem	0
19620	06/11/2015	M45036FBN	Bradford White	0
19621	06/10/2015	MI40T6FBN	Bradford White	0
19622	06/10/2015	MI5036FBN	Bradford White	0
19623	06/10/2015	DS150S6FBN	Bradford White	0
19624	06/15/2015	M440T6FBN	Bradford White	0
19625	06/17/2015	M45036FBN	Bradford White	0
19626	06/17/2015	MI5036FBN	Bradford White	0
19627	06/18/2015	MI40T6FBN	Bradford White	0
19628	05/28/2015	MI5036FBN	Bradford White	0
19629	06/22/2015	PROG2932NRU62	RUUD/RHEEM	0
19630	06/07/2015	MI40T6FBN	Bradford White	0
19631	06/29/2015	M440T6FBN	Bradford White	0
19632	06/17/2015	M45036FBN	Bradford White	0
19633	06/16/2015	PROG5036NRU60	RUUD/RHEEM	0
19634	06/20/2015	MI5036FBN	Bradford White	0
19635	06/18/2015	M440T6FBN	Bradford White	0
19636	05/26/2015	M45036FBN	Bradford White	0
19637	06/08/2015	MI5036FBN	Bradford White	0
19638	06/12/2015	MI403S6FBN	Bradford White	1
19639	06/15/2015	PROG5038NRU58	RUUD/RHEEM	0
19640	06/15/2015	M45036FBN	Bradford White	0
19641	06/11/2015	MI5036FBN	Bradford White	0
19642	06/12/2015	M45036FBN	Bradford White	1
19643	06/11/2015	PROG5038NRU58	RUUD/RHEEM	0
19644	06/15/2015	M440T6FBN	Bradford White	0
19645	06/05/2015	M45036FBN	Bradford White	0
19646	05/22/2015	MI5036FBN	Bradford White	0
19647	06/04/2015	M45036FBN	Bradford White	0
19648	06/06/2015	MI40T6FBN	Bradford White	0
19649	07/01/2015	MI403S6FBN	Bradford White	0
19650	07/01/2015	M45036FBN	Bradford White	0
19651	07/02/2015	MI5036FBN	Bradford White	0
19652	07/02/2015	MI5036FBN	Bradford White	0
19653	07/06/2015	PROG5038NRU58	RUUD/RHEEM	0
19654	06/16/2015	MI5036FBN	Bradford White	0
19655	06/18/2015	MI403S6FBN	Bradford White	0
19656	06/18/2015	MI5036FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19657	06/19/2015	M45036FBN	Bradford White	0
19658	06/19/2015	PROG5038NRU58	RUUD/RHEEM	0
19659	06/19/2015	MI5036FBN	Bradford White	0
19660	06/23/2015	MI5036FBN	Bradford White	0
19661	06/23/2015	MI40T6FBN	Bradford White	0
19662	06/23/2015	M45036FBN	Bradford White	0
19663	06/24/2015	M45036FBN	Bradford White	0
19664	06/25/2015	PROG5038NRU58	RUUD/RHEEM	0
19665	06/25/2015	M45036FBN	Bradford White	0
19666	06/25/2015	G91200	RUUD/RHEEM	0
19667	06/08/2015	M45036FBN	Bradford White	0
19668	06/16/2015	MI40T6FBN	Bradford White	0
19669	06/17/2015	MI5036FBN	Bradford White	1
19670	06/19/2015	MI5036FBN	Bradford White	0
19671	06/20/2015	MI403S6FBN	Bradford White	0
19672	06/21/2015	MI5036FBN	Bradford White	0
19673	06/22/2015	DS150S6FBN	Bradford White	0
19674	06/23/2015	MI5036FBN	Bradford White	0
19675	06/23/2015	DS150S6FBN	Bradford White	1
19676	06/24/2015	M45036FBN	Bradford White	0
19677	06/25/2015	M440T6FBN	Bradford White	1
19678	06/25/2015	G91200	Ru	0
19679	05/18/2015	M45036FBN	Bradford White	0
19680	06/16/2015	MI5036FBN	Bradford White	0
19681	06/22/2015	M45036FBN	Bradford White	1
19682	06/26/2015	G91200	RUUD/RHEEM	0
19683	06/26/2015	G91200	RUUD/RHEEM	0
19684	06/27/2015	M45036FBN	Bradford White	0
19685	06/29/2015	MI5036FBN	Bradford White	0
19686	06/29/2015	M45036FBN	Bradford White	0
19687	06/26/2015	MI40T6FBN	Bradford White	0
19688	06/24/2015	MI5036FBN	Bradford White	0
19689	06/25/2015	MI5036FBN	Bradford White	0
19690	06/26/2015	M45036FBN	Bradford White	0
19691	06/26/2015	G82156	RUUD/RHEEM	0
19692	06/29/2015	M45036FBN	Bradford White	0
19693	06/30/2015	MI5036FBN	Bradford White	1
19694	06/30/2015	M45036FBN	Bradford White	3
19695	06/25/2015	M45036FBN	Bradford White	0
19696	06/25/2015	MI5036FBN	Bradford White	0
19697	07/01/2015	G91200	RUUD/RHEEM	2
19698	07/02/2015	MI403S6FBN	Bradford White	0
19699	07/02/2015	MI5036FBN	Bradford White	0
19700	07/02/2015	PROG5036NRU60DV	RUUD/RHEEM	0
19701	07/03/2015	M45036FBN	Bradford White	0
19702	07/06/2015	MI5036FBN	Bradford White	0
19703	07/06/2015	PROG5036NRU60	RUUD/RHEEM	0
19704	07/06/2015	M440T6FBN	Bradford White	0
19705	07/06/2015	M45036FBN	Bradford White	0
19706	07/06/2015	M45036FBN	Bradford White	0
19707	07/02/2015	PROG5038NRU58	RUUD/RHEEM	1
19708	07/07/2015	M45036FBN	Bradford White	0
19709	07/06/2015	PH13080	Phoenix	4
19710	07/07/2015	G91200	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19711	06/12/2015	PROG5038NRU58	RUUD	2
19712	06/03/2015	MI5036FBN	Bradford White	0
19713	06/15/2015	MI5036FBN	Bradford White	0
19714	06/24/2015	MI40T6FBN	Bradford White	0
19715	06/25/2015	M45036FBN	Bradford White	0
19716	06/26/2015	M45036FBN	Bradford White	0
19717	06/29/2015	MI5036FBN	Bradford White	0
19718	06/29/2015	MI40T6FBN	Bradford White	0
19719	06/29/2015	PROG5038NRU58	RUUD/RHEEM	0
19720	06/30/2015	MI5036FBN	Bradford White	0
19721	06/30/2015	G91200	RUUD/RHEEM	0
19722	06/18/2015	G91200	RUUD/RHEEM	1
19723	07/15/2015	M45036FBN	BRADFORD WHITE	0
19724	07/01/2015	PROG5038NRU58DV	RUUD	1
19725	07/09/2015	M45036FBN	BRADFORD WHITE	0
19726	07/08/2015	PROG5036NRU60DV	RUUD	0
19727	07/08/2015	M45036FBN	BRADFORD WHITE	0
19728	07/15/2015	PROG5038NRU58DV	Ruud/Rheem	0
19729	07/13/2015	M45036FBN	Bradford White	0
19730	07/13/2015	M45036FBN	Bradford White	0
19731	07/10/2015	MI5036FBN	Bradford White	0
19732	07/15/2015	M45036FBN	Bradford White	0
19733	07/14/2015	MI40S6FBN	BRADFORD WHITE	0
19734	07/14/2015	M2XR504T6FBN	BRADFORD WHITE	0
19735	07/01/2015	M45036FBN	BRADFORD WHITE	0
19736	07/14/2015	M45036FBN	BRADFORD WHITE	1
19737	07/08/2015	M45036FBN	BRADFORD WHITE	0
19738	07/17/2015	PROG5038NRU58DV	RUUD	0
19739	07/17/2015	M45036FBN	BRADFORD WHITE	0
19740	07/20/2015	M45036FBN	BRADFORD WHITE	0
19741	07/28/2015	G82156	RUUD/RHEEM	1
19742	07/28/2015	G82156	RUUD/RHEEM	0
19743	07/01/2015	G91200	RUUD/RHEEM	1
19744	07/01/2015	G91200	RUUD/RHEEM	0
19745	07/27/2015	M45036FBN	Bradford White	0
19746	08/03/2015	G91200	RUUD/RHEEM	0
19747	08/03/2015	G82156	RUUD/RHEEM	0
19748	07/16/2015	M45036FBN	Bradford White	0
19749	07/17/2015	M45036FBN	Bradford White	0
19750	07/22/2015	M45036FBN	Bradford White	1
19751	07/23/2015	MI5036FBN	Bradford White	1
19752	07/10/2015	M2XR504T6FBN	Bradford White	0
19753	07/23/2015	MI5036FBN	Bradford White	0
19754	07/09/2015	MI5036FBN	BRADFORD WHITE	0
19755	07/24/2015	DS150S6FBN	Bradford White	0
19756	06/05/2015	M45036FBN	Bradford White	0
19757	07/15/2015	M45036FBN	Bradford White	0
19758	06/26/2015	M45036FBN	Bradford White	0
19759	07/23/2015	RG250T6N	Bradford White	0
19760	07/07/2015	G82156	RUUD/RHEEM	1
19761	07/30/2015	G82156	RUUD/RHEEM	0
19762	07/30/2015	PROG5036NRU60	RUUD/RHEEM	0
19763	07/29/2015	M440T6FBN	Bradford White	0
19764	07/29/2015	MI40T6FBN	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19765	07/28/2015	M45036FBN	Bradford White	0
19766	07/25/2015	MI403S6FBN	Bradford White	0
19767	07/21/2015	MI50L6FBN	Bradford White	0
19768	07/22/2015	M45036FBN	Bradford White	0
19769	07/30/2015	RG250T6N	Bradford White	0
19770	07/24/2015	M2XR504T6FBN	Bradford White	0
19771	07/29/2015	MI403S6FBN	Bradford White	0
19772	07/16/2015	M45036FBN	Bradford White	0
19773	06/30/2015	G76200	RUUD/RHEEM	0
19774	07/13/2015	M45036FBN	Bradford White	0
19775	07/19/2015	M45036FBN	Bradford White	0
19776	07/16/2015	MI5036FBN	Bradford White	0
19777	07/20/2015	MI403S6FBN	Bradford White	0
19778	07/29/2015	MI5036FBN	Bradford White	0
19779	07/29/2015	RG250T6N	Bradford White	0
19780	07/07/2015	M45036FBN	Bradford White	2
19781	07/09/2015	MI40T6FBN	Bradford White	0
19782	07/11/2015	M45036FBN	Bradford White	0
19783	07/08/2015	M2XR504T6FBN	Bradford White	0
19784	07/14/2015	DS150S6FBN	Bradford White	0
19785	07/13/2015	MI5036FBN	BRADFORD WHITE	0
19786	07/08/2015	M45036FBN	BRADFORD WHITE	0
19787	07/10/2015	MI5036FBN	BRADFORD WHITE	0
19788	07/09/2015	M45036FBN	BRADFORD WHITE	1
19789	07/08/2015	MI5036FBN	BRADFORD WHITE	0
19790	07/10/2015	M45036FBN	BRADFORD WHITE	0
19791	07/21/2015	M45036FBN	BRADFORD WHITE	0
19792	07/20/2015	MI40T6FBN	BRADFORD WHITE	0
19793	07/17/2015	PROG5036NRU60DV	RUUD	0
19794	07/20/2015	PROG5038NRU58	RUUD	0
19795	07/07/2015	MI5036FBN	Bradford White	0
19796	07/15/2015	MI5036FBN	Bradford White	0
19797	07/08/2015	MI5036FBN	Bradford White	0
19798	07/07/2015	M45036FBN	Bradford White	0
19799	07/18/2015	G82156	RUUD/RHEEM	0
19800	07/18/2015	PROG5038NRU58	Ruud/Rheem	0
19801	07/07/2015	MI40T6FBN	Bradford White	0
19802	07/15/2015	MI403S6FBN	Bradford White	0
19803	07/21/2015	M45036FBN	Bradford White	0
19804	07/21/2015	M440T6FBN	Bradford White	0
19805	07/21/2015	M2XR504T6FBN	Bradford White	0
19806	07/20/2015	M45036FBN	Bradford White	0
19807	07/10/2015	M45036FBN	BRADFORD WHITE	0
19808	07/22/2015	MI40T6FBN	BRADFORD WHITE	0
19809	07/23/2015	MI403S6FBN	BRADFORD WHITE	0
19810	07/23/2015	M45036FBN	BRADFORD WHITE	2
19811	07/09/2015	M45036FBN	BRADFORD WHITE	1
19812	07/15/2015	M440T6FBN	BRADFORD WHITE	0
19813	07/24/2015	M440T6FBN	BRADFORD WHITE	0
19814	07/22/2015	M45036FBN	BRADFORD WHITE	0
19815	06/12/2015	M45036FBN	BRADFORD WHITE	1
19816	06/20/2015	MI5036FBN	BRADFORD WHITE	0
19817	06/20/2015	MI5036FBN	BRADFORD WHITE	0
19818	06/30/2015	M45036FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19819	07/27/2015	M45036FBN	Bradford White	0
19820	07/27/2015	MI5036FBN	Bradford White	0
19821	07/29/2015	M45036FBN	Bradford White	0
19822	07/21/2015	MI50L6FBN	Bradford White	0
19823	07/17/2015	PROG5036NRU60	RUUD/RHEEM	0
19824	07/16/2015	MI50L6FBN	Bradford White	0
19825	07/22/2015	MI40T6FBN	Bradford White	0
19826	07/28/2015	RG250T6N	Bradford White	1
19827	07/22/2015	G76200	RUUD/RHEEM	1
19828	07/16/2015	G91200	RUUD/RHEEM	0
19829	07/16/2015	G91200	RUUD/RHEEM	0
19830	07/03/2015	G82156	RUUD/RHEEM	0
19831	07/28/2015	G82156	RUUD/RHEEM	0
19832	07/23/2015	G82156	RUUD/RHEEM	0
19833	07/08/2015	G91200	RUUD/RHEEM	0
19834	07/27/2015	PROG5038NRU58	RUUD/RHEEM	0
19835	07/28/2015	RG250T6N	Bradford White	0
19836	07/27/2015	MI5036FBN	Bradford White	0
19837	07/21/2015	MI40T6FBN	Bradford White	0
19838	07/23/2015	RG250T6N	Bradford White	1
19839	07/23/2015	M45036FBN	Bradford White	1
19840	07/18/2015	MI5036FBN	Bradford White	0
19841	03/12/2015	M45036FBN	BRADFORD WHITE	0
19842	08/05/2015	RG250T6N	Bradford White	0
19843	08/04/2015	PROG5036NRU60	RUUD/RHEEM	0
19844	08/05/2015	M45036FBN	Bradford White	0
19845	08/03/2015	MI5036FBN	Bradford White	0
19846	07/15/2015	MI40T6FBN	Bradford White	0
19847	08/07/2015	MI40T6FBN	Bradford White	0
19848	08/06/2015	M45036FBN	Bradford White	0
19849	08/11/2015	M2XR504T6FBN	Bradford White	0
19850	08/07/2015	MI5036FBN	Bradford White	0
19851	08/06/2015	MI5036FBN	Bradford White	0
19852	08/03/2015	MI5036FBN	Bradford White	1
19853	08/04/2015	M45036FBN	Bradford White	0
19854	08/03/2015	RG250T6N	Bradford White	0
19855	08/06/2015	RG250T6N	Bradford White	0
19856	07/21/2015	M45036FBN	Bradford White	0
19857	08/10/2015	RG250T6N	Bradford White	0
19858	08/10/2015	RG250T6N	Bradford White	0
19859	07/28/2015	M45036FBN	Bradford White	1
19860	07/31/2015	MI5036FBN	Bradford White	0
19861	07/31/2015	M45036FBN	Bradford White	0
19862	08/06/2015	MI5036FBN	Bradford White	0
19863	07/22/2015	MI40T6FBN	Bradford White	0
19864	07/23/2015	RG250T6N	Bradford White	0
19865	07/24/2015	MI5036FBN	Bradford White	0
19866	08/04/2015	RG250T6N	Bradford White	2
19867	08/05/2015	RG250T6N	Bradford White	0
19868	08/15/2015	RG250T6N	Bradford White	1
19869	08/04/2015	G91200	RUUD/RHEEM	0
19870	08/05/2015	MI75S6FBN	Bradford White	0
19871	07/01/2015	G82156	RUUD/RHEEM	1
19872	08/20/2015	FGR40	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19873	08/24/2015	M2XR504T6FBN	Bradford White	0
19874	08/21/2015	RG250T6N	Bradford White	0
19875	08/21/2015	RG250T6N	Bradford White	0
19876	08/24/2015	MI40T6FBN	Bradford White	0
19877	07/19/2015	PROG2932NRU62	RUUD/RHEEM	0
19878	08/23/2015	RG250T6N	Bradford White	0
19879	08/21/2015	DS140S6FBN	Bradford White	0
19880	08/20/2015	MI403S6FBN	Bradford White	0
19881	08/18/2015	G91200	RUUD/RHEEM	0
19882	08/22/2015	RG250T6N	Bradford White	0
19883	08/18/2015	DS150S6FBN	Bradford White	1
19884	08/24/2015	PROG5036NRU60	RUUD/RHEEM	0
19885	08/24/2015	PROG5036NRU60DV	RUUD/RHEEM	1
19886	08/19/2015	RG250T6N	Bradford White	0
19887	08/08/2015	M45036FBN	Bradford White	0
19888	08/18/2015	RG250T6N	Bradford White	0
19889	08/23/2015	MI40T6FBN	Bradford White	1
19890	08/25/2015	MI40T6FBN	Bradford White	0
19891	08/25/2015	RG250T6N	Bradford White	1
19892	08/25/2015	MI40T6FBN	Bradford White	0
19893	08/26/2015	RG250T6N	Bradford White	0
19894	08/28/2015	RG250T6N	Bradford White	1
19895	08/28/2015	M2XR504T6FBN	Bradford White	0
19896	08/28/2015	RG250T6N	Bradford White	0
19897	08/19/2015	MI403S6FBN	BRADFORD WHITE	0
19898	08/05/2015	RG250T6N	Bradford White	0
19899	08/14/2015	PROG5038NRU58	RUUD/RHEEM	0
19900	08/17/2015	RG250T6N	Bradford White	0
19901	08/18/2015	M45036FBN	Bradford White	0
19902	08/24/2015	PROG5036NRU60	RUUD/RHEEM	0
19903	08/24/2015	MI40T6FBN	Bradford White	0
19904	08/26/2015	RG250T6N	Bradford White	0
19905	08/27/2015	MI40T6FBN	Bradford White	0
19906	08/27/2015	PROG5038NRU58	RUUD/RHEEM	0
19907	08/19/2015	MI50L6FBN	BRADFORD WHITE	0
19908	08/17/2015	XTN050	LOCHINVAR	0
19909	08/14/2015	G82156	RUUD/RHEEM	2
19910	08/14/2015	PROG5036NRU60	RUUD/RHEEM	1
19911	08/03/2015	PROG5038NRU58	RUUD/RHEEM	0
19912	07/14/2015	M45036FBN	Bradford White	0
19913	08/08/2015	RG250T6N	Bradford White	0
19914	07/01/2015	MI40T6FBN	Bradford White	0
19915	08/05/2015	M45036FBN	Bradford White	2
19916	08/14/2015	RG250T6N	Bradford White	0
19917	08/06/2015	RG250T6N	Bradford White	0
19918	08/11/2015	M45036FBN	Bradford White	0
19919	08/11/2015	M440T6FBN	Bradford White	0
19920	08/17/2015	RG250L6N	Bradford White	0
19921	08/11/2015	MI50L6FBN	Bradford White	0
19922	08/14/2015	M45036FBN	Bradford White	0
19923	08/14/2015	MI40T6FBN	Bradford White	0
19924	08/06/2015	M2XR504T6FBN	Bradford White	0
19925	08/13/2015	MI40T6FBN	Bradford White	0
19926	07/31/2015	PROG5038NRU58	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19927	08/12/2015	M45036FBN	Bradford White	0
19928	08/12/2015	M440T6FBN	Bradford White	0
19929	08/06/2015	MI40T6FBN	Bradford White	0
19930	07/30/2015	MI40T6FBN	Bradford White	0
19931	08/06/2015	RG250T6N	Bradford White	0
19932	08/10/2015	RG250T6N	Bradford White	0
19933	08/08/2015	MI5036FBN	Bradford White	0
19934	08/08/2015	M45036FBN	Bradford White	0
19935	08/07/2015	RG250T6N	Bradford White	0
19936	08/07/2015	RG250T6N	Bradford White	0
19937	08/04/2015	M2XR504T6FBN	Bradford White	1
19938	08/04/2015	RG250T6N	Bradford White	0
19939	08/02/2015	MI5036FBN	Bradford White	0
19940	08/02/2015	MI403S6FBN	Bradford White	0
19941	08/19/2015	RG250L6N	Bradford White	0
19942	08/18/2015	MI5036FBN	Bradford White	0
19943	07/31/2015	M45036FBN	Bradford White	0
19944	08/18/2015	MI5036FBN	Bradford White	0
19945	08/13/2015	M45036FBN	Bradford White	0
19946	08/19/2015	PROG5036NRU60DV	RUUD	0
19947	08/20/2015	RG250T6N	BRADFORD WHITE	0
19948	08/20/2015	RG250T6N	BRADFORD WHITE	0
19949	08/21/2015	RG250T6N	BRADFORD WHITE	0
19950	08/19/2015	G76200	RUUD/RHEEM	0
19951	08/17/2015	MI40T6FBN	BRADFORD-WHITE	0
19952	08/17/2015	M1403S6FBN	Bradford White	1
19953	08/29/2015	RG250T6N	Bradford White	0
19954	08/27/2015	MI5036FBN	Bradford White	0
19955	08/31/2015	MI40T6FBN	Bradford White	0
19956	08/27/2015	G91200	RUUD/RHEEM	0
19957	08/27/2015	RG250T6N	Bradford White	0
19958	05/07/2015	PROG5038NRU58	RUUD/RHEEM	0
19959	05/07/2015	M45036FBN	Bradford White	0
19960	09/02/2015	DS140S6FBN	Bradford White	0
19961	09/02/2015	RG250T6N	Bradford White	0
19962	09/02/2015	RG250T6N	Bradford White	0
19963	09/04/2015	RG250T6N	Bradford White	0
19964	08/27/2015	RG250T6N	Bradford White	0
19965	08/31/2015	RG250T6N	Bradford White	0
19966	08/31/2015	RG250T6N	Bradford White	1
19967	08/31/2015	RG250T6N	Bradford White	0
19968	08/24/2015	G91200	RUUD/RHEEM	2
19969	08/28/2015	RG250T6N	Bradford White	0
19970	09/01/2015	MI40T6FBN	Bradford White	0
19971	09/01/2015	RG250T6N	Bradford White	0
19972	09/01/2015	RG250T6N	BRADFORD-WHITE	0
19973	09/02/2015	RG250T6N	BRADFORD WHITE	0
19974	09/09/2015	DS140S6FBN	STATE	0
19975	09/08/2015	MI403S6FBN	Bradford White	0
19976	09/14/2015	G82156	RUUD/RHEEM	0
19977	09/14/2015	G75125	RUUD/RHEEM	0
19978	09/08/2015	RG250T6N	BRADFORD WHITE	0
19979	09/10/2015	M440T6FBN	BRADFORD WHITE	0
19980	09/02/2015	RG250T6N	BRADFORD WHITE	3

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
19981	09/13/2015	RG250T6N	BRADFORD WHITE	0
19982	09/11/2015	RG250T6N	BRADFORD WHITE	0
19983	09/12/2015	G76200	RUUD/RHEEM	1
19984	09/09/2015	G91200	RUUD/RHEEM	0
19985	09/02/2015	MI50L6FBN	BRADFORD-WHITE	0
19986	09/11/2015	RG250T6N	BRADFORD WHITE	0
19987	09/08/2015	RG250T6N	BRADFORD WHITE	0
19988	09/13/2015	RG250T6N	BRADFORD-WHITE	0
19989	09/10/2015	RG250T6N	BRADFORD-WHITE	0
19990	09/04/2015	RG250T6N	BRADFORD-WHITE	0
19991	07/07/2015	PROG5036NRU60DV	RUUD	0
19992	09/09/2015	RG250T6N	BRADFORD-WHITE	0
19993	09/01/2015	RG250T6N	BRADFORD-WHITE	0
19994	09/22/2015	RG250T6N	BRADFORD-WHITE	0
19995	09/14/2015	MI40T6FBN	BRADFORD-WHITE	0
19996	09/16/2015	DS140S6FBN	BRADFORD-WHITE	0
19997	08/21/2015	MI40T6FBN	BRADFORD-WHITE	0
19998	09/18/2015	PROG5036NRU60DV	RUUD	0
19999	09/17/2015	LTN050	LOCHINVAR	1
20000	09/22/2015	RG250T6N	BRADFORD-WHITE	0
20001	09/22/2015	RG250T6N	BRADFORD-WHITE	0
20002	09/18/2015	MI403S6FBN	BRADFORD-WHITE	2
20003	09/16/2015	MI403S6FBN	BRADFORD-WHITE	2
20004	09/14/2015	G91200	RUUD	0
20005	09/09/2015	RG250T6N	BRADFORD-WHITE	0
20006	09/09/2015	RG250T6N	BRADFORD-WHITE	1
20007	09/01/2015	MI40T6FBN	BRADFORD-WHITE	0
20008	08/24/2015	PROG5036NRU60DV	RUUD	0
20009	09/15/2015	M2XR504T6FBN	BRADFORD-WHITE	0
20010	09/16/2015	RG250T6N	BRADFORD-WHITE	0
20011	09/18/2015	RG250T6N	BRADFORD-WHITE	0
20012	09/18/2015	RG250T6N	BRADFORD-WHITE	0
20013	09/08/2015	MI40T6FBN	BRADFORD-WHITE	0
20014	09/16/2015	RG250T6N	BRADFORD-WHITE	0
20015	09/18/2015	RG250T6N	BRADFORD-WHITE	0
20016	09/21/2015	MI5036FBN	BRADFORD-WHITE	1
20017	09/14/2015	G91200	RUUD	0
20018	09/17/2015	G76200	RUUD	1
20019	09/08/2015	PROG5036NRU60DV	RUUD	0
20020	09/08/2015	RG250T6N	BRADFORD-WHITE	0
20021	09/14/2015	PROG5036NRU60DV	BRADFORD-WHITE	0
20022	09/08/2015	MI40T6FBN	BRADFORD-WHITE	0
20023	09/14/2015	M2XR504T6FBN	BRADFORD-WHITE	0
20024	09/14/2015	RG250T6N	BRADFORD-WHITE	0
20025	09/02/2015	RG250T6N	BRADFORD-WHITE	0
20026	09/11/2015	RG250T6N	BRADFORD-WHITE	0
20027	09/08/2015	MI40T6FBN	BRADFORD-WHITE	0
20028	09/21/2015	PROG2932NRU62	RUUD	0
20029	09/29/2015	RG250T6N	BRADFORD-WHITE	0
20030	09/30/2015	MI403S6FBN	BRADFORD-WHITE	1
20031	09/30/2015	MI403S6FBN	BRADFORD-WHITE	0
20032	09/29/2015	RG250T6N	BRADFORD-WHITE	0
20033	09/30/2015	M440T6FBN	BRADFORD WHITE	0
20034	09/30/2015	M2XR504T6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20035	09/28/2015	RG250T6N	BRADFORD WHITE	0
20036	09/28/2015	RG240S6N	BRADFORD WHITE	0
20037	09/28/2015	RG250T6N	BRADFORD WHITE	0
20038	09/28/2015	RG250T6N	BRADFORD WHITE	0
20039	09/28/2015	M440T6FBN	BRADFORD WHITE	0
20040	09/28/2015	RG250T6N	BRADFORD WHITE	0
20041	09/28/2015	RG250T6N	BRADFORD WHITE	0
20042	09/16/2015	RG250T6N	BRADFORD WHITE	0
20043	09/17/2015	RG250T6N	BRADFORD WHITE	1
20044	09/16/2015	M2XR504T6FBN	BRADFORD WHITE	0
20045	09/02/2015	M440T6FBN	BRADFORD WHITE	0
20046	09/21/2015	RG250T6N	BRADFORD WHITE	0
20047	09/18/2015	PROG5036NRU60DV	RUUD	0
20048	09/24/2015	PROG5038NRU60DV	RUUD	0
20049	09/26/2015	RG250T6N	BRADFORD-WHITE	0
20050	09/25/2015	MI403S6FBN	BRADFORD WHITE	0
20051	09/27/2015	RG250T6N	BRADFORD WHITE	0
20052	09/21/2015	RG250T6N	BRADFORD WHITE	0
20053	09/21/2015	RG250T6N	BRADFORD WHITE	0
20054	09/22/2015	MI5036FBN	BRADFORD WHITE	0
20055	09/22/2015	MI40T6FBN	BRADFORD WHITE	0
20056	09/23/2015	RG250T6N	BRADFORD WHITE	0
20057	09/23/2015	MI403S6FBN	BRADFORD WHITE	0
20058	09/24/2015	RG250T6N	BRADFORD WHITE	0
20059	09/26/2015	RG250T6N	BRADFORD WHITE	0
20060	09/27/2015	RG250T6N	BRADFORD WHITE	0
20061	09/29/2015	MI40T6FBN	BRADFORD WHITE	0
20062	09/30/2015	MI50L6FBN	BRADFORD WHITE	0
20063	09/18/2015	MI50L6FBN	BRADFORD-WHITE	0
20064	09/29/2015	PROG5036NRU60DV	RUUD	0
20065	09/25/2015	MI403S6FBN	BRADFORD WHITE	0
20066	09/17/2015	G91200	RUUD	0
20067	09/24/2015	RG250T6N	BRADFORD-WHITE	0
20068	08/24/2015	PROG5036NRU60DV	RUUD	0
20069	09/11/2015	RG250T6N	BRADFORD WHITE	0
20070	09/29/2015	MI50L6FBN	BRADFORD WHITE	0
20071	10/05/2015	MI5036FBN	BRADFORD WHITE	0
20072	10/05/2015	RG250L6N	BRADFORD WHITE	0
20073	10/07/2015	RG250T6N	BRADFORD WHITE	0
20074	10/07/2015	PROG5036NRU60DV	RUUD	0
20075	10/08/2015	RG240S6N	BRADFORD WHITE	0
20076		RG250T6N	BRADFORD WHITE	0
20077	10/01/2015	RG240S6N	BRADFORD WHITE	0
20078	10/01/2015	PROG5036NRU60DV	RUUD	0
20079	10/01/2015	RG250T6N	BRADFORD WHITE	0
20080	10/02/2015	M440T6FBN	BRADFORD WHITE	0
20081	10/02/2015	RG250T6N	BRADFORD WHITE	0
20082	10/02/2015	MI40T6FBN	BRADFORD WHITE	0
20083	10/05/2015	PROG5036NRU60DV	RUUD	0
20084	10/05/2015	RG250T6N	BRADFORD WHITE	0
20085	10/05/2015	RG250T6N	BRADFORD WHITE	0
20086	10/05/2015	RG250T6N	BRADFORD WHITE	0
20087	10/05/2015	RG250T6N	BRADFORD WHITE	0
20088	10/06/2015	RG250T6N	BRADFORD WHITE	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20089	10/06/2015	RG250T6N	BRADFORD WHITE	0
20090	10/03/2015	G91200	RUUD	0
20091	10/08/2015	RG250T6N	BRADFORD-WHITE	0
20092	10/02/2015	RG250T6N	BRADFORD-WHITE	0
20093	09/24/2015	MI40T6FBN	BRADFORD-WHITE	0
20094	10/12/2015	RG250T6N	BRADFORD-WHITE	0
20095	10/09/2015	RG250T6N	BRADFORD-WHITE	0
20096	10/09/2015	RG250T6N	BRADFORD-WHITE	0
20097	10/09/2015	MI40T6FBN	BRADFORD-WHITE	0
20098	10/08/2015	RG250T6N	BRADFORD-WHITE	1
20099	10/07/2015	RG250T6N	BRADFORD-WHITE	0
20100	10/07/2015	M440T6FBN	BRADFORD-WHITE	0
20101	10/07/2015	RG250T6N	BRADFORD-WHITE	0
20102	10/06/2015	RG250T6N	BRADFORD-WHITE	1
20103	10/06/2015	RG250T6N	BRADFORD-WHITE	0
20104	10/04/2015	MI50L6FBN	BRADFORD-WHITE	0
20105	10/09/2015	RG250T6N	BRADFORD-WHITE	0
20106	10/07/2015	RG250T6N	BRADFORD-WHITE	0
20107	10/15/2015	RG250T6N	BRADFORD-WHITE	0
20108	10/15/2015	M440T6FBN	BRADFORD-WHITE	1
20109	10/14/2015	RG250T6N	BRADFORD-WHITE	2
20110	10/13/2015	PROG5036NRU60DV	RUUD	0
20111	09/13/2015	G75125	RUUD/RHEEM	0
20112	09/24/2015	RG250T6N	BRADFORD WHITE	0
20113	10/09/2015	RG250T6N	BRADFORD WHITE	0
20114	10/09/2015	RG250T6N	BRADFORD WHITE	0
20115	10/09/2015	PROG2932NRU62	RUUD	0
20116	10/08/2015	RG250T6N	BRADFORD WHITE	0
20117	10/08/2015	MI40T6FBN	BRADFORD WHITE	0
20118	10/07/2015	MI40T6FBN	BRADFORD WHITE	0
20119	10/16/2015	RG250T6N	BRADFORD WHITE	0
20120	10/15/2015	RG250T6N	BRADFORD WHITE	0
20121	10/15/2015	RG250T6N	BRADFORD WHITE	0
20122	10/14/2015	RG250T6N	BRADFORD WHITE	0
20123	10/14/2015	M2XR504T6FBN	BRADFORD WHITE	0
20124	10/14/2015	RG250T6N	BRADFORD WHITE	1
20125	10/13/2015	PROG5036NRU60DV	RUUD	0
20126	10/13/2015	RG250T6N	BRADFORD-WHITE	0
20127	10/13/2015	RG250T6N	BRADFORD-WHITE	0
20128	10/13/2015	RG250T6N	BRADFORD-WHITE	0
20129	10/06/2015	RG240S6N	BRADFORD-WHITE	0
20130	10/13/2015	RG250T6N	BRADFORD-WHITE	0
20131	10/19/2015	M2XR504T6FBN	BRADFORD-WHITE	0
20132	10/19/2015	RG250T6N	BRADFORD-WHITE	0
20133	10/19/2015	RG250T6N	BRADFORD-WHITE	0
20134	10/19/2015	RG250T6N	BRADFORD-WHITE	1
20135	10/16/2015	RG250T6N	BRADFORD-WHITE	0
20136	10/15/2015	RG250T6N	BRADFORD-WHITE	0
20137	10/14/2015	PROG2932NRU62	RUUD	0
20138	10/08/2015	RG250T6N	BRADFORD-WHITE	0
20139	10/01/2015	RG250T6N	BRADFORD-WHITE	0
20140	10/16/2015	RG250T6N	BRADFORD-WHITE	0
20141	10/17/2015	PROG5036NRU60DV	RUUD	0
20142	10/15/2015	G91200	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20143	10/20/2015	RG250T6N	BRADFORD-WHITE	0
20144	10/20/2015	RG250T6N	BRADFORD-WHITE	0
20145	10/20/2015	RG250T6N	BRADFORD-WHITE	0
20146	09/15/2015	RG250T6N	BRADFORD-WHITE	0
20147	10/12/2015	RG250T6N	BRADFORD-WHITE	0
20148	10/12/2015	PROG5036NRU60DV	RUUD	0
20149	10/16/2015	RG250T6N	BRADFORD-WHITE	0
20150	10/20/2015	M440T6FBN	BRADFORD-WHITE	0
20151	10/20/2015	RG250T6N	BRADFORD-WHITE	0
20152	10/15/2015	RG250T6N	BRADFORD-WHITE	1
20153	10/15/2015	RG250T6N	BRADFORD-WHITE	0
20154	10/17/2015	RG250T6N	BRADFORD-WHITE	0
20155	10/20/2015	M2XR504T6FBN	BRADFORD-WHITE	0
20156	10/14/2015	RG250T6N	BRADFORD-WHITE	0
20157	10/26/2015	PROG5036NRU60DV	RUUD	0
20158	10/26/2015	RG250T6N	BRADFORD-WHITE	0
20159	10/30/2015	RG250T6N	BRADFORD-WHITE	0
20160	10/21/2015	PROG5036NRU60DV	RUUD	0
20161	10/26/2015	RG250T6N	BRADFORD-WHITE	0
20162	10/31/2015	G82156	RUUD	0
20163	10/23/2015	G82156	RUUD/RHEEM	2
20164	10/17/2015	RG250T6N	BRADFORD-WHITE	0
20165	10/29/2015	PH199119	PHOENIX	0
20166	10/28/2015	G82156	RUUD/RHEEM	2
20167	10/19/2015	G82156	RUUD/RHEEM	0
20168	10/19/2015	G91200	RUUD/RHEEM	0
20169	10/20/2015	G91200	RUUD/RHEEM	2
20170	10/23/2015	PROG5036NRU60DV	RUUD	3
20171	10/29/2015	PROG2932NRU63	RUUD	0
20172	10/29/2015	RG240S6N	BRADFORD-WHITE	0
20173	10/22/2015	RG240T6N	BRADFORD-WHITE	0
20174	10/22/2015	RG250T6N	BRADFORD-WHITE	0
20175	10/21/2015	RG250T6N	BRADFORD-WHITE	0
20176	10/21/2015	M440T6FBN	BRADFORD-WHITE	0
20177	10/28/2015	RG240T6N	BRADFORD-WHITE	0
20178	10/26/2015	RG250T6N	BRADFORD-WHITE	0
20179	10/28/2015	RG250T6N	BRADFORD-WHITE	0
20180	10/30/2015	M440T6FBN	BRADFORD-WHITE	0
20181	10/23/2015	RG240S6N	BRADFORD-WHITE	0
20182	10/23/2015	RG250L6N	BRADFORD-WHITE	0
20183	10/12/2015	PROG5036NRU60DV	RUUD	0
20184	10/13/2015	RG250T6N	BRADFORD-WHITE	1
20185	10/23/2015	G91200	RUUD/RHEEM	0
20186	11/03/2015	RG250T6N	BRADFORD-WHITE	0
20187	11/03/2015	RG250T6N	BRADFORD-WHITE	0
20188	11/03/2015	MI403S6FBN	BRADFORD-WHITE	0
20189	11/04/2015	RG250T6N	BRADFORD WHITE	0
20190	11/05/2015	RG250T6N	BRADFORD WHITE	0
20191	11/03/2015	RG250T6N	BRADFORD WHITE	1
20192	11/03/2015	PROG5036NRU60DV	RUUD	0
20193	11/03/2015	RG250T6N	BRADFORD WHITE	0
20194	11/02/2015	MI403S6FBN	BRADFORD WHITE	0
20195	11/04/2015	RG250T6N	BRADFORD-WHITE	0
20196	11/02/2015	RG250T6N	BRADFORD-WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20197	11/01/2015	PROG5036NRU60DV	RUUD	0
20198	10/31/2015	RG250T6N	BRADFORD-WHITE	0
20199	10/28/2015	RG250T6N	BRADFORD-WHITE	0
20200	10/28/2015	RG250T6N	BRADFORD-WHITE	0
20201	10/29/2015	MI403S6FBN	BRADFORD-WHITE	0
20202	11/05/2015	G82156	RUUD	0
20203	11/04/2015	RG240T6N	BRADFORD-WHITE	0
20204	11/04/2015	G91200	RUUD/RHEEM	0
20205	09/23/2015	G91200	RUUD/RHEEM	2
20206	11/15/2015	RG250T6N	BRADFORD WHITE	0
20207	11/03/2015	RG250T6N	BRADFORD WHITE	0
20208	10/29/2015	RG250T6N	BRADFORD WHITE	0
20209	11/06/2015	RG250T6N	BRADFORD WHITE	0
20210	11/06/2015	RG250T6N	BRADFORD WHITE	0
20211	11/09/2015	RG250T6N	BRADFORD WHITE	0
20212	11/04/2015	RG240T6N	BRADFORD WHITE	0
20213	10/21/2015	RG250T6N	Bradford White	0
20214	10/30/2015	MI40T6FBN	BRADFORD WHITE	0
20215	10/28/2015	RG250T6N	BRADFORD WHITE	0
20216	11/06/2015	RG250T6N	BRADFORD WHITE	0
20217	11/06/2015	RG250T6N	BRADFORD WHITE	0
20218	11/06/2015	RG240T6N	BRADFORD WHITE	0
20219	11/05/2015	RG250T6N	BRADFORD WHITE	0
20220	11/08/2015	RG250T6N	BRADFORD WHITE	0
20221	11/10/2015	RG250T6N	BRADFORD WHITE	0
20222	11/10/2015	M440T6FBN	BRADFORD WHITE	0
20223	11/10/2015	RG250T6N	BRADFORD WHITE	0
20224	11/10/2015	RG250T6N	BRADFORD WHITE	0
20225	11/10/2015	RG250T6N	BRADFORD WHITE	0
20226	11/11/2015	RG250T6N	BRADFORD WHITE	0
20227	11/13/2015	RG250T6N	BRADFORD WHITE	0
20228	10/28/2015	G82156	RUUD	1
20229	11/11/2015	PROG5036NRU60DV	RUUD	0
20230	11/11/2015	RG250T6N	BRADFORD WHITE	0
20231	11/12/2015	PROG5036NRU60DV	STATE	0
20232	11/12/2015	PROG5036NRU60DV	RUUD	0
20233	11/11/2015	RG250T6N	BRADFORD WHITE	0
20234	11/11/2015	RG250T6N	BRADFORD WHITE	0
20235		DS150S6FBN	BRADFORD WHITE	0
20236	11/10/2015	RG240T6N	BRADFORD WHITE	0
20237	11/07/2015	RG250T6N	BRADFORD WHITE	0
20238	10/22/2015	RG250T6N	BRADFORD WHITE	0
20239	11/13/2015	RG250T6N	BRADFORD WHITE	0
20240	11/13/2015	RG250T6N	BRADFORD WHITE	0
20241	11/11/2015	RG240S6N	BRADFORD WHITE	0
20242	11/10/2015	RG250T6N	BRADFORD WHITE	2
20243	11/11/2015	RG250T6N	BRADFORD WHITE	0
20244	11/11/2015	RG250T6N	BRADFORD WHITE	0
20245	11/05/2015	RG250T6N	BRADFORD WHITE	0
20246	11/09/2015	RG250T6N	BRADFORD WHITE	0
20247	11/09/2015	RG250T6N	BRADFORD WHITE	0
20248	11/09/2015	PROG5036NRU60DV	RUUD	0
20249	11/12/2015	RG250T6N	BRADFORD WHITE	0
20250	11/13/2015	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20251	11/13/2015	RG250T6N	BRADFORD WHITE	0
20252	11/17/2015	RG250T6N	BRADFORD WHITE	0
20253	11/16/2015	RG250T6N	BRADFORD WHITE	0
20254	11/12/2015	RG250T6N	BRADFORD WHITE	0
20255	10/30/2015	RG250T6N	BRADFORD WHITE	0
20256	01/31/2015	RG250T6N	BRADFORD WHITE	0
20257	11/09/2015	RG250T6N	Bradford White	0
20258	11/23/2015	RG250T6N	Bradford White	0
20259	11/18/2015	RG250T6N	BRADFORD WHITE	0
20260	10/27/2015	G82156	RUUD/RHEEM	2
20261	11/18/2015	RG250T6N	Bradford White	2
20262	11/18/2015	RG250T6N	Bradford White	0
20263	11/17/2015	RG250T6N	Bradford White	0
20264	11/13/2015	PROG5036NRU60DV	RUUD	0
20265	11/24/2015	M2XR504T6FBN	BRADFORD WHITE	0
20266	11/19/2015	M2XR504T6FBN	BRADFORD WHITE	0
20267	11/13/2015	G82156	RUUD	1
20268	11/14/2015	G91200	RUUD	2
20269	11/21/2015	G76200	RUUD	0
20270	11/04/2015	RG240T6N	BRADFORD WHITE	0
20271	11/14/2015	RG250T6N	BRADFORD WHITE	0
20272	10/01/2015	RG250T6N	BRADFORD WHITE	0
20273	11/09/2015	RG250T6N	BRADFORD WHITE	1
20274	11/11/2015	RG250T6N	BRADFORD WHITE	2
20275	11/12/2015	RG250T6N	BRADFORD WHITE	0
20276	11/16/2015	RG250T6N	BRADFORD WHITE	0
20277	11/16/2015	RG250T6N	BRADFORD WHITE	0
20278	11/18/2015	RG240S6N	BRADFORD WHITE	0
20279	11/18/2015	RG250T6N	BRADFORD WHITE	0
20280	11/18/2015	RG240T6N	BRADFORD WHITE	0
20281	11/12/2015	M2XR504T6FBN	Bradford White	0
20282	11/10/2015	RG250T6N	Bradford White	2
20283	11/06/2015	PROG2932NRU62	RUUD	0
20284	11/30/2015	RG250T6N	BRADFORD WHITE	0
20285	11/20/2015	RG250T6N	BRADFORD WHITE	0
20286	11/20/2015	RG250T6N	BRADFORD WHITE	0
20287	11/16/2015	GVC50	RUUD	0
20288	11/23/2015	RG250T6N	BRADFORD WHITE	2
20289	11/28/2015	DS150S6FBN	BRADFORD WHITE	0
20290	11/09/2015	G76200	RUUD	0
20291	10/26/2015	G91200	RUUD	1
20292	11/27/2015	RG250T6N	Bradford White	0
20293	11/13/2015	RG250T6N	Bradford White	0
20294	12/04/2015	RG250T6N	Bradford White	0
20295	12/14/2015	PROG5036NRU60DV	RUUD	0
20296	12/14/2015	RG250T6N	Bradford White	0
20297	12/14/2015	RG250T6N	Bradford White	0
20298	12/11/2015	RG250T6N	Bradford White	0
20299	12/09/2015	RG250T6N	Bradford White	0
20300	12/10/2015	RG240T6N	Bradford White	0
20301	12/10/2015	RG250T6N	Bradford White	0
20302	12/08/2015	PROG5036NRU60DV	RUUD	0
20303	12/08/2015	RG250T6N	Bradford White	0
20304	12/03/2015	PROG5036NRU60DV	RUUD	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20305	08/25/2015	RG250T6N	BRADFORD WHITE	0
20306	11/16/2015	RG250T6N	BRADFORD WHITE	0
20307	11/16/2015	PROG5036NRU60DV	RUUD	0
20308	11/19/2015	RG250T6N	Bradford White	1
20309	10/30/2015	RG250T6N	Bradford White	0
20310	11/25/2015	RG250T6N	Bradford White	0
20311	11/30/2015	RG250T6N	Bradford White	0
20312	11/30/2015	RG250T6N	Bradford White	0
20313	11/24/2015	RG250T6N	BRADFORD WHITE	0
20314	11/24/2015	PROG5036NRU60DV	RUUD	0
20315	11/27/2015	FSG50	AO SMITH	0
20316	11/16/2015	RG250T6N	BRADFORD WHITE	0
20317	11/18/2015	RG250T6N	Bradford White	0
20318	11/17/2015	RG250T6N	Bradford White	0
20319	11/10/2015	RG250T6N	Bradford White	0
20320	11/25/2015	RG250T6N	Bradford White	0
20321	11/23/2015	PROG40S34NRU62	RUUD	0
20322	11/28/2015	G75125	RUUD/RHEEM	0
20323	11/25/2015	PROG2932NRU62	RUUD	0
20324	12/02/2015	RG250T6N	Bradford White	0
20325	12/01/2015	RG250T6N	Bradford White	0
20326	11/25/2015	RG250T6N	Bradford White	0
20327	12/05/2015	RG240T6N	Bradford White	0
20328	12/02/2015	RG250T6N	Bradford White	0
20329	12/01/2015	MI403S6FBN	BRADFORD WHITE	0
20330	11/26/2015	PROG5036NRU60DV	RUUD	0
20331	12/10/2015	RG250T6N	Bradford White	0
20332	12/10/2015	RG250T6N	Bradford White	0
20333	12/11/2015	RG250T6N	Bradford White	0
20334	12/10/2015	RG250T6N	Bradford White	0
20335	11/17/2015	PROG5036NRU60DV	RUUD	0
20336	11/05/2015	PROG5036NRU60DV	RUUD	0
20337	11/30/2015	RG250T6N	Bradford White	0
20338	11/29/2015	RG250T6N	BRADFORD WHITE	0
20339	10/05/2015	RG250T6N	BRADFORD WHITE	1
20340	11/23/2015	RG250T6N	BRADFORD WHITE	0
20341	11/20/2015	RG250T6N	BRADFORD WHITE	0
20342	09/22/2015	M440T6FBN	BRADFORD WHITE	0
20343	11/28/2015	RG250T6N	BRADFORD WHITE	0
20344	11/23/2015	RG250T6N	BRADFORD WHITE	0
20345	11/21/2015	PROG5036NRU60DV	RUUD	0
20346		RG240S6N	BRADFORD WHITE	0
20347	11/25/2015	MI50L6FBN	BRADFORD WHITE	0
20348	11/25/2015	RG250T6N	BRADFORD WHITE	1
20349	11/18/2015	PROG30S30NRU63	RHEEM	0
20350	11/24/2015	RG250T6N	BRADFORD WHITE	0
20351	11/30/2015	M440T6FBN	BRADFORD WHITE	1
20352	11/30/2015	G75125	RUUD	1
20353	11/30/2015	RG250T6N	BRADFORD WHITE	0
20354	12/01/2015	M440T6FBN	BRADFORD WHITE	0
20355	12/03/2015	RG250T6N	BRADFORD WHITE	0
20356	12/06/2015	RG250T6N	BRADFORD WHITE	1
20357	12/07/2015	RG250T6N	BRADFORD WHITE	0
20358	12/09/2015	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20359	12/09/2015	RG250T6N	BRADFORD WHITE	0
20360	12/10/2015	RG240T6N	BRADFORD WHITE	0
20361	12/04/2015	RG250T6N	BRADFORD WHITE	0
20362	12/06/2015	PROG5036NRU60DV	RUUD	0
20363	11/23/2015	MI50L6FBN	BRADFORD WHITE	0
20364		RG250T6N	BRADFORD WHITE	0
20365		PROG5036NRU60DV	RUUD	0
20366	12/02/2015	RG250T6N	BRADFORD WHITE	0
20367	12/02/2015	RG250T6N	BRADFORD WHITE	2
20368	12/03/2015	RG240T6N	BRADFORD WHITE	1
20369	12/10/2015	RG250T6N	BRADFORD WHITE	0
20370	12/11/2015	RG250T6N	BRADFORD WHITE	0
20371	11/28/2015	G91200	RUUD/RHEEM	3
20372	12/02/2015	RG250T6N	BRADFORD WHITE	0
20373	12/03/2015	RG250T6N	BRADFORD WHITE	0
20374	12/07/2015	RG250T6N	BRADFORD WHITE	0
20375	11/18/2015	RG250T6N	BRADFORD WHITE	0
20376	12/10/2015	RG250H6N	Bradford White	0
20377	12/10/2015	RG250T6N	Bradford White	0
20378	11/22/2015	RG250T6N	Bradford White	0
20379	11/26/2015	PROG5036NRU60DV	RUUD	0
20380	12/07/2015	RG250T6N	Bradford White	0
20381	12/14/2015	RG250T6N	Bradford White	0
20382	12/07/2015	G91200	RHEEM / RUUD	1
20383	12/11/2015	G82156	RUUD	2
20384	12/09/2015	RG250T6N	Bradford White	0
20385	12/03/2015	RG240T6N	Bradford White	0
20386	12/13/2015	RG250T6N	Bradford White	0
20387	12/16/2015	RG250T6N	Bradford White	4
20388	12/16/2015	RG250T6N	Bradford White	0
20389	12/16/2015	RG250T6N	Bradford White	0
20390	12/15/2015	RG240T6N	Bradford White	0
20391	12/15/2015	M440T6FBN	Bradford White	0
20392	12/15/2015	G91200	RUUD/RHEEM	0
20393	12/23/2015	RG250T6N	Bradford White	0
20394	12/22/2015	RG250T6N	Bradford White	4
20395	12/22/2015	RG250T6N	Bradford White	0
20396		MI75S6FBN	Bradford White	0
20397	01/04/2016	G91200	RUUD/RHEEM	0
20398	01/11/2016	RG250T6N	Bradford White	2
20399	01/06/2016	RG240T6N	Bradford White	0
20400	01/11/2016	RG250T6N	Bradford White	0
20401	01/13/2016	DS140S6FBN	Bradford White	0
20402	01/13/2016	RG2D40S6N	Bradford White	1
20403	01/05/2016	RG250T6N	Bradford White	0
20404	01/15/2016	RG250T6N	Bradford White	0
20405	01/12/2016	M440T6FBN	Bradford White	0
20406	12/09/2015	RG240T6N	Bradford White	0
20407	01/06/2016	RG250T6N	Bradford White	0
20408	01/14/2016	PROG5038NRU60	RUUD	0
20409	01/13/2016	RG250T6N	Bradford White	1
20410	01/20/2016	RG250T6N	Bradford White	0
20411	12/13/2015	RG250T6N	Bradford White	0
20412	01/27/2016	RG250T6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20413	01/23/2016	RG250T6N	BRADFORD WHITE	0
20414	01/29/2016	RG250T6N	Bradford White	0
20415	01/28/2016	RG250T6N	Bradford White	0
20416	01/22/2016	RG250T6N	Bradford White	0
20417	01/26/2016	G82156	RUUD/RHEEM	0
20418	01/29/2016	G91200	RUUD	0
20419	01/29/2016	RG250T6N	BRADFORD WHITE	0
20420	12/31/2015	PROG5038NRU58DV	RUUD	0
20421	01/14/2016	RG250T6N	Bradford White	0
20422	01/19/2016	RG250T6N	Bradford White	1
20423	12/11/2015	M440T6FBN	Bradford White	1
20424	12/14/2015	RG250T6N	Bradford White	0
20425	11/20/2015	RG240T6N	Bradford White	0
20426	12/11/2015	RG250T6N	BRADFORD WHITE	0
20427	12/13/2015	MI50L6FBN	BRADFORD WHITE	1
20428	12/17/2015	RG250T6N	BRADFORD WHITE	0
20429	12/03/2015	RG250H6N	BRADFORD WHITE	1
20430	12/13/2015	RG250T6N	Bradford White	0
20431	12/14/2015	PROG5036NRU60DV	RUUD	1
20432	12/11/2015	RG250T6N	Bradford White	0
20433	12/03/2015	RG240T6N	Bradford White	0
20434	12/18/2015	RG250T6N	Bradford White	0
20435	12/11/2015	RG250T6N	BRADFORD WHITE	0
20436	12/14/2015	RG250T6N	BRADFORD WHITE	0
20437	09/06/2015	MI40T6FBN	BRADFORD WHITE	2
20438	12/13/2015	RG240S6N	BRADFORD WHITE	0
20439	12/18/2015	PROG5038NRU60DV	RUUD	0
20440	12/18/2015	RG250T6N	BRADFORD WHITE	0
20441	12/19/2015	RG240T6N	BRADFORD WHITE	0
20442	12/19/2015	PROG5038NRU58DV	RUUD	0
20443	12/18/2015	RG240S6N	BRADFORD WHITE	0
20444	12/12/2015	RG250T6N	BRADFORD WHITE	0
20445	12/16/2015	RG250T6N	BRADFORD WHITE	0
20446	12/21/2015	G91200	RUUD	1
20447	12/21/2015	G91200	RUUD	0
20448	12/23/2015	G91200	RUUD	2
20449	12/17/2015	RG250T6N	Bradford White	0
20450	12/17/2015	RG250T6N	Bradford White	0
20451	12/28/2015	PROG5036NRU60DV	Rheem	2
20452	01/08/2016	RG250T6N	Bradford White	0
20453	01/11/2016	PROG5036NRU60DV	RUUD	0
20454	01/08/2016	RG250T6N	Bradford White	0
20455	01/11/2016	RG250T6N	Bradford White	0
20456	01/09/2016	G82156	RUUD/RHEEM	1
20457	12/23/2015	G82156	RUUD/RHEEM	0
20458	12/26/2015	RG275H6N	Bradford White	0
20459	12/26/2015	G76200	RUUD	2
20460	01/28/2016	RG250T6N	Bradford White	0
20461	01/15/2016	G91200	RUUD/RHEEM	0
20462	02/02/2016	RG240T6N	Bradford White	0
20463	02/01/2016	RG240T6N	Bradford White	0
20464	12/30/2015	PROG2932NRU62	RUUD	0
20465	12/18/2015	RG250T6N	Bradford White	0
20466	12/30/2015	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20467	12/28/2015	RG250T6N	Bradford White	0
20468	12/30/2015	RG250T6N	BRADFORD WHITE	0
20469	12/21/2015	G82156	RUUD/RHEEM	0
20470	12/28/2015	RG250T6N	Bradford White	1
20471	12/28/2015	RG250T6N	Bradford White	0
20472	12/31/2015	G75125	RUUD	2
20473	12/28/2015	RG240T6N	Bradford White	0
20474	12/30/2015	RG250T6N	Bradford White	0
20475	12/11/2015	M440T6FBN	B	0
20476		MI40T6FBN	BRADFORD WHITE	0
20477	12/18/2015	RG250T6N	BRADFORD WHITE	0
20478	12/21/2015	RG250T6N	BRADFORD WHITE	0
20479	12/21/2015	RG250T6N	BRADFORD WHITE	0
20480	12/21/2015	RG250T6N	BRADFORD WHITE	1
20481	12/23/2015	RG250T6N	Bradford White	0
20482	12/18/2015	RG250T6N	Bradford White	0
20483	12/08/2015	RG250T6N	Bradford White	0
20484	12/24/2015	RG250T6N	Bradford White	0
20485	12/23/2015	RG250T6N	Bradford White	0
20486	12/22/2015	M2XR504T6FBN	Bradford White	0
20487	12/22/2015	RG250T6N	Bradford White	0
20488	12/31/2015	M440T6FBN	Bradford White	0
20489	12/17/2015	DS140S6FBN	Bradford White	0
20490	12/23/2015	RG250T6N	Bradford White	0
20491	12/30/2015	RG240S6N	Bradford White	0
20492	12/22/2015	RG250T6N	BRADFORD WHITE	0
20493	12/23/2015	MI40T6FBN	BRADFORD WHITE	0
20494	12/24/2015	RG250T6N	BRADFORD WHITE	0
20495	12/28/2015	RG250T6N	BRADFORD WHITE	0
20496	12/28/2015	RG250T6N	BRADFORD WHITE	0
20497	12/29/2015	PROG5036NRU60DV	RUUD	0
20498	12/30/2015	RG250T6N	BRADFORD WHITE	0
20499	12/22/2015	RG250T6N	BRADFORD-WHITE	1
20500	12/26/2015	RG250T6N	BRADFORD WHITE	0
20501	12/29/2015	RG250T6N	BRADFORD WHITE	1
20502	12/23/2015	RG250T6N	BRADFORD WHITE	0
20503	12/30/2015	RG240T6N	BRADFORD WHITE	0
20504	01/03/2016	PROG5036NRU60DV	RUUD	1
20505	12/31/2015	RG275H6N	Bradford White	0
20506	01/02/2016	RG250T6N	Bradford White	0
20507	12/16/2015	RG250T6N	Bradford White	0
20508	12/22/2015	RG240T6N	Bradford White	0
20509	12/31/2015	RG250T6N	Bradford White	0
20510	01/05/2016	RG240T6N	Bradford White	0
20511	01/04/2016	RG240T6N	Bradford White	0
20512	01/07/2016	PROG5036NRU60DV	RUUD	0
20513	01/04/2016	M440T6FBN	BRADFORD WHITE	0
20514	01/04/2016	RG250T6N	BRADFORD WHITE	1
20515	12/14/2015	RG250T6N	Bradford White	0
20516	01/05/2016	RG250T6N	Bradford White	0
20517	12/15/2015	M2XR504T6FBN	Bradford White	1
20518	01/05/2016	RG250T6N	BRADFORD WHITE	0
20519	01/05/2016	RG250T6N	BRADFORD WHITE	0
20520	01/05/2016	RG250T6N	BRADFORD WHITE	2

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20521	01/05/2016	RG250T6N	BRADFORD WHITE	0
20522	01/06/2016	RG250T6N	BRADFORD WHITE	1
20523	01/06/2016	RG250T6N	BRADFORD WHITE	0
20524	01/06/2015	RG250T6N	Bradford White	0
20525	12/21/2015	RG250T6N	Bradford White	0
20526	01/07/2016	RG250T6N	Bradford White	0
20527	01/05/2016	M440T6FBN	Bradford White	0
20528	12/17/2015	MI50L6FBN	BRADFORD WHITE	0
20529	12/31/2015	RG240S6N	BRADFORD WHITE	0
20530	12/31/2015	RG250T6N	BRADFORD WHITE	0
20531	01/06/2016	RG240T6N	BRADFORD WHITE	0
20532	01/12/2016	MI40T6FBN	BRADFORD WHITE	0
20533	01/08/2016	MI403S6FBN	BRADFORD WHITE	0
20534	01/02/2016	RG250T6N	BRADFORD WHITE	0
20535	01/11/2016	RG250T6N	BRADFORD WHITE	0
20536	01/11/2016	RG250T6N	BRADFORD WHITE	0
20537	01/11/2016	RG250T6N	BRADFORD WHITE	0
20538	01/12/2016	RG250T6N	BRADFORD WHITE	0
20539	01/14/2016	RG250T6N	BRADFORD WHITE	0
20540	01/13/2016	RG250T6N	BRADFORD WHITE	0
20541	01/17/2016	RG240T6N	BRADFORD WHITE	0
20542	01/04/2016	RG250T6N	BRADFORD WHITE	0
20543	01/14/2016	DS150S6FBN	BRADFORD WHITE	0
20544	01/14/2016	RG250T6N	BRADFORD WHITE	0
20545	01/14/2016	RG250T6N	BRADFORD WHITE	0
20546	01/22/2016	RG240T6N	BRADFORD-WHITE	0
20547	01/20/2016	RG250T6N	Bradford White	0
20548	01/21/2016	RG250T6N	Bradford White	0
20549	12/24/2015	RG250T6N	BRADFORD WHITE	0
20550	12/30/2015	RG250H6N	BRADFORD WHITE	1
20551	01/22/2016	PROG2932NRU62	RUUD	0
20552	01/19/2016	RG250T6N	Bradford White	0
20553	01/02/2016	RG250T6N	BRADFORD WHITE	0
20554	01/04/2016	MI40T6FBN	BRADFORD WHITE	0
20555	01/11/2016	PGR50	AO SMITH	0
20556	01/13/2016	M440T6FBN	BRADFORD WHITE	0
20557	01/13/2016	RG240T6N	BRADFORD WHITE	0
20558	01/15/2016	PROG5036NRU60DV	RUUD	0
20559	12/18/2015	RG250T6N	BRADFORD WHITE	0
20560	01/22/2016	G76200	RUUD	0
20561	01/20/2016	G91200	RUUD	0
20562	01/15/2016	RG250T6N	Bradford White	0
20563	01/13/2016	RG250T6N	Bradford White	1
20564	01/22/2016	RG250T6N	Bradford White	0
20565	01/18/2016	RG250T6N	Bradford White	0
20566	01/14/2016	RG250T6N	Bradford White	0
20567	01/20/2016	M440T6FBN	Bradford White	0
20568	01/20/2016	RG250T6N	Bradford White	0
20569	01/21/2016	PROG5036NRU60DV	RUUD	0
20570	01/25/2016	RG2D40S6N	Bradford White	0
20571	01/25/2016	RG240T6N	Bradford White	0
20572	01/24/2016	RG250T6N	Bradford White	0
20573	01/19/2016	RG250T6N	BRADFORD WHITE	0
20574	01/21/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20575	01/22/2016	RG240T6N	BRADFORD WHITE	1
20576	01/11/2016	RG250T6N	BRADFORD WHITE	0
20577	01/12/2016	PROG5036NRU60DV	RUUD	0
20578	01/14/2016	RG250T6N	BRADFORD WHITE	0
20579	01/16/2016	RG250T6N	BRADFORD WHITE	0
20580	01/19/2016	RG240S6N	BRADFORD WHITE	0
20581	01/20/2016	RG250T6N	BRADFORD WHITE	1
20582	01/20/2016	PROG5036NRU60DV	RUUD	0
20583	01/21/2016	RG250T6N	BRADFORD WHITE	0
20584	01/25/2016	RG240T6N	BRADFORD WHITE	0
20585	12/29/2015	MI40T6FBN	BRADFORD WHITE	0
20586	01/08/2016	RG250T6N	BRADFORD WHITE	0
20587	01/18/2016	RG250T6N	BRADFORD WHITE	0
20588	01/25/2016	PROG5036NRU60DV	RUUD	0
20589	01/25/2016	RG250T6N	BRADFORD WHITE	0
20590	01/26/2016	RG250H6N	BRADFORD WHITE	0
20591	01/28/2016	RG250T6N	BRADFORD WHITE	0
20592	01/27/2016	G76200	RHEEM	2
20593	12/23/2015	G82156	RUUD/RHEEM	0
20594	12/28/2015	G75125	RUUD/RHEEM	0
20595	01/11/2016	RG250T6N	BRADFORD WHITE	0
20596	01/22/2016	RG250T6N	BRADFORD WHITE	0
20597	01/22/2016	RG250T6N	BRADFORD WHITE	0
20598	01/27/2016	PROG2932NRU63	RUUD	0
20599	01/28/2016	RG250T6N	BRADFORD WHITE	0
20600	01/29/2016	RG250T6N	BRADFORD WHITE	0
20601	01/26/2016	G75125	RUUD/RHEEM	0
20602	01/29/2016	G91200	RUUD	2
20603	02/04/2016	RG250H6N	BRADFORD WHITE	2
20604	01/19/2016	RG250T6N	BRADFORD WHITE	0
20605	01/30/2016	RG240T6N	BRADFORD WHITE	0
20606	01/25/2016	RG250T6N	BRADFORD WHITE	0
20607	01/30/2016	RG250T6N	BRADFORD WHITE	0
20608	02/02/2016	RG250T6N	Bradford White	0
20609	02/02/2016	RG250T6N	Bradford White	0
20610	02/03/2016	RG250T6N	Bradford White	0
20611	02/04/2016	PROG5036NRU60DV	RUUD	0
20612	02/03/2016	M430T6FBN	Bradford White	0
20613	02/01/2016	RG250T6N	Bradford White	0
20614	02/01/2016	RG250T6N	BRADFORD WHITE	0
20615	02/01/2016	RG250T6N	BRADFORD WHITE	0
20616	02/03/2016	RG250T6N	BRADFORD WHITE	0
20617	02/06/2016	PROG5036NRU60DV	RUUD	0
20618	02/08/2016	RG250T6N	BRADFORD WHITE	0
20619	02/01/2016	RG250H6N	BRADFORD WHITE	0
20620	02/02/2016	RG250T6N	BRADFORD WHITE	0
20621	02/02/2016	PROG5036NRU60DV	RUUD	0
20622	02/03/2016	RG240T6N	BRADFORD WHITE	0
20623	02/04/2016	RG250T6N	BRADFORD WHITE	0
20624	02/05/2016	RG250T6N	BRADFORD WHITE	0
20625	02/06/2016	PROG5036NRU60DV	RUUD	0
20626	02/05/2016	PROG5036NRU60DV	RUUD	0
20627	02/09/2016	PROG5036NRU60DV	RUUD	0
20628	02/06/2016	M2XR504T6FBN	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20629	02/05/2016	RG250T6N	BRADFORD WHITE	0
20630	02/05/2016	RG250T6N	BRADFORD WHITE	0
20631	02/09/2016	RG250T6N	BRADFORD WHITE	0
20632	02/05/2016	RG250T6N	BRADFORD WHITE	0
20633	02/02/2016	M440T6FBN	BRADFORD WHITE	0
20634	02/09/2016	RG250H6N	BRADFORD WHITE	0
20635	01/28/2016	RG250T6N	BRADFORD WHITE	0
20636	01/08/2016	RG250T6N	BRADFORD WHITE	0
20637	01/25/2016	RG250T6N	BRADFORD WHITE	0
20638	01/26/2016	RG250T6N	BRADFORD WHITE	0
20639	02/03/2016	RG250T6N	BRADFORD WHITE	0
20640	01/16/2016	G76200	RUUD/RHEEM	0
20641	01/06/2016	RG250T6N	BRADFORD WHITE	1
20642	01/26/2016	RG250T6N	BRADFORD WHITE	0
20643	01/26/2016	RG240T6N	BRADFORD WHITE	0
20644	01/26/2016	RG2DV50S6N	BRADFORD WHITE	1
20645	01/28/2016	RG240T6N	BRADFORD WHITE	0
20646	01/28/2016	RG250T6N	BRADFORD WHITE	0
20647	01/31/2016	PROG5036NRU60DV	RUUD	0
20648	02/03/2016	PROG5036NRU60DV	RUUD	0
20649	02/04/2016	RG250T6N	BRADFORD WHITE	0
20650	02/08/2016	RG250T6N	BRADFORD WHITE	0
20651	01/28/2016	G91200	RUUD	0
20652	02/08/2016	PH13080	PHOENIX	0
20653	01/12/2016	PH199119	PHOENIX	0
20654	02/09/2016	M440T6FBN	BRADFORD WHITE	0
20655	02/10/2016	RG250T6N	BRADFORD WHITE	0
20656	02/11/2016	RG240S6N	BRADFORD WHITE	0
20657	02/12/2016	RG250L6N	BRADFORD WHITE	0
20658	02/17/2016	PROG5036NRU60DV	RUUD	0
20659	02/18/2016	RG250T6N	BRADFORD WHITE	0
20660	02/18/2016	PROG5036NRU60DV	RUUD	0
20661	02/18/2016	RG250T6N	BRADFORD WHITE	2
20662	02/16/2016	RG250T6N	BRADFORD WHITE	0
20663	02/16/2016	RG250T6N	BRADFORD WHITE	0
20664	02/16/2016	RG250T6N	BRADFORD WHITE	0
20665	02/16/2016	RG250T6N	BRADFORD WHITE	0
20666	02/16/2016	PROG5036NRU60DV	RUUD	0
20667	02/17/2016	RG250T6N	BRADFORD WHITE	0
20668	02/17/2016	PROG5036NRU60DV	RUUD	0
20669	02/17/2016	RG250H6N	BRADFORD WHITE	0
20670	02/17/2016	RG250T6N	BRADFORD WHITE	0
20671	02/17/2016	RG250T6N	BRADFORD WHITE	0
20672	02/17/2016	PROG5036NRU60DV	RUUD	0
20673	02/18/2016	PROG5036NRU60DV	RUUD	0
20674	02/23/2016	G82156	RUUD/RHEEM	4
20675	02/22/2016	RG250T6N	BRADFORD WHITE	0
20676	02/23/2016	RG250T6N	BRADFORD WHITE	0
20677	02/23/2016	RG240T6N	BRADFORD WHITE	0
20678	02/23/2016	RG250T6N	BRADFORD WHITE	0
20679	02/24/2016	RG250T6N	BRADFORD WHITE	0
20680	02/25/2016	RG250T6N	BRADFORD WHITE	0
20681	02/25/2016	RG250T6N	BRADFORD WHITE	0
20682	02/26/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20683	02/26/2016	RG250T6N	BRADFORD WHITE	0
20684	02/26/2016	RG250T6N	BRADFORD WHITE	0
20685	01/08/2016	G75125	RUUD/RHEEM	0
20686	01/26/2016	MI403S6FBN	BRADFORD WHITE	0
20687	02/05/2016	RG250T6N	BRADFORD WHITE	0
20688	02/09/2016	RG240T6N	BRADFORD WHITE	0
20689	02/10/2016	PROG5036NRU60DV	RUUD	0
20690	02/10/2016	RG250T6N	BRADFORD WHITE	0
20691	02/10/2016	PROG5036NRU60DV	RUUD	0
20692	02/11/2016	RG250T6N	BRADFORD WHITE	0
20693	02/11/2016	MI50L6FBN	BRADFORD WHITE	0
20694	02/11/2016	RG250T6N	BRADFORD WHITE	0
20695	02/11/2016	RG240T6N	BRADFORD WHITE	0
20696	02/11/2016	RG250T6N	BRADFORD WHITE	0
20697	02/12/2016	RG250T6N	BRADFORD WHITE	0
20698	02/12/2016	RG240T6N	BRADFORD WHITE	0
20699	02/08/2016	RG250T6N	BRADFORD WHITE	0
20700	02/14/2016	RG250T6N	BRADFORD WHITE	0
20701	02/15/2016	RG240T6N	BRADFORD WHITE	0
20702	02/18/2016	RG250T6N	BRADFORD WHITE	0
20703	02/19/2016	RG250T6N	BRADFORD WHITE	1
20704	02/20/2016	RG250T6N	BRADFORD WHITE	0
20705	02/20/2016	RG250T6N	BRADFORD WHITE	0
20706	02/22/2016	RG250T6N	BRADFORD WHITE	0
20707	02/22/2016	RG250T6N	BRADFORD WHITE	0
20708	02/19/2016	PROG5036NRU60DV	RUUD	0
20709	02/23/2016	RG250T6N	BRADFORD WHITE	0
20710	02/29/2016	RG250T6N	BRADFORD WHITE	0
20711	03/01/2016	RG250T6N	BRADFORD WHITE	0
20712	03/03/2016	RG250T6N	BRADFORD WHITE	0
20713	03/03/2016	RG240T6N	BRADFORD WHITE	0
20714	03/04/2016	RG250T6N	BRADFORD WHITE	0
20715	03/06/2016	RG240T6N	BRADFORD WHITE	0
20716	01/27/2016	MI75S6FBN	BRADFORD WHITE	0
20717	02/17/2016	RG240T6N	BRADFORD WHITE	0
20718	02/19/2016	M440T6FBN	BRADFORD WHITE	0
20719	02/19/2016	RG240T6N	BRADFORD WHITE	0
20720	03/02/2016	RG240T6N	BRADFORD WHITE	0
20721	03/02/2016	PROG5036NRU60DV	RUUD	0
20722	03/02/2016	RG2DV40S6N	BRADFORD WHITE	0
20723	03/02/2016	RG2DV40S6N	BRADFORD WHITE	0
20724	03/07/2016	PROG4038NRH62	RUUD	0
20725	03/07/2016	RG250T6N	BRADFORD WHITE	0
20726	03/07/2016	RG250T6N	BRADFORD WHITE	0
20727	03/07/2016	RG240T6N	BRADFORD WHITE	0
20728	03/07/2016	RG250T6N	BRADFORD WHITE	0
20729	02/23/2016	41XR40	RHEEM	0
20730	02/25/2016	G91200	RUUD/RHEEM	1
20731	03/03/2016	RG240S6N	BRADFORD WHITE	0
20732	02/11/2016	G91200	RUUD/RHEEM	0
20733	01/24/2016	MI50L6FBN	BRADFORD WHITE	0
20734	01/26/2016	RG250T6N	BRADFORD WHITE	0
20735	02/10/2016	RG250T6N	BRADFORD WHITE	1
20736	02/12/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20737	02/18/2016	RG250T6N	BRADFORD WHITE	1
20738	02/19/2016	RG250T6N	BRADFORD WHITE	0
20739	02/01/2016	RG250T6N	BRADFORD WHITE	0
20740	02/06/2016	RG250T6N	BRADFORD WHITE	0
20741	02/12/2016	M440T6FBN	BRADFORD WHITE	0
20742	02/13/2016	RG250T6N	BRADFORD WHITE	0
20743	02/18/2016	RG250T6N	BRADFORD WHITE	0
20744	02/18/2016	RG240S6N	BRADFORD WHITE	0
20745	02/19/2016	RG250T6N	BRADFORD WHITE	0
20746	02/23/2016	RG240S6N	BRADFORD WHITE	0
20747	02/23/2016	PROG5036NRU60DV	RUUD	0
20748	02/24/2016	RG250T6N	BRADFORD WHITE	0
20749	02/25/2016	PROG5036NRU60DV	RUUD	0
20750	02/26/2016	RG250T6N	BRADFORD WHITE	0
20751	02/23/2016	G91200	RUUD/RHEEM	0
20752	02/23/2016	G91200	RUUD/RHEEM	0
20753	02/24/2016	G91200	RUUD/RHEEM	0
20754	02/24/2016	G82156	RUUD/RHEEM	0
20755	03/02/2016	RG250T6N	BRADFORD WHITE	0
20756	02/02/2016	G75125	RUUD/RHEEM	0
20757	03/01/2016	G76200	RUUD/RHEEM	0
20758	02/24/2016	RG250T6N	BRADFORD WHITE	0
20759	02/29/2016	RG250T6N	BRADFORD WHITE	0
20760	02/29/2016	RG250T6N	BRADFORD WHITE	0
20761	02/22/2016	RG250T6N	BRADFORD WHITE	0
20762	02/22/2016	RG250T6N	BRADFORD WHITE	1
20763	02/22/2016	RG240T6N	BRADFORD WHITE	1
20764	03/08/2016	PROG5036NRU60DV	RUUD	0
20765	03/08/2016	RG250H6N	BRADFORD WHITE	0
20766	03/09/2016	RG240T6N	BRADFORD WHITE	0
20767	03/14/2016	PROG5036NRU60DV	RUUD	1
20768	03/14/2016	RG250T6N	BRADFORD WHITE	0
20769	03/14/2016	RG250T6N	BRADFORD WHITE	0
20770	03/15/2016	RG240T6N	BRADFORD WHITE	1
20771	03/15/2016	RG240S6N	BRADFORD WHITE	0
20772	03/15/2016	PROG5036NRU60DV	RUUD	0
20773	03/15/2016	PROG2932NRU63	RUUD	0
20774	03/03/2016	RG250T6N	BRADFORD WHITE	0
20775	03/03/2016	RG250T6N	BRADFORD WHITE	0
20776	03/04/2016	PH19980	PHOENIX	0
20777	03/04/2016	RG250T6N	BRADFORD WHITE	0
20778	03/05/2016	RG250T6N	BRADFORD WHITE	0
20779	03/06/2016	G76200	RUUD/RHEEM	2
20780	03/08/2016	G82156	RUUD/RHEEM	0
20781	03/08/2016	G82156	RUUD/RHEEM	0
20782	03/09/2016	PROG5036NRU60DV	RUUD	0
20783	03/08/2016	PROG5036NRU60DV	RUUD	1
20784	03/08/2016	PROG5036NRU60DV	RUUD	0
20785	01/29/2016	RG250T6N	BRADFORD WHITE	1
20786	03/01/2016	PH199119	PHOENIX	2
20787	03/04/2016	PROG5036NRU60DV	RUUD	0
20788	03/07/2016	RG250T6N	BRADFORD WHITE	0
20789	03/11/2016	G91200	RUUD/RHEEM	0
20790	03/11/2016	PROG5036NRU60DV	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20791	03/11/2016	PROG5036NRU60DV	RUUD	0
20792	04/01/2016	G91200	RUUD/RHEEM	0
20793	03/16/2016	M2XR504T6FBN	BRADFORD WHITE	0
20794	03/16/2016	RG250T6N	BRADFORD WHITE	0
20795	03/17/2016	RG250T6N	BRADFORD WHITE	0
20796	03/09/2016	RG250T6N	BRADFORD WHITE	0
20797	03/09/2016	RG240T6N	BRADFORD WHITE	0
20798	03/09/2016	RG250T6N	BRADFORD WHITE	0
20799	03/10/2016	RG250T6N	BRADFORD WHITE	0
20800	03/11/2016	RG250T6N	BRADFORD WHITE	1
20801	03/01/2016	PROG5036NRU60DV	RUUD	0
20802	03/02/2016	RG250T6N	BRADFORD WHITE	0
20803	03/04/2016	RG250T6N	BRADFORD WHITE	0
20804	03/04/2016	RG275H6N	BRADFORD WHITE	0
20805	03/05/2016	RG250T6N	BRADFORD WHITE	0
20806	03/07/2016	RG250T6N	BRADFORD WHITE	0
20807	03/08/2016	RG250T6N	BRADFORD WHITE	0
20808	03/12/2016	RG250T6N	BRADFORD WHITE	0
20809	03/22/2016	RG250T6N	BRADFORD WHITE	1
20810	03/23/2016	RG240T6N	BRADFORD WHITE	0
20811	03/23/2016	RG250T6N	BRADFORD WHITE	0
20812	03/23/2016	RG250T6N	BRADFORD WHITE	0
20813	03/23/2016	RG250T6N	BRADFORD WHITE	2
20814	03/25/2016	RG250T6N	BRADFORD WHITE	0
20815	03/25/2016	G76200	RUUD/RHEEM	0
20816	03/25/2016	RG250T6N	BRADFORD WHITE	0
20817	03/25/2016	RG250T6N	BRADFORD WHITE	0
20818	03/25/2016	RG240T6N	BRADFORD WHITE	0
20819	03/25/2016	RG250T6N	BRADFORD WHITE	0
20820	03/25/2016	FSG50	AO SMITH	0
20821	03/28/2016	PROG5036NRU60DV	RUUD	0
20822	03/28/2016	RG250T6N	BRADFORD WHITE	0
20823	03/28/2016	RG250T6N	BRADFORD WHITE	0
20824	03/29/2016	RG250T6N	BRADFORD WHITE	0
20825	03/29/2016	RG250T6N	BRADFORD WHITE	0
20826	03/30/2016	RG250H6N	BRADFORD WHITE	0
20827	03/30/2016	RG240S6N	BRADFORD WHITE	0
20828	03/30/2016	RG250T6N	BRADFORD WHITE	0
20829	03/31/2016	RG250T6N	BRADFORD WHITE	0
20830	03/31/2016	RG250T6N	BRADFORD WHITE	0
20831	03/31/2016	RG250T6N	BRADFORD WHITE	0
20832	03/31/2016	G76200	RUUD/RHEEM	0
20833	03/30/2016	RG250T6N	BRADFORD WHITE	0
20834	03/10/2016	PROG5036NRU60DV	RUUD	0
20835		RG240S6N	BRADFORD WHITE	0
20836	03/11/2016	RG240T6N	BRADFORD WHITE	0
20837	03/16/2016	RG250T6N	BRADFORD WHITE	0
20838	03/15/2016	G75125	RUUD/RHEEM	0
20839	03/14/2016	RG250T6N	BRADFORD WHITE	0
20840	03/08/2016	RG250T6N	BRADFORD WHITE	0
20841	03/19/2016	RG240S6N	BRADFORD WHITE	0
20842	03/20/2016	RG250T6N	BRADFORD WHITE	0
20843	03/18/2016	RG250T6N	BRADFORD WHITE	0
20844	04/17/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20845	04/20/2016	RG250T6N	BRADFORD WHITE	0
20846	03/02/2016	FSG50	AO SMITH	0
20847	03/07/2016	RG250T6N	BRADFORD WHITE	0
20848	03/11/2016	PROG5036NRU60DV	RUUD/RHEEM	1
20849	03/14/2016	RG250T6N	BRADFORD WHITE	1
20850	03/15/2016	RG250T6N	BRADFORD WHITE	0
20851	03/17/2016	RG250T6N	BRADFORD WHITE	0
20852	03/17/2016	RG250T6N	BRADFORD WHITE	0
20853	03/17/2016	RG250T6N	BRADFORD WHITE	0
20854	03/18/2016	RG250T6N	BRADFORD WHITE	0
20855	03/20/2016	RG250T6N	BRADFORD WHITE	0
20856	03/22/2016	PROG30S30NRU63	RUUD/RHEEM	0
20857	03/22/2016	RG240T6N	BRADFORD WHITE	0
20858	03/18/2016	G91-200	RUUD/RHEEM	1
20859	03/21/2016	RG250T6N	BRADFORD WHITE	0
20860	03/22/2016	RG250T6N	BRADFORD WHITE	0
20861	03/22/2016	RG250T6N	BRADFORD WHITE	0
20862	03/23/2016	RG240S6N	BRADFORD WHITE	0
20863	04/05/2016	RG250T6N	BRADFORD WHITE	0
20864	04/05/2016	RG240T6N	BRADFORD WHITE	0
20865	04/06/2016	RG250T6N	BRADFORD WHITE	0
20866	04/06/2016	RG250T6N	BRADFORD WHITE	0
20867	04/07/2016	RG250T6N	BRADFORD WHITE	0
20868	04/07/2016	RG250T6N	BRADFORD WHITE	1
20869	04/08/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20870	04/08/2016	RG250T6N	BRADFORD WHITE	0
20871	03/26/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20872	03/29/2016	RG250T6N	BRADFORD WHITE	0
20873	03/30/2016	RG250T6N	BRADFORD WHITE	0
20874	03/31/2016	RG250T6N	BRADFORD WHITE	2
20875	03/31/2016	RG250T6N	BRADFORD WHITE	0
20876	03/31/2016	PROG2932NRU63	RUUD/RHEEM	0
20877	03/31/2016	G76200	RUUD/RHEEM	1
20878	04/01/2016	G91200	RUUD/RHEEM	0
20879	03/06/2016	RG250T6N	BRADFORD WHITE	0
20880	02/10/2016	RG250T6N	BRADFORD WHITE	0
20881	03/10/2016	M440T6FBN	BRADFORD WHITE	0
20882	03/11/2016	RG250T6N	BRADFORD WHITE	0
20883	03/13/2016	RG250T6N	BRADFORD WHITE	1
20884	03/16/2016	RG250T6N	BRADFORD WHITE	0
20885	03/22/2016	PROG5036NRU60DV	RUUD/RHEEM	1
20886	03/22/2016	RG240T6N	BRADFORD WHITE	0
20887	03/24/2016	RG240T6N	BRADFORD WHITE	1
20888	03/24/2016	RG250T6N	BRADFORD WHITE	0
20889	03/25/2016	RG250T6N	BRADFORD WHITE	0
20890	03/26/2016	RG250T6N	BRADFORD WHITE	0
20891	04/01/2016	G91200	RUUD/RHEEM	0
20892	04/05/2016	RG250T6N	BRADFORD WHITE	0
20893	04/06/2016	RG250T6N	BRADFORD WHITE	0
20894	02/18/2016	G91200	RUUD/RHEEM	0
20895	04/08/2016	RG240T6N	Bradford White	0
20896	04/01/2016	RG250T6N	Bradford White	0
20897	04/05/2016	RG250T6N	Bradford White	0
20898	04/05/2015	RG240S6N	Bradford White	3

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20899	04/07/2016	RG240T6N	Bradford White	0
20900	03/10/2016	RG250T6N	BRADFORD WHITE	0
20901	03/26/2016	RG250T6N	BRADFORD WHITE	0
20902	03/30/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20903	03/31/2016	RG250T6N	BRADFORD WHITE	0
20904	04/02/2016	RG250T6N	BRADFORD WHITE	0
20905	04/03/2016	RG250T6N	BRADFORD WHITE	0
20906	04/04/2016	RG250T6N	BRADFORD WHITE	0
20907	04/05/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20908	04/08/2016	RG250T6N	BRADFORD WHITE	0
20909	04/08/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20910	04/10/2016	RG250T6N	BRADFORD WHITE	0
20911	04/06/2016	G75125	RUUD/RHEEM	0
20912	04/06/2016	G75125	RUUD/RHEEM	0
20913	04/11/2016	RG250T6N	BRADFORD WHITE	0
20914	04/12/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20915	03/29/2016	G82156	RUUD/RHEEM	0
20916	04/14/2016	G91200	RUUD/RHEEM	0
20917	04/18/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20918	04/19/2016	RG240T6N	BRADFORD WHITE	0
20919	04/18/2016	RG240S6N	BRADFORD WHITE	0
20920	04/15/2016	RG250T6N	BRADFORD WHITE	0
20921	04/15/2016	RG250T6N	BRADFORD WHITE	0
20922	04/15/2016	RG250T6N	BRADFORD WHITE	0
20923	04/14/2016	RG250T6N	BRADFORD WHITE	0
20924	04/14/2016	RG250T6N	BRADFORD WHITE	0
20925	04/14/2016	RG250T6N	BRADFORD WHITE	0
20926	04/14/2016	RG250T6N	BRADFORD WHITE	0
20927	04/11/2016	RG250T6N	BRADFORD WHITE	0
20928	04/12/2016	RG250T6N	BRADFORD WHITE	0
20929	04/12/2016	RG250T6N	BRADFORD WHITE	0
20930	04/12/2016	RG240T6N	BRADFORD WHITE	0
20931	04/12/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20932	04/01/2016	RG250T6N	BRADFORD WHITE	0
20933	04/13/2016	RG250T6N	BRADFORD WHITE	0
20934	04/08/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20935	03/23/2016	RG250T6N	BRADFORD WHITE	0
20936	04/14/2016	RG240T6N	BRADFORD WHITE	0
20937	04/26/2016	RG250T6N	BRADFORD WHITE	0
20938	04/26/2016	RG250T6N	BRADFORD WHITE	0
20939	04/27/2016	RG250T6N	BRADFORD WHITE	1
20940	04/10/2016	PH199119	PHOENIX	0
20941	02/29/2016	RG250T6N	BRADFORD WHITE	0
20942	04/19/2016	G76200	RUUD/RHEEM	2
20943	04/21/2016	G91200	RUUD/RHEEM	0
20944	03/19/2016	RG250T6N	BRADFORD WHITE	0
20945	04/15/2016	RG250T6N	BRADFORD WHITE	0
20946	04/16/2016	RG250T6N	BRADFORD WHITE	0
20947	03/19/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20948	04/18/2016	G82156	RUUD/RHEEM	0
20949	04/20/2016	RG240T6N	BRADFORD WHITE	0
20950	04/20/2016	RG250T6N	BRADFORD WHITE	0
20951	04/21/2016	RG250T6N	BRADFORD WHITE	0
20952	04/20/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
20953	04/17/2016	RG250T6N	BRADFORD WHITE	0
20954	04/19/2016	PROG5036NRU60DV	RUUD/RHEEM	1
20955	04/25/2016	RG250T6N	BRADFORD WHITE	0
20956	04/13/2016	RG250T6N	BRADFORD WHITE	0
20957	03/31/2016	RG250T6N	BRADFORD WHITE	0
20958	03/08/2016	RG250T6N	BRADFORD WHITE	0
20959	04/05/2016	RG250T6N	BRADFORD WHITE	0
20960	04/07/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20961	04/01/2016	RG250T6N	BRADFORD WHITE	0
20962	04/20/2016	PROG2932NRU63	RUUD/RHEEM	0
20963	04/23/2016	RG240S6N	BRADFORD WHITE	0
20964	04/22/2016	RG250T6N	BRADFORD WHITE	1
20965	04/19/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20966	04/20/2016	RG250T6N	BRADFORD WHITE	0
20967	04/21/2016	RG250T6N	BRADFORD WHITE	0
20968	04/22/2016	RG250T6N	BRADFORD WHITE	0
20969	04/14/2016	RG250T6N	BRADFORD WHITE	0
20970	04/14/2016	G91200	RUUD/RHEEM	1
20971	04/27/2016	RG240T6N	BRADFORD WHITE	0
20972	04/27/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20973	04/25/2016	RG240T6N	BRADFORD WHITE	0
20974	04/18/2016	RG250T6N	BRADFORD WHITE	0
20975	04/26/2016	RG250T6N	BRADFORD WHITE	0
20976	04/10/2016	G76200	RUUD/RHEEM	1
20977	04/27/2016	RG250T6N	BRADFORD WHITE	0
20978	04/27/2016	RG250T6N	BRADFORD WHITE	0
20979	06/02/2016	G91200	RUUD/RHEEM	2
20980	04/29/2016	RG250T6N	BRADFORD WHITE	0
20981	04/29/2016	RG240T6N	BRADFORD WHITE	0
20982	04/30/2016	RG240T6N	BRADFORD WHITE	0
20983	04/30/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20984	04/21/2016	RG240T6N	BRADFORD WHITE	0
20985	04/21/2016	RG250T6N	BRADFORD WHITE	3
20986	04/20/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20987	04/22/2016	RG250T6N	BRADFORD WHITE	1
20988	04/28/2016	MI50L6FBN	BRADFORD WHITE	0
20989	04/28/2016	PROG5036NRU60DV	RUUD/RHEEM	0
20990	04/28/2016	RG250T6N	BRADFORD WHITE	0
20991	04/28/2016	RG250H6N	BRADFORD WHITE	0
20992	04/23/2016	RG250T6N	BRADFORD WHITE	0
20993	04/18/2016	RG250T6N	BRADFORD WHITE	0
20994	06/07/2016	RG250T6N	BRADFORD WHITE	0
20995	05/01/2016	RG250T6N	BRADFORD WHITE	0
20996	04/12/2016	RG250T6N	BRADFORD WHITE	0
20997	05/03/2016	RG250T6N	BRADFORD WHITE	0
20998	04/26/2016	RG250T6N	BRADFORD WHITE	0
20999	04/05/2016	G82156	RUUD/RHEEM	0
21000	04/18/2016	G82156	RUUD/RHEEM	0
21001	04/26/2016	RG250T6N	BRADFORD WHITE	0
21002	05/05/2016	RG250T6N	BRADFORD WHITE	0
21003	04/21/2016	RG250T6N	BRADFORD WHITE	0
21004	05/05/2016	RG250T6N	BRADFORD WHITE	0
21005	04/18/2016	RG240T6N	BRADFORD WHITE	0
21006	05/27/2016	RG240T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21007	06/16/2016	RG240T6N	Bradford White	1
21008	05/17/2016	RG250T6N	Bradford White	0
21009	05/05/2016	RG250T6N	BRADFORD WHITE	0
21010	05/03/2016	RG250T6N	BRADFORD WHITE	0
21011	05/03/2016	RG250T6N	BRADFORD WHITE	0
21012	04/27/2016	PROG4038NRH62	RUUD	0
21013	07/09/2016	RG240S6N	Bradford White	0
21014	05/04/2016	RG250T6N	BRADFORD WHITE	0
21015	05/06/2016	RG250T6N	BRADFORD WHITE	0
21016	04/14/2016	PROG5036NRU60	RUUD	0
21017	04/30/2016	PROG5036NRU60	RUUD	1
21018	04/30/2016	RG240T6N	BRADFORD WHITE	0
21019	04/20/2016	RG240S6N	BRADFORD WHITE	0
21020	05/04/2016	RG250T6N	BRADFORD WHITE	0
21021	05/04/2016	RG250T6N	BRADFORD WHITE	0
21022	05/02/2016	RG250T6N	BRADFORD WHITE	0
21023	04/28/2016	M2XR504T6FBN	BRADFORD WHITE	0
21024	05/02/2016	RG250T6N	BRADFORD WHITE	1
21025	07/14/2016	RG250T6N	Bradford White	0
21026	04/23/2016	RG240S6N	Bradford White	0
21027	05/11/2016	RG250T6N	Bradford White	0
21028	05/04/2016	RG240S6N	Bradford White	0
21029	05/08/2016	RG250T6N	Bradford White	0
21030	05/12/2016	RG250T6N	Bradford White	0
21031	05/26/2016	RG250T6N	BRADFORD WHITE	0
21032	05/26/2016	RG240T6N	BRADFORD WHITE	0
21033	05/26/2016	RG240T6N	BRADFORD WHITE	0
21034	05/27/2016	RG250T6N	BRADFORD WHITE	0
21035	05/27/2016	RG250T6N	BRADFORD WHITE	0
21036	05/25/2016	RG250T6N	BRADFORD WHITE	0
21037	05/25/2016	PROG5036NRU60	RUUD	0
21038	05/25/2016	RG250T6N	BRADFORD WHITE	0
21039	05/24/2016	PROG5036NRU60	RUUD	0
21040	05/16/2016	PROG5036NRU60	RUUD	0
21041	05/24/2016	RG250T6N	BRADFORD WHITE	0
21042	02/10/2016	RG250T6N	BRADFORD WHITE	0
21043	05/16/2016	RG240T6N	BRADFORD WHITE	0
21044	05/26/2016	PROG5036NRU60	RUUD	0
21045	05/27/2016	RG250T6N	BRADFORD WHITE	0
21046	05/31/2016	RG240S6N	BRADFORD WHITE	0
21047	05/26/2016	G75125	RUUD/RHEEM	0
21048	05/31/2016	G91200	RUUD/RHEEM	2
21049	05/21/2016	RG2DV40S6N	BRADFORD WHITE	0
21050	06/14/2016	G91200	RUUD/RHEEM	0
21051	05/31/2016	PROG5036NRU60	RUUD	0
21052	06/16/2015	MI5036FBN	BRADFORD WHITE	0
21053	05/29/2016	RG250T6N	BRADFORD WHITE	0
21054	05/27/2016	RG240T6N	BRADFORD WHITE	0
21055	05/29/2016	RG250T6N	BRADFORD WHITE	0
21056	05/27/2016	RG250T6N	BRADFORD WHITE	1
21057	05/23/2016	RG250T6N	BRADFORD WHITE	0
21058	05/19/2016	RG250T6N	BRADFORD WHITE	0
21059	05/14/2016	RG250T6N	BRADFORD WHITE	0
21060	06/01/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21061	06/01/2016	PROG5036NRU60	RUUD	0
21062	06/05/2016	RG250T6N	BRADFORD WHITE	0
21063	06/04/2016	M2XR504T6FBN	BRADFORD WHITE	0
21064	06/04/2016	RG250T6N	BRADFORD WHITE	0
21065	06/02/2016	RG250T6N	BRADFORD WHITE	0
21066	06/07/2016	PROG5036NRU60	RUUD	0
21067	05/28/2016	RG2DV40S6N	BRADFORD WHITE	0
21068	02/18/2016	RG250T6N	BRADFORD WHITE	0
21069	05/31/2016	RG250T6N	BRADFORD WHITE	0
21070	06/03/2016	RG250T6N	BRADFORD WHITE	0
21071	05/12/2016	RG250T6N	Bradford White	0
21072	05/09/2016	RG250T6N	Bradford White	0
21073	05/09/2016	RG250T6N	Bradford White	0
21074	04/26/2016	RG240T6N	Bradford White	0
21075	05/11/2016	G82156	RUUD/RHEEM	1
21076	05/10/2016	RG250T6N	Bradford White	0
21077	07/28/2016	RG250T6N	Bradford White	0
21078	05/08/2016	PROG5036NRU60DV	Ruud	0
21079	05/09/2016	RG250T6N	Bradford White	0
21080	05/09/2016	PROG5036NRU60DV	STATE	0
21081	05/06/2016	RG250T6N	Bradford White	0
21082	05/11/2016	RG250T6N	Bradford White	0
21083	05/11/2016	RG250T6N	Bradford White	0
21084	08/01/2016	RG250T6N	BRADFORD WHITE	0
21085	07/11/2016	G91200	RUUD/RHEEM	1
21086	04/14/2016	G76200	Ruud/Rheem	0
21087	04/14/2016	G76200	Ruud/Rheem	0
21088	06/08/2016	G82156	RUUD/RHEEM	2
21089	05/06/2016	RG250T6N	Bradford White	0
21090	05/12/2016	RG240T6N	Bradford White	0
21091	05/13/2016	PRX50	STATE	0
21092	06/06/2016	RG250T6N	BRADFORD WHITE	0
21093	06/08/2016	RG250T6N	BRADFORD WHITE	0
21094	06/08/2016	RG240T6N	BRADFORD WHITE	0
21095	06/14/2016	PROG5036NRU60	RUUD RHEEM	0
21096	06/08/2016	RG240T6N	BRADFORD WHITE	0
21097	06/07/2016	RG250T6N	BRADFORD WHITE	0
21098	06/13/2016	RG250L6N	BRADFORD WHITE	3
21099	06/02/2016	RG2DV50S6N	BRADFORD WHITE	0
21100	06/16/2016	PROG5036NRU60DV	RUUD RHEEM	0
21101	06/14/2016	PROG5036NRU60	RUUD RHEEM	0
21102	05/17/2016	RG250T6N	Bradford White	0
21103	05/10/2016	RG250T6N	Bradford White	0
21104	05/13/2016	G91200	RUUD/RHEEM	1
21105	05/17/2016	RG275H6N	Bradford White	0
21106	05/06/2016	RG240T6N	Bradford White	1
21107	05/17/2016	RG250T6N	Bradford White	0
21108	05/18/2016	PROG5036NRU60DV	Ruud	0
21109	05/18/2016	PGR50	AO SMITH	0
21110	06/07/2016	RG250T6N	BRADFORD WHITE	0
21111	06/08/2016	RG250T6N	BRADFORD WHITE	0
21112	06/06/2016	RG250T6N	BRADFORD WHITE	1
21113	06/13/2016	RG250T6N	BRADFORD WHITE	0
21114	06/13/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21115	06/13/2016	RG240T6N	BRADFORD WHITE	0
21116	06/09/2016	RG240T6N	BRADFORD WHITE	0
21117	06/09/2016	RG250T6N	BRADFORD WHITE	1
21118	06/06/2016	RG250T6N	BRADFORD WHITE	0
21119	06/24/2016	RG250T6N	BRADFORD WHITE	0
21120	06/17/2016	RG240S6N	BRADFORD WHITE	0
21121	06/08/2016	RG250T6N	BRADFORD WHITE	0
21122	06/17/2016	RG240T6N	BRADFORD WHITE	0
21123	06/17/2016	PROG5036NRU60	RUUD RHEEM	0
21124	06/20/2016	RG250T6N	BRADFORD WHITE	0
21125	06/23/2016	RG250L6N	BRADFORD WHITE	0
21126	07/01/2016	PROG5036NRU60	RUUD RHEEM	0
21127	07/01/2016	PROG5036NRU60	RUUD RHEEM	0
21128	07/06/2016	RG250T6N	BRADFORD WHITE	0
21129	07/01/2016	PROG5036NRU60	RUUD RHEEM	0
21130	07/01/2016	RG250T6N	BRADFORD WHITE	0
21131	06/30/2016	G91200	RUUD/RHEEM	0
21132	06/30/2016	G91200	RUUD/RHEEM	0
21133	06/16/2016	G76200	RUUD/RHEEM	1
21134	06/30/2016	G75125	RUUD RHEEM	1
21135	06/28/2016	G91200	RUUD/RHEEM	0
21136	06/28/2016	G91200	RUUD/RHEEM	0
21137	05/13/2016	RG250T6N	Bradford White	0
21138	05/13/2016	PROG5036NRU60DV	Ruud/Rheem	0
21139	05/12/2016	RG250T6N	Bradford White	0
21140	05/16/2016	PGR50	AO SMITH	0
21141	05/14/2016	PROG5036NRU60DV	Ruud/Rheem	0
21142	05/16/2016	RG250H6N	Bradford White	2
21143	05/16/2016	RG250T6N	Bradford White	0
21144	05/17/2016	RG240S6N	Bradford White	0
21145	05/17/2016	PROG5036NRU60DV	Ruud/Rheem	0
21146	05/17/2016	RG240S6N	Bradford White	0
21147	05/17/2016	RG250T6N	Bradford White	0
21148	05/09/2016	RG240T6N	Bradford White	0
21149	05/05/2016	RG250T6N	Bradford White	0
21150	05/16/2016	RG250T6N	Bradford White	0
21151	05/23/2016	G82156	Ruud/Rheem	0
21152	05/20/2016	RG250T6N	Bradford White	0
21153	05/20/2016	RG240T6N	Bradford White	0
21154	05/20/2016	RG240T6N	Bradford White	0
21155	05/17/2016	RG240T6N	Bradford White	0
21156	05/22/2016	RG250T6N	Bradford White	0
21157	05/04/2016	G91200	RUUD/RHEEM	0
21158	04/04/2016	G91200	RUUD/RHEEM	3
21159	05/24/2016	RG250T6N	Bradford White	0
21160	06/15/2016	RG250T6N	Bradford White	0
21161	06/15/2016	RG250T6N	Bradford White	0
21162	06/16/2016	G91200	Ruud/Rheem	1
21163	05/19/2016	RG250T6N	Bradford White	0
21164	05/20/2016	PROG5036NRU60	Ruud/Rheem	0
21165	05/19/2016	RG250T6N	Bradford White	0
21166	05/16/2016	RG240T6N	Bradford White	0
21167	05/22/2016	RG240T6N	Bradford White	0
21168	05/12/2016	G91200	Ruud/Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21169	05/23/2016	G82156	Ruud/Rheem	3
21170	05/19/2016	G75125	RUUD/RHEEM	0
21171	05/20/2016	G82156	RUUD/RHEEM	2
21172	05/24/2016	RG250T6N	Bradford White	0
21173	05/24/2016	RG240T6N	Bradford White	0
21174	05/02/2016	RG250T6N	Bradford White	0
21175	05/11/2016	RG250T6N	Bradford White	0
21176	05/20/2016	RG250T6N	Bradford White	0
21177	06/29/2016	RG250T6N	Bradford White	0
21178	06/29/2016	RG250T6N	Bradford White	0
21179	06/29/2016	RG240T6N	Bradford White	0
21180	06/20/2016	RG250T6N	Bradford White	0
21181	06/28/2016	RG250T6N	Bradford White	0
21182	06/28/2016	RG250T6N	Bradford White	0
21183	06/03/2016	RG250T6N	Bradford White	0
21184	06/15/2016	RG250T6N	Bradford White	0
21185	06/20/2016	RG240T6N	Bradford White	0
21186	06/09/2016	RG250T6N	Bradford White	0
21187	06/09/2016	RG240T6N	Bradford White	0
21188	06/27/2016	RG250T6N	Bradford White	0
21189	06/30/2016	RG250T6N	Bradford White	0
21190	06/25/2016	RG240T6N	Bradford White	0
21191	06/25/2016	RG250T6N	Bradford White	0
21192	06/20/2016	RG250T6N	Bradford White	0
21193	06/25/2016	RG250T6N	Bradford White	0
21194	06/27/2016	PROG5036NRU60	RUUD	0
21195	06/22/2016	RG240T6N	Bradford White	0
21196	06/20/2016	RG250T6N	Bradford White	0
21197	06/21/2016	RG250T6N	Bradford White	0
21198	06/20/2016	RG250H6N	Bradford White	1
21199	06/30/2016	PROG5036NRU60	RUUD	0
21200	06/30/2016	RG240T6N	Bradford White	0
21201	07/01/2016	PROG5036NRU60	RUUD	0
21202	07/06/2016	RG240T6N	Bradford White	0
21203	07/06/2016	RG250T6N	Bradford White	0
21204	03/11/2015	M45036FBN	RUUD	0
21205	07/05/2016	RG250T6N	Bradford White	0
21206	07/05/2016	RG250L6N	Bradford White	0
21207	07/01/2016	PROG5036NRU60	RUUD	0
21208	07/01/2016	RG250T6N	Bradford White	0
21209	06/27/2016	RG250T6N	Bradford White	0
21210	07/05/2016	PROG5036NRU60	RUUD	0
21211	07/05/2016	PROG5036NRU60	RUUD	0
21212	07/05/2016	RG240T6N	Bradford White	0
21213	07/05/2016	RG250T6N	Bradford White	0
21214	07/02/2016	PROG5036NRU60	RUUD	0
21215	07/06/2016	RG240T6N	Bradford White	0
21216	07/07/2016	RG250T6N	Bradford White	0
21217	07/06/2016	G75125	RUUD/RHEEM	0
21218	05/20/2016	RG250T6N	Bradford White	0
21219	07/08/2016	RG250T6N	Bradford White	0
21220	07/03/2016	RG250T6N	Bradford White	0
21221	05/20/2016	PROG5036NRU60DV	Ruud/Rheem	0
21222	05/18/2016	RG250T6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21223	06/07/2016	RG250T6N	Bradford White	0
21224	06/14/2016	RG250T6N	Bradford White	0
21225	06/16/2016	RG240S6N	Bradford White	0
21226	06/20/2016	RG250T6N	Bradford White	0
21227	06/14/2016	RG250T6N	Bradford White	0
21228	06/14/2016	RG250T6N	Bradford White	0
21229	06/15/2016	RG250H6N	Bradford White	1
21230	06/16/2016	RG250T6N	Bradford White	0
21231	06/07/2016	RG250T6N	Bradford White	1
21232	06/06/2016	RG250T6N	Bradford White	0
21233	05/28/2016	RG240S6N	Bradford White	0
21234	04/28/2016	PROG2932NRU62	Ruud/Rheem	0
21235	05/21/2016	RG250T6N	Bradford White	0
21236	07/07/2016	RG240S6N	Bradford White	0
21237	07/07/2016	RG250T6N	Bradford White	0
21238	08/15/2016	RG250T6N	Bradford White	1
21239	07/06/2016	G82156	RUUD/RHEEM	0
21240	07/26/2016	G91200	RUUD/RHEEM	1
21241	07/15/2016	RG250T6N	Bradford White	0
21242	10/21/2015	RG250T6N	Bradford White	1
21243	07/30/2016	RG250T6N	Bradford White	0
21244	07/30/2016	RG240S6N	Bradford White	0
21245	07/18/2016	RG250T6N	Bradford White	0
21246	07/18/2016	RG250T6N	Bradford White	0
21247	07/18/2016	RG250T6N	Bradford White	0
21248	08/08/2016	RG250T6N	Bradford White	0
21249	08/17/2016	G91200	RUUD/RHEEM	1
21250	08/16/2016	PROG5036NRU60DV	Ruud/Rheem	0
21251	08/05/2016	PROG5036NRU60DV	Ruud/Rheem	0
21252	08/05/2016	PROG5036NRU60DV	Ruud/Rheem	0
21253	08/05/2016	RG250T6N	Bradford White	0
21254	08/03/2016	RG240T6N	Bradford White	0
21255	08/03/2016	RG250T6N	Bradford White	0
21256	08/02/2016	RG250T6N	Bradford White	0
21257	12/12/2015	RG250T6N	Bradford White	0
21258	06/14/2016	G75125	RUUD/RHEEM	0
21259	07/03/2016	RG250T6N	Bradford White	0
21260	03/21/2016	PH199119	PHOENIX	0
21261	03/21/2016	PH199119	PHOENIX	1
21262	07/13/2016	RG250T6N	Bradford White	0
21263	07/13/2016	RG240T6N	Bradford White	1
21264	07/13/2016	RG240T6N	Bradford White	0
21265	03/15/2016	RG240T6N	Bradford White	0
21266	05/01/2016	RG250T6N	Bradford White	0
21267	06/19/2016	RG250T6N	Bradford White	0
21268	07/11/2016	RG240T6N	Bradford White	1
21269	07/13/2016	RG240T6N	Bradford White	0
21270	07/14/2016	RG250T6N	Bradford White	0
21271	07/14/2016	FSG50	AO SMITH	0
21272	07/13/2016	RG250T6N	Bradford White	0
21273	07/13/2016	RG250T6N	Bradford White	0
21274	07/15/2016	RG240T6N	Bradford White	0
21275	07/16/2016	RG240T6N	Bradford White	0
21276	07/18/2016	RG250T6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21277	07/14/2016	RG275H6N	Bradford White	0
21278	07/14/2016	RG275H6N	Bradford White	0
21279	06/24/2016	RG250H6N	Bradford White	0
21280	07/08/2016	RG250T6N	Bradford White	0
21281	07/02/2016	RG240T6N	Bradford White	0
21282	07/15/2016	RG240S6N	Bradford White	0
21283	07/15/2016	RG240T6N	Bradford White	0
21284	07/12/2016	PROG5036NRU60	RUUD	0
21285	07/12/2016	RG250T6N	Bradford White	0
21286	07/12/2016	RG250T6N	Bradford White	0
21287	07/11/2016	PROG5036NRU60	RUUD	0
21288	07/11/2016	RG250T6N	Bradford White	0
21289	07/11/2016	RG250T6N	Bradford White	0
21290	07/11/2016	RG250T6N	Bradford White	0
21291	07/02/2016	RG240S6N	BRADFORD-WHITE	0
21292	07/01/2016	RG250T6N	Bradford White	0
21293	07/11/2016	RG250H6N	Bradford White	0
21294	07/09/2016	RG250T6N	Bradford White	1
21295	07/09/2016	RG250T6N	Bradford White	0
21296	07/06/2016	G75125	RUUD/RHEEM	0
21297	07/07/2016	RG240T6N	Bradford White	0
21298	06/19/2016	RG250T6N	BRADFORD WHITE	0
21299	06/22/2016	RG250T6N	BRADFORD WHITE	0
21300	06/23/2016	RG240T6N	BRADFORD WHITE	0
21301	06/21/2016	RG250T6N	BRADFORD WHITE	0
21302	05/27/2016	PROG5036NRU60	RUUD	1
21303	06/17/2016	RG250T6N	BRADFORD WHITE	0
21304	06/17/2016	PROG5036NRU60DV	RUUD	0
21305	06/21/2016	RG275H6N	BRADFORD WHITE	0
21306	07/29/2016	PROG5038NRU60	RUUD	0
21307	07/23/2016	G91200	RUUD	2
21308	08/22/2016	RG240T6N	BRADFORD WHITE	0
21309	07/18/2016	RG250T6N	BRADFORD WHITE	0
21310	07/18/2016	RG250T6N	BRADFORD WHITE	0
21311	07/18/2016	G91200	RUUD	0
21312	07/16/2016	G82156	RUUD/RHEEM	0
21313	07/16/2016	G82156	RUUD/RHEEM	4
21314	07/11/2016	G82156	RUUD/RHEEM	0
21315	07/18/2016	G91200	RUUD/RHEEM	1
21316	07/25/2016	G76200	RUUD/RHEEM	0
21317	07/20/2016	RG250T6N	BRADFORD WHITE	0
21318	07/25/2016	RG250T6N	BRADFORD WHITE	0
21319	07/27/2016	RG240S6N	BRADFORD WHITE	0
21320	07/21/2016	PROG5036NRU60DV	RUUD RHEEM	0
21321	07/25/2016	RG240T6N	BRADFORD WHITE	0
21322	07/20/2016	RG240S6N	BRADFORD WHITE	3
21323	07/21/2016	RG250T6N	BRADFORD WHITE	0
21324	08/02/2016	RG240S6N	BRADFORD WHITE	0
21325	08/02/2016	RG250T6N	BRADFORD WHITE	0
21326	08/02/2016	RG240T6N	BRADFORD WHITE	1
21327	08/02/2016	RG250T6N	BRADFORD WHITE	0
21328	08/01/2016	RG250T6N	BRADFORD WHITE	0
21329	08/02/2016	G82156	RUUD/RHEEM	0
21330	07/08/2016	G91200	RUUD RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21331	07/08/2016	G91200	RUUD RHEEM	0
21332	04/04/2016	PH199119	PHOENIX	0
21333	07/28/2016	G91200	RUUD	0
21334	07/26/2016	PROG5036NRU60DV	RUUD	0
21335	07/13/2016	RG250T6N	BRADFORD WHITE	0
21336	07/25/2016	RG250T6N	BRADFORD WHITE	0
21337	07/25/2016	RG240S6N	BRADFORD WHITE	1
21338	07/16/2016	RG250T6N	BRADFORD WHITE	0
21339	07/19/2016	RG250T6N	BRADFORD WHITE	1
21340	07/25/2016	RG250T6N	BRADFORD WHITE	0
21341	07/20/2016	RG250T6N	BRADFORD WHITE	0
21342	07/27/2016	RG250T6N	BRADFORD WHITE	0
21343	07/27/2016	RG240T6N	BRADFORD WHITE	0
21344	07/22/2016	RG240T6N	BRADFORD WHITE	0
21345	07/26/2016	PROG5036NRU60DV	RUUD	0
21346	07/26/2016	PROG5038NRU60	RUUD	0
21347	07/26/2016	PROG5036NRU60DV	RUUD	0
21348	07/25/2016	RG250T6N	BRADFORD WHITE	0
21349	07/22/2016	RG250T6N	BRADFORD WHITE	0
21350	07/22/2016	RG250T6N	BRADFORD WHITE	0
21351	07/14/2016	RG240T6N	BRADFORD WHITE	0
21352	07/14/2016	RG250L6N	BRADFORD WHITE	0
21353	08/10/2016	RG250T6N	BRADFORD WHITE	0
21354	08/10/2016	RG250T6N	BRADFORD WHITE	0
21355	08/10/2016	RG250T6N	BRADFORD WHITE	0
21356	08/09/2016	RG250T6N	BRADFORD WHITE	0
21357	08/09/2016	RG250T6N	BRADFORD WHITE	0
21358	08/09/2016	PROG2932NRU62	RUUD	0
21359	07/27/2016	PROG2932NRU62	RUUD	0
21360	08/11/2016	PROG5036NRU60DV	RUUD	0
21361	08/11/2016	RG250T6N	BRADFORD WHITE	0
21362	08/12/2016	PROG5036NRU60DV	RUUD	1
21363	07/29/2016	G76200	RUUD	0
21364	07/28/2016	G91200	RUUD	1
21365	08/08/2016	RG250T6N	Bradford White	0
21366	08/08/2016	RG250T6N	Bradford White	0
21367	07/22/2016	RG250T6N	Bradford White	0
21368	07/28/2016	RG240S6N	Bradford White	0
21369	08/01/2016	RG250T6N	Bradford White	0
21370	07/20/2016	21VR40	RHEEM	1
21371	07/20/2016	PROG2932NRU62	Ruud/Rheem	0
21372	07/27/2016	RG240T6N	BRADFORD WHITE	0
21373	07/28/2016	RG250T6N	BRADFORD WHITE	0
21374	07/28/2016	RG250H6N	BRADFORD WHITE	0
21375	07/31/2016	PROG5036NRU60DV	RUUD	0
21376	07/29/2016	RG250T6N	BRADFORD WHITE	0
21377	07/20/2016	PROG5036NRU60DV	RUUD	0
21378	07/13/2016	RG250T6N	BRADFORD WHITE	0
21379	07/19/2016	RG250T6N	BRADFORD WHITE	0
21380	08/04/2016	RG240S6N	BRADFORD WHITE	0
21381	07/11/2016	RG240T6N	BRADFORD WHITE	0
21382	07/14/2016	RG250T6N	BRADFORD WHITE	0
21383	07/14/2016	PROG2932NRU63	RUUD	0
21384	07/18/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21385	07/18/2016	RG250T6N	BRADFORD WHITE	0
21386	07/18/2016	PROG5036NRU60DV	RUUD	0
21387	08/08/2016	RG250T6N	BRADFORD WHITE	0
21388	08/04/2016	RG250T6N	BRADFORD WHITE	0
21389	08/06/2016	RG240T6N	BRADFORD WHITE	0
21390	08/04/2016	RG240T6N	BRADFORD WHITE	0
21391	07/27/2016	RG240S6N	Bradford White	1
21392	07/21/2016	RG250T6N	Bradford White	0
21393	07/21/2016	RG250T6N	Bradford White	0
21394	07/22/2016	RG250T6N	BRADFORD-WHITE	0
21395	07/22/2016	RG250T6N	Bradford White	1
21396	07/24/2016	RG250T6N	Bradford White	0
21397	07/22/2016	RG250T6N	Bradford White	0
21398	07/22/2016	RG250T6N	Bradford White	0
21399	07/25/2016	RG250T6N	Bradford White	0
21400	07/22/2016	RG240T6N	Bradford White	1
21401	08/12/2016	RG250T6N	BRADFORD WHITE	0
21402	08/11/2016	RG250T6N	BRADFORD WHITE	0
21403	08/13/2016	RG250T6N	BRADFORD WHITE	0
21404	08/09/2016	RG250T6N	BRADFORD WHITE	0
21405	08/08/2016	RG250T6N	BRADFORD WHITE	0
21406	08/05/2016	RG250T6N	BRADFORD WHITE	0
21407	08/11/2016	PROG5038NRU60	RUUD	0
21408	08/12/2016	PROG5036NRU60DV	RUUD	0
21409	08/12/2016	RG250T6N	BRADFORD WHITE	0
21410	08/12/2016	RG250T6N	BRADFORD WHITE	0
21411	08/15/2016	PROG5036NRU60DV	RUUD	0
21412	08/02/2016	RG250T6N	BRADFORD WHITE	0
21413	08/02/2016	RG240S6N	BRADFORD WHITE	0
21414	08/14/2016	RG250T6N	BRADFORD WHITE	0
21415	08/15/2016	RG250T6N	BRADFORD WHITE	0
21416	08/11/2016	RG250T6N	BRADFORD WHITE	0
21417	08/16/2016	RG250T6N	BRADFORD WHITE	0
21418	08/08/2016	RG250T6N	BRADFORD WHITE	0
21419	06/21/2016	RG250T6N	BRADFORD WHITE	0
21420	08/12/2016	G91200	RUUD/RHEEM	2
21421	08/22/2016	G75125	RUUD/RHEEM	1
21422	08/12/2016	PROG2932NRU63	RUUD	1
21423	08/22/2016	RG250T6N	BRADFORD WHITE	0
21424	08/19/2016	RG250T6N	BRADFORD WHITE	0
21425	08/23/2016	RG240T6N	BRADFORD WHITE	0
21426	08/23/2016	RG2DV50S6N	BRADFORD WHITE	1
21427	08/11/2016	RG250T6N	Bradford White	0
21428	08/08/2016	RG250T6N	Bradford White	0
21429	08/08/2016	RG240T6N	Bradford White	0
21430	08/15/2016	PROG5036NRU60DV	Ruud/Rheem	0
21431	08/19/2016	PROG5036NRU60DV	Ruud/Rheem	0
21432	08/16/2016	PROG5036NRU60DV	Ruud/Rheem	0
21433	08/13/2016	RG250T6N	Bradford White	0
21434	08/17/2016	RG240T6N	Bradford White	0
21435	08/17/2016	RG250L6N	Bradford White	0
21436	08/12/2016	RG250H6N	Bradford White	0
21437	07/28/2016	G82156	RUUD/RHEEM	3
21438	08/12/2016	G91200	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21439	08/18/2016	RG250T6N	Bradford White	0
21440	08/05/2016	RG250T6N	Bradford White	0
21441	08/16/2016	RG250T6N	Bradford White	0
21442	08/18/2016	RG250T6N	Bradford White	0
21443	08/21/2016	RG250T6N	BRADFORD WHITE	0
21444	08/19/2016	PROG5036NRU60DV	RUUD	0
21445	08/15/2016	RG240T6N	BRADFORD WHITE	0
21446	07/02/2016	PROG5036NRU60DV	RUUD	0
21447	08/23/2016	RG250T6N	BRADFORD WHITE	0
21448	08/23/2016	RG240T6N	BRADFORD WHITE	0
21449	08/23/2016	RG250T6N	BRADFORD WHITE	0
21450	08/17/2016	RG250T6N	BRADFORD WHITE	0
21451	08/23/2016	PROG5036NRU60DV	RUUD	0
21452	08/23/2016	RG250T6N	BRADFORD WHITE	0
21453	08/22/2016	RG240S6N	BRADFORD WHITE	0
21454	08/25/2016	MI50L6FBN	BRADFORD WHITE	0
21455	07/22/2016	RG240T6N	BRADFORD WHITE	0
21456	08/24/2016	RG250T6N	BRADFORD WHITE	0
21457	08/31/2016	PROG5036NRU60DV	RUUD	0
21458	08/31/2016	RG250T6N	BRADFORD WHITE	0
21459	08/31/2016	RG240T6N	BRADFORD WHITE	0
21460	08/31/2016	RG250T6N	BRADFORD WHITE	0
21461	08/30/2016	RG250T6N	BRADFORD WHITE	0
21462	08/30/2016	RG240S6N	BRADFORD WHITE	0
21463	08/25/2016	RG250H6N	BRADFORD WHITE	0
21464	08/29/2016	RG240T6N	BRADFORD WHITE	0
21465	08/29/2016	RG240T6N	BRADFORD WHITE	0
21466	08/29/2016	PROG5036NRU60DV	RUUD	0
21467	08/29/2016	RG2DV50S6N	BRADFORD WHITE	0
21468	08/26/2016	PROG5036NRU60DV	RUUD	0
21469	08/26/2016	RG250T6N	BRADFORD WHITE	0
21470	08/20/2016	PROG5036NRU60DV	RUUD	0
21471	08/27/2016	RG250T6N	BRADFORD WHITE	0
21472	08/27/2016	RG250T6N	BRADFORD WHITE	0
21473	08/26/2016	RG240T6N	BRADFORD WHITE	0
21474	08/26/2016	RG240T6N	BRADFORD WHITE	0
21475	08/21/2016	RG250T6N	BRADFORD WHITE	0
21476	08/21/2016	RG250T6N	BRADFORD WHITE	1
21477	08/23/2016	RG240S6N	BRADFORD WHITE	0
21478	08/23/2016	RG240T6N	BRADFORD WHITE	0
21479	08/25/2016	RG250T6N	BRADFORD WHITE	0
21480	08/25/2016	RG250T6N	BRADFORD WHITE	0
21481	08/24/2016	RG250T6N	BRADFORD WHITE	0
21482	08/24/2016	RG250T6N	BRADFORD WHITE	0
21483	08/24/2016	RG250T6N	BRADFORD WHITE	0
21484	07/26/2016	RG250H6N	BRADFORD WHITE	0
21485	08/14/2016	G91200	RUUD	0
21486	07/17/2016	PH199119	PHOENIX	1
21487	08/25/2016	RG275H6N	BRADFORD WHITE	1
21488	09/02/2016	RG250T6N	BRADFORD WHITE	0
21489	09/01/2016	RG250T6N	BRADFORD WHITE	0
21490	08/22/2016	PROG2932NRU62	RUUD	0
21491	08/16/2016	RG240S6N	BRADFORD WHITE	0
21492	09/01/2016	RG240T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21493	09/02/2016	RG250T6N	BRADFORD WHITE	0
21494	09/08/2016	RG250T6N	BRADFORD WHITE	0
21495	09/08/2016	RG250T6N	BRADFORD WHITE	0
21496	09/08/2016	RG250T6N	BRADFORD WHITE	0
21497	09/08/2016	RG250T6N	BRADFORD WHITE	0
21498	09/08/2016	RG250T6N	BRADFORD WHITE	0
21499	09/03/2016	RG250T6N	BRADFORD WHITE	0
21500	09/02/2016	MI50L6FBN	BRADFORD WHITE	0
21501	09/06/2016	RG250T6N	BRADFORD WHITE	0
21502	09/07/2016	RG250T6N	BRADFORD WHITE	0
21503	09/06/2016	RG250T6N	BRADFORD WHITE	0
21504	09/02/2016	RG275H6N	BRADFORD WHITE	4
21505	09/13/2016	G91200	RUUD/RHEEM	2
21506	09/09/2016	G76200	RUUD	0
21507	09/03/2016	G91200	RUUD/RHEEM	0
21508	07/30/2016	G76200	RUUD	0
21509	09/06/2016	RG250T6N	BRADFORD WHITE	0
21510	08/29/2016	RG250T6N	BRADFORD WHITE	0
21511	09/06/2016	RG250T6N	BRADFORD WHITE	0
21512	09/07/2016	RG250T6N	BRADFORD WHITE	0
21513	09/06/2016	PROG5036NRU60DV	RUUD	0
21514	09/06/2016	RG250T6N	BRADFORD WHITE	0
21515	09/06/2016	RG250T6N	BRADFORD WHITE	0
21516	09/02/2016	RG250T6N	BRADFORD WHITE	0
21517	09/02/2016	RG250T6N	BRADFORD WHITE	0
21518	09/12/2016	RG250T6N	BRADFORD WHITE	0
21519	09/12/2016	RG250T6N	BRADFORD WHITE	0
21520	09/12/2016	RG250T6N	BRADFORD WHITE	0
21521	09/12/2016	RG240T6N	BRADFORD WHITE	0
21522	09/10/2016	PROG5036NRU60DV	RUUD	0
21523	09/05/2016	RG250L6N	BRADFORD WHITE	0
21524	09/08/2016	RG250T6N	BRADFORD WHITE	1
21525	09/13/2016	RG250T6N	BRADFORD WHITE	1
21526	09/13/2016	RG250T6N	BRADFORD WHITE	0
21527	09/13/2016	PROG5036NRU60DV	RUUD	0
21528	09/09/2016	RG250T6N	BRADFORD WHITE	0
21529	09/09/2016	PROG2932NRU63	RUUD	0
21530	09/07/2016	RG250T6N	BRADFORD WHITE	0
21531	09/09/2016	RG250T6N	BRADFORD WHITE	0
21532	09/13/2016	PROG5036NRU60DV	RUUD	0
21533	09/15/2016	RG250T6N	BRADFORD WHITE	0
21534	09/07/2016	PROG5036NRU60DV	RUUD	0
21535	09/13/2016	RG250T6N	BRADFORD WHITE	0
21536	09/16/2016	RG250T6N	BRADFORD WHITE	1
21537	09/16/2016	RG250T6N	BRADFORD WHITE	0
21538	09/16/2016	RG250T6N	BRADFORD WHITE	0
21539	09/20/2016	RG250T6N	BRADFORD WHITE	2
21540	09/18/2016	RG250T6N	BRADFORD WHITE	0
21541	09/18/2016	RG250T6N	BRADFORD WHITE	0
21542	09/16/2016	RG250T6N	BRADFORD WHITE	0
21543	09/26/2016	RG250T6N	BRADFORD WHITE	0
21544	09/11/2016	RG250T6N	BRADFORD WHITE	0
21545	09/10/2016	RG240S6N	BRADFORD WHITE	0
21546	09/10/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21547	09/13/2016	RG250T6N	BRADFORD WHITE	0
21548	09/22/2016	G91200	RUUD	0
21549	09/29/2016	G75125	RUUD/RHEEM	0
21550	11/01/2016	RG250T6N	BRADFORD WHITE	0
21551	06/29/2016	G91200	RUUD/RHEEM	0
21552	06/29/2016	G91200	RUUD/RHEEM	0
21553	06/29/2016	G91200	RUUD/RHEEM	0
21554	09/12/2016	G76200	RUUD/RHEEM	0
21555	09/12/2016	G91200	RUUD/RHEEM	2
21556	09/16/2016	RG250H6N	BRADFORD WHITE	0
21557	08/09/2016	PROG2932NRU63	RUUD	0
21558	09/09/2016	RG250T6N	BRADFORD WHITE	0
21559	09/07/2016	RG240S6N	BRADFORD WHITE	0
21560	09/09/2016	RG250T6N	BRADFORD WHITE	0
21561	09/09/2016	PROG2932NRU62	RUUD	0
21562	09/09/2016	RG240T6N	BRADFORD WHITE	0
21563	09/09/2016	PROG5036NRU60DV	RUUD	0
21564	09/12/2016	RG250T6N	BRADFORD WHITE	1
21565	09/12/2016	RG240T6N	BRADFORD WHITE	1
21566	09/21/2016	RG250T6N	BRADFORD WHITE	0
21567	09/20/2016	RG250H6N	BRADFORD WHITE	0
21568	09/20/2016	RG250T6N	BRADFORD WHITE	0
21569	09/19/2016	RG250T6N	BRADFORD WHITE	0
21570	09/19/2016	RG250T6N	BRADFORD WHITE	0
21571	09/16/2016	RG250T6N	BRADFORD WHITE	0
21572	09/20/2016	RG250T6N	BRADFORD WHITE	0
21573	09/20/2016	RG250T6N	BRADFORD WHITE	0
21574	09/21/2016	PROG5036NRU60DV	RUUD	0
21575	09/19/2016	RG250T6N	BRADFORD WHITE	0
21576	09/13/2016	RG250T6N	BRADFORD WHITE	1
21577	09/02/2016	RG250T6N	BRAD	0
21578	09/16/2016	RG250T6N	BRADFORD WHITE	1
21579	09/27/2016	RG240T6N	BRADFORD WHITE	0
21580	09/22/2016	RG240T6N	BRADFORD WHITE	0
21581	09/21/2016	RG250T6N	BRADFORD WHITE	0
21582	09/19/2016	RG250T6N	BRADFORD WHITE	0
21583	09/14/2016	RG250T6N	BRADFORD WHITE	0
21584	09/12/2016	RG250T6N	BRADFORD WHITE	0
21585	10/20/2016	RG250H6N	Bradford White	0
21586	09/27/2016	RG240S6N	Bradford White	0
21587	09/28/2016	RG240S6N	Bradford White	0
21588	09/28/2016	RG250T6N	Bradford White	0
21589	09/29/2016	RG250T6N	Bradford White	0
21590	09/29/2016	RG250T6N	Bradford White	0
21591	09/18/2016	RG250T6N	BRADFORD WHITE	0
21592	09/18/2016	RG250T6N	BRADFORD WHITE	0
21593	09/16/2016	G91200	RUUD/RHEEM	0
21594	09/29/2016	G91200	RUUD/RHEEM	1
21595	09/29/2016	G75125	RUUD/RHEEM	1
21596	09/17/2016	G82156	RUUD/RHEEM	1
21597	10/03/2016	RG250T6N	BRADFORD WHITE	0
21598	10/04/2016	RG250T6N	BRADFORD WHITE	0
21599	10/06/2016	PROG5036NRU60	RUUD	0
21600	10/01/2016	PROG5036NRU60DV	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21601	10/02/2016	RG250T6N	BRADFORD WHITE	0
21602	10/01/2016	RG250T6N	BRADFORD WHITE	0
21603	09/27/2016	RG250T6N	BRADFORD WHITE	0
21604	09/30/2016	RG240T6N	BRADFORD WHITE	0
21605	10/05/2016	RG250T6N	BRADFORD WHITE	0
21606	10/04/2016	PROG5036NRU60DV	RUUD	0
21607	10/04/2016	RG250T6N	BRADFORD WHITE	0
21608	10/07/2016	RG250T6N	BRADFORD WHITE	0
21609	10/02/2016	RG250T6N	BRADFORD WHITE	0
21610	10/07/2016	RG250T6N	BRADFORD WHITE	1
21611	10/06/2016	RG250T6N	BRADFORD WHITE	0
21612	10/13/2016	PROG5036NRU60DV	RUUD	0
21613	10/18/2016	RG250T6N	BRADFORD WHITE	0
21614	10/18/2016	RG240S6N	BRADFORD WHITE	0
21615	10/18/2016	RG250T6N	BRADFORD WHITE	0
21616	10/18/2016	RG250T6N	BRADFORD WHITE	0
21617	10/08/2016	RG250T6N	BRADFORD WHITE	0
21618	10/07/2016	DS140S6FBN	BRADFORD WHITE	0
21619	10/07/2016	RG250T6N	BRADFORD WHITE	0
21620	10/10/2016	RG250T6N	BRADFORD WHITE	0
21621	10/10/2016	RG250T6N	BRADFORD WHITE	0
21622	10/10/2016	RG250T6N	BRADFORD WHITE	0
21623	10/11/2016	RG240S6N	BRADFORD WHITE	0
21624	09/30/2016	G76200	Rheem	0
21625	10/11/2016	RG250T6N	Bradford White	0
21626	10/11/2016	RG250T6N	Bradford White	0
21627	10/12/2016	RG240T6N	Bradford White	0
21628	10/06/2016	RG250T6N	Bradford White	0
21629	09/28/2016	RG250T6N	Bradford White	0
21630	10/01/2016	RG250T6N	Bradford White	0
21631	10/02/2016	RG250T6N	Bradford White	0
21632	09/16/2016	RG250T6N	BRADFORD WHITE	0
21633	09/26/2016	RG250L6N	BRADFORD WHITE	0
21634	09/26/2016	RG250T6N	BRADFORD WHITE	0
21635	09/27/2016	RG250T6N	BRADFORD WHITE	0
21636	10/05/2016	PROG5036NRU60DV	RUUD	0
21637	10/07/2016	RG240S6N	BRADFORD WHITE	0
21638	10/08/2016	RG250T6N	BRADFORD WHITE	0
21639	10/06/2016	RG250T6N	BRADFORD WHITE	0
21640	10/12/2016	PROG5036NRU60DV	RUUD	0
21641	10/12/2016	RG250T6N	BRADFORD WHITE	2
21642	10/02/2016	RG250T6N	BRADFORD WHITE	0
21643	10/13/2016	RG240S6N	BRADFORD WHITE	0
21644	10/14/2016	RG250T6N	BRADFORD WHITE	0
21645	10/15/2016	RG250T6N	BRADFORD WHITE	0
21646	10/17/2016	RG250T6N	BRADFORD WHITE	0
21647	10/14/2016	RG240T6N	BRADFORD WHITE	0
21648	10/09/2016	PROG5036NRU60DV	RUUD	0
21649	10/12/2016	G76200	RUUD/RHEEM	0
21650	10/17/2016	RG250H6N	BRADFORD WHITE	0
21651	10/20/2016	RG250T6N	BRADFORD WHITE	0
21652	10/19/2016	RG250T6N	BRADFORD WHITE	0
21653	09/23/2016	RG250T6N	BRADFORD WHITE	0
21654	10/21/2016	PROG5036NRH60DV	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21655	10/20/2016	RG250T6N	BRADFORD WHITE	0
21656	10/20/2016	RG250T6N	BRADFORD WHITE	0
21657	10/21/2016	RG250T6N	BRADFORD WHITE	0
21658	10/21/2016	RG250T6N	BRADFORD WHITE	0
21659	10/22/2016	RG250T6N	BRADFORD WHITE	0
21660	10/22/2016	RG250T6N	BRADFORD WHITE	0
21661	10/20/2016	RG250T6N	BRADFORD WHITE	0
21662	10/20/2016	RG250T6N	BRADFORD WHITE	0
21663	10/21/2016	RG250T6N	BRADFORD WHITE	0
21664	10/23/2016	RG250H6N	BRADFORD WHITE	0
21665	10/19/2016	G82156	RUUD	0
21666	10/18/2016	RG250H6N	BRADFORD WHITE	0
21667	10/19/2016	PROG5036NRU60DV	RHEEM	0
21668	10/18/2016	RG250T6N	BRADFORD WHITE	0
21669	10/11/2016	RG240S6N	BRADFORD WHITE	1
21670	10/06/2016	RG250T6N	BRADFORD WHITE	0
21671	10/17/2016	RG250T6N	BRADFORD WHITE	0
21672	10/17/2016	RG250T6N	BRADFORD WHITE	0
21673	10/19/2016	RG250T6N	BRADFORD WHITE	1
21674	10/25/2016	RG240S6N	BRADFORD WHITE	0
21675	10/26/2016	RG250T6N	BRADFORD WHITE	0
21676	10/25/2016	RG250T6N	BRADFORD WHITE	0
21677	10/25/2016	RG250T6N	BRADFORD WHITE	0
21678	10/24/2016	RG250T6N	BRADFORD WHITE	0
21679	10/27/2016	RG250T6N	BRADFORD WHITE	0
21680	10/27/2016	RG250T6N	BRADFORD WHITE	0
21681	10/28/2016	RG250T6N	BRADFORD WHITE	0
21682	10/27/2016	RG250T6N	BRADFORD WHITE	0
21683	10/27/2016	PROG5036NRU60DV	RUUD	0
21684	10/26/2016	RG250T6N	BRADFORD WHITE	0
21685	10/26/2016	RG240S6N	BRADFORD WHITE	0
21686	10/26/2016	RG250T6N	BRADFORD WHITE	0
21687	09/23/2016	RG250T6N	BRADFORD WHITE	0
21688	09/15/2016	RG250T6N	BRADFORD WHITE	0
21689	09/30/2016	PROG5036NRU60DV	RUUD	0
21690	10/31/2016	RG240S6N	BRADFORD WHITE	0
21691	10/29/2016	RG250T6N	BRADFORD WHITE	0
21692	10/28/2016	RG250T6N	BRADFORD WHITE	0
21693	10/28/2016	RG250T6N	BRADFORD WHITE	0
21694	10/17/2016	RG250T6N	BRADFORD WHITE	0
21695	10/13/2016	RG250H6N	BRADFORD WHITE	0
21696	10/06/2016	RG250T6N	BRADFORD WHITE	0
21697	10/06/2016	RG250T6N	BRADFORD WHITE	0
21698	10/20/2016	RG250T6N	BRADFORD WHITE	0
21699	10/22/2016	PROG5036NRU60DV	RUUD	0
21700	10/14/2016	RG250T6N	BRADFORD WHITE	0
21701	10/25/2016	RG250T6N	BRADFORD WHITE	0
21702	10/20/2016	RG250T6N	BRADFORD WHITE	0
21703	10/20/2016	RG250T6N	BRADFORD WHITE	0
21704	10/19/2016	RG250T6N	BRADFORD WHITE	0
21705	10/18/2016	RG250T6N	BRADFORD WHITE	0
21706	10/18/2016	G91200	RUUD/RHEEM	0
21707	10/26/2016	G91200	RUUD	0
21708	10/25/2016	RG250H6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21709	10/12/2016	PH199119	PHOENIX	1
21710	10/15/2016	RG250T6N	BRADFORD WHITE	0
21711	10/15/2016	PROG5036NRU60DV	RUUD	0
21712	10/24/2016	RG250T6N	BRADFORD WHITE	0
21713	10/28/2016	RG250T6N	BRADFORD WHITE	0
21714	11/06/2016	PROG5036NRU60	RUUD	0
21715	11/01/2016	PROG5036NRU60DV	RUUD	1
21716	11/01/2016	RG250T6N	BRADFORD WHITE	0
21717	10/29/2016	RG240S6N	BRADFORD WHITE	0
21718	10/21/2016	RG250T6N	BRADFORD WHITE	0
21719	11/08/2016	RG250H6N	BRADFORD WHITE	0
21720	11/08/2016	PROG5036NRU60DV	RUUD	0
21721	10/29/2016	RG250T6N	BRADFORD WHITE	1
21722	11/01/2016	RG240T6N	BRADFORD WHITE	0
21723	11/07/2016	RG250T6N	BRADFORD WHITE	0
21724	11/07/2016	RG240T6N	BRADFORD WHITE	1
21725	11/09/2016	RG250T6N	BRADFORD WHITE	0
21726	11/08/2016	PROG5036NRU60DV	RUUD	1
21727	11/09/2016	RG240T6N	BRADFORD WHITE	0
21728	10/31/2016	G75125	RUUD/RHEEM	0
21729	11/10/2016	RG240T6N	BRADFORD WHITE	0
21730	11/07/2016	RG250H6N	BRADFORD WHITE	0
21731	11/04/2016	RG250T6N	BRADFORD WHITE	0
21732	10/21/2016	RG250T6N	BRADFORD WHITE	0
21733	10/26/2016	PH13080	PHOENIX	0
21734	10/16/2016	PROG5036NRU60DV	RUUD	1
21735	11/02/2016	RG250T6N	BRADFORD WHITE	0
21736	11/02/2016	RG250T6N	BRADFORD WHITE	0
21737	11/02/2016	RG250T6N	BRADFORD WHITE	0
21738	11/02/2016	RG240T6N	BRADFORD WHITE	0
21739	11/07/2016	PROG5036NRU60DV	RUUD	0
21740	11/04/2016	RG250T6N	BRADFORD WHITE	0
21741	11/04/2016	RG250T6N	BRADFORD WHITE	0
21742	11/04/2016	RG250T6N	BRADFORD WHITE	0
21743	11/07/2016	RG250T6N	BRADFORD WHITE	0
21744	10/31/2016	RG240T6N	BRADFORD WHITE	0
21745	11/01/2016	RG250T6N	BRADFORD WHITE	0
21746	11/15/2016	PROG5036NRU60DV	RUUD	0
21747	11/15/2016	RG250T6N	BRADFORD WHITE	0
21748	11/14/2016	RG250T6N	BRADFORD WHITE	0
21749	10/04/2016	RG250T6N	BRADFORD WHITE	0
21750	10/31/2016	RG240T6N	BRADFORD WHITE	0
21751	11/01/2016	PROG5036NRU60DV	RUUD	0
21752	10/29/2016	RG250T6N	BRADFORD WHITE	0
21753	11/11/2016	RG250T6N	BRADFORD WHITE	0
21754	11/18/2016	RG250T6N	BRADFORD WHITE	0
21755	11/22/2016	RG250T6N	BRADFORD WHITE	0
21756	11/16/2016	RG250T6N	BRADFORD WHITE	0
21757	11/17/2016	RG250T6N	BRADFORD WHITE	0
21758	11/17/2016	RG250T6N	BRADFORD WHITE	0
21759	11/23/2016	RG240T6N	BRADFORD WHITE	0
21760	11/17/2016	RG250T6N	BRADFORD WHITE	0
21761	11/17/2016	RG250T6N	BRADFORD WHITE	0
21762	11/17/2016	RG250H6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21763	11/05/2016	RG240T6N	BRADFORD WHITE	0
21764	11/07/2016	RG250T6N	BRADFORD WHITE	0
21765	11/11/2016	PROG5036NRU60DV	RUUD	0
21766	11/15/2016	RG240T6N	BRADFORD WHITE	2
21767	10/30/2016	G76200	RUUD/RHEEM	4
21768	10/30/2016	G76200	RUUD/RHEEM	0
21769	11/14/2016	G91200	RUUD/RHEEM	0
21770	11/15/2016	RG240T6N	BRADFORD WHITE	0
21771	11/16/2016	RG240T6N	BRADFORD WHITE	0
21772	11/16/2016	RG250T6N	BRADFORD WHITE	0
21773	11/15/2016	RG250T6N	BRADFORD WHITE	0
21774	09/28/2016	RG250T6N	BRADFORD WHITE	0
21775	10/27/2016	RG250T6N	BRADFORD WHITE	0
21776	10/31/2016	RG2DV50S6N	BRADFORD WHITE	0
21777	11/01/2016	RG240T6N	BRADFORD WHITE	0
21778	11/02/2016	PROG5036NRU60DV	RUUD	0
21779	11/05/2016	RG250T6N	BRADFORD WHITE	0
21780	11/19/2016	RG240T6N	BRADFORD WHITE	0
21781	11/29/2016	RG240S6N	BRADFORD WHITE	0
21782	11/29/2016	RG250T6N	BRADFORD WHITE	0
21783	11/30/2016	RG250T6N	BRADFORD WHITE	0
21784	11/30/2016	RG250T6N	BRADFORD WHITE	0
21785	11/30/2016	RG250L6N	BRADFORD WHITE	0
21786	11/29/2016	RG250T6N	BRADFORD WHITE	0
21787	11/29/2016	RG250T6N	BRADFORD WHITE	0
21788	11/28/2016	PROG5036NRU60DV	RUUD	0
21789	11/07/2016	RG250T6N	BRADFORD WHITE	0
21790	11/29/2016	RG250T6N	BRADFORD WHITE	0
21791	11/10/2016	RG250T6N	BRADFORD WHITE	0
21792	11/19/2016	PROG5036NRU60DV	RUUD	0
21793	11/20/2016	RG250T6N	BRADFORD WHITE	0
21794	11/21/2016	RG250T6N	BRADFORD WHITE	0
21795	11/23/2016	PROG5036NRU60DV	RUUD	0
21796	11/23/2016	PROG5036NRU60DV	RUUD	0
21797	11/23/2016	RG250T6N	BRADFORD WHITE	0
21798	11/23/2016	RG250T6N	BRADFORD WHITE	0
21799	11/28/2016	RG240T6N	BRADFORD WHITE	0
21800	11/28/2016	RG250T6N	BRADFORD WHITE	0
21801	11/28/2016	RG250T6N	BRADFORD WHITE	0
21802	11/29/2016	RG240S6N	BRADFORD WHITE	0
21803	11/25/2016	PROG5036NRU60DV	RUUD	0
21804	11/21/2016	RG240S6N	BRADFORD WHITE	0
21805	11/22/2016	RG240S6N	BRADFORD WHITE	0
21806	11/18/2016	RG250T6N	BRADFORD WHITE	0
21807	11/16/2016	RG240S6N	BRADFORD WHITE	0
21808	11/16/2016	RG240S6N	BRADFORD WHITE	0
21809	11/14/2016	RG240T6N	BRADFORD WHITE	0
21810	11/10/2016	RG250T6N	BRADFORD WHITE	0
21811	11/05/2016	RG250T6N	BRADFORD WHITE	0
21812	11/01/2016	RG250H6N	BRADFORD WHITE	0
21813	11/22/2016	PROG5036NRU60DV	RUUD	0
21814	11/17/2016	PH199119	PHOENIX	2
21815	11/25/2016	G75125	RUUD/RHEEM	0
21816	11/19/2016	G75125	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21817	11/18/2016	G91200	RUUD/RHEEM	1
21818	11/25/2016	RG275H6N	BRADFORD WHITE	1
21819	12/01/2016	PROG5036NRU60	RUUD	0
21820	12/01/2016	RG250T6N	BRADFORD WHITE	0
21821	12/01/2016	RG250T6N	BRADFORD WHITE	0
21822	12/02/2016	RG240S6N	BRADFORD WHITE	0
21823	12/02/2016	PROG5036NRU60DV	RUUD	0
21824	12/01/2016	RG250T6N	BRADFORD WHITE	0
21825	12/01/2016	RG250T6N	BRADFORD WHITE	0
21826	12/01/2016	RG250T6N	BRADFORD WHITE	0
21827	12/02/2016	RG240T6N	BRADFORD WHITE	0
21828	12/01/2016	RG250T6N	BRADFORD WHITE	0
21829	12/03/2016	G75125	RUUD/RHEEM	0
21830	12/03/2016	G75125	RUUD/RHEEM	0
21831	12/09/2016	RG250T6N	BRADFORD WHITE	0
21832	12/09/2016	RG240S6N	BRADFORD WHITE	0
21833	12/09/2016	RG250T6N	BRADFORD WHITE	0
21834	12/09/2016	RG240T6N	BRADFORD WHITE	0
21835	12/08/2016	RG250L6N	BRADFORD WHITE	1
21836	12/07/2016	RG250T6N	BRADFORD WHITE	0
21837	12/06/2016	RG250T6N	BRADFORD WHITE	0
21838	12/05/2016	RG250T6N	BRADFORD WHITE	0
21839	11/23/2016	RG240T6N	BRADFORD WHITE	1
21840	12/03/2016	RG250T6N	BRADFORD WHITE	0
21841	12/01/2016	RG250T6N	BRADFORD WHITE	0
21842	12/01/2016	RG240T6N	BRADFORD WHITE	0
21843	11/30/2016	RG240T6N	BRADFORD WHITE	0
21844	11/27/2016	RG250T6N	BRADFORD WHITE	1
21845	12/12/2016	RG250T6N	BRADFORD WHITE	1
21846	12/12/2016	RG250T6N	BRADFORD WHITE	0
21847	12/12/2016	RG250T6N	BRADFORD WHITE	0
21848	12/05/2016	RG250T6N	BRADFORD WHITE	0
21849	12/05/2016	RG250T6N	BRADFORD WHITE	0
21850	12/06/2016	RG250T6N	BRADFORD WHITE	0
21851	12/06/2016	RG250T6N	BRADFORD WHITE	0
21852	11/23/2016	RG250T6N	BRADFORD WHITE	0
21853	12/21/2016	RG250T6N	BRADFORD WHITE	0
21854	12/21/2016	PROG2932NRU63	RUUD	0
21855	12/12/2016	RG250H6N	BRADFORD WHITE	1
21856	12/06/2016	RG250T6N	BRADFORD WHITE	0
21857	12/08/2016	RG250T6N	BRADFORD WHITE	0
21858	12/08/2016	RG240T6N	BRADFORD WHITE	4
21859	12/08/2016	PROG5036NRU60DV	RUUD	0
21860	12/09/2016	RG240T6N	BRADFORD WHITE	1
21861	12/09/2016	RG250T6N	BRADFORD WHITE	0
21862	12/30/2016	RG250T6N	BRADFORD WHITE	0
21863	12/30/2016	RG240T6N	BRADFORD WHITE	0
21864	12/31/2016	RG240T6N	BRADFORD WHITE	0
21865	12/28/2016	RG250T6N	BRADFORD WHITE	0
21866	12/28/2016	RG240T6N	BRADFORD WHITE	0
21867	12/28/2016	RG240T6N	BRADFORD WHITE	0
21868	12/28/2016	RG240T6N	BRADFORD WHITE	0
21869	12/23/2016	RG250T6N	BRADFORD WHITE	0
21870	12/23/2016	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21871	12/22/2016	RG250T6N	BRADFORD WHITE	0
21872	12/22/2016	RG250T6N	BRADFORD WHITE	0
21873	12/22/2016	PROG5036NRU60DV	RUUD	0
21874	12/21/2016	PROG5036NRU60DV	RUUD	0
21875	12/21/2016	RG250T6N	BRADFORD WHITE	0
21876	12/02/2016	PROG5036NRU60DV	RUUD	0
21877	12/31/2016	RG250T6N	BRADFORD WHITE	0
21878	12/20/2016	RG250T6N	BRADFORD WHITE	0
21879	12/13/2016	RG240T6N	BRADFORD WHITE	0
21880	12/19/2016	RG250T6N	BRADFORD WHITE	0
21881	12/21/2016	RG250H6N	BRADFORD WHITE	0
21882	12/23/2016	RG240T6N	BRADFORD WHITE	0
21883	12/22/2016	MI50L6FBN	BRADFORD WHITE	0
21884	12/22/2016	RG240S6N	BRADFORD WHITE	0
21885	12/20/2016	RG250T6N	BRADFORD WHITE	0
21886	12/05/2016	RG250T6N	BRADFORD WHITE	0
21887	12/09/2016	RG250T6N	BRADFORD WHITE	0
21888	12/13/2016	RG240T6N	BRADFORD WHITE	0
21889	12/13/2016	PROG5036NRU60DV	RUUD	0
21890	12/30/2016	PROG2932NRU63	RUUD	0
21891	12/01/2016	G91200	RUUD/RHEEM	0
21892	12/14/2016	G91200	RUUD/RHEEM	0
21893	12/08/2016	G82156	RUUD/RHEEM	0
21894	12/23/2016	RG250T6N	BRADFORD WHITE	0
21895	12/24/2016	RG250T6N	BRADFORD WHITE	0
21896	12/29/2016	RG250T6N	BRADFORD WHITE	0
21897	12/29/2016	RG240T6N	BRADFORD WHITE	0
21898	12/27/2016	RG250T6N	BRADFORD WHITE	0
21899	12/27/2016	RG250T6N	BRADFORD WHITE	0
21900	12/27/2016	RG240T6N	BRADFORD WHITE	0
21901	12/27/2016	RG250T6N	BRADFORD WHITE	0
21902	12/27/2016	PROG5036NRU60DV	RUUD	0
21903	12/27/2016	PROG5036NRU60DV	RUUD	0
21904	12/29/2016	RG250T6N	BRADFORD WHITE	0
21905	12/31/2016	RG250T6N	BRADFORD WHITE	0
21906	12/28/2016	PROG2932NRU62	RUUD	0
21907	12/30/2016	RG240T6N	BRADFORD WHITE	0
21908	12/24/2016	PROG5036NRU60DV	RUUD	0
21909	12/29/2016	RG250T6N	BRADFORD WHITE	0
21910	12/29/2016	RG250T6N	BRADFORD WHITE	1
21911	12/29/2016	RG240S6N	BRADFORD WHITE	1
21912	12/23/2016	PROG5036NRU60DV	RUUD	0
21913	12/30/2016	RG250T6N	BRADFORD WHITE	1
21914	12/29/2016	RG250T6N	BRADFORD WHITE	0
21915	12/21/2016	PROG2932NRU62	RUUD	0
21916	12/24/2016	PROG5036NRU60DV	RUUD	0
21917	12/29/2016	RG250T6N	BRADFORD WHITE	0
21918	12/23/2016	RG240S6N	BRADFORD WHITE	0
21919	12/31/2016	RG250T6N	BRADFORD WHITE	0
21920	12/27/2016	RG250T6N	BRADFORD WHITE	0
21921	12/28/2016	G91200	RUUD/RHEEM	0
21922	12/13/2016	G91200	RUUD/RHEEM	0
21923	01/19/2017	MI50L6FBN	BRADFORD WHITE	0
21924	01/04/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21925	12/29/2016	RG240S6N	BRADFORD WHITE	0
21926	01/05/2017	RG250T6N	BRADFORD WHITE	0
21927	01/04/2017	PROG2932NRU62	RUUD	0
21928	01/04/2017	RG250T6N	BRADFORD WHITE	0
21929	01/04/2017	RG250T6N	BRADFORD WHITE	0
21930	01/04/2017	RG250T6N	BRADFORD WHITE	0
21931	01/04/2017	PROG5036NRU60DV	RUUD	1
21932	01/05/2017	RG250T6N	BRADFORD WHITE	0
21933	01/04/2017	RG250T6N	BRADFORD WHITE	0
21934	01/08/2017	RG240T6N	BRADFORD WHITE	0
21935	01/07/2017	RG250T6N	BRADFORD WHITE	0
21936	01/06/2017	RG250T6N	BRADFORD WHITE	2
21937	01/06/2017	PROG5036NRU60DV	RUUD	0
21938	01/06/2017	RG240T6N	BRADFORD WHITE	0
21939	02/13/2017	RG250T6N	Bradford White	0
21940	12/01/2016	RG240T6N	BRADFORD WHITE	0
21941	02/20/2017	RG240T6N	BRADFORD WHITE	0
21942	11/29/2016	RG240S6N	BRADFORD WHITE	0
21943	12/11/2016	RG250T6N	BRADFORD WHITE	0
21944	12/11/2016	RG250T6N	BRADFORD WHITE	0
21945	12/10/2016	RG240T6N	BRADFORD WHITE	0
21946	12/10/2016	RG240S6N	BRADFORD WHITE	0
21947	12/10/2016	RG240S6N	BRADFORD WHITE	0
21948	12/09/2016	RG250T6N	BRADFORD WHITE	0
21949	12/10/2016	RG250T6N	BRADFORD WHITE	0
21950	12/19/2016	RG250T6N	BRADFORD WHITE	0
21951	12/19/2016	PROG5036NRU60DV	RUUD	0
21952	01/05/2017	G91200	RUUD/RHEEM	0
21953	12/14/2016	RG250T6N	BRADFORD WHITE	0
21954	12/10/2016	G91200	RUUD/RHEEM	0
21955	11/21/2016	RG275H6N	BRADFORD WHITE	1
21956	12/19/2016	G82156	RUUD/RHEEM	0
21957	12/14/2016	G76200	RUUD/RHEEM	0
21958	12/14/2016	G91200	RUUD/RHEEM	1
21959	12/11/2016	G82156	RUUD/RHEEM	0
21960	12/19/2016	RG240S6N	BRADFORD WHITE	0
21961	12/19/2016	PROG5036NRU60DV	RUUD	0
21962	12/19/2016	RG240T6N	BRADFORD WHITE	0
21963	12/19/2016	RG240S6N	BRADFORD WHITE	0
21964	12/20/2016	RG240T6N	BRADFORD WHITE	0
21965	12/20/2016	RG250T6N	BRADFORD WHITE	0
21966	12/15/2016	RG250T6N	BRADFORD WHITE	0
21967	12/15/2016	PROG5036NRU60DV	RUUD	0
21968	12/16/2016	RG250T6N	BRADFORD WHITE	0
21969	12/16/2016	RG250T6N	BRADFORD WHITE	0
21970	12/16/2016	RG250T6N	BRADFORD WHITE	0
21971	12/20/2016	G76200	RUUD/RHEEM	0
21972	12/19/2016	RG250T6N	BRADFORD WHITE	0
21973	01/03/2017	PROG5036NRU60DV	RUUD	0
21974	01/01/2017	RG250T6N	BRADFORD WHITE	0
21975	01/03/2017	RG250T6N	BRADFORD WHITE	0
21976	01/03/2017	RG250T6N	BRADFORD WHITE	0
21977	01/03/2017	RG250T6N	BRADFORD WHITE	0
21978	01/03/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
21979	01/03/2017	RG250T6N	BRADFORD WHITE	0
21980	01/04/2017	RG250T6N	BRADFORD WHITE	0
21981	01/13/2017	RG275H6N	BRADFORD WHITE	1
21982	03/04/2017	PROG5036NRU60DV	RHEEM	0
21983	01/17/2017	RG250T6N	BRADFORD WHITE	0
21984	01/17/2017	PROG5036NRU60DV	RUUD	0
21985	01/09/2017	RG250T6N	BRADFORD WHITE	0
21986	01/12/2017	PROG5036NRU60DV	RUUD	0
21987	01/03/2017	RG250T6N	BRADFORD WHITE	0
21988	01/11/2017	RG250T6N	BRADFORD WHITE	0
21989	01/11/2017	PROG5036NRU60DV	RUUD	1
21990	01/18/2017	G75125	RUUD/RHEEM	0
21991	01/13/2017	RG250T6N	BRADFORD WHITE	0
21992	01/13/2017	PROG5036NRU60DV	RUUD	0
21993	01/11/2017	RG250T6N	BRADFORD WHITE	0
21994	01/13/2017	RG250T6N	BRADFORD WHITE	0
21995	01/13/2017	RG250T6N	BRADFORD WHITE	0
21996	01/14/2017	RG250T6N	BRADFORD WHITE	0
21997	01/14/2017	MI50L6FBN	BRADFORD WHITE	0
21998	01/06/2017	RG250T6N	BRADFORD WHITE	0
21999	01/13/2017	RG250T6N	BRADFORD-WHITE	0
22000	01/11/2017	RG250T6N	BRADFORD WHITE	0
22001	01/16/2017	RG250L6N	BRADFORD WHITE	0
22002	01/17/2017	RG250T6N	BRADFORD WHITE	0
22003	01/11/2017	RG250T6N	BRADFORD WHITE	0
22004	01/09/2017	RG250L6N	BRADFORD WHITE	0
22005	01/10/2017	G75125	RUUD	0
22006	03/08/2017	RG250T6N	BRADFORD WHITE	0
22007	02/13/2017	PROG5036NRU60DV	RUUD	1
22008	03/04/2013	MI5036FBN	BRADFORD WHITE	4
22009	12/29/2016	RG250T6N	BRADFORD WHITE	0
22010	12/30/2016	RG250T6N	BRADFORD WHITE	1
22011	12/29/2016	RG250T6N	BRADFORD WHITE	1
22012	01/31/2017	G75125	RUUD/RHEEM	0
22013	01/31/2017	RG250T6N	BRADFORD WHITE	1
22014	01/31/2017	RG250T6N	BRADFORD WHITE	0
22015	01/31/2017	RG250T6N	BRADFORD WHITE	0
22016	01/31/2017	RG240T6N	BRADFORD WHITE	0
22017	01/30/2017	RG250T6N	BRADFORD WHITE	0
22018	01/30/2017	RG250T6N	BRADFORD WHITE	1
22019	01/30/2017	RG240T6N	BRADFORD WHITE	0
22020	01/30/2017	RG250T6N	BRADFORD WHITE	0
22021	01/28/2017	PROG5036NRU60DV	RUUD	0
22022	01/28/2017	RG250T6N	BRADFORD WHITE	0
22023	01/27/2017	RG240T6N	BRADFORD WHITE	0
22024	01/27/2017	RG250T6N	BRADFORD WHITE	0
22025	01/27/2017	RG250T6N	BRADFORD WHITE	0
22026	01/27/2017	RG250T6N	BRADFORD WHITE	0
22027	01/26/2017	RG250T6N	BRADFORD WHITE	0
22028	01/26/2017	RG240T6N	BRADFORD WHITE	0
22029	01/26/2017	PROG5036NRH60DV	RHEEM	0
22030	01/26/2017	RG250T6N	BRADFORD WHITE	0
22031	01/26/2017	RG250T6N	BRADFORD WHITE	1
22032	01/25/2017	RG250H6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22033	01/26/2017	RG250T6N	BRADFORD WHITE	0
22034	01/25/2017	RG250T6N	BRADFORD WHITE	1
22035	01/24/2017	RG250T6N	BRADFORD WHITE	0
22036	01/24/2017	PROG5036NRU60	RUUD	0
22037	01/24/2017	RG240S6N	BRADFORD WHITE	0
22038	01/24/2017	RG250T6N	BRADFORD WHITE	1
22039	01/23/2017	RG250T6N	BRADFORD WHITE	1
22040	01/23/2017	PGR40	AO SMITH	0
22041	02/02/2017	RG240S6N	BRADFORD WHITE	0
22042	02/02/2017	PROG5036NRU60	RUUD	0
22043	02/02/2017	RG250T6N	BRADFORD WHITE	0
22044	02/01/2017	RG250T6N	BRADFORD WHITE	0
22045	02/01/2017	RG250T6N	BRADFORD WHITE	0
22046	02/01/2017	RG250T6N	BRADFORD WHITE	0
22047	02/08/2017	RG250T6N	BRADFORD WHITE	0
22048	02/10/2017	RG250T6N	BRADFORD WHITE	0
22049	02/09/2017	RG250T6N	BRADFORD WHITE	0
22050	01/17/2017	RG250T6N	Bradford White	0
22051	12/04/2016	RG250T6N	Bradford White	0
22052	01/06/2017	PROG5036NRU60	RUUD	0
22053	01/06/2017	RG250T6N	Bradford White	1
22054	01/05/2017	RG240S6N	Bradford White	0
22055	01/03/2017	RG250T6N	Bradford White	0
22056	01/04/2017	RG240S6N	Bradford White	0
22057	01/05/2017	PGX50	AO SMITH	0
22058	01/18/2017	RG250T6N	Bradford White	0
22059	01/18/2017	RG250T6N	Bradford White	0
22060	01/10/2017	RG250T6N	Bradford White	0
22061	01/10/2017	RG250T6N	Bradford White	0
22062	01/21/2017	PROG5036NRU60	Ruud	0
22063	01/22/2017	RG240T6N	Bradford White	0
22064	01/20/2017	PROG5036NRU60	Ruud	0
22065	01/20/2017	RG250T6N	Bradford White	0
22066	01/20/2017	RG250T6N	Bradford White	0
22067	01/20/2017	RG250T6N	Bradford White	0
22068	01/20/2017	RG250T6N	Bradford White	0
22069	01/19/2017	RG250T6N	Bradford White	0
22070	01/19/2017	RG250T6N	Bradford White	0
22071	01/13/2017	RG250T6N	Bradford White	0
22072	01/13/2017	RG250T6N	Bradford White	0
22073	01/13/2017	RG250T6N	Bradford White	0
22074	01/13/2017	PGR50	AO SMITH	0
22075	01/18/2017	G91200	RUUD/RHEEM	0
22076	02/09/2017	RG2DV50S6N	BRADFORD WHITE	0
22077	02/03/2017	RG250T6N	BRADFORD WHITE	0
22078	02/09/2017	RG250T6N	BRADFORD WHITE	0
22079	02/09/2017	RG250T6N	BRADFORD WHITE	0
22080	02/01/2017	RG250T6N	BRADFORD WHITE	0
22081	01/30/2017	PROG5036NRU60	RUUD	0
22082	01/21/2017	RG250T6N	BRADFORD WHITE	0
22083	01/21/2017	RG230T6N	BRADFORD WHITE	0
22084	01/19/2017	PROG2932NRU62	RUUD	0
22085	01/27/2017	RG250T6N	BRADFORD WHITE	0
22086	01/26/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22087	01/28/2017	PROG5036NRU60	RUUD	0
22088	01/22/2017	RG250T6N	BRADFORD WHITE	0
22089	01/20/2017	RG250T6N	BRADFORD WHITE	0
22090	02/07/2017	RG240T6N	BRADFORD WHITE	0
22091	02/08/2017	RG250T6N	BRADFORD WHITE	0
22092	02/14/2017	RG240T6N	BRADFORD WHITE	0
22093	02/15/2017	PROG4040NRU62	RUUD	0
22094	02/15/2017	RG250H6N	BRADFORD WHITE	0
22095	02/15/2017	RG250T6N	BRADFORD WHITE	0
22096	02/14/2017	RG240T6N	BRADFORD WHITE	0
22097	02/16/2017	RG250T6N	BRADFORD WHITE	0
22098	02/14/2017	RG240T6N	BRADFORD WHITE	0
22099	02/10/2017	RG250T6N	BRADFORD WHITE	1
22100	02/10/2017	PROG5036NRU60	RUUD	0
22101	02/11/2017	RG250T6N	BRADFORD WHITE	0
22102	02/13/2017	RG250T6N	BRADFORD WHITE	0
22103	02/09/2017	RG250T6N	BRADFORD WHITE	0
22104	02/21/2017	RG240T6N	BRADFORD WHITE	0
22105	02/21/2017	RG250T6N	BRADFORD WHITE	0
22106	02/21/2017	PROG5036NRU60	RUUD	0
22107	02/22/2017	RG250T6N	BRADFORD WHITE	0
22108	02/21/2017	RG240T6N	BRADFORD WHITE	0
22109	02/15/2017	RG250T6N	BRADFORD WHITE	1
22110	02/12/2017	RG250T6N	BRADFORD WHITE	0
22111	01/19/2017	RG250T6N	Bradford White	2
22112	01/19/2017	RG2DV50S6N	Bradford White	0
22113	01/18/2017	RG250T6N	Bradford White	0
22114	01/10/2017	RG250T6N	Bradford White	0
22115	01/14/2017	RG250T6N	Bradford White	0
22116	01/17/2017	PROG5036NRU60	Ruud	0
22117	01/18/2017	RG250T6N	Bradford White	0
22118	01/05/2017	RG250T6N	Bradford White	1
22119	01/03/2017	RG250T6N	Bradford White	0
22120	07/25/2011	M45036FBN	BRADFORD WHITE	0
22121	02/23/2017	RG250T6N	BRADFORD WHITE	0
22122	02/13/2017	RG250T6N	BRADFORD WHITE	0
22123	03/06/2017	RG250T6N	Bradford White	0
22124	02/06/2017	FSG40	AO SMITH	0
22125	02/07/2017	RG240T6N	Bradford White	0
22126	02/11/2017	RG250T6N	Bradford White	0
22127	02/01/2017	RG250T6N	Bradford White	0
22128	02/02/2017	PROG5036NRU60	Ruud	0
22129	02/03/2017	PROG5036NRU60	Ruud	0
22130	02/13/2017	RG250T6N	Bradford White	0
22131	02/13/2017	RG250T6N	Bradford White	0
22132	02/13/2017	RG240T6N	Bradford White	0
22133	02/09/2017	RG240T6N	Bradford White	0
22134	02/02/2017	PROG5036NRU60	Ruud	0
22135	02/06/2017	RG250T6N	Bradford White	0
22136	02/07/2017	RG250T6N	Bradford White	0
22137	02/07/2017	RG250T6N	Bradford White	0
22138	02/07/2017	PROG5036NRU60	Ruud	0
22139	02/07/2017	RG250T6N	Bradford White	0
22140	01/26/2017	RG250T6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22141	01/31/2017	RG250T6N	Bradford White	0
22142	01/11/2017	RG250T6N	Bradford White	0
22143	01/15/2017	RG250T6N	Bradford White	0
22144	01/26/2017	PROG5036NRU60	Ruud	0
22145	01/28/2017	MI5036FBN	BRADFORD-WHITE	0
22146	01/31/2017	RG250T6N	Bradford White	0
22147	01/23/2017	RG240T6N	Bradford White	0
22148	01/26/2017	PROG5036NRU60	Ruud	0
22149	01/07/2017	G91200	RUUD/RHEEM	0
22150	01/23/2017	RG250T6N	Bradford White	0
22151	02/13/2017	RG250T6N	Bradford White	0
22152	02/14/2017	RG250T6N	Bradford White	0
22153	02/06/2017	PROG5036NRU60DV	Ruud	0
22154	02/06/2017	RG240T6N	Bradford White	0
22155	02/15/2017	RG250T6N	Bradford White	0
22156	02/15/2017	RG240S6N	Bradford White	0
22157	02/09/2017	RG240T6N	Bradford White	0
22158	02/21/2017	RG250T6N	Bradford White	0
22159	02/14/2017	RG250T6N	Bradford White	0
22160	02/11/2017	RG250T6N	Bradford White	0
22161	02/20/2017	RG250T6N	Bradford White	0
22162	02/18/2017	RG250T6N	Bradford White	0
22163	02/06/2017	RG250H6N	Bradford White	0
22164	02/09/2017	G75125	RUUD/RHEEM	0
22165	07/28/2003	FCV50	AO SMITH	0
22166	01/08/2017	RG250H6N	BRADFORD WHITE	0
22167	01/04/2017	G91200	RUUD/RHEEM	0
22168	01/04/2017	G91200	RUUD/RHEEM	0
22169	03/17/2017	RG250T6N	Bradford White	0
22170	02/25/2017	RG250T6N	BRADFORD WHITE	0
22171	02/23/2017	RG250T6N	BRADFORD WHITE	0
22172	02/23/2017	RG250T6N	BRADFORD WHITE	0
22173	02/21/2017	RG250T6N	BRADFORD WHITE	0
22174	02/22/2017	PROG5036NRU60DV	RUUD	0
22175	02/23/2017	RG250T6N	BRADFORD WHITE	0
22176	02/24/2017	RG250T6N	BRADFORD WHITE	0
22177	02/28/2017	RG250T6N	BRADFORD WHITE	0
22178	01/24/2017	RG250T6N	BRADFORD WHITE	0
22179	02/27/2017	RG250T6N	BRADFORD WHITE	0
22180	02/21/2017	RG2DV50S6N	BRADFORD WHITE	0
22181	02/28/2017	RG250H6N	BRADFORD WHITE	0
22182	02/16/2017	PROG5036NRU60DV	RUUD	0
22183	02/16/2017	RG250T6N	BRADFORD WHITE	0
22184	02/10/2017	RG275H6N	BRADFORD WHITE	0
22185	02/15/2017	RG240T6N	BRADFORD WHITE	0
22186	02/15/2017	RG240S6N	BRADFORD WHITE	0
22187	02/13/2017	RG250T6N	BRADFORD WHITE	0
22188		RG240T6N	BRADFORD WHITE	0
22189	02/27/2017	RG250T6N	BRADFORD WHITE	0
22190	02/27/2017	RG250T6N	BRADFORD WHITE	0
22191	02/28/2017	G76200	RUUD	0
22192	03/02/2017	PROG2932NRU63	RUUD	0
22193	03/01/2017	PROG2932NRU63	RUUD	0
22194	03/02/2017	PROG5036NRU60	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22195	03/01/2017	RG250T6N	BRADFORD WHITE	0
22196	03/03/2017	RG250T6N	BRADFORD WHITE	0
22197	03/01/2017	PROG5036NRU60	RUUD	0
22198	03/03/2017	MI50L6FBN	BRADFORD WHITE	0
22199	03/07/2017	RG240T6N	BRADFORD WHITE	0
22200	03/07/2017	RG250T6N	BRADFORD WHITE	0
22201	03/07/2017	RG2DV50S6N	BRADFORD WHITE	0
22202	03/03/2017	RG250T6N	BRADFORD WHITE	0
22203	03/08/2017	RG250T6N	BRADFORD WHITE	0
22204	03/08/2017	PROG5036NRU60	RUUD	0
22205	03/08/2017	RG240S6N	BRADFORD WHITE	0
22206	03/06/2017	RG250T6N	BRADFORD WHITE	0
22207	03/09/2017	RG240T6N	BRADFORD WHITE	0
22208	03/10/2017	RG250H6N	BRADFORD WHITE	0
22209	03/10/2017	RG250T6N	BRADFORD WHITE	0
22210	03/07/2017	G75125	RUUD	0
22211	03/09/2017	G75125	RUUD	0
22212	03/10/2017	RG240T6N	BRADFORD WHITE	0
22213	03/09/2017	RG250T6N	BRADFORD WHITE	0
22214	03/13/2017	MI50L6FBN	BRADFORD WHITE	0
22215	03/07/2017	RG250T6N	BRADFORD WHITE	0
22216	03/14/2017	RG240T6N	BRADFORD WHITE	0
22217	03/15/2017	RG250T6N	BRADFORD WHITE	0
22218	03/16/2017	RG250T6N	BRADFORD WHITE	0
22219	03/16/2017	RG250T6N	BRADFORD WHITE	0
22220	03/17/2017	PROG5036NRU60DV	RUUD	0
22221	03/17/2017	RG240T6N	BRADFORD WHITE	0
22222	03/17/2017	RG250T6N	BRADFORD WHITE	0
22223	03/15/2017	RG250T6N	BRADFORD WHITE	0
22224	03/10/2017	G75125	RUUD	0
22225	03/13/2017	G76200	RUUD	0
22226	03/21/2017	RG250T6N	BRADFORD WHITE	0
22227	03/21/2017	RG250T6N	BRADFORD WHITE	0
22228	03/06/2017	RG250T6N	BRADFORD WHITE	0
22229	01/18/2017	RG250T6N	BRADFORD WHITE	1
22230	02/13/2017	RG250T6N	BRADFORD WHITE	0
22231	02/27/2017	RG250T6N	BRADFORD WHITE	0
22232	03/01/2017	RG240T6N	BRADFORD WHITE	0
22233	03/02/2017	RG250T6N	BRADFORD WHITE	0
22234	03/06/2017	RG250T6N	BRADFORD WHITE	0
22235	03/03/2017	RG250T6N	BRADFORD WHITE	0
22236	03/03/2017	RG250T6N	BRADFORD WHITE	0
22237	03/06/2017	RG250T6N	BRADFORD WHITE	0
22238	03/06/2017	RG250T6N	BRADFORD WHITE	0
22239	03/09/2017	PROG5036NRU60DV	RUUD	0
22240	03/12/2017	RG250T6N	BRADFORD WHITE	1
22241	03/13/2017	RG250T6N	BRADFORD WHITE	0
22242	03/13/2017	RG250T6N	BRADFORD WHITE	0
22243	03/13/2017	RG250H6N	BRADFORD WHITE	0
22244	03/16/2017	RG240T6N	BRADFORD WHITE	0
22245	03/17/2017	RG250T6N	BRADFORD WHITE	0
22246	03/17/2017	RG250T6N	BRADFORD WHITE	1
22247	03/21/2017	RG250T6N	BRADFORD WHITE	0
22248	02/03/2017	RG250L6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22249	03/02/2017	PROG2932NRU63	RUUD	1
22250	03/01/2017	RG250T6N	BRADFORD WHITE	0
22251	03/25/2017	RG250T6N	BRADFORD WHITE	0
22252	03/22/2017	RG240T6N	BRADFORD WHITE	0
22253	03/23/2017	RG250T6N	BRADFORD WHITE	0
22254	03/23/2017	RG250T6N	BRADFORD WHITE	0
22255	03/13/2017	PROG5038NRU60	RUUD	0
22256	03/22/2017	PROG5036NRU60DV	RUUD	0
22257	03/22/2017	RG240S6N	BRADFORD WHITE	0
22258	03/22/2017	RG250T6N	BRADFORD WHITE	0
22259	03/22/2017	PROG5036NRU60DV	RUUD	0
22260	03/24/2017	RG250T6N	BRADFORD WHITE	0
22261	03/25/2017	RG250T6N	BRADFORD WHITE	0
22262	03/24/2017	PROG5036NRU60	RUUD	0
22263	02/16/2017	RG250T6N	BRADFORD WHITE	1
22264	03/28/2017	PROG5036NRU60	RUUD	0
22265	03/27/2017	PROG5036NRU60	RUUD	0
22266	03/27/2017	RG250T6N	BRADFORD WHITE	0
22267	03/27/2017	RG240T6N	BRADFORD WHITE	0
22268	03/27/2017	RG250T6N	BRADFORD WHITE	0
22269	03/24/2017	RG250T6N	BRADFORD WHITE	0
22270	03/28/2017	RG250T6N	BRADFORD WHITE	0
22271	03/21/2017	PROG40S34NRU62	RUUD	0
22272	03/31/2017	RG250T6N	BRADFORD WHITE	0
22273	03/31/2017	RG250T6N	BRADFORD WHITE	0
22274	03/15/2017	RG250T6N	BRADFORD WHITE	0
22275	03/17/2017	RG250T6N	BRADFORD WHITE	1
22276	02/27/2017	RG250T6N	BRADFORD WHITE	0
22277	03/18/2017	RG250T6N	BRADFORD WHITE	0
22278	03/20/2017	RG240T6N	BRADFORD WHITE	0
22279	03/22/2017	RG250T6N	BRADFORD WHITE	0
22280	03/23/2017	RG250T6N	BRADFORD WHITE	0
22281	03/25/2017	RG250T6N	BRADFORD WHITE	0
22282	03/29/2017	RG250H6N	BRADFORD WHITE	0
22283	03/30/2017	RG240T6N	BRADFORD WHITE	0
22284	03/30/2017	RG250T6N	BRADFORD WHITE	0
22285	03/30/2017	RG250T6N	BRADFORD WHITE	0
22286	02/17/2017	RG250T6N	BRADFORD WHITE	0
22287	02/15/2017	RG250H6N	BRADFORD WHITE	0
22288	03/27/2017	RG250T6N	BRADFORD WHITE	0
22289	03/23/2017	RG250T6N	BRADFORD WHITE	0
22290	03/16/2017	RG250H6N	BRADFORD WHITE	0
22291	02/27/2017	RG250T6N	BRADFORD WHITE	0
22292	03/21/2017	RG250T6N	BRADFORD WHITE	0
22293	03/29/2017	RG250T6N	BRADFORD WHITE	0
22294	02/03/2017	RG250T6N	BRADFORD WHITE	0
22295	03/15/2017	PROG5036NRU60DV	RUUD	0
22296	03/21/2017	RG240T6N	BRADFORD WHITE	0
22297	03/07/2017	RG230S6N	BRADFORD WHITE	0
22298	03/08/2017	RG250T6N	BRADFORD WHITE	0
22299	03/08/2017	RG250T6N	BRADFORD WHITE	0
22300	03/11/2017	RG240S6N	BRADFORD WHITE	0
22301	03/15/2017	RG250T6N	BRADFORD WHITE	0
22302	03/18/2017	RG250L6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22303	03/17/2017	RG275H6N	BRADFORD WHITE	0
22304	03/22/2017	PH19980	Phoenix	0
22305	03/31/2017	G91200	RUUD	0
22306	03/31/2017	G91200	RUUD	0
22307	03/17/2017	RG250T6N	BRADFORD WHITE	0
22308	03/28/2017	RG250H6N	BRADFORD WHITE	0
22309	03/26/2017	G82156	RUUD	0
22310	03/15/2017	G82156	RUUD	0
22311	03/23/2017	G75125	RUUD	0
22312	03/17/2017	RG250T6N	BRADFORD WHITE	1
22313	04/06/2017	RG250T6N	BRADFORD-WHITE	0
22314	04/07/2017	RG250T6N	BRADFORD WHITE	0
22315	04/07/2017	PROG5036NRU60DV	RUUD	0
22316	04/06/2017	RG250T6N	BRADFORD WHITE	0
22317	04/05/2017	PROG5036NRU60DV	RUUD	0
22318	04/10/2017	PROG5036NRU60DV	RUUD	0
22319	04/09/2017	RG250T6N	BRADFORD WHITE	0
22320	04/07/2017	RG250T6N	BRADFORD WHITE	0
22321	04/17/2017	RG250H6N	BRADFORD WHITE	0
22322	04/17/2017	RG240T6N	BRADFORD WHITE	0
22323	04/17/2017	RG250T6N	BRADFORD WHITE	2
22324	04/19/2017	RG250T6N	BRADFORD WHITE	0
22325	04/18/2017	RG250T6N	BRADFORD WHITE	0
22326	04/20/2017	RG250T6N	BRADFORD WHITE	0
22327	04/24/2017	RG250T6N	BRADFORD WHITE	0
22328	04/21/2017	RG250T6N	BRADFORD WHITE	0
22329	04/14/2017	G75125	RUUD/RHEEM	1
22330	04/07/2017	RG250T6N	BRADFORD WHITE	0
22331	04/07/2017	RG250T6N	BRADFORD WHITE	0
22332	04/26/2017	RG240T6N	Bradford White	0
22333	04/03/2017	RG250T6N	BRADFORD WHITE	0
22334	04/03/2017	RG250T6N	BRADFORD WHITE	0
22335	04/01/2017	RG240T6N	BRADFORD WHITE	0
22336	04/01/2017	RG250T6N	BRADFORD WHITE	0
22337	03/23/2017	RG250T6N	BRADFORD WHITE	0
22338	04/05/2017	RG250H6N	BRADFORD WHITE	0
22339	04/04/2017	RG250T6N	BRADFORD WHITE	0
22340	04/05/2017	RG250T6N	BRADFORD WHITE	0
22341	04/10/2017	RG250T6N	BRADFORD WHITE	0
22342	04/03/2017	RG250T6N	BRADFORD WHITE	0
22343	04/12/2017	RG240T6N	BRADFORD WHITE	0
22344	04/13/2017	RG250T6N	BRADFORD WHITE	0
22345	02/13/2017	PROG5036NRU60DV	RUUD	0
22346	04/11/2017	RG240T6N	BRADFORD WHITE	0
22347	04/12/2017	RG250T6N	BRADFORD WHITE	0
22348	03/28/2017	RG275H6N	BRADFORD WHITE	0
22349	04/04/2017	G76200	RUUD	1
22350	04/17/2017	RG250H6N	BRADFORD WHITE	0
22351	04/21/2017	RG250T6N	BRADFORD WHITE	0
22352	03/16/2017	RG250T6N	BRADFORD WHITE	0
22353	03/27/2017	G91200	RUUD/RHEEM	2
22354	02/28/2017	PH19980	PHOENIX	1
22355	04/25/2017	RG250T6N	BRADFORD WHITE	1
22356	04/25/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22357	04/25/2017	RG240T6N	BRADFORD WHITE	0
22358	04/25/2017	PROG5036NRU60DV	RUUD	0
22359	04/20/2017	RG240T6N	BRADFORD WHITE	0
22360	04/24/2017	RG250T6N	BRADFORD WHITE	0
22361	04/21/2017	RG250T6N	BRADFORD WHITE	0
22362	04/20/2017	RG240S6N	BRADFORD WHITE	0
22363	04/19/2017	RG250H6N	BRADFORD WHITE	0
22364	04/18/2017	RG250T6N	BRADFORD WHITE	0
22365	04/17/2017	RG250T6N	BRADFORD WHITE	0
22366	04/12/2017	RG250T6N	BRADFORD WHITE	0
22367	04/13/2017	RG250T6N	BRADFORD WHITE	0
22368	04/09/2017	RG250T6N	BRADFORD WHITE	0
22369	03/30/2017	RG250T6N	BRADFORD WHITE	0
22370	04/06/2017	RG240T6N	BRADFORD WHITE	0
22371	03/27/2017	RG240S6N	BRADFORD WHITE	0
22372	03/23/2017	RG240T6N	BRADFORD WHITE	0
22373	03/23/2017	RG250T6N	BRADFORD WHITE	0
22374	03/23/2017	RG250T6N	BRADFORD WHITE	0
22375	03/21/2017	RG250T6N	BRADFORD WHITE	0
22376	03/21/2017	RG250T6N	Bradford-White	0
22377	04/27/2017	RG250T6N	BRADFORD WHITE	0
22378	04/25/2017	RG250T6N	BRADFORD WHITE	1
22379	04/17/2017	G91200	RUUD/RHEEM	0
22380	04/22/2017	G82156	RUUD/RHEEM	0
22381	04/28/2017	RG250H6N	BRADFORD WHITE	0
22382	04/27/2017	RG240T6N	BRADFORD WHITE	0
22383	04/27/2017	RG250T6N	BRADFORD WHITE	0
22384	04/13/2017	RG240S6N	BRADFORD WHITE	0
22385	04/24/2017	RG250T6N	BRADFORD WHITE	0
22386	04/14/2017	RG250T6N	BRADFORD WHITE	0
22387	04/11/2017	RG250T6N	BRADFORD WHITE	0
22388	04/10/2017	RG240T6N	BRADFORD WHITE	0
22389	04/12/2017	RG240T6N	BRADFORD WHITE	0
22390	03/07/2017	RG2DV50S6N	BRADFORD WHITE	0
22391	04/04/2017	RG250T6N	BRADFORD WHITE	0
22392	04/20/2017	RG250T6N	BRADFORD WHITE	0
22393	04/23/2017	G75125	RUUD/RHEEM	0
22394	03/13/2017	RG250H6N	BRADFORD WHITE	1
22395	05/01/2017	RG250T6N	BRADFORD WHITE	0
22396	05/08/2017	RG250T6N	BRADFORD WHITE	0
22397	05/08/2017	RG250T6N	BRADFORD WHITE	0
22398	05/09/2017	RG250T6N	BRADFORD WHITE	0
22399	05/01/2017	G75125	RHEEM / RUUD	0
22400	05/03/2017	G82156	RUUD/RHEEM	0
22401	05/01/2017	G91200	RUUD/RHEEM	0
22402	05/04/2017	PH199119	Phoenix	0
22403	05/16/2017	G91200	RUUD/RHEEM	0
22404	05/04/2017	RG250T6N	BRADFORD WHITE	0
22405	05/05/2017	RG250T6N	BRADFORD WHITE	0
22406	05/05/2017	RG250T6N	BRADFORD WHITE	0
22407	05/05/2017	PROG5036NRU60	RUUD	0
22408	05/04/2017	RG250T6N	BRADFORD WHITE	0
22409	05/05/2017	RG240T6N	BRADFORD-WHITE	1
22410	05/04/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22411	05/04/2017	RG250T6N	BRADFORD WHITE	0
22412	05/04/2017	RG250T6N	BRADFORD WHITE	0
22413	05/04/2017	RG250T6N	BRADFORD WHITE	0
22414	05/08/2017	RG250T6N	BRADFORD WHITE	0
22415	05/08/2017	RG240T6N	BRADFORD WHITE	0
22416	05/16/2017	RG240S6N	BRADFORD WHITE	0
22417	05/15/2017	RG240T6N	BRADFORD WHITE	0
22418	05/14/2017	RG250H6N	BRADFORD WHITE	0
22419	05/12/2017	RG250T6N	BRADFORD WHITE	0
22420	04/29/2017	G76200	RUUD/RHEEM	0
22421	04/24/2017	RG275H6N	BRADFORD WHITE	0
22422	05/11/2017	G75125	RUUD/RHEEM	0
22423	05/11/2017	G75125	RUUD/RHEEM	0
22424	05/24/2017	PROG5036NRU60DV	RUUD	0
22425	04/29/2017	PROG5036NRU60	RUUD	0
22426	03/17/2017	RG240T6N	BRADFORD WHITE	0
22427	04/28/2017	RG250T6N	BRADFORD WHITE	0
22428	04/29/2017	RG250T6N	BRADFORD WHITE	0
22429	04/30/2017	RG240S6N	BRADFORD WHITE	0
22430	05/31/2017	RG240S6N	BRADFORD WHITE	0
22431	05/31/2017	RG250T6N	BRADFORD WHITE	0
22432	05/19/2017	G76200	RUUD	1
22433	05/06/2017	G91200	RUUD/RHEEM	0
22434	05/13/2017	RG240T6N	BRADFORD WHITE	0
22435	05/12/2017	RG250L6N	BRADFORD WHITE	0
22436	05/11/2017	RG250T6N	BRADFORD WHITE	1
22437	05/10/2017	RG250T6N	BRADFORD WHITE	0
22438	05/10/2017	RG240T6N	BRADFORD WHITE	0
22439	05/09/2017	RG250T6N	BRADFORD WHITE	0
22440	05/03/2017	RG240S6N	BRADFORD WHITE	0
22441	05/08/2017	RG250T6N	BRADFORD WHITE	0
22442	05/04/2017	RG240S6N	BRADFORD WHITE	0
22443	05/03/2017	RG250T6N	BRADFORD WHITE	0
22444	05/03/2017	RG250T6N	BRADFORD WHITE	0
22445	05/02/2017	RG240T6N	BRADFORD WHITE	0
22446	05/02/2017	PROG5036NRU60	RUUD	0
22447	05/01/2017	RG240T6N	BRADFORD WHITE	0
22448	05/01/2017	RG250T6N	BRADFORD WHITE	0
22449	05/01/2017	RG250T6N	BRADFORD WHITE	0
22450	01/24/2017	RG250T6N	BRADFORD WHITE	0
22451	05/17/2017	RG250T6N	BRADFORD WHITE	0
22452	05/04/2017	RG250T6N	BRADFORD WHITE	0
22453	05/12/2017	RG250T6N	BRADFORD WHITE	0
22454	05/31/2017	PROG5036NRU60	RUUD	0
22455	05/31/2017	PROG5036NRH60	RUUD	0
22456	05/30/2017	RG250T6N	BRADFORD WHITE	0
22457	05/23/2017	PROG5036NRU60	RUUD	0
22458	05/30/2017	RG250T6N	BRADFORD WHITE	0
22459	05/26/2017	RG250T6N	BRADFORD WHITE	0
22460	05/26/2017	PROG5036NRU60	RUUD	0
22461	05/30/2017	RG240T6N	BRADFORD WHITE	0
22462	05/30/2017	RG250T6N	BRADFORD WHITE	1
22463	05/29/2017	RG250T6N	BRADFORD WHITE	0
22464	05/24/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22465	03/24/2017	RG250T6N	BRADFORD WHITE	0
22466	05/24/2017	RG250T6N	BRADFORD WHITE	0
22467	05/25/2017	RG250T6N	BRADFORD WHITE	0
22468	05/15/2017	PROG5036NRU60	RUUD	0
22469	05/23/2017	RG250T6N	BRADFORD WHITE	0
22470	06/09/2017	RG240T6N	BRADFORD WHITE	0
22471	06/09/2017	RG250T6N	BRADFORD WHITE	0
22472	06/12/2017	RG250T6N	BRADFORD WHITE	0
22473	06/12/2017	RG250T6N	BRADFORD WHITE	0
22474	06/13/2017	RG250T6N	BRADFORD WHITE	0
22475	06/13/2017	RG250T6N	BRADFORD WHITE	0
22476	06/06/2017	RG250T6N	BRADFORD WHITE	0
22477	06/06/2017	RG250T6N	BRADFORD WHITE	0
22478	06/07/2017	RG250T6N	BRADFORD WHITE	0
22479	06/17/2017	RG250T6N	BRADFORD WHITE	0
22480	06/08/2017	PROG5036NRU60	RUUD	0
22481	06/08/2017	PROG5036NRU60	RUUD	1
22482	06/09/2017	RG250T6N	BRADFORD WHITE	0
22483	05/16/2017	RG250T6N	BRADFORD WHITE	0
22484	05/13/2017	RG250T6N	BRADFORD WHITE	0
22485	04/07/2017	RG240T6N	BRADFORD WHITE	0
22486	06/09/2017	RG250T6N	BRADFORD WHITE	0
22487	06/09/2017	RG250T6N	BRADFORD WHITE	0
22488	06/12/2017	RG240T6N	BRADFORD WHITE	0
22489	06/12/2017	RG250T6N	BRADFORD WHITE	0
22490	06/12/2017	RG250T6N	BRADFORD WHITE	0
22491	06/05/2017	RG250T6N	BRADFORD WHITE	0
22492	06/05/2017	RG250H6N	BRADFORD WHITE	0
22493	06/15/2017	RG250T6N	BRADFORD WHITE	0
22494	06/15/2017	RG250T6N	BRADFORD WHITE	0
22495	06/13/2017	RG250T6N	BRADFORD WHITE	0
22496	06/11/2017	G82156	RUUD/RHEEM	0
22497	03/31/2017	G76200	RUUD/RHEEM	0
22498	05/17/2017	G91200	RUUD	0
22499	05/18/2017	G91200	RUUD/RHEEM	0
22500	04/18/2017	PH199119	Phoenix	0
22501	05/17/2017	G91200	RUUD/RHEEM	0
22502	06/28/2017	RG2DV50S6N	Bradford White	0
22503	05/25/2017	G75125	RUUD/RHEEM	0
22504	04/15/2017	G82156	RUUD/RHEEM	0
22505	05/17/2017	PROG5036NRU60DV	RUUD	1
22506	05/17/2017	RG250T6N	BRADFORD WHITE	0
22507	04/28/2017	RG250T6N	BRADFORD WHITE	0
22508	04/27/2017	RG250T6N	BRADFORD WHITE	0
22509	04/25/2017	RG240T6N	BRADFORD WHITE	0
22510	04/24/2017	RG240T6N	BRADFORD WHITE	0
22511	04/21/2017	RG250T6N	BRADFORD WHITE	0
22512	04/19/2017	PROG5036NRU60	RUUD	0
22513	04/27/2017	RG250H6N	BRADFORD WHITE	0
22514	04/27/2017	RG250T6N	BRADFORD WHITE	0
22515	06/22/2017	RG250H6N	BRADFORD WHITE	0
22516	06/22/2017	RG250T6N	BRADFORD WHITE	0
22517	06/22/2017	RG250T6N	BRADFORD WHITE	0
22518	06/21/2017	PROG5036NRU60	RUUD	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22519	06/21/2017	PROG5036NRU60	RUUD	0
22520	06/21/2017	G91200	RUUD/RHEEM	3
22521	06/19/2017	RG275H6N	BRADFORD WHITE	0
22522	06/18/2017	G91200	RUUD/RHEEM	0
22523	06/20/2017	RG250T6N	BRADFORD WHITE	1
22524	06/16/2017	RG240T6N	BRADFORD WHITE	0
22525	06/16/2017	RG250T6N	BRADFORD WHITE	0
22526	06/19/2017	RG250T6N	BRADFORD WHITE	0
22527	06/16/2017	RG250T6N	BRADFORD WHITE	0
22528	06/15/2017	RG250T6N	BRADFORD WHITE	0
22529	06/19/2017	RG250T6N	BRADFORD WHITE	0
22530	06/20/2017	RG250T6N	BRADFORD WHITE	0
22531	06/20/2017	RG250T6N	BRADFORD WHITE	0
22532	06/11/2017	RG240T6N	BRADFORD WHITE	0
22533	02/24/2017	RG250T6N	BRADFORD WHITE	0
22534	06/20/2017	PROG5036NRU60	RUUD	0
22535	02/27/2017	PROG5036NRU60	RUUD	0
22536	04/05/2017	RG250T6N	BRADFORD WHITE	0
22537	04/05/2017	RG240T6N	BRADFORD WHITE	0
22538	04/06/2017	RG250T6N	BRADFORD WHITE	0
22539	04/18/2017	RG250T6N	BRADFORD WHITE	0
22540	04/27/2017	RG240S6N	BRADFORD WHITE	0
22541	04/25/2017	RG250T6N	BRADFORD WHITE	0
22542	04/18/2017	RG240T6N	BRADFORD WHITE	0
22543	04/28/2017	RG250T6N	BRADFORD WHITE	0
22544	07/05/2017	G91200	RUUD/RHEEM	1
22545	07/05/2017	G75125	RUUD/RHEEM	1
22546	06/02/2017	PROG5036NRU60	RUUD	0
22547	06/01/2017	RG250T6N	BRADFORD WHITE	0
22548	05/17/2017	RG240S6N	BRADFORD WHITE	0
22549	06/01/2017	RG250T6N	BRADFORD WHITE	0
22550	06/02/2017	RG250T6N	BRADFORD WHITE	0
22551	06/02/2017	RG250T6N	BRADFORD WHITE	0
22552	06/02/2017	RG250T6N	BRADFORD WHITE	0
22553	05/22/2017	RG250T6N	BRADFORD WHITE	0
22554	06/16/2017	RG250T6N	BRADFORD WHITE	0
22555	06/25/2017	RG240T6N	BRADFORD WHITE	0
22556	06/22/2017	RG240S6N	BRADFORD WHITE	0
22557	06/23/2017	RG250L6N	BRADFORD WHITE	0
22558	06/23/2017	RG250T6N	BRADFORD WHITE	0
22559	06/26/2017	RG250T6N	BRADFORD WHITE	1
22560	06/26/2017	RG250T6N	BRADFORD WHITE	0
22561	06/26/2017	RG250T6N	BRADFORD WHITE	0
22562	05/12/2017	RG250T6N	BRADFORD WHITE	0
22563	05/09/2017	RG250H6N	BRADFORD WHITE	0
22564	05/05/2017	RG240T6N	BRADFORD WHITE	0
22565	05/06/2017	RG250T6N	BRADFORD WHITE	0
22566	05/05/2017	RG250T6N	BRADFORD WHITE	0
22567	05/05/2017	RG250T6N	BRADFORD WHITE	0
22568	04/29/2017	RG250T6N	BRADFORD WHITE	0
22569	05/01/2017	RG250T6N	BRADFORD WHITE	0
22570	04/26/2017	RG250T6N	BRADFORD WHITE	0
22571	05/22/2017	RG250T6N	BRADFORD WHITE	0
22572	05/22/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22573	05/19/2017	RG240T6N	BRADFORD WHITE	0
22574	05/22/2017	RG250T6N	BRADFORD WHITE	0
22575	06/23/2017	RG250T6N	BRADFORD WHITE	0
22576	06/28/2017	RG240S6N	BRADFORD WHITE	0
22577	05/06/2017	RG240T6N	BRADFORD WHITE	0
22578	06/20/2017	PROG5036NRU60DV	RUUD	0
22579	05/24/2017	PROG5036NRU60	RUUD	0
22580	06/01/2017	RG250T6N	BRADFORD WHITE	0
22581	05/04/2017	RG250T6N	BRADFORD WHITE	0
22582	05/23/2017	RG250T6N	BRADFORD WHITE	0
22583	05/18/2017	PROG5036NRU60	RUUD	0
22584	05/08/2017	RG240T6N	BRADFORD WHITE	0
22585	05/02/2017	PROG5036NRU60	RUUD	1
22586	04/30/2017	RG250T6N	BRADFORD WHITE	0
22587	05/27/2017	RG250T6N	BRADFORD WHITE	0
22588	05/30/2017	PROG5036NRU60	RUUD	0
22589	05/30/2017	RG250T6N	BRADFORD WHITE	0
22590	05/25/2017	RG250T6N	BRADFORD WHITE	0
22591	05/25/2017	RG250T6N	BRADFORD WHITE	0
22592	05/23/2017	RG250T6N	BRADFORD WHITE	0
22593	05/23/2017	RG250T6N	BRADFORD WHITE	0
22594	05/22/2017	RG250T6N	BRADFORD WHITE	0
22595	05/16/2017	RG250T6N	BRADFORD WHITE	0
22596	05/15/2017	RG250T6N	BRADFORD WHITE	0
22597	05/15/2017	RG240T6N	BRADFORD WHITE	0
22598	05/16/2017	RG250T6N	BRADFORD WHITE	0
22599	05/30/2017	RG240T6N	BRADFORD WHITE	0
22600	05/23/2017	RG240T6N	BRADFORD WHITE	0
22601	06/06/2017	PROG5036NRU60	RUUD	0
22602	06/06/2017	RG250T6N	BRADFORD WHITE	0
22603	06/06/2017	RG250T6N	BRADFORD-WHITE	0
22604	06/04/2017	RG250T6N	BRADFORD-WHITE	0
22605	06/02/2017	RG250H6N	BRADFORD WHITE	0
22606	05/31/2017	RG250T6N	BRADFORD WHITE	0
22607	05/26/2017	RG250T6N	BRADFORD WHITE	0
22608	05/25/2017	RG240T6N	BRADFORD WHITE	0
22609	06/19/2017	RG250T6N	BRADFORD WHITE	0
22610	06/19/2017	RG240T6N	BRADFORD WHITE	0
22611	06/02/2017	RG240T6N	BRADFORD WHITE	0
22612	05/15/2017	RG250T6N	BRADFORD WHITE	0
22613	06/09/2017	RG250H6N	BRADFORD WHITE	0
22614	06/08/2017	RG250T6N	BRADFORD WHITE	0
22615	06/07/2017	RG240S6N	BRADFORD WHITE	1
22616	05/24/2017	RG250T6N	BRADFORD WHITE	0
22617	05/23/2017	RG250T6N	BRADFORD WHITE	0
22618	06/06/2017	RG240T6N	BRADFORD WHITE	0
22619	06/14/2017	RG250T6N	BRADFORD WHITE	0
22620	06/14/2017	RG250T6N	BRADFORD WHITE	0
22621	06/12/2017	RG250T6N	BRADFORD WHITE	1
22622	06/12/2017	PROG5036NRU60	RUUD	0
22623	06/12/2017	RG250T6N	BRADFORD WHITE	0
22624	06/12/2017	RG250T6N	BRADFORD WHITE	0
22625	06/09/2017	RG250T6N	BRADFORD WHITE	0
22626	06/09/2017	RG250T6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22627	06/09/2017	RG250T6N	BRADFORD WHITE	0
22628	06/09/2017	RG240T6N	BRADFORD WHITE	0
22629	06/09/2017	RG250T6N	BRADFORD WHITE	0
22630	05/18/2017	RG250T6N	BRADFORD WHITE	0
22631	05/12/2017	RG250T6N	BRADFORD WHITE	1
22632	05/12/2017	RG250T6N	BRADFORD WHITE	0
22633	05/07/2017	RG250T6N	BRADFORD WHITE	0
22634	05/07/2017	RG250T6N	BRADFORD WHITE	0
22635	06/24/2017	RG250T6N	BRADFORD WHITE	0
22636	06/19/2017	RG240S6N	BRADFORD WHITE	0
22637	06/20/2017	RG250T6N	BRADFORD WHITE	0
22638	06/02/2017	RG250T6N	BRADFORD WHITE	0
22639	06/20/2017	RG240T6N	BRADFORD WHITE	0
22640	06/23/2017	RG250T6N	BRADFORD WHITE	0
22641	05/25/2017	RG250T6N	BRADFORD WHITE	0
22642	06/26/2017	RG250T6N	BRADFORD WHITE	0
22643	05/05/2017	RG250T6N	BRADFORD WHITE	0
22644	04/20/2017	PH19980	PHOENIX	0
22645	05/04/2017	G75125	RUUD/RHEEM	0
22646	06/27/2017	G76200	RUUD/RHEEM	2
22647	05/05/2017	G91200	RUUD/RHEEM	2
22648	06/22/2017	G82156	RUUD/RHEEM	5
22649	06/22/2017	G82156	RUUD/RHEEM	0
22650	05/23/2017	RG275H6N	BRADFORD WHITE	0
22651	05/23/2017	RG275H6N	BRADFORD WHITE	0
22652	05/23/2017	RG250H6N	BRADFORD WHITE	0
22653	06/19/2017	G91200	RUUD/RHEEM	0
22654	06/05/2017	PROG5036NRU60	RUUD	1
22655	07/02/2017	RG250T6N	BRADFORD WHITE	0
22656	06/21/2017	RG250T6N	BRADFORD WHITE	0
22657	05/30/2017	RG240T6N	BRADFORD-WHITE	0
22658	06/06/2017	RG250T6N	BRADFORD WHITE	0
22659	05/30/2017	RG250T6N	BRADFORD WHITE	0
22660	06/01/2017	RG240T6N	BRADFORD WHITE	0
22661	04/28/2017	RG240S6N	BRADFORD WHITE	0
22662	09/25/2015	RG250T6N	BRADFORD WHITE	0
22663	08/07/2014	M45036FBN	BRADFORD WHITE	0
22664	09/15/2014	PROG5038NRU58	RUUD	0
22665	07/14/2015	M45036FBN	BRADFORD WHITE	0
22666	06/13/2017	PROG5036NRU60	RUUD	0
22667	05/28/2017	G82156	RUUD/RHEEM	0
22668	12/21/2016	RG250T6N	BRADFORD WHITE	0
22669	12/22/2014	M45036FBN	BRADFORD WHITE	0
22670	06/17/2017	RG230T6N	BRADFORD WHITE	0
22671	05/25/2017	RG250T6N	BRADFORD WHITE	0
22672	05/31/2017	RG240T6N	BRADFORD WHITE	0
22673	04/30/2017	RG250T6N	BRADFORD WHITE	0
22674	02/14/2017	RG240T6N	BRADFORD WHITE	1
22675	05/27/2017	RG250H6N	BRADFORD WHITE	2
22676	06/23/2017	RG250H6N	BRADFORD WHITE	0
22677	06/30/2017	PROG4038NRH62	RHEEM	0
22678	07/02/2017	PROG5036NRH60DV	RHEEM	0
22679	07/02/2017	PROG40S38NRH62	RHEEM	0
22680	06/26/2017	PROG40S38NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22681	06/29/2017	PROG4038NRH62	RHEEM	0
22682	07/01/2017	PROG5038NRH60	RHEEM	0
22683	06/29/2017	PROG5038NRH60	RHEEM	0
22684	06/30/2017	RG2DV50S6N	BRADFORD WHITE	0
22685	06/30/2017	PROG40S38NRH62	RUUD/RHEEM	0
22686	06/27/2017	PROG50S40NRH61	RUUD/RHEEM	0
22687	06/27/2017	G82156	RUUD/RHEEM	0
22688	06/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22689	07/01/2017	PROG4038NRH62	RUUD/RHEEM	0
22690	06/30/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22691	06/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22692	06/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22693	06/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22694	06/29/2017	PROG40S38NRH62	RUUD/RHEEM	0
22695	07/07/2017	PROG5038NRH60	RUUD/RHEEM	1
22696	07/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22697	07/03/2017	PROG5038NRH60	RUUD/RHEEM	0
22698	06/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22699	07/03/2017	PROG5038NRH60	RUUD/RHEEM	0
22700	07/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22701	07/03/2017	PROG5038NRH60	RUUD/RHEEM	0
22702	07/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22703	07/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22704	07/03/2017	PROG40S38NRH62	RUUD/RHEEM	0
22705	07/07/2017	PROG4038NRH62	RUUD/RHEEM	0
22706	07/07/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22707	07/11/2017	PROG5038NRH60	RUUD/RHEEM	0
22708	07/13/2017	PROG4038NRH62	RUUD/RHEEM	0
22709	07/10/2017	PROG5038NRH60	RUUD/RHEEM	0
22710	07/12/2017	PROG2932NRH63	RUUD/RHEEM	0
22711	07/12/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22712	07/06/2017	G91200	RUUD/RHEEM	0
22713	07/01/2017	PROG4038NRH62	RUUD/RHEEM	0
22714	07/02/2017	PROG4038NRH62	RUUD/RHEEM	0
22715	06/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22716	06/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22717	06/27/2017	PROG4860NRH60	RUUD/RHEEM	0
22718	08/07/2017	PROG4038NRH62	RUUD/RHEEM	0
22719	07/02/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22720	06/30/2017	G91200	RUUD/RHEEM	0
22721	06/12/2012	PROG5038NRH60	RUUD/RHEEM	0
22722	07/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22723	07/05/2017	PROG5038NRH60	RUUD/RHEEM	2
22724	07/06/2017	RG250S6N	BRADFORD WHITE	0
22725	07/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22726	06/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22727	07/08/2017	PROG5038NRH60	RUUD/RHEEM	0
22728	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22729	07/04/2017	G100200	RUUD/RHEEM	1
22730	07/06/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22731	07/12/2017	PROG5038NRH60	RUUD/RHEEM	0
22732	07/13/2017	PROG50S40NRH61	RUUD/RHEEM	0
22733	07/11/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22734	07/13/2017	PROG5038NRH60	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22735	07/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22736	07/11/2017	PROG5038NRH60	RUUD/RHEEM	0
22737	07/11/2017	PROG5038NRH60	RUUD/RHEEM	0
22738	07/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22739	07/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22740	07/12/2017	PROG5038NRH60	RUUD/RHEEM	0
22741	07/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22742	07/22/2017	PROG5038NRH60	RUUD/RHEEM	0
22743	07/19/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22744	07/21/2017	PROG40S38NRH62	RUUD/RHEEM	0
22745	07/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22746	07/21/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22747	07/18/2017	PROG5038NRH60	RUUD/RHEEM	0
22748	07/17/2017	PROG5038NRH60	RUUD/RHEEM	0
22749	07/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22750	07/18/2017	PROG40S38NRH62	RUUD/RHEEM	0
22751	07/10/2017	PROG5038NRH60	RUUD/RHEEM	0
22752	07/12/2017	PROG5038NRH60	RUUD/RHEEM	0
22753	07/22/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22754	07/14/2017	G76200	RUUD/RHEEM	1
22755	07/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22756	07/29/2017	PROG5038NRH60	RUUD/RHEEM	0
22757	07/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22758	07/26/2017	PROG50S40NRH61	RUUD/RHEEM	0
22759	07/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22760	07/17/2017	PROG4038NRH62	RUUD/RHEEM	0
22761	07/17/2017	PROG5038NRH60	RUUD/RHEEM	0
22762	07/18/2017	PROG5038NRH60	RUUD/RHEEM	0
22763	07/20/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22764	07/19/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22765	07/17/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22766	07/17/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22767	07/24/2017	PROG4038NRH62	RUUD/RHEEM	0
22768	07/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22769	07/26/2017	PROG50S40NRH61	RUUD/RHEEM	0
22770	07/27/2017	PROG4038NRH62	RUUD/RHEEM	0
22771	07/29/2017	PROG5038NRH60	RUUD/RHEEM	0
22772	07/25/2017	PROG50S40NRH61	RUUD/RHEEM	0
22773	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22774	07/25/2017	PROG40S38NRH62	RUUD/RHEEM	0
22775	07/24/2017	PROG5038NRH60	RUUD/RHEEM	0
22776	07/28/2017	PROG40S38NRH62	RUUD/RHEEM	0
22777	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22778	07/24/2017	PROG40S38NRH62	RUUD/RHEEM	0
22779	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22780	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22781	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22782	07/25/2017	PROG4038NRH62	RUUD/RHEEM	0
22783	07/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22784	07/28/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22785	07/25/2017	PROG5038NRH60	RUUD/RHEEM	0
22786	07/24/2017	PROG5038NRH60	RUUD/RHEEM	0
22787	07/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22788	07/28/2017	G75125	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22789	07/31/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22790	08/01/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22791	07/31/2017	PROG5038NRH60	RUUD/RHEEM	0
22792	07/31/2017	PROG5038NRH60	RUUD/RHEEM	0
22793	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	0
22794	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	0
22795	08/03/2017	PROG5038NRH60	RUUD/RHEEM	1
22796	07/31/2017	PROG4038NRH62	RUUD/RHEEM	0
22797	08/04/2017	PROG5038NRH60	RUUD/RHEEM	0
22798	08/04/2017	PROG5038NRH60	RUUD/RHEEM	0
22799	08/04/2017	PROG4038NRH62	RUUD/RHEEM	0
22800	08/06/2017	PROG40S38NRH62	RUUD/RHEEM	1
22801	08/02/2017	PROG5038NRH60	RUUD/RHEEM	0
22802	08/05/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22803	08/02/2017	PROG50S40NRH61	RUUD/RHEEM	0
22804	07/31/2017	PROG5038NRH60	RUUD/RHEEM	0
22805	08/09/2017	PROG5038NRH60	RUUD/RHEEM	0
22806	07/31/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22807	08/10/2017	PROG40S38NRH62	RUUD/RHEEM	0
22808	08/06/2017	PROG4038NRH62	RUUD/RHEEM	0
22809	08/04/2017	PROG4038NRH62	RUUD/RHEEM	0
22810	08/10/2017	PROG5038NRH60	RUUD/RHEEM	0
22811	09/16/2017	PROG5038NRH60	RUUD/RHEEM	0
22812	08/02/2017	PROG4038NRH62	RUUD/RHEEM	0
22813	07/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22814	08/08/2017	PROG5038NRH60	RUUD/RHEEM	0
22815	08/08/2017	PROG40S38NRH62	RUUD/RHEEM	0
22816	08/08/2017	PROG4038NRH62	RUUD/RHEEM	0
22817	08/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22818	08/09/2017	PROG5038NRH60	RUUD/RHEEM	0
22819	08/04/2017	PROG40S38NRH62	RUUD/RHEEM	0
22820	08/10/2017	PROG4038NRH62	RUUD/RHEEM	0
22821	08/08/2017	PROG5038NRH60	RUUD/RHEEM	0
22822	08/01/2017	PROG5038NRH60	RUUD/RHEEM	0
22823	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	0
22824	08/01/2017	PROG5038NRH60	RUUD/RHEEM	0
22825	08/11/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22826	08/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22827	08/09/2017	PROG40S38NRH62	RUUD/RHEEM	0
22828	08/09/2017	PROG40S38NRH62	RUUD/RHEEM	0
22829	08/08/2017	PROG40S38NRH62	RUUD/RHEEM	1
22830	08/09/2017	PROG5038NRH60	RUUD/RHEEM	0
22831	08/09/2017	PROG50S40NRH61	RUUD/RHEEM	0
22832	08/06/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22833	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22834	08/16/2017	PROG5038NRH60	RUUD/RHEEM	0
22835	08/19/2017	PROG50S40NRH61	RUUD/RHEEM	0
22836	08/17/2017	PROG5038NRH60	RUUD/RHEEM	0
22837	08/08/2017	PROG5038NRH60	RUUD/RHEEM	0
22838	08/10/2017	PROG5038NRH60	RUUD/RHEEM	0
22839	08/11/2017	PROG5038NRH60	RUUD/RHEEM	0
22840	08/03/2017	G82156	RUUD/RHEEM	0
22841	08/09/2017	PROG5038NRH60	RUUD/RHEEM	0
22842	08/03/2017	G91200	RUUD/RHEEM	1

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22843	08/07/2017	G91200	RUUD/RHEEM	1
22844	07/30/2017	G82156	RUUD/RHEEM	0
22845	08/17/2017	PROG5038NRH60	RUUD/RHEEM	0
22846	08/18/2017	PROG4038NRH62	RUUD/RHEEM	0
22847	08/18/2017	PROG4038NRH62	RUUD/RHEEM	0
22848	08/16/2017	PROG5038NRH60	RUUD/RHEEM	0
22849	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22850	07/30/2017	PROG40S38NRH62	RUUD/RHEEM	0
22851	08/03/2017	PROG5038NRH60	RUUD/RHEEM	0
22852	07/25/2017	G75125	RUUD/RHEEM	2
22853	08/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22854	08/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22855	08/26/2017	PROG50S40NRH61	RUUD/RHEEM	0
22856	08/17/2017	G82156	RUUD/RHEEM	3
22857	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22858	07/21/2017	G75125	RUUD/RHEEM	0
22859	07/18/2017	G91200	RUUD/RHEEM	0
22860	07/20/2017	PH199119	PHOENIX	0
22861	03/31/2017	PROG40S34NRU62	RUUD/RHEEM	4
22862	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22863	08/16/2017	PROG5038NRH60	RUUD/RHEEM	0
22864	08/18/2017	PROG4038NRH62	RUUD/RHEEM	0
22865	08/14/2017	PROG5038NRH60	RUUD/RHEEM	0
22866	08/18/2017	PROG40S38NRH62	RUUD/RHEEM	0
22867	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22868	08/15/2017	PROG50S40NRH61	RUUD/RHEEM	0
22869	08/15/2017	PROG4038NRH62	RUUD/RHEEM	0
22870	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22871	08/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22872	08/25/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22873	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22874	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22875	08/22/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22876	08/23/2017	PROG4038NRH62	RUUD/RHEEM	0
22877	08/07/2017	PH199119	PHOENIX	0
22878	08/08/2017	PH199119	PHOENIX	0
22879	08/22/2017	PROG5038NRH60	RUUD/RHEEM	0
22880	08/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22881	08/24/2017	PROG40S38NRH62	RUUD/RHEEM	0
22882	08/22/2017	PROG40S38NRH62	RUUD/RHEEM	0
22883	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22884	08/23/2017	PROG2932NRH63	RUUD/RHEEM	0
22885	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22886	08/23/2017	G82156	RUUD	0
22887	08/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22888	08/27/2017	PROG40S38NRH62	RUUD/RHEEM	0
22889	08/25/2017	G75125	RUUD/RHEEM	1
22890	08/23/2017	RG2DV40S6N	BRADFORD WHITE	0
22891	08/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22892	08/22/2017	PROG5038NRH60	RUUD/RHEEM	0
22893	08/22/2017	G76200	RUUD/RHEEM	0
22894	08/23/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22895	08/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22896	08/26/2017	PROG5038NRH60	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22897	09/01/2017	PROG50S40NRH61	RUUD/RHEEM	0
22898	08/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22899	08/28/2017	PROG4038NRH62	RUUD/RHEEM	0
22900	09/01/2017	RG2DV50S6N	BRADFORD WHITE	0
22901	08/29/2017	PROG40S38NRH62	RUUD/RHEEM	0
22902	09/02/2017	PROG5038NRH60	RUUD/RHEEM	0
22903	09/02/2017	PROG5038NRH60	RUUD/RHEEM	0
22904	09/02/2017	PROG5038NRH60	RUUD/RHEEM	0
22905	09/02/2017	PROG5038NRH60	RUUD/RHEEM	0
22906	08/29/2017	PROG5038NRH60	RUUD/RHEEM	0
22907	08/30/2017	PROG40S38NRH62	RUUD/RHEEM	0
22908	09/01/2017	PROG5038NRH60	RUUD/RHEEM	0
22909	08/29/2017	PROG5038NRH60	RUUD/RHEEM	0
22910	08/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22911	08/28/2017	PROG5038NRH60	RUUD/RHEEM	1
22912	08/31/2017	PROG4038NRH62	RUUD/RHEEM	0
22913	08/29/2017	PROG4038NRH62	RUUD/RHEEM	2
22914	08/28/2017	PROG4038NRH62	RUUD/RHEEM	0
22915	08/29/2017	PROG5038NRH60	RUUD/RHEEM	0
22916	08/28/2017	PROG4038NRH62	RUUD/RHEEM	0
22917	08/30/2017	PROG5038NRH60	RUUD/RHEEM	0
22918	09/01/2017	PROG5038NRH60	RUUD/RHEEM	0
22919	08/31/2017	PROG5038NRH60	RUUD/RHEEM	0
22920	08/28/2017	G82156	RUUD/RHEEM	0
22921	09/08/2017	PROG5038NRH60	RUUD/RHEEM	0
22922	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22923	09/07/2017	PROG5038NRH60	RUUD/RHEEM	1
22924	09/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22925	09/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22926	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22927	09/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22928	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22929	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22930	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22931	09/05/2017	PROG4038NRH62	RUUD/RHEEM	0
22932	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22933	09/11/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22934	09/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22935	09/09/2017	PROG5038NRH60	RUUD	1
22936	09/01/2017	G91200	RUUD/RHEEM	0
22937	09/08/2017	PROG5038NRH60	RUUD/RHEEM	1
22938	09/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22939	09/09/2017	PROG5038NRH60	RUUD/RHEEM	0
22940	09/07/2017	PROG5038NRH60	RUUD/RHEEM	0
22941	09/06/2017	PROG7576NRH	RUUD/RHEEM	0
22942	09/11/2017	PROG5038NRH60	RUUD/RHEEM	0
22943	09/13/2017	PROG40S38NRH62	RUUD/RHEEM	1
22944	09/17/2017	PROG4038NRH62	RUUD/RHEEM	0
22945	09/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22946	09/15/2017	RG2DV50S6N	BRADFORD WHITE	0
22947	09/12/2017	PROG40S38NRH62	RUUD/RHEEM	0
22948	09/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22949	09/11/2017	G76200	RUUD/RHEEM	0
22950	09/14/2017	PROG5038NRH60	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
22951	09/12/2017	PROG5038NRH60	RUUD/RHEEM	0
22952	09/16/2017	PROG5038NRH60	RUUD/RHEEM	0
22953	09/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22954	09/14/2017	PROG5038NRH60	RUUD/RHEEM	0
22955	09/16/2017	PROG40S38NRH62	RUUD/RHEEM	0
22956	09/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22957	09/06/2017	PROG5038NRH60	RUUD/RHEEM	0
22958	09/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22959	09/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22960	09/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22961	09/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22962	09/23/2017	PROG5038NRH60	RUUD/RHEEM	0
22963	09/19/2017	PROG5038NRH60	RUUD/RHEEM	0
22964	09/18/2017	PROG5038NRH60	RUUD/RHEEM	0
22965	09/22/2017	PROG5038NRH60	RUUD/RHEEM	0
22966	09/24/2017	PROG5038NRH60	RUUD/RHEEM	0
22967	09/21/2017	PROG5038NRH60	RUUD/RHEEM	0
22968	09/23/2017	PROG40S38NRH62	RUUD/RHEEM	0
22969	09/18/2017	PROG4038NRH62	RUUD/RHEEM	0
22970	09/20/2017	G82156	RUUD/RHEEM	0
22971	09/19/2017	G91200	RUUD/RHEEM	0
22972	09/13/2017	PROG4038NRH62	RUUD/RHEEM	0
22973	09/19/2017	PROG5038NRH60	RUUD/RHEEM	0
22974	09/22/2017	G82156	RUUD/RHEEM	0
22975	09/29/2017	PROG50S40NRH61	RUUD/RHEEM	0
22976	09/26/2017	PROG5038NRH60	RUUD/RHEEM	0
22977	10/01/2017	PROG5038NRH60	RUUD/RHEEM	0
22978	09/27/2017	PROG5038NRH60	RUUD/RHEEM	0
22979	09/28/2017	PROG5038NRH60	RUUD/RHEEM	0
22980	09/13/2017	G7575	RUUD/RHEEM	0
22981	09/16/2017	PROG40S38NRH62	RUUD/RHEEM	1
22982	09/15/2017	PROG5038NRH60	RUUD/RHEEM	0
22983	09/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22984	09/14/2017	PROG40S38NRH62	RUUD/RHEEM	0
22985	09/15/2017	PROG5036NRH60DV	RUUD/RHEEM	0
22986	09/04/2017	G91200	RUUD/RHEEM	0
22987	09/13/2017	PROG5038NRH60	RUUD/RHEEM	0
22988	09/07/2017	PROG4038NRH62	RUUD/RHEEM	0
22989	09/05/2017	PROG5038NRH60	RUUD/RHEEM	0
22990	09/08/2017	RG130T6N	BRADFORD WHITE	0
22991	09/19/2017	PROG5036NRH60DV	RUUD/RHEEM	1
22992	09/20/2017	PROG5038NRH60	RUUD/RHEEM	0
22993	09/20/2017	PROG4038NRH62	RUUD/RHEEM	0
22994	09/20/2017	PROG5038NRH60	RUUD/RHEEM	0
22995	09/24/2017	PROG5038NRH60	RUUD/RHEEM	0
22996	09/18/2017	PROG5038NRH60	RUUD/RHEEM	0
22997	09/19/2017	PROG5038NRH60	RUUD/RHEEM	0
22998	09/20/2017	PROG5038NRH60	RUUD/RHEEM	0
22999	09/19/2017	PROG5038NRH60	RUUD/RHEEM	1
23000	09/21/2017	PROG5038NRH60	RUUD/RHEEM	0
23001	09/23/2017	PROG4038NRH62	RUUD/RHEEM	0
23002	09/19/2017	PROG5038NRH60	RUUD/RHEEM	0
23003	09/22/2017	PROG4038NRH62	RUUD/RHEEM	0
23004	09/19/2017	PROG5038NRH60	RUUD/RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23005	09/23/2017	PROG5038NRH60	RUUD/RHEEM	0
23006	09/22/2017	PROG50S40NRH61	RUUD/RHEEM	0
23007	09/28/2017	PROG5038NRH60	RUUD/RHEEM	0
23008	09/27/2017	PROG4038NRH62	RUUD/RHEEM	0
23009	09/27/2017	PROG5036NRH60DV	RUUD/RHEEM	0
23010	09/27/2017	PROG5038NRH60	RUUD/RHEEM	0
23011	09/19/2017	G91200	RUUD/RHEEM	0
23012	09/19/2017	G91200	RUUD/RHEEM	0
23013	09/25/2017	G76200	RUUD/RHEEM	0
23014	10/01/2017	PROG4038NRH62	RUUD/RHEEM	0
23015	09/30/2017	PROG5038NRH60	RUUD/RHEEM	0
23016	09/25/2017	G82156	RUUD/RHEEM	0
23017	09/29/2017	PROG40S38NRH62	RUUD/RHEEM	0
23018	09/26/2017	PROG5038NRH60	RUUD/RHEEM	1
23019	09/25/2017	PROG4038NRH62	RUUD/RHEEM	0
23020	09/25/2017	PROG40S38NRH62	RUUD/RHEEM	0
23021	11/09/2017	PROG4860NRH60	RUUD/RHEEM	0
23022	09/26/2017	PROG5038NRH60	RUUD/RHEEM	0
23023	09/29/2017	PROG5038NRH60	RUUD/RHEEM	0
23024	09/29/2017	PROG5038NRH60	RUUD/RHEEM	0
23025	09/27/2017	PROG5038NRH60	RUUD/RHEEM	0
23026	09/29/2017	PROG5038NRH60	RUUD/RHEEM	0
23027	09/26/2017	PROG5038NRH60	RUUD/RHEEM	0
23028	09/30/2017	PROG5036NRH60DV	RUUD/RHEEM	0
23029	10/15/2017	PROG5038NRU60	Rheem	0
23030	10/06/2017	PROG40S38NRH62	Rheem	0
23031	10/13/2017	PROG5038NRU60	Rheem	0
23032	10/13/2017	PROG4038NRH62	Rheem	0
23033	09/29/2017	PROG5036NRH60DV	RHEEM	0
23034	10/01/2017	PROG5038NRH60	RHEEM	0
23035	09/26/2017	PROG5036NRH60DV	RHEEM	0
23036	09/28/2017	PROG5036NRH60DV	RHEEM	0
23037	09/25/2017	G75125	RUUD/RHEEM	0
23038	09/27/2017	G91200	RUUD/RHEEM	0
23039	09/28/2017	G91200	RUUD/RHEEM	0
23040	10/06/2017	PROG5038NRH60	RHEEM	0
23041	10/08/2017	PROG5038NRH60	RHEEM	0
23042	10/03/2017	PROG40S38NRH62	RHEEM	0
23043	10/03/2017	PROG4038NRH62	RHEEM	0
23044	10/06/2017	PROG5038NRH60	RHEEM	0
23045	10/07/2017	PROG5036NRH60DV	RHEEM	0
23046	10/04/2017	PROG5036NRH60DV	RHEEM	0
23047	10/03/2017	PROG5038NRH60	RHEEM	0
23048	10/04/2017	PROG4038NRH62	RHEEM	0
23049	10/02/2017	PROG50S40NRH61	RHEEM	0
23050	10/07/2017	G82156	RUUD/RHEEM	1
23051	10/06/2017	PROG5038NRH60	RHEEM	0
23052	10/12/2017	PROG40S38NRH62	Rheem	0
23053	10/12/2017	PROG5038NRH60	Rheem	0
23054	10/10/2017	PROG5038NRH60	Rheem	0
23055	10/11/2017	PROG4038NRH62	Rheem	0
23056	10/10/2017	G91200	Rheem	0
23057	10/15/2017	PROG5038NRH60	Rheem	0
23058	10/14/2017	RG250H6N	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23059	10/13/2017	PROG50S40NRH61	Rheem	0
23060	10/10/2017	PROG5038NRH60	Rheem	0
23061	10/05/2017	PROG5038NRH60	RHEEM	0
23062	10/06/2017	PROG5038NRH60	RHEEM	0
23063	10/02/2017	G91200	RUUD/RHEEM	0
23064	10/02/2017	PROG5036NRH60DV	RHEEM	0
23065	10/04/2017	PROG40S38NRH62	RHEEM	0
23066	10/04/2017	PROG5038NRH60	RHEEM	0
23067	10/03/2017	RG2DV50S6N	BRADFORD WHITE	0
23068	10/05/2017	PROG5038NRH60	RHEEM	0
23069	10/08/2017	PROG5038NRH60	RHEEM	0
23070	10/03/2017	PROG5038NRH60	RHEEM	0
23071	10/07/2017	PROG5038NRH60	RHEEM	0
23072	10/05/2017	PROG5036NRH60DV	RHEEM	0
23073	10/02/2017	PROG5038NRH60	RHEEM	0
23074	10/02/2017	PROG4038NRH62	RHEEM	0
23075	10/02/2017	PROG5038NRH60	RHEEM	0
23076	10/04/2017	PROG4038NRH62	RHEEM	0
23077	10/06/2017	PROG5038NRH60	RHEEM	0
23078	09/27/2017	RG2DV40S6N	BRADFORD WHITE	0
23079	10/11/2017	PROG5036NRH60DV	Rheem	0
23080	10/14/2017	PROG5038NRH60	Rheem	0
23081	10/10/2017	PROG50S40NRH61	Rheem	0
23082	10/14/2017	PROG5038NRH60	Rheem	0
23083	10/10/2017	PROG5038NRH60	Rheem	0
23084	10/11/2017	PROG5038NRH60	Rheem	0
23085	10/12/2017	PROG5038NRH60	Rheem	0
23086	10/09/2017	PROG5038NRH60	Rheem	0
23087	10/14/2017	G91200	Rheem	0
23088	10/13/2017	PROG4038NRH62	Rheem	0
23089	10/13/2017	PROG5036NRH60	RHEEM	0
23090	10/11/2017	PROG40S38NRH62	RHEEM	0
23091	10/12/2017	G91200	RHEEM	0
23092	10/12/2017	G91200	RHEEM	0
23093	10/14/2017	G75125	Rheem	0
23094	10/14/2017	PROG5038NRH60	Rheem	0
23095	10/22/2017	PROG5038NRH60	RHEEM	0
23096	10/17/2017	PROG4038NRH62	RHEEM	0
23097	10/18/2017	PROG5038NRH60	RHEEM	0
23098	10/20/2017	PROG50S40NRH61	RHEEM	0
23099	10/17/2017	PROG5036NRH60DV	RHEEM	0
23100	10/11/2017	PROG40S38NRH62	RHEEM	0
23101	10/11/2017	PROG40S38NRH62	RHEEM	0
23102	10/12/2017	PROG50S40NRH61	RHEEM	0
23103	10/04/2017	PROG5038NRH60	RHEEM	0
23104	10/20/2017	PROG50S40NRH61	RHEEM	0
23105	10/18/2017	PROG5038NRH60	RHEEM	0
23106	10/18/2017	PROG5036NRH60	RHEEM	0
23107	10/16/2017	PROG5038NRH60	Rheem	0
23108	10/23/2017	PROG5038NRH60	Rheem	0
23109	10/27/2017	PROG5038NRH60	Rheem	0
23110	10/24/2017	PROG5038NRH60	Rheem	0
23111	10/19/2017	RG2DV40S6N	Bradford White	0
23112	10/27/2017	RG2DV40S6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23113	10/20/2017	PROG40S38NRH62	Rheem	0
23114	10/17/2017	PROG5038NRH60	RHEEM	0
23115	10/16/2017	PROG5038NRH60	RHEEM	0
23116	10/21/2017	PROG4038NRH62	RHEEM	0
23117	10/17/2017	PROG5038NRH60	RHEEM	0
23118	10/20/2017	PROG5038NRH60	RHEEM	0
23119	10/19/2017	PROG5038NRH60	RHEEM	0
23120	10/30/2017	PROG4038NRH62	RHEEM	0
23121	11/05/2017	PROG5038NRH60	RHEEM	0
23122	10/25/2017	G82156	RHEEM	1
23123	10/25/2017	G82156	RHEEM	0
23124	10/25/2017	PROG5038NRH60	RHEEM	0
23125	10/25/2017	PROG5038NRH60	RHEEM	0
23126	10/28/2017	PROG4038NRH62	RHEEM	0
23127	10/26/2017	PROG40S38NRH62	RHEEM	0
23128	10/28/2017	PROG5038NRH60	RHEEM	0
23129	10/23/2017	PROG5038NRH60	RHEEM	0
23130	10/26/2017	PROG4038NRH62	RHEEM	0
23131	10/27/2017	PROG50S40NRH61	RHEEM	0
23132	10/23/2017	PROG5038NRH60	RHEEM	0
23133	10/28/2017	PROG5038NRH60	RHEEM	1
23134	10/24/2017	PROG5038NRH60	RHEEM	0
23135	10/27/2017	PROG5036NRH60	RHEEM	0
23136	10/28/2017	RG2DV50S6N	BRADFORD WHITE	1
23137	10/23/2017	RG2DV40S6N	BRADFORD WHITE	0
23138	10/19/2017	PROG4038NRH62	RHEEM	0
23139	10/25/2017	PROG4038NRH62	RHEEM	0
23140	10/23/2017	PROG5038NRH60	RHEEM	1
23141	10/27/2017	PROG4038NRH62	RHEEM	0
23142	10/26/2017	PROG5038NRH60	RHEEM	0
23143	11/05/2017	RG2DV50S6N	Bradford White	0
23144	11/02/2017	PROG5038NRH60	Rheem	0
23145	10/30/2017	PROG5038NRH60	Rheem	0
23146	11/03/2017	PROG5038NRH60	RHEEM	0
23147	11/05/2017	PROG5038NRH60	Rheem	0
23148	11/18/2017	PROG5038NRH60	Rheem	0
23149	11/19/2017	PROG5038NRH60	Rheem	0
23150	11/16/2017	PROG50S40NRH61	Rheem	0
23151	11/16/2017	PROG5038NRH60	Rheem	0
23152	11/16/2017	PROG5038NRH60	Rheem	0
23153	11/17/2017	PROG5038NRH60	Rheem	0
23154	11/19/2017	PROG5038NRH60	Rheem	0
23155	10/30/2017	PROG5038NRH60	RHEEM	1
23156	11/01/2017	PROG5038NRH60	RHEEM	0
23157	11/01/2017	PROG4038NRH62	RHEEM	0
23158	10/31/2017	PROG4038NRH62	RHEEM	0
23159	11/02/2017	PROG5038NRH60	RHEEM	0
23160	10/30/2017	PROG4038NRH62	RHEEM	0
23161	11/04/2017	PROG5038NRH60	RHEEM	0
23162	11/02/2017	G82156	RHEEM	0
23163	11/02/2017	G91200	RHEEM	0
23164	11/07/2017	PROG4038NRH62	RHEEM	0
23165	11/12/2017	PROG5036NRH60	RHEEM	0
23166	11/09/2017	PROG4038NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23167	11/09/2017	PROG4038NRH62	RHEEM	0
23168	11/09/2017	PROG5036NRH60	RHEEM	0
23169	11/11/2017	RG2DV50S6N	BRADFORD WHITE	0
23170	11/11/2017	PROG4038NRH62	RHEEM	0
23171	11/14/2017	PROG5036NRH60	RHEEM	0
23172	11/15/2017	PROG5038NRH60	RHEEM	0
23173	11/19/2017	PROG5038NRH60	RHEEM	0
23174	11/18/2017	PROG5038NRH60	RHEEM	0
23175	11/15/2017	PROG4038NRH62	RHEEM	0
23176	11/15/2017	PROG5038NRH60	RHEEM	0
23177	11/17/2017	PROG5036NRH60	RHEEM	0
23178	11/17/2017	RG2DV50S6N	BRADFORD WHITE	0
23179	11/14/2017	PROG5038NRH60	RHEEM	0
23180	11/14/2017	G91200	RHEEM	0
23181	11/13/2017	PROG4038NRH62	RHEEM	0
23182	11/04/2017	PROG4038NRH62	Rheem	0
23183	11/03/2017	PROG5038NRH60	Rheem	1
23184	10/31/2017	RG250H6N	Bradford White	1
23185	10/31/2017	PROG5038NRH60	Rheem	0
23186	10/30/2017	PROG40S38NRH62	Rheem	0
23187	11/03/2017	PROG5038NRH60	Rheem	0
23188	11/02/2017	PROG5038NRH60	Rheem	0
23189	11/01/2017	PROG5038NRH60	Rheem	0
23190	11/06/2017	PROG5038NRH60	RHEEM	0
23191	11/06/2017	PROG5038NRH60	RHEEM	0
23192	11/12/2017	PROG5038NRH60	Rheem	0
23193	11/06/2017	PROG5038NRH60	Rheem	0
23194	11/11/2017	PROG5038NRH60	Rheem	0
23195	11/08/2017	PROG40S38NRH62	Rheem	0
23196	11/07/2017	PROG5038NRH60	Rheem	0
23197	11/08/2017	PROG5038NRH60	Rheem	0
23198	11/07/2017	PROG50S40NRH61	Rheem	0
23199	11/12/2017	PROG5038NRH60	Rheem	0
23200	11/08/2017	PROG5038NRH60	Rheem	0
23201	11/12/2017	G75125	Rheem	0
23202	11/06/2017	PROG5038NRH60	Rheem	0
23203	11/11/2017	PROG5038NRH60	Rheem	0
23204	11/10/2017	PROG40S38NRH62	Rheem	0
23205	11/06/2017	FSG50	AO SMITH	0
23206	11/09/2017	PROG5038NRH60	Rheem	0
23207	11/09/2017	PROG5038NRH60	Rheem	0
23208	11/10/2017	PROG5038NRH60	Rheem	0
23209	11/08/2017	PROG5038NRH60	Rheem	0
23210	11/11/2017	RG2DV50S6N	Bradford White	0
23211	10/31/2017	G76200	Rheem	0
23212	11/06/2017	PROG5038NRH60	Rheem	0
23213	11/14/2017	PROG5038NRH60	Rheem	0
23214	11/13/2017	PROG5038NRH60	Rheem	0
23215	11/15/2017	RG2DV50S6N	Bradford White	0
23216	11/18/2017	PROG5038NRH60	Rheem	0
23217	11/16/2017	PROG5038NRH60	Rheem	0
23218	11/14/2017	PROG5038NRH60	Rheem	0
23219	11/16/2017	PROG5038NRH60	Rheem	0
23220	11/19/2017	PROG50S40NRH61	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23221	11/13/2017	RG2DV50S6N	Bradford White	0
23222	11/13/2017	PROG5036NRH60DV	Rheem	0
23223	11/19/2017	PROG5038NRH60	Rheem	0
23224	11/13/2017	PROG5038NRH60	Rheem	1
23225	11/14/2017	PROG5038NRH60	Rheem	0
23226	11/29/2017	PROG5038NRH60	RHEEM	0
23227	12/02/2017	PROG5038NRH60	RHEEM	0
23228	11/28/2017	PROG5038NRH60	RHEEM	0
23229	12/02/2017	PROG5038NRH60	RHEEM	0
23230	12/02/2017	RG2DV50S6N	BRADFORD WHITE	0
23231	12/01/2017	PROG5038NRH60	RHEEM	0
23232	11/27/2017	PROG5038NRH60	RHEEM	0
23233	12/02/2017	PROG5038NRH60	RHEEM	0
23234	11/29/2017	PROG40S38NRH62	RHEEM	0
23235	11/29/2017	PROG4038NRH62	RHEEM	0
23236	11/29/2017	PROG50S40NRH61	RHEEM	0
23237	12/02/2017	PROG5038NRH60	RHEEM	0
23238	12/03/2017	PROG4038NRH62	RHEEM	0
23239	12/01/2017	PROG5038NRH60	RHEEM	0
23240	11/17/2017	PROG5036NRH60	RHEEM	0
23241	12/01/2017	G91200	RHEEM	0
23242	12/03/2017	PROG4860NRH60	RHEEM	0
23243	11/13/2017	PROG40S38NRH62	RHEEM	0
23244	11/17/2017	PROG50S40NRH61	RHEEM	1
23245	11/18/2017	PROG5038NRH60	RHEEM	0
23246	11/21/2017	PROG4860NRH60	RHEEM	0
23247	11/26/2017	PROG4038NRH62	RHEEM	0
23248	11/26/2017	PROG5038NRH60	RHEEM	0
23249	11/24/2017	G82156	RHEEM	0
23250	11/22/2017	RG140T6N	BRADFORD WHITE	0
23251	11/21/2017	PH19980	PHOENIX	0
23252	11/21/2017	PH19980	PHOENIX	2
23253	11/24/2017	PROG5038NRH60	RHEEM	0
23254	11/21/2017	PROG5038NRH60	RHEEM	0
23255	11/26/2017	PROG5038NRH60	RHEEM	0
23256	11/22/2017	PROG50S40NRH61	RHEEM	0
23257	11/09/2017	PROG5036NRH60	RHEEM	0
23258	11/20/2017	PROG5038NRH60	RHEEM	0
23259	11/20/2017	RG250H6N	BRADFORD WHITE	0
23260	11/20/2017	PROG5038NRH60	RHEEM	0
23261	11/22/2017	PROG5038NRH60	RHEEM	0
23262	11/25/2017	PROG5038NRH60	RHEEM	0
23263	11/20/2017	PROG5038NRH60	RHEEM	1
23264	11/22/2017	PROG4038NRH62	RHEEM	0
23265	11/20/2017	PROG4038NRH62	RHEEM	0
23266	11/20/2017	PROG40S38NRH62	RHEEM	1
23267	11/21/2017	PROG5038NRH60	RHEEM	0
23268	11/27/2017	RG140T6N	BRADFORD WHITE	0
23269	11/30/2017	RG2DV50S6N	BRADFORD WHITE	0
23270	12/03/2017	PROG4038NRH62	RHEEM	0
23271	12/01/2017	RG2DV40S6N	BRADFORD WHITE	0
23272	11/29/2017	PROG5036NRH60	RHEEM	0
23273	11/28/2017	PROG40S38NRH62	RHEEM	0
23274	11/27/2017	PROG50S40NRH61	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23275	11/29/2017	PROG5038NRH60	RHEEM	0
23276	12/01/2017	PROG5038NRH60	RHEEM	0
23277	11/30/2017	PROG4038NRH62	RHEEM	0
23278	11/30/2017	PROG5036NRH60	RHEEM	0
23279	12/03/2017	PROG5038NRH60	RHEEM	0
23280	12/01/2017	PROG5038NRH60	RHEEM	0
23281	12/07/2017	PROG5038NRH60	RHEEM	0
23282	12/07/2017	PROG5038NRH60	RHEEM	0
23283	12/10/2017	PROG5036NRH60	RHEEM	0
23284	12/08/2017	PROG5038NRH60	RHEEM	0
23285	12/06/2017	PROG5038NRH60	RHEEM	0
23286	12/06/2017	PROG4038NRH62	RHEEM	0
23287	12/07/2017	PROG5038NRH60	RHEEM	0
23288	12/04/2017	RG2DV50S6N	BRADFORD WHITE	0
23289	12/08/2017	PROG4038NRH62	RHEEM	0
23290	12/06/2017	PROG5038NRH60	RHEEM	0
23291	12/05/2017	RG250H6N	BRADFORD WHITE	0
23292	11/30/2017	PROG5038NRH60	RHEEM	0
23293	12/10/2017	PROG5038NRH60	RHEEM	0
23294	12/04/2017	PROG5038NRH60	RHEEM	0
23295	12/08/2017	PROG5038NRH60	RHEEM	0
23296	12/05/2017	PROG50S40NRH61	RHEEM	0
23297	12/05/2017	RG2DV50S6N	BRADFORD WHITE	0
23298	11/17/2017	PROG5038NRH60	RHEEM	0
23299	11/22/2017	PROG5038NRH60	RHEEM	0
23300	11/21/2017	PROG5038NRH60	RHEEM	0
23301	11/22/2017	G91200	RHEEM	0
23302	11/21/2017	PROG50S40NRH61	RHEEM	0
23303	12/10/2017	G91200	RHEEM	0
23304	12/09/2017	PROG5038NRH60	RHEEM	1
23305	10/17/2017	PROG50S40NRH61	RHEEM	1
23306	12/17/2017	PROG4038NRH62	RHEEM	0
23307	12/12/2017	PROG5038NRH60	RHEEM	0
23308	12/13/2017	PROG5038NRH60	RHEEM	0
23309	12/16/2017	PROG5038NRH60	RHEEM	0
23310	12/17/2017	PROG5038NRH60	RHEEM	0
23311	12/17/2017	PROG40S38NRH62	RHEEM	0
23312	12/12/2017	PROG4038NRH62	RHEEM	0
23313	12/13/2017	PROG5038NRH60	RHEEM	0
23314	12/13/2017	PROG5038NRH60	RHEEM	0
23315	12/14/2017	PROG5038NRH60	RHEEM	0
23316	12/15/2017	PROG40S38NRH62	RHEEM	0
23317	12/15/2017	PROG5038NRH60	RHEEM	0
23318	12/15/2017	PROG5038NRH60	RHEEM	0
23319	12/15/2017	PROG5038NRH60	RHEEM	0
23320	12/17/2017	G75125	RHEEM	0
23321	12/09/2017	PROG4038NRH62	RHEEM	0
23322	12/12/2017	PROG4038NRH62	RHEEM	0
23323	12/12/2017	RG2DV50S6N	BRADFORD WHITE	0
23324	12/19/2017	PROG5038NRH60	RHEEM	0
23325	12/13/2017	PROG5036NRH60	RHEEM	0
23326	12/15/2017	G75125	RHEEM	0
23327	12/12/2017	PROG50S40NRH61	RHEEM	0
23328	12/12/2017	PROG40S38NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23329	12/13/2017	PROG5036NRH60	RHEEM	0
23330	12/14/2017	RG140T6N	Bradford White	0
23331	12/21/2017	PROG5038NRH60	Rheem	0
23332	12/23/2017	PROG4038NRH62	RHEEM	1
23333	12/31/2017	PROG5038NRH60	Rheem	0
23334	12/27/2017	PROG5038NRH60	Rheem	0
23335	12/26/2017	PROG5038NRH60	Rheem	0
23336	12/30/2017	PROG4038NRH62	Rheem	0
23337	12/31/2017	PROG5038NRH60	Rheem	0
23338	12/31/2017	PROG4038NRH62	Rheem	0
23339	12/28/2017	PROG4038NRH62	RHEEM	0
23340	12/26/2017	PROG4038NRH62	RHEEM	0
23341	12/28/2017	G82156	RHEEM	0
23342	12/28/2017	PROG5038NRH60	RHEEM	0
23343	12/29/2017	PROG5038NRH60	RHEEM	0
23344	12/30/2017	PROG5038NRH60	RHEEM	0
23345	12/20/2017	PROG5038NRH60	Rheem	0
23346	12/22/2017	PROG5038NRH60	RUUD/RHEEM	0
23347	12/22/2017	PROG5038NRH60	Rheem	0
23348	12/23/2017	PROG50S40NRH61	Rheem	0
23349	12/24/2017	PROG5038NRH60	Rheem	0
23350	12/18/2017	PROG5038NRH60	Rheem	0
23351	12/22/2017	PROG5036NRH60DV	RHEEM	0
23352	12/22/2017	PROG5038NRH60	Rheem	0
23353	12/22/2017	PROG5038NRH60	Rheem	0
23354	12/20/2017	PROG5038NRH60	Rheem	1
23355	12/21/2017	RG2DV50S6N	Bradford White	0
23356	12/23/2017	PROG5036NRH60DV	Rheem	0
23357	12/19/2017	G75125	RHEEM	0
23358	12/21/2017	PROG5038NRH60	RHEEM	0
23359	12/23/2017	PROG5038NRH60	RHEEM	0
23360	12/20/2017	PROG4038NRH62	RHEEM	0
23361	11/25/2017	G82156	RHEEM	1
23362	12/29/2017	PROG50S40NRH61	Rheem	0
23363	12/28/2017	G82156	RHEEM	0
23364	12/29/2017	PROG5038NRH60	RHEEM	0
23365	01/04/2018	PROG5038NRH60	Rheem	0
23366	01/04/2018	RG250H6N	Bradford White	0
23367	01/03/2018	G75125	RHEEM	0
23368	01/10/2018	G91200	RHEEM	0
23369	01/12/2018	PROG4038NRH62	RHEEM	0
23370	01/12/2018	PROG5038NRH60	RHEEM	0
23371	01/19/2018	PROG5038NRH60	RHEEM	0
23372	01/08/2018	PROG5038NRH60	RHEEM	0
23373	01/12/2018	RG2DV50S6N	BRADFORD WHITE	0
23374	01/10/2018	PROG5038NRH60	RHEEM	0
23375	01/10/2018	PROG5036NRH60	RHEEM	0
23376	01/09/2018	PROG5038NRH60	RHEEM	0
23377	01/10/2018	PROG5038NRH60	RHEEM	0
23378	01/12/2018	PROG5038NRH60	RHEEM	0
23379	01/09/2018	PROG5038NRH60	RHEEM	0
23380	01/09/2018	PROG5038NRH60	Rheem	0
23381	01/08/2018	RG250H6N	Bradford White	0
23382	12/27/2017	G75125	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23383	12/26/2017	PROG4038NRH62	RHEEM	0
23384	01/03/2018	PROG5038NRH60	RHEEM	0
23385	01/04/2018	PROG5038NRH60	RHEEM	0
23386	01/02/2018	PROG5038NRH60	RHEEM	0
23387	01/04/2018	PROG5038NRH60	RHEEM	0
23388	01/03/2018	PROG4038NRH62	RHEEM	0
23389	01/02/2018	G82156	RHEEM	0
23390	01/05/2018	G91200	RHEEM	0
23391	01/06/2018	PROG5038NRH60	RHEEM	0
23392	01/05/2018	PROG5038NRH60	RHEEM	0
23393	01/03/2018	PROG5038NRH60	RHEEM	0
23394	01/07/2018	PROG4038NRH62	RHEEM	0
23395	01/06/2018	PROG5038NRH60	RHEEM	0
23396	01/05/2018	PROG5038NRH60	RHEEM	0
23397	01/25/1993	FSG50	AO SMITH	1
23398	01/09/2018	PROG5038NRH60	Rheem	0
23399	01/12/2018	PROG5038NRH60	Rheem	0
23400	01/12/2018	PROG5038NRH60	Rheem	0
23401	01/13/2018	PROG40S38NRH62	Rheem	0
23402	01/13/2018	RG2DV50S6N	Bradford White	0
23403	01/13/2018	PROG5038NRH60	Rheem	0
23404	08/30/2016	G91200	RUUD/RHEEM	0
23405	08/05/2017	PROG5038NRH60	RHEEM	0
23406	10/12/2017	G91200	RHEEM	0
23407	10/09/2017	PROG4038NRH62	RHEEM	0
23408	10/24/2017	PROG5038NRH60	Rheem	0
23409	01/03/2018	RG250H6N	Bradford White	0
23410	01/03/2018	PROG5038NRH60	Rheem	0
23411	01/08/2018	G91200	RHEEM	0
23412	11/29/2017	PROG5036NRH60	RHEEM	0
23413	01/13/2018	PROG5038NRH60	RHEEM	0
23414	01/18/2018	PROG5038NRH60	RHEEM	0
23415	01/16/2018	G75125	RHEEM	2
23416	01/16/2018	PROG30S30NRH63	RHEEM	0
23417	01/15/2018	PROG4038NRH62	RHEEM	0
23418	01/16/2018	RG2DV50S6N	BRADFORD WHITE	0
23419	12/29/2017	PROG5038NRH60	Rheem	0
23420	01/15/2018	RG2DV50S6N	Bradford White	1
23421	01/18/2018	PROG5036NRH60DV	Rheem	0
23422	01/17/2018	PROG5038NRH60	Rheem	0
23423	01/17/2018	PROG5038NRH60	Rheem	0
23424	11/08/2017	PROG5036NRH60DV	Rheem	0
23425	11/18/2017	PROG5038NRH60	Rheem	0
23426	11/15/2017	PROG4036NRH62DV	Rheem	0
23427	11/29/2017	PROG5038NRH60	Rheem	0
23428	01/13/2018	PROG4038NRH62	RHEEM	2
23429	01/09/2018	PROG4038NRH62	Rheem	0
23430	01/19/2018	PROG5038NRH60	RHEEM	1
23431	01/20/2018	PROG5036NRH60	RHEEM	0
23432	01/21/2018	PROG5038NRH60	RHEEM	0
23433	01/19/2018	PROG5038NRH60	RHEEM	0
23434	01/16/2018	PROG50S40NRH61	RHEEM	0
23435	01/16/2018	PROG5038NRH60	RHEEM	0
23436	01/15/2018	RG2DV50S6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23437	01/20/2018	PROG40S38NRH62	RHEEM	0
23438	01/17/2018	PROG5038NRH60	RHEEM	0
23439	01/17/2018	PROG5038NRH60	RHEEM	0
23440	01/19/2018	PROG5038NRH60	RHEEM	0
23441	01/10/2018	PROG4860NRH60	RHEEM	0
23442	01/12/2018	GSN03035B	Lochinvar	0
23443	01/25/2018	PROG5038NRH60	Rheem	0
23444	01/26/2018	RG2DV50S6N	Bradford White	0
23445	01/26/2018	PROG5038NRH60	Rheem	0
23446	01/26/2018	PROG5036NRH60DV	Rheem	0
23447	10/10/2017	G91200	Rheem	0
23448	01/19/2018	PROG5038NRH60	RHEEM	0
23449	01/19/2018	PROG40S38NRH62	Rheem	0
23450	01/18/2018	G91200	RHEEM	0
23451	01/18/2018	G91200	RHEEM	0
23452	01/17/2018	PROG4038NRH62	RHEEM	0
23453	01/17/2018	RG2DV50S6N	Bradford White	0
23454	12/21/2017	PROG5038NRH60	Rheem	0
23455	01/24/2018	PROG5038NRH60	RHEEM	0
23456	01/24/2018	PROG4038NRH62	RHEEM	0
23457	01/22/2018	PROG5036NRH60	RHEEM	0
23458	01/24/2018	PROG4860NRH60	RHEEM	0
23459	01/27/2018	PROG5038NRH60	RHEEM	0
23460	01/22/2018	G76200	RUUD/RHEEM	0
23461	01/31/2018	PROG50S40NRH61	Rheem	0
23462	01/29/2018	RG2DV50S6N	Bradford White	0
23463	01/30/2018	PROG4038NRH62	Rheem	0
23464	01/30/2018	PROG4038NRH62	Rheem	0
23465	02/01/2018	PROG5038NRH60	Rheem	0
23466	02/03/2018	PROG5038NRH60	Rheem	0
23467	01/27/2018	PROG5038NRH60	Rheem	0
23468	11/21/2017	PH19980	PHOENIX	0
23469	12/23/2017	G91200	RHEEM	0
23470	02/05/2018	PROG5038NRH60	RHEEM	0
23471	01/29/2018	PROG5038NRH60	RHEEM	0
23472	01/29/2018	PROG5038NRH60	RHEEM	0
23473	01/30/2018	PROG5038NRH60	RHEEM	0
23474	01/30/2018	PROG5038NRH60	RHEEM	0
23475	01/31/2018	PROG5038nrh60	RHEEM	0
23476	02/01/2018	PROG5038NRH60	RHEEM	0
23477	01/30/2018	PROG5038NRH60	RHEEM	0
23478	01/31/2018	PROG5038NRH60	RHEEM	0
23479	01/29/2018	PROG5038NRH60	RHEEM	0
23480	01/31/2018	PROG5038NRH60	RHEEM	0
23481	02/02/2018	PROG5038NRH60	RHEEM	0
23482	02/04/2018	RG2DV50S6N	BRADFORD WHITE	0
23483	02/04/2018	PROG5038NRH60	RHEEM	0
23484	02/02/2018	PROG5038NRH60	RHEEM	0
23485	02/01/2018	PROG5038NRH60	RHEEM	0
23486	02/02/2018	PROG5038NRH60	Rheem	0
23487	02/03/2018	G76200	RHEEM	0
23488	02/02/2018	PROG5038NRH60	RHEEM	0
23489	02/09/2018	PROG40S38NRH62	RHEEM	0
23490	01/25/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23491	01/27/2018	PROG5038NRH60	RHEEM	0
23492	01/22/2018	PROG50S40NRH61	RHEEM	0
23493	01/25/2018	PROG5038NRH60	RHEEM	0
23494	01/26/2018	PROG5038NRH60	RHEEM	0
23495	02/07/2018	PROG5036NRU60	RHEEM	0
23496	02/07/2018	RG2DV40S6N	BRADFORD WHITE	0
23497	02/07/2018	PROG5038NRH60	RHEEM	0
23498	02/06/2018	PROG50S40NRH61	RHEEM	0
23499	02/09/2018	RG2DV50S6N	BRADFORD WHITE	0
23500	02/04/2018	PROG50S40NRH61	RHEEM	0
23501	02/08/2018	PROG4038NRH62	RHEEM	0
23502	02/05/2018	PROG2932NRH63	RHEEM	0
23503	02/05/2018	PROG5036NRH60	RHEEM	0
23504	02/05/2018	PROG4860NRH60	RHEEM	0
23505	02/07/2018	PROG5038NRH60	RHEEM	0
23506	02/07/2018	PH199119	PHOENIX	0
23507	02/07/2018	PROG7576NRU	Rheem	0
23508	02/06/2018	PROG5038NRH60	Rheem	0
23509	02/07/2018	PROG5036NRH60DV	RHEEM	0
23510	02/06/2018	PROG5036NRH60DV	Rheem	0
23511	02/06/2018	PROG5038NRH60	Rheem	0
23512	02/08/2018	PROG5038NRH60	Rheem	0
23513	02/07/2018	PROG5038NRH60	Rheem	0
23514	02/06/2018	RG2DV50S6N	Bradford White	0
23515	11/04/1982	PRV40	State	0
23516	02/14/2018	PROG40S38NRH62	RHEEM	0
23517	02/16/2018	PROG5038NRH60	RHEEM	0
23518	02/16/2018	PROG5038NRH60	RHEEM	0
23519	02/16/2018	PROG5036NRH60	RHEEM	0
23520	02/12/2018	PROG5038NRH60	RHEEM	1
23521	02/13/2018	PROG5038NRH60	RHEEM	0
23522	02/17/2018	PROG5036NRH60	RHEEM	0
23523	02/13/2018	PROG5038NRH60	RHEEM	0
23524	02/13/2018	PROG40S38NRH62	RHEEM	0
23525	02/13/2018	PROG50S40NRH61	RHEEM	0
23526	02/15/2018	PROG5038NRH60	RHEEM	0
23527	02/17/2018	PROG5038NRH60	RHEEM	0
23528	02/13/2018	PROG5038NRH60	RHEEM	0
23529	02/16/2018	PROG5038NRH60	RHEEM	0
23530	02/14/2018	PROG50S40NRH61	RHEEM	0
23531	02/08/2018	PROG5038NRH60	RHEEM	0
23532	02/07/2018	PROG5038NRH60	RHEEM	0
23533	02/09/2018	PROG5036NRH60	RHEEM	0
23534	02/08/2018	G91200	RHEEM	1
23535	02/12/2018	PROG40S38NRH62	Rheem	0
23536	02/14/2018	PROG40S38NRH62	Rheem	0
23537	02/13/2018	PROG5038NRH60	Rheem	0
23538	02/20/2018	G91200	Rheem	3
23539	02/17/2018	PROG5038NRH60	Rheem	0
23540	02/12/2018	RG2DV50S6N	Bradford White	0
23541	02/12/2018	PH199119	PHOENIX	0
23542	02/14/2018	G75125	RHEEM	0
23543	02/07/2018	PROG5038NRH60	Rheem	0
23544	02/18/2018	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23545	02/16/2018	PROG50S40NRH61	Rheem	0
23546	02/16/2018	PROG5038NRH60	Rheem	0
23547	02/18/2018	PROG5038NRH60	RHEEM	0
23548	02/17/2018	PROG30S30NRH63	Rheem	0
23549	02/25/2018	PROG5038NRH60	Rheem	0
23550	02/19/2018	PROG5038NRH60	Rheem	0
23551	02/23/2018	PROG5038NRH60	RHEEM	0
23552	02/21/2018	PROG5038NRH60	RHEEM	0
23553	02/19/2018	PROG5038NRH60	RHEEM	0
23554	02/23/2018	PROG5038NRH60	RHEEM	0
23555	02/25/2018	PROG5038NRH60	RHEEM	0
23556	02/21/2018	PROG5038NRH60	RHEEM	0
23557	02/21/2018	PROG5038NRH60	RHEEM	0
23558	02/23/2018	PROG5038NRH60	RHEEM	0
23559	02/24/2018	PROG5038NRH60	RHEEM	0
23560	03/05/2018	G91200	RUUD/RHEEM	1
23561	01/30/2018	PROG4038NRH62	Rheem	0
23562	01/31/2018	G75125	RUUD/RHEEM	0
23563	02/02/2018	PROG5038NRH60	Rheem	0
23564	02/23/2018	PROG4038NRH62	Rheem	0
23565	01/30/2018	PROG5038NRH60	RHEEM	0
23566	03/02/2018	RG2DV50S6N	Bradford White	0
23567	02/28/2018	PROG5038NRH60	Rheem	0
23568	03/01/2018	G7575	Rheem	0
23569	03/02/2018	G75125	RUUD/RHEEM	0
23570	02/26/2018	PROG5038NRH60	Rheem	0
23571	03/02/2018	G91200	Rheem	0
23572	03/03/2018	PROG40S38NRH62	Rheem	0
23573	03/01/2018	PROG5038NRH60	Rheem	0
23574	03/04/2018	PROG5036NRH60DV	Rheem	0
23575	02/28/2018	G91200	Rheem	0
23576	02/28/2018	G91200	Rheem	0
23577	03/03/2018	PROG5038NRH60	RHEEM	0
23578	02/27/2018	RG2DV50S6N	BRADFORD WHITE	0
23579	02/28/2018	PROG50S40NRH61	RHEEM	0
23580	03/03/2018	PROG5036NRH60	RHEEM	0
23581	03/01/2018	PROG4038NRH62	RHEEM	0
23582	03/01/2018	PROG5038NRH60	RHEEM	0
23583	03/03/2018	PROG5038NRH60	RHEEM	0
23584	02/26/2018	RG140T6N	BRADFORD WHITE	0
23585	03/02/2018	PROG5038NRH60	RHEEM	0
23586	03/04/2018	RG2DV50S6N	BRADFORD WHITE	0
23587	03/04/2018	PROG5038NRH60	RHEEM	1
23588	03/04/2018	PROG5038NRH60	RHEEM	0
23589	02/27/2018	RG2DV40S6N	BRADFORD WHITE	0
23590	02/26/2018	PROG5038NRH60	RHEEM	0
23591	03/01/2018	PROG5038NRH60	RHEEM	0
23592	02/19/2018	PROG5038NRH60	Rheem	0
23593	02/22/2018	PROG5036NRH60DV	Rheem	0
23594	02/26/2018	PROG5038NRH60	Rheem	0
23595	02/26/2018	PROG5036NRH60DV	Rheem	0
23596	02/21/2018	PROG5036NRH60	Rheem	0
23597	02/28/2018	PROG5036NRH60	Rheem	0
23598	02/27/2018	PROG50S40NRH61	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23599	02/26/2018	PROG5038NRH60	Rheem	0
23600	03/09/2018	G76200	RHEEM	0
23601	03/06/2018	PROG40S38NRH62	RHEEM	0
23602	03/06/2018	PROG5038NRH60	Rheem	0
23603	03/01/2018	RG2DV50S6N	BRADFORD WHITE	0
23604	03/05/2018	PROG5038NRH60	RHEEM	0
23605	03/11/2018	PROG4038NRH62	RHEEM	0
23606	03/09/2018	PROG5038NRH60	RHEEM	0
23607	03/07/2018	PROG5038NRH60	RHEEM	0
23608	03/08/2018	PROG5038NRH60	Rheem	0
23609	03/07/2018	PROG5038NRH60	RHEEM	0
23610	03/07/2018	PROG5038NRH60	Rheem	0
23611	03/06/2018	PROG5038NRH60	Rheem	0
23612	03/05/2018	PROG5038NRH60	Rheem	0
23613	03/10/2018	PROG5038NRH60	Rheem	0
23614	03/05/2018	PROG40S38NRH62	Rheem	0
23615	02/14/2018	PROG5036NRH60	Rheem	0
23616	03/14/2018	PH19980	PHOENIX	0
23617	03/13/2018	PROG5038NRH60	RHEEM	0
23618	03/06/2018	PROG5038NRH60	RHEEM	0
23619	03/07/2018	PROG40S38NRH62	RHEEM	0
23620	03/10/2018	PROG5038NRH60	RHEEM	0
23621	03/10/2018	PROG4038NRH62	RHEEM	0
23622	03/07/2018	PROG50S40NRH61	RHEEM	0
23623	03/07/2018	PROG40S38NRH62	Rheem	0
23624	03/05/2018	PROG5038NRH60	RHEEM	0
23625	03/12/2018	PROG40S38NRH62	RHEEM	0
23626	03/14/2018	PROG4038NRH62	RHEEM	0
23627	03/13/2018	RG140T6N	BRADFORD WHITE	0
23628	03/12/2018	PROG5036NRH60	RHEEM	0
23629	03/14/2018	PROG5038NRH60	RHEEM	0
23630	03/17/2018	PROG5038NRH60	RHEEM	0
23631	03/17/2018	PROG4038NRH62	RHEEM	0
23632	03/16/2018	PROG5036NRH60	RHEEM	0
23633	03/13/2018	PROG40S38NRH62	RHEEM	0
23634	03/16/2018	G91200	RHEEM	0
23635	03/15/2018	PROG5038NRH60	Rheem	0
23636	03/15/2018	PROG5038NRH60	Rheem	0
23637	03/12/2018	RG2DV40S6N	Bradford White	0
23638	03/12/2018	PROG5038NRH60	Rheem	0
23639	03/15/2018	PROG5038NRH60	Rheem	0
23640	03/14/2018	G82156	Rheem	0
23641	03/14/2018	G91200	Rheem	0
23642	03/12/2018	G100200	Rheem	0
23643	03/20/2018	G91200	RHEEM	0
23644	03/24/2018	PROG5038NRH60	RHEEM	0
23645	03/23/2018	PROG5038NRH60	RHEEM	0
23646	03/20/2018	PROG40S38NRH62	RHEEM	0
23647	03/24/2018	PROG5038NRH60	RHEEM	0
23648	03/14/2018	PROG5038NRH60	Rheem	0
23649	03/19/2018	RG2DV50S6N	BRADFORD WHITE	0
23650	03/22/2018	PROG5038NRH60	RHEEM	0
23651	03/19/2018	G82156	RHEEM	0
23652	03/21/2018	PROG50S40NRH61	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23653	03/20/2018	G75125	RHEEM	0
23654	03/25/2018	PROG5038NRH60	RHEEM	0
23655	03/25/2018	PROG5038NRH60	RHEEM	0
23656	03/06/2018	PROG50S40NRH61	Rheem	0
23657	03/11/2018	PROG5038NRH60	Rheem	0
23658	03/08/2018	PROG4038NRH62	Rheem	0
23659	03/08/2018	PROG4038NRH62	Rheem	0
23660	03/20/2018	PROG4860NRH60	RHEEM	0
23661	03/22/2018	PROG40S38NRH62	RHEEM	0
23662	03/20/2018	PROG5038NRH60	RHEEM	0
23663	03/21/2018	PROG5038NRH60	RHEEM	0
23664	03/22/2018	PROG2932NRH63	RHEEM	0
23665	03/21/2018	PROG5038NRH60	RHEEM	0
23666	03/22/2018	PROG40S38NRH62	RHEEM	0
23667	03/20/2018	PROG5036NRH60	RHEEM	0
23668	03/19/2018	PROG5038NRH60	RHEEM	0
23669	03/23/2018	PROG5038NRH60	RHEEM	1
23670	03/22/2018	PROG5038NRH60	RHEEM	0
23671	03/23/2018	PROG5038NRH60	RHEEM	0
23672	03/24/2018	PROG5038NRH60	RHEEM	0
23673	03/02/2018	PROG5038NRH60	RHEEM	0
23674	03/15/2018	PROG5038NRH60	RHEEM	0
23675	03/30/2018	PROG4860NRH60	RHEEM	0
23676		PROG5038NRH60	RHEEM	0
23677	03/31/2018	PROG50S40NRH61	RHEEM	0
23678	03/29/2018	PROG40S38NRH62	RHEEM	0
23679	03/30/2018	PROG5038NRH60	RHEEM	0
23680	03/27/2018	PROG5038NRH60	RHEEM	0
23681	03/29/2018	PROG5038NRH60	RHEEM	0
23682	03/27/2018	PROG5038NRH60	RHEEM	0
23683	03/26/2018	G100200	RHEEM	0
23684	03/31/2018	PROG5038NRH60	RHEEM	0
23685	03/29/2018	PROG5036NRH60	RHEEM	0
23686	03/30/2018	PROG5038NRH60	RHEEM	0
23687	03/31/2018	PROG5038NRH60	RHEEM	0
23688	03/29/2018	RG2DV50S6N	BRADFORD WHITE	0
23689	03/26/2018	PROG50S40NRH61	RHEEM	0
23690	02/17/2018	PROG30S30NRH63	Rheem	0
23691	02/13/2018	PROG50S40NRH61	Rheem	0
23692	02/16/2018	PROG5038NRH60	Rheem	0
23693	02/14/2018	PROG5038NRH60	Rheem	0
23694	03/31/2018	RG2DV40S6N	Bradford White	0
23695	03/30/2018	PROG5038NRH60	Rheem	0
23696	03/30/2018	PROG30S30NRH63	Rheem	0
23697	03/30/2018	PROG30S30NRH63	RHEEM	0
23698	03/30/2018	PROG5038NRH60	Rheem	0
23699	03/31/2018	PROG5036NRH60	Rheem	0
23700	03/30/2018	PROG5038NRH60	Rheem	1
23701	03/30/2018	G76200	Rheem	0
23702	03/07/2018	PROG5038NRH60	RHEEM	0
23703	03/09/2018	PROG5038NRH60	Rheem	0
23704	03/07/2018	PROG5038NRH60	Rheem	0
23705	04/11/2018	RG2DV40S6N	RHEEM	0
23706	04/09/2018	PROG50S40NRH61	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23707	04/09/2018	PH19980	Phoenix	0
23708	04/14/2018	PROG5038NRH60	Rheem	0
23709	04/15/2018	PROG5038NRH60	Rheem	0
23710	04/10/2018	PROG5036NRH60	Rheem	0
23711	04/10/2018	PROG5038NRH60	Rheem	0
23712	04/11/2018	PROG5038NRH60	RHEEM	0
23713	04/11/2018	PROG5038NRH60	Rheem	0
23714	04/12/2018	PROG5038NRH60	Rheem	0
23715	04/09/2018	PROG5038NRH60	Rheem	0
23716	04/10/2018	PROG5038NRH60	Rheem	0
23717	03/28/2018	PROG5038NRH60	Rheem	0
23718	04/06/2018	PROG5038NRH60	Rheem	0
23719	03/21/2018	PROG40S38NRH62	RHEEM	0
23720	04/02/2018	PROG5036NRH60DV	Rheem	0
23721	03/24/2018	PROG5038NRH60	RHEEM	0
23722	04/02/2018	PROG5038NRH60	Rheem	0
23723	04/03/2018	PROG5038NRH60	Rheem	0
23724	04/02/2018	PROG5038NRH60	Rheem	0
23725	04/12/2018	G91200	RHEEM	0
23726	04/10/2018	PROG5038NRH60	RHEEM	0
23727	04/12/2018	PROG50S40NRH61	RHEEM	0
23728	04/09/2018	PROG5038NRH60	RHEEM	0
23729	04/12/2018	PROG4860NRH60	RHEEM	0
23730	04/09/2018	RG2DV50S6N	BRADFORD WHITE	0
23731	04/11/2018	PROG5036NRH60	RHEEM	1
23732	04/05/2018	PROG5038NRH60	RHEEM	0
23733	04/12/2018	PROG5038NRH60	RHEEM	0
23734	04/26/2017	RG250L6N	Bradford White	1
23735	04/03/2018	PROG4038NRH62	RHEEM	0
23736	04/03/2018	PROG5038NRH60	RHEEM	0
23737	04/05/2018	PROG5038NRH60	RHEEM	0
23738	04/03/2018	PROG40S38NRH62	RHEEM	0
23739	04/08/2018	PROG5038NRH60	RHEEM	0
23740	04/03/2018	PROG5038NRH60	RHEEM	0
23741	04/04/2018	PROG5038NRH60	RHEEM	0
23742	04/04/2018	PROG5038NRH60	RHEEM	0
23743	04/03/2018	G82156	RHEEM	0
23744	04/03/2018	G82156	RHEEM	0
23745	04/02/2018	PROG5038NRH60	Rheem	0
23746	04/02/2018	PROG5038NRH60	Rheem	0
23747	04/04/2018	PROG4038NRH62	Rheem	0
23748	04/05/2018	PROG5038NRH60	Rheem	0
23749	04/05/2018	PROG4038NRH62	RHEEM	0
23750	04/15/2018	PROG5038NRH60	RHEEM	0
23751	04/10/2018	PROG5038NRH60	RHEEM	0
23752	04/10/2018	G91200	RHEEM	1
23753	04/12/2018	G75125	RHEEM	0
23754	04/03/2018	G91200	RHEEM	0
23755	04/06/2018	PROG5038NRH60	RHEEM	0
23756	04/02/2018	PROG4038NRH62	RHEEM	0
23757	04/02/2018	PROG4038NRH62	RHEEM	0
23758	04/04/2018	PROG5038NRH60	RHEEM	0
23759	04/03/2018	PROG5038NRH60	RHEEM	0
23760	04/11/2018	G82156	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23761	03/21/2018	PROG5036NRH60	RHEEM	0
23762	04/06/2018	PROG40S38NRH62	RHEEM	0
23763	05/01/2018	G76200	Rheem	1
23764	03/05/2018	PROG4038NRH62	Rheem	0
23765	04/07/2018	G75125	RUUD/RHEEM	0
23766	04/14/2018	GSN040	LOCHINVAR	0
23767	04/19/2018	PROG4038NRH62	RHEEM	0
23768	04/17/2018	PROG4860NRH60	RHEEM	0
23769	04/22/2018	PROG5038NRH60	RHEEM	0
23770	04/17/2018	RG2DV40S6N	BRADFORD WHITE	1
23771	04/19/2018	PROG5038NRH60	RHEEM	0
23772	04/17/2018	PROG5038NRH60	RHEEM	0
23773	04/17/2018	PROG50S40NRH61	RHEEM	0
23774	04/18/2018	PROG5038NRH60	Rheem	0
23775	03/08/2018	PROG5036NRH60	RHEEM	0
23776	03/11/2018	PROG5038NRH60	RHEEM	0
23777	04/16/2018	PROG5038NRH60	Rheem	0
23778	04/18/2018	PROG5038NRH60	Rheem	0
23779	04/19/2018	PROG5038NRH60	Rheem	0
23780	04/18/2018	PH199119	PHOENIX	1
23781	04/17/2018	PROG30S30NRH63	Rheem	0
23782	04/20/2018	G82156	Rheem	0
23783	04/19/2018	PROG5038NRH60	Rheem	0
23784	04/16/2018	G91200	Rheem	0
23785	04/18/2018	PROG5038NRH60	Rheem	0
23786	04/29/2018	PROG5038NRH60	RHEEM	0
23787	04/29/2018	PROG5038NRH60	RHEEM	0
23788	04/24/2018	PROG5038NRH60	RHEEM	0
23789	04/26/2018	G91200	RHEEM	0
23790	04/27/2018	PROG4038NRH62	RHEEM	0
23791	04/29/2018	G91200	Rheem	0
23792	04/26/2018	PROG5038NRH60	RHEEM	3
23793	05/05/2018	PROG5038NRH60	Rheem	0
23794	05/04/2018	PROG5038NRH60	Rheem	0
23795	05/06/2018	RG2DV50S6N	Bradford White	0
23796	04/23/2018	PROG5036NRH60	RHEEM	0
23797	04/23/2018	PROG5038NRH60	RHEEM	0
23798	04/23/2018	PROG5038NRH60	RHEEM	0
23799	04/29/2018	PROG5038NRH60	RHEEM	0
23800	04/28/2018	PROG40S38NRH62	RHEEM	0
23801	04/28/2018	PROG40S38NRH62	RHEEM	0
23802	04/26/2018	PROG50S40NRH61	RHEEM	0
23803	04/27/2018	PROG40S38NRH62	RHEEM	0
23804	04/23/2018	PROG5036NRH60	RHEEM	0
23805	04/20/2018	PROG5038NRH60	RHEEM	0
23806	04/18/2018	PROG5036NRH60	RHEEM	0
23807	04/17/2018	PROG5038NRH60	RHEEM	0
23808	04/18/2018	RG2DV40S6N	BRADFORD WHITE	0
23809	04/18/2018	RG2DV40S6N	BRADFORD WHITE	0
23810	05/06/2018	G91200	RHEEM	0
23811	05/02/2018	PROG5036NRH60	RHEEM	0
23812	05/01/2018	PROG5038NRH60	RHEEM	0
23813	04/30/2018	PROG5038NRH60	RHEEM	0
23814	04/30/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23815	05/01/2018	PROG5038NRH60	RHEEM	0
23816	03/28/2018	PROG5038NRH60	RHEEM	0
23817	05/01/2018	PROG5036NRH60	RHEEM	0
23818	04/30/2018	PROG40S38NRH62	RHEEM	0
23819	03/01/2018	RG2DV40S6N	Rheem	0
23820	04/26/2018	PROG5038NRH60	Rheem	0
23821	04/29/2018	PROG5038NRH60	RHEEM	0
23822	04/25/2018	PROG5038NRH60	Rheem	0
23823	04/23/2018	GSN040	Lochinvar	0
23824	04/23/2018	PROG4038NRH62	Rheem	0
23825	04/28/2018	PROG5038NRH60	Rheem	0
23826	04/27/2018	PROG4860NRH60	Rheem	0
23827	04/29/2018	PROG5038NRH60	Rheem	0
23828	04/28/2018	PROG4038NRH62	Rheem	0
23829	05/02/2018	G75125	RHEEM	0
23830	05/01/2018	PH19980	PHOENIX	1
23831	05/04/2018	PROG5038NRH60	Rheem	0
23832	05/01/2018	PROG5038NRH60	Rheems	0
23833	05/04/2018	PROG4038NRH62	Rheem	0
23834	04/30/2018	PROG5038NRH60	Rheem	0
23835	05/04/2018	PROG5038NRH60	Rheem	0
23836	05/11/2018	RG2DV50S6N	Bradford White	0
23837	05/12/2018	PROG40S38NRH62	Rheem	0
23838	05/08/2018	PROG5036NRH60DV	Rheem	0
23839	05/08/2018	PROG5038NRH60	Rheem	0
23840	05/12/2018	PROG5036NRH60DV	Rheem	0
23841	05/13/2018	PROG5038NRH60	Rheem	0
23842	05/13/2018	PROG5038NRH60	RHEEM	0
23843	05/09/2018	PROG5038NRH60	RHEEM	0
23844	05/09/2018	PROG5038NRH60	RHEEM	0
23845	05/07/2018	PROG5038NRH60	RHEEM	0
23846	05/07/2018	PROG7576NRU	RHEEM	0
23847	05/11/2018	PROG4038NRH62	RHEEM	0
23848	05/13/2018	PROG5038NRH60	RHEEM	0
23849	05/08/2018	PROG5036NRH60DV	RHEEM	0
23850	05/09/2018	PROG5038NRH60	Rheem	0
23851	05/10/2018	PROG5038NRH60	Rheem	0
23852	05/10/2018	PROG5036NRH60DV	Rheem	0
23853	05/08/2018	RG2DV50H6N	Bradford White	0
23854	05/12/2018	PROG5038NRH60	Rheem	0
23855	05/12/2018	PROG5038NRH60	Rheem	0
23856	05/10/2018	PROG5038NRH60	Rheem	0
23857	05/18/2018	PROG50S40NRH61	RHEEM	0
23858	05/16/2018	PROG5038NRH60	RHEEM	0
23859	05/14/2018	PROG5038NRH60	RHEEM	0
23860	05/19/2018	PROG5038NRH60	RHEEM	0
23861	05/16/2018	PROG5038NRH60	RHEEM	0
23862	05/20/2018	PROG5038NRH60	RHEEM	0
23863	05/16/2018	RG2DV50S6N	BRADFORD WHITE	0
23864	05/17/2018	PROG5038NRH60	RHEEM	0
23865	05/17/2018	PROG4038NRH62	RHEEM	0
23866	05/18/2018	PROG5038NRH60	RHEEM	0
23867	05/20/2018	PROG5038NRH60	RHEEM	0
23868	05/16/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23869	05/19/2018	PROG5038NRH60	RHEEM	0
23870	05/07/2018	PROG5038NRH60	Rheem	0
23871	05/18/2018	PROG5038NRH60	Rheem	0
23872	05/20/2018	PROG5038NRH60	Rheem	0
23873	05/20/2018	PROG5038NRH60	Rheem	0
23874	05/18/2018	PROG5038NRH60	Rheem	0
23875	05/17/2018	PROG4860NRH60	Rheem	0
23876	05/19/2018	G82156	Rheem	0
23877	05/14/2018	G76200	Rheem	0
23878	05/18/2018	RG2DV50S6N	Bradford White	0
23879	05/15/2018	PROG40S38NRH62	Rheem	0
23880	05/14/2018	PROG4038NRH62	Rheem	0
23881	05/15/2018	PROG40S38NRH62	RHEEM	0
23882	05/15/2018	PROG5038NRH60	Rheem	0
23883	05/16/2018	PROG5038NRH60	Rheem	0
23884	03/20/2018	PROG4038NRH62	RHEEM	0
23885	05/13/2018	RG2DV50S6N	BRADFORD WHITE	0
23886	05/12/2018	G82156	RHEEM	0
23887	05/17/2018	PROG4038NRH62	RHEEM	0
23888	05/26/2018	PROG5038NRH60	RHEEM	0
23889	05/24/2018	G76200	RHEEM	0
23890	05/27/2018	PROG5038NRH60	RHEEM	0
23891	05/23/2018	G82156	RHEEM	0
23892	05/21/2018	PROG5038NRH60	RHEEM	0
23893	05/25/2018	PROG40S38NRH62	RHEEM	0
23894	05/24/2018	PROG5038NRH60	RHEEM	0
23895	05/26/2018	PROG40S38NRH62	RHEEM	0
23896	05/23/2018	PROG5038NRH60	RHEEM	0
23897	05/22/2018	PROG5038NRH60	Rheem	0
23898	05/22/2018	PH199119	PHOENIX	0
23899	05/22/2018	PH199119	PHOENIX	0
23900	05/21/2018	PROG5038NRH60	Rheem	0
23901	05/24/2018	PROG40S38NRH62	Rheem	0
23902	05/25/2018	PROG40S38NRH62	Rheem	0
23903	05/25/2018	PROG5038NRH60	Rheem	0
23904	05/26/2018	PROG40S38NRH62	Rheem	0
23905	05/24/2018	PROG5038NRH60	Rheem	0
23906	05/25/2018	PROG5038NRH60	Rheem	0
23907	05/27/2018	PROG5038NRH60	Rheem	0
23908	05/23/2018	PROG5038NRH60	Rheem	0
23909	05/26/2018	PROG4038NRH62	Rheem	0
23910	05/21/2018	PROG4038NRH62	Rheem	0
23911	05/30/2018	G82156	Rheem	1
23912	05/29/2018	PROG5036NRH60DV	Rheem	0
23913	06/02/2018	PROG7576NRH	Rheem	0
23914	06/02/2018	PROG4038NRH62	RHEEM	0
23915	06/01/2018	PROG5038NRH60	Rheem	0
23916	05/29/2018	PROG5038NRH60	RHEEM	0
23917	05/29/2018	PROG5038NRH60	RHEEM	0
23918	06/01/2018	PH19980	PHOENIX	1
23919	05/29/2018	PROG5038NRH60	RHEEM	0
23920	05/29/2018	PROG5038NRH60	RHEEM	0
23921	05/31/2018	PROG4038NRH62	RHEEM	0
23922	06/02/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23923	06/01/2018	PROG4038NRH62	RHEEM	0
23924	06/02/2018	PROG5038NRH60	RHEEM	0
23925	06/03/2018	PROG4038NRH62	RHEEM	0
23926	06/03/2018	RG2DV50S6N	BRADFORD WHITE	0
23927	05/30/2018	G75125	RHEEM	1
23928	06/05/2018	PROG5038NRH60	RHEEM	0
23929	06/09/2018	PROG5036NRH60DV	RHEEM	0
23930	06/04/2018	RG2DV40S6N	BRADFORD WHITE	0
23931	06/08/2018	G91200	RHEEM	0
23932	06/08/2018	PROG5038NRH60	RHEEM	0
23933	06/09/2018	PROG5038NRH60	RHEEM	0
23934	06/09/2018	PROG40S38NRH62	RHEEM	0
23935	06/06/2018	PROG5038NRH60	RHEEM	0
23936	06/05/2018	PH199119	PHOENIX	0
23937	06/04/2018	PROG5038NRH60	Rheem	0
23938	06/04/2018	PROG5038NRH60	Rheem	0
23939	06/04/2018	PROG5038NRH60	Rheem	0
23940	06/04/2018	PROG5038NRH60	Rheem	1
23941	06/08/2018	PROG5038NRH60	RHEEM	0
23942	06/08/2018	PROG50S40NRH61	RHEEM	0
23943	06/06/2018	PROG5038NRH60	RHEEM	0
23944	06/05/2018	PROG5038NRH60	RHEEM	0
23945	06/10/2018	PROG5038NRH60	RHEEM	0
23946	06/10/2018	RG2DV50S6N	BRADFORD WHITE	0
23947	06/08/2018	PROG5038NRH60	RHEEM	0
23948	06/08/2018	PROG5038NRH60	RHEEM	0
23949	06/06/2018	PROG40S38NRH62	RHEEM	0
23950	06/04/2018	PROG5038NRH60	RHEEM	0
23951	06/04/2018	PROG5038NRH60	RHEEM	0
23952	06/08/2018	G75125	RHEEM	0
23953	06/08/2018	G75125	RHEEM	0
23954	06/06/2018	PROG5038NRH60	RHEEM	0
23955	05/31/2018	PROG5038NRH60	RHEEM	0
23956	06/15/2018	G82156	RHEEM	0
23957	06/11/2018	PROG5038NRH60	RHEEM	0
23958	06/13/2018	PROG5038NRH60	RHEEM	1
23959	06/13/2018	PROG4038NRH62	RHEEM	0
23960	06/11/2018	PROG5038NRH60	RHEEM	0
23961	06/12/2018	PROG5038NRH60	RHEEM	2
23962	06/17/2018	PROG5038NRH60	RHEEM	0
23963	06/12/2018	PROG5038NRH60	RHEEM	0
23964	06/15/2018	PROG5038NRH60	Rheem	0
23965	06/14/2018	PROG5036NRU60DV	Rheem	0
23966	06/17/2018	PROG5038NRH60	Rheem	0
23967	06/16/2018	G91200	Rheem	0
23968	06/16/2018	G91200	Rheem	0
23969	06/16/2018	PROG5038NRH60	Rheem	0
23970	06/15/2018	PROG5038NRH60	Rheem	0
23971	06/15/2018	RG2DV50S6N	Bradford White	0
23972	06/15/2018	PROG5036NRU60DV	Rheem	0
23973	06/12/2018	PROG7576NRH	RHEEM	0
23974	06/12/2018	G76200	RUUD/RHEEM	0
23975	06/12/2018	PROG5038NRH60	RHEEM	0
23976	06/19/2018	RG2DV50S6N	BRADFORD WHITE	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
23977	06/19/2018	PROG5036NRH60	RHEEM	0
23978	06/21/2018	PROG5038NRH60	RHEEM	0
23979	06/23/2018	RG2DV50S6N	BRADFORD WHITE	0
23980	06/21/2018	PROG5038NRH60	RHEEM	0
23981	06/20/2018	PROG5038NRH60	RHEEM	2
23982	06/22/2018	PROG4038NRH62	RHEEM	1
23983	06/23/2018	PROG5038NRH60	RHEEM	0
23984	06/24/2018	PROG5038NRH60	RHEEM	0
23985	06/23/2018	PROG7576NRH	RHEEM	0
23986	06/21/2018	PROG5036NRH60	RHEEM	0
23987	06/21/2018	PROG5038NRH60	RHEEM	0
23988	06/20/2018	PROG50S40NRH61	RHEEM	0
23989	06/18/2018	PROG40S38NRH62	RHEEM	0
23990	06/18/2018	PROG5038NRH60	RHEEM	0
23991	06/18/2018	PROG5038NRH60	RHEEM	0
23992	06/20/2018	PROG4038NRH62	RHEEM	0
23993	06/20/2018	PROG5038NRH60	RHEEM	0
23994	06/22/2018	PROG5038NRH60	RHEEM	0
23995	06/23/2018	PROG4860NRH60	RHEEM	0
23996	06/24/2018	PROG5038NRH60	RHEEM	0
23997	06/18/2018	PROG5038NRH60	RHEEM	0
23998	06/18/2018	G82156	RHEEM	0
23999	06/18/2018	G91200	RHEEM	0
24000	06/24/2018	PROG5038NRH60	RHEEM	0
24001	06/26/2018	RG2DV40S6N	BRADFORD WHITE	0
24002	05/30/2018	PROG2932NRH63	RHEEM	0
24003	06/27/2018	PROG5038NRH60	RHEEM	0
24004	06/27/2018	PROG5038NRH60	RHEEM	0
24005	06/27/2018	PROG5036NRH60	RHEEM	0
24006	06/29/2018	PROG5038NRH60	RHEEM	0
24007	06/25/2018	PROG5036NRH60DV	RHEEM	0
24008	06/28/2018	PROG5038NRH60	RHEEM	0
24009	06/26/2018	G82156	RHEEM	0
24010	06/25/2018	PROG5038NRH60	RHEEM	0
24011	06/30/2018	RG2DV50S6N	BRADFORD WHITE	0
24012	06/30/2018	PROG5038NRH60	RHEEM	0
24013	06/27/2018	PROG5036NRH60DV	RHEEM	0
24014	06/28/2018	PROG5038NRH60	RHEEM	0
24015	06/30/2018	PROG4038NRH62	RHEEM	0
24016	07/01/2018	PROG5038NRH60	RHEEM	0
24017	06/29/2018	PROG40S38NRH62	RHEEM	0
24018	06/30/2018	PROG5036NRH60DV	RHEEM	0
24019	07/01/2018	PROG5038NRH60	Rheem	0
24020	06/26/2018	G82156	Rheem	0
24021	06/25/2018	PROG5038NRH60	Rheem	0
24022	06/26/2018	PROG5038NRH60	Rheem	0
24023	06/29/2018	PROG5038NRH60	Rheem	0
24024	06/28/2018	PROG5038NRH60	Rheem	0
24025	06/29/2018	PROG5038NRH60	Rheem	0
24026	06/26/2018	PROG5038NRH60	Rheem	0
24027	06/26/2018	PROG5038NRH60	Rheem	0
24028	06/26/2018	PROG4038NRH62	Rheem	0
24029	06/27/2018	PROG5038NRH60	Rheem	0
24030	06/26/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24031	06/25/2018	RG2DV50S6N	Bradford White	0
24032	06/29/2018	PROG5038NRH60	Rheem	0
24033	06/25/2018	PROG50S40NRH61	Rheem	0
24034	06/25/2018	PROG40S38NRH62	Rheem	0
24035	06/28/2018	PROG40S38NRH62	Rheem	0
24036	07/01/2018	PROG4038NRH62	Rheem	0
24037	07/03/2018	RG2DV50S6N	Bradford White	0
24038	06/27/2018	G100200	Rheem	0
24039	06/27/2018	G100200	Rheem	0
24040	07/06/2018	PROG5038NRH60	Rheem	0
24041	07/06/2018	PROG5038NRH60	Rheem	0
24042	07/06/2018	PROG5038NRH60	Rheem	0
24043	07/07/2018	PROG4038NRH62	Rheem	0
24044	07/08/2018	PROG5036NRH60DV	Rheem	0
24045	07/03/2018	PROG5036NRH60DV	Rheem	0
24046	07/02/2018	PROG5038NRH60	Rheem	0
24047	07/02/2018	PROG5036NRH60DV	Rheem	0
24048	07/07/2018	PROG5038NRH60	Rheem	0
24049	07/03/2018	RG2DV40S6N	Bradford White	0
24050	07/05/2018	RG2DV50S6N	Bradford White	0
24051	07/06/2018	RG2DV50S6N	Bradford White	0
24052	07/05/2018	PROG5036NRH60DV	Rheem	0
24053	07/05/2018	G91200	Rheem	0
24054	07/10/2018	PROG5038NRH60	RHEEM	0
24055	07/13/2018	PROG5038NRH60	RHEEM	0
24056	07/13/2018	PROG5036NRH60DV	RHEEM	0
24057	07/13/2018	PROG5038NRH60	RHEEM	0
24058	07/12/2018	RG2DV40S6N	BRADFORD WHITE	0
24059	07/13/2018	G91200	RHEEM	0
24060	07/12/2018	G91200	Rheem	1
24061	07/11/2018	PROG50S40NRH61	RHEEM	0
24062	07/14/2018	PROG4860NRH60	RHEEM	0
24063	07/12/2018	PROG40S38NRH62	Rheem	0
24064	07/13/2018	PROG5038NRH60	Rheem	0
24065	07/14/2018	PROG5038NRH60	RHEEM	0
24066	06/18/2018	G75125	RHEEM	0
24067	06/24/2018	PROG5038NRH60	RHEEM	0
24068	06/20/2018	PROG7576NRH	RHEEM	0
24069	06/20/2018	G91200	RHEEM	0
24070	06/20/2018	G91200	RHEEM	0
24071	07/24/2018	PROG5036NRH60DV	RHEEM	0
24072	07/25/2018	PROG4038NRH62	RHEEM	0
24073	07/27/2018	PROG5038NRH60	RHEEM	0
24074	07/28/2018	PROG5036NRH60DV	RHEEM	0
24075	07/26/2018	PROG5038NRH60	RHEEM	0
24076	07/28/2018	PROG5038NRH60	RHEEM	0
24077	07/20/2018	PROG5038NRH60	RHEEM	0
24078	07/28/2018	PROG5038NRH60	Rheem	1
24079	07/28/2018	G82156	Rheem	0
24080	07/26/2018	PROG5038NRH60	Rheem	0
24081	07/30/2018	PROG4038NRH62	Rheem	0
24082	07/25/2018	PROG5038NRH60	Rheem	0
24083	07/26/2018	PROG5038NRH60	Rheem	0
24084	07/26/2018	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24085	07/27/2018	PROG4860NRH60	Rheem	0
24086	07/26/2018	G91200	Rheem	1
24087	07/25/2018	PROG40S38NRH62	Rheem	0
24088	07/28/2018	PROG5038NRH60	Rheem	0
24089	07/23/2018	PROG5038NRH60	Rheem	0
24090	07/23/2018	PROG5038NRH60	Rheem	0
24091	07/26/2018	PROG4860NRH60	Rheem	0
24092	07/19/2018	PROG40S38NRH62	RHEEM	0
24093	07/16/2018	PROG5038NRH60	RHEEM	0
24094	07/17/2018	PROG5038NRH60	RHEEM	0
24095	07/18/2018	PROG5038NRH60	RHEEM	0
24096	07/18/2018	PROG5038NRH60	RHEEM	0
24097	07/20/2018	PROG5038NRH60	RHEEM	0
24098	07/19/2018	PROG4038NRH62	RHEEM	0
24099	07/19/2018	PROG5038NRH60	RHEEM	0
24100	07/21/2018	PROG4860NRH60	RHEEM	0
24101	07/21/2018	PROG5038NRH60	RHEEM	0
24102	07/22/2018	PROG50S40NRH61	RHEEM	0
24103	07/20/2018	PROG5038NRH60	RHEEM	0
24104	07/21/2018	RG2DV50S6N	Bradford White	0
24105	07/21/2018	PROG5038NRH60	Rheem	0
24106	07/21/2018	PROG40S38NRH62	Rheem	0
24107	07/20/2018	PROG5038NRH60	Rheem	0
24108	07/16/2018	PROG5036NRH60DV	Rheem	0
24109	07/17/2018	RG2DV50S6N	Bradford White	0
24110	07/18/2018	PROG5038NRH60	Rheem	0
24111	07/18/2018	PROG5038NRH60	Rheem	0
24112	08/01/2018	RG2DV50S6N	BRADFORD WHITE	0
24113	07/31/2018	PROG5038NRH60	RHEEM	0
24114	08/01/2018	PROG5038NRH60	RHEEM	0
24115	08/05/2018	GSN040	LOCHINVAR	0
24116	08/04/2018	PROG5038NRH60	RHEEM	0
24117	08/02/2018	PROG4038NRH62	RHEEM	0
24118	08/02/2018	PROG5038NRH60	RHEEM	0
24119	07/31/2018	PROG5038NRH60	RHEEM	0
24120	08/01/2018	PROG5038NRH60	Rheem	0
24121	08/03/2018	PROG5036NRH60DV	Rheem	0
24122	08/03/2018	PROG5038NRH60	Rheem	0
24123	08/04/2018	G75125	Rheem	0
24124	07/31/2018	RG2DV50S6N	Bradford White	0
24125	07/30/2018	PROG5038NRH60	Rheem	0
24126	08/04/2018	PROG40S38NRH62	Rheem	0
24127	07/30/2018	PROG5038NRH60	Rheem	0
24128	08/02/2018	PROG5038NRH60	Rheem	0
24129	08/04/2018	PROG4038NRH62	Rheem	0
24130	07/31/2018	PROG40S38NRH62	Rheem	0
24131	08/04/2018	PROG5036NRH60DV	Rheem	0
24132	07/30/2018	PROG5038NRH60	Rheem	0
24133	08/02/2018	PROG4038NRH62	Rheem	0
24134	08/05/2018	PROG5038NRH60	Rheem	0
24135	07/31/2018	PROG5038NRH60	Rheem	0
24136	08/01/2018	PROG40S38NRH62	Rheem	0
24137	07/30/2018	G91200	Rheem	0
24138	08/03/2018	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24139	08/04/2018	PROG5038NRH60	Rheem	0
24140	08/09/2018	PROG4038NRH62	RHEEM	0
24141	08/07/2018	PROG5038NRH60	RHEEM	0
24142	08/10/2018	G82156	RHEEM	0
24143	08/08/2018	PROG5036NRH60DV	RHEEM	0
24144	08/08/2018	PROG5038NRH60	RHEEM	0
24145	08/09/2018	PROG5038NRH60	RHEEM	0
24146	08/09/2018	PROG5038NRH60	RHEEM	0
24147	08/06/2018	PROG5038NRH60	RHEEM	1
24148	08/12/2018	PROG5038NRH60	RHEEM	0
24149	08/09/2018	MI50L6FBN	BRADFORD-WHITE	0
24150	08/02/2018	PROG5038NRH60	RHEEM	0
24151	08/07/2018	PROG4038NRH62	Rheem	0
24152	08/10/2018	PROG5038NRH60	Rheem	0
24153	08/07/2018	PROG5038NRH60	Rheem	0
24154	08/10/2018	PROG5038NRH60	Rheem	0
24155	08/08/2018	PH199119	PHOENIX	1
24156	08/07/2018	PROG5038NRH60	Rheem	0
24157	08/09/2018	PROG5038NRH60	Rheem	0
24158	08/07/2018	G91200	RHEEM	0
24159	08/09/2018	PROG5036NRH60DV	Rheem	0
24160	08/07/2018	PROG5038NRH60	Rheem	0
24161	08/07/2018	PROG5038NRH60	Rheem	0
24162	08/06/2018	PROG5038NRH60	Rheem	0
24163	08/09/2018	PROG40S38NRH62	Rheem	0
24164	08/08/2018	PROG50S40NRH61	Rheem	0
24165	08/08/2018	PROG4038NRH62	Rheem	0
24166	08/10/2018	PROG5038NRH60	Rheem	0
24167	08/11/2018	PROG5038NRH60	Rheem	0
24168	08/11/2018	PROG5038NRH60	Rheem	0
24169	08/09/2018	PROG7576NRH	Rheem	0
24170	08/12/2018	PROG5038NRH60	Rheem	0
24171	08/18/2018	PROG5038NRH60	RHEEM	0
24172	08/13/2018	PROG5038NRH60	RHEEM	0
24173	08/13/2018	PROG5038NRH60	RHEEM	0
24174	08/16/2018	PROG40S38NRH62	RHEEM	0
24175	08/13/2018	PROG5038NRH60	RHEEM	0
24176	08/15/2018	PROG4038NRH62	RHEEM	0
24177	08/19/2018	PROG5038NRH60	RHEEM	0
24178	08/13/2018	RG2DV40S6N	BRADFORD WHITE	0
24179	08/18/2018	GSN040	LOCHINVAR	0
24180	08/14/2018	PROG5038NRH60	RHEEM	0
24181	08/16/2018	PROG4038NRH62	RHEEM	0
24182	08/15/2018	PROG40S38NRH62	RHEEM	0
24183	08/17/2018	PROG40S38NRH62	RHEEM	0
24184	08/21/2018	PROG5036NRH60DV	Rheem	0
24185	08/21/2018	PROG4038NRH62	Rheem	0
24186	08/26/2018	PROG50S40NRH61	Rheem	2
24187	08/22/2018	PROG50S40NRH61	Rheem	0
24188	08/26/2018	PROG5038NRH60	Rheem	0
24189	08/21/2018	PROG5038NRH60	Rheem	0
24190	08/23/2018	RG2DV50S6N	Bradford White	0
24191	08/13/2018	PROG5038NRH60	Rheem	0
24192	08/20/2018	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24193	08/24/2018	PROG5038NRH60	Rheem	0
24194	08/18/2018	PROG40S38NRH62	RHEEM	0
24195	08/14/2018	G91200	RHEEM	0
24196	08/14/2018	G91200	RHEEM	0
24197	08/14/2018	PROG5038NRH60	RHEEM	0
24198	08/13/2018	PROG5038NRH60	RHEEM	0
24199	08/16/2018	PROG5038NRH60	RHEEM	0
24200	08/19/2018	PROG5038NRH60	RHEEM	1
24201	08/16/2018	PROG4038NRH62	RHEEM	0
24202	08/17/2018	PROG4038NRH62	RHEEM	0
24203	08/16/2018	PROG40S38NRH62	RHEEM	0
24204	08/16/2018	PROG5038NRH60	RHEEM	0
24205	08/30/2018	PROG5038NRH60	Rheem	0
24206	08/30/2018	PROG5038NRH60	Rheem	0
24207	08/28/2018	PROG5038NRH60	Rheem	0
24208	08/27/2018	RG2DV50S6N	Bradford White	0
24209	08/30/2018	G75125	Rheem	0
24210	08/28/2018	PROG5038NRH60	Rheem	0
24211	08/31/2018	PROG5038NRH60	Rheem	0
24212	08/30/2018	PROG5038NRH60	Rheem	0
24213	09/01/2018	G75125	RHEEM	0
24214	08/24/2018	PROG5036NRH60DV	RHEEM	0
24215	08/22/2018	PROG5038NRH60	RHEEM	0
24216	08/21/2018	PROG5038NRH60	RHEEM	0
24217	08/24/2018	PROG5038NRH60	RHEEM	0
24218	08/26/2018	PROG4038NRH62	RHEEM	0
24219	08/25/2018	PROG5038NRH60	RHEEM	0
24220	08/22/2018	PROG5038NRH60	RHEEM	0
24221	08/24/2018	PROG5038NRH60	RHEEM	0
24222	08/23/2018	PROG5038NRH60	RHEEM	0
24223	08/23/2018	PROG5038NRH60	RHEEM	0
24224	08/23/2018	PROG5038NRH60	RHEEM	0
24225	08/21/2018	PROG4860NRH60	RHEEM	0
24226	08/21/2018	PROG5038NRH60	RHEEM	0
24227	08/08/2018	G91200	RHEEM	0
24228	08/24/2018	PROG5038NRH60	RHEEM	0
24229	08/25/2018	PROG5038NRH60	RHEEM	0
24230	08/24/2018	PROG50S40NRH61	RHEEM	0
24231	08/24/2018	PROG5038NRH60	RHEEM	0
24232	08/22/2018	PROG5038NRH60	Rheem	0
24233	08/24/2018	RG2DV50S6N	Bradford White	0
24234	08/23/2018	PROG5038NRH60	Rheem	0
24235	08/21/2018	PROG5038NRH60	Rheem	0
24236	08/22/2018	PROG40S38NRH62	Rheem	0
24237	08/20/2018	G76200	RHEEM	0
24238	08/22/2018	G82156	RHEEM	0
24239	08/31/2018	PROG5038NRH60	RHEEM	0
24240	08/27/2018	PROG5038NRH60	RHEEM	0
24241	08/30/2018	PROG50S40NRH61	RHEEM	0
24242	08/28/2018	PROG5036NRH60DV	RHEEM	0
24243	08/28/2018	PROG5038NRH60	RHEEM	0
24244	09/01/2018	PROG5038NRH60	RHEEM	0
24245	09/04/2018	PROG5038NRH60	RHEEM	0
24246	08/28/2018	PROG4038NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24247	08/30/2018	PROG5038NRH60	RHEEM	0
24248	08/27/2018	PROG50S40NRH61	RHEEM	0
24249	08/28/2018	PROG5038NRH60	RHEEM	0
24250	08/29/2018	PROG5038NRH60	RHEEM	0
24251	08/28/2018	RG2DV50S6N	BRADFORD WHITE	0
24252	08/28/2018	PROG4860NRH60	RHEEM	0
24253	08/28/2018	PROG5038NRH60	Rheem	0
24254	08/31/2018	PROG5036NRH60DV	Rheem	0
24255	09/08/2018	PROG5038NRH60	RHEEM	0
24256	09/06/2018	PROG5038NRH60	RHEEM	0
24257	09/06/2018	PROG5038NRH60	RHEEM	0
24258	09/05/2018	PROG4860NRH60	RHEEM	0
24259	09/05/2018	PROG5038NRH60	RHEEM	0
24260	09/06/2018	PROG5038NRH60	RHEEM	0
24261	09/07/2018	PROG40S38NRH62	RHEEM	0
24262	09/06/2018	PROG5038NRH60	RHEEM	0
24263	09/04/2018	G91200	RHEEM	0
24264	09/05/2018	PROG5038NRH60	RHEEM	0
24265	09/08/2018	PROG40S38NRH62	RHEEM	0
24266	09/05/2018	PROG5038NRH60	RHEEM	0
24267	09/06/2018	PROG5036NRH60DV	Rheem	0
24268	09/07/2018	PROG5038NRU60	Rheem	0
24269	09/08/2018	PROG4038NRH62	Rheem	0
24270	09/08/2018	PROG2932NRH63	Rheem	0
24271	09/08/2018	PROG5036NRH60DV	RHEEM	0
24272	09/07/2018	PROG5038NRH60	Rheem	0
24273	09/05/2018	PROG5038NRH60	Rheem	0
24274	08/25/2018	PROG4038NRH62	Rheem	0
24275	09/05/2018	PROG5038NRH60	Rheem	0
24276	09/04/2018	RG250H6N	Bradford White	0
24277	09/06/2018	PROG4860NRH60	RHEEM	0
24278	09/07/2018	PROG5036NRH60DV	Rheem	0
24279	09/04/2018	PROG5038NRH60	Rheem	0
24280	08/23/2018	PROG5038NRH60	RHEEM	0
24281	08/28/2018	RG150T6N	BRADFORD WHITE	0
24282	08/20/2018	PROG50S40NRH61	RHEEM	0
24283	09/10/2018	PROG5038NRH60	RHEEM	0
24284	09/14/2018	PROG5038NRH60	Rheem	0
24285	09/16/2018	PROG40S38NRH62	Rheem	0
24286	09/15/2018	PROG5038NRH60	Rheem	0
24287	09/10/2018	PROG4038NRH62	Rheem	0
24288	09/10/2018	PROG5038NRH60	Rheem	0
24289	09/16/2018	PROG5038NRH60	Rheem	0
24290	09/15/2018	PROG5038NRH60	Rheem	0
24291	09/14/2018	PROG5038NRH60	Rheem	0
24292	09/16/2018	RG2DV50S6N	BRADFORD WHITE	0
24293	09/10/2018	PROG5036NRH60DV	RHEEM	0
24294	09/15/2018	PROG5038NRH60	RHEEM	0
24295	09/10/2018	G75125	RHEEM	0
24296	09/11/2018	PROG5038NRH60	RHEEM	0
24297	09/15/2018	G76200	RHEEM	0
24298	09/14/2018	PH19980	PHOENIX	1
24299	09/12/2018	PROG5038NRH60	RHEEM	0
24300	09/13/2018	PROG4038NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24301	09/15/2018	PROG5038NRH60	RHEEM	0
24302	09/10/2018	G91200	RHEEM	0
24303	09/10/2018	G82156	RHEEM	0
24304	09/12/2018	PROG5038NRH60	RHEEM	0
24305	09/16/2018	PROG5038NRH60	RHEEM	0
24306	09/17/2018	PROG5038NRH60	RHEEM	0
24307	09/20/2018	PROG5038NRH60	RHEEM	0
24308	09/20/2018	PROG5038NRH60	RHEEM	0
24309	09/21/2018	RG2DV50S6N	BRADFORD WHITE	0
24310	09/21/2018	PROG4038NRH62	RHEEM	0
24311	09/18/2018	PROG40S38NRH62	RHEEM	0
24312	09/20/2018	PROG5038NRH60	RHEEM	0
24313	09/22/2018	PROG5038NRH60	RHEEM	0
24314	09/22/2018	PROG5038NRH60	RHEEM	0
24315	09/18/2018	G91200	RHEEM	0
24316	09/19/2018	G82156	RHEEM	0
24317	09/17/2018	PROG5038NRH60	RHEEM	1
24318	09/21/2018	PROG4038NRH62	RHEEM	0
24319	09/04/2018	PROG5036NRH60DV	RHEEM	0
24320	09/21/2018	RG2DV40S6N	Bradford White	0
24321	09/17/2018	G7575	RHEEM	0
24322	09/21/2018	G91200	Rheem	0
24323	09/23/2018	PROG5038NRH60	Rheem	0
24324	09/19/2018	PROG5038NRH60	Rheem	0
24325	09/19/2018	PROG5038NRH60	Rheem	0
24326	09/18/2018	PROG5038NRH60	RHEEM	0
24327	09/17/2018	PROG50S40NRH61	Rheem	0
24328	09/18/2018	PROG5038NRH60	Rheem	0
24329	09/17/2018	PROG5036NRH60DV	Rheem	0
24330	09/22/2018	PROG5038NRH60	Rheem	0
24331	10/07/2018	PROG5038NRH60	Rheem	0
24332	09/29/2018	PROG5038NRH60	Rheem	0
24333	09/28/2018	PROG5038NRH60	Rheem	0
24334	10/01/2018	PROG50S40NRH61	Rheem	0
24335	09/24/2018	PROG4860NRH60	RHEEM	0
24336	09/29/2018	PROG5038NRH60	Rheem	0
24337	09/26/2018	G82156	Rheem	0
24338	09/25/2018	PROG5038NRH60	Rheem	0
24339	09/25/2018	PROG5038NRH60	RHEEM	0
24340	09/28/2018	PROG4038NRH62	Rheem	0
24341	09/28/2018	PROG5038NRH60	Rheem	0
24342	09/25/2018	PROG5038NRH60	RHEEM	0
24343	09/27/2018	PROG4038NRH62	RHEEM	0
24344	09/27/2018	PROG5038NRH60	RHEEM	0
24345	09/30/2018	PROG5038NRH60	RHEEM	0
24346	09/29/2018	PROG5038NRH60	RHEEM	0
24347	09/28/2018	PROG5036NRH60DV	RHEEM	0
24348	09/26/2018	G82156	RHEEM	0
24349	09/26/2018	G82156	RHEEM	0
24350	09/27/2018	G91200	RHEEM	0
24351	09/30/2018	PROG5038NRH60	RHEEM	0
24352	09/30/2018	PROG5038NRH60	RHEEM	0
24353	09/29/2018	PROG5038NRH60	RHEEM	1
24354	09/28/2018	PROG4038NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24355	09/28/2018	PROG4038NRH62	RHEEM	0
24356	10/07/2018	PROG5038NRH60	RHEEM	0
24357	10/06/2018	PROG5038NRH60	RHEEM	0
24358	10/03/2018	PH199119	PHOENIX	0
24359	09/24/2018	PROG5038NRH60	RHEEM	0
24360	09/25/2018	PROG50S40NRH61	RHEEM	0
24361	09/30/2018	PROG5038NRH60	RHEEM	0
24362	09/25/2018	PROG5038NRH60	RHEEM	0
24363	09/28/2018	PROG5038NRH60	RHEEM	0
24364	09/30/2018	RG140T6N	BRADFORD WHITE	0
24365	10/01/2018	PROG5038NRH60	RHEEM	0
24366	10/01/2018	G75125	RHEEM	0
24367	10/07/2018	PROG5038NRH60	RHEEM	0
24368	10/05/2018	PROG5038NRH60	RHEEM	0
24369	10/02/2018	PROG5038NRH60	RHEEM	0
24370	10/05/2018	PROG5038NRH60	RHEEM	0
24371	10/05/2018	PROG5038NRH60	RHEEM	0
24372	10/05/2018	PROG5038NRH60	RHEEM	0
24373	10/04/2018	PROG40S38NRH62	RHEEM	0
24374	10/06/2018	PROG7576NRH	RHEEM	0
24375	10/01/2018	PROG5036NRH60DV	RHEEM	0
24376	10/05/2018	PROG40S38NRH62	Rheem	0
24377	10/05/2018	PROG5038NRH60	Rheem	0
24378	10/05/2018	PROG40S38NRH62	Rheem	0
24379	10/02/2018	G75125	Rheem	0
24380	10/05/2018	PROG5038NRH60	Rheem	0
24381	10/02/2018	G75125	Rheem	0
24382	10/11/2018	PROG4038NRH62	RHEEM	0
24383	10/08/2018	G91200	RHEEM	0
24384	10/08/2018	PROG5038NRH60	RHEEM	0
24385	10/08/2018	PROG50S40NRH61	RHEEM	0
24386	10/13/2018	PROG5038NRH60	RHEEM	0
24387	10/11/2018	PROG5038NRH60	RHEEM	0
24388	10/09/2018	PROG5038NRH60	RHEEM	0
24389	10/12/2018	PROG5038NRH60	RHEEM	0
24390	10/08/2018	PH199119	PHOENIX	1
24391	10/13/2018	PROG5036NRH60DV	RHEEM	0
24392	10/14/2018	PROG5038NRH60	RHEEM	0
24393	10/11/2018	PROG5036NRH60DV	RHEEM	0
24394	10/12/2018	PROG4038NRH62	RHEEM	0
24395	10/08/2018	PROG5038NRH60	RHEEM	0
24396	10/09/2018	PROG5038NRH60	Rheem	0
24397	10/12/2018	PROG5038NRH60	Rheem	0
24398	10/11/2018	PROG50S40NRH61	Rheem	0
24399	10/08/2018	PROG5038NRH60	Rheem	1
24400	10/08/2018	PROG5038NRH60	Rheem	0
24401	10/14/2018	PROG5038NRH60	Rheem	0
24402	10/12/2018	PROG5038NRH60	Rheem	0
24403	10/08/2018	PH199119	Phoenix	0
24404	09/22/2018	G75125	RHEEM	0
24405	09/22/2018	G82156	RHEEM	0
24406	09/19/2018	G82156	RHEEM	0
24407	09/21/2018	PROG4038NRH62	RHEEM	0
24408	10/17/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24409	10/19/2018	PROG5038NRH60	RHEEM	0
24410	10/19/2018	PROG5038NRH60	RHEEM	0
24411	10/18/2018	PROG5038NRH60	RHEEM	0
24412	10/19/2018	PROG5038NRH60	RHEEM	0
24413	10/16/2018	RG2DV50S6N	BRADFORD WHITE	0
24414	10/20/2018	PROG5036NRH60DV	RHEEM	0
24415	10/17/2018	PROG5038NRH60	RHEEM	0
24416	10/19/2018	PROG5038NRH60	RHEEM	0
24417	10/18/2018	PROG40S38NRH62	RHEEM	0
24418	10/17/2018	G82156	RHEEM	0
24419	10/20/2018	PH199119	PHOENIX	1
24420	10/20/2018	PH199119	PHOENIX	0
24421	10/19/2018	PROG5036NRH60DV	RHEEM	0
24422	10/16/2018	PROG5038NRH60	RHEEM	0
24423	10/19/2018	PROG4038NRH62	RHEEM	0
24424	10/20/2018	PROG5038NRH60	RHEEM	0
24425	10/21/2018	PROG5038NRH60	Rheem	1
24426	10/15/2018	PROG5038NRH60	Rheem	0
24427	10/17/2018	PROG5038NRH60	Rheem	0
24428	10/18/2018	RG2DV50S6N	BRADFORD-WHITE	0
24429	10/15/2018	PROG5038NRH60	Rheem	0
24430	10/18/2018	PROG5038NRH60	Rheem	0
24431	10/16/2018	PROG40S38NRH62	Rheem	0
24432	10/20/2018	PROG5038NRH60	Rheem	0
24433	10/16/2018	PROG5038NRH60	Rheem	0
24434	10/26/2018	PROG5038NRH60	RHEEM	0
24435	10/23/2018	PROG5036NRH60DV	RHEEM	0
24436	10/23/2018	PROG5038NRH60	RHEEM	0
24437	10/22/2018	PROG5038NRH60	RHEEM	0
24438	10/22/2018	PROG2932NRH63	Rheem	0
24439	10/24/2018	PROG5038NRH60	Rheem	0
24440	10/27/2018	PROG5038NRH60	Rheem	0
24441	10/26/2018	MI5036FBN	BRADFORD-WHITE	0
24442	10/28/2018	PROG5038NRH60	Rheem	0
24443	10/22/2018	PROG4038NRH62	Rheem	0
24444	10/24/2018	PROG5038NRH60	Rheem	0
24445	11/03/2018	PROG5038NRH60	Rheem	0
24446	10/29/2018	PROG5038NRH60	RHEEM	0
24447	10/29/2018	PROG5038NRH60	Rheem	0
24448	10/29/2018	PROG5038NRH60	Rheem	0
24449	10/29/2018	PROG5038NRH60	Rheem	0
24450	10/30/2018	RG2DV50S6N	Bradford White	0
24451	11/03/2018	PROG5038NRH60	Rheem	0
24452	11/03/2018	PROG5036NRH60DV	Rheem	0
24453	10/29/2018	PROG5038NRH60	Rheem	0
24454	10/24/2018	PROG5038NRH60	RHEEM	0
24455	10/25/2018	RG2DV50S6N	Bradford White	0
24456	10/23/2018	PROG5038NRH60	Rheem	0
24457	10/26/2018	PROG4038NRH62	Rheem	0
24458	10/05/2018	PROG5038NRH60	RHEEM	0
24459	11/03/2018	PROG5038NRH60	RHEEM	0
24460	11/03/2018	PROG5038NRH60	RHEEM	0
24461	11/01/2018	PROG4038NRH62	RHEEM	0
24462	10/31/2018	PROG40S38NRH62	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24463	10/30/2018	PROG5038NRH60	Rheem	0
24464	10/31/2018	PROG5036NRH60DV	Rheem	0
24465	11/04/2018	PROG4038NRH62	Rheem	0
24466	11/04/2018	G91200	Rheem	0
24467	10/30/2018	RG2DV50S6N	BRADFORD WHITE	0
24468	11/02/2018	PROG5038NRH60	RHEEM	0
24469	11/02/2018	PROG5038NRH60	RHEEM	0
24470	11/02/2018	PROG5038NRH60	RHEEM	1
24471	10/31/2018	PROG5036NRH60DV	RHEEM	0
24472	11/01/2018	PROG5038NRH60	Rheem	0
24473	11/04/2018	PROG5038NRH60	Rheem	0
24474	11/02/2018	G75125	Rheem	0
24475	11/02/2018	G75125	Rheem	0
24476	10/30/2018	PROG50S40NRH61	Rheem	0
24477	11/09/2018	PROG50S40NRH61	RHEEM	0
24478	11/09/2018	PROG5038NRH60	RHEEM	1
24479	11/10/2018	PROG5038NRH60	RHEEM	0
24480	11/11/2018	PROG5038NRH60	RHEEM	0
24481	11/11/2018	PROG5038NRH60	RHEEM	0
24482	11/10/2018	PROG5038NRH60	RHEEM	0
24483	11/09/2018	PROG5036NRH60DV	RHEEM	0
24484	11/08/2018	PROG5038NRH60	RHEEM	0
24485	11/10/2018	PROG5036NRH60DV	RHEEM	0
24486	11/08/2018	PROG5036NRH60DV	RHEEM	0
24487	11/09/2018	PROG5038NRH60	RHEEM	0
24488	11/07/2018	PROG5038NRH60	RHEEM	0
24489	11/05/2018	PROG5038NRH60	RHEEM	1
24490	11/08/2018	G82156	RHEEM	0
24491	11/07/2018	PROG4038NRH62	RHEEM	0
24492	11/09/2018	PROG5036NRH60DV	RHEEM	0
24493	11/09/2018	PROG5038NRH60	RHEEM	0
24494	11/09/2018	PROG5036NRH60DV	RHEEM	0
24495	11/15/2018	PROG5038NRH60	RHEEM	0
24496	11/12/2018	PROG4038NRH62	RHEEM	0
24497	11/13/2018	G91200	RHEEM	0
24498	11/14/2018	PROG5036NRH60DV	RHEEM	0
24499	11/16/2018	PROG40S38NRH62	RHEEM	0
24500	11/16/2018	PROG5038NRH60	Rheem	0
24501	11/15/2018	PROG5038NRH60	Rheem	0
24502	11/23/2018	PROG5038NRH60	RHEEM	0
24503	11/21/2018	PROG5038NRH60	RHEEM	0
24504	11/20/2018	PROG5038NRH60	RHEEM	0
24505	11/21/2018	G76200	RHEEM	0
24506	11/20/2018	PROG5038NRH60	RHEEM	0
24507	11/19/2018	PROG4038NRH62	RHEEM	0
24508	11/21/2018	PROG5038NRH60	RHEEM	0
24509	11/19/2018	PROG4038NRH62	RHEEM	1
24510	11/17/2018	PROG5036NRH60DV	Rheem	0
24511	11/21/2018	PROG4038NRH62	RHEEM	0
24512	11/16/2018	PROG5038NRH60	Rheem	0
24513	11/16/2018	PROG5038NRH60	RHEEM	0
24514	11/19/2018	PROG5038NRH60	Rheem	0
24515	11/20/2018	PROG5038NRH60	Rheem	0
24516	11/24/2018	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24517	11/20/2018	PROG5036NRH60DV	Rheem	0
24518	11/23/2018	G91200	Rheem	0
24519	11/19/2018	G75125	Rheem	0
24520	11/19/2018	G75125	Rheem	0
24521	11/20/2018	PH13055	PHOENIX	0
24522	11/21/2018	G75125	Rheem	0
24523	11/18/2018	PROG5038NRH60	Rheem	0
24524	11/30/2018	PROG5038NRH60	Rheem	0
24525	11/28/2018	PROG5038NRH60	Rheem	0
24526	12/02/2018	PROG50S40NRH61	Rheem	0
24527	11/30/2018	PROG5036NRH60DV	Rheem	0
24528	11/28/2018	PROG40S38NRH62	Rheem	0
24529	12/03/2018	PROG5038NRH60	RHEEM	0
24530	12/04/2018	PROG5038NRH60	RHEEM	0
24531	12/08/2018	PROG40S38NRH62	RHEEM	0
24532	12/04/2018	PROG5038NRH60	RHEEM	0
24533	12/05/2018	G91200	RHEEM	0
24534	11/28/2018	PROG5038NRH60	Rheem	0
24535	11/26/2018	PROG5036NRH60DV	Rheem	0
24536	11/26/2018	PROG50S40NRH61	Rheem	0
24537	11/26/2018	PROG5038NRH60	Rheem	0
24538	11/28/2018	MI5036FBN	BRADFORD-WHITE	0
24539	12/04/2018	G91200	RHEEM	0
24540	12/04/2018	G91200	RHEEM	0
24541	12/09/2018	G91200	RHEEM	0
24542	12/09/2018	PROG5038NRH60	RHEEM	0
24543	12/07/2018	PROG5038NRH60	RHEEM	0
24544	12/08/2018	PROG4038NRH62	RHEEM	0
24545	12/08/2018	PROG5038NRH60	RHEEM	0
24546	12/09/2018	PROG5038NRH60	RHEEM	0
24547	12/08/2018	PROG40S38NRH62	RHEEM	0
24548	12/06/2018	PROG5036NRH60DV	RHEEM	1
24549	12/06/2018	RG2DV50S6N	BRADFORD WHITE	0
24550	12/05/2018	PROG5038NRH60	RHEEM	0
24551	12/06/2018	PROG5038NRH60	RHEEM	0
24552	12/04/2018	G75125	RHEEM	0
24553	12/01/2018	PROG5036NRH60DV	RHEEM	0
24554	11/27/2018	PROG4038NRH62	RHEEM	0
24555	12/03/2018	PROG5038NRH60	RHEEM	0
24556	11/30/2018	RG140T6N	BRADFORD WHITE	0
24557	11/26/2018	PROG2932NRH63	RHEEM	0
24558	11/30/2018	PROG40S38NRH62	RHEEM	0
24559	11/30/2018	PROG5038NRH60	RHEEM	0
24560	11/28/2018	PROG5038NRH60	RHEEM	0
24561	11/28/2018	PROG5038NRH60	RHEEM	0
24562	12/02/2018	PROG5038NRH60	RHEEM	0
24563	12/02/2018	PROG5038NRH60	RHEEM	0
24564	11/09/2018	PROG5038NRH60	RHEEM	0
24565	11/05/2018	G75125	RHEEM	0
24566	11/30/2018	PROG7576NRH	RHEEM	0
24567	11/29/2018	G91200	RHEEM	0
24568	11/28/2018	RG2DV50S6N	BRADFORD WHITE	0
24569	11/26/2018	PROG40S38NRH62	RHEEM	0
24570	12/01/2018	G91200	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24571	11/28/2018	PROG5038NRH60	RHEEM	0
24572	11/30/2018	PROG4038NRH62	Rheem	0
24573	12/01/2018	PROG5036NRH60DV	Rheem	0
24574	12/04/2018	PROG5038NRH60TT	Rheem	0
24575	12/07/2018	PROG5038NRH60TT	Rheem	0
24576	12/07/2018	PROG7576N	Rheem	0
24577	12/07/2018	PROG40S38NRH62	Rheem	0
24578	12/08/2018	PROG5038NRH60TT	RHEEM	0
24579	12/09/2018	PROG5038NRH60TT	Rheem	0
24580	12/05/2018	PROG5038NRH60TT	Rheem	0
24581	12/03/2018	PROG5038NRH60TT	Rheem	0
24582	12/04/2018	PROG5038NRH60TT	Rheem	0
24583	12/04/2018	PROG50S40NRH61	A. O. SMITH	0
24584	12/03/2018	PROG4038NRH62TT	Rheem	0
24585	12/05/2018	PROG5038NRH60TT	Rheem	0
24586	12/08/2018	PROG4038NRH62TT	Rheem	0
24587	12/06/2018	PROG4038NRH62TT	Rheem	0
24588	12/08/2018	PROG5036NRH60DV	Rheem	0
24589	12/09/2018	PROG5036NRH60DV	RHEEM	0
24590	12/12/2018	PROG5038NRH60	RHEEM	0
24591	12/12/2018	G75125	RHEEM	0
24592	12/13/2018	PROG5038NRH60	RHEEM	0
24593	12/13/2018	PROG5038NRH60	RHEEM	0
24594	12/11/2018	G91200	RHEEM	0
24595	12/11/2018	G91200	RHEEM	0
24596	12/11/2018	G91200	RHEEM	0
24597	12/11/2018	G91200	RHEEM	0
24598	12/12/2018	PROG5038NRH60	RHEEM	0
24599	12/14/2018	G91200	RHEEM	0
24600	12/14/2018	PROG4038NRH62	RHEEM	0
24601	12/15/2018	PROG4038NRH62	RHEEM	0
24602	12/15/2018	PROG5038NRH60	RHEEM	0
24603	12/16/2018	PROG5038NRH60	RHEEM	0
24604	12/16/2018	PROG5038NRH60	RHEEM	0
24605	12/13/2018	PROG40S38NRH62	RHEEM	0
24606	12/12/2018	PROG5038NRH60	RHEEM	0
24607	12/10/2018	PROG5038NRH60	RHEEM	0
24608	12/16/2018	G91200	RHEEM	0
24609	12/08/2018	PROG4038NRH62	RHEEM	0
24610	12/10/2018	PROG5036NRH60DV	RHEEM	0
24611	12/14/2018	PROG5038NRH60	RHEEM	0
24612	12/16/2018	PROG5038NRH60	RHEEM	0
24613	12/16/2018	PROG40S38NRH62	RHEEM	0
24614	12/14/2018	G82156	RHEEM	0
24615	12/13/2018	RG2DV40S6N	BRADFORD WHITE	0
24616	12/13/2018	PROG5038NRH60	RHEEM	0
24617	12/13/2018	PROG40S38NRH62	RHEEM	0
24618	12/10/2018	PROG5038NRH60	RHEEM	0
24619	12/15/2018	PROG50S40NRH61	RHEEM	0
24620	12/11/2018	PROG5038NRH60	RHEEM	0
24621	12/12/2018	PROG5038NRH60	RHEEM	0
24622	12/15/2018	BTH199	AO SMITH	0
24623	12/20/2018	PROG5038NRH60	RHEEM	0
24624	12/19/2018	PROG5038NRH60	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24625	12/22/2018	PROG5038NRH60	RHEEM	0
24626	12/20/2018	PROG5038NRH60	RHEEM	0
24627	12/21/2018	PROG5038NRH60	RHEEM	0
24628	12/19/2018	PROG5038NRH60	RHEEM	0
24629	12/20/2018	PROG5036NRH60DV	RHEEM	0
24630	12/20/2018	PROG5036NRH60DV	RHEEM	0
24631	12/17/2018	PROG5038NRH60	RHEEM	0
24632	12/22/2018	PROG5038NRH60	RHEEM	0
24633	12/21/2018	PROG4038NRH62	RHEEM	0
24634	12/22/2018	PROG40S38NRH62	RHEEM	0
24635	12/22/2018	RG2DV50S6N	BRADFORD WHITE	0
24636	12/23/2018	PROG5038NRH60	RHEEM	0
24637	12/21/2018	PROG5036NRH60DV	RHEEM	0
24638	12/21/2018	PROG5038NRH60	RHEEM	0
24639	12/21/2018	PROG40S38NRH62	RHEEM	0
24640	12/21/2018	RG250H6N	BRADFORD WHITE	0
24641	12/22/2018	PROG5038NRH60	RHEEM	0
24642	12/18/2018	RG250H6N	BRADFORD WHITE	0
24643	12/18/2018	PROG5038NRH60	RHEEM	0
24644	12/19/2018	G82156	RHEEM	0
24645	12/20/2018	PROG5038NRH60	RHEEM	0
24646	12/20/2018	PROG5038NRH60	RHEEM	0
24647	12/18/2018	PROG5038NRH60	RHEEM	0
24648	12/20/2018	G91200	RHEEM	0
24649	12/18/2018	G82156	RHEEM	0
24650	12/17/2018	G82156	RHEEM	0
24651	12/29/2018	PROG5038NRH60	Rheem	0
24652	12/28/2018	RG2DV50S6N	Bradford White	0
24653	12/24/2018	PROG5038NRH60	Rheem	0
24654	12/30/2018	MI5036FBN	Bradford White	0
24655	12/24/2018	PROG5038NRH60	Rheem	0
24656	12/28/2018	RG250H6N	Bradford White	0
24657	12/31/2018	PROG5038NRH60	RHEEM	0
24658	12/28/2018	PROG5038NRH60	RHEEM	0
24659	12/26/2018	PROG4860NRH60	RHEEM	0
24660	12/28/2018	PROG5038NRH60	RHEEM	0
24661	01/06/2019	PROG5038NRH60	RHEEM	0
24662	01/05/2019	PROG5038NRH60	RHEEM	0
24663	12/31/2018	PROG40S38NRH62	RHEEM	0
24664	01/05/2019	PROG5038NRH60	RHEEM	0
24665	11/28/2018	G91200	RHEEM	0
24666	12/07/2018	G82156	RHEEM	0
24667	01/19/2018	PROG5038NRH60	RHEEM	0
24668	01/02/2019	PROG5038NRH60	Rheem	0
24669	01/02/2019	PROG5036NRH60DV	RHEEM	0
24670	01/03/2019	PROG5038NRH60	Rheem	0
24671	01/04/2019	PROG40S38NRH62	Rheem	0
24672	01/04/2019	PROG4038NRH62	Rheem	0
24673	01/05/2019	PROG5036NRH60DV	Rheem	0
24674	01/06/2019	PROG5038NRH60	BRADFORD WHITE	0
24675	01/05/2019	G76200	Rheem	0
24676	01/04/2019	PROG4038NRH62	Rheem	0
24677	01/02/2019	PH13055	PHOENIX	0
24678	01/04/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24679	01/03/2019	PROG40S38NRH62	Rheem	0
24680	01/03/2019	G91200	Rheem	0
24681	01/02/2019	RG2DV40S6N	Bradford White	0
24682	01/05/2019	PROG5038NRH60	Rheem	0
24683	01/05/2019	PROG5038NRH60	Rheem	0
24684	12/24/2018	PROG5038NRH60	Rheem	0
24685	11/28/2018	PROG5038NRH60	Rheem	0
24686	11/30/2018	PROG5038NRH60	Rheem	0
24687	11/27/2018	PH199119	PHOENIX	0
24688	12/04/2018	PH199119	PHOENIX	0
24689	01/22/2019	21VR40	RHEEM	1
24690	01/04/2019	PROG5038NRH60	RHEEM	0
24691	01/10/2019	PROG5038NRH60	RHEEM	0
24692	01/10/2019	PROG5038NRH60	RHEEM	0
24693	01/11/2019	PROG50S40NRH61	RHEEM	0
24694	01/11/2019	G91200	RHEEM	0
24695	01/07/2019	PROG4038NRH62	RHEEM	0
24696	01/10/2019	PROG5038NRH60	Rheem	0
24697	01/12/2019	PROG50S40NRH61	Rheem	0
24698	01/14/2019	G75125	Rheem	0
24699	01/09/2019	PROG5036NRH60DV	Rheem	0
24700	01/12/2019	PROG5038NRH60	Rheem	0
24701	01/11/2019	RG250H6N	Bradford White	0
24702	01/13/2019	PROG5038NRH60	Rheem	1
24703	01/10/2019	PROG5036NRH60DV	Rheem	0
24704	01/09/2019	PROG5038NRH60	Rheem	0
24705	01/07/2019	PROG2932NRH63	Rheem	0
24706	01/16/2019	PROG5038NRH60	RHEEM	0
24707	01/16/2019	PROG5038NRH60	RHEEM	0
24708	01/18/2019	PROG5038NRH60	RHEEM	0
24709	01/20/2019	PROG5036NRH60DV	RHEEM	0
24710	01/19/2019	PH199119	PHOENIX	0
24711	01/17/2019	PROG4038NRH62	Rheem	0
24712	01/19/2019	PROG5036NRH60DV	Rheem	0
24713	01/19/2019	PH199119	PHOENIX	0
24714	01/18/2019	PROG5038NRH60	RHEEM	0
24715	01/14/2019	PROG5038NRH60	RHEEM	0
24716	01/09/2019	G91200	RHEEM	0
24717	01/21/2019	PROG40S38NRH62	Rheem	0
24718	01/18/2019	PROG5038NRH60	Rheem	0
24719	01/18/2019	PROG5038NRH60	Rheem	0
24720	01/15/2019	PROG5038NRH60	Rheem	0
24721	01/15/2019	PROG5038NRH60	Rheem	0
24722	01/14/2019	PROG4038NRH62	Rheem	0
24723	01/15/2019	PROG5038NRH60	RHEEM	0
24724	01/17/2019	PROG5038NRH60	Rheem	0
24725	01/19/2019	PROG5038NRH60	Rheem	0
24726	01/15/2019	PROG5038NRH60	Rheem	0
24727	01/14/2019	PROG5038NRH60	Rheem	0
24728	01/14/2019	PROG5038NRH60	Rheem	0
24729	01/15/2019	PROG5038NRH60	Rheem	0
24730	01/23/2019	PROG5038NRH60	RHEEM	0
24731	01/22/2019	PROG5038NRH60	RHEEM	0
24732	01/23/2019	G76200	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24733	01/21/2019	PROG40S38NRH62	RHEEM	0
24734	01/21/2019	G76200	RHEEM	0
24735	01/23/2019	PROG4860NRH60	RHEEM	0
24736	01/24/2019	PROG5038NRH60	RHEEM	0
24737	01/24/2019	PH199119	PHOENIX	0
24738	01/25/2019	PROG5038NRH60	RHEEM	0
24739	01/24/2019	PROG2932NRH63	RHEEM	0
24740	01/24/2019	PROG5038NRH60	RHEEM	0
24741	01/23/2019	PROG5036NRH60DV	RHEEM	0
24742	01/24/2019	PROG4860NRH60	RHEEM	0
24743	01/26/2019	PROG5038NRH60	RHEEM	0
24744	01/25/2019	PROG5038NRH60	Rheem	0
24745	01/22/2019	PROG40S38NRH62	Rheem	0
24746	01/24/2019	PROG4860NRH60	RHEEM	0
24747	01/25/2019	G91200	Rheem	0
24748	01/27/2019	PROG5038NRH60	Rheem	0
24749	02/02/2019	PROG40S38NRH62	RHEEM	0
24750	01/31/2019	PROG5038NRH60	RHEEM	0
24751	01/29/2019	PROG5038NRH60	RHEEM	0
24752	01/29/2019	PROG5038NRH60	RHEEM	0
24753	01/29/2019	G91200	RHEEM	0
24754	01/31/2019	PROG2932NRH63	Rheem	0
24755	01/29/2019	G76200	Rheem	0
24756	01/29/2019	PROG5038NRH60	Rheem	0
24757	01/28/2019	PROG5038NRH60	Rheem	0
24758	02/01/2019	PROG5038NRH60	Rheem	0
24759	01/30/2019	PROG5038NRH60	Rheem	0
24760	02/02/2019	RG2DV50S6N	Bradford White	0
24761	02/01/2019	PROG5038NRH60	Rheem	0
24762	01/31/2019	RG2DV50S6N	BRADFORD WHITE	0
24763	02/01/2019	PROG5038NRH60	RHEEM	0
24764	02/01/2019	PROG5038NRH60	RHEEM	0
24765	01/30/2019	PROG5038NRH60	RHEEM	0
24766	01/30/2019	PROG5038NRH60	RHEEM	0
24767	01/31/2019	PROG5038NRH60	RHEEM	0
24768	02/08/2019	PROG5038NRH60	Rheem	0
24769	02/07/2019	PROG5038NRH60	Rheem	0
24770	02/07/2019	PROG5038NRH60	Rheem	0
24771	02/06/2019	PROG5038NRH60	Rheem	0
24772	02/07/2019	PROG5038NRH60	Rheem	0
24773	02/05/2019	PROG5038NRH60	RHEEM	0
24774	02/05/2019	PROG5038NRH60	RHEEM	0
24775	02/08/2019	PROG5038NRH60	RHEEM	0
24776	02/06/2019	G91200	RHEEM	0
24777	02/05/2019	PROG4860NRH60	RHEEM	0
24778	01/30/2019	PROG5038NRH60	RHEEM	0
24779	01/18/2019	PROG5038NRH60	RHEEM	0
24780	02/13/2019	RG2DV50S6N	Bradford White	0
24781	02/14/2019	PROG5038NRH60	Rheem	0
24782	02/17/2019	PROG50S40NRH61	RHEEM	0
24783	02/16/2019	PROG5036NRH60DV	Rheem	0
24784	02/15/2019	G91200	Rheem	0
24785	02/17/2019	PROG5038NRH60	RHEEM	0
24786	02/17/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24787	02/13/2019	PROG30S30NRH63	Rheem	0
24788	02/14/2019	PROG5038NRH60	Rheem	0
24789	02/13/2019	RG2DV50S6N	BRADFORD WHITE	0
24790	02/13/2019	PROG5038NRH60	RHEEM	0
24791	02/15/2019	PROG5038NRH60	RHEEM	0
24792	02/06/2019	PROG5038NRH60	RHEEM	0
24793	02/12/2019	PROG4038NRH62	RHEEM	0
24794	02/15/2019	PROG5036NRH60DV	RHEEM	0
24795	02/13/2019	PROG5038NRH60	RHEEM	0
24796	02/17/2019	PROG4860NRH60	RHEEM	0
24797	02/20/2019	PROG5038NRH60	RHEEM	0
24798	02/23/2019	G75125	RHEEM	0
24799	02/20/2019	PROG5036NRH60DV	RHEEM	0
24800	02/22/2019	PROG5038NRH60	RHEEM	0
24801	02/20/2019	PROG5038NRH60	RHEEM	0
24802	02/22/2019	PROG5038NRH60	RHEEM	0
24803	02/19/2019	G91200	RHEEM	0
24804	02/20/2019	PROG40S38NRH62	RHEEM	0
24805	02/23/2019	PROG5038NRH60	RHEEM	0
24806	02/23/2019	PROG4038NRH62	RHEEM	0
24807	02/23/2019	PROG5038NRH60	RHEEM	0
24808	02/22/2019	PROG5038NRH60	RHEEM	0
24809	02/20/2019	PROG5036NRH60DV	RHEEM	0
24810	02/16/2019	RG2DV50S6N	Bradford White	1
24811	02/20/2019	PROG5038NRH60	Rheem	0
24812	02/13/2019	PROG50S40NRH61	Rheem	0
24813	02/15/2019	PROG2932NRH63	Rheem	0
24814	02/19/2019	RG2DV50S6N	Bradford White	0
24815	02/18/2019	PROG5038NRH60	Rheem	0
24816	02/23/2019	PROG2932NRH63	Rheem	0
24817	02/23/2019	PROG5038NRH60	RHEEM	0
24818	02/20/2019	PROG4038NRH62	Rheem	0
24819	02/20/2019	PROG5038NRH60	Rheem	0
24820	02/23/2019	PROG5038NRH60	Rheem	0
24821	02/21/2019	PROG5038NRH60	Rheem	0
24822	02/18/2019	RG2DV50S6N	Bradford White	0
24823	02/18/2019	G82156	Rheem	0
24824	02/18/2019	PROG5038NRH60	Rheem	0
24825	02/27/2019	PROG5038NRH60	Rheem	0
24826	02/25/2019	PROG5038NRH60	Rheem	0
24827	02/26/2019	RG2DV50S6N	Bradford White	0
24828	03/01/2019	PROG5038NRH60	Rheem	0
24829	03/01/2019	PROG4860NRH60	RHEEM	0
24830	03/01/2019	PROG40S38NRH62	Rheem	0
24831	03/03/2019	PROG5038NRH60	Rheem	0
24832	03/02/2019	PROG40S38NRH62	Rheem	0
24833	02/28/2019	PROG50S40NRH61	Rheem	0
24834	02/26/2019	PROG40S38NRH62	Rheem	0
24835	02/28/2019	PROG50S40NRH61	Rheem	0
24836	02/28/2019	PROG40S38NRH62	Rheem	0
24837	02/26/2019	PROG5038NRH60	Rheem	1
24838	02/26/2019	PROG5038NRH60	Rheem	0
24839	02/26/2019	PROG5038NRH60	Rheem	0
24840	02/28/2019	PH19980	PHOENIX	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24841	02/24/2019	PROG40S38NRH62	Rheem	0
24842	02/27/2019	PROG40S38NRH62	Rheem	0
24843	03/02/2019	G91200	RHEEM	0
24844	03/01/2019	G91200	RHEEM	0
24845	03/01/2019	PROG5036NRH60DV	RHEEM	0
24846	03/02/2019	PROG5038NRH60	RHEEM	0
24847	03/01/2019	PROG5038NRH60	RHEEM	0
24848	02/27/2019	PROG50S40NRH61	RHEEM	0
24849	02/27/2019	PROG5038NRH60	RHEEM	0
24850	02/28/2019	PROG5038NRH60	RHEEM	0
24851	03/02/2019	PROG5038NRH60	RHEEM	0
24852	03/01/2019	PROG5038NRH60	RHEEM	0
24853	03/07/2019	PROG5038NRH60	Rheem	0
24854	03/04/2019	PROG5038NRH60	Rheem	0
24855	03/05/2019	PROG5038NRH60	Rheem	0
24856	03/05/2019	PROG5038NRH60	Rheem	0
24857	03/04/2019	PROG5038NRH60	Rheem	0
24858	03/08/2019	PROG5038NRH60	Rheem	0
24859	03/06/2019	PROG4860NRH60	RHEEM	0
24860	03/05/2019	PROG5038NRH60	Rheem	0
24861	03/04/2019	PROG5038NRH60	Rheem	0
24862	03/04/2019	RG2DV50S6N	Bradford White	0
24863	03/06/2019	PROG5038NRH60	Rheem	0
24864	03/08/2019	PROG40S38NRH62	Rheem	0
24865	03/09/2019	PROG4038NRH62	Rheem	0
24866	02/19/2019	PROG5038NRH60	Rheem	0
24867	03/08/2019	PROG5038NRH60	RHEEM	0
24868	03/05/2019	PROG5038NRH60	RHEEM	0
24869	03/10/2019	PROG5038NRH60	RHEEM	0
24870	03/10/2019	PROG40S38NRH62	RHEEM	0
24871	03/04/2019	PROG4860NRH60	RHEEM	0
24872	03/07/2019	PROG5038NRH60	RHEEM	0
24873	03/07/2019	PROG5038NRH60	RHEEM	0
24874	03/10/2019	PROG5038NRH60	RHEEM	0
24875	03/10/2019	PROG50S40NRH61	RHEEM	0
24876	03/09/2019	PROG4038NRH62	RHEEM	0
24877	03/09/2019	PROG40S38NRH62	RHEEM	0
24878	03/08/2019	PROG50S40NRH61	RHEEM	0
24879	03/13/2019	PROG50S40NRH61	RHEEM	0
24880	03/14/2019	PROG5038NRH60	RHEEM	0
24881	03/16/2019	PROG5038NRH60	RHEEM	0
24882	03/12/2019	PROG5038NRH60	RHEEM	0
24883	03/15/2019	PROG5038NRH60	RHEEM	0
24884	03/18/2019	PROG5038NRH60	RHEEM	0
24885	03/17/2019	PROG5036NRH60DV	RHEEM	0
24886	03/17/2019	PROG5038NRH60	RHEEM	0
24887	03/14/2019	GSN040	LOCHINVAR	0
24888	03/17/2019	G75125	RHEEM	0
24889	03/16/2019	PH19955	Phoenix	0
24890	03/14/2019	PROG50S40NRH61	RHEEM	0
24891	03/14/2019	PROG5038NRH60	Rheem	0
24892	03/14/2019	GSN040	Lochinvar	0
24893	03/14/2019	GSN040	LOCHINVAR	0
24894	03/12/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24895	03/17/2019	PROG4038NRH62	Rheem	0
24896	03/17/2019	PROG5038NRH60	Rheem	0
24897	03/17/2019	PROG5038NRH60	Rheem	0
24898	03/16/2019	PROG40S38NRH62	RHEEM	0
24899	03/15/2019	PROG5038NRH60	Rheem	0
24900	03/17/2019	PROG5038NRH60	Rheem	0
24901	03/11/2019	PROG5038NRH60	Rheem	0
24902	03/15/2019	G91200	Rheem	0
24903	03/17/2019	PROG5038NRH60	Rheem	0
24904	03/22/2019	PROG5038NRH60	RHEEM	0
24905	03/21/2019	PROG5038NRH60	RHEEM	0
24906	03/18/2019	PROG5038NRH60	RHEEM	0
24907	03/18/2019	PROG5038NRH60	RHEEM	0
24908	03/19/2019	PROG5038NRH60	RHEEM	0
24909	03/14/2019	G75125	RHEEM	0
24910	03/18/2019	PROG5036NRH60DV	RHEEM	0
24911	03/21/2019	PROG5038NRH60	Rheem	0
24912	03/22/2019	PROG5038NRH60	Rheem	0
24913	03/24/2019	PROG40S38NRH62	RHEEM	0
24914	03/23/2019	PROG4038NRH62	Rheem	0
24915	03/18/2019	G75125	RHEEM	0
24916	03/20/2019	PROG5038NRH60	Rheem	0
24917	03/22/2019	G75125	Rheem	0
24918	03/19/2019	PROG5038NRH60	Rheem	0
24919	03/19/2019	RG2DV50S6N	Bradford White	0
24920	03/23/2019	PROG5038NRH60	Rheem	0
24921	03/18/2019	PROG30S30NRH63	RHEEM	0
24922	03/21/2019	PROG5038NRH60	RHEEM	0
24923	03/23/2019	PROG5038NRH60	RHEEM	0
24924	03/21/2019	PH199119	PHOENIX	0
24925	03/22/2019	PROG5038NRH60	RHEEM	0
24926	03/18/2019	PROG40S38NRH62	RHEEM	0
24927	03/19/2019	PROG40S38NRH62	RHEEM	0
24928	03/23/2019	PROG50S40NRH61	Rheem	0
24929	03/22/2019	G75125	Rheem	0
24930	03/19/2019	PROG5038NRH60	Rheem	0
24931	04/05/2019	PROG5038NRH60	Rheem	0
24932	04/04/2019	PROG5038NRH60	Rheem	0
24933	04/08/2019	RG2DV50S6N	Bradford White	0
24934	04/06/2019	PROG5038NRH60	Rheem	0
24935	04/06/2019	PROG4038NRH62	RHEEM	0
24936	04/04/2019	LTN050G	LOCHINVAR	0
24937	04/08/2019	PROG4038NRH62	Rheem	0
24938	03/31/2019	PROG4038NRH62	RHEEM	0
24939	04/01/2019	PROG5038NRH60	RHEEM	0
24940	03/28/2019	RG2DV50S6N	BRADFORD WHITE	0
24941	03/31/2019	PROG5038NRH60	RHEEM	0
24942	03/30/2019	PROG5038NRH60	RHEEM	0
24943	03/30/2019	PROG5038NRH60	RHEEM	0
24944	03/31/2019	PROG5038NRH60	RHEEM	0
24945	03/31/2019	PROG5038NRH60	RHEEM	0
24946	03/30/2019	PROG5038NRH60	RHEEM	0
24947	03/30/2019	G76200	RHEEM	0
24948	03/31/2019	G82156	RHEEM	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
24949	03/26/2019	G82156	RHEEM	0
24950	03/28/2019	PROG5038NRH60	RHEEM	0
24951	03/26/2019	PROG4038NRH62	RHEEM	0
24952	03/29/2019	PROG4038NRH62	RHEEM	0
24953	03/25/2019	RG2DV50S6N	BRADFORD WHITE	0
24954	03/29/2019	G91200	RHEEM	0
24955	03/13/2019	G75125	RHEEM	0
24956	04/02/2019	PROG5038NRH60	RHEEM	0
24957	04/04/2019	PROG5038NRH60	RHEEM	0
24958	04/05/2019	PROG5036NRH60DV	RHEEM	0
24959	04/05/2019	PROG50S40NRH61	RHEEM	0
24960	04/05/2019	PROG5038NRH60	RHEEM	0
24961	04/05/2019	PROG5038NRH60	RHEEM	0
24962	04/05/2019	PROG5038NRH60	RHEEM	0
24963	04/06/2019	PROG5038NRH60	RHEEM	0
24964	04/04/2019	PROG4038NRH62	RHEEM	0
24965	04/04/2019	PROG5036NRH60DV	RHEEM	0
24966	04/01/2019	PROG5038NRH60	RHEEM	0
24967	04/02/2019	G91200	RHEEM	0
24968	04/04/2019	PROG5038NRH60	RHEEM	0
24969	04/02/2019	PROG40S38NRH62	RHEEM	0
24970	04/02/2019	PROG5038NRH60	RHEEM	0
24971	04/09/2019	PROG5038NRH60	RHEEM	0
24972	04/11/2019	PROG5038NRH60	RHEEM	0
24973	04/13/2019	G75125	RHEEM	0
24974	04/10/2019	PROG5036NRH60DV	RHEEM	0
24975	04/12/2019	PROG5038NRH60	RHEEM	0
24976	04/11/2019	PROG4038NRH62	RHEEM	0
24977	04/10/2019	PROG50S40NRH61	RHEEM	0
24978	04/10/2019	PROG5038NRH60	RHEEM	0
24979	04/09/2019	PROG50S40NRH61	RHEEM	0
24980	04/11/2019	PROG5038NRH60	RHEEM	0
24981	04/15/2019	PROG5038NRH60	Rheem	0
24982	04/13/2019	PROG50S40NRH61	Rheem	0
24983	04/12/2019	PROG5038NRH60	RHEEM	0
24984	04/11/2019	PROG5038NRH60	Rheem	0
24985	04/14/2019	PROG5038NRH60	Rheem	0
24986	04/12/2019	RG2DV40S6NSLD	Bradford White	0
24987	04/09/2019	PROG5038NRH60	Rheem	0
24988	04/10/2019	PROG5038NRH60	Rheem	0
24989	04/10/2019	PROG5038NRH60	Rheem	0
24990	04/16/2019	PROG5038NRH60	RHEEM	0
24991	04/19/2019	PROG5038NRH60	RHEEM	0
24992	04/19/2019	PROG5038NRH60	RHEEM	0
24993	04/18/2019	PROG5036NRH60DV	RHEEM	0
24994	04/19/2019	PROG50S40NRH61	RHEEM	0
24995	04/19/2019	PROG40S38NRH62	RHEEM	0
24996	04/19/2019	PROG5038NRH60	RHEEM	0
24997	04/20/2019	PROG4860NRH60	RHEEM	0
24998	04/18/2019	PROG5038NRH60	RHEEM	0
24999	04/16/2019	PROG5038NRH60	RHEEM	0
25000	04/21/2019	PROG5038NRH60	RHEEM	0
25001	04/15/2019	G91200	Rheem	1
25002	04/17/2019	RG2DV50S6N	Bradford White	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25003	04/21/2019	PROG5038NRH60	Rheem	0
25004	04/20/2019	PROG4038NRH62	Rheem	0
25005	04/21/2019	PROG5038NRH60	Rheem	0
25006	04/20/2019	RG2DV50S6N	Bradford White	0
25007	04/20/2019	PROG5038NRH60	Rheem	0
25008	04/19/2019	PROG5038NRH60	Rheem	0
25009	04/18/2019	PROG7576NRH	Rheem	0
25010	04/15/2019	PROG5038NRH60	Rheem	0
25011	04/24/2019	PROG5038NRH60	RHEEM	0
25012	04/26/2019	PROG5038NRH60	RHEEM	0
25013	04/24/2019	PROG5038NRH60	RHEEM	0
25014	04/22/2019	PROG5038NRH60	RHEEM	0
25015	04/26/2019	PROG5036NRH60DV	RHEEM	0
25016	04/23/2019	PROG5038NRH60	RHEEM	0
25017	04/22/2019	PROG40S38NRH62	RHEEM	0
25018	04/23/2019	PROG5038NRH60	RHEEM	0
25019	04/27/2019	PROG5036NRH60DV	RHEEM	0
25020	04/23/2019	PROG4038NRH62	RHEEM	0
25021	04/28/2019	PROG5038NRH60	RHEEM	0
25022	04/23/2019	PROG5038NRH60	Rheem	0
25023	04/24/2019	PROG5038NRH60	Rheem	0
25024	04/26/2019	PROG5038NRH60	Rheem	0
25025	04/28/2019	PROG40S38NRH62	Rheem	0
25026	04/25/2019	PROG5038NRH60	Rheem	0
25027	04/22/2019	PROG5038NRH60	Rheem	0
25028	04/22/2019	PROG5038NRH60	Rheem	0
25029	04/25/2019	PROG5038NRH60	Rheem	0
25030	04/23/2019	PROG4038NRH62	Rheem	0
25031	04/26/2019	PROG50S40NRH61	RHEEM	0
25032	04/25/2019	RG250T6N	Bradford White	0
25033	05/19/2019	PROG5038NRH60	RHEEM	0
25034	05/19/2019	PROG5038NRH60	RHEEM	0
25035	05/15/2019	PROG2932NRH63	RHEEM	0
25036	05/17/2019	PROG40S38NRH62	RHEEM	0
25037	05/15/2019	PROG5038NRH60	RHEEM	0
25038	05/13/2019	PROG5038NRH60	RHEEM	0
25039	05/18/2019	PROG5038NRH60	RHEEM	0
25040	05/16/2019	PROG5038NRH60	RHEEM	0
25041	04/30/2019	PROG5038NRH60	Rheem	0
25042	05/03/2019	PROG4038NRH62	Rheem	0
25043	05/03/2019	G76200	Rheem	0
25044	05/03/2019	PROG40S38NRH62	Rheem	0
25045	05/01/2019	PROG5038NRH60	Rheem	0
25046	05/05/2019	PROG5038NRH60	Rheem	0
25047	05/05/2019	PROG5036NRU60DV	Rheem	0
25048	04/30/2019	PROG5038NRH60	Rheem	0
25049	04/15/2019	G91200	Rheem	0
25050	05/02/2019	PROG5038NRH60	Rheem	0
25051	05/10/2019	PROG5038NRH60	Rheem	0
25052	05/10/2019	PROG5038NRH60	Rheem	0
25053	05/07/2019	PROG5038NRH60	Rheem	0
25054	05/09/2019	PROG5038NRH60	Rheem	0
25055	05/09/2019	BTH199	AO Smith	0
25056	05/07/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25057	05/07/2019	PROG5038NRH60	Rheem	0
25058	05/08/2019	RG2DV50S6N	Bradford White	0
25059	05/11/2019	PROG2932NRU62	Rheem	0
25060	05/09/2019	PROG5038NRH60	Rheem	0
25061	04/30/2019	PROG5038NRH60	Rheem	0
25062	04/16/2019	PROG5038NRH60	RHEEM	0
25063	05/02/2019	RG2DV50S6N	BRADFORD WHITE	0
25064	05/02/2019	RG2DV50S6N	BRADFORD WHITE	0
25065	05/03/2019	PROG5036NRH60DV	RHEEM	0
25066	05/05/2019	PROG40S38NRH62	RHEEM	0
25067	05/03/2019	PROG4038NRH62	RHEEM	0
25068	05/05/2019	PROG5038NRH60	RHEEM	0
25069	05/02/2019	PROG4038NRH62	RHEEM	0
25070	05/02/2019	PROG5038NRH60	RHEEM	0
25071	05/03/2019	PROG5038NRH60	RHEEM	0
25072	04/29/2019	PROG5036NRH60DV	RHEEM	0
25073	05/03/2019	PROG4038NRH62	RHEEM	0
25074	05/05/2019	RG250H6N	RHEEM	0
25075	05/01/2019	RG2DV50S6N	BRADFORD WHITE	0
25076	04/30/2019	PROG40S38NRH62	RHEEM	0
25077	05/01/2019	PROG5038NRH60	RHEEM	0
25078	05/12/2019	PROG5038NRH60	RHEEM	0
25079	05/11/2019	PROG5038NRH60	RHEEM	0
25080	05/06/2019	G91200	RHEEM	0
25081	05/09/2019	PROG40S38NRH62	RHEEM	0
25082	05/08/2019	PROG4860NRH60	RHEEM	0
25083	05/11/2019	PROG5038NRH60	RHEEM	0
25084	05/06/2019	PROG4860NRH60	RHEEM	0
25085	05/06/2019	PROG5038NRH60	RHEEM	0
25086	05/10/2019	PROG5038NRH60	RHEEM	0
25087	05/08/2019	PROG4038NRH62	RHEEM	0
25088	05/08/2019	PROG5038NRH60	RHEEM	0
25089	05/07/2019	G76200	RHEEM	0
25090	05/06/2019	PROG5038NRH60	RHEEM	0
25091	05/07/2019	PROG5038NRH60	RHEEM	0
25092	05/10/2019	PROG5038NRH60	RHEEM	0
25093	05/16/2019	PROG5038NRH60	RHEEM	0
25094	05/15/2019	PROG5038NRH60	RHEEM	0
25095	05/16/2019	G91200	RHEEM	0
25096	05/18/2019	PROG5036NRH60DV	RHEEM	0
25097	05/13/2019	PROG5038NRH60	RHEEM	0
25098	05/15/2019	PROG5038NRH60	Rheem	0
25099	05/14/2019	PROG5038NRH60	Rheem	0
25100	05/14/2019	PROG5038NRH60	Rheem	0
25101	05/19/2019	PROG5038NRH60	Rheem	0
25102	05/18/2019	PROG5038NRH60	Rheem	0
25103	05/17/2019	PROG40S38NRH62	Rheem	0
25104	05/14/2019	PROG5036NRU60DV	Rheem	0
25105	05/13/2019	PROG5038NRH60	Rheem	0
25106	05/18/2019	PROG5038NRH60	Rheem	0
25107	05/13/2019	PROG5038NRH60	Rheem	0
25108	05/16/2019	PROG5036NRU60DV	Rheem	0
25109	05/17/2019	PROG5038NRH60	Rheem	0
25110	05/17/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25111	05/21/2019	PROG5038NRH60	RHEEM	0
25112	05/25/2019	PROG50S40NRH61	RHEEM	0
25113	05/21/2019	PROG5038NRH60	RHEEM	0
25114	05/20/2019	PROG5038NRH60	RHEEM	0
25115	05/25/2019	PROG5038NRH60	RHEEM	0
25116	05/20/2019	PROG5038NRH60	RHEEM	0
25117	05/23/2019	PROG5038NRH60	RHEEM	0
25118	05/21/2019	PROG5038NRH60	RHEEM	0
25119	05/25/2019	PROG5038NRH60	RHEEM	0
25120	05/20/2019	PROG5038NRH60	RHEEM	0
25121	05/21/2019	PROG5038NRH60	RHEEM	0
25122	05/21/2019	PROG5038NRH60	RHEEM	0
25123	06/05/2019	PROG5038NRH60	Rheem	0
25124	05/26/2019	PROG5038NRH60	Rheem	0
25125	05/24/2019	RG2DV50S6N	Bradford White	0
25126	05/21/2019	PROG2932NRU63	Rheem	0
25127	05/24/2019	PROG40S38NRH62	Rheem	0
25128	05/21/2019	PROG5038NRH60	Rheem	0
25129	05/21/2019	RG2DV50S6N	Bradford White	0
25130	05/23/2019	PROG5038NRH60	Rheem	0
25131	05/20/2019	G91200	Rheem	0
25132	05/24/2019	G76200	Rheem	0
25133	05/31/2019	PROG50S40NRH61	RHEEM	0
25134	06/01/2019	PROG5038NRH60	RHEEM	0
25135	05/28/2019	PROG5038NRH60	RHEEM	0
25136	05/29/2019	PROG5038NRH60	RHEEM	0
25137	05/29/2019	G91200	RHEEM	0
25138	05/31/2019	PROG5036NRH60DV	RHEEM	0
25139	06/02/2019	PROG5038NRH60	RHEEM	0
25140	05/30/2019	PROG4038NRH62	Rheem	0
25141	06/02/2019	PROG5038NRH60	Rheem	0
25142	05/29/2019	PROG50S40NRH61	Rheem	0
25143	05/31/2019	PROG5038NRH60	RHEEM	0
25144	05/30/2019	PROG5038NRH60	Rheem	0
25145	06/03/2019	PROG40S38NRH62	Rheem	0
25146	05/28/2019	PH199119	PHOENIX	0
25147	06/01/2019	PROG5038NRH60	Rheem	0
25148	06/01/2019	PROG5038NRH60	Rheem	0
25149	05/31/2019	PROG50S40NRH61	Rheem	1
25150	05/28/2019	PROG4038NRH62	Rheem	0
25151	06/02/2019	PROG5038NRH60	Rheem	0
25152	06/02/2019	PROG50S40NRH61	Rheem	0
25153	06/08/2019	G75125	RHEEM	0
25154	06/09/2019	PROG40S38NRH62	RHEEM	0
25155	06/06/2019	PROG40S38NRH62	RHEEM	0
25156	06/07/2019	PROG5038NRH60	RHEEM	0
25157	06/08/2019	PROG40S38NRH62	RHEEM	0
25158	06/08/2019	PROG5038NRH60	RHEEM	0
25159	06/07/2019	PROG5038NRH60	RHEEM	0
25160	06/04/2019	PROG5038NRH60	Rheem	0
25161	06/05/2019	PROG5038NRH60	Rheem	0
25162	06/04/2019	PROG40S38NRH62	Rheem	0
25163	06/06/2019	PROG5038NRH60	Rheem	0
25164	06/06/2019	PROG50S40NRH61	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25165	06/05/2019	PROG4038NRH62	RHEEM	0
25166	06/04/2019	PROG4038NRH62	Rheem	0
25167	06/03/2019	GSN040	Lochinvar	0
25168	06/03/2019	G91200	Rheem	0
25169	06/03/2019	PROG5038NRH60	Rheem	0
25170	06/03/2019	G91200	Rheem	0
25171	06/04/2019	PROG5036NRU60DV	Rheem	0
25172	06/07/2019	PROG40S38NRH62	Rheem	0
25173	06/14/2019	PROG5038NRH60	RHEEM	0
25174	06/16/2019	PROG5038NRH60	RHEEM	0
25175	06/10/2019	PROG5038NRH60	RHEEM	0
25176	06/13/2019	RG2DV40S6N	BRADFORD WHITE	0
25177	06/13/2019	PROG5038NRH60	RHEEM	0
25178	06/12/2019	PROG5038NRH60	RHEEM	0
25179	06/10/2019	PROG5038NRH60	RHEEM	0
25180	06/11/2019	PROG5036NRH60DV	RHEEM	0
25181	06/10/2019	PROG5038NRH60	RHEEM	0
25182	06/14/2019	PROG40S38NRH62	RHEEM	0
25183	06/10/2019	PROG4860NRH60	RHEEM	0
25184	06/11/2019	PROG5038NRH60	RHEEM	0
25185	06/12/2019	PROG5036NRH60DV	RHEEM	0
25186	06/12/2019	PROG40S38NRH62	RHEEM	0
25187	06/12/2019	PROG5036NRH60DV	RHEEM	0
25188	06/13/2019	PROG5038NRH60	RHEEM	0
25189	06/11/2019	PROG5036NRH60DV	RHEEM	0
25190	06/11/2019	PROG5038NRH60	RHEEM	0
25191	06/10/2019	G82156	RHEEM	0
25192	06/10/2019	PROG40S38NRH62	RHEEM	0
25193	06/14/2019	PROG5038NRH60	RHEEM	0
25194	06/15/2019	PROG50S40NRH61	RHEEM	0
25195	06/16/2019	PROG5038NRH60	RHEEM	0
25196	06/19/2019	PROG5038NRH60	Rheem	0
25197	06/18/2019	PROG5038NRH60	Rheem	0
25198	06/20/2019	PROG40S38NRH62	Rheem	0
25199	06/18/2019	PROG5038NRH60	Rheem	0
25200	06/21/2019	PROG5038NRH60	Rheem	0
25201	06/19/2019	PROG4038NRH62	Rheem	0
25202	06/20/2019	PROG40S38NRH62	Rheem	0
25203	06/17/2019	PROG4038NRH62	Rheem	0
25204	06/17/2019	PROG5038NRH60	Rheem	0
25205	06/21/2019	PROG40S38NRH62	Rheem	0
25206	06/19/2019	PROG5036NRU60DV	Rheem	0
25207	06/19/2019	G82156	Rheem	0
25208	06/21/2019	PROG40S38NRH62	Rheem	0
25209	06/19/2019	PROG5038NRH60	Rheem	0
25210	06/22/2019	PROG5038NRH60	Rheem	0
25211	06/18/2019	PROG50S40NRH61	Rheem	0
25212	06/21/2019	PROG40S38NRH62	Rheem	0
25213	06/20/2019	PROG5038NRH60	RHEEM	0
25214	06/20/2019	PROG5038NRH60	Rheem	0
25215	06/19/2019	PROG5038NRH60	Rheem	0
25216	06/21/2019	PROG5038NRH60	Rheem	0
25217	06/19/2019	PROG40S38NRH62	Rheem	0
25218	06/21/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25219	06/21/2019	PROG5038NRH60	Rheem	0
25220	06/16/2019	PROG2932NRU63	Rheem	0
25221	06/17/2019	PROG40S38NRH62	Rheem	0
25222	06/18/2019	PROG50S40NRH61	Rheem	0
25223	06/18/2019	PROG5038NRH60	Rheem	0
25224	06/19/2019	PROG4038NRH62	Rheem	0
25225	06/19/2019	PROG4038NRH62	Rheem	0
25226	06/20/2019	PROG5038NRH60	Rheem	0
25227	06/21/2019	PROG5038NRH60	Rheem	0
25228	06/24/2019	PROG5038NRH60	Rheem	0
25229	06/24/2019	PROG5038NRH60	Rheem	0
25230	06/20/2019	PROG40S38NRH62	Rheem	0
25231	06/19/2014	MI5036FBN	Bradford White	0
25232	06/25/2019	PROG5038NRH60	Rheem	0
25233	06/25/2019	PROG5038NRH60	Rheem	0
25234	06/25/2019	PROG5038NRH60	Rheem	0
25235	06/29/2019	G91200	Rheem	0
25236	06/29/2019	G91200	Rheem	0
25237	06/28/2019	RG250T6N	Bradford White	0
25238	05/31/2019	PROG5038NRH60	Rheem	0
25239	07/01/2019	PROG40S38NRH62	Rheem	0
25240	06/26/2019	RG2DV50S6N	Bradford White	0
25241	06/26/2019	PROG5038NRH60	Rheem	0
25242	06/28/2019	PROG40S38NRH62	Rheem	0
25243	06/25/2019	PROG40S38NRH62	Rheem	0
25244	06/29/2019	PROG5038NRH60	Rheem	0
25245	06/02/2019	G75125	Rheem	0
25246	07/07/2019	PROG4038NRH62	Rheem	0
25247	07/01/2019	PROG5038NRH60	Rheem	0
25248	07/05/2019	RG2DV40S6N	Bradford White	0
25249	07/01/2019	PROG5038NRH60	Rheem	0
25250	07/02/2019	PROG5038NRH60	Rheem	0
25251	07/02/2019	PROG5038NRH60	Rheem	0
25252	06/27/2019	PROG5038NRH60	Rheem	0
25253	06/29/2019	RG250H6N	Rheem	0
25254	06/29/2019	PROG5038NRH60	Rheem	0
25255	06/27/2019	PROG5038NRH60	Rheem	0
25256	06/24/2019	PROG4860NRH60	Rheem	0
25257	06/24/2019	RG250H6N	Rheem	0
25258	06/27/2019	PROG2932NRU63	Rheem	0
25259	06/27/2019	PROG50S40NRH61	Rheem	0
25260	06/27/2019	G91200	Rheem	0
25261	07/01/2019	PROG5038NRH60	Rheem	0
25262	07/08/2019	PROG5038NRH60	Rheem	0
25263	07/06/2019	PROG4038NRH62	Rheem	0
25264	07/07/2019	PROG5038NRH60	Rheem	0
25265	07/07/2019	PROG50S40NRH61	Rheem	0
25266	07/05/2019	PROG5038NRH60	Rheem	0
25267	07/02/2019	G91200	Rheem	0
25268	07/03/2019	PROG5038NRH60	Rheem	0
25269	07/03/2019	PROG5038NRH60	Rheem	0
25270	07/03/2019	PROG5038NRH60	Rheem	0
25271	07/05/2019	PROG4038NRH62	Rheem	0
25272	07/07/2019	PROG5038NRH60	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25273	07/06/2019	PROG40S38NRH62	Rheem	0
25274	07/02/2019	RG2DV50S6N	Bradford White	0
25275	07/02/2019	PROG2932NRU63	Rheem	0
25276	07/04/2019	PROG5038NRH60	Rheem	0
25277	07/05/2019	PROG5038NRH60	Rheem	0
25278	07/05/2019	PROG5038NRH60	Rheem	0
25279	07/07/2019	PROG5038NRH60	Rheem	0
25280	07/06/2019	PROG5036NRH60DV	Rheem	0
25281	07/14/2019	PROG5038NRH60	Rheem	0
25282	07/08/2019	PROG50S40NRH61	Rheem	0
25283	07/10/2019	RG2DV50S6N	Bradford White	0
25284	07/10/2019	PROG5038NRH60	Rheem	0
25285	07/11/2019	PROG5038NRH60	AO Smith	0
25286	07/12/2019	PROG5038NRH60	Rheem	0
25287	07/11/2019	PROG5038NRH60	Rheem	0
25288	07/12/2019	G75125	Rheem	0
25289	07/13/2019	PROG5038NRH60	Rheem	0
25290	07/14/2019	PROG40S38NRH62	Rheem	0
25291	07/08/2019	RG2DV50S6N	Bradford White	0
25292	07/10/2019	G75125	Rheem	0
25293	07/11/2019	G75125	Rheem	0
25294	07/11/2019	G75125	RHEEM	0
25295	07/11/2019	G75125	Rheem	0
25296	07/13/2019	G91200	Rheem	0
25297	07/08/2019	PROG5038NRH60	Rheem	0
25298	07/09/2019	PROG5038NRH60	Rheem	0
25299	07/09/2019	PROG5038NRH60	Rheem	0
25300	07/09/2019	PROG5038NRH60	Rheem	0
25301	07/12/2019	G76200	Rheem	0
25302	07/14/2019	PROG5038NRH60	Rheem	0
25303	07/12/2019	PROG4038NRH62	Rheem	0
25304	07/12/2019	RG2DV50S6N	Bradford White	0
25305	07/10/2019	PROG4038NRH62	Rheem	0
25306	07/10/2019	PROG5038NRH60	Rheem	0
25307	07/12/2019	PROG5038NRH60	Rheem	0
25308	07/08/2019	PROG4038NRH62	Rheem	0
25309	07/11/2019	PROG5038NRH60	Rheem	0
25310	07/09/2019	RG2DV50S6N	BRADFORD WHITE	0
25311	07/12/2019	PROG4038NRH62	Rheem	0
25312	07/08/2019	PROG2932NRU63	Rheem	0
25313	07/14/2019	PROG5038NRH60	Rheem	0
25314	07/19/2019	PROG5038NRH60	Rheem	0
25315	07/20/2019	PROG5038NRH60	Rheem	0
25316	07/19/2019	PROG5038NRH60	Rheem	0
25317	07/19/2019	PROG4038NRH62	Rheem	0
25318	07/17/2019	PROG5038NRH60	Rheem	0
25319	07/17/2019	PROG5038NRH60	Rheem	0
25320	07/18/2019	PROG5038NRH60	RHEEM	0
25321	07/20/2019	PROG4038NRH62	Rheem	0
25322	07/20/2019	PROG5038NRH60	Rheem	0
25323	07/18/2019	PROG5038NRH60	Rheem	0
25324	07/18/2019	PROG4038NRH62	Rheem	0
25325	07/20/2019	G75125	Rheem	0
25326	07/20/2019	PROG40S38NRH62	Rheem	0

Customer #	Installation Date	Model number	Manufacturer	No. of Repairs
25327	07/20/2019	PROG5038NRH60	Rheem	0
25328	07/17/2019	PROG5038NRH60	Rheem	0
25329	07/15/2019	PROG5038NRH60	Rheem	0
25330	07/16/2019	RG2DV40S6N	Bradford White	0
25331	07/17/2019	PROG5036NRH60DV	Rheem	0
25332	07/19/2019	G75125	Rheem	0
25333	07/19/2019	PROG5038NRH60	Rheem	0
25334	07/17/2019	PROG5038NRH60	Rheem	0
25335	07/19/2019	PROG5036NRH60DV	Rheem	0
25336	07/26/2019	PROG5038NRH60	Rheem	0
25337	07/26/2019	PROG5038NRH60	Rheem	0
25338	07/24/2019	PROG50S40NRH61	Rheem	0
25339	07/26/2019	PROG5038NRH60	Rheem	0
25340	07/24/2019	PROG5038NRH60	Rheem	0
25341	07/22/2019	PROG5036NRH60DV	Rheem	0
25342	07/22/2019	G65360	Rheem	0
25343	07/26/2019	PROG5038NRH60	Rheem	0
25344	07/26/2019	PROG5038NRH60	Rheem	0
25345	07/24/2019	PROG5036NRH60DV	Rheem	0
25346	07/24/2019	PROG4038NRH62	Rheem	0
25347	07/22/2019	G91200	Rheem	0
25348	07/24/2019	PROG5038NRH60	RHEEM	0
25349	07/23/2019	G91200	Rheem	0
25350	07/25/2019	PROG4038NRH62	Rheem	0
25351	07/29/2019	G91200	Rheem	0
25352	07/27/2019	PROG5038NRH60	Rheem	0
25353	07/25/2019	G91200	Rheem	0
25354	07/23/2019	PROG4860NRH60	Rheem	0
25355	07/23/2019	PROG5042NRH67PV	Rheem	0
25356	07/23/2019	PROG5038NRH60	Rheem	0
25357	07/23/2019	PROG4038NRH62	Rheem	0

BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION**Dockets UE-190529 & UG-190530
Puget Sound Energy
2019 General Rate Case****PUBLIC COUNSEL DATA REQUEST NO. 096:****Re: Water Heater Program.**

Please provide an updated response to Staff Informal Data Requests No. 007 from the Water Heater Rental Program Collaborative. Please provide by lease agreement number the following information:

- a) Commencement date of each lease agreement associated with each water heater.
- b) End date of each lease agreement (if applicable).
- c) If a lease automatically transformed into a month-to-month lease at the end of its term, the number of months that the customer was on the month-to-month lease as of the earlier of June 30, 2018, or the time the customer terminated the lease.
- d) Rate charged at commencement date of each lease agreement.
- e) Model, make, and efficiency of each water heater.
- f) Book value recorded by PSE when each water heater was initially installed.

Response:

Puget Sound Energy's ("PSE") Lease Agreements do not have their own unique number. PSE uses the equipment number.

- a. Please see Attachment A to PSE's Response to Public Counsel Data Request No. 096 for a report showing active leased water heaters; column C shows the "Commencement Date." Please see Attachment B to PSE's Response to Public Counsel Data Request No. 096 for a report showing inactive leased water heaters; column B shows the "Commencement Date."
- b. There is no end date on a PSE Lease Agreement.
- c. Please see Attachment B to PSE's Response to Public Counsel Data Request No. 096 for a report showing inactive leased equipment and those that have been retired from PSE's system, column H "Date Lease Terminated" and column J "No. of Months Leasing."

- d. Please see Attachment A to PSE's Response to Public Counsel Data Request No. 096 for a report showing active leased water heaters, column G "Rate Charged at Commencement." Please see Attachment B to PSE's Response to Public Counsel Data Request No. 096 for a report showing inactive leased water heaters, column I "Rate Charged at Commencement."
- e. The model and make for each water heater are included in Attachments A and B to PSE's Response to Public Counsel Data Request No. 096. Please see Attachment A for a report showing active leased water heaters, columns D "Model Number" and E "Make/Manufacturer"; and Attachment B for the report showing inactive leased water heaters. Model efficiency is not available.
- f. Please see Attachment A to PSE's Response to Public Counsel Data Request No. 096 for a report showing active leased water heaters, column F "Book Value at Initial Installation"; and Attachment B to PSE's Response to Public Counsel Data Request No. 096 for a report showing inactive leased water heaters, column C "Book Value at Initial Installation."

**ATTACHMENT A to PSE's Response to
PUBLIC COUNSEL Data Request No. 096**

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1	Installed/Active	01/06/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2	Installed/Active	10/08/1993	FSG40	AO SMITH	\$ 850.00	
3	Installed/Active	11/01/2000	41XR40	RHEEM	\$ 850.00	
4	Installed/Active	05/29/2002	FSG40	AO SMITH	\$ 850.00	
5	Installed/Active	04/10/1995	FGR30	AO SMITH	\$ 850.00	
6	Installed/Active	05/06/2002	FSG40	AO SMITH	\$ 850.00	
7	Installed/Active	08/17/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
8	Installed/Active	07/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
9	Installed/Active	04/18/2005	GVC50	A. O. SMITH	\$ 620.00	
10	Installed/Active	08/27/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
11	Installed/Active	08/25/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
12	Installed/Active	03/08/1999	FGR50	AO SMITH	\$ 850.00	
13	Installed/Active	06/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14	Installed/Active	11/03/2010	21VR40	RHEEM	\$ 850.00	\$ 6.04
15	Installed/Active	07/31/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
16	Installed/Active	02/12/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
17	Installed/Active	03/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
18	Installed/Active	05/30/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
19	Installed/Active	03/18/2005	XVR40	A. O. SMITH	\$ 850.00	
20	Installed/Active	05/03/2005	LTN050	LOCHINVAR	\$ 850.00	
21	Installed/Active	03/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
22	Installed/Active	01/22/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
23	Installed/Active	07/15/2002	FSG40	AO SMITH	\$ 850.00	
24	Installed/Active	12/13/2002	PGR30	AO SMITH	\$ 850.00	
25	Installed/Active	12/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
26	Installed/Active	05/21/2003	PGR50	AO SMITH	\$ 850.00	
27	Installed/Active	11/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
28	Installed/Active	12/14/2009	PRX50	STATE	\$ 1,075.00	\$ 16.47
29	Installed/Active	12/04/2005	LTN051G	LOCHINVAR	\$ 1,150.00	
30	Installed/Active	05/17/2001	FSG50	AO SMITH	\$ 850.00	
31	Installed/Active	07/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
32	Installed/Active	09/26/2001	FSG50	AO SMITH	\$ 850.00	
33	Installed/Active	02/07/2001	41V50	RHEEM	\$ 850.00	
34	Installed/Active	06/23/2003	FSG50	AO SMITH	\$ 850.00	
35	Installed/Active	03/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
36	Installed/Active	11/06/2002	FSGL40	AO SMITH	\$ 850.00	
37	Installed/Active	02/13/2007	FSG50	AO SMITH	\$ 850.00	\$ 10.23
38	Installed/Active	04/14/1988	FSG50	AO SMITH	\$ 850.00	
39	Installed/Active	10/29/2000	41XR40	RHEEM	\$ 850.00	
40	Installed/Active	12/13/1988	FSG50	AO SMITH	\$ 850.00	
41	Installed/Active	04/09/2003	FSG50	AO SMITH	\$ 850.00	
42	Installed/Active	11/23/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
43	Installed/Active	08/21/1998	FGR50	AO SMITH	\$ 850.00	
44	Installed/Active	06/28/1999	FSG50	AO SMITH	\$ 850.00	
45	Installed/Active	05/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
46	Installed/Active	10/16/2006	PR650X0DS	STATE	\$ 1,075.00	
47	Installed/Active	04/14/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
48	Installed/Active	02/20/2005	XVR50	A. O. SMITH	\$ 850.00	
49	Installed/Active	09/13/2006	PR650	STATE	\$ 1,075.00	
50	Installed/Active	12/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
51	Installed/Active	03/17/2000	FSG50	AO SMITH	\$ 850.00	
52	Installed/Active	05/27/2000	41XR50	RHEEM	\$ 850.00	
53	Installed/Active	03/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
54	Installed/Active	12/07/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
55	Installed/Active	09/27/1997	41XR50	RHEEM	\$ 850.00	
56	Installed/Active	04/30/2003	FSG50	AO SMITH	\$ 850.00	
57	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
58	Installed/Active	06/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
59	Installed/Active	01/11/2002	PGR50	AO SMITH	\$ 850.00	
60	Installed/Active	06/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
61	Installed/Active	08/29/2005	LTN050G	LOCHINVAR	\$ 850.00	
62	Installed/Active	10/19/2004	PGR50	AO SMITH	\$ 850.00	
63	Installed/Active	02/04/2004	FCV50	AO SMITH	\$ 850.00	
64	Installed/Active	05/25/1988	FSG50	AO SMITH	\$ 850.00	
65	Installed/Active	04/13/2005	GVC50	A. O. SMITH	\$ 850.00	
66	Installed/Active	09/23/1988	PRX50	STATE	\$ 1,075.00	
67	Installed/Active	11/02/1970	PGX40	AO SMITH	\$ 850.00	
68	Installed/Active	06/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
69	Installed/Active	08/25/2010	GVC50	A. O. SMITH	\$ 850.00	\$ 7.51
70	Installed/Active	05/18/2000	21V506	RHEEM	\$ 1,125.00	
71	Installed/Active	06/22/2005	LTN050	LOCHINVAR	\$ 850.00	
72	Installed/Active	01/19/2005	GVC50	A. O. SMITH	\$ 850.00	
73	Installed/Active	05/24/1995	PR502T	RUUD	\$ 850.00	
74	Installed/Active	07/31/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
75	Installed/Active	12/01/1970	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
76	Installed/Active	03/22/1994	FGR50	AO SMITH	\$ 850.00	
77	Installed/Active	04/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
78	Installed/Active	06/28/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
79	Installed/Active	11/03/2005	LTN040G	LOCHINVAR	\$ 850.00	
80	Installed/Active	10/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
81	Installed/Active	02/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
82	Installed/Active	11/10/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
83	Installed/Active	01/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
84	Installed/Active	04/18/2003	PGR50	AO SMITH	\$ 850.00	
85	Installed/Active	01/09/2003	FSG40	AO SMITH	\$ 850.00	
86	Installed/Active	12/13/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
87	Installed/Active	04/01/1971	PGX40	AO SMITH	\$ 850.00	
88	Installed/Active	10/12/2000	21V506	RHEEM	\$ 1,125.00	
89	Installed/Active	05/18/1997	FSG50	AO SMITH	\$ 850.00	
90	Installed/Active	04/20/2001	FSG40	AO SMITH	\$ 850.00	
91	Installed/Active	10/09/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
92	Installed/Active	04/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
93	Installed/Active	10/15/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
94	Installed/Active	06/24/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
95	Installed/Active	03/31/2011	PH199119	PHOENIX	\$ 3,350.00	\$ 61.05
96	Installed/Active	07/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
97	Installed/Active	03/07/1997	PGR40	AO SMITH	\$ 850.00	
98	Installed/Active	07/28/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
99	Installed/Active	07/04/1998	FGR40	AO SMITH	\$ 850.00	
100	Installed/Active	01/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
101	Installed/Active	07/08/2000	FSG50	AO SMITH	\$ 850.00	
102	Installed/Active	12/06/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
103	Installed/Active	03/29/2003	FSGL40	AO SMITH	\$ 850.00	
104	Installed/Active	11/21/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
105	Installed/Active	08/14/2008	RM5063	RHEEM	\$ 500.00	\$ 16.35
106	Installed/Active	04/17/2003	BTC198	AO SMITH	\$ 3,350.00	
107	Installed/Active	01/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
108	Installed/Active	09/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
109	Installed/Active	10/09/1992	P506	RUUD	\$ 1,125.00	
110	Installed/Active	12/16/2010	21V502	RHEEM	\$ 1,125.00	\$ 19.26
111	Installed/Active	01/23/2004	XTN040	LOCHINVAR	\$ 850.00	
112	Installed/Active	09/03/2008	FSG30	AO SMITH	\$ 850.00	\$ 6.37
113	Installed/Active	03/31/2000	FSG40	AO SMITH	\$ 850.00	
114	Installed/Active	03/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
115	Installed/Active	06/27/2005	LTN050	LOCHINVAR	\$ 850.00	
116	Installed/Active	09/29/2003	PGR50	AO SMITH	\$ 850.00	
117	Installed/Active	01/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
118	Installed/Active	09/22/2004	GVC50	A. O. SMITH	\$ 850.00	
119	Installed/Active	11/17/1988	FSG40	AO SMITH	\$ 850.00	
120	Installed/Active	03/21/1995	PR407	RUUD	\$ 850.00	
121	Installed/Active	10/04/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
122	Installed/Active	03/25/2002	PGR50	AO SMITH	\$ 850.00	
123	Installed/Active	06/13/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
124	Installed/Active	06/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
125	Installed/Active	09/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
126	Installed/Active	10/01/1968	FSGL40	AO SMITH	\$ 850.00	
127	Installed/Active	11/21/1997	FSG40	AO SMITH	\$ 850.00	
128	Installed/Active	11/27/1995	PR502T	RUUD	\$ 850.00	
129	Installed/Active	12/11/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
130	Installed/Active	07/22/2003	FSG40	AO SMITH	\$ 850.00	
131	Installed/Active	12/21/2001	41XR50	RHEEM	\$ 850.00	
132	Installed/Active	10/09/2001	FSGL40	AO SMITH	\$ 850.00	
133	Installed/Active	05/17/2005	LTN050	LOCHINVAR	\$ 850.00	
134	Installed/Active	01/13/2001	41V40	RHEEM	\$ 850.00	
135	Installed/Active	01/03/2002	FSG40	AO SMITH	\$ 850.00	
136	Installed/Active	08/01/1966	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
137	Installed/Active	05/11/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 5.12
138	Installed/Active	08/18/1999	FSG50	AO SMITH	\$ 850.00	
139	Installed/Active	03/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
140	Installed/Active	08/17/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
141	Installed/Active	07/21/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
142	Installed/Active	06/09/2000	FSG30	AO SMITH	\$ 850.00	
143	Installed/Active	02/01/1965	PGX30	AO SMITH	\$ 850.00	
144	Installed/Active	09/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
145	Installed/Active	05/29/2001	41XR40	RHEEM	\$ 850.00	
146	Installed/Active	10/27/1995	FGR30	AO SMITH	\$ 850.00	
147	Installed/Active	07/12/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
148	Installed/Active	12/26/2003	FCV50	AO SMITH	\$ 850.00	
149	Installed/Active	04/05/2001	FSG50	AO SMITH	\$ 850.00	
150	Installed/Active	02/07/2005	GVC40	A. O. SMITH	\$ 850.00	
151	Installed/Active	05/30/2003	FSG40	AO SMITH	\$ 850.00	
152	Installed/Active	03/18/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
153	Installed/Active	02/18/1997	G91200	RUUD/RHEEM	\$ 3,350.00	
154	Installed/Active	05/04/1998	FGR50	AO SMITH	\$ 850.00	
155	Installed/Active	09/18/1998	41VR50	RHEEM	\$ 850.00	
156	Installed/Active	07/17/2002	FSG40	AO SMITH	\$ 850.00	
157	Installed/Active	04/05/2000	PGR40	AO SMITH	\$ 850.00	
158	Installed/Active	11/04/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
159	Installed/Active	09/20/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
160	Installed/Active	10/28/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
161	Installed/Active	04/06/2004	FCV40	AO SMITH	\$ 850.00	
162	Installed/Active	07/01/1966	PGX40	AO SMITH	\$ 850.00	
163	Installed/Active	02/07/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
164	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
165	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
166	Installed/Active	03/21/2002	FSG40	AO SMITH	\$ 850.00	
167	Installed/Active	12/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
168	Installed/Active	11/18/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
169	Installed/Active	07/09/2004	GVC40	A. O. SMITH	\$ 850.00	
170	Installed/Active	12/22/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
171	Installed/Active	03/14/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
172	Installed/Active	03/07/2003	PGR40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
173	Installed/Active	01/23/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
174	Installed/Active	11/08/2004	GVC40	A. O. SMITH	\$ 850.00	
175	Installed/Active	05/03/2000	FSG40	AO SMITH	\$ 850.00	
176	Installed/Active	09/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
177	Installed/Active	06/20/2001	FSG40	AO SMITH	\$ 850.00	
178	Installed/Active	11/08/2012	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.95
179	Installed/Active	08/24/2001	FSGL40	AO SMITH	\$ 850.00	
180	Installed/Active	10/16/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
181	Installed/Active	07/03/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
182	Installed/Active	03/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
183	Installed/Active	09/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
184	Installed/Active	07/23/2003	FSG30	AO SMITH	\$ 850.00	
185	Installed/Active	06/09/2011	41VR40	RHEEM	\$ 850.00	\$ 6.34
186	Installed/Active	08/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
187	Installed/Active	12/02/1993	FGR50	AO SMITH	\$ 850.00	
188	Installed/Active	03/10/1999	21V407	RHEEM	\$ 850.00	
189	Installed/Active	01/18/2011	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
190	Installed/Active	01/03/1999	FSGL40	AO SMITH	\$ 850.00	
191	Installed/Active	06/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
192	Installed/Active	12/21/2004	GVC30	AOSMITH	\$ 850.00	
193	Installed/Active	05/26/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
194	Installed/Active	11/06/2002	PGR50	AO SMITH	\$ 850.00	
195	Installed/Active	05/22/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
196	Installed/Active	01/11/1999	PHR50	RUUD	\$ 850.00	
197	Installed/Active	03/06/1998	G67114	RHEEM	\$ 1,900.00	
198	Installed/Active	10/17/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
199	Installed/Active	04/10/2001	FSG40	AO SMITH	\$ 850.00	
200	Installed/Active	05/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
201	Installed/Active	06/28/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
202	Installed/Active	01/29/2013	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	\$ 6.39
203	Installed/Active	01/15/1999	FSG50	AO SMITH	\$ 850.00	
204	Installed/Active	08/25/1999	FSG50	AO SMITH	\$ 850.00	
205	Installed/Active	06/03/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
206	Installed/Active	01/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
207	Installed/Active	08/01/1964	PGX30	AO AMITH	\$ 850.00	
208	Installed/Active	02/06/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
209	Installed/Active	01/22/2004	PVR40	AO SMITH	\$ 850.00	
210	Installed/Active	09/30/1999	G72DUMMY	AO SMITH	\$ 1,125.00	
211	Installed/Active	10/22/2010	21VR40	RHEEM	\$ 850.00	\$ 6.04
212	Installed/Active	10/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
213	Installed/Active	02/06/2004	PVR40	AO SMITH	\$ 850.00	
214	Installed/Active	06/19/2004	GVC40	A. O. SMITH	\$ 850.00	
215	Installed/Active	11/03/2000	FSG40	AO SMITH	\$ 850.00	
216	Installed/Active	08/11/1994	PGR30	AO SMITH	\$ 850.00	
217	Installed/Active	05/26/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
218	Installed/Active	11/08/2000	FSG40	AO SMITH	\$ 850.00	
219	Installed/Active	02/22/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
220	Installed/Active	06/30/2009	LTN030G	AO SMITH	\$ 850.00	\$ 7.31
221	Installed/Active	01/06/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
222	Installed/Active	02/07/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
223	Installed/Active	03/10/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
224	Installed/Active	01/18/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
225	Installed/Active	12/08/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
226	Installed/Active	07/19/1993	FSG40	AO SMITH	\$ 850.00	
227	Installed/Active	03/26/2002	FSG30	AO SMITH	\$ 850.00	
228	Installed/Active	08/11/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
229	Installed/Active	08/23/2002	FSG50	AO SMITH	\$ 850.00	
230	Installed/Active	12/26/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
231	Installed/Active	03/14/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
232	Installed/Active	08/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
233	Installed/Active	08/16/2001	FSG40	AO SMITH	\$ 850.00	
234	Installed/Active	02/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
235	Installed/Active	03/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
236	Installed/Active	10/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
237	Installed/Active	03/04/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
238	Installed/Active	01/18/2001	FSGL40	AO SMITH	\$ 850.00	
239	Installed/Active	05/01/1967	PGXL40	AO SMITH	\$ 850.00	
240	Installed/Active	06/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
241	Installed/Active	10/01/1967	KGA40	AO SMITH	\$ 850.00	
242	Installed/Active	05/06/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
243	Installed/Active	05/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
244	Installed/Active	06/09/2003	FSG50	AO SMITH	\$ 850.00	
245	Installed/Active	05/15/2006	LTN040G	LOCHINVAR	\$ 850.00	
246	Installed/Active	01/19/2004	FCV30	AO SMITH	\$ 850.00	
247	Installed/Active	07/13/1998	G72DUMMY	AO SMITH	\$ 1,125.00	
248	Installed/Active	02/13/2001	FSG40	AO SMITH	\$ 850.00	
249	Installed/Active	05/25/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
250	Installed/Active	01/02/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
251	Installed/Active	12/14/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
252	Installed/Active	07/05/2005	LSN041G	LOCHINVAR	\$ 850.00	
253	Installed/Active	12/13/2001	PGR50	AO SMITH	\$ 850.00	
254	Installed/Active	01/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
255	Installed/Active	07/17/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
256	Installed/Active	05/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
257	Installed/Active	12/08/1997	G67114	RHEEM	\$ 1,900.00	
258	Installed/Active	04/06/1998	FSG30	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
259	Installed/Active	11/21/2003	FCV40	AO SMITH	\$ 850.00	
260	Installed/Active	07/16/2001	41VR50	RHEEM	\$ 850.00	
261	Installed/Active	09/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
262	Installed/Active	09/12/2002	FSGL40	AO SMITH	\$ 850.00	
263	Installed/Active	11/26/2002	BTR154	AO SMITH	\$ 3,350.00	
264	Installed/Active	04/10/2001	41XR40	RHEEM	\$ 850.00	
265	Installed/Active	01/08/1996	PGR50	AO SMITH	\$ 850.00	
266	Installed/Active	01/11/2005	GVC30	AOSMITH	\$ 850.00	
267	Installed/Active	11/15/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
268	Installed/Active	02/16/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
269	Installed/Active	10/18/1998	FSG40	AO SMITH	\$ 850.00	
270	Installed/Active	02/01/1981	KGA30	AO SMITH	\$ 850.00	
271	Installed/Active	04/25/2011	FSG30	AO SMITH	\$ 850.00	\$ 7.88
272	Installed/Active	09/08/1997	FSG30	AO SMITH	\$ 850.00	
273	Installed/Active	02/08/2007	LTN050G	LOCHINVAR	\$ 350.00	\$ 12.50
274	Installed/Active	04/06/1988	21V506	RHEEM	\$ 850.00	
275	Installed/Active	03/18/1999	FGR50	AO SMITH	\$ 850.00	
276	Installed/Active	01/14/2005	GVC30	AOSMITH	\$ 850.00	
277	Installed/Active	03/29/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
278	Installed/Active	03/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
279	Installed/Active	11/06/2001	FSG40	AO SMITH	\$ 850.00	
280	Installed/Active	08/06/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
281	Installed/Active	05/21/2001	41XR50	RHEEM	\$ 850.00	
282	Installed/Active	01/29/2001	FSG30	AO SMITH	\$ 850.00	
283	Installed/Active	10/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
284	Installed/Active	01/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
285	Installed/Active	04/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
286	Installed/Active	09/03/2011	P230F	RUUD	\$ 850.00	\$ 6.34
287	Installed/Active	08/19/2004	GVC40	A. O. SMITH	\$ 850.00	
288	Installed/Active	08/14/2003	FSG30	AO SMITH	\$ 850.00	
289	Installed/Active	03/26/2001	21V407	RHEEM	\$ 850.00	
290	Installed/Active	05/29/1998	FSG30	AO SMITH	\$ 850.00	
291	Installed/Active	04/08/2005	XVR50	A. O. SMITH	\$ 850.00	
292	Installed/Active	10/04/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
293	Installed/Active	03/27/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
294	Installed/Active	02/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
295	Installed/Active	05/25/2005	LTN050	LOCHINVAR	\$ 850.00	
296	Installed/Active	06/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
297	Installed/Active	09/05/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
298	Installed/Active	03/11/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
299	Installed/Active	01/20/2009	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
300	Installed/Active	04/24/2001	FSG40	AO SMITH	\$ 850.00	
301	Installed/Active	10/13/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
302	Installed/Active	11/09/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
303	Installed/Active	01/11/2005	GVR50	AO SMITH	\$ 850.00	
304	Installed/Active	01/01/1960	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
305	Installed/Active	03/19/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 5.12
306	Installed/Active	06/05/2003	FGR40	AO SMITH	\$ 850.00	
307	Installed/Active	10/27/2004	GVC50	A. O. SMITH	\$ 850.00	
308	Installed/Active	07/24/1969	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
309	Installed/Active	10/26/2004	42XR50	RHEEM	\$ 850.00	
310	Installed/Active	05/03/2005	LSN041G	LOCHINVAR	\$ 850.00	
311	Installed/Active	06/01/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
312	Installed/Active	06/19/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
313	Installed/Active	11/10/2004	XVR40	A. O. SMITH	\$ 850.00	
314	Installed/Active	10/28/2011	FSGL40	AO SMITH	\$ 850.00	\$ 12.64
315	Installed/Active	03/17/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
316	Installed/Active	02/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
317	Installed/Active	05/10/2005	GVC40	A. O. SMITH	\$ 850.00	
318	Installed/Active	10/20/2009	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
319	Installed/Active	08/11/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
320	Installed/Active	10/05/2010	41V50	RHEEM	\$ 850.00	\$ 6.04
321	Installed/Active	10/01/2001	41V40S	RHEEM	\$ 850.00	
322	Installed/Active	06/12/1996	PR407	RUUD	\$ 850.00	
323	Installed/Active	11/14/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
324	Installed/Active	01/29/2001	41XR40	RHEEM	\$ 850.00	
325	Installed/Active	02/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
326	Installed/Active	11/14/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
327	Installed/Active	10/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
328	Installed/Active	02/04/2011	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
329	Installed/Active	09/12/2002	FSGL40	AO SMITH	\$ 850.00	
330	Installed/Active	08/30/2010	LTN030G	AO SMITH	\$ 850.00	\$ 6.04
331	Installed/Active	06/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
332	Installed/Active	04/03/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
333	Installed/Active	02/29/2000	FSG50	AO SMITH	\$ 850.00	
334	Installed/Active	08/26/1997	RFD91200	RUUD	\$ 3,350.00	
335	Installed/Active	06/29/2012	P230F	RUUD	\$ 850.00	\$ 6.39
336	Installed/Active	02/10/2000	FSG40	AO SMITH	\$ 850.00	
337	Installed/Active	06/21/2012	P230F	RUUD	\$ 850.00	\$ 6.39
338	Installed/Active	02/04/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
339	Installed/Active	01/06/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
340	Installed/Active	12/17/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
341	Installed/Active	06/15/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
342	Installed/Active	08/06/1996	FGR50	AO SMITH	\$ 850.00	
343	Installed/Active	09/14/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 39.36
344	Installed/Active	03/01/2004	41VR50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
345	Installed/Active	08/03/1993	FSGL40	AO SMITH	\$ 500.00	
346	Installed/Active	09/04/2002	PGR40	AO SMITH	\$ 850.00	
347	Installed/Active	02/13/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
348	Installed/Active	03/09/2000	41XR40	RHEEM	\$ 850.00	
349	Installed/Active	05/05/2003	41V50S	RHEEM	\$ 850.00	
350	Installed/Active	02/16/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
351	Installed/Active	11/04/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
352	Installed/Active	02/01/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
353	Installed/Active	08/29/1999	41V40S	RHEEM	\$ 850.00	
354	Installed/Active	08/08/2009	FSG50	AO SMITH	\$ 850.00	\$ 7.31
355	Installed/Active	12/16/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
356	Installed/Active	09/22/2001	FSG50	AO SMITH	\$ 850.00	
357	Installed/Active	11/04/2011	FSG40	AO SMITH	\$ 850.00	\$ 12.64
358	Installed/Active	02/22/1977	RM5063	RHEEM	\$ 500.00	
359	Installed/Active	10/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
360	Installed/Active	12/07/2006	FGR50	AO SMITH	\$ 850.00	
361	Installed/Active	05/27/1991	FSGL40	AO SMITH	\$ 850.00	
362	Installed/Active	06/30/2002	PGR50	AO SMITH	\$ 850.00	
363	Installed/Active	08/07/2001	FSG30	AO SMITH	\$ 850.00	
364	Installed/Active	05/03/1997	G72DUMMY	AO SMITH	\$ 1,125.00	
365	Installed/Active	08/29/2002	PGR50	AO SMITH	\$ 850.00	
366	Installed/Active	12/20/2005	GVC50	A. O. SMITH	\$ 850.00	
367	Installed/Active	12/12/1984	41XR50	RHEEM	\$ 850.00	
368	Installed/Active	07/08/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
369	Installed/Active	03/31/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 5.12
370	Installed/Active	01/01/1960	G82156	RUUD/RHEEM	\$ 3,350.00	
371	Installed/Active	10/23/2012	LTN050	LOCHINVAR	\$ 850.00	\$ 6.39
372	Installed/Active	01/07/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
373	Installed/Active	02/06/2004	XTN050	LOCHINVAR	\$ 850.00	
374	Installed/Active	10/03/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
375	Installed/Active	03/21/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
376	Installed/Active	06/02/2005	LTN050	LOCHINVAR	\$ 850.00	
377	Installed/Active	04/01/1965	PGX30	AO SMITH	\$ 850.00	
378	Installed/Active	07/03/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
379	Installed/Active	01/11/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
380	Installed/Active	02/02/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
381	Installed/Active	10/04/1999	FSG40	AO SMITH	\$ 850.00	
382	Installed/Active	01/24/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
383	Installed/Active	03/07/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
384	Installed/Active	03/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
385	Installed/Active	02/10/2004	FSG30	AO SMITH	\$ 350.00	
386	Installed/Active	12/01/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
387	Installed/Active	05/10/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
388	Installed/Active	03/24/2001	21V506	RHEEM	\$ 1,125.00	
389	Installed/Active	02/26/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
390	Installed/Active	08/15/2004	GVC40	A. O. SMITH	\$ 850.00	
391	Installed/Active	06/25/1999	G82156	RUUD/RHEEM	\$ 3,350.00	
392	Installed/Active	09/05/2002	FSG40	AO SMITH	\$ 850.00	
393	Installed/Active	11/04/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
394	Installed/Active	03/30/1996	FGR40	AO SMITH	\$ 850.00	
395	Installed/Active	03/03/1995	G76200	RUUD/RHEEM	\$ 3,350.00	
396	Installed/Active	03/03/1995	G76200	RUUD/RHEEM	\$ 3,350.00	
397	Installed/Active	12/15/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
398	Installed/Active	11/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
399	Installed/Active	01/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
400	Installed/Active	08/18/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
401	Installed/Active	04/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
402	Installed/Active	03/31/2010	RF82156	RUUD	\$ 3,350.00	\$ 51.18
403	Installed/Active	11/15/2001	41XR50	RHEEM	\$ 850.00	
404	Installed/Active	05/29/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
405	Installed/Active	04/18/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 5.12
406	Installed/Active	10/31/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
407	Installed/Active	05/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
408	Installed/Active	08/01/1971	PGX40	AO SMITH	\$ 850.00	
409	Installed/Active	12/22/2006	LSN041G	LOCHINVAR	\$ 850.00	
410	Installed/Active	10/23/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
411	Installed/Active	05/14/2002	PGR40	AO SMITH	\$ 850.00	
412	Installed/Active	04/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
413	Installed/Active	08/20/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
414	Installed/Active	04/19/2000	41V40S	RHEEM	\$ 850.00	
415	Installed/Active	10/09/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
416	Installed/Active	09/01/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
417	Installed/Active	04/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
418	Installed/Active	07/20/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
419	Installed/Active	12/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
420	Installed/Active	12/06/1996	G76200	RUUD/RHEEM	\$ 3,350.00	
421	Installed/Active	11/08/2006	LSN041G	LOCHINVAR	\$ 850.00	
422	Installed/Active	12/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
423	Installed/Active	09/29/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
424	Installed/Active	01/20/2010	41VR50	RHEEM	\$ 850.00	\$ 5.88
425	Installed/Active	10/01/2002	FSG50	AO SMITH	\$ 850.00	
426	Installed/Active	09/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
427	Installed/Active	08/08/2000	PHR40	RUUD	\$ 850.00	
428	Installed/Active	04/19/2004	FCV50	AO SMITH	\$ 850.00	
429	Installed/Active	06/04/1965	PGX30	AO SMITH	\$ 850.00	
430	Installed/Active	03/27/2003	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
431	Installed/Active	05/11/2007	XVR50	A. O. SMITH	\$ 850.00	\$ 5.12
432	Installed/Active	12/04/2010	42VR50	RHEEM	\$ 850.00	\$ 7.51
433	Installed/Active	11/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
434	Installed/Active	05/24/2001	FSG40	AO SMITH	\$ 850.00	
435	Installed/Active	02/17/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
436	Installed/Active	10/08/2009	FGR50	AO SMITH	\$ 850.00	\$ 5.88
437	Installed/Active	01/05/2006	LTN040G	LOCHINVAR	\$ 850.00	
438	Installed/Active	06/30/2005	LTN040	LOCHINVAR	\$ 850.00	
439	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
440	Installed/Active	02/17/2000	41V50	RHEEM	\$ 850.00	
441	Installed/Active	10/04/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 39.36
442	Installed/Active	07/26/2001	21V407	RHEEM	\$ 850.00	
443	Installed/Active	03/17/2005	GVC40	A. O. SMITH	\$ 850.00	
444	Installed/Active	06/01/2004	GCVL40	A. O. SMITH	\$ 850.00	
445	Installed/Active	07/09/2001	PGR50	AO SMITH	\$ 850.00	
446	Installed/Active	08/16/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
447	Installed/Active	01/26/2001	FSG50	AO SMITH	\$ 850.00	
448	Installed/Active	02/26/2009	41VR50	RHEEM	\$ 850.00	\$ 11.74
449	Installed/Active	02/20/1994	PGR40	AO SMITH	\$ 850.00	
450	Installed/Active	04/25/2003	FGR40	AO SMITH	\$ 850.00	
451	Installed/Active	10/06/2011	22V30F	RHEEM	\$ 850.00	\$ 6.34
452	Installed/Active	07/24/2000	PGR50	AO SMITH	\$ 850.00	
453	Installed/Active	06/13/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
454	Installed/Active	05/21/2006	LTN040G	LOCHINVAR	\$ 850.00	
455	Installed/Active	05/21/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
456	Installed/Active	07/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
457	Installed/Active	01/19/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
458	Installed/Active	04/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
459	Installed/Active	08/06/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
460	Installed/Active	03/21/2007	XTN050	LOCHINVAR	\$ 850.00	\$ 10.23
461	Installed/Active	06/28/2011	MI40S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
462	Installed/Active	04/15/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
463	Installed/Active	07/29/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
464	Installed/Active	07/27/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
465	Installed/Active	08/31/2005	LTN040	LOCHINVAR	\$ 850.00	
466	Installed/Active	03/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
467	Installed/Active	02/07/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
468	Installed/Active	03/31/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
469	Installed/Active	09/11/2001	FSG50	AO SMITH	\$ 850.00	
470	Installed/Active	01/02/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
471	Installed/Active	11/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
472	Installed/Active	07/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
473	Installed/Active	01/23/1998	FSG40	AO SMITH	\$ 850.00	
474	Installed/Active	05/01/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
475	Installed/Active	01/18/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
476	Installed/Active	10/16/2009	FSG50	AO SMITH	\$ 850.00	\$ 5.88
477	Installed/Active	05/18/2010	FSG30	AO SMITH	\$ 850.00	\$ 6.04
478	Installed/Active	06/12/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
479	Installed/Active	12/22/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
480	Installed/Active	06/29/2005	LSN041G	LOCHINVAR	\$ 850.00	
481	Installed/Active	06/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
482	Installed/Active	10/02/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
483	Installed/Active	05/01/1996	FGR40	AO SMITH	\$ 850.00	
484	Installed/Active	11/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
485	Installed/Active	05/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
486	Installed/Active	10/15/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
487	Installed/Active	08/03/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
488	Installed/Active	06/10/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
489	Installed/Active	02/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
490	Installed/Active	03/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
491	Installed/Active	06/12/2000	G72DUMMY	AO SMITH	\$ 1,125.00	
492	Installed/Active	10/27/2001	21V407	RHEEM	\$ 850.00	
493	Installed/Active	02/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
494	Installed/Active	05/14/1997	FSGL40	AO SMITH	\$ 850.00	
495	Installed/Active	10/18/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
496	Installed/Active	04/11/2001	PGR50	AO SMITH	\$ 850.00	
497	Installed/Active	06/12/2000	FSGL40	AO SMITH	\$ 850.00	
498	Installed/Active	08/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
499	Installed/Active	01/27/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
500	Installed/Active	03/02/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
501	Installed/Active	06/16/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
502	Installed/Active	06/04/2005	LTN050	LOCHINVAR	\$ 850.00	
503	Installed/Active	07/22/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
504	Installed/Active	03/11/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
505	Installed/Active	05/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
506	Installed/Active	06/29/1996	FSGL40	AO SMITH	\$ 850.00	
507	Installed/Active	02/16/2002	FSGL40	AO SMITH	\$ 850.00	
508	Installed/Active	12/20/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
509	Installed/Active	11/26/2002	PGR50	AO SMITH	\$ 850.00	
510	Installed/Active	06/06/2005	LTN050G	LOCHINVAR	\$ 850.00	
511	Installed/Active	09/24/1997	PGR50	AO SMITH	\$ 850.00	
512	Installed/Active	08/31/1998	FSG40	AO SMITH	\$ 850.00	
513	Installed/Active	01/15/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
514	Installed/Active	10/10/1996	PGR50	AO SMITH	\$ 850.00	
515	Installed/Active	08/21/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
516	Installed/Active	07/17/2003	FSG40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
517	Installed/Active	10/06/1992	FSG40	AO SMITH	\$ 850.00	
518	Installed/Active	05/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
519	Installed/Active	07/12/2011	LTN050G	LOCHINVAR	\$ 500.00	\$ 20.21
520	Installed/Active	11/30/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
521	Installed/Active	11/16/2000	FSGL40	AO SMITH	\$ 850.00	
522	Installed/Active	09/22/2006	LTN040G	LOCHINVAR	\$ 850.00	
523	Installed/Active	02/15/2005	LTN040	LOCHINVAR	\$ 850.00	
524	Installed/Active	07/08/2011	21V506	RHEEM	\$ 500.00	\$ 20.21
525	Installed/Active	04/15/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
526	Installed/Active	06/04/2003	FSG50	AO SMITH	\$ 850.00	
527	Installed/Active	01/01/1986	P506	RUUD	\$ 500.00	
528	Installed/Active	03/04/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
529	Installed/Active	09/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
530	Installed/Active	09/26/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
531	Installed/Active	08/30/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
532	Installed/Active	08/22/2012	RF82156	RUUD	\$ 3,350.00	\$ 55.60
533	Installed/Active	11/13/1989	FSG40	AO SMITH	\$ 850.00	
534	Installed/Active	12/08/2005	LTN040G	LOCHINVAR	\$ 850.00	
535	Installed/Active	09/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
536	Installed/Active	11/29/2000	FSG40	AO SMITH	\$ 850.00	
537	Installed/Active	10/20/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
538	Installed/Active	08/27/1999	FGR40	AO SMITH	\$ 850.00	
539	Installed/Active	01/20/1999	41VR50	RHEEM	\$ 850.00	
540	Installed/Active	09/14/1998	G76200	RUUD/RHEEM	\$ 3,350.00	
541	Installed/Active	02/15/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
542	Installed/Active	11/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
543	Installed/Active	06/17/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
544	Installed/Active	09/15/2001	FSG30	AO SMITH	\$ 850.00	
545	Installed/Active	02/18/2004	FSGL40	AO SMITH	\$ 850.00	
546	Installed/Active	10/18/2009	PRV50NODS	STATE	\$ 1,125.00	\$ 18.76
547	Installed/Active	03/26/2002	FSG30	AO SMITH	\$ 850.00	
548	Installed/Active	03/04/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
549	Installed/Active	05/04/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
550	Installed/Active	02/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
551	Installed/Active	08/20/2004	FCV50	AO SMITH	\$ 850.00	
552	Installed/Active	02/10/1996	PR407	RUUD	\$ 850.00	
553	Installed/Active	12/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
554	Installed/Active	01/05/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
555	Installed/Active	01/27/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
556	Installed/Active	08/11/2000	FSG50	AO SMITH	\$ 850.00	
557	Installed/Active	02/15/2002	FSG40	AO SMITH	\$ 850.00	
558	Installed/Active	01/01/1973	PGX40	AO SMITH	\$ 850.00	
559	Installed/Active	03/04/2004	FCV50	AO SMITH	\$ 850.00	
560	Installed/Active	01/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
561	Installed/Active	10/26/2001	FSG40	AO SMITH	\$ 850.00	
562	Installed/Active	12/21/2004	GVC40	A. O. SMITH	\$ 850.00	
563	Installed/Active	02/23/2005	GVC40	A. O. SMITH	\$ 850.00	
564	Installed/Active	01/31/2002	H72DUMMY	AO SMITH	\$ 1,900.00	
565	Installed/Active	05/10/2011	42VR50	RHEEM	\$ 850.00	\$ 6.34
566	Installed/Active	08/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
567	Installed/Active	04/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
568	Installed/Active	09/10/1997	PGR50	AO SMITH	\$ 850.00	
569	Installed/Active	03/11/2005	GCVL40	A. O. SMITH	\$ 850.00	
570	Installed/Active	06/15/2006	G76200	RUUD/RHEEM	\$ 3,350.00	
571	Installed/Active	02/10/2009	FSG30	AO SMITH	\$ 850.00	\$ 11.74
572	Installed/Active	01/19/2001	41VR40	RHEEM	\$ 850.00	
573	Installed/Active	12/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
574	Installed/Active	08/22/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
575	Installed/Active	03/01/1980	FSG50	AO SMITH	\$ 850.00	
576	Installed/Active	03/31/1997	PGR40	AO SMITH	\$ 850.00	
577	Installed/Active	10/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
578	Installed/Active	03/22/1999	41VR40	RHEEM	\$ 850.00	
579	Installed/Active	05/25/2004	FCV40	AO SMITH	\$ 850.00	
580	Installed/Active	07/27/1999	FSG40	AO SMITH	\$ 850.00	
581	Installed/Active	08/27/2005	LTN050	LOCHINVAR	\$ 850.00	
582	Installed/Active	09/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
583	Installed/Active	10/31/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
584	Installed/Active	11/20/2002	FSG50	AO SMITH	\$ 850.00	
585	Installed/Active	11/27/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
586	Installed/Active	05/21/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
587	Installed/Active	02/25/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
588	Installed/Active	08/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
589	Installed/Active	03/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
590	Installed/Active	09/19/2003	FSG30	AO SMITH	\$ 350.00	
591	Installed/Active	04/19/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
592	Installed/Active	05/01/1966	A71	UNKNOW	\$ 850.00	
593	Installed/Active	06/27/1989	FSG50	AO SMITH	\$ 850.00	
594	Installed/Active	10/26/2005	LSN041G	LOCHINVAR	\$ 850.00	
595	Installed/Active	08/19/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
596	Installed/Active	04/16/2004	41V40	RHEEM	\$ 850.00	
597	Installed/Active	02/06/2000	41XR40	RHEEM	\$ 850.00	
598	Installed/Active	02/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
599	Installed/Active	02/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
600	Installed/Active	09/22/2005	LTN050	LOCHINVAR	\$ 850.00	
601	Installed/Active	05/21/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
602	Installed/Active	02/01/1971	PGX50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
603	Installed/Active	05/09/2011	21VR40	RHEEM	\$ 850.00	\$ 7.88
604	Installed/Active	01/28/1999	41VR50	RHEEM	\$ 850.00	
605	Installed/Active	06/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
606	Installed/Active	03/07/2001	PGR50	AO SMITH	\$ 850.00	
607	Installed/Active	10/30/2006	LTN040G	LOCHINVAR	\$ 850.00	
608	Installed/Active	03/18/2011	21V506	RHEEM	\$ 1,125.00	\$ 19.26
609	Installed/Active	08/22/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
610	Installed/Active	11/05/2010	42VR50	RHEEM	\$ 850.00	\$ 7.51
611	Installed/Active	10/21/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
612	Installed/Active	03/23/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
613	Installed/Active	05/15/2005	LTN050	LOCHINVAR	\$ 850.00	
614	Installed/Active	01/27/1999	FSG30	AO SMITH	\$ 850.00	
615	Installed/Active	08/21/2001	PGR50	AO SMITH	\$ 850.00	
616	Installed/Active	08/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.51
617	Installed/Active	04/13/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
618	Installed/Active	09/06/2006	LTN050G	LOCHINVAR	\$ 1,125.00	
619	Installed/Active	01/26/1991	P506	RUUD	\$ 1,900.00	
620	Installed/Active	02/10/2011	22V30F	RHEEM	\$ 850.00	\$ 6.04
621	Installed/Active	04/01/2003	PGR40	AO SMITH	\$ 850.00	
622	Installed/Active	05/01/1971	PGX40	AO SMITH	\$ 850.00	
623	Installed/Active	06/21/2002	PGR50	AO SMITH	\$ 850.00	
624	Installed/Active	01/31/2002	FSG50	AO SMITH	\$ 850.00	
625	Installed/Active	12/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
626	Installed/Active	12/06/2004	XVR50	A. O. SMITH	\$ 850.00	
627	Installed/Active	02/27/2000	41XR50	RHEEM	\$ 850.00	
628	Installed/Active	08/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
629	Installed/Active	03/26/2001	41XR50	RHEEM	\$ 850.00	
630	Installed/Active	02/16/2001	41VR40	RHEEM	\$ 850.00	
631	Installed/Active	02/09/2011	41VR40	RHEEM	\$ 850.00	\$ 7.51
632	Installed/Active	11/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
633	Installed/Active	04/16/2003	FSG40	AO SMITH	\$ 850.00	
634	Installed/Active	03/12/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
635	Installed/Active	09/06/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
636	Installed/Active	06/06/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
637	Installed/Active	09/13/2006	LTN040GEF	Lochinvar	\$ 745.00	
638	Installed/Active	05/30/1991	FSG40	AO SMITH	\$ 850.00	
639	Installed/Active	11/29/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
640	Installed/Active	08/12/1998	FGR40	AO SMITH	\$ 850.00	
641	Installed/Active	10/09/2003	PGR40	AO SMITH	\$ 850.00	
642	Installed/Active	04/19/2001	FSGL40	AO SMITH	\$ 850.00	
643	Installed/Active	12/27/2001	FSG40	AO SMITH	\$ 850.00	
644	Installed/Active	11/03/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
645	Installed/Active	09/13/2006	LTN040GEF	L	\$ 745.00	
646	Installed/Active	07/17/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
647	Installed/Active	10/17/2001	PGR50	AO SMITH	\$ 850.00	
648	Installed/Active	03/20/2001	FSG40	AO SMITH	\$ 850.00	
649	Installed/Active	03/03/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
650	Installed/Active	11/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
651	Installed/Active	04/01/1967	PGX50	AO SMITH	\$ 850.00	
652	Installed/Active	01/14/2011	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
653	Installed/Active	03/03/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
654	Installed/Active	06/18/2005	LTN050	LOCHINVAR	\$ 850.00	
655	Installed/Active	02/21/2003	FSGL40	AO SMITH	\$ 850.00	
656	Installed/Active	02/10/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
657	Installed/Active	03/05/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
658	Installed/Active	11/11/2005	LTN050G	LOCHINVAR	\$ 850.00	
659	Installed/Active	10/20/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
660	Installed/Active	06/29/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
661	Installed/Active	01/14/2005	LTN050	LOCHINVAR	\$ 850.00	
662	Installed/Active	06/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
663	Installed/Active	04/14/1997	21VR502T	RHEEM	\$ 850.00	
664	Installed/Active	07/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
665	Installed/Active	02/24/2003	FSGL40	AO SMITH	\$ 850.00	
666	Installed/Active	04/06/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
667	Installed/Active	06/09/2004	XSN040	LOCHINVAR	\$ 850.00	
668	Installed/Active	09/16/2005	LTN040	LOCHINVAR	\$ 850.00	
669	Installed/Active	05/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
670	Installed/Active	07/12/1974	F72DUMMY	AO SMITH	\$ 3,350.00	
671	Installed/Active	07/12/1974	F72DUMMY	AO SMITH	\$ 3,350.00	
672	Installed/Active	07/08/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
673	Installed/Active	03/01/1971	PGX40	AO SMITH	\$ 850.00	
674	Installed/Active	12/10/1991	FSG30	AO SMITH	\$ 850.00	
675	Installed/Active	04/04/2001	41XR50	RHEEM	\$ 850.00	
676	Installed/Active	09/28/1993	FSG40	AO SMITH	\$ 850.00	
677	Installed/Active	12/19/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
678	Installed/Active	09/26/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
679	Installed/Active	06/07/1983	KGA50	AO SMITH	\$ 850.00	
680	Installed/Active	10/04/2001	PGR50	AO SMITH	\$ 850.00	
681	Installed/Active	04/21/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
682	Installed/Active	10/06/2004	XVR50	A. O. SMITH	\$ 850.00	
683	Installed/Active	01/16/1998	21V407	RHEEM	\$ 850.00	
684	Installed/Active	03/22/2001	FSG40	AO SMITH	\$ 850.00	
685	Installed/Active	12/10/2008	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
686	Installed/Active	12/13/2012	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 20.38
687	Installed/Active	04/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
688	Installed/Active	06/26/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
689	Installed/Active	02/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
690	Installed/Active	11/23/2005	LTN040G	LOCHINVAR	\$ 850.00	
691	Installed/Active	06/13/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
692	Installed/Active	07/19/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
693	Installed/Active	08/01/1974	KGL40	AO SMITH	\$ 850.00	
694	Installed/Active	12/01/1998	21V506	RHEEM	\$ 1,125.00	
695	Installed/Active	07/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
696	Installed/Active	02/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
697	Installed/Active	05/26/2004	XTN050	LOCHINVAR	\$ 850.00	
698	Installed/Active	02/02/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
699	Installed/Active	01/03/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
700	Installed/Active	05/27/1998	FSG40	AO SMITH	\$ 850.00	
701	Installed/Active	06/20/1994	PGR40	AO SMITH	\$ 850.00	
702	Installed/Active	06/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
703	Installed/Active	10/28/2003	FCVL40	AO SMITH	\$ 850.00	
704	Installed/Active	01/18/1999	FSG50	AO SMITH	\$ 850.00	
705	Installed/Active	12/29/1999	41V40S	RHEEM	\$ 850.00	
706	Installed/Active	05/13/2011	41VR50	RHEEM	\$ 850.00	\$ 7.88
707	Installed/Active	05/15/2000	41XR50	RHEEM	\$ 850.00	
708	Installed/Active	07/11/2001	FSG40	AO SMITH	\$ 850.00	
709	Installed/Active	10/01/1976	KGA50	AO SMITH	\$ 850.00	
710	Installed/Active	02/07/2001	41VR50	RHEEM	\$ 850.00	
711	Installed/Active	05/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
712	Installed/Active	09/22/2000	41V40S	RHEEM	\$ 850.00	
713	Installed/Active	09/11/2003	FSGL40	AO SMITH	\$ 850.00	
714	Installed/Active	09/06/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
715	Installed/Active	07/08/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
716	Installed/Active	12/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
717	Installed/Active	05/11/2001	FSGL40	AO SMITH	\$ 850.00	
718	Installed/Active	02/11/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
719	Installed/Active	02/26/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
720	Installed/Active	06/06/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
721	Installed/Active	03/30/2002	FSG50	AO SMITH	\$ 850.00	
722	Installed/Active	05/11/2001	FSGL40	AO SMITH	\$ 850.00	
723	Installed/Active	08/18/1977	KGA40	AO SMITH	\$ 850.00	
724	Installed/Active	12/21/2012	FSGL40	AO SMITH	\$ 850.00	\$ 7.95
725	Installed/Active	11/05/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
726	Installed/Active	08/16/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
727	Installed/Active	03/18/2002	FSGL40	AO SMITH	\$ 850.00	
728	Installed/Active	08/15/2000	FSGL40	AO SMITH	\$ 850.00	
729	Installed/Active	05/02/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
730	Installed/Active	04/15/2004	PRX50	STATE	\$ 850.00	
731	Installed/Active	04/23/1997	P506	RUUD	\$ 1,150.00	
732	Installed/Active	02/10/2009	KGL40	AO SMITH	\$ 850.00	\$ 7.31
733	Installed/Active	12/02/2000	41XR50	RHEEM	\$ 850.00	
734	Installed/Active	07/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
735	Installed/Active	05/27/1975	KGA50	AO SMITH	\$ 850.00	
736	Installed/Active	07/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
737	Installed/Active	03/28/2005	GCVL40	A. O. SMITH	\$ 850.00	
738	Installed/Active	04/09/2011	21VR50	RHEEM	\$ 850.00	\$ 7.88
739	Installed/Active	08/04/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
740	Installed/Active	03/17/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
741	Installed/Active	05/18/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.51
742	Installed/Active	06/22/2002	PGR40	AO SMITH	\$ 850.00	
743	Installed/Active	12/19/1997	PGR50	AO SMITH	\$ 850.00	
744	Installed/Active	12/31/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
745	Installed/Active	06/26/2006	PGR50	AO SMITH	\$ 850.00	
746	Installed/Active	11/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
747	Installed/Active	08/23/2003	FSG40	AO SMITH	\$ 850.00	
748	Installed/Active	11/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
749	Installed/Active	11/18/1997	FSG50	AO SMITH	\$ 850.00	
750	Installed/Active	04/23/2004	XVR40	A. O. SMITH	\$ 850.00	
751	Installed/Active	04/01/2002	FSG50	AO SMITH	\$ 850.00	
752	Installed/Active	12/14/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
753	Installed/Active	03/21/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
754	Installed/Active	12/21/2005	GVC50	A. O. SMITH	\$ 850.00	
755	Installed/Active	09/02/1996	FGR50	AO SMITH	\$ 850.00	
756	Installed/Active	11/19/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
757	Installed/Active	10/19/1994	G72DUMMY	AO SMITH	\$ 1,750.00	
758	Installed/Active	10/04/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
759	Installed/Active	09/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
760	Installed/Active	10/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
761	Installed/Active	05/28/2003	FSG50	AO SMITH	\$ 850.00	
762	Installed/Active	01/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
763	Installed/Active	02/08/2003	FSG30	AO SMITH	\$ 850.00	
764	Installed/Active	05/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
765	Installed/Active	02/02/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
766	Installed/Active	10/13/2006	LTN040G	LOCHINVAR	\$ 850.00	
767	Installed/Active	03/04/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
768	Installed/Active	03/30/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
769	Installed/Active	02/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
770	Installed/Active	07/27/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
771	Installed/Active	12/20/1973	RM5063	RHEEM	\$ 500.00	
772	Installed/Active	10/13/2001	PGR40	AO SMITH	\$ 850.00	
773	Installed/Active	03/23/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
774	Installed/Active	10/08/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
775	Installed/Active	05/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
776	Installed/Active	03/21/1995	PR407	RUUD	\$ 850.00	
777	Installed/Active	03/24/2005	GVC40	A. O. SMITH	\$ 850.00	
778	Installed/Active	03/17/1997	PGR40	AO SMITH	\$ 850.00	
779	Installed/Active	03/22/2005	XVR50	A. O. SMITH	\$ 850.00	
780	Installed/Active	04/11/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
781	Installed/Active	04/08/1985	FSG50	AO SMITH	\$ 850.00	
782	Installed/Active	10/08/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
783	Installed/Active	05/31/1999	FSG50	AO SMITH	\$ 850.00	
784	Installed/Active	10/15/2002	PGR50	AO SMITH	\$ 850.00	
785	Installed/Active	02/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
786	Installed/Active	05/17/2005	XSN040	LOCHINVAR	\$ 850.00	
787	Installed/Active	02/12/2004	FCVL40	AO SMITH	\$ 850.00	
788	Installed/Active	12/22/2005	LTN040G	LOCHINVAR	\$ 850.00	
789	Installed/Active	12/31/2005	LTN050G	LOCHINVAR	\$ 850.00	
790	Installed/Active	08/31/2010	21V502	RHEEM	\$ 850.00	\$ 7.51
791	Installed/Active	01/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
792	Installed/Active	02/21/1989	FSGL40	AO SMITH	\$ 850.00	
793	Installed/Active	12/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
794	Installed/Active	06/04/2001	FSGL40	AO SMITH	\$ 850.00	
795	Installed/Active	08/31/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
796	Installed/Active	03/17/2004	PVR50	AO SMITH	\$ 850.00	
797	Installed/Active	05/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
798	Installed/Active	02/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
799	Installed/Active	07/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
800	Installed/Active	09/13/1999	FSGL40	AO SMITH	\$ 850.00	
801	Installed/Active	10/03/1997	PGR50	AO SMITH	\$ 850.00	
802	Installed/Active	11/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
803	Installed/Active	09/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
804	Installed/Active	08/02/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
805	Installed/Active	01/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
806	Installed/Active	08/24/2004	GVR50	AO SMITH	\$ 850.00	
807	Installed/Active	02/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
808	Installed/Active	01/24/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
809	Installed/Active	12/11/2000	41XR40	RHEEM	\$ 850.00	
810	Installed/Active	06/17/1999	41VR50	RHEEM	\$ 850.00	
811	Installed/Active	10/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
812	Installed/Active	02/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
813	Installed/Active	05/18/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
814	Installed/Active	03/22/2001	PGR50	AO SMITH	\$ 850.00	
815	Installed/Active	02/20/2001	FSG40	AO SMITH	\$ 850.00	
816	Installed/Active	07/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
817	Installed/Active	01/28/2005	FSG40	AO SMITH	\$ 850.00	
818	Installed/Active	07/23/2004	GCVL40	A. O. SMITH	\$ 850.00	
819	Installed/Active	06/25/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
820	Installed/Active	02/22/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
821	Installed/Active	04/17/2001	FSGL40	AO SMITH	\$ 850.00	
822	Installed/Active	06/27/2005	LTN050	LOCHINVAR	\$ 850.00	
823	Installed/Active	01/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
824	Installed/Active	03/16/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
825	Installed/Active	06/23/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
826	Installed/Active	06/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
827	Installed/Active	05/03/1998	FSGL40	AO SMITH	\$ 850.00	
828	Installed/Active	06/19/2001	FSG40	AO SMITH	\$ 850.00	
829	Installed/Active	12/22/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
830	Installed/Active	10/18/1994	FGR40	AO SMITH	\$ 850.00	
831	Installed/Active	02/25/2009	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
832	Installed/Active	12/28/1994	G82156	RUUD/RHEEM	\$ 3,350.00	
833	Installed/Active	02/13/2007	P506	RUUD	\$ 1,125.00	\$ 16.35
834	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
835	Installed/Active	09/08/2002	FSG50	AO SMITH	\$ 850.00	
836	Installed/Active	07/03/2001	FSG50	AO SMITH	\$ 850.00	
837	Installed/Active	03/02/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
838	Installed/Active	11/03/2002	PGR50	AO SMITH	\$ 850.00	
839	Installed/Active	09/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
840	Installed/Active	10/23/2003	FSG40	AO SMITH	\$ 850.00	
841	Installed/Active	07/08/2002	FSG40	AO SMITH	\$ 850.00	
842	Installed/Active	03/26/1999	FSG40	AO SMITH	\$ 850.00	
843	Installed/Active	11/12/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
844	Installed/Active	11/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
845	Installed/Active	11/09/1996	PGR50	AO SMITH	\$ 850.00	
846	Installed/Active	03/31/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
847	Installed/Active	04/01/2004	FCV50	AO SMITH	\$ 850.00	
848	Installed/Active	07/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
849	Installed/Active	10/01/1977	RH3063	RUUD	\$ 350.00	
850	Installed/Active	06/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
851	Installed/Active	03/27/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
852	Installed/Active	03/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
853	Installed/Active	11/10/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
854	Installed/Active	02/20/2004	FCV40	AO SMITH	\$ 850.00	
855	Installed/Active	12/26/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 7.31
856	Installed/Active	01/19/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
857	Installed/Active	08/22/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
858	Installed/Active	12/11/2004	G72DUMMY	AO SMITH	\$ 500.00	
859	Installed/Active	03/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
860	Installed/Active	02/08/2006	LTN040G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
861	Installed/Active	07/07/2008	42VR50	RHEEM	\$ 850.00	\$ 5.12
862	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
863	Installed/Active	04/26/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
864	Installed/Active	05/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
865	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
866	Installed/Active	07/21/2005	LSN041G	LOCHINVAR	\$ 850.00	
867	Installed/Active	01/08/2004	PVR40	AO SMITH	\$ 850.00	
868	Installed/Active	03/27/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
869	Installed/Active	12/30/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
870	Installed/Active	10/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
871	Installed/Active	01/31/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
872	Installed/Active	01/05/2001	FSG50	AO SMITH	\$ 850.00	
873	Installed/Active	04/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
874	Installed/Active	02/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
875	Installed/Active	04/09/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
876	Installed/Active	12/03/2011	MIS0L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
877	Installed/Active	04/14/1999	FSGL40	AO SMITH	\$ 850.00	
878	Installed/Active	03/06/2004	FCV40	AO SMITH	\$ 850.00	
879	Installed/Active	11/26/2005	LTN040	LOCHINVAR	\$ 850.00	
880	Installed/Active	05/14/2001	PGR50	AO SMITH	\$ 850.00	
881	Installed/Active	09/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
882	Installed/Active	11/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
883	Installed/Active	02/20/2012	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.88
884	Installed/Active	12/19/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
885	Installed/Active	07/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
886	Installed/Active	09/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
887	Installed/Active	06/12/2005	LTN040	LOCHINVAR	\$ 850.00	
888	Installed/Active	01/06/2005	GVC40	A. O. SMITH	\$ 850.00	
889	Installed/Active	01/23/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
890	Installed/Active	12/13/2002	PGR50	AO SMITH	\$ 850.00	
891	Installed/Active	06/06/2012	FSG50	AO SMITH	\$ 850.00	\$ 6.39
892	Installed/Active	08/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
893	Installed/Active	04/27/2001	PGR50	AO SMITH	\$ 850.00	
894	Installed/Active	11/12/1992	FSG50	AO SMITH	\$ 850.00	
895	Installed/Active	01/29/2002	FSGL40	AO SMITH	\$ 850.00	
896	Installed/Active	10/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
897	Installed/Active	08/06/1999	FGR50	AO SMITH	\$ 850.00	
898	Installed/Active	03/04/2003	FSG50	AO SMITH	\$ 850.00	
899	Installed/Active	03/22/2001	FSG40	AO SMITH	\$ 850.00	
900	Installed/Active	01/31/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
901	Installed/Active	01/25/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
902	Installed/Active	04/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
903	Installed/Active	01/27/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
904	Installed/Active	08/04/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
905	Installed/Active	08/11/1997	PGR50	AO SMITH	\$ 850.00	
906	Installed/Active	11/20/2001	FSG30	AO SMITH	\$ 850.00	
907	Installed/Active	03/09/2000	FSGL40	AO SMITH	\$ 850.00	
908	Installed/Active	02/22/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 5.12
909	Installed/Active	10/23/2012	MIS0L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
910	Installed/Active	11/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
911	Installed/Active	10/03/2002	PGR50	AO SMITH	\$ 850.00	
912	Installed/Active	09/01/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
913	Installed/Active	10/19/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
914	Installed/Active	10/31/2007	FSG30	AO SMITH	\$ 850.00	\$ 5.12
915	Installed/Active	01/11/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
916	Installed/Active	04/29/2004	PVR50	AO SMITH	\$ 850.00	
917	Installed/Active	11/13/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
918	Installed/Active	12/01/2006	LTN030G	AO SMITH	\$ 850.00	
919	Installed/Active	03/09/2012	PH250SF	RUUD	\$ 850.00	\$ 6.34
920	Installed/Active	07/08/2010	FSG40	AO SMITH	\$ 850.00	\$ 6.04
921	Installed/Active	12/28/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
922	Installed/Active	01/26/2011	42VR50	RHEEM	\$ 850.00	\$ 7.51
923	Installed/Active	05/21/2001	PGR50	AO SMITH	\$ 850.00	
924	Installed/Active	07/21/1997	FGR50	AO SMITH	\$ 850.00	
925	Installed/Active	06/10/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
926	Installed/Active	01/07/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
927	Installed/Active	04/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
928	Installed/Active	12/02/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
929	Installed/Active	09/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
930	Installed/Active	11/07/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
931	Installed/Active	11/19/1998	FSG30	AO SMITH	\$ 350.00	
932	Installed/Active	09/13/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
933	Installed/Active	03/09/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
934	Installed/Active	05/10/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
935	Installed/Active	07/11/2004	GVC50	A. O. SMITH	\$ 850.00	
936	Installed/Active	08/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
937	Installed/Active	05/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
938	Installed/Active	05/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
939	Installed/Active	06/01/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
940	Installed/Active	01/09/1999	PGR40	AO SMITH	\$ 850.00	
941	Installed/Active	04/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
942	Installed/Active	04/04/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
943	Installed/Active	12/10/2012	MIS0L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
944	Installed/Active	04/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
945	Installed/Active	12/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
946	Installed/Active	02/01/1994	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
947	Installed/Active	01/09/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
948	Installed/Active	10/26/1999	FSGL40	AO SMITH	\$ 850.00	
949	Installed/Active	02/10/2004	XTN050	LOCHINVAR	\$ 850.00	
950	Installed/Active	12/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
951	Installed/Active	09/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
952	Installed/Active	08/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
953	Installed/Active	11/01/1975	KGA50	AO SMITH	\$ 850.00	
954	Installed/Active	06/04/1998	FSG40	AO SMITH	\$ 850.00	
955	Installed/Active	07/11/2006	LTN040G	LOCHINVAR	\$ 850.00	
956	Installed/Active	04/16/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
957	Installed/Active	06/14/1999	FSG50	AO SMITH	\$ 850.00	
958	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
959	Installed/Active	04/02/2005	FCV40	AO SMITH	\$ 850.00	
960	Installed/Active	02/24/2011	41VR40	RHEEM	\$ 850.00	\$ 7.51
961	Installed/Active	04/09/1998	G67114	RHEEM	\$ 1,900.00	
962	Installed/Active	09/20/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
963	Installed/Active	03/12/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 6.37
964	Installed/Active	07/14/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
965	Installed/Active	07/16/2003	FSG50	AO SMITH	\$ 850.00	
966	Installed/Active	06/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
967	Installed/Active	10/11/1997	21V407	RHEEM	\$ 850.00	
968	Installed/Active	09/11/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
969	Installed/Active	11/24/1992	BTR199	AO SMITH	\$ 3,350.00	
970	Installed/Active	02/13/2005	GVC40	A. O. SMITH	\$ 850.00	
971	Installed/Active	05/05/1993	FSG30	AO SMITH	\$ 850.00	
972	Installed/Active	07/19/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
973	Installed/Active	12/08/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
974	Installed/Active	12/19/1991	FSG30	AO SMITH	\$ 850.00	
975	Installed/Active	09/02/2004	GVC50	A. O. SMITH	\$ 850.00	
976	Installed/Active	04/12/2002	FSG40	AO SMITH	\$ 850.00	
977	Installed/Active	01/19/2005	LTN050	LOCHINVAR	\$ 850.00	
978	Installed/Active	02/07/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
979	Installed/Active	12/20/1973	PGXL30	AO SMITH	\$ 850.00	
980	Installed/Active	06/08/1998	FGR40	AO SMITH	\$ 350.00	
981	Installed/Active	11/12/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
982	Installed/Active	01/13/1999	I72DUMMY	AO SMITH	\$ 1,900.00	
983	Installed/Active	07/13/2002	41XR50	RHEEM	\$ 850.00	
984	Installed/Active	10/17/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
985	Installed/Active	12/10/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
986	Installed/Active	10/20/1999	P506	RUUD	\$ 1,125.00	
987	Installed/Active	02/27/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
988	Installed/Active	12/10/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
989	Installed/Active	06/28/1989	FSG50	AO SMITH	\$ 850.00	
990	Installed/Active	06/22/1999	FSG50	AO SMITH	\$ 850.00	
991	Installed/Active	11/06/2000	FSG40	AO SMITH	\$ 850.00	
992	Installed/Active	03/18/1996	PGR40	AO SMITH	\$ 850.00	
993	Installed/Active	02/04/2006	FSGL30	AO SMITH	\$ 850.00	
994	Installed/Active	01/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
995	Installed/Active	02/18/2005	XVR50	A. O. SMITH	\$ 850.00	
996	Installed/Active	09/07/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
997	Installed/Active	12/28/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
998	Installed/Active	06/27/2001	FSG50	AO SMITH	\$ 850.00	
999	Installed/Active	12/28/2009	FGR30	AO SMITH	\$ 850.00	\$ 5.88
1000	Installed/Active	03/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1001	Installed/Active	08/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1002	Installed/Active	12/28/2009	FSG30	AO SMITH	\$ 850.00	\$ 5.88
1003	Installed/Active	12/28/2009	PGX30	AO SMITH	\$ 850.00	\$ 5.88
1004	Installed/Active	12/17/2012	FSGL40	AO SMITH	\$ 850.00	\$ 6.39
1005	Installed/Active	12/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
1006	Installed/Active	04/10/2004	XTN050	LOCHINVAR	\$ 850.00	
1007	Installed/Active	07/28/1987	G72DUMMY	AO SMITH	\$ 1,750.00	
1008	Installed/Active	06/20/1998	FGR50	AO SMITH	\$ 850.00	
1009	Installed/Active	12/14/2006	LTN040G	LOCHINVAR	\$ 850.00	
1010	Installed/Active	07/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
1011	Installed/Active	12/03/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
1012	Installed/Active	08/01/1967	PGX40	AO SMITH	\$ 850.00	
1013	Installed/Active	02/12/2003	FSGL40	AO SMITH	\$ 850.00	
1014	Installed/Active	02/25/1999	FSG50	AO SMITH	\$ 850.00	
1015	Installed/Active	11/17/1998	FSG50	AO SMITH	\$ 850.00	
1016	Installed/Active	12/17/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1017	Installed/Active	11/10/1999	PGR50	AO SMITH	\$ 850.00	
1018	Installed/Active	02/12/2013	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1019	Installed/Active	02/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1020	Installed/Active	12/06/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
1021	Installed/Active	07/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1022	Installed/Active	06/15/2010	PR502T	RUUD	\$ 850.00	\$ 6.04
1023	Installed/Active	09/21/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
1024	Installed/Active	07/08/2003	FSG40	AO SMITH	\$ 850.00	
1025	Installed/Active	09/20/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.51
1026	Installed/Active	11/14/2003	PVR40	AO SMITH	\$ 850.00	
1027	Installed/Active	04/26/2004	FCV40	AO SMITH	\$ 850.00	
1028	Installed/Active	01/04/2002	FSG40	AO SMITH	\$ 850.00	
1029	Installed/Active	02/17/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1030	Installed/Active	01/03/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
1031	Installed/Active	01/29/2004	XTN040	LOCHINVAR	\$ 850.00	
1032	Installed/Active	03/26/1996	PGR40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1033	Installed/Active	01/14/2005	XTN050	LOCHINVAR	\$ 850.00	
1034	Installed/Active	01/10/1996	PR502T	RUUD	\$ 850.00	
1035	Installed/Active	12/27/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
1036	Installed/Active	08/15/2007	FGR50	AO SMITH	\$ 850.00	\$ 10.23
1037	Installed/Active	03/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1038	Installed/Active	10/24/2005	LTN050G	LOCHINVAR	\$ 850.00	
1039	Installed/Active	07/24/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1040	Installed/Active	08/03/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
1041	Installed/Active	01/12/1999	FSG40	AO SMITH	\$ 850.00	
1042	Installed/Active	11/05/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1043	Installed/Active	12/13/2001	PGR50	AO SMITH	\$ 850.00	
1044	Installed/Active	12/13/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1045	Installed/Active	02/14/2006	LTN040G	LOCHINVAR	\$ 850.00	
1046	Installed/Active	11/29/2001	FSG50	AO SMITH	\$ 850.00	
1047	Installed/Active	07/23/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1048	Installed/Active	02/10/2006	LTN040G	LOCHINVAR	\$ 850.00	
1049	Installed/Active	03/03/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
1050	Installed/Active	08/09/2004	XTN050	LOCHINVAR	\$ 850.00	
1051	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1052	Installed/Active	12/18/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1053	Installed/Active	02/07/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1054	Installed/Active	11/27/2000	PGR50	AO SMITH	\$ 850.00	
1055	Installed/Active	07/12/2010	PGR50	AO SMITH	\$ 850.00	\$ 6.04
1056	Installed/Active	06/01/2001	21V402S	RHEEM	\$ 850.00	
1057	Installed/Active	05/04/2006	LTN040G	LOCHINVAR	\$ 850.00	
1058	Installed/Active	11/15/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1059	Installed/Active	11/02/1998	FSG50	AO SMITH	\$ 850.00	
1060	Installed/Active	01/18/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
1061	Installed/Active	04/25/1997	FSG40	AO SMITH	\$ 850.00	
1062	Installed/Active	07/14/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1063	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
1064	Installed/Active	10/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1065	Installed/Active	08/14/2006	LSN041G	LOCHINVAR	\$ 850.00	
1066	Installed/Active	01/12/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
1067	Installed/Active	04/28/2003	PGR50	AO SMITH	\$ 850.00	
1068	Installed/Active	04/11/2005	GVC40	A. O. SMITH	\$ 850.00	
1069	Installed/Active	05/24/2004	RF67120	RUUD	\$ 1,900.00	
1070	Installed/Active	10/13/2011	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.88
1071	Installed/Active	06/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1072	Installed/Active	08/15/1979	RH3063	RUUD	\$ 350.00	
1073	Installed/Active	04/12/1994	G76200	RUUD/RHEEM	\$ 3,350.00	
1074	Installed/Active	03/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
1075	Installed/Active	04/09/1997	FSGL40	AO SMITH	\$ 850.00	
1076	Installed/Active	07/24/2007	P506	RUUD	\$ 1,125.00	\$ 16.35
1077	Installed/Active	11/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
1078	Installed/Active	08/18/2004	GVC50	A. O. SMITH	\$ 850.00	
1079	Installed/Active	11/04/1986	RM5063	RHEEM	\$ 500.00	
1080	Installed/Active	01/17/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
1081	Installed/Active	12/24/2008	FSG30	AO SMITH	\$ 350.00	\$ 14.35
1082	Installed/Active	10/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1083	Installed/Active	05/24/2005	GVC30	AOSMITH	\$ 850.00	
1084	Installed/Active	09/21/2004	XVR50	A. O. SMITH	\$ 850.00	
1085	Installed/Active	05/30/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1086	Installed/Active	04/18/1999	41VR50	RHEEM	\$ 850.00	
1087	Installed/Active	07/17/2002	FSG40	AO SMITH	\$ 850.00	
1088	Installed/Active	04/08/2002	FSG50	AO SMITH	\$ 850.00	
1089	Installed/Active	10/30/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1090	Installed/Active	08/15/2003	FSG40	AO SMITH	\$ 850.00	
1091	Installed/Active	02/09/2013	PH2DV50F	RUUD	\$ 850.00	\$ 7.95
1092	Installed/Active	01/08/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
1093	Installed/Active	04/17/2002	FSG50	AO SMITH	\$ 850.00	
1094	Installed/Active	09/18/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1095	Installed/Active	05/04/1999	FSG50	AO SMITH	\$ 850.00	
1096	Installed/Active	11/03/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
1097	Installed/Active	02/08/2002	FSG40	AO SMITH	\$ 850.00	
1098	Installed/Active	01/22/1999	FGR40	AO SMITH	\$ 850.00	
1099	Installed/Active	11/06/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1100	Installed/Active	01/27/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
1101	Installed/Active	03/06/2006	LSN041G	LOCHINVAR	\$ 850.00	
1102	Installed/Active	06/10/2011	42VR5040F	RHEEM	\$ 850.00	\$ 6.34
1103	Installed/Active	06/02/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
1104	Installed/Active	05/08/1995	FGR50	AO SMITH	\$ 850.00	
1105	Installed/Active	01/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1106	Installed/Active	10/02/2001	PGR40	AO SMITH	\$ 850.00	
1107	Installed/Active	08/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1108	Installed/Active	11/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1109	Installed/Active	07/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1110	Installed/Active	04/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1111	Installed/Active	11/11/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
1112	Installed/Active	02/28/2001	41V50	RHEEM	\$ 850.00	
1113	Installed/Active	07/09/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.51
1114	Installed/Active	04/25/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
1115	Installed/Active	09/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
1116	Installed/Active	07/15/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1117	Installed/Active	10/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1118	Installed/Active	07/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1119	Installed/Active	02/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1120	Installed/Active	04/24/1992	FSG50	AO SMITH	\$ 850.00	
1121	Installed/Active	06/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1122	Installed/Active	02/02/1999	FSGL40	AO SMITH	\$ 850.00	
1123	Installed/Active	08/17/1999	FSG40	AO SMITH	\$ 850.00	
1124	Installed/Active	03/19/1986	PGD30	AO SMITH	\$ 350.00	
1125	Installed/Active	12/31/1992	FSG40	AO SMITH	\$ 850.00	
1126	Installed/Active	06/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.51
1127	Installed/Active	01/11/2001	41VR50	RHEEM	\$ 850.00	
1128	Installed/Active	07/10/2004	GCVL40	A. O. SMITH	\$ 850.00	
1129	Installed/Active	01/16/2004	FCVL40	AO SMITH	\$ 850.00	
1130	Installed/Active	12/01/1976	KGA40	AO SMITH	\$ 850.00	
1131	Installed/Active	12/05/2006	41V50	RHEEM	\$ 850.00	
1132	Installed/Active	03/19/2004	41XR40	RHEEM	\$ 850.00	
1133	Installed/Active	10/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1134	Installed/Active	01/16/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1135	Installed/Active	12/13/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
1136	Installed/Active	01/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1137	Installed/Active	04/11/2011	42VR50	RHEEM	\$ 850.00	\$ 6.34
1138	Installed/Active	01/01/1978	PGC50	AO SMITH	\$ 850.00	
1139	Installed/Active	04/09/1988	FSG40	AO SMITH	\$ 850.00	
1140	Installed/Active	11/24/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1141	Installed/Active	03/21/1989	FSG40	AO SMITH	\$ 850.00	
1142	Installed/Active	07/27/2004	GVC50	A. O. SMITH	\$ 850.00	
1143	Installed/Active	01/04/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1144	Installed/Active	04/11/2003	FSGL30	AO SMITH	\$ 850.00	
1145	Installed/Active	08/15/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1146	Installed/Active	10/29/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1147	Installed/Active	02/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
1148	Installed/Active	09/12/1988	RF67120	RUUD	\$ 1,900.00	
1149	Installed/Active	03/03/2001	41XR40	RHEEM	\$ 850.00	
1150	Installed/Active	08/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1151	Installed/Active	04/17/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1152	Installed/Active	12/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1153	Installed/Active	05/01/1989	G72DUMMY	AO SMITH	\$ 1,750.00	
1154	Installed/Active	05/16/2006	LTN040G	LOCHINVAR	\$ 850.00	
1155	Installed/Active	07/29/2003	FSG40	AO SMITH	\$ 850.00	
1156	Installed/Active	02/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
1157	Installed/Active	10/01/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
1158	Installed/Active	11/02/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1159	Installed/Active	08/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1160	Installed/Active	03/03/1999	41V40	RHEEM	\$ 850.00	
1161	Installed/Active	10/09/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1162	Installed/Active	12/15/2009	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
1163	Installed/Active	08/18/1998	FSG40	AO SMITH	\$ 850.00	
1164	Installed/Active	11/15/2010	21VR40	RHEEM	\$ 850.00	\$ 6.04
1165	Installed/Active	02/05/2013	41XR40	RHEEM	\$ 850.00	\$ 6.39
1166	Installed/Active	10/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1167	Installed/Active	01/13/2006	LTN040G	LOCHINVAR	\$ 850.00	
1168	Installed/Active	02/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1169	Installed/Active	08/17/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.51
1170	Installed/Active	12/20/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1171	Installed/Active	03/15/2006	LTN040G	LOCHINVAR	\$ 850.00	
1172	Installed/Active	09/01/2004	GVC50	A. O. SMITH	\$ 850.00	
1173	Installed/Active	08/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1174	Installed/Active	03/30/2003	21V407	RHEEM	\$ 850.00	
1175	Installed/Active	03/25/2002	PGR50	AO SMITH	\$ 850.00	
1176	Installed/Active	02/01/1978	PGCL40	AO SMITH	\$ 850.00	
1177	Installed/Active	01/06/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
1178	Installed/Active	10/26/2002	FSG50	AO SMITH	\$ 850.00	
1179	Installed/Active	08/20/2004	GVC40	A. O. SMITH	\$ 850.00	
1180	Installed/Active	01/24/2007	PGR50	AO SMITH	\$ 850.00	\$ 5.12
1181	Installed/Active	02/01/1978	KGA30	AO SMITH	\$ 850.00	
1182	Installed/Active	12/29/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1183	Installed/Active	07/08/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1184	Installed/Active	09/11/2003	PVR50	AO SMITH	\$ 850.00	
1185	Installed/Active	02/23/2001	21V407	RHEEM	\$ 850.00	
1186	Installed/Active	04/11/1977	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
1187	Installed/Active	12/21/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
1188	Installed/Active	01/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1189	Installed/Active	07/01/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1190	Installed/Active	01/06/2004	PVR50	AO SMITH	\$ 850.00	
1191	Installed/Active	02/27/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
1192	Installed/Active	01/02/1998	PGR50	AO SMITH	\$ 850.00	
1193	Installed/Active	07/15/1991	FSGL40	AO SMITH	\$ 850.00	
1194	Installed/Active	05/14/2002	FSG30	AO SMITH	\$ 850.00	
1195	Installed/Active	02/11/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1196	Installed/Active	11/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1197	Installed/Active	09/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1198	Installed/Active	07/30/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1199	Installed/Active	10/17/2006	LSN041G	LOCHINVAR	\$ 850.00	
1200	Installed/Active	06/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1201	Installed/Active	01/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1202	Installed/Active	12/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1203	Installed/Active	06/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
1204	Installed/Active	05/05/2003	FSG40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1205	Installed/Active	01/07/1999	FSGL40	AO SMITH	\$ 850.00	
1206	Installed/Active	10/30/2003	PGR50	AO SMITH	\$ 850.00	
1207	Installed/Active	01/25/2006	GVC50	A. O. SMITH	\$ 850.00	
1208	Installed/Active	08/24/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
1209	Installed/Active	09/02/1989	FSG40	AO SMITH	\$ 850.00	
1210	Installed/Active	07/12/2005	LTN050	LOCHINVAR	\$ 850.00	
1211	Installed/Active	01/31/2000	G82156	RUUD/RHEEM	\$ 3,350.00	
1212	Installed/Active	02/25/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
1213	Installed/Active	02/02/2005	FSG30	AO SMITH	\$ 850.00	
1214	Installed/Active	06/12/2001	FSG50	AO SMITH	\$ 850.00	
1215	Installed/Active	07/07/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
1216	Installed/Active	06/12/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1217	Installed/Active	12/27/1988	FSG40	AO SMITH	\$ 850.00	
1218	Installed/Active	04/29/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
1219	Installed/Active	01/15/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
1220	Installed/Active	05/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
1221	Installed/Active	12/06/2002	FSG50	AO SMITH	\$ 850.00	
1222	Installed/Active	03/23/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
1223	Installed/Active	08/10/1999	FSG30	AO SMITH	\$ 850.00	
1224	Installed/Active	02/05/2001	41V50S	RHEEM	\$ 850.00	
1225	Installed/Active	08/30/2005	LTN040	LOCHINVAR	\$ 850.00	
1226	Installed/Active	07/27/2005	LTN050	LOCHINVAR	\$ 850.00	
1227	Installed/Active	09/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1228	Installed/Active	03/04/2003	FSG40	AO SMITH	\$ 850.00	
1229	Installed/Active	11/28/2012	MI75S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.64
1230	Installed/Active	12/20/1991	FSG50	AO SMITH	\$ 850.00	
1231	Installed/Active	11/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1232	Installed/Active	08/27/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1233	Installed/Active	07/14/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1234	Installed/Active	05/02/1998	FGR50	AO SMITH	\$ 850.00	
1235	Installed/Active	12/30/2009	PGX50	AO SMITH	\$ 850.00	\$ 5.88
1236	Installed/Active	11/16/1983	KGA50	AO SMITH	\$ 850.00	
1237	Installed/Active	03/22/2005	GVC40	A. O. SMITH	\$ 850.00	
1238	Installed/Active	11/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1239	Installed/Active	10/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
1240	Installed/Active	11/29/1999	PGR50	AO SMITH	\$ 850.00	
1241	Installed/Active	02/28/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1242	Installed/Active	04/23/2012	P230F	Rheem	\$ 850.00	\$ 6.34
1243	Installed/Active	01/08/1998	FSGL40	AO SMITH	\$ 850.00	
1244	Installed/Active	04/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1245	Installed/Active	04/10/2006	LTN040G	LOCHINVAR	\$ 850.00	
1246	Installed/Active	03/15/2013	MI403S6FBN	Bradford - White	\$ 850.00	\$ 6.39
1247	Installed/Active	07/06/2004	GVC40	A. O. SMITH	\$ 850.00	
1248	Installed/Active	12/18/2007	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
1249	Installed/Active	04/14/2006	LTN030G	AO SMITH	\$ 850.00	
1250	Installed/Active	12/31/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1251	Installed/Active	06/01/1994	PGR30	AO SMITH	\$ 850.00	
1252	Installed/Active	04/14/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
1253	Installed/Active	05/02/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1254	Installed/Active	05/01/1965	PGX40	AO SMITH	\$ 850.00	
1255	Installed/Active	08/20/1999	PHR50	RUUD	\$ 850.00	
1256	Installed/Active	08/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
1257	Installed/Active	02/14/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1258	Installed/Active	11/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1259	Installed/Active	07/16/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1260	Installed/Active	10/15/2002	FSG40	AO SMITH	\$ 850.00	
1261	Installed/Active	08/31/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1262	Installed/Active	06/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1263	Installed/Active	12/14/2001	FSGL40	AO SMITH	\$ 850.00	
1264	Installed/Active	02/25/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1265	Installed/Active	10/20/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
1266	Installed/Active	12/28/2009	21V502	RHEEM	\$ 850.00	\$ 5.88
1267	Installed/Active	07/27/1999	41VR40	RHEEM	\$ 850.00	
1268	Installed/Active	05/10/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
1269	Installed/Active	06/01/1977	KGL40	AO SMITH	\$ 850.00	
1270	Installed/Active	04/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1271	Installed/Active	07/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.51
1272	Installed/Active	08/01/2006	LSN041G	LOCHINVAR	\$ 850.00	
1273	Installed/Active	04/04/2011	42VR50	RHEEM	\$ 850.00	\$ 6.34
1274	Installed/Active	03/29/2004	BT80112	AO SMITH	\$ 1,900.00	
1275	Installed/Active	04/01/2004	GVC50	A. O. SMITH	\$ 850.00	
1276	Installed/Active	04/10/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1277	Installed/Active	01/23/2001	FSG50	AO SMITH	\$ 850.00	
1278	Installed/Active	08/26/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1279	Installed/Active	08/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1280	Installed/Active	10/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1281	Installed/Active	05/14/2004	XTN040	LOCHINVAR	\$ 850.00	
1282	Installed/Active	06/06/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
1283	Installed/Active	02/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1284	Installed/Active	02/03/2000	PGR50	AO SMITH	\$ 850.00	
1285	Installed/Active	03/10/1997	FSGL40	AO SMITH	\$ 850.00	
1286	Installed/Active	04/16/2004	GVC50	A. O. SMITH	\$ 850.00	
1287	Installed/Active	07/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1288	Installed/Active	10/21/2003	PVR50	AO SMITH	\$ 850.00	
1289	Installed/Active	04/30/2001	PGR50	AO SMITH	\$ 850.00	
1290	Installed/Active	05/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1291	Installed/Active	10/14/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
1292	Installed/Active	11/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1293	Installed/Active	02/01/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1294	Installed/Active	10/14/2009	FSG30	AO SMITH	\$ 850.00	\$ 5.88
1295	Installed/Active	01/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1296	Installed/Active	01/07/2010	41V40S	RHEEM	\$ 850.00	\$ 11.74
1297	Installed/Active	10/18/2002	FSG30	AO SMITH	\$ 850.00	
1298	Installed/Active	03/08/1990	FSG40	AO SMITH	\$ 850.00	
1299	Installed/Active	12/03/2003	FCV40	AO SMITH	\$ 850.00	
1300	Installed/Active	05/25/1995	PGR40	AO SMITH	\$ 850.00	
1301	Installed/Active	08/13/2002	FSG40	AO SMITH	\$ 850.00	
1302	Installed/Active	10/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1303	Installed/Active	12/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1304	Installed/Active	07/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1305	Installed/Active	10/12/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1306	Installed/Active	07/01/1978	PGC50	AO SMITH	\$ 850.00	
1307	Installed/Active	07/30/2006	LTN040G	LOCHINVAR	\$ 850.00	
1308	Installed/Active	11/22/2002	G76200	RUUD/RHEEM	\$ 3,350.00	
1309	Installed/Active	02/01/1973	PGX50	AO SMITH	\$ 850.00	
1310	Installed/Active	11/30/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
1311	Installed/Active	03/13/1996	H72DUMMY	AO SMITH	\$ 1,900.00	
1312	Installed/Active	09/05/2004	GVC50	A. O. SMITH	\$ 850.00	
1313	Installed/Active	03/09/2009	21VR40	RHEEM	\$ 850.00	\$ 7.31
1314	Installed/Active	08/23/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
1315	Installed/Active	05/29/2012	P230F	RUUD	\$ 850.00	\$ 6.39
1316	Installed/Active	06/09/2005	LTN050	LOCHINVAR	\$ 850.00	
1317	Installed/Active	08/05/2003	FSG30	AO SMITH	\$ 850.00	
1318	Installed/Active	09/17/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1319	Installed/Active	01/10/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
1320	Installed/Active	08/17/1999	FSG40	AO SMITH	\$ 850.00	
1321	Installed/Active	09/29/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1322	Installed/Active	01/04/2002	FSG50	AO SMITH	\$ 850.00	
1323	Installed/Active	03/28/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
1324	Installed/Active	10/17/2008	RM5063	RUUD	\$ 500.00	\$ 16.35
1325	Installed/Active	03/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1326	Installed/Active	10/18/2002	FSG50	AO SMITH	\$ 850.00	
1327	Installed/Active	10/01/1975	PGD30	AO SMITH	\$ 350.00	
1328	Installed/Active	11/24/2001	FSG50	AO SMITH	\$ 850.00	
1329	Installed/Active	12/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
1330	Installed/Active	05/04/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
1331	Installed/Active	08/11/2000	41XR50	RHEEM	\$ 850.00	
1332	Installed/Active	01/31/2006	LTN040G	LOCHINVAR	\$ 850.00	
1333	Installed/Active	04/08/2005	FCV40	AO SMITH	\$ 850.00	
1334	Installed/Active	02/06/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
1335	Installed/Active	12/08/2004	GVC40	A. O. SMITH	\$ 850.00	
1336	Installed/Active	03/07/2005	GVC50	A. O. SMITH	\$ 850.00	
1337	Installed/Active	02/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1338	Installed/Active	06/23/2012	PH199119	PHOENIX	\$ 3,350.00	\$ 55.60
1339	Installed/Active	09/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
1340	Installed/Active	10/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1341	Installed/Active	05/22/2005	LTN050	LOCHINVAR	\$ 850.00	
1342	Installed/Active	09/21/2012	F72DUMMY	UNKNOWN AT CONVERSION	\$ 350.00	\$ 15.60
1343	Installed/Active	01/05/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1344	Installed/Active	02/24/2006	FSG50	AO SMITH	\$ 850.00	
1345	Installed/Active	02/01/1966	PGX50	AO SMITH	\$ 850.00	
1346	Installed/Active	01/25/1994	H72DUMMY	AO SMITH	\$ 1,900.00	
1347	Installed/Active	09/14/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
1348	Installed/Active	09/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1349	Installed/Active	06/26/1998	FSG40	AO SMITH	\$ 850.00	
1350	Installed/Active	04/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1351	Installed/Active	12/06/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1352	Installed/Active	03/30/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1353	Installed/Active	08/25/2003	FCV50	AO SMITH	\$ 850.00	
1354	Installed/Active	09/04/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1355	Installed/Active	07/19/1999	21V506	RHEEM	\$ 1,125.00	
1356	Installed/Active	03/05/2012	PGX40	AO SMITH	\$ 850.00	\$ 12.64
1357	Installed/Active	03/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1358	Installed/Active	04/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1359	Installed/Active	12/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1360	Installed/Active	02/07/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
1361	Installed/Active	09/13/2001	PGR50	AO SMITH	\$ 850.00	
1362	Installed/Active	12/01/1975	KGL40	AO SMITH	\$ 850.00	
1363	Installed/Active	06/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1364	Installed/Active	06/12/2000	FSGL40	AO SMITH	\$ 850.00	
1365	Installed/Active	08/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1366	Installed/Active	10/19/2003	PGR40	AO SMITH	\$ 850.00	
1367	Installed/Active	11/30/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
1368	Installed/Active	04/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1369	Installed/Active	09/29/2005	LTN040G	LOCHINVAR	\$ 850.00	
1370	Installed/Active	10/05/1998	PGR50	AO SMITH	\$ 850.00	
1371	Installed/Active	10/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1372	Installed/Active	05/27/1998	41VR40	RHEEM	\$ 850.00	
1373	Installed/Active	11/08/2010	21VR40	RHEEM	\$ 850.00	\$ 7.51
1374	Installed/Active	09/12/2000	41V40S	RHEEM	\$ 850.00	
1375	Installed/Active	10/20/2005	LTN050G	LOCHINVAR	\$ 850.00	
1376	Installed/Active	12/11/2000	41XR50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1377	Installed/Active	04/27/2011	21VR50	RHEEM	\$ 850.00	\$ 7.88
1378	Installed/Active	07/08/1997	21V506	RHEEM	\$ 500.00	
1379	Installed/Active	04/17/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1380	Installed/Active	03/21/2006	LTN040G	LOCHINVAR	\$ 850.00	
1381	Installed/Active	10/29/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1382	Installed/Active	10/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
1383	Installed/Active	01/01/1960	G72DUMMY	UNKNOWN AT CONVERSION	\$ 500.00	
1384	Installed/Active	07/31/2002	PGR50	AO SMITH	\$ 850.00	
1385	Installed/Active	11/01/1978	KGA40	AO SMITH	\$ 850.00	
1386	Installed/Active	01/08/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1387	Installed/Active	11/29/2005	G82156	RUUD/RHEEM	\$ 3,350.00	
1388	Installed/Active	03/13/2005	XVR50	A. O. SMITH	\$ 850.00	
1389	Installed/Active	04/13/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 6.37
1390	Installed/Active	01/03/2007	LTN050G	LOCHINVAR	\$ 850.00	
1391	Installed/Active	04/27/2005	GVC50	A. O. SMITH	\$ 850.00	
1392	Installed/Active	08/07/1997	41VR40	RHEEM	\$ 850.00	
1393	Installed/Active	12/28/1999	41XR50	RHEEM	\$ 850.00	
1394	Installed/Active	08/31/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1395	Installed/Active	08/31/2005	GVC50	A. O. SMITH	\$ 850.00	
1396	Installed/Active	03/23/2005	ETN076	LOCHINVAR	\$ 1,900.00	
1397	Installed/Active	10/10/2005	LTN050	LOCHINVAR	\$ 850.00	
1398	Installed/Active	08/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1399	Installed/Active	10/27/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1400	Installed/Active	11/07/2000	21V506	RHEEM	\$ 500.00	
1401	Installed/Active	02/19/2013	M140S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1402	Installed/Active	01/05/2005	LSN041G	LOCHINVAR	\$ 850.00	
1403	Installed/Active	03/02/1999	41VR50	RHEEM	\$ 850.00	
1404	Installed/Active	03/07/2013	M140S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.75
1405	Installed/Active	05/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1406	Installed/Active	05/01/1973	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
1407	Installed/Active	12/21/1999	FSGL40	AO SMITH	\$ 850.00	
1408	Installed/Active	09/27/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1409	Installed/Active	08/31/2000	41XR40	RHEEM	\$ 850.00	
1410	Installed/Active	08/26/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1411	Installed/Active	03/01/2004	XTN040	LOCHINVAR	\$ 850.00	
1412	Installed/Active	11/10/2004	XVR50	A. O. SMITH	\$ 850.00	
1413	Installed/Active	08/31/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1414	Installed/Active	09/02/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1415	Installed/Active	01/05/1996	FSGL40	AO SMITH	\$ 850.00	
1416	Installed/Active	04/06/2005	GVC40	A. O. SMITH	\$ 850.00	
1417	Installed/Active	04/04/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
1418	Installed/Active	12/26/2003	PGR50	AO SMITH	\$ 850.00	
1419	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1420	Installed/Active	04/20/2005	GVC40	A. O. SMITH	\$ 850.00	
1421	Installed/Active	11/17/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
1422	Installed/Active	04/23/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
1423	Installed/Active	12/27/1988	FSGL40	AO SMITH	\$ 850.00	
1424	Installed/Active	08/18/2006	LSN041G	LOCHINVAR	\$ 850.00	
1425	Installed/Active	02/02/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
1426	Installed/Active	04/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1427	Installed/Active	09/10/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
1428	Installed/Active	10/13/2005	LTN050G	LOCHINVAR	\$ 850.00	
1429	Installed/Active	05/29/2002	PGR50	AO SMITH	\$ 850.00	
1430	Installed/Active	11/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1431	Installed/Active	09/05/2008	P506	RUUD	\$ 1,125.00	\$ 16.35
1432	Installed/Active	01/17/2001	41VR40	RHEEM	\$ 850.00	
1433	Installed/Active	05/27/2003	FSG40	AO SMITH	\$ 850.00	
1434	Installed/Active	12/20/1993	FSGL40	AO SMITH	\$ 850.00	
1435	Installed/Active	09/29/1999	FSG50	AO SMITH	\$ 850.00	
1436	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1437	Installed/Active	01/05/2002	PGR50	AO SMITH	\$ 850.00	
1438	Installed/Active	04/25/2000	PHR50	RUUD	\$ 850.00	
1439	Installed/Active	08/18/2006	LTN040G	LOCHINVAR	\$ 850.00	
1440	Installed/Active	04/23/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
1441	Installed/Active	01/29/2004	XTN040	LOCHINVAR	\$ 850.00	
1442	Installed/Active	10/29/2002	FSG50	AO SMITH	\$ 850.00	
1443	Installed/Active	04/06/2001	FSG50	AO SMITH	\$ 850.00	
1444	Installed/Active	12/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1445	Installed/Active	09/25/1999	41VR40	RHEEM	\$ 850.00	
1446	Installed/Active	10/01/1972	PGX50	AO SMITH	\$ 850.00	
1447	Installed/Active	01/11/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1448	Installed/Active	03/11/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
1449	Installed/Active	11/25/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
1450	Installed/Active	06/06/2005	LTN050	LOCHINVAR	\$ 850.00	
1451	Installed/Active	01/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1452	Installed/Active	07/10/2001	FSG40	AO SMITH	\$ 850.00	
1453	Installed/Active	08/27/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1454	Installed/Active	01/13/2011	42VR50	RHEEM	\$ 850.00	\$ 7.51
1455	Installed/Active	11/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1456	Installed/Active	10/06/2003	FCV40	AO SMITH	\$ 850.00	
1457	Installed/Active	08/13/2004	21V502	RHEEM	\$ 850.00	
1458	Installed/Active	04/14/2011	21VR50	RHEEM	\$ 850.00	\$ 7.88
1459	Installed/Active	12/23/2002	PGR50	AO SMITH	\$ 850.00	
1460	Installed/Active	12/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1461	Installed/Active	10/08/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1462	Installed/Active	05/12/2004	GVC50	A. O. SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1463	Installed/Active	01/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1464	Installed/Active	01/11/2012	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1465	Installed/Active	09/10/2004	GVC40	A. O. SMITH	\$ 850.00	
1466	Installed/Active	07/26/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
1467	Installed/Active	09/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1468	Installed/Active	12/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1469	Installed/Active	09/01/1978	PGC40	AO SMITH	\$ 850.00	
1470	Installed/Active	06/23/1993	FSGL40	AO SMITH	\$ 850.00	
1471	Installed/Active	04/13/2004	GVC40	A. O. SMITH	\$ 850.00	
1472	Installed/Active	03/16/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
1473	Installed/Active	09/06/2001	PGR50	AO SMITH	\$ 850.00	
1474	Installed/Active	03/03/2003	FSGL40	AO SMITH	\$ 850.00	
1475	Installed/Active	07/16/2005	LTN040	LOCHINVAR	\$ 850.00	
1476	Installed/Active	07/28/2005	LTN050	LOCHINVAR	\$ 850.00	
1477	Installed/Active	03/08/2000	41XR50	RHEEM	\$ 850.00	
1478	Installed/Active	12/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1479	Installed/Active	04/24/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1480	Installed/Active	08/16/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
1481	Installed/Active	01/17/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
1482	Installed/Active	01/11/1999	FGR40	AO SMITH	\$ 850.00	
1483	Installed/Active	11/20/2007	GVC30	AOSMITH	\$ 850.00	\$ 6.37
1484	Installed/Active	02/25/2005	GVC50	A. O. SMITH	\$ 850.00	
1485	Installed/Active	07/01/1973	PGX40	AO SMITH	\$ 850.00	
1486	Installed/Active	03/16/2004	GVC50	A. O. SMITH	\$ 850.00	
1487	Installed/Active	09/12/2002	PGR50	AO SMITH	\$ 850.00	
1488	Installed/Active	01/30/2004	PVR50	AO SMITH	\$ 850.00	
1489	Installed/Active	01/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1490	Installed/Active	07/22/2002	PGR40	AO SMITH	\$ 850.00	
1491	Installed/Active	05/03/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
1492	Installed/Active	04/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
1493	Installed/Active	01/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1494	Installed/Active	09/03/1999	41VR50	RHEEM	\$ 850.00	
1495	Installed/Active	03/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
1496	Installed/Active	10/21/2000	PGR50	AO SMITH	\$ 850.00	
1497	Installed/Active	05/22/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1498	Installed/Active	10/01/1996	FGR50	AO SMITH	\$ 850.00	
1499	Installed/Active	04/19/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1500	Installed/Active	07/18/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
1501	Installed/Active	08/22/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1502	Installed/Active	03/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
1503	Installed/Active	09/26/2002	FSGL40	AO SMITH	\$ 850.00	
1504	Installed/Active	04/26/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.51
1505	Installed/Active	07/23/1998	FGR40	AO SMITH	\$ 850.00	
1506	Installed/Active	10/10/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
1507	Installed/Active	03/06/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1508	Installed/Active	01/18/2005	XVR40	A. O. SMITH	\$ 850.00	
1509	Installed/Active	03/26/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1510	Installed/Active	03/22/2002	FSG40	AO SMITH	\$ 850.00	
1511	Installed/Active	02/23/2011	22V40SF	RHEEM	\$ 850.00	\$ 6.04
1512	Installed/Active	04/04/2005	GVC40	A. O. SMITH	\$ 850.00	
1513	Installed/Active	05/12/1992	FSG40	AO SMITH	\$ 850.00	
1514	Installed/Active	06/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1515	Installed/Active	10/18/2004	GVC50	A. O. SMITH	\$ 850.00	
1516	Installed/Active	02/24/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
1517	Installed/Active	11/07/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1518	Installed/Active	10/01/1976	KGA40	AO SMITH	\$ 850.00	
1519	Installed/Active	06/04/2011	41VR40	RHEEM	\$ 850.00	\$ 6.34
1520	Installed/Active	01/21/2000	PGR50	AO SMITH	\$ 850.00	
1521	Installed/Active	12/17/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1522	Installed/Active	09/12/2002	FSG50	AO SMITH	\$ 850.00	
1523	Installed/Active	06/01/1971	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
1524	Installed/Active	10/23/1999	FSG30	AO SMITH	\$ 850.00	
1525	Installed/Active	02/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1526	Installed/Active	12/16/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
1527	Installed/Active	10/16/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1528	Installed/Active	12/02/2000	FSGL40	AO SMITH	\$ 850.00	
1529	Installed/Active	05/18/2001	41V50	RHEEM	\$ 850.00	
1530	Installed/Active	08/05/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1531	Installed/Active	06/24/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
1532	Installed/Active	05/28/2000	41XR40	RHEEM	\$ 850.00	
1533	Installed/Active	11/02/1999	PGR50	AO SMITH	\$ 850.00	
1534	Installed/Active	11/14/1978	RH3063	RUUD	\$ 350.00	
1535	Installed/Active	09/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1536	Installed/Active	11/18/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1537	Installed/Active	04/28/1995	PHR50	RUUD	\$ 850.00	
1538	Installed/Active	12/13/2002	FSGL40	AO SMITH	\$ 850.00	
1539	Installed/Active	11/17/1978	G76200	RUUD/RHEEM	\$ 3,350.00	
1540	Installed/Active	04/07/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 6.37
1541	Installed/Active	10/31/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1542	Installed/Active	11/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1543	Installed/Active	12/24/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1544	Installed/Active	05/28/1999	FGR50	AO SMITH	\$ 850.00	
1545	Installed/Active	09/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
1546	Installed/Active	02/13/2009	PGXL40	AO SMITH	\$ 850.00	\$ 5.88
1547	Installed/Active	08/10/2006	LSN041G	LOCHINVAR	\$ 850.00	
1548	Installed/Active	09/02/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1549	Installed/Active	06/15/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1550	Installed/Active	06/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1551	Installed/Active	05/04/2001	FSG50	AO SMITH	\$ 850.00	
1552	Installed/Active	09/22/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
1553	Installed/Active	02/28/2000	FSG40	AO SMITH	\$ 850.00	
1554	Installed/Active	06/09/2006	LSN041G	LOCHINVAR	\$ 850.00	
1555	Installed/Active	10/23/2005	LTN040G	LOCHINVAR	\$ 850.00	
1556	Installed/Active	01/18/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
1557	Installed/Active	06/27/1995	FGR40	AO SMITH	\$ 850.00	
1558	Installed/Active	05/27/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
1559	Installed/Active	08/17/1993	P506	RUUD	\$ 1,125.00	
1560	Installed/Active	03/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1561	Installed/Active	01/11/1997	FGR30	AO SMITH	\$ 850.00	
1562	Installed/Active	03/06/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
1563	Installed/Active	07/02/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1564	Installed/Active	08/08/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1565	Installed/Active	03/10/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
1566	Installed/Active	06/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1567	Installed/Active	06/04/2011	21VR50	RHEEM	\$ 850.00	\$ 7.88
1568	Installed/Active	02/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1569	Installed/Active	03/07/1994	RF92200	RUUD	\$ 3,350.00	
1570	Installed/Active	01/30/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
1571	Installed/Active	02/18/1999	FSG40	AO SMITH	\$ 850.00	
1572	Installed/Active	06/17/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1573	Installed/Active	02/19/1999	FSG40	AO SMITH	\$ 850.00	
1574	Installed/Active	12/18/2012	L72DUMMY	UNKNOWN AT CONVERSION	\$ 3,350.00	\$ 64.59
1575	Installed/Active	03/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
1576	Installed/Active	09/18/2002	PGR50	AO SMITH	\$ 850.00	
1577	Installed/Active	02/17/1989	FSG40	AO SMITH	\$ 850.00	
1578	Installed/Active	03/15/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
1579	Installed/Active	02/26/2000	FSG40	AO SMITH	\$ 850.00	
1580	Installed/Active	11/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1581	Installed/Active	07/15/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1582	Installed/Active	03/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1583	Installed/Active	09/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1584	Installed/Active	08/22/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.51
1585	Installed/Active	01/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1586	Installed/Active	06/01/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
1587	Installed/Active	06/14/2005	LTN050	LOCHINVAR	\$ 850.00	
1588	Installed/Active	07/24/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
1589	Installed/Active	10/01/2003	FSG40	AO SMITH	\$ 850.00	
1590	Installed/Active	04/18/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1591	Installed/Active	01/31/1997	FSGL40	AO SMITH	\$ 850.00	
1592	Installed/Active	08/01/2002	FSG40	AO SMITH	\$ 850.00	
1593	Installed/Active	03/12/1997	FGR40	AO SMITH	\$ 850.00	
1594	Installed/Active	09/28/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1595	Installed/Active	11/17/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1596	Installed/Active	03/16/1999	21V407	RHEEM	\$ 850.00	
1597	Installed/Active	05/23/1997	FGR50	AO SMITH	\$ 850.00	
1598	Installed/Active	05/31/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
1599	Installed/Active	06/01/1964	G67114	RUUD	\$ 850.00	
1600	Installed/Active	06/17/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1601	Installed/Active	05/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
1602	Installed/Active	11/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1603	Installed/Active	02/27/1995	FGR40	AO SMITH	\$ 850.00	
1604	Installed/Active	07/01/2003	PGR40	AO SMITH	\$ 850.00	
1605	Installed/Active	10/10/2001	FSG40	AO SMITH	\$ 850.00	
1606	Installed/Active	12/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1607	Installed/Active	02/17/2007	41V50	RHEEM	\$ 850.00	\$ 6.37
1608	Installed/Active	06/25/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1609	Installed/Active	04/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1610	Installed/Active	12/28/2001	41XR50	RHEEM	\$ 850.00	
1611	Installed/Active	05/26/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1612	Installed/Active	12/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.51
1613	Installed/Active	07/04/1998	FSG40	AO SMITH	\$ 850.00	
1614	Installed/Active	02/14/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
1615	Installed/Active	03/26/1999	G82156	RUUD/RHEEM	\$ 3,350.00	
1616	Installed/Active	06/17/2001	PGR40	AO SMITH	\$ 850.00	
1617	Installed/Active	08/31/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1618	Installed/Active	09/06/2001	FSGL40	AO SMITH	\$ 850.00	
1619	Installed/Active	07/31/1996	G67114	RHEEM	\$ 1,900.00	
1620	Installed/Active	06/09/2005	ETN076	LOCHINVAR	\$ 1,900.00	
1621	Installed/Active	02/19/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
1622	Installed/Active	05/28/1996	FGR40	AO SMITH	\$ 850.00	
1623	Installed/Active	09/13/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1624	Installed/Active	09/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1625	Installed/Active	10/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
1626	Installed/Active	06/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1627	Installed/Active	11/15/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
1628	Installed/Active	11/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1629	Installed/Active	03/27/1991	FSGL40	AO SMITH	\$ 850.00	
1630	Installed/Active	02/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1631	Installed/Active	02/20/2003	FSG30	AO SMITH	\$ 850.00	
1632	Installed/Active	03/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1633	Installed/Active	09/16/2002	FSGL40	AO SMITH	\$ 850.00	
1634	Installed/Active	08/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1635	Installed/Active	09/16/2000	41XR50	RHEEM	\$ 850.00	
1636	Installed/Active	03/27/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
1637	Installed/Active	12/06/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1638	Installed/Active	08/04/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1639	Installed/Active	08/06/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1640	Installed/Active	09/09/2008	P506	RUUD	\$ 1,125.00	\$ 16.35
1641	Installed/Active	03/13/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1642	Installed/Active	10/17/2004	GCVL40	A. O. SMITH	\$ 850.00	
1643	Installed/Active	05/31/2002	FSG50	AO SMITH	\$ 850.00	
1644	Installed/Active	02/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1645	Installed/Active	05/17/1978	RM5063	RHEEM	\$ 500.00	
1646	Installed/Active	07/03/2000	41XR50	RHEEM	\$ 850.00	
1647	Installed/Active	06/18/2002	FSG40	AO SMITH	\$ 850.00	
1648	Installed/Active	09/23/1994	FSGL40	AO SMITH	\$ 850.00	
1649	Installed/Active	12/03/2004	GVC50	A. O. SMITH	\$ 850.00	
1650	Installed/Active	04/21/2003	PGR50	AO SMITH	\$ 850.00	
1651	Installed/Active	10/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1652	Installed/Active	10/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1653	Installed/Active	08/17/2004	XVR50	A. O. SMITH	\$ 850.00	
1654	Installed/Active	03/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1655	Installed/Active	10/29/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1656	Installed/Active	04/06/2001	41V50	RHEEM	\$ 850.00	
1657	Installed/Active	02/25/2010	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
1658	Installed/Active	11/27/2001	FSGL40	AO SMITH	\$ 850.00	
1659	Installed/Active	01/14/2009	21VR40	RHEEM	\$ 850.00	\$ 5.88
1660	Installed/Active	08/19/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1661	Installed/Active	12/10/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1662	Installed/Active	05/02/2004	GVC40	A. O. SMITH	\$ 850.00	
1663	Installed/Active	12/19/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1664	Installed/Active	08/27/2008	ETN076	LOCHINVAR	\$ 1,900.00	\$ 33.40
1665	Installed/Active	07/03/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1666	Installed/Active	10/03/2003	PVR40	AO SMITH	\$ 850.00	
1667	Installed/Active	11/04/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
1668	Installed/Active	02/26/2004	XTN050	LOCHINVAR	\$ 850.00	
1669	Installed/Active	05/03/2000	FSG50	AO SMITH	\$ 850.00	
1670	Installed/Active	06/01/1967	PGX50	AO SMITH	\$ 850.00	
1671	Installed/Active	03/18/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1672	Installed/Active	06/14/2002	PRX50	STATE	\$ 1,075.00	
1673	Installed/Active	05/20/1992	H72DUMMY	AO SMITH	\$ 1,900.00	
1674	Installed/Active	05/03/2004	GVC50	A. O. SMITH	\$ 850.00	
1675	Installed/Active	12/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1676	Installed/Active	09/21/1998	FGR40	AO SMITH	\$ 350.00	
1677	Installed/Active	10/28/2010	PVR50	AO SMITH	\$ 850.00	\$ 6.04
1678	Installed/Active	02/05/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 5.12
1679	Installed/Active	07/21/1994	FGR40	AO SMITH	\$ 850.00	
1680	Installed/Active	10/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1681	Installed/Active	04/27/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
1682	Installed/Active	05/28/2012	P230F	RUUD	\$ 850.00	\$ 6.39
1683	Installed/Active	09/21/2007	ETN065	LOCHINVAR	\$ 1,125.00	\$ 16.35
1684	Installed/Active	05/26/2005	LTN040	LOCHINVAR	\$ 850.00	
1685	Installed/Active	09/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1686	Installed/Active	04/11/1995	21V506	RHEEM	\$ 1,900.00	
1687	Installed/Active	02/11/2002	FSG40	AO SMITH	\$ 850.00	
1688	Installed/Active	04/12/2002	FSG40	AO SMITH	\$ 850.00	
1689	Installed/Active	06/05/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1690	Installed/Active	01/01/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1691	Installed/Active	04/12/2002	PGR50	AO SMITH	\$ 850.00	
1692	Installed/Active	07/22/2004	42V6050	RHEEM	\$ 1,125.00	
1693	Installed/Active	07/25/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1694	Installed/Active	10/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1695	Installed/Active	02/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1696	Installed/Active	03/02/2000	PGR50	AO SMITH	\$ 850.00	
1697	Installed/Active	04/23/2007	XSN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1698	Installed/Active	10/09/2000	41XR50	RHEEM	\$ 850.00	
1699	Installed/Active	01/12/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
1700	Installed/Active	06/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
1701	Installed/Active	01/24/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1702	Installed/Active	02/02/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
1703	Installed/Active	07/14/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
1704	Installed/Active	09/17/2004	XVR50	A. O. SMITH	\$ 850.00	
1705	Installed/Active	09/28/2004	LTN040	LOCHINVAR	\$ 850.00	
1706	Installed/Active	05/05/2010	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
1707	Installed/Active	12/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1708	Installed/Active	07/14/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
1709	Installed/Active	05/01/2001	FSG50	AO SMITH	\$ 850.00	
1710	Installed/Active	05/05/2010	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
1711	Installed/Active	11/14/1997	21V402S	RHEEM	\$ 850.00	
1712	Installed/Active	06/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
1713	Installed/Active	01/04/2005	LSN041G	LOCHINVAR	\$ 850.00	
1714	Installed/Active	03/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
1715	Installed/Active	04/13/1998	PGR40	AO SMITH	\$ 850.00	
1716	Installed/Active	12/11/1999	FSG40	AO SMITH	\$ 850.00	
1717	Installed/Active	10/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1718	Installed/Active	10/06/1997	FGR50	AO SMITH	\$ 1,125.00	
1719	Installed/Active	08/29/1997	PGR40	AO SMITH	\$ 850.00	
1720	Installed/Active	04/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1721	Installed/Active	01/15/2002	FSG40	AO SMITH	\$ 850.00	
1722	Installed/Active	10/20/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
1723	Installed/Active	02/07/2013	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1724	Installed/Active	02/18/2005	XVR50	A. O. SMITH	\$ 850.00	
1725	Installed/Active	02/21/2001	FSG50	AO SMITH	\$ 850.00	
1726	Installed/Active	07/23/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1727	Installed/Active	05/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
1728	Installed/Active	08/30/1994	RF67120	RUUD	\$ 1,900.00	
1729	Installed/Active	05/23/1997	FSG40	AO SMITH	\$ 850.00	
1730	Installed/Active	09/29/2000	FSGL40	AO SMITH	\$ 850.00	
1731	Installed/Active	05/02/2002	41XR50	RHEEM	\$ 850.00	
1732	Installed/Active	05/01/1979	RM5063	RUUD	\$ 500.00	
1733	Installed/Active	01/02/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1734	Installed/Active	01/05/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
1735	Installed/Active	10/23/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1736	Installed/Active	02/19/1999	41VR50	RHEEM	\$ 850.00	
1737	Installed/Active	08/29/2002	FSG50	AO SMITH	\$ 850.00	
1738	Installed/Active	01/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1739	Installed/Active	05/04/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
1740	Installed/Active	11/29/2004	XVR50	A. O. SMITH	\$ 850.00	
1741	Installed/Active	07/01/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
1742	Installed/Active	01/18/1996	PR502T	RUUD	\$ 850.00	
1743	Installed/Active	09/28/2001	41XR50	RHEEM	\$ 850.00	
1744	Installed/Active	10/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1745	Installed/Active	12/27/2001	FSG40	AO SMITH	\$ 850.00	
1746	Installed/Active	11/03/2002	FSG50	AO SMITH	\$ 850.00	
1747	Installed/Active	04/26/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1748	Installed/Active	04/01/2011	41VR40	RHEEM	\$ 850.00	\$ 6.34
1749	Installed/Active	12/23/1997	PGR50	AO SMITH	\$ 850.00	
1750	Installed/Active	10/01/1994	PGR50	AO SMITH	\$ 850.00	
1751	Installed/Active	11/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1752	Installed/Active	02/14/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
1753	Installed/Active	11/27/2004	XVR50	A. O. SMITH	\$ 850.00	
1754	Installed/Active	08/31/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
1755	Installed/Active	03/31/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
1756	Installed/Active	03/16/2004	XTN040	LOCHINVAR	\$ 850.00	
1757	Installed/Active	01/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1758	Installed/Active	06/29/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1759	Installed/Active	01/03/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
1760	Installed/Active	04/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1761	Installed/Active	12/30/1992	FSG50	AO SMITH	\$ 850.00	
1762	Installed/Active	11/23/2011	PR502T	RUUD	\$ 850.00	\$ 12.64
1763	Installed/Active	07/01/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1764	Installed/Active	06/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1765	Installed/Active	10/01/2003	FSG40	AO SMITH	\$ 850.00	
1766	Installed/Active	04/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1767	Installed/Active	05/24/2005	LTN040	LOCHINVAR	\$ 850.00	
1768	Installed/Active	08/30/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
1769	Installed/Active	05/26/2000	PGR50	AO SMITH	\$ 850.00	
1770	Installed/Active	04/26/1996	G75125	RUUD/RHEEM	\$ 1,900.00	
1771	Installed/Active	02/13/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
1772	Installed/Active	10/01/1968	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
1773	Installed/Active	05/21/1998	FGR50	AO SMITH	\$ 850.00	
1774	Installed/Active	09/16/1999	FSG40	AO SMITH	\$ 850.00	
1775	Installed/Active	07/08/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
1776	Installed/Active	03/28/2003	FSGL40	AO SMITH	\$ 850.00	
1777	Installed/Active	01/14/2009	21VR40	RHEEM	\$ 850.00	\$ 5.88
1778	Installed/Active	08/17/2001	FSG40	AO SMITH	\$ 850.00	
1779	Installed/Active	10/23/2003	FCV50	AO SMITH	\$ 850.00	
1780	Installed/Active	09/18/2001	FSG50	AO SMITH	\$ 850.00	
1781	Installed/Active	02/18/1999	41V50	RHEEM	\$ 850.00	
1782	Installed/Active	07/10/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1783	Installed/Active	12/26/1996	PGR40	AO SMITH	\$ 850.00	
1784	Installed/Active	07/10/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1785	Installed/Active	08/02/2006	LSN041G	LOCHINVAR	\$ 850.00	
1786	Installed/Active	11/02/2010	21VR50	RHEEM	\$ 850.00	\$ 7.51
1787	Installed/Active	03/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
1788	Installed/Active	06/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1789	Installed/Active	09/24/2008	PHR40	RUUD	\$ 850.00	\$ 10.23
1790	Installed/Active	02/19/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
1791	Installed/Active	01/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1792	Installed/Active	10/08/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
1793	Installed/Active	10/08/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1794	Installed/Active	12/10/1999	PGR50	AO SMITH	\$ 850.00	
1795	Installed/Active	10/11/1999	FSGL40	AO SMITH	\$ 850.00	
1796	Installed/Active	02/27/2007	FSG40	AO SMITH	\$ 850.00	\$ 10.23
1797	Installed/Active	01/02/2002	FSG50	AO SMITH	\$ 850.00	
1798	Installed/Active	12/15/2006	GCVL40	A. O. SMITH	\$ 850.00	
1799	Installed/Active	12/11/2009	LTN030G	AO SMITH	\$ 850.00	\$ 5.88
1800	Installed/Active	10/30/2003	PGR40	AO SMITH	\$ 850.00	
1801	Installed/Active	10/11/2005	LTN050	LOCHINVAR	\$ 850.00	
1802	Installed/Active	02/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
1803	Installed/Active	07/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1804	Installed/Active	01/05/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
1805	Installed/Active	06/14/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
1806	Installed/Active	10/16/2002	PRX50	STATE	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1807	Installed/Active	12/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
1808	Installed/Active	04/21/2006	LTN040G	LOCHINVAR	\$ 850.00	
1809	Installed/Active	11/20/2003	PGR50	AO SMITH	\$ 850.00	
1810	Installed/Active	03/16/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
1811	Installed/Active	09/01/1981	H72DUMMY	AO SMITH	\$ 1,900.00	
1812	Installed/Active	07/21/1994	FGR40	AO SMITH	\$ 850.00	
1813	Installed/Active	09/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
1814	Installed/Active	09/05/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1815	Installed/Active	12/07/2007	LTN040	LOCHINVAR	\$ 850.00	\$ 5.12
1816	Installed/Active	09/13/2005	LTN040	LOCHINVAR	\$ 850.00	
1817	Installed/Active	03/28/2002	FSGL40	AO SMITH	\$ 850.00	
1818	Installed/Active	12/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1819	Installed/Active	03/09/1998	PGR40	AO SMITH	\$ 850.00	
1820	Installed/Active	06/22/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
1821	Installed/Active	09/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.51
1822	Installed/Active	12/23/2006	LSN041G	LOCHINVAR	\$ 850.00	
1823	Installed/Active	01/31/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1824	Installed/Active	02/17/1998	G67114	RHEEM	\$ 1,900.00	
1825	Installed/Active	12/23/2003	PGR50	AO SMITH	\$ 850.00	
1826	Installed/Active	11/03/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1827	Installed/Active	02/15/2011	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1828	Installed/Active	08/17/2007	TNR200100	LOCHINVAR	\$ 3,350.00	\$ 51.80
1829	Installed/Active	03/21/1998	PGR50	AO SMITH	\$ 850.00	
1830	Installed/Active	09/30/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1831	Installed/Active	08/16/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1832	Installed/Active	02/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1833	Installed/Active	05/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1834	Installed/Active	09/12/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
1835	Installed/Active	01/23/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1836	Installed/Active	10/31/2006	LSN041G	LOCHINVAR	\$ 850.00	
1837	Installed/Active	02/21/2006	LTN040G	LOCHINVAR	\$ 850.00	
1838	Installed/Active	08/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1839	Installed/Active	09/16/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1840	Installed/Active	05/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1841	Installed/Active	08/01/1964	PGX30	AO SMITH	\$ 850.00	
1842	Installed/Active	02/01/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1843	Installed/Active	11/29/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1844	Installed/Active	09/13/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1845	Installed/Active	08/27/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
1846	Installed/Active	06/29/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
1847	Installed/Active	02/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
1848	Installed/Active	09/16/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1849	Installed/Active	08/05/2009	42VR50	RHEEM	\$ 850.00	\$ 7.31
1850	Installed/Active	09/04/1996	FGR50	AO SMITH	\$ 850.00	
1851	Installed/Active	08/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1852	Installed/Active	03/15/2005	GCVL40	A. O. SMITH	\$ 850.00	
1853	Installed/Active	04/25/2011	41VR50	RHEEM	\$ 850.00	\$ 7.88
1854	Installed/Active	03/12/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 6.37
1855	Installed/Active	05/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1856	Installed/Active	11/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
1857	Installed/Active	03/25/2002	FSGL40	AO SMITH	\$ 850.00	
1858	Installed/Active	01/20/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1859	Installed/Active	08/02/2004	P506	RUUD	\$ 1,125.00	
1860	Installed/Active	10/10/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
1861	Installed/Active	09/17/1996	PGR40	AO SMITH	\$ 850.00	
1862	Installed/Active	08/11/1998	FGR40	AO SMITH	\$ 850.00	
1863	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
1864	Installed/Active	07/31/2006	LSN041G	LOCHINVAR	\$ 850.00	
1865	Installed/Active	06/14/2012	FCV50	AO SMITH	\$ 850.00	\$ 6.39
1866	Installed/Active	04/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
1867	Installed/Active	07/08/2002	FSG50	AO SMITH	\$ 850.00	
1868	Installed/Active	04/13/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
1869	Installed/Active	01/05/2011	41VR40	RHEEM	\$ 850.00	\$ 6.04
1870	Installed/Active	04/26/2000	FSG40	AO SMITH	\$ 850.00	
1871	Installed/Active	06/08/1992	FSG50	AO SMITH	\$ 850.00	
1872	Installed/Active	05/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
1873	Installed/Active	02/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1874	Installed/Active	05/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
1875	Installed/Active	05/27/2005	LTN050	LOCHINVAR	\$ 850.00	
1876	Installed/Active	04/21/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
1877	Installed/Active	04/08/2003	PGR50	AO SMITH	\$ 850.00	
1878	Installed/Active	12/30/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1879	Installed/Active	09/10/1999	PHR50	RUUD	\$ 850.00	
1880	Installed/Active	10/30/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1881	Installed/Active	05/10/2012	PH2DV50F	RUUD	\$ 850.00	\$ 6.34
1882	Installed/Active	10/30/2000	FSG40	AO SMITH	\$ 850.00	
1883	Installed/Active	06/07/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
1884	Installed/Active	11/27/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
1885	Installed/Active	08/03/2006	LTN040G	LOCHINVAR	\$ 850.00	
1886	Installed/Active	05/11/2000	FSG40	AO SMITH	\$ 850.00	
1887	Installed/Active	01/08/2003	41V50S	RHEEM	\$ 850.00	
1888	Installed/Active	06/19/2004	FCV40	AO SMITH	\$ 850.00	
1889	Installed/Active	11/12/2002	FSG40	AO SMITH	\$ 850.00	
1890	Installed/Active	06/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1891	Installed/Active	12/21/2002	FSGL40	AO SMITH	\$ 850.00	
1892	Installed/Active	01/11/2001	41XR50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1893	Installed/Active	09/17/1999	41VR50	RHEEM	\$ 850.00	
1894	Installed/Active	07/01/1978	PGC50	AO SMITH	\$ 850.00	
1895	Installed/Active	05/29/2004	XVR50	A. O. SMITH	\$ 850.00	
1896	Installed/Active	01/21/2002	FSG30	AO SMITH	\$ 850.00	
1897	Installed/Active	10/02/2000	FSGL40	AO SMITH	\$ 850.00	
1898	Installed/Active	05/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1899	Installed/Active	01/08/2004	21V506	RHEEM	\$ 500.00	
1900	Installed/Active	05/07/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
1901	Installed/Active	03/05/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 6.37
1902	Installed/Active	11/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1903	Installed/Active	12/27/2005	LTN040G	LOCHINVAR	\$ 850.00	
1904	Installed/Active	12/22/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
1905	Installed/Active	04/01/2005	GVC50	A. O. SMITH	\$ 850.00	
1906	Installed/Active	05/05/1997	PGR50	AO SMITH	\$ 850.00	
1907	Installed/Active	03/04/2002	PGR40	AO SMITH	\$ 850.00	
1908	Installed/Active	05/25/1994	PGR50	AO SMITH	\$ 850.00	
1909	Installed/Active	10/22/1986	G76200	RUUD/RHEEM	\$ 3,350.00	
1910	Installed/Active	07/12/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
1911	Installed/Active	07/23/2003	FSG40	AO SMITH	\$ 850.00	
1912	Installed/Active	10/03/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1913	Installed/Active	04/12/1999	FGR50	AO SMITH	\$ 850.00	
1914	Installed/Active	12/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
1915	Installed/Active	09/08/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1916	Installed/Active	03/06/2003	FSG40	AO SMITH	\$ 850.00	
1917	Installed/Active	05/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1918	Installed/Active	06/02/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1919	Installed/Active	06/12/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
1920	Installed/Active	07/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1921	Installed/Active	09/02/1999	41VR40	RHEEM	\$ 850.00	
1922	Installed/Active	01/22/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1923	Installed/Active	12/05/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
1924	Installed/Active	06/16/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
1925	Installed/Active	07/17/2000	PHR40	RUUD	\$ 850.00	
1926	Installed/Active	12/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1927	Installed/Active	08/24/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
1928	Installed/Active	08/27/2003	PGR40	AO SMITH	\$ 850.00	
1929	Installed/Active	09/17/2002	PGR50	AO SMITH	\$ 850.00	
1930	Installed/Active	02/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
1931	Installed/Active	12/10/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
1932	Installed/Active	03/28/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1933	Installed/Active	12/04/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
1934	Installed/Active	07/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1935	Installed/Active	07/11/1997	PGR50	AO SMITH	\$ 850.00	
1936	Installed/Active	10/15/2004	GCVL40	A. O. SMITH	\$ 850.00	
1937	Installed/Active	03/05/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
1938	Installed/Active	09/17/2001	FSG40	AO SMITH	\$ 850.00	
1939	Installed/Active	01/15/2003	H72DUMMY	AO SMITH	\$ 1,900.00	
1940	Installed/Active	11/25/1997	FGR40	AO SMITH	\$ 850.00	
1941	Installed/Active	11/08/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
1942	Installed/Active	04/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1943	Installed/Active	03/21/2005	GVC50	A. O. SMITH	\$ 850.00	
1944	Installed/Active	08/18/2008	P506	RUUD	\$ 1,125.00	\$ 16.35
1945	Installed/Active	12/24/2001	FSG40	AO SMITH	\$ 850.00	
1946	Installed/Active	01/10/2011	42XR50	RHEEM	\$ 850.00	\$ 6.04
1947	Installed/Active	12/01/2005	LTN040G	LOCHINVAR	\$ 850.00	
1948	Installed/Active	07/08/2011	42VR50	RHEEM	\$ 850.00	\$ 7.88
1949	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
1950	Installed/Active	03/11/2003	PGR50	AO SMITH	\$ 850.00	
1951	Installed/Active	09/14/1991	21V502	RHEEM	\$ 850.00	
1952	Installed/Active	11/01/1974	PGX50	AO SMITH	\$ 850.00	
1953	Installed/Active	12/30/1974	PGX40	AO SMITH	\$ 850.00	
1954	Installed/Active	07/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1955	Installed/Active	12/07/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1956	Installed/Active	12/29/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1957	Installed/Active	08/02/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1958	Installed/Active	01/12/2006	LSN041G	LOCHINVAR	\$ 850.00	
1959	Installed/Active	06/07/1996	FGR50	AO SMITH	\$ 850.00	
1960	Installed/Active	02/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
1961	Installed/Active	10/11/2001	FSG30	AO SMITH	\$ 850.00	
1962	Installed/Active	07/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
1963	Installed/Active	02/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1964	Installed/Active	04/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1965	Installed/Active	06/19/2003	FSG50	AO SMITH	\$ 850.00	
1966	Installed/Active	05/05/2006	SBF100199NES	STATE	\$ 3,350.00	
1967	Installed/Active	01/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
1968	Installed/Active	08/16/2000	FSG40	AO SMITH	\$ 850.00	
1969	Installed/Active	03/13/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
1970	Installed/Active	01/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1971	Installed/Active	11/17/2011	FGR50	AO SMITH	\$ 850.00	\$ 12.64
1972	Installed/Active	01/26/1998	FSG50	AO SMITH	\$ 850.00	
1973	Installed/Active	06/09/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
1974	Installed/Active	06/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
1975	Installed/Active	10/24/1974	PGXL40	AO SMITH	\$ 850.00	
1976	Installed/Active	03/04/2005	GVC50	A. O. SMITH	\$ 850.00	
1977	Installed/Active	05/31/1997	PGR40	AO SMITH	\$ 850.00	
1978	Installed/Active	03/11/1997	21VR40	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
1979	Installed/Active	03/04/1999	FSG40	AO SMITH	\$ 850.00	
1980	Installed/Active	12/13/2001	FSG50	AO SMITH	\$ 850.00	
1981	Installed/Active	10/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
1982	Installed/Active	11/11/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
1983	Installed/Active	02/09/2002	FSG40	AO SMITH	\$ 850.00	
1984	Installed/Active	01/09/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
1985	Installed/Active	12/11/2009	21V407	RHEEM	\$ 350.00	\$ 14.35
1986	Installed/Active	08/24/2005	G82156	RUUD/RHEEM	\$ 3,350.00	
1987	Installed/Active	11/23/2001	PGR50	AO SMITH	\$ 850.00	
1988	Installed/Active	09/01/1978	RH3063	RUUD	\$ 350.00	
1989	Installed/Active	07/24/2001	FSG40	AO SMITH	\$ 850.00	
1990	Installed/Active	09/04/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1991	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
1992	Installed/Active	04/20/1999	FGR50	AO SMITH	\$ 850.00	
1993	Installed/Active	09/30/1970	PGX50	AO SMITH	\$ 850.00	
1994	Installed/Active	04/27/2005	LTN050	LOCHINVAR	\$ 850.00	
1995	Installed/Active	02/11/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
1996	Installed/Active	08/29/1999	FGR40	AO SMITH	\$ 850.00	
1997	Installed/Active	02/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
1998	Installed/Active	06/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
1999	Installed/Active	12/11/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
2000	Installed/Active	10/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
2001	Installed/Active	12/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2002	Installed/Active	07/05/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2003	Installed/Active	06/29/1993	FSG40	AO SMITH	\$ 850.00	
2004	Installed/Active	10/16/2001	FSG40	AO SMITH	\$ 850.00	
2005	Installed/Active	09/10/2004	FSG40	AO SMITH	\$ 850.00	
2006	Installed/Active	07/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2007	Installed/Active	10/12/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2008	Installed/Active	10/03/2001	FSG40	AO SMITH	\$ 850.00	
2009	Installed/Active	06/22/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
2010	Installed/Active	02/12/2001	41V40S	RHEEM	\$ 850.00	
2011	Installed/Active	07/01/1969	PGX40	AO SMITH	\$ 850.00	
2012	Installed/Active	12/14/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
2013	Installed/Active	09/18/2006	LTN040G	LOCHINVAR	\$ 850.00	
2014	Installed/Active	08/14/2001	FSG40	AO SMITH	\$ 850.00	
2015	Installed/Active	07/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2016	Installed/Active	08/29/1997	41VR50	RHEEM	\$ 850.00	
2017	Installed/Active	08/15/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2018	Installed/Active	08/05/2003	PVR40	AO SMITH	\$ 850.00	
2019	Installed/Active	12/28/2004	GCVL40	A. O. SMITH	\$ 850.00	
2020	Installed/Active	05/27/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
2021	Installed/Active	03/30/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 5.12
2022	Installed/Active	01/11/2005	GVC40	A. O. SMITH	\$ 850.00	
2023	Installed/Active	05/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
2024	Installed/Active	08/19/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2025	Installed/Active	10/05/1992	FSG50	AO SMITH	\$ 850.00	
2026	Installed/Active	04/13/2004	XVR40	A. O. SMITH	\$ 850.00	
2027	Installed/Active	02/18/2005	LTN050	LOCHINVAR	\$ 850.00	
2028	Installed/Active	10/29/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2029	Installed/Active	08/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
2030	Installed/Active	05/16/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
2031	Installed/Active	08/11/2003	FSGL40	AO SMITH	\$ 850.00	
2032	Installed/Active	03/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2033	Installed/Active	04/14/2001	41V50	RHEEM	\$ 850.00	
2034	Installed/Active	04/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2035	Installed/Active	12/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
2036	Installed/Active	01/16/2009	FGR50	AO SMITH	\$ 850.00	\$ 5.88
2037	Installed/Active	09/03/1992	RF67120	RUUD	\$ 1,900.00	
2038	Installed/Active	06/20/2000	FSG40	AO SMITH	\$ 850.00	
2039	Installed/Active	10/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2040	Installed/Active	04/23/2004	XSN040	LOCHINVAR	\$ 850.00	
2041	Installed/Active	05/02/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
2042	Installed/Active	03/08/2005	XVR40	A. O. SMITH	\$ 850.00	
2043	Installed/Active	05/26/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2044	Installed/Active	01/17/2007	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
2045	Installed/Active	04/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
2046	Installed/Active	09/15/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 39.36
2047	Installed/Active	05/31/2000	FSGL30	AO SMITH	\$ 850.00	
2048	Installed/Active	11/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2049	Installed/Active	07/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2050	Installed/Active	11/20/2001	FSG30	AO SMITH	\$ 850.00	
2051	Installed/Active	12/06/1990	FSG40	AO SMITH	\$ 850.00	
2052	Installed/Active	11/21/2001	PGR50	AO SMITH	\$ 850.00	
2053	Installed/Active	09/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
2054	Installed/Active	06/06/2002	FSG40	AO SMITH	\$ 850.00	
2055	Installed/Active	06/12/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2056	Installed/Active	11/02/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2057	Installed/Active	12/16/1991	FSG40	AO SMITH	\$ 850.00	
2058	Installed/Active	12/18/2001	FSGL40	AO SMITH	\$ 850.00	
2059	Installed/Active	04/07/2010	41V50	RHEEM	\$ 850.00	\$ 5.88
2060	Installed/Active	10/18/2004	FSG40	AO SMITH	\$ 850.00	
2061	Installed/Active	11/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2062	Installed/Active	01/17/2007	A71	UNKNOWN	\$ 850.00	\$ 6.37
2063	Installed/Active	07/23/2002	FSG50	AO SMITH	\$ 850.00	
2064	Installed/Active	09/11/2001	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2065	Installed/Active	04/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2066	Installed/Active	01/12/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
2067	Installed/Active	02/28/1990	FSG30	AO SMITH	\$ 850.00	
2068	Installed/Active	07/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
2069	Installed/Active	02/06/2003	FSG50	AO SMITH	\$ 850.00	
2070	Installed/Active	11/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2071	Installed/Active	06/30/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
2072	Installed/Active	08/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2073	Installed/Active	11/08/1991	RF82156	RUUD	\$ 3,350.00	
2074	Installed/Active	01/22/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2075	Installed/Active	06/09/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2076	Installed/Active	05/22/2011	21V506	RHEEM	\$ 1,125.00	\$ 20.21
2077	Installed/Active	06/21/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
2078	Installed/Active	10/19/2001	FSG50	AO SMITH	\$ 850.00	
2079	Installed/Active	05/07/2012	P230F	RUUD	\$ 850.00	\$ 6.34
2080	Installed/Active	08/11/1999	P402	RUUD	\$ 850.00	
2081	Installed/Active	03/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2082	Installed/Active	12/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2083	Installed/Active	03/18/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2084	Installed/Active	05/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
2085	Installed/Active	03/20/2012	M403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2086	Installed/Active	08/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2087	Installed/Active	02/14/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2088	Installed/Active	05/01/2006	LTN040G	LOCHINVAR	\$ 850.00	
2089	Installed/Active	04/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2090	Installed/Active	12/29/1999	41V50	RHEEM	\$ 850.00	
2091	Installed/Active	08/01/1969	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
2092	Installed/Active	04/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
2093	Installed/Active	05/28/1991	21V502	RHEEM	\$ 850.00	
2094	Installed/Active	12/04/2002	PGR50	AO SMITH	\$ 850.00	
2095	Installed/Active	07/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2096	Installed/Active	06/20/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
2097	Installed/Active	10/23/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2098	Installed/Active	07/13/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
2099	Installed/Active	03/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2100	Installed/Active	05/21/2002	FSG40	AO SMITH	\$ 850.00	
2101	Installed/Active	07/31/2000	41XR40	RHEEM	\$ 850.00	
2102	Installed/Active	01/10/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.31
2103	Installed/Active	02/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
2104	Installed/Active	03/06/2000	FSG30	AO SMITH	\$ 850.00	
2105	Installed/Active	12/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2106	Installed/Active	12/14/2001	FSG50	AO SMITH	\$ 850.00	
2107	Installed/Active	06/04/2007	FSG50	AO SMITH	\$ 850.00	\$ 6.37
2108	Installed/Active	04/17/2001	PGR50	AO SMITH	\$ 850.00	
2109	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2110	Installed/Active	10/22/2008	FSG40	AO SMITH	\$ 850.00	\$ 6.37
2111	Installed/Active	04/01/1969	PGX50	AO SMITH	\$ 850.00	
2112	Installed/Active	09/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
2113	Installed/Active	11/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2114	Installed/Active	10/14/2005	KGA50	AO SMITH	\$ 850.00	
2115	Installed/Active	07/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2116	Installed/Active	05/05/1975	KGA50	AO SMITH	\$ 850.00	
2117	Installed/Active	06/27/1989	FSG50	AO SMITH	\$ 850.00	
2118	Installed/Active	01/14/2010	FGR30	AO SMITH	\$ 850.00	\$ 5.88
2119	Installed/Active	12/22/1999	FSG40	AO SMITH	\$ 850.00	
2120	Installed/Active	10/15/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2121	Installed/Active	04/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
2122	Installed/Active	09/12/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2123	Installed/Active	05/12/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2124	Installed/Active	11/04/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
2125	Installed/Active	04/08/2002	FSG40	AO SMITH	\$ 850.00	
2126	Installed/Active	05/01/1975	PGX40	AO SMITH	\$ 850.00	
2127	Installed/Active	03/06/2000	FSG50	AO SMITH	\$ 850.00	
2128	Installed/Active	10/28/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2129	Installed/Active	02/28/2000	FSG30	AO SMITH	\$ 850.00	
2130	Installed/Active	03/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2131	Installed/Active	03/01/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2132	Installed/Active	05/28/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
2133	Installed/Active	07/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2134	Installed/Active	04/17/2001	FSG40	AO SMITH	\$ 850.00	
2135	Installed/Active	01/28/2004	XTN050	LOCHINVAR	\$ 850.00	
2136	Installed/Active	11/04/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.51
2137	Installed/Active	06/24/2003	21V407	RHEEM	\$ 850.00	
2138	Installed/Active	02/26/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
2139	Installed/Active	03/27/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
2140	Installed/Active	07/12/2000	FSG40	AO SMITH	\$ 850.00	
2141	Installed/Active	02/02/2001	FSG40	AO SMITH	\$ 850.00	
2142	Installed/Active	05/09/1992	FSG40	AO SMITH	\$ 850.00	
2143	Installed/Active	05/24/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2144	Installed/Active	02/17/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
2145	Installed/Active	07/11/2001	FSG50	AO SMITH	\$ 850.00	
2146	Installed/Active	04/06/2011	21VR50	RHEEM	\$ 850.00	\$ 6.34
2147	Installed/Active	06/06/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2148	Installed/Active	03/27/1995	PHR50	RUUD	\$ 850.00	
2149	Installed/Active	02/07/2011	FCV40	AO SMITH	\$ 350.00	\$ 14.74
2150	Installed/Active	11/14/1995	41XR40	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2151	Installed/Active	06/10/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2152	Installed/Active	01/31/1989	FSG50	AO SMITH	\$ 850.00	
2153	Installed/Active	10/08/1999	41XR40	RHEEM	\$ 850.00	
2154	Installed/Active	02/22/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2155	Installed/Active	04/11/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2156	Installed/Active	06/24/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2157	Installed/Active	12/27/2000	FSGL40	AO SMITH	\$ 850.00	
2158	Installed/Active	12/08/1986	FSG50	AO SMITH	\$ 850.00	
2159	Installed/Active	05/04/2002	FSG50	AO SMITH	\$ 850.00	
2160	Installed/Active	09/04/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
2161	Installed/Active	10/01/1969	PGX40	AO SMITH	\$ 850.00	
2162	Installed/Active	09/09/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
2163	Installed/Active	06/17/2002	PGR50	AO SMITH	\$ 850.00	
2164	Installed/Active	01/26/1994	FGR40	AO SMITH	\$ 850.00	
2165	Installed/Active	09/09/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
2166	Installed/Active	08/06/2001	FSG40	AO SMITH	\$ 850.00	
2167	Installed/Active	12/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2168	Installed/Active	04/11/2011	42VR50	RHEEM	\$ 850.00	\$ 6.34
2169	Installed/Active	10/29/1999	41V40S	RHEEM	\$ 850.00	
2170	Installed/Active	01/31/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
2171	Installed/Active	01/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2172	Installed/Active	02/09/2004	XTN050	LOCHINVAR	\$ 850.00	
2173	Installed/Active	10/16/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
2174	Installed/Active	08/01/2006	LTN040G	LOCHINVAR	\$ 850.00	
2175	Installed/Active	03/20/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 6.37
2176	Installed/Active	03/01/2001	41VR50	RHEEM	\$ 850.00	
2177	Installed/Active	10/01/1967	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
2178	Installed/Active	05/26/2004	XTN050	LOCHINVAR	\$ 850.00	
2179	Installed/Active	12/16/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
2180	Installed/Active	03/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2181	Installed/Active	01/09/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2182	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2183	Installed/Active	09/05/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
2184	Installed/Active	07/01/2002	41V50	RHEEM	\$ 850.00	
2185	Installed/Active	05/26/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
2186	Installed/Active	12/17/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2187	Installed/Active	10/03/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
2188	Installed/Active	08/17/1992	FSG50	AO SMITH	\$ 850.00	
2189	Installed/Active	05/26/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
2190	Installed/Active	05/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2191	Installed/Active	05/29/2002	PGR40	AO SMITH	\$ 850.00	
2192	Installed/Active	10/11/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
2193	Installed/Active	09/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2194	Installed/Active	04/20/2011	21VR50	RHEEM	\$ 850.00	\$ 6.34
2195	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2196	Installed/Active	08/21/2006	LTN040	LOCHINVAR	\$ 850.00	
2197	Installed/Active	08/05/2004	GCVL40	A. O. SMITH	\$ 850.00	
2198	Installed/Active	04/18/1968	PGX50	AO SMITH	\$ 850.00	
2199	Installed/Active	03/01/1967	E71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
2200	Installed/Active	09/04/1992	FSG40	AO SMITH	\$ 850.00	
2201	Installed/Active	07/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2202	Installed/Active	04/23/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
2203	Installed/Active	09/01/1966	PGL40	AO SMITH	\$ 850.00	
2204	Installed/Active	05/21/2001	PGR50	AO SMITH	\$ 850.00	
2205	Installed/Active	04/01/1967	PGXL40	AO SMITH	\$ 850.00	
2206	Installed/Active	11/20/1995	FGR30	AO SMITH	\$ 850.00	
2207	Installed/Active	06/06/2012	M403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2208	Installed/Active	07/07/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
2209	Installed/Active	01/16/2003	FSG50	AO SMITH	\$ 850.00	
2210	Installed/Active	08/24/2004	XVR40	A. O. SMITH	\$ 850.00	
2211	Installed/Active	09/06/2005	LTN040G	LOCHINVAR	\$ 850.00	
2212	Installed/Active	04/08/2004	GVC40	A. O. SMITH	\$ 850.00	
2213	Installed/Active	01/28/1997	FSG40	AO SMITH	\$ 850.00	
2214	Installed/Active	10/26/2012	PH199119	PHOENIX	\$ 3,350.00	\$ 64.59
2215	Installed/Active	07/20/2000	41XR40	RHEEM	\$ 850.00	
2216	Installed/Active	10/24/2003	FSG40	AO SMITH	\$ 850.00	
2217	Installed/Active	05/18/2002	FSG50	AO SMITH	\$ 850.00	
2218	Installed/Active	10/02/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
2219	Installed/Active	01/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2220	Installed/Active	11/21/2002	FSG40	AO SMITH	\$ 850.00	
2221	Installed/Active	06/06/2002	PGR50	AO SMITH	\$ 850.00	
2222	Installed/Active	12/02/2002	FSGL40	AO SMITH	\$ 850.00	
2223	Installed/Active	09/19/2001	FSG30	AO SMITH	\$ 850.00	
2224	Installed/Active	03/14/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
2225	Installed/Active	09/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2226	Installed/Active	02/27/2004	FCV40	AO SMITH	\$ 850.00	
2227	Installed/Active	08/01/1970	PGX50	AO SMITH	\$ 850.00	
2228	Installed/Active	01/13/1999	FSGL40	AO SMITH	\$ 850.00	
2229	Installed/Active	04/06/2005	XVR50	A. O. SMITH	\$ 850.00	
2230	Installed/Active	10/27/2005	G82156	RUUD/RHEEM	\$ 3,350.00	
2231	Installed/Active	01/15/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2232	Installed/Active	05/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
2233	Installed/Active	07/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
2234	Installed/Active	04/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2235	Installed/Active	07/12/2004	XTN050	LOCHINVAR	\$ 850.00	
2236	Installed/Active	12/26/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2237	Installed/Active	01/14/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
2238	Installed/Active	11/04/2002	FSG40	AO SMITH	\$ 850.00	
2239	Installed/Active	06/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2240	Installed/Active	06/11/2001	PGR50	AO SMITH	\$ 850.00	
2241	Installed/Active	12/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2242	Installed/Active	04/04/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 5.12
2243	Installed/Active	09/12/2000	FSG50	AO SMITH	\$ 850.00	
2244	Installed/Active	03/07/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
2245	Installed/Active	12/12/1995	FGR40	AO SMITH	\$ 350.00	
2246	Installed/Active	12/23/2005	GVC50	A. O. SMITH	\$ 850.00	
2247	Installed/Active	05/13/2005	FSG30	AO SMITH	\$ 850.00	
2248	Installed/Active	09/24/2001	PGR40	AO SMITH	\$ 850.00	
2249	Installed/Active	09/26/2003	FSG40	AO SMITH	\$ 850.00	
2250	Installed/Active	04/05/2002	PGR50	AO SMITH	\$ 850.00	
2251	Installed/Active	01/04/2000	FSG40	AO SMITH	\$ 850.00	
2252	Installed/Active	05/23/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2253	Installed/Active	07/06/1995	PR502T	RUUD	\$ 850.00	
2254	Installed/Active	09/07/1999	FSGL40	AO SMITH	\$ 850.00	
2255	Installed/Active	01/04/2011	41VR40	RHEEM	\$ 850.00	\$ 6.04
2256	Installed/Active	08/01/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2257	Installed/Active	08/02/2010	PGR50	AO SMITH	\$ 850.00	\$ 7.51
2258	Installed/Active	12/03/1998	21VR40	RHEEM	\$ 850.00	
2259	Installed/Active	01/01/1970	PGX50	AO SMITH	\$ 850.00	
2260	Installed/Active	12/27/1997	PGR50	AO SMITH	\$ 850.00	
2261	Installed/Active	12/22/1999	FSG40	AO SMITH	\$ 850.00	
2262	Installed/Active	11/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2263	Installed/Active	03/22/2002	FSG50	AO SMITH	\$ 850.00	
2264	Installed/Active	12/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
2265	Installed/Active	04/26/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2266	Installed/Active	10/01/1996	FGR40	AO SMITH	\$ 850.00	
2267	Installed/Active	02/01/1997	PGR40	AO SMITH	\$ 850.00	
2268	Installed/Active	06/21/2001	FSG50	AO SMITH	\$ 850.00	
2269	Installed/Active	09/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2270	Installed/Active	12/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2271	Installed/Active	04/12/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
2272	Installed/Active	08/15/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2273	Installed/Active	12/10/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
2274	Installed/Active	02/27/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2275	Installed/Active	08/04/2004	XTN040	LOCHINVAR	\$ 850.00	
2276	Installed/Active	11/27/2000	41V40S	RHEEM	\$ 850.00	
2277	Installed/Active	04/06/2006	LSN041G	LOCHINVAR	\$ 850.00	
2278	Installed/Active	04/18/2001	PGR50	AO SMITH	\$ 850.00	
2279	Installed/Active	02/03/2002	PGR50	AO SMITH	\$ 850.00	
2280	Installed/Active	10/23/2002	FSG40	AO SMITH	\$ 850.00	
2281	Installed/Active	07/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
2282	Installed/Active	09/09/2011	PH19980	PHOENIX	\$ 3,350.00	\$ 64.06
2283	Installed/Active	03/11/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
2284	Installed/Active	08/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2285	Installed/Active	06/24/2003	FSG40	AO SMITH	\$ 850.00	
2286	Installed/Active	06/08/1999	FSGL40	AO SMITH	\$ 850.00	
2287	Installed/Active	09/01/1975	KGA40	AO SMITH	\$ 850.00	
2288	Installed/Active	11/06/2003	FCV40	AO SMITH	\$ 850.00	
2289	Installed/Active	04/15/2005	GVC40	A. O. SMITH	\$ 850.00	
2290	Installed/Active	01/01/1960	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
2291	Installed/Active	05/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2292	Installed/Active	01/02/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2293	Installed/Active	06/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2294	Installed/Active	04/22/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
2295	Installed/Active	01/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2296	Installed/Active	06/06/2003	PGR50	AO SMITH	\$ 850.00	
2297	Installed/Active	10/03/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2298	Installed/Active	03/30/2002	FSGL40	AO SMITH	\$ 850.00	
2299	Installed/Active	04/12/2011	21VR50	RHEEM	\$ 850.00	\$ 6.34
2300	Installed/Active	02/22/2002	FSG40	AO SMITH	\$ 850.00	
2301	Installed/Active	08/01/2012	P230F	Ruud	\$ 850.00	\$ 6.39
2302	Installed/Active	04/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2303	Installed/Active	05/26/2006	LTN040G	LOCHINVAR	\$ 850.00	
2304	Installed/Active	01/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2305	Installed/Active	03/06/2005	GVC40	A. O. SMITH	\$ 850.00	
2306	Installed/Active	07/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
2307	Installed/Active	06/23/1996	FGR50	AO SMITH	\$ 850.00	
2308	Installed/Active	10/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2309	Installed/Active	11/05/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2310	Installed/Active	02/28/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
2311	Installed/Active	08/17/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
2312	Installed/Active	04/21/2004	GVC40	A. O. SMITH	\$ 850.00	
2313	Installed/Active	07/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2314	Installed/Active	03/04/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
2315	Installed/Active	03/01/1979	FSG50	AO SMITH	\$ 850.00	
2316	Installed/Active	10/12/2004	XVR50	A. O. SMITH	\$ 850.00	
2317	Installed/Active	03/17/1999	FGR50	AO SMITH	\$ 850.00	
2318	Installed/Active	11/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2319	Installed/Active	11/22/2002	FGR50	AO SMITH	\$ 850.00	
2320	Installed/Active	09/24/2003	41XR50	RHEEM	\$ 850.00	
2321	Installed/Active	11/19/1982	G76200	RUUD/RHEEM	\$ 3,350.00	
2322	Installed/Active	04/12/2005	XVR50	A. O. SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2323	Installed/Active	09/28/2010	41VR50	RHEEM	\$ 850.00	\$ 6.04
2324	Installed/Active	09/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
2325	Installed/Active	08/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
2326	Installed/Active	06/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2327	Installed/Active	08/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2328	Installed/Active	06/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
2329	Installed/Active	07/12/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2330	Installed/Active	09/01/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
2331	Installed/Active	11/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
2332	Installed/Active	11/23/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2333	Installed/Active	02/07/2003	FSG30	AO SMITH	\$ 850.00	
2334	Installed/Active	03/25/2003	FSG40	AO SMITH	\$ 850.00	
2335	Installed/Active	05/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2336	Installed/Active	06/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
2337	Installed/Active	08/14/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
2338	Installed/Active	05/04/1999	FSG40	AO SMITH	\$ 850.00	
2339	Installed/Active	01/22/2001	FSG40	AO SMITH	\$ 850.00	
2340	Installed/Active	11/01/1970	PGX40	AO SMITH	\$ 850.00	
2341	Installed/Active	12/21/2001	FSG50	AO SMITH	\$ 850.00	
2342	Installed/Active	10/01/1975	KGA40	AO SMITH	\$ 850.00	
2343	Installed/Active	08/14/2001	FSGL40	AO SMITH	\$ 850.00	
2344	Installed/Active	05/03/1999	FGR50	AO SMITH	\$ 850.00	
2345	Installed/Active	01/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2346	Installed/Active	12/18/2001	FSG40	AO SMITH	\$ 850.00	
2347	Installed/Active	02/01/1976	KGA40	AO SMITH	\$ 850.00	
2348	Installed/Active	08/18/1997	PGR50	AO SMITH	\$ 850.00	
2349	Installed/Active	03/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
2350	Installed/Active	04/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2351	Installed/Active	02/09/2001	PGR50	AO SMITH	\$ 850.00	
2352	Installed/Active	12/26/2006	LSN041G	LOCHINVAR	\$ 850.00	
2353	Installed/Active	02/19/2013	FGR40	AO SMITH	\$ 850.00	\$ 6.39
2354	Installed/Active	07/20/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2355	Installed/Active	10/10/1997	PGR40	AO SMITH	\$ 850.00	
2356	Installed/Active	12/01/1975	KGA50	AO SMITH	\$ 850.00	
2357	Installed/Active	07/16/2001	FSG40	AO SMITH	\$ 850.00	
2358	Installed/Active	07/21/2001	FSG50	AO SMITH	\$ 850.00	
2359	Installed/Active	12/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
2360	Installed/Active	11/25/1997	41V40	RHEEM	\$ 850.00	
2361	Installed/Active	05/05/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
2362	Installed/Active	10/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2363	Installed/Active	03/29/2005	XVR50	A. O. SMITH	\$ 850.00	
2364	Installed/Active	08/16/2010	41V50	RHEEM	\$ 850.00	\$ 7.51
2365	Installed/Active	07/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2366	Installed/Active	04/07/2005	GCVL40	A. O. SMITH	\$ 850.00	
2367	Installed/Active	07/02/1997	FGR30	AO SMITH	\$ 850.00	
2368	Installed/Active	03/01/1995	L72DUMMY	AO SMITH	\$ 3,350.00	
2369	Installed/Active	07/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2370	Installed/Active	01/30/1994	F72DUMMY	AO SMITH	\$ 3,350.00	
2371	Installed/Active	11/07/1999	PHR40	RUUD	\$ 850.00	
2372	Installed/Active	11/01/1995	L72DUMMY	AO SMITH	\$ 3,350.00	
2373	Installed/Active	04/03/2000	BTR154	AO SMITH	\$ 3,350.00	
2374	Installed/Active	10/19/2000	FSG40	AO SMITH	\$ 850.00	
2375	Installed/Active	01/17/2000	FSG50	AO SMITH	\$ 850.00	
2376	Installed/Active	12/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2377	Installed/Active	08/12/2003	FSG40	AO SMITH	\$ 850.00	
2378	Installed/Active	07/25/1991	FSG40	AO SMITH	\$ 850.00	
2379	Installed/Active	07/29/2001	FSGL40	AO SMITH	\$ 850.00	
2380	Installed/Active	09/24/1987	G91200	RUUD/RHEEM	\$ 3,350.00	
2381	Installed/Active	05/18/2000	41XR50	RHEEM	\$ 850.00	
2382	Installed/Active	10/29/2004	XVR40	A. O. SMITH	\$ 850.00	
2383	Installed/Active	01/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2384	Installed/Active	06/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
2385	Installed/Active	05/23/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
2386	Installed/Active	03/28/2013	MI403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
2387	Installed/Active	08/16/2005	LTN050G	LOCHINVAR	\$ 850.00	
2388	Installed/Active	09/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
2389	Installed/Active	04/29/1998	PGR40	AO SMITH	\$ 850.00	
2390	Installed/Active	05/25/2003	PGR50	AO SMITH	\$ 850.00	
2391	Installed/Active	08/10/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2392	Installed/Active	09/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2393	Installed/Active	10/28/2002	FSGL40	AO SMITH	\$ 850.00	
2394	Installed/Active	10/14/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
2395	Installed/Active	05/02/2008	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 16.35
2396	Installed/Active	09/24/2003	PGR50	AO SMITH	\$ 850.00	
2397	Installed/Active	11/01/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
2398	Installed/Active	02/02/1993	RF67120	RUUD	\$ 1,900.00	
2399	Installed/Active	04/01/1971	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
2400	Installed/Active	02/11/1986	E71DUMMY	AO SMITH	\$ 3,350.00	
2401	Installed/Active	12/01/1979	FSGL40	AO SMITH	\$ 850.00	
2402	Installed/Active	10/12/1999	FSGL40	AO SMITH	\$ 850.00	
2403	Installed/Active	10/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2404	Installed/Active	05/21/2012	41VR50	RHEEM	\$ 850.00	\$ 6.39
2405	Installed/Active	01/01/1976	KGL40	AO SMITH	\$ 850.00	
2406	Installed/Active	08/03/1995	BTC197	AO SMITH	\$ 3,350.00	
2407	Installed/Active	03/08/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2408	Installed/Active	03/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2409	Installed/Active	06/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2410	Installed/Active	08/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
2411	Installed/Active	10/14/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2412	Installed/Active	08/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2413	Installed/Active	12/11/2000	41XR40	RHEEM	\$ 850.00	
2414	Installed/Active	11/16/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2415	Installed/Active	01/01/1980	FSG40	AO SMITH	\$ 850.00	
2416	Installed/Active	02/01/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2417	Installed/Active	10/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2418	Installed/Active	02/14/2002	FSG40	AO SMITH	\$ 850.00	
2419	Installed/Active	07/07/1995	PHR50	RUUD	\$ 850.00	
2420	Installed/Active	11/19/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2421	Installed/Active	12/15/2002	FSG40	AO SMITH	\$ 850.00	
2422	Installed/Active	08/11/2005	41VR50	RHEEM	\$ 1,075.00	
2423	Installed/Active	09/07/2001	PGR50	AO SMITH	\$ 850.00	
2424	Installed/Active	11/22/2002	PGR40	AO SMITH	\$ 850.00	
2425	Installed/Active	05/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2426	Installed/Active	08/18/1992	FSG50	AO SMITH	\$ 850.00	
2427	Installed/Active	04/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2428	Installed/Active	11/01/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
2429	Installed/Active	03/19/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2430	Installed/Active	04/16/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
2431	Installed/Active	07/30/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2432	Installed/Active	05/16/2011	41VR40	RHEEM	\$ 850.00	\$ 7.88
2433	Installed/Active	09/24/2003	PGR50	AO SMITH	\$ 850.00	
2434	Installed/Active	10/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2435	Installed/Active	07/11/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2436	Installed/Active	02/28/2011	21VR50	RHEEM	\$ 850.00	\$ 7.51
2437	Installed/Active	10/01/1974	RH3063	RUUD	\$ 350.00	
2438	Installed/Active	03/09/2011	42VR50	RHEEM	\$ 850.00	\$ 7.51
2439	Installed/Active	01/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
2440	Installed/Active	02/11/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2441	Installed/Active	10/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2442	Installed/Active	10/01/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2443	Installed/Active	10/27/1993	FSG40	AO SMITH	\$ 850.00	
2444	Installed/Active	10/23/2004	GVC40	A. O. SMITH	\$ 850.00	
2445	Installed/Active	03/12/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
2446	Installed/Active	09/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
2447	Installed/Active	07/22/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2448	Installed/Active	01/24/1997	PGR40	AO SMITH	\$ 850.00	
2449	Installed/Active	04/06/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 7.31
2450	Installed/Active	08/30/2003	PGR50	AO SMITH	\$ 850.00	
2451	Installed/Active	05/16/2006	LTN040G	LOCHINVAR	\$ 850.00	
2452	Installed/Active	08/19/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2453	Installed/Active	08/10/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2454	Installed/Active	11/12/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
2455	Installed/Active	09/16/2003	FSG40	AO SMITH	\$ 850.00	
2456	Installed/Active	05/08/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
2457	Installed/Active	12/23/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2458	Installed/Active	10/12/2005	FSG30	AO SMITH	\$ 850.00	
2459	Installed/Active	03/09/2001	PGR50	AO SMITH	\$ 850.00	
2460	Installed/Active	06/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
2461	Installed/Active	09/19/2000	41XR40	RHEEM	\$ 850.00	
2462	Installed/Active	06/23/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
2463	Installed/Active	06/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2464	Installed/Active	05/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2465	Installed/Active	03/01/1980	FSG50	AO SMITH	\$ 850.00	
2466	Installed/Active	03/28/2001	PGR50	AO SMITH	\$ 850.00	
2467	Installed/Active	05/16/1999	FGR40	AO SMITH	\$ 850.00	
2468	Installed/Active	09/30/1995	RF67120	RUUD	\$ 1,900.00	
2469	Installed/Active	12/22/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2470	Installed/Active	10/29/2003	PVR40	AO SMITH	\$ 850.00	
2471	Installed/Active	10/17/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
2472	Installed/Active	11/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2473	Installed/Active	05/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2474	Installed/Active	07/19/2001	FSG40	AO SMITH	\$ 850.00	
2475	Installed/Active	07/17/2004	XTN050	LOCHINVAR	\$ 850.00	
2476	Installed/Active	05/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2477	Installed/Active	06/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2478	Installed/Active	11/08/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2479	Installed/Active	11/11/2002	FSG50	AO SMITH	\$ 850.00	
2480	Installed/Active	12/24/1998	G67114	RHEEM	\$ 1,900.00	
2481	Installed/Active	08/13/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2482	Installed/Active	01/30/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2483	Installed/Active	06/25/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2484	Installed/Active	12/29/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2485	Installed/Active	12/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2486	Installed/Active	03/02/2006	LTN040G	LOCHINVAR	\$ 850.00	
2487	Installed/Active	05/18/2011	41VR40	RHEEM	\$ 850.00	\$ 12.64
2488	Installed/Active	12/24/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
2489	Installed/Active	05/10/2003	41XR40	RHEEM	\$ 850.00	
2490	Installed/Active	07/18/2000	41V40	RHEEM	\$ 850.00	
2491	Installed/Active	12/08/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
2492	Installed/Active	05/16/2002	FSGL40	AO SMITH	\$ 850.00	
2493	Installed/Active	08/21/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2494	Installed/Active	03/03/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2495	Installed/Active	12/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
2496	Installed/Active	10/08/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
2497	Installed/Active	10/26/1999	FSG30	AO SMITH	\$ 850.00	
2498	Installed/Active	11/09/2001	FSG40	AO SMITH	\$ 850.00	
2499	Installed/Active	03/08/2002	FSGL40	AO SMITH	\$ 850.00	
2500	Installed/Active	10/04/1999	FSGL30	AO SMITH	\$ 850.00	
2501	Installed/Active	10/20/2009	FSG50	AO SMITH	\$ 850.00	\$ 11.74
2502	Installed/Active	12/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2503	Installed/Active	07/25/2001	PGR50	AO SMITH	\$ 850.00	
2504	Installed/Active	01/31/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2505	Installed/Active	01/02/2002	PGR40	AO SMITH	\$ 850.00	
2506	Installed/Active	11/30/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2507	Installed/Active	04/10/2001	PGR50	AO SMITH	\$ 850.00	
2508	Installed/Active	04/09/2002	PGR50	AO SMITH	\$ 850.00	
2509	Installed/Active	11/23/1988	FSG40	AO SMITH	\$ 850.00	
2510	Installed/Active	11/09/2001	21V407	RHEEM	\$ 350.00	
2511	Installed/Active	07/06/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
2512	Installed/Active	11/05/2005	FSG30	AO SMITH	\$ 850.00	
2513	Installed/Active	01/17/1987	FSG50	AO SMITH	\$ 850.00	
2514	Installed/Active	08/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2515	Installed/Active	07/19/2001	FSG40	AO SMITH	\$ 850.00	
2516	Installed/Active	11/28/2000	FSG40	AO SMITH	\$ 850.00	
2517	Installed/Active	07/24/2005	LSN041G	LOCHINVAR	\$ 850.00	
2518	Installed/Active	05/17/2011	21VR40	RHEEM	\$ 850.00	\$ 7.88
2519	Installed/Active	09/08/1992	FSG50	AO SMITH	\$ 850.00	
2520	Installed/Active	05/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2521	Installed/Active	01/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2522	Installed/Active	03/03/2003	FSG40	AO SMITH	\$ 850.00	
2523	Installed/Active	01/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2524	Installed/Active	10/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2525	Installed/Active	05/19/1997	PGR50	AO SMITH	\$ 850.00	
2526	Installed/Active	11/27/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2527	Installed/Active	03/10/1999	SSV119199	VOYAGER	\$ 3,350.00	
2528	Installed/Active	03/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2529	Installed/Active	06/01/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2530	Installed/Active	03/11/1999	FSG50	AO SMITH	\$ 850.00	
2531	Installed/Active	05/02/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
2532	Installed/Active	01/31/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2533	Installed/Active	08/22/1999	41VR50	RHEEM	\$ 850.00	
2534	Installed/Active	02/15/2002	FSG40	AO SMITH	\$ 850.00	
2535	Installed/Active	01/01/1973	PGX40	AO SMITH	\$ 850.00	
2536	Installed/Active	12/30/2005	LSN041G	LOCHINVAR	\$ 850.00	
2537	Installed/Active	11/01/1970	PGX50	AO SMITH	\$ 850.00	
2538	Installed/Active	02/22/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2539	Installed/Active	03/19/1973	PGD30	AO SMITH	\$ 350.00	
2540	Installed/Active	12/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2541	Installed/Active	07/25/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2542	Installed/Active	05/25/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 6.37
2543	Installed/Active	08/27/2003	PGR50	AO SMITH	\$ 850.00	
2544	Installed/Active	04/01/1999	G67114	RHEEM	\$ 1,900.00	
2545	Installed/Active	03/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
2546	Installed/Active	06/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.37
2547	Installed/Active	08/24/1991	FSG50	AO SMITH	\$ 850.00	
2548	Installed/Active	02/10/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2549	Installed/Active	03/25/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 6.39
2550	Installed/Active	11/01/1988	FSG50	AO SMITH	\$ 850.00	
2551	Installed/Active	12/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
2552	Installed/Active	08/08/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
2553	Installed/Active	11/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2554	Installed/Active	02/26/2002	PGR50	AO SMITH	\$ 850.00	
2555	Installed/Active	12/14/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2556	Installed/Active	04/17/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.04
2557	Installed/Active	12/02/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2558	Installed/Active	07/31/2000	FGR40	AO SMITH	\$ 850.00	
2559	Installed/Active	06/24/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2560	Installed/Active	11/10/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2561	Installed/Active	09/18/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2562	Installed/Active	03/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
2563	Installed/Active	04/02/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
2564	Installed/Active	06/02/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
2565	Installed/Active	12/08/1993	PGR40	AO SMITH	\$ 850.00	
2566	Installed/Active	10/24/2004	XVR40	A. O. SMITH	\$ 850.00	
2567	Installed/Active	05/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
2568	Installed/Active	11/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
2569	Installed/Active	11/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
2570	Installed/Active	08/22/2002	PGR50	AO SMITH	\$ 850.00	
2571	Installed/Active	04/17/1996	G91200	RUUD/RHEEM	\$ 3,350.00	
2572	Installed/Active	04/03/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
2573	Installed/Active	10/10/1997	G75125	RUUD/RHEEM	\$ 1,900.00	
2574	Installed/Active	02/02/2003	FSGL40	AO SMITH	\$ 850.00	
2575	Installed/Active	12/08/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2576	Installed/Active	07/21/1999	FSG30	AO SMITH	\$ 850.00	
2577	Installed/Active	06/04/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
2578	Installed/Active	12/26/2007	FSG30	AO SMITH	\$ 850.00	\$ 6.37
2579	Installed/Active	10/26/2010	41XR50	RHEEM	\$ 850.00	\$ 6.04
2580	Installed/Active	10/25/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2581	Installed/Active	12/17/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
2582	Installed/Active	02/08/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2583	Installed/Active	01/05/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
2584	Installed/Active	11/19/2002	FSG40	AO SMITH	\$ 850.00	
2585	Installed/Active	12/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2586	Installed/Active	01/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2587	Installed/Active	12/08/1987	BTR199	AO SMITH	\$ 3,350.00	
2588	Installed/Active	02/19/2002	FSG50	AO SMITH	\$ 850.00	
2589	Installed/Active	02/02/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
2590	Installed/Active	05/27/2003	21V506	RHEEM	\$ 1,125.00	
2591	Installed/Active	06/17/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
2592	Installed/Active	05/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2593	Installed/Active	10/17/2002	FSG30	AO SMITH	\$ 850.00	
2594	Installed/Active	02/27/2004	PGR40	AO SMITH	\$ 850.00	
2595	Installed/Active	11/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2596	Installed/Active	02/01/1979	G72DUMMY	AO SMITH	\$ 1,125.00	
2597	Installed/Active	03/17/2003	FSG40	AO SMITH	\$ 850.00	
2598	Installed/Active	02/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2599	Installed/Active	12/29/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
2600	Installed/Active	07/01/1997	FGR30	AO SMITH	\$ 850.00	
2601	Installed/Active	04/08/2005	GVC50	A. O. SMITH	\$ 850.00	
2602	Installed/Active	05/02/2001	FSG30	AO SMITH	\$ 850.00	
2603	Installed/Active	03/15/1994	21V506	RHEEM	\$ 1,125.00	
2604	Installed/Active	10/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2605	Installed/Active	01/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
2606	Installed/Active	04/27/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
2607	Installed/Active	02/01/1999	FSG30	AO SMITH	\$ 850.00	
2608	Installed/Active	03/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
2609	Installed/Active	03/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2610	Installed/Active	02/21/2002	FSL40	AO SMITH	\$ 850.00	
2611	Installed/Active	07/03/2003	PGR40	AO SMITH	\$ 850.00	
2612	Installed/Active	04/13/2006	PGR50	AO SMITH	\$ 850.00	
2613	Installed/Active	07/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2614	Installed/Active	03/22/2004	GCVL40	A. O. SMITH	\$ 850.00	
2615	Installed/Active	11/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
2616	Installed/Active	12/19/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2617	Installed/Active	05/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2618	Installed/Active	09/01/1976	KGA50	AO SMITH	\$ 850.00	
2619	Installed/Active	02/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
2620	Installed/Active	08/24/1997	FGR50	AO SMITH	\$ 850.00	
2621	Installed/Active	05/02/2006	LTN040G	LOCHINVAR	\$ 850.00	
2622	Installed/Active	11/13/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2623	Installed/Active	10/10/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2624	Installed/Active	10/17/2002	PGR50	AO SMITH	\$ 850.00	
2625	Installed/Active	07/24/2003	FSG50	AO SMITH	\$ 850.00	
2626	Installed/Active	03/06/2007	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
2627	Installed/Active	03/13/2002	PGR50	AO SMITH	\$ 850.00	
2628	Installed/Active	05/29/2004	GVC50	A. O. SMITH	\$ 850.00	
2629	Installed/Active	12/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2630	Installed/Active	10/16/2010	SBF100199NES	STATE	\$ 3,350.00	\$ 61.05
2631	Installed/Active	07/01/1985	RF67120	RUUD	\$ 1,900.00	
2632	Installed/Active	08/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2633	Installed/Active	12/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
2634	Installed/Active	05/28/2002	FSG50	AO SMITH	\$ 850.00	
2635	Installed/Active	06/06/1999	FSG50	AO SMITH	\$ 850.00	
2636	Installed/Active	04/05/2011	22DV50F	RHEEM	\$ 850.00	\$ 12.64
2637	Installed/Active	06/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2638	Installed/Active	11/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2639	Installed/Active	06/17/1996	FGR50	AO SMITH	\$ 850.00	
2640	Installed/Active	07/26/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2641	Installed/Active	06/17/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
2642	Installed/Active	02/12/2013	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
2643	Installed/Active	12/21/2005	GVC50	A. O. SMITH	\$ 850.00	
2644	Installed/Active	07/28/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
2645	Installed/Active	09/22/2006	PR640	STATE	\$ 1,075.00	
2646	Installed/Active	06/25/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
2647	Installed/Active	03/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
2648	Installed/Active	01/15/2003	PRX50	STATE	\$ 1,075.00	
2649	Installed/Active	03/09/2000	FSG50	AO SMITH	\$ 850.00	
2650	Installed/Active	04/01/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2651	Installed/Active	07/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2652	Installed/Active	05/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
2653	Installed/Active	11/18/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2654	Installed/Active	09/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2655	Installed/Active	11/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2656	Installed/Active	01/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2657	Installed/Active	03/21/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
2658	Installed/Active	02/19/1998	FGR50	AO SMITH	\$ 850.00	
2659	Installed/Active	05/18/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
2660	Installed/Active	09/12/2002	FSG50	AO SMITH	\$ 850.00	
2661	Installed/Active	01/07/2002	FSG30	AO SMITH	\$ 850.00	
2662	Installed/Active	09/29/1971	G91200	RUUD/RHEEM	\$ 3,350.00	
2663	Installed/Active	07/28/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2664	Installed/Active	12/19/2001	FSL40	AO SMITH	\$ 850.00	
2665	Installed/Active	12/02/2002	FSG50	AO SMITH	\$ 850.00	
2666	Installed/Active	11/15/2006	LTN040G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2667	Installed/Active	03/04/2005	GVC40	A. O. SMITH	\$ 850.00	
2668	Installed/Active	12/19/2001	FSGL30	AO SMITH	\$ 850.00	
2669	Installed/Active	04/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2670	Installed/Active	06/19/2000	FSGL40	AO SMITH	\$ 850.00	
2671	Installed/Active	06/04/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
2672	Installed/Active	09/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2673	Installed/Active	08/06/2003	FCV50	AO SMITH	\$ 850.00	
2674	Installed/Active	08/11/2005	LTN050	LOCHINVAR	\$ 850.00	
2675	Installed/Active	04/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2676	Installed/Active	11/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
2677	Installed/Active	08/20/1997	FSGL40	AO SMITH	\$ 850.00	
2678	Installed/Active	09/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2679	Installed/Active	04/30/2003	PGR50	AO SMITH	\$ 850.00	
2680	Installed/Active	08/01/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2681	Installed/Active	08/24/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
2682	Installed/Active	08/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2683	Installed/Active	06/01/1980	KGA40	AO SMITH	\$ 850.00	
2684	Installed/Active	02/06/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
2685	Installed/Active	12/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2686	Installed/Active	05/17/1996	PGR50	AO SMITH	\$ 850.00	
2687	Installed/Active	10/02/1997	FSGL40	AO SMITH	\$ 850.00	
2688	Installed/Active	04/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2689	Installed/Active	02/04/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
2690	Installed/Active	07/16/2002	PGR50	AO SMITH	\$ 850.00	
2691	Installed/Active	12/20/2004	GCVL40	A. O. SMITH	\$ 850.00	
2692	Installed/Active	11/16/2005	LSN041G	LOCHINVAR	\$ 850.00	
2693	Installed/Active	07/23/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
2694	Installed/Active	11/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2695	Installed/Active	01/13/2000	FSG40	AO SMITH	\$ 850.00	
2696	Installed/Active	10/19/1983	FSG50	AO SMITH	\$ 850.00	
2697	Installed/Active	12/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2698	Installed/Active	10/05/1984	F72DUMMY	AO SMITH	\$ 3,350.00	
2699	Installed/Active	06/09/1998	FGR50	AO SMITH	\$ 850.00	
2700	Installed/Active	04/06/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
2701	Installed/Active	07/29/1996	PGR40	AO SMITH	\$ 850.00	
2702	Installed/Active	12/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
2703	Installed/Active	02/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2704	Installed/Active	11/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2705	Installed/Active	04/10/1998	41V50	RHEEM	\$ 850.00	
2706	Installed/Active	07/09/2009	L72DUMMY	AO SMITH	\$ 3,350.00	\$ 51.18
2707	Installed/Active	03/30/1998	FGR50	AO SMITH	\$ 850.00	
2708	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
2709	Installed/Active	05/29/1997	G76200	RUUD/RHEEM	\$ 3,350.00	
2710	Installed/Active	11/13/2000	FSG40	AO SMITH	\$ 850.00	
2711	Installed/Active	10/31/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2712	Installed/Active	10/07/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
2713	Installed/Active	01/16/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2714	Installed/Active	08/30/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2715	Installed/Active	09/28/2010	21VR-50	RHEEM	\$ 850.00	\$ 12.05
2716	Installed/Active	12/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2717	Installed/Active	11/01/2008	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
2718	Installed/Active	02/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2719	Installed/Active	07/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2720	Installed/Active	12/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2721	Installed/Active	10/05/1983	KGA30	AO SMITH	\$ 850.00	
2722	Installed/Active	02/02/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
2723	Installed/Active	07/19/2000	FSG50	AO SMITH	\$ 850.00	
2724	Installed/Active	08/10/1997	PRX40	STATE	\$ 1,075.00	
2725	Installed/Active	11/04/1982	KGA30	AO SMITH	\$ 850.00	
2726	Installed/Active	03/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2727	Installed/Active	05/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2728	Installed/Active	11/04/1982	KGA30	AO SMITH	\$ 850.00	
2729	Installed/Active	05/19/2011	PGR50	AO SMITH	\$ 850.00	\$ 12.64
2730	Installed/Active	10/10/2001	FSG40	AO SMITH	\$ 850.00	
2731	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
2732	Installed/Active	05/02/2006	FSG30	AO SMITH	\$ 850.00	
2733	Installed/Active	02/28/2013	I72DUMMY	UNKNOWN AT CONVERSION	\$ 1,750.00	\$ 31.92
2734	Installed/Active	07/03/1995	PHR50	RUUD	\$ 850.00	
2735	Installed/Active	09/16/2004	GCVL40	A. O. SMITH	\$ 850.00	
2736	Installed/Active	06/17/2005	LSN041G	LOCHINVAR	\$ 850.00	
2737	Installed/Active	02/22/1999	P506	RUUD	\$ 1,125.00	
2738	Installed/Active	08/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2739	Installed/Active	07/03/2003	PVR50	AO SMITH	\$ 850.00	
2740	Installed/Active	12/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
2741	Installed/Active	11/04/1982	BW50	BRADFORD-WHITE	\$ 850.00	
2742	Installed/Active	03/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2743	Installed/Active	05/09/2003	41V40S	RHEEM	\$ 850.00	
2744	Installed/Active	02/09/2006	LTN040G	LOCHINVAR	\$ 850.00	
2745	Installed/Active	02/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
2746	Installed/Active	09/24/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2747	Installed/Active	01/01/1997	FSGL40	AO SMITH	\$ 850.00	
2748	Installed/Active	11/29/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2749	Installed/Active	08/28/2002	FSGL40	AO SMITH	\$ 850.00	
2750	Installed/Active	04/26/2001	FSGL40	AO SMITH	\$ 850.00	
2751	Installed/Active	06/05/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2752	Installed/Active	03/13/1984	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2753	Installed/Active	03/12/2004	FCVL40	AO SMITH	\$ 850.00	
2754	Installed/Active	01/01/2002	FSG30	AO SMITH	\$ 850.00	
2755	Installed/Active	11/30/2004	GVC50	A. O. SMITH	\$ 850.00	
2756	Installed/Active	07/16/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2757	Installed/Active	10/09/2000	FSG40	AO SMITH	\$ 850.00	
2758	Installed/Active	08/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2759	Installed/Active	10/06/2010	LTN040	LOCHINVAR	\$ 850.00	\$ 12.05
2760	Installed/Active	04/12/2002	PGR50	AO SMITH	\$ 850.00	
2761	Installed/Active	07/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2762	Installed/Active	09/26/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
2763	Installed/Active	08/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2764	Installed/Active	12/03/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2765	Installed/Active	03/05/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2766	Installed/Active	01/20/2006	PR640	STATE	\$ 1,075.00	
2767	Installed/Active	01/01/1996	FSG30	AO SMITH	\$ 850.00	
2768	Installed/Active	03/05/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2769	Installed/Active	01/01/1996	FSG30	AO SMITH	\$ 850.00	
2770	Installed/Active	12/03/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2771	Installed/Active	01/26/2006	PGXL30	AO SMITH	\$ 850.00	
2772	Installed/Active	07/07/2005	GVC40	A. O. SMITH	\$ 850.00	
2773	Installed/Active	01/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2774	Installed/Active	03/10/2011	SBD100199NES	STATE	\$ 3,350.00	\$ 61.05
2775	Installed/Active	03/29/2008	FSG30	AO SMITH	\$ 850.00	\$ 5.12
2776	Installed/Active	08/21/2003	FCV50	AO SMITH	\$ 850.00	
2777	Installed/Active	07/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2778	Installed/Active	06/09/2005	LTN050	LOCHINVAR	\$ 850.00	
2779	Installed/Active	10/24/2008	FSG30	AO SMITH	\$ 850.00	\$ 5.12
2780	Installed/Active	03/10/2011	SBD100199NES	STATE	\$ 3,350.00	\$ 61.05
2781	Installed/Active	09/30/1999	FSG50	AO SMITH	\$ 850.00	
2782	Installed/Active	11/01/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
2783	Installed/Active	06/18/2003	FSG50	AO SMITH	\$ 850.00	
2784	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
2785	Installed/Active	07/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2786	Installed/Active	11/02/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
2787	Installed/Active	04/09/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
2788	Installed/Active	09/12/2001	FSG50	AO SMITH	\$ 850.00	
2789	Installed/Active	02/18/2000	41XR50	RHEEM	\$ 850.00	
2790	Installed/Active	06/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2791	Installed/Active	09/21/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
2792	Installed/Active	06/18/2007	LTN030G	AO SMITH	\$ 850.00	\$ 5.12
2793	Installed/Active	09/19/2003	PVR40	AO SMITH	\$ 850.00	
2794	Installed/Active	03/19/2004	GVC50	A. O. SMITH	\$ 850.00	
2795	Installed/Active	04/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2796	Installed/Active	11/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2797	Installed/Active	05/07/2003	41V50	RHEEM	\$ 850.00	
2798	Installed/Active	01/07/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
2799	Installed/Active	11/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2800	Installed/Active	12/06/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
2801	Installed/Active	11/03/2000	21V407	RHEEM	\$ 850.00	
2802	Installed/Active	01/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2803	Installed/Active	02/19/2004	PVR40	AO SMITH	\$ 850.00	
2804	Installed/Active	06/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2805	Installed/Active	03/18/2013	FGR50	AO SMITH	\$ 850.00	\$ 12.75
2806	Installed/Active	01/01/1998	PRV50NORT	STATE	\$ 850.00	
2807	Installed/Active	11/03/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
2808	Installed/Active	05/21/2001	PGR50	AO SMITH	\$ 850.00	
2809	Installed/Active	06/25/1984	FSG50	AO SMITH	\$ 850.00	
2810	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2811	Installed/Active	01/01/1993	FSG30	AO SMITH	\$ 850.00	
2812	Installed/Active	03/11/2003	FSG40	AO SMITH	\$ 850.00	
2813	Installed/Active	05/16/1997	PGR50	AO SMITH	\$ 850.00	
2814	Installed/Active	08/06/2003	FCV50	AO SMITH	\$ 850.00	
2815	Installed/Active	10/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2816	Installed/Active	05/15/1996	H72DUMMY	AO SMITH	\$ 1,900.00	
2817	Installed/Active	12/21/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
2818	Installed/Active	03/07/1984	FSG50	AO SMITH	\$ 850.00	
2819	Installed/Active	01/01/1997	PRV50NORT	STATE	\$ 850.00	
2820	Installed/Active	06/28/2004	XTN040	LOCHINVAR	\$ 850.00	
2821	Installed/Active	01/01/1982	FSG40	AO SMITH	\$ 850.00	
2822	Installed/Active	09/19/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2823	Installed/Active	01/01/2003	FSG30	AO SMITH	\$ 850.00	
2824	Installed/Active	05/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
2825	Installed/Active	08/11/2003	FSGL40	AO SMITH	\$ 850.00	
2826	Installed/Active	06/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
2827	Installed/Active	11/12/1998	FGR40	AO SMITH	\$ 850.00	
2828	Installed/Active	09/13/2000	41V40S	RHEEM	\$ 850.00	
2829	Installed/Active	11/07/1983	FSGL40	AO SMITH	\$ 850.00	
2830	Installed/Active	01/01/2003	FSG30	AO SMITH	\$ 850.00	
2831	Installed/Active	12/17/2001	PGR50	AO SMITH	\$ 850.00	
2832	Installed/Active	01/24/2002	FSG50	AO SMITH	\$ 850.00	
2833	Installed/Active	09/22/2012	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2834	Installed/Active	05/05/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
2835	Installed/Active	05/13/2003	PGR50	AO SMITH	\$ 850.00	
2836	Installed/Active	08/17/2004	GCVL40	A. O. SMITH	\$ 850.00	
2837	Installed/Active	04/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
2838	Installed/Active	04/17/2001	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2839	Installed/Active	03/06/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
2840	Installed/Active	09/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2841	Installed/Active	06/08/2007	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 16.35
2842	Installed/Active	12/16/2008	KGA30	AO SMITH	\$ 850.00	\$ 5.88
2843	Installed/Active	09/08/2004	XTN050	LOCHINVAR	\$ 850.00	
2844	Installed/Active	04/09/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
2845	Installed/Active	07/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2846	Installed/Active	11/22/1999	FSGL40	AO SMITH	\$ 850.00	
2847	Installed/Active	11/20/2002	FSG50	AO SMITH	\$ 850.00	
2848	Installed/Active	01/20/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2849	Installed/Active	04/11/2001	PGR50	AO SMITH	\$ 850.00	
2850	Installed/Active	10/12/2004	XVR50	A. O. SMITH	\$ 850.00	
2851	Installed/Active	12/04/1979	FSG50	AO SMITH	\$ 850.00	
2852	Installed/Active	12/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
2853	Installed/Active	11/01/1979	FSG50	AO SMITH	\$ 850.00	
2854	Installed/Active	11/26/2003	PVR50	AO SMITH	\$ 850.00	
2855	Installed/Active	05/23/1983	21V502	RHEEM	\$ 850.00	
2856	Installed/Active	12/03/2002	FSG50	AO SMITH	\$ 850.00	
2857	Installed/Active	12/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2858	Installed/Active	08/04/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
2859	Installed/Active	04/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2860	Installed/Active	03/01/2001	21V407	RHEEM	\$ 850.00	
2861	Installed/Active	09/26/2012	M1506FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2862	Installed/Active	08/04/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
2863	Installed/Active	10/10/2000	41XR50	RHEEM	\$ 850.00	
2864	Installed/Active	10/17/1983	FSG50	AO SMITH	\$ 850.00	
2865	Installed/Active	12/19/2006	FSGL40	AO SMITH	\$ 850.00	
2866	Installed/Active	05/12/2004	FSG50	AO SMITH	\$ 850.00	
2867	Installed/Active	10/10/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
2868	Installed/Active	07/03/2003	FSG40	AO SMITH	\$ 850.00	
2869	Installed/Active	10/25/2003	FCVL40	AO SMITH	\$ 850.00	
2870	Installed/Active	07/08/2003	PGR40	AO SMITH	\$ 850.00	
2871	Installed/Active	09/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2872	Installed/Active	06/24/1998	FGR50	AO SMITH	\$ 850.00	
2873	Installed/Active	02/18/1997	FSGL40	AO SMITH	\$ 850.00	
2874	Installed/Active	10/10/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2875	Installed/Active	01/17/1999	41V50	RHEEM	\$ 850.00	
2876	Installed/Active	06/16/1998	FSG40	AO SMITH	\$ 850.00	
2877	Installed/Active	12/12/2005	LSN041G	LOCHINVAR	\$ 850.00	
2878	Installed/Active	07/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
2879	Installed/Active	07/11/1999	PHR50	RUUD	\$ 850.00	
2880	Installed/Active	10/31/2010	21VR40	RHEEM	\$ 850.00	\$ 7.51
2881	Installed/Active	12/01/1982	FSG40	AO SMITH	\$ 850.00	
2882	Installed/Active	04/02/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2883	Installed/Active	06/29/2004	GVC40	A. O. SMITH	\$ 850.00	
2884	Installed/Active	03/29/2003	FSG50	AO SMITH	\$ 850.00	
2885	Installed/Active	11/07/2002	PGR50	AO SMITH	\$ 850.00	
2886	Installed/Active	05/04/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2887	Installed/Active	11/17/2005	LTN040G	LOCHINVAR	\$ 850.00	
2888	Installed/Active	11/09/2003	PGR50	AO SMITH	\$ 850.00	
2889	Installed/Active	10/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2890	Installed/Active	04/28/1998	FSG40	AO SMITH	\$ 850.00	
2891	Installed/Active	12/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2892	Installed/Active	10/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2893	Installed/Active	04/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2894	Installed/Active	11/22/2000	41XR50	RHEEM	\$ 850.00	
2895	Installed/Active	11/09/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
2896	Installed/Active	03/08/1999	FSGL40	AO SMITH	\$ 850.00	
2897	Installed/Active	10/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2898	Installed/Active	02/05/2002	FSG40	AO SMITH	\$ 850.00	
2899	Installed/Active	01/05/2004	FCVL40	AO SMITH	\$ 850.00	
2900	Installed/Active	06/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
2901	Installed/Active	08/10/2001	FSG40	AO SMITH	\$ 850.00	
2902	Installed/Active	11/27/1993	FSGL40	AO SMITH	\$ 850.00	
2903	Installed/Active	09/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2904	Installed/Active	08/01/1982	FSG50	AO SMITH	\$ 850.00	
2905	Installed/Active	05/06/2002	FSGL40	AO SMITH	\$ 850.00	
2906	Installed/Active	10/16/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2907	Installed/Active	09/29/1996	FSGL40	AO SMITH	\$ 850.00	
2908	Installed/Active	01/29/1999	FGR50	AO SMITH	\$ 850.00	
2909	Installed/Active	05/29/1999	FSG50	AO SMITH	\$ 850.00	
2910	Installed/Active	03/11/2003	FSG50	AO SMITH	\$ 850.00	
2911	Installed/Active	06/21/2001	FSG50	AO SMITH	\$ 850.00	
2912	Installed/Active	09/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2913	Installed/Active	01/01/1982	RF67120	RUUD	\$ 1,900.00	
2914	Installed/Active	07/24/2004	XVR50	A. O. SMITH	\$ 850.00	
2915	Installed/Active	07/02/2001	FSG50	AO SMITH	\$ 850.00	
2916	Installed/Active	06/14/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
2917	Installed/Active	01/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2918	Installed/Active	12/23/1982	21V407	RHEEM	\$ 850.00	
2919	Installed/Active	07/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2920	Installed/Active	10/13/1997	FSG30	AO SMITH	\$ 850.00	
2921	Installed/Active	07/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2922	Installed/Active	05/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
2923	Installed/Active	11/12/1997	FSG30	AO SMITH	\$ 850.00	
2924	Installed/Active	05/30/2006	LTN040G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
2925	Installed/Active	10/14/2011	M-I-5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2926	Installed/Active	01/27/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
2927	Installed/Active	11/14/2012	M2XR504T6FBN	BRADFORD WHITE	\$ 500.00	\$ 20.38
2928	Installed/Active	12/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2929	Installed/Active	10/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2930	Installed/Active	10/07/2006	LTN051G	LOCHINVAR	\$ 850.00	
2931	Installed/Active	03/23/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2932	Installed/Active	01/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
2933	Installed/Active	01/29/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
2934	Installed/Active	11/19/1999	PHR50	RUUD	\$ 850.00	
2935	Installed/Active	11/11/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
2936	Installed/Active	07/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2937	Installed/Active	03/01/2001	H72DUMMY	AO SMITH	\$ 1,900.00	
2938	Installed/Active	02/03/2004	PVR50	AO SMITH	\$ 850.00	
2939	Installed/Active	03/06/2006	LTN040G	LOCHINVAR	\$ 850.00	
2940	Installed/Active	06/28/1984	FSG50	AO SMITH	\$ 850.00	
2941	Installed/Active	02/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
2942	Installed/Active	02/17/2004	XTN050	LOCHINVAR	\$ 850.00	
2943	Installed/Active	10/01/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2944	Installed/Active	03/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2945	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2946	Installed/Active	12/20/2005	LSN041G	LOCHINVAR	\$ 850.00	
2947	Installed/Active	02/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2948	Installed/Active	10/30/1990	21V502	RHEEM	\$ 850.00	
2949	Installed/Active	09/10/2003	FSGL40	AO SMITH	\$ 850.00	
2950	Installed/Active	08/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2951	Installed/Active	07/09/2010	LTN040	LOCHINVAR	\$ 850.00	\$ 12.05
2952	Installed/Active	06/28/1984	RM5063	RUUD	\$ 500.00	
2953	Installed/Active	10/01/1999	FGR50	AO SMITH	\$ 850.00	
2954	Installed/Active	11/05/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
2955	Installed/Active	10/08/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
2956	Installed/Active	05/26/1999	FGR50	AO SMITH	\$ 850.00	
2957	Installed/Active	05/02/2003	FSG50	AO SMITH	\$ 850.00	
2958	Installed/Active	05/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
2959	Installed/Active	04/29/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2960	Installed/Active	07/19/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2961	Installed/Active	05/28/1998	FGR50	AO SMITH	\$ 850.00	
2962	Installed/Active	05/13/2005	LTN050	LOCHINVAR	\$ 850.00	
2963	Installed/Active	01/11/1996	PGR50	AO SMITH	\$ 850.00	
2964	Installed/Active	02/07/2009	21VR40	RHEEM	\$ 850.00	\$ 11.74
2965	Installed/Active	01/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2966	Installed/Active	02/12/1999	41VR50	RHEEM	\$ 850.00	
2967	Installed/Active	01/27/2000	FSG40	AO SMITH	\$ 850.00	
2968	Installed/Active	08/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
2969	Installed/Active	01/04/2007	41V50	RHEEM	\$ 850.00	
2970	Installed/Active	07/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2971	Installed/Active	12/28/2004	41V50	RHEEM	\$ 850.00	
2972	Installed/Active	06/18/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
2973	Installed/Active	03/29/2012	P230F	RUUD	\$ 850.00	\$ 6.34
2974	Installed/Active	08/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
2975	Installed/Active	09/10/2001	FSGL40	AO SMITH	\$ 850.00	
2976	Installed/Active	11/19/1997	PGR50	AO SMITH	\$ 850.00	
2977	Installed/Active	08/20/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
2978	Installed/Active	02/10/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
2979	Installed/Active	12/27/1999	21V407	RHEEM	\$ 850.00	
2980	Installed/Active	05/17/1999	FSG50	AO SMITH	\$ 850.00	
2981	Installed/Active	03/29/2012	P230F	RUUD	\$ 850.00	\$ 7.88
2982	Installed/Active	06/12/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2983	Installed/Active	10/02/2000	41XR50	RHEEM	\$ 850.00	
2984	Installed/Active	10/22/2002	FSG40	AO SMITH	\$ 850.00	
2985	Installed/Active	06/15/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
2986	Installed/Active	09/17/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
2987	Installed/Active	05/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2988	Installed/Active	01/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2989	Installed/Active	06/22/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
2990	Installed/Active	07/20/2005	LTN050	LOCHINVAR	\$ 850.00	
2991	Installed/Active	03/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
2992	Installed/Active	07/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
2993	Installed/Active	06/22/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
2994	Installed/Active	03/15/1995	BTC197	AO SMITH	\$ 3,350.00	
2995	Installed/Active	10/07/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
2996	Installed/Active	10/05/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
2997	Installed/Active	03/23/2000	FSG50	AO SMITH	\$ 850.00	
2998	Installed/Active	05/01/2012	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.64
2999	Installed/Active	03/26/1999	FSG40	AO SMITH	\$ 850.00	
3000	Installed/Active	10/02/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3001	Installed/Active	11/29/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3002	Installed/Active	12/03/1997	PGR40	AO SMITH	\$ 850.00	
3003	Installed/Active	06/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3004	Installed/Active	09/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3005	Installed/Active	04/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3006	Installed/Active	07/27/2010	PH199119	PHOENIX	\$ 3,350.00	\$ 61.05
3007	Installed/Active	06/15/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
3008	Installed/Active	06/01/2009	PR502T	RUUD	\$ 850.00	\$ 11.74
3009	Installed/Active	03/26/2004	FCV50	AO SMITH	\$ 850.00	
3010	Installed/Active	12/14/1999	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3011	Installed/Active	07/27/2010	PH199119	PHOENIX	\$ 3,350.00	\$ 61.05
3012	Installed/Active	02/24/2003	PGR50	AO SMITH	\$ 850.00	
3013	Installed/Active	05/15/2002	FSG50	AO SMITH	\$ 850.00	
3014	Installed/Active	06/02/2000	PGR50	AO SMITH	\$ 850.00	
3015	Installed/Active	03/15/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3016	Installed/Active	01/07/2004	PRX40	STATE	\$ 1,075.00	
3017	Installed/Active	11/08/1996	G67114	RHEEM	\$ 1,900.00	
3018	Installed/Active	08/16/1983	21V407	RHEEM	\$ 850.00	
3019	Installed/Active	08/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3020	Installed/Active	12/31/2008	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
3021	Installed/Active	08/09/2003	FCV50	AO SMITH	\$ 850.00	
3022	Installed/Active	04/18/1995	PHR50	RUUD	\$ 850.00	
3023	Installed/Active	03/27/1997	PGR50	AO SMITH	\$ 850.00	
3024	Installed/Active	11/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3025	Installed/Active	01/31/1998	FGR40	AO SMITH	\$ 850.00	
3026	Installed/Active	10/11/2001	FSG50	AO SMITH	\$ 850.00	
3027	Installed/Active	12/15/1995	PR502T	RUUD	\$ 850.00	
3028	Installed/Active	09/23/1997	PGR50	AO SMITH	\$ 850.00	
3029	Installed/Active	07/18/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3030	Installed/Active	01/13/2009	FSGL40	AO SMITH	\$ 850.00	\$ 11.74
3031	Installed/Active	03/01/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3032	Installed/Active	01/18/2005	FSG50	AO SMITH	\$ 850.00	
3033	Installed/Active	04/25/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
3034	Installed/Active	02/28/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
3035	Installed/Active	07/23/2001	FSG40	AO SMITH	\$ 850.00	
3036	Installed/Active	06/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3037	Installed/Active	03/26/1999	41VR40	RHEEM	\$ 850.00	
3038	Installed/Active	03/21/2012	PGR50	AO SMITH	\$ 850.00	\$ 12.64
3039	Installed/Active	04/13/1996	PGR50	AO SMITH	\$ 850.00	
3040	Installed/Active	07/16/2001	PGR50	AO SMITH	\$ 850.00	
3041	Installed/Active	08/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3042	Installed/Active	10/31/2006	LTN040G	LOCHINVAR	\$ 850.00	
3043	Installed/Active	03/09/2001	FSG50	AO SMITH	\$ 850.00	
3044	Installed/Active	11/01/1980	B71	UNKNOWN	\$ 850.00	
3045	Installed/Active	07/02/1997	PGR50	AO SMITH	\$ 850.00	
3046	Installed/Active	02/04/1982	RM5063	RUUD	\$ 500.00	
3047	Installed/Active	03/04/2003	FSG40	AO SMITH	\$ 850.00	
3048	Installed/Active	04/03/2001	41XR50	RHEEM	\$ 850.00	
3049	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3050	Installed/Active	11/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3051	Installed/Active	01/20/2003	FSG50	AO SMITH	\$ 850.00	
3052	Installed/Active	10/11/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
3053	Installed/Active	09/28/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3054	Installed/Active	07/18/2005	LTN050	LOCHINVAR	\$ 850.00	
3055	Installed/Active	04/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
3056	Installed/Active	11/18/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3057	Installed/Active	02/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3058	Installed/Active	08/30/2001	PGR40	AO SMITH	\$ 850.00	
3059	Installed/Active	02/26/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3060	Installed/Active	09/17/2002	PGR50	AO SMITH	\$ 850.00	
3061	Installed/Active	08/02/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3062	Installed/Active	03/22/2010	21VR40	RHEEM	\$ 850.00	\$ 11.74
3063	Installed/Active	08/08/2008	FSG50	AO SMITH	\$ 850.00	\$ 10.23
3064	Installed/Active	02/26/1996	PRV40NODS	STATE	\$ 1,075.00	
3065	Installed/Active	02/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3066	Installed/Active	12/21/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
3067	Installed/Active	05/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3068	Installed/Active	05/09/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
3069	Installed/Active	02/01/1982	FSG50	AO SMITH	\$ 850.00	
3070	Installed/Active	07/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3071	Installed/Active	07/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3072	Installed/Active	05/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
3073	Installed/Active	02/28/2001	41VR40	RHEEM	\$ 850.00	
3074	Installed/Active	01/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3075	Installed/Active	01/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3076	Installed/Active	03/20/1997	FSG50	AO SMITH	\$ 850.00	
3077	Installed/Active	07/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3078	Installed/Active	11/18/1998	41VR50	RHEEM	\$ 850.00	
3079	Installed/Active	10/01/1981	FSG50	AO SMITH	\$ 850.00	
3080	Installed/Active	01/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3081	Installed/Active	06/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3082	Installed/Active	12/28/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
3083	Installed/Active	04/28/1999	FSG50	AO SMITH	\$ 850.00	
3084	Installed/Active	10/24/2005	LTN050G	LOCHINVAR	\$ 850.00	
3085	Installed/Active	02/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
3086	Installed/Active	02/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3087	Installed/Active	12/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3088	Installed/Active	05/15/2002	PGR50	AO SMITH	\$ 850.00	
3089	Installed/Active	09/11/2002	41XR50	RHEEM	\$ 850.00	
3090	Installed/Active	12/29/2000	PGR50	AO SMITH	\$ 850.00	
3091	Installed/Active	08/24/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
3092	Installed/Active	09/11/2002	41XR50	RHEEM	\$ 850.00	
3093	Installed/Active	02/02/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
3094	Installed/Active	01/22/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3095	Installed/Active	06/05/2003	FSG50	AO SMITH	\$ 850.00	
3096	Installed/Active	02/14/1994	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3097	Installed/Active	07/25/2002	BTR198	AO SMITH	\$ 3,350.00	
3098	Installed/Active	02/11/1999	FGR50	AO SMITH	\$ 850.00	
3099	Installed/Active	01/24/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3100	Installed/Active	02/27/2002	FSG50	AO SMITH	\$ 850.00	
3101	Installed/Active	07/23/2002	BTR198	AO SMITH	\$ 3,350.00	
3102	Installed/Active	08/03/1998	G67114	RHEEM	\$ 1,900.00	
3103	Installed/Active	06/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3104	Installed/Active	09/22/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3105	Installed/Active	11/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3106	Installed/Active	02/10/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
3107	Installed/Active	02/18/1999	FGR50	AO SMITH	\$ 850.00	
3108	Installed/Active	10/03/2002	FSG50	AO SMITH	\$ 850.00	
3109	Installed/Active	10/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3110	Installed/Active	08/16/1996	FSGL40	AO SMITH	\$ 850.00	
3111	Installed/Active	09/26/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
3112	Installed/Active	11/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3113	Installed/Active	07/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
3114	Installed/Active	03/10/2005	GVC50	A. O. SMITH	\$ 850.00	
3115	Installed/Active	11/01/1980	FSG50	AO SMITH	\$ 850.00	
3116	Installed/Active	01/14/2003	FSG50	AO SMITH	\$ 850.00	
3117	Installed/Active	07/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3118	Installed/Active	02/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3119	Installed/Active	01/28/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3120	Installed/Active	07/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3121	Installed/Active	06/14/2004	XVR50	A. O. SMITH	\$ 850.00	
3122	Installed/Active	03/06/1995	FSGL40	AO SMITH	\$ 850.00	
3123	Installed/Active	02/01/2003	PGR40	AO SMITH	\$ 850.00	
3124	Installed/Active	02/16/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3125	Installed/Active	10/14/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3126	Installed/Active	01/03/1998	PGR50	AO SMITH	\$ 850.00	
3127	Installed/Active	07/10/2002	BTR198	AO SMITH	\$ 3,350.00	
3128	Installed/Active	04/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3129	Installed/Active	04/07/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3130	Installed/Active	01/11/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
3131	Installed/Active	05/27/2005	XSN040	LOCHINVAR	\$ 850.00	
3132	Installed/Active	06/30/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
3133	Installed/Active	11/29/1995	PGR50	AO SMITH	\$ 850.00	
3134	Installed/Active	03/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3135	Installed/Active	11/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
3136	Installed/Active	03/15/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3137	Installed/Active	04/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3138	Installed/Active	09/23/2005	LTN050	LOCHINVAR	\$ 850.00	
3139	Installed/Active	04/13/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
3140	Installed/Active	04/07/1998	FSG50	AO SMITH	\$ 850.00	
3141	Installed/Active	08/11/2004	GVC50	A. O. SMITH	\$ 850.00	
3142	Installed/Active	10/18/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3143	Installed/Active	07/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.51
3144	Installed/Active	08/17/1998	G67114	RHEEM	\$ 1,900.00	
3145	Installed/Active	04/02/2004	FCV50	AO SMITH	\$ 850.00	
3146	Installed/Active	12/29/2009	PR502T	RUUD	\$ 850.00	\$ 11.74
3147	Installed/Active	04/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
3148	Installed/Active	06/21/2005	GCVL40	A. O. SMITH	\$ 850.00	
3149	Installed/Active	10/17/2000	41XR50	RHEEM	\$ 850.00	
3150	Installed/Active	07/07/1998	FGR50	AO SMITH	\$ 850.00	
3151	Installed/Active	01/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3152	Installed/Active	10/21/2003	FCV50	AO SMITH	\$ 850.00	
3153	Installed/Active	04/25/1998	FGR50	AO SMITH	\$ 850.00	
3154	Installed/Active	05/02/2006	LTN040G	LOCHINVAR	\$ 850.00	
3155	Installed/Active	11/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3156	Installed/Active	07/28/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
3157	Installed/Active	02/11/2002	FSG40	AO SMITH	\$ 850.00	
3158	Installed/Active	12/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3159	Installed/Active	04/11/2000	41V40S	RHEEM	\$ 850.00	
3160	Installed/Active	12/13/2001	FSG50	AO SMITH	\$ 850.00	
3161	Installed/Active	03/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3162	Installed/Active	12/10/1998	FGR50	AO SMITH	\$ 850.00	
3163	Installed/Active	08/24/2004	XTN050	LOCHINVAR	\$ 850.00	
3164	Installed/Active	01/10/2003	PGR50	AO SMITH	\$ 850.00	
3165	Installed/Active	11/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3166	Installed/Active	02/03/2006	LTN051G	LOCHINVAR	\$ 850.00	
3167	Installed/Active	08/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3168	Installed/Active	12/18/2001	PGR50	AO SMITH	\$ 850.00	
3169	Installed/Active	05/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3170	Installed/Active	10/16/1996	PGR50	AO SMITH	\$ 850.00	
3171	Installed/Active	08/26/2003	FSG50	AO SMITH	\$ 850.00	
3172	Installed/Active	11/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3173	Installed/Active	05/08/2005	LTN050	LOCHINVAR	\$ 850.00	
3174	Installed/Active	07/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
3175	Installed/Active	03/22/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
3176	Installed/Active	01/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3177	Installed/Active	01/21/1986	PH30	RUUD	\$ 350.00	
3178	Installed/Active	05/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3179	Installed/Active	05/16/2005	LTN050	LOCHINVAR	\$ 850.00	
3180	Installed/Active	01/09/2007	LTN050G	LOCHINVAR	\$ 850.00	
3181	Installed/Active	11/18/2004	XVR50	A. O. SMITH	\$ 850.00	
3182	Installed/Active	06/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3183	Installed/Active	10/09/1999	41VR50	RHEEM	\$ 850.00	
3184	Installed/Active	11/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3185	Installed/Active	02/17/2004	FCV50	AO SMITH	\$ 850.00	
3186	Installed/Active	11/27/1984	FSG50	AO SMITH	\$ 850.00	
3187	Installed/Active	03/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3188	Installed/Active	10/12/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
3189	Installed/Active	08/19/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3190	Installed/Active	02/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3191	Installed/Active	07/12/1997	PGR50	AO SMITH	\$ 850.00	
3192	Installed/Active	09/06/2012	SBF100199NES	STATE	\$ 3,350.00	\$ 64.59
3193	Installed/Active	10/09/2003	FSG50	AO SMITH	\$ 850.00	
3194	Installed/Active	10/14/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
3195	Installed/Active	06/15/1983	FSG40	AO SMITH	\$ 850.00	
3196	Installed/Active	03/12/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
3197	Installed/Active	03/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
3198	Installed/Active	03/27/2002	FSG50	AO SMITH	\$ 850.00	
3199	Installed/Active	02/02/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 7.31
3200	Installed/Active	01/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3201	Installed/Active	09/14/1998	FSGL40	AO SMITH	\$ 850.00	
3202	Installed/Active	08/31/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
3203	Installed/Active	03/18/2003	PGR50	AO SMITH	\$ 850.00	
3204	Installed/Active	03/09/1998	FGR50	AO SMITH	\$ 850.00	
3205	Installed/Active	06/22/2001	POWERMISER 9	KENMORE	\$ 850.00	
3206	Installed/Active	03/16/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3207	Installed/Active	04/29/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
3208	Installed/Active	04/06/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
3209	Installed/Active	09/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3210	Installed/Active	07/29/2002	FSG40	AO SMITH	\$ 850.00	
3211	Installed/Active	06/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3212	Installed/Active	10/30/1998	G72DUMMY	AO SMITH	\$ 1,125.00	
3213	Installed/Active	11/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3214	Installed/Active	03/28/2005	XVR50	A. O. SMITH	\$ 850.00	
3215	Installed/Active	09/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3216	Installed/Active	11/11/2004	FSG50	AO SMITH	\$ 850.00	
3217	Installed/Active	04/12/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3218	Installed/Active	06/25/2005	LTN040	LOCHINVAR	\$ 850.00	
3219	Installed/Active	11/22/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3220	Installed/Active	02/18/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
3221	Installed/Active	01/13/2004	FCVL40	AO SMITH	\$ 850.00	
3222	Installed/Active	07/06/2001	FSG50	AO SMITH	\$ 850.00	
3223	Installed/Active	09/09/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3224	Installed/Active	09/11/2001	FSG50	AO SMITH	\$ 850.00	
3225	Installed/Active	03/04/1997	FSG50	AO SMITH	\$ 850.00	
3226	Installed/Active	11/12/2001	PGR50	AO SMITH	\$ 850.00	
3227	Installed/Active	03/12/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3228	Installed/Active	12/01/1985	FSG50	AO SMITH	\$ 850.00	
3229	Installed/Active	02/07/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3230	Installed/Active	11/21/2001	PGR50	AO SMITH	\$ 850.00	
3231	Installed/Active	09/20/2001	PGR50	AO SMITH	\$ 850.00	
3232	Installed/Active	05/09/2000	FSG50	AO SMITH	\$ 850.00	
3233	Installed/Active	10/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3234	Installed/Active	07/30/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3235	Installed/Active	05/19/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
3236	Installed/Active	01/19/1999	FSG50	AO SMITH	\$ 850.00	
3237	Installed/Active	04/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
3238	Installed/Active	09/27/1985	FSG50	AO SMITH	\$ 850.00	
3239	Installed/Active	12/10/2005	PR640	STATE	\$ 1,075.00	
3240	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3241	Installed/Active	04/23/1986	FSG50	AO SMITH	\$ 850.00	
3242	Installed/Active	11/23/1985	FSG50	AO SMITH	\$ 850.00	
3243	Installed/Active	04/18/2005	GVC50	A. O. SMITH	\$ 850.00	
3244	Installed/Active	02/05/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
3245	Installed/Active	02/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3246	Installed/Active	02/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3247	Installed/Active	02/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
3248	Installed/Active	10/10/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3249	Installed/Active	07/31/2003	PRV50NODS	STATE	\$ 1,075.00	
3250	Installed/Active	07/19/2009	41V50	RHEEM	\$ 850.00	\$ 11.74
3251	Installed/Active	04/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3252	Installed/Active	08/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3253	Installed/Active	12/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
3254	Installed/Active	11/14/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3255	Installed/Active	03/29/2001	FSG50	AO SMITH	\$ 850.00	
3256	Installed/Active	02/19/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
3257	Installed/Active	09/16/1999	FGR40	AO SMITH	\$ 850.00	
3258	Installed/Active	01/20/1998	41VR50	RHEEM	\$ 850.00	
3259	Installed/Active	09/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3260	Installed/Active	08/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3261	Installed/Active	05/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
3262	Installed/Active	02/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
3263	Installed/Active	12/19/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
3264	Installed/Active	05/20/2002	FSG40	AO SMITH	\$ 850.00	
3265	Installed/Active	05/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3266	Installed/Active	10/26/2001	PGR50	AO SMITH	\$ 850.00	
3267	Installed/Active	07/07/2000	FSGL40	AO SMITH	\$ 850.00	
3268	Installed/Active	10/21/2005	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3269	Installed/Active	09/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3270	Installed/Active	10/17/1994	PGR40	AO SMITH	\$ 850.00	
3271	Installed/Active	11/16/1983	FSSL40	AO SMITH	\$ 850.00	
3272	Installed/Active	08/06/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
3273	Installed/Active	02/12/2004	XTN050	LOCHINVAR	\$ 850.00	
3274	Installed/Active	06/10/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
3275	Installed/Active	07/27/2002	PGR50	AO SMITH	\$ 850.00	
3276	Installed/Active	08/05/2003	FCVL40	AO SMITH	\$ 850.00	
3277	Installed/Active	12/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3278	Installed/Active	01/23/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3279	Installed/Active	05/15/2003	FSSL40	AO SMITH	\$ 850.00	
3280	Installed/Active	08/06/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3281	Installed/Active	03/05/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
3282	Installed/Active	09/08/1982	FSSL40	AO SMITH	\$ 850.00	
3283	Installed/Active	12/08/1994	H72DUMMY	AO SMITH	\$ 1,900.00	
3284	Installed/Active	10/17/1997	41VR50	RHEEM	\$ 850.00	
3285	Installed/Active	03/09/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
3286	Installed/Active	11/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3287	Installed/Active	10/06/2005	LTN040G	LOCHINVAR	\$ 850.00	
3288	Installed/Active	11/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
3289	Installed/Active	04/22/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3290	Installed/Active	12/07/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3291	Installed/Active	02/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3292	Installed/Active	12/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
3293	Installed/Active	02/20/2002	PGR50	AO SMITH	\$ 850.00	
3294	Installed/Active	11/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3295	Installed/Active	08/22/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
3296	Installed/Active	08/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3297	Installed/Active	06/26/2000	FSG50	AO SMITH	\$ 850.00	
3298	Installed/Active	12/18/1998	FSG50	AO SMITH	\$ 850.00	
3299	Installed/Active	04/26/2005	LTN050	LOCHINVAR	\$ 850.00	
3300	Installed/Active	01/11/2002	FSG50	AO SMITH	\$ 850.00	
3301	Installed/Active	06/24/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
3302	Installed/Active	05/18/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
3303	Installed/Active	03/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3304	Installed/Active	11/18/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3305	Installed/Active	09/05/2006	PR650	STATE	\$ 1,075.00	
3306	Installed/Active	10/08/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3307	Installed/Active	07/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3308	Installed/Active	03/03/2009	FSSL40	AO SMITH	\$ 850.00	\$ 11.74
3309	Installed/Active	11/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3310	Installed/Active	10/23/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
3311	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3312	Installed/Active	05/02/2000	FSG40	AO SMITH	\$ 850.00	
3313	Installed/Active	11/18/1997	FSG40	AO SMITH	\$ 850.00	
3314	Installed/Active	05/19/2005	LTN040	LOCHINVAR	\$ 850.00	
3315	Installed/Active	11/06/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3316	Installed/Active	03/03/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
3317	Installed/Active	11/16/2005	LSN041G	LOCHINVAR	\$ 850.00	
3318	Installed/Active	09/04/1998	41VR50	RHEEM	\$ 850.00	
3319	Installed/Active	07/08/2002	FSG50	AO SMITH	\$ 850.00	
3320	Installed/Active	01/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3321	Installed/Active	02/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3322	Installed/Active	01/16/1985	FSG40	AO SMITH	\$ 850.00	
3323	Installed/Active	02/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3324	Installed/Active	01/26/2004	FCV50	AO SMITH	\$ 850.00	
3325	Installed/Active	06/01/2003	FSG50	AO SMITH	\$ 850.00	
3326	Installed/Active	08/30/2000	41V40S	RHEEM	\$ 850.00	
3327	Installed/Active	12/12/2003	PVR50	AO SMITH	\$ 850.00	
3328	Installed/Active	09/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3329	Installed/Active	08/30/1999	FSG50	AO SMITH	\$ 850.00	
3330	Installed/Active	08/31/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
3331	Installed/Active	06/21/2001	PGR50	AO SMITH	\$ 850.00	
3332	Installed/Active	01/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3333	Installed/Active	06/25/2003	FSSL40	AO SMITH	\$ 850.00	
3334	Installed/Active	03/05/2001	FSG50	AO SMITH	\$ 850.00	
3335	Installed/Active	06/06/2002	FSG50	AO SMITH	\$ 850.00	
3336	Installed/Active	05/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3337	Installed/Active	09/28/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3338	Installed/Active	06/12/2001	FSG50	AO SMITH	\$ 850.00	
3339	Installed/Active	12/20/2002	41V40S	RHEEM	\$ 850.00	
3340	Installed/Active	03/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3341	Installed/Active	04/12/2005	GCVL40	A. O. SMITH	\$ 850.00	
3342	Installed/Active	10/12/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3343	Installed/Active	03/05/2011	42VR50	RHEEM	\$ 850.00	\$ 7.51
3344	Installed/Active	02/24/2005	GCVL40	A. O. SMITH	\$ 850.00	
3345	Installed/Active	08/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3346	Installed/Active	05/02/2003	FSG50	AO SMITH	\$ 850.00	
3347	Installed/Active	12/18/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3348	Installed/Active	03/21/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
3349	Installed/Active	01/12/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3350	Installed/Active	11/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3351	Installed/Active	09/14/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
3352	Installed/Active	11/23/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3353	Installed/Active	04/11/1988	SBF75120NE	STATE	\$ 1,900.00	
3354	Installed/Active	01/24/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3355	Installed/Active	08/20/2011	42V50SF	RHEEM	\$ 850.00	\$ 12.64
3356	Installed/Active	12/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3357	Installed/Active	02/10/2006	LTN040G	LOCHINVAR	\$ 850.00	
3358	Installed/Active	10/14/1998	FSG40	AO SMITH	\$ 850.00	
3359	Installed/Active	09/15/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
3360	Installed/Active	10/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
3361	Installed/Active	10/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3362	Installed/Active	12/09/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
3363	Installed/Active	04/12/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
3364	Installed/Active	07/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
3365	Installed/Active	09/09/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3366	Installed/Active	03/31/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3367	Installed/Active	04/19/2000	FSG50	AO SMITH	\$ 850.00	
3368	Installed/Active	12/03/2002	41XR50	RHEEM	\$ 850.00	
3369	Installed/Active	05/03/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
3370	Installed/Active	12/23/2004	GVC50	A. O. SMITH	\$ 850.00	
3371	Installed/Active	09/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3372	Installed/Active	03/19/1998	FSG50	AO SMITH	\$ 850.00	
3373	Installed/Active	04/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
3374	Installed/Active	07/28/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3375	Installed/Active	03/31/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
3376	Installed/Active	02/03/1999	FGR50	AO SMITH	\$ 850.00	
3377	Installed/Active	03/03/1991	PRX50	STATE	\$ 1,075.00	
3378	Installed/Active	05/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3379	Installed/Active	12/11/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
3380	Installed/Active	09/14/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
3381	Installed/Active	02/07/2003	21V506	RHEEM	\$ 1,125.00	
3382	Installed/Active	08/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3383	Installed/Active	12/06/1985	FSG50	AO SMITH	\$ 850.00	
3384	Installed/Active	03/19/2001	FSG50	AO SMITH	\$ 850.00	
3385	Installed/Active	08/26/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3386	Installed/Active	12/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3387	Installed/Active	05/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3388	Installed/Active	04/18/2001	PRX50	STATE	\$ 1,075.00	
3389	Installed/Active	03/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3390	Installed/Active	05/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3391	Installed/Active	10/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3392	Installed/Active	01/18/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
3393	Installed/Active	12/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3394	Installed/Active	10/19/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
3395	Installed/Active	04/24/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3396	Installed/Active	10/14/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
3397	Installed/Active	04/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
3398	Installed/Active	06/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3399	Installed/Active	03/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3400	Installed/Active	03/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3401	Installed/Active	11/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3402	Installed/Active	07/01/1998	FSG50	AO SMITH	\$ 850.00	
3403	Installed/Active	10/03/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
3404	Installed/Active	06/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3405	Installed/Active	07/03/1997	21V407	RHEEM	\$ 850.00	
3406	Installed/Active	11/26/2010	42VR50	RHEEM	\$ 850.00	\$ 16.55
3407	Installed/Active	08/17/2004	XVR50	A. O. SMITH	\$ 850.00	
3408	Installed/Active	04/23/1999	FSGL30	AO SMITH	\$ 350.00	
3409	Installed/Active	08/17/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3410	Installed/Active	06/11/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3411	Installed/Active	01/18/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
3412	Installed/Active	04/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3413	Installed/Active	01/13/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3414	Installed/Active	09/01/1982	P402	RUUD	\$ 850.00	
3415	Installed/Active	07/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3416	Installed/Active	04/25/2012	41XR50	RHEEM	\$ 850.00	\$ 12.64
3417	Installed/Active	05/15/2001	FGR40	AO SMITH	\$ 850.00	
3418	Installed/Active	01/05/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3419	Installed/Active	05/30/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3420	Installed/Active	12/01/1984	FSG50	AO SMITH	\$ 850.00	
3421	Installed/Active	05/16/1994	PR502T	RUUD	\$ 850.00	
3422	Installed/Active	04/28/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
3423	Installed/Active	01/14/1997	RF67120	RUUD	\$ 1,900.00	
3424	Installed/Active	12/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3425	Installed/Active	01/29/2004	XTN050	LOCHINVAR	\$ 850.00	
3426	Installed/Active	12/14/1983	FSG50	AO SMITH	\$ 850.00	
3427	Installed/Active	05/03/2006	LTN040G	LOCHINVAR	\$ 850.00	
3428	Installed/Active	02/15/2005	FGR40	AO SMITH	\$ 850.00	
3429	Installed/Active	09/25/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
3430	Installed/Active	11/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3431	Installed/Active	03/17/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
3432	Installed/Active	07/20/2004	XTN050	LOCHINVAR	\$ 850.00	
3433	Installed/Active	10/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3434	Installed/Active	09/01/1983	FSG50	AO SMITH	\$ 850.00	
3435	Installed/Active	08/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3436	Installed/Active	02/19/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3437	Installed/Active	02/21/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3438	Installed/Active	08/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3439	Installed/Active	05/02/2005	LTN050	LOCHINVAR	\$ 850.00	
3440	Installed/Active	07/23/2001	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3441	Installed/Active	02/07/2003	FSG50	AO SMITH	\$ 850.00	
3442	Installed/Active	09/17/1998	BTR198	AO SMITH	\$ 3,350.00	
3443	Installed/Active	12/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
3444	Installed/Active	08/17/2000	FGR30	AO SMITH	\$ 850.00	
3445	Installed/Active	01/27/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3446	Installed/Active	12/03/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
3447	Installed/Active	10/30/2009	PRX40	STATE	\$ 1,075.00	\$ 16.47
3448	Installed/Active	07/20/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
3449	Installed/Active	07/22/2003	FSG40	AO SMITH	\$ 350.00	
3450	Installed/Active	06/03/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3451	Installed/Active	06/23/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3452	Installed/Active	09/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3453	Installed/Active	10/27/2006	LTN040G	LOCHINVAR	\$ 850.00	
3454	Installed/Active	06/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
3455	Installed/Active	04/11/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
3456	Installed/Active	01/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3457	Installed/Active	04/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3458	Installed/Active	12/18/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3459	Installed/Active	08/02/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3460	Installed/Active	02/08/2002	PGR50	AO SMITH	\$ 850.00	
3461	Installed/Active	11/06/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3462	Installed/Active	08/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3463	Installed/Active	12/24/2002	FSG50	AO SMITH	\$ 850.00	
3464	Installed/Active	12/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3465	Installed/Active	02/01/2007	41V50	RHEEM	\$ 850.00	\$ 10.23
3466	Installed/Active	06/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3467	Installed/Active	11/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
3468	Installed/Active	01/23/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3469	Installed/Active	10/26/1999	FSG40	AO SMITH	\$ 850.00	
3470	Installed/Active	01/10/2004	FSG50	AO SMITH	\$ 850.00	
3471	Installed/Active	04/05/2010	PGR50	AO SMITH	\$ 850.00	\$ 11.74
3472	Installed/Active	04/19/2004	PR650	STATE	\$ 1,075.00	
3473	Installed/Active	07/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3474	Installed/Active	11/28/2004	GVC50	A. O. SMITH	\$ 850.00	
3475	Installed/Active	10/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3476	Installed/Active	05/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3477	Installed/Active	09/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3478	Installed/Active	01/08/1996	BTC197	AO SMITH	\$ 3,350.00	
3479	Installed/Active	01/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3480	Installed/Active	10/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3481	Installed/Active	05/03/2006	LSN041	LOCHINVAR	\$ 850.00	
3482	Installed/Active	01/08/1996	BTC197	AO SMITH	\$ 3,350.00	
3483	Installed/Active	07/22/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3484	Installed/Active	12/28/1992	FSG50	AO SMITH	\$ 850.00	
3485	Installed/Active	04/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3486	Installed/Active	12/10/2001	PGR50	AO SMITH	\$ 850.00	
3487	Installed/Active	11/08/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3488	Installed/Active	08/10/2006	LSN041G	LOCHINVAR	\$ 850.00	
3489	Installed/Active	10/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3490	Installed/Active	11/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3491	Installed/Active	07/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3492	Installed/Active	12/07/2004	GVC30	AOSMITH	\$ 850.00	
3493	Installed/Active	08/11/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3494	Installed/Active	06/30/1997	PGR40	AO SMITH	\$ 850.00	
3495	Installed/Active	07/13/2002	PGR40	AO SMITH	\$ 850.00	
3496	Installed/Active	04/20/2000	PHR50	RUUD	\$ 850.00	
3497	Installed/Active	08/25/2000	FSG40	AO SMITH	\$ 850.00	
3498	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3499	Installed/Active	04/07/2003	PGR50	AO SMITH	\$ 850.00	
3500	Installed/Active	01/03/2010	FGR50	AO SMITH	\$ 850.00	\$ 11.74
3501	Installed/Active	10/23/2001	PGR50	AO SMITH	\$ 850.00	
3502	Installed/Active	02/12/2002	FSG40	AO SMITH	\$ 850.00	
3503	Installed/Active	03/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3504	Installed/Active	10/25/2001	PGR50	AO SMITH	\$ 850.00	
3505	Installed/Active	05/22/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
3506	Installed/Active	07/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3507	Installed/Active	10/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3508	Installed/Active	09/29/1996	RF67120	RUUD	\$ 1,900.00	
3509	Installed/Active	07/10/2004	GVC50	A. O. SMITH	\$ 850.00	
3510	Installed/Active	12/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3511	Installed/Active	05/11/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3512	Installed/Active	05/14/2003	PGR50	AO SMITH	\$ 850.00	
3513	Installed/Active	01/27/2000	FGR40	AO SMITH	\$ 850.00	
3514	Installed/Active	03/17/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 5.12
3515	Installed/Active	01/06/2007	LTN040G	LOCHINVAR	\$ 850.00	
3516	Installed/Active	01/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3517	Installed/Active	07/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3518	Installed/Active	05/07/2004	XVR50	A. O. SMITH	\$ 850.00	
3519	Installed/Active	04/01/2002	PGR50	AO SMITH	\$ 850.00	
3520	Installed/Active	04/26/2001	FSL40	AO SMITH	\$ 850.00	
3521	Installed/Active	10/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3522	Installed/Active	07/20/2001	41XR50	RHEEM	\$ 850.00	
3523	Installed/Active	08/31/2011	SBF100199NES	STATE	\$ 3,350.00	\$ 64.06
3524	Installed/Active	12/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3525	Installed/Active	03/02/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3526	Installed/Active	12/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3527	Installed/Active	12/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3528	Installed/Active	02/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3529	Installed/Active	02/06/2012	PH2DV50F	RUUD	\$ 850.00	\$ 12.64
3530	Installed/Active	03/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
3531	Installed/Active	03/01/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3532	Installed/Active	12/13/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3533	Installed/Active	01/25/1985	FSG50	AO SMITH	\$ 850.00	
3534	Installed/Active	07/28/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
3535	Installed/Active	03/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3536	Installed/Active	03/29/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
3537	Installed/Active	09/20/2005	LTN040G	LOCHINVAR	\$ 850.00	
3538	Installed/Active	03/01/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
3539	Installed/Active	04/05/2005	XVR50	A. O. SMITH	\$ 850.00	
3540	Installed/Active	01/20/1997	PGR50	AO SMITH	\$ 850.00	
3541	Installed/Active	11/15/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3542	Installed/Active	01/02/2002	FSGL40	AO SMITH	\$ 850.00	
3543	Installed/Active	06/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
3544	Installed/Active	04/22/1986	FSG50	AO SMITH	\$ 850.00	
3545	Installed/Active	09/15/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
3546	Installed/Active	07/25/1985	FSG50	AO SMITH	\$ 850.00	
3547	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3548	Installed/Active	10/04/2001	FSG40	AO SMITH	\$ 850.00	
3549	Installed/Active	02/24/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3550	Installed/Active	05/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
3551	Installed/Active	05/02/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
3552	Installed/Active	04/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3553	Installed/Active	01/06/2005	GVC50	A. O. SMITH	\$ 850.00	
3554	Installed/Active	05/30/2000	PGR50	AO SMITH	\$ 850.00	
3555	Installed/Active	01/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
3556	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
3557	Installed/Active	01/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3558	Installed/Active	04/10/2002	FSG40	AO SMITH	\$ 850.00	
3559	Installed/Active	12/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3560	Installed/Active	03/12/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3561	Installed/Active	02/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3562	Installed/Active	07/14/1998	41VR50	RHEEM	\$ 850.00	
3563	Installed/Active	06/25/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
3564	Installed/Active	01/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3565	Installed/Active	06/15/2004	XTN050	LOCHINVAR	\$ 850.00	
3566	Installed/Active	08/30/2010	FSG40	AO SMITH	\$ 850.00	\$ 12.05
3567	Installed/Active	02/03/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3568	Installed/Active	06/21/2005	LTN050	LOCHINVAR	\$ 850.00	
3569	Installed/Active	04/18/1986	FSG50	AO SMITH	\$ 850.00	
3570	Installed/Active	04/28/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3571	Installed/Active	09/26/2001	PGR50	AO SMITH	\$ 850.00	
3572	Installed/Active	02/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3573	Installed/Active	10/21/2005	LTN040G	LOCHINVAR	\$ 850.00	
3574	Installed/Active	10/25/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
3575	Installed/Active	09/07/2000	BTR197	AO SMITH	\$ 3,350.00	
3576	Installed/Active	01/23/1995	PR502T	RUUD	\$ 850.00	
3577	Installed/Active	04/25/1985	PH30	RUUD	\$ 350.00	
3578	Installed/Active	06/02/2001	FSG40	AO SMITH	\$ 850.00	
3579	Installed/Active	07/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3580	Installed/Active	08/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3581	Installed/Active	06/23/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
3582	Installed/Active	12/27/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
3583	Installed/Active	09/28/2006	PR650	STATE	\$ 1,075.00	
3584	Installed/Active	01/02/2002	PGR50	AO SMITH	\$ 850.00	
3585	Installed/Active	05/26/2011	21V506	RHEEM	\$ 500.00	\$ 41.30
3586	Installed/Active	11/12/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
3587	Installed/Active	03/08/2001	PGR50	AO SMITH	\$ 500.00	
3588	Installed/Active	08/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3589	Installed/Active	10/14/1998	FGR50	AO SMITH	\$ 850.00	
3590	Installed/Active	04/20/2000	21V506	RHEEM	\$ 1,150.00	
3591	Installed/Active	05/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3592	Installed/Active	10/30/1999	41XR50	RHEEM	\$ 850.00	
3593	Installed/Active	09/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3594	Installed/Active	08/16/2002	PGR50	AO SMITH	\$ 850.00	
3595	Installed/Active	11/14/2003	FCV50	AO SMITH	\$ 850.00	
3596	Installed/Active	06/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3597	Installed/Active	11/26/2001	41XR50	RHEEM	\$ 850.00	
3598	Installed/Active	11/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3599	Installed/Active	10/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3600	Installed/Active	07/21/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
3601	Installed/Active	07/21/1999	FSG50	AO SMITH	\$ 850.00	
3602	Installed/Active	10/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
3603	Installed/Active	11/15/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
3604	Installed/Active	02/28/2005	PRX50	STATE	\$ 1,075.00	
3605	Installed/Active	09/11/2001	FSG50	AO SMITH	\$ 850.00	
3606	Installed/Active	03/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
3607	Installed/Active	04/18/1986	RM5063	RUUD	\$ 500.00	
3608	Installed/Active	08/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3609	Installed/Active	09/30/1985	FSG50	AO SMITH	\$ 850.00	
3610	Installed/Active	06/27/2006	LTN040G	LOCHINVAR	\$ 850.00	
3611	Installed/Active	10/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3612	Installed/Active	01/02/2004	XTN050	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3613	Installed/Active	04/25/2002	FSG50	AO SMITH	\$ 850.00	
3614	Installed/Active	12/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3615	Installed/Active	09/11/2000	41XR50	RHEEM	\$ 850.00	
3616	Installed/Active	12/05/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3617	Installed/Active	12/16/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
3618	Installed/Active	04/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3619	Installed/Active	03/27/1984	FSG50	AO SMITH	\$ 850.00	
3620	Installed/Active	10/03/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
3621	Installed/Active	06/12/2006	LSN041G	LOCHINVAR	\$ 850.00	
3622	Installed/Active	02/08/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
3623	Installed/Active	07/07/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3624	Installed/Active	08/25/1999	PGR50	AO SMITH	\$ 850.00	
3625	Installed/Active	03/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3626	Installed/Active	12/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3627	Installed/Active	07/28/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
3628	Installed/Active	06/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3629	Installed/Active	08/29/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
3630	Installed/Active	09/08/2000	41XR50	RHEEM	\$ 850.00	
3631	Installed/Active	01/22/2003	FSG50	AO SMITH	\$ 850.00	
3632	Installed/Active	07/18/2002	FSG30	AO SMITH	\$ 850.00	
3633	Installed/Active	01/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3634	Installed/Active	04/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3635	Installed/Active	08/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3636	Installed/Active	07/03/1997	PGR50	AO SMITH	\$ 850.00	
3637	Installed/Active	09/04/2002	FSG40	AO SMITH	\$ 850.00	
3638	Installed/Active	11/01/1993	FSG50	AO SMITH	\$ 850.00	
3639	Installed/Active	10/07/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3640	Installed/Active	01/13/1996	PGR50	AO SMITH	\$ 850.00	
3641	Installed/Active	05/18/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
3642	Installed/Active	03/06/1999	41VR40	RHEEM	\$ 850.00	
3643	Installed/Active	11/29/1993	21V502	RHEEM	\$ 850.00	
3644	Installed/Active	04/21/1997	PGR40	AO SMITH	\$ 850.00	
3645	Installed/Active	05/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3646	Installed/Active	08/13/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3647	Installed/Active	01/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
3648	Installed/Active	12/23/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
3649	Installed/Active	03/11/1996	PGR50	AO SMITH	\$ 850.00	
3650	Installed/Active	04/21/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3651	Installed/Active	12/03/2004	GVC50	A. O. SMITH	\$ 850.00	
3652	Installed/Active	04/11/2002	FSG50	AO SMITH	\$ 850.00	
3653	Installed/Active	01/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3654	Installed/Active	09/09/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
3655	Installed/Active	05/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
3656	Installed/Active	05/06/2011	41V50S	RHEEM	\$ 850.00	\$ 12.64
3657	Installed/Active	02/22/2003	FSG50	AO SMITH	\$ 850.00	
3658	Installed/Active	06/23/2005	LTN050	LOCHINVAR	\$ 850.00	
3659	Installed/Active	11/18/1986	FSG50	AO SMITH	\$ 850.00	
3660	Installed/Active	01/28/2012	M175S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.30
3661	Installed/Active	10/10/1985	FSG50	AO SMITH	\$ 850.00	
3662	Installed/Active	08/02/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3663	Installed/Active	02/11/2005	XVR50	A. O. SMITH	\$ 850.00	
3664	Installed/Active	06/28/1993	21V502	RHEEM	\$ 850.00	
3665	Installed/Active	03/01/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3666	Installed/Active	10/14/2004	GDVS50	AOSMITH	\$ 1,075.00	
3667	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3668	Installed/Active	10/03/2000	41XR40	RHEEM	\$ 850.00	
3669	Installed/Active	01/09/2006	LSN041G	LOCHINVAR	\$ 850.00	
3670	Installed/Active	10/14/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3671	Installed/Active	03/10/2004	PRX50	STATE	\$ 1,075.00	
3672	Installed/Active	05/22/2000	PGR50	AO SMITH	\$ 850.00	
3673	Installed/Active	07/18/2001	PRX50	STATE	\$ 1,075.00	
3674	Installed/Active	11/14/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
3675	Installed/Active	02/12/2003	PRX50	STATE	\$ 1,075.00	
3676	Installed/Active	08/29/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
3677	Installed/Active	01/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
3678	Installed/Active	02/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
3679	Installed/Active	12/18/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
3680	Installed/Active	03/11/2000	PRV50NODS	STATE	\$ 1,075.00	
3681	Installed/Active	06/24/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
3682	Installed/Active	10/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
3683	Installed/Active	09/22/2010	41V50	RHEEM	\$ 500.00	\$ 19.26
3684	Installed/Active	10/17/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
3685	Installed/Active	02/27/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
3686	Installed/Active	02/01/2004	FCVL40	AO SMITH	\$ 850.00	
3687	Installed/Active	12/13/1999	FGR50	AO SMITH	\$ 850.00	
3688	Installed/Active	06/29/2004	FSG30	AO SMITH	\$ 850.00	
3689	Installed/Active	08/30/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
3690	Installed/Active	10/16/1999	PGR50	AO SMITH	\$ 850.00	
3691	Installed/Active	06/08/2011	H72DUMMY	AO SMITH	\$ 1,900.00	\$ 41.30
3692	Installed/Active	09/09/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3693	Installed/Active	09/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
3694	Installed/Active	10/12/2006	GVC50	A. O. SMITH	\$ 850.00	
3695	Installed/Active	05/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3696	Installed/Active	12/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3697	Installed/Active	01/10/2000	FSG40	AO SMITH	\$ 850.00	
3698	Installed/Active	08/11/2008	PR640	STATE	\$ 1,075.00	\$ 14.35

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3699	Installed/Active	11/20/2001	41XR40	RHEEM	\$ 850.00	
3700	Installed/Active	02/15/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3701	Installed/Active	11/17/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3702	Installed/Active	02/13/2004	FCV40	AO SMITH	\$ 850.00	
3703	Installed/Active	06/17/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3704	Installed/Active	01/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
3705	Installed/Active	01/22/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3706	Installed/Active	07/31/2003	FSGL40	AO SMITH	\$ 850.00	
3707	Installed/Active	11/22/2004	PRX40	STATE	\$ 1,075.00	
3708	Installed/Active	10/26/2001	PGR50	AO SMITH	\$ 850.00	
3709	Installed/Active	04/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
3710	Installed/Active	07/01/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
3711	Installed/Active	01/25/1997	PR502T	RUUD	\$ 850.00	
3712	Installed/Active	07/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3713	Installed/Active	09/17/2001	FSG50	AO SMITH	\$ 850.00	
3714	Installed/Active	05/17/2005	XSN040	LOCHINVAR	\$ 850.00	
3715	Installed/Active	07/01/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
3716	Installed/Active	06/20/2000	FSG50	AO SMITH	\$ 850.00	
3717	Installed/Active	07/15/2003	FSG50	AO SMITH	\$ 850.00	
3718	Installed/Active	09/23/2003	FSGL40	AO SMITH	\$ 850.00	
3719	Installed/Active	06/29/2005	LTN050	LOCHINVAR	\$ 850.00	
3720	Installed/Active	11/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
3721	Installed/Active	01/11/2006	LSN041G	LOCHINVAR	\$ 850.00	
3722	Installed/Active	12/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3723	Installed/Active	09/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
3724	Installed/Active	09/10/2004	XTN050	LOCHINVAR	\$ 850.00	
3725	Installed/Active	12/12/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3726	Installed/Active	01/03/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3727	Installed/Active	03/22/2004	XTN040	LOCHINVAR	\$ 850.00	
3728	Installed/Active	10/15/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3729	Installed/Active	04/05/2003	FSG40	AO SMITH	\$ 850.00	
3730	Installed/Active	11/11/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3731	Installed/Active	03/04/2005	GVC40	A. O. SMITH	\$ 850.00	
3732	Installed/Active	01/11/2005	GVC50	A. O. SMITH	\$ 850.00	
3733	Installed/Active	06/13/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3734	Installed/Active	08/02/2006	LSN041G	LOCHINVAR	\$ 850.00	
3735	Installed/Active	10/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3736	Installed/Active	08/26/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3737	Installed/Active	08/10/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
3738	Installed/Active	02/02/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
3739	Installed/Active	02/16/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
3740	Installed/Active	05/25/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.64
3741	Installed/Active	11/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3742	Installed/Active	04/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3743	Installed/Active	10/03/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3744	Installed/Active	11/16/1999	21V506	RHEEM	\$ 1,150.00	
3745	Installed/Active	07/16/2004	GVC50	A. O. SMITH	\$ 850.00	
3746	Installed/Active	01/22/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3747	Installed/Active	01/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3748	Installed/Active	01/02/1986	FSG50	AO SMITH	\$ 850.00	
3749	Installed/Active	08/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3750	Installed/Active	03/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3751	Installed/Active	06/23/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3752	Installed/Active	02/13/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3753	Installed/Active	10/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3754	Installed/Active	01/28/2013	M140356FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3755	Installed/Active	06/28/2000	FSG50	AO SMITH	\$ 850.00	
3756	Installed/Active	12/21/2009	PR650	STATE	\$ 1,075.00	\$ 16.47
3757	Installed/Active	02/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
3758	Installed/Active	11/24/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
3759	Installed/Active	10/22/2001	PGR50	AO SMITH	\$ 850.00	
3760	Installed/Active	04/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3761	Installed/Active	04/30/1986	FSGL40	AO SMITH	\$ 850.00	
3762	Installed/Active	06/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3763	Installed/Active	04/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
3764	Installed/Active	10/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
3765	Installed/Active	03/06/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3766	Installed/Active	11/01/2004	RM5063	RUUD	\$ 500.00	
3767	Installed/Active	11/17/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3768	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3769	Installed/Active	04/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3770	Installed/Active	01/24/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3771	Installed/Active	08/28/2004	GVC30	AOSMITH	\$ 850.00	
3772	Installed/Active	01/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3773	Installed/Active	08/09/2004	FSGL40	AO SMITH	\$ 850.00	
3774	Installed/Active	04/11/2000	PR640	STATE	\$ 1,075.00	
3775	Installed/Active	11/07/2003	FCV40	AO SMITH	\$ 850.00	
3776	Installed/Active	02/21/2008	PR640	STATE	\$ 1,075.00	\$ 14.35
3777	Installed/Active	09/22/2002	FSG50	AO SMITH	\$ 850.00	
3778	Installed/Active	03/03/2000	PR650	STATE	\$ 1,075.00	
3779	Installed/Active	11/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3780	Installed/Active	05/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
3781	Installed/Active	12/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3782	Installed/Active	05/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3783	Installed/Active	05/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3784	Installed/Active	06/08/2002	FSG40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3785	Installed/Active	12/16/2011	P506	RUUD	\$ 1,125.00	\$ 20.21
3786	Installed/Active	02/13/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
3787	Installed/Active	08/03/2005	PR650	STATE	\$ 1,075.00	
3788	Installed/Active	03/01/2005	GVC40	A. O. SMITH	\$ 850.00	
3789	Installed/Active	12/12/2005	PR650	STATE	\$ 1,075.00	
3790	Installed/Active	09/20/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3791	Installed/Active	05/04/2001	FSG50	AO SMITH	\$ 850.00	
3792	Installed/Active	05/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3793	Installed/Active	02/13/2002	PGR50	AO SMITH	\$ 850.00	
3794	Installed/Active	11/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3795	Installed/Active	07/02/2004	XVR50	A. O. SMITH	\$ 850.00	
3796	Installed/Active	11/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3797	Installed/Active	07/16/2005	PR650	STATE	\$ 1,075.00	
3798	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
3799	Installed/Active	03/14/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3800	Installed/Active	11/20/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
3801	Installed/Active	02/14/2002	FSG40	AO SMITH	\$ 850.00	
3802	Installed/Active	06/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3803	Installed/Active	02/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
3804	Installed/Active	07/24/2003	FSG50	AO SMITH	\$ 850.00	
3805	Installed/Active	08/16/1996	PGR50	AO SMITH	\$ 850.00	
3806	Installed/Active	09/23/2011	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
3807	Installed/Active	06/10/2003	FDV50	AO SMITH	\$ 1,075.00	
3808	Installed/Active	05/04/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
3809	Installed/Active	07/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3810	Installed/Active	03/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3811	Installed/Active	12/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
3812	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3813	Installed/Active	11/08/2001	PRX50	STATE	\$ 1,075.00	
3814	Installed/Active	05/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3815	Installed/Active	03/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3816	Installed/Active	04/11/2006	FSG50	AO SMITH	\$ 850.00	
3817	Installed/Active	06/14/2006	PR650	STATE	\$ 1,075.00	
3818	Installed/Active	08/19/2004	XSN040	LOCHINVAR	\$ 850.00	
3819	Installed/Active	06/28/2012	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3820	Installed/Active	09/13/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3821	Installed/Active	01/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
3822	Installed/Active	07/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3823	Installed/Active	06/02/1987	PRV30	STATE	\$ 1,075.00	
3824	Installed/Active	02/24/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3825	Installed/Active	02/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3826	Installed/Active	08/29/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3827	Installed/Active	04/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3828	Installed/Active	11/26/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
3829	Installed/Active	12/22/2000	PRX50	STATE	\$ 1,075.00	
3830	Installed/Active	05/21/1997	P506	RUUD	\$ 1,125.00	
3831	Installed/Active	07/07/1983	FSG50	AO SMITH	\$ 850.00	
3832	Installed/Active	02/01/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.05
3833	Installed/Active	12/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3834	Installed/Active	07/18/2003	FSG40	AO SMITH	\$ 850.00	
3835	Installed/Active	02/03/2005	FSG50	AO SMITH	\$ 850.00	
3836	Installed/Active	12/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
3837	Installed/Active	04/30/2003	PGR50	AO SMITH	\$ 850.00	
3838	Installed/Active	11/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
3839	Installed/Active	09/29/2011	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.64
3840	Installed/Active	02/09/2000	FSGL40	AO SMITH	\$ 850.00	
3841	Installed/Active	09/19/1998	G82156	RUUD/RHEEM	\$ 3,350.00	
3842	Installed/Active	05/28/2001	41V40S	RHEEM	\$ 850.00	
3843	Installed/Active	12/20/1984	FSG50	AO SMITH	\$ 850.00	
3844	Installed/Active	01/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
3845	Installed/Active	10/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3846	Installed/Active	06/01/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
3847	Installed/Active	03/27/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 10.23
3848	Installed/Active	11/04/2001	PGR40	AO SMITH	\$ 850.00	
3849	Installed/Active	11/29/2001	FSG50	AO SMITH	\$ 850.00	
3850	Installed/Active	07/22/2001	41V50	RHEEM	\$ 850.00	
3851	Installed/Active	02/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3852	Installed/Active	03/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
3853	Installed/Active	11/23/2002	PGR50	AO SMITH	\$ 850.00	
3854	Installed/Active	05/21/2002	FSGL40	AO SMITH	\$ 850.00	
3855	Installed/Active	08/12/2006	LTN040G	LOCHINVAR	\$ 850.00	
3856	Installed/Active	08/27/2001	FSG50	AO SMITH	\$ 850.00	
3857	Installed/Active	02/25/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
3858	Installed/Active	02/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3859	Installed/Active	12/30/1998	21V506	RHEEM	\$ 850.00	
3860	Installed/Active	05/12/2001	41V50	RHEEM	\$ 850.00	
3861	Installed/Active	01/08/1992	P502	RUUD	\$ 850.00	
3862	Installed/Active	01/17/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3863	Installed/Active	03/09/2007	GVC40	A. O. SMITH	\$ 850.00	\$ 10.23
3864	Installed/Active	02/21/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3865	Installed/Active	03/29/1984	KGA50	AO SMITH	\$ 850.00	
3866	Installed/Active	11/07/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
3867	Installed/Active	08/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3868	Installed/Active	05/10/1999	FSGL40	AO SMITH	\$ 850.00	
3869	Installed/Active	01/13/2004	PVR50	AO SMITH	\$ 850.00	
3870	Installed/Active	08/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3871	Installed/Active	01/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3872	Installed/Active	01/02/2004	FCV50	AO SMITH	\$ 850.00	
3873	Installed/Active	12/07/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3874	Installed/Active	02/23/2001	FSG50	AO SMITH	\$ 850.00	
3875	Installed/Active	10/20/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3876	Installed/Active	11/07/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
3877	Installed/Active	01/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3878	Installed/Active	01/16/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
3879	Installed/Active	05/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
3880	Installed/Active	03/30/2004	GVC50	A. O. SMITH	\$ 850.00	
3881	Installed/Active	03/16/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
3882	Installed/Active	01/26/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
3883	Installed/Active	02/22/2005	LTN050	LOCHINVAR	\$ 850.00	
3884	Installed/Active	02/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3885	Installed/Active	05/19/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
3886	Installed/Active	08/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3887	Installed/Active	07/26/2001	FSG50	AO SMITH	\$ 850.00	
3888	Installed/Active	01/05/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
3889	Installed/Active	03/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3890	Installed/Active	05/27/2003	PGR50	AO SMITH	\$ 850.00	
3891	Installed/Active	07/26/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
3892	Installed/Active	02/09/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3893	Installed/Active	07/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3894	Installed/Active	01/31/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
3895	Installed/Active	06/12/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
3896	Installed/Active	02/22/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3897	Installed/Active	03/26/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
3898	Installed/Active	04/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3899	Installed/Active	10/19/2001	FSG50	AO SMITH	\$ 850.00	
3900	Installed/Active	08/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3901	Installed/Active	09/10/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
3902	Installed/Active	02/07/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3903	Installed/Active	05/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3904	Installed/Active	11/27/1998	BTC197	AO SMITH	\$ 3,350.00	
3905	Installed/Active	01/11/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3906	Installed/Active	12/24/2002	FSG50	AO SMITH	\$ 850.00	
3907	Installed/Active	01/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3908	Installed/Active	12/01/1999	FGR50	AO SMITH	\$ 850.00	
3909	Installed/Active	02/24/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
3910	Installed/Active	08/28/2001	FSG50	AO SMITH	\$ 850.00	
3911	Installed/Active	11/01/1999	FSG40	AO SMITH	\$ 850.00	
3912	Installed/Active	12/20/2002	PGR50	AO SMITH	\$ 850.00	
3913	Installed/Active	02/26/1994	E71DUMMY	AO SMITH	\$ 3,350.00	
3914	Installed/Active	04/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
3915	Installed/Active	10/11/2006	LTN050G	LOCHINVAR	\$ 500.00	
3916	Installed/Active	04/13/2006	LSN041	LOCHINVAR	\$ 850.00	
3917	Installed/Active	09/27/1982	21V502	RHEEM	\$ 850.00	
3918	Installed/Active	09/16/2005	LTN040	LOCHINVAR	\$ 850.00	
3919	Installed/Active	03/29/1984	KGA50	AO SMITH	\$ 850.00	
3920	Installed/Active	01/03/2004	PGR40	AO SMITH	\$ 850.00	
3921	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
3922	Installed/Active	11/17/1998	FSGL40	AO SMITH	\$ 850.00	
3923	Installed/Active	12/17/1984	RM5063	RUUD	\$ 500.00	
3924	Installed/Active	02/21/2002	FSG50	AO SMITH	\$ 850.00	
3925	Installed/Active	07/13/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
3926	Installed/Active	10/27/1995	PHR50	RUUD	\$ 850.00	
3927	Installed/Active	05/05/2003	FSG50	AO SMITH	\$ 850.00	
3928	Installed/Active	03/20/2002	PGR50	AO SMITH	\$ 850.00	
3929	Installed/Active	12/06/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
3930	Installed/Active	06/06/2001	PRX50	STATE	\$ 1,075.00	
3931	Installed/Active	01/31/2003	FSG40	AO SMITH	\$ 850.00	
3932	Installed/Active	06/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
3933	Installed/Active	08/01/1997	PGR40	AO SMITH	\$ 850.00	
3934	Installed/Active	03/29/1997	FGR40	AO SMITH	\$ 850.00	
3935	Installed/Active	09/16/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
3936	Installed/Active	04/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3937	Installed/Active	03/03/2003	PGR50	AO SMITH	\$ 850.00	
3938	Installed/Active	08/04/2002	41XR50	RHEEM	\$ 850.00	
3939	Installed/Active	07/30/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
3940	Installed/Active	07/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
3941	Installed/Active	09/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
3942	Installed/Active	01/03/1997	H72DUMMY	AO SMITH	\$ 1,900.00	
3943	Installed/Active	11/13/2001	FSG50	AO SMITH	\$ 850.00	
3944	Installed/Active	12/07/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
3945	Installed/Active	11/26/2007	ETN076	LOCHINVAR	\$ 1,900.00	\$ 33.40
3946	Installed/Active	09/13/1996	FGR50	AO SMITH	\$ 850.00	
3947	Installed/Active	08/01/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
3948	Installed/Active	01/08/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
3949	Installed/Active	03/14/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3950	Installed/Active	03/13/2009	21VR40	RHEEM	\$ 850.00	\$ 11.74
3951	Installed/Active	08/25/2008	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
3952	Installed/Active	09/08/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
3953	Installed/Active	01/25/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
3954	Installed/Active	11/29/2007	PRX50	STATE	\$ 1,075.00	\$ 14.35
3955	Installed/Active	06/17/1987	FSG50	AO SMITH	\$ 850.00	
3956	Installed/Active	01/29/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
3957	Installed/Active	08/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3958	Installed/Active	06/24/2004	XVR50	A. O. SMITH	\$ 850.00	
3959	Installed/Active	05/06/2000	41VR40	RHEEM	\$ 850.00	
3960	Installed/Active	09/15/2003	PRX50	STATE	\$ 1,075.00	
3961	Installed/Active	07/28/2005	LTN050	LOCHINVAR	\$ 850.00	
3962	Installed/Active	02/21/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
3963	Installed/Active	12/20/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
3964	Installed/Active	11/18/1986	FSG50	AO SMITH	\$ 850.00	
3965	Installed/Active	05/17/2000	41XR50	RHEEM	\$ 850.00	
3966	Installed/Active	06/08/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
3967	Installed/Active	06/29/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
3968	Installed/Active	07/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3969	Installed/Active	10/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
3970	Installed/Active	12/04/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
3971	Installed/Active	05/07/2004	PVR50	AO SMITH	\$ 850.00	
3972	Installed/Active	11/24/1996	FSG50	AO SMITH	\$ 850.00	
3973	Installed/Active	09/28/2004	LTN050G	LOCHINVAR	\$ 850.00	
3974	Installed/Active	12/11/2003	PVR50	AO SMITH	\$ 850.00	
3975	Installed/Active	11/29/2001	PRX50	STATE	\$ 1,075.00	
3976	Installed/Active	04/20/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
3977	Installed/Active	02/28/2006	ETN076	LOCHINVAR	\$ 1,900.00	
3978	Installed/Active	09/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3979	Installed/Active	11/18/2003	41XR50	RHEEM	\$ 850.00	
3980	Installed/Active	12/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3981	Installed/Active	01/29/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
3982	Installed/Active	05/01/1987	FSG50	AO SMITH	\$ 850.00	
3983	Installed/Active	02/23/2001	PRX50	STATE	\$ 1,075.00	
3984	Installed/Active	11/09/2005	LTN040G	LOCHINVAR	\$ 850.00	
3985	Installed/Active	12/02/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
3986	Installed/Active	09/20/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
3987	Installed/Active	11/29/2005	LTN050G	LOCHINVAR	\$ 850.00	
3988	Installed/Active	02/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
3989	Installed/Active	04/20/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
3990	Installed/Active	10/06/2000	41V40S	RHEEM	\$ 850.00	
3991	Installed/Active	09/25/1986	FSG50	AO SMITH	\$ 1,125.00	
3992	Installed/Active	02/02/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
3993	Installed/Active	06/04/2001	41XR50	RHEEM	\$ 850.00	
3994	Installed/Active	04/25/1998	FSL40	AO SMITH	\$ 850.00	
3995	Installed/Active	08/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3996	Installed/Active	09/26/2006	ETN076	LOCHINVAR	\$ 1,900.00	
3997	Installed/Active	01/04/2008	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
3998	Installed/Active	11/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
3999	Installed/Active	03/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4000	Installed/Active	06/28/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
4001	Installed/Active	05/16/2002	BTR154	AO SMITH	\$ 3,350.00	
4002	Installed/Active	07/29/1997	FGR50	AO SMITH	\$ 850.00	
4003	Installed/Active	08/16/1998	FGR50	AO SMITH	\$ 850.00	
4004	Installed/Active	02/06/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4005	Installed/Active	11/11/1985	FSG50	AO SMITH	\$ 850.00	
4006	Installed/Active	04/30/2003	FSG50	AO SMITH	\$ 850.00	
4007	Installed/Active	12/29/2003	PRX50	STATE	\$ 1,075.00	
4008	Installed/Active	06/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4009	Installed/Active	04/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4010	Installed/Active	02/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
4011	Installed/Active	06/26/2002	FSG30	AO SMITH	\$ 850.00	
4012	Installed/Active	12/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
4013	Installed/Active	09/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4014	Installed/Active	02/09/2000	41V50	RHEEM	\$ 1,125.00	
4015	Installed/Active	07/16/2003	FSG50	AO SMITH	\$ 850.00	
4016	Installed/Active	08/11/2001	PGR50	AO SMITH	\$ 850.00	
4017	Installed/Active	04/25/2005	LTN050	LOCHINVAR	\$ 850.00	
4018	Installed/Active	10/10/2002	PRX50	STATE	\$ 1,075.00	
4019	Installed/Active	11/13/2002	FSL40	AO SMITH	\$ 850.00	
4020	Installed/Active	09/28/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
4021	Installed/Active	08/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4022	Installed/Active	11/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4023	Installed/Active	03/30/2000	FSG30	AO SMITH	\$ 850.00	
4024	Installed/Active	01/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4025	Installed/Active	06/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4026	Installed/Active	06/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
4027	Installed/Active	01/14/1997	PGR50	AO SMITH	\$ 850.00	
4028	Installed/Active	02/10/2005	GVC50	A. O. SMITH	\$ 850.00	
4029	Installed/Active	08/20/1985	G91200	RUUD/RHEEM	\$ 3,350.00	
4030	Installed/Active	07/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4031	Installed/Active	11/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4032	Installed/Active	02/20/2009	LTN050G	LOCHINVAR	\$ 500.00	\$ 18.76
4033	Installed/Active	03/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4034	Installed/Active	09/15/2003	FSG50	AO SMITH	\$ 850.00	
4035	Installed/Active	11/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4036	Installed/Active	04/26/2005	LTN050	LOCHINVAR	\$ 850.00	
4037	Installed/Active	06/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4038	Installed/Active	08/20/1996	PGR50	AO SMITH	\$ 850.00	
4039	Installed/Active	10/16/1998	PGR50	AO SMITH	\$ 850.00	
4040	Installed/Active	12/05/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
4041	Installed/Active	01/06/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
4042	Installed/Active	11/26/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4043	Installed/Active	04/05/2002	PGR50	AO SMITH	\$ 850.00	
4044	Installed/Active	03/24/2005	XVR50	A. O. SMITH	\$ 850.00	
4045	Installed/Active	11/03/2000	FSG50	AO SMITH	\$ 850.00	
4046	Installed/Active	11/10/2004	GVC50	A. O. SMITH	\$ 850.00	
4047	Installed/Active	02/27/1987	FSG50	AO SMITH	\$ 850.00	
4048	Installed/Active	01/20/2003	FSG50	AO SMITH	\$ 850.00	
4049	Installed/Active	11/10/1986	FSG50	AO SMITH	\$ 850.00	
4050	Installed/Active	03/26/2002	FSG50	AO SMITH	\$ 850.00	
4051	Installed/Active	10/09/2002	21V506	RHEEM	\$ 1,150.00	
4052	Installed/Active	01/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4053	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4054	Installed/Active	08/04/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4055	Installed/Active	12/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
4056	Installed/Active	11/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4057	Installed/Active	03/03/1998	FGR50	AO SMITH	\$ 850.00	
4058	Installed/Active	01/06/2001	41XR50	RHEEM	\$ 850.00	
4059	Installed/Active	04/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4060	Installed/Active	02/04/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
4061	Installed/Active	01/29/2003	FSG50	AO SMITH	\$ 850.00	
4062	Installed/Active	10/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4063	Installed/Active	01/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4064	Installed/Active	02/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4065	Installed/Active	10/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4066	Installed/Active	04/15/1987	FSG50	AO SMITH	\$ 850.00	
4067	Installed/Active	07/13/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
4068	Installed/Active	08/14/2001	PGR50	AO SMITH	\$ 850.00	
4069	Installed/Active	05/29/2003	PGR50	AO SMITH	\$ 850.00	
4070	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4071	Installed/Active	04/07/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4072	Installed/Active	08/10/2009	42XR50	RHEEM	\$ 850.00	\$ 11.74
4073	Installed/Active	04/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
4074	Installed/Active	07/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4075	Installed/Active	07/19/1995	FGR50	AO SMITH	\$ 850.00	
4076	Installed/Active	08/23/1999	FGR50	AO SMITH	\$ 850.00	
4077	Installed/Active	01/12/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4078	Installed/Active	05/11/1999	FGR50	AO SMITH	\$ 850.00	
4079	Installed/Active	12/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
4080	Installed/Active	03/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4081	Installed/Active	12/20/1986	FSG50	AO SMITH	\$ 850.00	
4082	Installed/Active	11/13/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
4083	Installed/Active	08/08/1995	PR502T	RUUD	\$ 850.00	
4084	Installed/Active	11/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4085	Installed/Active	11/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4086	Installed/Active	02/15/2006	PR640	STATE	\$ 1,075.00	
4087	Installed/Active	12/04/2007	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
4088	Installed/Active	03/21/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
4089	Installed/Active	06/18/1987	PRX50	STATE	\$ 1,075.00	
4090	Installed/Active	06/16/2003	FSG50	AO SMITH	\$ 850.00	
4091	Installed/Active	03/27/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
4092	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4093	Installed/Active	01/01/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
4094	Installed/Active	10/17/2003	PGR50	AO SMITH	\$ 850.00	
4095	Installed/Active	10/19/2005	LTN050G	LOCHINVAR	\$ 850.00	
4096	Installed/Active	04/29/1986	FSG50	AO SMITH	\$ 850.00	
4097	Installed/Active	06/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4098	Installed/Active	07/03/2006	LTN040G	LOCHINVAR	\$ 850.00	
4099	Installed/Active	03/20/2002	PGR50	AO SMITH	\$ 850.00	
4100	Installed/Active	05/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4101	Installed/Active	01/16/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4102	Installed/Active	03/08/1986	FSG50	AO SMITH	\$ 850.00	
4103	Installed/Active	02/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4104	Installed/Active	06/27/2005	PR650	STATE	\$ 1,075.00	
4105	Installed/Active	04/08/2005	SBF100199NES	STATE	\$ 3,350.00	
4106	Installed/Active	11/23/2005	FSGL40	AO SMITH	\$ 850.00	
4107	Installed/Active	12/30/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4108	Installed/Active	12/17/1985	FSGL40	AO SMITH	\$ 850.00	
4109	Installed/Active	03/20/1986	FSG50	AO SMITH	\$ 850.00	
4110	Installed/Active	01/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4111	Installed/Active	08/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4112	Installed/Active	02/28/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
4113	Installed/Active	11/10/2005	FGR50	AO SMITH	\$ 850.00	
4114	Installed/Active	08/18/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4115	Installed/Active	09/28/1999	FSG50	AO SMITH	\$ 850.00	
4116	Installed/Active	10/11/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
4117	Installed/Active	03/24/2004	XTN050	LOCHINVAR	\$ 850.00	
4118	Installed/Active	06/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4119	Installed/Active	09/20/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4120	Installed/Active	12/24/2009	LTN050G	LOCHINVAR	\$ 700.00	\$ 11.74
4121	Installed/Active	06/29/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
4122	Installed/Active	06/11/1997	G76200	RUUD/RHEEM	\$ 3,350.00	
4123	Installed/Active	05/15/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4124	Installed/Active	08/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4125	Installed/Active	06/12/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4126	Installed/Active	04/11/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
4127	Installed/Active	02/26/1996	G76200	RUUD/RHEEM	\$ 3,350.00	
4128	Installed/Active	02/25/2004	PVR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4129	Installed/Active	09/11/2003	PGR50	AO SMITH	\$ 850.00	
4130	Installed/Active	05/15/1996	BTC197	AO SMITH	\$ 3,350.00	
4131	Installed/Active	12/09/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
4132	Installed/Active	11/08/2003	PVR50	AO SMITH	\$ 850.00	
4133	Installed/Active	08/11/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
4134	Installed/Active	10/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4135	Installed/Active	05/24/2002	PGR50	AO SMITH	\$ 850.00	
4136	Installed/Active	07/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.51
4137	Installed/Active	11/08/2002	FSG50	AO SMITH	\$ 850.00	
4138	Installed/Active	09/27/2001	FSG50	AO SMITH	\$ 850.00	
4139	Installed/Active	11/01/2012	FGR50	AO SMITH	\$ 850.00	\$ 12.75
4140	Installed/Active	09/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4141	Installed/Active	09/22/2010	42VR50	RHEEM	\$ 850.00	\$ 7.51
4142	Installed/Active	01/02/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
4143	Installed/Active	12/12/2005	LTN050G	LOCHINVAR	\$ 850.00	
4144	Installed/Active	01/14/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
4145	Installed/Active	11/09/2001	FSG40	AO SMITH	\$ 850.00	
4146	Installed/Active	08/21/2003	FCV50	AO SMITH	\$ 850.00	
4147	Installed/Active	03/05/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4148	Installed/Active	11/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4149	Installed/Active	11/28/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
4150	Installed/Active	07/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4151	Installed/Active	02/06/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4152	Installed/Active	06/03/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4153	Installed/Active	02/01/1973	PGX50	AO SMITH	\$ 850.00	
4154	Installed/Active	08/29/2012	FGR50	AO SMITH	\$ 850.00	\$ 12.75
4155	Installed/Active	04/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
4156	Installed/Active	09/22/2002	PGR50	AO SMITH	\$ 850.00	
4157	Installed/Active	11/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
4158	Installed/Active	09/13/2000	41XR40	RHEEM	\$ 850.00	
4159	Installed/Active	09/12/2001	PGR50	AO SMITH	\$ 850.00	
4160	Installed/Active	09/11/2003	FSG50	AO SMITH	\$ 850.00	
4161	Installed/Active	10/11/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
4162	Installed/Active	09/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4163	Installed/Active	10/26/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4164	Installed/Active	06/18/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 44.60
4165	Installed/Active	05/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4166	Installed/Active	05/14/2003	21V506	RHEEM	\$ 1,150.00	
4167	Installed/Active	04/26/2002	PGR50	AO SMITH	\$ 850.00	
4168	Installed/Active	02/21/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4169	Installed/Active	07/15/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4170	Installed/Active	10/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4171	Installed/Active	09/14/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
4172	Installed/Active	01/23/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4173	Installed/Active	07/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4174	Installed/Active	12/20/1985	FSG50	AO SMITH	\$ 850.00	
4175	Installed/Active	02/06/2005	XTN050	LOCHINVAR	\$ 850.00	
4176	Installed/Active	04/12/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
4177	Installed/Active	10/29/2004	PRX50	STATE	\$ 1,075.00	
4178	Installed/Active	02/01/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
4179	Installed/Active	04/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4180	Installed/Active	03/08/1999	FGR50	AO SMITH	\$ 850.00	
4181	Installed/Active	10/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4182	Installed/Active	02/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4183	Installed/Active	07/13/2002	FSG50	AO SMITH	\$ 850.00	
4184	Installed/Active	11/13/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4185	Installed/Active	12/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4186	Installed/Active	09/13/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4187	Installed/Active	03/04/1998	FGR50	AO SMITH	\$ 850.00	
4188	Installed/Active	02/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4189	Installed/Active	09/08/1999	PGR50	AO SMITH	\$ 850.00	
4190	Installed/Active	01/08/2001	21V407	RHEEM	\$ 850.00	
4191	Installed/Active	01/08/2002	FSG50	AO SMITH	\$ 850.00	
4192	Installed/Active	09/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
4193	Installed/Active	11/25/2002	FSG50	AO SMITH	\$ 850.00	
4194	Installed/Active	09/22/1999	PR650	STATE	\$ 1,075.00	
4195	Installed/Active	06/13/1994	FGR50	AO SMITH	\$ 850.00	
4196	Installed/Active	08/29/2005	PR650	STATE	\$ 1,075.00	
4197	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4198	Installed/Active	03/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4199	Installed/Active	08/31/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
4200	Installed/Active	11/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4201	Installed/Active	12/18/1985	FSG50	AO SMITH	\$ 850.00	
4202	Installed/Active	03/22/2005	GVC50	A. O. SMITH	\$ 850.00	
4203	Installed/Active	03/13/2013	M15036FBN	Bradford - White	\$ 850.00	\$ 12.75
4204	Installed/Active	07/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4205	Installed/Active	02/25/1986	FSG50	AO SMITH	\$ 850.00	
4206	Installed/Active	05/14/1985	FSG50	AO SMITH	\$ 850.00	
4207	Installed/Active	07/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4208	Installed/Active	05/24/2001	41XR50	RHEEM	\$ 850.00	
4209	Installed/Active	07/19/2000	41XR50	RHEEM	\$ 850.00	
4210	Installed/Active	11/05/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4211	Installed/Active	08/29/1997	FSG50	AO SMITH	\$ 850.00	
4212	Installed/Active	04/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4213	Installed/Active	06/25/1999	FGR50	AO SMITH	\$ 850.00	
4214	Installed/Active	07/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4215	Installed/Active	05/19/2006	PR650	STATE	\$ 1,075.00	
4216	Installed/Active	03/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4217	Installed/Active	07/13/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
4218	Installed/Active	11/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4219	Installed/Active	08/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4220	Installed/Active	11/22/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4221	Installed/Active	10/01/2001	FSG50	AO SMITH	\$ 850.00	
4222	Installed/Active	08/09/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
4223	Installed/Active	02/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4224	Installed/Active	07/30/2003	PRX50	STATE	\$ 1,075.00	
4225	Installed/Active	10/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4226	Installed/Active	10/04/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4227	Installed/Active	09/07/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
4228	Installed/Active	07/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4229	Installed/Active	12/24/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
4230	Installed/Active	11/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
4231	Installed/Active	10/13/2000	FSG50	AO SMITH	\$ 850.00	
4232	Installed/Active	01/18/1999	PR650	STATE	\$ 1,075.00	
4233	Installed/Active	10/21/2002	PRX50	STATE	\$ 1,075.00	
4234	Installed/Active	09/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4235	Installed/Active	05/17/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4236	Installed/Active	02/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4237	Installed/Active	03/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4238	Installed/Active	03/04/2005	PRX50	STATE	\$ 1,075.00	
4239	Installed/Active	06/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4240	Installed/Active	09/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4241	Installed/Active	01/26/2005	GVR50	AO SMITH	\$ 850.00	
4242	Installed/Active	04/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
4243	Installed/Active	06/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4244	Installed/Active	09/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
4245	Installed/Active	05/12/2004	GVC50	A. O. SMITH	\$ 850.00	
4246	Installed/Active	06/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
4247	Installed/Active	08/28/1997	FSG50	AO SMITH	\$ 850.00	
4248	Installed/Active	07/12/1995	PR502T	RUUD	\$ 850.00	
4249	Installed/Active	06/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4250	Installed/Active	02/07/2002	PGR50	AO SMITH	\$ 850.00	
4251	Installed/Active	07/29/1987	PRV50NODS	STATE	\$ 1,075.00	
4252	Installed/Active	11/24/2004	GVC50	A. O. SMITH	\$ 850.00	
4253	Installed/Active	03/24/1987	FSG50	AO SMITH	\$ 850.00	
4254	Installed/Active	05/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4255	Installed/Active	12/09/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
4256	Installed/Active	09/24/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
4257	Installed/Active	06/18/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 44.60
4258	Installed/Active	01/13/1984	FSG50	AO SMITH	\$ 850.00	
4259	Installed/Active	07/06/2002	PGR40	AO SMITH	\$ 850.00	
4260	Installed/Active	01/24/2000	PGR50	AO SMITH	\$ 850.00	
4261	Installed/Active	06/10/1999	FSG50	AO SMITH	\$ 850.00	
4262	Installed/Active	03/23/2005	GVC50	A. O. SMITH	\$ 850.00	
4263	Installed/Active	08/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
4264	Installed/Active	02/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4265	Installed/Active	09/10/1998	21V506	RHEEM	\$ 500.00	
4266	Installed/Active	02/21/2003	FSGL40	AO SMITH	\$ 850.00	
4267	Installed/Active	03/20/2001	FSG50	AO SMITH	\$ 850.00	
4268	Installed/Active	03/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
4269	Installed/Active	06/03/1993	21V506	RHEEM	\$ 850.00	
4270	Installed/Active	07/19/2005	LTN050	LOCHINVAR	\$ 850.00	
4271	Installed/Active	02/01/1983	FSG50	AO SMITH	\$ 850.00	
4272	Installed/Active	11/01/1995	PGR50	AO SMITH	\$ 850.00	
4273	Installed/Active	06/30/2005	LTN040	LOCHINVAR	\$ 850.00	
4274	Installed/Active	08/19/2002	FSG40	AO SMITH	\$ 850.00	
4275	Installed/Active	10/26/2004	LTN050	LOCHINVAR	\$ 850.00	
4276	Installed/Active	03/23/2001	BTR154	AO SMITH	\$ 3,350.00	
4277	Installed/Active	07/25/2002	PGR50	AO SMITH	\$ 850.00	
4278	Installed/Active	08/13/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4279	Installed/Active	03/08/2000	FGR50	AO SMITH	\$ 850.00	
4280	Installed/Active	02/14/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
4281	Installed/Active	09/06/2000	FSG40	AO SMITH	\$ 850.00	
4282	Installed/Active	05/12/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4283	Installed/Active	10/05/1999	FSG40	AO SMITH	\$ 850.00	
4284	Installed/Active	05/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
4285	Installed/Active	04/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4286	Installed/Active	04/13/1999	FSG50	AO SMITH	\$ 850.00	
4287	Installed/Active	01/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4288	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4289	Installed/Active	12/18/1997	FSGL40	AO SMITH	\$ 850.00	
4290	Installed/Active	10/30/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
4291	Installed/Active	07/11/2000	P40S	RUUD	\$ 850.00	
4292	Installed/Active	12/09/2001	FSG50	AO SMITH	\$ 850.00	
4293	Installed/Active	11/20/1995	FSG50	AO SMITH	\$ 850.00	
4294	Installed/Active	09/25/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
4295	Installed/Active	06/23/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
4296	Installed/Active	09/22/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
4297	Installed/Active	12/04/2004	LTN050G	LOCHINVAR	\$ 850.00	
4298	Installed/Active	05/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4299	Installed/Active	12/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4300	Installed/Active	12/28/2006	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4301	Installed/Active	01/23/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4302	Installed/Active	01/27/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4303	Installed/Active	01/30/2002	FSG50	AO SMITH	\$ 850.00	
4304	Installed/Active	01/26/1996	PRX50	STATE	\$ 1,075.00	
4305	Installed/Active	09/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4306	Installed/Active	08/15/1999	FSG40	AO SMITH	\$ 850.00	
4307	Installed/Active	05/06/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4308	Installed/Active	12/02/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4309	Installed/Active	01/27/2000	41XR40	RHEEM	\$ 850.00	
4310	Installed/Active	05/13/2002	PGR50	AO SMITH	\$ 850.00	
4311	Installed/Active	11/03/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4312	Installed/Active	06/11/1986	FSG50	AO SMITH	\$ 850.00	
4313	Installed/Active	07/16/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4314	Installed/Active	03/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4315	Installed/Active	03/10/2005	GVC50	A. O. SMITH	\$ 850.00	
4316	Installed/Active	01/28/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4317	Installed/Active	06/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4318	Installed/Active	11/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4319	Installed/Active	04/09/1999	FGR50	AO SMITH	\$ 850.00	
4320	Installed/Active	07/10/2008	22DV50F	Rheem	\$ 1,075.00	\$ 14.35
4321	Installed/Active	04/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4322	Installed/Active	08/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4323	Installed/Active	08/08/2000	PGR50	AO SMITH	\$ 850.00	
4324	Installed/Active	02/25/2005	GCVL40	A. O. SMITH	\$ 850.00	
4325	Installed/Active	12/21/2004	H72DUMMY	AO SMITH	\$ 1,900.00	
4326	Installed/Active	09/29/2003	PGR50	AO SMITH	\$ 850.00	
4327	Installed/Active	12/30/2006	PR650	STATE	\$ 1,075.00	
4328	Installed/Active	08/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4329	Installed/Active	03/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4330	Installed/Active	03/10/1986	FSG50	AO SMITH	\$ 850.00	
4331	Installed/Active	02/09/1997	FGR50	AO SMITH	\$ 850.00	
4332	Installed/Active	03/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4333	Installed/Active	06/07/2002	PGR50	AO SMITH	\$ 850.00	
4334	Installed/Active	11/07/2004	XVR50	A. O. SMITH	\$ 850.00	
4335	Installed/Active	01/23/2006	GVC50	A. O. SMITH	\$ 850.00	
4336	Installed/Active	02/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4337	Installed/Active	08/19/2003	PGR50	AO SMITH	\$ 850.00	
4338	Installed/Active	10/24/1997	FSG50	AO SMITH	\$ 850.00	
4339	Installed/Active	12/29/2001	FSG50	AO SMITH	\$ 850.00	
4340	Installed/Active	01/08/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4341	Installed/Active	04/13/1987	FSG50	AO SMITH	\$ 850.00	
4342	Installed/Active	09/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4343	Installed/Active	09/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4344	Installed/Active	05/13/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4345	Installed/Active	06/19/2006	PRV40NODS	STATE	\$ 1,075.00	
4346	Installed/Active	11/05/2004	GVC50	A. O. SMITH	\$ 850.00	
4347	Installed/Active	03/11/1999	FSG30	AO SMITH	\$ 850.00	
4348	Installed/Active	09/02/2002	PRX40	STATE	\$ 1,075.00	
4349	Installed/Active	10/10/2003	FSG50	AO SMITH	\$ 850.00	
4350	Installed/Active	12/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4351	Installed/Active	04/22/1987	FSG50	AO SMITH	\$ 850.00	
4352	Installed/Active	07/14/2003	PRX50	STATE	\$ 1,075.00	
4353	Installed/Active	01/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4354	Installed/Active	05/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
4355	Installed/Active	08/17/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
4356	Installed/Active	08/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4357	Installed/Active	10/04/2001	PGR50	AO SMITH	\$ 850.00	
4358	Installed/Active	04/07/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4359	Installed/Active	04/24/2002	PGR50	AO SMITH	\$ 850.00	
4360	Installed/Active	04/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4361	Installed/Active	07/14/2000	BTR154	AO SMITH	\$ 3,350.00	
4362	Installed/Active	12/09/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
4363	Installed/Active	12/15/1986	BTR199	AO SMITH	\$ 3,350.00	
4364	Installed/Active	12/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4365	Installed/Active	09/14/1987	E71DUMMY	AO SMITH	\$ 3,350.00	
4366	Installed/Active	05/12/2010	21V506	RHEEM	\$ 1,125.00	\$ 19.26
4367	Installed/Active	01/31/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4368	Installed/Active	11/21/1999	41VR50	RHEEM	\$ 850.00	
4369	Installed/Active	11/26/2004	GCVL40	A. O. SMITH	\$ 850.00	
4370	Installed/Active	08/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4371	Installed/Active	09/07/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4372	Installed/Active	05/18/1995	RFD82156	RUUD	\$ 3,350.00	
4373	Installed/Active	01/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4374	Installed/Active	01/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4375	Installed/Active	11/19/1999	FSG50	AO SMITH	\$ 850.00	
4376	Installed/Active	09/29/2000	PGR50	AO SMITH	\$ 850.00	
4377	Installed/Active	04/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4378	Installed/Active	09/23/2005	LTN050G	LOCHINVAR	\$ 850.00	
4379	Installed/Active	12/09/2001	FSG50	AO SMITH	\$ 850.00	
4380	Installed/Active	12/14/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4381	Installed/Active	10/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4382	Installed/Active	09/23/2005	PR650	STATE	\$ 1,075.00	
4383	Installed/Active	05/23/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
4384	Installed/Active	01/17/2012	PRX50	STATE	\$ 1,075.00	\$ 17.74
4385	Installed/Active	02/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4386	Installed/Active	05/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4387	Installed/Active	02/11/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4388	Installed/Active	05/08/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
4389	Installed/Active	02/26/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4390	Installed/Active	05/18/1994	41XR40	RHEEM	\$ 850.00	
4391	Installed/Active	02/26/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4392	Installed/Active	01/22/2001	H72DUMMY	AO SMITH	\$ 1,900.00	
4393	Installed/Active	05/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4394	Installed/Active	10/22/1998	FSG50	AO SMITH	\$ 850.00	
4395	Installed/Active	05/02/2002	FSG50	AO SMITH	\$ 850.00	
4396	Installed/Active	12/08/1999	PGR50	AO SMITH	\$ 850.00	
4397	Installed/Active	04/05/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4398	Installed/Active	07/17/2005	LTN050	LOCHINVAR	\$ 850.00	
4399	Installed/Active	08/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4400	Installed/Active	08/31/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 7.51
4401	Installed/Active	12/30/2003	FCV50	AO SMITH	\$ 850.00	
4402	Installed/Active	12/28/2001	21V407	RHEEM	\$ 850.00	
4403	Installed/Active	02/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
4404	Installed/Active	10/17/2002	FSG40	AO SMITH	\$ 850.00	
4405	Installed/Active	11/11/2005	LTN040G	LOCHINVAR	\$ 850.00	
4406	Installed/Active	09/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4407	Installed/Active	11/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4408	Installed/Active	02/01/1971	A71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
4409	Installed/Active	03/04/1983	FSG50	AO SMITH	\$ 850.00	
4410	Installed/Active	09/13/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
4411	Installed/Active	01/03/1999	41VR50	RHEEM	\$ 850.00	
4412	Installed/Active	02/23/2004	PVR50	AO SMITH	\$ 850.00	
4413	Installed/Active	10/14/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
4414	Installed/Active	09/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4415	Installed/Active	12/26/2003	FSG30	AO SMITH	\$ 350.00	
4416	Installed/Active	07/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4417	Installed/Active	07/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4418	Installed/Active	11/13/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4419	Installed/Active	03/21/1988	FSG50	AO SMITH	\$ 850.00	
4420	Installed/Active	05/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4421	Installed/Active	12/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
4422	Installed/Active	08/14/1997	FGR50	AO SMITH	\$ 850.00	
4423	Installed/Active	11/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4424	Installed/Active	11/03/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
4425	Installed/Active	08/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4426	Installed/Active	03/22/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4427	Installed/Active	01/09/2003	FSG40	AO SMITH	\$ 850.00	
4428	Installed/Active	04/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4429	Installed/Active	12/02/1996	P506	RUUD	\$ 1,125.00	
4430	Installed/Active	11/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4431	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4432	Installed/Active	05/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
4433	Installed/Active	11/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4434	Installed/Active	02/08/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
4435	Installed/Active	09/08/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4436	Installed/Active	08/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4437	Installed/Active	09/24/1987	FSG50	AO SMITH	\$ 850.00	
4438	Installed/Active	06/16/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
4439	Installed/Active	04/12/1988	FSG50	AO SMITH	\$ 850.00	
4440	Installed/Active	08/17/1998	FSG50	AO SMITH	\$ 850.00	
4441	Installed/Active	10/18/1999	41VR50	RHEEM	\$ 850.00	
4442	Installed/Active	01/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
4443	Installed/Active	10/09/2001	PRX50	STATE	\$ 1,075.00	
4444	Installed/Active	06/07/2003	PGR50	AO SMITH	\$ 850.00	
4445	Installed/Active	03/11/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4446	Installed/Active	01/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4447	Installed/Active	05/30/2005	LTN050	LOCHINVAR	\$ 850.00	
4448	Installed/Active	05/05/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
4449	Installed/Active	08/22/2005	XSN040	LOCHINVAR	\$ 850.00	
4450	Installed/Active	12/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4451	Installed/Active	12/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4452	Installed/Active	07/10/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4453	Installed/Active	12/13/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
4454	Installed/Active	11/14/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4455	Installed/Active	04/04/1986	FSG50	AO SMITH	\$ 850.00	
4456	Installed/Active	08/27/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
4457	Installed/Active	06/25/2012	XTN050	LOCHINVAR	\$ 850.00	\$ 12.75
4458	Installed/Active	05/14/2002	FSSL40	AO SMITH	\$ 850.00	
4459	Installed/Active	08/12/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4460	Installed/Active	07/11/1998	PRV50NODS	STATE	\$ 1,075.00	
4461	Installed/Active	04/20/2004	GCVL40	A. O. SMITH	\$ 850.00	
4462	Installed/Active	06/28/2004	XVR50	A. O. SMITH	\$ 850.00	
4463	Installed/Active	08/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4464	Installed/Active	05/08/1996	FGR50	AO SMITH	\$ 850.00	
4465	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4466	Installed/Active	01/10/2000	PGR50	AO SMITH	\$ 850.00	
4467	Installed/Active	12/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4468	Installed/Active	09/25/1997	FSG50	AO SMITH	\$ 850.00	
4469	Installed/Active	08/16/1990	SBF100199NES	STATE	\$ 3,350.00	
4470	Installed/Active	01/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4471	Installed/Active	08/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
4472	Installed/Active	08/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4473	Installed/Active	11/04/1985	FSG50	AO SMITH	\$ 850.00	
4474	Installed/Active	01/06/1986	RF67120	RUUD	\$ 1,900.00	
4475	Installed/Active	10/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4476	Installed/Active	05/24/2001	FSG50	AO SMITH	\$ 850.00	
4477	Installed/Active	01/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4478	Installed/Active	10/07/2001	41VR50	RHEEM	\$ 850.00	
4479	Installed/Active	12/05/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4480	Installed/Active	10/26/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
4481	Installed/Active	02/28/1986	FSGL40	AO SMITH	\$ 850.00	
4482	Installed/Active	03/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4483	Installed/Active	11/18/1985	21V502	RHEEM	\$ 850.00	
4484	Installed/Active	01/02/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4485	Installed/Active	05/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
4486	Installed/Active	01/09/2002	PGR50	AO SMITH	\$ 850.00	
4487	Installed/Active	06/06/2000	FSG50	AO SMITH	\$ 850.00	
4488	Installed/Active	04/09/2003	FSG50	AO SMITH	\$ 850.00	
4489	Installed/Active	02/12/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
4490	Installed/Active	02/16/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4491	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4492	Installed/Active	02/12/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
4493	Installed/Active	04/20/2005	GVC50	A. O. SMITH	\$ 850.00	
4494	Installed/Active	06/10/2002	PGR50	AO SMITH	\$ 850.00	
4495	Installed/Active	06/21/2005	G82156	RUUD/RHEEM	\$ 3,350.00	
4496	Installed/Active	12/08/1997	FGR50	AO SMITH	\$ 850.00	
4497	Installed/Active	10/05/1998	FGR50	AO SMITH	\$ 850.00	
4498	Installed/Active	10/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4499	Installed/Active	01/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4500	Installed/Active	04/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4501	Installed/Active	12/05/2000	FSG50	AO SMITH	\$ 850.00	
4502	Installed/Active	07/06/1998	PGR50	AO SMITH	\$ 850.00	
4503	Installed/Active	09/06/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
4504	Installed/Active	07/18/2001	PGR50	AO SMITH	\$ 850.00	
4505	Installed/Active	06/09/2003	PRX40	STATE	\$ 1,075.00	
4506	Installed/Active	11/29/1994	PR502T	RUUD	\$ 850.00	
4507	Installed/Active	02/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4508	Installed/Active	03/02/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
4509	Installed/Active	05/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
4510	Installed/Active	09/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4511	Installed/Active	05/19/2006	PR650	STATE	\$ 1,075.00	
4512	Installed/Active	05/22/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4513	Installed/Active	12/24/2000	41V40	RHEEM	\$ 850.00	
4514	Installed/Active	05/01/2004	PRX50	STATE	\$ 1,075.00	
4515	Installed/Active	03/30/2005	GVC50	A. O. SMITH	\$ 850.00	
4516	Installed/Active	03/23/1987	FSG50	AO SMITH	\$ 850.00	
4517	Installed/Active	02/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
4518	Installed/Active	05/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
4519	Installed/Active	06/24/1986	FSG50	AO SMITH	\$ 850.00	
4520	Installed/Active	08/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4521	Installed/Active	09/19/1999	PHR50	RUUD	\$ 850.00	
4522	Installed/Active	08/31/2001	FSG50	AO SMITH	\$ 850.00	
4523	Installed/Active	10/31/1986	FSG50	AO SMITH	\$ 850.00	
4524	Installed/Active	11/14/1994	PR502T	RUUD	\$ 850.00	
4525	Installed/Active	01/29/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
4526	Installed/Active	03/07/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4527	Installed/Active	02/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
4528	Installed/Active	07/22/2003	FSGL40	AO SMITH	\$ 850.00	
4529	Installed/Active	08/24/1987	FSG50	AO SMITH	\$ 850.00	
4530	Installed/Active	12/24/2004	XVR50	A. O. SMITH	\$ 850.00	
4531	Installed/Active	06/15/2005	LTN050	LOCHINVAR	\$ 850.00	
4532	Installed/Active	05/02/1994	PHR50	RUUD	\$ 1,150.00	
4533	Installed/Active	04/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4534	Installed/Active	08/29/1986	FSG50	AO SMITH	\$ 850.00	
4535	Installed/Active	04/29/2002	FSG50	AO SMITH	\$ 850.00	
4536	Installed/Active	11/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4537	Installed/Active	08/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4538	Installed/Active	05/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
4539	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4540	Installed/Active	09/29/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4541	Installed/Active	05/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4542	Installed/Active	03/05/2003	PGR50	AO SMITH	\$ 850.00	
4543	Installed/Active	09/02/1997	PGR40	AO SMITH	\$ 850.00	
4544	Installed/Active	10/11/2002	PGR50	AO SMITH	\$ 850.00	
4545	Installed/Active	05/19/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4546	Installed/Active	02/18/2000	FSG40	AO SMITH	\$ 850.00	
4547	Installed/Active	07/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
4548	Installed/Active	05/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4549	Installed/Active	05/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4550	Installed/Active	11/15/2005	LTN040G	LOCHINVAR	\$ 850.00	
4551	Installed/Active	05/05/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4552	Installed/Active	09/20/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
4553	Installed/Active	02/23/2007	PGX50	AO SMITH	\$ 850.00	\$ 6.37
4554	Installed/Active	10/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4555	Installed/Active	11/25/1995	PGR50	AO SMITH	\$ 850.00	
4556	Installed/Active	03/28/2002	FSG50	AO SMITH	\$ 850.00	
4557	Installed/Active	03/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
4558	Installed/Active	07/03/2000	FSGL40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4559	Installed/Active	01/04/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
4560	Installed/Active	08/14/1996	FSGL40	AO SMITH	\$ 850.00	
4561	Installed/Active	04/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
4562	Installed/Active	04/24/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4563	Installed/Active	11/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4564	Installed/Active	10/03/2002	PGR50	AO SMITH	\$ 850.00	
4565	Installed/Active	08/12/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
4566	Installed/Active	10/23/2000	PGR50	AO SMITH	\$ 850.00	
4567	Installed/Active	10/01/1993	FSG50	AO SMITH	\$ 850.00	
4568	Installed/Active	08/23/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4569	Installed/Active	07/10/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.37
4570	Installed/Active	10/08/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
4571	Installed/Active	09/28/1984	FSG50	AO SMITH	\$ 850.00	
4572	Installed/Active	08/01/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
4573	Installed/Active	03/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4574	Installed/Active	12/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
4575	Installed/Active	07/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
4576	Installed/Active	02/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
4577	Installed/Active	08/13/2001	PGR50	AO SMITH	\$ 850.00	
4578	Installed/Active	12/29/1995	FGR50	AO SMITH	\$ 850.00	
4579	Installed/Active	08/30/1999	41VR50	RHEEM	\$ 850.00	
4580	Installed/Active	10/08/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4581	Installed/Active	03/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4582	Installed/Active	10/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4583	Installed/Active	02/16/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
4584	Installed/Active	01/15/2009	21VR40	RHEEM	\$ 850.00	\$ 11.74
4585	Installed/Active	10/20/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
4586	Installed/Active	07/10/2007	LTN051G	LOCHINVAR	\$ 850.00	\$ 6.37
4587	Installed/Active	07/14/2005	LSN041G	LOCHINVAR	\$ 850.00	
4588	Installed/Active	04/25/2001	41V50	RHEEM	\$ 850.00	
4589	Installed/Active	01/01/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
4590	Installed/Active	09/24/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4591	Installed/Active	06/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4592	Installed/Active	10/27/2003	PVR50	AO SMITH	\$ 850.00	
4593	Installed/Active	05/01/2009	RM5063	RUUD	\$ 500.00	\$ 18.76
4594	Installed/Active	06/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
4595	Installed/Active	07/26/2003	FSG50	AO SMITH	\$ 850.00	
4596	Installed/Active	02/11/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
4597	Installed/Active	03/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4598	Installed/Active	04/13/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
4599	Installed/Active	12/07/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4600	Installed/Active	12/12/2001	FSG50	AO SMITH	\$ 850.00	
4601	Installed/Active	08/31/2003	FSGL40	AO SMITH	\$ 850.00	
4602	Installed/Active	07/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
4603	Installed/Active	07/28/1993	FSG50	AO SMITH	\$ 850.00	
4604	Installed/Active	08/31/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4605	Installed/Active	03/10/2007	PR650	STATE	\$ 850.00	\$ 10.23
4606	Installed/Active	09/05/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4607	Installed/Active	08/09/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4608	Installed/Active	01/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4609	Installed/Active	12/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4610	Installed/Active	10/09/1997	PGR50	AO SMITH	\$ 850.00	
4611	Installed/Active	05/08/1986	F72DUMMY	AO SMITH	\$ 3,350.00	
4612	Installed/Active	12/14/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4613	Installed/Active	02/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4614	Installed/Active	03/30/2002	PGR50	AO SMITH	\$ 850.00	
4615	Installed/Active	01/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4616	Installed/Active	04/14/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4617	Installed/Active	07/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4618	Installed/Active	03/07/1985	FSG50	AO SMITH	\$ 850.00	
4619	Installed/Active	11/17/2006	PR650	STATE	\$ 1,075.00	
4620	Installed/Active	12/01/1995	RF67120	RUUD	\$ 1,900.00	
4621	Installed/Active	08/30/1985	FSG50	AO SMITH	\$ 850.00	
4622	Installed/Active	02/12/2002	FSG50	AO SMITH	\$ 850.00	
4623	Installed/Active	05/14/2001	FSG40	AO SMITH	\$ 850.00	
4624	Installed/Active	10/27/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4625	Installed/Active	01/11/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
4626	Installed/Active	06/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4627	Installed/Active	09/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4628	Installed/Active	06/20/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4629	Installed/Active	11/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4630	Installed/Active	01/03/2000	PHR50	RUUD	\$ 850.00	
4631	Installed/Active	09/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4632	Installed/Active	06/09/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4633	Installed/Active	10/20/1999	FGR50	AO SMITH	\$ 850.00	
4634	Installed/Active	04/28/2011	P506	RUUD	\$ 500.00	\$ 20.21
4635	Installed/Active	04/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4636	Installed/Active	01/09/2004	PVR50	AO SMITH	\$ 850.00	
4637	Installed/Active	11/08/2001	FSG50	AO SMITH	\$ 850.00	
4638	Installed/Active	11/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4639	Installed/Active	04/25/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4640	Installed/Active	12/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4641	Installed/Active	05/23/2003	FSG50	AO SMITH	\$ 850.00	
4642	Installed/Active	11/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
4643	Installed/Active	09/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4644	Installed/Active	12/16/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4645	Installed/Active	03/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4646	Installed/Active	08/28/2006	42VR50	RHEEM	\$ 850.00	
4647	Installed/Active	01/30/1995	PR502T	RUUD	\$ 850.00	
4648	Installed/Active	06/08/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
4649	Installed/Active	10/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4650	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4651	Installed/Active	02/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4652	Installed/Active	05/15/1988	FSG50	AO SMITH	\$ 850.00	
4653	Installed/Active	07/25/2005	LTN050	LOCHINVAR	\$ 850.00	
4654	Installed/Active	12/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
4655	Installed/Active	04/26/2002	41V40S	RHEEM	\$ 850.00	
4656	Installed/Active	05/10/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4657	Installed/Active	06/19/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
4658	Installed/Active	07/23/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
4659	Installed/Active	09/17/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
4660	Installed/Active	10/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4661	Installed/Active	05/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4662	Installed/Active	06/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4663	Installed/Active	05/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4664	Installed/Active	04/17/2004	PRX50	STATE	\$ 1,075.00	
4665	Installed/Active	12/01/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4666	Installed/Active	08/15/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4667	Installed/Active	12/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4668	Installed/Active	09/28/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4669	Installed/Active	06/25/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4670	Installed/Active	02/11/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
4671	Installed/Active	03/18/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4672	Installed/Active	04/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4673	Installed/Active	02/04/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4674	Installed/Active	07/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4675	Installed/Active	04/01/2001	41XR50	RHEEM	\$ 850.00	
4676	Installed/Active	11/23/1998	41VR50	RHEEM	\$ 850.00	
4677	Installed/Active	01/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	
4678	Installed/Active	04/20/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
4679	Installed/Active	07/18/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
4680	Installed/Active	12/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4681	Installed/Active	11/09/2004	GVC50	A. O. SMITH	\$ 850.00	
4682	Installed/Active	01/07/2005	LTN050G	LOCHINVAR	\$ 850.00	
4683	Installed/Active	05/27/2006	PR650	STATE	\$ 1,075.00	
4684	Installed/Active	09/07/2007	LSN041G	Lochinvar	\$ 850.00	\$ 10.23
4685	Installed/Active	01/03/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
4686	Installed/Active	06/13/1996	PGR40	AO SMITH	\$ 850.00	
4687	Installed/Active	09/06/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4688	Installed/Active	10/19/2004	GVC50	A. O. SMITH	\$ 850.00	
4689	Installed/Active	11/05/2004	XVR50	A. O. SMITH	\$ 850.00	
4690	Installed/Active	12/21/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
4691	Installed/Active	10/30/1995	FGR50	AO SMITH	\$ 850.00	
4692	Installed/Active	01/14/2000	FSG50	AO SMITH	\$ 850.00	
4693	Installed/Active	02/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4694	Installed/Active	03/26/1986	FSG50	AO SMITH	\$ 850.00	
4695	Installed/Active	12/08/2005	LTN050G	LOCHINVAR	\$ 850.00	
4696	Installed/Active	02/10/2010	PGR40	AO SMITH	\$ 850.00	\$ 11.74
4697	Installed/Active	10/04/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4698	Installed/Active	10/30/2001	PGR50	AO SMITH	\$ 850.00	
4699	Installed/Active	04/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4700	Installed/Active	02/23/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4701	Installed/Active	09/14/1995	PR502T	RUUD	\$ 850.00	
4702	Installed/Active	11/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4703	Installed/Active	12/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
4704	Installed/Active	02/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4705	Installed/Active	01/17/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4706	Installed/Active	10/18/1996	P506	RUUD	\$ 500.00	
4707	Installed/Active	03/27/1999	PHR50	RUUD	\$ 850.00	
4708	Installed/Active	10/03/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
4709	Installed/Active	11/07/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
4710	Installed/Active	11/17/2006	FSG50	AO SMITH	\$ 850.00	
4711	Installed/Active	01/09/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
4712	Installed/Active	09/01/1998	41VR50	RHEEM	\$ 850.00	
4713	Installed/Active	02/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4714	Installed/Active	03/02/2011	41VR40	RHEEM	\$ 850.00	\$ 12.05
4715	Installed/Active	11/12/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
4716	Installed/Active	01/20/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4717	Installed/Active	08/05/2002	PGR50	AO SMITH	\$ 850.00	
4718	Installed/Active	11/21/1999	PRV40NODS	STATE	\$ 1,075.00	
4719	Installed/Active	12/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
4720	Installed/Active	11/13/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4721	Installed/Active	01/03/1986	FSG50	AO SMITH	\$ 850.00	
4722	Installed/Active	05/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4723	Installed/Active	04/16/2004	PRX40	STATE	\$ 1,075.00	
4724	Installed/Active	05/13/1982	P40S	RUUD	\$ 850.00	
4725	Installed/Active	08/31/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 7.31
4726	Installed/Active	02/12/2001	41VR50	RHEEM	\$ 850.00	
4727	Installed/Active	08/25/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
4728	Installed/Active	05/24/2002	FSG50	AO SMITH	\$ 850.00	
4729	Installed/Active	08/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
4730	Installed/Active	06/24/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4731	Installed/Active	04/23/2004	FCV50	AO SMITH	\$ 850.00	
4732	Installed/Active	07/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 7.31
4733	Installed/Active	05/23/2011	21VR50	RHEEM	\$ 850.00	\$ 7.88
4734	Installed/Active	12/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4735	Installed/Active	03/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4736	Installed/Active	07/06/2005	LTN040	LOCHINVAR	\$ 850.00	
4737	Installed/Active	09/09/2003	FSG40	AO SMITH	\$ 850.00	
4738	Installed/Active	04/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4739	Installed/Active	05/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4740	Installed/Active	11/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
4741	Installed/Active	12/23/1993	PGR50	AO SMITH	\$ 850.00	
4742	Installed/Active	12/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
4743	Installed/Active	01/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4744	Installed/Active	11/18/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4745	Installed/Active	03/12/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
4746	Installed/Active	07/21/1999	PHR50	RUUD	\$ 850.00	
4747	Installed/Active	01/04/2005	GVC40	A. O. SMITH	\$ 850.00	
4748	Installed/Active	10/22/1999	PGR50	AO SMITH	\$ 850.00	
4749	Installed/Active	10/19/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4750	Installed/Active	04/06/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
4751	Installed/Active	10/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4752	Installed/Active	03/08/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
4753	Installed/Active	11/09/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
4754	Installed/Active	04/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
4755	Installed/Active	01/04/2000	FSG40	AO SMITH	\$ 850.00	
4756	Installed/Active	04/06/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
4757	Installed/Active	03/08/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
4758	Installed/Active	05/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4759	Installed/Active	04/03/2001	FSG50	AO SMITH	\$ 850.00	
4760	Installed/Active	03/09/2003	PRX50	STATE	\$ 1,075.00	
4761	Installed/Active	12/03/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4762	Installed/Active	11/19/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4763	Installed/Active	02/02/2003	FSG50	AO SMITH	\$ 850.00	
4764	Installed/Active	08/12/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4765	Installed/Active	02/16/2001	FSG50	AO SMITH	\$ 850.00	
4766	Installed/Active	12/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4767	Installed/Active	12/01/1971	PGX30	AO SMITH	\$ 850.00	
4768	Installed/Active	10/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
4769	Installed/Active	04/13/2001	41XR50	RHEEM	\$ 850.00	
4770	Installed/Active	03/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4771	Installed/Active	08/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4772	Installed/Active	01/20/2000	PGR50	AO SMITH	\$ 850.00	
4773	Installed/Active	06/29/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4774	Installed/Active	04/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4775	Installed/Active	02/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4776	Installed/Active	08/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4777	Installed/Active	12/05/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
4778	Installed/Active	11/01/1999	FSG50	AO SMITH	\$ 850.00	
4779	Installed/Active	09/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
4780	Installed/Active	08/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4781	Installed/Active	04/27/1987	P506	RUUD	\$ 1,125.00	
4782	Installed/Active	12/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4783	Installed/Active	04/03/2003	FSG50	AO SMITH	\$ 850.00	
4784	Installed/Active	12/29/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4785	Installed/Active	03/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4786	Installed/Active	08/26/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
4787	Installed/Active	02/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
4788	Installed/Active	10/09/2006	PR640	STATE	\$ 1,075.00	
4789	Installed/Active	08/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
4790	Installed/Active	02/29/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
4791	Installed/Active	11/02/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
4792	Installed/Active	12/22/2004	PRX50	STATE	\$ 1,075.00	
4793	Installed/Active	01/13/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4794	Installed/Active	12/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4795	Installed/Active	04/07/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
4796	Installed/Active	11/13/2001	PGR50	AO SMITH	\$ 850.00	
4797	Installed/Active	08/12/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
4798	Installed/Active	08/13/1998	21V407	RHEEM	\$ 850.00	
4799	Installed/Active	05/14/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4800	Installed/Active	03/07/2005	GVC50	A. O. SMITH	\$ 850.00	
4801	Installed/Active	01/13/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4802	Installed/Active	08/26/1995	FGR50	AO SMITH	\$ 850.00	
4803	Installed/Active	05/17/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
4804	Installed/Active	06/23/2004	XVR50	A. O. SMITH	\$ 850.00	
4805	Installed/Active	04/25/2000	PGR50	AO SMITH	\$ 850.00	
4806	Installed/Active	11/05/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4807	Installed/Active	04/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4808	Installed/Active	05/29/1995	BTC197	AO SMITH	\$ 3,350.00	
4809	Installed/Active	12/13/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4810	Installed/Active	01/09/2009	41V50	RHEEM	\$ 850.00	\$ 11.74
4811	Installed/Active	03/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4812	Installed/Active	04/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4813	Installed/Active	12/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4814	Installed/Active	01/10/2008	FSG50	AO SMITH	\$ 850.00	\$ 10.23
4815	Installed/Active	07/17/2001	PRX50	STATE	\$ 1,075.00	
4816	Installed/Active	07/01/1988	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4817	Installed/Active	07/17/2012	PH199119	PHOENIX	\$ 3,350.00	\$ 64.59
4818	Installed/Active	12/15/1999	PGR50	AO SMITH	\$ 850.00	
4819	Installed/Active	12/09/2003	FCV50	AO SMITH	\$ 850.00	
4820	Installed/Active	11/17/1999	FSG50	AO SMITH	\$ 850.00	
4821	Installed/Active	01/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4822	Installed/Active	11/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4823	Installed/Active	01/24/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.05
4824	Installed/Active	04/24/1995	FGR50	AO SMITH	\$ 850.00	
4825	Installed/Active	05/06/2004	XVR50	A. O. SMITH	\$ 850.00	
4826	Installed/Active	03/27/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4827	Installed/Active	07/08/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
4828	Installed/Active	03/21/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4829	Installed/Active	05/10/2001	PRV50NODS	STATE	\$ 1,075.00	
4830	Installed/Active	12/27/1995	FGR50	AO SMITH	\$ 850.00	
4831	Installed/Active	10/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
4832	Installed/Active	03/11/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
4833	Installed/Active	11/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4834	Installed/Active	11/29/1997	RFD91200	RUUD	\$ 3,350.00	
4835	Installed/Active	09/26/2001	41XR50	RHEEM	\$ 850.00	
4836	Installed/Active	04/14/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4837	Installed/Active	02/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4838	Installed/Active	06/26/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4839	Installed/Active	06/07/2001	PRX50	STATE	\$ 1,075.00	
4840	Installed/Active	05/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
4841	Installed/Active	07/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4842	Installed/Active	03/25/1988	21V506	RHEEM	\$ 500.00	
4843	Installed/Active	05/10/1988	FSG50	AO SMITH	\$ 850.00	
4844	Installed/Active	10/06/2009	PGR50	AO SMITH	\$ 850.00	\$ 11.74
4845	Installed/Active	05/17/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
4846	Installed/Active	03/06/1998	PRV50NODS	STATE	\$ 1,075.00	
4847	Installed/Active	03/17/2000	41XR50	RHEEM	\$ 850.00	
4848	Installed/Active	06/24/1988	FSG50	AO SMITH	\$ 850.00	
4849	Installed/Active	01/26/2003	PGR50	AO SMITH	\$ 850.00	
4850	Installed/Active	09/22/1987	RF67120	RUUD	\$ 1,900.00	
4851	Installed/Active	07/09/2004	XTN050	LOCHINVAR	\$ 850.00	
4852	Installed/Active	02/09/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4853	Installed/Active	08/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4854	Installed/Active	12/07/1998	PHR50	RUUD	\$ 850.00	
4855	Installed/Active	05/20/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
4856	Installed/Active	06/10/1988	FSG50	AO SMITH	\$ 850.00	
4857	Installed/Active	11/08/2004	XVR50	A. O. SMITH	\$ 850.00	
4858	Installed/Active	08/01/2000	PRV50NODS	STATE	\$ 1,075.00	
4859	Installed/Active	03/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4860	Installed/Active	11/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4861	Installed/Active	05/03/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4862	Installed/Active	02/13/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4863	Installed/Active	01/31/2002	FSG50	AO SMITH	\$ 850.00	
4864	Installed/Active	09/03/2004	GVC50	A. O. SMITH	\$ 850.00	
4865	Installed/Active	07/25/2005	LTN040	LOCHINVAR	\$ 850.00	
4866	Installed/Active	09/25/2001	FSG40	AO SMITH	\$ 850.00	
4867	Installed/Active	07/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4868	Installed/Active	10/15/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4869	Installed/Active	03/28/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
4870	Installed/Active	04/19/2005	GVC50	A. O. SMITH	\$ 850.00	
4871	Installed/Active	10/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4872	Installed/Active	11/02/1998	FSG40	AO SMITH	\$ 850.00	
4873	Installed/Active	03/13/1985	FSG50	AO SMITH	\$ 850.00	
4874	Installed/Active	05/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4875	Installed/Active	08/29/2005	LTN050G	LOCHINVAR	\$ 850.00	
4876	Installed/Active	10/16/2010	PRV50NODS	STATE	\$ 1,075.00	\$ 16.91
4877	Installed/Active	04/08/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4878	Installed/Active	08/21/2000	41XR50	RHEEM	\$ 850.00	
4879	Installed/Active	01/05/1996	PGR50	AO SMITH	\$ 850.00	
4880	Installed/Active	10/19/2005	LTN050G	LOCHINVAR	\$ 850.00	
4881	Installed/Active	01/19/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
4882	Installed/Active	10/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4883	Installed/Active	05/15/1999	FSG50	AO SMITH	\$ 850.00	
4884	Installed/Active	05/08/1985	RM50632	RUUD	\$ 500.00	
4885	Installed/Active	12/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
4886	Installed/Active	06/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4887	Installed/Active	11/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4888	Installed/Active	04/28/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
4889	Installed/Active	03/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4890	Installed/Active	11/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4891	Installed/Active	04/24/2004	FSG50	AO SMITH	\$ 850.00	
4892	Installed/Active	05/19/1986	P506	RUUD	\$ 1,150.00	
4893	Installed/Active	01/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
4894	Installed/Active	02/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4895	Installed/Active	05/06/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
4896	Installed/Active	03/11/2002	FSG50	AO SMITH	\$ 850.00	
4897	Installed/Active	01/12/2012	FGR50	AO SMITH	\$ 850.00	\$ 12.64
4898	Installed/Active	12/28/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4899	Installed/Active	04/04/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4900	Installed/Active	08/15/2000	41XR50	RHEEM	\$ 850.00	
4901	Installed/Active	11/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4902	Installed/Active	09/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4903	Installed/Active	07/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4904	Installed/Active	12/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4905	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4906	Installed/Active	11/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
4907	Installed/Active	05/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4908	Installed/Active	10/25/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4909	Installed/Active	10/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4910	Installed/Active	10/18/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
4911	Installed/Active	08/17/1987	FSG50	AO SMITH	\$ 850.00	
4912	Installed/Active	04/23/2004	GVC50	A. O. SMITH	\$ 850.00	
4913	Installed/Active	05/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
4914	Installed/Active	12/12/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4915	Installed/Active	01/18/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
4916	Installed/Active	04/11/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
4917	Installed/Active	03/09/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
4918	Installed/Active	07/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4919	Installed/Active	10/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4920	Installed/Active	11/16/2005	LTN050G	LOCHINVAR	\$ 850.00	
4921	Installed/Active	03/22/2003	PGR50	AO SMITH	\$ 850.00	
4922	Installed/Active	12/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4923	Installed/Active	11/07/1986	FSG40	AO SMITH	\$ 850.00	
4924	Installed/Active	01/03/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
4925	Installed/Active	02/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4926	Installed/Active	04/25/2002	FSG50	AO SMITH	\$ 850.00	
4927	Installed/Active	03/13/2001	FSG50	AO SMITH	\$ 850.00	
4928	Installed/Active	02/09/2001	41V40	RHEEM	\$ 850.00	
4929	Installed/Active	06/08/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4930	Installed/Active	10/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4931	Installed/Active	05/29/1999	21V506	RHEEM	\$ 850.00	
4932	Installed/Active	01/31/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
4933	Installed/Active	05/23/2006	GVC40	A. O. SMITH	\$ 850.00	
4934	Installed/Active	03/30/2001	PGR50	AO SMITH	\$ 850.00	
4935	Installed/Active	04/03/2006	LSN041G	LOCHINVAR	\$ 850.00	
4936	Installed/Active	08/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4937	Installed/Active	10/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4938	Installed/Active	05/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4939	Installed/Active	08/05/2003	PRX50	STATE	\$ 1,075.00	
4940	Installed/Active	10/05/1998	FGR50	AO SMITH	\$ 850.00	
4941	Installed/Active	07/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4942	Installed/Active	06/27/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
4943	Installed/Active	05/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4944	Installed/Active	11/02/2000	41VR50	RHEEM	\$ 850.00	
4945	Installed/Active	01/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4946	Installed/Active	12/20/1999	41XR50	RHEEM	\$ 850.00	
4947	Installed/Active	01/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4948	Installed/Active	04/22/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
4949	Installed/Active	10/15/2002	PGR50	AO SMITH	\$ 850.00	
4950	Installed/Active	08/28/1998	21V402S	RHEEM	\$ 850.00	
4951	Installed/Active	08/08/1983	FGL40	AO SMITH	\$ 850.00	
4952	Installed/Active	10/05/2000	41XR50	RHEEM	\$ 850.00	
4953	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
4954	Installed/Active	02/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
4955	Installed/Active	05/15/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
4956	Installed/Active	04/08/2004	GVC40	A. O. SMITH	\$ 850.00	
4957	Installed/Active	01/09/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
4958	Installed/Active	12/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4959	Installed/Active	05/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4960	Installed/Active	04/09/2002	FSG30	AO SMITH	\$ 850.00	
4961	Installed/Active	10/27/2003	FSG50	AO SMITH	\$ 850.00	
4962	Installed/Active	05/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4963	Installed/Active	03/09/1992	FSG40	AO SMITH	\$ 850.00	
4964	Installed/Active	10/22/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
4965	Installed/Active	03/22/2005	GVC50	A. O. SMITH	\$ 850.00	
4966	Installed/Active	05/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4967	Installed/Active	01/24/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.04
4968	Installed/Active	10/28/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
4969	Installed/Active	12/27/1984	FSG50	AO SMITH	\$ 850.00	
4970	Installed/Active	02/28/2002	PGR50	AO SMITH	\$ 850.00	
4971	Installed/Active	10/12/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
4972	Installed/Active	08/18/2009	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
4973	Installed/Active	09/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
4974	Installed/Active	05/24/2005	LTN050	LOCHINVAR	\$ 850.00	
4975	Installed/Active	03/03/1997	21V402S	RHEEM	\$ 850.00	
4976	Installed/Active	02/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
4977	Installed/Active	07/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
4978	Installed/Active	12/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
4979	Installed/Active	07/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
4980	Installed/Active	10/04/2005	LSN041G	LOCHINVAR	\$ 850.00	
4981	Installed/Active	11/11/2002	FSG50	AO SMITH	\$ 850.00	
4982	Installed/Active	03/23/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
4983	Installed/Active	05/18/2005	LTN050	LOCHINVAR	\$ 850.00	
4984	Installed/Active	04/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4985	Installed/Active	04/28/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 39.36
4986	Installed/Active	08/12/2002	PGR50	AO SMITH	\$ 850.00	
4987	Installed/Active	04/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
4988	Installed/Active	08/28/2002	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
4989	Installed/Active	07/23/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
4990	Installed/Active	03/03/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
4991	Installed/Active	07/23/2006	LSN041G	LOCHINVAR	\$ 850.00	
4992	Installed/Active	12/30/2004	PRX50	STATE	\$ 1,075.00	
4993	Installed/Active	05/20/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
4994	Installed/Active	09/15/2001	FSGL40	AO SMITH	\$ 850.00	
4995	Installed/Active	11/24/1999	FGR40	AO SMITH	\$ 850.00	
4996	Installed/Active	03/26/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
4997	Installed/Active	02/19/2004	PVR50	AO SMITH	\$ 850.00	
4998	Installed/Active	09/09/2004	GVC50	A. O. SMITH	\$ 850.00	
4999	Installed/Active	01/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5000	Installed/Active	06/12/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5001	Installed/Active	12/02/1987	FSG50	AO SMITH	\$ 850.00	
5002	Installed/Active	02/24/2005	GVC50	A. O. SMITH	\$ 850.00	
5003	Installed/Active	04/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5004	Installed/Active	08/12/1988	FSG50	AO SMITH	\$ 850.00	
5005	Installed/Active	05/16/2002	PGR50	AO SMITH	\$ 850.00	
5006	Installed/Active	09/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5007	Installed/Active	07/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5008	Installed/Active	02/17/1988	RF82156	RUUD	\$ 3,350.00	
5009	Installed/Active	10/15/2001	FSG40	AO SMITH	\$ 850.00	
5010	Installed/Active	10/11/2004	PRX50	STATE	\$ 1,075.00	
5011	Installed/Active	11/30/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5012	Installed/Active	10/23/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
5013	Installed/Active	04/17/2004	PRX50	STATE	\$ 1,075.00	
5014	Installed/Active	11/07/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
5015	Installed/Active	05/20/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
5016	Installed/Active	02/08/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
5017	Installed/Active	10/08/1987	FSG50	AO SMITH	\$ 850.00	
5018	Installed/Active	10/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5019	Installed/Active	01/09/2005	PRX40	STATE	\$ 1,075.00	
5020	Installed/Active	10/25/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5021	Installed/Active	03/08/2001	PGR50	AO SMITH	\$ 850.00	
5022	Installed/Active	08/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5023	Installed/Active	07/27/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
5024	Installed/Active	11/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
5025	Installed/Active	06/30/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
5026	Installed/Active	02/01/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5027	Installed/Active	06/30/2002	PGR50	AO SMITH	\$ 850.00	
5028	Installed/Active	03/05/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5029	Installed/Active	10/09/1985	FSG50	AO SMITH	\$ 850.00	
5030	Installed/Active	08/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5031	Installed/Active	08/23/1998	41V50	RHEEM	\$ 850.00	
5032	Installed/Active	02/26/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
5033	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5034	Installed/Active	11/05/2003	PGR50	AO SMITH	\$ 850.00	
5035	Installed/Active	07/20/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
5036	Installed/Active	11/09/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
5037	Installed/Active	12/18/2006	LSN041G	LOCHINVAR	\$ 850.00	
5038	Installed/Active	08/11/2003	PRX50	STATE	\$ 1,075.00	
5039	Installed/Active	05/11/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
5040	Installed/Active	07/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5041	Installed/Active	10/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5042	Installed/Active	04/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5043	Installed/Active	03/20/2002	PGR50	AO SMITH	\$ 850.00	
5044	Installed/Active	05/23/2001	FSG50	AO SMITH	\$ 850.00	
5045	Installed/Active	05/31/1985	FSG50	AO SMITH	\$ 850.00	
5046	Installed/Active	09/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5047	Installed/Active	01/05/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
5048	Installed/Active	06/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5049	Installed/Active	09/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5050	Installed/Active	03/01/2013	M1403S6FBN	BRADFORD WHITE	\$ 744.00	\$ 12.75
5051	Installed/Active	09/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5052	Installed/Active	08/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5053	Installed/Active	03/30/2005	GVC50	A. O. SMITH	\$ 850.00	
5054	Installed/Active	03/01/2013	FSGL40	AO SMITH	\$ 850.00	\$ 12.75
5055	Installed/Active	01/20/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
5056	Installed/Active	06/17/2003	PR650	STATE	\$ 1,075.00	
5057	Installed/Active	12/19/2003	41XR50	RHEEM	\$ 850.00	
5058	Installed/Active	10/01/2004	LTN050G	LOCHINVAR	\$ 850.00	
5059	Installed/Active	03/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5060	Installed/Active	05/20/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
5061	Installed/Active	04/21/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
5062	Installed/Active	03/13/2002	FSG50	AO SMITH	\$ 850.00	
5063	Installed/Active	05/31/2000	PGR50	AO SMITH	\$ 850.00	
5064	Installed/Active	05/25/1999	21V506	RHEEM	\$ 1,150.00	
5065	Installed/Active	12/28/2007	PR640XODS	STATE	\$ 1,075.00	\$ 14.35
5066	Installed/Active	12/14/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5067	Installed/Active	05/03/2002	PGR50	AO SMITH	\$ 850.00	
5068	Installed/Active	06/10/2003	FSG50	AO SMITH	\$ 850.00	
5069	Installed/Active	01/07/2002	FSG50	AO SMITH	\$ 850.00	
5070	Installed/Active	11/28/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5071	Installed/Active	11/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5072	Installed/Active	07/01/2001	PGR50	AO SMITH	\$ 850.00	
5073	Installed/Active	04/20/2003	FSG50	AO SMITH	\$ 850.00	
5074	Installed/Active	01/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5075	Installed/Active	07/05/2003	PVR50	AO SMITH	\$ 850.00	
5076	Installed/Active	01/10/2002	PRX50	STATE	\$ 1,075.00	
5077	Installed/Active	05/30/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
5078	Installed/Active	04/16/2012	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.37
5079	Installed/Active	12/28/2001	41XR50	RHEEM	\$ 850.00	
5080	Installed/Active	11/23/1998	21V506	RHEEM	\$ 1,125.00	
5081	Installed/Active	10/07/2008	PGR50	AO SMITH	\$ 850.00	\$ 10.23
5082	Installed/Active	08/20/2003	PRX50	STATE	\$ 1,075.00	
5083	Installed/Active	04/05/2006	LTN040G	LOCHINVAR	\$ 850.00	
5084	Installed/Active	06/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5085	Installed/Active	01/25/2002	FSG50	AO SMITH	\$ 850.00	
5086	Installed/Active	07/07/2004	GVC40	A. O. SMITH	\$ 850.00	
5087	Installed/Active	12/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5088	Installed/Active	06/17/2003	FSG50	AO SMITH	\$ 850.00	
5089	Installed/Active	12/09/1998	PR502T	RUUD	\$ 850.00	
5090	Installed/Active	05/22/2003	PRV50NODS	STATE	\$ 1,075.00	
5091	Installed/Active	03/06/2006	LTN051G	LOCHINVAR	\$ 850.00	
5092	Installed/Active	11/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5093	Installed/Active	03/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5094	Installed/Active	02/14/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.05
5095	Installed/Active	10/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5096	Installed/Active	09/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
5097	Installed/Active	01/27/2004	FSG50	AO SMITH	\$ 850.00	
5098	Installed/Active	11/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5099	Installed/Active	06/22/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5100	Installed/Active	10/01/1996	PGR50	AO SMITH	\$ 850.00	
5101	Installed/Active	04/14/1997	FGR50	AO SMITH	\$ 850.00	
5102	Installed/Active	03/17/1987	FSG50	AO SMITH	\$ 850.00	
5103	Installed/Active	10/25/2002	PRX50	STATE	\$ 1,075.00	
5104	Installed/Active	04/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5105	Installed/Active	10/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
5106	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5107	Installed/Active	09/08/1999	41VR50	RHEEM	\$ 850.00	
5108	Installed/Active	08/11/2000	PRX50	STATE	\$ 1,075.00	
5109	Installed/Active	06/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5110	Installed/Active	11/30/2004	GVC40	A. O. SMITH	\$ 850.00	
5111	Installed/Active	07/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
5112	Installed/Active	07/01/2003	PGR50	AO SMITH	\$ 850.00	
5113	Installed/Active	06/17/2005	LTN050	LOCHINVAR	\$ 850.00	
5114	Installed/Active	02/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5115	Installed/Active	08/22/1993	FSG50	AO SMITH	\$ 850.00	
5116	Installed/Active	01/12/2005	XVR50	A. O. SMITH	\$ 850.00	
5117	Installed/Active	02/13/2001	FSG50	AO SMITH	\$ 850.00	
5118	Installed/Active	02/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5119	Installed/Active	09/29/2008	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
5120	Installed/Active	08/30/2000	41XR50	RHEEM	\$ 850.00	
5121	Installed/Active	10/29/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
5122	Installed/Active	07/02/2001	FSG40	AO SMITH	\$ 850.00	
5123	Installed/Active	07/31/2004	XTN050	LOCHINVAR	\$ 850.00	
5124	Installed/Active	07/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
5125	Installed/Active	05/23/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
5126	Installed/Active	09/21/2006	LSN041G	LOCHINVAR	\$ 850.00	
5127	Installed/Active	01/11/1984	KGA50	AO SMITH	\$ 850.00	
5128	Installed/Active	03/31/2002	FSGL40	AO SMITH	\$ 850.00	
5129	Installed/Active	10/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5130	Installed/Active	04/03/2007	41V50	RHEEM	\$ 850.00	\$ 10.23
5131	Installed/Active	08/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5132	Installed/Active	02/08/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5133	Installed/Active	04/04/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
5134	Installed/Active	03/01/1983	FSG50	AO SMITH	\$ 850.00	
5135	Installed/Active	02/05/2002	FSGL40	AO SMITH	\$ 850.00	
5136	Installed/Active	07/02/1998	PRV40NODS	STATE	\$ 1,075.00	
5137	Installed/Active	01/02/1991	FSG50	AO SMITH	\$ 850.00	
5138	Installed/Active	08/09/1999	FGR50	AO SMITH	\$ 850.00	
5139	Installed/Active	10/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
5140	Installed/Active	01/18/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5141	Installed/Active	10/30/2000	PGR50	AO SMITH	\$ 850.00	
5142	Installed/Active	10/11/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5143	Installed/Active	07/01/2002	21V506	RHEEM	\$ 1,125.00	
5144	Installed/Active	08/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
5145	Installed/Active	04/03/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5146	Installed/Active	02/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
5147	Installed/Active	08/18/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
5148	Installed/Active	03/11/1997	PGR50	AO SMITH	\$ 850.00	
5149	Installed/Active	05/13/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5150	Installed/Active	02/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5151	Installed/Active	06/16/2005	LTN050	LOCHINVAR	\$ 850.00	
5152	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
5153	Installed/Active	10/26/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5154	Installed/Active	10/11/2011	PGR50	AO SMITH	\$ 850.00	\$ 12.64
5155	Installed/Active	12/06/2002	PRX40	STATE	\$ 1,075.00	
5156	Installed/Active	01/22/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5157	Installed/Active	03/16/2004	PRX50	STATE	\$ 1,075.00	
5158	Installed/Active	05/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
5159	Installed/Active	08/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
5160	Installed/Active	04/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5161	Installed/Active	11/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5162	Installed/Active	02/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
5163	Installed/Active	12/06/1985	FSG50	AO SMITH	\$ 850.00	
5164	Installed/Active	09/16/1999	FSGL40	AO SMITH	\$ 850.00	
5165	Installed/Active	08/26/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5166	Installed/Active	06/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
5167	Installed/Active	12/06/1985	FSG50	AO SMITH	\$ 850.00	
5168	Installed/Active	02/10/2003	FSGL40	AO SMITH	\$ 850.00	
5169	Installed/Active	08/25/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5170	Installed/Active	04/03/2001	41V50	RHEEM	\$ 850.00	
5171	Installed/Active	11/05/2001	PGR50	AO SMITH	\$ 850.00	
5172	Installed/Active	12/08/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5173	Installed/Active	07/19/2004	XVR50	A. O. SMITH	\$ 850.00	
5174	Installed/Active	01/11/2006	LTN050	LOCHINVAR	\$ 850.00	
5175	Installed/Active	04/23/2011	21DV50	RHEEM	\$ 1,075.00	\$ 17.74
5176	Installed/Active	07/27/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5177	Installed/Active	11/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5178	Installed/Active	03/10/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5179	Installed/Active	12/16/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
5180	Installed/Active	04/10/2003	41V50	RHEEM	\$ 500.00	
5181	Installed/Active	10/24/2005	LTN040G	LOCHINVAR	\$ 850.00	
5182	Installed/Active	01/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5183	Installed/Active	03/07/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5184	Installed/Active	10/27/2006	LSN041G	LOCHINVAR	\$ 850.00	
5185	Installed/Active	06/07/1985	FSGL40	AO SMITH	\$ 850.00	
5186	Installed/Active	09/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5187	Installed/Active	03/12/1985	FSG50	AO SMITH	\$ 850.00	
5188	Installed/Active	03/13/2000	21V506	RHEEM	\$ 1,125.00	
5189	Installed/Active	04/02/1985	FSG50	AO SMITH	\$ 850.00	
5190	Installed/Active	06/13/2004	XSN040	LOCHINVAR	\$ 850.00	
5191	Installed/Active	01/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5192	Installed/Active	06/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5193	Installed/Active	12/14/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5194	Installed/Active	01/06/2005	GVR50	AO SMITH	\$ 850.00	
5195	Installed/Active	04/04/2003	PRX50	STATE	\$ 1,075.00	
5196	Installed/Active	06/13/2003	FSGL40	AO SMITH	\$ 850.00	
5197	Installed/Active	09/14/2004	GVC50	A. O. SMITH	\$ 850.00	
5198	Installed/Active	10/06/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5199	Installed/Active	09/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5200	Installed/Active	10/19/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
5201	Installed/Active	11/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5202	Installed/Active	04/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5203	Installed/Active	03/26/2003	FSG40	AO SMITH	\$ 850.00	
5204	Installed/Active	03/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5205	Installed/Active	08/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5206	Installed/Active	11/14/1997	FSGL40	AO SMITH	\$ 850.00	
5207	Installed/Active	06/03/1988	FSG50	AO SMITH	\$ 850.00	
5208	Installed/Active	06/01/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
5209	Installed/Active	10/06/1998	FSG40	AO SMITH	\$ 850.00	
5210	Installed/Active	03/23/2007	FSG50	AO SMITH	\$ 850.00	\$ 10.23
5211	Installed/Active	10/25/2004	LTN050	LOCHINVAR	\$ 850.00	
5212	Installed/Active	12/27/2001	41V50	RHEEM	\$ 850.00	
5213	Installed/Active	04/27/1988	FSG50	AO SMITH	\$ 850.00	
5214	Installed/Active	11/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5215	Installed/Active	08/09/1988	FSG50	AO SMITH	\$ 850.00	
5216	Installed/Active	06/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5217	Installed/Active	05/10/2005	FSG50	AO SMITH	\$ 850.00	
5218	Installed/Active	02/24/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5219	Installed/Active	04/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5220	Installed/Active	11/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5221	Installed/Active	02/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5222	Installed/Active	04/22/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5223	Installed/Active	08/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5224	Installed/Active	09/13/2000	FGR50	AO SMITH	\$ 850.00	
5225	Installed/Active	09/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5226	Installed/Active	03/09/1996	FSGL40	AO SMITH	\$ 850.00	
5227	Installed/Active	09/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5228	Installed/Active	04/03/2002	PRX50	STATE	\$ 1,075.00	
5229	Installed/Active	02/13/2004	FSG50	AO SMITH	\$ 850.00	
5230	Installed/Active	03/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5231	Installed/Active	07/10/2002	PRX50	STATE	\$ 1,075.00	
5232	Installed/Active	04/25/2001	PGR50	AO SMITH	\$ 850.00	
5233	Installed/Active	09/08/1998	FSG40	AO SMITH	\$ 850.00	
5234	Installed/Active	07/25/2004	GVC50	A. O. SMITH	\$ 850.00	
5235	Installed/Active	12/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5236	Installed/Active	03/13/2008	42XR50	RHEEM	\$ 850.00	\$ 10.23
5237	Installed/Active	11/10/2004	GVC50	A. O. SMITH	\$ 850.00	
5238	Installed/Active	10/23/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
5239	Installed/Active	12/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5240	Installed/Active	07/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5241	Installed/Active	01/17/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5242	Installed/Active	07/17/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5243	Installed/Active	05/04/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
5244	Installed/Active	08/24/2004	GVC50	A. O. SMITH	\$ 850.00	
5245	Installed/Active	09/17/1997	PGR40	AO SMITH	\$ 850.00	
5246	Installed/Active	09/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5247	Installed/Active	03/09/2007	XTN050	LOCHINVAR	\$ 850.00	\$ 10.23
5248	Installed/Active	01/07/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5249	Installed/Active	04/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5250	Installed/Active	04/16/2004	XVR50	A. O. SMITH	\$ 850.00	
5251	Installed/Active	01/04/2001	FSG50	AO SMITH	\$ 850.00	
5252	Installed/Active	01/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5253	Installed/Active	03/24/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5254	Installed/Active	12/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5255	Installed/Active	11/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5256	Installed/Active	09/22/1998	FSG50	AO SMITH	\$ 850.00	
5257	Installed/Active	02/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5258	Installed/Active	08/30/1985	H72DUMMY	AO SMITH	\$ 1,900.00	
5259	Installed/Active	03/30/1999	FGR50	AO SMITH	\$ 850.00	
5260	Installed/Active	09/10/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5261	Installed/Active	12/30/1992	FSG50	AO SMITH	\$ 850.00	
5262	Installed/Active	04/21/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5263	Installed/Active	05/06/1985	FSG50	AO SMITH	\$ 850.00	
5264	Installed/Active	05/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5265	Installed/Active	11/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5266	Installed/Active	02/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5267	Installed/Active	03/05/2007	GVC40	A. O. SMITH	\$ 850.00	\$ 10.23
5268	Installed/Active	10/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5269	Installed/Active	02/06/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5270	Installed/Active	03/10/2003	PGR50	AO SMITH	\$ 850.00	
5271	Installed/Active	04/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5272	Installed/Active	04/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
5273	Installed/Active	07/26/2004	GDVS50	AOSMITH	\$ 1,075.00	
5274	Installed/Active	06/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5275	Installed/Active	06/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5276	Installed/Active	08/17/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
5277	Installed/Active	11/01/1985	FSG50	AO SMITH	\$ 850.00	
5278	Installed/Active	09/13/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5279	Installed/Active	04/01/2004	GCVL40	A. O. SMITH	\$ 850.00	
5280	Installed/Active	11/22/1999	PGR50	AO SMITH	\$ 850.00	
5281	Installed/Active	04/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
5282	Installed/Active	05/30/2002	PGR50	AO SMITH	\$ 850.00	
5283	Installed/Active	04/30/2009	41V50	RHEEM	\$ 850.00	\$ 11.74
5284	Installed/Active	09/27/2001	FSG50	AO SMITH	\$ 850.00	
5285	Installed/Active	09/08/2000	41XR50	RHEEM	\$ 850.00	
5286	Installed/Active	04/24/2005	PRX50	STATE	\$ 1,075.00	
5287	Installed/Active	07/10/1999	PRV50NODS	STATE	\$ 1,075.00	
5288	Installed/Active	01/12/2005	LTN050	LOCHINVAR	\$ 850.00	
5289	Installed/Active	01/12/2004	PVR50	AO SMITH	\$ 850.00	
5290	Installed/Active	01/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
5291	Installed/Active	10/26/2001	FSG50	AO SMITH	\$ 850.00	
5292	Installed/Active	05/25/2000	PGR50	AO SMITH	\$ 850.00	
5293	Installed/Active	02/06/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
5294	Installed/Active	09/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5295	Installed/Active	07/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5296	Installed/Active	11/04/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5297	Installed/Active	03/18/1987	FSG50	AO SMITH	\$ 850.00	
5298	Installed/Active	03/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
5299	Installed/Active	03/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5300	Installed/Active	12/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5301	Installed/Active	10/05/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5302	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
5303	Installed/Active	08/15/1999	41VR50	RHEEM	\$ 850.00	
5304	Installed/Active	09/20/2000	41XR50	RHEEM	\$ 850.00	
5305	Installed/Active	12/10/1998	FGR50	AO SMITH	\$ 850.00	
5306	Installed/Active	01/05/2006	PR650	STATE	\$ 1,075.00	
5307	Installed/Active	02/12/1987	FSG50	AO SMITH	\$ 850.00	
5308	Installed/Active	02/23/2009	FSG30	AO SMITH	\$ 350.00	\$ 14.35
5309	Installed/Active	03/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5310	Installed/Active	11/26/2007	G82156	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
5311	Installed/Active	03/20/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
5312	Installed/Active	04/01/2003	FSGL40	AO SMITH	\$ 850.00	
5313	Installed/Active	03/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5314	Installed/Active	05/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5315	Installed/Active	04/28/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
5316	Installed/Active	02/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5317	Installed/Active	05/21/2002	FSG50	AO SMITH	\$ 850.00	
5318	Installed/Active	06/27/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5319	Installed/Active	06/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5320	Installed/Active	10/25/2002	PGR50	AO SMITH	\$ 850.00	
5321	Installed/Active	05/26/1998	FSG50	AO SMITH	\$ 850.00	
5322	Installed/Active	07/22/2004	GDVS50	AOSMITH	\$ 1,075.00	
5323	Installed/Active	12/13/2000	41VR50	RHEEM	\$ 850.00	
5324	Installed/Active	09/03/1996	FSGL40	AO SMITH	\$ 850.00	
5325	Installed/Active	04/06/2005	FCVL40	AO SMITH	\$ 850.00	
5326	Installed/Active	08/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5327	Installed/Active	03/08/2011	41VR40	RHEEM	\$ 850.00	\$ 12.05
5328	Installed/Active	11/27/1998	PHR50	RUUD	\$ 850.00	
5329	Installed/Active	05/06/2001	41XR50	RHEEM	\$ 850.00	
5330	Installed/Active	11/29/2002	FSG50	AO SMITH	\$ 850.00	
5331	Installed/Active	09/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5332	Installed/Active	02/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5333	Installed/Active	08/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5334	Installed/Active	07/25/1997	FSGL40	AO SMITH	\$ 850.00	
5335	Installed/Active	06/26/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5336	Installed/Active	07/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
5337	Installed/Active	03/14/2000	FSGL40	AO SMITH	\$ 850.00	
5338	Installed/Active	02/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
5339	Installed/Active	08/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
5340	Installed/Active	09/27/2002	FSG50	AO SMITH	\$ 850.00	
5341	Installed/Active	07/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5342	Installed/Active	09/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5343	Installed/Active	02/07/1997	FGR40	AO SMITH	\$ 850.00	
5344	Installed/Active	02/13/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5345	Installed/Active	06/07/1999	FSG50	AO SMITH	\$ 850.00	
5346	Installed/Active	08/07/1995	41XR40	RHEEM	\$ 850.00	
5347	Installed/Active	09/02/1997	FSG50	AO SMITH	\$ 850.00	
5348	Installed/Active	10/23/1995	41XR40	RHEEM	\$ 850.00	
5349	Installed/Active	06/03/1992	E71DUMMY	AO SMITH	\$ 3,350.00	
5350	Installed/Active	06/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
5351	Installed/Active	05/13/2002	PGR40	AO SMITH	\$ 850.00	
5352	Installed/Active	07/23/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
5353	Installed/Active	03/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5354	Installed/Active	02/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5355	Installed/Active	11/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
5356	Installed/Active	05/16/2002	PGR50	AO SMITH	\$ 850.00	
5357	Installed/Active	02/07/2003	PGR50	AO SMITH	\$ 850.00	
5358	Installed/Active	09/23/1997	FGR50	AO SMITH	\$ 1,125.00	
5359	Installed/Active	09/10/1997	FGR50	AO SMITH	\$ 850.00	
5360	Installed/Active	04/05/2004	PVR50	AO SMITH	\$ 850.00	
5361	Installed/Active	02/14/1999	FSG50	AO SMITH	\$ 850.00	
5362	Installed/Active	07/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
5363	Installed/Active	01/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5364	Installed/Active	03/10/2005	GVC50	A. O. SMITH	\$ 850.00	
5365	Installed/Active	08/17/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5366	Installed/Active	10/23/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
5367	Installed/Active	04/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5368	Installed/Active	10/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5369	Installed/Active	07/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5370	Installed/Active	11/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5371	Installed/Active	06/05/2001	FSG50	AO SMITH	\$ 850.00	
5372	Installed/Active	08/17/2004	GVC50	A. O. SMITH	\$ 850.00	
5373	Installed/Active	12/17/1987	FSG50	AO SMITH	\$ 850.00	
5374	Installed/Active	03/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
5375	Installed/Active	10/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5376	Installed/Active	03/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5377	Installed/Active	03/08/1988	FSG50	AO SMITH	\$ 850.00	
5378	Installed/Active	09/21/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5379	Installed/Active	04/22/2002	PGR50	AO SMITH	\$ 850.00	
5380	Installed/Active	08/28/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
5381	Installed/Active	05/08/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5382	Installed/Active	02/04/1988	FSG50	AO SMITH	\$ 850.00	
5383	Installed/Active	03/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5384	Installed/Active	02/09/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
5385	Installed/Active	11/07/2001	PGR50	AO SMITH	\$ 850.00	
5386	Installed/Active	01/27/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
5387	Installed/Active	05/24/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5388	Installed/Active	02/27/1999	41VR50	RHEEM	\$ 850.00	
5389	Installed/Active	04/20/2006	LTN040G	LOCHINVAR	\$ 850.00	
5390	Installed/Active	05/15/2003	FSG50	AO SMITH	\$ 850.00	
5391	Installed/Active	05/09/2005	LTN050	LOCHINVAR	\$ 850.00	
5392	Installed/Active	03/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5393	Installed/Active	02/17/2010	21V502	RHEEM	\$ 850.00	\$ 11.74
5394	Installed/Active	03/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5395	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5396	Installed/Active	01/21/2002	41VR50	RHEEM	\$ 850.00	
5397	Installed/Active	11/21/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5398	Installed/Active	11/10/2006	LSN041G	LOCHINVAR	\$ 850.00	
5399	Installed/Active	04/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5400	Installed/Active	08/08/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5401	Installed/Active	09/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5402	Installed/Active	02/02/1988	FSG50	AO SMITH	\$ 850.00	
5403	Installed/Active	10/18/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5404	Installed/Active	10/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5405	Installed/Active	03/25/2000	41XR50	RHEEM	\$ 850.00	
5406	Installed/Active	01/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5407	Installed/Active	08/18/2005	LTN050	LOCHINVAR	\$ 850.00	
5408	Installed/Active	09/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5409	Installed/Active	09/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5410	Installed/Active	09/20/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
5411	Installed/Active	06/03/1988	FSGL30	AO SMITH	\$ 350.00	
5412	Installed/Active	02/14/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5413	Installed/Active	12/16/1985	FSG40	AO SMITH	\$ 850.00	
5414	Installed/Active	03/20/2001	41V50	RHEEM	\$ 850.00	
5415	Installed/Active	10/29/2005	PR650	STATE	\$ 1,075.00	
5416	Installed/Active	06/17/2002	FSG50	AO SMITH	\$ 850.00	
5417	Installed/Active	12/06/1999	PHR50	RUUD	\$ 850.00	
5418	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5419	Installed/Active	11/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5420	Installed/Active	06/03/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5421	Installed/Active	04/14/2011	PGR50	AO SMITH	\$ 850.00	\$ 12.64
5422	Installed/Active	01/21/2006	LSN041G	LOCHINVAR	\$ 850.00	
5423	Installed/Active	06/27/2000	FSG40	AO SMITH	\$ 850.00	
5424	Installed/Active	11/16/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
5425	Installed/Active	10/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
5426	Installed/Active	06/22/2006	LSN041G	LOCHINVAR	\$ 850.00	
5427	Installed/Active	11/01/2003	FCV50	AO SMITH	\$ 850.00	
5428	Installed/Active	12/07/1999	PGR50	AO SMITH	\$ 850.00	
5429	Installed/Active	03/22/2004	FCV50	AO SMITH	\$ 850.00	
5430	Installed/Active	12/23/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5431	Installed/Active	01/16/2001	FSG40	AO SMITH	\$ 850.00	
5432	Installed/Active	10/16/2002	FSG50	AO SMITH	\$ 850.00	
5433	Installed/Active	04/30/2004	PRX40	STATE	\$ 1,075.00	
5434	Installed/Active	09/10/2005	GVC50	A. O. SMITH	\$ 850.00	
5435	Installed/Active	05/13/1986	PRV50NODS	STATE	\$ 1,075.00	
5436	Installed/Active	02/03/2001	41XR40	RHEEM	\$ 850.00	
5437	Installed/Active	03/14/1999	FGR50	AO SMITH	\$ 850.00	
5438	Installed/Active	05/15/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5439	Installed/Active	06/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5440	Installed/Active	03/02/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5441	Installed/Active	03/17/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
5442	Installed/Active	02/15/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.05
5443	Installed/Active	03/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5444	Installed/Active	04/29/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5445	Installed/Active	11/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5446	Installed/Active	06/17/2005	LTN050	LOCHINVAR	\$ 850.00	
5447	Installed/Active	07/05/2006	PR640	STATE	\$ 1,075.00	
5448	Installed/Active	05/11/1994	PRV40NODS	STATE	\$ 1,075.00	
5449	Installed/Active	02/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5450	Installed/Active	01/10/2002	FSG50	AO SMITH	\$ 850.00	
5451	Installed/Active	05/02/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
5452	Installed/Active	02/09/1996	PRX50	STATE	\$ 1,075.00	
5453	Installed/Active	06/29/2001	PGR50	AO SMITH	\$ 850.00	
5454	Installed/Active	04/22/1997	FSG40	AO SMITH	\$ 850.00	
5455	Installed/Active	10/21/2002	PGR50	AO SMITH	\$ 850.00	
5456	Installed/Active	04/12/2005	GVC50	A. O. SMITH	\$ 850.00	
5457	Installed/Active	04/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5458	Installed/Active	07/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5459	Installed/Active	07/01/1986	G72DUMMY	UNKNOWN AT CONVERSION	\$ 500.00	
5460	Installed/Active	09/25/1997	41VR50	RHEEM	\$ 850.00	
5461	Installed/Active	02/19/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
5462	Installed/Active	12/20/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5463	Installed/Active	07/04/2005	LTN050G	LOCHINVAR	\$ 850.00	
5464	Installed/Active	02/17/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
5465	Installed/Active	08/16/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
5466	Installed/Active	06/23/2004	GVC50	A. O. SMITH	\$ 850.00	
5467	Installed/Active	06/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5468	Installed/Active	02/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5469	Installed/Active	10/24/2000	PGR50	AO SMITH	\$ 850.00	
5470	Installed/Active	02/12/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
5471	Installed/Active	10/12/2005	LSN041G	LOCHINVAR	\$ 850.00	
5472	Installed/Active	01/12/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
5473	Installed/Active	10/31/2002	FSG40	AO SMITH	\$ 850.00	
5474	Installed/Active	05/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
5475	Installed/Active	03/14/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5476	Installed/Active	09/28/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5477	Installed/Active	07/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5478	Installed/Active	09/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5479	Installed/Active	01/21/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5480	Installed/Active	08/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5481	Installed/Active	01/30/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5482	Installed/Active	06/21/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
5483	Installed/Active	12/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5484	Installed/Active	01/27/2004	PVR50	AO SMITH	\$ 850.00	
5485	Installed/Active	01/18/2003	FSG40	AO SMITH	\$ 850.00	
5486	Installed/Active	11/07/1986	FSG50	AO SMITH	\$ 850.00	
5487	Installed/Active	12/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5488	Installed/Active	09/01/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
5489	Installed/Active	07/21/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
5490	Installed/Active	08/08/2001	PRX50	STATE	\$ 1,075.00	
5491	Installed/Active	05/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5492	Installed/Active	04/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5493	Installed/Active	09/19/2005	PR650	STATE	\$ 1,075.00	
5494	Installed/Active	04/15/2005	FCV40	AO SMITH	\$ 850.00	
5495	Installed/Active	05/07/2004	CPN199100	LOCHINVAR	\$ 3,350.00	
5496	Installed/Active	03/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5497	Installed/Active	06/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5498	Installed/Active	05/28/2002	PGR50	AO SMITH	\$ 850.00	
5499	Installed/Active	12/27/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
5500	Installed/Active	11/04/1992	P506	RUUD	\$ 1,125.00	
5501	Installed/Active	10/19/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
5502	Installed/Active	08/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5503	Installed/Active	04/07/2005	GCVL40	A. O. SMITH	\$ 850.00	
5504	Installed/Active	02/11/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5505	Installed/Active	08/29/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
5506	Installed/Active	01/26/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5507	Installed/Active	11/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5508	Installed/Active	04/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5509	Installed/Active	05/01/2001	FSG50	AO SMITH	\$ 850.00	
5510	Installed/Active	06/22/2004	GCVL40	A. O. SMITH	\$ 850.00	
5511	Installed/Active	01/20/2000	41XR40	RHEEM	\$ 850.00	
5512	Installed/Active	08/07/2000	G76200	RUUD/RHEEM	\$ 3,350.00	
5513	Installed/Active	10/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5514	Installed/Active	04/12/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
5515	Installed/Active	12/29/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
5516	Installed/Active	10/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5517	Installed/Active	03/28/1996	PGR40	AO SMITH	\$ 850.00	
5518	Installed/Active	08/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5519	Installed/Active	07/21/2010	LSN041	LOCHINVAR	\$ 850.00	\$ 12.05
5520	Installed/Active	10/13/2000	FSG50	AO SMITH	\$ 850.00	
5521	Installed/Active	10/23/2009	PGX50	AO SMITH	\$ 850.00	\$ 5.88
5522	Installed/Active	11/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5523	Installed/Active	06/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5524	Installed/Active	08/08/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.88
5525	Installed/Active	11/27/2001	41XR50	RHEEM	\$ 850.00	
5526	Installed/Active	07/21/2000	FSG40	AO SMITH	\$ 850.00	
5527	Installed/Active	01/24/2001	FSG30	AO SMITH	\$ 850.00	
5528	Installed/Active	11/13/2003	FSGL30	AO SMITH	\$ 850.00	
5529	Installed/Active	04/04/2000	FSG50	AO SMITH	\$ 850.00	
5530	Installed/Active	08/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5531	Installed/Active	09/13/1983	FSG50	AO SMITH	\$ 850.00	
5532	Installed/Active	01/07/2002	PGR50	AO SMITH	\$ 850.00	
5533	Installed/Active	10/26/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 6.37
5534	Installed/Active	04/10/2006	LTN040G	LOCHINVAR	\$ 850.00	
5535	Installed/Active	07/01/1986	G72DUMMY	UNKNOWN AT CONVERSION	\$ 500.00	
5536	Installed/Active	02/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5537	Installed/Active	08/17/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5538	Installed/Active	05/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5539	Installed/Active	11/27/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5540	Installed/Active	03/15/1985	FSG50	AO SMITH	\$ 850.00	
5541	Installed/Active	01/11/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
5542	Installed/Active	08/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5543	Installed/Active	04/26/2002	PRX50	STATE	\$ 1,075.00	
5544	Installed/Active	06/21/2006	CPN13585FS	LOCHINVAR	\$ 1,900.00	
5545	Installed/Active	01/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5546	Installed/Active	12/28/2004	LTN050	LOCHINVAR	\$ 850.00	
5547	Installed/Active	04/26/1996	PGR50	AO SMITH	\$ 850.00	
5548	Installed/Active	09/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
5549	Installed/Active	10/17/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5550	Installed/Active	07/21/2005	LSN041G	LOCHINVAR	\$ 850.00	
5551	Installed/Active	09/30/2005	LTN050G	LOCHINVAR	\$ 850.00	
5552	Installed/Active	10/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5553	Installed/Active	06/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5554	Installed/Active	04/04/1986	FSG50	AO SMITH	\$ 850.00	
5555	Installed/Active	05/19/1998	FSG40	AO SMITH	\$ 850.00	
5556	Installed/Active	11/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5557	Installed/Active	12/20/2005	LTN050G	LOCHINVAR	\$ 850.00	
5558	Installed/Active	12/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5559	Installed/Active	10/29/1988	FSG50	AO SMITH	\$ 850.00	
5560	Installed/Active	07/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5561	Installed/Active	04/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5562	Installed/Active	01/20/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
5563	Installed/Active	06/11/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5564	Installed/Active	11/09/2002	FSG50	AO SMITH	\$ 850.00	
5565	Installed/Active	04/26/2004	PVR50	AO SMITH	\$ 850.00	
5566	Installed/Active	08/18/2000	FSG50	AO SMITH	\$ 850.00	
5567	Installed/Active	02/17/2004	FCV40	AO SMITH	\$ 850.00	
5568	Installed/Active	12/19/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5569	Installed/Active	04/12/2001	PGR50	AO SMITH	\$ 850.00	
5570	Installed/Active	01/30/2006	LTN040G	LOCHINVAR	\$ 850.00	
5571	Installed/Active	12/06/1999	PR650	STATE	\$ 1,075.00	
5572	Installed/Active	02/06/2006	LSN041G	LOCHINVAR	\$ 850.00	
5573	Installed/Active	01/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5574	Installed/Active	09/11/2002	FSG50	AO SMITH	\$ 850.00	
5575	Installed/Active	11/12/2003	FSGL40	AO SMITH	\$ 850.00	
5576	Installed/Active	04/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5577	Installed/Active	02/19/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
5578	Installed/Active	02/18/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
5579	Installed/Active	01/07/2002	PGR50	AO SMITH	\$ 850.00	
5580	Installed/Active	10/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5581	Installed/Active	10/10/2002	PGR50	AO SMITH	\$ 850.00	
5582	Installed/Active	10/20/2003	FCV50	AO SMITH	\$ 850.00	
5583	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
5584	Installed/Active	02/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5585	Installed/Active	08/21/2003	PR650	STATE	\$ 1,075.00	
5586	Installed/Active	08/23/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5587	Installed/Active	09/19/2003	21V506	RHEEM	\$ 1,125.00	
5588	Installed/Active	07/16/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5589	Installed/Active	12/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5590	Installed/Active	09/08/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5591	Installed/Active	06/20/2005	LTN050	LOCHINVAR	\$ 850.00	
5592	Installed/Active	07/15/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5593	Installed/Active	09/01/1988	FSG50	AO SMITH	\$ 850.00	
5594	Installed/Active	01/08/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5595	Installed/Active	04/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5596	Installed/Active	10/27/2002	FSG50	AO SMITH	\$ 850.00	
5597	Installed/Active	02/21/1998	FSG50	AO SMITH	\$ 850.00	
5598	Installed/Active	05/13/2004	FSGT50	AO SMITH	\$ 850.00	
5599	Installed/Active	03/22/2011	P506	RUUD	\$ 1,125.00	\$ 19.26
5600	Installed/Active	03/06/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5601	Installed/Active	03/20/1999	FGR50	AO SMITH	\$ 850.00	
5602	Installed/Active	12/03/2002	PRX50	STATE	\$ 1,075.00	
5603	Installed/Active	10/21/1987	H72DUMMY	AO SMITH	\$ 1,900.00	
5604	Installed/Active	04/29/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5605	Installed/Active	09/20/1988	FSG50	AO SMITH	\$ 850.00	
5606	Installed/Active	07/06/1999	FSG50	AO SMITH	\$ 850.00	
5607	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5608	Installed/Active	08/30/2006	LTN040G	LOCHINVAR	\$ 850.00	
5609	Installed/Active	07/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
5610	Installed/Active	04/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5611	Installed/Active	07/09/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5612	Installed/Active	12/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
5613	Installed/Active	01/15/2006	LTN040G	LOCHINVAR	\$ 850.00	
5614	Installed/Active	12/17/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5615	Installed/Active	05/22/2000	BTR120	AO SMITH	\$ 1,900.00	
5616	Installed/Active	03/25/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
5617	Installed/Active	05/21/2000	41XR50	RHEEM	\$ 850.00	
5618	Installed/Active	01/27/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
5619	Installed/Active	06/04/2001	FSG50	AO SMITH	\$ 850.00	
5620	Installed/Active	02/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5621	Installed/Active	08/18/2004	GVC50	A. O. SMITH	\$ 850.00	
5622	Installed/Active	02/17/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5623	Installed/Active	06/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
5624	Installed/Active	06/18/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
5625	Installed/Active	07/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5626	Installed/Active	12/27/1999	41XR50	RHEEM	\$ 850.00	
5627	Installed/Active	03/08/2005	GVC40	A. O. SMITH	\$ 850.00	
5628	Installed/Active	12/26/2003	PRX50	STATE	\$ 1,075.00	
5629	Installed/Active	09/17/2002	FSG50	AO SMITH	\$ 850.00	
5630	Installed/Active	12/31/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 11.74
5631	Installed/Active	08/25/2008	22DV50F	RHEEM	\$ 850.00	\$ 10.23
5632	Installed/Active	01/12/2004	PRX50	STATE	\$ 1,075.00	
5633	Installed/Active	06/23/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5634	Installed/Active	12/10/2003	PGR50	AO SMITH	\$ 850.00	
5635	Installed/Active	08/20/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5636	Installed/Active	04/28/2006	LTN050	LOCHINVAR	\$ 850.00	
5637	Installed/Active	04/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5638	Installed/Active	05/01/2001	PRX50	STATE	\$ 1,075.00	
5639	Installed/Active	09/09/2002	PGR50	AO SMITH	\$ 850.00	
5640	Installed/Active	02/12/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5641	Installed/Active	03/18/2004	PRX50	STATE	\$ 1,075.00	
5642	Installed/Active	07/24/1996	G76200	RUUD/RHEEM	\$ 3,350.00	
5643	Installed/Active	11/12/2002	PGR50	AO SMITH	\$ 850.00	
5644	Installed/Active	04/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5645	Installed/Active	08/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
5646	Installed/Active	01/26/2010	FSG50	AO SMITH	\$ 850.00	\$ 11.74
5647	Installed/Active	06/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5648	Installed/Active	10/30/2003	FCV50	AO SMITH	\$ 850.00	
5649	Installed/Active	12/01/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
5650	Installed/Active	01/07/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5651	Installed/Active	12/11/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
5652	Installed/Active	01/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5653	Installed/Active	12/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5654	Installed/Active	12/25/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5655	Installed/Active	02/06/2001	PRV50NODS	STATE	\$ 1,075.00	
5656	Installed/Active	12/29/1997	PGR50	AO SMITH	\$ 850.00	
5657	Installed/Active	01/05/2001	41XR50	RHEEM	\$ 850.00	
5658	Installed/Active	03/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5659	Installed/Active	11/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5660	Installed/Active	07/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
5661	Installed/Active	01/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5662	Installed/Active	11/21/2000	PRX50	STATE	\$ 1,075.00	
5663	Installed/Active	02/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5664	Installed/Active	02/12/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5665	Installed/Active	10/01/2002	41XR50	RHEEM	\$ 850.00	
5666	Installed/Active	10/06/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5667	Installed/Active	12/28/2004	XVR50	A. O. SMITH	\$ 850.00	
5668	Installed/Active	11/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
5669	Installed/Active	12/14/2001	FSG50	AO SMITH	\$ 850.00	
5670	Installed/Active	10/03/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
5671	Installed/Active	09/24/2002	FSG50	AO SMITH	\$ 850.00	
5672	Installed/Active	12/05/2005	LTN050	LOCHINVAR	\$ 850.00	
5673	Installed/Active	01/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	
5674	Installed/Active	01/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5675	Installed/Active	08/03/2000	41XR50	RHEEM	\$ 850.00	
5676	Installed/Active	03/28/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5677	Installed/Active	09/16/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
5678	Installed/Active	03/10/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
5679	Installed/Active	06/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5680	Installed/Active	11/06/2006	PR650	STATE	\$ 1,075.00	
5681	Installed/Active	11/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5682	Installed/Active	05/20/2003	PGR50	AO SMITH	\$ 850.00	
5683	Installed/Active	09/15/2002	FSG30	AO SMITH	\$ 850.00	
5684	Installed/Active	01/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5685	Installed/Active	05/24/1999	FSG50	AO SMITH	\$ 850.00	
5686	Installed/Active	05/07/1985	FSG50	AO SMITH	\$ 850.00	
5687	Installed/Active	06/17/2004	GVC50	A. O. SMITH	\$ 850.00	
5688	Installed/Active	12/01/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5689	Installed/Active	02/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5690	Installed/Active	04/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5691	Installed/Active	06/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5692	Installed/Active	05/23/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 10.23
5693	Installed/Active	11/25/1997	PGR50	AO SMITH	\$ 850.00	
5694	Installed/Active	06/25/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
5695	Installed/Active	04/09/2000	PRX50	STATE	\$ 1,075.00	
5696	Installed/Active	05/27/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
5697	Installed/Active	02/04/2005	XTN050	LOCHINVAR	\$ 850.00	
5698	Installed/Active	09/20/1988	FSG50	AO SMITH	\$ 850.00	
5699	Installed/Active	09/28/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5700	Installed/Active	10/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
5701	Installed/Active	01/20/2005	GVR50	AO SMITH	\$ 850.00	
5702	Installed/Active	03/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5703	Installed/Active	12/22/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5704	Installed/Active	07/17/1986	FSG50	AO SMITH	\$ 850.00	
5705	Installed/Active	04/26/2002	FSG50	AO SMITH	\$ 850.00	
5706	Installed/Active	09/05/2001	FSG50	AO SMITH	\$ 850.00	
5707	Installed/Active	05/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5708	Installed/Active	01/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
5709	Installed/Active	11/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5710	Installed/Active	01/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5711	Installed/Active	08/24/1998	FSG50	AO SMITH	\$ 850.00	
5712	Installed/Active	09/10/2009	21VR50	RHEEM	\$ 850.00	\$ 11.74
5713	Installed/Active	03/01/2001	41XR50	RHEEM	\$ 850.00	
5714	Installed/Active	04/08/2005	XVR50	A. O. SMITH	\$ 850.00	
5715	Installed/Active	08/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
5716	Installed/Active	06/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
5717	Installed/Active	03/16/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5718	Installed/Active	02/13/2012	M175S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.30
5719	Installed/Active	05/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
5720	Installed/Active	04/03/2002	FSG50	AO SMITH	\$ 850.00	
5721	Installed/Active	03/27/1996	RF67120	RUUD	\$ 1,900.00	
5722	Installed/Active	01/16/1984	FSG40	AO SMITH	\$ 850.00	
5723	Installed/Active	10/13/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5724	Installed/Active	11/09/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5725	Installed/Active	01/03/2003	PGR50	AO SMITH	\$ 850.00	
5726	Installed/Active	02/07/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
5727	Installed/Active	02/03/2006	LTN040G	LOCHINVAR	\$ 850.00	
5728	Installed/Active	02/21/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5729	Installed/Active	02/21/2003	FSG40	AO SMITH	\$ 850.00	
5730	Installed/Active	05/29/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
5731	Installed/Active	04/25/2005	SBF100199NES	STATE	\$ 3,350.00	
5732	Installed/Active	06/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5733	Installed/Active	07/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5734	Installed/Active	01/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5735	Installed/Active	06/07/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
5736	Installed/Active	08/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
5737	Installed/Active	04/29/1998	FGR50	AO SMITH	\$ 850.00	
5738	Installed/Active	07/29/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
5739	Installed/Active	02/13/1985	FSG50	AO SMITH	\$ 850.00	
5740	Installed/Active	07/28/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
5741	Installed/Active	11/16/2004	42V6050	RHEEM	\$ 500.00	
5742	Installed/Active	06/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5743	Installed/Active	08/01/2012	P230F	RUUD	\$ 850.00	\$ 6.39
5744	Installed/Active	07/14/2005	LTN050	LOCHINVAR	\$ 850.00	
5745	Installed/Active	05/14/2002	PGR50	AO SMITH	\$ 850.00	
5746	Installed/Active	10/30/1996	PGR50	AO SMITH	\$ 850.00	
5747	Installed/Active	02/25/2002	FSG50	AO SMITH	\$ 850.00	
5748	Installed/Active	01/27/2003	FSG50	AO SMITH	\$ 850.00	
5749	Installed/Active	08/20/2002	FSG50	AO SMITH	\$ 850.00	
5750	Installed/Active	02/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5751	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
5752	Installed/Active	04/23/2004	XSN040	LOCHINVAR	\$ 850.00	
5753	Installed/Active	10/16/2006	PR650	STATE	\$ 1,075.00	
5754	Installed/Active	05/07/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
5755	Installed/Active	12/08/2007	21V506	RHEEM	\$ 1,150.00	\$ 14.05
5756	Installed/Active	04/22/2005	LTN050	LOCHINVAR	\$ 850.00	
5757	Installed/Active	10/18/2002	PRX50	STATE	\$ 1,075.00	
5758	Installed/Active	02/06/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5759	Installed/Active	04/11/1991	FSG50	AO SMITH	\$ 850.00	
5760	Installed/Active	07/21/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
5761	Installed/Active	08/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
5762	Installed/Active	05/26/2006	PR650	STATE	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5763	Installed/Active	11/30/1987	PRV50NODS	STATE	\$ 1,075.00	
5764	Installed/Active	05/31/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
5765	Installed/Active	11/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5766	Installed/Active	02/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5767	Installed/Active	10/23/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5768	Installed/Active	01/06/2001	PR650	STATE	\$ 1,075.00	
5769	Installed/Active	10/28/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5770	Installed/Active	05/24/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5771	Installed/Active	11/19/1987	FSG50	AO SMITH	\$ 850.00	
5772	Installed/Active	07/31/2010	PH199119	PHOENIX	\$ 3,350.00	\$ 61.05
5773	Installed/Active	06/06/1988	FSG50	AO SMITH	\$ 850.00	
5774	Installed/Active	06/13/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5775	Installed/Active	12/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5776	Installed/Active	07/03/2004	GVC50	A. O. SMITH	\$ 850.00	
5777	Installed/Active	04/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5778	Installed/Active	12/01/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5779	Installed/Active	03/01/1988	FSG50	AO SMITH	\$ 850.00	
5780	Installed/Active	11/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
5781	Installed/Active	05/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5782	Installed/Active	07/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
5783	Installed/Active	06/03/1988	G67114	RHEEM	\$ 1,900.00	
5784	Installed/Active	04/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5785	Installed/Active	02/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5786	Installed/Active	07/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5787	Installed/Active	10/15/2002	FSG50	AO SMITH	\$ 850.00	
5788	Installed/Active	12/14/2001	PGR50	AO SMITH	\$ 850.00	
5789	Installed/Active	11/18/1985	FSG50	AO SMITH	\$ 850.00	
5790	Installed/Active	01/04/2001	41V50	RHEEM	\$ 850.00	
5791	Installed/Active	09/30/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
5792	Installed/Active	10/19/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5793	Installed/Active	10/08/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5794	Installed/Active	03/04/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5795	Installed/Active	10/31/2008	PR640	STATE	\$ 1,075.00	\$ 14.35
5796	Installed/Active	01/06/1998	FSG30	AO SMITH	\$ 850.00	
5797	Installed/Active	12/19/2002	PRX50	STATE	\$ 1,075.00	
5798	Installed/Active	09/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5799	Installed/Active	08/13/1997	SBF100199NES	STATE	\$ 3,350.00	
5800	Installed/Active	06/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5801	Installed/Active	01/12/1999	PR650	STATE	\$ 1,075.00	
5802	Installed/Active	03/01/2005	XVR50	A. O. SMITH	\$ 850.00	
5803	Installed/Active	01/10/1986	PRX50	STATE	\$ 1,075.00	
5804	Installed/Active	07/09/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5805	Installed/Active	01/28/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5806	Installed/Active	02/12/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5807	Installed/Active	09/07/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
5808	Installed/Active	08/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5809	Installed/Active	07/21/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
5810	Installed/Active	11/22/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5811	Installed/Active	10/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5812	Installed/Active	01/25/2012	PR502T	RUUD	\$ 850.00	\$ 12.64
5813	Installed/Active	09/10/2008	ETN076	LOCHINVAR	\$ 1,900.00	\$ 33.40
5814	Installed/Active	06/24/1985	FSG40	AO SMITH	\$ 850.00	
5815	Installed/Active	02/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5816	Installed/Active	01/29/2011	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5817	Installed/Active	11/16/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
5818	Installed/Active	10/04/2006	SBF100199NES	STATE	\$ 3,350.00	
5819	Installed/Active	06/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5820	Installed/Active	09/19/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
5821	Installed/Active	01/18/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
5822	Installed/Active	10/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5823	Installed/Active	11/09/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
5824	Installed/Active	03/11/2003	PRX50	STATE	\$ 1,075.00	
5825	Installed/Active	12/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5826	Installed/Active	07/26/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
5827	Installed/Active	11/06/2001	PGR50	AO SMITH	\$ 850.00	
5828	Installed/Active	09/28/2001	PGR50	AO SMITH	\$ 850.00	
5829	Installed/Active	03/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5830	Installed/Active	11/18/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
5831	Installed/Active	11/03/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
5832	Installed/Active	02/12/2002	FSG50	AO SMITH	\$ 850.00	
5833	Installed/Active	09/03/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
5834	Installed/Active	03/09/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
5835	Installed/Active	06/29/2006	LTN040G	LOCHINVAR	\$ 850.00	
5836	Installed/Active	04/18/2002	PGR50	AO SMITH	\$ 850.00	
5837	Installed/Active	09/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5838	Installed/Active	01/16/2003	FCV50	AO SMITH	\$ 850.00	
5839	Installed/Active	01/16/2000	FSG30	AO SMITH	\$ 850.00	
5840	Installed/Active	02/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
5841	Installed/Active	04/24/2003	PGR50	AO SMITH	\$ 850.00	
5842	Installed/Active	08/11/1987	21V506	RHEEM	\$ 1,150.00	
5843	Installed/Active	09/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
5844	Installed/Active	12/19/2005	LTN040G	LOCHINVAR	\$ 850.00	
5845	Installed/Active	01/25/1999	FSGL40	AO SMITH	\$ 850.00	
5846	Installed/Active	11/20/2001	FSG50	AO SMITH	\$ 850.00	
5847	Installed/Active	08/06/2004	XVR50	A. O. SMITH	\$ 850.00	
5848	Installed/Active	12/02/1998	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5849	Installed/Active	04/29/2005	PRX50	STATE	\$ 1,075.00	
5850	Installed/Active	04/30/1997	PGR50	AO SMITH	\$ 850.00	
5851	Installed/Active	06/05/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
5852	Installed/Active	12/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5853	Installed/Active	08/27/2004	XTN050	LOCHINVAR	\$ 850.00	
5854	Installed/Active	09/22/2004	FSG50	AO SMITH	\$ 850.00	
5855	Installed/Active	11/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5856	Installed/Active	09/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5857	Installed/Active	06/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5858	Installed/Active	07/13/2010	FSGL40	AO SMITH	\$ 850.00	\$ 6.04
5859	Installed/Active	06/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5860	Installed/Active	08/18/2004	21V506	RHEEM	\$ 1,150.00	
5861	Installed/Active	07/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5862	Installed/Active	11/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5863	Installed/Active	06/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
5864	Installed/Active	01/14/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5865	Installed/Active	08/21/1987	FSG50	AO SMITH	\$ 850.00	
5866	Installed/Active	05/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
5867	Installed/Active	07/07/1995	PGR50	AO SMITH	\$ 850.00	
5868	Installed/Active	07/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5869	Installed/Active	11/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
5870	Installed/Active	03/22/2007	FSG30	AO SMITH	\$ 850.00	\$ 10.23
5871	Installed/Active	10/14/2009	FGR30	AO SMITH	\$ 850.00	\$ 5.88
5872	Installed/Active	08/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5873	Installed/Active	08/10/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5874	Installed/Active	07/17/2012	P230F	RUUD	\$ 850.00	\$ 6.39
5875	Installed/Active	03/15/2004	FCVL40	AO SMITH	\$ 850.00	
5876	Installed/Active	01/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5877	Installed/Active	01/30/1997	FGR50	AO SMITH	\$ 850.00	
5878	Installed/Active	12/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5879	Installed/Active	08/18/2005	LTN050	LOCHINVAR	\$ 850.00	
5880	Installed/Active	05/01/1981	FSG40	AO SMITH	\$ 850.00	
5881	Installed/Active	11/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
5882	Installed/Active	01/30/1997	FGR50	AO SMITH	\$ 850.00	
5883	Installed/Active	01/03/2002	41XR50	RHEEM	\$ 850.00	
5884	Installed/Active	06/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5885	Installed/Active	06/13/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 6.37
5886	Installed/Active	02/23/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
5887	Installed/Active	05/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
5888	Installed/Active	08/03/2011	G75125	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
5889	Installed/Active	12/10/1996	FGR40	AO SMITH	\$ 850.00	
5890	Installed/Active	05/15/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
5891	Installed/Active	09/06/1994	PHR50	RUUD	\$ 850.00	
5892	Installed/Active	10/22/2001	PGR50	AO SMITH	\$ 850.00	
5893	Installed/Active	09/30/1992	21V407	RHEEM	\$ 850.00	
5894	Installed/Active	08/14/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
5895	Installed/Active	07/06/1998	PHR50	RUUD	\$ 850.00	
5896	Installed/Active	12/31/2005	G75125	RUUD/RHEEM	\$ 3,350.00	
5897	Installed/Active	06/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5898	Installed/Active	11/01/1997	FSGL40	AO SMITH	\$ 850.00	
5899	Installed/Active	12/06/2001	PGR50	AO SMITH	\$ 850.00	
5900	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5901	Installed/Active	05/10/1984	FSG50	AO SMITH	\$ 850.00	
5902	Installed/Active	04/14/1998	FSGL40	AO SMITH	\$ 850.00	
5903	Installed/Active	03/10/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5904	Installed/Active	03/07/2002	FSG40	AO SMITH	\$ 850.00	
5905	Installed/Active	10/21/2005	LTN050G	LOCHINVAR	\$ 850.00	
5906	Installed/Active	09/13/2000	FSG50	AO SMITH	\$ 850.00	
5907	Installed/Active	08/25/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
5908	Installed/Active	05/19/2005	LTN050	LOCHINVAR	\$ 850.00	
5909	Installed/Active	01/31/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
5910	Installed/Active	09/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5911	Installed/Active	07/18/2005	PR640	STATE	\$ 1,075.00	
5912	Installed/Active	01/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5913	Installed/Active	04/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
5914	Installed/Active	01/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5915	Installed/Active	03/26/2002	PGR50	AO SMITH	\$ 850.00	
5916	Installed/Active	09/16/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
5917	Installed/Active	04/30/2001	FSG50	AO SMITH	\$ 850.00	
5918	Installed/Active	12/27/2001	41XR50	RHEEM	\$ 850.00	
5919	Installed/Active	05/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5920	Installed/Active	08/13/1996	RM5063	RUUD	\$ 1,125.00	
5921	Installed/Active	08/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5922	Installed/Active	11/18/2004	GVC50	A. O. SMITH	\$ 850.00	
5923	Installed/Active	01/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5924	Installed/Active	09/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5925	Installed/Active	11/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5926	Installed/Active	09/29/1988	FSG50	AO SMITH	\$ 850.00	
5927	Installed/Active	04/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
5928	Installed/Active	04/08/1985	FSG50	AO SMITH	\$ 850.00	
5929	Installed/Active	09/09/2008	FGR50	AO SMITH	\$ 850.00	\$ 10.23
5930	Installed/Active	04/16/2001	FSGL40	AO SMITH	\$ 850.00	
5931	Installed/Active	10/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5932	Installed/Active	03/21/2005	GVC50	A. O. SMITH	\$ 850.00	
5933	Installed/Active	09/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5934	Installed/Active	01/05/2007	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
5935	Installed/Active	11/01/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
5936	Installed/Active	01/24/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
5937	Installed/Active	11/18/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
5938	Installed/Active	10/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
5939	Installed/Active	04/11/1997	PR502T	RUUD	\$ 850.00	
5940	Installed/Active	07/18/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5941	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
5942	Installed/Active	12/27/1988	PRV50NODS	STATE	\$ 1,075.00	
5943	Installed/Active	09/10/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
5944	Installed/Active	01/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5945	Installed/Active	09/20/1988	FSG50	AO SMITH	\$ 850.00	
5946	Installed/Active	01/11/2001	PRX50	STATE	\$ 1,075.00	
5947	Installed/Active	06/05/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5948	Installed/Active	10/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5949	Installed/Active	04/08/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
5950	Installed/Active	11/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5951	Installed/Active	06/04/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
5952	Installed/Active	10/12/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5953	Installed/Active	09/13/2005	LSN041G	LOCHINVAR	\$ 850.00	
5954	Installed/Active	01/15/1999	PHR50	RUUD	\$ 850.00	
5955	Installed/Active	11/05/2003	FCV50	AO SMITH	\$ 850.00	
5956	Installed/Active	06/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5957	Installed/Active	03/24/2004	FCV50	AO SMITH	\$ 850.00	
5958	Installed/Active	04/12/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5959	Installed/Active	11/18/2004	GVC50	A. O. SMITH	\$ 850.00	
5960	Installed/Active	12/28/1998	21VR50	RHEEM	\$ 850.00	
5961	Installed/Active	06/14/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
5962	Installed/Active	07/23/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
5963	Installed/Active	12/15/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5964	Installed/Active	02/08/1989	FSG50	AO SMITH	\$ 850.00	
5965	Installed/Active	07/24/2003	FSG50	AO SMITH	\$ 850.00	
5966	Installed/Active	12/21/2005	LTN050G	LOCHINVAR	\$ 850.00	
5967	Installed/Active	09/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
5968	Installed/Active	11/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5969	Installed/Active	11/05/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
5970	Installed/Active	12/30/2002	PRX50	STATE	\$ 1,075.00	
5971	Installed/Active	03/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5972	Installed/Active	07/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5973	Installed/Active	03/25/2000	41XR50	RHEEM	\$ 850.00	
5974	Installed/Active	04/20/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
5975	Installed/Active	10/13/2005	LTN050	LOCHINVAR	\$ 850.00	
5976	Installed/Active	03/01/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5977	Installed/Active	12/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
5978	Installed/Active	10/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5979	Installed/Active	05/20/1999	FGR50	AO SMITH	\$ 850.00	
5980	Installed/Active	02/13/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
5981	Installed/Active	04/14/1988	FSG50	AO SMITH	\$ 850.00	
5982	Installed/Active	07/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5983	Installed/Active	01/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
5984	Installed/Active	03/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
5985	Installed/Active	09/22/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5986	Installed/Active	04/16/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
5987	Installed/Active	10/05/2006	GVC50	A. O. SMITH	\$ 850.00	
5988	Installed/Active	08/31/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
5989	Installed/Active	03/06/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
5990	Installed/Active	05/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
5991	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
5992	Installed/Active	02/29/1988	FSG50	AO SMITH	\$ 850.00	
5993	Installed/Active	12/06/2000	21V407	RHEEM	\$ 850.00	
5994	Installed/Active	10/05/2006	GVC50	A. O. SMITH	\$ 850.00	
5995	Installed/Active	03/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
5996	Installed/Active	10/28/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
5997	Installed/Active	02/13/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
5998	Installed/Active	03/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
5999	Installed/Active	11/04/2010	G72DUMMY	AO SMITH	\$ 1,125.00	\$ 19.26
6000	Installed/Active	10/04/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6001	Installed/Active	06/16/1997	FSGL40	AO SMITH	\$ 850.00	
6002	Installed/Active	04/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6003	Installed/Active	07/12/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6004	Installed/Active	10/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6005	Installed/Active	10/04/2003	PGR50	AO SMITH	\$ 850.00	
6006	Installed/Active	07/20/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
6007	Installed/Active	02/15/1994	FGR50	AO SMITH	\$ 850.00	
6008	Installed/Active	04/05/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
6009	Installed/Active	11/04/2004	XVR40	A. O. SMITH	\$ 850.00	
6010	Installed/Active	07/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6011	Installed/Active	10/21/1997	FGR50	AO SMITH	\$ 850.00	
6012	Installed/Active	10/25/2012	G100200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
6013	Installed/Active	06/01/1984	FSG50	AO SMITH	\$ 850.00	
6014	Installed/Active	10/05/2006	PR650	STATE	\$ 1,075.00	
6015	Installed/Active	03/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
6016	Installed/Active	06/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6017	Installed/Active	10/29/2001	G82156	RUUD/RHEEM	\$ 3,350.00	
6018	Installed/Active	09/24/2002	PGR50	AO SMITH	\$ 850.00	
6019	Installed/Active	03/03/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
6020	Installed/Active	04/02/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6021	Installed/Active	12/18/1984	FSG50	AO SMITH	\$ 850.00	
6022	Installed/Active	10/17/2000	PGR50	AO SMITH	\$ 850.00	
6023	Installed/Active	05/23/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
6024	Installed/Active	03/09/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6025	Installed/Active	07/20/2001	PGR50	AO SMITH	\$ 850.00	
6026	Installed/Active	12/09/2002	H72DUMMY	AO SMITH	\$ 1,900.00	
6027	Installed/Active	11/05/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6028	Installed/Active	04/01/2000	41XR40	RHEEM	\$ 850.00	
6029	Installed/Active	09/01/2001	FSG50	AO SMITH	\$ 850.00	
6030	Installed/Active	02/01/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6031	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6032	Installed/Active	10/03/2007	PR640XODS	STATE	\$ 1,075.00	\$ 14.35
6033	Installed/Active	04/14/2000	FSG40	AO SMITH	\$ 850.00	
6034	Installed/Active	08/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
6035	Installed/Active	10/13/2003	21DV50	RHEEM	\$ 1,075.00	
6036	Installed/Active	06/22/1987	FSG50	AO SMITH	\$ 850.00	
6037	Installed/Active	01/07/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
6038	Installed/Active	11/05/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6039	Installed/Active	08/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6040	Installed/Active	03/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6041	Installed/Active	12/05/2002	FSG50	AO SMITH	\$ 850.00	
6042	Installed/Active	06/07/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
6043	Installed/Active	07/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
6044	Installed/Active	04/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6045	Installed/Active	03/17/2005	GVC50	A. O. SMITH	\$ 850.00	
6046	Installed/Active	12/20/2005	GVC50	A. O. SMITH	\$ 850.00	
6047	Installed/Active	03/27/1993	FSG50	AO SMITH	\$ 850.00	
6048	Installed/Active	02/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6049	Installed/Active	10/05/2005	LTN040G	LOCHINVAR	\$ 850.00	
6050	Installed/Active	05/23/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
6051	Installed/Active	08/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6052	Installed/Active	10/31/2003	PRX50	STATE	\$ 1,075.00	
6053	Installed/Active	01/25/2002	FSG50	AO SMITH	\$ 850.00	
6054	Installed/Active	12/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6055	Installed/Active	02/07/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6056	Installed/Active	07/31/2003	PGR50	AO SMITH	\$ 850.00	
6057	Installed/Active	01/27/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6058	Installed/Active	12/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
6059	Installed/Active	12/16/2001	FSG50	AO SMITH	\$ 850.00	
6060	Installed/Active	06/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6061	Installed/Active	02/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6062	Installed/Active	04/25/2002	PRX50	STATE	\$ 1,075.00	
6063	Installed/Active	11/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6064	Installed/Active	08/02/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
6065	Installed/Active	05/29/2003	FSG50	AO SMITH	\$ 850.00	
6066	Installed/Active	12/19/2001	FSG50	AO SMITH	\$ 850.00	
6067	Installed/Active	02/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6068	Installed/Active	09/08/2003	PVR50	AO SMITH	\$ 850.00	
6069	Installed/Active	08/22/2002	FSG50	AO SMITH	\$ 850.00	
6070	Installed/Active	08/02/2003	PGR50	AO SMITH	\$ 850.00	
6071	Installed/Active	02/15/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
6072	Installed/Active	02/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6073	Installed/Active	05/14/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
6074	Installed/Active	08/20/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
6075	Installed/Active	05/04/1999	FSG50	AO SMITH	\$ 850.00	
6076	Installed/Active	01/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6077	Installed/Active	03/01/2001	41XR50	RHEEM	\$ 850.00	
6078	Installed/Active	06/17/1987	FSG50	AO SMITH	\$ 850.00	
6079	Installed/Active	07/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6080	Installed/Active	08/13/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6081	Installed/Active	05/31/2001	21V506	RHEEM	\$ 1,150.00	
6082	Installed/Active	08/05/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6083	Installed/Active	07/18/2000	P506	RUUD	\$ 1,150.00	
6084	Installed/Active	03/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
6085	Installed/Active	08/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6086	Installed/Active	01/12/2004	PRX50	STATE	\$ 1,075.00	
6087	Installed/Active	10/16/2002	PGR50	AO SMITH	\$ 850.00	
6088	Installed/Active	10/16/2002	PGR50	AO SMITH	\$ 850.00	
6089	Installed/Active	11/04/1999	G82156	RUUD/RHEEM	\$ 3,350.00	
6090	Installed/Active	07/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6091	Installed/Active	11/23/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
6092	Installed/Active	05/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6093	Installed/Active	04/18/1995	FGR50	AO SMITH	\$ 850.00	
6094	Installed/Active	10/20/1988	PRV50NODS	STATE	\$ 1,075.00	
6095	Installed/Active	04/10/1985	FSG50	AO SMITH	\$ 850.00	
6096	Installed/Active	10/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6097	Installed/Active	06/30/2003	FSG50	AO SMITH	\$ 850.00	
6098	Installed/Active	06/05/1985	FSG50	AO SMITH	\$ 850.00	
6099	Installed/Active	12/14/2010	41VR40	RHEEM	\$ 850.00	\$ 12.05
6100	Installed/Active	02/05/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.05
6101	Installed/Active	01/15/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
6102	Installed/Active	11/19/2004	GVC50	A. O. SMITH	\$ 850.00	
6103	Installed/Active	05/16/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
6104	Installed/Active	04/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6105	Installed/Active	10/13/1988	FSG50	AO SMITH	\$ 850.00	
6106	Installed/Active	10/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6107	Installed/Active	01/07/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
6108	Installed/Active	02/06/2002	PGR40	AO SMITH	\$ 850.00	
6109	Installed/Active	01/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6110	Installed/Active	11/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6111	Installed/Active	11/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6112	Installed/Active	12/14/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6113	Installed/Active	10/26/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
6114	Installed/Active	01/15/2005	GVR50	AO SMITH	\$ 850.00	
6115	Installed/Active	10/07/1988	FSG50	AO SMITH	\$ 850.00	
6116	Installed/Active	03/31/2003	FSG50	AO SMITH	\$ 850.00	
6117	Installed/Active	12/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6118	Installed/Active	03/07/1995	PHR50	RUUD	\$ 850.00	
6119	Installed/Active	08/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6120	Installed/Active	12/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
6121	Installed/Active	01/04/2001	41XR50	RHEEM	\$ 850.00	
6122	Installed/Active	08/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
6123	Installed/Active	09/16/1999	FSG50	AO SMITH	\$ 850.00	
6124	Installed/Active	04/13/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6125	Installed/Active	05/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6126	Installed/Active	02/05/2004	XTN050	LOCHINVAR	\$ 850.00	
6127	Installed/Active	03/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
6128	Installed/Active	05/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6129	Installed/Active	11/03/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6130	Installed/Active	07/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
6131	Installed/Active	01/25/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
6132	Installed/Active	06/19/2002	PGR50	AO SMITH	\$ 850.00	
6133	Installed/Active	09/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6134	Installed/Active	06/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6135	Installed/Active	02/10/2005	PRX50	STATE	\$ 1,075.00	
6136	Installed/Active	08/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
6137	Installed/Active	03/06/1998	FSG50	AO SMITH	\$ 850.00	
6138	Installed/Active	01/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
6139	Installed/Active	03/14/2012	P230F	RUUD	\$ 850.00	\$ 12.64
6140	Installed/Active	12/11/1987	SBF100199NES	STATE	\$ 3,350.00	
6141	Installed/Active	09/01/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6142	Installed/Active	05/14/2006	LTN051G	LOCHINVAR	\$ 850.00	
6143	Installed/Active	08/06/2001	PGR50	AO SMITH	\$ 850.00	
6144	Installed/Active	10/14/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
6145	Installed/Active	01/28/1988	FSG50	AO SMITH	\$ 850.00	
6146	Installed/Active	02/20/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6147	Installed/Active	03/31/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6148	Installed/Active	06/15/2000	FSG50	AO SMITH	\$ 850.00	
6149	Installed/Active	01/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6150	Installed/Active	01/11/2013	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
6151	Installed/Active	08/23/2004	PRX50	STATE	\$ 1,075.00	
6152	Installed/Active	11/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
6153	Installed/Active	08/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
6154	Installed/Active	02/23/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
6155	Installed/Active	04/30/1999	PRV50NODS	STATE	\$ 1,075.00	
6156	Installed/Active	01/23/2003	PRX50	STATE	\$ 1,075.00	
6157	Installed/Active	07/09/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
6158	Installed/Active	09/18/2001	FSG50	AO SMITH	\$ 850.00	
6159	Installed/Active	05/06/1997	FGR50	AO SMITH	\$ 850.00	
6160	Installed/Active	10/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6161	Installed/Active	01/04/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
6162	Installed/Active	01/21/2005	GDVS50	AOSMITH	\$ 1,075.00	
6163	Installed/Active	08/08/2000	41XR50	RHEEM	\$ 850.00	
6164	Installed/Active	04/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6165	Installed/Active	02/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
6166	Installed/Active	04/09/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
6167	Installed/Active	03/13/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6168	Installed/Active	03/18/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6169	Installed/Active	12/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
6170	Installed/Active	04/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6171	Installed/Active	02/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6172	Installed/Active	03/03/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6173	Installed/Active	11/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6174	Installed/Active	09/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6175	Installed/Active	04/14/1987	FSG50	AO SMITH	\$ 850.00	
6176	Installed/Active	05/19/2003	PRX50	STATE	\$ 1,075.00	
6177	Installed/Active	06/19/2008	PR640	STATE	\$ 1,075.00	\$ 14.35
6178	Installed/Active	01/09/2004	FCVL40	AO SMITH	\$ 850.00	
6179	Installed/Active	12/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6180	Installed/Active	01/15/2004	XTN050	LOCHINVAR	\$ 850.00	
6181	Installed/Active	04/10/1987	RF82156	RUUD	\$ 3,350.00	
6182	Installed/Active	11/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6183	Installed/Active	04/21/2004	PVR50	AO SMITH	\$ 850.00	
6184	Installed/Active	04/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6185	Installed/Active	04/26/1996	FGR50	AO SMITH	\$ 850.00	
6186	Installed/Active	03/23/2001	41XR50	RHEEM	\$ 850.00	
6187	Installed/Active	04/10/1987	RF67120	RUUD	\$ 1,900.00	
6188	Installed/Active	04/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
6189	Installed/Active	02/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6190	Installed/Active	04/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6191	Installed/Active	02/08/2005	GVR50	AO SMITH	\$ 850.00	
6192	Installed/Active	11/11/1986	FSG40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6193	Installed/Active	03/15/2003	FSG50	AO SMITH	\$ 850.00	
6194	Installed/Active	10/25/2012	FGR50	AO SMITH	\$ 850.00	\$ 12.75
6195	Installed/Active	03/07/1994	FGR50	AO SMITH	\$ 850.00	
6196	Installed/Active	12/08/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6197	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6198	Installed/Active	11/14/1995	PHR50	RUUD	\$ 850.00	
6199	Installed/Active	03/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6200	Installed/Active	10/08/1997	41VR50	RHEEM	\$ 850.00	
6201	Installed/Active	11/09/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
6202	Installed/Active	08/19/2004	GVC40	A. O. SMITH	\$ 850.00	
6203	Installed/Active	06/23/1996	PGR50	AO SMITH	\$ 850.00	
6204	Installed/Active	06/18/2002	FSG50	AO SMITH	\$ 850.00	
6205	Installed/Active	10/19/2005	LTN050G	LOCHINVAR	\$ 850.00	
6206	Installed/Active	12/09/2002	PRX50	STATE	\$ 1,075.00	
6207	Installed/Active	12/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6208	Installed/Active	11/29/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
6209	Installed/Active	03/26/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6210	Installed/Active	05/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6211	Installed/Active	12/27/2008	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
6212	Installed/Active	08/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
6213	Installed/Active	02/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6214	Installed/Active	07/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6215	Installed/Active	03/21/1997	PRX50	STATE	\$ 1,075.00	
6216	Installed/Active	11/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6217	Installed/Active	12/24/1986	P506	RUUD	\$ 1,125.00	
6218	Installed/Active	02/14/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
6219	Installed/Active	09/25/2005	LTN050	LOCHINVAR	\$ 850.00	
6220	Installed/Active	03/28/2005	GVC50	A. O. SMITH	\$ 850.00	
6221	Installed/Active	06/27/2000	P502	RUUD	\$ 850.00	
6222	Installed/Active	11/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
6223	Installed/Active	05/19/2003	FSG40	AO SMITH	\$ 850.00	
6224	Installed/Active	07/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6225	Installed/Active	10/11/2011	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.64
6226	Installed/Active	05/21/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
6227	Installed/Active	04/12/1983	FSG50	AO SMITH	\$ 850.00	
6228	Installed/Active	07/23/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
6229	Installed/Active	04/23/2012	M140356FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6230	Installed/Active	08/18/2003	PGR40	AO SMITH	\$ 850.00	
6231	Installed/Active	06/16/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.37
6232	Installed/Active	12/01/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6233	Installed/Active	02/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6234	Installed/Active	03/29/1984	FSG50	AO SMITH	\$ 850.00	
6235	Installed/Active	02/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6236	Installed/Active	01/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6237	Installed/Active	03/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6238	Installed/Active	07/24/1991	FSG50	AO SMITH	\$ 850.00	
6239	Installed/Active	08/26/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
6240	Installed/Active	07/07/2005	LTN050	LOCHINVAR	\$ 850.00	
6241	Installed/Active	06/12/2002	FSG50	AO SMITH	\$ 850.00	
6242	Installed/Active	01/24/1996	FGR50	AO SMITH	\$ 850.00	
6243	Installed/Active	04/12/1983	RM5063	RUUD	\$ 500.00	
6244	Installed/Active	04/16/1997	FSG50	AO SMITH	\$ 850.00	
6245	Installed/Active	08/15/2005	LSN041G	LOCHINVAR	\$ 850.00	
6246	Installed/Active	03/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6247	Installed/Active	03/12/1985	FSG50	AO SMITH	\$ 850.00	
6248	Installed/Active	11/20/1999	PGR50	AO SMITH	\$ 850.00	
6249	Installed/Active	05/01/2001	PGR50	AO SMITH	\$ 850.00	
6250	Installed/Active	02/18/2005	LTN050	LOCHINVAR	\$ 850.00	
6251	Installed/Active	07/12/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6252	Installed/Active	12/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
6253	Installed/Active	05/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6254	Installed/Active	02/08/2003	PGR50	AO SMITH	\$ 850.00	
6255	Installed/Active	07/15/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
6256	Installed/Active	10/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
6257	Installed/Active	03/04/2002	FSG50	AO SMITH	\$ 850.00	
6258	Installed/Active	08/25/1999	G72DUMMY	AO SMITH	\$ 1,125.00	
6259	Installed/Active	03/08/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6260	Installed/Active	12/07/1988	FSG50	AO SMITH	\$ 850.00	
6261	Installed/Active	04/02/2004	GVC50	A. O. SMITH	\$ 850.00	
6262	Installed/Active	11/09/1999	PGR50	AO SMITH	\$ 850.00	
6263	Installed/Active	06/28/2002	FSG50	AO SMITH	\$ 850.00	
6264	Installed/Active	08/05/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6265	Installed/Active	10/25/2004	XVR50	A. O. SMITH	\$ 850.00	
6266	Installed/Active	08/17/1988	FSG50	AO SMITH	\$ 850.00	
6267	Installed/Active	04/01/2004	PRX50	STATE	\$ 1,075.00	
6268	Installed/Active	01/15/2000	41V50	RHEEM	\$ 850.00	
6269	Installed/Active	01/13/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6270	Installed/Active	03/22/2002	FSGL40	AO SMITH	\$ 850.00	
6271	Installed/Active	03/26/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
6272	Installed/Active	04/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6273	Installed/Active	10/06/1988	FSGL40	AO SMITH	\$ 850.00	
6274	Installed/Active	05/09/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
6275	Installed/Active	10/12/2005	LTN051G	LOCHINVAR	\$ 850.00	
6276	Installed/Active	12/24/2005	GVC50	A. O. SMITH	\$ 850.00	
6277	Installed/Active	11/23/2004	XVR50	A. O. SMITH	\$ 850.00	
6278	Installed/Active	02/12/2013	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6279	Installed/Active	09/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6280	Installed/Active	02/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6281	Installed/Active	10/20/2011	D71	UNKNOWN	\$ 1,150.00	\$ 17.37
6282	Installed/Active	01/02/2001	PGR50	AO SMITH	\$ 850.00	
6283	Installed/Active	07/06/2004	PRX50	STATE	\$ 1,075.00	
6284	Installed/Active	12/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6285	Installed/Active	10/24/2001	PRX50	STATE	\$ 1,075.00	
6286	Installed/Active	01/07/1989	FSG50	AO SMITH	\$ 850.00	
6287	Installed/Active	09/08/2003	PVR50	AO SMITH	\$ 850.00	
6288	Installed/Active	12/26/2003	FCV50	AO SMITH	\$ 850.00	
6289	Installed/Active	07/18/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6290	Installed/Active	02/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6291	Installed/Active	02/03/1999	41VR50	RHEEM	\$ 850.00	
6292	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6293	Installed/Active	08/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6294	Installed/Active	07/30/2004	XSN040	LOCHINVAR	\$ 850.00	
6295	Installed/Active	08/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
6296	Installed/Active	10/07/2006	LTN040G	LOCHINVAR	\$ 850.00	
6297	Installed/Active	10/15/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6298	Installed/Active	01/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6299	Installed/Active	10/10/2000	41VR50	RHEEM	\$ 850.00	
6300	Installed/Active	11/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6301	Installed/Active	03/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6302	Installed/Active	08/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6303	Installed/Active	11/06/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6304	Installed/Active	03/20/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6305	Installed/Active	12/19/2003	PRX50	STATE	\$ 1,075.00	
6306	Installed/Active	10/22/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
6307	Installed/Active	02/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6308	Installed/Active	10/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6309	Installed/Active	01/08/2004	PVR50	AO SMITH	\$ 850.00	
6310	Installed/Active	01/05/2007	PR650	STATE	\$ 1,075.00	
6311	Installed/Active	06/26/2001	41V50	RHEEM	\$ 850.00	
6312	Installed/Active	08/18/2007	PRX50	STATE	\$ 1,075.00	\$ 14.35
6313	Installed/Active	08/21/2002	PRX50	STATE	\$ 1,075.00	
6314	Installed/Active	10/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6315	Installed/Active	10/23/1987	FSG50	AO SMITH	\$ 850.00	
6316	Installed/Active	11/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
6317	Installed/Active	06/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6318	Installed/Active	04/27/2004	XTN040	LOCHINVAR	\$ 850.00	
6319	Installed/Active	11/12/2003	41XR50	RHEEM	\$ 850.00	
6320	Installed/Active	05/16/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
6321	Installed/Active	04/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6322	Installed/Active	01/28/2000	PR650	STATE	\$ 1,075.00	
6323	Installed/Active	09/23/2006	PR650	STATE	\$ 1,075.00	
6324	Installed/Active	12/03/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
6325	Installed/Active	11/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6326	Installed/Active	08/02/2000	41XR50	RHEEM	\$ 850.00	
6327	Installed/Active	07/11/1988	FSG50	AO SMITH	\$ 850.00	
6328	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6329	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6330	Installed/Active	07/07/2003	FSG40	AO SMITH	\$ 850.00	
6331	Installed/Active	04/10/2002	PGR50	AO SMITH	\$ 850.00	
6332	Installed/Active	01/07/2007	LTN050G	LOCHINVAR	\$ 850.00	
6333	Installed/Active	01/14/2002	PGR50	AO SMITH	\$ 850.00	
6334	Installed/Active	12/27/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6335	Installed/Active	03/06/2001	41V50	RHEEM	\$ 850.00	
6336	Installed/Active	11/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6337	Installed/Active	12/09/2002	PRX50	STATE	\$ 1,075.00	
6338	Installed/Active	01/16/2002	FSG50	AO SMITH	\$ 850.00	
6339	Installed/Active	11/16/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
6340	Installed/Active	05/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6341	Installed/Active	12/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
6342	Installed/Active	02/06/2003	PGR50	AO SMITH	\$ 850.00	
6343	Installed/Active	01/17/2003	PGR50	AO SMITH	\$ 850.00	
6344	Installed/Active	02/18/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
6345	Installed/Active	05/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6346	Installed/Active	08/17/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
6347	Installed/Active	10/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
6348	Installed/Active	02/26/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
6349	Installed/Active	10/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6350	Installed/Active	03/16/1988	FSG40	AO SMITH	\$ 850.00	
6351	Installed/Active	04/20/2005	PR650	STATE	\$ 1,075.00	
6352	Installed/Active	09/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6353	Installed/Active	02/01/2001	41V50	RHEEM	\$ 850.00	
6354	Installed/Active	03/16/1988	FSG40	AO SMITH	\$ 850.00	
6355	Installed/Active	06/21/2012	D71	UNKNOWN	\$ 850.00	\$ 17.52
6356	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6357	Installed/Active	05/29/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
6358	Installed/Active	04/20/1983	FSG40	AO SMITH	\$ 850.00	
6359	Installed/Active	10/27/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6360	Installed/Active	08/15/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6361	Installed/Active	07/13/1996	BTR154	AO SMITH	\$ 3,350.00	
6362	Installed/Active	01/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6363	Installed/Active	09/08/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
6364	Installed/Active	05/18/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6365	Installed/Active	09/30/2000	FSG50	AO SMITH	\$ 850.00	
6366	Installed/Active	02/02/2001	FSG50	AO SMITH	\$ 850.00	
6367	Installed/Active	05/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6368	Installed/Active	02/12/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6369	Installed/Active	08/06/1998	FSGL40	AO SMITH	\$ 850.00	
6370	Installed/Active	02/25/1991	21V506	RHEEM	\$ 850.00	
6371	Installed/Active	03/14/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
6372	Installed/Active	07/26/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
6373	Installed/Active	12/20/2000	FSG50	AO SMITH	\$ 850.00	
6374	Installed/Active	07/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6375	Installed/Active	05/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6376	Installed/Active	12/23/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
6377	Installed/Active	08/19/2003	FCV40	AO SMITH	\$ 850.00	
6378	Installed/Active	01/28/1992	21V502	RHEEM	\$ 850.00	
6379	Installed/Active	12/15/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
6380	Installed/Active	02/14/1985	FSG50	AO SMITH	\$ 850.00	
6381	Installed/Active	10/31/1984	FSG50	AO SMITH	\$ 850.00	
6382	Installed/Active	01/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6383	Installed/Active	12/04/2006	LSN041G	LOCHINVAR	\$ 850.00	
6384	Installed/Active	03/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6385	Installed/Active	04/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6386	Installed/Active	01/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
6387	Installed/Active	01/10/2004	PRX50	STATE	\$ 1,075.00	
6388	Installed/Active	12/22/1998	PHR40	RUUD	\$ 850.00	
6389	Installed/Active	12/12/2002	PRX50	STATE	\$ 1,075.00	
6390	Installed/Active	02/28/2002	PGR50	AO SMITH	\$ 850.00	
6391	Installed/Active	08/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6392	Installed/Active	12/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
6393	Installed/Active	08/17/1999	FSG50	AO SMITH	\$ 850.00	
6394	Installed/Active	11/19/2004	XVR50	A. O. SMITH	\$ 850.00	
6395	Installed/Active	03/23/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6396	Installed/Active	10/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6397	Installed/Active	06/15/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6398	Installed/Active	10/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6399	Installed/Active	03/01/2001	41XR50	RHEEM	\$ 850.00	
6400	Installed/Active	08/09/1997	PGR50	AO SMITH	\$ 850.00	
6401	Installed/Active	05/19/1987	21V502	RHEEM	\$ 1,150.00	
6402	Installed/Active	02/17/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
6403	Installed/Active	03/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6404	Installed/Active	06/24/2004	GVC50	A. O. SMITH	\$ 850.00	
6405	Installed/Active	11/28/1995	41XR40	RHEEM	\$ 850.00	
6406	Installed/Active	08/26/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6407	Installed/Active	04/15/2009	LTN030G	AO SMITH	\$ 850.00	\$ 11.74
6408	Installed/Active	06/10/2002	PGR50	AO SMITH	\$ 850.00	
6409	Installed/Active	08/20/1996	PGR50	AO SMITH	\$ 850.00	
6410	Installed/Active	10/26/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6411	Installed/Active	08/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6412	Installed/Active	03/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
6413	Installed/Active	12/24/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6414	Installed/Active	03/23/1997	PGR50	AO SMITH	\$ 850.00	
6415	Installed/Active	02/10/2004	FCV50	AO SMITH	\$ 850.00	
6416	Installed/Active	12/17/2001	PGR50	AO SMITH	\$ 850.00	
6417	Installed/Active	01/28/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6418	Installed/Active	03/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6419	Installed/Active	08/05/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
6420	Installed/Active	09/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6421	Installed/Active	01/05/2007	LTN050G	LOCHINVAR	\$ 850.00	
6422	Installed/Active	02/03/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6423	Installed/Active	02/02/2001	PGR50	AO SMITH	\$ 850.00	
6424	Installed/Active	06/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6425	Installed/Active	10/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6426	Installed/Active	06/03/2002	PGR50	AO SMITH	\$ 850.00	
6427	Installed/Active	08/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6428	Installed/Active	08/13/2002	PGR50	AO SMITH	\$ 850.00	
6429	Installed/Active	01/07/2002	PGR50	AO SMITH	\$ 850.00	
6430	Installed/Active	07/05/2000	21V506	RHEEM	\$ 1,150.00	
6431	Installed/Active	07/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6432	Installed/Active	06/17/2008	22DV5038	RHEEM	\$ 1,075.00	\$ 14.35
6433	Installed/Active	12/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6434	Installed/Active	01/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
6435	Installed/Active	01/21/1988	FSG50	AO SMITH	\$ 850.00	
6436	Installed/Active	07/12/1996	FSG50	AO SMITH	\$ 850.00	
6437	Installed/Active	03/14/2001	FSG50	AO SMITH	\$ 850.00	
6438	Installed/Active	03/16/1988	FSGL30	AO SMITH	\$ 850.00	
6439	Installed/Active	01/03/2002	PRX50	STATE	\$ 1,075.00	
6440	Installed/Active	02/01/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6441	Installed/Active	11/09/2005	PR650	STATE	\$ 1,075.00	
6442	Installed/Active	12/23/1987	FSG40	AO SMITH	\$ 850.00	
6443	Installed/Active	06/29/1988	RF82156	RUUD	\$ 3,350.00	
6444	Installed/Active	12/02/1996	PRX50	STATE	\$ 1,075.00	
6445	Installed/Active	07/23/2004	PVR50	AO SMITH	\$ 850.00	
6446	Installed/Active	09/24/1987	FSG50	AO SMITH	\$ 850.00	
6447	Installed/Active	01/04/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6448	Installed/Active	09/09/1988	FSG50	AO SMITH	\$ 850.00	
6449	Installed/Active	12/07/2001	PGR50	AO SMITH	\$ 850.00	
6450	Installed/Active	01/30/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6451	Installed/Active	08/11/2004	GVC50	A. O. SMITH	\$ 850.00	
6452	Installed/Active	06/02/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
6453	Installed/Active	01/31/2006	PR650	STATE	\$ 1,075.00	
6454	Installed/Active	09/14/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
6455	Installed/Active	05/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
6456	Installed/Active	12/28/1995	PRX40	STATE	\$ 1,075.00	
6457	Installed/Active	08/11/2001	FSG50	AO SMITH	\$ 850.00	
6458	Installed/Active	12/17/2004	PRX50	STATE	\$ 1,075.00	
6459	Installed/Active	10/18/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
6460	Installed/Active	01/22/2003	FSG50	AO SMITH	\$ 850.00	
6461	Installed/Active	12/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6462	Installed/Active	04/29/1988	PRX50	STATE	\$ 1,075.00	
6463	Installed/Active	01/20/2004	FSGL40	AO SMITH	\$ 850.00	
6464	Installed/Active	02/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6465	Installed/Active	07/12/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
6466	Installed/Active	05/14/2006	PR650	STATE	\$ 1,075.00	
6467	Installed/Active	10/17/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
6468	Installed/Active	12/09/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
6469	Installed/Active	07/25/2002	PRX50	STATE	\$ 1,075.00	
6470	Installed/Active	07/12/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
6471	Installed/Active	12/06/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6472	Installed/Active	11/26/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6473	Installed/Active	06/17/2004	FSG50	AO SMITH	\$ 850.00	
6474	Installed/Active	01/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6475	Installed/Active	01/29/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6476	Installed/Active	09/15/2005	LTN050	LOCHINVAR	\$ 850.00	
6477	Installed/Active	12/12/2000	41VR50	RHEEM	\$ 850.00	
6478	Installed/Active	11/06/2000	PGR50	AO SMITH	\$ 850.00	
6479	Installed/Active	02/25/1988	P506	RUUD	\$ 500.00	
6480	Installed/Active	07/08/1997	PRV50NODS	STATE	\$ 1,075.00	
6481	Installed/Active	06/19/1997	PGR50	AO SMITH	\$ 850.00	
6482	Installed/Active	01/01/1985	FSG50	AO SMITH	\$ 850.00	
6483	Installed/Active	11/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6484	Installed/Active	02/07/2003	BTC198	AO SMITH	\$ 3,350.00	
6485	Installed/Active	10/02/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6486	Installed/Active	04/27/2006	LSN041	LOCHINVAR	\$ 850.00	
6487	Installed/Active	08/12/2002	FSG50	AO SMITH	\$ 850.00	
6488	Installed/Active	02/08/2002	FSG50	AO SMITH	\$ 850.00	
6489	Installed/Active	05/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6490	Installed/Active	01/12/2000	FSGL40	AO SMITH	\$ 850.00	
6491	Installed/Active	01/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
6492	Installed/Active	04/21/2011	41VR40	RHEEM	\$ 850.00	\$ 12.64
6493	Installed/Active	05/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6494	Installed/Active	09/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6495	Installed/Active	12/19/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6496	Installed/Active	01/03/2008	G82156	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
6497	Installed/Active	12/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6498	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6499	Installed/Active	08/02/2003	FSG50	AO SMITH	\$ 850.00	
6500	Installed/Active	11/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6501	Installed/Active	09/21/1983	KGA40	AO SMITH	\$ 850.00	
6502	Installed/Active	03/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6503	Installed/Active	07/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
6504	Installed/Active	01/14/2002	PGR50	AO SMITH	\$ 850.00	
6505	Installed/Active	10/19/2004	GVC40	A. O. SMITH	\$ 850.00	
6506	Installed/Active	07/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6507	Installed/Active	09/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6508	Installed/Active	10/25/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6509	Installed/Active	12/10/2002	PGR50	AO SMITH	\$ 850.00	
6510	Installed/Active	09/20/2002	FSG50	AO SMITH	\$ 850.00	
6511	Installed/Active	06/23/2006	LSN041G	LOCHINVAR	\$ 850.00	
6512	Installed/Active	07/13/1995	PR502T	RUUD	\$ 850.00	
6513	Installed/Active	01/24/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6514	Installed/Active	12/24/2001	FSGL40	AO SMITH	\$ 850.00	
6515	Installed/Active	02/12/2001	FGR50	AO SMITH	\$ 850.00	
6516	Installed/Active	07/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6517	Installed/Active	06/27/2002	FSG40	AO SMITH	\$ 850.00	
6518	Installed/Active	07/27/1987	FSG50	AO SMITH	\$ 850.00	
6519	Installed/Active	10/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6520	Installed/Active	08/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6521	Installed/Active	12/23/2003	FSG50	AO SMITH	\$ 850.00	
6522	Installed/Active	05/27/2003	FSG50	AO SMITH	\$ 850.00	
6523	Installed/Active	12/15/2001	PGR50	AO SMITH	\$ 850.00	
6524	Installed/Active	03/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
6525	Installed/Active	03/21/2001	PGR50	AO SMITH	\$ 850.00	
6526	Installed/Active	04/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6527	Installed/Active	09/23/1998	FSG50	AO SMITH	\$ 850.00	
6528	Installed/Active	11/18/2006	PR650	STATE	\$ 1,075.00	
6529	Installed/Active	01/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6530	Installed/Active	04/20/2002	PGR50	AO SMITH	\$ 850.00	
6531	Installed/Active	04/05/2002	FSG50	AO SMITH	\$ 850.00	
6532	Installed/Active	06/24/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6533	Installed/Active	10/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6534	Installed/Active	05/04/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6535	Installed/Active	08/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6536	Installed/Active	01/30/2005	PRX50	STATE	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6537	Installed/Active	08/29/1997	FSG50	AO SMITH	\$ 850.00	
6538	Installed/Active	08/13/2003	PGR50	AO SMITH	\$ 850.00	
6539	Installed/Active	01/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6540	Installed/Active	01/27/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
6541	Installed/Active	08/01/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6542	Installed/Active	12/15/2003	FCV50	AO SMITH	\$ 850.00	
6543	Installed/Active	09/18/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6544	Installed/Active	06/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6545	Installed/Active	09/17/2003	FCV50	AO SMITH	\$ 850.00	
6546	Installed/Active	03/18/2000	41V50	RHEEM	\$ 850.00	
6547	Installed/Active	04/03/2000	PGR50	AO SMITH	\$ 850.00	
6548	Installed/Active	07/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6549	Installed/Active	10/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6550	Installed/Active	12/23/1999	FSG50	AO SMITH	\$ 850.00	
6551	Installed/Active	08/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6552	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
6553	Installed/Active	10/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6554	Installed/Active	08/14/1998	41VR50	RHEEM	\$ 850.00	
6555	Installed/Active	11/04/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
6556	Installed/Active	03/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6557	Installed/Active	02/19/1996	FGR50	AO SMITH	\$ 850.00	
6558	Installed/Active	10/05/2000	41XR40	RHEEM	\$ 850.00	
6559	Installed/Active	07/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
6560	Installed/Active	07/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6561	Installed/Active	04/13/2004	XVR50	A. O. SMITH	\$ 850.00	
6562	Installed/Active	02/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6563	Installed/Active	02/21/2004	FCV50	AO SMITH	\$ 850.00	
6564	Installed/Active	07/17/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6565	Installed/Active	08/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6566	Installed/Active	01/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6567	Installed/Active	02/20/1987	FSG50	AO SMITH	\$ 850.00	
6568	Installed/Active	03/18/2006	PR650X0DS	STATE	\$ 1,075.00	
6569	Installed/Active	10/07/2001	41VR40	RHEEM	\$ 850.00	
6570	Installed/Active	08/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6571	Installed/Active	01/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6572	Installed/Active	02/05/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
6573	Installed/Active	06/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6574	Installed/Active	09/09/1988	FSG50	AO SMITH	\$ 850.00	
6575	Installed/Active	01/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6576	Installed/Active	03/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6577	Installed/Active	11/02/1988	FSG50	AO SMITH	\$ 850.00	
6578	Installed/Active	02/03/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6579	Installed/Active	07/06/2006	LTN040G	LOCHINVAR	\$ 850.00	
6580	Installed/Active	03/08/2004	PRX50	STATE	\$ 1,075.00	
6581	Installed/Active	01/09/2001	FSG50	AO SMITH	\$ 850.00	
6582	Installed/Active	02/05/2007	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
6583	Installed/Active	11/30/2006	FSG50	AO SMITH	\$ 850.00	
6584	Installed/Active	11/17/1997	FSG50	AO SMITH	\$ 850.00	
6585	Installed/Active	10/07/2000	PRV50NODS	STATE	\$ 1,075.00	
6586	Installed/Active	11/29/2004	GVC50	A. O. SMITH	\$ 850.00	
6587	Installed/Active	08/18/2004	GVC50	A. O. SMITH	\$ 850.00	
6588	Installed/Active	03/13/2006	PR650	STATE	\$ 1,075.00	
6589	Installed/Active	08/18/2004	GVC50	A. O. SMITH	\$ 850.00	
6590	Installed/Active	01/01/2004	PRV50NODS	STATE	\$ 1,075.00	
6591	Installed/Active	10/12/1988	P506	RUUD	\$ 1,125.00	
6592	Installed/Active	04/29/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6593	Installed/Active	03/02/2001	41XR50	RHEEM	\$ 850.00	
6594	Installed/Active	01/23/2004	PRX50	STATE	\$ 1,075.00	
6595	Installed/Active	10/25/1988	PRV50NODS	STATE	\$ 1,075.00	
6596	Installed/Active	12/19/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6597	Installed/Active	12/22/1988	FSG50	AO SMITH	\$ 850.00	
6598	Installed/Active	05/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6599	Installed/Active	04/10/2000	FSG50	AO SMITH	\$ 850.00	
6600	Installed/Active	02/14/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6601	Installed/Active	02/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6602	Installed/Active	01/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6603	Installed/Active	05/24/2000	PGR50	AO SMITH	\$ 850.00	
6604	Installed/Active	01/15/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6605	Installed/Active	02/01/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6606	Installed/Active	03/13/2000	FSG50	AO SMITH	\$ 850.00	
6607	Installed/Active	09/14/2006	PR650X0DS	STATE	\$ 1,075.00	
6608	Installed/Active	05/05/2000	41XR50	RHEEM	\$ 850.00	
6609	Installed/Active	08/10/1997	PGR50	AO SMITH	\$ 850.00	
6610	Installed/Active	02/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6611	Installed/Active	01/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6612	Installed/Active	02/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6613	Installed/Active	08/30/2002	FSG50	AO SMITH	\$ 850.00	
6614	Installed/Active	01/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
6615	Installed/Active	10/28/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6616	Installed/Active	08/16/1997	FSL40	AO SMITH	\$ 850.00	
6617	Installed/Active	01/25/1984	FSG50	AO SMITH	\$ 850.00	
6618	Installed/Active	09/16/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
6619	Installed/Active	02/23/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6620	Installed/Active	05/30/1998	41VR50	RHEEM	\$ 850.00	
6621	Installed/Active	06/07/2004	XVR50	A. O. SMITH	\$ 850.00	
6622	Installed/Active	05/04/2005	LTN050GEF	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6623	Installed/Active	10/17/1997	PGR50	AO SMITH	\$ 850.00	
6624	Installed/Active	08/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6625	Installed/Active	04/02/1998	FGR50	AO SMITH	\$ 850.00	
6626	Installed/Active	03/01/1977	KGA40	AO SMITH	\$ 850.00	
6627	Installed/Active	04/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6628	Installed/Active	01/31/1984	FSG50	AO SMITH	\$ 850.00	
6629	Installed/Active	02/12/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
6630	Installed/Active	10/28/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
6631	Installed/Active	06/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6632	Installed/Active	01/08/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
6633	Installed/Active	05/18/2004	GVC40	A. O. SMITH	\$ 850.00	
6634	Installed/Active	11/13/2003	SBF100199NES	STATE	\$ 3,350.00	
6635	Installed/Active	04/30/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
6636	Installed/Active	06/18/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
6637	Installed/Active	01/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6638	Installed/Active	08/22/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6639	Installed/Active	05/06/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6640	Installed/Active	10/25/2005	LTN040G	LOCHINVAR	\$ 850.00	
6641	Installed/Active	08/24/2005	PR640	STATE	\$ 1,075.00	
6642	Installed/Active	06/17/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
6643	Installed/Active	01/01/1985	FSG50	AO SMITH	\$ 850.00	
6644	Installed/Active	01/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6645	Installed/Active	04/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
6646	Installed/Active	07/17/2000	PRX50	STATE	\$ 1,075.00	
6647	Installed/Active	07/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6648	Installed/Active	05/23/2003	PGR50	AO SMITH	\$ 850.00	
6649	Installed/Active	06/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6650	Installed/Active	10/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6651	Installed/Active	03/16/2005	PRX50	STATE	\$ 1,075.00	
6652	Installed/Active	01/17/2004	FCV40	AO SMITH	\$ 850.00	
6653	Installed/Active	01/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6654	Installed/Active	03/08/2005	GVC50	A. O. SMITH	\$ 850.00	
6655	Installed/Active	09/02/2003	PRX50	STATE	\$ 1,075.00	
6656	Installed/Active	05/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
6657	Installed/Active	01/17/2004	FCVL40	AO SMITH	\$ 850.00	
6658	Installed/Active	10/15/2001	FSG50	AO SMITH	\$ 1,125.00	
6659	Installed/Active	10/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6660	Installed/Active	06/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6661	Installed/Active	12/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6662	Installed/Active	12/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
6663	Installed/Active	10/25/2007	LTN050G	LOCHINVAR	\$ 500.00	\$ 16.35
6664	Installed/Active	11/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6665	Installed/Active	11/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6666	Installed/Active	06/17/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
6667	Installed/Active	10/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
6668	Installed/Active	08/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
6669	Installed/Active	07/14/1988	FSG50	AO SMITH	\$ 850.00	
6670	Installed/Active	07/24/1999	FSG50	AO SMITH	\$ 850.00	
6671	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6672	Installed/Active	01/31/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
6673	Installed/Active	01/02/2007	LTN050G	LOCHINVAR	\$ 850.00	
6674	Installed/Active	08/15/2001	FSGL40	AO SMITH	\$ 850.00	
6675	Installed/Active	05/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
6676	Installed/Active	05/01/1999	FSG50	AO SMITH	\$ 850.00	
6677	Installed/Active	01/06/1988	21V506	RHEEM	\$ 1,150.00	
6678	Installed/Active	05/08/2004	GVC50	A. O. SMITH	\$ 850.00	
6679	Installed/Active	12/20/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6680	Installed/Active	08/19/1988	FSG50	AO SMITH	\$ 850.00	
6681	Installed/Active	06/05/2006	LSN041G	LOCHINVAR	\$ 850.00	
6682	Installed/Active	06/18/2002	FSG50	AO SMITH	\$ 850.00	
6683	Installed/Active	06/08/2000	PGR50	AO SMITH	\$ 850.00	
6684	Installed/Active	09/26/1988	P506	RUUD	\$ 1,150.00	
6685	Installed/Active	04/28/2005	LTN050	LOCHINVAR	\$ 850.00	
6686	Installed/Active	07/27/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
6687	Installed/Active	09/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6688	Installed/Active	11/15/2002	PRX40	STATE	\$ 1,075.00	
6689	Installed/Active	02/12/2001	PGR50	AO SMITH	\$ 850.00	
6690	Installed/Active	07/08/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
6691	Installed/Active	04/28/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
6692	Installed/Active	03/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6693	Installed/Active	04/22/2003	FSG50	AO SMITH	\$ 850.00	
6694	Installed/Active	09/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6695	Installed/Active	12/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
6696	Installed/Active	12/17/1986	FSG50	AO SMITH	\$ 850.00	
6697	Installed/Active	04/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6698	Installed/Active	01/18/2006	GVC50	A. O. SMITH	\$ 850.00	
6699	Installed/Active	12/17/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
6700	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6701	Installed/Active	12/26/1995	FGR50	AO SMITH	\$ 850.00	
6702	Installed/Active	10/05/1999	PRV50NODS	STATE	\$ 1,075.00	
6703	Installed/Active	04/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
6704	Installed/Active	02/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6705	Installed/Active	11/14/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6706	Installed/Active	12/29/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6707	Installed/Active	03/07/2005	PR640	STATE	\$ 1,075.00	
6708	Installed/Active	09/07/1993	G91200	RUUD/RHEEM	\$ 3,350.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6709	Installed/Active	02/09/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6710	Installed/Active	10/30/1997	PGR50	AO SMITH	\$ 850.00	
6711	Installed/Active	03/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6712	Installed/Active	06/27/2002	PRX50	STATE	\$ 1,075.00	
6713	Installed/Active	05/10/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
6714	Installed/Active	04/17/2002	PGR50	AO SMITH	\$ 850.00	
6715	Installed/Active	04/15/2005	PRX50	STATE	\$ 1,075.00	
6716	Installed/Active	02/10/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6717	Installed/Active	02/13/2004	FSGL40	AO SMITH	\$ 850.00	
6718	Installed/Active	07/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6719	Installed/Active	02/11/2002	PRX50	STATE	\$ 1,075.00	
6720	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
6721	Installed/Active	09/08/1986	FSG50	AO SMITH	\$ 850.00	
6722	Installed/Active	10/30/2008	P506	RUUD	\$ 1,125.00	\$ 16.35
6723	Installed/Active	09/30/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
6724	Installed/Active	02/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6725	Installed/Active	09/01/2004	GVC50	A. O. SMITH	\$ 850.00	
6726	Installed/Active	11/09/2004	GVC40	A. O. SMITH	\$ 850.00	
6727	Installed/Active	10/10/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6728	Installed/Active	07/28/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6729	Installed/Active	04/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
6730	Installed/Active	12/01/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
6731	Installed/Active	04/29/1999	FGR50	AO SMITH	\$ 850.00	
6732	Installed/Active	08/19/1987	FSG50	AO SMITH	\$ 850.00	
6733	Installed/Active	10/13/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
6734	Installed/Active	04/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6735	Installed/Active	08/02/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6736	Installed/Active	08/31/2005	SSV50	STATE	\$ 1,075.00	
6737	Installed/Active	02/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6738	Installed/Active	07/27/2004	XTN040	LOCHINVAR	\$ 850.00	
6739	Installed/Active	12/09/2003	PGR50	AO SMITH	\$ 850.00	
6740	Installed/Active	04/16/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6741	Installed/Active	11/03/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6742	Installed/Active	12/12/2005	LTN050G	LOCHINVAR	\$ 850.00	
6743	Installed/Active	10/20/2001	FSG50	AO SMITH	\$ 850.00	
6744	Installed/Active	11/26/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6745	Installed/Active	02/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6746	Installed/Active	11/21/2002	21V506	RHEEM	\$ 1,150.00	
6747	Installed/Active	01/06/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
6748	Installed/Active	03/18/2006	LSN041G	LOCHINVAR	\$ 850.00	
6749	Installed/Active	05/23/2005	42VR506	RHEEM	\$ 1,150.00	
6750	Installed/Active	02/14/1989	FSG50	AO SMITH	\$ 850.00	
6751	Installed/Active	07/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6752	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6753	Installed/Active	10/19/2000	41XR50	RHEEM	\$ 850.00	
6754	Installed/Active	06/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6755	Installed/Active	10/20/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6756	Installed/Active	02/11/2004	21V502	RHEEM	\$ 500.00	
6757	Installed/Active	11/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6758	Installed/Active	01/31/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
6759	Installed/Active	09/21/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6760	Installed/Active	01/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6761	Installed/Active	04/03/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.37
6762	Installed/Active	01/16/1997	G82156	RUUD/RHEEM	\$ 3,350.00	
6763	Installed/Active	07/14/2004	XTN050	LOCHINVAR	\$ 850.00	
6764	Installed/Active	05/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6765	Installed/Active	08/08/2001	FSG50	AO SMITH	\$ 850.00	
6766	Installed/Active	04/30/1999	FGR50	AO SMITH	\$ 850.00	
6767	Installed/Active	12/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6768	Installed/Active	10/31/2011	PGR50	AO SMITH	\$ 850.00	\$ 12.64
6769	Installed/Active	02/25/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6770	Installed/Active	06/25/2004	GVC50	A. O. SMITH	\$ 850.00	
6771	Installed/Active	12/11/2001	PRX50	STATE	\$ 1,075.00	
6772	Installed/Active	08/31/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6773	Installed/Active	11/27/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6774	Installed/Active	03/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6775	Installed/Active	07/31/2005	LTN050G	LOCHINVAR	\$ 850.00	
6776	Installed/Active	04/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6777	Installed/Active	10/15/1988	FSG50	AO SMITH	\$ 850.00	
6778	Installed/Active	04/05/2002	PGR50	AO SMITH	\$ 850.00	
6779	Installed/Active	08/31/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6780	Installed/Active	11/15/1988	P506	RUUD	\$ 1,150.00	
6781	Installed/Active	09/20/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6782	Installed/Active	08/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6783	Installed/Active	10/11/1988	BTR120	AO SMITH	\$ 1,900.00	
6784	Installed/Active	11/25/2003	PRX50	STATE	\$ 1,075.00	
6785	Installed/Active	12/26/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6786	Installed/Active	12/18/1998	41XR50	RHEEM	\$ 850.00	
6787	Installed/Active	04/16/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
6788	Installed/Active	08/21/2009	22V50F1	RHEEM	\$ 850.00	\$ 5.88
6789	Installed/Active	04/15/2005	P506	RUUD	\$ 1,125.00	
6790	Installed/Active	01/26/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6791	Installed/Active	04/01/2002	FSG50	AO SMITH	\$ 850.00	
6792	Installed/Active	05/22/2002	PGR50	AO SMITH	\$ 850.00	
6793	Installed/Active	05/05/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6794	Installed/Active	01/16/1997	FGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6795	Installed/Active	02/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6796	Installed/Active	06/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6797	Installed/Active	06/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
6798	Installed/Active	02/13/2013	G75125	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
6799	Installed/Active	03/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6800	Installed/Active	03/12/2001	FSG40	AO SMITH	\$ 350.00	
6801	Installed/Active	04/21/2005	GVC50	A. O. SMITH	\$ 850.00	
6802	Installed/Active	11/23/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
6803	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6804	Installed/Active	12/15/2003	PVR50	AO SMITH	\$ 850.00	
6805	Installed/Active	01/09/1998	FGR50	AO SMITH	\$ 850.00	
6806	Installed/Active	07/20/2006	PR650X0DS	STATE	\$ 1,075.00	
6807	Installed/Active	01/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6808	Installed/Active	06/22/2005	LTN050	LOCHINVAR	\$ 850.00	
6809	Installed/Active	03/05/2002	FSG40	AO SMITH	\$ 850.00	
6810	Installed/Active	09/17/2005	LTN040G	LOCHINVAR	\$ 850.00	
6811	Installed/Active	11/15/2000	PGR50	AO SMITH	\$ 850.00	
6812	Installed/Active	01/08/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6813	Installed/Active	07/18/2003	21V407	RHEEM	\$ 850.00	
6814	Installed/Active	08/04/1977	PGC50	AO SMITH	\$ 850.00	
6815	Installed/Active	05/22/1997	FSGL40	AO SMITH	\$ 850.00	
6816	Installed/Active	03/04/2006	LTN040G	LOCHINVAR	\$ 850.00	
6817	Installed/Active	09/12/2005	GCVL40	A. O. SMITH	\$ 850.00	
6818	Installed/Active	01/14/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6819	Installed/Active	03/31/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6820	Installed/Active	09/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6821	Installed/Active	02/04/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.37
6822	Installed/Active	04/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6823	Installed/Active	11/15/2001	41XR50	RHEEM	\$ 850.00	
6824	Installed/Active	12/04/2004	GVC50	A. O. SMITH	\$ 850.00	
6825	Installed/Active	10/12/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6826	Installed/Active	11/21/2005	LTN050G	LOCHINVAR	\$ 850.00	
6827	Installed/Active	07/24/1998	FGR50	AO SMITH	\$ 850.00	
6828	Installed/Active	12/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6829	Installed/Active	06/01/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
6830	Installed/Active	10/24/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6831	Installed/Active	12/10/2001	FSGL40	AO SMITH	\$ 850.00	
6832	Installed/Active	01/04/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6833	Installed/Active	07/05/2005	PR650	STATE	\$ 1,075.00	
6834	Installed/Active	11/27/2002	PGR50	AO SMITH	\$ 850.00	
6835	Installed/Active	01/16/2000	21V506	RHEEM	\$ 1,150.00	
6836	Installed/Active	07/17/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
6837	Installed/Active	09/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
6838	Installed/Active	06/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
6839	Installed/Active	11/19/1987	FSG50	AO SMITH	\$ 850.00	
6840	Installed/Active	04/20/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6841	Installed/Active	12/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6842	Installed/Active	03/07/2003	PRX50	STATE	\$ 1,075.00	
6843	Installed/Active	02/09/1988	FSG50	AO SMITH	\$ 850.00	
6844	Installed/Active	02/11/1988	FSG50	AO SMITH	\$ 850.00	
6845	Installed/Active	09/16/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6846	Installed/Active	01/20/1996	PR502T	RUUD	\$ 850.00	
6847	Installed/Active	01/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6848	Installed/Active	04/01/2000	FGR50	AO SMITH	\$ 850.00	
6849	Installed/Active	06/30/1988	FSG50	AO SMITH	\$ 850.00	
6850	Installed/Active	02/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6851	Installed/Active	03/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6852	Installed/Active	11/13/1997	PGR50	AO SMITH	\$ 850.00	
6853	Installed/Active	01/04/2013	LTN051G	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
6854	Installed/Active	01/29/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6855	Installed/Active	03/21/1988	FSG50	AO SMITH	\$ 850.00	
6856	Installed/Active	12/11/2002	FSG40	AO SMITH	\$ 850.00	
6857	Installed/Active	05/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6858	Installed/Active	12/09/2004	GVC50	A. O. SMITH	\$ 850.00	
6859	Installed/Active	12/04/2006	PR650	STATE	\$ 1,075.00	
6860	Installed/Active	10/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6861	Installed/Active	09/24/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
6862	Installed/Active	10/15/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6863	Installed/Active	08/10/2004	GVC50	A. O. SMITH	\$ 850.00	
6864	Installed/Active	05/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6865	Installed/Active	10/09/2000	PRX50	STATE	\$ 1,075.00	
6866	Installed/Active	01/05/2004	XTN050	LOCHINVAR	\$ 850.00	
6867	Installed/Active	09/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6868	Installed/Active	09/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6869	Installed/Active	10/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6870	Installed/Active	06/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6871	Installed/Active	10/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
6872	Installed/Active	09/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6873	Installed/Active	04/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6874	Installed/Active	11/07/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
6875	Installed/Active	04/26/2004	PRX50	STATE	\$ 1,075.00	
6876	Installed/Active	12/27/2001	FSG50	AO SMITH	\$ 850.00	
6877	Installed/Active	05/04/1999	FGR50	AO SMITH	\$ 850.00	
6878	Installed/Active	10/26/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6879	Installed/Active	04/02/2001	PGR50	AO SMITH	\$ 850.00	
6880	Installed/Active	01/05/2002	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6881	Installed/Active	09/20/2005	LTN050G	LOCHINVAR	\$ 850.00	
6882	Installed/Active	08/07/1987	FSG50	AO SMITH	\$ 850.00	
6883	Installed/Active	07/02/1986	FSG40	AO SMITH	\$ 850.00	
6884	Installed/Active	02/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6885	Installed/Active	07/31/2002	FSGL40	AO SMITH	\$ 850.00	
6886	Installed/Active	11/30/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6887	Installed/Active	08/02/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6888	Installed/Active	01/30/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
6889	Installed/Active	02/02/2002	FSG50	AO SMITH	\$ 850.00	
6890	Installed/Active	04/26/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.64
6891	Installed/Active	12/04/1998	FSG50	AO SMITH	\$ 850.00	
6892	Installed/Active	05/28/1987	21V506	RHEEM	\$ 1,150.00	
6893	Installed/Active	04/06/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6894	Installed/Active	01/04/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.05
6895	Installed/Active	12/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
6896	Installed/Active	09/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6897	Installed/Active	07/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6898	Installed/Active	10/23/2001	FSG50	AO SMITH	\$ 850.00	
6899	Installed/Active	09/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6900	Installed/Active	07/18/1986	FSG50	AO SMITH	\$ 850.00	
6901	Installed/Active	10/07/2004	LTN050G	LOCHINVAR	\$ 850.00	
6902	Installed/Active	03/08/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6903	Installed/Active	11/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6904	Installed/Active	09/28/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6905	Installed/Active	05/09/1995	PR502T	RUUD	\$ 850.00	
6906	Installed/Active	05/26/2004	GVC50	A. O. SMITH	\$ 850.00	
6907	Installed/Active	07/15/2003	FSG50	AO SMITH	\$ 850.00	
6908	Installed/Active	12/31/2001	PGR50	AO SMITH	\$ 850.00	
6909	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
6910	Installed/Active	06/03/2002	FSG50	AO SMITH	\$ 850.00	
6911	Installed/Active	05/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6912	Installed/Active	08/22/2000	41XR50	RHEEM	\$ 850.00	
6913	Installed/Active	04/26/1998	PGR50	AO SMITH	\$ 850.00	
6914	Installed/Active	04/27/2005	LTN050	LOCHINVAR	\$ 850.00	
6915	Installed/Active	05/19/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
6916	Installed/Active	02/28/2012	PH2DV50F	RUUD	\$ 850.00	\$ 12.64
6917	Installed/Active	01/05/2000	FSG50	AO SMITH	\$ 850.00	
6918	Installed/Active	04/21/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
6919	Installed/Active	04/27/2000	PGR50	AO SMITH	\$ 850.00	
6920	Installed/Active	05/12/2006	LSN041G	LOCHINVAR	\$ 850.00	
6921	Installed/Active	01/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
6922	Installed/Active	12/07/1998	FGR50	AO SMITH	\$ 850.00	
6923	Installed/Active	12/02/1993	P506	RUUD	\$ 1,125.00	
6924	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6925	Installed/Active	08/06/1984	21V502	RHEEM	\$ 850.00	
6926	Installed/Active	12/19/1994	PR502T	RUUD	\$ 850.00	
6927	Installed/Active	02/14/2000	FSG50	AO SMITH	\$ 850.00	
6928	Installed/Active	06/06/2005	LTN050	LOCHINVAR	\$ 850.00	
6929	Installed/Active	06/05/1999	41VR40	RHEEM	\$ 850.00	
6930	Installed/Active	05/14/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
6931	Installed/Active	10/26/1997	G91200	RUUD/RHEEM	\$ 3,350.00	
6932	Installed/Active	05/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6933	Installed/Active	03/13/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
6934	Installed/Active	08/30/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
6935	Installed/Active	06/12/2001	PGR50	AO SMITH	\$ 850.00	
6936	Installed/Active	06/11/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
6937	Installed/Active	05/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6938	Installed/Active	01/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6939	Installed/Active	07/18/2005	LTN050	LOCHINVAR	\$ 850.00	
6940	Installed/Active	09/22/1989	SBF100199NES	STATE	\$ 3,350.00	
6941	Installed/Active	08/01/1978	PGC50	AO SMITH	\$ 850.00	
6942	Installed/Active	09/25/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
6943	Installed/Active	06/02/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
6944	Installed/Active	09/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6945	Installed/Active	04/01/1998	PGR50	AO SMITH	\$ 850.00	
6946	Installed/Active	12/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6947	Installed/Active	02/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
6948	Installed/Active	12/01/1981	G76200	RUUD/RHEEM	\$ 3,350.00	
6949	Installed/Active	02/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
6950	Installed/Active	11/06/2003	PRX50	STATE	\$ 1,075.00	
6951	Installed/Active	07/31/2003	41XR50	RHEEM	\$ 850.00	
6952	Installed/Active	04/01/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
6953	Installed/Active	12/09/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
6954	Installed/Active	06/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6955	Installed/Active	05/02/2001	PGR50	AO SMITH	\$ 850.00	
6956	Installed/Active	06/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6957	Installed/Active	01/31/2004	PRX50	STATE	\$ 1,075.00	
6958	Installed/Active	12/11/1987	P506	RUUD	\$ 1,125.00	
6959	Installed/Active	06/23/2004	GVC50	A. O. SMITH	\$ 850.00	
6960	Installed/Active	07/14/2006	LTN040G	LOCHINVAR	\$ 850.00	
6961	Installed/Active	08/06/2002	FSG50	AO SMITH	\$ 850.00	
6962	Installed/Active	10/10/2001	PGR50	AO SMITH	\$ 850.00	
6963	Installed/Active	11/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6964	Installed/Active	08/29/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
6965	Installed/Active	02/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6966	Installed/Active	04/08/1998	FGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
6967	Installed/Active	05/29/2003	FSG50	AO SMITH	\$ 850.00	
6968	Installed/Active	05/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
6969	Installed/Active	10/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
6970	Installed/Active	04/21/2012	BT80	AO SMITH	\$ 1,900.00	\$ 41.30
6971	Installed/Active	09/29/1987	FSG50	AO SMITH	\$ 850.00	
6972	Installed/Active	08/08/2003	FSGL40	AO SMITH	\$ 850.00	
6973	Installed/Active	07/18/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
6974	Installed/Active	11/15/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
6975	Installed/Active	02/11/2004	PRX50	STATE	\$ 1,075.00	
6976	Installed/Active	01/02/2005	GVC50	A. O. SMITH	\$ 850.00	
6977	Installed/Active	09/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6978	Installed/Active	01/02/2004	PRX50	STATE	\$ 1,075.00	
6979	Installed/Active	07/13/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
6980	Installed/Active	07/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6981	Installed/Active	02/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6982	Installed/Active	01/19/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
6983	Installed/Active	01/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
6984	Installed/Active	03/15/2005	PRX50	STATE	\$ 1,075.00	
6985	Installed/Active	04/22/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
6986	Installed/Active	04/15/2002	PGR50	AO SMITH	\$ 850.00	
6987	Installed/Active	12/17/2004	LTN050	LOCHINVAR	\$ 850.00	
6988	Installed/Active	11/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6989	Installed/Active	07/01/1988	FSG50	AO SMITH	\$ 850.00	
6990	Installed/Active	09/09/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
6991	Installed/Active	09/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
6992	Installed/Active	10/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6993	Installed/Active	01/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
6994	Installed/Active	08/27/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
6995	Installed/Active	04/18/2005	GVC50	A. O. SMITH	\$ 850.00	
6996	Installed/Active	11/20/2002	21V506	RHEEM	\$ 1,150.00	
6997	Installed/Active	06/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6998	Installed/Active	09/17/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
6999	Installed/Active	07/14/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
7000	Installed/Active	02/15/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
7001	Installed/Active	02/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7002	Installed/Active	03/23/2001	FSG40	AO SMITH	\$ 850.00	
7003	Installed/Active	10/17/2002	PGR50	AO SMITH	\$ 850.00	
7004	Installed/Active	01/14/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
7005	Installed/Active	03/23/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
7006	Installed/Active	09/13/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7007	Installed/Active	02/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7008	Installed/Active	01/07/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7009	Installed/Active	06/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7010	Installed/Active	12/11/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
7011	Installed/Active	08/06/1986	FSG50	AO SMITH	\$ 850.00	
7012	Installed/Active	03/19/2004	GVC50	A. O. SMITH	\$ 850.00	
7013	Installed/Active	03/07/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7014	Installed/Active	03/06/1997	PGR50	AO SMITH	\$ 850.00	
7015	Installed/Active	03/08/1997	PGR50	AO SMITH	\$ 850.00	
7016	Installed/Active	12/28/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
7017	Installed/Active	02/04/2003	FSG50	AO SMITH	\$ 850.00	
7018	Installed/Active	03/18/2004	XTN050	LOCHINVAR	\$ 850.00	
7019	Installed/Active	04/21/1995	PRX40	STATE	\$ 1,075.00	
7020	Installed/Active	03/23/2004	41XR50	RHEEM	\$ 850.00	
7021	Installed/Active	04/18/2012	PH250SF	RUUD	\$ 850.00	\$ 12.64
7022	Installed/Active	10/12/2000	PGR50	AO SMITH	\$ 850.00	
7023	Installed/Active	11/04/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
7024	Installed/Active	05/09/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
7025	Installed/Active	03/24/2004	PR650	STATE	\$ 1,075.00	
7026	Installed/Active	10/18/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7027	Installed/Active	09/16/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7028	Installed/Active	01/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7029	Installed/Active	06/08/2004	XVR50	A. O. SMITH	\$ 850.00	
7030	Installed/Active	05/20/1987	P505	RUUD	\$ 850.00	
7031	Installed/Active	11/20/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
7032	Installed/Active	12/21/2001	FSG50	AO SMITH	\$ 850.00	
7033	Installed/Active	11/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
7034	Installed/Active	12/28/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7035	Installed/Active	11/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7036	Installed/Active	04/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7037	Installed/Active	03/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7038	Installed/Active	04/28/2005	LTN050	LOCHINVAR	\$ 850.00	
7039	Installed/Active	04/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7040	Installed/Active	09/30/1988	FSGL40	AO SMITH	\$ 850.00	
7041	Installed/Active	10/10/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7042	Installed/Active	11/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7043	Installed/Active	02/15/2004	PRX40	STATE	\$ 1,075.00	
7044	Installed/Active	09/14/2000	FSG50	AO SMITH	\$ 850.00	
7045	Installed/Active	08/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7046	Installed/Active	03/17/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
7047	Installed/Active	10/03/2003	FSG50	AO SMITH	\$ 850.00	
7048	Installed/Active	02/21/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
7049	Installed/Active	02/28/1989	FSG50	AO SMITH	\$ 850.00	
7050	Installed/Active	08/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7051	Installed/Active	08/17/2000	PRX50	STATE	\$ 1,075.00	
7052	Installed/Active	12/27/2002	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7053	Installed/Active	03/19/2004	PRX50	STATE	\$ 1,075.00	
7054	Installed/Active	03/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
7055	Installed/Active	10/01/2001	FSG40	AO SMITH	\$ 850.00	
7056	Installed/Active	04/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7057	Installed/Active	08/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7058	Installed/Active	10/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7059	Installed/Active	09/20/2005	LTN050	LOCHINVAR	\$ 850.00	
7060	Installed/Active	04/05/2003	PRX50	STATE	\$ 1,075.00	
7061	Installed/Active	06/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7062	Installed/Active	12/21/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7063	Installed/Active	06/16/2006	PR640	STATE	\$ 1,075.00	
7064	Installed/Active	12/21/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7065	Installed/Active	08/18/2000	PRX50	STATE	\$ 1,075.00	
7066	Installed/Active	06/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
7067	Installed/Active	03/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7068	Installed/Active	04/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
7069	Installed/Active	05/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7070	Installed/Active	10/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7071	Installed/Active	07/01/2003	PRX50	STATE	\$ 1,075.00	
7072	Installed/Active	09/18/2003	FSG50	AO SMITH	\$ 850.00	
7073	Installed/Active	06/22/2006	PR650	STATE	\$ 1,075.00	
7074	Installed/Active	08/12/1988	FSG50	AO SMITH	\$ 850.00	
7075	Installed/Active	07/31/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7076	Installed/Active	03/24/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
7077	Installed/Active	03/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7078	Installed/Active	03/08/2004	FCVL40	AO SMITH	\$ 850.00	
7079	Installed/Active	03/19/2004	GVC50	A. O. SMITH	\$ 850.00	
7080	Installed/Active	09/19/1988	FSGL40	AO SMITH	\$ 850.00	
7081	Installed/Active	07/25/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7082	Installed/Active	04/06/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7083	Installed/Active	12/19/1988	FSG50	AO SMITH	\$ 850.00	
7084	Installed/Active	03/01/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7085	Installed/Active	11/28/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
7086	Installed/Active	01/27/2004	41VR50	RHEEM	\$ 850.00	
7087	Installed/Active	03/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7088	Installed/Active	03/06/2002	PGR50	AO SMITH	\$ 850.00	
7089	Installed/Active	06/25/2001	PGR50	AO SMITH	\$ 850.00	
7090	Installed/Active	07/27/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7091	Installed/Active	01/21/2003	PGR50	AO SMITH	\$ 850.00	
7092	Installed/Active	06/01/1982	P502	RUUD	\$ 850.00	
7093	Installed/Active	05/21/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
7094	Installed/Active	05/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7095	Installed/Active	07/17/2001	41VR50	RHEEM	\$ 850.00	
7096	Installed/Active	02/22/2001	PGR50	AO SMITH	\$ 850.00	
7097	Installed/Active	02/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7098	Installed/Active	01/05/2007	LTN050G	LOCHINVAR	\$ 850.00	
7099	Installed/Active	05/22/2005	GCVL40	A. O. SMITH	\$ 850.00	
7100	Installed/Active	02/19/2004	FCV50	AO SMITH	\$ 850.00	
7101	Installed/Active	06/08/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.64
7102	Installed/Active	06/20/2002	FSG40	AO SMITH	\$ 850.00	
7103	Installed/Active	06/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7104	Installed/Active	07/20/2006	LSN041G	LOCHINVAR	\$ 850.00	
7105	Installed/Active	04/27/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
7106	Installed/Active	07/26/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7107	Installed/Active	01/30/1996	PRX40	STATE	\$ 850.00	
7108	Installed/Active	11/14/2006	LTN040G	LOCHINVAR	\$ 850.00	
7109	Installed/Active	05/09/1983	P40S	RUUD	\$ 850.00	
7110	Installed/Active	01/14/1985	FSG50	AO SMITH	\$ 850.00	
7111	Installed/Active	03/19/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
7112	Installed/Active	10/15/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7113	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7114	Installed/Active	11/24/1999	PGR50	AO SMITH	\$ 850.00	
7115	Installed/Active	07/04/2003	41XR50	RHEEM	\$ 850.00	
7116	Installed/Active	04/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7117	Installed/Active	10/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7118	Installed/Active	05/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7119	Installed/Active	10/17/2007	P506	RUUD	\$ 1,125.00	\$ 16.35
7120	Installed/Active	10/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
7121	Installed/Active	10/17/2003	FSG50	AO SMITH	\$ 850.00	
7122	Installed/Active	01/14/2004	XTN050	LOCHINVAR	\$ 850.00	
7123	Installed/Active	12/24/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
7124	Installed/Active	05/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7125	Installed/Active	07/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7126	Installed/Active	11/23/2004	GVC40	A. O. SMITH	\$ 850.00	
7127	Installed/Active	07/02/2004	GVC50	A. O. SMITH	\$ 850.00	
7128	Installed/Active	01/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7129	Installed/Active	01/14/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 11.74
7130	Installed/Active	08/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7131	Installed/Active	01/01/1979	FSG50	AO SMITH	\$ 850.00	
7132	Installed/Active	02/26/2007	PGR50	AO SMITH	\$ 850.00	\$ 10.23
7133	Installed/Active	10/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7134	Installed/Active	09/29/2005	PR650	STATE	\$ 1,075.00	
7135	Installed/Active	05/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7136	Installed/Active	06/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7137	Installed/Active	03/13/2001	FSG50	AO SMITH	\$ 850.00	
7138	Installed/Active	04/10/2003	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7139	Installed/Active	02/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7140	Installed/Active	10/27/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
7141	Installed/Active	10/16/2010	PRV50NODS	STATE	\$ 1,075.00	\$ 16.91
7142	Installed/Active	01/29/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
7143	Installed/Active	11/14/2001	FSGL40	AO SMITH	\$ 850.00	
7144	Installed/Active	06/11/2003	FDV50T	AO SMITH	\$ 1,075.00	
7145	Installed/Active	09/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7146	Installed/Active	12/07/1998	FGR50	AO SMITH	\$ 850.00	
7147	Installed/Active	03/03/2004	FSG40	AO SMITH	\$ 850.00	
7148	Installed/Active	07/21/2004	XVR50	A. O. SMITH	\$ 850.00	
7149	Installed/Active	08/04/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
7150	Installed/Active	12/24/2003	21V506	RHEEM	\$ 1,150.00	
7151	Installed/Active	07/28/2005	LTN050	LOCHINVAR	\$ 850.00	
7152	Installed/Active	08/25/2001	41V50	RHEEM	\$ 850.00	
7153	Installed/Active	09/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7154	Installed/Active	05/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7155	Installed/Active	11/16/1994	PR502T	RUUD	\$ 850.00	
7156	Installed/Active	01/15/2005	PRX50	STATE	\$ 1,075.00	
7157	Installed/Active	09/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7158	Installed/Active	12/20/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
7159	Installed/Active	09/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7160	Installed/Active	05/15/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7161	Installed/Active	06/01/2001	PGR50	AO SMITH	\$ 850.00	
7162	Installed/Active	12/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7163	Installed/Active	12/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7164	Installed/Active	01/13/2003	FSG50	AO SMITH	\$ 850.00	
7165	Installed/Active	09/05/2001	PGR50	AO SMITH	\$ 850.00	
7166	Installed/Active	06/29/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7167	Installed/Active	01/21/1988	FSG50	AO SMITH	\$ 850.00	
7168	Installed/Active	04/11/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
7169	Installed/Active	01/25/2001	41V40S	RHEEM	\$ 850.00	
7170	Installed/Active	05/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7171	Installed/Active	01/21/1988	FSG50	AO SMITH	\$ 850.00	
7172	Installed/Active	05/04/2002	FSG50	AO SMITH	\$ 850.00	
7173	Installed/Active	04/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7174	Installed/Active	12/19/2004	XVR50	A. O. SMITH	\$ 850.00	
7175	Installed/Active	11/03/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7176	Installed/Active	06/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7177	Installed/Active	01/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7178	Installed/Active	12/17/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
7179	Installed/Active	09/23/2003	FSG50	AO SMITH	\$ 850.00	
7180	Installed/Active	10/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7181	Installed/Active	03/27/2002	FSG40	AO SMITH	\$ 850.00	
7182	Installed/Active	04/09/1997	FGR50	AO SMITH	\$ 850.00	
7183	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7184	Installed/Active	08/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7185	Installed/Active	05/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
7186	Installed/Active	07/02/2010	LTN040	LOCHINVAR	\$ 850.00	\$ 12.05
7187	Installed/Active	02/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7188	Installed/Active	02/14/1997	PRX50	STATE	\$ 1,075.00	
7189	Installed/Active	10/29/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7190	Installed/Active	08/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7191	Installed/Active	07/30/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
7192	Installed/Active	04/19/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
7193	Installed/Active	07/07/2000	PGR50	AO SMITH	\$ 850.00	
7194	Installed/Active	07/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7195	Installed/Active	02/13/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7196	Installed/Active	02/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7197	Installed/Active	03/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
7198	Installed/Active	05/13/2002	FSG50	AO SMITH	\$ 850.00	
7199	Installed/Active	01/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
7200	Installed/Active	12/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7201	Installed/Active	03/11/1987	21V502	RHEEM	\$ 850.00	
7202	Installed/Active	01/04/2002	PGR50	AO SMITH	\$ 850.00	
7203	Installed/Active	06/03/2005	PRX50	STATE	\$ 1,075.00	
7204	Installed/Active	03/04/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7205	Installed/Active	12/26/2003	XTN050	LOCHINVAR	\$ 850.00	
7206	Installed/Active	07/24/2001	PGR40	AO SMITH	\$ 850.00	
7207	Installed/Active	06/02/2007	XSN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7208	Installed/Active	08/03/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7209	Installed/Active	12/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7210	Installed/Active	04/14/2001	41V40S	RHEEM	\$ 850.00	
7211	Installed/Active	05/18/1998	FGR50	AO SMITH	\$ 850.00	
7212	Installed/Active	10/19/2008	41XR50	RHEEM	\$ 850.00	\$ 10.23
7213	Installed/Active	01/19/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7214	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7215	Installed/Active	03/03/2000	FSGL40	AO SMITH	\$ 850.00	
7216	Installed/Active	08/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7217	Installed/Active	07/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7218	Installed/Active	04/20/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
7219	Installed/Active	07/16/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7220	Installed/Active	02/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7221	Installed/Active	03/07/2003	FSG50	AO SMITH	\$ 850.00	
7222	Installed/Active	06/06/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
7223	Installed/Active	07/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7224	Installed/Active	08/15/2002	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7225	Installed/Active	03/31/2001	PGR40	AO SMITH	\$ 850.00	
7226	Installed/Active	02/22/2001	FGR50	AO SMITH	\$ 850.00	
7227	Installed/Active	08/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7228	Installed/Active	03/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7229	Installed/Active	08/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7230	Installed/Active	12/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7231	Installed/Active	02/15/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
7232	Installed/Active	10/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
7233	Installed/Active	08/23/2002	FSG50	AO SMITH	\$ 850.00	
7234	Installed/Active	02/16/2005	XVR50	A. O. SMITH	\$ 850.00	
7235	Installed/Active	12/28/2004	GVC50	A. O. SMITH	\$ 850.00	
7236	Installed/Active	09/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7237	Installed/Active	12/19/2003	PVR50	AO SMITH	\$ 850.00	
7238	Installed/Active	10/11/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
7239	Installed/Active	01/10/2003	41XR50	RHEEM	\$ 850.00	
7240	Installed/Active	11/12/2007	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
7241	Installed/Active	12/05/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
7242	Installed/Active	07/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7243	Installed/Active	05/03/1989	FSG50	AO SMITH	\$ 850.00	
7244	Installed/Active	09/18/2001	PRX50	STATE	\$ 1,075.00	
7245	Installed/Active	05/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7246	Installed/Active	11/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7247	Installed/Active	02/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
7248	Installed/Active	01/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7249	Installed/Active	10/14/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
7250	Installed/Active	02/27/2002	FSG50	AO SMITH	\$ 850.00	
7251	Installed/Active	04/17/2003	PGR50	AO SMITH	\$ 850.00	
7252	Installed/Active	09/30/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
7253	Installed/Active	01/27/2005	XVR50	A. O. SMITH	\$ 850.00	
7254	Installed/Active	01/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7255	Installed/Active	04/20/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7256	Installed/Active	08/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
7257	Installed/Active	02/24/2005	GVC50	A. O. SMITH	\$ 850.00	
7258	Installed/Active	11/21/2003	PVR50	AO SMITH	\$ 850.00	
7259	Installed/Active	05/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7260	Installed/Active	05/30/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7261	Installed/Active	10/18/2003	PRX50	STATE	\$ 1,075.00	
7262	Installed/Active	09/16/2005	LSN041G	LOCHINVAR	\$ 850.00	
7263	Installed/Active	03/20/2002	FSG50	AO SMITH	\$ 850.00	
7264	Installed/Active	05/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
7265	Installed/Active	09/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7266	Installed/Active	12/09/2004	PRX50	STATE	\$ 1,075.00	
7267	Installed/Active	11/24/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
7268	Installed/Active	12/19/1989	FSG50	AO SMITH	\$ 850.00	
7269	Installed/Active	05/23/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7270	Installed/Active	02/25/2005	XVR50	A. O. SMITH	\$ 1,075.00	
7271	Installed/Active	02/02/2001	FSG50	AO SMITH	\$ 850.00	
7272	Installed/Active	03/07/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.05
7273	Installed/Active	01/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7274	Installed/Active	05/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7275	Installed/Active	10/12/2002	FSG50	AO SMITH	\$ 850.00	
7276	Installed/Active	05/28/2003	PGR50	AO SMITH	\$ 850.00	
7277	Installed/Active	07/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7278	Installed/Active	09/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7279	Installed/Active	01/21/2003	PRX50	STATE	\$ 1,075.00	
7280	Installed/Active	09/09/1999	PR650	STATE	\$ 1,075.00	
7281	Installed/Active	03/23/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
7282	Installed/Active	01/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7283	Installed/Active	06/15/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7284	Installed/Active	06/30/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7285	Installed/Active	01/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7286	Installed/Active	03/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7287	Installed/Active	09/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7288	Installed/Active	02/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7289	Installed/Active	03/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7290	Installed/Active	04/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7291	Installed/Active	09/24/1997	FSG50	AO SMITH	\$ 850.00	
7292	Installed/Active	07/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7293	Installed/Active	06/08/2001	FSGL40	AO SMITH	\$ 850.00	
7294	Installed/Active	06/23/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7295	Installed/Active	08/31/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7296	Installed/Active	11/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
7297	Installed/Active	08/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7298	Installed/Active	11/27/1998	PR650	STATE	\$ 1,075.00	
7299	Installed/Active	01/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7300	Installed/Active	01/25/2005	FSGL40	AO SMITH	\$ 850.00	
7301	Installed/Active	01/20/2009	41V50	RHEEM	\$ 850.00	\$ 11.74
7302	Installed/Active	08/22/2003	PVR50	AO SMITH	\$ 850.00	
7303	Installed/Active	11/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
7304	Installed/Active	02/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7305	Installed/Active	02/28/2000	FSG50	AO SMITH	\$ 850.00	
7306	Installed/Active	12/30/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7307	Installed/Active	07/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7308	Installed/Active	05/01/1999	FSG50	AO SMITH	\$ 850.00	
7309	Installed/Active	12/13/1988	FSG50	AO SMITH	\$ 850.00	
7310	Installed/Active	01/17/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7311	Installed/Active	03/21/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
7312	Installed/Active	09/01/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
7313	Installed/Active	10/06/2005	LTN050	LOCHINVAR	\$ 850.00	
7314	Installed/Active	12/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7315	Installed/Active	12/24/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7316	Installed/Active	01/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
7317	Installed/Active	11/07/1988	BTR120	AO SMITH	\$ 1,900.00	
7318	Installed/Active	10/04/2004	GCVL40	A. O. SMITH	\$ 850.00	
7319	Installed/Active	02/27/2004	PRX50	STATE	\$ 1,075.00	
7320	Installed/Active	03/22/2004	PVR50	AO SMITH	\$ 850.00	
7321	Installed/Active	04/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7322	Installed/Active	10/05/1999	FSG50	AO SMITH	\$ 850.00	
7323	Installed/Active	01/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
7324	Installed/Active	12/10/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
7325	Installed/Active	11/21/2001	FSG50	AO SMITH	\$ 850.00	
7326	Installed/Active	05/13/2004	FSG40	AO SMITH	\$ 850.00	
7327	Installed/Active	01/06/2003	PGR50	AO SMITH	\$ 850.00	
7328	Installed/Active	04/12/2001	41V50	RHEEM	\$ 850.00	
7329	Installed/Active	03/26/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7330	Installed/Active	08/13/2002	FSG50	AO SMITH	\$ 850.00	
7331	Installed/Active	10/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
7332	Installed/Active	07/23/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7333	Installed/Active	03/30/2005	XVR40	A. O. SMITH	\$ 850.00	
7334	Installed/Active	12/15/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7335	Installed/Active	06/17/1988	FSG50	AO SMITH	\$ 850.00	
7336	Installed/Active	06/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7337	Installed/Active	07/08/2005	LTN050	LOCHINVAR	\$ 850.00	
7338	Installed/Active	04/03/2003	PGR50	AO SMITH	\$ 850.00	
7339	Installed/Active	06/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7340	Installed/Active	01/13/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7341	Installed/Active	08/27/2001	41XR50	RHEEM	\$ 850.00	
7342	Installed/Active	01/15/2004	FCV50	AO SMITH	\$ 850.00	
7343	Installed/Active	02/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7344	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7345	Installed/Active	07/19/2004	PRX50	STATE	\$ 1,075.00	
7346	Installed/Active	05/14/1999	FGR50	AO SMITH	\$ 850.00	
7347	Installed/Active	01/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7348	Installed/Active	10/20/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
7349	Installed/Active	05/25/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7350	Installed/Active	01/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7351	Installed/Active	01/08/2001	FSG50	AO SMITH	\$ 850.00	
7352	Installed/Active	11/24/2006	G76200	RUUD/RHEEM	\$ 3,350.00	
7353	Installed/Active	08/10/2001	PRX50	STATE	\$ 1,075.00	
7354	Installed/Active	12/27/1999	FSG50	AO SMITH	\$ 850.00	
7355	Installed/Active	03/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7356	Installed/Active	02/26/1999	FGR50	AO SMITH	\$ 850.00	
7357	Installed/Active	05/07/1999	41VR50	RHEEM	\$ 850.00	
7358	Installed/Active	03/22/2011	LTN040	LOCHINVAR	\$ 850.00	\$ 12.05
7359	Installed/Active	06/04/2004	GVC50	A. O. SMITH	\$ 850.00	
7360	Installed/Active	10/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
7361	Installed/Active	08/29/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
7362	Installed/Active	04/07/2008	PRX50	STATE	\$ 1,075.00	\$ 14.35
7363	Installed/Active	08/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7364	Installed/Active	11/28/2011	PH2DV50F	RUUD	\$ 850.00	\$ 12.64
7365	Installed/Active	09/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
7366	Installed/Active	07/03/2005	LTN050	LOCHINVAR	\$ 850.00	
7367	Installed/Active	12/08/2010	41XR50	RHEEM	\$ 850.00	\$ 12.05
7368	Installed/Active	06/27/2001	PRX50	STATE	\$ 1,075.00	
7369	Installed/Active	02/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7370	Installed/Active	01/02/1987	21V502	RHEEM	\$ 850.00	
7371	Installed/Active	02/23/2012	PH250SF	RUUD	\$ 850.00	\$ 12.64
7372	Installed/Active	12/03/2004	GVC50	A. O. SMITH	\$ 850.00	
7373	Installed/Active	06/24/1987	FSG50	AO SMITH	\$ 850.00	
7374	Installed/Active	05/19/1987	FSG50	AO SMITH	\$ 850.00	
7375	Installed/Active	08/29/2003	FCV40	AO SMITH	\$ 850.00	
7376	Installed/Active	04/19/2002	PGR50	AO SMITH	\$ 850.00	
7377	Installed/Active	04/11/2002	PGR50	AO SMITH	\$ 850.00	
7378	Installed/Active	05/03/2004	41XR50	RHEEM	\$ 850.00	
7379	Installed/Active	12/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7380	Installed/Active	09/26/2000	PGR50	AO SMITH	\$ 850.00	
7381	Installed/Active	11/23/1997	FGR50	AO SMITH	\$ 850.00	
7382	Installed/Active	01/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7383	Installed/Active	08/14/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
7384	Installed/Active	09/15/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7385	Installed/Active	03/21/2004	FSG50	AO SMITH	\$ 1,125.00	
7386	Installed/Active	09/28/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
7387	Installed/Active	01/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
7388	Installed/Active	05/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
7389	Installed/Active	12/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
7390	Installed/Active	12/02/1987	FSG50	AO SMITH	\$ 850.00	
7391	Installed/Active	05/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
7392	Installed/Active	01/04/2011	41VR40	RHEEM	\$ 850.00	\$ 12.05
7393	Installed/Active	08/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7394	Installed/Active	08/17/1987	PRX50	STATE	\$ 1,075.00	
7395	Installed/Active	10/05/2000	PGR50	AO SMITH	\$ 850.00	
7396	Installed/Active	05/09/2005	P506	RUUD	\$ 500.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7397	Installed/Active	07/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7398	Installed/Active	01/17/1995	PHR50	RUUD	\$ 850.00	
7399	Installed/Active	11/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7400	Installed/Active	02/07/2003	21V506	RHEEM	\$ 1,150.00	
7401	Installed/Active	08/27/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
7402	Installed/Active	09/12/1986	FSG50	AO SMITH	\$ 850.00	
7403	Installed/Active	03/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7404	Installed/Active	01/27/2011	42V50SF	RHEEM	\$ 850.00	\$ 12.05
7405	Installed/Active	11/15/1988	FSG50	AO SMITH	\$ 850.00	
7406	Installed/Active	12/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7407	Installed/Active	02/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7408	Installed/Active	09/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7409	Installed/Active	12/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7410	Installed/Active	02/15/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7411	Installed/Active	12/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7412	Installed/Active	09/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7413	Installed/Active	09/04/1998	FGR50	AO SMITH	\$ 850.00	
7414	Installed/Active	07/15/1988	FSG50	AO SMITH	\$ 850.00	
7415	Installed/Active	08/27/2000	FSG50	AO SMITH	\$ 850.00	
7416	Installed/Active	04/14/1999	PRV40NODS	STATE	\$ 1,075.00	
7417	Installed/Active	12/19/2000	41XR50	RHEEM	\$ 850.00	
7418	Installed/Active	10/23/1987	FSG50	AO SMITH	\$ 850.00	
7419	Installed/Active	11/30/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
7420	Installed/Active	12/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7421	Installed/Active	11/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
7422	Installed/Active	09/24/2001	FSG50	AO SMITH	\$ 850.00	
7423	Installed/Active	10/01/2003	PRX50	STATE	\$ 1,075.00	
7424	Installed/Active	09/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7425	Installed/Active	12/14/2001	PGR50	AO SMITH	\$ 850.00	
7426	Installed/Active	08/21/2001	PRX50	STATE	\$ 1,075.00	
7427	Installed/Active	01/21/2000	PGR50	AO SMITH	\$ 850.00	
7428	Installed/Active	08/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7429	Installed/Active	07/22/2005	LTN050	LOCHINVAR	\$ 850.00	
7430	Installed/Active	08/08/1997	FSG50	AO SMITH	\$ 850.00	
7431	Installed/Active	06/30/2001	PRX50	STATE	\$ 1,075.00	
7432	Installed/Active	10/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7433	Installed/Active	10/11/2005	PR650	STATE	\$ 1,075.00	
7434	Installed/Active	12/23/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7435	Installed/Active	04/09/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
7436	Installed/Active	12/20/2005	LTN050G	LOCHINVAR	\$ 850.00	
7437	Installed/Active	10/01/2004	42XR50	RHEEM	\$ 850.00	
7438	Installed/Active	09/04/2004	GCVL40	A. O. SMITH	\$ 850.00	
7439	Installed/Active	01/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7440	Installed/Active	08/16/2001	PGR50	AO SMITH	\$ 850.00	
7441	Installed/Active	12/07/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
7442	Installed/Active	01/08/1996	FGR50	AO SMITH	\$ 850.00	
7443	Installed/Active	04/06/1988	FSG50	AO SMITH	\$ 850.00	
7444	Installed/Active	12/23/2002	PGR50	AO SMITH	\$ 850.00	
7445	Installed/Active	01/21/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
7446	Installed/Active	08/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7447	Installed/Active	05/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
7448	Installed/Active	12/04/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7449	Installed/Active	01/03/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7450	Installed/Active	11/30/2001	PGR50	AO SMITH	\$ 850.00	
7451	Installed/Active	10/08/2002	FSG50	AO SMITH	\$ 850.00	
7452	Installed/Active	08/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7453	Installed/Active	08/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7454	Installed/Active	05/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7455	Installed/Active	11/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7456	Installed/Active	11/09/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
7457	Installed/Active	01/07/2002	FSG50	AO SMITH	\$ 850.00	
7458	Installed/Active	08/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7459	Installed/Active	01/01/1987	FSG50	AO SMITH	\$ 850.00	
7460	Installed/Active	01/12/2007	LTN040G	LOCHINVAR	\$ 850.00	
7461	Installed/Active	05/19/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
7462	Installed/Active	06/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7463	Installed/Active	01/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7464	Installed/Active	11/09/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
7465	Installed/Active	01/15/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7466	Installed/Active	06/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7467	Installed/Active	02/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7468	Installed/Active	01/15/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7469	Installed/Active	06/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
7470	Installed/Active	12/19/1995	PGR50	AO SMITH	\$ 850.00	
7471	Installed/Active	01/07/2002	21V407	RHEEM	\$ 350.00	
7472	Installed/Active	10/19/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7473	Installed/Active	07/06/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7474	Installed/Active	07/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7475	Installed/Active	01/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7476	Installed/Active	01/10/2003	PR650	STATE	\$ 1,075.00	
7477	Installed/Active	10/18/2004	GVC50	A. O. SMITH	\$ 850.00	
7478	Installed/Active	01/14/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7479	Installed/Active	10/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7480	Installed/Active	03/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
7481	Installed/Active	04/19/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.37
7482	Installed/Active	02/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7483	Installed/Active	09/09/1986	FSG50	AO SMITH	\$ 850.00	
7484	Installed/Active	09/09/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
7485	Installed/Active	03/20/1998	PRV50NODS	STATE	\$ 1,075.00	
7486	Installed/Active	06/16/2003	FSG40	AO SMITH	\$ 850.00	
7487	Installed/Active	12/02/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
7488	Installed/Active	07/05/2005	LTN050	LOCHINVAR	\$ 850.00	
7489	Installed/Active	01/04/1999	41VR50	RHEEM	\$ 850.00	
7490	Installed/Active	02/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7491	Installed/Active	10/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7492	Installed/Active	11/27/1997	PGR50	AO SMITH	\$ 850.00	
7493	Installed/Active	09/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7494	Installed/Active	04/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7495	Installed/Active	07/09/2001	FSG50	AO SMITH	\$ 850.00	
7496	Installed/Active	04/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7497	Installed/Active	11/21/1988	PRX50	STATE	\$ 1,075.00	
7498	Installed/Active	11/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7499	Installed/Active	12/30/1988	FSG50	AO SMITH	\$ 850.00	
7500	Installed/Active	12/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7501	Installed/Active	10/19/2000	21V506	RHEEM	\$ 1,150.00	
7502	Installed/Active	10/27/2004	GVC50	A. O. SMITH	\$ 850.00	
7503	Installed/Active	02/14/2003	FSG50	AO SMITH	\$ 850.00	
7504	Installed/Active	05/20/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
7505	Installed/Active	11/09/2004	GVC50	A. O. SMITH	\$ 850.00	
7506	Installed/Active	08/13/2012	PRX50	STATE	\$ 1,075.00	\$ 17.89
7507	Installed/Active	09/15/2006	PR650	STATE	\$ 1,075.00	
7508	Installed/Active	02/01/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7509	Installed/Active	12/21/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7510	Installed/Active	12/08/2012	B71	UNKNOWN	\$ 850.00	\$ 12.75
7511	Installed/Active	01/11/2000	FSG40	AO SMITH	\$ 850.00	
7512	Installed/Active	04/26/2005	PRX50	STATE	\$ 1,075.00	
7513	Installed/Active	06/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7514	Installed/Active	01/23/2004	XTN050	LOCHINVAR	\$ 850.00	
7515	Installed/Active	10/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7516	Installed/Active	12/15/2011	PH19980	PHOENIX	\$ 3,350.00	\$ 64.06
7517	Installed/Active	05/26/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7518	Installed/Active	11/21/2000	FSG50	AO SMITH	\$ 850.00	
7519	Installed/Active	04/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7520	Installed/Active	12/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7521	Installed/Active	05/28/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
7522	Installed/Active	10/10/2003	FCV50	AO SMITH	\$ 850.00	
7523	Installed/Active	03/17/2001	PR650	STATE	\$ 1,075.00	
7524	Installed/Active	08/15/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
7525	Installed/Active	02/07/2000	PRX50	STATE	\$ 1,075.00	
7526	Installed/Active	11/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7527	Installed/Active	08/26/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7528	Installed/Active	09/07/1988	FSG50	AO SMITH	\$ 850.00	
7529	Installed/Active	08/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7530	Installed/Active	05/15/2003	FSG40	AO SMITH	\$ 850.00	
7531	Installed/Active	10/07/1988	FSG50	AO SMITH	\$ 850.00	
7532	Installed/Active	03/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7533	Installed/Active	04/17/2006	PR650	STATE	\$ 1,075.00	
7534	Installed/Active	07/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7535	Installed/Active	07/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7536	Installed/Active	07/06/1999	PRV50NODS	STATE	\$ 1,075.00	
7537	Installed/Active	12/27/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7538	Installed/Active	09/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7539	Installed/Active	06/05/2001	FSG50	AO SMITH	\$ 850.00	
7540	Installed/Active	11/09/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7541	Installed/Active	04/09/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
7542	Installed/Active	02/22/1995	BTC197	AO SMITH	\$ 3,350.00	
7543	Installed/Active	01/02/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7544	Installed/Active	02/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7545	Installed/Active	11/27/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
7546	Installed/Active	07/19/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
7547	Installed/Active	10/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7548	Installed/Active	02/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7549	Installed/Active	12/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7550	Installed/Active	03/13/2001	41XR50	RHEEM	\$ 850.00	
7551	Installed/Active	01/16/2001	41V50	RHEEM	\$ 850.00	
7552	Installed/Active	04/13/2004	PRX50	STATE	\$ 1,075.00	
7553	Installed/Active	05/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7554	Installed/Active	07/20/2005	LTN050	LOCHINVAR	\$ 850.00	
7555	Installed/Active	03/04/2005	PR640	STATE	\$ 1,075.00	
7556	Installed/Active	09/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7557	Installed/Active	08/12/2005	LTN050G	LOCHINVAR	\$ 850.00	
7558	Installed/Active	01/10/2005	XVR50	A. O. SMITH	\$ 850.00	
7559	Installed/Active	08/28/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7560	Installed/Active	08/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7561	Installed/Active	04/05/2010	PGR50	AO SMITH	\$ 1,150.00	\$ 16.12
7562	Installed/Active	08/19/1987	FSG50	AO SMITH	\$ 850.00	
7563	Installed/Active	03/11/2005	GVC50	A. O. SMITH	\$ 850.00	
7564	Installed/Active	09/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7565	Installed/Active	07/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
7566	Installed/Active	09/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7567	Installed/Active	04/24/1987	FSG50	AO SMITH	\$ 850.00	
7568	Installed/Active	01/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7569	Installed/Active	05/04/2001	FSG40	AO SMITH	\$ 850.00	
7570	Installed/Active	01/03/2001	41V50	RHEEM	\$ 850.00	
7571	Installed/Active	07/05/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
7572	Installed/Active	07/23/2004	GVC50	A. O. SMITH	\$ 850.00	
7573	Installed/Active	02/15/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7574	Installed/Active	01/06/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7575	Installed/Active	04/28/2003	PGR50	AO SMITH	\$ 850.00	
7576	Installed/Active	12/21/2004	PRX50	STATE	\$ 1,075.00	
7577	Installed/Active	12/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7578	Installed/Active	05/17/1998	FGR50	AO SMITH	\$ 850.00	
7579	Installed/Active	03/08/1988	FSG50	AO SMITH	\$ 850.00	
7580	Installed/Active	07/18/2005	LSN041G	LOCHINVAR	\$ 850.00	
7581	Installed/Active	08/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7582	Installed/Active	11/01/2000	FSG50	AO SMITH	\$ 850.00	
7583	Installed/Active	07/15/2002	PGR50	AO SMITH	\$ 850.00	
7584	Installed/Active	06/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7585	Installed/Active	01/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
7586	Installed/Active	02/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7587	Installed/Active	10/05/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7588	Installed/Active	10/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7589	Installed/Active	01/20/2003	PGR50	AO SMITH	\$ 850.00	
7590	Installed/Active	02/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7591	Installed/Active	01/30/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
7592	Installed/Active	01/28/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.05
7593	Installed/Active	08/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7594	Installed/Active	08/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7595	Installed/Active	06/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7596	Installed/Active	11/15/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
7597	Installed/Active	05/26/1988	FSG50	AO SMITH	\$ 850.00	
7598	Installed/Active	12/14/2003	FCV50	AO SMITH	\$ 850.00	
7599	Installed/Active	07/21/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7600	Installed/Active	07/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7601	Installed/Active	05/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7602	Installed/Active	07/01/2004	GVC50	A. O. SMITH	\$ 850.00	
7603	Installed/Active	12/31/1996	PRV50NODS	STATE	\$ 1,075.00	
7604	Installed/Active	12/31/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7605	Installed/Active	05/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7606	Installed/Active	12/01/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
7607	Installed/Active	08/31/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7608	Installed/Active	08/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7609	Installed/Active	05/16/2003	FSG50	AO SMITH	\$ 850.00	
7610	Installed/Active	01/25/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
7611	Installed/Active	03/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7612	Installed/Active	02/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7613	Installed/Active	03/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7614	Installed/Active	05/13/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
7615	Installed/Active	03/04/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
7616	Installed/Active	07/29/2004	PRX50	STATE	\$ 1,075.00	
7617	Installed/Active	06/25/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
7618	Installed/Active	02/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
7619	Installed/Active	08/29/2005	XSN040GEF	LOCHINVAR	\$ 850.00	
7620	Installed/Active	02/09/2005	GVC50	A. O. SMITH	\$ 850.00	
7621	Installed/Active	08/26/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
7622	Installed/Active	10/27/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
7623	Installed/Active	10/11/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7624	Installed/Active	11/18/1988	FSG50	AO SMITH	\$ 850.00	
7625	Installed/Active	10/26/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7626	Installed/Active	10/13/1988	FSG50	AO SMITH	\$ 850.00	
7627	Installed/Active	04/19/2005	XVR50	A. O. SMITH	\$ 850.00	
7628	Installed/Active	12/04/1989	FSG50	AO SMITH	\$ 850.00	
7629	Installed/Active	01/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7630	Installed/Active	01/03/1999	41VR50	RHEEM	\$ 850.00	
7631	Installed/Active	06/17/2002	PRX50	STATE	\$ 1,075.00	
7632	Installed/Active	08/24/2004	PRX50	STATE	\$ 1,075.00	
7633	Installed/Active	10/21/2002	FSG50	AO SMITH	\$ 850.00	
7634	Installed/Active	02/20/2004	FCVL40	AO SMITH	\$ 850.00	
7635	Installed/Active	01/02/1999	41V50S	RHEEM	\$ 850.00	
7636	Installed/Active	08/13/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7637	Installed/Active	08/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
7638	Installed/Active	07/15/2003	PGR50	AO SMITH	\$ 850.00	
7639	Installed/Active	03/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7640	Installed/Active	01/22/1996	RF67120	RUUD	\$ 1,900.00	
7641	Installed/Active	03/29/2002	FSG50	AO SMITH	\$ 850.00	
7642	Installed/Active	07/19/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7643	Installed/Active	03/22/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
7644	Installed/Active	04/29/1999	FGR50	AO SMITH	\$ 850.00	
7645	Installed/Active	02/23/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7646	Installed/Active	03/23/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7647	Installed/Active	07/26/2005	LTN050G	LOCHINVAR	\$ 850.00	
7648	Installed/Active	08/25/1988	PRV50NODS	STATE	\$ 1,075.00	
7649	Installed/Active	03/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7650	Installed/Active	03/31/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7651	Installed/Active	02/08/1989	FSG50	AO SMITH	\$ 850.00	
7652	Installed/Active	10/27/1988	FSG50	AO SMITH	\$ 850.00	
7653	Installed/Active	01/15/2003	PRX50	STATE	\$ 1,075.00	
7654	Installed/Active	02/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7655	Installed/Active	12/10/2001	41XR50	RHEEM	\$ 850.00	
7656	Installed/Active	01/06/2007	PR650	STATE	\$ 1,075.00	
7657	Installed/Active	11/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
7658	Installed/Active	09/15/2003	FCVL40	AO SMITH	\$ 850.00	
7659	Installed/Active	08/09/2005	PR650	STATE	\$ 1,075.00	
7660	Installed/Active	11/15/2002	FSG50	AO SMITH	\$ 850.00	
7661	Installed/Active	05/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7662	Installed/Active	11/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7663	Installed/Active	09/17/2001	PRX50	STATE	\$ 1,075.00	
7664	Installed/Active	03/04/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
7665	Installed/Active	11/09/1987	FSG50	AO SMITH	\$ 850.00	
7666	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7667	Installed/Active	12/22/2001	41V40S	RHEEM	\$ 850.00	
7668	Installed/Active	10/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7669	Installed/Active	08/27/1987	PRX50	STATE	\$ 1,075.00	
7670	Installed/Active	05/19/2005	LTN050	LOCHINVAR	\$ 850.00	
7671	Installed/Active	08/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7672	Installed/Active	04/01/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
7673	Installed/Active	04/03/2012	41VR50	RHEEM	\$ 850.00	\$ 12.64
7674	Installed/Active	02/05/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7675	Installed/Active	07/07/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7676	Installed/Active	01/24/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7677	Installed/Active	05/06/1999	FSG50	AO SMITH	\$ 850.00	
7678	Installed/Active	04/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7679	Installed/Active	03/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7680	Installed/Active	08/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
7681	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7682	Installed/Active	09/25/1986	FSGL40	AO SMITH	\$ 850.00	
7683	Installed/Active	02/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7684	Installed/Active	12/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7685	Installed/Active	10/01/2004	GCVL40	A. O. SMITH	\$ 850.00	
7686	Installed/Active	03/09/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7687	Installed/Active	02/22/2012	D71	UNKNOWN	\$ 1,150.00	\$ 17.37
7688	Installed/Active	12/19/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
7689	Installed/Active	07/24/1986	FSG50	AO SMITH	\$ 850.00	
7690	Installed/Active	06/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7691	Installed/Active	11/25/2002	PGR50	AO SMITH	\$ 850.00	
7692	Installed/Active	07/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7693	Installed/Active	02/01/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
7694	Installed/Active	08/25/2001	PGR50	AO SMITH	\$ 850.00	
7695	Installed/Active	10/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7696	Installed/Active	02/18/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7697	Installed/Active	03/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7698	Installed/Active	01/10/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7699	Installed/Active	03/01/2001	41XR50	RHEEM	\$ 850.00	
7700	Installed/Active	11/25/2005	FSG50	AO SMITH	\$ 850.00	
7701	Installed/Active	02/15/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7702	Installed/Active	01/26/2004	PVR50	AO SMITH	\$ 850.00	
7703	Installed/Active	10/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7704	Installed/Active	08/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7705	Installed/Active	04/04/1988	FSG50	AO SMITH	\$ 850.00	
7706	Installed/Active	08/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7707	Installed/Active	10/04/1988	FSG50	AO SMITH	\$ 850.00	
7708	Installed/Active	04/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
7709	Installed/Active	06/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
7710	Installed/Active	07/08/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
7711	Installed/Active	03/31/2005	GVC50	A. O. SMITH	\$ 850.00	
7712	Installed/Active	06/16/1997	PGR50	AO SMITH	\$ 850.00	
7713	Installed/Active	07/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7714	Installed/Active	09/08/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
7715	Installed/Active	12/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7716	Installed/Active	03/01/1988	FSG50	AO SMITH	\$ 850.00	
7717	Installed/Active	11/19/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
7718	Installed/Active	11/16/2001	FSG50	AO SMITH	\$ 850.00	
7719	Installed/Active	07/24/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
7720	Installed/Active	02/06/2003	FSG50	AO SMITH	\$ 850.00	
7721	Installed/Active	05/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
7722	Installed/Active	01/07/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7723	Installed/Active	10/30/1987	P506	RUUD	\$ 1,125.00	
7724	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7725	Installed/Active	03/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
7726	Installed/Active	03/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7727	Installed/Active	01/07/2001	PRX50	STATE	\$ 1,075.00	
7728	Installed/Active	03/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7729	Installed/Active	01/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7730	Installed/Active	03/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7731	Installed/Active	05/19/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7732	Installed/Active	06/10/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7733	Installed/Active	12/26/2005	PR650	STATE	\$ 1,075.00	
7734	Installed/Active	04/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7735	Installed/Active	04/26/2007	42VR50	RHEEM	\$ 850.00	\$ 10.23
7736	Installed/Active	08/22/2002	PRX50	STATE	\$ 1,075.00	
7737	Installed/Active	11/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7738	Installed/Active	10/05/1987	FSG50	AO SMITH	\$ 850.00	
7739	Installed/Active	03/23/2001	41XR50	RHEEM	\$ 850.00	
7740	Installed/Active	03/16/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7741	Installed/Active	01/18/2002	41XR50	RHEEM	\$ 850.00	
7742	Installed/Active	02/21/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7743	Installed/Active	05/25/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7744	Installed/Active	02/28/2006	FGR50	AO SMITH	\$ 850.00	
7745	Installed/Active	05/28/2005	LTN040	LOCHINVAR	\$ 850.00	
7746	Installed/Active	09/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7747	Installed/Active	12/16/2005	LTN050G	LOCHINVAR	\$ 850.00	
7748	Installed/Active	11/12/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
7749	Installed/Active	11/22/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
7750	Installed/Active	02/01/1998	PRV50NODS	STATE	\$ 1,125.00	
7751	Installed/Active	01/19/2002	FSG50	AO SMITH	\$ 850.00	
7752	Installed/Active	11/17/2006	PR650	STATE	\$ 1,075.00	
7753	Installed/Active	09/27/2004	PRX50	STATE	\$ 1,075.00	
7754	Installed/Active	01/31/2011	PGR50	AO SMITH	\$ 350.00	\$ 14.74
7755	Installed/Active	08/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
7756	Installed/Active	08/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7757	Installed/Active	02/05/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7758	Installed/Active	01/19/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
7759	Installed/Active	08/23/2000	41XR50	RHEEM	\$ 850.00	
7760	Installed/Active	02/23/2005	LTN050	LOCHINVAR	\$ 850.00	
7761	Installed/Active	02/01/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
7762	Installed/Active	02/01/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7763	Installed/Active	01/17/2002	FSG50	AO SMITH	\$ 850.00	
7764	Installed/Active	07/01/2003	PGR50	AO SMITH	\$ 850.00	
7765	Installed/Active	09/27/2002	FSG50	AO SMITH	\$ 850.00	
7766	Installed/Active	02/02/1987	FSG50	AO SMITH	\$ 850.00	
7767	Installed/Active	09/06/2002	FSG50	AO SMITH	\$ 850.00	
7768	Installed/Active	04/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
7769	Installed/Active	07/06/1997	PRX50	STATE	\$ 1,075.00	
7770	Installed/Active	02/01/2000	41XR50	RHEEM	\$ 850.00	
7771	Installed/Active	05/22/1987	FSG50	AO SMITH	\$ 850.00	
7772	Installed/Active	09/11/1987	FSG50	AO SMITH	\$ 850.00	
7773	Installed/Active	04/29/2004	PRX50	STATE	\$ 1,075.00	
7774	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7775	Installed/Active	03/06/2003	PGR50	AO SMITH	\$ 850.00	
7776	Installed/Active	07/14/2004	GVC50	A. O. SMITH	\$ 850.00	
7777	Installed/Active	04/23/2004	XTN050	LOCHINVAR	\$ 850.00	
7778	Installed/Active	07/05/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
7779	Installed/Active	05/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
7780	Installed/Active	04/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7781	Installed/Active	01/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7782	Installed/Active	08/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7783	Installed/Active	02/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7784	Installed/Active	04/28/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7785	Installed/Active	06/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7786	Installed/Active	04/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7787	Installed/Active	08/27/2001	PGR50	AO SMITH	\$ 850.00	
7788	Installed/Active	09/01/1998	PR650	STATE	\$ 1,075.00	
7789	Installed/Active	08/17/1998	PRV50NODS	STATE	\$ 1,075.00	
7790	Installed/Active	05/18/2001	FSGL40	AO SMITH	\$ 850.00	
7791	Installed/Active	05/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7792	Installed/Active	01/07/1999	FSG40	AO SMITH	\$ 850.00	
7793	Installed/Active	04/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
7794	Installed/Active	10/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7795	Installed/Active	04/16/1987	FSG50	AO SMITH	\$ 850.00	
7796	Installed/Active	02/25/2002	FSG50	AO SMITH	\$ 850.00	
7797	Installed/Active	12/06/1999	PGR50	AO SMITH	\$ 850.00	
7798	Installed/Active	09/03/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7799	Installed/Active	05/26/2002	PRX50	STATE	\$ 1,075.00	
7800	Installed/Active	02/26/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
7801	Installed/Active	06/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
7802	Installed/Active	04/15/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
7803	Installed/Active	11/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7804	Installed/Active	05/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7805	Installed/Active	08/20/2001	PGR50	AO SMITH	\$ 850.00	
7806	Installed/Active	01/12/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7807	Installed/Active	12/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
7808	Installed/Active	07/24/1998	21V402S	RHEEM	\$ 850.00	
7809	Installed/Active	01/29/2000	PRX50	STATE	\$ 1,075.00	
7810	Installed/Active	10/11/2005	PR650	STATE	\$ 1,075.00	
7811	Installed/Active	10/13/2007	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
7812	Installed/Active	03/27/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
7813	Installed/Active	11/30/1988	FSG50	AO SMITH	\$ 850.00	
7814	Installed/Active	03/09/1997	FGR50	AO SMITH	\$ 850.00	
7815	Installed/Active	02/24/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
7816	Installed/Active	03/01/2005	PRX50	STATE	\$ 1,075.00	
7817	Installed/Active	07/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7818	Installed/Active	09/27/1988	FSG50	AO SMITH	\$ 850.00	
7819	Installed/Active	12/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7820	Installed/Active	12/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
7821	Installed/Active	06/29/2001	FSG50	AO SMITH	\$ 850.00	
7822	Installed/Active	02/05/1999	FGR50	AO SMITH	\$ 850.00	
7823	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7824	Installed/Active	01/03/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7825	Installed/Active	11/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7826	Installed/Active	07/20/2002	21DV50	RHEEM	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7827	Installed/Active	11/30/1988	PRX50	STATE	\$ 1,075.00	
7828	Installed/Active	10/27/1988	FSG50	AO SMITH	\$ 850.00	
7829	Installed/Active	01/09/2004	FCV50	AO SMITH	\$ 850.00	
7830	Installed/Active	11/17/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
7831	Installed/Active	11/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7832	Installed/Active	10/25/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7833	Installed/Active	11/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
7834	Installed/Active	03/13/1989	FSG50	AO SMITH	\$ 850.00	
7835	Installed/Active	01/10/2007	LTN050G	LOCHINVAR	\$ 850.00	
7836	Installed/Active	03/23/2006	PRX50	STATE	\$ 1,075.00	
7837	Installed/Active	01/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
7838	Installed/Active	02/28/2005	PRX40	STATE	\$ 1,075.00	
7839	Installed/Active	05/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7840	Installed/Active	01/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7841	Installed/Active	02/10/1998	PRV50NODS	STATE	\$ 1,075.00	
7842	Installed/Active	07/05/2010	PRX50	STATE	\$ 1,075.00	\$ 16.91
7843	Installed/Active	05/05/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
7844	Installed/Active	11/14/2001	FSG50	AO SMITH	\$ 850.00	
7845	Installed/Active	10/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7846	Installed/Active	12/01/2000	41V50	RHEEM	\$ 850.00	
7847	Installed/Active	04/19/2002	FSG50	AO SMITH	\$ 850.00	
7848	Installed/Active	12/18/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
7849	Installed/Active	12/20/1988	FSG50	AO SMITH	\$ 850.00	
7850	Installed/Active	10/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
7851	Installed/Active	08/31/2004	XVR50	A. O. SMITH	\$ 850.00	
7852	Installed/Active	06/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7853	Installed/Active	02/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7854	Installed/Active	03/09/2004	PVR50	AO SMITH	\$ 850.00	
7855	Installed/Active	03/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
7856	Installed/Active	10/17/1998	FGR50	AO SMITH	\$ 850.00	
7857	Installed/Active	08/17/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
7858	Installed/Active	02/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7859	Installed/Active	02/23/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7860	Installed/Active	07/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7861	Installed/Active	06/21/2004	GVC50	A. O. SMITH	\$ 850.00	
7862	Installed/Active	02/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7863	Installed/Active	09/30/1987	FSG50	AO SMITH	\$ 850.00	
7864	Installed/Active	05/02/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.64
7865	Installed/Active	03/02/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
7866	Installed/Active	06/20/2003	FSG50	AO SMITH	\$ 850.00	
7867	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7868	Installed/Active	04/09/2002	PGR50	AO SMITH	\$ 850.00	
7869	Installed/Active	06/24/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
7870	Installed/Active	10/10/2002	BTR198	AO SMITH	\$ 3,350.00	
7871	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7872	Installed/Active	10/18/1988	FSG50	AO SMITH	\$ 850.00	
7873	Installed/Active	08/16/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
7874	Installed/Active	08/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7875	Installed/Active	11/14/2001	FSG50	AO SMITH	\$ 850.00	
7876	Installed/Active	07/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7877	Installed/Active	05/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7878	Installed/Active	01/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7879	Installed/Active	08/16/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
7880	Installed/Active	01/27/1988	FSG50	AO SMITH	\$ 850.00	
7881	Installed/Active	01/04/1988	FSG50	AO SMITH	\$ 850.00	
7882	Installed/Active	03/09/1988	FSG50	AO SMITH	\$ 850.00	
7883	Installed/Active	03/12/2000	FSG50	AO SMITH	\$ 850.00	
7884	Installed/Active	07/22/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7885	Installed/Active	01/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
7886	Installed/Active	03/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7887	Installed/Active	04/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7888	Installed/Active	08/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7889	Installed/Active	11/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7890	Installed/Active	05/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7891	Installed/Active	01/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7892	Installed/Active	07/22/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7893	Installed/Active	09/15/2010	PRX40	STATE	\$ 1,075.00	\$ 16.91
7894	Installed/Active	08/17/1988	FSG50	AO SMITH	\$ 850.00	
7895	Installed/Active	12/28/2009	FSGL40	AO SMITH	\$ 850.00	\$ 11.74
7896	Installed/Active	05/09/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
7897	Installed/Active	10/24/2004	XVR50	A. O. SMITH	\$ 850.00	
7898	Installed/Active	12/30/2004	GVC50	A. O. SMITH	\$ 850.00	
7899	Installed/Active	06/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
7900	Installed/Active	01/16/1998	41VR50	RHEEM	\$ 850.00	
7901	Installed/Active	12/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7902	Installed/Active	04/25/2005	LTN050	LOCHINVAR	\$ 850.00	
7903	Installed/Active	03/24/2006	LSN041	LOCHINVAR	\$ 850.00	
7904	Installed/Active	12/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7905	Installed/Active	12/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7906	Installed/Active	12/01/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
7907	Installed/Active	01/31/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
7908	Installed/Active	10/15/2004	PRX50	STATE	\$ 1,075.00	
7909	Installed/Active	10/19/2007	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
7910	Installed/Active	05/31/2006	PRX50	STATE	\$ 1,075.00	
7911	Installed/Active	09/23/1997	41V50	RHEEM	\$ 850.00	
7912	Installed/Active	07/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7913	Installed/Active	09/07/1999	FSG50	AO SMITH	\$ 850.00	
7914	Installed/Active	08/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7915	Installed/Active	01/09/1998	PRV50NODS	STATE	\$ 1,075.00	
7916	Installed/Active	01/28/2011	42XR50	RHEEM	\$ 850.00	\$ 12.05
7917	Installed/Active	01/24/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7918	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7919	Installed/Active	01/21/2004	XTN050	LOCHINVAR	\$ 850.00	
7920	Installed/Active	01/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7921	Installed/Active	05/30/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7922	Installed/Active	04/05/2002	FSG40	AO SMITH	\$ 850.00	
7923	Installed/Active	03/24/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7924	Installed/Active	04/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7925	Installed/Active	07/28/2004	XTN050	LOCHINVAR	\$ 850.00	
7926	Installed/Active	12/28/2004	GCVL40	A. O. SMITH	\$ 850.00	
7927	Installed/Active	07/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7928	Installed/Active	10/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7929	Installed/Active	05/20/2004	GVC50	A. O. SMITH	\$ 850.00	
7930	Installed/Active	07/06/2005	LTN050	LOCHINVAR	\$ 850.00	
7931	Installed/Active	03/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7932	Installed/Active	02/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7933	Installed/Active	07/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
7934	Installed/Active	12/23/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7935	Installed/Active	04/03/1998	FGR40	AO SMITH	\$ 850.00	
7936	Installed/Active	12/20/2012	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
7937	Installed/Active	02/24/2004	GVC50	A. O. SMITH	\$ 850.00	
7938	Installed/Active	06/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
7939	Installed/Active	12/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7940	Installed/Active	09/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
7941	Installed/Active	01/01/2005	P506	RUUD	\$ 1,150.00	
7942	Installed/Active	12/07/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7943	Installed/Active	10/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7944	Installed/Active	11/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7945	Installed/Active	09/25/2003	21DV50	RHEEM	\$ 1,075.00	
7946	Installed/Active	06/21/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
7947	Installed/Active	08/07/2002	PRX50	STATE	\$ 1,075.00	
7948	Installed/Active	06/02/1989	21V506	RHEEM	\$ 1,150.00	
7949	Installed/Active	03/21/2004	XTN050	LOCHINVAR	\$ 850.00	
7950	Installed/Active	05/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
7951	Installed/Active	03/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
7952	Installed/Active	01/03/2011	41XR50	RHEEM	\$ 850.00	\$ 12.05
7953	Installed/Active	10/19/1989	FSG50	AO SMITH	\$ 850.00	
7954	Installed/Active	01/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7955	Installed/Active	02/21/2004	FCV50	AO SMITH	\$ 850.00	
7956	Installed/Active	12/09/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
7957	Installed/Active	10/28/2001	21V506	RHEEM	\$ 1,150.00	
7958	Installed/Active	01/24/2003	FSG50	AO SMITH	\$ 850.00	
7959	Installed/Active	06/30/1989	PRX50	STATE	\$ 1,075.00	
7960	Installed/Active	04/15/2005	XVR50	A. O. SMITH	\$ 850.00	
7961	Installed/Active	11/26/2007	G82156	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
7962	Installed/Active	03/13/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
7963	Installed/Active	12/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
7964	Installed/Active	08/28/1989	21V506	RHEEM	\$ 1,150.00	
7965	Installed/Active	02/06/2005	XVR50	A. O. SMITH	\$ 850.00	
7966	Installed/Active	06/20/1998	FGR40	AO SMITH	\$ 850.00	
7967	Installed/Active	11/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7968	Installed/Active	12/08/2000	41XR50	RHEEM	\$ 850.00	
7969	Installed/Active	10/27/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
7970	Installed/Active	01/13/2001	41XR50	RHEEM	\$ 850.00	
7971	Installed/Active	12/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
7972	Installed/Active	12/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7973	Installed/Active	01/02/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7974	Installed/Active	01/10/2000	FGR40	AO SMITH	\$ 850.00	
7975	Installed/Active	01/05/2001	PGR50	AO SMITH	\$ 850.00	
7976	Installed/Active	08/13/2000	41XR50	RHEEM	\$ 850.00	
7977	Installed/Active	03/08/2001	PGR50	AO SMITH	\$ 850.00	
7978	Installed/Active	10/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7979	Installed/Active	05/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
7980	Installed/Active	07/05/2001	PGR50	AO SMITH	\$ 850.00	
7981	Installed/Active	08/21/2002	PGR50	AO SMITH	\$ 850.00	
7982	Installed/Active	09/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
7983	Installed/Active	12/02/1988	FSG50	AO SMITH	\$ 850.00	
7984	Installed/Active	05/29/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
7985	Installed/Active	01/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7986	Installed/Active	12/29/2005	PR650	STATE	\$ 1,075.00	
7987	Installed/Active	08/28/1989	FSG50	AO SMITH	\$ 850.00	
7988	Installed/Active	06/20/2000	FSG50	AO SMITH	\$ 850.00	
7989	Installed/Active	02/04/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
7990	Installed/Active	05/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7991	Installed/Active	08/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
7992	Installed/Active	11/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7993	Installed/Active	06/20/2003	PRX50	STATE	\$ 1,075.00	
7994	Installed/Active	04/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
7995	Installed/Active	12/12/2000	G82156	RUUD/RHEEM	\$ 3,350.00	
7996	Installed/Active	07/22/2002	FSG50	AO SMITH	\$ 850.00	
7997	Installed/Active	10/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
7998	Installed/Active	04/05/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
7999	Installed/Active	01/03/2003	PGR50	AO SMITH	\$ 850.00	
8000	Installed/Active	07/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8001	Installed/Active	08/12/2002	PRX50	STATE	\$ 1,075.00	
8002	Installed/Active	09/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8003	Installed/Active	01/27/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
8004	Installed/Active	03/13/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8005	Installed/Active	05/24/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
8006	Installed/Active	05/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8007	Installed/Active	10/13/2005	LTN050	LOCHINVAR	\$ 850.00	
8008	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8009	Installed/Active	04/09/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
8010	Installed/Active	11/11/1988	FSG40	AO SMITH	\$ 850.00	
8011	Installed/Active	12/07/1998	FSG50	AO SMITH	\$ 850.00	
8012	Installed/Active	11/08/1988	FSG50	AO SMITH	\$ 850.00	
8013	Installed/Active	06/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
8014	Installed/Active	05/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
8015	Installed/Active	10/10/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8016	Installed/Active	09/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
8017	Installed/Active	03/10/2003	FSGL40	AO SMITH	\$ 850.00	
8018	Installed/Active	01/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8019	Installed/Active	11/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8020	Installed/Active	04/21/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8021	Installed/Active	01/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8022	Installed/Active	03/28/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
8023	Installed/Active	05/12/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8024	Installed/Active	03/02/2001	41XR50	RHEEM	\$ 850.00	
8025	Installed/Active	10/31/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8026	Installed/Active	02/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8027	Installed/Active	10/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8028	Installed/Active	10/24/1988	P506	RUUD	\$ 1,125.00	
8029	Installed/Active	01/03/2007	LTN050G	LOCHINVAR	\$ 850.00	
8030	Installed/Active	11/21/1998	PR650	STATE	\$ 1,075.00	
8031	Installed/Active	10/20/1988	FSGL40	AO SMITH	\$ 850.00	
8032	Installed/Active	02/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8033	Installed/Active	12/11/2001	PR650	STATE	\$ 1,075.00	
8034	Installed/Active	09/21/2001	FSG50	AO SMITH	\$ 850.00	
8035	Installed/Active	01/12/1995	BTC197	AO SMITH	\$ 3,350.00	
8036	Installed/Active	07/19/2003	41XR40	RHEEM	\$ 850.00	
8037	Installed/Active	04/29/2002	FSG50	AO SMITH	\$ 850.00	
8038	Installed/Active	06/10/2003	FSG50	AO SMITH	\$ 850.00	
8039	Installed/Active	03/16/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
8040	Installed/Active	08/28/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
8041	Installed/Active	12/03/1987	FSG50	AO SMITH	\$ 850.00	
8042	Installed/Active	06/18/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
8043	Installed/Active	08/06/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
8044	Installed/Active	12/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8045	Installed/Active	12/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
8046	Installed/Active	03/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8047	Installed/Active	10/28/1998	PGR50	AO SMITH	\$ 850.00	
8048	Installed/Active	06/25/2000	PR650	STATE	\$ 1,075.00	
8049	Installed/Active	10/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
8050	Installed/Active	08/03/2001	PGR50	AO SMITH	\$ 850.00	
8051	Installed/Active	09/28/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8052	Installed/Active	07/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
8053	Installed/Active	11/15/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8054	Installed/Active	06/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8055	Installed/Active	05/12/2004	XTN050	LOCHINVAR	\$ 850.00	
8056	Installed/Active	06/22/2005	LTN050	LOCHINVAR	\$ 850.00	
8057	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8058	Installed/Active	10/17/2011	PR650	STATE	\$ 1,075.00	\$ 17.74
8059	Installed/Active	09/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8060	Installed/Active	11/06/1987	FSG50	AO SMITH	\$ 850.00	
8061	Installed/Active	01/10/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
8062	Installed/Active	12/19/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8063	Installed/Active	05/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8064	Installed/Active	08/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8065	Installed/Active	09/21/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
8066	Installed/Active	07/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8067	Installed/Active	02/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8068	Installed/Active	06/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8069	Installed/Active	02/02/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
8070	Installed/Active	11/12/2001	FSG50	AO SMITH	\$ 850.00	
8071	Installed/Active	09/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8072	Installed/Active	01/05/2007	PR650	STATE	\$ 1,075.00	
8073	Installed/Active	11/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8074	Installed/Active	02/19/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8075	Installed/Active	02/04/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8076	Installed/Active	03/18/2002	FSG50	AO SMITH	\$ 850.00	
8077	Installed/Active	05/05/2003	PGR50	AO SMITH	\$ 850.00	
8078	Installed/Active	12/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
8079	Installed/Active	11/16/1999	PGR50	AO SMITH	\$ 850.00	
8080	Installed/Active	08/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8081	Installed/Active	09/23/2004	GVC50	A. O. SMITH	\$ 850.00	
8082	Installed/Active	07/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8083	Installed/Active	02/12/2003	FSG40	AO SMITH	\$ 850.00	
8084	Installed/Active	08/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8085	Installed/Active	03/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8086	Installed/Active	06/26/1997	FSG50	AO SMITH	\$ 850.00	
8087	Installed/Active	05/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8088	Installed/Active	10/28/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
8089	Installed/Active	04/09/2009	FSG50	AO SMITH	\$ 850.00	\$ 11.74
8090	Installed/Active	11/13/2000	FSG40	AO SMITH	\$ 850.00	
8091	Installed/Active	12/04/2001	FSG50	AO SMITH	\$ 850.00	
8092	Installed/Active	03/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8093	Installed/Active	04/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8094	Installed/Active	01/31/2005	XTN050	LOCHINVAR	\$ 850.00	
8095	Installed/Active	12/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
8096	Installed/Active	04/15/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
8097	Installed/Active	06/22/2012	PH250SF	RUUD	\$ 850.00	\$ 12.75
8098	Installed/Active	01/18/2000	FSG50	AO SMITH	\$ 850.00	
8099	Installed/Active	11/13/2006	FSG50	AO SMITH	\$ 850.00	
8100	Installed/Active	08/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8101	Installed/Active	12/21/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
8102	Installed/Active	01/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8103	Installed/Active	12/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
8104	Installed/Active	09/13/2005	LTN040	LOCHINVAR	\$ 850.00	
8105	Installed/Active	06/02/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8106	Installed/Active	12/09/2003	FSGL40	AO SMITH	\$ 850.00	
8107	Installed/Active	10/06/2009	PR640	STATE	\$ 1,075.00	\$ 16.47
8108	Installed/Active	01/30/2004	PVR50	AO SMITH	\$ 850.00	
8109	Installed/Active	07/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8110	Installed/Active	02/16/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8111	Installed/Active	02/14/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8112	Installed/Active	04/08/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8113	Installed/Active	09/20/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8114	Installed/Active	09/01/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
8115	Installed/Active	03/05/2003	FSG40	AO SMITH	\$ 850.00	
8116	Installed/Active	11/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
8117	Installed/Active	09/27/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8118	Installed/Active	03/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8119	Installed/Active	09/17/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8120	Installed/Active	04/09/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8121	Installed/Active	01/12/2002	FSG50	AO SMITH	\$ 850.00	
8122	Installed/Active	03/02/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
8123	Installed/Active	01/07/1987	FSG50	AO SMITH	\$ 850.00	
8124	Installed/Active	10/30/1995	PGR50	AO SMITH	\$ 850.00	
8125	Installed/Active	07/25/2002	41XR50	RHEEM	\$ 850.00	
8126	Installed/Active	12/21/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8127	Installed/Active	11/10/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8128	Installed/Active	01/03/2003	PGR50	AO SMITH	\$ 850.00	
8129	Installed/Active	03/15/1991	FSG50	AO SMITH	\$ 850.00	
8130	Installed/Active	10/19/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8131	Installed/Active	09/25/2001	PGR50	AO SMITH	\$ 850.00	
8132	Installed/Active	02/16/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8133	Installed/Active	03/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
8134	Installed/Active	02/03/2003	PGR50	AO SMITH	\$ 850.00	
8135	Installed/Active	12/30/2004	LTN050G	LOCHINVAR	\$ 850.00	
8136	Installed/Active	08/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8137	Installed/Active	12/29/2003	XTN050	LOCHINVAR	\$ 850.00	
8138	Installed/Active	10/20/2005	LTN050G	LOCHINVAR	\$ 850.00	
8139	Installed/Active	09/14/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
8140	Installed/Active	12/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8141	Installed/Active	06/17/2004	XVR50	A. O. SMITH	\$ 850.00	
8142	Installed/Active	02/12/2004	XTN040	LOCHINVAR	\$ 850.00	
8143	Installed/Active	12/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8144	Installed/Active	06/23/1989	FSG50	AO SMITH	\$ 850.00	
8145	Installed/Active	12/23/2001	FSG40	AO SMITH	\$ 850.00	
8146	Installed/Active	08/22/2004	PRX50	STATE	\$ 1,075.00	
8147	Installed/Active	11/26/2001	PRX50	STATE	\$ 1,075.00	
8148	Installed/Active	08/21/2001	41XR50	RHEEM	\$ 1,125.00	
8149	Installed/Active	11/24/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
8150	Installed/Active	05/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8151	Installed/Active	01/02/2002	PGR50	AO SMITH	\$ 850.00	
8152	Installed/Active	05/31/1989	FSG50	AO SMITH	\$ 850.00	
8153	Installed/Active	01/04/2007	LTN050G	LOCHINVAR	\$ 850.00	
8154	Installed/Active	03/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
8155	Installed/Active	02/16/2006	PR650	STATE	\$ 1,075.00	
8156	Installed/Active	09/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8157	Installed/Active	05/01/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
8158	Installed/Active	09/23/1998	FSGL40	AO SMITH	\$ 850.00	
8159	Installed/Active	04/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8160	Installed/Active	04/19/2006	PR650	STATE	\$ 1,075.00	
8161	Installed/Active	06/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8162	Installed/Active	07/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8163	Installed/Active	08/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8164	Installed/Active	09/12/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
8165	Installed/Active	09/11/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8166	Installed/Active	09/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8167	Installed/Active	06/12/2003	FSGL40	AO SMITH	\$ 850.00	
8168	Installed/Active	09/30/2004	LTN050	LOCHINVAR	\$ 850.00	
8169	Installed/Active	05/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8170	Installed/Active	08/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8171	Installed/Active	12/21/2010	42V5065F	RHEEM	\$ 850.00	\$ 12.05
8172	Installed/Active	08/08/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8173	Installed/Active	02/16/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8174	Installed/Active	07/30/2008	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
8175	Installed/Active	11/29/2001	PRX50	STATE	\$ 1,075.00	
8176	Installed/Active	10/23/2003	FCV50	AO SMITH	\$ 850.00	
8177	Installed/Active	09/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8178	Installed/Active	08/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8179	Installed/Active	08/15/1988	21V502	RHEEM	\$ 850.00	
8180	Installed/Active	11/17/2011	42V50SF	RHEEM	\$ 850.00	\$ 12.64
8181	Installed/Active	11/11/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8182	Installed/Active	04/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
8183	Installed/Active	09/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8184	Installed/Active	08/25/2004	GVC50	A. O. SMITH	\$ 850.00	
8185	Installed/Active	08/15/1988	PRX50	STATE	\$ 1,075.00	
8186	Installed/Active	06/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8187	Installed/Active	03/18/2002	PGR50	AO SMITH	\$ 850.00	
8188	Installed/Active	05/31/2005	LTN050	LOCHINVAR	\$ 850.00	
8189	Installed/Active	07/30/2001	PGR50	AO SMITH	\$ 850.00	
8190	Installed/Active	04/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8191	Installed/Active	04/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8192	Installed/Active	10/30/2006	PR650	STATE	\$ 1,075.00	
8193	Installed/Active	11/09/2004	GVC50	A. O. SMITH	\$ 850.00	
8194	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8195	Installed/Active	03/21/2003	FSG50	AO SMITH	\$ 850.00	
8196	Installed/Active	09/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8197	Installed/Active	07/06/2012	P230F	RUUD	\$ 850.00	\$ 12.75
8198	Installed/Active	12/31/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8199	Installed/Active	01/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8200	Installed/Active	06/24/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
8201	Installed/Active	02/07/2005	GVC50	A. O. SMITH	\$ 850.00	
8202	Installed/Active	10/14/2011	PRX50	STATE	\$ 1,075.00	\$ 17.74
8203	Installed/Active	12/08/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8204	Installed/Active	01/07/2004	PR650	STATE	\$ 1,075.00	
8205	Installed/Active	06/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8206	Installed/Active	01/06/1997	RF67120	RUUD	\$ 1,900.00	
8207	Installed/Active	07/10/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
8208	Installed/Active	03/26/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8209	Installed/Active	10/26/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8210	Installed/Active	11/06/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 11.74
8211	Installed/Active	10/10/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8212	Installed/Active	01/15/2003	PGR50	AO SMITH	\$ 850.00	
8213	Installed/Active	10/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
8214	Installed/Active	07/01/1988	FSG50	AO SMITH	\$ 850.00	
8215	Installed/Active	05/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
8216	Installed/Active	02/23/2003	FSG50	AO SMITH	\$ 850.00	
8217	Installed/Active	12/28/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8218	Installed/Active	05/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8219	Installed/Active	10/19/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8220	Installed/Active	02/18/2001	FSG50	AO SMITH	\$ 850.00	
8221	Installed/Active	11/05/2009	PR502T	RUUD	\$ 850.00	\$ 11.74
8222	Installed/Active	06/10/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
8223	Installed/Active	12/05/1986	FSG50	AO SMITH	\$ 850.00	
8224	Installed/Active	08/20/2001	PGR50	AO SMITH	\$ 850.00	
8225	Installed/Active	08/21/2002	PGR50	AO SMITH	\$ 850.00	
8226	Installed/Active	10/24/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
8227	Installed/Active	03/20/2006	PR650	STATE	\$ 1,075.00	
8228	Installed/Active	03/27/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8229	Installed/Active	08/08/2005	LTN051	LOCHINVAR	\$ 1,150.00	
8230	Installed/Active	01/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8231	Installed/Active	10/24/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
8232	Installed/Active	09/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8233	Installed/Active	01/24/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8234	Installed/Active	10/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8235	Installed/Active	06/18/1999	FSG50	AO SMITH	\$ 850.00	
8236	Installed/Active	11/15/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8237	Installed/Active	05/08/2006	PR650	STATE	\$ 1,075.00	
8238	Installed/Active	02/17/2003	PRX40	STATE	\$ 1,075.00	
8239	Installed/Active	11/10/1986	FSG50	AO SMITH	\$ 850.00	
8240	Installed/Active	05/25/2005	LTN050	LOCHINVAR	\$ 850.00	
8241	Installed/Active	08/14/2000	PRX50	STATE	\$ 1,075.00	
8242	Installed/Active	02/28/1998	PGR50	AO SMITH	\$ 850.00	
8243	Installed/Active	04/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8244	Installed/Active	04/29/2005	LTN050	LOCHINVAR	\$ 850.00	
8245	Installed/Active	04/26/1987	FSG50	AO SMITH	\$ 850.00	
8246	Installed/Active	09/23/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8247	Installed/Active	05/09/2005	GVC50	A. O. SMITH	\$ 850.00	
8248	Installed/Active	05/18/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8249	Installed/Active	04/24/1987	FSG50	AO SMITH	\$ 850.00	
8250	Installed/Active	01/28/2002	FSG50	AO SMITH	\$ 850.00	
8251	Installed/Active	04/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8252	Installed/Active	10/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8253	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8254	Installed/Active	06/05/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
8255	Installed/Active	03/03/2000	FSG50	AO SMITH	\$ 850.00	
8256	Installed/Active	09/22/1999	FGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8257	Installed/Active	04/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8258	Installed/Active	07/07/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8259	Installed/Active	04/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8260	Installed/Active	07/13/2005	LTN050	LOCHINVAR	\$ 850.00	
8261	Installed/Active	04/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8262	Installed/Active	07/18/2002	PRX50	STATE	\$ 1,075.00	
8263	Installed/Active	02/26/1996	FSG50	AO SMITH	\$ 850.00	
8264	Installed/Active	05/13/1998	PGR50	AO SMITH	\$ 850.00	
8265	Installed/Active	01/26/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.05
8266	Installed/Active	12/21/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8267	Installed/Active	01/24/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8268	Installed/Active	08/14/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
8269	Installed/Active	07/07/2010	PRX50	STATE	\$ 1,075.00	\$ 16.91
8270	Installed/Active	05/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
8271	Installed/Active	04/06/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8272	Installed/Active	02/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8273	Installed/Active	10/10/2008	PR640	STATE	\$ 1,075.00	\$ 14.35
8274	Installed/Active	06/02/2003	FSG50	AO SMITH	\$ 850.00	
8275	Installed/Active	01/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8276	Installed/Active	02/20/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8277	Installed/Active	03/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8278	Installed/Active	01/16/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
8279	Installed/Active	07/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8280	Installed/Active	06/03/1999	FSG50	AO SMITH	\$ 850.00	
8281	Installed/Active	12/03/2001	PGR50	AO SMITH	\$ 850.00	
8282	Installed/Active	01/05/2004	XTN050	LOCHINVAR	\$ 850.00	
8283	Installed/Active	06/12/1989	FSG50	AO SMITH	\$ 850.00	
8284	Installed/Active	03/22/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8285	Installed/Active	06/22/1989	P502	RUUD	\$ 850.00	
8286	Installed/Active	02/14/2013	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
8287	Installed/Active	03/18/2004	GVC50	A. O. SMITH	\$ 850.00	
8288	Installed/Active	12/10/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8289	Installed/Active	08/03/2005	PR650	STATE	\$ 1,075.00	
8290	Installed/Active	06/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8291	Installed/Active	07/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8292	Installed/Active	09/19/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8293	Installed/Active	05/28/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8294	Installed/Active	11/08/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8295	Installed/Active	06/15/2004	GVC50	A. O. SMITH	\$ 850.00	
8296	Installed/Active	01/06/2007	PR650	STATE	\$ 1,075.00	
8297	Installed/Active	07/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8298	Installed/Active	07/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
8299	Installed/Active	07/26/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8300	Installed/Active	01/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8301	Installed/Active	11/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8302	Installed/Active	09/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8303	Installed/Active	08/04/2006	P506	RUUD	\$ 1,150.00	
8304	Installed/Active	09/11/1989	FSG50	AO SMITH	\$ 850.00	
8305	Installed/Active	06/16/2012	PRX50	STATE	\$ 1,075.00	\$ 17.89
8306	Installed/Active	05/09/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8307	Installed/Active	03/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8308	Installed/Active	10/18/2006	PR650	STATE	\$ 1,075.00	
8309	Installed/Active	03/22/2001	FSG50	AO SMITH	\$ 850.00	
8310	Installed/Active	02/12/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8311	Installed/Active	07/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8312	Installed/Active	09/10/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8313	Installed/Active	07/08/2002	PRX50	STATE	\$ 1,075.00	
8314	Installed/Active	03/09/1988	FSG40	AO SMITH	\$ 850.00	
8315	Installed/Active	04/22/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8316	Installed/Active	02/28/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
8317	Installed/Active	09/22/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8318	Installed/Active	03/04/2003	PGR50	AO SMITH	\$ 850.00	
8319	Installed/Active	04/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
8320	Installed/Active	11/16/2012	PRX50	STATE	\$ 1,075.00	\$ 17.89
8321	Installed/Active	06/27/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
8322	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
8323	Installed/Active	02/24/2004	XTN050	LOCHINVAR	\$ 850.00	
8324	Installed/Active	09/21/2004	GVC50	A. O. SMITH	\$ 850.00	
8325	Installed/Active	07/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8326	Installed/Active	05/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
8327	Installed/Active	09/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
8328	Installed/Active	12/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8329	Installed/Active	09/21/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
8330	Installed/Active	05/10/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
8331	Installed/Active	10/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8332	Installed/Active	09/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
8333	Installed/Active	12/16/2005	GVC50	A. O. SMITH	\$ 850.00	
8334	Installed/Active	01/05/2007	PR650	STATE	\$ 1,075.00	
8335	Installed/Active	06/20/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
8336	Installed/Active	08/30/2004	XTN040	LOCHINVAR	\$ 850.00	
8337	Installed/Active	09/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8338	Installed/Active	08/01/2005	LTN050	LOCHINVAR	\$ 850.00	
8339	Installed/Active	01/05/2007	PR640	STATE	\$ 1,075.00	
8340	Installed/Active	07/01/1999	FSGL40	AO SMITH	\$ 850.00	
8341	Installed/Active	07/26/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
8342	Installed/Active	07/07/1988	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8343	Installed/Active	02/16/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8344	Installed/Active	12/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
8345	Installed/Active	08/01/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
8346	Installed/Active	12/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8347	Installed/Active	10/01/1996	PGR50	AO SMITH	\$ 850.00	
8348	Installed/Active	07/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8349	Installed/Active	10/23/2003	FCV50	AO SMITH	\$ 850.00	
8350	Installed/Active	01/15/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
8351	Installed/Active	01/06/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8352	Installed/Active	05/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8353	Installed/Active	12/28/1998	21VR50	RHEEM	\$ 850.00	
8354	Installed/Active	12/09/1996	PRV50NODS	STATE	\$ 1,075.00	
8355	Installed/Active	09/26/2003	41XR50	RHEEM	\$ 850.00	
8356	Installed/Active	03/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8357	Installed/Active	07/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8358	Installed/Active	06/11/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8359	Installed/Active	07/20/2000	41XR50	RHEEM	\$ 850.00	
8360	Installed/Active	04/25/1997	G72DUMMY	AO SMITH	\$ 1,750.00	
8361	Installed/Active	10/17/2000	41XR50	RHEEM	\$ 850.00	
8362	Installed/Active	11/04/1986	FSG50	AO SMITH	\$ 850.00	
8363	Installed/Active	04/08/2008	ETN076	LOCHINVAR	\$ 3,350.00	\$ 51.80
8364	Installed/Active	10/24/2003	41XR50	RHEEM	\$ 850.00	
8365	Installed/Active	01/26/1995	PHR50	RUUD	\$ 850.00	
8366	Installed/Active	04/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8367	Installed/Active	09/14/1994	FSGL40	AO SMITH	\$ 850.00	
8368	Installed/Active	02/14/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8369	Installed/Active	11/25/1998	FSG50	AO SMITH	\$ 850.00	
8370	Installed/Active	10/22/2001	FSG50	AO SMITH	\$ 850.00	
8371	Installed/Active	02/16/2002	PGR50	AO SMITH	\$ 850.00	
8372	Installed/Active	08/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8373	Installed/Active	01/07/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8374	Installed/Active	07/02/2000	PGR50	AO SMITH	\$ 850.00	
8375	Installed/Active	09/10/1997	PGR50	AO SMITH	\$ 850.00	
8376	Installed/Active	01/05/2004	PVR50	AO SMITH	\$ 1,075.00	
8377	Installed/Active	03/03/2006	PR650X0DS	STATE	\$ 1,075.00	
8378	Installed/Active	08/27/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8379	Installed/Active	08/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8380	Installed/Active	01/13/2005	PRX40	STATE	\$ 1,075.00	
8381	Installed/Active	01/27/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8382	Installed/Active	04/29/2005	LTN050	LOCHINVAR	\$ 850.00	
8383	Installed/Active	05/12/1997	PGR50	AO SMITH	\$ 850.00	
8384	Installed/Active	11/05/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8385	Installed/Active	11/30/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8386	Installed/Active	05/23/2000	PGR50	AO SMITH	\$ 850.00	
8387	Installed/Active	07/25/2000	41XR50	RHEEM	\$ 850.00	
8388	Installed/Active	09/11/2003	FCV50	AO SMITH	\$ 850.00	
8389	Installed/Active	12/05/1986	PRX50	STATE	\$ 1,075.00	
8390	Installed/Active	06/05/1998	FGR50	AO SMITH	\$ 850.00	
8391	Installed/Active	10/19/1997	PHR50	RUUD	\$ 850.00	
8392	Installed/Active	01/15/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8393	Installed/Active	07/01/1987	PRV50NODS	STATE	\$ 1,075.00	
8394	Installed/Active	01/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8395	Installed/Active	12/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8396	Installed/Active	07/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8397	Installed/Active	12/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8398	Installed/Active	02/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8399	Installed/Active	01/22/2003	PRX40	STATE	\$ 1,075.00	
8400	Installed/Active	01/15/1987	FSG50	AO SMITH	\$ 850.00	
8401	Installed/Active	01/28/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
8402	Installed/Active	05/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8403	Installed/Active	02/04/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8404	Installed/Active	04/28/2010	SBF100199NET	STATE	\$ 3,350.00	\$ 61.05
8405	Installed/Active	05/29/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
8406	Installed/Active	02/06/2002	41V50	RHEEM	\$ 850.00	
8407	Installed/Active	11/20/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8408	Installed/Active	01/23/1989	PRV50NODS	STATE	\$ 1,075.00	
8409	Installed/Active	04/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8410	Installed/Active	02/17/2006	LTN050	LOCHINVAR	\$ 850.00	
8411	Installed/Active	08/26/1989	RF82156	RUUD	\$ 3,350.00	
8412	Installed/Active	08/26/2004	XTN050	LOCHINVAR	\$ 850.00	
8413	Installed/Active	02/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8414	Installed/Active	07/26/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
8415	Installed/Active	05/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8416	Installed/Active	11/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8417	Installed/Active	06/06/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8418	Installed/Active	08/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8419	Installed/Active	07/15/1989	D74DUMMY	AO SMITH	\$ 1,900.00	
8420	Installed/Active	03/10/2001	41XR50	RHEEM	\$ 850.00	
8421	Installed/Active	11/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8422	Installed/Active	04/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8423	Installed/Active	11/30/2000	PGR50	AO SMITH	\$ 850.00	
8424	Installed/Active	12/21/1989	FSG50	AO SMITH	\$ 850.00	
8425	Installed/Active	03/11/2004	PRX50	STATE	\$ 1,075.00	
8426	Installed/Active	02/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8427	Installed/Active	11/09/2006	LTN040G	LOCHINVAR	\$ 850.00	
8428	Installed/Active	07/06/2004	41XR50	RHEEM	\$ 1,150.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8429	Installed/Active	10/09/2005	LTN050	LOCHINVAR	\$ 850.00	
8430	Installed/Active	04/29/2004	FCV50	AO SMITH	\$ 850.00	
8431	Installed/Active	08/21/2012	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 20.38
8432	Installed/Active	03/16/2005	PRX40	STATE	\$ 1,075.00	
8433	Installed/Active	07/17/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8434	Installed/Active	04/16/2002	PR650	STATE	\$ 1,075.00	
8435	Installed/Active	10/11/2005	LTN050	LOCHINVAR	\$ 1,150.00	
8436	Installed/Active	06/05/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8437	Installed/Active	09/08/2005	LTN040	LOCHINVAR	\$ 850.00	
8438	Installed/Active	04/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8439	Installed/Active	05/11/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
8440	Installed/Active	05/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8441	Installed/Active	06/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8442	Installed/Active	11/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
8443	Installed/Active	01/10/2003	FSG50	AO SMITH	\$ 850.00	
8444	Installed/Active	03/09/2012	MIS036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8445	Installed/Active	07/12/1989	FSG50	AO SMITH	\$ 850.00	
8446	Installed/Active	02/16/1989	FSG50	AO SMITH	\$ 850.00	
8447	Installed/Active	01/28/2007	FSGL40	AO SMITH	\$ 350.00	\$ 12.50
8448	Installed/Active	06/13/2000	41V40S	RHEEM	\$ 850.00	
8449	Installed/Active	06/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
8450	Installed/Active	01/02/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8451	Installed/Active	08/11/1997	PGR50	AO SMITH	\$ 850.00	
8452	Installed/Active	09/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8453	Installed/Active	11/21/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8454	Installed/Active	06/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
8455	Installed/Active	03/02/2004	FCV50	AO SMITH	\$ 850.00	
8456	Installed/Active	01/29/2007	FSGL40	AO SMITH	\$ 350.00	\$ 12.50
8457	Installed/Active	09/27/2002	PRX50	STATE	\$ 1,075.00	
8458	Installed/Active	02/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
8459	Installed/Active	06/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8460	Installed/Active	12/27/2002	PGR50	AO SMITH	\$ 850.00	
8461	Installed/Active	12/03/2001	FSG50	AO SMITH	\$ 850.00	
8462	Installed/Active	06/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
8463	Installed/Active	04/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
8464	Installed/Active	12/28/1987	FSG50	AO SMITH	\$ 850.00	
8465	Installed/Active	01/16/2000	41XR50	RHEEM	\$ 850.00	
8466	Installed/Active	06/08/2005	XSN040	LOCHINVAR	\$ 850.00	
8467	Installed/Active	06/04/2003	PGR50	AO SMITH	\$ 850.00	
8468	Installed/Active	01/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8469	Installed/Active	09/19/1992	FSG30	AO SMITH	\$ 350.00	
8470	Installed/Active	12/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8471	Installed/Active	10/08/2012	MIS036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8472	Installed/Active	05/24/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
8473	Installed/Active	11/30/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8474	Installed/Active	04/21/2004	XTN050	LOCHINVAR	\$ 850.00	
8475	Installed/Active	04/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8476	Installed/Active	12/28/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
8477	Installed/Active	11/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8478	Installed/Active	08/02/2002	FSG50	AO SMITH	\$ 850.00	
8479	Installed/Active	01/31/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8480	Installed/Active	04/20/2002	PRX50	STATE	\$ 1,075.00	
8481	Installed/Active	06/02/1994	P506	RUUD	\$ 1,125.00	
8482	Installed/Active	05/22/2000	PRX50	STATE	\$ 1,075.00	
8483	Installed/Active	10/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
8484	Installed/Active	05/13/2002	PRX50	STATE	\$ 1,075.00	
8485	Installed/Active	01/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8486	Installed/Active	05/13/1988	FSG40	AO SMITH	\$ 850.00	
8487	Installed/Active	02/07/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8488	Installed/Active	08/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
8489	Installed/Active	08/05/2008	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
8490	Installed/Active	07/23/2004	FCV40	AO SMITH	\$ 850.00	
8491	Installed/Active	03/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8492	Installed/Active	05/04/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
8493	Installed/Active	02/24/1987	21V407	RHEEM	\$ 850.00	
8494	Installed/Active	10/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8495	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8496	Installed/Active	06/01/2004	GVC50	A. O. SMITH	\$ 850.00	
8497	Installed/Active	06/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8498	Installed/Active	08/24/2004	GVC50	A. O. SMITH	\$ 850.00	
8499	Installed/Active	03/04/1987	PRX50	STATE	\$ 1,075.00	
8500	Installed/Active	04/16/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
8501	Installed/Active	10/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
8502	Installed/Active	05/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8503	Installed/Active	11/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8504	Installed/Active	03/03/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8505	Installed/Active	01/15/2000	FSGL40	AO SMITH	\$ 850.00	
8506	Installed/Active	04/29/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
8507	Installed/Active	11/30/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8508	Installed/Active	06/20/2005	LTN050	LOCHINVAR	\$ 850.00	
8509	Installed/Active	05/20/2004	CPN199100	LOCHINVAR	\$ 3,350.00	
8510	Installed/Active	08/30/2000	FSG40	AO SMITH	\$ 850.00	
8511	Installed/Active	06/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8512	Installed/Active	08/01/1986	P506	RUUD	\$ 1,125.00	
8513	Installed/Active	09/09/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
8514	Installed/Active	02/26/2003	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8515	Installed/Active	06/08/2001	PRX50	STATE	\$ 1,075.00	
8516	Installed/Active	07/15/2004	XTN050	LOCHINVAR	\$ 850.00	
8517	Installed/Active	06/25/2002	FSG50	AO SMITH	\$ 850.00	
8518	Installed/Active	12/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8519	Installed/Active	02/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8520	Installed/Active	08/09/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8521	Installed/Active	06/06/2004	GCVL40	A. O. SMITH	\$ 850.00	
8522	Installed/Active	12/10/1999	PGR50	AO SMITH	\$ 850.00	
8523	Installed/Active	04/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
8524	Installed/Active	07/09/2004	XVR50	A. O. SMITH	\$ 850.00	
8525	Installed/Active	10/21/1987	FSG50	AO SMITH	\$ 850.00	
8526	Installed/Active	02/26/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
8527	Installed/Active	09/07/2001	PR650	STATE	\$ 1,075.00	
8528	Installed/Active	06/08/2002	FSG50	AO SMITH	\$ 850.00	
8529	Installed/Active	08/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8530	Installed/Active	01/02/2006	LTN040G	LOCHINVAR	\$ 850.00	
8531	Installed/Active	11/30/2005	LTN050G	LOCHINVAR	\$ 850.00	
8532	Installed/Active	08/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8533	Installed/Active	12/14/2002	FSG50	AO SMITH	\$ 850.00	
8534	Installed/Active	08/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8535	Installed/Active	11/16/2011	M403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8536	Installed/Active	11/13/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
8537	Installed/Active	02/09/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8538	Installed/Active	05/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8539	Installed/Active	01/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8540	Installed/Active	01/09/2004	41VR50	RHEEM	\$ 850.00	
8541	Installed/Active	08/09/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
8542	Installed/Active	12/15/1989	FSG50	AO SMITH	\$ 850.00	
8543	Installed/Active	08/30/2002	21V506	RHEEM	\$ 1,125.00	
8544	Installed/Active	02/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
8545	Installed/Active	06/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8546	Installed/Active	02/26/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
8547	Installed/Active	03/17/1989	P506	RUUD	\$ 1,150.00	
8548	Installed/Active	06/05/2006	PR650	STATE	\$ 1,075.00	
8549	Installed/Active	02/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
8550	Installed/Active	03/17/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8551	Installed/Active	12/07/2005	LTN050G	LOCHINVAR	\$ 850.00	
8552	Installed/Active	08/23/2000	41XR50	RHEEM	\$ 850.00	
8553	Installed/Active	02/25/1999	FGR50	AO SMITH	\$ 850.00	
8554	Installed/Active	12/21/2005	LTN051G	LOCHINVAR	\$ 1,150.00	
8555	Installed/Active	06/20/1989	FSG40	AO SMITH	\$ 850.00	
8556	Installed/Active	09/20/2005	LTN040	LOCHINVAR	\$ 850.00	
8557	Installed/Active	02/07/2001	41XR50	RHEEM	\$ 850.00	
8558	Installed/Active	02/25/2002	PGR50	AO SMITH	\$ 850.00	
8559	Installed/Active	06/24/2004	GVC50	A. O. SMITH	\$ 850.00	
8560	Installed/Active	06/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8561	Installed/Active	10/22/2001	PGR50	AO SMITH	\$ 850.00	
8562	Installed/Active	05/13/2005	LTN050	LOCHINVAR	\$ 850.00	
8563	Installed/Active	08/29/1989	FSG50	AO SMITH	\$ 850.00	
8564	Installed/Active	12/28/1988	FSG40	AO SMITH	\$ 850.00	
8565	Installed/Active	01/10/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8566	Installed/Active	01/22/2003	PRX50	STATE	\$ 1,075.00	
8567	Installed/Active	01/27/2007	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
8568	Installed/Active	03/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8569	Installed/Active	10/16/2005	LTN050G	LOCHINVAR	\$ 850.00	
8570	Installed/Active	03/03/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8571	Installed/Active	07/12/1989	PRX50	STATE	\$ 1,075.00	
8572	Installed/Active	03/26/2005	GVC50	A. O. SMITH	\$ 850.00	
8573	Installed/Active	07/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8574	Installed/Active	10/27/1995	FGR50	AO SMITH	\$ 850.00	
8575	Installed/Active	10/13/1989	FSG50	AO SMITH	\$ 850.00	
8576	Installed/Active	05/05/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
8577	Installed/Active	02/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8578	Installed/Active	01/01/2000	FSGL40	AO SMITH	\$ 850.00	
8579	Installed/Active	01/17/2005	GVR50	AO SMITH	\$ 850.00	
8580	Installed/Active	11/07/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
8581	Installed/Active	07/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8582	Installed/Active	05/24/1990	FSGL40	AO SMITH	\$ 350.00	
8583	Installed/Active	05/15/2004	XTN050	LOCHINVAR	\$ 850.00	
8584	Installed/Active	07/07/1998	PRV50NODS	STATE	\$ 1,075.00	
8585	Installed/Active	10/21/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8586	Installed/Active	06/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8587	Installed/Active	11/07/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
8588	Installed/Active	02/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8589	Installed/Active	01/15/1990	21V506	RHEEM	\$ 1,150.00	
8590	Installed/Active	05/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8591	Installed/Active	02/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8592	Installed/Active	04/27/2008	B71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	\$ 10.23
8593	Installed/Active	07/26/2004	XTN050	LOCHINVAR	\$ 850.00	
8594	Installed/Active	01/16/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
8595	Installed/Active	04/08/2003	PRX50	STATE	\$ 1,075.00	
8596	Installed/Active	10/01/1992	FSG50	AO SMITH	\$ 850.00	
8597	Installed/Active	04/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8598	Installed/Active	01/22/1993	FSG50	AO SMITH	\$ 850.00	
8599	Installed/Active	01/17/2007	41V50	RHEEM	\$ 850.00	\$ 10.23
8600	Installed/Active	11/11/2004	GVC50	A. O. SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8601	Installed/Active	10/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8602	Installed/Active	01/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8603	Installed/Active	12/13/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
8604	Installed/Active	12/10/2003	FCV50	AO SMITH	\$ 850.00	
8605	Installed/Active	04/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8606	Installed/Active	11/30/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8607	Installed/Active	04/03/2001	PGR50	AO SMITH	\$ 850.00	
8608	Installed/Active	07/30/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8609	Installed/Active	01/02/2012	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.64
8610	Installed/Active	11/12/2005	LTN050G	LOCHINVAR	\$ 850.00	
8611	Installed/Active	03/12/2013	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
8612	Installed/Active	07/14/1999	FSG50	AO SMITH	\$ 850.00	
8613	Installed/Active	07/08/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
8614	Installed/Active	07/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8615	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8616	Installed/Active	06/28/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
8617	Installed/Active	06/21/2004	GVC40	A. O. SMITH	\$ 850.00	
8618	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8619	Installed/Active	01/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8620	Installed/Active	01/07/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8621	Installed/Active	12/29/2005	LTN040G	LOCHINVAR	\$ 850.00	
8622	Installed/Active	05/12/2003	PGR50	AO SMITH	\$ 850.00	
8623	Installed/Active	04/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8624	Installed/Active	03/12/1997	BTC197	AO SMITH	\$ 3,350.00	
8625	Installed/Active	08/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8626	Installed/Active	09/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8627	Installed/Active	01/10/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
8628	Installed/Active	08/02/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8629	Installed/Active	07/25/2005	LTN050	LOCHINVAR	\$ 850.00	
8630	Installed/Active	12/22/1987	FSG50	AO SMITH	\$ 850.00	
8631	Installed/Active	01/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8632	Installed/Active	02/06/2008	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8633	Installed/Active	01/04/2001	PRX50	STATE	\$ 1,075.00	
8634	Installed/Active	04/12/1988	FSG50	AO SMITH	\$ 850.00	
8635	Installed/Active	06/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
8636	Installed/Active	04/16/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
8637	Installed/Active	12/10/1996	FSG50	AO SMITH	\$ 850.00	
8638	Installed/Active	10/07/1988	P506	RUUD	\$ 1,125.00	
8639	Installed/Active	03/03/1988	PH30	RUUD	\$ 350.00	
8640	Installed/Active	06/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8641	Installed/Active	07/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
8642	Installed/Active	04/03/2001	41XR50	RHEEM	\$ 850.00	
8643	Installed/Active	08/26/1988	FSG50	AO SMITH	\$ 850.00	
8644	Installed/Active	01/13/2004	FCV50	AO SMITH	\$ 850.00	
8645	Installed/Active	11/22/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8646	Installed/Active	12/16/2003	PRX50	STATE	\$ 1,075.00	
8647	Installed/Active	01/17/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8648	Installed/Active	07/01/2005	LTN050	LOCHINVAR	\$ 850.00	
8649	Installed/Active	04/14/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8650	Installed/Active	12/01/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8651	Installed/Active	07/09/1988	FSG50	AO SMITH	\$ 850.00	
8652	Installed/Active	01/07/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 16.91
8653	Installed/Active	08/24/1999	PHR50	RUUD	\$ 850.00	
8654	Installed/Active	10/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8655	Installed/Active	03/12/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
8656	Installed/Active	03/30/2004	FCV50	AO SMITH	\$ 850.00	
8657	Installed/Active	02/17/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8658	Installed/Active	02/04/1988	PRV50NODS	STATE	\$ 1,075.00	
8659	Installed/Active	03/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8660	Installed/Active	11/03/2007	FSGL40	AO SMITH	\$ 850.00	\$ 10.23
8661	Installed/Active	09/22/2004	GVC50	A. O. SMITH	\$ 850.00	
8662	Installed/Active	04/21/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8663	Installed/Active	12/07/2001	PRX50	STATE	\$ 1,075.00	
8664	Installed/Active	05/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8665	Installed/Active	10/10/2001	PGR50	AO SMITH	\$ 850.00	
8666	Installed/Active	01/13/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8667	Installed/Active	11/15/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
8668	Installed/Active	12/05/2004	FSG50	AO SMITH	\$ 850.00	
8669	Installed/Active	11/02/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
8670	Installed/Active	12/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
8671	Installed/Active	01/09/2002	FSG50	AO SMITH	\$ 850.00	
8672	Installed/Active	10/19/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8673	Installed/Active	04/20/1990	FSG50	AO SMITH	\$ 850.00	
8674	Installed/Active	05/14/2000	41XR50	RHEEM	\$ 850.00	
8675	Installed/Active	01/06/1996	PGR50	AO SMITH	\$ 850.00	
8676	Installed/Active	08/23/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
8677	Installed/Active	11/02/2004	GVC50	A. O. SMITH	\$ 850.00	
8678	Installed/Active	11/22/2002	FSG50	AO SMITH	\$ 850.00	
8679	Installed/Active	09/21/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
8680	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8681	Installed/Active	02/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8682	Installed/Active	11/02/2004	GVC50	A. O. SMITH	\$ 850.00	
8683	Installed/Active	04/23/2002	PGR50	AO SMITH	\$ 850.00	
8684	Installed/Active	01/28/2008	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8685	Installed/Active	09/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8686	Installed/Active	10/09/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8687	Installed/Active	12/28/2001	PR650	STATE	\$ 1,075.00	
8688	Installed/Active	07/26/2001	PGR40	AO SMITH	\$ 850.00	
8689	Installed/Active	05/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8690	Installed/Active	05/13/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8691	Installed/Active	11/23/2002	PGR50	AO SMITH	\$ 850.00	
8692	Installed/Active	03/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8693	Installed/Active	07/15/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8694	Installed/Active	01/29/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8695	Installed/Active	09/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8696	Installed/Active	03/26/2003	FSGT50	AO SMITH	\$ 1,150.00	
8697	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8698	Installed/Active	01/31/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
8699	Installed/Active	10/11/2003	41V50S	RHEEM	\$ 850.00	
8700	Installed/Active	01/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8701	Installed/Active	10/20/2003	41XR50	RHEEM	\$ 850.00	
8702	Installed/Active	12/15/1996	FGR50	AO SMITH	\$ 850.00	
8703	Installed/Active	07/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8704	Installed/Active	03/22/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8705	Installed/Active	05/13/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8706	Installed/Active	09/23/2009	21VR50	RHEEM	\$ 850.00	\$ 11.74
8707	Installed/Active	05/03/1990	FSG50	AO SMITH	\$ 850.00	
8708	Installed/Active	06/14/2000	FSSL40	AO SMITH	\$ 850.00	
8709	Installed/Active	10/17/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8710	Installed/Active	01/23/2004	XTN050	LOCHINVAR	\$ 850.00	
8711	Installed/Active	09/20/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8712	Installed/Active	06/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8713	Installed/Active	12/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8714	Installed/Active	03/08/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8715	Installed/Active	12/05/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
8716	Installed/Active	12/09/1988	FSG50	AO SMITH	\$ 850.00	
8717	Installed/Active	05/21/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
8718	Installed/Active	01/24/1989	P506	RUUD	\$ 1,125.00	
8719	Installed/Active	07/15/1997	RFD91200	RUUD	\$ 3,350.00	
8720	Installed/Active	11/03/2003	PVR40	AO SMITH	\$ 850.00	
8721	Installed/Active	08/07/2006	PR650	STATE	\$ 1,075.00	
8722	Installed/Active	11/27/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
8723	Installed/Active	08/07/2004	GVC50	A. O. SMITH	\$ 850.00	
8724	Installed/Active	07/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8725	Installed/Active	10/23/2003	FSG50	AO SMITH	\$ 850.00	
8726	Installed/Active	03/08/1989	FSG50	AO SMITH	\$ 850.00	
8727	Installed/Active	04/02/2003	PGR50	AO SMITH	\$ 850.00	
8728	Installed/Active	09/05/1997	FSG50	AO SMITH	\$ 850.00	
8729	Installed/Active	03/27/2001	PRV50NODS	STATE	\$ 1,075.00	
8730	Installed/Active	03/06/2000	FSG50	AO SMITH	\$ 850.00	
8731	Installed/Active	09/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8732	Installed/Active	01/10/2003	PGR50	AO SMITH	\$ 850.00	
8733	Installed/Active	05/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
8734	Installed/Active	05/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8735	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8736	Installed/Active	03/03/1989	FSG50	AO SMITH	\$ 850.00	
8737	Installed/Active	03/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8738	Installed/Active	05/08/1989	P506	RUUD	\$ 1,125.00	
8739	Installed/Active	04/07/2001	PRX50	STATE	\$ 1,075.00	
8740	Installed/Active	06/03/2002	PGR50	AO SMITH	\$ 850.00	
8741	Installed/Active	02/22/1999	FSG50	AO SMITH	\$ 850.00	
8742	Installed/Active	01/05/2007	LTN050G	LOCHINVAR	\$ 850.00	
8743	Installed/Active	12/22/1997	41VR50	RHEEM	\$ 850.00	
8744	Installed/Active	02/22/2000	FSG50	AO SMITH	\$ 850.00	
8745	Installed/Active	04/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8746	Installed/Active	06/01/2004	PRX50	STATE	\$ 1,075.00	
8747	Installed/Active	05/03/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
8748	Installed/Active	01/28/1999	41VR50	RHEEM	\$ 850.00	
8749	Installed/Active	06/03/2003	FSSL40	AO SMITH	\$ 850.00	
8750	Installed/Active	07/02/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
8751	Installed/Active	08/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8752	Installed/Active	08/08/2003	FSG50	AO SMITH	\$ 850.00	
8753	Installed/Active	07/27/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8754	Installed/Active	02/04/2010	22DV50F	RHEEM	\$ 850.00	\$ 11.74
8755	Installed/Active	04/28/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
8756	Installed/Active	07/18/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8757	Installed/Active	12/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8758	Installed/Active	11/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
8759	Installed/Active	01/19/2005	G76200	RUUD/RHEEM	\$ 3,350.00	
8760	Installed/Active	09/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8761	Installed/Active	11/01/2003	41V50	RHEEM	\$ 850.00	
8762	Installed/Active	11/29/1995	G91200	RUUD/RHEEM	\$ 3,350.00	
8763	Installed/Active	05/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8764	Installed/Active	03/03/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8765	Installed/Active	09/16/2003	PVR50	AO SMITH	\$ 850.00	
8766	Installed/Active	08/23/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
8767	Installed/Active	01/29/1999	PR650	STATE	\$ 1,075.00	
8768	Installed/Active	12/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
8769	Installed/Active	09/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8770	Installed/Active	03/02/1987	FSG50	AO SMITH	\$ 850.00	
8771	Installed/Active	10/15/2001	PRX50	STATE	\$ 1,075.00	
8772	Installed/Active	11/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8773	Installed/Active	04/29/2004	PGR50	AO SMITH	\$ 850.00	
8774	Installed/Active	02/05/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
8775	Installed/Active	01/13/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
8776	Installed/Active	05/27/1998	41VR50	RHEEM	\$ 850.00	
8777	Installed/Active	04/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8778	Installed/Active	08/16/2006	LTN040G	LOCHINVAR	\$ 850.00	
8779	Installed/Active	09/16/1998	FSG50	AO SMITH	\$ 850.00	
8780	Installed/Active	04/17/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
8781	Installed/Active	04/16/2004	41XR50	RHEEM	\$ 850.00	
8782	Installed/Active	07/21/1997	FGR50	AO SMITH	\$ 850.00	
8783	Installed/Active	11/10/2004	GVC40	A. O. SMITH	\$ 850.00	
8784	Installed/Active	01/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8785	Installed/Active	03/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8786	Installed/Active	10/08/2006	PR650	STATE	\$ 1,075.00	
8787	Installed/Active	03/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
8788	Installed/Active	10/23/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
8789	Installed/Active	04/11/2003	FSG40	AO SMITH	\$ 850.00	
8790	Installed/Active	06/01/1987	PRV50NODS	STATE	\$ 1,075.00	
8791	Installed/Active	03/30/2002	PGR50	AO SMITH	\$ 850.00	
8792	Installed/Active	02/17/2003	PGR50	AO SMITH	\$ 850.00	
8793	Installed/Active	05/03/2005	42VR506	RHEEM	\$ 1,150.00	
8794	Installed/Active	03/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8795	Installed/Active	09/28/2001	41XR50	RHEEM	\$ 850.00	
8796	Installed/Active	05/28/1987	FSG50	AO SMITH	\$ 850.00	
8797	Installed/Active	04/21/1987	FSG40	AO SMITH	\$ 850.00	
8798	Installed/Active	05/01/2002	41V50	RHEEM	\$ 850.00	
8799	Installed/Active	07/02/1999	41VR40	RHEEM	\$ 850.00	
8800	Installed/Active	07/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8801	Installed/Active	11/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8802	Installed/Active	08/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8803	Installed/Active	05/02/2004	SBF100199NES	STATE	\$ 3,350.00	
8804	Installed/Active	01/10/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8805	Installed/Active	07/17/2006	PR640	STATE	\$ 1,075.00	
8806	Installed/Active	01/02/1998	41VR50	RHEEM	\$ 850.00	
8807	Installed/Active	05/30/2006	LTN040G	LOCHINVAR	\$ 850.00	
8808	Installed/Active	08/16/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8809	Installed/Active	11/23/2001	PGR50	AO SMITH	\$ 850.00	
8810	Installed/Active	07/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8811	Installed/Active	10/18/2002	FSG50	AO SMITH	\$ 850.00	
8812	Installed/Active	05/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8813	Installed/Active	08/26/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8814	Installed/Active	08/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
8815	Installed/Active	02/25/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8816	Installed/Active	02/01/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8817	Installed/Active	06/08/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
8818	Installed/Active	08/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8819	Installed/Active	04/26/1991	FSG50	AO SMITH	\$ 850.00	
8820	Installed/Active	01/09/2002	FSG40	AO SMITH	\$ 850.00	
8821	Installed/Active	12/18/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8822	Installed/Active	02/18/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
8823	Installed/Active	04/25/2000	41XR50	RHEEM	\$ 850.00	
8824	Installed/Active	01/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8825	Installed/Active	09/27/2001	PGR50	AO SMITH	\$ 850.00	
8826	Installed/Active	01/28/1999	41VR50	RHEEM	\$ 850.00	
8827	Installed/Active	12/23/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
8828	Installed/Active	01/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8829	Installed/Active	05/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
8830	Installed/Active	08/25/2004	GCVL40	A. O. SMITH	\$ 850.00	
8831	Installed/Active	09/15/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8832	Installed/Active	08/04/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
8833	Installed/Active	04/10/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8834	Installed/Active	06/05/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8835	Installed/Active	12/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8836	Installed/Active	12/08/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8837	Installed/Active	07/01/1988	FSG50	AO SMITH	\$ 850.00	
8838	Installed/Active	01/13/2003	FSG50	AO SMITH	\$ 850.00	
8839	Installed/Active	11/02/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
8840	Installed/Active	08/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
8841	Installed/Active	04/23/1999	FSG50	AO SMITH	\$ 850.00	
8842	Installed/Active	12/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
8843	Installed/Active	01/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8844	Installed/Active	02/24/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8845	Installed/Active	01/06/2007	LTN050G	LOCHINVAR	\$ 850.00	
8846	Installed/Active	04/22/2000	FSG40	AO SMITH	\$ 850.00	
8847	Installed/Active	02/12/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8848	Installed/Active	11/05/2003	21V407	RHEEM	\$ 850.00	
8849	Installed/Active	06/30/1988	FSG50	AO SMITH	\$ 850.00	
8850	Installed/Active	10/05/2000	PGR50	AO SMITH	\$ 850.00	
8851	Installed/Active	02/21/2001	FSG50	AO SMITH	\$ 850.00	
8852	Installed/Active	02/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8853	Installed/Active	08/27/2000	41XR50	RHEEM	\$ 850.00	
8854	Installed/Active	06/28/1988	FSG50	AO SMITH	\$ 850.00	
8855	Installed/Active	05/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8856	Installed/Active	04/04/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8857	Installed/Active	12/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
8858	Installed/Active	12/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8859	Installed/Active	04/13/2002	PGR50	AO SMITH	\$ 850.00	
8860	Installed/Active	11/26/2003	FCV50	AO SMITH	\$ 850.00	
8861	Installed/Active	05/24/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8862	Installed/Active	10/19/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8863	Installed/Active	03/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8864	Installed/Active	06/06/1988	PRX50	STATE	\$ 1,075.00	
8865	Installed/Active	03/16/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8866	Installed/Active	02/04/2002	41VR50	RHEEM	\$ 850.00	
8867	Installed/Active	03/28/2005	PRX50	STATE	\$ 1,075.00	
8868	Installed/Active	09/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8869	Installed/Active	07/15/1988	FSG50	AO SMITH	\$ 850.00	
8870	Installed/Active	01/10/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
8871	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
8872	Installed/Active	04/20/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
8873	Installed/Active	01/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8874	Installed/Active	05/30/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8875	Installed/Active	11/24/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
8876	Installed/Active	11/23/2005	PR650	STATE	\$ 1,075.00	
8877	Installed/Active	07/08/2003	21V506	RHEEM	\$ 1,150.00	
8878	Installed/Active	03/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8879	Installed/Active	03/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8880	Installed/Active	02/14/2001	FSG50	AO SMITH	\$ 850.00	
8881	Installed/Active	01/04/2006	FSG50	AO SMITH	\$ 850.00	
8882	Installed/Active	11/21/1996	RF67120	RUUD	\$ 1,900.00	
8883	Installed/Active	02/05/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8884	Installed/Active	10/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8885	Installed/Active	04/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8886	Installed/Active	09/04/1997	FGR50	AO SMITH	\$ 850.00	
8887	Installed/Active	11/20/2002	PGR50	AO SMITH	\$ 850.00	
8888	Installed/Active	03/10/2004	21DV50	RHEEM	\$ 1,075.00	
8889	Installed/Active	10/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8890	Installed/Active	02/11/2005	XVR50	A. O. SMITH	\$ 850.00	
8891	Installed/Active	08/14/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
8892	Installed/Active	09/15/2009	GDVS40	AOSMITH	\$ 1,075.00	\$ 16.47
8893	Installed/Active	05/30/1990	PRV50NODS	STATE	\$ 1,075.00	
8894	Installed/Active	01/12/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8895	Installed/Active	07/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8896	Installed/Active	11/03/2012	MI75S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.64
8897	Installed/Active	11/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
8898	Installed/Active	11/14/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
8899	Installed/Active	12/02/2004	GVC50	A. O. SMITH	\$ 850.00	
8900	Installed/Active	02/21/1995	FGR50	AO SMITH	\$ 850.00	
8901	Installed/Active	02/24/1999	FGR50	AO SMITH	\$ 850.00	
8902	Installed/Active	12/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
8903	Installed/Active	05/19/2009	LTN051G	LOCHINVAR	\$ 850.00	\$ 11.74
8904	Installed/Active	08/22/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8905	Installed/Active	05/27/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
8906	Installed/Active	10/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
8907	Installed/Active	01/15/2001	PGR50	AO SMITH	\$ 850.00	
8908	Installed/Active	02/02/2001	41V40	RHEEM	\$ 850.00	
8909	Installed/Active	03/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8910	Installed/Active	01/14/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
8911	Installed/Active	07/01/2003	21DV50	RHEEM	\$ 1,075.00	
8912	Installed/Active	04/25/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
8913	Installed/Active	07/02/2001	PRX50	STATE	\$ 1,075.00	
8914	Installed/Active	05/25/2007	ETN076	LOCHINVAR	\$ 3,350.00	\$ 44.60
8915	Installed/Active	01/19/2005	PRX50	STATE	\$ 1,075.00	
8916	Installed/Active	06/29/2001	PRX50	STATE	\$ 1,075.00	
8917	Installed/Active	01/08/1990	PR407	RUUD	\$ 850.00	
8918	Installed/Active	04/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8919	Installed/Active	03/13/2002	PRX50	STATE	\$ 1,075.00	
8920	Installed/Active	06/15/2005	PR650	STATE	\$ 1,075.00	
8921	Installed/Active	01/13/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8922	Installed/Active	08/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
8923	Installed/Active	10/16/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
8924	Installed/Active	09/06/2005	PR650	STATE	\$ 1,075.00	
8925	Installed/Active	08/13/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
8926	Installed/Active	07/08/2004	GVC50	A. O. SMITH	\$ 850.00	
8927	Installed/Active	09/11/1989	21DV50	RHEEM	\$ 1,075.00	
8928	Installed/Active	09/22/2000	FSG50	AO SMITH	\$ 850.00	
8929	Installed/Active	01/17/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
8930	Installed/Active	04/13/2005	PHR50	RUUD	\$ 850.00	
8931	Installed/Active	05/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8932	Installed/Active	06/12/2002	FSG50	AO SMITH	\$ 850.00	
8933	Installed/Active	01/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8934	Installed/Active	09/27/1989	21V502	RHEEM	\$ 850.00	
8935	Installed/Active	05/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
8936	Installed/Active	12/29/1999	FGR50	AO SMITH	\$ 850.00	
8937	Installed/Active	10/23/1989	FSG50	AO SMITH	\$ 850.00	
8938	Installed/Active	02/08/2003	PRX50	STATE	\$ 1,075.00	
8939	Installed/Active	04/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8940	Installed/Active	12/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8941	Installed/Active	03/27/2002	FSG50	AO SMITH	\$ 850.00	
8942	Installed/Active	06/27/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8943	Installed/Active	01/11/2007	LTN050G	LOCHINVAR	\$ 850.00	
8944	Installed/Active	02/12/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
8945	Installed/Active	08/07/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
8946	Installed/Active	12/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
8947	Installed/Active	08/05/2004	PRX50	STATE	\$ 1,075.00	
8948	Installed/Active	12/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
8949	Installed/Active	02/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8950	Installed/Active	09/29/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
8951	Installed/Active	01/28/2005	GDVS50	AOSMITH	\$ 1,075.00	
8952	Installed/Active	09/25/2001	PGR50	AO SMITH	\$ 850.00	
8953	Installed/Active	03/11/2002	PRX50	STATE	\$ 1,075.00	
8954	Installed/Active	09/28/1989	FSG50	AO SMITH	\$ 850.00	
8955	Installed/Active	03/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
8956	Installed/Active	08/10/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8957	Installed/Active	05/15/2002	PGR50	AO SMITH	\$ 850.00	
8958	Installed/Active	02/25/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
8959	Installed/Active	07/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8960	Installed/Active	04/12/1989	P506	RUUD	\$ 500.00	
8961	Installed/Active	11/17/2003	PGR50	AO SMITH	\$ 850.00	
8962	Installed/Active	04/14/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
8963	Installed/Active	05/09/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8964	Installed/Active	10/06/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8965	Installed/Active	03/27/2001	PGR50	AO SMITH	\$ 850.00	
8966	Installed/Active	04/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
8967	Installed/Active	03/26/2012	G75125	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
8968	Installed/Active	06/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
8969	Installed/Active	02/04/2013	G72DUMMY	UNKNOWN AT CONVERSION	\$ 500.00	\$ 20.38
8970	Installed/Active	11/20/1998	PRX50	STATE	\$ 1,075.00	
8971	Installed/Active	08/30/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
8972	Installed/Active	11/26/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
8973	Installed/Active	11/17/2001	FSG50	AO SMITH	\$ 850.00	
8974	Installed/Active	05/23/2005	GVC50	A. O. SMITH	\$ 850.00	
8975	Installed/Active	10/15/1996	FGR50	AO SMITH	\$ 850.00	
8976	Installed/Active	03/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
8977	Installed/Active	07/17/1989	FSG50	AO SMITH	\$ 1,075.00	
8978	Installed/Active	08/01/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8979	Installed/Active	06/03/2005	LTN050	LOCHINVAR	\$ 850.00	
8980	Installed/Active	11/05/2012	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
8981	Installed/Active	06/17/2002	PGR50	AO SMITH	\$ 850.00	
8982	Installed/Active	02/03/1995	PR502T	RUUD	\$ 850.00	
8983	Installed/Active	02/16/2000	FSG50	AO SMITH	\$ 850.00	
8984	Installed/Active	05/23/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
8985	Installed/Active	09/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
8986	Installed/Active	03/02/2001	PGR50	AO SMITH	\$ 850.00	
8987	Installed/Active	06/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
8988	Installed/Active	12/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8989	Installed/Active	05/29/2006	PR650	STATE	\$ 1,075.00	
8990	Installed/Active	01/14/2005	PRX50	STATE	\$ 1,075.00	
8991	Installed/Active	01/18/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
8992	Installed/Active	05/09/2002	FSG40	AO SMITH	\$ 850.00	
8993	Installed/Active	03/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
8994	Installed/Active	08/18/1987	FSG50	AO SMITH	\$ 850.00	
8995	Installed/Active	01/15/1987	FSG50	AO SMITH	\$ 850.00	
8996	Installed/Active	01/16/1997	PGR50	AO SMITH	\$ 850.00	
8997	Installed/Active	12/20/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
8998	Installed/Active	01/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
8999	Installed/Active	01/05/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9000	Installed/Active	12/26/1986	G76200	RUUD/RHEEM	\$ 3,350.00	
9001	Installed/Active	01/08/2004	XTN050	LOCHINVAR	\$ 850.00	
9002	Installed/Active	04/14/2004	GVC50	A. O. SMITH	\$ 850.00	
9003	Installed/Active	03/22/2006	PR650X0DS	STATE	\$ 1,075.00	
9004	Installed/Active	06/22/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9005	Installed/Active	03/03/2001	41V50	RHEEM	\$ 850.00	
9006	Installed/Active	05/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9007	Installed/Active	01/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
9008	Installed/Active	05/02/1997	FGR50	AO SMITH	\$ 850.00	
9009	Installed/Active	04/20/1987	FSG50	AO SMITH	\$ 850.00	
9010	Installed/Active	05/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9011	Installed/Active	03/31/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
9012	Installed/Active	12/23/1999	FGR50	AO SMITH	\$ 850.00	
9013	Installed/Active	09/03/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
9014	Installed/Active	04/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9015	Installed/Active	06/02/2003	PGR50	AO SMITH	\$ 850.00	
9016	Installed/Active	12/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9017	Installed/Active	03/15/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
9018	Installed/Active	12/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9019	Installed/Active	07/05/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9020	Installed/Active	06/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
9021	Installed/Active	05/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9022	Installed/Active	01/17/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
9023	Installed/Active	09/24/1987	P506	RUUD	\$ 1,150.00	
9024	Installed/Active	05/02/2000	PGR50	AO SMITH	\$ 850.00	
9025	Installed/Active	12/14/1998	FGR50	AO SMITH	\$ 850.00	
9026	Installed/Active	03/01/2002	PRX40	STATE	\$ 1,075.00	
9027	Installed/Active	07/11/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
9028	Installed/Active	11/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
9029	Installed/Active	01/20/2005	LTN050	LOCHINVAR	\$ 850.00	
9030	Installed/Active	09/24/1987	P506	RUUD	\$ 1,150.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9031	Installed/Active	02/14/1990	FGR50	AO SMITH	\$ 850.00	
9032	Installed/Active	06/15/2000	G76200	RUUD/RHEEM	\$ 3,350.00	
9033	Installed/Active	10/13/2002	PGR50	AO SMITH	\$ 850.00	
9034	Installed/Active	09/18/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
9035	Installed/Active	10/27/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9036	Installed/Active	02/06/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9037	Installed/Active	06/21/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9038	Installed/Active	04/10/2004	XVR50	A. O. SMITH	\$ 850.00	
9039	Installed/Active	10/12/2004	PRX50	STATE	\$ 1,075.00	
9040	Installed/Active	05/06/2006	PR650	STATE	\$ 1,075.00	
9041	Installed/Active	04/19/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9042	Installed/Active	06/28/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9043	Installed/Active	05/20/1996	I72DUMMY	AO SMITH	\$ 1,900.00	
9044	Installed/Active	08/16/2003	PGR50	AO SMITH	\$ 850.00	
9045	Installed/Active	08/10/1990	FSG50	AO SMITH	\$ 850.00	
9046	Installed/Active	01/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9047	Installed/Active	05/04/1990	FSG50	AO SMITH	\$ 850.00	
9048	Installed/Active	10/03/1989	P506	RUUD	\$ 1,150.00	
9049	Installed/Active	12/09/2005	B71DUMMY	AMERICAN	\$ 850.00	
9050	Installed/Active	04/22/1997	FSG50	AO SMITH	\$ 850.00	
9051	Installed/Active	08/28/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9052	Installed/Active	10/20/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9053	Installed/Active	07/21/2004	PRX50	STATE	\$ 1,075.00	
9054	Installed/Active	03/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9055	Installed/Active	09/04/2003	PGR50	AO SMITH	\$ 850.00	
9056	Installed/Active	07/09/1999	41VR50	RHEEM	\$ 850.00	
9057	Installed/Active	07/05/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9058	Installed/Active	06/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9059	Installed/Active	02/05/2003	PRX50	STATE	\$ 1,075.00	
9060	Installed/Active	04/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9061	Installed/Active	08/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9062	Installed/Active	10/11/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9063	Installed/Active	05/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9064	Installed/Active	06/11/2003	PGR50	AO SMITH	\$ 850.00	
9065	Installed/Active	02/22/1990	P506	RUUD	\$ 1,150.00	
9066	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9067	Installed/Active	05/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9068	Installed/Active	12/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9069	Installed/Active	11/23/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
9070	Installed/Active	12/07/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9071	Installed/Active	08/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9072	Installed/Active	08/13/2001	FSG50	AO SMITH	\$ 850.00	
9073	Installed/Active	06/30/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9074	Installed/Active	03/15/2000	PRV50NODS	STATE	\$ 1,075.00	
9075	Installed/Active	05/15/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
9076	Installed/Active	03/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9077	Installed/Active	12/09/1987	FSG50	AO SMITH	\$ 850.00	
9078	Installed/Active	11/19/1987	FSG50	AO SMITH	\$ 850.00	
9079	Installed/Active	10/14/2003	PRX50	STATE	\$ 1,075.00	
9080	Installed/Active	08/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
9081	Installed/Active	02/19/1988	FSG50	AO SMITH	\$ 850.00	
9082	Installed/Active	02/19/1999	FGR50	AO SMITH	\$ 850.00	
9083	Installed/Active	03/03/2001	41XR50	RHEEM	\$ 850.00	
9084	Installed/Active	08/04/1988	FSG50	AO SMITH	\$ 850.00	
9085	Installed/Active	10/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9086	Installed/Active	10/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9087	Installed/Active	04/18/2002	FSG50	AO SMITH	\$ 850.00	
9088	Installed/Active	01/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9089	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9090	Installed/Active	07/09/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9091	Installed/Active	02/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9092	Installed/Active	12/11/1987	PRX50	STATE	\$ 1,075.00	
9093	Installed/Active	11/02/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
9094	Installed/Active	06/02/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
9095	Installed/Active	10/10/2005	LTN050	LOCHINVAR	\$ 850.00	
9096	Installed/Active	10/07/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
9097	Installed/Active	04/09/1988	FSG50	AO SMITH	\$ 850.00	
9098	Installed/Active	08/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9099	Installed/Active	06/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9100	Installed/Active	03/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9101	Installed/Active	08/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9102	Installed/Active	01/25/2012	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 12.64
9103	Installed/Active	11/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9104	Installed/Active	09/14/2005	LTN050	LOCHINVAR	\$ 850.00	
9105	Installed/Active	01/31/2000	FSG50	AO SMITH	\$ 850.00	
9106	Installed/Active	02/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9107	Installed/Active	02/20/2004	PRX40	STATE	\$ 1,075.00	
9108	Installed/Active	10/03/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
9109	Installed/Active	09/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9110	Installed/Active	05/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9111	Installed/Active	04/01/2002	PGR50	AO SMITH	\$ 850.00	
9112	Installed/Active	03/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9113	Installed/Active	03/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
9114	Installed/Active	03/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9115	Installed/Active	11/05/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
9116	Installed/Active	07/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9117	Installed/Active	10/20/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
9118	Installed/Active	11/27/2001	FSGL40	AO SMITH	\$ 850.00	
9119	Installed/Active	08/17/2004	PVR50	AO SMITH	\$ 850.00	
9120	Installed/Active	10/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9121	Installed/Active	08/17/2000	FSG50	AO SMITH	\$ 850.00	
9122	Installed/Active	09/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9123	Installed/Active	09/20/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
9124	Installed/Active	08/15/2011	42V50SF	RHEEM	\$ 850.00	\$ 12.64
9125	Installed/Active	06/24/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
9126	Installed/Active	12/11/2001	FSGL40	AO SMITH	\$ 850.00	
9127	Installed/Active	07/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9128	Installed/Active	02/28/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.05
9129	Installed/Active	08/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9130	Installed/Active	01/26/1989	FSG50	AO SMITH	\$ 850.00	
9131	Installed/Active	01/31/2005	XVR50	A. O. SMITH	\$ 850.00	
9132	Installed/Active	01/27/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9133	Installed/Active	07/20/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9134	Installed/Active	02/17/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9135	Installed/Active	01/26/1989	FSG50	AO SMITH	\$ 850.00	
9136	Installed/Active	08/03/2005	LTN050	LOCHINVAR	\$ 1,150.00	
9137	Installed/Active	01/29/2005	GDVS50	AOSMITH	\$ 1,075.00	
9138	Installed/Active	09/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
9139	Installed/Active	12/28/2004	LTN050	LOCHINVAR	\$ 850.00	
9140	Installed/Active	05/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9141	Installed/Active	07/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9142	Installed/Active	09/08/2003	PVR50	AO SMITH	\$ 850.00	
9143	Installed/Active	03/28/2007	ETN065	LOCHINVAR	\$ 1,900.00	\$ 33.40
9144	Installed/Active	06/11/2001	PGR50	AO SMITH	\$ 850.00	
9145	Installed/Active	07/29/2002	PRX50	STATE	\$ 1,075.00	
9146	Installed/Active	07/11/2000	FSG30	AO SMITH	\$ 850.00	
9147	Installed/Active	12/06/1988	FSG50	AO SMITH	\$ 850.00	
9148	Installed/Active	02/20/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9149	Installed/Active	10/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9150	Installed/Active	03/21/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9151	Installed/Active	10/10/2001	PGR50	AO SMITH	\$ 850.00	
9152	Installed/Active	01/17/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9153	Installed/Active	03/18/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
9154	Installed/Active	06/12/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
9155	Installed/Active	04/28/2005	LTN050	LOCHINVAR	\$ 850.00	
9156	Installed/Active	11/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
9157	Installed/Active	03/10/2004	FSGL40	AO SMITH	\$ 850.00	
9158	Installed/Active	02/10/2003	FSG50	AO SMITH	\$ 850.00	
9159	Installed/Active	08/06/2002	FSG50	AO SMITH	\$ 850.00	
9160	Installed/Active	04/08/2004	XTN050	LOCHINVAR	\$ 850.00	
9161	Installed/Active	06/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9162	Installed/Active	09/18/1997	PGR50	AO SMITH	\$ 850.00	
9163	Installed/Active	01/06/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9164	Installed/Active	03/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9165	Installed/Active	07/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9166	Installed/Active	04/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9167	Installed/Active	05/21/2000	41XR50	RHEEM	\$ 850.00	
9168	Installed/Active	12/29/2004	PR640	STATE	\$ 1,075.00	
9169	Installed/Active	08/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9170	Installed/Active	09/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9171	Installed/Active	06/13/2006	PR650	STATE	\$ 1,075.00	
9172	Installed/Active	12/22/2005	PR650	STATE	\$ 1,075.00	
9173	Installed/Active	05/15/1996	FSG50	AO SMITH	\$ 850.00	
9174	Installed/Active	04/10/2008	PR640	STATE	\$ 1,075.00	\$ 14.35
9175	Installed/Active	05/01/1990	PH30	RUUD	\$ 350.00	
9176	Installed/Active	03/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
9177	Installed/Active	12/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9178	Installed/Active	05/30/1990	H72DUMMY	AO SMITH	\$ 1,900.00	
9179	Installed/Active	12/01/1990	FSG50	AO SMITH	\$ 850.00	
9180	Installed/Active	07/23/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9181	Installed/Active	07/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9182	Installed/Active	11/15/1990	FSGL40	AO SMITH	\$ 350.00	
9183	Installed/Active	08/07/2006	PR650	STATE	\$ 1,075.00	
9184	Installed/Active	12/15/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
9185	Installed/Active	08/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9186	Installed/Active	06/22/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9187	Installed/Active	04/21/1994	PR502T	RUUD	\$ 850.00	
9188	Installed/Active	08/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9189	Installed/Active	09/26/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9190	Installed/Active	02/28/2000	41XR50	RHEEM	\$ 850.00	
9191	Installed/Active	11/20/2001	PGR50	AO SMITH	\$ 850.00	
9192	Installed/Active	07/28/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9193	Installed/Active	06/12/1990	BTR120	AO SMITH	\$ 1,900.00	
9194	Installed/Active	02/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
9195	Installed/Active	08/21/2001	PRX50	STATE	\$ 1,075.00	
9196	Installed/Active	02/25/2007	FGR50	AO SMITH	\$ 850.00	\$ 10.23
9197	Installed/Active	07/20/1990	P506	RUUD	\$ 1,125.00	
9198	Installed/Active	03/19/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
9199	Installed/Active	07/27/2004	GVC50	A. O. SMITH	\$ 850.00	
9200	Installed/Active	10/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
9201	Installed/Active	11/26/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9202	Installed/Active	03/15/2002	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9203	Installed/Active	12/20/1990	PRV40NODS	STATE	\$ 1,075.00	
9204	Installed/Active	10/25/1989	FSG50	AO SMITH	\$ 850.00	
9205	Installed/Active	04/07/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
9206	Installed/Active	11/14/1990	PRV50NODS	STATE	\$ 1,075.00	
9207	Installed/Active	03/07/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
9208	Installed/Active	10/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9209	Installed/Active	04/18/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9210	Installed/Active	10/06/1999	P506	RUUD	\$ 500.00	
9211	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
9212	Installed/Active	04/07/2006	ETN076	LOCHINVAR	\$ 1,900.00	
9213	Installed/Active	09/26/2001	FSG50	AO SMITH	\$ 850.00	
9214	Installed/Active	03/07/2000	FSG50	AO SMITH	\$ 850.00	
9215	Installed/Active	08/18/2004	PRX50	STATE	\$ 1,075.00	
9216	Installed/Active	05/28/1999	PRV50NODS	STATE	\$ 1,075.00	
9217	Installed/Active	05/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9218	Installed/Active	02/20/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
9219	Installed/Active	05/10/2002	FSG40	AO SMITH	\$ 850.00	
9220	Installed/Active	08/09/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
9221	Installed/Active	10/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9222	Installed/Active	09/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9223	Installed/Active	03/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9224	Installed/Active	06/21/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9225	Installed/Active	02/17/2012	G100200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
9226	Installed/Active	02/20/2003	PGR50	AO SMITH	\$ 850.00	
9227	Installed/Active	07/31/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9228	Installed/Active	07/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
9229	Installed/Active	05/23/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
9230	Installed/Active	02/11/2004	PRX50	STATE	\$ 1,075.00	
9231	Installed/Active	09/09/1986	FSG50	AO SMITH	\$ 850.00	
9232	Installed/Active	08/12/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9233	Installed/Active	10/03/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
9234	Installed/Active	06/29/2006	PR650	STATE	\$ 1,075.00	
9235	Installed/Active	10/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9236	Installed/Active	09/18/2002	PRX50	STATE	\$ 1,075.00	
9237	Installed/Active	09/18/1998	FGR50	AO SMITH	\$ 850.00	
9238	Installed/Active	12/30/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9239	Installed/Active	11/02/2004	GVC50	A. O. SMITH	\$ 850.00	
9240	Installed/Active	04/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9241	Installed/Active	10/11/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9242	Installed/Active	10/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
9243	Installed/Active	12/14/2001	FGR40	AO SMITH	\$ 850.00	
9244	Installed/Active	09/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9245	Installed/Active	01/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9246	Installed/Active	05/31/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
9247	Installed/Active	10/05/1998	PRV50NODS	STATE	\$ 1,075.00	
9248	Installed/Active	12/16/2002	FSG40	AO SMITH	\$ 850.00	
9249	Installed/Active	09/09/2004	GVC40	A. O. SMITH	\$ 850.00	
9250	Installed/Active	07/28/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9251	Installed/Active	09/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
9252	Installed/Active	08/20/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9253	Installed/Active	01/31/2003	FSG40	AO SMITH	\$ 850.00	
9254	Installed/Active	11/03/2003	PVR50	AO SMITH	\$ 850.00	
9255	Installed/Active	05/14/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9256	Installed/Active	02/06/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9257	Installed/Active	11/13/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
9258	Installed/Active	05/04/2006	PR650	STATE	\$ 1,075.00	
9259	Installed/Active	06/14/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
9260	Installed/Active	08/14/2009	FSGL40	AO SMITH	\$ 850.00	\$ 11.74
9261	Installed/Active	01/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9262	Installed/Active	01/25/1991	B71DUMMY	AMERICAN	\$ 850.00	
9263	Installed/Active	02/22/1991	21V506	RHEEM	\$ 1,150.00	
9264	Installed/Active	07/15/2005	LTN050	LOCHINVAR	\$ 850.00	
9265	Installed/Active	02/13/1990	PRX50	STATE	\$ 1,075.00	
9266	Installed/Active	09/18/1989	FSG50	AO SMITH	\$ 850.00	
9267	Installed/Active	07/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9268	Installed/Active	07/20/1990	FSG50	AO SMITH	\$ 850.00	
9269	Installed/Active	10/22/2012	FGR50	AO SMITH	\$ 850.00	\$ 12.75
9270	Installed/Active	02/19/1990	PRX50	STATE	\$ 1,075.00	
9271	Installed/Active	04/28/1990	PRV50NODS	STATE	\$ 1,075.00	
9272	Installed/Active	02/12/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9273	Installed/Active	03/01/2004	21DV50	RHEEM	\$ 1,075.00	
9274	Installed/Active	04/15/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9275	Installed/Active	05/01/2001	PRX50	STATE	\$ 1,075.00	
9276	Installed/Active	10/30/1995	PHR50	RUUD	\$ 850.00	
9277	Installed/Active	10/19/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9278	Installed/Active	04/18/2003	PGR50	AO SMITH	\$ 850.00	
9279	Installed/Active	08/09/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
9280	Installed/Active	11/12/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9281	Installed/Active	06/10/2004	GVC50	A. O. SMITH	\$ 850.00	
9282	Installed/Active	10/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9283	Installed/Active	12/17/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
9284	Installed/Active	11/30/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
9285	Installed/Active	09/06/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9286	Installed/Active	10/19/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
9287	Installed/Active	04/06/2004	PVR50	AO SMITH	\$ 850.00	
9288	Installed/Active	09/09/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9289	Installed/Active	06/28/2001	PGR50	AO SMITH	\$ 850.00	
9290	Installed/Active	04/02/2001	41XR50	RHEEM	\$ 850.00	
9291	Installed/Active	03/02/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9292	Installed/Active	07/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9293	Installed/Active	08/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9294	Installed/Active	07/09/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9295	Installed/Active	01/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9296	Installed/Active	08/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
9297	Installed/Active	07/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9298	Installed/Active	04/08/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9299	Installed/Active	08/06/1999	FSG50	AO SMITH	\$ 850.00	
9300	Installed/Active	02/08/2005	LTN050	LOCHINVAR	\$ 850.00	
9301	Installed/Active	02/13/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9302	Installed/Active	03/17/2006	PR650XODS	STATE	\$ 1,075.00	
9303	Installed/Active	10/17/2002	FSG40	AO SMITH	\$ 850.00	
9304	Installed/Active	07/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9305	Installed/Active	06/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9306	Installed/Active	09/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
9307	Installed/Active	07/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9308	Installed/Active	07/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9309	Installed/Active	03/16/1989	FSG50	AO SMITH	\$ 850.00	
9310	Installed/Active	11/30/2005	LTN050G	LOCHINVAR	\$ 850.00	
9311	Installed/Active	01/26/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9312	Installed/Active	08/09/2004	PRX40	STATE	\$ 1,075.00	
9313	Installed/Active	10/27/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
9314	Installed/Active	10/25/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
9315	Installed/Active	03/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9316	Installed/Active	04/30/2003	PGR50	AO SMITH	\$ 850.00	
9317	Installed/Active	04/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
9318	Installed/Active	12/23/2001	PRX40	STATE	\$ 1,075.00	
9319	Installed/Active	02/17/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
9320	Installed/Active	01/08/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9321	Installed/Active	06/17/2003	PRX50	STATE	\$ 1,075.00	
9322	Installed/Active	07/06/2006	PR650	STATE	\$ 1,075.00	
9323	Installed/Active	12/23/2004	PRX50	STATE	\$ 1,075.00	
9324	Installed/Active	04/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9325	Installed/Active	08/03/2004	XVR50	A. O. SMITH	\$ 850.00	
9326	Installed/Active	06/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9327	Installed/Active	05/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9328	Installed/Active	08/05/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
9329	Installed/Active	05/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9330	Installed/Active	05/13/2002	PGR50	AO SMITH	\$ 850.00	
9331	Installed/Active	10/22/2004	GCVL40	A. O. SMITH	\$ 850.00	
9332	Installed/Active	03/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9333	Installed/Active	12/04/1987	FSG50	AO SMITH	\$ 850.00	
9334	Installed/Active	08/16/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
9335	Installed/Active	03/23/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
9336	Installed/Active	08/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9337	Installed/Active	08/20/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9338	Installed/Active	07/30/2007	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
9339	Installed/Active	02/11/1988	FSG50	AO SMITH	\$ 850.00	
9340	Installed/Active	12/22/2005	GVC50	A. O. SMITH	\$ 850.00	
9341	Installed/Active	06/15/1988	FSG50	AO SMITH	\$ 850.00	
9342	Installed/Active	03/04/2004	FSG50	AO SMITH	\$ 850.00	
9343	Installed/Active	11/23/2005	PR650	STATE	\$ 1,075.00	
9344	Installed/Active	02/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9345	Installed/Active	09/08/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9346	Installed/Active	02/23/2005	LTN050	LOCHINVAR	\$ 850.00	
9347	Installed/Active	05/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9348	Installed/Active	08/28/2002	FSG50	AO SMITH	\$ 850.00	
9349	Installed/Active	07/31/1989	FSG50	AO SMITH	\$ 850.00	
9350	Installed/Active	10/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9351	Installed/Active	12/19/2004	PRX50	STATE	\$ 1,075.00	
9352	Installed/Active	07/21/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
9353	Installed/Active	05/28/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
9354	Installed/Active	08/10/1989	21V506	RHEEM	\$ 1,150.00	
9355	Installed/Active	06/14/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9356	Installed/Active	03/14/2002	21V506	RHEEM	\$ 1,150.00	
9357	Installed/Active	06/21/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
9358	Installed/Active	05/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9359	Installed/Active	12/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
9360	Installed/Active	04/17/1989	FSG50	AO SMITH	\$ 850.00	
9361	Installed/Active	09/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9362	Installed/Active	02/27/2005	PRX50	STATE	\$ 1,075.00	
9363	Installed/Active	09/24/2004	42XR50	RHEEM	\$ 850.00	
9364	Installed/Active	06/30/2003	G72DUMMY	AO SMITH	\$ 1,125.00	
9365	Installed/Active	03/17/2003	PRX50	STATE	\$ 1,075.00	
9366	Installed/Active	02/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9367	Installed/Active	05/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9368	Installed/Active	07/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9369	Installed/Active	07/06/2004	42VR506	RHEEM	\$ 1,150.00	
9370	Installed/Active	07/31/2003	PGR40	AO SMITH	\$ 850.00	
9371	Installed/Active	04/10/2000	FSG50	AO SMITH	\$ 850.00	
9372	Installed/Active	07/20/2004	GVC50	A. O. SMITH	\$ 850.00	
9373	Installed/Active	02/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9374	Installed/Active	02/01/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9375	Installed/Active	08/22/2003	PGR50	AO SMITH	\$ 850.00	
9376	Installed/Active	04/21/2006	PR650	STATE	\$ 1,075.00	
9377	Installed/Active	01/20/2004	XTN050	LOCHINVAR	\$ 850.00	
9378	Installed/Active	02/16/1989	FSG50	AO SMITH	\$ 850.00	
9379	Installed/Active	01/28/2003	PRX50	STATE	\$ 1,075.00	
9380	Installed/Active	08/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9381	Installed/Active	12/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9382	Installed/Active	10/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9383	Installed/Active	02/27/1990	FSG50	AO SMITH	\$ 850.00	
9384	Installed/Active	02/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9385	Installed/Active	05/31/2006	LTN050	LOCHINVAR	\$ 850.00	
9386	Installed/Active	06/18/1999	41VR50	RHEEM	\$ 850.00	
9387	Installed/Active	09/12/1989	FSG50	AO SMITH	\$ 850.00	
9388	Installed/Active	02/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9389	Installed/Active	08/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9390	Installed/Active	08/06/2001	P506	RUUD	\$ 1,150.00	
9391	Installed/Active	04/14/2004	XVR50	A. O. SMITH	\$ 850.00	
9392	Installed/Active	09/19/2002	PGR50	AO SMITH	\$ 850.00	
9393	Installed/Active	04/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9394	Installed/Active	12/20/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9395	Installed/Active	07/22/2009	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9396	Installed/Active	11/23/2001	41XR50	RHEEM	\$ 850.00	
9397	Installed/Active	05/02/2004	GVC50	A. O. SMITH	\$ 850.00	
9398	Installed/Active	10/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9399	Installed/Active	12/19/2005	LTN050G	LOCHINVAR	\$ 850.00	
9400	Installed/Active	08/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9401	Installed/Active	07/05/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9402	Installed/Active	05/04/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9403	Installed/Active	08/03/2004	PRX50	STATE	\$ 1,075.00	
9404	Installed/Active	03/26/1990	P506	RUUD	\$ 1,150.00	
9405	Installed/Active	11/13/1989	21V506	RHEEM	\$ 1,150.00	
9406	Installed/Active	07/25/2005	LSN041G	LOCHINVAR	\$ 850.00	
9407	Installed/Active	09/10/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9408	Installed/Active	02/19/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
9409	Installed/Active	06/15/1990	G82156	RUUD/RHEEM	\$ 3,350.00	
9410	Installed/Active	09/11/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
9411	Installed/Active	02/02/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
9412	Installed/Active	06/15/1990	G82156	RUUD/RHEEM	\$ 3,350.00	
9413	Installed/Active	10/20/1999	FSGL40	AO SMITH	\$ 850.00	
9414	Installed/Active	09/06/1995	PR502T	RUUD	\$ 850.00	
9415	Installed/Active	04/23/2001	41V40S	RHEEM	\$ 850.00	
9416	Installed/Active	12/13/2000	FSG50	AO SMITH	\$ 850.00	
9417	Installed/Active	02/04/2004	XTN050	LOCHINVAR	\$ 850.00	
9418	Installed/Active	07/04/1998	PGR50	AO SMITH	\$ 850.00	
9419	Installed/Active	09/03/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
9420	Installed/Active	10/09/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
9421	Installed/Active	09/15/2012	M44016FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9422	Installed/Active	01/08/2002	FSGL40	AO SMITH	\$ 850.00	
9423	Installed/Active	09/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
9424	Installed/Active	03/26/1999	41VR50	RHEEM	\$ 850.00	
9425	Installed/Active	04/10/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9426	Installed/Active	02/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9427	Installed/Active	10/05/2002	PGR50	AO SMITH	\$ 850.00	
9428	Installed/Active	05/01/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
9429	Installed/Active	03/11/2009	41V50	RHEEM	\$ 850.00	\$ 11.74
9430	Installed/Active	12/13/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9431	Installed/Active	04/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9432	Installed/Active	07/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9433	Installed/Active	02/04/1987	FSG50	AO SMITH	\$ 850.00	
9434	Installed/Active	12/03/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9435	Installed/Active	01/05/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9436	Installed/Active	07/14/1987	FSG50	AO SMITH	\$ 850.00	
9437	Installed/Active	10/09/2009	21VR50	RHEEM	\$ 850.00	\$ 11.74
9438	Installed/Active	02/10/1999	FGR50	AO SMITH	\$ 850.00	
9439	Installed/Active	05/09/2006	LSN041G	LOCHINVAR	\$ 850.00	
9440	Installed/Active	08/26/1999	FGR50	AO SMITH	\$ 850.00	
9441	Installed/Active	04/26/2005	LTN050	LOCHINVAR	\$ 850.00	
9442	Installed/Active	08/02/1999	FSG50	AO SMITH	\$ 850.00	
9443	Installed/Active	05/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9444	Installed/Active	03/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9445	Installed/Active	08/21/1987	FSG50	AO SMITH	\$ 850.00	
9446	Installed/Active	09/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9447	Installed/Active	02/13/2009	LTN051G	LOCHINVAR	\$ 1,075.00	\$ 16.47
9448	Installed/Active	11/04/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9449	Installed/Active	07/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9450	Installed/Active	02/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
9451	Installed/Active	09/06/2000	PRX50	STATE	\$ 1,075.00	
9452	Installed/Active	04/12/2007	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
9453	Installed/Active	09/06/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
9454	Installed/Active	10/26/2004	GCVL40	A. O. SMITH	\$ 850.00	
9455	Installed/Active	04/10/2003	PR650	STATE	\$ 1,075.00	
9456	Installed/Active	09/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
9457	Installed/Active	06/13/2007	FGR50	AO SMITH	\$ 850.00	\$ 10.23
9458	Installed/Active	01/30/2003	PRX50	STATE	\$ 1,075.00	
9459	Installed/Active	06/06/2002	PGR50	AO SMITH	\$ 850.00	
9460	Installed/Active	05/18/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9461	Installed/Active	09/12/2003	PRX50	STATE	\$ 1,075.00	
9462	Installed/Active	08/10/2004	XVR50	A. O. SMITH	\$ 850.00	
9463	Installed/Active	06/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9464	Installed/Active	10/06/2005	PR650X0DS	STATE	\$ 1,075.00	
9465	Installed/Active	03/10/2004	PVR50	AO SMITH	\$ 850.00	
9466	Installed/Active	06/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
9467	Installed/Active	07/21/1999	FGR40	AO SMITH	\$ 850.00	
9468	Installed/Active	07/01/2005	PR650	STATE	\$ 1,075.00	
9469	Installed/Active	03/29/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9470	Installed/Active	06/11/2001	FSGL40	AO SMITH	\$ 850.00	
9471	Installed/Active	04/28/1997	PGR50	AO SMITH	\$ 850.00	
9472	Installed/Active	11/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9473	Installed/Active	01/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9474	Installed/Active	12/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9475	Installed/Active	04/23/2001	41V40S	RHEEM	\$ 850.00	
9476	Installed/Active	06/27/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9477	Installed/Active	04/03/2002	FSG50	AO SMITH	\$ 850.00	
9478	Installed/Active	12/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
9479	Installed/Active	04/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
9480	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9481	Installed/Active	07/06/1990	PRV50NODS	STATE	\$ 1,075.00	
9482	Installed/Active	07/14/2008	42VR50	RHEEM	\$ 850.00	\$ 10.23
9483	Installed/Active	01/19/2004	PVR50	AO SMITH	\$ 850.00	
9484	Installed/Active	08/23/2003	FVR50	AO SMITH	\$ 850.00	
9485	Installed/Active	03/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9486	Installed/Active	12/02/1997	FGR40	AO SMITH	\$ 350.00	
9487	Installed/Active	01/26/2003	FSGL40	AO SMITH	\$ 850.00	
9488	Installed/Active	03/31/2000	PGR50	AO SMITH	\$ 850.00	
9489	Installed/Active	11/04/2004	GVC50	A. O. SMITH	\$ 850.00	
9490	Installed/Active	05/23/2002	FSG50	AO SMITH	\$ 850.00	
9491	Installed/Active	06/15/2004	GVC50	A. O. SMITH	\$ 850.00	
9492	Installed/Active	03/01/2001	41V50	RHEEM	\$ 850.00	
9493	Installed/Active	08/17/1999	FGR50	AO SMITH	\$ 850.00	
9494	Installed/Active	06/06/2005	LTN050	LOCHINVAR	\$ 850.00	
9495	Installed/Active	09/11/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9496	Installed/Active	01/27/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
9497	Installed/Active	04/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
9498	Installed/Active	12/06/2004	FSG50	AO SMITH	\$ 850.00	
9499	Installed/Active	09/13/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
9500	Installed/Active	05/05/2001	FSG40	AO SMITH	\$ 850.00	
9501	Installed/Active	06/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9502	Installed/Active	11/13/1990	FSG50	AO SMITH	\$ 850.00	
9503	Installed/Active	05/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9504	Installed/Active	08/06/2003	FCV50	AO SMITH	\$ 1,150.00	
9505	Installed/Active	11/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9506	Installed/Active	03/24/1999	FGR50	AO SMITH	\$ 850.00	
9507	Installed/Active	10/26/1999	41XR50	RHEEM	\$ 850.00	
9508	Installed/Active	11/20/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9509	Installed/Active	12/11/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
9510	Installed/Active	02/24/2004	PVR50	AO SMITH	\$ 850.00	
9511	Installed/Active	04/20/2009	PRV50NODS	STATE	\$ 1,075.00	\$ 16.47
9512	Installed/Active	11/01/1990	P506	RUUD	\$ 1,150.00	
9513	Installed/Active	02/06/1995	PR407	RUUD	\$ 850.00	
9514	Installed/Active	05/03/2003	21DV50	RHEEM	\$ 1,075.00	
9515	Installed/Active	04/20/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9516	Installed/Active	09/10/1990	FSGL40	AO SMITH	\$ 350.00	
9517	Installed/Active	02/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
9518	Installed/Active	06/16/2000	PGR50	AO SMITH	\$ 850.00	
9519	Installed/Active	12/10/1998	FSG50	AO SMITH	\$ 850.00	
9520	Installed/Active	01/02/2007	LTN050G	LOCHINVAR	\$ 850.00	
9521	Installed/Active	03/23/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
9522	Installed/Active	09/01/2006	LTN050GEF	LOCHINVAR	\$ 1,150.00	
9523	Installed/Active	01/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9524	Installed/Active	03/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9525	Installed/Active	04/28/1989	FSG50	AO SMITH	\$ 850.00	
9526	Installed/Active	01/31/1989	FSG50	AO SMITH	\$ 850.00	
9527	Installed/Active	06/28/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
9528	Installed/Active	01/17/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
9529	Installed/Active	06/27/1989	FSG50	AO SMITH	\$ 850.00	
9530	Installed/Active	11/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9531	Installed/Active	01/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9532	Installed/Active	07/16/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
9533	Installed/Active	03/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9534	Installed/Active	02/15/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
9535	Installed/Active	11/11/2004	42XR50	RHEEM	\$ 850.00	
9536	Installed/Active	10/03/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9537	Installed/Active	03/05/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9538	Installed/Active	02/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
9539	Installed/Active	10/13/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9540	Installed/Active	10/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
9541	Installed/Active	01/19/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
9542	Installed/Active	06/24/2002	FSG50	AO SMITH	\$ 850.00	
9543	Installed/Active	02/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9544	Installed/Active	09/10/1999	FSGL40	AO SMITH	\$ 850.00	
9545	Installed/Active	01/21/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9546	Installed/Active	11/16/2005	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9547	Installed/Active	06/03/2002	FSG50	AO SMITH	\$ 850.00	
9548	Installed/Active	03/26/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.64
9549	Installed/Active	08/03/1989	FSG50	AO SMITH	\$ 850.00	
9550	Installed/Active	03/16/2005	GVC50	A. O. SMITH	\$ 850.00	
9551	Installed/Active	09/30/2005	LTN050G	LOCHINVAR	\$ 850.00	
9552	Installed/Active	01/31/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
9553	Installed/Active	11/08/1988	FSG50	AO SMITH	\$ 850.00	
9554	Installed/Active	01/30/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9555	Installed/Active	10/30/2001	FSGL40	AO SMITH	\$ 850.00	
9556	Installed/Active	03/21/2005	PRX50	STATE	\$ 1,075.00	
9557	Installed/Active	04/04/2007	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
9558	Installed/Active	12/23/2005	GVC50	A. O. SMITH	\$ 850.00	
9559	Installed/Active	05/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9560	Installed/Active	08/10/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9561	Installed/Active	09/11/2001	FSG50	AO SMITH	\$ 850.00	
9562	Installed/Active	08/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
9563	Installed/Active	05/15/1998	41VR50	RHEEM	\$ 850.00	
9564	Installed/Active	02/15/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9565	Installed/Active	03/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9566	Installed/Active	07/07/2004	XTN050	LOCHINVAR	\$ 850.00	
9567	Installed/Active	09/19/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
9568	Installed/Active	04/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9569	Installed/Active	07/27/1988	FSG50	AO SMITH	\$ 850.00	
9570	Installed/Active	02/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9571	Installed/Active	08/11/2005	PR650	STATE	\$ 1,075.00	
9572	Installed/Active	12/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9573	Installed/Active	11/07/2002	PGR50	AO SMITH	\$ 850.00	
9574	Installed/Active	04/03/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9575	Installed/Active	02/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
9576	Installed/Active	08/05/2003	PRX50	STATE	\$ 1,075.00	
9577	Installed/Active	01/24/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
9578	Installed/Active	09/18/2004	XVR50	A. O. SMITH	\$ 850.00	
9579	Installed/Active	02/27/2006	LTN040G	LOCHINVAR	\$ 850.00	
9580	Installed/Active	02/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9581	Installed/Active	10/15/2001	PGR50	AO SMITH	\$ 850.00	
9582	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
9583	Installed/Active	08/05/2000	41XR50	RHEEM	\$ 850.00	
9584	Installed/Active	04/11/1996	41XR40	RHEEM	\$ 850.00	
9585	Installed/Active	04/24/2002	PGR50	AO SMITH	\$ 850.00	
9586	Installed/Active	07/20/1988	FSGL40	AO SMITH	\$ 850.00	
9587	Installed/Active	05/19/1988	FSG50	AO SMITH	\$ 850.00	
9588	Installed/Active	06/29/1988	PRX50	STATE	\$ 1,075.00	
9589	Installed/Active	05/04/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9590	Installed/Active	01/11/2008	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
9591	Installed/Active	07/28/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9592	Installed/Active	09/12/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9593	Installed/Active	06/09/2009	LTN030G	AO SMITH	\$ 850.00	\$ 11.74
9594	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9595	Installed/Active	06/14/2005	LTN050	LOCHINVAR	\$ 850.00	
9596	Installed/Active	09/29/2000	FSG50	AO SMITH	\$ 850.00	
9597	Installed/Active	01/10/2009	PRX50	STATE	\$ 1,075.00	\$ 16.47
9598	Installed/Active	04/22/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
9599	Installed/Active	07/20/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9600	Installed/Active	12/07/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
9601	Installed/Active	01/06/2007	LTN050G	LOCHINVAR	\$ 850.00	
9602	Installed/Active	04/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9603	Installed/Active	12/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9604	Installed/Active	03/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9605	Installed/Active	03/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9606	Installed/Active	02/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
9607	Installed/Active	09/08/2004	GVC50	A. O. SMITH	\$ 850.00	
9608	Installed/Active	11/22/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
9609	Installed/Active	04/01/2005	PVR50	AO SMITH	\$ 850.00	
9610	Installed/Active	09/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
9611	Installed/Active	08/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9612	Installed/Active	06/18/1990	FSG40	AO SMITH	\$ 850.00	
9613	Installed/Active	07/01/2004	GVC50	A. O. SMITH	\$ 850.00	
9614	Installed/Active	05/30/1996	FGR50	AO SMITH	\$ 850.00	
9615	Installed/Active	12/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9616	Installed/Active	09/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9617	Installed/Active	03/23/2002	FSG50	AO SMITH	\$ 850.00	
9618	Installed/Active	11/09/2010	41VR40	RHEEM	\$ 850.00	\$ 12.05
9619	Installed/Active	12/08/1989	PRV50NODS	STATE	\$ 1,075.00	
9620	Installed/Active	03/23/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9621	Installed/Active	08/14/1998	G72DUMMY	AO SMITH	\$ 1,125.00	
9622	Installed/Active	03/11/2003	PGR50	AO SMITH	\$ 850.00	
9623	Installed/Active	06/01/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
9624	Installed/Active	08/13/2009	PRV50NODS	STATE	\$ 1,075.00	\$ 16.47
9625	Installed/Active	02/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9626	Installed/Active	12/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
9627	Installed/Active	03/02/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9628	Installed/Active	01/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9629	Installed/Active	03/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9630	Installed/Active	04/04/1991	B71DUMMY	AMERICAN	\$ 850.00	
9631	Installed/Active	10/08/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9632	Installed/Active	12/28/2005	LTN050	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9633	Installed/Active	03/05/2001	PRX50	STATE	\$ 1,075.00	
9634	Installed/Active	06/17/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
9635	Installed/Active	04/03/1991	B71DUMMY	AMERICAN	\$ 850.00	
9636	Installed/Active	01/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9637	Installed/Active	09/07/1989	PRV50NODS	STATE	\$ 1,075.00	
9638	Installed/Active	02/26/2000	41XR50	RHEEM	\$ 850.00	
9639	Installed/Active	03/08/2003	FSG50	AO SMITH	\$ 850.00	
9640	Installed/Active	08/10/1999	FGR50	AO SMITH	\$ 850.00	
9641	Installed/Active	11/22/2002	PRX50	STATE	\$ 1,075.00	
9642	Installed/Active	11/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9643	Installed/Active	02/21/2003	FSG50	AO SMITH	\$ 850.00	
9644	Installed/Active	10/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9645	Installed/Active	10/20/2002	FSG50	AO SMITH	\$ 850.00	
9646	Installed/Active	07/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9647	Installed/Active	07/01/2004	GVC50	A. O. SMITH	\$ 850.00	
9648	Installed/Active	11/18/2002	PRX50	STATE	\$ 1,075.00	
9649	Installed/Active	03/25/2003	FSG50	AO SMITH	\$ 850.00	
9650	Installed/Active	02/15/2004	XTN040	LOCHINVAR	\$ 850.00	
9651	Installed/Active	10/10/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9652	Installed/Active	05/11/1997	PGR50	AO SMITH	\$ 850.00	
9653	Installed/Active	12/30/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
9654	Installed/Active	05/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9655	Installed/Active	11/30/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9656	Installed/Active	02/25/2002	PGR50	AO SMITH	\$ 850.00	
9657	Installed/Active	06/12/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9658	Installed/Active	12/12/1990	PRV50NODS	STATE	\$ 1,075.00	
9659	Installed/Active	03/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9660	Installed/Active	01/15/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9661	Installed/Active	01/27/2005	GVR50	AO SMITH	\$ 850.00	
9662	Installed/Active	10/24/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9663	Installed/Active	06/23/2003	PRX50	STATE	\$ 1,075.00	
9664	Installed/Active	07/20/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9665	Installed/Active	01/22/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
9666	Installed/Active	03/15/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9667	Installed/Active	04/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9668	Installed/Active	02/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
9669	Installed/Active	04/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9670	Installed/Active	01/27/1987	PRX50	STATE	\$ 1,075.00	
9671	Installed/Active	06/25/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9672	Installed/Active	06/26/2000	41XR50	RHEEM	\$ 850.00	
9673	Installed/Active	06/24/1999	FSG50	AO SMITH	\$ 850.00	
9674	Installed/Active	10/11/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9675	Installed/Active	11/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9676	Installed/Active	07/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9677	Installed/Active	04/17/2003	PGR50	AO SMITH	\$ 850.00	
9678	Installed/Active	02/26/2001	PR650	STATE	\$ 1,075.00	
9679	Installed/Active	08/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9680	Installed/Active	06/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9681	Installed/Active	09/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
9682	Installed/Active	09/29/1987	FSGL40	AO SMITH	\$ 850.00	
9683	Installed/Active	01/16/1987	FSG50	AO SMITH	\$ 850.00	
9684	Installed/Active	12/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9685	Installed/Active	08/03/2005	LTN050	LOCHINVAR	\$ 850.00	
9686	Installed/Active	10/14/2000	41XR50	RHEEM	\$ 850.00	
9687	Installed/Active	01/12/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9688	Installed/Active	12/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9689	Installed/Active	01/16/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9690	Installed/Active	05/03/2005	PR640	STATE	\$ 1,075.00	
9691	Installed/Active	08/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
9692	Installed/Active	09/23/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9693	Installed/Active	11/08/2001	21V506	RHEEM	\$ 500.00	
9694	Installed/Active	10/01/2004	XVR50	A. O. SMITH	\$ 850.00	
9695	Installed/Active	03/05/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
9696	Installed/Active	04/30/1987	FGR50	AO SMITH	\$ 850.00	
9697	Installed/Active	04/11/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
9698	Installed/Active	08/15/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
9699	Installed/Active	06/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9700	Installed/Active	10/27/2006	PHR50	RUUD	\$ 850.00	
9701	Installed/Active	10/28/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9702	Installed/Active	01/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9703	Installed/Active	12/13/1999	41VR50	RHEEM	\$ 850.00	
9704	Installed/Active	01/02/2001	PRX50	STATE	\$ 1,075.00	
9705	Installed/Active	12/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9706	Installed/Active	09/11/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9707	Installed/Active	11/12/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9708	Installed/Active	08/20/1998	FSG40	AO SMITH	\$ 850.00	
9709	Installed/Active	12/02/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9710	Installed/Active	11/21/2006	PR650	STATE	\$ 1,075.00	
9711	Installed/Active	11/22/2002	21V506	RHEEM	\$ 1,150.00	
9712	Installed/Active	11/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9713	Installed/Active	03/06/2002	PGR50	AO SMITH	\$ 850.00	
9714	Installed/Active	09/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9715	Installed/Active	05/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9716	Installed/Active	11/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
9717	Installed/Active	08/14/2001	PGR50	AO SMITH	\$ 850.00	
9718	Installed/Active	10/08/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9719	Installed/Active	12/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9720	Installed/Active	08/11/2005	LTN050	LOCHINVAR	\$ 850.00	
9721	Installed/Active	03/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9722	Installed/Active	01/04/2002	PGR40	AO SMITH	\$ 850.00	
9723	Installed/Active	11/30/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9724	Installed/Active	03/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9725	Installed/Active	01/30/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9726	Installed/Active	04/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9727	Installed/Active	09/27/1999	PRV50NODS	STATE	\$ 1,075.00	
9728	Installed/Active	02/01/1990	PRX50	STATE	\$ 1,075.00	
9729	Installed/Active	06/14/2003	PRX50	STATE	\$ 1,075.00	
9730	Installed/Active	01/30/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9731	Installed/Active	09/08/2005	PR650	STATE	\$ 1,075.00	
9732	Installed/Active	04/07/2011	ETN076	LOCHINVAR	\$ 1,900.00	\$ 41.30
9733	Installed/Active	12/27/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
9734	Installed/Active	11/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9735	Installed/Active	12/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
9736	Installed/Active	03/12/2004	FCV50	AO SMITH	\$ 850.00	
9737	Installed/Active	04/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9738	Installed/Active	03/11/2002	FSG50	AO SMITH	\$ 850.00	
9739	Installed/Active	08/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9740	Installed/Active	12/02/2008	FSG50	AO SMITH	\$ 850.00	\$ 11.74
9741	Installed/Active	05/25/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
9742	Installed/Active	08/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9743	Installed/Active	12/14/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
9744	Installed/Active	07/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9745	Installed/Active	11/08/2000	H72DUMMY	AO SMITH	\$ 1,900.00	
9746	Installed/Active	03/28/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
9747	Installed/Active	03/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9748	Installed/Active	07/17/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9749	Installed/Active	11/05/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
9750	Installed/Active	02/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9751	Installed/Active	05/19/2003	FSG50	AO SMITH	\$ 850.00	
9752	Installed/Active	03/10/2006	XSN0401GEF	LOCHINVAR	\$ 850.00	
9753	Installed/Active	02/04/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
9754	Installed/Active	05/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
9755	Installed/Active	03/01/2006	PR650	STATE	\$ 1,075.00	
9756	Installed/Active	11/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9757	Installed/Active	12/14/1988	FSG50	AO SMITH	\$ 850.00	
9758	Installed/Active	04/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9759	Installed/Active	09/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
9760	Installed/Active	09/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
9761	Installed/Active	10/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9762	Installed/Active	03/12/2012	M15036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
9763	Installed/Active	09/01/1999	FGR40	AO SMITH	\$ 850.00	
9764	Installed/Active	11/18/2010	42VR50	RHEEM	\$ 850.00	\$ 16.55
9765	Installed/Active	01/26/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
9766	Installed/Active	07/26/2007	FSGL40	AO SMITH	\$ 350.00	\$ 12.50
9767	Installed/Active	04/05/1999	FSG50	AO SMITH	\$ 850.00	
9768	Installed/Active	05/20/2006	PR650	STATE	\$ 1,075.00	
9769	Installed/Active	01/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9770	Installed/Active	07/30/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
9771	Installed/Active	05/05/1989	PRV50NODS	STATE	\$ 1,075.00	
9772	Installed/Active	02/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9773	Installed/Active	03/17/1989	FSG50	AO SMITH	\$ 850.00	
9774	Installed/Active	12/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9775	Installed/Active	12/08/2001	41VR40	RHEEM	\$ 850.00	
9776	Installed/Active	10/07/1998	41XR50	RHEEM	\$ 850.00	
9777	Installed/Active	07/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9778	Installed/Active	10/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9779	Installed/Active	07/21/1989	FSG50	AO SMITH	\$ 850.00	
9780	Installed/Active	03/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9781	Installed/Active	09/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
9782	Installed/Active	01/27/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
9783	Installed/Active	01/12/1998	PRV50NODS	STATE	\$ 1,075.00	
9784	Installed/Active	12/26/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9785	Installed/Active	11/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9786	Installed/Active	05/11/2005	LTN050	LOCHINVAR	\$ 850.00	
9787	Installed/Active	04/08/1989	FSG50	AO SMITH	\$ 850.00	
9788	Installed/Active	06/28/1989	RF82156	RUUD	\$ 3,350.00	
9789	Installed/Active	07/27/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9790	Installed/Active	10/25/2004	GVC50	A. O. SMITH	\$ 850.00	
9791	Installed/Active	04/12/2004	GVC50	A. O. SMITH	\$ 850.00	
9792	Installed/Active	08/14/1989	FSG40	AO SMITH	\$ 850.00	
9793	Installed/Active	10/04/1989	FSG40	AO SMITH	\$ 850.00	
9794	Installed/Active	05/18/2005	PR650	STATE	\$ 1,075.00	
9795	Installed/Active	05/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9796	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
9797	Installed/Active	02/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9798	Installed/Active	08/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9799	Installed/Active	06/13/2002	FSG50	AO SMITH	\$ 850.00	
9800	Installed/Active	03/07/2002	PGR50	AO SMITH	\$ 850.00	
9801	Installed/Active	10/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
9802	Installed/Active	04/22/2003	FSG50	AO SMITH	\$ 850.00	
9803	Installed/Active	08/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9804	Installed/Active	06/04/2003	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9805	Installed/Active	03/14/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9806	Installed/Active	09/04/2001	PRX50	STATE	\$ 1,075.00	
9807	Installed/Active	03/11/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9808	Installed/Active	04/22/2003	FSG50	AO SMITH	\$ 850.00	
9809	Installed/Active	10/04/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9810	Installed/Active	05/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9811	Installed/Active	02/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9812	Installed/Active	12/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
9813	Installed/Active	08/14/2003	FSGL40	AO SMITH	\$ 850.00	
9814	Installed/Active	04/13/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.64
9815	Installed/Active	10/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9816	Installed/Active	06/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
9817	Installed/Active	02/20/1989	FSG50	AO SMITH	\$ 850.00	
9818	Installed/Active	03/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
9819	Installed/Active	12/18/2001	41V50	RHEEM	\$ 850.00	
9820	Installed/Active	11/07/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9821	Installed/Active	03/26/2004	PRX50	STATE	\$ 1,075.00	
9822	Installed/Active	06/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
9823	Installed/Active	11/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9824	Installed/Active	01/14/1998	FGR50	AO SMITH	\$ 850.00	
9825	Installed/Active	08/13/2002	PGR50	AO SMITH	\$ 850.00	
9826	Installed/Active	04/02/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9827	Installed/Active	03/28/1988	FSG50	AO SMITH	\$ 850.00	
9828	Installed/Active	10/08/2002	PGR50	AO SMITH	\$ 850.00	
9829	Installed/Active	02/10/2004	PRX50	STATE	\$ 1,075.00	
9830	Installed/Active	06/29/2000	FSGL40	AO SMITH	\$ 850.00	
9831	Installed/Active	09/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9832	Installed/Active	12/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9833	Installed/Active	02/05/2002	PGR50	AO SMITH	\$ 850.00	
9834	Installed/Active	09/11/2002	PGR50	AO SMITH	\$ 850.00	
9835	Installed/Active	01/23/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
9836	Installed/Active	04/14/1988	FSG50	AO SMITH	\$ 850.00	
9837	Installed/Active	08/29/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9838	Installed/Active	08/09/2004	PRX50	STATE	\$ 1,075.00	
9839	Installed/Active	06/01/2004	PRX50	STATE	\$ 1,075.00	
9840	Installed/Active	07/28/2001	PRX50	STATE	\$ 1,075.00	
9841	Installed/Active	05/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9842	Installed/Active	10/26/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9843	Installed/Active	06/21/2005	LTN050	LOCHINVAR	\$ 850.00	
9844	Installed/Active	10/13/2011	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9845	Installed/Active	05/12/1988	FSG50	AO SMITH	\$ 850.00	
9846	Installed/Active	12/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9847	Installed/Active	02/04/1988	P505	RUUD	\$ 500.00	
9848	Installed/Active	04/20/1999	PGR50	AO SMITH	\$ 850.00	
9849	Installed/Active	03/14/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9850	Installed/Active	05/01/1999	FSG50	AO SMITH	\$ 850.00	
9851	Installed/Active	10/13/2006	XVR50	A. O. SMITH	\$ 850.00	
9852	Installed/Active	11/28/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
9853	Installed/Active	05/25/2004	GVC50	A. O. SMITH	\$ 850.00	
9854	Installed/Active	05/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9855	Installed/Active	03/31/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9856	Installed/Active	01/23/1991	BTC197	AO SMITH	\$ 3,350.00	
9857	Installed/Active	12/05/1987	FSG50	AO SMITH	\$ 850.00	
9858	Installed/Active	10/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9859	Installed/Active	01/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9860	Installed/Active	12/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9861	Installed/Active	04/09/2003	PRX50	STATE	\$ 1,075.00	
9862	Installed/Active	03/26/1998	H72DUMMY	AO SMITH	\$ 1,900.00	
9863	Installed/Active	11/28/1989	FSG50	AO SMITH	\$ 850.00	
9864	Installed/Active	06/30/2008	LTN051G	LOCHINVAR	\$ 850.00	\$ 10.23
9865	Installed/Active	07/15/2009	PGR50	AO SMITH	\$ 1,900.00	\$ 38.33
9866	Installed/Active	03/31/2001	PGR50	AO SMITH	\$ 850.00	
9867	Installed/Active	06/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9868	Installed/Active	03/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
9869	Installed/Active	11/13/2001	PGR50	AO SMITH	\$ 850.00	
9870	Installed/Active	04/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
9871	Installed/Active	12/06/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9872	Installed/Active	08/15/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9873	Installed/Active	11/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9874	Installed/Active	03/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9875	Installed/Active	10/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9876	Installed/Active	01/28/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9877	Installed/Active	10/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9878	Installed/Active	12/23/1999	41XR50	RHEEM	\$ 850.00	
9879	Installed/Active	01/03/1995	PRV50NODS	STATE	\$ 1,075.00	
9880	Installed/Active	02/05/1990	FSG50	AO SMITH	\$ 850.00	
9881	Installed/Active	02/09/1990	PRV50NODS	STATE	\$ 1,075.00	
9882	Installed/Active	04/22/2005	LTN040	LOCHINVAR	\$ 850.00	
9883	Installed/Active	07/13/2004	GVC40	A. O. SMITH	\$ 850.00	
9884	Installed/Active	10/14/2011	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.64
9885	Installed/Active	12/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9886	Installed/Active	07/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9887	Installed/Active	01/03/2000	FSG50	AO SMITH	\$ 850.00	
9888	Installed/Active	06/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9889	Installed/Active	11/05/1990	21V502	RHEEM	\$ 850.00	
9890	Installed/Active	04/12/2000	FSGL40	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9891	Installed/Active	10/25/2006	PR650	STATE	\$ 1,075.00	
9892	Installed/Active	02/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9893	Installed/Active	12/28/1989	21V502	RHEEM	\$ 850.00	
9894	Installed/Active	12/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9895	Installed/Active	09/10/2000	41XR50	RHEEM	\$ 850.00	
9896	Installed/Active	01/16/2000	41XR50	RHEEM	\$ 850.00	
9897	Installed/Active	02/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9898	Installed/Active	02/19/2002	PGR50	AO SMITH	\$ 850.00	
9899	Installed/Active	11/19/2004	GVC40	A. O. SMITH	\$ 850.00	
9900	Installed/Active	11/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9901	Installed/Active	10/29/1990	PRX50	STATE	\$ 1,075.00	
9902	Installed/Active	06/22/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9903	Installed/Active	01/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9904	Installed/Active	06/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
9905	Installed/Active	02/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
9906	Installed/Active	10/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9907	Installed/Active	11/30/1998	FSG50	AO SMITH	\$ 850.00	
9908	Installed/Active	12/17/2002	PGR50	AO SMITH	\$ 850.00	
9909	Installed/Active	01/30/2006	LTN050G	LOCHINVAR	\$ 1,150.00	
9910	Installed/Active	01/25/2000	FSG50	AO SMITH	\$ 850.00	
9911	Installed/Active	12/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9912	Installed/Active	02/29/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
9913	Installed/Active	12/15/1986	21V506	RHEEM	\$ 1,150.00	
9914	Installed/Active	08/14/1998	FGR50	AO SMITH	\$ 850.00	
9915	Installed/Active	07/08/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
9916	Installed/Active	12/30/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
9917	Installed/Active	06/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9918	Installed/Active	10/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9919	Installed/Active	09/07/2005	LTN050G	LOCHINVAR	\$ 850.00	
9920	Installed/Active	09/02/2004	GVC40	A. O. SMITH	\$ 850.00	
9921	Installed/Active	10/11/2001	FSG50	AO SMITH	\$ 850.00	
9922	Installed/Active	12/27/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
9923	Installed/Active	11/21/1986	P506	RUUD	\$ 500.00	
9924	Installed/Active	01/16/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
9925	Installed/Active	09/16/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
9926	Installed/Active	09/09/2009	PGR50	AO SMITH	\$ 850.00	\$ 11.74
9927	Installed/Active	06/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9928	Installed/Active	02/22/2002	FSG50	AO SMITH	\$ 850.00	
9929	Installed/Active	08/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
9930	Installed/Active	12/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9931	Installed/Active	03/22/2005	GVC50	A. O. SMITH	\$ 850.00	
9932	Installed/Active	08/31/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
9933	Installed/Active	12/12/1996	PGR50	AO SMITH	\$ 850.00	
9934	Installed/Active	06/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
9935	Installed/Active	11/24/2008	PR640	STATE	\$ 1,075.00	\$ 16.47
9936	Installed/Active	02/12/1992	21DV50	RHEEM	\$ 1,075.00	
9937	Installed/Active	11/08/2006	LTN040G	LOCHINVAR	\$ 850.00	
9938	Installed/Active	01/30/1998	FGR40	AO SMITH	\$ 850.00	
9939	Installed/Active	09/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9940	Installed/Active	10/05/2002	PRX40	STATE	\$ 1,075.00	
9941	Installed/Active	04/19/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
9942	Installed/Active	09/12/2002	FSG50	AO SMITH	\$ 850.00	
9943	Installed/Active	01/17/1990	PRX50	STATE	\$ 1,075.00	
9944	Installed/Active	02/14/2008	FSG40	AO SMITH	\$ 350.00	\$ 12.50
9945	Installed/Active	07/03/2002	FSG50	AO SMITH	\$ 850.00	
9946	Installed/Active	02/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9947	Installed/Active	01/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
9948	Installed/Active	06/10/2001	FSGL40	AO SMITH	\$ 850.00	
9949	Installed/Active	06/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9950	Installed/Active	04/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9951	Installed/Active	04/21/2006	PR650	STATE	\$ 1,075.00	
9952	Installed/Active	01/26/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
9953	Installed/Active	10/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9954	Installed/Active	06/21/2004	GVC50	A. O. SMITH	\$ 850.00	
9955	Installed/Active	11/27/2006	PRV50NODS	STATE	\$ 1,075.00	
9956	Installed/Active	03/11/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
9957	Installed/Active	04/09/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
9958	Installed/Active	05/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9959	Installed/Active	02/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
9960	Installed/Active	11/30/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
9961	Installed/Active	02/26/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
9962	Installed/Active	03/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9963	Installed/Active	06/20/2005	XSN0401GEF	LOCHINVAR	\$ 850.00	
9964	Installed/Active	03/08/2004	XTN050	LOCHINVAR	\$ 850.00	
9965	Installed/Active	06/28/2004	PRX50	STATE	\$ 1,075.00	
9966	Installed/Active	01/02/2013	F72DUMMY	UNKNOWN AT CONVERSION	\$ 350.00	\$ 15.60
9967	Installed/Active	01/23/2002	FSG50	AO SMITH	\$ 850.00	
9968	Installed/Active	08/08/2001	PRX50	STATE	\$ 1,075.00	
9969	Installed/Active	10/04/2003	PGR50	AO SMITH	\$ 850.00	
9970	Installed/Active	02/13/1990	P505	RUUD	\$ 1,150.00	
9971	Installed/Active	06/23/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9972	Installed/Active	01/15/2003	FSG50	AO SMITH	\$ 850.00	
9973	Installed/Active	10/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
9974	Installed/Active	02/16/2005	PRX50	STATE	\$ 1,075.00	
9975	Installed/Active	04/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
9976	Installed/Active	09/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
9977	Installed/Active	01/12/2004	XTN050	LOCHINVAR	\$ 850.00	
9978	Installed/Active	02/10/2005	GCVL40	A. O. SMITH	\$ 850.00	
9979	Installed/Active	02/06/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9980	Installed/Active	10/16/2001	FSG50	AO SMITH	\$ 850.00	
9981	Installed/Active	05/02/2005	LTN050	LOCHINVAR	\$ 850.00	
9982	Installed/Active	09/12/2002	PGR50	AO SMITH	\$ 850.00	
9983	Installed/Active	04/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
9984	Installed/Active	01/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9985	Installed/Active	06/05/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
9986	Installed/Active	08/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
9987	Installed/Active	10/12/2006	PR650	STATE	\$ 1,075.00	
9988	Installed/Active	01/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
9989	Installed/Active	07/07/1989	FSG50	AO SMITH	\$ 850.00	
9990	Installed/Active	10/11/1989	21V506	RHEEM	\$ 1,150.00	
9991	Installed/Active	09/08/1989	FSGL40	AO SMITH	\$ 850.00	
9992	Installed/Active	09/03/2001	PGR50	AO SMITH	\$ 850.00	
9993	Installed/Active	01/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
9994	Installed/Active	10/08/2003	PVR50	AO SMITH	\$ 850.00	
9995	Installed/Active	05/19/2008	LTN051G	LOCHINVAR	\$ 850.00	\$ 10.23
9996	Installed/Active	09/20/2006	PR650X0DS	STATE	\$ 1,075.00	
9997	Installed/Active	02/24/2000	41XR50	RHEEM	\$ 850.00	
9998	Installed/Active	11/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
9999	Installed/Active	02/14/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10000	Installed/Active	06/02/2004	PGR50	AO SMITH	\$ 850.00	
10001	Installed/Active	10/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10002	Installed/Active	09/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10003	Installed/Active	01/16/2013	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
10004	Installed/Active	02/12/1999	FSG40	AO SMITH	\$ 850.00	
10005	Installed/Active	07/18/2005	LTN050	LOCHINVAR	\$ 1,150.00	
10006	Installed/Active	10/25/1989	P506	RUUD	\$ 1,150.00	
10007	Installed/Active	03/24/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10008	Installed/Active	07/20/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10009	Installed/Active	06/28/2005	LTN050	LOCHINVAR	\$ 850.00	
10010	Installed/Active	03/01/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10011	Installed/Active	09/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10012	Installed/Active	06/07/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10013	Installed/Active	08/07/2004	GVC50	A. O. SMITH	\$ 850.00	
10014	Installed/Active	04/16/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
10015	Installed/Active	12/27/1999	PHR50	RUUD	\$ 850.00	
10016	Installed/Active	03/16/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 12.75
10017	Installed/Active	05/20/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
10018	Installed/Active	08/17/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
10019	Installed/Active	09/19/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10020	Installed/Active	02/28/2000	PGR50	AO SMITH	\$ 850.00	
10021	Installed/Active	10/11/2004	PRX50	STATE	\$ 1,075.00	
10022	Installed/Active	09/27/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10023	Installed/Active	11/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10024	Installed/Active	11/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10025	Installed/Active	03/17/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10026	Installed/Active	02/27/2008	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
10027	Installed/Active	08/24/2005	LTN050	LOCHINVAR	\$ 850.00	
10028	Installed/Active	04/27/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
10029	Installed/Active	10/23/1989	FSG50	AO SMITH	\$ 850.00	
10030	Installed/Active	04/14/1999	21V506	RHEEM	\$ 1,150.00	
10031	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10032	Installed/Active	04/01/1998	FSG50	AO SMITH	\$ 850.00	
10033	Installed/Active	11/08/2010	GVC50	A. O. SMITH	\$ 850.00	\$ 12.05
10034	Installed/Active	03/13/2008	PRV50N0DS	STATE	\$ 1,075.00	\$ 14.35
10035	Installed/Active	01/14/2002	PRX50	STATE	\$ 1,075.00	
10036	Installed/Active	04/07/1988	FSG50	AO SMITH	\$ 850.00	
10037	Installed/Active	02/24/1995	PHR50	RUUD	\$ 850.00	
10038	Installed/Active	11/08/1999	PGR50	AO SMITH	\$ 850.00	
10039	Installed/Active	11/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10040	Installed/Active	05/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10041	Installed/Active	09/17/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
10042	Installed/Active	03/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10043	Installed/Active	01/16/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
10044	Installed/Active	01/14/2005	LTN040GEF	LOCHINVAR	\$ 850.00	
10045	Installed/Active	02/19/2005	LTN050	LOCHINVAR	\$ 850.00	
10046	Installed/Active	11/18/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10047	Installed/Active	03/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10048	Installed/Active	09/27/1999	FSG40	AO SMITH	\$ 850.00	
10049	Installed/Active	04/16/2004	FCV50	AO SMITH	\$ 850.00	
10050	Installed/Active	08/01/1988	FSGL40	AO SMITH	\$ 350.00	
10051	Installed/Active	07/13/1997	FSGL40	AO SMITH	\$ 850.00	
10052	Installed/Active	09/23/1998	41V50S	RHEEM	\$ 850.00	
10053	Installed/Active	02/23/1996	PGR50	AO SMITH	\$ 850.00	
10054	Installed/Active	07/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10055	Installed/Active	08/12/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10056	Installed/Active	09/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
10057	Installed/Active	01/21/2002	PRX50	STATE	\$ 1,075.00	
10058	Installed/Active	08/24/1988	FSG50	AO SMITH	\$ 850.00	
10059	Installed/Active	07/08/2008	21V506	RHEEM	\$ 1,150.00	\$ 14.05
10060	Installed/Active	11/29/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10061	Installed/Active	03/21/2006	PR650	STATE	\$ 1,075.00	
10062	Installed/Active	06/15/2005	LTN050	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10063	Installed/Active	01/08/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
10064	Installed/Active	04/29/2003	PRX50	STATE	\$ 1,075.00	
10065	Installed/Active	12/28/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10066	Installed/Active	10/09/1999	FSG50	AO SMITH	\$ 850.00	
10067	Installed/Active	06/13/2002	PGR50	AO SMITH	\$ 850.00	
10068	Installed/Active	12/10/1987	FSG50	AO SMITH	\$ 850.00	
10069	Installed/Active	07/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10070	Installed/Active	04/18/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10071	Installed/Active	09/24/2001	PGR40	AO SMITH	\$ 850.00	
10072	Installed/Active	09/08/2004	XVR50	A. O. SMITH	\$ 850.00	
10073	Installed/Active	12/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10074	Installed/Active	06/02/2005	LTN050	LOCHINVAR	\$ 850.00	
10075	Installed/Active	04/26/2006	PR650	STATE	\$ 1,075.00	
10076	Installed/Active	04/05/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
10077	Installed/Active	03/22/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10078	Installed/Active	08/19/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10079	Installed/Active	06/11/2011	F72DUMMY	UNKNOWN AT CONVERSION	\$ 350.00	\$ 15.47
10080	Installed/Active	05/21/2003	FSG50	AO SMITH	\$ 850.00	
10081	Installed/Active	06/19/2001	21DV50	RHEEM	\$ 1,075.00	
10082	Installed/Active	09/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10083	Installed/Active	10/19/1990	PRV50NODS	STATE	\$ 1,075.00	
10084	Installed/Active	10/20/1998	FSG50	AO SMITH	\$ 850.00	
10085	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10086	Installed/Active	08/02/2011	21V506	RHEEM	\$ 1,150.00	\$ 17.37
10087	Installed/Active	03/26/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10088	Installed/Active	10/29/2004	GVC50	A. O. SMITH	\$ 850.00	
10089	Installed/Active	10/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10090	Installed/Active	02/25/2005	21V506	RHEEM	\$ 1,150.00	
10091	Installed/Active	03/30/2001	FSGL40	AO SMITH	\$ 850.00	
10092	Installed/Active	06/06/1990	FSG50	AO SMITH	\$ 850.00	
10093	Installed/Active	06/23/2004	PRX50	STATE	\$ 1,075.00	
10094	Installed/Active	03/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10095	Installed/Active	05/02/2001	21V506	RHEEM	\$ 1,150.00	
10096	Installed/Active	09/16/2006	PR650	STATE	\$ 1,075.00	
10097	Installed/Active	07/27/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
10098	Installed/Active	07/31/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10099	Installed/Active	09/15/2003	PRX50	STATE	\$ 1,150.00	
10100	Installed/Active	07/25/2001	FSG50	AO SMITH	\$ 850.00	
10101	Installed/Active	07/04/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10102	Installed/Active	04/12/1990	FSG50	AO SMITH	\$ 850.00	
10103	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
10104	Installed/Active	08/22/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10105	Installed/Active	09/23/2006	PR650	STATE	\$ 1,075.00	
10106	Installed/Active	10/19/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10107	Installed/Active	10/30/1996	FGR50	AO SMITH	\$ 850.00	
10108	Installed/Active	12/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10109	Installed/Active	05/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10110	Installed/Active	09/10/2008	42VR50	RHEEM	\$ 850.00	\$ 10.23
10111	Installed/Active	11/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10112	Installed/Active	05/28/1997	FSG40	AO SMITH	\$ 850.00	
10113	Installed/Active	03/16/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10114	Installed/Active	10/11/2005	PR650	STATE	\$ 1,075.00	
10115	Installed/Active	10/15/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10116	Installed/Active	03/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10117	Installed/Active	02/04/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10118	Installed/Active	07/26/1990	FSGL30	AO SMITH	\$ 350.00	
10119	Installed/Active	10/23/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
10120	Installed/Active	09/21/2005	LTN050G	LOCHINVAR	\$ 850.00	
10121	Installed/Active	05/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10122	Installed/Active	06/09/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10123	Installed/Active	11/27/1990	BT155	AO SMITH	\$ 1,900.00	
10124	Installed/Active	09/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10125	Installed/Active	04/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
10126	Installed/Active	10/21/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
10127	Installed/Active	12/17/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10128	Installed/Active	12/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10129	Installed/Active	02/19/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10130	Installed/Active	12/22/2006	PR650X0DS	STATE	\$ 1,075.00	
10131	Installed/Active	06/06/2001	PRX50	STATE	\$ 1,075.00	
10132	Installed/Active	06/24/1999	FGR50	AO SMITH	\$ 850.00	
10133	Installed/Active	02/09/1991	RF67120	RUUD	\$ 1,900.00	
10134	Installed/Active	01/21/1991	D74DUMMY	AO SMITH	\$ 1,900.00	
10135	Installed/Active	01/29/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10136	Installed/Active	01/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10137	Installed/Active	03/11/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10138	Installed/Active	04/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10139	Installed/Active	01/02/2001	41VR50	RHEEM	\$ 850.00	
10140	Installed/Active	07/16/2001	FSG50	AO SMITH	\$ 850.00	
10141	Installed/Active	09/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10142	Installed/Active	03/03/2006	21V506	RHEEM	\$ 1,150.00	
10143	Installed/Active	03/08/2002	FSG50	AO SMITH	\$ 850.00	
10144	Installed/Active	06/27/2005	LTN050	LOCHINVAR	\$ 850.00	
10145	Installed/Active	09/01/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
10146	Installed/Active	11/11/2004	GVC50	A. O. SMITH	\$ 850.00	
10147	Installed/Active	07/30/2005	LTN050	LOCHINVAR	\$ 850.00	
10148	Installed/Active	05/08/2003	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10149	Installed/Active	05/11/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
10150	Installed/Active	06/06/2009	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
10151	Installed/Active	01/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10152	Installed/Active	05/11/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
10153	Installed/Active	03/09/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10154	Installed/Active	12/22/2001	FSG50	AO SMITH	\$ 850.00	
10155	Installed/Active	01/29/2002	PR650	STATE	\$ 1,075.00	
10156	Installed/Active	02/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10157	Installed/Active	06/09/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10158	Installed/Active	03/09/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10159	Installed/Active	09/11/2000	FSG40	AO SMITH	\$ 850.00	
10160	Installed/Active	05/26/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
10161	Installed/Active	01/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10162	Installed/Active	12/11/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
10163	Installed/Active	06/22/1989	P506	RUUD	\$ 1,150.00	
10164	Installed/Active	10/24/2011	PH2DV50F	Rheem/Ruud	\$ 1,075.00	\$ 17.74
10165	Installed/Active	03/29/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10166	Installed/Active	10/30/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10167	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
10168	Installed/Active	07/25/1989	FSG50	AO SMITH	\$ 850.00	
10169	Installed/Active	02/21/2012	41XR50	RHEEM	\$ 850.00	\$ 12.64
10170	Installed/Active	04/30/2004	XTN050	LOCHINVAR	\$ 850.00	
10171	Installed/Active	03/01/2002	PGR50	AO SMITH	\$ 850.00	
10172	Installed/Active	04/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10173	Installed/Active	04/14/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
10174	Installed/Active	11/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10175	Installed/Active	04/28/2004	GVC50	A. O. SMITH	\$ 850.00	
10176	Installed/Active	06/04/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10177	Installed/Active	10/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10178	Installed/Active	05/13/2002	PRX50	STATE	\$ 1,075.00	
10179	Installed/Active	02/22/2013	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10180	Installed/Active	03/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10181	Installed/Active	07/09/2012	Mi40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10182	Installed/Active	12/23/1988	PRX50	STATE	\$ 1,075.00	
10183	Installed/Active	02/26/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.05
10184	Installed/Active	06/20/1989	PRV50NODS	STATE	\$ 1,075.00	
10185	Installed/Active	06/04/2005	PR650	STATE	\$ 1,075.00	
10186	Installed/Active	01/28/2002	FSG50	AO SMITH	\$ 850.00	
10187	Installed/Active	12/04/2001	PGR50	AO SMITH	\$ 850.00	
10188	Installed/Active	03/30/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10189	Installed/Active	03/29/1989	21V502	RHEEM	\$ 850.00	
10190	Installed/Active	05/28/2001	41VR50	RHEEM	\$ 850.00	
10191	Installed/Active	05/11/2006	PR650	STATE	\$ 1,075.00	
10192	Installed/Active	10/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10193	Installed/Active	11/16/1989	FSG50	AO SMITH	\$ 850.00	
10194	Installed/Active	06/26/2008	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 16.35
10195	Installed/Active	01/23/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10196	Installed/Active	11/26/1999	PR650	STATE	\$ 1,075.00	
10197	Installed/Active	01/21/1991	P506	RUUD	\$ 1,125.00	
10198	Installed/Active	08/17/2005	LTN050	LOCHINVAR	\$ 850.00	
10199	Installed/Active	12/17/2004	FSG50	AO SMITH	\$ 850.00	
10200	Installed/Active	04/24/1998	FSG50	AO SMITH	\$ 850.00	
10201	Installed/Active	04/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10202	Installed/Active	02/22/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10203	Installed/Active	08/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10204	Installed/Active	01/06/2002	PRX50	STATE	\$ 1,075.00	
10205	Installed/Active	11/09/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
10206	Installed/Active	03/08/2005	GVC50	A. O. SMITH	\$ 850.00	
10207	Installed/Active	05/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10208	Installed/Active	05/14/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10209	Installed/Active	07/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10210	Installed/Active	10/24/2005	LTN040G	LOCHINVAR	\$ 850.00	
10211	Installed/Active	05/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10212	Installed/Active	10/10/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10213	Installed/Active	06/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10214	Installed/Active	11/09/2005	PR650	STATE	\$ 1,075.00	
10215	Installed/Active	05/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10216	Installed/Active	10/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10217	Installed/Active	09/11/2003	41V40S	RHEEM	\$ 850.00	
10218	Installed/Active	03/11/2002	21V506	RHEEM	\$ 1,125.00	
10219	Installed/Active	02/07/2005	LTN050	LOCHINVAR	\$ 850.00	
10220	Installed/Active	03/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10221	Installed/Active	06/26/1999	FSG50	AO SMITH	\$ 850.00	
10222	Installed/Active	05/18/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10223	Installed/Active	07/01/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10224	Installed/Active	11/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10225	Installed/Active	03/27/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10226	Installed/Active	01/18/1990	21V506	RHEEM	\$ 1,150.00	
10227	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
10228	Installed/Active	08/26/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10229	Installed/Active	09/18/1989	FSG50	AO SMITH	\$ 850.00	
10230	Installed/Active	07/30/1990	PRV50NODS	STATE	\$ 1,075.00	
10231	Installed/Active	01/29/1998	PGR50	AO SMITH	\$ 850.00	
10232	Installed/Active	04/13/1999	FSG50	AO SMITH	\$ 850.00	
10233	Installed/Active	08/04/2003	PRX50	STATE	\$ 1,075.00	
10234	Installed/Active	12/20/2009	41V50	RHEEM	\$ 850.00	\$ 11.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10235	Installed/Active	11/20/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10236	Installed/Active	11/16/2005	LTN050G	LOCHINVAR	\$ 850.00	
10237	Installed/Active	06/29/1999	41XR50	RHEEM	\$ 850.00	
10238	Installed/Active	03/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10239	Installed/Active	06/07/1988	FSG50	AO SMITH	\$ 850.00	
10240	Installed/Active	01/23/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10241	Installed/Active	11/29/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10242	Installed/Active	10/15/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10243	Installed/Active	11/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10244	Installed/Active	12/18/2002	PRX50	STATE	\$ 1,075.00	
10245	Installed/Active	10/16/2006	PR650	STATE	\$ 1,075.00	
10246	Installed/Active	02/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10247	Installed/Active	03/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
10248	Installed/Active	12/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
10249	Installed/Active	09/08/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10250	Installed/Active	05/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10251	Installed/Active	12/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10252	Installed/Active	12/05/2001	FSG50	AO SMITH	\$ 850.00	
10253	Installed/Active	04/19/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
10254	Installed/Active	09/29/2005	PR650	STATE	\$ 1,075.00	
10255	Installed/Active	07/07/2000	FSG40	AO SMITH	\$ 850.00	
10256	Installed/Active	12/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10257	Installed/Active	02/02/2001	PGR50	AO SMITH	\$ 850.00	
10258	Installed/Active	03/13/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
10259	Installed/Active	11/06/2001	PGR50	AO SMITH	\$ 850.00	
10260	Installed/Active	03/01/2002	FSG50	AO SMITH	\$ 850.00	
10261	Installed/Active	08/23/2005	LTN050G	LOCHINVAR	\$ 850.00	
10262	Installed/Active	11/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10263	Installed/Active	10/26/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10264	Installed/Active	10/07/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10265	Installed/Active	01/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10266	Installed/Active	06/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10267	Installed/Active	11/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10268	Installed/Active	09/10/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10269	Installed/Active	04/13/1988	FSG50	AO SMITH	\$ 850.00	
10270	Installed/Active	12/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10271	Installed/Active	08/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10272	Installed/Active	01/15/2001	PGR50	AO SMITH	\$ 850.00	
10273	Installed/Active	02/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10274	Installed/Active	08/31/1999	PGR50	AO SMITH	\$ 850.00	
10275	Installed/Active	10/03/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
10276	Installed/Active	12/18/2000	PGR50	AO SMITH	\$ 850.00	
10277	Installed/Active	02/11/2005	GVC50	A. O. SMITH	\$ 850.00	
10278	Installed/Active	02/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10279	Installed/Active	03/01/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10280	Installed/Active	08/28/2006	PR650	STATE	\$ 1,075.00	
10281	Installed/Active	11/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10282	Installed/Active	08/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10283	Installed/Active	08/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
10284	Installed/Active	10/11/1990	FSGL40	AO SMITH	\$ 850.00	
10285	Installed/Active	10/15/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10286	Installed/Active	09/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
10287	Installed/Active	03/21/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 10.23
10288	Installed/Active	01/29/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10289	Installed/Active	06/21/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
10290	Installed/Active	08/26/1997	41VR50	RHEEM	\$ 850.00	
10291	Installed/Active	03/30/1999	PGR50	AO SMITH	\$ 850.00	
10292	Installed/Active	07/03/2001	FSG50	AO SMITH	\$ 850.00	
10293	Installed/Active	07/01/2002	FSG50	AO SMITH	\$ 850.00	
10294	Installed/Active	02/20/2006	LSN041G	LOCHINVAR	\$ 850.00	
10295	Installed/Active	03/27/2003	FSG50	AO SMITH	\$ 850.00	
10296	Installed/Active	03/14/2005	P506	RUUD	\$ 1,150.00	
10297	Installed/Active	01/09/2007	41V50	RHEEM	\$ 850.00	
10298	Installed/Active	08/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10299	Installed/Active	01/27/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10300	Installed/Active	08/08/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10301	Installed/Active	04/26/2003	PGR50	AO SMITH	\$ 850.00	
10302	Installed/Active	09/17/2004	PRX50	STATE	\$ 1,075.00	
10303	Installed/Active	08/10/1999	FSG50	AO SMITH	\$ 850.00	
10304	Installed/Active	05/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
10305	Installed/Active	05/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10306	Installed/Active	02/24/2012	D71	UNKNOWN	\$ 1,150.00	\$ 17.37
10307	Installed/Active	08/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10308	Installed/Active	04/02/1998	FSG50	AO SMITH	\$ 850.00	
10309	Installed/Active	04/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
10310	Installed/Active	03/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10311	Installed/Active	02/15/1990	PRV40NODS	STATE	\$ 1,075.00	
10312	Installed/Active	03/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10313	Installed/Active	04/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10314	Installed/Active	05/29/2001	PRX50	STATE	\$ 1,075.00	
10315	Installed/Active	09/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10316	Installed/Active	08/18/2004	XVR50	A. O. SMITH	\$ 850.00	
10317	Installed/Active	05/13/2002	PRX50	STATE	\$ 1,075.00	
10318	Installed/Active	02/15/1990	PRV40NODS	STATE	\$ 1,075.00	
10319	Installed/Active	12/18/2001	PGR50	AO SMITH	\$ 850.00	
10320	Installed/Active	05/18/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10321	Installed/Active	08/10/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
10322	Installed/Active	09/06/2006	LSN041G	LOCHINVAR	\$ 850.00	
10323	Installed/Active	05/02/1990	PRV50NODS	STATE	\$ 1,075.00	
10324	Installed/Active	07/13/1999	FGR50	AO SMITH	\$ 850.00	
10325	Installed/Active	01/14/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10326	Installed/Active	03/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10327	Installed/Active	02/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
10328	Installed/Active	02/19/2001	41XR50	RHEEM	\$ 850.00	
10329	Installed/Active	06/17/2005	21V506	RHEEM	\$ 1,150.00	
10330	Installed/Active	12/08/1989	FSG50	AO SMITH	\$ 850.00	
10331	Installed/Active	08/12/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
10332	Installed/Active	02/17/2005	GVC50	A. O. SMITH	\$ 850.00	
10333	Installed/Active	10/26/1998	FSG50	AO SMITH	\$ 850.00	
10334	Installed/Active	10/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10335	Installed/Active	05/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10336	Installed/Active	03/05/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10337	Installed/Active	02/14/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10338	Installed/Active	11/16/2001	FSG40	AO SMITH	\$ 850.00	
10339	Installed/Active	11/05/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10340	Installed/Active	04/19/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
10341	Installed/Active	12/01/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
10342	Installed/Active	06/23/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
10343	Installed/Active	01/05/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
10344	Installed/Active	08/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10345	Installed/Active	09/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10346	Installed/Active	07/24/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10347	Installed/Active	08/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10348	Installed/Active	04/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10349	Installed/Active	03/01/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10350	Installed/Active	06/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10351	Installed/Active	12/20/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
10352	Installed/Active	03/06/2005	PRX40	STATE	\$ 1,075.00	
10353	Installed/Active	01/30/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10354	Installed/Active	08/23/1989	FSG50	AO SMITH	\$ 850.00	
10355	Installed/Active	10/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10356	Installed/Active	09/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10357	Installed/Active	11/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10358	Installed/Active	07/10/2004	PRX50	STATE	\$ 1,075.00	
10359	Installed/Active	07/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10360	Installed/Active	05/28/2002	PGR50	AO SMITH	\$ 850.00	
10361	Installed/Active	07/06/2006	PR650	STATE	\$ 1,075.00	
10362	Installed/Active	02/27/1989	FSG40	AO SMITH	\$ 850.00	
10363	Installed/Active	04/04/2002	PRX50	STATE	\$ 1,075.00	
10364	Installed/Active	01/31/2000	PGR50	AO SMITH	\$ 850.00	
10365	Installed/Active	11/11/2010	XVR50	A. O. SMITH	\$ 850.00	\$ 12.05
10366	Installed/Active	10/13/2004	LTN050	LOCHINVAR	\$ 850.00	
10367	Installed/Active	08/09/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10368	Installed/Active	03/07/1989	P506	RUUD	\$ 1,150.00	
10369	Installed/Active	03/10/2006	PR650	STATE	\$ 1,075.00	
10370	Installed/Active	03/20/2006	21DV50	RHEEM	\$ 1,075.00	
10371	Installed/Active	04/11/2003	FSG50	AO SMITH	\$ 850.00	
10372	Installed/Active	09/16/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
10373	Installed/Active	11/08/2000	FSG50	AO SMITH	\$ 850.00	
10374	Installed/Active	06/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
10375	Installed/Active	05/05/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
10376	Installed/Active	03/19/2001	PRX50	STATE	\$ 1,075.00	
10377	Installed/Active	11/14/2005	PR650	STATE	\$ 1,075.00	
10378	Installed/Active	03/03/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10379	Installed/Active	07/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10380	Installed/Active	01/21/2004	FCV50	AO SMITH	\$ 850.00	
10381	Installed/Active	10/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10382	Installed/Active	02/11/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10383	Installed/Active	05/14/2003	21V506	RHEEM	\$ 1,150.00	
10384	Installed/Active	01/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10385	Installed/Active	02/19/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10386	Installed/Active	03/21/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10387	Installed/Active	05/25/1997	PRV50NODS	STATE	\$ 1,075.00	
10388	Installed/Active	05/12/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10389	Installed/Active	10/20/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
10390	Installed/Active	11/13/1999	41XR50	RHEEM	\$ 850.00	
10391	Installed/Active	02/13/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
10392	Installed/Active	08/16/2000	21V506	RHEEM	\$ 1,125.00	
10393	Installed/Active	07/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10394	Installed/Active	08/16/2001	PGR40	AO SMITH	\$ 850.00	
10395	Installed/Active	02/26/1990	PRX50	STATE	\$ 1,075.00	
10396	Installed/Active	08/28/2003	PRX50	STATE	\$ 1,075.00	
10397	Installed/Active	02/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10398	Installed/Active	09/04/2001	PGR50	AO SMITH	\$ 850.00	
10399	Installed/Active	07/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10400	Installed/Active	12/24/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10401	Installed/Active	10/12/2000	41XR50	RHEEM	\$ 850.00	
10402	Installed/Active	04/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
10403	Installed/Active	06/09/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
10404	Installed/Active	02/23/2000	FSG40	AO SMITH	\$ 850.00	
10405	Installed/Active	11/19/2009	21VR50	RHEEM	\$ 850.00	\$ 11.74
10406	Installed/Active	01/11/1990	P506	RUUD	\$ 1,150.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10407	Installed/Active	11/03/2000	PR650	STATE	\$ 1,075.00	
10408	Installed/Active	12/28/1994	PGR50	AO SMITH	\$ 850.00	
10409	Installed/Active	09/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10410	Installed/Active	01/02/1995	PRX50	STATE	\$ 1,075.00	
10411	Installed/Active	07/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10412	Installed/Active	10/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10413	Installed/Active	07/09/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
10414	Installed/Active	05/30/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10415	Installed/Active	07/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10416	Installed/Active	02/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10417	Installed/Active	03/20/2002	PRX50	STATE	\$ 1,075.00	
10418	Installed/Active	04/07/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
10419	Installed/Active	02/18/1988	FSG50	AO SMITH	\$ 850.00	
10420	Installed/Active	08/24/2000	PHR50	RUUD	\$ 850.00	
10421	Installed/Active	10/05/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10422	Installed/Active	02/12/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
10423	Installed/Active	10/26/2004	GCVL40	A. O. SMITH	\$ 850.00	
10424	Installed/Active	12/03/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
10425	Installed/Active	06/12/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10426	Installed/Active	01/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10427	Installed/Active	10/31/2005	LTN050G	LOCHINVAR	\$ 850.00	
10428	Installed/Active	12/13/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10429	Installed/Active	11/09/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
10430	Installed/Active	04/04/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10431	Installed/Active	11/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10432	Installed/Active	04/01/1988	21V502	RHEEM	\$ 850.00	
10433	Installed/Active	05/02/1988	PRX50	STATE	\$ 1,075.00	
10434	Installed/Active	06/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10435	Installed/Active	08/18/2005	LTN050	LOCHINVAR	\$ 850.00	
10436	Installed/Active	10/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10437	Installed/Active	11/13/2009	PRX40	STATE	\$ 1,075.00	\$ 16.47
10438	Installed/Active	01/14/2005	XVR50	A. O. SMITH	\$ 850.00	
10439	Installed/Active	02/25/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10440	Installed/Active	02/21/2003	41XR50	RHEEM	\$ 850.00	
10441	Installed/Active	07/29/1988	FSG50	AO SMITH	\$ 850.00	
10442	Installed/Active	09/02/2001	FSG50	AO SMITH	\$ 850.00	
10443	Installed/Active	10/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10444	Installed/Active	01/10/1997	PRV50NODS	STATE	\$ 1,075.00	
10445	Installed/Active	05/21/2002	FSG50	AO SMITH	\$ 850.00	
10446	Installed/Active	05/16/1988	FSG50	AO SMITH	\$ 850.00	
10447	Installed/Active	06/26/2002	PGR50	AO SMITH	\$ 850.00	
10448	Installed/Active	09/17/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
10449	Installed/Active	05/02/2005	PR640	STATE	\$ 1,075.00	
10450	Installed/Active	07/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10451	Installed/Active	01/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10452	Installed/Active	02/21/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
10453	Installed/Active	08/31/2003	FSG50	AO SMITH	\$ 850.00	
10454	Installed/Active	03/18/2007	XTN050	LOCHINVAR	\$ 850.00	\$ 10.23
10455	Installed/Active	06/13/2003	PGR50	AO SMITH	\$ 850.00	
10456	Installed/Active	06/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10457	Installed/Active	04/09/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
10458	Installed/Active	09/17/1990	FSG50	AO SMITH	\$ 850.00	
10459	Installed/Active	12/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
10460	Installed/Active	05/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10461	Installed/Active	02/19/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
10462	Installed/Active	09/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10463	Installed/Active	03/16/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10464	Installed/Active	01/21/2005	XTN050	LOCHINVAR	\$ 850.00	
10465	Installed/Active	11/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
10466	Installed/Active	03/22/2003	PGR50	AO SMITH	\$ 850.00	
10467	Installed/Active	01/17/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10468	Installed/Active	05/16/2000	FSG40	AO SMITH	\$ 850.00	
10469	Installed/Active	04/01/2002	FSG50	AO SMITH	\$ 850.00	
10470	Installed/Active	11/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10471	Installed/Active	02/16/2007	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10472	Installed/Active	10/19/1997	P502	RUUD	\$ 850.00	
10473	Installed/Active	11/30/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
10474	Installed/Active	10/11/2000	FSG40	AO SMITH	\$ 850.00	
10475	Installed/Active	06/25/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10476	Installed/Active	01/10/2002	PGR50	AO SMITH	\$ 850.00	
10477	Installed/Active	09/28/2001	FSGL40	AO SMITH	\$ 850.00	
10478	Installed/Active	01/29/1991	FSG50	AO SMITH	\$ 850.00	
10479	Installed/Active	09/23/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
10480	Installed/Active	09/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10481	Installed/Active	05/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
10482	Installed/Active	05/25/2005	PR650	STATE	\$ 1,075.00	
10483	Installed/Active	05/19/2001	41V50	RHEEM	\$ 850.00	
10484	Installed/Active	04/10/2002	PRX50	STATE	\$ 1,075.00	
10485	Installed/Active	04/14/1995	FGR50	AO SMITH	\$ 850.00	
10486	Installed/Active	01/04/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10487	Installed/Active	08/01/1990	SBF100199NES	STATE	\$ 3,350.00	
10488	Installed/Active	06/15/2008	FSG50	AO SMITH	\$ 850.00	\$ 10.23
10489	Installed/Active	01/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10490	Installed/Active	01/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10491	Installed/Active	03/08/2005	FSG50	AO SMITH	\$ 850.00	
10492	Installed/Active	08/01/1990	SBF100199NES	STATE	\$ 3,350.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10493	Installed/Active	01/10/2002	41XR50	RHEEM	\$ 850.00	
10494	Installed/Active	11/01/2004	GVC50	A. O. SMITH	\$ 850.00	
10495	Installed/Active	10/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10496	Installed/Active	03/07/1989	P506	RUUD	\$ 1,150.00	
10497	Installed/Active	03/16/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10498	Installed/Active	10/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10499	Installed/Active	02/16/2005	PRX50	STATE	\$ 1,075.00	
10500	Installed/Active	04/03/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10501	Installed/Active	04/09/2008	FSG50	AO SMITH	\$ 850.00	\$ 10.23
10502	Installed/Active	04/09/2004	GVC50	A. O. SMITH	\$ 850.00	
10503	Installed/Active	07/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
10504	Installed/Active	05/29/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
10505	Installed/Active	03/05/2005	XVR50	A. O. SMITH	\$ 850.00	
10506	Installed/Active	06/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10507	Installed/Active	09/18/2002	PGR50	AO SMITH	\$ 850.00	
10508	Installed/Active	12/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10509	Installed/Active	08/17/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
10510	Installed/Active	10/28/2004	PRX50	STATE	\$ 1,075.00	
10511	Installed/Active	10/27/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
10512	Installed/Active	06/04/2004	PRX50	STATE	\$ 1,075.00	
10513	Installed/Active	09/26/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10514	Installed/Active	07/13/2001	PR650	STATE	\$ 1,075.00	
10515	Installed/Active	04/07/2003	41V50	RHEEM	\$ 850.00	
10516	Installed/Active	10/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10517	Installed/Active	07/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
10518	Installed/Active	04/03/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10519	Installed/Active	04/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10520	Installed/Active	11/28/1989	FSG50	AO SMITH	\$ 850.00	
10521	Installed/Active	06/10/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
10522	Installed/Active	02/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10523	Installed/Active	12/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10524	Installed/Active	07/31/2001	PGR50	AO SMITH	\$ 850.00	
10525	Installed/Active	08/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10526	Installed/Active	10/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10527	Installed/Active	12/07/2000	FSGL40	AO SMITH	\$ 850.00	
10528	Installed/Active	07/23/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10529	Installed/Active	06/29/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10530	Installed/Active	03/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
10531	Installed/Active	12/08/2003	FCV50	AO SMITH	\$ 850.00	
10532	Installed/Active	06/29/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10533	Installed/Active	03/23/1990	B71DUMMY	AMERICAN	\$ 850.00	
10534	Installed/Active	01/03/2000	41V50	RHEEM	\$ 850.00	
10535	Installed/Active	12/10/2011	G67114	RHEEM	\$ 1,900.00	\$ 41.30
10536	Installed/Active	06/26/1990	FSG50	AO SMITH	\$ 850.00	
10537	Installed/Active	09/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10538	Installed/Active	03/23/2010	41V50	RHEEM	\$ 850.00	\$ 11.74
10539	Installed/Active	09/10/2011	PH2DV50F	RUUD	\$ 850.00	\$ 12.64
10540	Installed/Active	12/14/2005	LTN050G	LOCHINVAR	\$ 850.00	
10541	Installed/Active	06/23/2001	21V506	RHEEM	\$ 1,150.00	
10542	Installed/Active	07/24/2012	M140T8FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10543	Installed/Active	12/24/2001	PGR50	AO SMITH	\$ 850.00	
10544	Installed/Active	02/14/2005	GVC50	A. O. SMITH	\$ 850.00	
10545	Installed/Active	09/20/1989	FSG40	AO SMITH	\$ 850.00	
10546	Installed/Active	06/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10547	Installed/Active	03/02/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
10548	Installed/Active	05/10/1999	PR650	STATE	\$ 1,075.00	
10549	Installed/Active	02/10/2001	PRX50	STATE	\$ 1,075.00	
10550	Installed/Active	10/24/1990	FSG50	AO SMITH	\$ 850.00	
10551	Installed/Active	11/1/2004	XVR50	A. O. SMITH	\$ 850.00	
10552	Installed/Active	12/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
10553	Installed/Active	07/25/2002	FSG50	AO SMITH	\$ 850.00	
10554	Installed/Active	12/18/2000	PRX50	STATE	\$ 1,075.00	
10555	Installed/Active	10/11/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10556	Installed/Active	06/14/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10557	Installed/Active	06/26/2002	FSG50	AO SMITH	\$ 850.00	
10558	Installed/Active	11/10/2004	GVC50	A. O. SMITH	\$ 850.00	
10559	Installed/Active	06/30/2002	PGR50	AO SMITH	\$ 850.00	
10560	Installed/Active	11/20/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
10561	Installed/Active	10/25/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10562	Installed/Active	03/29/1990	P506	RUUD	\$ 1,125.00	
10563	Installed/Active	06/29/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
10564	Installed/Active	09/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10565	Installed/Active	12/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10566	Installed/Active	07/07/2006	FSGL30	AO SMITH	\$ 350.00	
10567	Installed/Active	12/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10568	Installed/Active	10/06/1987	FSG50	AO SMITH	\$ 850.00	
10569	Installed/Active	08/13/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
10570	Installed/Active	06/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10571	Installed/Active	07/07/2006	PH30	RUUD	\$ 350.00	
10572	Installed/Active	08/10/2001	PGR50	AO SMITH	\$ 850.00	
10573	Installed/Active	08/25/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10574	Installed/Active	03/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10575	Installed/Active	07/14/1997	FSG50	AO SMITH	\$ 850.00	
10576	Installed/Active	12/08/1987	FSG50	AO SMITH	\$ 850.00	
10577	Installed/Active	06/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10578	Installed/Active	02/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10579	Installed/Active	06/21/1988	P506	RUUD	\$ 1,125.00	
10580	Installed/Active	12/19/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
10581	Installed/Active	12/24/1999	PHR50	RUUD	\$ 850.00	
10582	Installed/Active	06/07/2003	FSG50	AO SMITH	\$ 850.00	
10583	Installed/Active	11/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
10584	Installed/Active	05/11/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10585	Installed/Active	08/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10586	Installed/Active	01/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
10587	Installed/Active	05/05/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
10588	Installed/Active	01/13/1988	21V502	RHEEM	\$ 850.00	
10589	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10590	Installed/Active	05/30/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
10591	Installed/Active	10/20/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10592	Installed/Active	05/25/1988	FSG50	AO SMITH	\$ 850.00	
10593	Installed/Active	01/13/1988	FSG50	AO SMITH	\$ 850.00	
10594	Installed/Active	08/24/1988	FSG50	AO SMITH	\$ 850.00	
10595	Installed/Active	01/05/2006	PR650	STATE	\$ 1,075.00	
10596	Installed/Active	08/22/2000	FSG50	AO SMITH	\$ 850.00	
10597	Installed/Active	05/23/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.64
10598	Installed/Active	10/10/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10599	Installed/Active	03/17/1988	FSG50	AO SMITH	\$ 850.00	
10600	Installed/Active	10/22/1987	FSG50	AO SMITH	\$ 850.00	
10601	Installed/Active	08/31/2005	GVC50	A. O. SMITH	\$ 850.00	
10602	Installed/Active	11/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
10603	Installed/Active	06/30/2004	GVC40	A. O. SMITH	\$ 850.00	
10604	Installed/Active	06/07/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
10605	Installed/Active	11/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10606	Installed/Active	01/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10607	Installed/Active	05/12/2003	PGR50	AO SMITH	\$ 850.00	
10608	Installed/Active	08/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10609	Installed/Active	01/13/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
10610	Installed/Active	04/01/2003	PGR50	AO SMITH	\$ 850.00	
10611	Installed/Active	05/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10612	Installed/Active	08/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10613	Installed/Active	08/12/1996	21DV50	RHEEM	\$ 1,075.00	
10614	Installed/Active	06/04/2001	PGR50	AO SMITH	\$ 850.00	
10615	Installed/Active	04/13/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
10616	Installed/Active	08/25/2005	PR640	STATE	\$ 1,075.00	
10617	Installed/Active	01/16/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10618	Installed/Active	11/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10619	Installed/Active	01/16/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10620	Installed/Active	03/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10621	Installed/Active	08/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10622	Installed/Active	04/06/2004	PVR50	AO SMITH	\$ 850.00	
10623	Installed/Active	10/28/2004	XVR50	A. O. SMITH	\$ 850.00	
10624	Installed/Active	02/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10625	Installed/Active	03/28/2011	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
10626	Installed/Active	06/06/1991	FSG50	AO SMITH	\$ 850.00	
10627	Installed/Active	04/03/2006	PR650	STATE	\$ 1,075.00	
10628	Installed/Active	02/07/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10629	Installed/Active	04/15/1999	FGR50	AO SMITH	\$ 850.00	
10630	Installed/Active	02/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10631	Installed/Active	07/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10632	Installed/Active	08/28/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
10633	Installed/Active	12/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10634	Installed/Active	07/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10635	Installed/Active	11/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10636	Installed/Active	12/20/2000	FSG40	AO SMITH	\$ 850.00	
10637	Installed/Active	06/23/2006	PR650	STATE	\$ 1,075.00	
10638	Installed/Active	11/23/2003	PVR40	AO SMITH	\$ 850.00	
10639	Installed/Active	01/06/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10640	Installed/Active	05/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10641	Installed/Active	01/18/2000	FSGL40	AO SMITH	\$ 850.00	
10642	Installed/Active	10/23/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
10643	Installed/Active	03/11/1991	PRV50NODS	STATE	\$ 1,075.00	
10644	Installed/Active	02/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10645	Installed/Active	11/20/2003	PRX50	STATE	\$ 1,075.00	
10646	Installed/Active	11/12/2003	FCV50	AO SMITH	\$ 850.00	
10647	Installed/Active	10/03/2005	LTN050	LOCHINVAR	\$ 850.00	
10648	Installed/Active	07/05/2005	LTN040	LOCHINVAR	\$ 850.00	
10649	Installed/Active	08/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10650	Installed/Active	01/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10651	Installed/Active	05/13/2002	PGR50	AO SMITH	\$ 850.00	
10652	Installed/Active	11/11/1991	21V502	RHEEM	\$ 850.00	
10653	Installed/Active	11/10/2006	PR650XODS	STATE	\$ 1,075.00	
10654	Installed/Active	09/14/2012	41VR50	RHEEM	\$ 850.00	\$ 12.75
10655	Installed/Active	01/26/2001	41XR50	RHEEM	\$ 850.00	
10656	Installed/Active	08/01/2000	41XR50	RHEEM	\$ 850.00	
10657	Installed/Active	11/08/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10658	Installed/Active	01/25/2006	PR650	STATE	\$ 1,075.00	
10659	Installed/Active	03/27/2004	PRX50	STATE	\$ 1,075.00	
10660	Installed/Active	11/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10661	Installed/Active	08/20/1990	P506	RUUD	\$ 1,150.00	
10662	Installed/Active	03/21/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
10663	Installed/Active	11/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10664	Installed/Active	03/21/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10665	Installed/Active	01/08/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10666	Installed/Active	02/14/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
10667	Installed/Active	03/01/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
10668	Installed/Active	09/26/2001	PGR50	AO SMITH	\$ 850.00	
10669	Installed/Active	06/25/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10670	Installed/Active	01/17/1990	FSG50	AO SMITH	\$ 850.00	
10671	Installed/Active	05/07/1990	FSG50	AO SMITH	\$ 850.00	
10672	Installed/Active	05/22/1990	PH30	RUUD	\$ 350.00	
10673	Installed/Active	12/01/1999	21V506	RHEEM	\$ 1,150.00	
10674	Installed/Active	01/23/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10675	Installed/Active	03/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10676	Installed/Active	12/12/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10677	Installed/Active	12/14/2000	41XR50	RHEEM	\$ 850.00	
10678	Installed/Active	10/19/2005	LTN050	LOCHINVAR	\$ 850.00	
10679	Installed/Active	02/18/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10680	Installed/Active	09/08/2005	LTN050	LOCHINVAR	\$ 850.00	
10681	Installed/Active	01/08/1991	P506	RUUD	\$ 1,150.00	
10682	Installed/Active	11/30/1990	FSG50	AO SMITH	\$ 850.00	
10683	Installed/Active	04/19/2004	FCV50	AO SMITH	\$ 850.00	
10684	Installed/Active	11/05/2012	M2XR504T6FBN	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
10685	Installed/Active	09/27/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
10686	Installed/Active	06/21/2006	PR650	STATE	\$ 1,075.00	
10687	Installed/Active	09/22/1990	FSG50	AO SMITH	\$ 850.00	
10688	Installed/Active	12/10/1999	FSG50	AO SMITH	\$ 850.00	
10689	Installed/Active	08/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10690	Installed/Active	06/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10691	Installed/Active	07/06/2010	LTN051G	LOCHINVAR	\$ 850.00	\$ 16.55
10692	Installed/Active	05/15/2001	FSG50	AO SMITH	\$ 850.00	
10693	Installed/Active	03/16/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10694	Installed/Active	11/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10695	Installed/Active	10/11/1997	PGR50	AO SMITH	\$ 850.00	
10696	Installed/Active	11/03/1990	P506	RUUD	\$ 1,125.00	
10697	Installed/Active	02/05/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10698	Installed/Active	08/15/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10699	Installed/Active	08/22/1989	P506	RUUD	\$ 1,125.00	
10700	Installed/Active	02/13/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10701	Installed/Active	07/27/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
10702	Installed/Active	05/14/2005	LTN040	LOCHINVAR	\$ 850.00	
10703	Installed/Active	02/20/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
10704	Installed/Active	07/28/2000	PHR50	RUUD	\$ 850.00	
10705	Installed/Active	01/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10706	Installed/Active	04/21/1994	FGR50	AO SMITH	\$ 850.00	
10707	Installed/Active	11/21/2001	FSG40	AO SMITH	\$ 850.00	
10708	Installed/Active	01/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10709	Installed/Active	02/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10710	Installed/Active	10/17/1989	FSG40	AO SMITH	\$ 850.00	
10711	Installed/Active	03/05/1997	FGR50	AO SMITH	\$ 850.00	
10712	Installed/Active	01/11/1989	FSG50	AO SMITH	\$ 850.00	
10713	Installed/Active	06/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10714	Installed/Active	07/07/2005	21V506	RHEEM	\$ 1,150.00	
10715	Installed/Active	11/04/1997	PGR50	AO SMITH	\$ 850.00	
10716	Installed/Active	12/14/1988	FSG50	AO SMITH	\$ 850.00	
10717	Installed/Active	01/06/2001	PRX50	STATE	\$ 1,075.00	
10718	Installed/Active	07/19/2012	21DV50	RHEEM	\$ 1,075.00	\$ 17.89
10719	Installed/Active	03/13/2001	PRX50	STATE	\$ 1,075.00	
10720	Installed/Active	01/10/1989	FSG50	AO SMITH	\$ 850.00	
10721	Installed/Active	11/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10722	Installed/Active	06/02/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
10723	Installed/Active	05/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10724	Installed/Active	03/23/2002	FSG50	AO SMITH	\$ 850.00	
10725	Installed/Active	02/19/2003	41XR50	RHEEM	\$ 850.00	
10726	Installed/Active	04/13/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10727	Installed/Active	07/27/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10728	Installed/Active	03/12/2003	FSG50	AO SMITH	\$ 850.00	
10729	Installed/Active	02/06/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10730	Installed/Active	04/08/1995	FGR40	AO SMITH	\$ 850.00	
10731	Installed/Active	11/23/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
10732	Installed/Active	06/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10733	Installed/Active	02/05/2003	FSG50	AO SMITH	\$ 850.00	
10734	Installed/Active	11/22/2000	PRV50NODS	STATE	\$ 1,075.00	
10735	Installed/Active	04/17/2006	LTN051G	LOCHINVAR	\$ 850.00	
10736	Installed/Active	03/03/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
10737	Installed/Active	11/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
10738	Installed/Active	11/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10739	Installed/Active	01/21/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10740	Installed/Active	04/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
10741	Installed/Active	02/11/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
10742	Installed/Active	08/30/2005	GVC50	A. O. SMITH	\$ 850.00	
10743	Installed/Active	10/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10744	Installed/Active	01/19/2001	PGR50	AO SMITH	\$ 850.00	
10745	Installed/Active	09/01/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10746	Installed/Active	07/19/2000	41XR50	RHEEM	\$ 850.00	
10747	Installed/Active	07/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
10748	Installed/Active	10/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10749	Installed/Active	03/30/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10750	Installed/Active	01/16/1999	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10751	Installed/Active	01/31/2002	FSG50	AO SMITH	\$ 850.00	
10752	Installed/Active	08/24/1999	FSG50	AO SMITH	\$ 850.00	
10753	Installed/Active	01/05/2001	PGR50	AO SMITH	\$ 850.00	
10754	Installed/Active	03/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10755	Installed/Active	02/22/1988	PRX50	STATE	\$ 1,075.00	
10756	Installed/Active	07/22/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10757	Installed/Active	01/18/1988	FSG50	AO SMITH	\$ 850.00	
10758	Installed/Active	12/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10759	Installed/Active	07/19/2005	PR650	STATE	\$ 1,075.00	
10760	Installed/Active	04/26/2003	PRX50	STATE	\$ 1,075.00	
10761	Installed/Active	05/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10762	Installed/Active	07/26/2002	PRX50	STATE	\$ 1,075.00	
10763	Installed/Active	02/08/1988	FSG50	AO SMITH	\$ 850.00	
10764	Installed/Active	08/11/2003	PGR50	AO SMITH	\$ 850.00	
10765	Installed/Active	03/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10766	Installed/Active	01/13/1988	FSG50	AO SMITH	\$ 850.00	
10767	Installed/Active	06/12/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10768	Installed/Active	07/19/1988	FSG40	AO SMITH	\$ 850.00	
10769	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
10770	Installed/Active	05/03/2012	PRX50	STATE	\$ 1,075.00	\$ 17.74
10771	Installed/Active	03/30/1992	BW50	BRADFORD-WHITE	\$ 850.00	
10772	Installed/Active	03/26/2011	41VR40	RHEEM	\$ 850.00	\$ 12.05
10773	Installed/Active	10/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10774	Installed/Active	03/20/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
10775	Installed/Active	05/22/1992	FSG50	AO SMITH	\$ 850.00	
10776	Installed/Active	04/15/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10777	Installed/Active	03/09/2004	XVR50	A. O. SMITH	\$ 850.00	
10778	Installed/Active	05/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10779	Installed/Active	10/28/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
10780	Installed/Active	04/21/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
10781	Installed/Active	12/16/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
10782	Installed/Active	05/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10783	Installed/Active	04/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10784	Installed/Active	02/12/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10785	Installed/Active	06/03/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.64
10786	Installed/Active	02/01/2008	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
10787	Installed/Active	10/25/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10788	Installed/Active	10/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
10789	Installed/Active	12/20/1989	FSG50	AO SMITH	\$ 850.00	
10790	Installed/Active	08/14/2003	FSG50	AO SMITH	\$ 850.00	
10791	Installed/Active	01/08/2005	PRX50	STATE	\$ 1,075.00	
10792	Installed/Active	02/11/2002	PGR50	AO SMITH	\$ 850.00	
10793	Installed/Active	04/18/2003	FSG50	AO SMITH	\$ 850.00	
10794	Installed/Active	04/14/2006	FSG50	AO SMITH	\$ 850.00	
10795	Installed/Active	10/09/1995	FSG40	AO SMITH	\$ 850.00	
10796	Installed/Active	05/28/2003	FSG50	AO SMITH	\$ 850.00	
10797	Installed/Active	01/02/1991	FSG50	AO SMITH	\$ 850.00	
10798	Installed/Active	07/19/2000	PRX50	STATE	\$ 1,075.00	
10799	Installed/Active	12/31/2005	PR650	STATE	\$ 1,075.00	
10800	Installed/Active	12/13/2004	PRX50	STATE	\$ 1,075.00	
10801	Installed/Active	11/29/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
10802	Installed/Active	09/26/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
10803	Installed/Active	08/05/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
10804	Installed/Active	02/27/2002	PGR50	AO SMITH	\$ 850.00	
10805	Installed/Active	02/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10806	Installed/Active	01/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
10807	Installed/Active	11/06/2003	21V506	RHEEM	\$ 1,150.00	
10808	Installed/Active	04/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10809	Installed/Active	04/29/2004	PRX50	STATE	\$ 1,075.00	
10810	Installed/Active	10/31/1998	FGR40	AO SMITH	\$ 850.00	
10811	Installed/Active	07/15/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
10812	Installed/Active	02/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10813	Installed/Active	07/31/2004	PRX50	STATE	\$ 1,075.00	
10814	Installed/Active	01/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10815	Installed/Active	05/11/1990	PRV50NODS	STATE	\$ 1,075.00	
10816	Installed/Active	09/27/1998	FSG50	AO SMITH	\$ 850.00	
10817	Installed/Active	07/08/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
10818	Installed/Active	05/07/2001	PGR50	AO SMITH	\$ 850.00	
10819	Installed/Active	02/19/1991	FSG50	AO SMITH	\$ 850.00	
10820	Installed/Active	07/02/1990	PRV50NODS	STATE	\$ 1,075.00	
10821	Installed/Active	12/23/2000	FSG50	AO SMITH	\$ 850.00	
10822	Installed/Active	04/03/2003	PGR50	AO SMITH	\$ 850.00	
10823	Installed/Active	05/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10824	Installed/Active	09/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10825	Installed/Active	06/16/2006	LSN041G	LOCHINVAR	\$ 850.00	
10826	Installed/Active	04/13/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10827	Installed/Active	12/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
10828	Installed/Active	02/20/2004	FCV50	AO SMITH	\$ 850.00	
10829	Installed/Active	01/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10830	Installed/Active	04/02/2003	FSG50	AO SMITH	\$ 850.00	
10831	Installed/Active	05/16/2005	42VR506	RHEEM	\$ 1,150.00	
10832	Installed/Active	04/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10833	Installed/Active	07/06/2001	PRX50	STATE	\$ 1,075.00	
10834	Installed/Active	03/04/2002	FSG50	AO SMITH	\$ 850.00	
10835	Installed/Active	01/14/1998	FGR40	AO SMITH	\$ 850.00	
10836	Installed/Active	03/26/1991	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10837	Installed/Active	01/09/2007	LTN050G	LOCHINVAR	\$ 850.00	
10838	Installed/Active	10/22/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
10839	Installed/Active	02/10/2011	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
10840	Installed/Active	10/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10841	Installed/Active	05/18/2004	XTN050	LOCHINVAR	\$ 850.00	
10842	Installed/Active	12/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
10843	Installed/Active	06/04/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
10844	Installed/Active	09/04/1991	21V502	RHEEM	\$ 850.00	
10845	Installed/Active	01/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.37
10846	Installed/Active	06/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
10847	Installed/Active	03/04/2003	21DV50	RHEEM	\$ 1,075.00	
10848	Installed/Active	02/21/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
10849	Installed/Active	07/14/2005	PR650	STATE	\$ 1,075.00	
10850	Installed/Active	06/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10851	Installed/Active	05/15/2009	P506	RUUD	\$ 1,125.00	\$ 18.76
10852	Installed/Active	03/22/1991	B71DUMMY	AMERICAN	\$ 850.00	
10853	Installed/Active	06/13/1991	P506	RUUD	\$ 1,150.00	
10854	Installed/Active	01/28/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10855	Installed/Active	12/03/1999	41XR50	RHEEM	\$ 850.00	
10856	Installed/Active	04/28/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
10857	Installed/Active	12/07/2003	FCV50	AO SMITH	\$ 850.00	
10858	Installed/Active	02/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10859	Installed/Active	03/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10860	Installed/Active	01/03/1991	FSG50	AO SMITH	\$ 850.00	
10861	Installed/Active	09/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10862	Installed/Active	09/18/2002	21V506	RHEEM	\$ 1,150.00	
10863	Installed/Active	09/20/1991	FSG50	AO SMITH	\$ 850.00	
10864	Installed/Active	03/26/2001	PGR50	AO SMITH	\$ 850.00	
10865	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10866	Installed/Active	09/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10867	Installed/Active	04/18/2001	PR650	STATE	\$ 1,075.00	
10868	Installed/Active	03/08/1999	FGR50	AO SMITH	\$ 850.00	
10869	Installed/Active	12/22/2004	PRX50	STATE	\$ 1,075.00	
10870	Installed/Active	11/27/1989	FSG50	AO SMITH	\$ 850.00	
10871	Installed/Active	01/31/2009	41V40	RHEEM	\$ 850.00	\$ 11.74
10872	Installed/Active	08/02/2004	PRX50	STATE	\$ 1,075.00	
10873	Installed/Active	07/12/2000	21V402S	RHEEM	\$ 850.00	
10874	Installed/Active	11/27/1989	FSG50	AO SMITH	\$ 850.00	
10875	Installed/Active	03/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10876	Installed/Active	05/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
10877	Installed/Active	02/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10878	Installed/Active	04/14/1989	FSG50	AO SMITH	\$ 850.00	
10879	Installed/Active	09/03/2003	H72DUMMY	AO SMITH	\$ 1,900.00	
10880	Installed/Active	09/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10881	Installed/Active	07/26/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
10882	Installed/Active	05/10/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
10883	Installed/Active	10/22/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10884	Installed/Active	09/28/1989	FSG50	AO SMITH	\$ 850.00	
10885	Installed/Active	03/23/2005	GVC50	A. O. SMITH	\$ 850.00	
10886	Installed/Active	06/25/2001	PGR50	AO SMITH	\$ 850.00	
10887	Installed/Active	09/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
10888	Installed/Active	12/10/2004	PRX50	STATE	\$ 1,075.00	
10889	Installed/Active	04/21/1989	PRV50NODS	STATE	\$ 1,075.00	
10890	Installed/Active	06/23/2008	PGR50	AO SMITH	\$ 850.00	\$ 10.23
10891	Installed/Active	06/02/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.64
10892	Installed/Active	11/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10893	Installed/Active	05/06/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
10894	Installed/Active	01/07/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
10895	Installed/Active	02/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10896	Installed/Active	06/28/1989	FSG50	AO SMITH	\$ 850.00	
10897	Installed/Active	12/07/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
10898	Installed/Active	12/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10899	Installed/Active	02/04/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
10900	Installed/Active	01/23/2001	FSG50	AO SMITH	\$ 850.00	
10901	Installed/Active	10/12/1989	B71DUMMY	AMERICAN	\$ 850.00	
10902	Installed/Active	02/04/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
10903	Installed/Active	10/03/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10904	Installed/Active	03/23/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.05
10905	Installed/Active	05/03/2005	PRX50	STATE	\$ 1,075.00	
10906	Installed/Active	08/25/2003	FCV40	AO SMITH	\$ 850.00	
10907	Installed/Active	06/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
10908	Installed/Active	06/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
10909	Installed/Active	08/11/1989	FSG50	AO SMITH	\$ 850.00	
10910	Installed/Active	09/17/2003	41XR50	RHEEM	\$ 850.00	
10911	Installed/Active	05/13/1999	FSG40	AO SMITH	\$ 850.00	
10912	Installed/Active	06/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10913	Installed/Active	11/28/2000	FSG50	AO SMITH	\$ 850.00	
10914	Installed/Active	01/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
10915	Installed/Active	06/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10916	Installed/Active	05/10/2001	PGR50	AO SMITH	\$ 850.00	
10917	Installed/Active	09/08/2001	FSG50	AO SMITH	\$ 1,125.00	
10918	Installed/Active	05/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10919	Installed/Active	06/27/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
10920	Installed/Active	09/02/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
10921	Installed/Active	05/11/2004	PRX50	STATE	\$ 1,075.00	
10922	Installed/Active	04/12/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
10923	Installed/Active	03/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10924	Installed/Active	01/17/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10925	Installed/Active	06/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10926	Installed/Active	07/29/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
10927	Installed/Active	05/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10928	Installed/Active	05/17/2004	GVC50	A. O. SMITH	\$ 850.00	
10929	Installed/Active	08/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
10930	Installed/Active	06/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10931	Installed/Active	05/22/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
10932	Installed/Active	11/13/1999	41XR50	RHEEM	\$ 850.00	
10933	Installed/Active	05/19/2003	PGR50	AO SMITH	\$ 850.00	
10934	Installed/Active	04/02/2006	21DV50	RHEEM	\$ 1,075.00	
10935	Installed/Active	10/09/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10936	Installed/Active	06/29/2005	PR650	STATE	\$ 1,075.00	
10937	Installed/Active	04/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10938	Installed/Active	06/01/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
10939	Installed/Active	12/22/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
10940	Installed/Active	05/23/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10941	Installed/Active	04/19/2005	GVC50	A. O. SMITH	\$ 850.00	
10942	Installed/Active	06/01/2001	PGR50	AO SMITH	\$ 850.00	
10943	Installed/Active	12/01/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
10944	Installed/Active	12/18/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10945	Installed/Active	10/12/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10946	Installed/Active	07/23/2003	PGR50	AO SMITH	\$ 850.00	
10947	Installed/Active	04/03/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10948	Installed/Active	11/20/2001	PGR50	AO SMITH	\$ 850.00	
10949	Installed/Active	09/13/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10950	Installed/Active	02/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10951	Installed/Active	10/04/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
10952	Installed/Active	06/15/1998	FSG50	AO SMITH	\$ 850.00	
10953	Installed/Active	11/08/2010	FGR50	AO SMITH	\$ 850.00	\$ 12.05
10954	Installed/Active	10/18/2004	GVC50	A. O. SMITH	\$ 850.00	
10955	Installed/Active	03/07/2002	FSG50	AO SMITH	\$ 850.00	
10956	Installed/Active	09/07/1990	FSG50	AO SMITH	\$ 850.00	
10957	Installed/Active	01/24/2009	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.12
10958	Installed/Active	03/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
10959	Installed/Active	04/27/2004	21V506	RHEEM	\$ 1,150.00	
10960	Installed/Active	10/13/2005	LTN050	LOCHINVAR	\$ 850.00	
10961	Installed/Active	04/12/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
10962	Installed/Active	09/06/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
10963	Installed/Active	12/29/2000	FSG50	AO SMITH	\$ 850.00	
10964	Installed/Active	09/14/2004	21DV50	RHEEM	\$ 1,075.00	
10965	Installed/Active	07/23/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
10966	Installed/Active	05/04/1990	FSG50	AO SMITH	\$ 850.00	
10967	Installed/Active	06/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
10968	Installed/Active	03/07/1996	PGR50	AO SMITH	\$ 850.00	
10969	Installed/Active	07/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
10970	Installed/Active	11/16/1990	21V506	RHEEM	\$ 1,150.00	
10971	Installed/Active	03/08/2000	FSG50	AO SMITH	\$ 850.00	
10972	Installed/Active	09/22/1989	FSG50	AO SMITH	\$ 850.00	
10973	Installed/Active	01/27/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
10974	Installed/Active	07/27/2001	PGR50	AO SMITH	\$ 850.00	
10975	Installed/Active	04/22/2005	PR650	STATE	\$ 1,075.00	
10976	Installed/Active	07/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
10977	Installed/Active	01/12/1990	FSG40	AO SMITH	\$ 850.00	
10978	Installed/Active	01/31/2004	PRX50	STATE	\$ 1,075.00	
10979	Installed/Active	09/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
10980	Installed/Active	11/08/1990	FSG50	AO SMITH	\$ 850.00	
10981	Installed/Active	12/13/2001	PRX50	STATE	\$ 1,075.00	
10982	Installed/Active	03/13/2006	PR650X0DS	STATE	\$ 1,075.00	
10983	Installed/Active	08/17/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
10984	Installed/Active	03/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
10985	Installed/Active	08/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
10986	Installed/Active	07/16/2006	PR650	STATE	\$ 1,075.00	
10987	Installed/Active	10/19/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
10988	Installed/Active	08/16/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
10989	Installed/Active	06/02/2006	CPN13585FS	LOCHINVAR	\$ 3,350.00	
10990	Installed/Active	05/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
10991	Installed/Active	03/14/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
10992	Installed/Active	11/16/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
10993	Installed/Active	04/03/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
10994	Installed/Active	01/11/2003	PGR50	AO SMITH	\$ 850.00	
10995	Installed/Active	06/03/2005	LTN040	LOCHINVAR	\$ 850.00	
10996	Installed/Active	07/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10997	Installed/Active	06/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
10998	Installed/Active	05/04/1989	21V502	RHEEM	\$ 850.00	
10999	Installed/Active	12/26/2001	PGR50	AO SMITH	\$ 850.00	
11000	Installed/Active	11/01/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11001	Installed/Active	02/08/1989	FSG50	AO SMITH	\$ 850.00	
11002	Installed/Active	06/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11003	Installed/Active	07/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11004	Installed/Active	11/16/2004	GVC50	A. O. SMITH	\$ 850.00	
11005	Installed/Active	02/10/1999	21V506	RHEEM	\$ 1,150.00	
11006	Installed/Active	06/30/1989	FSG40	AO SMITH	\$ 850.00	
11007	Installed/Active	09/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11008	Installed/Active	08/31/2005	GVC50	A. O. SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11009	Installed/Active	12/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11010	Installed/Active	10/18/2004	GVC50	A. O. SMITH	\$ 850.00	
11011	Installed/Active	05/10/2005	XSN0401GEF	LOCHINVAR	\$ 850.00	
11012	Installed/Active	05/10/2005	XSN0401GEF	LOCHINVAR	\$ 850.00	
11013	Installed/Active	03/23/1998	FGR50	AO SMITH	\$ 850.00	
11014	Installed/Active	11/11/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
11015	Installed/Active	01/07/2002	FSG40	AO SMITH	\$ 850.00	
11016	Installed/Active	09/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11017	Installed/Active	09/14/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
11018	Installed/Active	04/03/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11019	Installed/Active	12/01/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11020	Installed/Active	02/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11021	Installed/Active	08/24/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11022	Installed/Active	11/24/2004	GVC50	A. O. SMITH	\$ 850.00	
11023	Installed/Active	10/28/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11024	Installed/Active	08/20/2001	FSG50	AO SMITH	\$ 850.00	
11025	Installed/Active	09/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11026	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11027	Installed/Active	06/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11028	Installed/Active	02/24/2004	B71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	
11029	Installed/Active	03/10/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11030	Installed/Active	12/22/2002	21DV50	RHEEM	\$ 1,075.00	
11031	Installed/Active	06/22/2002	PRX50	STATE	\$ 1,075.00	
11032	Installed/Active	10/07/2004	PRX50	STATE	\$ 1,075.00	
11033	Installed/Active	08/30/2006	LTN050G	LOCHINVAR	\$ 350.00	
11034	Installed/Active	12/01/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11035	Installed/Active	08/21/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
11036	Installed/Active	12/31/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
11037	Installed/Active	02/03/2006	F72DUMMY	AO SMITH	\$ 3,350.00	
11038	Installed/Active	06/26/2007	EPN150085	LOCHINVAR	\$ 3,350.00	\$ 44.60
11039	Installed/Active	05/05/1997	FSG50	AO SMITH	\$ 850.00	
11040	Installed/Active	05/22/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11041	Installed/Active	09/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11042	Installed/Active	06/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11043	Installed/Active	08/25/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11044	Installed/Active	06/09/2000	41XR50	RHEEM	\$ 850.00	
11045	Installed/Active	09/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11046	Installed/Active	10/15/1991	PRV50NODS	STATE	\$ 1,075.00	
11047	Installed/Active	12/02/2010	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
11048	Installed/Active	12/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11049	Installed/Active	08/25/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11050	Installed/Active	03/16/2006	21V506	RHEEM	\$ 1,150.00	
11051	Installed/Active	01/04/2003	PRX50	STATE	\$ 1,075.00	
11052	Installed/Active	12/01/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11053	Installed/Active	02/15/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
11054	Installed/Active	07/03/2000	41VR40	RHEEM	\$ 850.00	
11055	Installed/Active	03/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11056	Installed/Active	06/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11057	Installed/Active	03/21/2002	FSG50	AO SMITH	\$ 850.00	
11058	Installed/Active	07/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11059	Installed/Active	03/29/1991	B71DUMMY	AMERICAN	\$ 850.00	
11060	Installed/Active	03/05/1999	PR650	STATE	\$ 1,075.00	
11061	Installed/Active	03/12/2002	FSG50	AO SMITH	\$ 850.00	
11062	Installed/Active	06/16/2008	22DV5038	RHEEM	\$ 1,075.00	\$ 14.35
11063	Installed/Active	02/12/1992	21V502	RHEEM	\$ 850.00	
11064	Installed/Active	03/31/2000	FSG50	AO SMITH	\$ 850.00	
11065	Installed/Active	03/06/2002	FSG50	AO SMITH	\$ 850.00	
11066	Installed/Active	08/16/2011	FGC40	AO SMITH	\$ 850.00	\$ 12.64
11067	Installed/Active	09/11/1991	FSG50	AO SMITH	\$ 850.00	
11068	Installed/Active	01/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11069	Installed/Active	09/29/2003	FSG50	AO SMITH	\$ 850.00	
11070	Installed/Active	11/26/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11071	Installed/Active	06/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11072	Installed/Active	08/08/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11073	Installed/Active	02/26/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
11074	Installed/Active	10/26/2004	GVC50	A. O. SMITH	\$ 850.00	
11075	Installed/Active	10/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11076	Installed/Active	12/14/1989	FSG50	AO SMITH	\$ 850.00	
11077	Installed/Active	06/26/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11078	Installed/Active	06/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11079	Installed/Active	01/29/2001	FGR50	AO SMITH	\$ 850.00	
11080	Installed/Active	05/19/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11081	Installed/Active	01/30/2002	FSG50	AO SMITH	\$ 850.00	
11082	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.12
11083	Installed/Active	10/13/2000	FSG50	AO SMITH	\$ 850.00	
11084	Installed/Active	02/05/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
11085	Installed/Active	02/16/2005	GDVS50	AOSMITH	\$ 1,075.00	
11086	Installed/Active	02/07/1990	PRV50NODS	STATE	\$ 1,075.00	
11087	Installed/Active	06/23/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11088	Installed/Active	09/10/2001	FSG40	AO SMITH	\$ 850.00	
11089	Installed/Active	05/17/2001	PGR50	AO SMITH	\$ 850.00	
11090	Installed/Active	02/18/2003	PRX50	STATE	\$ 1,075.00	
11091	Installed/Active	02/26/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
11092	Installed/Active	12/06/2004	GVC50	A. O. SMITH	\$ 1,150.00	
11093	Installed/Active	01/26/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
11094	Installed/Active	11/07/1991	P502	RUUD	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11095	Installed/Active	12/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
11096	Installed/Active	10/06/2004	LTN050	LOCHINVAR	\$ 850.00	
11097	Installed/Active	03/01/2001	41V50	RHEEM	\$ 850.00	
11098	Installed/Active	12/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11099	Installed/Active	09/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11100	Installed/Active	03/24/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
11101	Installed/Active	01/29/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11102	Installed/Active	12/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11103	Installed/Active	10/26/1996	FGR50	AO SMITH	\$ 850.00	
11104	Installed/Active	07/03/1990	RF92200	RUUD	\$ 3,350.00	
11105	Installed/Active	07/15/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11106	Installed/Active	05/06/2004	GVC50	A. O. SMITH	\$ 850.00	
11107	Installed/Active	07/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11108	Installed/Active	02/07/2000	BTR154	AO SMITH	\$ 3,350.00	
11109	Installed/Active	01/30/2004	41VR50	RHEEM	\$ 850.00	
11110	Installed/Active	03/12/1997	21V407	RHEEM	\$ 350.00	
11111	Installed/Active	02/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11112	Installed/Active	02/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11113	Installed/Active	06/24/2002	FSG50	AO SMITH	\$ 850.00	
11114	Installed/Active	05/24/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
11115	Installed/Active	12/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11116	Installed/Active	06/12/2003	41VR40	RHEEM	\$ 850.00	
11117	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11118	Installed/Active	02/23/2001	PGR50	AO SMITH	\$ 850.00	
11119	Installed/Active	03/04/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
11120	Installed/Active	04/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
11121	Installed/Active	05/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11122	Installed/Active	09/05/2003	PRX50	STATE	\$ 1,075.00	
11123	Installed/Active	10/16/1998	FSG50	AO SMITH	\$ 850.00	
11124	Installed/Active	11/07/2001	41V50	RHEEM	\$ 850.00	
11125	Installed/Active	12/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11126	Installed/Active	12/19/2003	41V50S	RHEEM	\$ 850.00	
11127	Installed/Active	01/28/2003	PGR50	AO SMITH	\$ 850.00	
11128	Installed/Active	01/24/1991	BTR199	AO SMITH	\$ 3,350.00	
11129	Installed/Active	11/12/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
11130	Installed/Active	01/22/2003	FSG50	AO SMITH	\$ 850.00	
11131	Installed/Active	09/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11132	Installed/Active	02/26/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11133	Installed/Active	08/31/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
11134	Installed/Active	02/20/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 11.74
11135	Installed/Active	10/30/2007	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
11136	Installed/Active	03/17/1999	41VR50	RHEEM	\$ 850.00	
11137	Installed/Active	01/25/2011	FSG40	AO SMITH	\$ 350.00	\$ 14.74
11138	Installed/Active	03/16/1990	FSG50	AO SMITH	\$ 850.00	
11139	Installed/Active	02/26/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
11140	Installed/Active	01/16/1990	PRX50	STATE	\$ 1,075.00	
11141	Installed/Active	11/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11142	Installed/Active	02/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11143	Installed/Active	07/25/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11144	Installed/Active	12/07/2004	XVR50	A. O. SMITH	\$ 850.00	
11145	Installed/Active	05/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
11146	Installed/Active	07/17/1990	FSG50	AO SMITH	\$ 850.00	
11147	Installed/Active	02/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11148	Installed/Active	09/05/1990	PRX50	STATE	\$ 1,075.00	
11149	Installed/Active	02/06/2003	H72DUMMY	AO SMITH	\$ 1,900.00	
11150	Installed/Active	08/08/2005	PR650	STATE	\$ 1,075.00	
11151	Installed/Active	04/18/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
11152	Installed/Active	12/04/1989	21V506	RHEEM	\$ 1,150.00	
11153	Installed/Active	06/11/1990	FSG50	AO SMITH	\$ 850.00	
11154	Installed/Active	03/06/1992	P506	RUUD	\$ 1,125.00	
11155	Installed/Active	08/23/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11156	Installed/Active	01/08/2005	GVC50	A. O. SMITH	\$ 850.00	
11157	Installed/Active	08/23/2004	41V50S	RHEEM	\$ 850.00	
11158	Installed/Active	09/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11159	Installed/Active	12/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
11160	Installed/Active	12/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11161	Installed/Active	11/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11162	Installed/Active	05/26/2004	GVC50	A. O. SMITH	\$ 850.00	
11163	Installed/Active	09/10/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11164	Installed/Active	08/28/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
11165	Installed/Active	05/12/1989	FSG50	AO SMITH	\$ 850.00	
11166	Installed/Active	07/02/1989	FSG40	AO SMITH	\$ 850.00	
11167	Installed/Active	07/18/2001	FSG50	AO SMITH	\$ 850.00	
11168	Installed/Active	08/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11169	Installed/Active	03/02/2012	PH250SF	RUUD	\$ 850.00	\$ 12.64
11170	Installed/Active	08/04/2004	XVR50	A. O. SMITH	\$ 850.00	
11171	Installed/Active	10/04/2005	LTN040G	LOCHINVAR	\$ 850.00	
11172	Installed/Active	12/27/1997	PGR50	AO SMITH	\$ 850.00	
11173	Installed/Active	10/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11174	Installed/Active	04/16/2006	LSN041	LOCHINVAR	\$ 850.00	
11175	Installed/Active	07/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11176	Installed/Active	06/17/1994	FGR50	AO SMITH	\$ 850.00	
11177	Installed/Active	11/14/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11178	Installed/Active	12/06/1996	H72DUMMY	AO SMITH	\$ 1,900.00	
11179	Installed/Active	12/06/2003	21V506	RHEEM	\$ 1,150.00	
11180	Installed/Active	08/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11181	Installed/Active	12/28/1989	PRV50NODS	STATE	\$ 1,075.00	
11182	Installed/Active	12/28/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11183	Installed/Active	02/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11184	Installed/Active	04/11/1989	FSG50	AO SMITH	\$ 850.00	
11185	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
11186	Installed/Active	01/12/2002	41XR50	RHEEM	\$ 850.00	
11187	Installed/Active	07/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11188	Installed/Active	01/24/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11189	Installed/Active	07/08/1997	PGR50	AO SMITH	\$ 850.00	
11190	Installed/Active	01/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11191	Installed/Active	12/29/1998	21VR50	RHEEM	\$ 850.00	
11192	Installed/Active	08/15/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11193	Installed/Active	03/24/2001	PRX50	STATE	\$ 1,075.00	
11194	Installed/Active	04/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11195	Installed/Active	11/30/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
11196	Installed/Active	09/19/2005	LTN050G	LOCHINVAR	\$ 850.00	
11197	Installed/Active	04/09/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
11198	Installed/Active	05/29/2002	PGR50	AO SMITH	\$ 850.00	
11199	Installed/Active	01/27/2004	FCV50	AO SMITH	\$ 850.00	
11200	Installed/Active	08/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11201	Installed/Active	09/14/2010	42V5065F	RHEEM	\$ 850.00	\$ 12.05
11202	Installed/Active	02/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11203	Installed/Active	12/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11204	Installed/Active	07/10/2012	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
11205	Installed/Active	05/06/1999	PRV50NODS	STATE	\$ 1,075.00	
11206	Installed/Active	03/02/2003	PGR50	AO SMITH	\$ 850.00	
11207	Installed/Active	05/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11208	Installed/Active	03/16/1999	41VR50	RHEEM	\$ 850.00	
11209	Installed/Active	05/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11210	Installed/Active	08/01/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
11211	Installed/Active	05/20/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
11212	Installed/Active	08/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11213	Installed/Active	03/09/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11214	Installed/Active	03/21/1994	PRX50	STATE	\$ 1,075.00	
11215	Installed/Active	06/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11216	Installed/Active	08/09/1989	FSG50	AO SMITH	\$ 850.00	
11217	Installed/Active	03/05/2000	FSSL40	AO SMITH	\$ 850.00	
11218	Installed/Active	01/04/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11219	Installed/Active	02/09/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11220	Installed/Active	07/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11221	Installed/Active	05/23/2002	21DV50	RHEEM	\$ 1,075.00	
11222	Installed/Active	03/25/2010	PRX50	STATE	\$ 1,075.00	\$ 16.47
11223	Installed/Active	03/13/2006	LSN041G	LOCHINVAR	\$ 850.00	
11224	Installed/Active	11/20/1999	FSSL40	AO SMITH	\$ 850.00	
11225	Installed/Active	07/26/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
11226	Installed/Active	12/19/1991	P506	RUUD	\$ 1,150.00	
11227	Installed/Active	02/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11228	Installed/Active	06/10/1999	FGR50	AO SMITH	\$ 850.00	
11229	Installed/Active	06/18/1991	FSG50	AO SMITH	\$ 850.00	
11230	Installed/Active	07/12/2005	LTN050	LOCHINVAR	\$ 850.00	
11231	Installed/Active	09/15/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
11232	Installed/Active	10/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11233	Installed/Active	12/14/2005	PR640	STATE	\$ 1,075.00	
11234	Installed/Active	10/31/1991	P506	RUUD	\$ 1,150.00	
11235	Installed/Active	04/02/2004	PR650	STATE	\$ 1,075.00	
11236	Installed/Active	03/14/2001	FSG40	AO SMITH	\$ 850.00	
11237	Installed/Active	02/11/1991	P506	RUUD	\$ 1,150.00	
11238	Installed/Active	10/23/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
11239	Installed/Active	02/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11240	Installed/Active	11/25/1991	21V502	RHEEM	\$ 850.00	
11241	Installed/Active	09/07/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11242	Installed/Active	12/09/2008	41V50S	RHEEM	\$ 850.00	\$ 11.74
11243	Installed/Active	07/25/2002	PGR50	AO SMITH	\$ 850.00	
11244	Installed/Active	11/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11245	Installed/Active	12/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11246	Installed/Active	02/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11247	Installed/Active	05/26/2003	FSG50	AO SMITH	\$ 850.00	
11248	Installed/Active	10/06/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11249	Installed/Active	04/21/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11250	Installed/Active	02/19/2011	22V40SF	RHEEM	\$ 850.00	\$ 12.05
11251	Installed/Active	11/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
11252	Installed/Active	04/10/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11253	Installed/Active	06/27/1991	21V502	RHEEM	\$ 850.00	
11254	Installed/Active	10/04/1991	FSG50	AO SMITH	\$ 850.00	
11255	Installed/Active	10/22/2003	41V50	RHEEM	\$ 850.00	
11256	Installed/Active	09/13/2000	PRV50NODS	STATE	\$ 1,075.00	
11257	Installed/Active	01/24/1992	PRV50NODS	STATE	\$ 1,075.00	
11258	Installed/Active	02/29/2012	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
11259	Installed/Active	09/05/2001	FSG40	AO SMITH	\$ 850.00	
11260	Installed/Active	03/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
11261	Installed/Active	07/18/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11262	Installed/Active	06/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11263	Installed/Active	05/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11264	Installed/Active	08/17/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
11265	Installed/Active	10/09/2001	FSG50	AO SMITH	\$ 850.00	
11266	Installed/Active	03/22/2001	FSG30	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11267	Installed/Active	02/24/2005	GVC50	A. O. SMITH	\$ 850.00	
11268	Installed/Active	04/29/2001	41XR50	RHEEM	\$ 850.00	
11269	Installed/Active	05/17/1991	P506	RUUD	\$ 1,150.00	
11270	Installed/Active	08/10/2004	41V50	RHEEM	\$ 1,150.00	
11271	Installed/Active	08/08/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11272	Installed/Active	02/07/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11273	Installed/Active	12/30/2008	P502	RUUD	\$ 850.00	\$ 11.74
11274	Installed/Active	07/02/2002	PRX50	STATE	\$ 1,075.00	
11275	Installed/Active	08/02/2001	PGR50	AO SMITH	\$ 850.00	
11276	Installed/Active	01/22/1991	P506	RUUD	\$ 1,125.00	
11277	Installed/Active	02/09/2007	TNR200100	LOCHINVAR	\$ 3,350.00	\$ 51.80
11278	Installed/Active	04/06/1990	FSG50	AO SMITH	\$ 850.00	
11279	Installed/Active	03/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11280	Installed/Active	06/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11281	Installed/Active	02/02/2005	GVC50	A. O. SMITH	\$ 850.00	
11282	Installed/Active	02/09/2007	TNR200100	LOCHINVAR	\$ 3,350.00	\$ 51.80
11283	Installed/Active	03/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11284	Installed/Active	11/23/1999	FSG50	AO SMITH	\$ 850.00	
11285	Installed/Active	11/15/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
11286	Installed/Active	01/18/2013	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
11287	Installed/Active	08/24/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
11288	Installed/Active	03/13/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11289	Installed/Active	04/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11290	Installed/Active	04/14/2006	21DV50	RHEEM	\$ 1,075.00	
11291	Installed/Active	01/18/2013	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
11292	Installed/Active	08/08/1999	FGR50	AO SMITH	\$ 850.00	
11293	Installed/Active	08/01/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11294	Installed/Active	08/13/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11295	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11296	Installed/Active	09/21/1990	FSG50	AO SMITH	\$ 850.00	
11297	Installed/Active	01/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
11298	Installed/Active	01/24/2000	FSG50	AO SMITH	\$ 850.00	
11299	Installed/Active	02/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11300	Installed/Active	03/04/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11301	Installed/Active	01/15/1991	P506	RUUD	\$ 1,125.00	
11302	Installed/Active	01/03/2003	PGR50	AO SMITH	\$ 850.00	
11303	Installed/Active	05/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11304	Installed/Active	09/25/2006	PRV50NODS	STATE	\$ 1,075.00	
11305	Installed/Active	01/16/2004	XTN050	LOCHINVAR	\$ 850.00	
11306	Installed/Active	09/18/2002	PGR50	AO SMITH	\$ 850.00	
11307	Installed/Active	10/22/2002	FSG50	AO SMITH	\$ 850.00	
11308	Installed/Active	07/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11309	Installed/Active	03/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
11310	Installed/Active	10/03/2005	LTN051G	LOCHINVAR	\$ 1,150.00	
11311	Installed/Active	03/23/1990	P506	RUUD	\$ 1,125.00	
11312	Installed/Active	09/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
11313	Installed/Active	06/29/2011	21V506	RHEEM	\$ 1,150.00	\$ 17.37
11314	Installed/Active	06/05/1990	PRV50NODS	STATE	\$ 1,075.00	
11315	Installed/Active	02/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11316	Installed/Active	05/26/2000	PR650	STATE	\$ 1,075.00	
11317	Installed/Active	08/28/2008	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
11318	Installed/Active	10/06/2000	FSGL40	AO SMITH	\$ 850.00	
11319	Installed/Active	11/10/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11320	Installed/Active	06/06/2003	PGR50	AO SMITH	\$ 850.00	
11321	Installed/Active	08/28/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11322	Installed/Active	06/08/2005	ETN076	LOCHINVAR	\$ 1,900.00	
11323	Installed/Active	07/28/2006	FSG50	AO SMITH	\$ 850.00	
11324	Installed/Active	10/13/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
11325	Installed/Active	06/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11326	Installed/Active	02/16/2001	PRX50	STATE	\$ 1,075.00	
11327	Installed/Active	05/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11328	Installed/Active	06/03/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
11329	Installed/Active	08/10/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
11330	Installed/Active	10/26/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11331	Installed/Active	03/02/1993	21V502	RHEEM	\$ 850.00	
11332	Installed/Active	03/21/2005	42XR50	RHEEM	\$ 850.00	
11333	Installed/Active	12/27/2002	PGR50	AO SMITH	\$ 850.00	
11334	Installed/Active	06/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11335	Installed/Active	02/09/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11336	Installed/Active	07/16/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11337	Installed/Active	03/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11338	Installed/Active	11/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11339	Installed/Active	06/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
11340	Installed/Active	11/27/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
11341	Installed/Active	11/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11342	Installed/Active	02/24/2002	PGR50	AO SMITH	\$ 850.00	
11343	Installed/Active	09/29/1992	FSG50	AO SMITH	\$ 850.00	
11344	Installed/Active	11/11/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
11345	Installed/Active	08/21/2004	XVR40	A. O. SMITH	\$ 850.00	
11346	Installed/Active	10/06/2005	LTN050G	LOCHINVAR	\$ 850.00	
11347	Installed/Active	06/20/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11348	Installed/Active	12/04/1992	21V506	RHEEM	\$ 1,150.00	
11349	Installed/Active	10/04/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11350	Installed/Active	04/11/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
11351	Installed/Active	09/08/1992	PRV50NORT	STATE	\$ 850.00	
11352	Installed/Active	07/08/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11353	Installed/Active	02/07/2005	XVR50	A. O. SMITH	\$ 850.00	
11354	Installed/Active	06/10/1993	21V502	RHEEM	\$ 850.00	
11355	Installed/Active	11/06/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
11356	Installed/Active	04/04/2002	FSG50	AO SMITH	\$ 850.00	
11357	Installed/Active	06/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11358	Installed/Active	06/11/1993	21V502	RHEEM	\$ 850.00	
11359	Installed/Active	02/24/2005	PRX50	STATE	\$ 1,075.00	
11360	Installed/Active	02/23/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
11361	Installed/Active	04/08/1992	PRX50	STATE	\$ 1,075.00	
11362	Installed/Active	03/24/2011	41VR40	RHEEM	\$ 850.00	\$ 12.05
11363	Installed/Active	09/26/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11364	Installed/Active	03/30/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11365	Installed/Active	07/28/1992	21V502	RHEEM	\$ 850.00	
11366	Installed/Active	01/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
11367	Installed/Active	04/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11368	Installed/Active	01/14/2003	41V50	RHEEM	\$ 850.00	
11369	Installed/Active	05/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11370	Installed/Active	07/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
11371	Installed/Active	02/03/2003	PGR40	AO SMITH	\$ 350.00	
11372	Installed/Active	11/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11373	Installed/Active	11/28/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11374	Installed/Active	12/21/1988	FSG50	AO SMITH	\$ 850.00	
11375	Installed/Active	11/28/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11376	Installed/Active	11/04/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11377	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11378	Installed/Active	09/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11379	Installed/Active	02/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11380	Installed/Active	06/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11381	Installed/Active	07/06/2005	LTN050	LOCHINVAR	\$ 850.00	
11382	Installed/Active	07/29/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11383	Installed/Active	09/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11384	Installed/Active	07/26/2008	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 14.05
11385	Installed/Active	10/31/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
11386	Installed/Active	08/20/1992	FSG50	AO SMITH	\$ 850.00	
11387	Installed/Active	09/18/1990	PRV50NODS	STATE	\$ 1,075.00	
11388	Installed/Active	07/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
11389	Installed/Active	09/22/2003	PR650	STATE	\$ 1,075.00	
11390	Installed/Active	08/24/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11391	Installed/Active	04/23/2000	41V50	RHEEM	\$ 850.00	
11392	Installed/Active	01/02/2004	PRX50	STATE	\$ 1,075.00	
11393	Installed/Active	02/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11394	Installed/Active	02/13/2007	42VR50	RHEEM	\$ 1,150.00	\$ 14.05
11395	Installed/Active	03/30/2012	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.37
11396	Installed/Active	06/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11397	Installed/Active	03/20/2001	FSG50	AO SMITH	\$ 850.00	
11398	Installed/Active	02/13/2007	P506	RUUD	\$ 1,150.00	\$ 14.05
11399	Installed/Active	07/23/2012	F72DUMMY	UNKNOWN AT CONVERSION	\$ 350.00	\$ 15.60
11400	Installed/Active	12/10/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11401	Installed/Active	01/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11402	Installed/Active	02/15/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11403	Installed/Active	11/12/2005	LTN050G	LOCHINVAR	\$ 850.00	
11404	Installed/Active	01/10/2005	GVC50	A. O. SMITH	\$ 850.00	
11405	Installed/Active	12/20/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
11406	Installed/Active	05/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11407	Installed/Active	01/24/1990	PRV50NODS	STATE	\$ 1,075.00	
11408	Installed/Active	12/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11409	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11410	Installed/Active	01/04/2001	FSG50	AO SMITH	\$ 850.00	
11411	Installed/Active	12/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11412	Installed/Active	06/30/1989	PRV50NORT	STATE	\$ 850.00	
11413	Installed/Active	01/31/1989	FSG50	AO SMITH	\$ 850.00	
11414	Installed/Active	02/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11415	Installed/Active	11/14/2003	PVR50	AO SMITH	\$ 850.00	
11416	Installed/Active	08/05/1989	FSG50	AO SMITH	\$ 850.00	
11417	Installed/Active	04/22/2002	PGR50	AO SMITH	\$ 850.00	
11418	Installed/Active	11/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11419	Installed/Active	04/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11420	Installed/Active	02/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11421	Installed/Active	11/27/2000	PGR50	AO SMITH	\$ 850.00	
11422	Installed/Active	02/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11423	Installed/Active	05/28/2002	FSGL40	AO SMITH	\$ 850.00	
11424	Installed/Active	02/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
11425	Installed/Active	05/23/1989	FSG50	AO SMITH	\$ 850.00	
11426	Installed/Active	06/28/1989	FSG40	AO SMITH	\$ 850.00	
11427	Installed/Active	01/09/2002	PGR50	AO SMITH	\$ 850.00	
11428	Installed/Active	02/12/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
11429	Installed/Active	04/13/1989	FSG50	AO SMITH	\$ 850.00	
11430	Installed/Active	03/18/1989	FSG40	AO SMITH	\$ 850.00	
11431	Installed/Active	03/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11432	Installed/Active	04/29/2002	FSG50	AO SMITH	\$ 850.00	
11433	Installed/Active	01/21/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11434	Installed/Active	02/20/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11435	Installed/Active	09/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11436	Installed/Active	05/31/1989	FSGL40	AO SMITH	\$ 850.00	
11437	Installed/Active	09/11/2000	41XR50	RHEEM	\$ 850.00	
11438	Installed/Active	01/28/2003	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11439	Installed/Active	03/25/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
11440	Installed/Active	09/01/2005	FSGL40	AO SMITH	\$ 850.00	
11441	Installed/Active	11/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
11442	Installed/Active	06/29/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
11443	Installed/Active	12/15/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11444	Installed/Active	09/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11445	Installed/Active	03/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11446	Installed/Active	01/08/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11447	Installed/Active	10/29/2009	H72DUMMY	AO SMITH	\$ 1,900.00	\$ 38.33
11448	Installed/Active	01/04/2000	PRV50NODS	STATE	\$ 1,075.00	
11449	Installed/Active	06/08/2004	GVC50	A. O. SMITH	\$ 850.00	
11450	Installed/Active	02/28/1989	FSG50	AO SMITH	\$ 850.00	
11451	Installed/Active	07/24/2003	FSG50	AO SMITH	\$ 850.00	
11452	Installed/Active	07/10/2003	21V506	RHEEM	\$ 1,150.00	
11453	Installed/Active	04/13/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11454	Installed/Active	09/25/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
11455	Installed/Active	07/16/2005	LTN050	LOCHINVAR	\$ 850.00	
11456	Installed/Active	03/27/1992	21DV50	RHEEM	\$ 1,075.00	
11457	Installed/Active	03/19/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11458	Installed/Active	02/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11459	Installed/Active	11/06/1991	FSG50	AO SMITH	\$ 850.00	
11460	Installed/Active	11/29/2004	GCVL40	A. O. SMITH	\$ 850.00	
11461	Installed/Active	08/15/2000	PRX50	STATE	\$ 1,075.00	
11462	Installed/Active	12/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11463	Installed/Active	08/31/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
11464	Installed/Active	12/11/1999	21V506	RHEEM	\$ 1,125.00	
11465	Installed/Active	09/10/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11466	Installed/Active	01/25/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11467	Installed/Active	07/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11468	Installed/Active	06/30/1991	FSG50	AO SMITH	\$ 850.00	
11469	Installed/Active	12/02/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11470	Installed/Active	12/10/1990	PRV50NORT	STATE	\$ 850.00	
11471	Installed/Active	07/10/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11472	Installed/Active	03/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11473	Installed/Active	12/10/1990	PRV50NORT	STATE	\$ 850.00	
11474	Installed/Active	09/08/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
11475	Installed/Active	02/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11476	Installed/Active	03/21/2005	LTN050	LOCHINVAR	\$ 850.00	
11477	Installed/Active	07/23/2009	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
11478	Installed/Active	08/26/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11479	Installed/Active	03/18/1991	P502	RUUD	\$ 850.00	
11480	Installed/Active	12/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11481	Installed/Active	09/23/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
11482	Installed/Active	11/09/2006	PR650	STATE	\$ 1,075.00	
11483	Installed/Active	12/29/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11484	Installed/Active	07/03/1991	FSG50	AO SMITH	\$ 850.00	
11485	Installed/Active	03/06/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11486	Installed/Active	10/05/2002	PGR50	AO SMITH	\$ 850.00	
11487	Installed/Active	12/29/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11488	Installed/Active	11/19/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
11489	Installed/Active	07/24/2006	21DV50	RHEEM	\$ 1,075.00	
11490	Installed/Active	08/08/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11491	Installed/Active	01/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11492	Installed/Active	12/20/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
11493	Installed/Active	11/03/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
11494	Installed/Active	04/21/2004	XTN050	LOCHINVAR	\$ 850.00	
11495	Installed/Active	10/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11496	Installed/Active	01/02/1996	PR502T	RUUD	\$ 850.00	
11497	Installed/Active	09/24/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11498	Installed/Active	03/02/2009	FGR50	AO SMITH	\$ 850.00	\$ 11.74
11499	Installed/Active	04/16/2003	FSGT50	AO SMITH	\$ 1,150.00	
11500	Installed/Active	08/17/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11501	Installed/Active	06/17/2005	LTN050	LOCHINVAR	\$ 850.00	
11502	Installed/Active	03/30/1990	B71DUMMY	AMERICAN	\$ 850.00	
11503	Installed/Active	08/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11504	Installed/Active	05/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11505	Installed/Active	04/04/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
11506	Installed/Active	02/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11507	Installed/Active	02/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11508	Installed/Active	11/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11509	Installed/Active	12/04/2002	PGR50	AO SMITH	\$ 850.00	
11510	Installed/Active	06/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11511	Installed/Active	09/27/2002	FSG40	AO SMITH	\$ 850.00	
11512	Installed/Active	04/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11513	Installed/Active	08/10/2011	21DV50	RHEEM	\$ 1,075.00	\$ 17.74
11514	Installed/Active	09/20/2002	PRX50	STATE	\$ 1,075.00	
11515	Installed/Active	03/22/2006	PR650	STATE	\$ 1,075.00	
11516	Installed/Active	11/08/1990	PRV50NODS	STATE	\$ 1,075.00	
11517	Installed/Active	01/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11518	Installed/Active	01/31/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11519	Installed/Active	10/06/2004	PRX50	STATE	\$ 1,075.00	
11520	Installed/Active	08/17/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11521	Installed/Active	04/08/1998	21V506	RHEEM	\$ 1,150.00	
11522	Installed/Active	05/01/2002	PRX50	STATE	\$ 1,075.00	
11523	Installed/Active	11/12/2003	41XR50	RHEEM	\$ 850.00	
11524	Installed/Active	02/03/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11525	Installed/Active	09/18/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
11526	Installed/Active	02/14/2000	PHR50	RUUD	\$ 850.00	
11527	Installed/Active	05/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11528	Installed/Active	10/11/2001	FSG50	AO SMITH	\$ 850.00	
11529	Installed/Active	06/01/1990	PRV50NODS	STATE	\$ 1,075.00	
11530	Installed/Active	10/14/1998	FGR40	AO SMITH	\$ 850.00	
11531	Installed/Active	06/06/2007	21V506	RHEEM	\$ 1,150.00	\$ 14.05
11532	Installed/Active	04/07/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
11533	Installed/Active	09/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11534	Installed/Active	06/28/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11535	Installed/Active	09/01/1989	FSG50	AO SMITH	\$ 850.00	
11536	Installed/Active	10/25/2003	FCV50	AO SMITH	\$ 850.00	
11537	Installed/Active	02/28/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11538	Installed/Active	09/13/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11539	Installed/Active	07/07/2009	PRX50	STATE	\$ 1,075.00	\$ 16.47
11540	Installed/Active	04/27/2000	FSG50	AO SMITH	\$ 850.00	
11541	Installed/Active	01/07/2002	PGR50	AO SMITH	\$ 850.00	
11542	Installed/Active	04/08/1999	FGR50	AO SMITH	\$ 850.00	
11543	Installed/Active	05/17/1989	FSG50	AO SMITH	\$ 850.00	
11544	Installed/Active	07/08/2008	42VR50	RHEEM	\$ 850.00	\$ 10.23
11545	Installed/Active	02/23/1989	21V506	RHEEM	\$ 1,150.00	
11546	Installed/Active	09/27/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
11547	Installed/Active	11/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11548	Installed/Active	08/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11549	Installed/Active	11/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11550	Installed/Active	10/26/1989	FSG50	AO SMITH	\$ 850.00	
11551	Installed/Active	06/26/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
11552	Installed/Active	12/15/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11553	Installed/Active	01/09/2003	SBF100199NES	STATE	\$ 3,350.00	
11554	Installed/Active	07/22/2005	LTN050	LOCHINVAR	\$ 850.00	
11555	Installed/Active	03/29/1989	FSG50	AO SMITH	\$ 850.00	
11556	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11557	Installed/Active	10/17/2005	LTN050G	LOCHINVAR	\$ 850.00	
11558	Installed/Active	12/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11559	Installed/Active	02/25/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11560	Installed/Active	01/09/2003	SBF100199NES	STATE	\$ 3,350.00	
11561	Installed/Active	11/27/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11562	Installed/Active	03/28/2003	PGR50	AO SMITH	\$ 850.00	
11563	Installed/Active	10/15/2007	PRX50	STATE	\$ 1,075.00	\$ 14.35
11564	Installed/Active	01/31/1989	FSG30	AO SMITH	\$ 850.00	
11565	Installed/Active	11/29/2003	21DV50	RHEEM	\$ 1,075.00	
11566	Installed/Active	04/18/2006	PR650	STATE	\$ 1,075.00	
11567	Installed/Active	10/07/2005	LTN050G	LOCHINVAR	\$ 850.00	
11568	Installed/Active	04/04/2003	FSG50	AO SMITH	\$ 850.00	
11569	Installed/Active	09/05/2003	FCV50	AO SMITH	\$ 850.00	
11570	Installed/Active	01/23/1989	FSG50	AO SMITH	\$ 850.00	
11571	Installed/Active	02/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
11572	Installed/Active	02/12/2004	FCV50	AO SMITH	\$ 850.00	
11573	Installed/Active	02/03/1989	FSG50	AO SMITH	\$ 850.00	
11574	Installed/Active	12/29/1989	F72DUMMY	AO SMITH	\$ 3,350.00	
11575	Installed/Active	03/24/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
11576	Installed/Active	02/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11577	Installed/Active	03/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11578	Installed/Active	06/22/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
11579	Installed/Active	07/11/1997	FGR40	AO SMITH	\$ 850.00	
11580	Installed/Active	05/10/1989	FSG50	AO SMITH	\$ 850.00	
11581	Installed/Active	05/30/2011	22V40SF	RHEEM	\$ 850.00	\$ 12.64
11582	Installed/Active	06/25/2004	XTN050	LOCHINVAR	\$ 850.00	
11583	Installed/Active	12/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
11584	Installed/Active	11/18/1992	P502	RUUD	\$ 850.00	
11585	Installed/Active	09/17/1999	PR650	STATE	\$ 1,075.00	
11586	Installed/Active	09/16/1992	FSG50	AO SMITH	\$ 850.00	
11587	Installed/Active	07/03/2005	FSG40	AO SMITH	\$ 850.00	
11588	Installed/Active	11/26/2001	FSG50	AO SMITH	\$ 850.00	
11589	Installed/Active	12/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
11590	Installed/Active	10/10/2003	PGR50	AO SMITH	\$ 850.00	
11591	Installed/Active	07/12/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
11592	Installed/Active	02/22/2005	XTN050	LOCHINVAR	\$ 850.00	
11593	Installed/Active	02/11/2005	XTN050	LOCHINVAR	\$ 850.00	
11594	Installed/Active	11/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11595	Installed/Active	02/21/2001	FSG50	AO SMITH	\$ 850.00	
11596	Installed/Active	04/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11597	Installed/Active	02/08/2008	LTN051	LOCHINVAR	\$ 1,150.00	\$ 14.05
11598	Installed/Active	05/22/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
11599	Installed/Active	01/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11600	Installed/Active	11/07/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
11601	Installed/Active	04/28/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11602	Installed/Active	12/21/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11603	Installed/Active	03/06/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
11604	Installed/Active	02/10/2005	GVC40	A. O. SMITH	\$ 850.00	
11605	Installed/Active	01/22/1993	PRV50NODS	STATE	\$ 1,075.00	
11606	Installed/Active	02/23/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
11607	Installed/Active	10/31/2002	BTR199	AO SMITH	\$ 3,350.00	
11608	Installed/Active	08/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
11609	Installed/Active	10/30/2012	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 20.38
11610	Installed/Active	06/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11611	Installed/Active	11/09/1992	P506	RUUD	\$ 1,150.00	
11612	Installed/Active	01/15/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11613	Installed/Active	04/27/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
11614	Installed/Active	03/21/2001	PGR50	AO SMITH	\$ 850.00	
11615	Installed/Active	06/19/2004	GVC50	A. O. SMITH	\$ 850.00	
11616	Installed/Active	09/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11617	Installed/Active	06/09/2006	PR650	STATE	\$ 1,075.00	
11618	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11619	Installed/Active	08/07/1992	RF67120	RUUD	\$ 1,900.00	
11620	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11621	Installed/Active	12/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11622	Installed/Active	12/10/2012	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
11623	Installed/Active	05/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11624	Installed/Active	10/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11625	Installed/Active	04/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11626	Installed/Active	05/16/2005	LTN050	LOCHINVAR	\$ 850.00	
11627	Installed/Active	10/06/2003	PVR50	AO SMITH	\$ 850.00	
11628	Installed/Active	03/16/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11629	Installed/Active	04/15/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11630	Installed/Active	12/06/2010	21V506	RHEEM	\$ 1,150.00	\$ 16.55
11631	Installed/Active	12/16/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
11632	Installed/Active	02/23/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
11633	Installed/Active	08/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
11634	Installed/Active	02/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
11635	Installed/Active	11/29/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
11636	Installed/Active	04/12/1990	B71DUMMY	AMERICAN	\$ 850.00	
11637	Installed/Active	01/03/2001	PRX50	STATE	\$ 1,075.00	
11638	Installed/Active	12/26/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11639	Installed/Active	12/18/2006	PR650	STATE	\$ 1,075.00	
11640	Installed/Active	05/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11641	Installed/Active	06/09/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
11642	Installed/Active	04/27/1990	P506	RUUD	\$ 1,150.00	
11643	Installed/Active	07/29/2004	XTN050	LOCHINVAR	\$ 850.00	
11644	Installed/Active	01/21/1991	PRX50	STATE	\$ 1,075.00	
11645	Installed/Active	02/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11646	Installed/Active	01/03/2011	21VR50	RHEEM	\$ 850.00	\$ 16.91
11647	Installed/Active	12/04/2003	PRX50	STATE	\$ 1,075.00	
11648	Installed/Active	10/15/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11649	Installed/Active	03/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11650	Installed/Active	03/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11651	Installed/Active	04/23/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11652	Installed/Active	10/20/2004	LTN050G	LOCHINVAR	\$ 850.00	
11653	Installed/Active	06/01/1999	FSG50	AO SMITH	\$ 850.00	
11654	Installed/Active	03/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11655	Installed/Active	10/23/2003	FSG30	AO SMITH	\$ 850.00	
11656	Installed/Active	09/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11657	Installed/Active	07/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11658	Installed/Active	05/21/2003	PGR50	AO SMITH	\$ 850.00	
11659	Installed/Active	01/22/1990	FSG50	AO SMITH	\$ 850.00	
11660	Installed/Active	12/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11661	Installed/Active	04/10/2000	FSG50	AO SMITH	\$ 850.00	
11662	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11663	Installed/Active	07/02/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
11664	Installed/Active	06/24/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
11665	Installed/Active	09/17/1990	P506	RUUD	\$ 500.00	
11666	Installed/Active	10/08/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11667	Installed/Active	10/05/2001	PGR40	AO SMITH	\$ 850.00	
11668	Installed/Active	02/24/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
11669	Installed/Active	04/18/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
11670	Installed/Active	06/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11671	Installed/Active	05/06/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
11672	Installed/Active	05/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11673	Installed/Active	08/22/1990	PRV50NORT	STATE	\$ 850.00	
11674	Installed/Active	05/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11675	Installed/Active	11/30/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
11676	Installed/Active	10/30/1990	FSG50	AO SMITH	\$ 850.00	
11677	Installed/Active	05/07/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
11678	Installed/Active	12/20/2005	GVC50	A. O. SMITH	\$ 850.00	
11679	Installed/Active	01/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11680	Installed/Active	07/04/2005	LSN041G	LOCHINVAR	\$ 850.00	
11681	Installed/Active	06/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
11682	Installed/Active	12/12/1991	P506	RUUD	\$ 1,150.00	
11683	Installed/Active	08/17/2002	FSG50	AO SMITH	\$ 850.00	
11684	Installed/Active	07/08/1991	FSG50	AO SMITH	\$ 850.00	
11685	Installed/Active	07/25/2003	FSG50	AO SMITH	\$ 850.00	
11686	Installed/Active	11/13/2008	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
11687	Installed/Active	02/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11688	Installed/Active	12/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11689	Installed/Active	05/06/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
11690	Installed/Active	11/16/2008	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
11691	Installed/Active	07/31/1991	FSG50	AO SMITH	\$ 850.00	
11692	Installed/Active	10/22/2001	PGR50	AO SMITH	\$ 850.00	
11693	Installed/Active	02/23/2007	P506	RUUD	\$ 1,075.00	\$ 14.35
11694	Installed/Active	09/18/1991	P502	RUUD	\$ 850.00	
11695	Installed/Active	10/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11696	Installed/Active	11/13/2008	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11697	Installed/Active	03/23/1991	G67114	RHEEM	\$ 1,900.00	
11698	Installed/Active	07/27/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11699	Installed/Active	12/07/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
11700	Installed/Active	06/28/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
11701	Installed/Active	11/07/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
11702	Installed/Active	01/29/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
11703	Installed/Active	10/15/1991	RF92200	RUUD	\$ 3,350.00	
11704	Installed/Active	06/08/2006	PR650	STATE	\$ 1,075.00	
11705	Installed/Active	01/29/2001	PRX50	STATE	\$ 1,075.00	
11706	Installed/Active	10/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11707	Installed/Active	06/04/2008	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
11708	Installed/Active	05/22/1991	41XR50	RHEEM	\$ 850.00	
11709	Installed/Active	02/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
11710	Installed/Active	08/08/1991	P506	RUUD	\$ 1,150.00	
11711	Installed/Active	07/22/2002	21V506	RHEEM	\$ 1,150.00	
11712	Installed/Active	11/29/1999	FSG50	AO SMITH	\$ 850.00	
11713	Installed/Active	11/06/2009	P502	RUUD	\$ 850.00	\$ 11.74
11714	Installed/Active	01/05/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11715	Installed/Active	05/15/2012	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.52
11716	Installed/Active	09/29/2007	FSG50	AO SMITH	\$ 850.00	\$ 10.23
11717	Installed/Active	02/23/2007	FSGL40	AO SMITH	\$ 850.00	\$ 10.23
11718	Installed/Active	01/31/2000	PGR50	AO SMITH	\$ 850.00	
11719	Installed/Active	03/15/2006	PR650	STATE	\$ 1,075.00	
11720	Installed/Active	11/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11721	Installed/Active	10/31/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
11722	Installed/Active	03/08/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
11723	Installed/Active	07/17/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11724	Installed/Active	10/27/2000	PGR50	AO SMITH	\$ 850.00	
11725	Installed/Active	06/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11726	Installed/Active	02/26/2004	PVR50	AO SMITH	\$ 850.00	
11727	Installed/Active	08/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11728	Installed/Active	07/01/2003	PRX50	STATE	\$ 1,075.00	
11729	Installed/Active	06/16/2006	PR650X0DS	STATE	\$ 1,075.00	
11730	Installed/Active	07/20/1998	FSG50	AO SMITH	\$ 850.00	
11731	Installed/Active	03/08/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11732	Installed/Active	06/11/2001	FSG50	AO SMITH	\$ 850.00	
11733	Installed/Active	12/31/2004	LTN050	LOCHINVAR	\$ 850.00	
11734	Installed/Active	12/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11735	Installed/Active	01/26/2005	GVC50	A. O. SMITH	\$ 850.00	
11736	Installed/Active	08/26/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11737	Installed/Active	11/17/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
11738	Installed/Active	02/06/2002	FSG50	AO SMITH	\$ 850.00	
11739	Installed/Active	03/31/2003	FSGL40	AO SMITH	\$ 850.00	
11740	Installed/Active	01/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11741	Installed/Active	01/06/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
11742	Installed/Active	05/18/1990	P506	RUUD	\$ 1,150.00	
11743	Installed/Active	06/05/1998	FSG50	AO SMITH	\$ 850.00	
11744	Installed/Active	04/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
11745	Installed/Active	05/10/1999	FSG50	AO SMITH	\$ 850.00	
11746	Installed/Active	03/05/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11747	Installed/Active	02/15/2006	PR650	STATE	\$ 1,075.00	
11748	Installed/Active	03/02/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11749	Installed/Active	04/12/1999	FSG50	AO SMITH	\$ 850.00	
11750	Installed/Active	10/24/2012	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11751	Installed/Active	02/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11752	Installed/Active	04/10/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
11753	Installed/Active	03/08/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
11754	Installed/Active	12/12/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11755	Installed/Active	12/27/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
11756	Installed/Active	10/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11757	Installed/Active	03/28/2002	FSG50	AO SMITH	\$ 850.00	
11758	Installed/Active	09/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11759	Installed/Active	01/05/1990	PRX50	STATE	\$ 1,075.00	
11760	Installed/Active	04/23/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11761	Installed/Active	12/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11762	Installed/Active	05/18/1990	PRX50	STATE	\$ 1,075.00	
11763	Installed/Active	11/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
11764	Installed/Active	11/20/1998	41XR50	RHEEM	\$ 850.00	
11765	Installed/Active	06/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11766	Installed/Active	03/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
11767	Installed/Active	04/23/1996	PHR50	RUUD	\$ 850.00	
11768	Installed/Active	11/28/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11769	Installed/Active	05/31/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11770	Installed/Active	05/22/2001	PGR50	AO SMITH	\$ 850.00	
11771	Installed/Active	11/25/2011	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11772	Installed/Active	03/03/2001	41VR50	RHEEM	\$ 850.00	
11773	Installed/Active	11/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11774	Installed/Active	10/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11775	Installed/Active	07/11/2001	PGR50	AO SMITH	\$ 850.00	
11776	Installed/Active	07/16/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11777	Installed/Active	02/17/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11778	Installed/Active	06/10/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
11779	Installed/Active	01/07/2000	PRX50	STATE	\$ 1,075.00	
11780	Installed/Active	07/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11781	Installed/Active	02/18/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11782	Installed/Active	06/05/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11783	Installed/Active	03/07/2001	FSG40	AO SMITH	\$ 850.00	
11784	Installed/Active	06/05/2007	XVR50	A. O. SMITH	\$ 850.00	\$ 10.23
11785	Installed/Active	06/29/2000	PGR50	AO SMITH	\$ 850.00	
11786	Installed/Active	06/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
11787	Installed/Active	02/08/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
11788	Installed/Active	06/09/2004	PRX50	STATE	\$ 1,075.00	
11789	Installed/Active	12/20/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11790	Installed/Active	04/17/1989	FSG50	AO SMITH	\$ 850.00	
11791	Installed/Active	06/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
11792	Installed/Active	05/09/2012	PH2DV50F	RUUD	\$ 850.00	\$ 12.64
11793	Installed/Active	04/26/2005	LTN050	LOCHINVAR	\$ 850.00	
11794	Installed/Active	08/16/2000	PGR50	AO SMITH	\$ 850.00	
11795	Installed/Active	07/20/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
11796	Installed/Active	10/24/1989	FSG50	AO SMITH	\$ 850.00	
11797	Installed/Active	08/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11798	Installed/Active	02/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11799	Installed/Active	01/05/2000	PGR50	AO SMITH	\$ 850.00	
11800	Installed/Active	08/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11801	Installed/Active	12/23/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
11802	Installed/Active	03/09/2005	GVC50	A. O. SMITH	\$ 850.00	
11803	Installed/Active	09/13/2011	41XR50	RHEEM	\$ 850.00	\$ 12.64
11804	Installed/Active	12/31/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11805	Installed/Active	03/09/2005	XVR50	A. O. SMITH	\$ 850.00	
11806	Installed/Active	12/16/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11807	Installed/Active	06/27/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11808	Installed/Active	06/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11809	Installed/Active	03/13/1989	P506	RUUD	\$ 1,125.00	
11810	Installed/Active	12/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
11811	Installed/Active	08/20/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11812	Installed/Active	05/19/2005	LTN050	LOCHINVAR	\$ 850.00	
11813	Installed/Active	03/04/2005	GVC50	A. O. SMITH	\$ 850.00	
11814	Installed/Active	05/12/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
11815	Installed/Active	08/10/2006	PR650XODS	STATE	\$ 1,075.00	
11816	Installed/Active	04/17/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11817	Installed/Active	09/04/2002	PGR50	AO SMITH	\$ 850.00	
11818	Installed/Active	01/09/2006	LTN050	LOCHINVAR	\$ 850.00	
11819	Installed/Active	01/25/1993	FSG50	AO SMITH	\$ 850.00	
11820	Installed/Active	07/13/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
11821	Installed/Active	03/31/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11822	Installed/Active	10/05/1992	P506	RUUD	\$ 1,150.00	
11823	Installed/Active	03/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11824	Installed/Active	05/13/1992	FSG40	AO SMITH	\$ 850.00	
11825	Installed/Active	05/16/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11826	Installed/Active	02/07/2003	PGR50	AO SMITH	\$ 850.00	
11827	Installed/Active	05/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11828	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11829	Installed/Active	04/30/1992	41V50	RHEEM	\$ 850.00	
11830	Installed/Active	05/05/2003	FSG40	AO SMITH	\$ 850.00	
11831	Installed/Active	05/30/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
11832	Installed/Active	01/15/2002	PGR50	AO SMITH	\$ 850.00	
11833	Installed/Active	08/05/1992	FSG50	AO SMITH	\$ 850.00	
11834	Installed/Active	08/14/2003	PRX50	STATE	\$ 1,075.00	
11835	Installed/Active	02/27/2003	FSG50	AO SMITH	\$ 850.00	
11836	Installed/Active	06/19/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
11837	Installed/Active	06/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11838	Installed/Active	09/15/2002	FSG50	AO SMITH	\$ 850.00	
11839	Installed/Active	02/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11840	Installed/Active	08/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11841	Installed/Active	07/26/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
11842	Installed/Active	12/28/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11843	Installed/Active	09/09/2002	21V506	RHEEM	\$ 1,150.00	
11844	Installed/Active	05/29/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
11845	Installed/Active	02/06/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11846	Installed/Active	09/15/2005	LTN050	LOCHINVAR	\$ 850.00	
11847	Installed/Active	11/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11848	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11849	Installed/Active	12/22/2010	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
11850	Installed/Active	12/02/1992	P506	RUUD	\$ 1,150.00	
11851	Installed/Active	08/25/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
11852	Installed/Active	10/14/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
11853	Installed/Active	10/01/1992	FSG50	AO SMITH	\$ 850.00	
11854	Installed/Active	06/12/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11855	Installed/Active	08/14/1998	FGR50	AO SMITH	\$ 850.00	
11856	Installed/Active	04/25/2008	41V50	RHEEM	\$ 850.00	\$ 10.23
11857	Installed/Active	06/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11858	Installed/Active	02/15/1990	21V506	RHEEM	\$ 1,150.00	
11859	Installed/Active	03/24/2004	PRX50	STATE	\$ 1,075.00	
11860	Installed/Active	10/13/2005	LTN050	LOCHINVAR	\$ 1,150.00	
11861	Installed/Active	03/28/2001	PGR50	AO SMITH	\$ 850.00	
11862	Installed/Active	12/02/2000	41XR50	RHEEM	\$ 850.00	
11863	Installed/Active	12/01/1993	FGR50	AO SMITH	\$ 850.00	
11864	Installed/Active	02/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11865	Installed/Active	07/30/2003	PRX50	STATE	\$ 1,075.00	
11866	Installed/Active	07/27/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
11867	Installed/Active	12/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11868	Installed/Active	12/18/2001	PRX50	STATE	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11869	Installed/Active	03/02/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
11870	Installed/Active	12/22/2004	C71	UNKNOWN	\$ 1,075.00	
11871	Installed/Active	03/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
11872	Installed/Active	12/30/1999	FGR50	AO SMITH	\$ 850.00	
11873	Installed/Active	10/10/1990	P506	RUUD	\$ 1,150.00	
11874	Installed/Active	12/03/2004	LTN050G	LOCHINVAR	\$ 850.00	
11875	Installed/Active	02/12/1990	P505	RUUD	\$ 1,125.00	
11876	Installed/Active	04/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11877	Installed/Active	08/07/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11878	Installed/Active	02/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11879	Installed/Active	03/26/2003	PGR50	AO SMITH	\$ 850.00	
11880	Installed/Active	05/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11881	Installed/Active	03/06/1991	B71DUMMY	AMERICAN	\$ 850.00	
11882	Installed/Active	04/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
11883	Installed/Active	01/10/2005	GVC50	A. O. SMITH	\$ 850.00	
11884	Installed/Active	08/02/2002	FSG50	AO SMITH	\$ 850.00	
11885	Installed/Active	09/03/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
11886	Installed/Active	03/10/1990	PRX40	STATE	\$ 1,075.00	
11887	Installed/Active	02/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11888	Installed/Active	03/06/1990	PRV50NODS	STATE	\$ 1,075.00	
11889	Installed/Active	06/20/2006	PR650	STATE	\$ 1,075.00	
11890	Installed/Active	04/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11891	Installed/Active	01/06/2006	PR650	STATE	\$ 1,075.00	
11892	Installed/Active	12/18/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
11893	Installed/Active	07/14/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
11894	Installed/Active	06/09/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11895	Installed/Active	09/30/2003	PGR50	AO SMITH	\$ 850.00	
11896	Installed/Active	09/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11897	Installed/Active	02/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11898	Installed/Active	03/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
11899	Installed/Active	09/17/1999	41VR50	RHEEM	\$ 850.00	
11900	Installed/Active	03/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
11901	Installed/Active	08/28/2001	FSG50	AO SMITH	\$ 850.00	
11902	Installed/Active	09/18/1991	FSG50	AO SMITH	\$ 850.00	
11903	Installed/Active	10/06/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11904	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11905	Installed/Active	07/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11906	Installed/Active	04/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11907	Installed/Active	12/11/2001	PGR50	AO SMITH	\$ 850.00	
11908	Installed/Active	01/07/2002	L72DUMMY	AO SMITH	\$ 3,350.00	
11909	Installed/Active	05/27/2001	PRX50	STATE	\$ 1,075.00	
11910	Installed/Active	04/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11911	Installed/Active	08/24/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
11912	Installed/Active	08/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11913	Installed/Active	04/13/2005	GVC50	A. O. SMITH	\$ 850.00	
11914	Installed/Active	01/14/2003	FSG40	AO SMITH	\$ 850.00	
11915	Installed/Active	05/23/1991	FSG50	AO SMITH	\$ 850.00	
11916	Installed/Active	07/23/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
11917	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11918	Installed/Active	09/27/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
11919	Installed/Active	08/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11920	Installed/Active	07/01/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
11921	Installed/Active	04/06/2012	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
11922	Installed/Active	08/19/1991	RF92200	RUUD	\$ 3,350.00	
11923	Installed/Active	12/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11924	Installed/Active	12/13/2005	LTN050G	LOCHINVAR	\$ 850.00	
11925	Installed/Active	05/08/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
11926	Installed/Active	05/01/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11927	Installed/Active	12/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11928	Installed/Active	02/03/2003	PRX50	STATE	\$ 1,075.00	
11929	Installed/Active	09/16/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11930	Installed/Active	02/18/2000	PGR50	AO SMITH	\$ 850.00	
11931	Installed/Active	10/11/2012	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
11932	Installed/Active	02/04/2002	PGR50	AO SMITH	\$ 850.00	
11933	Installed/Active	06/14/2002	21DV50	RHEEM	\$ 1,075.00	
11934	Installed/Active	09/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11935	Installed/Active	03/06/2004	PRX50	STATE	\$ 1,075.00	
11936	Installed/Active	12/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
11937	Installed/Active	10/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
11938	Installed/Active	11/04/2002	PRX50	STATE	\$ 1,075.00	
11939	Installed/Active	09/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11940	Installed/Active	07/29/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11941	Installed/Active	11/23/1994	FGR50	AO SMITH	\$ 850.00	
11942	Installed/Active	01/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11943	Installed/Active	03/12/1999	FGR50	AO SMITH	\$ 850.00	
11944	Installed/Active	12/21/2006	PR650	STATE	\$ 1,075.00	
11945	Installed/Active	08/18/2010	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 19.26
11946	Installed/Active	05/04/1998	FSG50	AO SMITH	\$ 850.00	
11947	Installed/Active	10/20/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11948	Installed/Active	02/26/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11949	Installed/Active	10/07/2010	21V506	RHEEM	\$ 1,125.00	\$ 19.26
11950	Installed/Active	06/28/2005	G76200	RUUD/RHEEM	\$ 3,350.00	
11951	Installed/Active	12/11/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
11952	Installed/Active	01/19/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
11953	Installed/Active	12/19/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.64
11954	Installed/Active	02/26/2001	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
11955	Installed/Active	06/04/2000	41XR50	RHEEM	\$ 850.00	
11956	Installed/Active	10/23/2001	FSG50	AO SMITH	\$ 850.00	
11957	Installed/Active	12/26/2004	PRX50	STATE	\$ 1,075.00	
11958	Installed/Active	07/03/1990	FSG50	AO SMITH	\$ 850.00	
11959	Installed/Active	07/29/2007	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 16.35
11960	Installed/Active	11/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11961	Installed/Active	08/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11962	Installed/Active	02/07/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11963	Installed/Active	09/24/2008	42VR50	RHEEM	\$ 850.00	\$ 10.23
11964	Installed/Active	10/31/2005	LTN050G	LOCHINVAR	\$ 850.00	
11965	Installed/Active	11/03/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
11966	Installed/Active	04/15/1997	FGR50	AO SMITH	\$ 850.00	
11967	Installed/Active	10/15/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
11968	Installed/Active	06/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11969	Installed/Active	07/04/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
11970	Installed/Active	01/09/2000	41VR50	RHEEM	\$ 850.00	
11971	Installed/Active	09/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
11972	Installed/Active	05/28/1999	FSG50	AO SMITH	\$ 850.00	
11973	Installed/Active	08/15/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11974	Installed/Active	05/01/2004	GVC50	A. O. SMITH	\$ 850.00	
11975	Installed/Active	12/26/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
11976	Installed/Active	08/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11977	Installed/Active	02/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
11978	Installed/Active	10/12/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
11979	Installed/Active	01/29/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
11980	Installed/Active	12/28/2005	GVC50	A. O. SMITH	\$ 850.00	
11981	Installed/Active	10/08/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
11982	Installed/Active	04/13/2010	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.55
11983	Installed/Active	11/21/1990	PRV50NODS	STATE	\$ 1,075.00	
11984	Installed/Active	04/05/1990	P506	RUUD	\$ 1,150.00	
11985	Installed/Active	07/01/2010	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 16.55
11986	Installed/Active	01/09/1998	FGR50	AO SMITH	\$ 850.00	
11987	Installed/Active	10/28/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
11988	Installed/Active	11/30/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
11989	Installed/Active	11/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
11990	Installed/Active	06/26/1990	FSG50	AO SMITH	\$ 850.00	
11991	Installed/Active	08/08/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
11992	Installed/Active	10/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
11993	Installed/Active	04/21/2005	LTN050	LOCHINVAR	\$ 850.00	
11994	Installed/Active	10/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
11995	Installed/Active	07/31/1989	FSG50	AO SMITH	\$ 850.00	
11996	Installed/Active	01/05/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
11997	Installed/Active	04/18/1989	PRX50	STATE	\$ 1,075.00	
11998	Installed/Active	10/28/1999	PGR50	AO SMITH	\$ 850.00	
11999	Installed/Active	08/08/1989	FSG50	AO SMITH	\$ 850.00	
12000	Installed/Active	12/14/2000	21V506	RHEEM	\$ 500.00	
12001	Installed/Active	11/09/2006	PR650	STATE	\$ 1,075.00	
12002	Installed/Active	03/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12003	Installed/Active	08/07/1997	PRV50NODS	STATE	\$ 1,075.00	
12004	Installed/Active	09/06/2001	PGR50	AO SMITH	\$ 850.00	
12005	Installed/Active	01/17/1989	PRX50	STATE	\$ 1,075.00	
12006	Installed/Active	01/23/2006	PR650	STATE	\$ 1,075.00	
12007	Installed/Active	08/25/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
12008	Installed/Active	10/26/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
12009	Installed/Active	03/31/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12010	Installed/Active	01/09/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12011	Installed/Active	02/06/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12012	Installed/Active	01/24/2005	GVC50	A. O. SMITH	\$ 850.00	
12013	Installed/Active	02/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
12014	Installed/Active	07/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12015	Installed/Active	08/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
12016	Installed/Active	01/06/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12017	Installed/Active	10/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12018	Installed/Active	01/08/2002	PGR50	AO SMITH	\$ 850.00	
12019	Installed/Active	03/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12020	Installed/Active	04/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
12021	Installed/Active	03/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
12022	Installed/Active	11/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
12023	Installed/Active	06/14/1989	FSG50	AO SMITH	\$ 850.00	
12024	Installed/Active	10/26/2006	PR650	STATE	\$ 1,075.00	
12025	Installed/Active	06/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12026	Installed/Active	03/05/1989	FSG50	AO SMITH	\$ 850.00	
12027	Installed/Active	12/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12028	Installed/Active	02/14/2003	PGR50	AO SMITH	\$ 850.00	
12029	Installed/Active	03/30/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12030	Installed/Active	08/30/1989	FSG50	AO SMITH	\$ 850.00	
12031	Installed/Active	11/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
12032	Installed/Active	04/08/1989	FSG50	AO SMITH	\$ 850.00	
12033	Installed/Active	05/08/1989	FSG50	AO SMITH	\$ 850.00	
12034	Installed/Active	11/24/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12035	Installed/Active	01/11/2004	FSG50	AO SMITH	\$ 850.00	
12036	Installed/Active	02/16/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
12037	Installed/Active	12/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12038	Installed/Active	03/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
12039	Installed/Active	10/10/2003	FSG50	AO SMITH	\$ 850.00	
12040	Installed/Active	08/12/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12041	Installed/Active	07/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
12042	Installed/Active	01/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12043	Installed/Active	12/23/2010	21V506	RHEEM	\$ 1,125.00	\$ 19.26
12044	Installed/Active	05/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12045	Installed/Active	03/19/2003	FSG50	AO SMITH	\$ 850.00	
12046	Installed/Active	11/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12047	Installed/Active	03/01/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
12048	Installed/Active	05/01/1992	21V502	RHEEM	\$ 850.00	
12049	Installed/Active	06/10/2005	GVC50	A. O. SMITH	\$ 850.00	
12050	Installed/Active	07/31/1992	FSG50	AO SMITH	\$ 850.00	
12051	Installed/Active	03/31/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12052	Installed/Active	11/03/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12053	Installed/Active	09/24/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12054	Installed/Active	08/05/1992	21V502	RHEEM	\$ 850.00	
12055	Installed/Active	01/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12056	Installed/Active	12/30/1992	21V502	RHEEM	\$ 850.00	
12057	Installed/Active	03/16/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
12058	Installed/Active	05/07/2009	LTN040	LOCHINVAR	\$ 850.00	\$ 11.74
12059	Installed/Active	01/15/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
12060	Installed/Active	11/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12061	Installed/Active	09/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12062	Installed/Active	11/22/2002	FSG50	AO SMITH	\$ 850.00	
12063	Installed/Active	01/11/2007	SBF100199NES	STATE	\$ 3,350.00	
12064	Installed/Active	06/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
12065	Installed/Active	03/04/2002	PGR50	AO SMITH	\$ 850.00	
12066	Installed/Active	11/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12067	Installed/Active	04/20/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
12068	Installed/Active	12/01/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12069	Installed/Active	06/18/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
12070	Installed/Active	02/03/1993	FSG40	AO SMITH	\$ 850.00	
12071	Installed/Active	05/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12072	Installed/Active	09/24/2005	LTN051	LOCHINVAR	\$ 1,150.00	
12073	Installed/Active	05/07/2002	PRX50	STATE	\$ 1,075.00	
12074	Installed/Active	04/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12075	Installed/Active	10/17/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12076	Installed/Active	11/17/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12077	Installed/Active	10/27/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
12078	Installed/Active	06/28/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
12079	Installed/Active	02/01/2002	FSG50	AO SMITH	\$ 850.00	
12080	Installed/Active	01/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
12081	Installed/Active	03/11/2002	FSGL40	AO SMITH	\$ 850.00	
12082	Installed/Active	04/04/2006	PR650	STATE	\$ 1,075.00	
12083	Installed/Active	07/09/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12084	Installed/Active	05/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
12085	Installed/Active	03/19/2005	XVR50	A. O. SMITH	\$ 1,150.00	
12086	Installed/Active	07/06/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12087	Installed/Active	05/13/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
12088	Installed/Active	05/23/2002	21DV50	RHEEM	\$ 1,075.00	
12089	Installed/Active	01/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12090	Installed/Active	10/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
12091	Installed/Active	03/27/1991	P506	RUUD	\$ 1,125.00	
12092	Installed/Active	01/23/2003	PRX50	STATE	\$ 1,075.00	
12093	Installed/Active	12/15/2005	LTN051G	LOCHINVAR	\$ 1,150.00	
12094	Installed/Active	04/28/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
12095	Installed/Active	08/22/2000	PRX50	STATE	\$ 1,075.00	
12096	Installed/Active	06/01/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12097	Installed/Active	10/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12098	Installed/Active	01/04/1991	21V506	RHEEM	\$ 1,150.00	
12099	Installed/Active	05/31/2006	LTN050G	LOCHINVAR	\$ 850.00	
12100	Installed/Active	01/23/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
12101	Installed/Active	08/02/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12102	Installed/Active	01/04/1991	21V506	RHEEM	\$ 1,150.00	
12103	Installed/Active	09/01/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
12104	Installed/Active	02/08/1991	FSG50	AO SMITH	\$ 850.00	
12105	Installed/Active	01/20/2003	FSG50	AO SMITH	\$ 850.00	
12106	Installed/Active	01/13/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12107	Installed/Active	04/02/1991	FSG50	AO SMITH	\$ 850.00	
12108	Installed/Active	03/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
12109	Installed/Active	05/29/1991	FSG50	AO SMITH	\$ 850.00	
12110	Installed/Active	07/17/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12111	Installed/Active	11/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
12112	Installed/Active	05/07/2005	LTN050	LOCHINVAR	\$ 850.00	
12113	Installed/Active	12/26/2007	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12114	Installed/Active	02/26/2004	FCV50	AO SMITH	\$ 850.00	
12115	Installed/Active	02/05/1991	BTR120	AO SMITH	\$ 1,900.00	
12116	Installed/Active	01/25/2002	FSGL40	AO SMITH	\$ 350.00	
12117	Installed/Active	03/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
12118	Installed/Active	02/27/2002	PGR50	AO SMITH	\$ 850.00	
12119	Installed/Active	03/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12120	Installed/Active	03/07/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12121	Installed/Active	12/13/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
12122	Installed/Active	05/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12123	Installed/Active	01/28/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
12124	Installed/Active	02/27/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12125	Installed/Active	12/05/2003	PVR50	AO SMITH	\$ 850.00	
12126	Installed/Active	08/15/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12127	Installed/Active	02/12/1991	PRX50	STATE	\$ 1,075.00	
12128	Installed/Active	02/14/1990	FSG50	AO SMITH	\$ 850.00	
12129	Installed/Active	01/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12130	Installed/Active	12/06/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12131	Installed/Active	06/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
12132	Installed/Active	09/16/2002	FSG40	AO SMITH	\$ 850.00	
12133	Installed/Active	11/08/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12134	Installed/Active	12/27/2004	GVC50	A. O. SMITH	\$ 850.00	
12135	Installed/Active	02/10/2010	21V502	RHEEM	\$ 850.00	\$ 11.74
12136	Installed/Active	01/03/2002	PRX50	STATE	\$ 1,075.00	
12137	Installed/Active	01/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
12138	Installed/Active	06/04/1998	FGR50	AO SMITH	\$ 850.00	
12139	Installed/Active	11/28/2003	PRX50	STATE	\$ 1,075.00	
12140	Installed/Active	03/06/1990	PH30	RUUD	\$ 350.00	
12141	Installed/Active	03/09/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
12142	Installed/Active	03/25/2005	GVC50	A. O. SMITH	\$ 850.00	
12143	Installed/Active	08/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
12144	Installed/Active	07/21/2012	MI75S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.64
12145	Installed/Active	07/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12146	Installed/Active	07/30/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12147	Installed/Active	11/26/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12148	Installed/Active	05/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12149	Installed/Active	09/13/2000	PRV50NODS	STATE	\$ 1,075.00	
12150	Installed/Active	01/11/2003	PRX50	STATE	\$ 1,075.00	
12151	Installed/Active	12/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12152	Installed/Active	03/31/2006	LTN040G	LOCHINVAR	\$ 850.00	
12153	Installed/Active	11/15/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12154	Installed/Active	02/26/1990	21V506	RHEEM	\$ 1,150.00	
12155	Installed/Active	12/10/2004	LTN050G	LOCHINVAR	\$ 850.00	
12156	Installed/Active	05/12/2004	XVR50	A. O. SMITH	\$ 850.00	
12157	Installed/Active	12/22/2005	GVC50	A. O. SMITH	\$ 850.00	
12158	Installed/Active	01/05/1990	FSG50	AO SMITH	\$ 850.00	
12159	Installed/Active	09/26/1999	41XR40	RHEEM	\$ 850.00	
12160	Installed/Active	03/18/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12161	Installed/Active	03/30/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
12162	Installed/Active	01/26/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
12163	Installed/Active	12/10/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12164	Installed/Active	06/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12165	Installed/Active	07/15/2000	41XR50	RHEEM	\$ 850.00	
12166	Installed/Active	01/19/2005	LTN040	LOCHINVAR	\$ 850.00	
12167	Installed/Active	03/25/2002	PRX50	STATE	\$ 1,075.00	
12168	Installed/Active	09/10/2010	PVR50	AO SMITH	\$ 850.00	\$ 12.05
12169	Installed/Active	11/02/1989	FSG50	AO SMITH	\$ 850.00	
12170	Installed/Active	03/24/2006	PR650	STATE	\$ 1,075.00	
12171	Installed/Active	12/07/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12172	Installed/Active	02/13/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
12173	Installed/Active	06/25/2001	PGR50	AO SMITH	\$ 850.00	
12174	Installed/Active	03/09/2004	21V506	RHEEM	\$ 1,150.00	
12175	Installed/Active	09/30/1999	41V50S	RHEEM	\$ 850.00	
12176	Installed/Active	02/27/2004	PRX50	STATE	\$ 1,075.00	
12177	Installed/Active	06/19/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12178	Installed/Active	03/17/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12179	Installed/Active	11/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
12180	Installed/Active	11/16/2002	PRX40	STATE	\$ 1,075.00	
12181	Installed/Active	11/15/2001	PGR50	AO SMITH	\$ 850.00	
12182	Installed/Active	02/12/2002	FSL40	AO SMITH	\$ 850.00	
12183	Installed/Active	08/06/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12184	Installed/Active	03/01/2005	41VR50	RHEEM	\$ 850.00	
12185	Installed/Active	05/16/2001	21V506	RHEEM	\$ 1,150.00	
12186	Installed/Active	10/18/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12187	Installed/Active	02/15/2001	41XR50	RHEEM	\$ 850.00	
12188	Installed/Active	01/02/2006	41VR50	RHEEM	\$ 850.00	
12189	Installed/Active	02/24/2005	21DV50	RHEEM	\$ 1,075.00	
12190	Installed/Active	07/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12191	Installed/Active	08/08/1989	FSG50	AO SMITH	\$ 850.00	
12192	Installed/Active	07/24/1998	FGR50	AO SMITH	\$ 850.00	
12193	Installed/Active	09/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12194	Installed/Active	05/16/2002	FSG50	AO SMITH	\$ 850.00	
12195	Installed/Active	08/17/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12196	Installed/Active	09/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12197	Installed/Active	10/28/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
12198	Installed/Active	02/27/2001	41XR50	RHEEM	\$ 850.00	
12199	Installed/Active	04/07/1995	PR502T	RUUD	\$ 850.00	
12200	Installed/Active	11/11/2012	PRV50NODS	STATE	\$ 1,075.00	\$ 17.89
12201	Installed/Active	01/30/1996	FGR50	AO SMITH	\$ 850.00	
12202	Installed/Active	10/11/1998	FGR50	AO SMITH	\$ 850.00	
12203	Installed/Active	07/30/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12204	Installed/Active	04/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12205	Installed/Active	06/29/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12206	Installed/Active	02/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12207	Installed/Active	05/17/2005	LTN040	LOCHINVAR	\$ 850.00	
12208	Installed/Active	11/20/2003	PVR50	AO SMITH	\$ 850.00	
12209	Installed/Active	10/30/2000	PGR50	AO SMITH	\$ 850.00	
12210	Installed/Active	10/04/2002	FSG50	AO SMITH	\$ 850.00	
12211	Installed/Active	02/25/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12212	Installed/Active	04/19/2002	PGR50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12213	Installed/Active	12/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12214	Installed/Active	09/08/2009	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
12215	Installed/Active	10/23/1990	FSG50	AO SMITH	\$ 850.00	
12216	Installed/Active	07/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12217	Installed/Active	12/26/2004	XVR50	A. O. SMITH	\$ 850.00	
12218	Installed/Active	02/04/2006	PR650	STATE	\$ 1,075.00	
12219	Installed/Active	05/02/1999	41VR50	RHEEM	\$ 850.00	
12220	Installed/Active	09/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12221	Installed/Active	03/29/1990	PRV50NODS	STATE	\$ 1,075.00	
12222	Installed/Active	04/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12223	Installed/Active	03/05/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12224	Installed/Active	01/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12225	Installed/Active	01/18/2006	PR650XODS	STATE	\$ 1,075.00	
12226	Installed/Active	06/25/2000	41XR50	RHEEM	\$ 850.00	
12227	Installed/Active	05/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12228	Installed/Active	09/27/2002	PGR50	AO SMITH	\$ 850.00	
12229	Installed/Active	12/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12230	Installed/Active	10/11/2003	PGR50	AO SMITH	\$ 850.00	
12231	Installed/Active	07/02/2005	PR650	STATE	\$ 1,075.00	
12232	Installed/Active	10/01/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12233	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
12234	Installed/Active	03/26/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
12235	Installed/Active	03/09/1990	FSG50	AO SMITH	\$ 850.00	
12236	Installed/Active	02/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12237	Installed/Active	03/24/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
12238	Installed/Active	02/26/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12239	Installed/Active	03/01/2005	PRX50	STATE	\$ 1,075.00	
12240	Installed/Active	01/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12241	Installed/Active	02/01/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
12242	Installed/Active	08/15/1991	FSG50	AO SMITH	\$ 850.00	
12243	Installed/Active	10/12/2002	PGR50	AO SMITH	\$ 1,150.00	
12244	Installed/Active	02/15/1991	FSG50	AO SMITH	\$ 850.00	
12245	Installed/Active	04/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12246	Installed/Active	02/03/2000	21V506	RHEEM	\$ 1,150.00	
12247	Installed/Active	12/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12248	Installed/Active	10/23/2000	PGR50	AO SMITH	\$ 850.00	
12249	Installed/Active	03/13/1997	FSG50	AO SMITH	\$ 850.00	
12250	Installed/Active	11/16/1990	FSG40	AO SMITH	\$ 850.00	
12251	Installed/Active	10/08/2011	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.37
12252	Installed/Active	01/10/2004	21DV50	RHEEM	\$ 1,075.00	
12253	Installed/Active	04/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12254	Installed/Active	07/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
12255	Installed/Active	04/12/2004	PRX50	STATE	\$ 1,075.00	
12256	Installed/Active	01/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12257	Installed/Active	10/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12258	Installed/Active	08/02/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12259	Installed/Active	09/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12260	Installed/Active	10/06/2005	LTN050G	LOCHINVAR	\$ 850.00	
12261	Installed/Active	07/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12262	Installed/Active	01/27/2005	GDVS50	AOSMITH	\$ 1,075.00	
12263	Installed/Active	06/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12264	Installed/Active	11/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12265	Installed/Active	02/17/2006	PR650	STATE	\$ 1,075.00	
12266	Installed/Active	11/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12267	Installed/Active	03/02/2006	LTN050G	LOCHINVAR	\$ 1,125.00	
12268	Installed/Active	09/14/2004	GVC50	A. O. SMITH	\$ 850.00	
12269	Installed/Active	08/27/1998	PHR50	RUUD	\$ 850.00	
12270	Installed/Active	05/15/2005	LTN050	LOCHINVAR	\$ 850.00	
12271	Installed/Active	12/06/2006	PR650	STATE	\$ 1,075.00	
12272	Installed/Active	11/12/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12273	Installed/Active	07/21/2001	21V407	RHEEM	\$ 850.00	
12274	Installed/Active	01/27/1992	P506	RUUD	\$ 1,125.00	
12275	Installed/Active	01/15/1991	FSG50	AO SMITH	\$ 850.00	
12276	Installed/Active	03/01/2002	PGR50	AO SMITH	\$ 850.00	
12277	Installed/Active	04/01/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12278	Installed/Active	09/03/2002	PGR50	AO SMITH	\$ 850.00	
12279	Installed/Active	05/23/1991	21V502	RHEEM	\$ 850.00	
12280	Installed/Active	10/19/2007	ETN076	LOCHINVAR	\$ 1,900.00	\$ 33.40
12281	Installed/Active	08/11/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12282	Installed/Active	02/08/1991	FSG40	AO SMITH	\$ 850.00	
12283	Installed/Active	04/16/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
12284	Installed/Active	07/05/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
12285	Installed/Active	05/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12286	Installed/Active	02/25/1992	PRX50	STATE	\$ 1,075.00	
12287	Installed/Active	06/30/1992	PRX40	STATE	\$ 1,075.00	
12288	Installed/Active	05/27/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
12289	Installed/Active	08/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
12290	Installed/Active	09/29/2006	LTN050G	LOCHINVAR	\$ 850.00	
12291	Installed/Active	03/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12292	Installed/Active	05/16/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
12293	Installed/Active	02/02/2004	G82156	RUUD/RHEEM	\$ 3,350.00	
12294	Installed/Active	03/21/2002	PGR50	AO SMITH	\$ 850.00	
12295	Installed/Active	08/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12296	Installed/Active	07/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12297	Installed/Active	12/07/2010	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
12298	Installed/Active	02/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12299	Installed/Active	01/29/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12300	Installed/Active	12/20/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12301	Installed/Active	05/06/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12302	Installed/Active	10/01/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12303	Installed/Active	05/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12304	Installed/Active	04/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12305	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12306	Installed/Active	02/22/2003	FSG50	AO SMITH	\$ 850.00	
12307	Installed/Active	06/08/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
12308	Installed/Active	04/24/2004	XTN050	LOCHINVAR	\$ 850.00	
12309	Installed/Active	12/03/2006	FSG50	AO SMITH	\$ 850.00	
12310	Installed/Active	04/01/2010	LTN030G	AO SMITH	\$ 850.00	\$ 11.74
12311	Installed/Active	10/05/1992	RF67120	RUUD	\$ 1,900.00	
12312	Installed/Active	10/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12313	Installed/Active	01/25/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
12314	Installed/Active	12/23/1992	FSGL40	AO SMITH	\$ 350.00	
12315	Installed/Active	10/07/1992	PRX50	STATE	\$ 1,075.00	
12316	Installed/Active	02/02/2006	PR640	STATE	\$ 1,075.00	
12317	Installed/Active	08/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12318	Installed/Active	03/11/1992	G82156	RUUD/RHEEM	\$ 3,350.00	
12319	Installed/Active	05/23/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12320	Installed/Active	07/26/2003	FSG50	AO SMITH	\$ 850.00	
12321	Installed/Active	05/22/1992	21V502	RHEEM	\$ 850.00	
12322	Installed/Active	11/01/2004	PRX50	STATE	\$ 1,075.00	
12323	Installed/Active	06/23/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12324	Installed/Active	02/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12325	Installed/Active	06/07/2005	21V506	RHEEM	\$ 1,150.00	
12326	Installed/Active	12/03/1992	FSG50	AO SMITH	\$ 850.00	
12327	Installed/Active	07/15/2004	XVR50	A. O. SMITH	\$ 850.00	
12328	Installed/Active	01/15/1992	FSG50	AO SMITH	\$ 850.00	
12329	Installed/Active	01/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12330	Installed/Active	03/02/2001	PGR50	AO SMITH	\$ 850.00	
12331	Installed/Active	03/28/2001	FSG40	AO SMITH	\$ 850.00	
12332	Installed/Active	01/13/2004	PVR50	AO SMITH	\$ 850.00	
12333	Installed/Active	03/16/1997	FGR50	AO SMITH	\$ 850.00	
12334	Installed/Active	07/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12335	Installed/Active	04/29/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.55
12336	Installed/Active	12/05/2005	LTN050G	LOCHINVAR	\$ 850.00	
12337	Installed/Active	02/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12338	Installed/Active	10/26/2010	21V506	RHEEM	\$ 1,150.00	\$ 16.55
12339	Installed/Active	04/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12340	Installed/Active	03/18/1993	FSG50	AO SMITH	\$ 850.00	
12341	Installed/Active	09/18/2004	21V506	RHEEM	\$ 1,150.00	
12342	Installed/Active	07/15/2010	22V50F1	RHEEM	\$ 850.00	\$ 12.05
12343	Installed/Active	01/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12344	Installed/Active	05/22/1997	FGR50	AO SMITH	\$ 850.00	
12345	Installed/Active	06/14/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12346	Installed/Active	04/20/1990	PRV50NODS	STATE	\$ 1,075.00	
12347	Installed/Active	03/28/2005	21V506	RHEEM	\$ 1,150.00	
12348	Installed/Active	07/10/2000	FSG50	AO SMITH	\$ 850.00	
12349	Installed/Active	10/19/1990	FSGL40	AO SMITH	\$ 850.00	
12350	Installed/Active	10/21/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12351	Installed/Active	10/19/2011	M45036FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
12352	Installed/Active	01/26/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
12353	Installed/Active	04/15/1999	FSG50	AO SMITH	\$ 850.00	
12354	Installed/Active	01/14/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12355	Installed/Active	04/06/2001	41XR50	RHEEM	\$ 850.00	
12356	Installed/Active	07/17/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
12357	Installed/Active	08/03/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12358	Installed/Active	11/07/2003	PRX50	STATE	\$ 1,075.00	
12359	Installed/Active	02/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12360	Installed/Active	06/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
12361	Installed/Active	11/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
12362	Installed/Active	10/21/1999	41XR50	RHEEM	\$ 850.00	
12363	Installed/Active	08/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
12364	Installed/Active	05/17/2000	41XR50	RHEEM	\$ 850.00	
12365	Installed/Active	10/29/2000	41XR50	RHEEM	\$ 850.00	
12366	Installed/Active	12/22/2004	42XR50	RHEEM	\$ 850.00	
12367	Installed/Active	03/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12368	Installed/Active	02/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12369	Installed/Active	08/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12370	Installed/Active	01/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12371	Installed/Active	01/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12372	Installed/Active	09/06/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12373	Installed/Active	06/04/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12374	Installed/Active	05/19/2003	PRX50	STATE	\$ 1,075.00	
12375	Installed/Active	03/10/2005	XVR50	A. O. SMITH	\$ 850.00	
12376	Installed/Active	08/29/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12377	Installed/Active	12/31/2006	P506	RUUD	\$ 1,150.00	
12378	Installed/Active	11/02/2005	H72DUMMY	AO SMITH	\$ 1,900.00	
12379	Installed/Active	01/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12380	Installed/Active	04/21/2004	XTN050	LOCHINVAR	\$ 850.00	
12381	Installed/Active	12/06/1989	P505	RUUD	\$ 1,125.00	
12382	Installed/Active	03/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12383	Installed/Active	05/08/1989	FSG50	AO SMITH	\$ 850.00	
12384	Installed/Active	01/24/2003	21DV50	RHEEM	\$ 1,075.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12385	Installed/Active	06/09/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
12386	Installed/Active	01/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12387	Installed/Active	06/16/2005	LTN050	LOCHINVAR	\$ 850.00	
12388	Installed/Active	08/21/2004	42XR50	RHEEM	\$ 850.00	
12389	Installed/Active	08/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12390	Installed/Active	07/31/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12391	Installed/Active	02/11/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
12392	Installed/Active	12/22/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12393	Installed/Active	07/15/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
12394	Installed/Active	04/10/2005	PRX50	STATE	\$ 1,075.00	
12395	Installed/Active	05/24/2010	D74DUMMY	AO SMITH	\$ 1,900.00	\$ 39.36
12396	Installed/Active	10/28/2005	LTN050G	LOCHINVAR	\$ 1,150.00	
12397	Installed/Active	03/28/2003	21DV50	RHEEM	\$ 1,075.00	
12398	Installed/Active	10/28/1993	P506	RUUD	\$ 1,150.00	
12399	Installed/Active	12/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12400	Installed/Active	11/13/2000	FSG50	AO SMITH	\$ 850.00	
12401	Installed/Active	08/16/1989	FSG50	AO SMITH	\$ 850.00	
12402	Installed/Active	11/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12403	Installed/Active	12/09/1997	PGR50	AO SMITH	\$ 850.00	
12404	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12405	Installed/Active	05/22/2007	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 14.05
12406	Installed/Active	03/09/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12407	Installed/Active	10/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
12408	Installed/Active	10/31/2008	PRV50NODS	STATE	\$ 1,075.00	\$ 14.35
12409	Installed/Active	01/31/1990	FSG50	AO SMITH	\$ 850.00	
12410	Installed/Active	07/11/1995	PHR50	RUUD	\$ 850.00	
12411	Installed/Active	02/25/2005	21DV50	RHEEM	\$ 1,075.00	
12412	Installed/Active	07/14/2008	42VR50	RHEEM	\$ 850.00	\$ 10.23
12413	Installed/Active	01/23/1990	FSG50	AO SMITH	\$ 850.00	
12414	Installed/Active	09/06/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
12415	Installed/Active	02/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12416	Installed/Active	11/24/2010	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
12417	Installed/Active	05/20/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
12418	Installed/Active	11/07/2001	41VR50	RHEEM	\$ 850.00	
12419	Installed/Active	05/22/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12420	Installed/Active	05/05/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12421	Installed/Active	06/22/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
12422	Installed/Active	01/15/1990	21V506	RHEEM	\$ 1,150.00	
12423	Installed/Active	04/28/2008	LTN051	LOCHINVAR	\$ 1,150.00	\$ 14.05
12424	Installed/Active	01/28/1999	41VR50	RHEEM	\$ 850.00	
12425	Installed/Active	02/20/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 10.23
12426	Installed/Active	09/14/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
12427	Installed/Active	01/22/1990	21V506	RHEEM	\$ 1,150.00	
12428	Installed/Active	09/14/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
12429	Installed/Active	04/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
12430	Installed/Active	10/28/1996	FSG50	AO SMITH	\$ 850.00	
12431	Installed/Active	09/27/2001	PRX50	STATE	\$ 1,075.00	
12432	Installed/Active	10/02/2002	PGR50	AO SMITH	\$ 850.00	
12433	Installed/Active	11/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12434	Installed/Active	06/19/2002	PGR50	AO SMITH	\$ 850.00	
12435	Installed/Active	02/25/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
12436	Installed/Active	06/06/1997	FSG50	AO SMITH	\$ 850.00	
12437	Installed/Active	12/27/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
12438	Installed/Active	01/13/2000	FSGL40	AO SMITH	\$ 850.00	
12439	Installed/Active	11/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12440	Installed/Active	04/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12441	Installed/Active	07/06/2006	PR650	STATE	\$ 1,075.00	
12442	Installed/Active	09/17/2002	21V506	RHEEM	\$ 1,150.00	
12443	Installed/Active	03/10/1993	FSG40	AO SMITH	\$ 850.00	
12444	Installed/Active	05/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12445	Installed/Active	05/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
12446	Installed/Active	06/01/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
12447	Installed/Active	11/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
12448	Installed/Active	03/10/1993	FSG50	AO SMITH	\$ 850.00	
12449	Installed/Active	01/06/2011	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
12450	Installed/Active	02/05/1999	42VR50	RHEEM	\$ 850.00	
12451	Installed/Active	04/03/2000	FSG50	AO SMITH	\$ 850.00	
12452	Installed/Active	04/11/2006	PR650	STATE	\$ 1,075.00	
12453	Installed/Active	07/06/2000	PRX50	STATE	\$ 1,075.00	
12454	Installed/Active	08/23/1999	PRV50NODS	STATE	\$ 1,075.00	
12455	Installed/Active	04/11/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12456	Installed/Active	05/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12457	Installed/Active	01/12/2002	FSG40	AO SMITH	\$ 850.00	
12458	Installed/Active	01/07/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12459	Installed/Active	11/17/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
12460	Installed/Active	08/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
12461	Installed/Active	02/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12462	Installed/Active	08/21/2002	PRX50	STATE	\$ 1,075.00	
12463	Installed/Active	11/14/2000	41VR50	RHEEM	\$ 850.00	
12464	Installed/Active	02/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12465	Installed/Active	12/13/1991	FSG50	AO SMITH	\$ 850.00	
12466	Installed/Active	11/09/1992	21V502	RHEEM	\$ 850.00	
12467	Installed/Active	03/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
12468	Installed/Active	02/13/1992	FSG50	AO SMITH	\$ 850.00	
12469	Installed/Active	03/26/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12470	Installed/Active	08/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12471	Installed/Active	05/09/2002	FSGL40	AO SMITH	\$ 850.00	
12472	Installed/Active	09/12/2002	41V40S	RHEEM	\$ 850.00	
12473	Installed/Active	03/21/2009	ETN076	LOCHINVAR	\$ 1,900.00	\$ 29.38
12474	Installed/Active	02/16/2005	GVR50	AO SMITH	\$ 850.00	
12475	Installed/Active	04/10/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
12476	Installed/Active	05/23/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12477	Installed/Active	02/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12478	Installed/Active	01/25/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
12479	Installed/Active	02/03/1993	FSG50	AO SMITH	\$ 850.00	
12480	Installed/Active	04/16/2004	PVR50	AO SMITH	\$ 850.00	
12481	Installed/Active	09/07/1993	21V506	RHEEM	\$ 1,150.00	
12482	Installed/Active	06/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12483	Installed/Active	02/11/2001	41XR50	RHEEM	\$ 850.00	
12484	Installed/Active	11/27/2000	41V50	RHEEM	\$ 850.00	
12485	Installed/Active	10/15/2003	21DV50	RHEEM	\$ 1,075.00	
12486	Installed/Active	01/18/2000	FSG40	AO SMITH	\$ 850.00	
12487	Installed/Active	07/15/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
12488	Installed/Active	08/31/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12489	Installed/Active	11/19/1998	FGR40	AO SMITH	\$ 850.00	
12490	Installed/Active	12/10/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12491	Installed/Active	05/22/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
12492	Installed/Active	04/25/2000	PGR50	AO SMITH	\$ 850.00	
12493	Installed/Active	10/30/1991	FSG50	AO SMITH	\$ 850.00	
12494	Installed/Active	07/22/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
12495	Installed/Active	08/04/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
12496	Installed/Active	11/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12497	Installed/Active	04/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
12498	Installed/Active	04/15/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
12499	Installed/Active	07/12/2005	PR650	STATE	\$ 1,075.00	
12500	Installed/Active	01/29/2001	FSG50	AO SMITH	\$ 850.00	
12501	Installed/Active	03/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
12502	Installed/Active	03/22/2002	PGR50	AO SMITH	\$ 850.00	
12503	Installed/Active	11/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12504	Installed/Active	04/15/1991	P506	RUUD	\$ 1,150.00	
12505	Installed/Active	12/12/1991	FSG50	AO SMITH	\$ 850.00	
12506	Installed/Active	08/06/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12507	Installed/Active	07/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12508	Installed/Active	03/16/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
12509	Installed/Active	09/12/2001	FSG50	AO SMITH	\$ 850.00	
12510	Installed/Active	01/18/2002	FSG40	AO SMITH	\$ 850.00	
12511	Installed/Active	10/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12512	Installed/Active	07/01/2010	41V50	RHEEM	\$ 850.00	\$ 12.05
12513	Installed/Active	01/18/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12514	Installed/Active	01/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12515	Installed/Active	04/19/2005	GCVL40	A. O. SMITH	\$ 850.00	
12516	Installed/Active	09/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12517	Installed/Active	10/05/2004	GVC50	A. O. SMITH	\$ 850.00	
12518	Installed/Active	02/03/2005	PRX50	STATE	\$ 1,075.00	
12519	Installed/Active	10/09/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12520	Installed/Active	09/03/2003	PRX50	STATE	\$ 1,075.00	
12521	Installed/Active	10/01/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
12522	Installed/Active	09/03/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
12523	Installed/Active	09/12/2000	41V40S	RHEEM	\$ 850.00	
12524	Installed/Active	04/01/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12525	Installed/Active	04/07/2005	PRX50	STATE	\$ 1,075.00	
12526	Installed/Active	05/29/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12527	Installed/Active	11/25/1990	FSG50	AO SMITH	\$ 850.00	
12528	Installed/Active	10/23/2000	PGR50	AO SMITH	\$ 850.00	
12529	Installed/Active	09/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
12530	Installed/Active	01/25/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12531	Installed/Active	10/24/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12532	Installed/Active	04/08/2003	21V506	RHEEM	\$ 1,150.00	
12533	Installed/Active	10/25/1993	FSG50	AO SMITH	\$ 850.00	
12534	Installed/Active	03/01/2004	PVR50	AO SMITH	\$ 850.00	
12535	Installed/Active	02/21/1991	FSG50	AO SMITH	\$ 850.00	
12536	Installed/Active	10/10/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12537	Installed/Active	04/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12538	Installed/Active	08/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12539	Installed/Active	01/23/2002	FSGL40	AO SMITH	\$ 850.00	
12540	Installed/Active	05/13/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
12541	Installed/Active	08/08/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
12542	Installed/Active	09/19/2005	XSN040GEF	LOCHINVAR	\$ 850.00	
12543	Installed/Active	09/20/2002	FSG50	AO SMITH	\$ 850.00	
12544	Installed/Active	01/03/2011	42VR5040F	RHEEM	\$ 850.00	\$ 12.05
12545	Installed/Active	03/22/1990	FSG50	AO SMITH	\$ 850.00	
12546	Installed/Active	01/03/2002	FSG50	AO SMITH	\$ 850.00	
12547	Installed/Active	09/13/2001	PGR50	AO SMITH	\$ 850.00	
12548	Installed/Active	04/21/2001	21V506	RHEEM	\$ 1,150.00	
12549	Installed/Active	12/16/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12550	Installed/Active	10/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12551	Installed/Active	01/08/2000	FSG50	AO SMITH	\$ 850.00	
12552	Installed/Active	06/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12553	Installed/Active	12/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12554	Installed/Active	02/14/2006	PR650	STATE	\$ 1,075.00	
12555	Installed/Active	01/09/2013	P230F	RUUD	\$ 850.00	\$ 12.75
12556	Installed/Active	03/18/2005	42VR506	RHEEM	\$ 1,150.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12557	Installed/Active	03/05/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
12558	Installed/Active	07/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12559	Installed/Active	10/14/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
12560	Installed/Active	09/08/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
12561	Installed/Active	01/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
12562	Installed/Active	01/04/2007	LTN050G	LOCHINVAR	\$ 850.00	
12563	Installed/Active	12/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12564	Installed/Active	09/02/2004	GDVS50	AOSMITH	\$ 1,075.00	
12565	Installed/Active	04/12/2012	22DV50F	RHEEM	\$ 1,075.00	\$ 11.11
12566	Installed/Active	02/02/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
12567	Installed/Active	03/23/2012	M175S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.30
12568	Installed/Active	06/26/2002	FSG50	AO SMITH	\$ 850.00	
12569	Installed/Active	02/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12570	Installed/Active	10/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
12571	Installed/Active	11/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12572	Installed/Active	12/21/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
12573	Installed/Active	09/18/2004	GVC40	A. O. SMITH	\$ 850.00	
12574	Installed/Active	04/23/2001	FSG40	AO SMITH	\$ 850.00	
12575	Installed/Active	12/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12576	Installed/Active	01/26/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12577	Installed/Active	02/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12578	Installed/Active	02/12/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
12579	Installed/Active	05/08/2000	PGR50	AO SMITH	\$ 850.00	
12580	Installed/Active	08/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12581	Installed/Active	05/10/1996	PGR50	AO SMITH	\$ 850.00	
12582	Installed/Active	02/05/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
12583	Installed/Active	08/05/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
12584	Installed/Active	11/06/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
12585	Installed/Active	08/31/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12586	Installed/Active	02/28/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
12587	Installed/Active	08/28/2000	41XR50	RHEEM	\$ 850.00	
12588	Installed/Active	04/20/2004	FSG50	AO SMITH	\$ 850.00	
12589	Installed/Active	12/10/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12590	Installed/Active	04/26/2005	LTN050	LOCHINVAR	\$ 850.00	
12591	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12592	Installed/Active	04/10/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12593	Installed/Active	04/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12594	Installed/Active	09/22/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12595	Installed/Active	07/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
12596	Installed/Active	11/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
12597	Installed/Active	06/05/1989	FSG50	AO SMITH	\$ 850.00	
12598	Installed/Active	09/25/1999	FSG50	AO SMITH	\$ 850.00	
12599	Installed/Active	08/21/2001	FSG50	AO SMITH	\$ 850.00	
12600	Installed/Active	09/06/2000	PGR50	AO SMITH	\$ 850.00	
12601	Installed/Active	10/27/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12602	Installed/Active	11/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
12603	Installed/Active	02/08/1989	F72DUMMY	AO SMITH	\$ 3,350.00	
12604	Installed/Active	07/11/1989	FSG50	AO SMITH	\$ 850.00	
12605	Installed/Active	10/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12606	Installed/Active	09/24/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12607	Installed/Active	05/05/2005	LTN050	LOCHINVAR	\$ 850.00	
12608	Installed/Active	09/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12609	Installed/Active	06/03/2011	H72DUMMY	AO SMITH	\$ 1,900.00	\$ 41.30
12610	Installed/Active	10/31/2002	PRX50	STATE	\$ 1,075.00	
12611	Installed/Active	02/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12612	Installed/Active	09/28/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12613	Installed/Active	10/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12614	Installed/Active	06/25/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12615	Installed/Active	10/19/2010	21VR50	RHEEM	\$ 850.00	\$ 16.91
12616	Installed/Active	02/13/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
12617	Installed/Active	11/07/1996	PGR40	AO SMITH	\$ 850.00	
12618	Installed/Active	11/20/2006	FSG50	AO SMITH	\$ 850.00	
12619	Installed/Active	11/27/2002	FSG50	AO SMITH	\$ 850.00	
12620	Installed/Active	05/17/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
12621	Installed/Active	11/14/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12622	Installed/Active	12/02/1991	PRX50	STATE	\$ 1,075.00	
12623	Installed/Active	04/08/2006	LTN050G	LOCHINVAR	\$ 850.00	
12624	Installed/Active	09/30/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
12625	Installed/Active	05/23/2000	41XR50	RHEEM	\$ 850.00	
12626	Installed/Active	04/15/2002	FSG50	AO SMITH	\$ 850.00	
12627	Installed/Active	01/23/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
12628	Installed/Active	09/05/2004	GVC50	A. O. SMITH	\$ 850.00	
12629	Installed/Active	01/09/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12630	Installed/Active	06/19/1992	FSG40	AO SMITH	\$ 850.00	
12631	Installed/Active	02/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12632	Installed/Active	01/09/1992	G67114	RHEEM	\$ 1,900.00	
12633	Installed/Active	01/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12634	Installed/Active	03/11/2002	FSG50	AO SMITH	\$ 850.00	
12635	Installed/Active	04/01/2002	PGR50	AO SMITH	\$ 850.00	
12636	Installed/Active	04/15/2004	PRX50	STATE	\$ 1,075.00	
12637	Installed/Active	01/08/2001	PRX40	STATE	\$ 1,075.00	
12638	Installed/Active	12/03/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12639	Installed/Active	10/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12640	Installed/Active	08/29/2000	PGR50	AO SMITH	\$ 850.00	
12641	Installed/Active	04/20/2003	FSG50	AO SMITH	\$ 850.00	
12642	Installed/Active	06/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12643	Installed/Active	03/28/2005	PRX50	STATE	\$ 1,075.00	
12644	Installed/Active	06/23/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12645	Installed/Active	10/24/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
12646	Installed/Active	10/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
12647	Installed/Active	07/02/2008	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 14.05
12648	Installed/Active	12/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12649	Installed/Active	01/12/2004	XTN050	LOCHINVAR	\$ 850.00	
12650	Installed/Active	12/30/2004	PRX50	STATE	\$ 1,075.00	
12651	Installed/Active	06/03/2010	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 19.26
12652	Installed/Active	06/23/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
12653	Installed/Active	10/25/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12654	Installed/Active	08/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12655	Installed/Active	06/07/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12656	Installed/Active	12/02/2005	LTN050G	LOCHINVAR	\$ 850.00	
12657	Installed/Active	08/06/1992	21V502	RHEEM	\$ 850.00	
12658	Installed/Active	01/31/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
12659	Installed/Active	12/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12660	Installed/Active	04/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12661	Installed/Active	09/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12662	Installed/Active	01/21/2004	PRX50	STATE	\$ 1,075.00	
12663	Installed/Active	06/02/2000	PGR50	AO SMITH	\$ 850.00	
12664	Installed/Active	04/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
12665	Installed/Active	08/05/2003	FSG50	AO SMITH	\$ 850.00	
12666	Installed/Active	07/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12667	Installed/Active	11/23/2004	GCVL40	A. O. SMITH	\$ 850.00	
12668	Installed/Active	05/08/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12669	Installed/Active	07/09/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12670	Installed/Active	08/09/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
12671	Installed/Active	04/27/1999	21V506	RHEEM	\$ 1,150.00	
12672	Installed/Active	12/05/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12673	Installed/Active	02/09/1998	41V40S	RHEEM	\$ 850.00	
12674	Installed/Active	02/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12675	Installed/Active	06/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
12676	Installed/Active	01/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12677	Installed/Active	01/14/2003	21DV50	RHEEM	\$ 1,075.00	
12678	Installed/Active	11/04/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12679	Installed/Active	10/06/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12680	Installed/Active	06/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
12681	Installed/Active	03/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12682	Installed/Active	03/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
12683	Installed/Active	03/23/2001	FSGL40	AO SMITH	\$ 850.00	
12684	Installed/Active	12/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12685	Installed/Active	01/26/2013	M45036FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
12686	Installed/Active	07/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12687	Installed/Active	01/20/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12688	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
12689	Installed/Active	07/31/1991	FSGL40	AO SMITH	\$ 850.00	
12690	Installed/Active	02/20/1991	BTR120	AO SMITH	\$ 1,900.00	
12691	Installed/Active	11/24/2001	FGR50	AO SMITH	\$ 850.00	
12692	Installed/Active	12/05/2002	PGR50	AO SMITH	\$ 850.00	
12693	Installed/Active	11/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12694	Installed/Active	09/08/2004	GVC50	A. O. SMITH	\$ 850.00	
12695	Installed/Active	11/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
12696	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12697	Installed/Active	10/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12698	Installed/Active	05/16/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
12699	Installed/Active	02/16/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12700	Installed/Active	08/27/2009	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
12701	Installed/Active	04/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12702	Installed/Active	01/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12703	Installed/Active	05/29/2000	PHR50	RUUD	\$ 850.00	
12704	Installed/Active	01/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
12705	Installed/Active	11/12/2004	PRX50	STATE	\$ 1,075.00	
12706	Installed/Active	11/25/1991	FSG50	AO SMITH	\$ 850.00	
12707	Installed/Active	12/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12708	Installed/Active	10/05/1989	FSG50	AO SMITH	\$ 850.00	
12709	Installed/Active	05/19/2002	PGR50	AO SMITH	\$ 850.00	
12710	Installed/Active	10/15/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12711	Installed/Active	02/07/2004	FCV50	AO SMITH	\$ 850.00	
12712	Installed/Active	09/08/2004	XVR50	A. O. SMITH	\$ 850.00	
12713	Installed/Active	05/29/1997	21VR502T	RHEEM	\$ 850.00	
12714	Installed/Active	05/05/2005	LTN050	LOCHINVAR	\$ 850.00	
12715	Installed/Active	02/15/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
12716	Installed/Active	11/16/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12717	Installed/Active	12/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12718	Installed/Active	07/16/2001	FSG50	AO SMITH	\$ 850.00	
12719	Installed/Active	07/09/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12720	Installed/Active	01/20/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12721	Installed/Active	05/26/2004	GVC50	A. O. SMITH	\$ 850.00	
12722	Installed/Active	03/23/2010	FSG50	AO SMITH	\$ 850.00	\$ 11.74
12723	Installed/Active	03/26/2001	41XR50	RHEEM	\$ 850.00	
12724	Installed/Active	09/27/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12725	Installed/Active	12/27/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12726	Installed/Active	11/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
12727	Installed/Active	01/08/2002	PGR50	AO SMITH	\$ 850.00	
12728	Installed/Active	08/30/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12729	Installed/Active	05/24/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
12730	Installed/Active	07/07/2004	FSG50	AO SMITH	\$ 850.00	
12731	Installed/Active	12/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12732	Installed/Active	01/24/2013	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
12733	Installed/Active	01/14/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
12734	Installed/Active	08/01/1989	FSG50	AO SMITH	\$ 850.00	
12735	Installed/Active	09/29/1989	FSG50	AO SMITH	\$ 850.00	
12736	Installed/Active	10/12/2000	FSG50	AO SMITH	\$ 850.00	
12737	Installed/Active	11/27/2004	GVC50	A. O. SMITH	\$ 850.00	
12738	Installed/Active	10/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12739	Installed/Active	11/06/2007	PR640	STATE	\$ 1,075.00	\$ 14.35
12740	Installed/Active	09/14/2001	21V506	RHEEM	\$ 1,150.00	
12741	Installed/Active	04/22/1998	FGR50	AO SMITH	\$ 850.00	
12742	Installed/Active	07/02/2003	FSGL40	AO SMITH	\$ 850.00	
12743	Installed/Active	10/25/2006	LSN041G	LOCHINVAR	\$ 850.00	
12744	Installed/Active	12/01/2006	LSN041G	LOCHINVAR	\$ 850.00	
12745	Installed/Active	03/07/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12746	Installed/Active	06/13/1989	FSG50	AO SMITH	\$ 850.00	
12747	Installed/Active	11/27/2003	PRX50	STATE	\$ 1,075.00	
12748	Installed/Active	04/25/2002	PRX50	STATE	\$ 1,075.00	
12749	Installed/Active	10/11/2004	XVR50	A. O. SMITH	\$ 850.00	
12750	Installed/Active	01/07/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
12751	Installed/Active	01/27/2005	GVC50	A. O. SMITH	\$ 850.00	
12752	Installed/Active	10/12/2011	M15036FBN	Bradford-White	\$ 850.00	\$ 12.64
12753	Installed/Active	08/09/1989	21V506	RHEEM	\$ 1,150.00	
12754	Installed/Active	06/17/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12755	Installed/Active	11/17/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12756	Installed/Active	08/05/2003	41V50S	RHEEM	\$ 850.00	
12757	Installed/Active	01/26/2011	21VR50	RHEEM	\$ 1,150.00	\$ 16.55
12758	Installed/Active	12/13/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12759	Installed/Active	10/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12760	Installed/Active	07/18/2004	XTN050	LOCHINVAR	\$ 850.00	
12761	Installed/Active	09/12/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12762	Installed/Active	02/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12763	Installed/Active	02/05/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
12764	Installed/Active	03/08/2004	PRX50	STATE	\$ 1,075.00	
12765	Installed/Active	06/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12766	Installed/Active	08/06/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
12767	Installed/Active	07/29/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12768	Installed/Active	10/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12769	Installed/Active	03/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
12770	Installed/Active	11/22/2004	GVC40	A. O. SMITH	\$ 850.00	
12771	Installed/Active	03/24/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
12772	Installed/Active	11/20/2012	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
12773	Installed/Active	02/15/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12774	Installed/Active	12/29/1992	P506	RUUD	\$ 1,125.00	
12775	Installed/Active	12/26/2002	FSG50	AO SMITH	\$ 850.00	
12776	Installed/Active	02/22/2006	PR650	STATE	\$ 1,075.00	
12777	Installed/Active	12/29/1992	P506	RUUD	\$ 1,125.00	
12778	Installed/Active	02/06/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
12779	Installed/Active	05/09/2007	FSG30	AO SMITH	\$ 850.00	\$ 10.23
12780	Installed/Active	12/26/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12781	Installed/Active	12/19/2001	PGR50	AO SMITH	\$ 850.00	
12782	Installed/Active	01/19/1993	FSG50	AO SMITH	\$ 850.00	
12783	Installed/Active	06/22/2001	FSG50	AO SMITH	\$ 850.00	
12784	Installed/Active	10/07/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12785	Installed/Active	10/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12786	Installed/Active	05/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12787	Installed/Active	07/19/2000	PHR40	RUUD	\$ 850.00	
12788	Installed/Active	06/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12789	Installed/Active	06/17/1992	FSG50	AO SMITH	\$ 850.00	
12790	Installed/Active	08/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12791	Installed/Active	08/10/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12792	Installed/Active	03/04/2008	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
12793	Installed/Active	07/23/1998	G67114	RHEEM	\$ 1,900.00	
12794	Installed/Active	09/27/2004	PRX50	STATE	\$ 1,075.00	
12795	Installed/Active	10/18/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
12796	Installed/Active	02/06/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12797	Installed/Active	11/18/2004	21V506	RHEEM	\$ 1,150.00	
12798	Installed/Active	12/29/1992	PRV50NODS	STATE	\$ 1,075.00	
12799	Installed/Active	05/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12800	Installed/Active	10/08/2006	PR650	STATE	\$ 1,075.00	
12801	Installed/Active	01/25/2004	XTN050	LOCHINVAR	\$ 850.00	
12802	Installed/Active	03/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12803	Installed/Active	10/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12804	Installed/Active	11/13/1992	FSG50	AO SMITH	\$ 850.00	
12805	Installed/Active	02/05/2003	PRX40	STATE	\$ 1,075.00	
12806	Installed/Active	06/02/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12807	Installed/Active	04/07/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
12808	Installed/Active	05/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12809	Installed/Active	09/06/2009	21VR50	RHEEM	\$ 850.00	\$ 11.74
12810	Installed/Active	05/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
12811	Installed/Active	03/08/2002	FSG50	AO SMITH	\$ 850.00	
12812	Installed/Active	09/24/1999	PHR50	RUUD	\$ 850.00	
12813	Installed/Active	11/08/1990	BTR197	AO SMITH	\$ 3,350.00	
12814	Installed/Active	05/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12815	Installed/Active	01/29/2003	PRX50	STATE	\$ 1,075.00	
12816	Installed/Active	08/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
12817	Installed/Active	05/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12818	Installed/Active	01/30/1999	FSG40	AO SMITH	\$ 850.00	
12819	Installed/Active	04/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12820	Installed/Active	02/01/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12821	Installed/Active	08/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12822	Installed/Active	01/05/2009	PGR30	AO SMITH	\$ 850.00	\$ 11.74
12823	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12824	Installed/Active	08/23/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
12825	Installed/Active	12/05/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.75
12826	Installed/Active	10/13/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
12827	Installed/Active	12/10/2008	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.12
12828	Installed/Active	12/10/2002	PRX50	STATE	\$ 1,075.00	
12829	Installed/Active	09/27/1991	PH30	RUUD	\$ 350.00	
12830	Installed/Active	05/01/2002	FSGL40	AO SMITH	\$ 850.00	
12831	Installed/Active	07/15/1991	B71DUMMY	AMERICAN	\$ 850.00	
12832	Installed/Active	02/07/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
12833	Installed/Active	10/10/1991	SBT5065NE	AO SMITH	\$ 1,125.00	
12834	Installed/Active	07/26/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12835	Installed/Active	01/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
12836	Installed/Active	11/15/1999	PGR50	AO SMITH	\$ 850.00	
12837	Installed/Active	02/03/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
12838	Installed/Active	01/11/2008	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 14.05
12839	Installed/Active	12/13/2001	PRX50	STATE	\$ 1,075.00	
12840	Installed/Active	09/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12841	Installed/Active	03/21/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
12842	Installed/Active	10/26/2004	GDVS50	AOSMITH	\$ 1,075.00	
12843	Installed/Active	05/18/2001	21V506	RHEEM	\$ 1,150.00	
12844	Installed/Active	02/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
12845	Installed/Active	03/28/2006	21DV50	RHEEM	\$ 1,075.00	
12846	Installed/Active	06/04/2003	41V50S	RHEEM	\$ 850.00	
12847	Installed/Active	03/22/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12848	Installed/Active	06/06/2005	PR650	STATE	\$ 1,075.00	
12849	Installed/Active	08/11/1989	FSG50	AO SMITH	\$ 850.00	
12850	Installed/Active	12/30/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
12851	Installed/Active	11/05/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
12852	Installed/Active	08/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12853	Installed/Active	08/02/2004	SBF100199NES	STATE	\$ 3,350.00	
12854	Installed/Active	04/07/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
12855	Installed/Active	09/24/2004	GVC40	A. O. SMITH	\$ 850.00	
12856	Installed/Active	10/23/2003	21V506	RHEEM	\$ 1,150.00	
12857	Installed/Active	10/11/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
12858	Installed/Active	02/01/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
12859	Installed/Active	01/31/2005	GVR50	AO SMITH	\$ 850.00	
12860	Installed/Active	02/07/1989	PRX50	STATE	\$ 1,075.00	
12861	Installed/Active	04/05/1989	FSG50	AO SMITH	\$ 850.00	
12862	Installed/Active	03/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12863	Installed/Active	05/29/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12864	Installed/Active	03/19/2007	XTN050	LOCHINVAR	\$ 850.00	\$ 10.23
12865	Installed/Active	08/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
12866	Installed/Active	08/21/1989	P506	RUUD	\$ 500.00	
12867	Installed/Active	09/14/1997	PRV50NODS	STATE	\$ 1,075.00	
12868	Installed/Active	11/28/1998	BTC197	AO SMITH	\$ 3,350.00	
12869	Installed/Active	12/30/2004	GVC50	A. O. SMITH	\$ 850.00	
12870	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12871	Installed/Active	02/08/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
12872	Installed/Active	08/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
12873	Installed/Active	06/04/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12874	Installed/Active	02/20/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12875	Installed/Active	05/22/2002	PRX50	STATE	\$ 1,075.00	
12876	Installed/Active	05/10/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
12877	Installed/Active	01/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12878	Installed/Active	09/23/1999	FGR50	AO SMITH	\$ 850.00	
12879	Installed/Active	05/29/2003	FSG50	AO SMITH	\$ 850.00	
12880	Installed/Active	06/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
12881	Installed/Active	10/23/2001	FSG50	AO SMITH	\$ 850.00	
12882	Installed/Active	09/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
12883	Installed/Active	12/22/2002	PRX50	STATE	\$ 1,075.00	
12884	Installed/Active	10/22/2003	41XR50	RHEEM	\$ 850.00	
12885	Installed/Active	04/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12886	Installed/Active	02/22/1989	FSG50	AO SMITH	\$ 850.00	
12887	Installed/Active	02/26/1998	PRV40NODS	STATE	\$ 1,075.00	
12888	Installed/Active	06/14/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
12889	Installed/Active	02/04/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12890	Installed/Active	05/18/2004	XVR50	Lochinvar	\$ 700.00	
12891	Installed/Active	11/26/2002	PRX50	STATE	\$ 1,075.00	
12892	Installed/Active	06/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12893	Installed/Active	11/04/1999	PGR50	AO SMITH	\$ 850.00	
12894	Installed/Active	11/26/1998	FSG50	AO SMITH	\$ 850.00	
12895	Installed/Active	05/11/2012	P230F	RUUD	\$ 850.00	\$ 12.64
12896	Installed/Active	08/14/1992	FSG50	AO SMITH	\$ 850.00	
12897	Installed/Active	10/21/2011	PRV50NODS	STATE	\$ 1,075.00	\$ 17.74
12898	Installed/Active	04/07/1992	FSG50	AO SMITH	\$ 850.00	
12899	Installed/Active	12/10/1992	FSGL40	AO SMITH	\$ 850.00	
12900	Installed/Active	08/21/2004	42XR50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12901	Installed/Active	12/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
12902	Installed/Active	04/09/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
12903	Installed/Active	09/19/2003	PGR50	AO SMITH	\$ 850.00	
12904	Installed/Active	10/15/2004	PRX40	STATE	\$ 1,075.00	
12905	Installed/Active	01/16/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12906	Installed/Active	03/06/2005	XVR50	A. O. SMITH	\$ 850.00	
12907	Installed/Active	06/12/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12908	Installed/Active	09/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12909	Installed/Active	02/19/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12910	Installed/Active	12/01/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12911	Installed/Active	11/12/2009	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
12912	Installed/Active	10/02/2003	PVR50	AO SMITH	\$ 850.00	
12913	Installed/Active	04/02/1996	L72DUMMY	AO SMITH	\$ 3,350.00	
12914	Installed/Active	02/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
12915	Installed/Active	10/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
12916	Installed/Active	10/05/2004	PRX50	STATE	\$ 1,075.00	
12917	Installed/Active	01/26/2005	GVC40	A. O. SMITH	\$ 850.00	
12918	Installed/Active	04/09/2004	PRX50	STATE	\$ 1,075.00	
12919	Installed/Active	05/14/1992	21V506	RHEEM	\$ 1,150.00	
12920	Installed/Active	05/22/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12921	Installed/Active	03/31/2004	GVC40	A. O. SMITH	\$ 850.00	
12922	Installed/Active	01/30/1992	PRX50	STATE	\$ 1,075.00	
12923	Installed/Active	03/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12924	Installed/Active	01/01/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12925	Installed/Active	03/12/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12926	Installed/Active	12/19/2005	PR650	STATE	\$ 1,075.00	
12927	Installed/Active	12/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12928	Installed/Active	03/22/2000	PGR50	AO SMITH	\$ 850.00	
12929	Installed/Active	08/06/2001	41V50	RHEEM	\$ 850.00	
12930	Installed/Active	03/24/1992	PRV50NODS	STATE	\$ 1,075.00	
12931	Installed/Active	02/23/2001	21V506	RHEEM	\$ 1,150.00	
12932	Installed/Active	10/19/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12933	Installed/Active	03/07/1992	FSG50	AO SMITH	\$ 850.00	
12934	Installed/Active	09/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12935	Installed/Active	05/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
12936	Installed/Active	06/21/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
12937	Installed/Active	01/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12938	Installed/Active	09/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12939	Installed/Active	01/21/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12940	Installed/Active	03/05/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12941	Installed/Active	04/19/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
12942	Installed/Active	02/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12943	Installed/Active	04/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12944	Installed/Active	05/29/2005	LTN050	LOCHINVAR	\$ 850.00	
12945	Installed/Active	03/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12946	Installed/Active	04/05/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
12947	Installed/Active	05/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12948	Installed/Active	09/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12949	Installed/Active	07/16/2008	P506	RUUD	\$ 1,150.00	\$ 14.05
12950	Installed/Active	08/05/1991	B71DUMMY	AMERICAN	\$ 850.00	
12951	Installed/Active	05/05/2003	PGR50	AO SMITH	\$ 850.00	
12952	Installed/Active	09/29/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
12953	Installed/Active	07/18/2001	PGR50	AO SMITH	\$ 850.00	
12954	Installed/Active	01/08/1991	B71DUMMY	AMERICAN	\$ 850.00	
12955	Installed/Active	06/18/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
12956	Installed/Active	06/19/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12957	Installed/Active	11/21/1991	FSG50	AO SMITH	\$ 850.00	
12958	Installed/Active	05/15/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
12959	Installed/Active	04/03/1991	P506	RUUD	\$ 1,125.00	
12960	Installed/Active	03/08/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
12961	Installed/Active	12/09/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
12962	Installed/Active	10/07/2001	FSG50	AO SMITH	\$ 850.00	
12963	Installed/Active	09/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12964	Installed/Active	01/06/2007	LTN050G	LOCHINVAR	\$ 850.00	
12965	Installed/Active	08/02/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
12966	Installed/Active	06/25/1991	FSG50	AO SMITH	\$ 850.00	
12967	Installed/Active	03/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
12968	Installed/Active	02/27/1998	G67114	RHEEM	\$ 1,900.00	
12969	Installed/Active	05/26/2005	LTN050	LOCHINVAR	\$ 850.00	
12970	Installed/Active	03/31/2007	PR650	STATE	\$ 1,075.00	\$ 10.23
12971	Installed/Active	01/02/2007	B71DUMMY	AMERICAN	\$ 850.00	
12972	Installed/Active	06/02/2005	XSN040	LOCHINVAR	\$ 850.00	
12973	Installed/Active	05/16/1999	41XR50	RHEEM	\$ 850.00	
12974	Installed/Active	09/26/2004	PRX50	STATE	\$ 1,075.00	
12975	Installed/Active	02/01/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12976	Installed/Active	07/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12977	Installed/Active	05/03/1999	FGR50	AO SMITH	\$ 850.00	
12978	Installed/Active	10/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12979	Installed/Active	07/13/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
12980	Installed/Active	07/07/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
12981	Installed/Active	10/31/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
12982	Installed/Active	05/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
12983	Installed/Active	08/17/2004	XVR50	A. O. SMITH	\$ 850.00	
12984	Installed/Active	01/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
12985	Installed/Active	11/08/2004	GVC50	A. O. SMITH	\$ 850.00	
12986	Installed/Active	11/17/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
12987	Installed/Active	03/17/2000	PGR50	AO SMITH	\$ 850.00	
12988	Installed/Active	08/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
12989	Installed/Active	11/29/1989	FSG50	AO SMITH	\$ 850.00	
12990	Installed/Active	05/24/2000	FSG50	AO SMITH	\$ 850.00	
12991	Installed/Active	08/14/2008	21V506	RHEEM	\$ 1,150.00	\$ 14.05
12992	Installed/Active	01/03/2003	FSG50	AO SMITH	\$ 850.00	
12993	Installed/Active	12/27/1997	PRV50NODS	STATE	\$ 1,075.00	
12994	Installed/Active	03/07/1989	H72DUMMY	AO SMITH	\$ 1,900.00	
12995	Installed/Active	05/01/2003	FSGL40	AO SMITH	\$ 350.00	
12996	Installed/Active	01/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
12997	Installed/Active	10/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
12998	Installed/Active	08/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
12999	Installed/Active	12/13/2001	FSG50	AO SMITH	\$ 850.00	
13000	Installed/Active	04/29/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
13001	Installed/Active	03/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
13002	Installed/Active	02/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13003	Installed/Active	12/15/1988	FSG50	AO SMITH	\$ 850.00	
13004	Installed/Active	05/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
13005	Installed/Active	01/11/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13006	Installed/Active	06/21/1998	FSG50	AO SMITH	\$ 850.00	
13007	Installed/Active	01/18/2001	FSG40	AO SMITH	\$ 850.00	
13008	Installed/Active	02/16/1989	FSG50	AO SMITH	\$ 850.00	
13009	Installed/Active	06/18/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
13010	Installed/Active	01/20/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
13011	Installed/Active	04/23/2003	FSG50	AO SMITH	\$ 850.00	
13012	Installed/Active	09/25/1989	FSG50	AO SMITH	\$ 850.00	
13013	Installed/Active	02/25/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13014	Installed/Active	06/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
13015	Installed/Active	09/25/2000	FSG50	AO SMITH	\$ 850.00	
13016	Installed/Active	08/09/2003	PVR50	AO SMITH	\$ 850.00	
13017	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13018	Installed/Active	05/25/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
13019	Installed/Active	09/16/2003	FCVL40	AO SMITH	\$ 850.00	
13020	Installed/Active	06/28/2004	XVR50	A. O. SMITH	\$ 850.00	
13021	Installed/Active	10/29/1993	PRX50	STATE	\$ 1,075.00	
13022	Installed/Active	01/08/2001	FSG50	AO SMITH	\$ 850.00	
13023	Installed/Active	12/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13024	Installed/Active	06/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13025	Installed/Active	07/27/2006	LSN041G	LOCHINVAR	\$ 850.00	
13026	Installed/Active	06/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13027	Installed/Active	07/01/2008	22DV5038	RHEEM	\$ 1,075.00	\$ 14.35
13028	Installed/Active	03/30/2004	PRX50	STATE	\$ 1,075.00	
13029	Installed/Active	06/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13030	Installed/Active	05/11/2006	PR650	STATE	\$ 1,075.00	
13031	Installed/Active	08/02/1989	PRV50NODS	STATE	\$ 1,075.00	
13032	Installed/Active	05/28/2005	LTN050	LOCHINVAR	\$ 850.00	
13033	Installed/Active	02/24/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
13034	Installed/Active	02/13/2002	FSG40	AO SMITH	\$ 850.00	
13035	Installed/Active	07/13/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
13036	Installed/Active	02/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13037	Installed/Active	02/03/2004	PRX50	STATE	\$ 1,075.00	
13038	Installed/Active	11/26/1991	FSG50	AO SMITH	\$ 850.00	
13039	Installed/Active	01/10/2011	21V502	RHEEM	\$ 850.00	\$ 12.05
13040	Installed/Active	03/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13041	Installed/Active	11/28/2000	PRX50	STATE	\$ 1,075.00	
13042	Installed/Active	06/08/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13043	Installed/Active	04/26/2001	FSG50	AO SMITH	\$ 850.00	
13044	Installed/Active	01/13/2002	FSG50	AO SMITH	\$ 850.00	
13045	Installed/Active	03/27/2004	41XR50	RHEEM	\$ 850.00	
13046	Installed/Active	10/14/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
13047	Installed/Active	10/08/2003	PGR50	AO SMITH	\$ 850.00	
13048	Installed/Active	08/11/2005	LTN050G	LOCHINVAR	\$ 850.00	
13049	Installed/Active	07/06/2004	GVC50	A. O. SMITH	\$ 1,150.00	
13050	Installed/Active	01/17/1991	BTR199	AO SMITH	\$ 3,350.00	
13051	Installed/Active	10/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13052	Installed/Active	04/25/2003	G82156	RUUD/RHEEM	\$ 3,350.00	
13053	Installed/Active	04/06/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13054	Installed/Active	01/17/1991	FSGL40	AO SMITH	\$ 350.00	
13055	Installed/Active	09/26/2004	PRX40	STATE	\$ 1,075.00	
13056	Installed/Active	04/03/2002	PRX50	STATE	\$ 1,075.00	
13057	Installed/Active	03/11/2005	GVC50	A. O. SMITH	\$ 850.00	
13058	Installed/Active	01/17/1991	FSGL40	AO SMITH	\$ 350.00	
13059	Installed/Active	01/20/1999	21DV50	RHEEM	\$ 1,075.00	
13060	Installed/Active	02/26/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13061	Installed/Active	12/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13062	Installed/Active	10/06/2005	LTN050G	LOCHINVAR	\$ 850.00	
13063	Installed/Active	11/16/2001	PGR50	AO SMITH	\$ 850.00	
13064	Installed/Active	04/14/2004	GVC50	A. O. SMITH	\$ 850.00	
13065	Installed/Active	09/24/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
13066	Installed/Active	05/23/1991	P506	RUUD	\$ 1,150.00	
13067	Installed/Active	05/20/2002	FSG50	AO SMITH	\$ 850.00	
13068	Installed/Active	10/09/1991	FSG50	AO SMITH	\$ 850.00	
13069	Installed/Active	11/17/2000	41XR50	RHEEM	\$ 850.00	
13070	Installed/Active	02/26/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
13071	Installed/Active	02/05/2010	41XR50	RHEEM	\$ 850.00	\$ 11.74
13072	Installed/Active	11/12/2004	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13073	Installed/Active	10/10/2001	FSG40	AO SMITH	\$ 850.00	
13074	Installed/Active	10/25/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
13075	Installed/Active	03/29/1999	FSG40	AO SMITH	\$ 850.00	
13076	Installed/Active	01/23/2011	41VR50	RHEEM	\$ 850.00	\$ 12.05
13077	Installed/Active	05/23/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13078	Installed/Active	01/03/2008	P506	RUUD	\$ 1,125.00	\$ 16.35
13079	Installed/Active	09/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13080	Installed/Active	01/05/2001	41XR50	RHEEM	\$ 850.00	
13081	Installed/Active	09/09/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
13082	Installed/Active	06/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13083	Installed/Active	03/15/2002	FSG50	AO SMITH	\$ 850.00	
13084	Installed/Active	11/03/1992	FSG50	AO SMITH	\$ 850.00	
13085	Installed/Active	05/21/2005	LTN040	LOCHINVAR	\$ 850.00	
13086	Installed/Active	04/17/1993	P506	RUUD	\$ 1,125.00	
13087	Installed/Active	04/03/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13088	Installed/Active	03/04/2010	LTN050G	LOCHINVAR	\$ 350.00	\$ 14.35
13089	Installed/Active	04/12/2002	FSGL40	AO SMITH	\$ 850.00	
13090	Installed/Active	01/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13091	Installed/Active	10/28/2002	FSG50	AO SMITH	\$ 850.00	
13092	Installed/Active	03/23/1992	FSGL40	AO SMITH	\$ 850.00	
13093	Installed/Active	02/22/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13094	Installed/Active	10/09/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13095	Installed/Active	10/08/2005	LTN050G	LOCHINVAR	\$ 850.00	
13096	Installed/Active	12/29/1992	21V506	RHEEM	\$ 1,150.00	
13097	Installed/Active	05/08/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13098	Installed/Active	12/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13099	Installed/Active	02/27/2004	PVR50	AO SMITH	\$ 850.00	
13100	Installed/Active	09/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13101	Installed/Active	12/13/2006	LTN040G	LOCHINVAR	\$ 850.00	
13102	Installed/Active	11/21/2002	BTR120	AO SMITH	\$ 1,900.00	
13103	Installed/Active	10/16/1992	F72DUMMY	AO SMITH	\$ 3,350.00	
13104	Installed/Active	02/11/1992	FSG50	AO SMITH	\$ 850.00	
13105	Installed/Active	09/02/2010	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.55
13106	Installed/Active	03/18/1999	FGR50	AO SMITH	\$ 850.00	
13107	Installed/Active	12/16/1992	FSG40	AO SMITH	\$ 850.00	
13108	Installed/Active	06/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
13109	Installed/Active	02/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13110	Installed/Active	10/31/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
13111	Installed/Active	11/10/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13112	Installed/Active	06/02/2005	PR650	STATE	\$ 1,075.00	
13113	Installed/Active	03/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13114	Installed/Active	12/11/1992	FSG50	AO SMITH	\$ 1,125.00	
13115	Installed/Active	07/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13116	Installed/Active	05/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13117	Installed/Active	05/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13118	Installed/Active	01/23/2002	FSG50	AO SMITH	\$ 850.00	
13119	Installed/Active	08/12/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
13120	Installed/Active	05/30/2005	LTN050	LOCHINVAR	\$ 850.00	
13121	Installed/Active	12/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13122	Installed/Active	10/19/1992	FSG50	AO SMITH	\$ 850.00	
13123	Installed/Active	12/29/2006	PR650	STATE	\$ 1,075.00	
13124	Installed/Active	07/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13125	Installed/Active	12/29/1992	FSG50	AO SMITH	\$ 850.00	
13126	Installed/Active	08/03/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
13127	Installed/Active	10/21/1992	FSG50	AO SMITH	\$ 850.00	
13128	Installed/Active	10/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13129	Installed/Active	04/21/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13130	Installed/Active	01/02/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13131	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13132	Installed/Active	10/01/2002	21V506	RHEEM	\$ 1,150.00	
13133	Installed/Active	09/05/1999	PRV50NODS	STATE	\$ 1,075.00	
13134	Installed/Active	07/10/2006	PR650	STATE	\$ 1,075.00	
13135	Installed/Active	09/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
13136	Installed/Active	12/26/1988	FSG50	AO SMITH	\$ 850.00	
13137	Installed/Active	10/21/2009	FSG50	AO SMITH	\$ 850.00	\$ 11.74
13138	Installed/Active	02/19/2004	PRX50	STATE	\$ 1,075.00	
13139	Installed/Active	04/03/1989	FSG50	AO SMITH	\$ 850.00	
13140	Installed/Active	06/26/1989	P506	RUUD	\$ 1,150.00	
13141	Installed/Active	10/08/2001	PGR50	AO SMITH	\$ 850.00	
13142	Installed/Active	07/02/2004	GVC50	A. O. SMITH	\$ 850.00	
13143	Installed/Active	07/14/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
13144	Installed/Active	09/10/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13145	Installed/Active	08/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13146	Installed/Active	03/13/2003	PRX50	STATE	\$ 1,075.00	
13147	Installed/Active	07/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13148	Installed/Active	03/04/2004	GVC50	A. O. SMITH	\$ 850.00	
13149	Installed/Active	01/09/2004	XTN050	LOCHINVAR	\$ 850.00	
13150	Installed/Active	11/08/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13151	Installed/Active	08/12/1997	PGR50	AO SMITH	\$ 850.00	
13152	Installed/Active	02/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13153	Installed/Active	12/21/2001	PRX50	STATE	\$ 1,075.00	
13154	Installed/Active	07/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
13155	Installed/Active	07/13/2004	XVR50	A. O. SMITH	\$ 850.00	
13156	Installed/Active	01/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
13157	Installed/Active	07/20/2009	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
13158	Installed/Active	02/11/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13159	Installed/Active	09/08/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
13160	Installed/Active	01/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13161	Installed/Active	10/04/2001	FSGL40	AO SMITH	\$ 850.00	
13162	Installed/Active	09/02/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13163	Installed/Active	01/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
13164	Installed/Active	03/10/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13165	Installed/Active	09/26/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13166	Installed/Active	05/02/2000	PHR50	RUUD	\$ 850.00	
13167	Installed/Active	01/28/2005	LTN050	LOCHINVAR	\$ 850.00	
13168	Installed/Active	05/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13169	Installed/Active	06/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13170	Installed/Active	06/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13171	Installed/Active	10/25/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
13172	Installed/Active	08/16/2006	LTN050G	LOCHINVAR	\$ 850.00	
13173	Installed/Active	01/06/2007	LTN050G	LOCHINVAR	\$ 850.00	
13174	Installed/Active	08/15/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
13175	Installed/Active	10/10/1991	FSG50	AO SMITH	\$ 850.00	
13176	Installed/Active	03/19/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
13177	Installed/Active	02/04/1991	FSG50	AO SMITH	\$ 850.00	
13178	Installed/Active	11/14/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13179	Installed/Active	08/09/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
13180	Installed/Active	11/13/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
13181	Installed/Active	09/25/2001	FSG50	AO SMITH	\$ 850.00	
13182	Installed/Active	10/25/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
13183	Installed/Active	01/24/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
13184	Installed/Active	03/25/2002	PGR50	AO SMITH	\$ 850.00	
13185	Installed/Active	04/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13186	Installed/Active	10/25/1991	F72DUMMY	AO SMITH	\$ 3,350.00	
13187	Installed/Active	04/11/2006	LTN050	LOCHINVAR	\$ 850.00	
13188	Installed/Active	01/26/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13189	Installed/Active	05/14/1991	FSG50	AO SMITH	\$ 850.00	
13190	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13191	Installed/Active	03/21/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
13192	Installed/Active	06/09/2012	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13193	Installed/Active	04/30/2003	PGR50	AO SMITH	\$ 850.00	
13194	Installed/Active	06/16/2005	LTN040	LOCHINVAR	\$ 850.00	
13195	Installed/Active	02/08/2005	GDVS50	AOSMITH	\$ 1,075.00	
13196	Installed/Active	09/11/2002	PRX50	STATE	\$ 1,075.00	
13197	Installed/Active	01/12/2007	LTN040G	LOCHINVAR	\$ 850.00	
13198	Installed/Active	05/25/2006	LTN050G	LOCHINVAR	\$ 850.00	
13199	Installed/Active	04/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13200	Installed/Active	10/27/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13201	Installed/Active	12/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13202	Installed/Active	03/23/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
13203	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13204	Installed/Active	11/21/2001	FSG40	AO SMITH	\$ 850.00	
13205	Installed/Active	06/15/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13206	Installed/Active	07/24/2004	GVC40	A. O. SMITH	\$ 850.00	
13207	Installed/Active	12/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13208	Installed/Active	06/14/1991	FSG50	AO SMITH	\$ 850.00	
13209	Installed/Active	07/12/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13210	Installed/Active	07/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13211	Installed/Active	02/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13212	Installed/Active	03/31/2003	FSG50	AO SMITH	\$ 850.00	
13213	Installed/Active	09/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13214	Installed/Active	08/25/2004	GVR50	AO SMITH	\$ 850.00	
13215	Installed/Active	07/02/2001	FSG50	AO SMITH	\$ 850.00	
13216	Installed/Active	07/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13217	Installed/Active	09/16/2004	XTN050	LOCHINVAR	\$ 850.00	
13218	Installed/Active	07/26/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
13219	Installed/Active	01/11/1989	PRX50	STATE	\$ 1,075.00	
13220	Installed/Active	04/21/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13221	Installed/Active	08/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13222	Installed/Active	04/15/2003	PR650	STATE	\$ 1,075.00	
13223	Installed/Active	11/08/2005	LTN050G	LOCHINVAR	\$ 850.00	
13224	Installed/Active	08/31/2010	42V5065F	RHEEM	\$ 850.00	\$ 12.05
13225	Installed/Active	04/23/1996	PR502T	RUUD	\$ 850.00	
13226	Installed/Active	08/03/1989	FSGL40	AO SMITH	\$ 850.00	
13227	Installed/Active	04/12/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13228	Installed/Active	04/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
13229	Installed/Active	12/27/2004	GVC50	A. O. SMITH	\$ 850.00	
13230	Installed/Active	12/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13231	Installed/Active	03/23/2001	PGR50	AO SMITH	\$ 850.00	
13232	Installed/Active	03/19/2004	XTN050	LOCHINVAR	\$ 850.00	
13233	Installed/Active	11/22/2004	XTN050	LOCHINVAR	\$ 850.00	
13234	Installed/Active	03/24/2005	XVR50	A. O. SMITH	\$ 850.00	
13235	Installed/Active	05/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
13236	Installed/Active	08/02/2004	XTN050	LOCHINVAR	\$ 850.00	
13237	Installed/Active	04/20/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
13238	Installed/Active	05/12/2005	LTN050	LOCHINVAR	\$ 850.00	
13239	Installed/Active	09/13/1989	FSG50	AO SMITH	\$ 850.00	
13240	Installed/Active	01/02/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
13241	Installed/Active	10/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13242	Installed/Active	05/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13243	Installed/Active	12/09/2010	42V5065F	RHEEM	\$ 850.00	\$ 12.05
13244	Installed/Active	01/18/2000	41VR40	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13245	Installed/Active	01/12/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
13246	Installed/Active	04/24/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13247	Installed/Active	12/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
13248	Installed/Active	08/27/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
13249	Installed/Active	12/06/2001	PGR50	AO SMITH	\$ 850.00	
13250	Installed/Active	12/12/2004	GVC50	A. O. SMITH	\$ 850.00	
13251	Installed/Active	12/01/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13252	Installed/Active	07/05/2000	21V506	RHEEM	\$ 1,150.00	
13253	Installed/Active	12/21/2000	41V50	RHEEM	\$ 850.00	
13254	Installed/Active	12/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13255	Installed/Active	12/08/1999	PGR50	AO SMITH	\$ 850.00	
13256	Installed/Active	01/02/2004	PRX50	STATE	\$ 1,075.00	
13257	Installed/Active	08/18/1992	P506	RUUD	\$ 1,150.00	
13258	Installed/Active	06/17/1992	P506	RUUD	\$ 1,125.00	
13259	Installed/Active	01/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13260	Installed/Active	12/13/2005	LTN050G	LOCHINVAR	\$ 850.00	
13261	Installed/Active	02/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13262	Installed/Active	09/23/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13263	Installed/Active	04/20/2004	GVC50	A. O. SMITH	\$ 850.00	
13264	Installed/Active	09/02/1992	FSG50	AO SMITH	\$ 850.00	
13265	Installed/Active	05/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
13266	Installed/Active	03/24/1994	21VR50	RHEEM	\$ 850.00	
13267	Installed/Active	11/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13268	Installed/Active	06/24/1992	21V502	RHEEM	\$ 850.00	
13269	Installed/Active	03/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13270	Installed/Active	10/20/2011	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13271	Installed/Active	01/07/2003	FSG40	AO SMITH	\$ 850.00	
13272	Installed/Active	01/16/2013	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13273	Installed/Active	01/09/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13274	Installed/Active	05/15/2006	PR650	STATE	\$ 1,075.00	
13275	Installed/Active	10/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13276	Installed/Active	10/20/1992	FSG50	AO SMITH	\$ 850.00	
13277	Installed/Active	10/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13278	Installed/Active	05/13/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13279	Installed/Active	01/30/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13280	Installed/Active	05/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13281	Installed/Active	04/02/1992	21V502	RHEEM	\$ 850.00	
13282	Installed/Active	02/26/2003	BTR198	AO SMITH	\$ 3,350.00	
13283	Installed/Active	03/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13284	Installed/Active	04/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
13285	Installed/Active	03/24/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13286	Installed/Active	10/08/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
13287	Installed/Active	08/10/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
13288	Installed/Active	06/27/2011	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13289	Installed/Active	07/15/2011	Mi40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13290	Installed/Active	12/04/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
13291	Installed/Active	07/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13292	Installed/Active	02/08/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 10.23
13293	Installed/Active	09/25/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13294	Installed/Active	02/13/2004	XTN050	LOCHINVAR	\$ 850.00	
13295	Installed/Active	02/02/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
13296	Installed/Active	01/13/1993	FSG50	AO SMITH	\$ 850.00	
13297	Installed/Active	03/03/2000	PGR50	AO SMITH	\$ 850.00	
13298	Installed/Active	09/30/2011	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13299	Installed/Active	10/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13300	Installed/Active	07/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13301	Installed/Active	04/14/2010	FGR50	AO SMITH	\$ 850.00	\$ 12.05
13302	Installed/Active	08/29/2002	PRX50	STATE	\$ 1,075.00	
13303	Installed/Active	08/20/1992	FSG50	AO SMITH	\$ 850.00	
13304	Installed/Active	07/29/2012	Mi5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13305	Installed/Active	04/29/2002	PRX50	STATE	\$ 1,075.00	
13306	Installed/Active	10/14/2004	GVC50	A. O. SMITH	\$ 850.00	
13307	Installed/Active	04/16/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
13308	Installed/Active	09/06/1989	PRX50	STATE	\$ 1,075.00	
13309	Installed/Active	06/23/2004	PRX50	STATE	\$ 1,075.00	
13310	Installed/Active	03/05/2004	XTN050	LOCHINVAR	\$ 850.00	
13311	Installed/Active	12/27/2005	GVC50	A. O. SMITH	\$ 850.00	
13312	Installed/Active	07/20/1994	FGR50	AO SMITH	\$ 850.00	
13313	Installed/Active	03/26/1999	FSG50	AO SMITH	\$ 850.00	
13314	Installed/Active	11/01/2003	41XR50	RHEEM	\$ 850.00	
13315	Installed/Active	07/14/2000	PGR50	AO SMITH	\$ 850.00	
13316	Installed/Active	10/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13317	Installed/Active	12/23/2004	PGR50	AO SMITH	\$ 850.00	
13318	Installed/Active	10/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13319	Installed/Active	10/06/2000	PRV40NODS	STATE	\$ 1,075.00	
13320	Installed/Active	11/11/2003	PVR50	AO SMITH	\$ 850.00	
13321	Installed/Active	02/24/2003	PRX40	STATE	\$ 1,075.00	
13322	Installed/Active	04/24/2001	FSG40	AO SMITH	\$ 850.00	
13323	Installed/Active	10/03/2012	G100200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
13324	Installed/Active	03/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13325	Installed/Active	09/05/1989	FSG50	AO SMITH	\$ 850.00	
13326	Installed/Active	12/17/2003	FCV50	AO SMITH	\$ 850.00	
13327	Installed/Active	07/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13328	Installed/Active	08/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13329	Installed/Active	04/05/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13330	Installed/Active	10/13/2005	LTN050	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13331	Installed/Active	01/03/2005	GVC50	A. O. SMITH	\$ 850.00	
13332	Installed/Active	11/13/2002	BTR120	AO SMITH	\$ 1,900.00	
13333	Installed/Active	03/07/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
13334	Installed/Active	07/09/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
13335	Installed/Active	01/15/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13336	Installed/Active	03/09/1989	FSSL40	AO SMITH	\$ 350.00	
13337	Installed/Active	02/09/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
13338	Installed/Active	01/18/2002	PGR50	AO SMITH	\$ 850.00	
13339	Installed/Active	05/27/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13340	Installed/Active	07/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13341	Installed/Active	10/22/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
13342	Installed/Active	11/28/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
13343	Installed/Active	05/02/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13344	Installed/Active	03/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13345	Installed/Active	09/10/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
13346	Installed/Active	09/29/1999	FGR50	AO SMITH	\$ 850.00	
13347	Installed/Active	12/20/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13348	Installed/Active	03/05/2001	FSG50	AO SMITH	\$ 850.00	
13349	Installed/Active	04/18/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13350	Installed/Active	01/04/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
13351	Installed/Active	09/25/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
13352	Installed/Active	04/18/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
13353	Installed/Active	02/14/2012	PRX50	STATE	\$ 1,075.00	\$ 17.74
13354	Installed/Active	06/27/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13355	Installed/Active	02/02/2005	GDVS50	AOSMITH	\$ 1,075.00	
13356	Installed/Active	02/15/2005	GVC50	A. O. SMITH	\$ 850.00	
13357	Installed/Active	06/06/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13358	Installed/Active	05/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13359	Installed/Active	10/12/2002	PGR40	AO SMITH	\$ 850.00	
13360	Installed/Active	01/28/2005	GVC50	A. O. SMITH	\$ 850.00	
13361	Installed/Active	01/14/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13362	Installed/Active	04/22/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13363	Installed/Active	08/25/2003	FSSL40	AO SMITH	\$ 850.00	
13364	Installed/Active	06/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
13365	Installed/Active	02/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
13366	Installed/Active	07/26/2005	LTN050G	LOCHINVAR	\$ 850.00	
13367	Installed/Active	04/01/2004	XVR50	A. O. SMITH	\$ 850.00	
13368	Installed/Active	10/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13369	Installed/Active	12/16/1992	21DV50	RHEEM	\$ 1,075.00	
13370	Installed/Active	07/09/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
13371	Installed/Active	11/12/2002	FSG50	AO SMITH	\$ 850.00	
13372	Installed/Active	08/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13373	Installed/Active	04/25/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13374	Installed/Active	08/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13375	Installed/Active	06/30/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
13376	Installed/Active	02/10/2005	21V506	RHEEM	\$ 1,150.00	
13377	Installed/Active	07/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13378	Installed/Active	01/06/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
13379	Installed/Active	02/21/2012	M175S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.30
13380	Installed/Active	11/13/2001	PGR50	AO SMITH	\$ 850.00	
13381	Installed/Active	06/24/2004	XTN050	LOCHINVAR	\$ 850.00	
13382	Installed/Active	01/14/2011	PRX50	STATE	\$ 1,075.00	\$ 16.91
13383	Installed/Active	06/24/2004	PRX50	STATE	\$ 1,075.00	
13384	Installed/Active	10/08/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
13385	Installed/Active	09/26/2000	BTR154	AO SMITH	\$ 3,350.00	
13386	Installed/Active	12/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13387	Installed/Active	03/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13388	Installed/Active	08/08/2005	LTN050G	LOCHINVAR	\$ 850.00	
13389	Installed/Active	02/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13390	Installed/Active	07/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
13391	Installed/Active	03/28/2005	GVC50	A. O. SMITH	\$ 850.00	
13392	Installed/Active	07/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13393	Installed/Active	10/21/1992	H72DUMMY	AO SMITH	\$ 1,900.00	
13394	Installed/Active	11/08/2005	PR650	STATE	\$ 1,075.00	
13395	Installed/Active	08/28/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
13396	Installed/Active	08/02/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13397	Installed/Active	04/22/1993	RF82156	RUUD	\$ 3,350.00	
13398	Installed/Active	01/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13399	Installed/Active	07/09/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13400	Installed/Active	12/04/2002	21V407	RHEEM	\$ 850.00	
13401	Installed/Active	01/02/2003	FSG50	AO SMITH	\$ 850.00	
13402	Installed/Active	03/06/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
13403	Installed/Active	06/12/1992	FSG50	AO SMITH	\$ 850.00	
13404	Installed/Active	01/25/2002	PGR50	AO SMITH	\$ 850.00	
13405	Installed/Active	12/30/2002	PRX50	STATE	\$ 1,075.00	
13406	Installed/Active	09/28/2004	21V502	RHEEM	\$ 850.00	
13407	Installed/Active	09/01/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13408	Installed/Active	05/14/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
13409	Installed/Active	02/17/1992	21V502	RHEEM	\$ 850.00	
13410	Installed/Active	06/22/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13411	Installed/Active	12/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13412	Installed/Active	02/10/2011	42V50SF	RHEEM	\$ 850.00	\$ 12.05
13413	Installed/Active	04/30/1991	21V502	RHEEM	\$ 850.00	
13414	Installed/Active	07/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13415	Installed/Active	07/12/2006	PRV50N0DS	STATE	\$ 1,075.00	
13416	Installed/Active	02/25/1991	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13417	Installed/Active	05/07/2009	PRX50	STATE	\$ 1,075.00	\$ 16.47
13418	Installed/Active	04/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13419	Installed/Active	08/12/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13420	Installed/Active	01/20/2010	ETN076	LOCHINVAR	\$ 1,125.00	\$ 18.76
13421	Installed/Active	03/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13422	Installed/Active	11/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13423	Installed/Active	04/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13424	Installed/Active	06/24/2004	21V506	RHEEM	\$ 1,150.00	
13425	Installed/Active	10/29/2006	PR650	STATE	\$ 1,075.00	
13426	Installed/Active	08/30/2006	PR650	STATE	\$ 1,075.00	
13427	Installed/Active	01/24/2011	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
13428	Installed/Active	03/12/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
13429	Installed/Active	06/04/2003	FDV50	AO SMITH	\$ 1,075.00	
13430	Installed/Active	10/31/1991	BTR120	AO SMITH	\$ 1,900.00	
13431	Installed/Active	10/04/1991	21V502	RHEEM	\$ 850.00	
13432	Installed/Active	05/25/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13433	Installed/Active	02/07/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13434	Installed/Active	06/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13435	Installed/Active	10/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13436	Installed/Active	12/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13437	Installed/Active	04/29/2005	LTN050	LOCHINVAR	\$ 850.00	
13438	Installed/Active	08/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13439	Installed/Active	03/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
13440	Installed/Active	12/18/2003	PRX50	STATE	\$ 1,075.00	
13441	Installed/Active	02/24/2004	FCV50	AO SMITH	\$ 850.00	
13442	Installed/Active	10/09/2001	PGR50	AO SMITH	\$ 850.00	
13443	Installed/Active	02/21/2006	LTN050G	LOCHINVAR	\$ 850.00	
13444	Installed/Active	11/29/2012	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13445	Installed/Active	04/28/2001	PRX50	STATE	\$ 1,075.00	
13446	Installed/Active	05/10/1991	P506	RUUD	\$ 1,150.00	
13447	Installed/Active	11/22/1989	FSG50	AO SMITH	\$ 850.00	
13448	Installed/Active	06/27/2005	ETN076	LOCHINVAR	\$ 1,900.00	
13449	Installed/Active	02/13/2004	41V50	RHEEM	\$ 850.00	
13450	Installed/Active	12/02/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
13451	Installed/Active	01/09/1989	FSG50	AO SMITH	\$ 850.00	
13452	Installed/Active	01/23/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13453	Installed/Active	08/26/2010	PRX50	STATE	\$ 1,075.00	\$ 16.91
13454	Installed/Active	06/01/2000	PRX50	STATE	\$ 1,075.00	
13455	Installed/Active	06/05/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
13456	Installed/Active	06/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13457	Installed/Active	08/25/2003	PRX50	STATE	\$ 1,075.00	
13458	Installed/Active	11/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13459	Installed/Active	07/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13460	Installed/Active	01/03/2006	22DV5038	RHEEM	\$ 1,075.00	
13461	Installed/Active	04/03/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
13462	Installed/Active	07/11/1989	FSG50	AO SMITH	\$ 850.00	
13463	Installed/Active	12/09/2003	FCV50	AO SMITH	\$ 850.00	
13464	Installed/Active	09/10/2001	41XR50	RHEEM	\$ 850.00	
13465	Installed/Active	02/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13466	Installed/Active	09/05/2006	PR650	STATE	\$ 1,075.00	
13467	Installed/Active	12/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
13468	Installed/Active	08/26/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
13469	Installed/Active	04/13/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
13470	Installed/Active	05/20/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13471	Installed/Active	07/26/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13472	Installed/Active	05/21/1996	PRX50	STATE	\$ 1,075.00	
13473	Installed/Active	03/18/2005	PVR50	AO SMITH	\$ 1,075.00	
13474	Installed/Active	10/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13475	Installed/Active	05/19/2003	PGR50	AO SMITH	\$ 850.00	
13476	Installed/Active	11/18/2005	LTN050G	LOCHINVAR	\$ 850.00	
13477	Installed/Active	05/09/2005	GDVS50	AOSMITH	\$ 1,075.00	
13478	Installed/Active	07/26/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
13479	Installed/Active	02/13/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13480	Installed/Active	06/30/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
13481	Installed/Active	03/12/2003	FSG50	AO SMITH	\$ 850.00	
13482	Installed/Active	02/18/2002	PGR50	AO SMITH	\$ 850.00	
13483	Installed/Active	12/23/2001	PGR50	AO SMITH	\$ 850.00	
13484	Installed/Active	09/08/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13485	Installed/Active	10/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13486	Installed/Active	07/10/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
13487	Installed/Active	11/06/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13488	Installed/Active	10/17/2003	FSG50	AO SMITH	\$ 850.00	
13489	Installed/Active	03/23/2001	PR650	STATE	\$ 1,075.00	
13490	Installed/Active	07/30/2003	PRX50	STATE	\$ 1,075.00	
13491	Installed/Active	06/05/2007	LTN050G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13492	Installed/Active	01/30/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13493	Installed/Active	02/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13494	Installed/Active	09/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13495	Installed/Active	01/28/2002	21V506	RHEEM	\$ 1,150.00	
13496	Installed/Active	09/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13497	Installed/Active	09/26/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13498	Installed/Active	01/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13499	Installed/Active	12/04/2006	PRV50NORT	STATE	\$ 850.00	
13500	Installed/Active	06/28/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
13501	Installed/Active	02/03/1998	PRX50	STATE	\$ 1,075.00	
13502	Installed/Active	12/26/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13503	Installed/Active	04/04/2005	GVC50	A. O. SMITH	\$ 850.00	
13504	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13505	Installed/Active	11/13/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13506	Installed/Active	02/24/1992	FSG50	AO SMITH	\$ 850.00	
13507	Installed/Active	10/06/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
13508	Installed/Active	06/10/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13509	Installed/Active	07/30/2004	PRX50	STATE	\$ 1,075.00	
13510	Installed/Active	01/24/2000	21V506	RHEEM	\$ 1,150.00	
13511	Installed/Active	02/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13512	Installed/Active	07/28/2002	PRX50	STATE	\$ 1,075.00	
13513	Installed/Active	11/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13514	Installed/Active	04/16/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
13515	Installed/Active	12/18/2003	PRX50	STATE	\$ 1,075.00	
13516	Installed/Active	10/14/2003	FCV50	AO SMITH	\$ 850.00	
13517	Installed/Active	09/17/1992	FSG50	AO SMITH	\$ 850.00	
13518	Installed/Active	12/12/2001	FSG50	AO SMITH	\$ 850.00	
13519	Installed/Active	09/07/2005	LTN050G	LOCHINVAR	\$ 850.00	
13520	Installed/Active	12/08/2003	PRX50	STATE	\$ 1,075.00	
13521	Installed/Active	06/10/1992	FSG50	AO SMITH	\$ 850.00	
13522	Installed/Active	09/27/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
13523	Installed/Active	12/07/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.74
13524	Installed/Active	10/19/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
13525	Installed/Active	11/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13526	Installed/Active	02/23/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
13527	Installed/Active	10/29/2004	GVC50	A. O. SMITH	\$ 850.00	
13528	Installed/Active	04/19/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13529	Installed/Active	09/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13530	Installed/Active	10/11/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
13531	Installed/Active	05/22/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13532	Installed/Active	08/04/2004	GVC50	A. O. SMITH	\$ 850.00	
13533	Installed/Active	04/01/2006	22DV50C	RHEEM	\$ 1,075.00	
13534	Installed/Active	03/28/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 10.23
13535	Installed/Active	05/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
13536	Installed/Active	10/28/2000	PRX50	STATE	\$ 1,075.00	
13537	Installed/Active	04/25/2001	FSG50	AO SMITH	\$ 850.00	
13538	Installed/Active	07/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13539	Installed/Active	04/12/2002	FSG50	AO SMITH	\$ 850.00	
13540	Installed/Active	03/17/2005	XSN040	LOCHINVAR	\$ 850.00	
13541	Installed/Active	05/04/2004	XVR50	A. O. SMITH	\$ 850.00	
13542	Installed/Active	02/08/2002	PGR50	AO SMITH	\$ 850.00	
13543	Installed/Active	02/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13544	Installed/Active	11/01/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13545	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13546	Installed/Active	01/28/2006	PR650	STATE	\$ 1,075.00	
13547	Installed/Active	07/30/1999	FGR50	AO SMITH	\$ 850.00	
13548	Installed/Active	07/11/2003	PGR50	AO SMITH	\$ 850.00	
13549	Installed/Active	06/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13550	Installed/Active	01/11/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13551	Installed/Active	12/12/2004	GCVL40	A. O. SMITH	\$ 850.00	
13552	Installed/Active	01/05/2005	GVC40	A. O. SMITH	\$ 850.00	
13553	Installed/Active	10/01/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13554	Installed/Active	05/07/2012	FSG50	AO SMITH	\$ 850.00	\$ 12.64
13555	Installed/Active	09/29/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
13556	Installed/Active	06/12/2002	21V506	RHEEM	\$ 1,150.00	
13557	Installed/Active	01/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13558	Installed/Active	12/08/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13559	Installed/Active	03/14/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
13560	Installed/Active	11/11/2002	BTR120	AO SMITH	\$ 1,900.00	
13561	Installed/Active	02/19/2000	FSG50	AO SMITH	\$ 850.00	
13562	Installed/Active	05/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13563	Installed/Active	11/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13564	Installed/Active	02/06/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13565	Installed/Active	03/16/1993	FSG50	AO SMITH	\$ 850.00	
13566	Installed/Active	07/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
13567	Installed/Active	05/18/2006	PR650	STATE	\$ 1,075.00	
13568	Installed/Active	07/25/2002	PGR50	AO SMITH	\$ 850.00	
13569	Installed/Active	08/30/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
13570	Installed/Active	12/28/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13571	Installed/Active	11/01/2001	PRX50	STATE	\$ 1,075.00	
13572	Installed/Active	07/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13573	Installed/Active	04/25/2003	FSG50	AO SMITH	\$ 850.00	
13574	Installed/Active	01/28/2004	PRX50	STATE	\$ 1,075.00	
13575	Installed/Active	09/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13576	Installed/Active	03/23/1998	FGR50	AO SMITH	\$ 850.00	
13577	Installed/Active	11/14/1989	21V506	RHEEM	\$ 1,150.00	
13578	Installed/Active	12/27/2011	FSG50	AO SMITH	\$ 850.00	\$ 12.64
13579	Installed/Active	07/30/2002	FSG50	AO SMITH	\$ 850.00	
13580	Installed/Active	07/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13581	Installed/Active	05/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13582	Installed/Active	07/14/2005	LTN050	LOCHINVAR	\$ 850.00	
13583	Installed/Active	12/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13584	Installed/Active	11/21/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13585	Installed/Active	08/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13586	Installed/Active	09/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13587	Installed/Active	10/11/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13588	Installed/Active	03/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13589	Installed/Active	05/04/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
13590	Installed/Active	07/27/2005	LTN050	LOCHINVAR	\$ 850.00	
13591	Installed/Active	03/11/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
13592	Installed/Active	10/18/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
13593	Installed/Active	05/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13594	Installed/Active	08/23/1999	PR650	STATE	\$ 1,075.00	
13595	Installed/Active	12/12/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13596	Installed/Active	03/11/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
13597	Installed/Active	08/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13598	Installed/Active	04/16/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
13599	Installed/Active	02/15/2001	PRX50	STATE	\$ 1,075.00	
13600	Installed/Active	01/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13601	Installed/Active	06/29/2010	LTN051G	LOCHINVAR	\$ 850.00	\$ 16.55
13602	Installed/Active	12/26/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13603	Installed/Active	10/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
13604	Installed/Active	11/08/2000	41XR50	RHEEM	\$ 850.00	
13605	Installed/Active	01/08/2002	PGR50	AO SMITH	\$ 850.00	
13606	Installed/Active	10/06/1995	FSG50	AO SMITH	\$ 850.00	
13607	Installed/Active	11/01/2002	FSG50	AO SMITH	\$ 850.00	
13608	Installed/Active	01/15/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13609	Installed/Active	11/11/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
13610	Installed/Active	06/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13611	Installed/Active	09/15/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13612	Installed/Active	05/18/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13613	Installed/Active	03/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13614	Installed/Active	04/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13615	Installed/Active	06/15/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13616	Installed/Active	01/04/1994	FGR50	AO SMITH	\$ 850.00	
13617	Installed/Active	04/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13618	Installed/Active	06/21/2004	XVR50	A. O. SMITH	\$ 850.00	
13619	Installed/Active	11/29/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13620	Installed/Active	08/23/1989	P506	RUUD	\$ 1,150.00	
13621	Installed/Active	08/16/2011	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13622	Installed/Active	04/22/1999	PHR50	RUUD	\$ 850.00	
13623	Installed/Active	01/04/2007	LTN050G	LOCHINVAR	\$ 850.00	
13624	Installed/Active	07/05/2004	GVC50	A. O. SMITH	\$ 850.00	
13625	Installed/Active	08/31/1999	FSG50	AO SMITH	\$ 850.00	
13626	Installed/Active	06/20/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13627	Installed/Active	12/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13628	Installed/Active	09/25/2004	GVC50	A. O. SMITH	\$ 850.00	
13629	Installed/Active	03/06/1991	PRV50NODS	STATE	\$ 1,075.00	
13630	Installed/Active	06/30/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13631	Installed/Active	09/17/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
13632	Installed/Active	11/28/1998	PR650	STATE	\$ 1,075.00	
13633	Installed/Active	03/12/2002	21V506	RHEEM	\$ 1,150.00	
13634	Installed/Active	11/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
13635	Installed/Active	11/23/2005	BTR154	AO SMITH	\$ 3,350.00	
13636	Installed/Active	08/11/2005	FSG40	AO SMITH	\$ 850.00	
13637	Installed/Active	08/21/1991	PRX50	STATE	\$ 1,075.00	
13638	Installed/Active	10/31/2005	BTR154	AO SMITH	\$ 3,350.00	
13639	Installed/Active	09/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13640	Installed/Active	01/05/1992	PRV50NODS	STATE	\$ 1,075.00	
13641	Installed/Active	11/27/2006	LSN041G	LOCHINVAR	\$ 850.00	
13642	Installed/Active	04/10/1991	FSG40	AO SMITH	\$ 850.00	
13643	Installed/Active	11/30/2001	PGR50	AO SMITH	\$ 850.00	
13644	Installed/Active	01/24/1992	P506	RUUD	\$ 1,125.00	
13645	Installed/Active	07/29/1991	21V407	RHEEM	\$ 850.00	
13646	Installed/Active	01/13/2002	FSG50	AO SMITH	\$ 850.00	
13647	Installed/Active	01/07/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
13648	Installed/Active	10/30/1991	FSG50	AO SMITH	\$ 850.00	
13649	Installed/Active	02/04/2002	PGR50	AO SMITH	\$ 850.00	
13650	Installed/Active	08/03/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13651	Installed/Active	02/17/2006	PR650X0DS	STATE	\$ 1,075.00	
13652	Installed/Active	04/04/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
13653	Installed/Active	01/25/2006	LTN040G	LOCHINVAR	\$ 850.00	
13654	Installed/Active	10/08/2001	PGR50	AO SMITH	\$ 850.00	
13655	Installed/Active	02/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
13656	Installed/Active	07/02/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
13657	Installed/Active	01/15/1991	P506	RUUD	\$ 1,125.00	
13658	Installed/Active	01/27/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13659	Installed/Active	11/22/2004	XVR50	A. O. SMITH	\$ 850.00	
13660	Installed/Active	08/15/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13661	Installed/Active	02/06/1999	FGR50	AO SMITH	\$ 850.00	
13662	Installed/Active	12/10/2004	LTN050	LOCHINVAR	\$ 850.00	
13663	Installed/Active	12/13/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13664	Installed/Active	10/01/1998	FSG50	AO SMITH	\$ 850.00	
13665	Installed/Active	07/05/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13666	Installed/Active	09/13/2001	PRX50	STATE	\$ 1,075.00	
13667	Installed/Active	12/30/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13668	Installed/Active	11/19/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13669	Installed/Active	01/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13670	Installed/Active	05/17/1991	B71DUMMY	AMERICAN	\$ 850.00	
13671	Installed/Active	07/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13672	Installed/Active	11/15/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13673	Installed/Active	01/31/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
13674	Installed/Active	09/10/1992	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13675	Installed/Active	04/01/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
13676	Installed/Active	10/27/2005	G76200	RUUD/RHEEM	\$ 3,350.00	
13677	Installed/Active	10/15/2005	PR650	STATE	\$ 1,075.00	
13678	Installed/Active	04/01/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
13679	Installed/Active	10/29/1992	P502	RUUD	\$ 850.00	
13680	Installed/Active	03/21/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
13681	Installed/Active	09/12/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
13682	Installed/Active	04/01/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
13683	Installed/Active	09/16/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
13684	Installed/Active	12/01/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13685	Installed/Active	11/10/1992	PRV50NORT	STATE	\$ 850.00	
13686	Installed/Active	08/02/2005	PR650	STATE	\$ 1,075.00	
13687	Installed/Active	01/23/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
13688	Installed/Active	03/11/2005	GVC50	A. O. SMITH	\$ 850.00	
13689	Installed/Active	04/23/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13690	Installed/Active	12/23/1992	21V502	RHEEM	\$ 850.00	
13691	Installed/Active	01/23/2002	PRX50	STATE	\$ 1,075.00	
13692	Installed/Active	04/23/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13693	Installed/Active	03/30/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13694	Installed/Active	03/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13695	Installed/Active	03/09/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
13696	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 1,150.00	\$ 16.12
13697	Installed/Active	12/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13698	Installed/Active	03/09/1993	P502	RUUD	\$ 850.00	
13699	Installed/Active	02/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13700	Installed/Active	05/08/1992	21V502	RHEEM	\$ 850.00	
13701	Installed/Active	03/13/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
13702	Installed/Active	08/31/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13703	Installed/Active	12/19/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13704	Installed/Active	01/28/2002	FSG50	AO SMITH	\$ 850.00	
13705	Installed/Active	01/24/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
13706	Installed/Active	12/27/2004	GVC50	A. O. SMITH	\$ 850.00	
13707	Installed/Active	10/27/1999	PRX50	STATE	\$ 1,075.00	
13708	Installed/Active	07/17/2003	FGR50	AO SMITH	\$ 850.00	
13709	Installed/Active	12/01/2003	PVR50	AO SMITH	\$ 850.00	
13710	Installed/Active	03/06/1989	21V506	RHEEM	\$ 1,150.00	
13711	Installed/Active	02/03/2001	41XR50	RHEEM	\$ 850.00	
13712	Installed/Active	07/16/2003	FSG50	AO SMITH	\$ 850.00	
13713	Installed/Active	11/11/2000	41XR50	RHEEM	\$ 850.00	
13714	Installed/Active	06/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
13715	Installed/Active	02/04/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13716	Installed/Active	06/26/1999	PR650	STATE	\$ 1,075.00	
13717	Installed/Active	11/20/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
13718	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13719	Installed/Active	12/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13720	Installed/Active	09/18/1998	FGR50	AO SMITH	\$ 850.00	
13721	Installed/Active	06/28/2001	41XR50	RHEEM	\$ 850.00	
13722	Installed/Active	11/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13723	Installed/Active	04/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13724	Installed/Active	05/25/1989	FSGL40	AO SMITH	\$ 850.00	
13725	Installed/Active	12/17/2003	PRX50	STATE	\$ 1,075.00	
13726	Installed/Active	12/23/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13727	Installed/Active	09/28/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
13728	Installed/Active	09/09/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
13729	Installed/Active	08/31/1989	FSG40	AO SMITH	\$ 850.00	
13730	Installed/Active	08/18/2010	PGR50	AO SMITH	\$ 850.00	\$ 12.05
13731	Installed/Active	11/12/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13732	Installed/Active	01/31/2005	GCVL40	A. O. SMITH	\$ 850.00	
13733	Installed/Active	06/22/2001	FSG50	AO SMITH	\$ 850.00	
13734	Installed/Active	02/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13735	Installed/Active	09/15/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
13736	Installed/Active	04/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13737	Installed/Active	05/15/1989	FSG50	AO SMITH	\$ 850.00	
13738	Installed/Active	08/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13739	Installed/Active	07/25/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
13740	Installed/Active	08/14/1989	FSG50	AO SMITH	\$ 850.00	
13741	Installed/Active	01/08/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13742	Installed/Active	01/29/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13743	Installed/Active	07/25/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
13744	Installed/Active	01/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13745	Installed/Active	01/26/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
13746	Installed/Active	06/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
13747	Installed/Active	11/19/2001	PGR50	AO SMITH	\$ 850.00	
13748	Installed/Active	07/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13749	Installed/Active	04/22/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13750	Installed/Active	01/30/2001	PGR50	AO SMITH	\$ 850.00	
13751	Installed/Active	06/24/1998	PGR50	AO SMITH	\$ 850.00	
13752	Installed/Active	05/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13753	Installed/Active	03/18/2013	41VR50	RHEEM	\$ 850.00	\$ 12.75
13754	Installed/Active	03/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13755	Installed/Active	01/23/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13756	Installed/Active	02/28/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13757	Installed/Active	06/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13758	Installed/Active	09/28/2005	PRX50	STATE	\$ 1,075.00	
13759	Installed/Active	03/23/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13760	Installed/Active	02/15/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13761	Installed/Active	10/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13762	Installed/Active	12/29/2006	41V50	RHEEM	\$ 850.00	
13763	Installed/Active	03/07/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
13764	Installed/Active	11/05/2007	21V402S	RHEEM	\$ 850.00	\$ 10.23
13765	Installed/Active	02/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13766	Installed/Active	03/09/1991	PRV50NODS	STATE	\$ 1,075.00	
13767	Installed/Active	02/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13768	Installed/Active	06/18/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13769	Installed/Active	10/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13770	Installed/Active	07/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13771	Installed/Active	09/05/1991	FSG50	AO SMITH	\$ 850.00	
13772	Installed/Active	10/22/2001	PGR50	AO SMITH	\$ 850.00	
13773	Installed/Active	04/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
13774	Installed/Active	09/26/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
13775	Installed/Active	02/12/2008	PR650	STATE	\$ 1,075.00	\$ 14.35
13776	Installed/Active	01/14/2003	PGR50	AO SMITH	\$ 850.00	
13777	Installed/Active	10/30/2003	41V50S	RHEEM	\$ 850.00	
13778	Installed/Active	10/28/2003	PGR50	AO SMITH	\$ 850.00	
13779	Installed/Active	11/13/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13780	Installed/Active	08/02/2002	FSG50	AO SMITH	\$ 850.00	
13781	Installed/Active	09/27/2005	LTN050	LOCHINVAR	\$ 1,150.00	
13782	Installed/Active	05/17/2010	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 19.26
13783	Installed/Active	08/06/1991	FSG50	AO SMITH	\$ 850.00	
13784	Installed/Active	06/14/2004	PRX50	STATE	\$ 1,075.00	
13785	Installed/Active	10/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13786	Installed/Active	09/05/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
13787	Installed/Active	07/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13788	Installed/Active	09/30/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
13789	Installed/Active	11/30/2004	GVC50	A. O. SMITH	\$ 850.00	
13790	Installed/Active	01/13/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
13791	Installed/Active	05/19/2006	LTN050G	LOCHINVAR	\$ 850.00	
13792	Installed/Active	01/25/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13793	Installed/Active	11/12/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13794	Installed/Active	10/14/2005	PR650	STATE	\$ 1,075.00	
13795	Installed/Active	08/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13796	Installed/Active	03/05/1991	FSG50	AO SMITH	\$ 850.00	
13797	Installed/Active	02/05/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13798	Installed/Active	12/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13799	Installed/Active	01/04/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13800	Installed/Active	04/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13801	Installed/Active	04/09/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
13802	Installed/Active	10/30/1992	FSG50	AO SMITH	\$ 850.00	
13803	Installed/Active	10/09/2001	PGR50	AO SMITH	\$ 850.00	
13804	Installed/Active	07/02/1992	FSG50	AO SMITH	\$ 850.00	
13805	Installed/Active	07/17/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13806	Installed/Active	09/23/2000	FSG50	AO SMITH	\$ 850.00	
13807	Installed/Active	07/10/1992	P502	RUUD	\$ 850.00	
13808	Installed/Active	06/10/2003	FSG40	AO SMITH	\$ 850.00	
13809	Installed/Active	03/28/2002	PGR50	AO SMITH	\$ 850.00	
13810	Installed/Active	10/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13811	Installed/Active	11/04/2005	LTN050G	LOCHINVAR	\$ 850.00	
13812	Installed/Active	02/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13813	Installed/Active	10/28/1992	FSG50	AO SMITH	\$ 850.00	
13814	Installed/Active	05/05/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13815	Installed/Active	01/08/2002	21V506	RHEEM	\$ 1,150.00	
13816	Installed/Active	11/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
13817	Installed/Active	03/10/2005	41XR50	RHEEM	\$ 850.00	
13818	Installed/Active	08/28/2006	PR650	STATE	\$ 1,075.00	
13819	Installed/Active	11/09/2002	PGR50	AO SMITH	\$ 850.00	
13820	Installed/Active	02/11/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13821	Installed/Active	08/01/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
13822	Installed/Active	08/04/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13823	Installed/Active	07/14/1993	21V502	RHEEM	\$ 850.00	
13824	Installed/Active	08/03/1992	FSSL40	AO SMITH	\$ 850.00	
13825	Installed/Active	03/20/2006	PR650	STATE	\$ 1,075.00	
13826	Installed/Active	12/03/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
13827	Installed/Active	02/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13828	Installed/Active	08/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13829	Installed/Active	09/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13830	Installed/Active	07/07/2004	GVC50	A. O. SMITH	\$ 850.00	
13831	Installed/Active	11/05/2002	PGR50	AO SMITH	\$ 850.00	
13832	Installed/Active	01/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
13833	Installed/Active	11/02/2002	FSG50	AO SMITH	\$ 850.00	
13834	Installed/Active	05/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13835	Installed/Active	01/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13836	Installed/Active	10/01/1992	FSG50	AO SMITH	\$ 850.00	
13837	Installed/Active	06/26/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13838	Installed/Active	07/22/2002	PGR50	AO SMITH	\$ 850.00	
13839	Installed/Active	12/15/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
13840	Installed/Active	04/23/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
13841	Installed/Active	06/08/2001	FSG50	AO SMITH	\$ 850.00	
13842	Installed/Active	09/20/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
13843	Installed/Active	02/19/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13844	Installed/Active	11/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13845	Installed/Active	03/25/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
13846	Installed/Active	11/08/2003	41V50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13847	Installed/Active	06/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13848	Installed/Active	05/08/2001	FSG40	AO SMITH	\$ 850.00	
13849	Installed/Active	12/30/1996	PR502T	RUUD	\$ 850.00	
13850	Installed/Active	11/28/1997	PGR50	AO SMITH	\$ 850.00	
13851	Installed/Active	08/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
13852	Installed/Active	01/25/2000	FSG50	AO SMITH	\$ 850.00	
13853	Installed/Active	09/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13854	Installed/Active	05/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13855	Installed/Active	12/18/1999	PHR50	RUUD	\$ 850.00	
13856	Installed/Active	11/01/2002	FSG50	AO SMITH	\$ 850.00	
13857	Installed/Active	06/24/2010	FCV50	AO SMITH	\$ 850.00	\$ 12.05
13858	Installed/Active	10/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13859	Installed/Active	09/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13860	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13861	Installed/Active	07/11/2011	M50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13862	Installed/Active	06/28/1989	P506	RUUD	\$ 1,125.00	
13863	Installed/Active	01/19/2006	PR650	STATE	\$ 1,075.00	
13864	Installed/Active	02/28/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
13865	Installed/Active	10/16/2012	41XR50	RHEEM	\$ 850.00	\$ 12.75
13866	Installed/Active	02/03/2006	PR650X0DS	STATE	\$ 1,075.00	
13867	Installed/Active	07/09/2001	FSG50	AO SMITH	\$ 850.00	
13868	Installed/Active	03/01/2002	FSG50	AO SMITH	\$ 850.00	
13869	Installed/Active	01/31/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13870	Installed/Active	11/11/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
13871	Installed/Active	06/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13872	Installed/Active	09/25/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
13873	Installed/Active	06/19/2008	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
13874	Installed/Active	08/18/2005	LSN041G	LOCHINVAR	\$ 850.00	
13875	Installed/Active	09/22/2006	LTN050G	LOCHINVAR	\$ 850.00	
13876	Installed/Active	08/29/2003	21V506	RHEEM	\$ 1,150.00	
13877	Installed/Active	10/18/1989	21V506	RHEEM	\$ 1,150.00	
13878	Installed/Active	09/23/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
13879	Installed/Active	10/10/2006	PR650X0DS	STATE	\$ 1,075.00	
13880	Installed/Active	03/29/2002	FSG50	AO SMITH	\$ 850.00	
13881	Installed/Active	07/24/1989	FSG50	AO SMITH	\$ 850.00	
13882	Installed/Active	05/09/2003	PGR50	AO SMITH	\$ 850.00	
13883	Installed/Active	10/18/2000	41XR50	RHEEM	\$ 850.00	
13884	Installed/Active	07/14/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
13885	Installed/Active	01/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13886	Installed/Active	09/15/2004	GVC50	A. O. SMITH	\$ 850.00	
13887	Installed/Active	12/22/2004	GVC50	A. O. SMITH	\$ 850.00	
13888	Installed/Active	04/24/2012	41VR50	RHEEM	\$ 850.00	\$ 12.64
13889	Installed/Active	11/05/2001	PRX50	STATE	\$ 1,075.00	
13890	Installed/Active	07/17/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13891	Installed/Active	09/10/2012	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13892	Installed/Active	12/27/2012	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13893	Installed/Active	06/03/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
13894	Installed/Active	01/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
13895	Installed/Active	08/16/2011	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13896	Installed/Active	08/12/2004	41V50	RHEEM	\$ 850.00	
13897	Installed/Active	06/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13898	Installed/Active	09/27/2005	LTN050G	LOCHINVAR	\$ 850.00	
13899	Installed/Active	05/13/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
13900	Installed/Active	03/28/2013	FSG50	AO SMITH	\$ 850.00	\$ 12.75
13901	Installed/Active	12/06/2004	XVR50	A. O. SMITH	\$ 850.00	
13902	Installed/Active	05/08/2003	PRX50	STATE	\$ 1,075.00	
13903	Installed/Active	01/25/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
13904	Installed/Active	05/17/1991	21V502	RHEEM	\$ 850.00	
13905	Installed/Active	12/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13906	Installed/Active	03/14/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
13907	Installed/Active	09/20/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
13908	Installed/Active	10/03/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
13909	Installed/Active	01/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13910	Installed/Active	07/09/1991	21V502	RHEEM	\$ 850.00	
13911	Installed/Active	06/02/2005	LTN050	LOCHINVAR	\$ 850.00	
13912	Installed/Active	11/14/1998	41VR50	RHEEM	\$ 850.00	
13913	Installed/Active	08/30/1991	FSG40	AO SMITH	\$ 850.00	
13914	Installed/Active	09/20/2001	PGR50	AO SMITH	\$ 850.00	
13915	Installed/Active	07/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
13916	Installed/Active	02/06/1991	PRV50NODS	STATE	\$ 1,075.00	
13917	Installed/Active	04/11/2003	FSG50	AO SMITH	\$ 850.00	
13918	Installed/Active	09/29/1999	41XR50	RHEEM	\$ 850.00	
13919	Installed/Active	08/30/1991	FSG40	AO SMITH	\$ 850.00	
13920	Installed/Active	12/30/1999	FSG50	AO SMITH	\$ 850.00	
13921	Installed/Active	06/26/2003	FSG40	AO SMITH	\$ 850.00	
13922	Installed/Active	04/08/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
13923	Installed/Active	11/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13924	Installed/Active	04/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
13925	Installed/Active	06/17/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13926	Installed/Active	04/08/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
13927	Installed/Active	01/08/2003	PRX50	STATE	\$ 1,075.00	
13928	Installed/Active	08/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13929	Installed/Active	05/17/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
13930	Installed/Active	06/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13931	Installed/Active	03/23/2001	G75125	RUUD/RHEEM	\$ 1,900.00	
13932	Installed/Active	09/20/2012	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
13933	Installed/Active	11/02/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13934	Installed/Active	12/12/1990	RF67120	RUUD	\$ 1,900.00	
13935	Installed/Active	01/28/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13936	Installed/Active	05/09/2003	CPN13585FS	LOCHINVAR	\$ 3,350.00	
13937	Installed/Active	03/15/2006	PR650XODS	STATE	\$ 1,075.00	
13938	Installed/Active	04/04/2002	PGR50	AO SMITH	\$ 850.00	
13939	Installed/Active	10/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13940	Installed/Active	08/07/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37
13941	Installed/Active	07/10/2008	42VR5040	RHEEM	\$ 850.00	\$ 10.23
13942	Installed/Active	10/13/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13943	Installed/Active	04/02/1996	RF67120	RUUD	\$ 1,900.00	
13944	Installed/Active	10/29/2009	FSG50	AO SMITH	\$ 850.00	\$ 11.74
13945	Installed/Active	01/09/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
13946	Installed/Active	06/17/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13947	Installed/Active	08/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13948	Installed/Active	01/15/2003	FSGT50	AO SMITH	\$ 1,150.00	
13949	Installed/Active	07/29/2005	PRX50	STATE	\$ 1,075.00	
13950	Installed/Active	11/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13951	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
13952	Installed/Active	07/08/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13953	Installed/Active	07/04/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
13954	Installed/Active	12/04/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13955	Installed/Active	10/24/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13956	Installed/Active	08/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13957	Installed/Active	06/15/2012	D71	UNKNOWN	\$ 1,150.00	\$ 17.52
13958	Installed/Active	02/17/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13959	Installed/Active	06/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13960	Installed/Active	02/17/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.05
13961	Installed/Active	03/23/1993	21DV50	RHEEM	\$ 1,075.00	
13962	Installed/Active	11/06/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
13963	Installed/Active	11/26/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 10.23
13964	Installed/Active	10/22/2003	FCV50	AO SMITH	\$ 850.00	
13965	Installed/Active	07/19/2004	PRX50	STATE	\$ 1,075.00	
13966	Installed/Active	04/14/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
13967	Installed/Active	03/08/2003	PRX50	STATE	\$ 1,075.00	
13968	Installed/Active	05/19/1992	FSG50	AO SMITH	\$ 850.00	
13969	Installed/Active	12/10/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
13970	Installed/Active	11/23/2005	PR650	STATE	\$ 1,075.00	
13971	Installed/Active	12/18/2005	GVC50	A. O. SMITH	\$ 850.00	
13972	Installed/Active	08/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13973	Installed/Active	12/31/2003	FCVL40	AO SMITH	\$ 850.00	
13974	Installed/Active	01/04/1993	PRV40NODS	STATE	\$ 1,075.00	
13975	Installed/Active	03/16/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
13976	Installed/Active	02/06/1992	PRV50NODS	STATE	\$ 1,075.00	
13977	Installed/Active	01/04/1993	PRX50	STATE	\$ 1,075.00	
13978	Installed/Active	03/25/2013	DS150S6FBN	Bradford - White	\$ 1,075.00	\$ 17.89
13979	Installed/Active	09/10/1992	P502	RUUD	\$ 850.00	
13980	Installed/Active	01/26/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
13981	Installed/Active	07/06/2004	PRX50	STATE	\$ 1,075.00	
13982	Installed/Active	10/02/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
13983	Installed/Active	11/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13984	Installed/Active	10/30/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
13985	Installed/Active	07/25/1991	FSG50	AO SMITH	\$ 850.00	
13986	Installed/Active	07/21/2003	FSG50	AO SMITH	\$ 850.00	
13987	Installed/Active	07/17/2001	PRX50	STATE	\$ 1,075.00	
13988	Installed/Active	07/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13989	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
13990	Installed/Active	01/15/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
13991	Installed/Active	01/31/1991	FSG50	AO SMITH	\$ 850.00	
13992	Installed/Active	10/15/1991	21V506	RHEEM	\$ 1,150.00	
13993	Installed/Active	11/25/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
13994	Installed/Active	09/27/1991	FSGL40	AO SMITH	\$ 850.00	
13995	Installed/Active	02/26/2003	PRX50	STATE	\$ 1,075.00	
13996	Installed/Active	11/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
13997	Installed/Active	09/13/2005	LTN050G	LOCHINVAR	\$ 850.00	
13998	Installed/Active	01/13/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
13999	Installed/Active	10/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14000	Installed/Active	08/16/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14001	Installed/Active	05/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
14002	Installed/Active	11/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14003	Installed/Active	12/29/2000	41XR50	RHEEM	\$ 850.00	
14004	Installed/Active	04/06/2001	FSG50	AO SMITH	\$ 850.00	
14005	Installed/Active	05/04/2004	PRX50	STATE	\$ 1,075.00	
14006	Installed/Active	09/01/2006	PR640XODS	STATE	\$ 1,075.00	
14007	Installed/Active	02/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14008	Installed/Active	03/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14009	Installed/Active	01/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14010	Installed/Active	01/01/2006	PR650XODS	STATE	\$ 1,075.00	
14011	Installed/Active	03/05/2000	PGR50	AO SMITH	\$ 850.00	
14012	Installed/Active	09/18/2006	FSG30	AO SMITH	\$ 850.00	
14013	Installed/Active	04/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14014	Installed/Active	10/24/2002	FSG50	AO SMITH	\$ 850.00	
14015	Installed/Active	08/24/2004	GVC50	A. O. SMITH	\$ 850.00	
14016	Installed/Active	04/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14017	Installed/Active	09/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14018	Installed/Active	02/27/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14019	Installed/Active	08/24/2004	FCV50	AO SMITH	\$ 850.00	
14020	Installed/Active	01/09/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14021	Installed/Active	02/03/1992	PRV50NODS	STATE	\$ 1,075.00	
14022	Installed/Active	09/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14023	Installed/Active	06/19/1991	FSG50	AO SMITH	\$ 850.00	
14024	Installed/Active	07/19/2000	PGR50	AO SMITH	\$ 850.00	
14025	Installed/Active	07/30/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14026	Installed/Active	01/06/1993	FSG50	AO SMITH	\$ 850.00	
14027	Installed/Active	09/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14028	Installed/Active	06/09/1992	PRX50	STATE	\$ 1,075.00	
14029	Installed/Active	05/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14030	Installed/Active	10/19/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
14031	Installed/Active	09/10/2001	FSG50	AO SMITH	\$ 850.00	
14032	Installed/Active	09/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14033	Installed/Active	08/23/2006	LTN040G	LOCHINVAR	\$ 850.00	
14034	Installed/Active	07/13/2004	GVC50	A. O. SMITH	\$ 850.00	
14035	Installed/Active	03/27/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
14036	Installed/Active	12/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14037	Installed/Active	01/24/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14038	Installed/Active	01/13/2006	LTN050	LOCHINVAR	\$ 850.00	
14039	Installed/Active	09/10/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
14040	Installed/Active	04/04/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
14041	Installed/Active	09/24/2009	GDVS40	AOSMITH	\$ 1,075.00	\$ 16.47
14042	Installed/Active	12/04/2001	FSG50	AO SMITH	\$ 850.00	
14043	Installed/Active	01/10/2001	FSG50	AO SMITH	\$ 850.00	
14044	Installed/Active	12/17/2003	PRX50	STATE	\$ 1,075.00	
14045	Installed/Active	02/04/2013	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
14046	Installed/Active	11/28/2005	21DV50	RHEEM	\$ 1,075.00	
14047	Installed/Active	08/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14048	Installed/Active	12/23/2004	PRX50	STATE	\$ 1,075.00	
14049	Installed/Active	05/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14050	Installed/Active	01/03/1992	FSG50	AO SMITH	\$ 850.00	
14051	Installed/Active	12/17/2008	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
14052	Installed/Active	06/06/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
14053	Installed/Active	01/14/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
14054	Installed/Active	07/28/2004	GVC40	A. O. SMITH	\$ 850.00	
14055	Installed/Active	03/07/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
14056	Installed/Active	12/01/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
14057	Installed/Active	05/14/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14058	Installed/Active	04/09/1992	FSG40	AO SMITH	\$ 850.00	
14059	Installed/Active	12/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14060	Installed/Active	04/07/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14061	Installed/Active	12/25/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
14062	Installed/Active	10/07/2003	FSG50	AO SMITH	\$ 850.00	
14063	Installed/Active	09/08/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
14064	Installed/Active	08/26/1992	PRV50NODS	STATE	\$ 1,075.00	
14065	Installed/Active	12/13/2004	LTN040	LOCHINVAR	\$ 850.00	
14066	Installed/Active	03/27/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14067	Installed/Active	05/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14068	Installed/Active	11/26/2005	LTN050G	LOCHINVAR	\$ 850.00	
14069	Installed/Active	11/16/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
14070	Installed/Active	08/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
14071	Installed/Active	03/08/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
14072	Installed/Active	10/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14073	Installed/Active	08/16/2004	XVR50	A. O. SMITH	\$ 850.00	
14074	Installed/Active	11/11/2001	PRX50	STATE	\$ 1,075.00	
14075	Installed/Active	10/11/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14076	Installed/Active	01/10/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14077	Installed/Active	06/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14078	Installed/Active	07/03/2002	FSG50	AO SMITH	\$ 850.00	
14079	Installed/Active	11/01/1991	RF67120	RUUD	\$ 1,900.00	
14080	Installed/Active	10/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14081	Installed/Active	11/20/2012	FSG40	AO SMITH	\$ 850.00	\$ 12.75
14082	Installed/Active	01/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14083	Installed/Active	12/08/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
14084	Installed/Active	03/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14085	Installed/Active	11/20/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14086	Installed/Active	04/13/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14087	Installed/Active	04/05/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
14088	Installed/Active	02/20/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14089	Installed/Active	04/22/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
14090	Installed/Active	06/07/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14091	Installed/Active	08/21/1997	FGR50	AO SMITH	\$ 850.00	
14092	Installed/Active	02/27/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14093	Installed/Active	04/18/1991	PRX40	STATE	\$ 1,075.00	
14094	Installed/Active	12/18/2003	PRX40	STATE	\$ 1,075.00	
14095	Installed/Active	03/21/1991	FSG50	AO SMITH	\$ 850.00	
14096	Installed/Active	01/28/2001	41XR50	RHEEM	\$ 850.00	
14097	Installed/Active	05/09/2002	FSG50	AO SMITH	\$ 850.00	
14098	Installed/Active	09/20/1998	FGR50	AO SMITH	\$ 850.00	
14099	Installed/Active	02/13/2001	PGR50	AO SMITH	\$ 850.00	
14100	Installed/Active	05/10/2012	21V502	RHEEM	\$ 850.00	\$ 12.64
14101	Installed/Active	05/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14102	Installed/Active	10/06/2000	PRX50	STATE	\$ 1,075.00	
14103	Installed/Active	07/04/2004	PRX50	STATE	\$ 1,075.00	
14104	Installed/Active	05/29/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14105	Installed/Active	11/02/2006	LTN050G	LOCHINVAR	\$ 850.00	
14106	Installed/Active	04/21/2003	PGR50	AO SMITH	\$ 850.00	
14107	Installed/Active	08/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14108	Installed/Active	04/05/2003	FSG50	AO SMITH	\$ 850.00	
14109	Installed/Active	01/17/2001	21V506	RHEEM	\$ 1,150.00	
14110	Installed/Active	01/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14111	Installed/Active	12/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14112	Installed/Active	01/07/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
14113	Installed/Active	08/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14114	Installed/Active	09/07/2010	41V50	RHEEM	\$ 1,150.00	\$ 16.55
14115	Installed/Active	05/29/1991	P502	RUUD	\$ 850.00	
14116	Installed/Active	06/05/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
14117	Installed/Active	06/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14118	Installed/Active	01/25/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14119	Installed/Active	12/23/2000	FSG50	AO SMITH	\$ 850.00	
14120	Installed/Active	05/18/2009	FSG50	AO SMITH	\$ 850.00	\$ 11.74
14121	Installed/Active	06/10/2004	PVR50	AO SMITH	\$ 1,150.00	
14122	Installed/Active	10/10/1991	FSG50	AO SMITH	\$ 850.00	
14123	Installed/Active	04/24/2004	PRX50	STATE	\$ 1,075.00	
14124	Installed/Active	06/18/2003	FSG50	AO SMITH	\$ 850.00	
14125	Installed/Active	09/17/1999	41XR50	RHEEM	\$ 850.00	
14126	Installed/Active	10/04/2011	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14127	Installed/Active	04/15/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14128	Installed/Active	11/08/2006	LTN050G	LOCHINVAR	\$ 1,150.00	
14129	Installed/Active	07/12/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14130	Installed/Active	08/31/2004	GDVS50	AOSMITH	\$ 1,075.00	
14131	Installed/Active	09/20/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14132	Installed/Active	08/11/1992	P502	RUUD	\$ 850.00	
14133	Installed/Active	02/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14134	Installed/Active	09/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14135	Installed/Active	07/02/2002	41V50	RHEEM	\$ 850.00	
14136	Installed/Active	08/11/1992	P502	RUUD	\$ 850.00	
14137	Installed/Active	12/24/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
14138	Installed/Active	02/22/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.37
14139	Installed/Active	10/27/2004	PRX50	STATE	\$ 1,075.00	
14140	Installed/Active	10/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14141	Installed/Active	02/22/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
14142	Installed/Active	10/26/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
14143	Installed/Active	01/14/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
14144	Installed/Active	09/02/1998	FGR50	AO SMITH	\$ 850.00	
14145	Installed/Active	11/01/2012	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
14146	Installed/Active	05/06/2004	PRX50	STATE	\$ 1,075.00	
14147	Installed/Active	08/11/2005	LTN050G	LOCHINVAR	\$ 850.00	
14148	Installed/Active	07/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14149	Installed/Active	01/12/2005	GVR50	AO SMITH	\$ 850.00	
14150	Installed/Active	06/30/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14151	Installed/Active	02/04/1992	FSG50	AO SMITH	\$ 850.00	
14152	Installed/Active	07/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14153	Installed/Active	05/28/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
14154	Installed/Active	07/01/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14155	Installed/Active	01/18/2011	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
14156	Installed/Active	12/09/2011	M1403S6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
14157	Installed/Active	12/28/2006	PR650	STATE	\$ 1,075.00	
14158	Installed/Active	06/24/2005	LTN050	LOCHINVAR	\$ 1,150.00	
14159	Installed/Active	11/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14160	Installed/Active	08/24/2004	XTN050	LOCHINVAR	\$ 850.00	
14161	Installed/Active	02/02/2010	22V50F1	RHEEM	\$ 1,075.00	\$ 16.47
14162	Installed/Active	01/14/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14163	Installed/Active	09/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14164	Installed/Active	03/30/2006	PR650	STATE	\$ 1,075.00	
14165	Installed/Active	02/26/2003	FSG50	AO SMITH	\$ 850.00	
14166	Installed/Active	11/06/2007	FSG50	AO SMITH	\$ 850.00	\$ 10.23
14167	Installed/Active	07/22/2005	FCV40	AO SMITH	\$ 850.00	
14168	Installed/Active	10/18/2000	FSG50	AO SMITH	\$ 850.00	
14169	Installed/Active	05/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14170	Installed/Active	02/08/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14171	Installed/Active	10/01/1991	FSG50	AO SMITH	\$ 850.00	
14172	Installed/Active	11/22/2004	GDVS50	AOSMITH	\$ 1,075.00	
14173	Installed/Active	12/18/2003	PRX50	STATE	\$ 1,075.00	
14174	Installed/Active	02/24/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
14175	Installed/Active	02/13/2004	FSG50	AO SMITH	\$ 850.00	
14176	Installed/Active	04/19/2005	GVC50	A. O. SMITH	\$ 850.00	
14177	Installed/Active	06/09/2005	LTN050	LOCHINVAR	\$ 850.00	
14178	Installed/Active	03/17/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
14179	Installed/Active	10/28/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14180	Installed/Active	01/08/1999	41VR50	RHEEM	\$ 850.00	
14181	Installed/Active	05/18/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
14182	Installed/Active	01/30/2007	GVC50	A. O. SMITH	\$ 850.00	\$ 10.23
14183	Installed/Active	04/07/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14184	Installed/Active	07/05/1991	FSG50	AO SMITH	\$ 850.00	
14185	Installed/Active	11/26/2003	FCV50	AO SMITH	\$ 850.00	
14186	Installed/Active	06/16/1999	21V506	RHEEM	\$ 1,150.00	
14187	Installed/Active	09/12/1991	FSG50	AO SMITH	\$ 850.00	
14188	Installed/Active	09/12/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14189	Installed/Active	04/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
14190	Installed/Active	10/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14191	Installed/Active	07/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14192	Installed/Active	02/01/2005	PRX50	STATE	\$ 1,075.00	
14193	Installed/Active	07/24/2004	PRX50	STATE	\$ 1,075.00	
14194	Installed/Active	05/18/2004	FCV50	AO SMITH	\$ 850.00	
14195	Installed/Active	03/08/1991	P506	RUUD	\$ 1,125.00	
14196	Installed/Active	07/21/2005	LTN040	LOCHINVAR	\$ 850.00	
14197	Installed/Active	12/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14198	Installed/Active	03/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
14199	Installed/Active	08/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14200	Installed/Active	02/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
14201	Installed/Active	10/21/1991	FSG50	AO SMITH	\$ 850.00	
14202	Installed/Active	05/21/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
14203	Installed/Active	03/24/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 11.74
14204	Installed/Active	02/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14205	Installed/Active	05/10/1991	21V506	RHEEM	\$ 1,150.00	
14206	Installed/Active	02/17/1993	PRV50NODS	STATE	\$ 1,075.00	
14207	Installed/Active	10/30/1992	21V407	RHEEM	\$ 850.00	
14208	Installed/Active	08/14/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14209	Installed/Active	10/08/2001	PGR50	AO SMITH	\$ 850.00	
14210	Installed/Active	07/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14211	Installed/Active	02/08/2004	XTN050	LOCHINVAR	\$ 850.00	
14212	Installed/Active	09/03/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14213	Installed/Active	09/29/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14214	Installed/Active	06/07/2006	PR650	STATE	\$ 1,075.00	
14215	Installed/Active	07/09/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14216	Installed/Active	11/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14217	Installed/Active	05/19/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14218	Installed/Active	08/05/1992	FSG50	AO SMITH	\$ 850.00	
14219	Installed/Active	01/31/1993	G67114	RHEEM	\$ 1,900.00	
14220	Installed/Active	10/04/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
14221	Installed/Active	03/14/2005	GVC50	A. O. SMITH	\$ 850.00	
14222	Installed/Active	02/11/2004	XTN050	LOCHINVAR	\$ 850.00	
14223	Installed/Active	02/18/1993	H72DUMMY	AO SMITH	\$ 1,900.00	
14224	Installed/Active	02/12/2002	FSG50	AO SMITH	\$ 850.00	
14225	Installed/Active	09/24/2003	FCVL40	AO SMITH	\$ 850.00	
14226	Installed/Active	05/03/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
14227	Installed/Active	02/19/2004	FSG50	AO SMITH	\$ 1,075.00	
14228	Installed/Active	06/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14229	Installed/Active	07/21/2001	PR650	STATE	\$ 1,075.00	
14230	Installed/Active	07/30/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
14231	Installed/Active	12/12/2008	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
14232	Installed/Active	04/02/2011	42VR50	RHEEM	\$ 850.00	\$ 12.64
14233	Installed/Active	08/02/2001	FSG50	AO SMITH	\$ 850.00	
14234	Installed/Active	10/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14235	Installed/Active	10/24/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14236	Installed/Active	07/26/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
14237	Installed/Active	01/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14238	Installed/Active	07/20/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14239	Installed/Active	07/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14240	Installed/Active	05/28/1992	PRV50NODS	STATE	\$ 1,075.00	
14241	Installed/Active	04/28/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
14242	Installed/Active	11/06/2005	LTN050G	LOCHINVAR	\$ 850.00	
14243	Installed/Active	05/06/2005	GDVS50	AOSMITH	\$ 1,075.00	
14244	Installed/Active	08/08/2001	PGR50	AO SMITH	\$ 850.00	
14245	Installed/Active	08/24/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14246	Installed/Active	08/16/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
14247	Installed/Active	04/18/2005	GVC50	A. O. SMITH	\$ 850.00	
14248	Installed/Active	02/25/2005	21V506	RHEEM	\$ 1,150.00	
14249	Installed/Active	02/20/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14250	Installed/Active	03/21/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
14251	Installed/Active	08/03/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
14252	Installed/Active	08/03/2001	FSG40	AO SMITH	\$ 850.00	
14253	Installed/Active	10/21/2002	FSG50	AO SMITH	\$ 850.00	
14254	Installed/Active	11/22/1991	FSG50	AO SMITH	\$ 850.00	
14255	Installed/Active	12/20/1997	PHR50	RUUD	\$ 850.00	
14256	Installed/Active	07/12/2004	GCVL40	A. O. SMITH	\$ 850.00	
14257	Installed/Active	09/03/2003	FCV50	AO SMITH	\$ 850.00	
14258	Installed/Active	01/28/1999	FSG50	AO SMITH	\$ 850.00	
14259	Installed/Active	08/06/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14260	Installed/Active	10/03/2005	LTN050G	LOCHINVAR	\$ 850.00	
14261	Installed/Active	11/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
14262	Installed/Active	12/01/2010	42VR50	RHEEM	\$ 1,150.00	\$ 16.55
14263	Installed/Active	07/30/2004	PRX50	STATE	\$ 1,075.00	
14264	Installed/Active	09/04/1991	FSG50	AO SMITH	\$ 850.00	
14265	Installed/Active	03/02/2005	PRX50	STATE	\$ 1,075.00	
14266	Installed/Active	10/25/1991	FSG50	AO SMITH	\$ 850.00	
14267	Installed/Active	09/18/2001	PGR50	AO SMITH	\$ 850.00	
14268	Installed/Active	09/10/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14269	Installed/Active	08/23/2006	LTN050G	LOCHINVAR	\$ 850.00	
14270	Installed/Active	11/12/2005	LTN040G	LOCHINVAR	\$ 850.00	
14271	Installed/Active	07/17/2000	PGR50	AO SMITH	\$ 850.00	
14272	Installed/Active	06/01/2002	FSG50	AO SMITH	\$ 850.00	
14273	Installed/Active	08/12/1991	FSG50	AO SMITH	\$ 850.00	
14274	Installed/Active	01/04/2002	PGR50	AO SMITH	\$ 850.00	
14275	Installed/Active	02/18/1999	G76200	RUUD/RHEEM	\$ 3,350.00	
14276	Installed/Active	10/27/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14277	Installed/Active	05/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14278	Installed/Active	09/06/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14279	Installed/Active	02/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
14280	Installed/Active	04/10/2002	PGR50	AO SMITH	\$ 850.00	
14281	Installed/Active	11/20/2004	GVC50	A. O. SMITH	\$ 850.00	
14282	Installed/Active	07/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14283	Installed/Active	08/19/2010	GVC50	A. O. SMITH	\$ 850.00	\$ 12.05
14284	Installed/Active	07/24/1991	FSG50	AO SMITH	\$ 850.00	
14285	Installed/Active	06/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14286	Installed/Active	08/20/2004	XVR50	A. O. SMITH	\$ 850.00	
14287	Installed/Active	07/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14288	Installed/Active	11/28/2012	GVC50	A. O. SMITH	\$ 850.00	\$ 12.75
14289	Installed/Active	10/10/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
14290	Installed/Active	06/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14291	Installed/Active	03/22/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14292	Installed/Active	01/04/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
14293	Installed/Active	10/04/2003	PRX50	STATE	\$ 1,075.00	
14294	Installed/Active	01/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14295	Installed/Active	12/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14296	Installed/Active	12/11/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
14297	Installed/Active	06/14/2003	FSG50	AO SMITH	\$ 850.00	
14298	Installed/Active	12/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14299	Installed/Active	05/29/2002	PRX50	STATE	\$ 1,075.00	
14300	Installed/Active	01/30/1993	H72DUMMY	AO SMITH	\$ 1,900.00	
14301	Installed/Active	09/13/2006	LTN040G	LOCHINVAR	\$ 850.00	
14302	Installed/Active	04/04/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
14303	Installed/Active	07/11/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14304	Installed/Active	07/10/1992	PRV50NODS	STATE	\$ 1,075.00	
14305	Installed/Active	11/03/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
14306	Installed/Active	02/29/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14307	Installed/Active	03/29/2005	XVR50	A. O. SMITH	\$ 850.00	
14308	Installed/Active	09/16/1992	FSG50	AO SMITH	\$ 850.00	
14309	Installed/Active	11/17/2004	GVC50	A. O. SMITH	\$ 850.00	
14310	Installed/Active	04/22/2003	21V506	RHEEM	\$ 850.00	
14311	Installed/Active	07/17/2006	PR650	STATE	\$ 1,075.00	
14312	Installed/Active	09/01/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14313	Installed/Active	05/23/2005	LTN050	LOCHINVAR	\$ 850.00	
14314	Installed/Active	11/20/2002	PGR50	AO SMITH	\$ 850.00	
14315	Installed/Active	10/08/1992	FSG40	AO SMITH	\$ 850.00	
14316	Installed/Active	08/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14317	Installed/Active	04/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14318	Installed/Active	09/24/2001	PRX50	STATE	\$ 1,075.00	
14319	Installed/Active	11/12/1992	FSG50	AO SMITH	\$ 850.00	
14320	Installed/Active	09/18/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
14321	Installed/Active	05/01/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
14322	Installed/Active	07/17/1992	P502	RUUD	\$ 850.00	
14323	Installed/Active	05/08/2005	LTN050	LOCHINVAR	\$ 850.00	
14324	Installed/Active	09/29/2005	LTN050G	LOCHINVAR	\$ 850.00	
14325	Installed/Active	08/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14326	Installed/Active	11/19/1992	FSGL40	AO SMITH	\$ 850.00	
14327	Installed/Active	01/18/2000	PHR40	RUUD	\$ 850.00	
14328	Installed/Active	05/29/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14329	Installed/Active	10/26/2001	PGR50	AO SMITH	\$ 850.00	
14330	Installed/Active	05/27/2005	LTN050	LOCHINVAR	\$ 850.00	
14331	Installed/Active	08/29/2001	PGR40	AO SMITH	\$ 850.00	
14332	Installed/Active	10/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14333	Installed/Active	05/06/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14334	Installed/Active	12/31/2005	PR650	STATE	\$ 1,075.00	
14335	Installed/Active	01/10/2005	GVC50	A. O. SMITH	\$ 850.00	
14336	Installed/Active	07/21/1992	FSGL40	AO SMITH	\$ 850.00	
14337	Installed/Active	04/06/2007	XSN040	LOCHINVAR	\$ 850.00	\$ 10.23
14338	Installed/Active	10/04/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
14339	Installed/Active	04/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14340	Installed/Active	06/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14341	Installed/Active	06/26/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14342	Installed/Active	10/04/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
14343	Installed/Active	01/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14344	Installed/Active	12/20/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
14345	Installed/Active	04/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14346	Installed/Active	10/14/2004	GDVS50	AOSMITH	\$ 1,075.00	
14347	Installed/Active	05/06/1993	P502	RUUD	\$ 850.00	
14348	Installed/Active	10/25/1991	FSG50	AO SMITH	\$ 850.00	
14349	Installed/Active	09/08/1998	FGR40	AO SMITH	\$ 850.00	
14350	Installed/Active	04/25/1991	P506	RUUD	\$ 1,150.00	
14351	Installed/Active	08/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14352	Installed/Active	09/22/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14353	Installed/Active	04/25/1991	P506	RUUD	\$ 1,150.00	
14354	Installed/Active	10/11/2003	PGR50	AO SMITH	\$ 850.00	
14355	Installed/Active	06/14/2003	PRX50	STATE	\$ 1,075.00	
14356	Installed/Active	09/12/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14357	Installed/Active	07/30/2010	LSN041	LOCHINVAR	\$ 850.00	\$ 12.05
14358	Installed/Active	05/06/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14359	Installed/Active	08/07/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14360	Installed/Active	10/20/2006	LSN041G	LOCHINVAR	\$ 850.00	
14361	Installed/Active	11/01/1998	FGR50	AO SMITH	\$ 850.00	
14362	Installed/Active	02/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14363	Installed/Active	02/14/1998	PHR50	RUUD	\$ 850.00	
14364	Installed/Active	06/10/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
14365	Installed/Active	03/28/1991	FSG50	AO SMITH	\$ 850.00	
14366	Installed/Active	02/24/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14367	Installed/Active	11/30/2002	PGR40	AO SMITH	\$ 850.00	
14368	Installed/Active	09/15/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14369	Installed/Active	04/27/2011	G76200	RUUD/RHEEM	\$ 1,125.00	\$ 20.21
14370	Installed/Active	03/26/2001	FSG50	AO SMITH	\$ 850.00	
14371	Installed/Active	08/12/1992	B71DUMMY	AMERICAN	\$ 850.00	
14372	Installed/Active	12/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14373	Installed/Active	02/22/1991	21V502	RHEEM	\$ 850.00	
14374	Installed/Active	03/12/2003	PRX50	STATE	\$ 1,075.00	
14375	Installed/Active	01/03/2000	PRX50	STATE	\$ 1,075.00	
14376	Installed/Active	08/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14377	Installed/Active	07/26/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14378	Installed/Active	04/21/2005	PRX50	STATE	\$ 1,075.00	
14379	Installed/Active	03/11/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
14380	Installed/Active	05/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14381	Installed/Active	09/09/2005	GVC50	A. O. SMITH	\$ 850.00	
14382	Installed/Active	05/01/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
14383	Installed/Active	03/20/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14384	Installed/Active	06/11/1993	FSG50	AO SMITH	\$ 850.00	
14385	Installed/Active	04/25/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
14386	Installed/Active	10/12/1998	FGR50	AO SMITH	\$ 850.00	
14387	Installed/Active	11/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14388	Installed/Active	08/02/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
14389	Installed/Active	07/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14390	Installed/Active	05/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14391	Installed/Active	10/23/1991	PRV50NODS	STATE	\$ 1,075.00	
14392	Installed/Active	09/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14393	Installed/Active	08/04/2003	PVR50	AO SMITH	\$ 850.00	
14394	Installed/Active	03/17/2002	PGR50	AO SMITH	\$ 850.00	
14395	Installed/Active	09/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14396	Installed/Active	10/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14397	Installed/Active	04/10/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
14398	Installed/Active	01/12/1993	FSG50	AO SMITH	\$ 850.00	
14399	Installed/Active	07/23/2004	GVC50	A. O. SMITH	\$ 850.00	
14400	Installed/Active	06/02/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14401	Installed/Active	09/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14402	Installed/Active	11/26/2002	PRX50	STATE	\$ 1,075.00	
14403	Installed/Active	02/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14404	Installed/Active	10/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14405	Installed/Active	05/28/1992	PRX40	STATE	\$ 1,075.00	
14406	Installed/Active	01/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14407	Installed/Active	12/12/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
14408	Installed/Active	12/31/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14409	Installed/Active	12/03/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
14410	Installed/Active	08/07/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14411	Installed/Active	03/27/2002	FSG50	AO SMITH	\$ 850.00	
14412	Installed/Active	06/06/2011	21VR50	RHEEM	\$ 850.00	\$ 12.64
14413	Installed/Active	12/31/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14414	Installed/Active	01/02/2001	PGR50	AO SMITH	\$ 850.00	
14415	Installed/Active	01/05/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
14416	Installed/Active	06/16/2003	41XR50	RHEEM	\$ 850.00	
14417	Installed/Active	03/08/1993	P506	RUUD	\$ 1,125.00	
14418	Installed/Active	05/28/1992	FSG50	AO SMITH	\$ 850.00	
14419	Installed/Active	10/01/2012	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.52
14420	Installed/Active	03/03/1992	FSG50	AO SMITH	\$ 850.00	
14421	Installed/Active	10/03/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
14422	Installed/Active	07/20/1992	RF67120	RUUD	\$ 1,900.00	
14423	Installed/Active	04/24/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14424	Installed/Active	02/22/2007	LTN051G	LOCHINVAR	\$ 850.00	\$ 10.23
14425	Installed/Active	11/21/2012	P502	RUUD	\$ 850.00	\$ 12.75
14426	Installed/Active	02/04/2001	21V506	RHEEM	\$ 1,150.00	
14427	Installed/Active	11/27/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
14428	Installed/Active	07/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14429	Installed/Active	02/18/2005	XVR50	A. O. SMITH	\$ 850.00	
14430	Installed/Active	06/24/2002	FSGL40	AO SMITH	\$ 850.00	
14431	Installed/Active	12/15/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14432	Installed/Active	01/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
14433	Installed/Active	11/26/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14434	Installed/Active	01/16/2002	FSG50	AO SMITH	\$ 850.00	
14435	Installed/Active	01/06/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
14436	Installed/Active	04/02/2012	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
14437	Installed/Active	11/23/2005	LTN050G	LOCHINVAR	\$ 850.00	
14438	Installed/Active	05/11/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14439	Installed/Active	01/26/2001	41XR40	RHEEM	\$ 850.00	
14440	Installed/Active	01/12/2005	GVC50	A. O. SMITH	\$ 850.00	
14441	Installed/Active	01/30/2011	22V50F1	RHEEM	\$ 850.00	\$ 12.05
14442	Installed/Active	01/08/2004	PRX50	STATE	\$ 1,075.00	
14443	Installed/Active	04/28/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
14444	Installed/Active	05/29/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
14445	Installed/Active	11/17/1992	FSG50	AO SMITH	\$ 850.00	
14446	Installed/Active	12/11/1991	PH30	RUUD	\$ 350.00	
14447	Installed/Active	02/26/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
14448	Installed/Active	03/27/2006	LTN050G	LOCHINVAR	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14449	Installed/Active	12/19/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14450	Installed/Active	04/22/1992	21V502	RHEEM	\$ 850.00	
14451	Installed/Active	12/22/1999	FSG50	AO SMITH	\$ 850.00	
14452	Installed/Active	12/23/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14453	Installed/Active	02/16/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14454	Installed/Active	06/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14455	Installed/Active	09/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14456	Installed/Active	02/04/2013	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
14457	Installed/Active	04/10/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
14458	Installed/Active	09/30/2006	LSN041G	LOCHINVAR	\$ 850.00	
14459	Installed/Active	01/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
14460	Installed/Active	04/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
14461	Installed/Active	01/25/1991	P506	RUUD	\$ 1,125.00	
14462	Installed/Active	07/29/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14463	Installed/Active	08/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14464	Installed/Active	07/03/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
14465	Installed/Active	08/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14466	Installed/Active	12/20/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14467	Installed/Active	01/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14468	Installed/Active	06/13/2003	FSG50	AO SMITH	\$ 850.00	
14469	Installed/Active	09/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
14470	Installed/Active	01/09/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
14471	Installed/Active	04/27/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
14472	Installed/Active	08/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14473	Installed/Active	01/26/1991	P506	RUUD	\$ 500.00	
14474	Installed/Active	09/26/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
14475	Installed/Active	01/06/2001	41XR50	RHEEM	\$ 850.00	
14476	Installed/Active	05/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14477	Installed/Active	02/21/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
14478	Installed/Active	04/10/1991	PRV50NODS	STATE	\$ 1,075.00	
14479	Installed/Active	06/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14480	Installed/Active	11/01/1990	41XR40	RHEEM	\$ 850.00	
14481	Installed/Active	01/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14482	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14483	Installed/Active	02/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14484	Installed/Active	09/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 17.52
14485	Installed/Active	08/19/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14486	Installed/Active	06/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14487	Installed/Active	07/09/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
14488	Installed/Active	06/06/2001	FSG50	AO SMITH	\$ 850.00	
14489	Installed/Active	07/08/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
14490	Installed/Active	10/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
14491	Installed/Active	03/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14492	Installed/Active	04/15/2004	PRX50	STATE	\$ 1,075.00	
14493	Installed/Active	04/30/2001	41XR50	RHEEM	\$ 850.00	
14494	Installed/Active	09/25/1996	FGR50	AO SMITH	\$ 850.00	
14495	Installed/Active	05/29/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14496	Installed/Active	08/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14497	Installed/Active	12/18/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14498	Installed/Active	09/21/2004	GVC50	A. O. SMITH	\$ 850.00	
14499	Installed/Active	04/02/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
14500	Installed/Active	01/03/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
14501	Installed/Active	03/12/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14502	Installed/Active	08/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14503	Installed/Active	11/05/1992	21V502	RHEEM	\$ 850.00	
14504	Installed/Active	05/20/1992	FSG50	AO SMITH	\$ 850.00	
14505	Installed/Active	08/27/2007	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 14.05
14506	Installed/Active	07/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14507	Installed/Active	12/18/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14508	Installed/Active	12/16/2003	FCVL40	AO SMITH	\$ 850.00	
14509	Installed/Active	03/28/2003	FSG50	AO SMITH	\$ 850.00	
14510	Installed/Active	12/26/1992	21V502	RHEEM	\$ 850.00	
14511	Installed/Active	11/25/2003	FCV50	AO SMITH	\$ 850.00	
14512	Installed/Active	03/31/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
14513	Installed/Active	09/18/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14514	Installed/Active	06/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
14515	Installed/Active	05/03/2004	G82156	RUUD/RHEEM	\$ 3,350.00	
14516	Installed/Active	08/01/2009	21V407	RHEEM	\$ 850.00	\$ 11.74
14517	Installed/Active	09/16/2006	PR650	STATE	\$ 1,075.00	
14518	Installed/Active	01/28/2010	B71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	\$ 11.74
14519	Installed/Active	08/01/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14520	Installed/Active	07/28/2004	GVC50	A. O. SMITH	\$ 850.00	
14521	Installed/Active	10/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14522	Installed/Active	01/10/2005	PR640	STATE	\$ 1,075.00	
14523	Installed/Active	09/17/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14524	Installed/Active	12/29/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14525	Installed/Active	12/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14526	Installed/Active	07/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14527	Installed/Active	10/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14528	Installed/Active	02/03/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14529	Installed/Active	08/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14530	Installed/Active	03/05/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
14531	Installed/Active	02/10/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14532	Installed/Active	06/26/1992	FSG50	AO SMITH	\$ 850.00	
14533	Installed/Active	05/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14534	Installed/Active	05/25/2011	42VR50	RHEEM	\$ 1,150.00	\$ 17.37

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14535	Installed/Active	05/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14536	Installed/Active	05/28/2003	FSG50	AO SMITH	\$ 850.00	
14537	Installed/Active	10/23/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14538	Installed/Active	03/08/2008	21DV50	RHEEM	\$ 1,075.00	\$ 14.35
14539	Installed/Active	10/22/1999	PHR50	RUUD	\$ 850.00	
14540	Installed/Active	10/26/1993	P506	RUUD	\$ 1,150.00	
14541	Installed/Active	01/12/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14542	Installed/Active	01/10/1998	PHR50	RUUD	\$ 850.00	
14543	Installed/Active	09/18/2010	41VR50	RHEEM	\$ 850.00	\$ 6.04
14544	Installed/Active	11/09/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14545	Installed/Active	07/02/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
14546	Installed/Active	10/25/2003	PRX50	STATE	\$ 1,075.00	
14547	Installed/Active	12/21/2010	21VR40	RHEEM	\$ 850.00	\$ 12.05
14548	Installed/Active	01/02/1999	41VR40	RHEEM	\$ 850.00	
14549	Installed/Active	08/03/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
14550	Installed/Active	09/10/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
14551	Installed/Active	11/27/2007	SBD100199NES	STATE	\$ 3,350.00	\$ 51.80
14552	Installed/Active	07/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14553	Installed/Active	04/22/1996	FGR50	AO SMITH	\$ 850.00	
14554	Installed/Active	06/05/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 8.98
14555	Installed/Active	01/18/2006	LTN040G	LOCHINVAR	\$ 850.00	
14556	Installed/Active	12/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14557	Installed/Active	10/02/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14558	Installed/Active	05/23/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
14559	Installed/Active	10/02/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
14560	Installed/Active	05/16/1996	FGR50	AO SMITH	\$ 850.00	
14561	Installed/Active	08/28/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
14562	Installed/Active	01/13/1998	21VR502T	RHEEM	\$ 850.00	
14563	Installed/Active	01/19/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
14564	Installed/Active	01/14/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14565	Installed/Active	01/06/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14566	Installed/Active	05/31/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
14567	Installed/Active	05/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14568	Installed/Active	08/15/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
14569	Installed/Active	09/30/1993	21V502	RHEEM	\$ 850.00	
14570	Installed/Active	12/07/1999	G76200	RUUD/RHEEM	\$ 3,350.00	
14571	Installed/Active	05/29/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14572	Installed/Active	01/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14573	Installed/Active	08/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14574	Installed/Active	02/21/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
14575	Installed/Active	07/10/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14576	Installed/Active	01/07/1999	FGR40	AO SMITH	\$ 850.00	
14577	Installed/Active	04/25/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
14578	Installed/Active	04/23/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14579	Installed/Active	11/24/1999	PHR40	RUUD	\$ 850.00	
14580	Installed/Active	10/19/2007	PR650	STATE	\$ 1,075.00	\$ 8.98
14581	Installed/Active	11/26/1999	FGR50	AO SMITH	\$ 850.00	
14582	Installed/Active	02/05/1998	21V506	RHEEM	\$ 1,125.00	
14583	Installed/Active	01/19/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
14584	Installed/Active	08/11/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14585	Installed/Active	09/09/1991	BTR197	AO SMITH	\$ 3,350.00	
14586	Installed/Active	12/05/1999	41XR50	RHEEM	\$ 850.00	
14587	Installed/Active	03/21/1991	RF67120	RUUD	\$ 1,900.00	
14588	Installed/Active	11/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14589	Installed/Active	08/08/2012	P230F	RUUD	\$ 850.00	\$ 12.75
14590	Installed/Active	10/01/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14591	Installed/Active	10/31/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
14592	Installed/Active	10/07/1991	FSG50	AO SMITH	\$ 850.00	
14593	Installed/Active	11/13/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14594	Installed/Active	09/12/1991	FSG50	AO SMITH	\$ 850.00	
14595	Installed/Active	05/30/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14596	Installed/Active	12/12/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14597	Installed/Active	01/14/2005	PRX50	STATE	\$ 1,075.00	
14598	Installed/Active	02/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14599	Installed/Active	11/06/1991	PRX50	STATE	\$ 1,075.00	
14600	Installed/Active	01/17/2004	PRX50	STATE	\$ 1,075.00	
14601	Installed/Active	07/30/2003	PGR50	AO SMITH	\$ 850.00	
14602	Installed/Active	12/29/2004	GVC50	A. O. SMITH	\$ 850.00	
14603	Installed/Active	06/04/2012	PH250SF	RUUD	\$ 850.00	\$ 12.75
14604	Installed/Active	01/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14605	Installed/Active	01/29/2004	PRX50	STATE	\$ 1,075.00	
14606	Installed/Active	06/02/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
14607	Installed/Active	05/16/1997	FGR50	AO SMITH	\$ 850.00	
14608	Installed/Active	07/29/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14609	Installed/Active	05/13/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
14610	Installed/Active	02/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14611	Installed/Active	09/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14612	Installed/Active	07/24/1991	FSGL40	AO SMITH	\$ 350.00	
14613	Installed/Active	07/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14614	Installed/Active	05/29/1991	B71DUMMY	AMERICAN	\$ 850.00	
14615	Installed/Active	10/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14616	Installed/Active	06/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14617	Installed/Active	07/18/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14618	Installed/Active	01/16/1992	PRV50NODS	STATE	\$ 1,075.00	
14619	Installed/Active	08/31/2012	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
14620	Installed/Active	06/27/1991	P506	RUUD	\$ 1,150.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14621	Installed/Active	07/25/2011	DH165TSFBN	BRADFORD-WHITE	\$ 1,125.00	\$ 20.21
14622	Installed/Active	08/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
14623	Installed/Active	05/09/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
14624	Installed/Active	04/07/1993	P506	RUUD	\$ 1,125.00	
14625	Installed/Active	02/05/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14626	Installed/Active	10/26/1993	RF67120	RUUD	\$ 1,900.00	
14627	Installed/Active	03/22/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
14628	Installed/Active	09/08/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14629	Installed/Active	06/22/2004	GVC50	A. O. SMITH	\$ 850.00	
14630	Installed/Active	04/09/1993	FSGL40	AO SMITH	\$ 350.00	
14631	Installed/Active	04/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14632	Installed/Active	12/06/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14633	Installed/Active	07/02/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14634	Installed/Active	07/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
14635	Installed/Active	04/14/1993	PRV50NODS	STATE	\$ 1,075.00	
14636	Installed/Active	07/18/2011	PRV50NODS	STATE	\$ 1,075.00	\$ 11.11
14637	Installed/Active	03/10/2009	FSG50	AO SMITH	\$ 850.00	\$ 5.88
14638	Installed/Active	10/23/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14639	Installed/Active	04/07/1993	FSGL40	AO SMITH	\$ 350.00	
14640	Installed/Active	01/13/2000	FGR40	AO SMITH	\$ 850.00	
14641	Installed/Active	08/30/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
14642	Installed/Active	02/27/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
14643	Installed/Active	07/21/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
14644	Installed/Active	08/30/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
14645	Installed/Active	08/05/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
14646	Installed/Active	05/07/2009	I72DUMMY	RHEEM	\$ 3,350.00	\$ 59.45
14647	Installed/Active	01/13/2006	LTN050G	LOCHINVAR	\$ 850.00	
14648	Installed/Active	09/24/2004	PRX50	STATE	\$ 1,075.00	
14649	Installed/Active	12/09/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
14650	Installed/Active	02/17/1993	FSG50	AO SMITH	\$ 850.00	
14651	Installed/Active	12/19/2001	41V50	RHEEM	\$ 850.00	
14652	Installed/Active	10/22/1993	FGR50	AO SMITH	\$ 850.00	
14653	Installed/Active	02/04/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
14654	Installed/Active	05/06/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14655	Installed/Active	02/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14656	Installed/Active	06/15/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
14657	Installed/Active	07/12/1996	FGR50	AO SMITH	\$ 850.00	
14658	Installed/Active	01/21/1999	PHR50	RUUD	\$ 850.00	
14659	Installed/Active	11/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14660	Installed/Active	11/10/2005	LTN051G	LOCHINVAR	\$ 850.00	
14661	Installed/Active	09/15/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14662	Installed/Active	11/22/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14663	Installed/Active	11/30/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
14664	Installed/Active	03/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14665	Installed/Active	02/29/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14666	Installed/Active	03/19/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
14667	Installed/Active	02/26/2013	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14668	Installed/Active	07/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14669	Installed/Active	05/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14670	Installed/Active	07/11/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14671	Installed/Active	04/21/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14672	Installed/Active	12/16/1991	FSG40	AO SMITH	\$ 850.00	
14673	Installed/Active	06/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14674	Installed/Active	08/17/1992	FSG50	AO SMITH	\$ 850.00	
14675	Installed/Active	01/05/2004	FCV50	AO SMITH	\$ 850.00	
14676	Installed/Active	06/08/1992	FSGL40	AO SMITH	\$ 850.00	
14677	Installed/Active	02/18/2004	FCV50	AO SMITH	\$ 850.00	
14678	Installed/Active	09/18/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14679	Installed/Active	03/23/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
14680	Installed/Active	04/17/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14681	Installed/Active	08/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14682	Installed/Active	04/14/2010	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
14683	Installed/Active	05/26/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
14684	Installed/Active	02/12/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
14685	Installed/Active	08/25/2003	FSG50	AO SMITH	\$ 850.00	
14686	Installed/Active	02/03/1993	21V502	RHEEM	\$ 850.00	
14687	Installed/Active	02/27/2006	PRV50NODS	STATE	\$ 1,075.00	
14688	Installed/Active	06/19/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14689	Installed/Active	12/27/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14690	Installed/Active	07/20/2001	PRX50	STATE	\$ 1,075.00	
14691	Installed/Active	05/14/1992	FSG50	AO SMITH	\$ 850.00	
14692	Installed/Active	03/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14693	Installed/Active	09/21/1992	P502	RUUD	\$ 850.00	
14694	Installed/Active	05/04/2012	PH250SF	RUUD	\$ 850.00	\$ 12.64
14695	Installed/Active	12/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
14696	Installed/Active	08/05/2006	PR650	STATE	\$ 1,075.00	
14697	Installed/Active	11/06/2002	FSG50	AO SMITH	\$ 850.00	
14698	Installed/Active	11/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
14699	Installed/Active	06/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14700	Installed/Active	11/24/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14701	Installed/Active	08/20/2012	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14702	Installed/Active	04/15/2006	PR650	STATE	\$ 1,075.00	
14703	Installed/Active	01/02/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14704	Installed/Active	06/11/2004	XTN050	LOCHINVAR	\$ 850.00	
14705	Installed/Active	11/19/2002	41V40	RHEEM	\$ 850.00	
14706	Installed/Active	04/22/2002	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14707	Installed/Active	06/11/1992	PRX50	STATE	\$ 1,075.00	
14708	Installed/Active	12/15/2006	22DV50C	RHEEM	\$ 1,075.00	
14709	Installed/Active	12/04/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
14710	Installed/Active	12/12/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14711	Installed/Active	12/20/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
14712	Installed/Active	09/01/1998	PHR50	RUUD	\$ 850.00	
14713	Installed/Active	01/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14714	Installed/Active	10/22/1991	FSG40	AO SMITH	\$ 850.00	
14715	Installed/Active	05/10/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
14716	Installed/Active	12/02/2002	FSGT50	AO SMITH	\$ 1,150.00	
14717	Installed/Active	02/01/1999	PR650	STATE	\$ 1,075.00	
14718	Installed/Active	09/07/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14719	Installed/Active	11/12/1991	B71DUMMY	AMERICAN	\$ 850.00	
14720	Installed/Active	11/22/2005	PRV50NODS	STATE	\$ 1,075.00	
14721	Installed/Active	08/22/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14722	Installed/Active	01/14/2013	MIS0L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14723	Installed/Active	06/20/2006	ETN076	LOCHINVAR	\$ 1,900.00	
14724	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14725	Installed/Active	02/15/2005	XVR50	A. O. SMITH	\$ 850.00	
14726	Installed/Active	07/12/1991	FSG50	AO SMITH	\$ 850.00	
14727	Installed/Active	11/03/2004	GVC50	A. O. SMITH	\$ 850.00	
14728	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14729	Installed/Active	03/18/1991	FSG50	AO SMITH	\$ 850.00	
14730	Installed/Active	02/22/2002	PGR50	AO SMITH	\$ 850.00	
14731	Installed/Active	09/07/2005	GVC50	A. O. SMITH	\$ 850.00	
14732	Installed/Active	05/25/1998	FSG50	AO SMITH	\$ 850.00	
14733	Installed/Active	04/23/1991	FSG50	AO SMITH	\$ 850.00	
14734	Installed/Active	11/07/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14735	Installed/Active	02/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14736	Installed/Active	12/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14737	Installed/Active	03/01/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
14738	Installed/Active	06/15/2001	FSG40	AO SMITH	\$ 850.00	
14739	Installed/Active	07/09/2001	FSG40	AO SMITH	\$ 850.00	
14740	Installed/Active	11/01/1991	PRX50	STATE	\$ 1,075.00	
14741	Installed/Active	11/01/1991	FSG50	AO SMITH	\$ 850.00	
14742	Installed/Active	01/12/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
14743	Installed/Active	07/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14744	Installed/Active	07/17/1991	P506	RUUD	\$ 1,150.00	
14745	Installed/Active	02/17/2010	21V502	RHEEM	\$ 850.00	\$ 11.74
14746	Installed/Active	02/10/2005	GVC50	A. O. SMITH	\$ 850.00	
14747	Installed/Active	03/18/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14748	Installed/Active	06/17/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
14749	Installed/Active	05/14/2008	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
14750	Installed/Active	05/20/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14751	Installed/Active	05/18/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
14752	Installed/Active	07/22/2005	LTN050	LOCHINVAR	\$ 850.00	
14753	Installed/Active	12/06/1999	PR650	STATE	\$ 1,075.00	
14754	Installed/Active	12/02/1993	RF67120	RUUD	\$ 1,900.00	
14755	Installed/Active	04/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
14756	Installed/Active	06/18/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14757	Installed/Active	01/18/1999	PRV40NODS	STATE	\$ 1,075.00	
14758	Installed/Active	07/18/1996	PR502T	RUUD	\$ 850.00	
14759	Installed/Active	12/07/1999	PHR50	RUUD	\$ 850.00	
14760	Installed/Active	07/03/2004	XVR50	A. O. SMITH	\$ 850.00	
14761	Installed/Active	07/30/1996	FGR50	AO SMITH	\$ 850.00	
14762	Installed/Active	02/18/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
14763	Installed/Active	06/25/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14764	Installed/Active	02/11/1998	PHR50	RUUD	\$ 850.00	
14765	Installed/Active	01/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14766	Installed/Active	06/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14767	Installed/Active	01/10/2004	XTN040	LOCHINVAR	\$ 850.00	
14768	Installed/Active	02/13/1998	PHR50	RUUD	\$ 850.00	
14769	Installed/Active	11/28/2012	FSG40	AO SMITH	\$ 850.00	\$ 6.39
14770	Installed/Active	01/03/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14771	Installed/Active	06/29/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.88
14772	Installed/Active	07/31/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14773	Installed/Active	12/06/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14774	Installed/Active	12/13/1999	41VR50	RHEEM	\$ 850.00	
14775	Installed/Active	08/29/2005	LTN050G	LOCHINVAR	\$ 850.00	
14776	Installed/Active	05/25/1993	P506	RUUD	\$ 1,125.00	
14777	Installed/Active	02/01/1999	41VR50	RHEEM	\$ 850.00	
14778	Installed/Active	08/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14779	Installed/Active	10/14/2002	BTR198	AO SMITH	\$ 3,350.00	
14780	Installed/Active	02/16/1998	FGR50	AO SMITH	\$ 850.00	
14781	Installed/Active	01/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14782	Installed/Active	05/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14783	Installed/Active	03/10/2004	G76200	RUUD/RHEEM	\$ 3,350.00	
14784	Installed/Active	07/12/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14785	Installed/Active	11/28/2002	PRX50	STATE	\$ 1,075.00	
14786	Installed/Active	06/02/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
14787	Installed/Active	06/14/2002	PGR50	AO SMITH	\$ 850.00	
14788	Installed/Active	08/22/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14789	Installed/Active	06/16/2008	22DV5038	RHEEM	\$ 1,075.00	\$ 8.98
14790	Installed/Active	11/21/2003	PRX50	STATE	\$ 1,075.00	
14791	Installed/Active	02/20/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14792	Installed/Active	09/08/2001	FSG50	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14793	Installed/Active	01/09/2003	PGR50	AO SMITH	\$ 850.00	
14794	Installed/Active	04/14/2008	SBF100199NES	STATE	\$ 3,350.00	\$ 51.80
14795	Installed/Active	10/22/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
14796	Installed/Active	08/09/1992	21V502	RHEEM	\$ 850.00	
14797	Installed/Active	06/14/2004	GVC50	AO SMITH	\$ 850.00	
14798	Installed/Active	07/02/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14799	Installed/Active	08/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14800	Installed/Active	12/15/1999	BTR154	AO SMITH	\$ 3,350.00	
14801	Installed/Active	10/13/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14802	Installed/Active	09/04/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14803	Installed/Active	08/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14804	Installed/Active	12/16/1999	FGR50	AO SMITH	\$ 850.00	
14805	Installed/Active	11/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14806	Installed/Active	08/25/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14807	Installed/Active	09/24/1992	PRV50NODS	STATE	\$ 1,075.00	
14808	Installed/Active	01/31/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14809	Installed/Active	11/17/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14810	Installed/Active	05/12/1992	P506	RUUD	\$ 1,150.00	
14811	Installed/Active	12/20/2003	FCVL40	AO SMITH	\$ 850.00	
14812	Installed/Active	06/04/2003	FSG40	AO SMITH	\$ 850.00	
14813	Installed/Active	05/11/2005	LTN050	LOCHINVAR	\$ 850.00	
14814	Installed/Active	11/17/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14815	Installed/Active	04/30/1992	21V506	RHEEM	\$ 1,150.00	
14816	Installed/Active	02/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14817	Installed/Active	09/19/2003	21V506	RHEEM	\$ 1,150.00	
14818	Installed/Active	06/09/2005	LTN040	LOCHINVAR	\$ 850.00	
14819	Installed/Active	10/14/1992	FSG50	AO SMITH	\$ 850.00	
14820	Installed/Active	05/10/2003	PGR50	AO SMITH	\$ 850.00	
14821	Installed/Active	07/26/2011	42V5065F	RHEEM	\$ 1,150.00	\$ 17.37
14822	Installed/Active	12/20/2001	FSG50	AO SMITH	\$ 850.00	
14823	Installed/Active	10/10/2005	LTN050G	LOCHINVAR	\$ 850.00	
14824	Installed/Active	12/03/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14825	Installed/Active	05/12/2011	42V5065F	RHEEM	\$ 850.00	\$ 12.64
14826	Installed/Active	07/13/2004	GVC50	A. O. SMITH	\$ 850.00	
14827	Installed/Active	09/08/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14828	Installed/Active	08/13/2003	FSG40	AO SMITH	\$ 850.00	
14829	Installed/Active	07/28/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
14830	Installed/Active	09/11/1992	P506	RUUD	\$ 1,125.00	
14831	Installed/Active	01/13/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
14832	Installed/Active	05/02/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
14833	Installed/Active	06/25/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14834	Installed/Active	03/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14835	Installed/Active	09/30/2001	PGR50	AO SMITH	\$ 850.00	
14836	Installed/Active	08/28/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
14837	Installed/Active	04/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
14838	Installed/Active	01/04/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
14839	Installed/Active	05/05/2003	PRX50	STATE	\$ 1,075.00	
14840	Installed/Active	06/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
14841	Installed/Active	05/24/1999	FGR50	AO SMITH	\$ 850.00	
14842	Installed/Active	10/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
14843	Installed/Active	12/30/2011	D71	UNKNOW	\$ 1,150.00	\$ 17.37
14844	Installed/Active	10/30/1997	PRV50NODS	STATE	\$ 1,075.00	
14845	Installed/Active	03/13/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14846	Installed/Active	10/21/1992	FSG50	AO SMITH	\$ 850.00	
14847	Installed/Active	12/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14848	Installed/Active	02/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14849	Installed/Active	02/20/1992	H72DUMMY	AO SMITH	\$ 1,900.00	
14850	Installed/Active	08/27/2003	PVR50	AO SMITH	\$ 850.00	
14851	Installed/Active	05/02/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
14852	Installed/Active	12/23/1991	FSG50	AO SMITH	\$ 850.00	
14853	Installed/Active	05/23/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
14854	Installed/Active	02/27/2004	FCV40	AO SMITH	\$ 850.00	
14855	Installed/Active	05/30/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14856	Installed/Active	06/01/2005	LTN050G	LOCHINVAR	\$ 850.00	
14857	Installed/Active	04/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14858	Installed/Active	04/26/2001	FSG50	AO SMITH	\$ 850.00	
14859	Installed/Active	08/11/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14860	Installed/Active	02/28/2013	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
14861	Installed/Active	01/14/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14862	Installed/Active	01/12/1999	FGR50	AO SMITH	\$ 850.00	
14863	Installed/Active	09/06/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
14864	Installed/Active	07/17/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14865	Installed/Active	12/30/1999	FGR40	AO SMITH	\$ 850.00	
14866	Installed/Active	07/28/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
14867	Installed/Active	11/22/2005	PR650	STATE	\$ 1,075.00	
14868	Installed/Active	12/07/2007	PR650	STATE	\$ 1,075.00	\$ 8.98
14869	Installed/Active	12/29/1992	21DV50	RHEEM	\$ 1,075.00	
14870	Installed/Active	11/09/2005	LTN050G	LOCHINVAR	\$ 850.00	
14871	Installed/Active	07/15/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
14872	Installed/Active	04/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14873	Installed/Active	03/03/1998	FGR40	AO SMITH	\$ 850.00	
14874	Installed/Active	11/18/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
14875	Installed/Active	10/03/2002	FSG50	AO SMITH	\$ 850.00	
14876	Installed/Active	11/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
14877	Installed/Active	09/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14878	Installed/Active	05/13/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14879	Installed/Active	03/04/1998	FGR50	AO SMITH	\$ 850.00	
14880	Installed/Active	08/14/2001	FSG50	AO SMITH	\$ 850.00	
14881	Installed/Active	03/04/1993	FSGL40	AO SMITH	\$ 850.00	
14882	Installed/Active	09/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14883	Installed/Active	01/16/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
14884	Installed/Active	06/05/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
14885	Installed/Active	09/25/1996	FGR50	AO SMITH	\$ 850.00	
14886	Installed/Active	11/23/2009	LSN041G	LOCHINVAR	\$ 850.00	\$ 11.74
14887	Installed/Active	02/05/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14888	Installed/Active	04/30/2004	G82156	RUUD/RHEEM	\$ 3,350.00	
14889	Installed/Active	04/30/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
14890	Installed/Active	03/18/2000	PRV50NODS	STATE	\$ 1,075.00	
14891	Installed/Active	08/20/1996	FGR50	AO SMITH	\$ 850.00	
14892	Installed/Active	11/04/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14893	Installed/Active	04/30/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
14894	Installed/Active	04/14/2008	SBD100199NES	STATE	\$ 3,350.00	\$ 51.80
14895	Installed/Active	09/04/1996	FGR50	AO SMITH	\$ 850.00	
14896	Installed/Active	01/10/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
14897	Installed/Active	05/20/2005	PR650	STATE	\$ 1,075.00	
14898	Installed/Active	09/28/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
14899	Installed/Active	02/17/1999	PHR50	RUUD	\$ 850.00	
14900	Installed/Active	10/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
14901	Installed/Active	11/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14902	Installed/Active	01/11/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
14903	Installed/Active	06/28/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14904	Installed/Active	02/18/1999	G76200	RUUD/RHEEM	\$ 3,350.00	
14905	Installed/Active	12/27/2005	PR640	STATE	\$ 1,075.00	
14906	Installed/Active	06/27/2007	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.12
14907	Installed/Active	09/30/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14908	Installed/Active	06/20/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
14909	Installed/Active	04/01/2003	FSG50	AO SMITH	\$ 850.00	
14910	Installed/Active	06/02/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
14911	Installed/Active	10/02/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14912	Installed/Active	03/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14913	Installed/Active	06/02/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
14914	Installed/Active	12/11/2006	LTN051G	LOCHINVAR	\$ 1,150.00	
14915	Installed/Active	09/20/1991	D74DUMMY	AO SMITH	\$ 1,900.00	
14916	Installed/Active	03/10/2010	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
14917	Installed/Active	02/16/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
14918	Installed/Active	10/14/2003	PGR50	AO SMITH	\$ 850.00	
14919	Installed/Active	10/04/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
14920	Installed/Active	09/29/2011	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14921	Installed/Active	01/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14922	Installed/Active	02/11/1991	FSG50	AO SMITH	\$ 850.00	
14923	Installed/Active	07/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14924	Installed/Active	10/24/2002	FSG50	AO SMITH	\$ 850.00	
14925	Installed/Active	08/02/2005	LTN050	LOCHINVAR	\$ 850.00	
14926	Installed/Active	06/02/2005	LTN050	LOCHINVAR	\$ 850.00	
14927	Installed/Active	05/20/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
14928	Installed/Active	09/26/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
14929	Installed/Active	11/16/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
14930	Installed/Active	03/11/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14931	Installed/Active	04/22/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14932	Installed/Active	05/29/2004	21DV50	RHEEM	\$ 1,075.00	
14933	Installed/Active	07/27/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14934	Installed/Active	10/06/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
14935	Installed/Active	12/28/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14936	Installed/Active	08/12/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
14937	Installed/Active	04/25/2012	PH250SF	RUUD	\$ 850.00	\$ 12.64
14938	Installed/Active	07/10/2002	FSG50	AO SMITH	\$ 850.00	
14939	Installed/Active	10/02/2005	PR650	STATE	\$ 1,075.00	
14940	Installed/Active	04/19/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
14941	Installed/Active	05/13/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14942	Installed/Active	11/21/1991	G67114	RHEEM	\$ 1,900.00	
14943	Installed/Active	09/13/1991	P506	RUUD	\$ 1,125.00	
14944	Installed/Active	02/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14945	Installed/Active	09/21/2004	PRX50	STATE	\$ 1,075.00	
14946	Installed/Active	05/06/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
14947	Installed/Active	01/31/1991	FSG50	AO SMITH	\$ 850.00	
14948	Installed/Active	03/03/2006	LTN050G	LOCHINVAR	\$ 850.00	
14949	Installed/Active	05/08/2006	LSN041G	LOCHINVAR	\$ 850.00	
14950	Installed/Active	07/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
14951	Installed/Active	07/24/2001	FSG50	AO SMITH	\$ 850.00	
14952	Installed/Active	10/04/2002	PRX50	STATE	\$ 1,075.00	
14953	Installed/Active	11/03/1993	FSGL40	AO SMITH	\$ 850.00	
14954	Installed/Active	10/21/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14955	Installed/Active	09/16/1996	FGR40	AO SMITH	\$ 850.00	
14956	Installed/Active	02/06/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
14957	Installed/Active	08/09/2001	41V50	RHEEM	\$ 850.00	
14958	Installed/Active	06/28/2004	GVC50	A. O. SMITH	\$ 850.00	
14959	Installed/Active	10/21/2011	21V502	RHEEM	\$ 850.00	\$ 12.64
14960	Installed/Active	09/17/1996	21VR502T	RHEEM	\$ 850.00	
14961	Installed/Active	02/21/2008	21DV50	RHEEM	\$ 1,075.00	\$ 8.98
14962	Installed/Active	09/18/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
14963	Installed/Active	07/27/2004	GVC50	A. O. SMITH	\$ 850.00	
14964	Installed/Active	08/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
14965	Installed/Active	03/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14966	Installed/Active	05/01/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14967	Installed/Active	10/08/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
14968	Installed/Active	09/15/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
14969	Installed/Active	02/15/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
14970	Installed/Active	08/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14971	Installed/Active	03/29/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
14972	Installed/Active	04/26/1994	RFD91200	RUUD	\$ 3,350.00	
14973	Installed/Active	02/09/1993	P502	RUUD	\$ 850.00	
14974	Installed/Active	03/25/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
14975	Installed/Active	01/26/2005	ETN076	LOCHINVAR	\$ 1,900.00	
14976	Installed/Active	08/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
14977	Installed/Active	03/25/1998	41VR50	RHEEM	\$ 850.00	
14978	Installed/Active	10/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
14979	Installed/Active	02/08/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 5.88
14980	Installed/Active	11/04/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
14981	Installed/Active	10/13/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
14982	Installed/Active	02/01/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
14983	Installed/Active	04/28/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14984	Installed/Active	05/01/2005	LTN050	LOCHINVAR	\$ 850.00	
14985	Installed/Active	12/22/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
14986	Installed/Active	08/28/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
14987	Installed/Active	01/13/2000	41VR40	RHEEM	\$ 850.00	
14988	Installed/Active	03/30/1998	FGR40	AO SMITH	\$ 850.00	
14989	Installed/Active	02/17/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
14990	Installed/Active	11/19/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14991	Installed/Active	01/12/2000	FGR50	AO SMITH	\$ 850.00	
14992	Installed/Active	02/19/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
14993	Installed/Active	03/16/1994	RFD91200	RUUD	\$ 3,350.00	
14994	Installed/Active	10/24/2010	42V75F	RHEEM	\$ 1,179.00	\$ 39.36
14995	Installed/Active	10/22/1996	PR502T	RUUD	\$ 850.00	
14996	Installed/Active	03/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
14997	Installed/Active	07/19/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
14998	Installed/Active	07/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
14999	Installed/Active	10/04/1999	BTR120	AO SMITH	\$ 1,900.00	
15000	Installed/Active	02/11/2009	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
15001	Installed/Active	10/06/2006	PR650	STATE	\$ 1,075.00	
15002	Installed/Active	01/04/2006	LTN050	LOCHINVAR	\$ 850.00	
15003	Installed/Active	08/06/1992	FSG50	AO SMITH	\$ 850.00	
15004	Installed/Active	03/04/1993	GVF8533T	RUUD	\$ 850.00	
15005	Installed/Active	11/14/2006	PR650X0DS	STATE	\$ 1,075.00	
15006	Installed/Active	04/18/2006	PR650	STATE	\$ 1,075.00	
15007	Installed/Active	09/18/1992	FSG50	AO SMITH	\$ 850.00	
15008	Installed/Active	07/15/2003	PRX50	STATE	\$ 1,075.00	
15009	Installed/Active	03/16/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15010	Installed/Active	02/16/2005	GVC50	A. O. SMITH	\$ 850.00	
15011	Installed/Active	01/13/2004	XTN050	LOCHINVAR	\$ 850.00	
15012	Installed/Active	04/04/2002	PGR50	AO SMITH	\$ 850.00	
15013	Installed/Active	10/24/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
15014	Installed/Active	08/05/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15015	Installed/Active	02/23/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15016	Installed/Active	01/20/2000	PHR50	RUUD	\$ 850.00	
15017	Installed/Active	12/17/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
15018	Installed/Active	12/20/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15019	Installed/Active	11/11/1998	41XR50	RHEEM	\$ 850.00	
15020	Installed/Active	11/03/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
15021	Installed/Active	12/06/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15022	Installed/Active	06/23/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
15023	Installed/Active	12/17/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
15024	Installed/Active	12/20/1991	FSG40	AO SMITH	\$ 850.00	
15025	Installed/Active	08/12/2003	PRX50	STATE	\$ 1,075.00	
15026	Installed/Active	12/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15027	Installed/Active	12/17/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
15028	Installed/Active	06/23/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
15029	Installed/Active	11/29/2005	LTN051G	LOCHINVAR	\$ 1,150.00	
15030	Installed/Active	10/27/2002	FSG50	AO SMITH	\$ 850.00	
15031	Installed/Active	01/05/1999	FSG50	AO SMITH	\$ 850.00	
15032	Installed/Active	01/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15033	Installed/Active	12/30/1991	FSGL40	AO SMITH	\$ 850.00	
15034	Installed/Active	08/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15035	Installed/Active	05/18/2002	FSG50	AO SMITH	\$ 850.00	
15036	Installed/Active	05/16/2000	41XR50	RHEEM	\$ 850.00	
15037	Installed/Active	05/28/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15038	Installed/Active	05/07/2012	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15039	Installed/Active	09/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15040	Installed/Active	07/30/1992	FSG50	AO SMITH	\$ 850.00	
15041	Installed/Active	02/27/2007	42V6050	RHEEM	\$ 1,125.00	\$ 16.35
15042	Installed/Active	06/16/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15043	Installed/Active	10/15/2005	LTN050G	LOCHINVAR	\$ 850.00	
15044	Installed/Active	10/22/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15045	Installed/Active	03/06/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15046	Installed/Active	06/06/2005	PR650	STATE	\$ 1,075.00	
15047	Installed/Active	06/28/2003	PVR50	AO SMITH	\$ 850.00	
15048	Installed/Active	06/15/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
15049	Installed/Active	02/06/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
15050	Installed/Active	12/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15051	Installed/Active	01/31/1991	FSG50	AO SMITH	\$ 850.00	
15052	Installed/Active	04/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15053	Installed/Active	06/20/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15054	Installed/Active	02/28/1999	FGR50	AO SMITH	\$ 850.00	
15055	Installed/Active	05/18/1993	FSG50	AO SMITH	\$ 850.00	
15056	Installed/Active	08/22/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15057	Installed/Active	06/08/2011	42VR5040F	RHEEM	\$ 850.00	\$ 6.34
15058	Installed/Active	04/27/1993	FSG50	AO SMITH	\$ 850.00	
15059	Installed/Active	02/09/1994	FGR50	AO SMITH	\$ 850.00	
15060	Installed/Active	04/13/2003	G91200	RUUD/RHEEM	\$ 3,350.00	
15061	Installed/Active	07/12/1993	21V502	RHEEM	\$ 850.00	
15062	Installed/Active	10/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15063	Installed/Active	03/30/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15064	Installed/Active	02/26/1993	P502	RUUD	\$ 850.00	
15065	Installed/Active	01/12/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
15066	Installed/Active	10/17/2002	PRX50	STATE	\$ 1,075.00	
15067	Installed/Active	09/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15068	Installed/Active	02/08/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
15069	Installed/Active	01/18/2000	41XR40	RHEEM	\$ 850.00	
15070	Installed/Active	10/27/2009	21V502	RHEEM	\$ 850.00	\$ 11.74
15071	Installed/Active	02/23/1999	41VR50	RHEEM	\$ 850.00	
15072	Installed/Active	03/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15073	Installed/Active	01/09/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15074	Installed/Active	02/25/2005	PRX50	STATE	\$ 1,075.00	
15075	Installed/Active	03/22/1993	21V506	RHEEM	\$ 1,150.00	
15076	Installed/Active	09/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15077	Installed/Active	12/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15078	Installed/Active	09/06/2005	LTN050	LOCHINVAR	\$ 1,150.00	
15079	Installed/Active	02/09/1993	FSG50	AO SMITH	\$ 850.00	
15080	Installed/Active	07/31/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15081	Installed/Active	03/14/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15082	Installed/Active	08/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15083	Installed/Active	04/24/1998	FGR50	AO SMITH	\$ 850.00	
15084	Installed/Active	11/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15085	Installed/Active	03/18/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
15086	Installed/Active	12/07/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15087	Installed/Active	02/01/2000	FGR50	AO SMITH	\$ 850.00	
15088	Installed/Active	03/05/1999	PHR50	RUUD	\$ 850.00	
15089	Installed/Active	09/20/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15090	Installed/Active	08/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15091	Installed/Active	06/25/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15092	Installed/Active	01/15/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
15093	Installed/Active	03/27/2003	PGR50	AO SMITH	\$ 850.00	
15094	Installed/Active	04/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15095	Installed/Active	03/27/2011	41VR50	RHEEM	\$ 850.00	\$ 6.04
15096	Installed/Active	02/03/2000	PRV50NODS	STATE	\$ 1,075.00	
15097	Installed/Active	06/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15098	Installed/Active	05/05/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15099	Installed/Active	07/26/2005	21DV50	RHEEM	\$ 1,075.00	
15100	Installed/Active	10/17/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15101	Installed/Active	05/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15102	Installed/Active	04/01/1994	F72DUMMY	AO SMITH	\$ 3,350.00	
15103	Installed/Active	09/21/2010	41VR50	RHEEM	\$ 850.00	\$ 6.04
15104	Installed/Active	01/12/2004	PVR50	AO SMITH	\$ 850.00	
15105	Installed/Active	04/01/1994	F72DUMMY	AO SMITH	\$ 3,350.00	
15106	Installed/Active	06/10/2000	FSG50	AO SMITH	\$ 850.00	
15107	Installed/Active	04/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15108	Installed/Active	10/31/1996	FGR50	AO SMITH	\$ 850.00	
15109	Installed/Active	02/04/2000	FGR50	AO SMITH	\$ 850.00	
15110	Installed/Active	10/28/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
15111	Installed/Active	12/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15112	Installed/Active	08/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15113	Installed/Active	07/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15114	Installed/Active	09/29/2011	PH250SF	RUUD	\$ 850.00	\$ 6.34
15115	Installed/Active	06/08/2006	LTN040G	LOCHINVAR	\$ 850.00	
15116	Installed/Active	03/10/1999	41VR50	RHEEM	\$ 850.00	
15117	Installed/Active	08/01/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
15118	Installed/Active	06/17/2006	LTN050G	LOCHINVAR	\$ 850.00	
15119	Installed/Active	03/12/1999	41VR50	RHEEM	\$ 850.00	
15120	Installed/Active	09/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
15121	Installed/Active	11/26/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15122	Installed/Active	05/04/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15123	Installed/Active	04/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15124	Installed/Active	11/11/2004	GVC50	A. O. SMITH	\$ 850.00	
15125	Installed/Active	01/30/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15126	Installed/Active	02/11/2000	PHR50	RUUD	\$ 850.00	
15127	Installed/Active	07/07/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15128	Installed/Active	10/27/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15129	Installed/Active	07/12/1993	FSG50	AO SMITH	\$ 850.00	
15130	Installed/Active	11/10/2008	SBF100199NES	STATE	\$ 3,350.00	\$ 59.45
15131	Installed/Active	05/21/2003	PGR50	AO SMITH	\$ 850.00	
15132	Installed/Active	10/20/2008	SBF100199NES	STATE	\$ 3,350.00	\$ 51.80
15133	Installed/Active	05/26/1993	FSG50	AO SMITH	\$ 850.00	
15134	Installed/Active	03/23/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
15135	Installed/Active	01/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
15136	Installed/Active	10/20/2004	FSG30	AO SMITH	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15137	Installed/Active	06/22/1992	FSG50	AO SMITH	\$ 850.00	
15138	Installed/Active	10/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15139	Installed/Active	01/19/1993	21V502	RHEEM	\$ 850.00	
15140	Installed/Active	03/24/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15141	Installed/Active	12/21/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
15142	Installed/Active	07/09/1993	PRV50NODS	STATE	\$ 1,075.00	
15143	Installed/Active	06/19/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15144	Installed/Active	07/27/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15145	Installed/Active	11/14/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
15146	Installed/Active	02/05/2005	XVR40	A. O. SMITH	\$ 850.00	
15147	Installed/Active	10/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
15148	Installed/Active	02/15/1993	FSG50	AO SMITH	\$ 850.00	
15149	Installed/Active	02/22/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15150	Installed/Active	11/11/2003	PRX50	STATE	\$ 1,075.00	
15151	Installed/Active	09/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15152	Installed/Active	10/25/2000	FSGL40	AO SMITH	\$ 350.00	
15153	Installed/Active	03/04/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
15154	Installed/Active	03/12/2000	41XR50	RHEEM	\$ 850.00	
15155	Installed/Active	01/21/2002	PRX50	STATE	\$ 1,075.00	
15156	Installed/Active	11/15/2004	GVC50	A. O. SMITH	\$ 850.00	
15157	Installed/Active	06/27/2009	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
15158	Installed/Active	02/13/2002	FSG50	AO SMITH	\$ 850.00	
15159	Installed/Active	08/31/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15160	Installed/Active	01/19/2005	GVR50	AO SMITH	\$ 850.00	
15161	Installed/Active	04/12/1993	PRV50NODS	STATE	\$ 1,075.00	
15162	Installed/Active	11/14/2002	FSG50	AO SMITH	\$ 850.00	
15163	Installed/Active	01/21/2009	B71DUMMY	UNKNOWN AT CONVERSION	\$ 850.00	\$ 11.74
15164	Installed/Active	04/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15165	Installed/Active	07/30/1993	21DV50	RHEEM	\$ 1,075.00	
15166	Installed/Active	01/09/2006	LTN050G	LOCHINVAR	\$ 850.00	
15167	Installed/Active	11/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15168	Installed/Active	04/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15169	Installed/Active	12/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
15170	Installed/Active	03/11/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
15171	Installed/Active	03/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15172	Installed/Active	11/21/2002	PRX50	STATE	\$ 1,075.00	
15173	Installed/Active	07/09/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
15174	Installed/Active	08/04/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 12.05
15175	Installed/Active	07/07/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15176	Installed/Active	02/18/2006	LTN050G	LOCHINVAR	\$ 850.00	
15177	Installed/Active	11/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15178	Installed/Active	05/04/1998	PRV50NODS	STATE	\$ 1,075.00	
15179	Installed/Active	04/29/1993	H72DUMMY	AO SMITH	\$ 1,900.00	
15180	Installed/Active	08/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15181	Installed/Active	11/22/2002	FSG50	AO SMITH	\$ 850.00	
15182	Installed/Active	08/03/2006	FGR40	AO SMITH	\$ 850.00	
15183	Installed/Active	01/09/2002	PRX50	STATE	\$ 1,075.00	
15184	Installed/Active	04/15/1994	RFD91200	RUUD	\$ 3,350.00	
15185	Installed/Active	01/14/2005	XVR50	A. O. SMITH	\$ 850.00	
15186	Installed/Active	01/08/1997	PR502T	RUUD	\$ 850.00	
15187	Installed/Active	03/19/1999	FGR50	AO SMITH	\$ 850.00	
15188	Installed/Active	05/07/1998	41VR40	RHEEM	\$ 850.00	
15189	Installed/Active	01/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
15190	Installed/Active	01/21/2012	M175S6FBN	BRADFORD-WHITE	\$ 1,900.00	\$ 41.30
15191	Installed/Active	12/21/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
15192	Installed/Active	08/31/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15193	Installed/Active	01/18/2013	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
15194	Installed/Active	03/19/1998	FGR50	AO SMITH	\$ 850.00	
15195	Installed/Active	04/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15196	Installed/Active	02/18/2000	FGR50	AO SMITH	\$ 850.00	
15197	Installed/Active	02/05/2007	PR650XODS	STATE	\$ 1,075.00	\$ 14.35
15198	Installed/Active	07/30/2004	XTN050	LOCHINVAR	\$ 850.00	
15199	Installed/Active	05/05/1993	H72DUMMY	AO SMITH	\$ 1,900.00	
15200	Installed/Active	01/04/2005	LTN050	LOCHINVAR	\$ 850.00	
15201	Installed/Active	03/19/1998	FGR50	AO SMITH	\$ 850.00	
15202	Installed/Active	09/25/2003	PVR50	AO SMITH	\$ 850.00	
15203	Installed/Active	01/24/2001	41VR50	RHEEM	\$ 850.00	
15204	Installed/Active	03/10/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
15205	Installed/Active	01/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15206	Installed/Active	06/03/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15207	Installed/Active	04/30/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15208	Installed/Active	02/23/2000	PR650	STATE	\$ 1,075.00	
15209	Installed/Active	08/07/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15210	Installed/Active	07/20/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
15211	Installed/Active	05/26/2006	PR650	STATE	\$ 1,075.00	
15212	Installed/Active	02/23/2000	FGR40	AO SMITH	\$ 850.00	
15213	Installed/Active	02/08/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
15214	Installed/Active	09/03/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
15215	Installed/Active	02/25/2000	FGR40	AO SMITH	\$ 850.00	
15216	Installed/Active	03/11/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.38
15217	Installed/Active	11/17/2003	PVR50	AO SMITH	\$ 850.00	
15218	Installed/Active	08/04/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15219	Installed/Active	05/06/1994	FGR50	AO SMITH	\$ 850.00	
15220	Installed/Active	07/28/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15221	Installed/Active	02/25/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
15222	Installed/Active	03/07/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15223	Installed/Active	07/07/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 11.11
15224	Installed/Active	03/06/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15225	Installed/Active	03/01/2000	41XR50	RHEEM	\$ 850.00	
15226	Installed/Active	07/15/1993	PRV50NODS	STATE	\$ 1,075.00	
15227	Installed/Active	05/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
15228	Installed/Active	11/15/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
15229	Installed/Active	08/23/2003	PRX50	STATE	\$ 1,075.00	
15230	Installed/Active	04/06/2011	21VR40	RHEEM	\$ 850.00	\$ 12.64
15231	Installed/Active	08/11/2006	LTN050G	LOCHINVAR	\$ 850.00	
15232	Installed/Active	05/22/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
15233	Installed/Active	03/31/2011	21VR40	RHEEM	\$ 850.00	\$ 12.05
15234	Installed/Active	09/25/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15235	Installed/Active	03/17/2001	41XR50	RHEEM	\$ 850.00	
15236	Installed/Active	02/26/1993	FSG50	AO SMITH	\$ 850.00	
15237	Installed/Active	06/20/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15238	Installed/Active	11/07/2005	PR650	STATE	\$ 1,075.00	
15239	Installed/Active	01/24/2011	LTN040G	LOCHINVAR	\$ 850.00	\$ 12.05
15240	Installed/Active	11/18/1992	FSG50	AO SMITH	\$ 850.00	
15241	Installed/Active	12/18/2001	PGR50	AO SMITH	\$ 850.00	
15242	Installed/Active	07/11/2006	PR650	STATE	\$ 1,075.00	
15243	Installed/Active	08/21/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
15244	Installed/Active	03/24/1993	21V506	RHEEM	\$ 1,150.00	
15245	Installed/Active	08/23/2002	PGR50	AO SMITH	\$ 850.00	
15246	Installed/Active	04/06/2005	GVC50	A. O. SMITH	\$ 850.00	
15247	Installed/Active	07/20/2001	FSG50	AO SMITH	\$ 850.00	
15248	Installed/Active	01/10/1992	FSG50	AO SMITH	\$ 850.00	
15249	Installed/Active	01/10/2010	21V502	RHEEM	\$ 850.00	\$ 11.74
15250	Installed/Active	04/06/2005	GVC50	A. O. SMITH	\$ 850.00	
15251	Installed/Active	10/14/2006	LSN041G	LOCHINVAR	\$ 850.00	
15252	Installed/Active	04/11/2006	PR650	STATE	\$ 1,075.00	
15253	Installed/Active	02/01/1993	FSG50	AO SMITH	\$ 850.00	
15254	Installed/Active	04/08/2003	PRX50	STATE	\$ 1,075.00	
15255	Installed/Active	11/08/2005	PR650	STATE	\$ 1,075.00	
15256	Installed/Active	03/19/2011	21VR50	RHEEM	\$ 850.00	\$ 12.05
15257	Installed/Active	03/14/2012	P502	RUUD	\$ 850.00	\$ 12.64
15258	Installed/Active	05/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15259	Installed/Active	05/28/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
15260	Installed/Active	08/11/1992	PRV50NODS	STATE	\$ 1,075.00	
15261	Installed/Active	11/26/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15262	Installed/Active	08/20/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15263	Installed/Active	12/05/2012	MI75S6FBN	BRADFORD-WHITE	\$ 3,350.00	\$ 55.60
15264	Installed/Active	10/29/2002	PRX50	STATE	\$ 1,075.00	
15265	Installed/Active	06/01/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15266	Installed/Active	10/22/2004	GCVL40	A. O. SMITH	\$ 850.00	
15267	Installed/Active	12/30/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
15268	Installed/Active	12/01/2004	GDVS50	AOSMITH	\$ 1,075.00	
15269	Installed/Active	08/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
15270	Installed/Active	03/17/2004	FCV50	AO SMITH	\$ 850.00	
15271	Installed/Active	01/19/2006	GVC50	A. O. SMITH	\$ 850.00	
15272	Installed/Active	03/26/2006	LTN050G	LOCHINVAR	\$ 850.00	
15273	Installed/Active	02/01/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15274	Installed/Active	09/25/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15275	Installed/Active	11/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15276	Installed/Active	11/19/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
15277	Installed/Active	01/14/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15278	Installed/Active	08/20/2005	LTN050	LOCHINVAR	\$ 850.00	
15279	Installed/Active	11/19/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
15280	Installed/Active	01/05/2006	21DV50	RHEEM	\$ 1,075.00	
15281	Installed/Active	07/10/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15282	Installed/Active	06/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15283	Installed/Active	12/15/2011	PR407	RUUD	\$ 850.00	\$ 6.34
15284	Installed/Active	03/26/1999	FGR40	AO SMITH	\$ 850.00	
15285	Installed/Active	05/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15286	Installed/Active	10/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15287	Installed/Active	03/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15288	Installed/Active	03/27/1999	PHR40	RUUD	\$ 850.00	
15289	Installed/Active	11/10/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15290	Installed/Active	10/04/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
15291	Installed/Active	12/30/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15292	Installed/Active	04/20/1999	PR650	STATE	\$ 1,075.00	
15293	Installed/Active	01/28/1997	FGR50	AO SMITH	\$ 350.00	
15294	Installed/Active	05/19/1994	F72DUMMY	AO SMITH	\$ 3,350.00	
15295	Installed/Active	08/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15296	Installed/Active	11/16/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15297	Installed/Active	04/01/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
15298	Installed/Active	01/13/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
15299	Installed/Active	08/24/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15300	Installed/Active	03/30/1999	41VR50	RHEEM	\$ 850.00	
15301	Installed/Active	03/18/1993	21V502	RHEEM	\$ 850.00	
15302	Installed/Active	05/19/1998	FGR50	AO SMITH	\$ 850.00	
15303	Installed/Active	04/22/2011	41VR50	RHEEM	\$ 850.00	\$ 6.34
15304	Installed/Active	05/14/2004	G75125	RUUD/RHEEM	\$ 3,350.00	
15305	Installed/Active	12/30/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
15306	Installed/Active	06/20/2006	LTN050G	LOCHINVAR	\$ 850.00	
15307	Installed/Active	05/14/2004	G75125	RUUD/RHEEM	\$ 3,350.00	
15308	Installed/Active	02/15/2000	PHR50	RUUD	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15309	Installed/Active	05/21/1998	FGR50	AO SMITH	\$ 850.00	
15310	Installed/Active	10/26/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15311	Installed/Active	10/25/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15312	Installed/Active	02/15/2008	LSN041	LOCHINVAR	\$ 850.00	\$ 5.12
15313	Installed/Active	05/13/2004	PRX50	STATE	\$ 1,075.00	
15314	Installed/Active	03/09/2000	41XR50	RHEEM	\$ 850.00	
15315	Installed/Active	07/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15316	Installed/Active	10/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15317	Installed/Active	04/06/1999	21V407	RHEEM	\$ 350.00	
15318	Installed/Active	12/17/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
15319	Installed/Active	09/20/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
15320	Installed/Active	10/03/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
15321	Installed/Active	02/03/2010	21V502	RHEEM	\$ 850.00	\$ 11.74
15322	Installed/Active	08/01/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15323	Installed/Active	03/16/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
15324	Installed/Active	02/11/1997	PRV50NODS	STATE	\$ 1,075.00	
15325	Installed/Active	11/09/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
15326	Installed/Active	06/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15327	Installed/Active	03/02/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
15328	Installed/Active	04/07/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
15329	Installed/Active	06/01/1998	41VR50	RHEEM	\$ 850.00	
15330	Installed/Active	01/10/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15331	Installed/Active	12/30/2012	FGR50	AO SMITH	\$ 850.00	\$ 6.39
15332	Installed/Active	05/05/2006	LTN040GEF	LOCHINVAR	\$ 850.00	
15333	Installed/Active	04/01/2008	G75125	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15334	Installed/Active	02/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15335	Installed/Active	07/17/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15336	Installed/Active	12/02/2004	GVC50	A. O. SMITH	\$ 850.00	
15337	Installed/Active	10/25/2004	GVC50	A. O. SMITH	\$ 850.00	
15338	Installed/Active	06/21/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15339	Installed/Active	05/01/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15340	Installed/Active	12/04/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
15341	Installed/Active	02/20/1997	PR502T	RUUD	\$ 850.00	
15342	Installed/Active	05/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15343	Installed/Active	12/15/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15344	Installed/Active	05/02/2007	SBD100199NES	STATE	\$ 3,350.00	\$ 51.80
15345	Installed/Active	06/18/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
15346	Installed/Active	02/04/2011	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15347	Installed/Active	01/11/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15348	Installed/Active	02/27/1997	G67114	RHEEM	\$ 1,900.00	
15349	Installed/Active	12/29/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15350	Installed/Active	02/15/2008	PR650	STATE	\$ 1,075.00	\$ 5.12
15351	Installed/Active	01/27/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15352	Installed/Active	12/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15353	Installed/Active	05/27/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15354	Installed/Active	11/06/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15355	Installed/Active	07/25/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15356	Installed/Active	07/21/2005	PR650	STATE	\$ 1,075.00	
15357	Installed/Active	03/18/2000	41XR50	RHEEM	\$ 850.00	
15358	Installed/Active	11/26/2003	FCV50	AO SMITH	\$ 850.00	
15359	Installed/Active	11/18/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
15360	Installed/Active	09/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15361	Installed/Active	04/29/1999	41VR50	RHEEM	\$ 850.00	
15362	Installed/Active	09/05/2002	G91200	RUUD/RHEEM	\$ 3,350.00	
15363	Installed/Active	01/27/2006	LTN050G	LOCHINVAR	\$ 850.00	
15364	Installed/Active	10/05/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15365	Installed/Active	11/02/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15366	Installed/Active	07/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15367	Installed/Active	08/01/2002	FSG50	AO SMITH	\$ 850.00	
15368	Installed/Active	12/14/2005	PR650	STATE	\$ 1,075.00	
15369	Installed/Active	02/07/2006	PR650	STATE	\$ 1,075.00	
15370	Installed/Active	03/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15371	Installed/Active	04/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15372	Installed/Active	01/05/2004	XVR50	A. O. SMITH	\$ 1,150.00	
15373	Installed/Active	04/21/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
15374	Installed/Active	08/12/2000	41XR50	RHEEM	\$ 850.00	
15375	Installed/Active	07/16/1992	21V502	RHEEM	\$ 850.00	
15376	Installed/Active	11/21/2009	LTN051G	LOCHINVAR	\$ 1,150.00	\$ 16.12
15377	Installed/Active	09/24/1993	FSG50	AO SMITH	\$ 850.00	
15378	Installed/Active	06/14/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
15379	Installed/Active	03/25/2005	XVR50	A. O. SMITH	\$ 850.00	
15380	Installed/Active	06/28/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.05
15381	Installed/Active	03/15/2006	LTN050G	LOCHINVAR	\$ 850.00	
15382	Installed/Active	10/24/2006	PR650	STATE	\$ 1,075.00	
15383	Installed/Active	04/27/2001	G82156	RUUD/RHEEM	\$ 3,350.00	
15384	Installed/Active	07/18/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
15385	Installed/Active	01/07/2005	GDVS50	AOSMITH	\$ 1,075.00	
15386	Installed/Active	12/18/2006	LTN040G	LOCHINVAR	\$ 850.00	
15387	Installed/Active	11/20/1992	P502	RUUD	\$ 850.00	
15388	Installed/Active	04/16/2004	PVR50	AO SMITH	\$ 850.00	
15389	Installed/Active	02/19/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15390	Installed/Active	12/20/2004	LTN050	LOCHINVAR	\$ 850.00	
15391	Installed/Active	12/11/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15392	Installed/Active	09/16/2002	PGR50	AO SMITH	\$ 850.00	
15393	Installed/Active	02/04/2009	FSGL40	AO SMITH	\$ 350.00	\$ 14.35
15394	Installed/Active	10/10/2001	G91200	RUUD/RHEEM	\$ 3,350.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15395	Installed/Active	04/27/2006	G91200	RUUD/RHEEM	\$ 3,350.00	
15396	Installed/Active	07/06/2010	21DV50	RHEEM	\$ 1,075.00	\$ 16.91
15397	Installed/Active	02/07/2006	ETN076	LOCHINVAR	\$ 1,900.00	
15398	Installed/Active	09/25/1992	FSG50	AO SMITH	\$ 850.00	
15399	Installed/Active	05/06/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15400	Installed/Active	03/14/2006	PR650	STATE	\$ 1,075.00	
15401	Installed/Active	02/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15402	Installed/Active	04/28/2003	FSG50	AO SMITH	\$ 1,125.00	
15403	Installed/Active	09/23/1992	SBF100199NET	STATE	\$ 3,350.00	
15404	Installed/Active	11/17/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
15405	Installed/Active	06/01/1992	P502	RUUD	\$ 850.00	
15406	Installed/Active	03/02/2002	PRX50	STATE	\$ 1,075.00	
15407	Installed/Active	09/14/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15408	Installed/Active	03/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15409	Installed/Active	04/29/1999	41VR50	RHEEM	\$ 850.00	
15410	Installed/Active	01/11/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15411	Installed/Active	09/06/2006	G75125	RUUD/RHEEM	\$ 1,900.00	
15412	Installed/Active	03/22/2000	41XR50	RHEEM	\$ 850.00	
15413	Installed/Active	06/08/2001	PGR50	AO SMITH	\$ 850.00	
15414	Installed/Active	11/12/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15415	Installed/Active	07/17/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15416	Installed/Active	05/10/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
15417	Installed/Active	12/29/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15418	Installed/Active	05/23/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
15419	Installed/Active	03/20/1997	PR502T	RUUD	\$ 850.00	
15420	Installed/Active	04/21/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15421	Installed/Active	07/27/1994	FGR50	AO SMITH	\$ 850.00	
15422	Installed/Active	12/09/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15423	Installed/Active	03/27/2000	PHR50	RUUD	\$ 850.00	
15424	Installed/Active	10/24/2005	G75125	RUUD/RHEEM	\$ 1,900.00	
15425	Installed/Active	06/23/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
15426	Installed/Active	01/10/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15427	Installed/Active	04/21/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
15428	Installed/Active	10/09/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15429	Installed/Active	05/18/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15430	Installed/Active	09/27/2011	PH250SF	RUUD	\$ 850.00	\$ 12.64
15431	Installed/Active	01/14/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15432	Installed/Active	05/12/1999	FGR50	AO SMITH	\$ 850.00	
15433	Installed/Active	05/17/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15434	Installed/Active	05/26/1993	FSG50	AO SMITH	\$ 850.00	
15435	Installed/Active	11/18/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15436	Installed/Active	07/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15437	Installed/Active	05/10/1999	G75125	RUUD/RHEEM	\$ 1,900.00	
15438	Installed/Active	03/15/2000	41XR50	RHEEM	\$ 850.00	
15439	Installed/Active	03/23/1997	H72DUMMY	AO SMITH	\$ 1,900.00	
15440	Installed/Active	04/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15441	Installed/Active	01/26/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15442	Installed/Active	09/24/2009	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
15443	Installed/Active	07/19/2004	GVC40	A. O. SMITH	\$ 850.00	
15444	Installed/Active	04/16/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
15445	Installed/Active	03/07/2007	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
15446	Installed/Active	10/12/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
15447	Installed/Active	02/03/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 16.91
15448	Installed/Active	03/18/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
15449	Installed/Active	02/02/2000	G75125	RUUD/RHEEM	\$ 1,900.00	
15450	Installed/Active	01/21/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 11.74
15451	Installed/Active	03/11/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
15452	Installed/Active	10/25/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15453	Installed/Active	08/17/1994	FGR50	AO SMITH	\$ 850.00	
15454	Installed/Active	01/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15455	Installed/Active	11/03/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15456	Installed/Active	02/28/2000	41XR50	RHEEM	\$ 850.00	
15457	Installed/Active	10/24/2010	41VR50	RHEEM	\$ 850.00	\$ 6.04
15458	Installed/Active	01/13/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
15459	Installed/Active	01/15/1992	21V502	RHEEM	\$ 850.00	
15460	Installed/Active	09/15/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15461	Installed/Active	12/23/2005	GVC50	A. O. SMITH	\$ 850.00	
15462	Installed/Active	12/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15463	Installed/Active	01/23/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15464	Installed/Active	09/21/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15465	Installed/Active	08/05/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
15466	Installed/Active	07/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15467	Installed/Active	09/02/2011	M15036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.37
15468	Installed/Active	10/16/2009	21DV50	RHEEM	\$ 1,075.00	\$ 16.47
15469	Installed/Active	11/15/2002	G82156	RUUD/RHEEM	\$ 3,350.00	
15470	Installed/Active	05/16/2001	PGR50	AO SMITH	\$ 850.00	
15471	Installed/Active	09/23/1992	FSG50	AO SMITH	\$ 850.00	
15472	Installed/Active	06/20/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
15473	Installed/Active	02/27/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15474	Installed/Active	11/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
15475	Installed/Active	05/14/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
15476	Installed/Active	01/04/2007	LTN040G	LOCHINVAR	\$ 850.00	
15477	Installed/Active	07/20/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15478	Installed/Active	07/22/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15479	Installed/Active	03/09/2004	FCV40	AO SMITH	\$ 850.00	
15480	Installed/Active	02/19/2013	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15481	Installed/Active	07/27/2006	LTN050G	LOCHINVAR	\$ 1,150.00	
15482	Installed/Active	07/09/2010	FCV50	AO SMITH	\$ 850.00	\$ 16.55
15483	Installed/Active	05/08/1992	FSG50	AO SMITH	\$ 850.00	
15484	Installed/Active	06/03/2003	FSG50	AO SMITH	\$ 850.00	
15485	Installed/Active	12/22/2006	PR650X0DS	STATE	\$ 1,075.00	
15486	Installed/Active	05/05/2005	FSG50	AO SMITH	\$ 850.00	
15487	Installed/Active	12/28/2006	LTN050G	LOCHINVAR	\$ 850.00	
15488	Installed/Active	05/11/2001	PR650	STATE	\$ 1,075.00	
15489	Installed/Active	07/05/2004	GVC50	A. O. SMITH	\$ 850.00	
15490	Installed/Active	12/18/1992	21DV50	RHEEM	\$ 1,075.00	
15491	Installed/Active	03/07/2006	21V506	RHEEM	\$ 1,150.00	
15492	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15493	Installed/Active	04/21/2002	FSGL40	AO SMITH	\$ 850.00	
15494	Installed/Active	06/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15495	Installed/Active	10/25/2001	FSG50	AO SMITH	\$ 850.00	
15496	Installed/Active	06/12/2005	21V502	RHEEM	\$ 350.00	
15497	Installed/Active	12/04/2002	PGR50	AO SMITH	\$ 850.00	
15498	Installed/Active	10/21/2004	G75125	RUUD/RHEEM	\$ 1,900.00	
15499	Installed/Active	03/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15500	Installed/Active	10/28/2003	PGR50	AO SMITH	\$ 850.00	
15501	Installed/Active	04/26/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
15502	Installed/Active	03/15/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.74
15503	Installed/Active	03/15/2001	FSG50	AO SMITH	\$ 850.00	
15504	Installed/Active	01/04/2004	PRX50	STATE	\$ 1,075.00	
15505	Installed/Active	11/05/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
15506	Installed/Active	06/23/1998	41VR50	RHEEM	\$ 850.00	
15507	Installed/Active	10/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15508	Installed/Active	06/18/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
15509	Installed/Active	11/15/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
15510	Installed/Active	02/12/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
15511	Installed/Active	06/23/1998	FGR50	AO SMITH	\$ 850.00	
15512	Installed/Active	11/04/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15513	Installed/Active	09/10/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
15514	Installed/Active	03/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15515	Installed/Active	06/27/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15516	Installed/Active	05/14/1999	FGR50	AO SMITH	\$ 850.00	
15517	Installed/Active	03/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15518	Installed/Active	09/07/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15519	Installed/Active	10/29/2009	PR650	STATE	\$ 1,075.00	\$ 10.31
15520	Installed/Active	06/30/1998	41VR50	RHEEM	\$ 850.00	
15521	Installed/Active	08/30/2007	CPN199100	LOCHINVAR	\$ 3,350.00	\$ 51.80
15522	Installed/Active	04/09/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15523	Installed/Active	04/02/1997	BTC197	AO SMITH	\$ 3,350.00	
15524	Installed/Active	08/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15525	Installed/Active	03/08/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15526	Installed/Active	04/18/2000	PHR50	RUUD	\$ 850.00	
15527	Installed/Active	08/15/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15528	Installed/Active	06/21/1998	41VR50	RHEEM	\$ 850.00	
15529	Installed/Active	09/20/2012	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.52
15530	Installed/Active	04/04/2000	PGR50	AO SMITH	\$ 850.00	
15531	Installed/Active	01/14/2005	GVC50	A. O. SMITH	\$ 850.00	
15532	Installed/Active	07/09/1998	FGR50	AO SMITH	\$ 850.00	
15533	Installed/Active	08/04/1994	FGR50	AO SMITH	\$ 850.00	
15534	Installed/Active	04/04/2006	PR650	STATE	\$ 1,075.00	
15535	Installed/Active	09/19/1998	FSG50	AO SMITH	\$ 850.00	
15536	Installed/Active	10/19/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
15537	Installed/Active	11/29/1994	PRV50NODS	STATE	\$ 1,075.00	
15538	Installed/Active	12/15/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15539	Installed/Active	04/07/1997	21VR502T	RHEEM	\$ 850.00	
15540	Installed/Active	08/18/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15541	Installed/Active	03/16/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15542	Installed/Active	08/04/1993	21DV50	RHEEM	\$ 1,075.00	
15543	Installed/Active	08/19/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15544	Installed/Active	09/21/1994	FGR50	AO SMITH	\$ 850.00	
15545	Installed/Active	08/11/2005	LTN050	LOCHINVAR	\$ 850.00	
15546	Installed/Active	04/15/1997	FGR50	AO SMITH	\$ 1,125.00	
15547	Installed/Active	10/02/1994	FGR50	AO SMITH	\$ 850.00	
15548	Installed/Active	09/18/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15549	Installed/Active	01/08/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15550	Installed/Active	04/24/2000	PRX50	STATE	\$ 1,075.00	
15551	Installed/Active	02/16/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15552	Installed/Active	11/24/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15553	Installed/Active	01/13/2006	LTN050	LOCHINVAR	\$ 850.00	
15554	Installed/Active	09/10/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15555	Installed/Active	03/08/2006	42VR5040	RHEEM	\$ 850.00	
15556	Installed/Active	04/28/2000	FGR50	AO SMITH	\$ 850.00	
15557	Installed/Active	05/20/1999	G91200	RUUD/RHEEM	\$ 3,350.00	
15558	Installed/Active	07/15/1998	FGR50	AO SMITH	\$ 850.00	
15559	Installed/Active	05/31/2011	42VR5040F	RHEEM	\$ 850.00	\$ 6.34
15560	Installed/Active	03/06/2006	LTN050G	LOCHINVAR	\$ 850.00	
15561	Installed/Active	04/29/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15562	Installed/Active	09/17/2011	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15563	Installed/Active	12/09/2008	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
15564	Installed/Active	02/28/2005	GVC50	A. O. SMITH	\$ 850.00	
15565	Installed/Active	04/25/1997	PR407	RUUD	\$ 850.00	
15566	Installed/Active	04/28/1997	G91200	RUUD/RHEEM	\$ 3,350.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15567	Installed/Active	01/18/2009	PH13080	PHOENIX	\$ 3,350.00	\$ 59.45
15568	Installed/Active	09/30/2010	41VR50	RHEEM	\$ 850.00	\$ 12.05
15569	Installed/Active	11/07/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15570	Installed/Active	01/21/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15571	Installed/Active	02/19/2001	G91200	RUUD/RHEEM	\$ 3,350.00	
15572	Installed/Active	05/02/2000	41XR40	RHEEM	\$ 850.00	
15573	Installed/Active	05/24/1999	41VR50	RHEEM	\$ 850.00	
15574	Installed/Active	10/05/2011	41V50	RHEEM	\$ 1,125.00	\$ 20.21
15575	Installed/Active	08/18/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
15576	Installed/Active	05/02/2000	FGR40	AO SMITH	\$ 850.00	
15577	Installed/Active	03/03/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15578	Installed/Active	05/03/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
15579	Installed/Active	01/28/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15580	Installed/Active	11/05/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15581	Installed/Active	10/27/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15582	Installed/Active	02/14/2002	PRX50	STATE	\$ 850.00	
15583	Installed/Active	05/26/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
15584	Installed/Active	06/01/1999	FGR50	AO SMITH	\$ 850.00	
15585	Installed/Active	12/05/1994	FGR50	AO SMITH	\$ 850.00	
15586	Installed/Active	05/05/2000	FSG50	AO SMITH	\$ 850.00	
15587	Installed/Active	04/30/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15588	Installed/Active	02/03/2012	41VR50	RHEEM	\$ 850.00	\$ 6.34
15589	Installed/Active	01/30/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15590	Installed/Active	02/22/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15591	Installed/Active	06/02/1999	FGR50	AO SMITH	\$ 850.00	
15592	Installed/Active	02/22/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15593	Installed/Active	04/22/2005	LTN050G	LOCHINVAR	\$ 850.00	
15594	Installed/Active	03/19/2003	FSG50	AO SMITH	\$ 850.00	
15595	Installed/Active	09/16/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15596	Installed/Active	04/28/2001	PRX50	STATE	\$ 1,075.00	
15597	Installed/Active	06/02/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
15598	Installed/Active	12/05/2011	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15599	Installed/Active	11/24/1992	FSG50	AO SMITH	\$ 850.00	
15600	Installed/Active	04/21/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15601	Installed/Active	07/24/1998	G82156	RUUD/RHEEM	\$ 3,350.00	
15602	Installed/Active	10/22/1994	PR407	RUUD	\$ 850.00	
15603	Installed/Active	05/08/2000	PHR50	RUUD	\$ 850.00	
15604	Installed/Active	10/18/2000	BTC197	AO SMITH	\$ 3,350.00	
15605	Installed/Active	02/09/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15606	Installed/Active	03/09/2011	I72DUMMY	AO SMITH	\$ 1,900.00	\$ 39.36
15607	Installed/Active	10/18/2000	BTC197	AO SMITH	\$ 3,350.00	
15608	Installed/Active	04/17/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15609	Installed/Active	05/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15610	Installed/Active	11/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15611	Installed/Active	12/15/1994	PR502T	RUUD	\$ 850.00	
15612	Installed/Active	07/15/2010	G67114	RHEEM	\$ 1,900.00	\$ 39.36
15613	Installed/Active	05/10/2010	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 39.36
15614	Installed/Active	05/12/2000	FGR50	AO SMITH	\$ 850.00	
15615	Installed/Active	03/24/2003	FSG50	AO SMITH	\$ 850.00	
15616	Installed/Active	03/18/1993	H72DUMMY	AO SMITH	\$ 1,900.00	
15617	Installed/Active	08/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15618	Installed/Active	04/01/2004	G82156	RUUD/RHEEM	\$ 3,350.00	
15619	Installed/Active	01/13/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15620	Installed/Active	06/19/2000	G91200	RUUD/RHEEM	\$ 3,350.00	
15621	Installed/Active	03/16/2005	GVC50	A. O. SMITH	\$ 850.00	
15622	Installed/Active	08/03/1998	H72DUMMY	AO SMITH	\$ 1,900.00	
15623	Installed/Active	07/09/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15624	Installed/Active	07/10/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15625	Installed/Active	05/29/1999	FGR50	AO SMITH	\$ 850.00	
15626	Installed/Active	05/18/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15627	Installed/Active	01/12/1995	SBF100199NES	STATE	\$ 3,350.00	
15628	Installed/Active	07/07/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
15629	Installed/Active	01/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15630	Installed/Active	04/11/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15631	Installed/Active	07/30/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
15632	Installed/Active	09/19/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 14.35
15633	Installed/Active	01/24/2002	PGR50	AO SMITH	\$ 850.00	
15634	Installed/Active	10/09/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
15635	Installed/Active	05/18/2000	41XR50	RHEEM	\$ 850.00	
15636	Installed/Active	09/08/2010	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15637	Installed/Active	05/11/2002	41XR50	RHEEM	\$ 850.00	
15638	Installed/Active	07/05/2006	LTN050G	LOCHINVAR	\$ 850.00	
15639	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15640	Installed/Active	01/22/2009	RF92200	RUUD	\$ 3,350.00	\$ 59.45
15641	Installed/Active	07/29/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
15642	Installed/Active	05/03/2011	21VR50	RHEEM	\$ 850.00	\$ 6.34
15643	Installed/Active	02/19/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15644	Installed/Active	05/24/2000	FGR40	AO SMITH	\$ 850.00	
15645	Installed/Active	05/21/1997	G82156	RUUD/RHEEM	\$ 3,350.00	
15646	Installed/Active	05/30/2000	G82156	RUUD/RHEEM	\$ 3,350.00	
15647	Installed/Active	11/28/2005	PR650	STATE	\$ 1,075.00	
15648	Installed/Active	10/13/2006	LTN040G	LOCHINVAR	\$ 850.00	
15649	Installed/Active	06/14/1999	41VR50	RHEEM	\$ 850.00	
15650	Installed/Active	08/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15651	Installed/Active	01/20/1995	PR502T	RUUD	\$ 850.00	
15652	Installed/Active	05/24/2000	41XR50	RHEEM	\$ 850.00	

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15653	Installed/Active	01/15/2011	41VR50	RHEEM	\$ 850.00	\$ 6.04
15654	Installed/Active	05/09/1997	PRV50NODS	STATE	\$ 1,075.00	
15655	Installed/Active	12/30/2005	LTN050G	LOCHINVAR	\$ 850.00	
15656	Installed/Active	08/10/1998	RF67120	RUUD	\$ 1,900.00	
15657	Installed/Active	11/04/2003	G75125	RUUD/RHEEM	\$ 1,900.00	
15658	Installed/Active	04/16/2003	PGR50	AO SMITH	\$ 850.00	
15659	Installed/Active	11/17/2005	PR650	STATE	\$ 1,075.00	
15660	Installed/Active	01/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15661	Installed/Active	06/18/1999	41VR50	RHEEM	\$ 850.00	
15662	Installed/Active	04/02/2008	PR650	STATE	\$ 1,075.00	\$ 8.98
15663	Installed/Active	06/04/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
15664	Installed/Active	10/31/2012	MI75S8FBN	BRADFORD-WHITE	\$ 950.00	\$ 41.64
15665	Installed/Active	04/11/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
15666	Installed/Active	03/01/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15667	Installed/Active	01/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15668	Installed/Active	06/04/2009	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 59.45
15669	Installed/Active	12/06/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15670	Installed/Active	10/14/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
15671	Installed/Active	01/06/2007	LTN050	LOCHINVAR	\$ 850.00	
15672	Installed/Active	07/28/2005	LTN050G	LOCHINVAR	\$ 850.00	
15673	Installed/Active	09/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15674	Installed/Active	12/28/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
15675	Installed/Active	07/22/2004	PRX50	STATE	\$ 1,075.00	
15676	Installed/Active	05/30/2000	PHR50	RUUD	\$ 850.00	
15677	Installed/Active	06/10/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 6.04
15678	Installed/Active	06/09/1997	FGR50	AO SMITH	\$ 850.00	
15679	Installed/Active	12/14/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15680	Installed/Active	11/12/2006	PR650	STATE	\$ 1,075.00	
15681	Installed/Active	01/09/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15682	Installed/Active	05/24/2000	41XR50	RHEEM	\$ 850.00	
15683	Installed/Active	02/05/2003	BTR197	AO SMITH	\$ 3,350.00	
15684	Installed/Active	03/05/2008	PR640	STATE	\$ 1,075.00	\$ 8.98
15685	Installed/Active	05/09/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15686	Installed/Active	02/20/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15687	Installed/Active	12/31/2004	PRX50	STATE	\$ 1,075.00	
15688	Installed/Active	07/14/1993	RF67120	RUUD	\$ 1,900.00	
15689	Installed/Active	08/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15690	Installed/Active	01/17/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15691	Installed/Active	11/09/2009	PH199119	PHOENIX	\$ 3,350.00	\$ 59.45
15692	Installed/Active	05/14/2003	PGR50	AO SMITH	\$ 850.00	
15693	Installed/Active	02/03/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15694	Installed/Active	03/31/1993	21V502	RHEEM	\$ 850.00	
15695	Installed/Active	11/17/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15696	Installed/Active	06/28/2011	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15697	Installed/Active	10/12/2010	21V407	RHEEM	\$ 850.00	\$ 6.04
15698	Installed/Active	05/26/2009	41V50	RHEEM	\$ 850.00	\$ 5.88
15699	Installed/Active	02/08/2010	GVC50	A. O. SMITH	\$ 850.00	\$ 11.74
15700	Installed/Active	01/25/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15701	Installed/Active	07/21/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15702	Installed/Active	06/15/1999	SSV119199	VOYAGER	\$ 3,350.00	
15703	Installed/Active	06/15/1999	SSV119199	VOYAGER	\$ 3,350.00	
15704	Installed/Active	09/28/2007	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 33.40
15705	Installed/Active	08/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15706	Installed/Active	08/26/1998	PHR50	RUUD	\$ 850.00	
15707	Installed/Active	11/01/2007	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
15708	Installed/Active	06/11/2003	H72DUMMY	AO SMITH	\$ 1,900.00	
15709	Installed/Active	12/15/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15710	Installed/Active	06/12/2000	G76200	RUUD/RHEEM	\$ 3,350.00	
15711	Installed/Active	07/02/1993	RFD91200	RUUD	\$ 3,350.00	
15712	Installed/Active	11/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15713	Installed/Active	06/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15714	Installed/Active	06/06/2000	41XR50	RHEEM	\$ 850.00	
15715	Installed/Active	03/28/1994	RF82156	RUUD	\$ 3,350.00	
15716	Installed/Active	01/30/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15717	Installed/Active	06/18/1997	21VR50	RHEEM	\$ 850.00	
15718	Installed/Active	04/18/2008	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15719	Installed/Active	06/30/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
15720	Installed/Active	09/02/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
15721	Installed/Active	01/27/2005	GVC50	A. O. SMITH	\$ 850.00	
15722	Installed/Active	03/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15723	Installed/Active	02/17/2003	41VR50	RHEEM	\$ 850.00	
15724	Installed/Active	06/26/1997	FGR50	AO SMITH	\$ 850.00	
15725	Installed/Active	05/14/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15726	Installed/Active	10/02/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15727	Installed/Active	03/31/1995	FGR50	AO SMITH	\$ 850.00	
15728	Installed/Active	09/03/1998	BTR199	AO SMITH	\$ 3,350.00	
15729	Installed/Active	07/02/2007	PR650	STATE	\$ 1,075.00	\$ 14.35
15730	Installed/Active	03/08/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15731	Installed/Active	12/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15732	Installed/Active	06/21/2000	41XR40	RHEEM	\$ 850.00	
15733	Installed/Active	07/22/2005	LTN050	LOCHINVAR	\$ 850.00	
15734	Installed/Active	08/07/2012	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15735	Installed/Active	11/02/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15736	Installed/Active	07/07/1997	G67114	RHEEM	\$ 1,900.00	
15737	Installed/Active	12/28/2007	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15738	Installed/Active	04/26/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15739	Installed/Active	07/09/1993	RF82156	RUUD	\$ 3,350.00	
15740	Installed/Active	02/11/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
15741	Installed/Active	01/06/2011	41VR40	RHEEM	\$ 850.00	\$ 6.04
15742	Installed/Active	03/07/2005	GVC50	A. O. SMITH	\$ 850.00	
15743	Installed/Active	08/23/1999	PHR50	RUUD	\$ 850.00	
15744	Installed/Active	07/09/1993	P506	RUUD	\$ 1,125.00	
15745	Installed/Active	01/04/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
15746	Installed/Active	07/08/1997	PR502T	RUUD	\$ 850.00	
15747	Installed/Active	12/18/2003	G76200	RUUD/RHEEM	\$ 3,350.00	
15748	Installed/Active	07/20/1999	PHR50	RUUD	\$ 850.00	
15749	Installed/Active	06/04/2012	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
15750	Installed/Active	07/15/1997	41VR50	RHEEM	\$ 850.00	
15751	Installed/Active	09/06/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15752	Installed/Active	02/14/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15753	Installed/Active	04/25/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
15754	Installed/Active	05/30/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15755	Installed/Active	11/17/2010	LTN040G	LOCHINVAR	\$ 850.00	\$ 6.04
15756	Installed/Active	06/04/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
15757	Installed/Active	03/29/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15758	Installed/Active	07/19/2010	PGR50	AO SMITH	\$ 850.00	\$ 6.04
15759	Installed/Active	07/20/1999	PHR40	RUUD	\$ 850.00	
15760	Installed/Active	03/30/2011	42VR50	RHEEM	\$ 850.00	\$ 6.04
15761	Installed/Active	04/13/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15762	Installed/Active	11/02/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
15763	Installed/Active	06/18/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
15764	Installed/Active	06/08/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 11.11
15765	Installed/Active	07/23/1999	FGR50	AO SMITH	\$ 850.00	
15766	Installed/Active	10/02/1998	BTR199	AO SMITH	\$ 3,350.00	
15767	Installed/Active	05/06/1993	21V502	RHEEM	\$ 850.00	
15768	Installed/Active	07/01/2000	BTR154	AO SMITH	\$ 3,350.00	
15769	Installed/Active	10/31/2007	PR650	STATE	\$ 1,075.00	\$ 8.98
15770	Installed/Active	10/06/2007	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
15771	Installed/Active	02/24/2006	PH30	RUUD	\$ 350.00	
15772	Installed/Active	12/27/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15773	Installed/Active	11/30/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15774	Installed/Active	11/04/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15775	Installed/Active	07/13/1993	P502	RUUD	\$ 850.00	
15776	Installed/Active	09/22/2012	FGR50	AO SMITH	\$ 850.00	\$ 6.39
15777	Installed/Active	08/14/2008	42VR5040	RHEEM	\$ 850.00	\$ 10.23
15778	Installed/Active	09/18/1998	41VR50	RHEEM	\$ 850.00	
15779	Installed/Active	12/27/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15780	Installed/Active	03/05/2011	LTN030G	AO SMITH	\$ 850.00	\$ 6.04
15781	Installed/Active	03/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
15782	Installed/Active	08/06/1997	FGR50	AO SMITH	\$ 850.00	
15783	Installed/Active	02/04/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15784	Installed/Active	09/21/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
15785	Installed/Active	08/13/2008	FGR30	AO SMITH	\$ 850.00	\$ 5.12
15786	Installed/Active	04/06/2005	FCV40	AO SMITH	\$ 850.00	
15787	Installed/Active	06/11/2012	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15788	Installed/Active	06/06/2006	LTN040G	LOCHINVAR	\$ 850.00	
15789	Installed/Active	09/20/2007	FGR30	AO SMITH	\$ 850.00	\$ 5.12
15790	Installed/Active	08/13/1997	BTC197	AO SMITH	\$ 3,350.00	
15791	Installed/Active	08/20/1999	PHR50	RUUD	\$ 850.00	
15792	Installed/Active	08/30/2010	LSN041G	LOCHINVAR	\$ 850.00	\$ 12.05
15793	Installed/Active	03/25/2010	21DV50	RHEEM	\$ 1,075.00	\$ 10.31
15794	Installed/Active	08/02/1999	FGR50	AO SMITH	\$ 850.00	
15795	Installed/Active	07/27/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15796	Installed/Active	10/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15797	Installed/Active	10/27/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15798	Installed/Active	07/27/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15799	Installed/Active	01/19/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
15800	Installed/Active	03/31/2004	GVC50	A. O. SMITH	\$ 850.00	
15801	Installed/Active	09/21/1998	41VR50	RHEEM	\$ 850.00	
15802	Installed/Active	01/06/2010	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
15803	Installed/Active	05/15/1992	21V502	RHEEM	\$ 850.00	
15804	Installed/Active	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15805	Installed/Active	05/11/2002	PGR40	AO SMITH	\$ 850.00	
15806	Installed/Active	11/01/1993	21V506	RHEEM	\$ 1,150.00	
15807	Installed/Active	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15808	Installed/Active	12/28/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15809	Installed/Active	06/30/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
15810	Installed/Active	10/08/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15811	Installed/Active	07/24/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15812	Installed/Active	02/24/2008	LTN040	LOCHINVAR	\$ 850.00	\$ 5.12
15813	Installed/Active	08/22/2006	PR650	STATE	\$ 1,075.00	
15814	Installed/Active	01/24/2011	P502	RUUD	\$ 850.00	\$ 12.05
15815	Installed/Active	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15816	Installed/Active	10/02/1998	FGR50	AO SMITH	\$ 850.00	
15817	Installed/Active	04/09/2008	LTN050	LOCHINVAR	\$ 850.00	\$ 5.12
15818	Installed/Active	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15819	Installed/Active	10/08/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
15820	Installed/Active	10/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15821	Installed/Active	07/25/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15822	Installed/Active	08/10/1999	PHR50	RUUD	\$ 850.00	
15823	Installed/Active	06/15/2012	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 20.38
15824	Installed/Active	02/13/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15825	Installed/Active	10/01/1998	41VR50	RHEEM	\$ 850.00	
15826	Installed/Active	06/15/2012	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 20.38
15827	Installed/Active	08/31/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15828	Installed/Active	10/07/2010	22DV50C	RHEEM	\$ 1,075.00	\$ 16.91
15829	Installed/Active	05/22/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
15830	Installed/Active	01/15/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15831	Installed/Active	06/15/2012	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 20.38
15832	Installed/Active	08/30/1997	41VR50	RHEEM	\$ 850.00	
15833	Installed/Active	12/05/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15834	Installed/Active	07/26/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15835	Installed/Active	07/26/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.38
15836	Installed/Active	07/09/2003	BTR120	AO SMITH	\$ 1,900.00	
15837	Installed/Active	08/09/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15838	Installed/Active	03/31/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15839	Installed/Active	01/06/2010	LTN050G	LOCHINVAR	\$ 1,125.00	\$ 18.76
15840	Installed/Active	04/13/2009	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 38.33
15841	Installed/Active	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.21
15842	Installed/Active	05/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
15843	Installed/Active	09/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15844	Installed/Active	10/09/1998	PHR50	RUUD	\$ 850.00	
15845	Installed/Active	08/28/1999	PHR50	RUUD	\$ 850.00	
15846	Installed/Active	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.21
15847	Installed/Active	08/09/1993	P502	RUUD	\$ 850.00	
15848	Installed/Active	08/12/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15849	Installed/Active	02/22/2012	H72DUMMY	UNKNOWN AT CONVERSION	\$ 1,125.00	\$ 20.21
15850	Installed/Active	09/11/1997	PR502T	RUUD	\$ 850.00	
15851	Installed/Active	12/07/2005	LTN050GEF	LOCHINVAR	\$ 850.00	
15852	Installed/Active	08/03/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 6.04
15853	Installed/Active	05/30/2006	G82156	RUUD/RHEEM	\$ 3,350.00	
15854	Installed/Active	08/21/1999	PHR50	RUUD	\$ 850.00	
15855	Installed/Active	08/10/1993	FSG50	AO SMITH	\$ 850.00	
15856	Installed/Active	01/14/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15857	Installed/Active	10/09/1998	FGR50	AO SMITH	\$ 850.00	
15858	Installed/Active	10/03/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15859	Installed/Active	08/03/1995	L72DUMMY	AO SMITH	\$ 3,350.00	
15860	Installed/Active	08/27/1993	21V502	RHEEM	\$ 850.00	
15861	Installed/Active	09/17/1997	41VR50	RHEEM	\$ 850.00	
15862	Installed/Active	10/09/1998	41VR50	RHEEM	\$ 850.00	
15863	Installed/Active	06/11/2004	GCVL40	A. O. SMITH	\$ 850.00	
15864	Installed/Active	08/27/1999	PHR50	RUUD	\$ 850.00	
15865	Installed/Active	02/04/2002	PGR50	AO SMITH	\$ 850.00	
15866	Installed/Active	05/05/1995	FGR50	AO SMITH	\$ 850.00	
15867	Installed/Active	12/12/1997	PR502T	RUUD	\$ 850.00	
15868	Installed/Active	02/09/2007	LTN050	LOCHINVAR	\$ 850.00	\$ 10.23
15869	Installed/Active	04/28/2008	22DV50F	RHEEM	\$ 1,075.00	\$ 8.98
15870	Installed/Active	09/16/1997	PRV50NODS	STATE	\$ 1,075.00	
15871	Installed/Active	08/18/1999	41VR50	RHEEM	\$ 850.00	
15872	Installed/Active	03/22/2006	LSN041G	LOCHINVAR	\$ 850.00	
15873	Installed/Active	10/12/1998	PR650	STATE	\$ 1,075.00	
15874	Installed/Active	04/01/2009	FGR50	AO SMITH	\$ 850.00	\$ 5.88
15875	Installed/Active	02/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15876	Installed/Active	09/18/1997	G91200	RUUD/RHEEM	\$ 3,350.00	
15877	Installed/Active	10/14/1998	PHR50	RUUD	\$ 850.00	
15878	Installed/Active	12/03/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15879	Installed/Active	11/01/2006	LTN050G	LOCHINVAR	\$ 850.00	
15880	Installed/Active	07/08/2008	22DV50C	RHEEM	\$ 1,075.00	\$ 14.35
15881	Installed/Active	02/04/2010	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
15882	Installed/Active	03/11/2013	D71DUMMY	UNKNOWN AT CONVERSION	\$ 1,150.00	\$ 17.52
15883	Installed/Active	08/27/2001	PR650	STATE	\$ 1,075.00	
15884	Installed/Active	08/12/2003	PGR50	AO SMITH	\$ 850.00	
15885	Installed/Active	05/26/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15886	Installed/Active	10/26/2010	21VR50	RHEEM	\$ 850.00	\$ 6.04
15887	Installed/Active	03/31/2010	ETN076	LOCHINVAR	\$ 1,900.00	\$ 38.33
15888	Installed/Active	02/21/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15889	Installed/Active	12/28/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15890	Installed/Active	09/22/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 10.23
15891	Installed/Active	08/17/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15892	Installed/Active	03/10/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15893	Installed/Active	07/22/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15894	Installed/Active	08/25/1999	FGR50	AO SMITH	\$ 850.00	
15895	Installed/Active	08/06/1993	FSG50	AO SMITH	\$ 850.00	
15896	Installed/Active	04/08/2005	FCV40	AO SMITH	\$ 850.00	
15897	Installed/Active	03/12/1993	G72DUMMY	AO SMITH	\$ 1,125.00	
15898	Installed/Active	10/30/1995	FGR40	AO SMITH	\$ 850.00	
15899	Installed/Active	04/19/2011	21VR40	RHEEM	\$ 850.00	\$ 6.34
15900	Installed/Active	08/04/1993	P502	RUUD	\$ 850.00	
15901	Installed/Active	10/11/1999	BTH199	AO SMITH	\$ 3,350.00	
15902	Installed/Active	01/15/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15903	Installed/Active	03/12/1993	FSG50	AO SMITH	\$ 850.00	
15904	Installed/Active	03/12/2006	LTN050G	LOCHINVAR	\$ 850.00	
15905	Installed/Active	01/03/2004	PRX50	STATE	\$ 1,075.00	
15906	Installed/Active	10/03/1997	I72DUMMY	AO SMITH	\$ 1,900.00	
15907	Installed/Active	02/12/2010	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.88
15908	Installed/Active	08/28/1999	PHR40	RUUD	\$ 850.00	
15909	Installed/Active	02/20/2003	FGR50	AO SMITH	\$ 850.00	
15910	Installed/Active	04/24/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15911	Installed/Active	10/27/1998	FGR40	AO SMITH	\$ 850.00	
15912	Installed/Active	11/10/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15913	Installed/Active	08/27/1999	H72DUMMY	AO SMITH	\$ 1,900.00	
15914	Installed/Active	10/25/2005	LTN050G	LOCHINVAR	\$ 850.00	
15915	Installed/Active	04/11/2011	42VR50	RHEEM	\$ 850.00	\$ 6.34
15916	Installed/Active	02/26/1993	21V502	RHEEM	\$ 850.00	
15917	Installed/Active	08/05/1999	41VR50	RHEEM	\$ 850.00	
15918	Installed/Active	01/21/2010	PR650	STATE	\$ 1,075.00	\$ 10.31
15919	Installed/Active	03/17/1993	P506	RUUD	\$ 1,150.00	
15920	Installed/Active	02/19/2008	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 44.60
15921	Installed/Active	01/03/2004	PVR50	AO SMITH	\$ 850.00	
15922	Installed/Active	11/11/2011	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15923	Installed/Active	10/25/2008	LSN041G	LOCHINVAR	\$ 850.00	\$ 5.12
15924	Installed/Active	10/11/2009	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 5.88
15925	Installed/Active	05/30/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15926	Installed/Active	03/19/2007	TNR200100	LOCHINVAR	\$ 3,350.00	\$ 51.80
15927	Installed/Active	04/02/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15928	Installed/Active	01/19/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15929	Installed/Active	11/01/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15930	Installed/Active	09/07/1999	FGR40	AO SMITH	\$ 850.00	
15931	Installed/Active	02/18/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15932	Installed/Active	01/04/2001	G82156	RUUD/RHEEM	\$ 3,350.00	
15933	Installed/Active	12/08/2010	21VR50	RHEEM	\$ 850.00	\$ 12.05
15934	Installed/Active	01/23/2001	H72DUMMY	AO SMITH	\$ 1,900.00	
15935	Installed/Active	10/05/2006	PR650	STATE	\$ 1,075.00	
15936	Installed/Active	10/16/1997	41VR40	RHEEM	\$ 850.00	
15937	Installed/Active	01/14/2005	GVC50	A. O. SMITH	\$ 850.00	
15938	Installed/Active	09/09/1999	PHR50	RUUD	\$ 850.00	
15939	Installed/Active	11/06/1998	21V502	RHEEM	\$ 850.00	
15940	Installed/Active	09/28/2009	PRV50NODS	STATE	\$ 1,075.00	\$ 10.31
15941	Installed/Active	05/29/2010	LTN050	LOCHINVAR	\$ 850.00	\$ 6.04
15942	Installed/Active	04/05/2008	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
15943	Installed/Active	06/15/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15944	Installed/Active	06/25/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.20
15945	Installed/Active	11/16/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
15946	Installed/Active	07/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
15947	Installed/Active	06/24/1993	FGS50	AO SMITH	\$ 850.00	
15948	Installed/Active	07/26/2012	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.64
15949	Installed/Active	01/04/2012	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.64
15950	Installed/Active	07/09/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
15951	Installed/Active	02/12/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15952	Installed/Active	10/04/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.14
15953	Installed/Active	05/04/2006	LTN050G	LOCHINVAR	\$ 850.00	
15954	Installed/Active	04/23/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15955	Installed/Active	06/29/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15956	Installed/Active	02/13/2004	H72DUMMY	AO SMITH	\$ 1,900.00	
15957	Installed/Active	01/16/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
15958	Installed/Active	01/06/2011	21VR40	RHEEM	\$ 850.00	\$ 6.04
15959	Installed/Active	02/13/2004	H72DUMMY	AO SMITH	\$ 1,900.00	
15960	Installed/Active	10/28/1997	FGR50	AO SMITH	\$ 850.00	
15961	Installed/Active	03/14/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
15962	Installed/Active	06/23/1999	FGR50	AO SMITH	\$ 850.00	
15963	Installed/Active	07/14/2011	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 11.11
15964	Installed/Active	08/30/1993	21V502	RHEEM	\$ 850.00	
15965	Installed/Active	11/30/2004	GVC50	A. O. SMITH	\$ 850.00	
15966	Installed/Active	10/30/1995	PRV50NODS	STATE	\$ 1,125.00	
15967	Installed/Active	11/19/1998	BW50	BRADFORD-WHITE	\$ 850.00	
15968	Installed/Active	06/16/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 10.23
15969	Installed/Active	08/22/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
15970	Installed/Active	03/06/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
15971	Installed/Active	11/19/1998	BW50	BRADFORD-WHITE	\$ 850.00	
15972	Installed/Active	09/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
15973	Installed/Active	12/11/1995	BTC197	AO SMITH	\$ 3,350.00	
15974	Installed/Active	01/05/1994	FGR50	AO SMITH	\$ 850.00	
15975	Installed/Active	11/23/1998	FGR50	AO SMITH	\$ 850.00	
15976	Installed/Active	09/20/1999	FGR50	AO SMITH	\$ 850.00	
15977	Installed/Active	12/14/2006	LTN050G	LOCHINVAR	\$ 850.00	
15978	Installed/Active	03/01/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
15979	Installed/Active	09/30/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
15980	Installed/Active	05/30/2006	LTN050G	LOCHINVAR	\$ 850.00	
15981	Installed/Active	12/30/1998	SBF100199NET	STATE	\$ 3,350.00	
15982	Installed/Active	09/30/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
15983	Installed/Active	10/01/2009	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 51.18
15984	Installed/Active	04/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
15985	Installed/Active	12/09/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
15986	Installed/Active	08/04/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15987	Installed/Active	02/19/2011	21VR50	RHEEM	\$ 850.00	\$ 6.04
15988	Installed/Active	09/22/1999	PHR50	RUUD	\$ 850.00	
15989	Installed/Active	01/07/2012	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
15990	Installed/Active	12/13/2010	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.04
15991	Installed/Active	04/10/2006	LTN050G	LOCHINVAR	\$ 850.00	
15992	Installed/Active	02/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
15993	Installed/Active	03/18/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
15994	Installed/Active	03/22/2008	PH199119	PHOENIX	\$ 3,350.00	\$ 51.80
15995	Installed/Active	11/07/1997	41VR50	RHEEM	\$ 850.00	
15996	Installed/Active	12/11/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
15997	Installed/Active	12/21/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
15998	Installed/Active	11/30/1998	SSV119199	VOYAGER	\$ 3,350.00	
15999	Installed/Active	04/14/2005	GVC50	A. O. SMITH	\$ 850.00	
16000	Installed/Active	01/09/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
16001	Installed/Active	01/10/1994	FSG50	AO SMITH	\$ 850.00	
16002	Installed/Active	11/25/1998	41VR50	RHEEM	\$ 850.00	
16003	Installed/Active	02/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
16004	Installed/Active	03/12/2012	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
16005	Installed/Active	12/02/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
16006	Installed/Active	02/26/1993	FSG50	AO SMITH	\$ 850.00	
16007	Installed/Active	11/22/1997	FGR50	AO SMITH	\$ 850.00	
16008	Installed/Active	04/16/2012	G72DUMMY	AO SMITH	\$ 1,125.00	\$ 20.21
16009	Installed/Active	01/27/2006	LTN040G	LOCHINVAR	\$ 850.00	
16010	Installed/Active	05/26/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16011	Installed/Active	10/28/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
16012	Installed/Active	10/02/2009	H72DUMMY	LOCHINVAR	\$ 1,125.00	\$ 18.76
16013	Installed/Active	09/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16014	Installed/Active	04/28/2011	41VR50	RHEEM	\$ 850.00	\$ 12.64
16015	Installed/Active	07/14/2011	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
16016	Installed/Active	11/12/2012	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16017	Installed/Active	10/06/1999	PHR50	RUUD	\$ 850.00	
16018	Installed/Active	05/22/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16019	Installed/Active	12/16/2004	FGR50	AO SMITH	\$ 850.00	
16020	Installed/Active	06/07/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16021	Installed/Active	09/28/2009	22DV50C	RHEEM	\$ 1,075.00	\$ 16.47
16022	Installed/Active	12/11/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16023	Installed/Active	03/28/2003	PGR50	AO SMITH	\$ 850.00	
16024	Installed/Active	09/30/1993	FSG50	AO SMITH	\$ 850.00	
16025	Installed/Active	10/01/2001	PGR50	AO SMITH	\$ 850.00	
16026	Installed/Active	05/22/2002	G75125	RUUD/RHEEM	\$ 1,900.00	
16027	Installed/Active	12/14/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
16028	Installed/Active	10/08/1999	PHR50	RUUD	\$ 850.00	
16029	Installed/Active	12/07/2004	PRX50	STATE	\$ 1,075.00	
16030	Installed/Active	11/30/1998	PR650	STATE	\$ 1,075.00	
16031	Installed/Active	12/05/1997	FGR50	AO SMITH	\$ 850.00	
16032	Installed/Active	07/12/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 17.74
16033	Installed/Active	10/08/1999	PR650	STATE	\$ 1,075.00	
16034	Installed/Active	12/06/1997	FGR50	AO SMITH	\$ 850.00	
16035	Installed/Active	06/03/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
16036	Installed/Active	12/03/2010	42VR50	RHEEM	\$ 850.00	\$ 6.04
16037	Installed/Active	11/27/1997	41VR50	RHEEM	\$ 850.00	
16038	Installed/Active	08/24/2007	FSG30	AO SMITH	\$ 850.00	\$ 10.23
16039	Installed/Active	07/14/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 16.47
16040	Installed/Active	02/23/2011	I72DUMMY	AO SMITH	\$ 1,900.00	\$ 39.36
16041	Installed/Active	02/20/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16042	Installed/Active	10/18/2007	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.12
16043	Installed/Active	05/21/2011	22DV50F	RHEEM	\$ 1,075.00	\$ 11.11
16044	Installed/Active	12/03/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16045	Installed/Active	01/05/2011	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 52.55
16046	Installed/Active	05/09/2007	PR650X0DS	STATE	\$ 1,075.00	\$ 14.35
16047	Installed/Active	12/03/1998	41VR50	RHEEM	\$ 850.00	
16048	Installed/Active	09/10/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16049	Installed/Active	07/07/2006	LTN050G	LOCHINVAR	\$ 850.00	
16050	Installed/Active	11/07/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
16051	Installed/Active	07/30/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16052	Installed/Active	05/17/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
16053	Installed/Active	12/08/2008	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16054	Installed/Active	03/13/2007	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
16055	Installed/Active	08/02/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16056	Installed/Active	11/22/2009	PRV50NODS	STATE	\$ 1,075.00	\$ 10.31
16057	Installed/Active	12/26/2007	ETN076	LOCHINVAR	\$ 1,900.00	\$ 33.40
16058	Installed/Active	10/29/1999	41VR50	RHEEM	\$ 850.00	
16059	Installed/Active	10/29/2009	22DV50F	RHEEM	\$ 1,075.00	\$ 10.31
16060	Installed/Active	07/19/2010	22DV50F	RHEEM	\$ 1,075.00	\$ 10.59
16061	Installed/Active	04/27/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
16062	Installed/Active	02/21/2012	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
16063	Installed/Active	12/10/1997	FSGL40	AO SMITH	\$ 850.00	
16064	Installed/Active	10/13/2004	G91200	RUUD/RHEEM	\$ 3,350.00	
16065	Installed/Active	08/04/2007	PR650	STATE	\$ 1,075.00	\$ 8.98
16066	Installed/Active	08/28/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 6.04
16067	Installed/Active	09/01/1993	FSG50	AO SMITH	\$ 850.00	
16068	Installed/Active	07/04/2005	G91200	RUUD/RHEEM	\$ 3,350.00	
16069	Installed/Active	12/08/2011	PH2DV50F	RUUD	\$ 1,075.00	\$ 11.11
16070	Installed/Active	10/25/1999	PHR50	RUUD	\$ 850.00	
16071	Installed/Active	10/17/2012	M175S6FBN	BRADFORD-WHITE	\$ 3,350.00	\$ 55.60
16072	Installed/Active	08/20/2012	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16073	Installed/Active	06/09/2004	41VR50	RHEEM	\$ 850.00	
16074	Installed/Active	10/31/2005	LTN040G	LOCHINVAR	\$ 850.00	
16075	Installed/Active	12/01/1998	G67114	RHEEM	\$ 1,900.00	
16076	Installed/Active	12/11/2002	PGR50	AO SMITH	\$ 850.00	
16077	Installed/Active	11/21/1997	PRV50NODS	STATE	\$ 1,075.00	
16078	Installed/Active	03/12/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16079	Installed/Active	10/10/2011	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 41.30
16080	Installed/Active	02/23/1996	PR502T	RUUD	\$ 850.00	
16081	Installed/Active	10/29/1999	41XR50	RHEEM	\$ 850.00	
16082	Installed/Active	03/10/2012	FGR40	AO SMITH	\$ 850.00	\$ 6.34

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16083	Installed/Active	10/29/1999	PHR50	RUUD	\$ 850.00	
16084	Installed/Active	02/14/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16085	Installed/Active	03/17/1994	PRV50NODS	STATE	\$ 1,075.00	
16086	Installed/Active	12/12/1998	PRV40NODS	STATE	\$ 1,075.00	
16087	Installed/Active	11/15/2011	GVC50	A. O. SMITH	\$ 850.00	\$ 12.64
16088	Installed/Active	05/02/2012	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 11.11
16089	Installed/Active	01/11/2011	41VR50	RHEEM	\$ 850.00	\$ 6.04
16090	Installed/Active	04/12/2005	P506	RUUD	\$ 1,150.00	
16091	Installed/Active	11/27/2001	FSG50	AO SMITH	\$ 850.00	
16092	Installed/Active	07/08/2004	XTN050	LOCHINVAR	\$ 850.00	
16093	Installed/Active	12/22/2010	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 61.05
16094	Installed/Active	04/24/2002	PRX50	STATE	\$ 1,075.00	
16095	Installed/Active	01/21/2005	G82156	RUUD/RHEEM	\$ 3,350.00	
16096	Installed/Active	03/16/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16097	Installed/Active	05/19/2005	LTN050	LOCHINVAR	\$ 850.00	
16098	Installed/Active	11/17/1999	PHR50	RUUD	\$ 850.00	
16099	Installed/Active	10/16/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16100	Installed/Active	04/13/1998	G91200	RUUD/RHEEM	\$ 3,350.00	
16101	Installed/Active	01/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16102	Installed/Active	10/19/2011	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.06
16103	Installed/Active	05/03/2012	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.34
16104	Installed/Active	10/10/2011	PR650	STATE	\$ 1,075.00	\$ 17.74
16105	Installed/Active	06/07/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 5.12
16106	Installed/Active	09/17/1993	G76200	RUUD/RHEEM	\$ 3,350.00	
16107	Installed/Active	02/04/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16108	Installed/Active	11/12/1999	FGR40	AO SMITH	\$ 850.00	
16109	Installed/Active	09/17/1993	G76200	RUUD/RHEEM	\$ 3,350.00	
16110	Installed/Active	04/24/2006	LTN050G	LOCHINVAR	\$ 850.00	
16111	Installed/Active	04/14/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16112	Installed/Active	07/28/2009	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 5.88
16113	Installed/Active	07/02/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16114	Installed/Active	07/31/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16115	Installed/Active	01/06/1998	41VR40	RHEEM	\$ 850.00	
16116	Installed/Active	02/06/1998	PRV50NODS	STATE	\$ 1,075.00	
16117	Installed/Active	03/23/1993	PH30	RUUD	\$ 350.00	
16118	Installed/Active	05/01/2001	41V40S	RHEEM	\$ 850.00	
16119	Installed/Active	03/14/2011	42VR50	RHEEM	\$ 850.00	\$ 12.05
16120	Installed/Active	01/27/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16121	Installed/Active	02/21/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 10.23
16122	Installed/Active	08/24/2010	42VR50	RHEEM	\$ 850.00	\$ 12.05
16123	Installed/Active	05/18/2006	LTN050GEF	LOCHINVAR	\$ 850.00	
16124	Installed/Active	09/28/2001	FSG50	AO SMITH	\$ 850.00	
16125	Installed/Active	04/08/2010	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 12.05
16126	Installed/Active	09/27/2010	FSG50	AO SMITH	\$ 850.00	\$ 12.05
16127	Installed/Active	08/31/2004	G76200	RUUD/RHEEM	\$ 3,350.00	
16128	Installed/Active	08/31/2004	G76200	RUUD/RHEEM	\$ 3,350.00	
16129	Installed/Active	08/31/2004	G76200	RUUD/RHEEM	\$ 3,350.00	
16130	Installed/Active	01/08/2009	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 11.74
16131	Installed/Active	06/17/2010	21V502	RHEEM	\$ 850.00	\$ 12.05
16132	Installed/Active	04/06/1993	FSG50	AO SMITH	\$ 850.00	
16133	Installed/Active	03/25/2013	ph2dv50f	ruud	\$ 1,075.00	\$ 17.89
16134	Installed/Active	03/14/2013	ph2dv50f	ruud	\$ 1,075.00	\$ 17.89
16135	Installed/Active	03/29/2013	mi5036fbn	bradford-white	\$ 850.00	\$ 12.75
16136	Installed/Active	03/29/2013	M45036FBN	bradford-white	\$ 683.00	\$ 12.75
16137	Installed/Active	03/30/2013	M1403S6FBN	Bradford-White	\$ 850.00	\$ 7.95
16138	Installed/Active	03/13/2013	M45036Fbn	Bradford-White	\$ 683.00	\$ 12.75
16139	Installed/Active	03/19/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16140	Installed/Active	03/13/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16141	Installed/Active	03/17/2013	M15036FBN	bradford-white	\$ 683.00	\$ 12.75
16142	Installed/Active	03/29/2013	M140T6FBN	Bradfor-White	\$ 683.00	\$ 12.75
16143	Installed/Active	03/18/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16144	Installed/Active	03/20/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16145	Installed/Active	03/18/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16146	Installed/Active	03/23/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 12.75
16147	Installed/Active	03/28/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16148	Installed/Active	03/29/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16149	Installed/Active	03/15/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.75
16150	Installed/Active	03/29/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16151	Installed/Active	03/18/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16152	Installed/Active	03/16/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.75
16153	Installed/Active	03/15/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.52
16154	Installed/Active	01/26/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.75
16155	Installed/Active	02/03/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16156	Installed/Active	03/13/2013	M140T6FBN	Bradford White	\$ 646.00	\$ 15.60
16157	Installed/Active	03/27/2013	M15036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16158	Installed/Active	03/27/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16159	Installed/Active	03/17/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 12.75
16160	Installed/Active	03/27/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16161	Installed/Active	03/13/2013	FGR50	AO SMITH	\$ 850.00	\$ 12.75
16162	Installed/Active	03/26/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16163	Installed/Active	03/23/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16164	Installed/Active	03/27/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16165	Installed/Active	03/08/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16166	Installed/Active	03/21/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.75
16167	Installed/Active	03/14/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 12.75
16168	Installed/Active	03/15/2013	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.39

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16169	Installed/Active	03/15/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16170	Installed/Active	03/15/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
16171	Installed/Active	03/18/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16172	Installed/Active	03/30/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16173	Installed/Active	03/23/2013	MI403S6FBN	Bradford-White	\$ 646.00	\$ 12.75
16174	Installed/Active	03/11/2013	MI5036FBN	Bradford-White	\$ 683.00	\$ 12.75
16175	Installed/Active	03/12/2013	MI5036FBN	Bradford-White	\$ 683.00	\$ 12.75
16176	Installed/Active	03/12/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16177	Installed/Active	03/27/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16178	Installed/Active	03/28/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.75
16179	Installed/Active	03/18/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.75
16180	Installed/Active	03/21/2013	MI50L6FBN	Bradford-White	\$ 744.00	\$ 12.75
16181	Installed/Active	03/25/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16182	Installed/Active	03/05/2013	MI40T6FBN	Bradford - White	\$ 850.00	\$ 12.75
16183	Installed/Active	03/21/2013	M45036FBN	Bradford - White	\$ 850.00	\$ 12.75
16184	Installed/Active	03/28/2013	MI5036FBN	Bradford - White	\$ 850.00	\$ 12.75
16185	Installed/Active	03/22/2013	MI50L6FBN	Bradford White	\$ 850.00	\$ 12.75
16186	Installed/Active	03/18/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.75
16187	Installed/Active	03/19/2013	FSGL40	AO SMITH	\$ 850.00	\$ 12.75
16188	Installed/Active	03/18/2013	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.75
16189	Installed/Active	03/09/2013	FSG50	AO SMITH	\$ 850.00	\$ 7.95
16190	Installed/Active	03/27/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.75
16191	Installed/Active	03/21/2013	MI40T6FBN	BRADFORD WHITE	\$ 657.00	\$ 6.39
16192	Installed/Active	10/10/1980	DS20	ECON	\$ 750.00	
16193	Installed/Active	04/08/2013	G75125	RUUD	\$ 2,835.00	\$ 41.64
16194	Installed/Active	04/05/2013	G91200	RUUD	\$ 3,367.00	\$ 64.59
16195	Installed/Active	04/03/2013	MI50L6FBN	Bradford-White	\$ 1,175.00	\$ 12.75
16196	Installed/Active	04/03/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.75
16197	Installed/Active	04/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16198	Installed/Active	04/02/2013	22DV50F	Rheem	\$ 1,141.51	\$ 17.89
16199	Installed/Active	03/27/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16200	Installed/Active	04/09/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.75
16201	Installed/Active	04/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16202	Installed/Active	04/09/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16203	Installed/Active	03/21/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.75
16204	Installed/Active	04/03/2013	MI40T6FBN	Bradford-White	\$ 646.00	\$ 12.75
16205	Installed/Active	04/03/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16206	Installed/Active	04/04/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16207	Installed/Active	04/05/2013	G82156	Rheem	\$ 3,501.96	\$ 55.60
16208	Installed/Active	04/01/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
16209	Installed/Active	04/01/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16210	Installed/Active	04/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16211	Installed/Active	04/02/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16212	Installed/Active	04/02/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16213	Installed/Active	04/03/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
16214	Installed/Active	03/28/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16215	Installed/Active	04/25/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.89
16216	Installed/Active	01/24/2013	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16217	Installed/Active	01/16/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
16218	Installed/Active	04/17/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16219	Installed/Active	03/25/2013	MI40T6FBN	Bradford-White	\$ 646.00	\$ 7.95
16220	Installed/Active	04/30/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16221	Installed/Active	04/30/2013	PH2DV50F	Ruud	\$ 1,075.00	\$ 17.89
16222	Installed/Active	03/07/2013	G75125	RHEEM	\$ 2,917.34	\$ 41.64
16223	Installed/Active	04/19/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16224	Installed/Active	03/26/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.75
16225	Installed/Active	05/15/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 41.64
16226	Installed/Active	03/28/2013	PH2DV50F	RHEEM	\$ 683.00	\$ 12.75
16227	Installed/Active	03/23/2013	MI403S6FBN	Bradford White	\$ 850.00	\$ 12.75
16228	Installed/Active	03/25/2013	MI5036FBN	Bradford White	\$ 683.00	\$ 12.75
16229	Installed/Active	04/04/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16230	Installed/Active	04/04/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16231	Installed/Active	04/04/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16232	Installed/Active	04/04/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16233	Installed/Active	03/29/2013	MI5036FBN	Bradford White	\$ 850.00	\$ 12.75
16234	Installed/Active	04/11/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16235	Installed/Active	04/11/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 6.39
16236	Installed/Active	04/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.95
16237	Installed/Active	04/06/2013	M45036FBN	Bradford-White	\$ 660.00	\$ 12.75
16238	Installed/Active	04/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16239	Installed/Active	04/09/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16240	Installed/Active	04/09/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16241	Installed/Active	04/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16242	Installed/Active	04/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16243	Installed/Active	04/03/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
16244	Installed/Active	04/02/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.39
16245	Installed/Active	04/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16246	Installed/Active	03/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16247	Installed/Active	04/08/2013	P230F	Ruud	\$ 865.00	\$ 6.39
16248	Installed/Active	04/04/2013	M45036FBN	Bradford-White	\$ 660.00	\$ 6.39
16249	Installed/Active	03/30/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.39
16250	Installed/Active	03/16/2013	MI40T6FBN	Bradford-White	\$ 646.00	\$ 7.95
16251	Installed/Active	04/02/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 6.39
16252	Installed/Active	03/25/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
16253	Installed/Active	04/03/2013	G91200	RUUD/RHEEM	\$ 3,648.12	\$ 64.59
16254	Installed/Active	04/17/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16255	Installed/Active	04/14/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16256	Installed/Active	04/17/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16257	Installed/Active	04/16/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16258	Installed/Active	04/05/2013	M45036FBN	BARDFORD WHITE	\$ 683.00	\$ 12.75
16259	Installed/Active	03/11/2013	PH2DV50F	RUUD	\$ 979.00	\$ 11.20
16260	Installed/Active	04/16/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16261	Installed/Active	04/12/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 12.75
16262	Installed/Active	03/15/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16263	Installed/Active	04/15/2013	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 55.60
16264	Installed/Active	04/23/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16265	Installed/Active	04/18/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16266	Installed/Active	04/09/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
16267	Installed/Active	04/17/2013	PH2DV50F	RUUD	\$ 1,078.00	\$ 17.89
16268	Installed/Active	04/17/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16269	Installed/Active	04/17/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16270	Installed/Active	04/18/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16271	Installed/Active	04/13/2013	M140S6FBN	Bradford-White	\$ 850.00	\$ 6.39
16272	Installed/Active	04/19/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
16273	Installed/Active	03/10/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16274	Installed/Active	04/06/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16275	Installed/Active	04/16/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16276	Installed/Active	04/22/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16277	Installed/Active	04/16/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16278	Installed/Active	04/24/2013	PH199119	PHOENIX	\$ 3,350.00	\$ 64.59
16279	Installed/Active	04/27/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
16280	Installed/Active	04/26/2013	G91200	RUUD	\$ 3,350.00	\$ 64.59
16281	Installed/Active	04/23/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16282	Installed/Active	04/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16283	Installed/Active	04/26/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16284	Installed/Active	04/24/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16285	Installed/Active	04/19/2013	M2XR504T6FBN	Bradford-White	\$ 1,150.00	\$ 17.52
16286	Installed/Active	04/29/2013	G91200	Ruud	\$ 3,367.00	\$ 64.59
16287	Installed/Active	04/21/2013	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 64.59
16288	Installed/Active	04/16/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16289	Installed/Active	04/16/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16290	Installed/Active	05/14/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16291	Installed/Active	05/15/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16292	Installed/Active	05/09/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 12.75
16293	Installed/Active	05/15/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16294	Installed/Active	05/11/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.75
16295	Installed/Active	04/17/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16296	Installed/Active	04/14/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16297	Installed/Active	04/29/2013	M140S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16298	Installed/Active	04/15/2013	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 64.59
16299	Installed/Active	04/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16300	Installed/Active	04/16/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.95
16301	Installed/Active	04/23/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16302	Installed/Active	04/25/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16303	Installed/Active	04/25/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16304	Installed/Active	04/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16305	Installed/Active	04/23/2013	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 17.89
16306	Installed/Active	05/11/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
16307	Installed/Active	04/15/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16308	Installed/Active	04/15/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16309	Installed/Active	04/13/2013	PH2DV50F	Ruud	\$ 1,075.00	\$ 17.89
16310	Installed/Active	04/14/2013	G82156	Ruud	\$ 3,360.00	\$ 55.60
16311	Installed/Active	04/12/2013	M140T6FBN	Bradford-White	\$ 657.00	\$ 6.39
16312	Installed/Active	05/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16313	Installed/Active	05/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16314	Installed/Active	05/11/2013	G91200	RUUD	\$ 3,350.00	\$ 64.59
16315	Installed/Active	02/15/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16316	Installed/Active	05/11/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16317	Installed/Active	04/23/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16318	Installed/Active	03/25/2013	G76200	Rheem	\$ 3,490.73	\$ 64.59
16319	Installed/Active	05/15/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16320	Installed/Active	05/16/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16321	Installed/Active	04/09/2013	G75125	RHEEM	\$ 2,917.34	\$ 41.64
16322	Installed/Active	05/03/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.39
16323	Installed/Active	05/02/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16324	Installed/Active	04/22/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16325	Installed/Active	04/17/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16326	Installed/Active	04/18/2013	M140T6FBN	Bradford-White	\$ 1,175.00	\$ 6.39
16327	Installed/Active	04/20/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16328	Installed/Active	04/17/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16329	Installed/Active	04/12/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16330	Installed/Active	04/18/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16331	Installed/Active	05/14/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16332	Installed/Active	04/17/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 12.75
16333	Installed/Active	04/15/2013	M140T6FBN	Bradford-White	\$ 1,175.00	\$ 6.39
16334	Installed/Active	04/10/2013	M150L6FBN	Bradford-White	\$ 744.00	\$ 12.75
16335	Installed/Active	03/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16336	Installed/Active	05/14/2013	M140T6FBN	Bradford-White	\$ 657.00	\$ 12.75
16337	Installed/Active	04/29/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16338	Installed/Active	04/26/2013	M15036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16339	Installed/Active	04/24/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16340	Installed/Active	04/16/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16341	Installed/Active	05/13/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16342	Installed/Active	05/13/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16343	Installed/Active	02/26/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16344	Installed/Active	03/22/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16345	Installed/Active	04/23/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
16346	Installed/Active	05/13/2013	M15036FBN	BRADFORD-WHITE	\$ 500.00	\$ 20.38
16347	Installed/Active	05/05/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.39
16348	Installed/Active	05/06/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16349	Installed/Active	04/30/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.75
16350	Installed/Active	05/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16351	Installed/Active	05/03/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16352	Installed/Active	05/04/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16353	Installed/Active	04/09/2013	G75125	Ruud	\$ 2,835.00	\$ 41.64
16354	Installed/Active	05/08/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16355	Installed/Active	04/25/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.89
16356	Installed/Active	05/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16357	Installed/Active	04/20/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16358	Installed/Active	05/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16359	Installed/Active	05/06/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16360	Installed/Active	05/03/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16361	Installed/Active	05/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16362	Installed/Active	05/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16363	Installed/Active	05/01/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16364	Installed/Active	04/25/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.75
16365	Installed/Active	05/21/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16366	Installed/Active	05/17/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16367	Installed/Active	05/13/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 12.75
16368	Installed/Active	05/13/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16369	Installed/Active	05/17/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 17.52
16370	Installed/Active	05/02/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.75
16371	Installed/Active	05/09/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16372	Installed/Active	05/08/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16373	Installed/Active	05/15/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 6.39
16374	Installed/Active	05/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16375	Installed/Active	05/21/2013	G91200	RUUD/RHEEM	\$ 3,648.12	\$ 64.59
16376	Installed/Active	05/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16377	Installed/Active	05/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16378	Installed/Active	05/22/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16379	Installed/Active	05/17/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.39
16380	Installed/Active	05/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16381	Installed/Active	05/01/2013	M150L6FBN	Bradford-White	\$ 850.00	\$ 12.75
16382	Installed/Active	05/13/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16383	Installed/Active	05/08/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.39
16384	Installed/Active	05/17/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16385	Installed/Active	05/10/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
16386	Installed/Active	04/01/2013	M1403S6FBN	Bradford-White	\$ 850.00	\$ 12.75
16387	Installed/Active	05/03/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16388	Installed/Active	05/01/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.39
16389	Installed/Active	05/06/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16390	Installed/Active	05/06/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.39
16391	Installed/Active	05/09/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16392	Installed/Active	05/28/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 12.75
16393	Installed/Active	05/25/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
16394	Installed/Active	05/22/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16395	Installed/Active	05/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16396	Installed/Active	05/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16397	Installed/Active	05/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16398	Installed/Active	05/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.39
16399	Installed/Active	05/25/2013	M140T6FBN	BRADFORD WHITE	\$ 657.00	\$ 6.39
16400	Installed/Active	05/28/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16401	Installed/Active	05/01/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16402	Installed/Active	05/22/2013	P230S30F	RUUD	\$ 865.00	\$ 7.95
16403	Installed/Active	05/21/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
16404	Installed/Active	05/17/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16405	Installed/Active	05/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16406	Installed/Active	05/22/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16407	Installed/Active	06/28/2013	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 15.60
16408	Installed/Active	06/28/2013	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 15.60
16409	Installed/Active	05/01/2013	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 55.60
16410	Installed/Active	05/30/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16411	Installed/Active	06/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16412	Installed/Active	05/30/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16413	Installed/Active	06/04/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16414	Installed/Active	06/05/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 6.39
16415	Installed/Active	05/25/2013	G82156	RHEEM	\$ 3,501.96	\$ 55.60
16416	Installed/Active	06/04/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16417	Installed/Active	05/06/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16418	Installed/Active	05/08/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.75
16419	Installed/Active	05/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16420	Installed/Active	05/17/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16421	Installed/Active	05/09/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16422	Installed/Active	05/11/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.75
16423	Installed/Active	05/31/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16424	Installed/Active	06/07/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16425	Installed/Active	06/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.39
16426	Installed/Active	05/08/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 7.95

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16427	Installed/Active	04/22/2013	PH199-80	PHOENIX	\$ 6,563.69	\$ 64.59
16428	Installed/Active	05/24/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16429	Installed/Active	05/25/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 6.39
16430	Installed/Active	05/22/2013	M1403S6FBN	Bradford-White	\$ 850.00	\$ 12.75
16431	Installed/Active	05/10/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16432	Installed/Active	05/09/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16433	Installed/Active	03/21/2013	G75125	RUUD	\$ 2,835.00	\$ 41.64
16434	Installed/Active	05/18/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.75
16435	Installed/Active	05/07/2013	PH19980	Phoenix	\$ 3,350.00	\$ 64.59
16436	Installed/Active	04/26/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16437	Installed/Active	05/03/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16438	Installed/Active	05/02/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16439	Installed/Active	05/18/2013	G91200	RUUD/RHEEM	\$ 3,648.12	\$ 64.59
16440	Installed/Active	05/03/2013	G75125	RUUD/RHEEM	\$ 2,917.34	\$ 41.64
16441	Installed/Active	05/23/2013	G91200	Ruud/Rheem	\$ 3,648.12	\$ 41.64
16442	Installed/Active	05/24/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 12.75
16443	Installed/Active	05/04/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16444	Installed/Active	05/21/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.75
16445	Installed/Active	05/24/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.89
16446	Installed/Active	06/05/2013	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 17.89
16447	Installed/Active	06/05/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 12.75
16448	Installed/Active	05/08/2013	M45036FBN	Bradford White	\$ 850.00	\$ 6.39
16449	Installed/Active	05/20/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16450	Installed/Active	05/24/2013	G82156	RHEEM	\$ 3,501.00	\$ 55.60
16451	Installed/Active	05/26/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 7.95
16452	Installed/Active	06/12/2013	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.39
16453	Installed/Active	06/11/2013	M430T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
16454	Installed/Active	05/28/2013	M2XR504T6FBN	Bradford-White	\$ 1,150.00	\$ 17.52
16455	Installed/Active	06/03/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 6.39
16456	Installed/Active	06/01/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16457	Installed/Active	06/06/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16458	Installed/Active	06/05/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16459	Installed/Active	06/26/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.39
16460	Installed/Active	06/18/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 6.39
16461	Installed/Active	06/20/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 6.39
16462	Installed/Active	06/28/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16463	Installed/Active	06/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16464	Installed/Active	06/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16465	Installed/Active	06/13/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16466	Installed/Active	06/10/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16467	Installed/Active	06/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16468	Installed/Active	05/16/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.95
16469	Installed/Active	05/24/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16470	Installed/Active	05/25/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16471	Installed/Active	05/28/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16472	Installed/Active	06/05/2013	M15036FBN	Bradford-White	\$ 646.00	\$ 12.75
16473	Installed/Active	05/31/2013	P230F	RUUD	\$ 865.00	\$ 6.39
16474	Installed/Active	06/11/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 6.39
16475	Installed/Active	05/13/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16476	Installed/Active	05/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16477	Installed/Active	06/11/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16478	Installed/Active	06/02/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.95
16479	Installed/Active	06/22/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16480	Installed/Active	06/18/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16481	Installed/Active	06/12/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.39
16482	Installed/Active	06/26/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16483	Installed/Active	06/08/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.75
16484	Installed/Active	06/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16485	Installed/Active	07/11/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 6.06
16486	Installed/Active	06/01/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16487	Installed/Active	06/18/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16488	Installed/Active	06/28/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.89
16489	Installed/Active	06/11/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 12.75
16490	Installed/Active	06/05/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 12.75
16491	Installed/Active	06/26/2013	M175S6FBN	Bradford-White	\$ 950.00	\$ 20.38
16492	Installed/Active	06/17/2013	M45036Fbn	Bradford-White	\$ 683.00	\$ 6.39
16493	Installed/Active	06/20/2013	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 64.59
16494	Installed/Active	06/03/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16495	Installed/Active	06/21/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16496	Installed/Active	06/28/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16497	Installed/Active	06/28/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 17.89
16498	Installed/Active	06/24/2013	P230F	RUUD	\$ 865.00	\$ 6.39
16499	Installed/Active	06/26/2013	G91200	RHEEM	\$ 3,648.12	\$ 64.59
16500	Installed/Active	07/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16501	Installed/Active	07/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16502	Installed/Active	07/03/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16503	Installed/Active	06/25/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16504	Installed/Active	07/05/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16505	Installed/Active	06/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16506	Installed/Active	07/02/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16507	Installed/Active	06/30/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16508	Installed/Active	07/02/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16509	Installed/Active	06/28/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16510	Installed/Active	07/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.65
16511	Installed/Active	07/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16512	Installed/Active	07/12/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16513	Installed/Active	07/15/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16514	Installed/Active	07/18/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16515	Installed/Active	07/11/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16516	Installed/Active	07/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16517	Installed/Active	07/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16518	Installed/Active	05/25/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.75
16519	Installed/Active	06/03/2013	M140T6FBN	Bradford-White	\$ 850.00	\$ 6.39
16520	Installed/Active	06/26/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16521	Installed/Active	06/19/2013	M15036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16522	Installed/Active	05/31/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16523	Installed/Active	06/05/2013	M15036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16524	Installed/Active	05/20/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.75
16525	Installed/Active	06/11/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16526	Installed/Active	06/28/2013	M140T6FBN	Bradford-White	\$ 1,175.00	\$ 12.75
16527	Installed/Active	06/05/2013	M140T6FBN	Bradford-White	\$ 646.00	\$ 6.39
16528	Installed/Active	06/12/2013	PRV50NODS	STATE	\$ 1,075.00	\$ 17.89
16529	Installed/Active	06/18/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16530	Installed/Active	06/22/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.75
16531	Installed/Active	06/25/2013	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 17.89
16532	Installed/Active	06/11/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16533	Installed/Active	06/17/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.75
16534	Installed/Active	06/25/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16535	Installed/Active	06/12/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 7.95
16536	Installed/Active	05/26/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16537	Installed/Active	06/03/2013	P230F	RUUD	\$ 865.00	\$ 12.75
16538	Installed/Active	06/05/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.39
16539	Installed/Active	06/24/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75
16540	Installed/Active	05/25/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.75
16541	Installed/Active	05/30/2013	P230F	RUUD	\$ 865.00	\$ 6.39
16542	Installed/Active	06/10/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.52
16543	Installed/Active	06/22/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16544	Installed/Active	06/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16545	Installed/Active	06/07/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16546	Installed/Active	06/05/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 6.39
16547	Installed/Active	06/27/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.39
16548	Installed/Active	06/27/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16549	Installed/Active	06/25/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 6.39
16550	Installed/Active	06/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16551	Installed/Active	06/22/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16552	Installed/Active	06/06/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16553	Installed/Active	06/06/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.39
16554	Installed/Active	06/05/2013	M440T6FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16555	Installed/Active	06/03/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.75
16556	Installed/Active	06/01/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.39
16557	Installed/Active	06/08/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.39
16558	Installed/Active	06/18/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16559	Installed/Active	06/19/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16560	Installed/Active	06/24/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
16561	Installed/Active	06/28/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 17.89
16562	Installed/Active	06/27/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 7.95
16563	Installed/Active	06/25/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
16564	Installed/Active	06/28/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16565	Installed/Active	06/11/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 12.75
16566	Installed/Active	06/26/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16567	Installed/Active	06/27/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.39
16568	Installed/Active	07/12/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.81
16569	Installed/Active	06/13/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 12.75
16570	Installed/Active	07/16/2013	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 56.35
16571	Installed/Active	07/01/2013	M140T6FBN	Bradford-White	\$ 850.00	\$ 12.56
16572	Installed/Active	06/17/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16573	Installed/Active	06/18/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.89
16574	Installed/Active	06/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.75
16575	Installed/Active	06/27/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.75
16576	Installed/Active	07/03/2013	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 17.81
16577	Installed/Active	07/05/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16578	Installed/Active	07/02/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.81
16579	Installed/Active	07/10/2013	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 17.81
16580	Installed/Active	07/11/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16581	Installed/Active	07/20/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16582	Installed/Active	07/16/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.81
16583	Installed/Active	07/15/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16584	Installed/Active	07/17/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16585	Installed/Active	07/19/2013	G75125	RUUD/RHEEM	\$ 2,917.00	\$ 42.08
16586	Installed/Active	07/16/2013	M15036FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.56
16587	Installed/Active	07/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16588	Installed/Active	07/06/2013	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16589	Installed/Active	07/19/2013	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.06
16590	Installed/Active	07/11/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16591	Installed/Active	07/08/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.65
16592	Installed/Active	06/20/2013	G91200	RHEEM	\$ 3,648.12	\$ 64.59
16593	Installed/Active	07/23/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16594	Installed/Active	07/19/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16595	Installed/Active	07/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16596	Installed/Active	07/24/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16597	Installed/Active	07/19/2013	G82156	RHEEM / RUUD	\$ 3,501.96	\$ 56.35
16598	Installed/Active	06/28/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.75

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16599	Installed/Active	07/15/2013	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 65.53
16600	Installed/Active	07/08/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16601	Installed/Active	07/15/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 17.81
16602	Installed/Active	07/08/2013	FSG50	AO SMITH	\$ 850.00	\$ 12.56
16603	Installed/Active	07/06/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 12.56
16604	Installed/Active	07/02/2013	MI40T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16605	Installed/Active	06/22/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16606	Installed/Active	07/03/2013	MI403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16607	Installed/Active	06/28/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16608	Installed/Active	07/02/2013	MI403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16609	Installed/Active	07/01/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16610	Installed/Active	07/16/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16611	Installed/Active	07/10/2013	PH2DV50F	Ruud	\$ 979.00	\$ 7.65
16612	Installed/Active	07/09/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16613	Installed/Active	07/24/2013	MI403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16614	Installed/Active	07/19/2013	M45036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16615	Installed/Active	07/07/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16616	Installed/Active	07/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16617	Installed/Active	07/01/2013	M440T6FBN	BRADFORD-WHITE	\$ 667.00	\$ 12.56
16618	Installed/Active	07/20/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16619	Installed/Active	07/10/2013	MI40T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16620	Installed/Active	07/06/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16621	Installed/Active	07/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16622	Installed/Active	07/17/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16623	Installed/Active	07/12/2013	DS140S6FBN	BRADFORD-WHITE	\$ 1,020.00	\$ 17.81
16624	Installed/Active	07/11/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16625	Installed/Active	06/29/2013	MI50L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.75
16626	Installed/Active	07/15/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 17.81
16627	Installed/Active	07/17/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16628	Installed/Active	07/11/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16629	Installed/Active	07/28/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16630	Installed/Active	07/26/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16631	Installed/Active	07/17/2013	P230F	RUUD	\$ 850.00	\$ 6.06
16632	Installed/Active	06/06/2013	MI50L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.75
16633	Installed/Active	07/24/2013	P230S30F	RUUD	\$ 865.00	\$ 6.06
16634	Installed/Active	07/24/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16635	Installed/Active	07/26/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16636	Installed/Active	07/05/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16637	Installed/Active	07/16/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 6.06
16638	Installed/Active	07/05/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16639	Installed/Active	07/15/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 7.65
16640	Installed/Active	07/13/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
16641	Installed/Active	07/26/2013	MI403S6FBN	Bradford-White	\$ 850.00	\$ 12.56
16642	Installed/Active	06/06/2013	MI50L6FBN	Bradford-White	\$ 744.00	\$ 12.75
16643	Installed/Active	07/02/2013	M2XR504T6FBN	Bradford-White	\$ 1,150.00	\$ 20.36
16644	Installed/Active	07/26/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16645	Installed/Active	07/26/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16646	Installed/Active	07/09/2013	M45036FBN	RHEEM	\$ 683.00	\$ 12.56
16647	Installed/Active	07/31/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16648	Installed/Active	07/30/2013	MI5036FBN	Bradford-White	\$ 850.00	\$ 12.56
16649	Installed/Active	08/05/2013	MI403S6FBN	Bradford-White	\$ 646.00	\$ 12.56
16650	Installed/Active	08/09/2013	M45036FBN	Bradford-White	\$ 660.00	\$ 12.56
16651	Installed/Active	08/02/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16652	Installed/Active	08/05/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 12.56
16653	Installed/Active	07/25/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16654	Installed/Active	07/25/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16655	Installed/Active	07/23/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16656	Installed/Active	07/27/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16657	Installed/Active	07/24/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16658	Installed/Active	07/18/2013	MI403S6FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16659	Installed/Active	07/28/2013	MI40T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.65
16660	Installed/Active	07/22/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
16661	Installed/Active	07/31/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.43
16662	Installed/Active	07/31/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16663	Installed/Active	07/30/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16664	Installed/Active	07/27/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16665	Installed/Active	07/26/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16666	Installed/Active	07/12/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
16667	Installed/Active	07/25/2013	MI75S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 42.08
16668	Installed/Active	06/14/2013	G76200	RUUD	\$ 3,380.00	\$ 64.59
16669	Installed/Active	07/30/2013	MI403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 6.06
16670	Installed/Active	07/24/2013	MI403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16671	Installed/Active	07/27/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16672	Installed/Active	07/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16673	Installed/Active	07/26/2013	MI5036FBN	BRADFORD-WHITE	\$ 660.00	\$ 17.43
16674	Installed/Active	07/30/2013	PR650	STATE	\$ 1,075.00	\$ 17.81
16675	Installed/Active	09/03/2013	MI5036FBN	Bradford-White	\$ 660.00	\$ 12.56
16676	Installed/Active	08/07/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16677	Installed/Active	07/30/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16678	Installed/Active	08/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16679	Installed/Active	08/04/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16680	Installed/Active	08/07/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16681	Installed/Active	07/25/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16682	Installed/Active	07/31/2013	MI5036FBN	BRADFORD WHITE	\$ 660.00	\$ 6.06
16683	Installed/Active	07/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16684	Installed/Active	07/21/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16685	Installed/Active	08/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
16686	Installed/Active	08/06/2013	M45036FBn	Bradford-White	\$ 683.00	\$ 12.56
16687	Installed/Active	08/06/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16688	Installed/Active	08/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16689	Installed/Active	08/06/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16690	Installed/Active	07/19/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16691	Installed/Active	08/09/2013	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16692	Installed/Active	08/15/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16693	Installed/Active	08/15/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16694	Installed/Active	08/24/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 6.06
16695	Installed/Active	08/15/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.06
16696	Installed/Active	08/16/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16697	Installed/Active	08/14/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16698	Installed/Active	08/15/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16699	Installed/Active	08/16/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16700	Installed/Active	08/25/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16701	Installed/Active	08/30/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.06
16702	Installed/Active	07/31/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16703	Installed/Active	08/12/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.81
16704	Installed/Active	08/05/2013	PH19980	PHOENIX	\$ 6,563.69	\$ 65.53
16705	Installed/Active	08/12/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16706	Installed/Active	08/25/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16707	Installed/Active	08/28/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16708	Installed/Active	07/08/2013	G82156	RHEEM	\$ 3,501.96	\$ 56.35
16709	Installed/Active	08/13/2013	G75125	RHEEM	\$ 2,917.34	\$ 42.08
16710	Installed/Active	08/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16711	Installed/Active	08/28/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 7.65
16712	Installed/Active	08/27/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.56
16713	Installed/Active	08/27/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 6.06
16714	Installed/Active	08/27/2013	PH2DV50F	Bradford-White	\$ 979.00	\$ 17.81
16715	Installed/Active	08/23/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16716	Installed/Active	08/23/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16717	Installed/Active	08/26/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 6.06
16718	Installed/Active	08/27/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 6.06
16719	Installed/Active	04/23/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.75
16720	Installed/Active	04/26/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 6.39
16721	Installed/Active	04/24/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 6.39
16722	Installed/Active	08/26/2013	DS140S6FBN	Bradford-White	\$ 1,020.00	\$ 17.81
16723	Installed/Active	04/22/2013	PH13080	Phoenix	\$ 5,916.00	\$ 41.64
16724	Installed/Active	08/30/2013	M1403S6FBN	Bradford-White	\$ 646.00	\$ 6.06
16725	Installed/Active	08/29/2013	PH2DV50F	Ruud	\$ 979.00	\$ 10.98
16726	Installed/Active	08/23/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.56
16727	Installed/Active	08/04/2013	M140T6FBN	Bradford-White	\$ 1,175.00	\$ 12.56
16728	Installed/Active	08/01/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16729	Installed/Active	08/07/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16730	Installed/Active	08/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16731	Installed/Active	07/30/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.65
16732	Installed/Active	08/08/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16733	Installed/Active	08/08/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16734	Installed/Active	07/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16735	Installed/Active	08/23/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16736	Installed/Active	08/03/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16737	Installed/Active	08/16/2013	M15036FBN	Bradford-White	\$ 850.00	\$ 12.56
16738	Installed/Active	08/12/2013	M45036FBN	BRADFORD-WHITE	\$ 680.00	\$ 12.56
16739	Installed/Active	08/06/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16740	Installed/Active	08/30/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16741	Installed/Active	08/29/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16742	Installed/Active	08/13/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.56
16743	Installed/Active	07/30/2013	PH2DV50F	Ruud	\$ 979.00	\$ 10.98
16744	Installed/Active	08/01/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16745	Installed/Active	08/23/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16746	Installed/Active	08/16/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16747	Installed/Active	08/07/2013	DS150S6FBN	Bradford-White	\$ 1,078.00	\$ 17.81
16748	Installed/Active	07/10/2013	PH2DV50F	RUUD	\$ 979.00	\$ 7.65
16749	Installed/Active	04/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.75
16750	Installed/Active	04/28/2013	PH2DV50F	RUUD	\$ 979.00	\$ 11.20
16751	Installed/Active	04/29/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.75
16752	Installed/Active	08/29/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16753	Installed/Active	08/29/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 12.56
16754	Installed/Active	08/10/2013	M45036FBN	Bradford-White	\$ 683.00	\$ 12.56
16755	Installed/Active	07/29/2013	P230F	Ruud	\$ 850.00	\$ 12.56
16756	Installed/Active	08/27/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 12.56
16757	Installed/Active	08/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16758	Installed/Active	08/21/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16759	Installed/Active	08/21/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16760	Installed/Active	08/16/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16761	Installed/Active	08/05/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16762	Installed/Active	08/22/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16763	Installed/Active	08/22/2013	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
16764	Installed/Active	08/16/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16765	Installed/Active	08/19/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.06
16766	Installed/Active	08/30/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.65
16767	Installed/Active	08/26/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16768	Installed/Active	08/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16769	Installed/Active	08/28/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16770	Installed/Active	08/20/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 17.43

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16771	Installed/Active	08/20/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 17.43
16772	Installed/Active	08/20/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16773	Installed/Active	08/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16774	Installed/Active	08/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16775	Installed/Active	08/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16776	Installed/Active	08/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
16777	Installed/Active	08/14/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16778	Installed/Active	08/10/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16779	Installed/Active	08/09/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16780	Installed/Active	08/09/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16781	Installed/Active	08/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16782	Installed/Active	08/15/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16783	Installed/Active	08/13/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16784	Installed/Active	07/31/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16785	Installed/Active	07/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16786	Installed/Active	07/28/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16787	Installed/Active	07/31/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 12.56
16788	Installed/Active	08/01/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16789	Installed/Active	08/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16790	Installed/Active	08/04/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16791	Installed/Active	08/15/2013	M15036FBN	Bradford-White	\$ 683.00	\$ 12.56
16792	Installed/Active	09/09/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16793	Installed/Active	09/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16794	Installed/Active	09/20/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16795	Installed/Active	09/19/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16796	Installed/Active	09/25/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16797	Installed/Active	09/19/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16798	Installed/Active	09/27/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16799	Installed/Active	09/28/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16800	Installed/Active	09/25/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16801	Installed/Active	09/25/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16802	Installed/Active	09/24/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16803	Installed/Active	09/23/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 7.65
16804	Installed/Active	09/23/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16805	Installed/Active	09/18/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 7.65
16806	Installed/Active	08/12/2013	M2XR504T6FBN	Bradford-White	\$ 1,150.00	\$ 17.43
16807	Installed/Active	08/07/2013	M440T6FBN	Bradford-White	\$ 657.00	\$ 12.56
16808	Installed/Active	08/06/2013	M15036FBN	Bradford-White	\$ 660.00	\$ 6.06
16809	Installed/Active	09/14/2013	M45036FBN	Bradford-White	\$ 850.00	\$ 12.56
16810	Installed/Active	08/25/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16811	Installed/Active	09/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16812	Installed/Active	09/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16813	Installed/Active	09/06/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16814	Installed/Active	08/21/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16815	Installed/Active	09/04/2013	PH2DV50F	RUUD	\$ 990.00	\$ 17.81
16816	Installed/Active	09/13/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16817	Installed/Active	09/13/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16818	Installed/Active	09/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16819	Installed/Active	09/24/2013	M140T6FBN	BRADFORD WHITEQ	\$ 646.00	\$ 12.56
16820	Installed/Active	09/24/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16821	Installed/Active	09/21/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.43
16822	Installed/Active	09/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16823	Installed/Active	09/24/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16824	Installed/Active	09/23/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16825	Installed/Active	09/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16826	Installed/Active	09/24/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.65
16827	Installed/Active	09/11/2013	G91200	RHEEM	\$ 3,648.12	\$ 65.53
16828	Installed/Active	09/17/2013	G91200	RHEEM	\$ 3,648.12	\$ 65.53
16829	Installed/Active	09/03/2013	G75125	RHEEM	\$ 2,917.34	\$ 42.08
16830	Installed/Active	09/05/2013	M175S6FBN	BRADFORD WHITE	\$ 950.00	\$ 42.08
16831	Installed/Active	09/11/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16832	Installed/Active	09/10/2013	M150L6FBN	BRADFORD WHITE	\$ 744.00	\$ 12.56
16833	Installed/Active	09/09/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16834	Installed/Active	08/03/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16835	Installed/Active	09/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16836	Installed/Active	09/04/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16837	Installed/Active	09/06/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16838	Installed/Active	09/07/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16839	Installed/Active	08/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16840	Installed/Active	08/27/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
16841	Installed/Active	08/26/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16842	Installed/Active	09/14/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16843	Installed/Active	09/06/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16844	Installed/Active	09/12/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16845	Installed/Active	09/01/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16846	Installed/Active	09/12/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.06
16847	Installed/Active	09/14/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16848	Installed/Active	08/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 7.65
16849	Installed/Active	09/18/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16850	Installed/Active	09/18/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16851	Installed/Active	09/20/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16852	Installed/Active	09/20/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16853	Installed/Active	09/07/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16854	Installed/Active	09/10/2013	M440T6FBN	Bradford White	\$ 657.00	\$ 6.06
16855	Installed/Active	09/02/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16856	Installed/Active	08/23/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16857	Installed/Active	09/13/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16858	Installed/Active	09/12/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
16859	Installed/Active	08/24/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16860	Installed/Active	09/14/2013	MI40T6FBN	Bradford White	\$ 646.00	\$ 12.56
16861	Installed/Active	09/14/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16862	Installed/Active	09/04/2013	M150L6FBN	Bradford White	\$ 744.00	\$ 12.56
16863	Installed/Active	09/26/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16864	Installed/Active	09/26/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16865	Installed/Active	09/20/2013	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 42.08
16866	Installed/Active	09/15/2013	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 56.35
16867	Installed/Active	09/21/2013	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 56.35
16868	Installed/Active	08/03/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.81
16869	Installed/Active	09/21/2013	M45036FBN	Bradford White	\$ 660.00	\$ 12.56
16870	Installed/Active	09/14/2013	PH2DV50F	Ruud	\$ 979.00	\$ 10.98
16871	Installed/Active	09/13/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16872	Installed/Active	09/13/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16873	Installed/Active	08/27/2013	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 17.81
16874	Installed/Active	09/11/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16875	Installed/Active	09/06/2013	PH2DV50F	RUUD	\$ 979.00	\$ 10.98
16876	Installed/Active	09/12/2013	MI40T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16877	Installed/Active	09/28/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 20.36
16878	Installed/Active	08/12/2013	MI40T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 6.06
16879	Installed/Active	10/01/2013	MI75S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 20.36
16880	Installed/Active	10/04/2013	G91200	RHEEMRUUD	\$ 3,367.00	\$ 65.53
16881	Installed/Active	09/12/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16882	Installed/Active	09/16/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16883	Installed/Active	09/11/2013	MI40S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.65
16884	Installed/Active	09/05/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16885	Installed/Active	09/23/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16886	Installed/Active	09/17/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16887	Installed/Active	10/09/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16888	Installed/Active	10/15/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16889	Installed/Active	10/06/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
16890	Installed/Active	10/24/2013	G75125	Ruud	\$ 2,835.00	\$ 42.08
16891	Installed/Active	10/07/2013	G75125	Ruud	\$ 2,835.00	\$ 42.08
16892	Installed/Active	10/27/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
16893	Installed/Active	10/14/2013	M15036FBN	Bradford White	\$ 683.00	\$ 6.06
16894	Installed/Active	10/28/2013	MI40T6FBN	Bradford White	\$ 1,175.00	\$ 12.56
16895	Installed/Active	10/28/2013	MI40T6FBN	Bradford White	\$ 1,175.00	\$ 12.56
16896	Installed/Active	10/28/2013	MI40T6FBN	Bradford White	\$ 1,175.00	\$ 12.56
16897	Installed/Active	09/26/2013	PH2DV50F	Ruud	\$ 979.00	\$ 10.98
16898	Installed/Active	10/02/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16899	Installed/Active	10/17/2013	M440T6FBN	Bradford White	\$ 657.00	\$ 6.06
16900	Installed/Active	10/29/2013	MI40T6FBN	Bradford White	\$ 1,175.00	\$ 12.56
16901	Installed/Active	10/04/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16902	Installed/Active	10/12/2013	MI40T6FBN	Bradford White	\$ 1,175.00	\$ 6.06
16903	Installed/Active	10/16/2013	MI40S6FBN	Bradford White	\$ 646.00	\$ 12.56
16904	Installed/Active	10/31/2013	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 42.08
16905	Installed/Active	10/04/2013	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.56
16906	Installed/Active	09/16/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16907	Installed/Active	08/25/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16908	Installed/Active	08/25/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16909	Installed/Active	09/16/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16910	Installed/Active	10/03/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.81
16911	Installed/Active	10/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16912	Installed/Active	10/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16913	Installed/Active	10/07/2013	MI40T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16914	Installed/Active	10/10/2013	MI40S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16915	Installed/Active	10/10/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.43
16916	Installed/Active	10/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.65
16917	Installed/Active	10/12/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16918	Installed/Active	10/07/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16919	Installed/Active	09/27/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 7.65
16920	Installed/Active	10/01/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16921	Installed/Active	09/30/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16922	Installed/Active	10/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16923	Installed/Active	09/14/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16924	Installed/Active	10/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16925	Installed/Active	10/03/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16926	Installed/Active	10/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16927	Installed/Active	10/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16928	Installed/Active	10/04/2013	P230F	RUUD	\$ 865.00	\$ 6.06
16929	Installed/Active	09/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16930	Installed/Active	10/02/2013	G75125	RUUD	\$ 2,835.00	\$ 42.08
16931	Installed/Active	07/09/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16932	Installed/Active	10/01/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16933	Installed/Active	10/03/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
16934	Installed/Active	10/02/2013	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 12.56
16935	Installed/Active	10/04/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16936	Installed/Active	10/09/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16937	Installed/Active	09/04/2013	MI40S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
16938	Installed/Active	09/26/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
16939	Installed/Active	09/26/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
16940	Installed/Active	08/26/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
16941	Installed/Active	09/06/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16942	Installed/Active	08/28/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 6.06

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
16943	Installed/Active	09/29/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16944	Installed/Active	09/14/2013	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.65
16945	Installed/Active	09/30/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
16946	Installed/Active	10/18/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16947	Installed/Active	10/16/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.65
16948	Installed/Active	10/08/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 7.65
16949	Installed/Active	09/16/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16950	Installed/Active	10/19/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16951	Installed/Active	10/18/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
16952	Installed/Active	10/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16953	Installed/Active	10/19/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16954	Installed/Active	10/27/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16955	Installed/Active	10/20/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16956	Installed/Active	10/23/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16957	Installed/Active	10/19/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16958	Installed/Active	10/15/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16959	Installed/Active	10/18/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.36
16960	Installed/Active	10/29/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.36
16961	Installed/Active	11/03/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16962	Installed/Active	11/07/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16963	Installed/Active	11/18/2013	FSG50	AO SMITH	\$ 850.00	\$ 12.56
16964	Installed/Active	11/19/2013	M45036FBN	Bradford White	\$ 660.00	\$ 12.56
16965	Installed/Active	11/11/2013	PRV50NODS	STATE	\$ 1,075.00	\$ 17.81
16966	Installed/Active	11/15/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16967	Installed/Active	11/08/2013	M150L6FBN	Bradford White	\$ 774.00	\$ 12.56
16968	Installed/Active	10/21/2013	M45036FBN	Bradford White	\$ 660.00	\$ 12.56
16969	Installed/Active	11/01/2013	M150L6FBN	Bradford White	\$ 744.00	\$ 12.56
16970	Installed/Active	11/02/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
16971	Installed/Active	11/15/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16972	Installed/Active	11/03/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16973	Installed/Active	11/18/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16974	Installed/Active	09/17/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
16975	Installed/Active	10/16/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
16976	Installed/Active	10/08/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16977	Installed/Active	10/10/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16978	Installed/Active	10/08/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16979	Installed/Active	10/03/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
16980	Installed/Active	09/09/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
16981	Installed/Active	10/15/2013	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 65.53
16982	Installed/Active	10/15/2013	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 65.53
16983	Installed/Active	10/20/2013	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 56.35
16984	Installed/Active	09/01/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16985	Installed/Active	10/28/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16986	Installed/Active	10/08/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16987	Installed/Active	10/23/2013	M440T6FBN	BRADFORD WHITE	\$ 657.00	\$ 12.56
16988	Installed/Active	10/20/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
16989	Installed/Active	10/28/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
16990	Installed/Active	10/26/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16991	Installed/Active	10/23/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
16992	Installed/Active	10/25/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
16993	Installed/Active	10/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16994	Installed/Active	10/31/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16995	Installed/Active	10/17/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16996	Installed/Active	10/31/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
16997	Installed/Active	10/29/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16998	Installed/Active	10/26/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
16999	Installed/Active	10/21/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17000	Installed/Active	10/06/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17001	Installed/Active	09/17/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.43
17002	Installed/Active	09/17/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17003	Installed/Active	09/24/2013	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17004	Installed/Active	09/25/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17005	Installed/Active	09/04/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
17006	Installed/Active	09/24/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 7.65
17007	Installed/Active	09/20/2013	P230F	RUUD	\$ 865.00	\$ 7.65
17008	Installed/Active	09/10/2013	DS140S6FBN	BRADFORD-WHITE DIRECT VENT	\$ 1,020.00	\$ 17.81
17009	Installed/Active	09/14/2013	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17010	Installed/Active	09/17/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17011	Installed/Active	09/14/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17012	Installed/Active	09/14/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 7.65
17013	Installed/Active	09/13/2013	M440T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 7.65
17014	Installed/Active	11/06/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17015	Installed/Active	10/23/2013	M150L6FBN	Bradford White	\$ 744.00	\$ 12.56
17016	Installed/Active	11/01/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17017	Installed/Active	11/04/2013	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 17.81
17018	Installed/Active	10/28/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17019	Installed/Active	11/02/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.43
17020	Installed/Active	10/30/2013	M1403S6FBN	Bradford White	\$ 646.00	\$ 6.06
17021	Installed/Active	11/07/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17022	Installed/Active	10/31/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17023	Installed/Active	11/04/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17024	Installed/Active	11/01/2013	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17025	Installed/Active	11/02/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17026	Installed/Active	10/26/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17027	Installed/Active	11/05/2013	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17028	Installed/Active	11/07/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17029	Installed/Active	11/02/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17030	Installed/Active	11/01/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17031	Installed/Active	10/24/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17032	Installed/Active	11/14/2013	G76200	RUUD	\$ 3,380.00	\$ 65.53
17033	Installed/Active	11/11/2013	G75125	RUUD	\$ 2,835.00	\$ 42.08
17034	Installed/Active	01/16/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17035	Installed/Active	11/28/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17036	Installed/Active	11/07/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17037	Installed/Active	11/07/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17038	Installed/Active	11/04/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17039	Installed/Active	11/02/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17040	Installed/Active	11/01/2013	M140T6FBN	Bradford White	\$ 646.00	\$ 6.06
17041	Installed/Active	11/13/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17042	Installed/Active	11/12/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17043	Installed/Active	10/29/2013	M150L6FBN	Bradford White	\$ 744.00	\$ 6.06
17044	Installed/Active	11/13/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.43
17045	Installed/Active	11/14/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17046	Installed/Active	11/11/2013	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 17.81
17047	Installed/Active	11/11/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17048	Installed/Active	11/06/2013	M15036FBN	Bradford White	\$ 660.00	\$ 7.65
17049	Installed/Active	10/27/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17050	Installed/Active	11/01/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17051	Installed/Active	10/26/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17052	Installed/Active	11/01/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17053	Installed/Active	11/07/2013	M1403S6FBN	Bradford White	\$ 646.00	\$ 6.06
17054	Installed/Active	11/01/2013	PH2DV50F	Bradford White	\$ 979.00	\$ 17.81
17055	Installed/Active	11/19/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17056	Installed/Active	09/17/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17057	Installed/Active	09/14/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17058	Installed/Active	09/12/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17059	Installed/Active	09/12/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17060	Installed/Active	09/19/2013	M140T6FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
17061	Installed/Active	09/19/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17062	Installed/Active	09/19/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17063	Installed/Active	11/01/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17064	Installed/Active	10/13/2013	G91200	RUUD/RHEEM	\$ 3,650.00	\$ 65.53
17065	Installed/Active	10/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17066	Installed/Active	10/29/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17067	Installed/Active	10/31/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17068	Installed/Active	10/29/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.06
17069	Installed/Active	11/06/2013	M140T6FBN	Bradford White	\$ 850.00	\$ 7.65
17070	Installed/Active	11/11/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17071	Installed/Active	11/14/2013	M150L6FBN	Bradford White	\$ 744.00	\$ 12.56
17072	Installed/Active	10/24/2013	M1403S6FBN	BRADFORD-WHITE	\$ 664.00	\$ 12.56
17073	Installed/Active	10/29/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17074	Installed/Active	11/14/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17075	Installed/Active	10/23/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17076	Installed/Active	10/30/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17077	Installed/Active	11/08/2013	M15036FBN	Bradford White	\$ 660.00	\$ 7.65
17078	Installed/Active	10/23/2013	M15036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17079	Installed/Active	10/28/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17080	Installed/Active	12/08/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17081	Installed/Active	11/14/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 15.47
17082	Installed/Active	11/25/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17083	Installed/Active	11/27/2013	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 17.81
17084	Installed/Active	11/20/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17085	Installed/Active	11/22/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17086	Installed/Active	11/16/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
17087	Installed/Active	11/19/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17088	Installed/Active	11/23/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17089	Installed/Active	11/25/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17090	Installed/Active	11/22/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
17091	Installed/Active	11/28/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17092	Installed/Active	11/27/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17093	Installed/Active	11/04/2013	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 17.81
17094	Installed/Active	10/22/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17095	Installed/Active	10/23/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17096	Installed/Active	10/22/2013	M15036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17097	Installed/Active	10/28/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17098	Installed/Active	10/31/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 7.65
17099	Installed/Active	10/28/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17100	Installed/Active	10/24/2013	M150L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.56
17101	Installed/Active	10/11/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17102	Installed/Active	10/18/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17103	Installed/Active	10/18/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17104	Installed/Active	10/18/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17105	Installed/Active	12/09/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 17.81
17106	Installed/Active	12/06/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
17107	Installed/Active	10/21/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17108	Installed/Active	10/20/2013	M150L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.56
17109	Installed/Active	10/08/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17110	Installed/Active	10/22/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17111	Installed/Active	10/21/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 12.56
17112	Installed/Active	10/29/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17113	Installed/Active	10/23/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17114	Installed/Active	10/28/2013	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17115	Installed/Active	10/28/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17116	Installed/Active	10/15/2013	M45036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17117	Installed/Active	10/16/2013	DS150S6FBN	BRADFORD-WHITE DIRECT VENT	\$ 1,078.00	\$ 17.81
17118	Installed/Active	08/29/2013	M150L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.56
17119	Installed/Active	10/08/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17120	Installed/Active	10/15/2013	P230F	RUUD	\$ 865.00	\$ 6.06
17121	Installed/Active	10/12/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17122	Installed/Active	12/21/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17123	Installed/Active	12/20/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17124	Installed/Active	12/26/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17125	Installed/Active	12/20/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
17126	Installed/Active	12/21/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 20.36
17127	Installed/Active	12/13/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17128	Installed/Active	12/11/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17129	Installed/Active	12/02/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17130	Installed/Active	12/12/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17131	Installed/Active	10/07/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17132	Installed/Active	12/10/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
17133	Installed/Active	12/10/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17134	Installed/Active	12/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17135	Installed/Active	10/07/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17136	Installed/Active	10/15/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17137	Installed/Active	08/15/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 12.56
17138	Installed/Active	09/30/2013	M1403S6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.65
17139	Installed/Active	10/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 17.43
17140	Installed/Active	10/17/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17141	Installed/Active	10/15/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17142	Installed/Active	11/26/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17143	Installed/Active	10/10/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 6.06
17144	Installed/Active	11/29/2013	G91200	Ruud	\$ 3,367.00	\$ 65.53
17145	Installed/Active	11/20/2013	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 65.53
17146	Installed/Active	11/20/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17147	Installed/Active	11/20/2013	M140T6FBN	Bradford White	\$ 646.00	\$ 6.06
17148	Installed/Active	11/20/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17149	Installed/Active	11/18/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17150	Installed/Active	11/21/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17151	Installed/Active	11/26/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17152	Installed/Active	12/02/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17153	Installed/Active	12/04/2013	M45036FBN	BRADFORD WHITEQ	\$ 683.00	\$ 12.56
17154	Installed/Active	12/13/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17155	Installed/Active	11/26/2013	DS150S6FBN	Bradford White	\$ 1,078.00	\$ 17.81
17156	Installed/Active	12/13/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 6.06
17157	Installed/Active	11/19/2013	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 12.56
17158	Installed/Active	10/10/2013	P230F	RUUD/RHEEM	\$ 865.00	\$ 12.56
17159	Installed/Active	12/10/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17160	Installed/Active	12/18/2013	M1403S6FBN	Bradford White	\$ 646.00	\$ 6.06
17161	Installed/Active	11/18/2013	M45036FBN	Bradford White	\$ 660.00	\$ 12.56
17162	Installed/Active	12/06/2013	M15036FBN	Bradford White	\$ 850.00	\$ 6.06
17163	Installed/Active	12/06/2013	FSG40	AO SMITH	\$ 850.00	\$ 12.56
17164	Installed/Active	12/02/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17165	Installed/Active	12/04/2013	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 17.81
17166	Installed/Active	11/26/2013	M1403S6FBN	Bradford White	\$ 646.00	\$ 6.06
17167	Installed/Active	12/20/2013	M45036FBN	Bradford White	\$ 660.00	\$ 12.56
17168	Installed/Active	12/03/2013	M45036FBN	Bradford White	\$ 660.00	\$ 6.06
17169	Installed/Active	12/17/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17170	Installed/Active	12/17/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.43
17171	Installed/Active	11/27/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17172	Installed/Active	12/19/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17173	Installed/Active	12/08/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17174	Installed/Active	12/11/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17175	Installed/Active	10/25/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17176	Installed/Active	11/07/2013	M175S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 42.08
17177	Installed/Active	11/03/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17178	Installed/Active	11/06/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17179	Installed/Active	11/17/2013	G82156	RUUD	\$ 3,367.00	\$ 56.35
17180	Installed/Active	11/16/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.65
17181	Installed/Active	12/04/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17182	Installed/Active	11/18/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17183	Installed/Active	11/05/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17184	Installed/Active	11/18/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 6.06
17185	Installed/Active	11/18/2013	M1403S6FBN	BRADFORD-WHITE	\$ 646.00	\$ 12.56
17186	Installed/Active	12/24/2013	G82156	RUUD	\$ 3,360.00	\$ 65.53
17187	Installed/Active	11/16/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17188	Installed/Active	12/16/2013	M140T6FBN	BRADFORD WHITE	\$ 646.00	\$ 7.65
17189	Installed/Active	12/11/2013	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.43
17190	Installed/Active	11/14/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17191	Installed/Active	12/15/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17192	Installed/Active	12/11/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17193	Installed/Active	12/23/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17194	Installed/Active	12/04/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17195	Installed/Active	10/29/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17196	Installed/Active	11/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17197	Installed/Active	11/12/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17198	Installed/Active	11/09/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 7.65
17199	Installed/Active	11/11/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17200	Installed/Active	11/19/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17201	Installed/Active	11/15/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17202	Installed/Active	11/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17203	Installed/Active	11/22/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17204	Installed/Active	11/23/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17205	Installed/Active	11/23/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17206	Installed/Active	11/23/2013	M140T6FBN	BRADFORD-WHITE	\$ 657.00	\$ 7.65
17207	Installed/Active	11/25/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17208	Installed/Active	11/22/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.56
17209	Installed/Active	11/25/2013	M15036FBN	BRADFORD-WHITE	\$ 660.00	\$ 12.56
17210	Installed/Active	12/20/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17211	Installed/Active	12/02/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17212	Installed/Active	12/27/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17213	Installed/Active	12/20/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17214	Installed/Active	08/14/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17215	Installed/Active	12/07/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17216	Installed/Active	12/05/2013	M15036FBN	Bradford White	\$ 660.00	\$ 12.56
17217	Installed/Active	12/06/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17218	Installed/Active	12/04/2013	M45036FBN	Bradford White	\$ 683.00	\$ 17.43
17219	Installed/Active	10/30/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17220	Installed/Active	11/27/2013	G76200	RUUD/RHEEM	\$ 3,380.00	\$ 65.53
17221	Installed/Active	11/30/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17222	Installed/Active	11/27/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17223	Installed/Active	11/19/2013	M440T6FBN	Bradford White	\$ 657.00	\$ 12.56
17224	Installed/Active	12/14/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17225	Installed/Active	12/27/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17226	Installed/Active	12/24/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17227	Installed/Active	12/30/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17228	Installed/Active	12/07/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17229	Installed/Active	12/13/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17230	Installed/Active	12/09/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17231	Installed/Active	12/09/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17232	Installed/Active	12/05/2013	PH199119	PHOENIX	\$ 6,732.00	\$ 65.53
17233	Installed/Active	12/16/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17234	Installed/Active	12/14/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17235	Installed/Active	12/16/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17236	Installed/Active	12/06/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17237	Installed/Active	12/17/2013	M15036FBN	BRADFORD WHITE	\$ 660.00	\$ 12.56
17238	Installed/Active	12/28/2013	M45036FBN	BRADFORD WHITE	\$ 683.00	\$ 12.56
17239	Installed/Active	11/26/2013	M45036FBN	Bradford White	\$ 683.00	\$ 17.43
17240	Installed/Active	01/25/2014	M45036FBN	Bradford White	\$ 683.00	\$ 12.84
17241	Installed/Active	12/12/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17242	Installed/Active	12/31/2013	PH2DV50F	Ruud	\$ 979.00	\$ 17.81
17243	Installed/Active	12/03/2013	M45036FBN	Bradford White	\$ 683.00	\$ 12.56
17244	Installed/Active	12/05/2013	M45036FBN	Bradford White	\$ 683.00	\$ 6.06
17245	Installed/Active	12/06/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17246	Installed/Active	11/21/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17247	Installed/Active	11/19/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17248	Installed/Active	11/26/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17249	Installed/Active	12/09/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17250	Installed/Active	12/11/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17251	Installed/Active	12/12/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17252	Installed/Active	12/05/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
17253	Installed/Active	12/09/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17254	Installed/Active	12/10/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17255	Installed/Active	12/09/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17256	Installed/Active	12/06/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17257	Installed/Active	12/03/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17258	Installed/Active	12/05/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17259	Installed/Active	11/26/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17260	Installed/Active	11/26/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17261	Installed/Active	12/30/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17262	Installed/Active	12/30/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17263	Installed/Active	09/26/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17264	Installed/Active	01/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17265	Installed/Active	12/26/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17266	Installed/Active	12/24/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17267	Installed/Active	01/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17268	Installed/Active	10/29/2013	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17269	Installed/Active	12/10/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17270	Installed/Active	12/12/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17271	Installed/Active	01/06/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17272	Installed/Active	01/08/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 20.81
17273	Installed/Active	12/26/2013	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.06
17274	Installed/Active	01/04/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17275	Installed/Active	01/08/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17276	Installed/Active	12/12/2013	G100200	RUUD	\$ 3,419.00	\$ 65.53
17277	Installed/Active	12/06/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17278	Installed/Active	10/10/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17279	Installed/Active	06/26/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.89
17280	Installed/Active	01/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17281	Installed/Active	01/08/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
17282	Installed/Active	01/08/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17283	Installed/Active	12/26/2013	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.43
17284	Installed/Active	12/23/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 20.36
17285	Installed/Active	12/19/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17286	Installed/Active	12/15/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17287	Installed/Active	12/29/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17288	Installed/Active	01/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 17.81
17289	Installed/Active	12/31/2013	M440T6FBN	Bradford White	\$ 850.00	\$ 12.56
17290	Installed/Active	12/17/2013	M45036FBN	Bradford White	\$ 850.00	\$ 6.06
17291	Installed/Active	12/26/2013	PH2DV50F	Bradford White	\$ 979.00	\$ 17.81
17292	Installed/Active	01/02/2014	M150L6FBN	Bradford White	\$ 850.00	\$ 12.84
17293	Installed/Active	01/02/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17294	Installed/Active	01/06/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
17295	Installed/Active	12/29/2013	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 20.36
17296	Installed/Active	01/12/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17297	Installed/Active	01/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17298	Installed/Active	01/14/2014	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 18.20
17299	Installed/Active	01/14/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17300	Installed/Active	01/20/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17301	Installed/Active	01/21/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17302	Installed/Active	01/27/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
17303	Installed/Active	01/24/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17304	Installed/Active	01/20/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17305	Installed/Active	01/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17306	Installed/Active	12/19/2013	M140T6FBN	Bradford White	\$ 850.00	\$ 12.56
17307	Installed/Active	01/17/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17308	Installed/Active	11/18/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17309	Installed/Active	01/16/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17310	Installed/Active	01/24/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17311	Installed/Active	12/04/2013	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 56.35
17312	Installed/Active	12/31/2013	M45036FBN	Bradford White	\$ 850.00	\$ 7.65
17313	Installed/Active	01/19/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17314	Installed/Active	01/17/2014	FGR50	AO SMITH	\$ 850.00	\$ 6.19
17315	Installed/Active	01/26/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17316	Installed/Active	01/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17317	Installed/Active	01/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17318	Installed/Active	01/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17319	Installed/Active	01/19/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17320	Installed/Active	01/28/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17321	Installed/Active	12/17/2013	G91200	RUUD	\$ 3,367.00	\$ 65.53
17322	Installed/Active	12/15/2013	M45036FBN	Bradford White	\$ 850.00	\$ 6.06
17323	Installed/Active	12/14/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17324	Installed/Active	12/31/2013	M440T6FBN	Bradford White	\$ 850.00	\$ 6.06
17325	Installed/Active	01/08/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17326	Installed/Active	01/10/2014	PH2DV50F	RUUD/RHEEM	\$ 979.00	\$ 18.20
17327	Installed/Active	12/19/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
17328	Installed/Active	12/06/2013	G75125	Bradford White	\$ 1,900.00	\$ 42.08
17329	Installed/Active	12/15/2013	M150L6FBN	Bradford White	\$ 850.00	\$ 12.56
17330	Installed/Active	01/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17331	Installed/Active	01/02/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17332	Installed/Active	01/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17333	Installed/Active	12/17/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
17334	Installed/Active	01/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17335	Installed/Active	12/23/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
17336	Installed/Active	12/04/2013	P230F	RUUD	\$ 850.00	\$ 6.06
17337	Installed/Active	11/06/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.65
17338	Installed/Active	10/30/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17339	Installed/Active	10/30/2013	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17340	Installed/Active	11/30/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.43
17341	Installed/Active	12/07/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17342	Installed/Active	01/09/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17343	Installed/Active	12/18/2013	M15036FBN	Bradford White	\$ 850.00	\$ 12.56
17344	Installed/Active	01/05/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 7.82
17345	Installed/Active	01/09/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17346	Installed/Active	12/21/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17347	Installed/Active	12/27/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17348	Installed/Active	11/26/2013	M140T6FBN	Bradford White	\$ 850.00	\$ 7.65
17349	Installed/Active	12/22/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
17350	Installed/Active	12/29/2013	PH2DV50F	RUUD	\$ 979.00	\$ 10.98
17351	Installed/Active	12/29/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17352	Installed/Active	12/30/2013	PHR50	RUUD	\$ 850.00	\$ 6.06
17353	Installed/Active	12/30/2013	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
17354	Installed/Active	12/16/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17355	Installed/Active	12/31/2013	PH2DV50F	RUUD	\$ 1,075.00	\$ 10.98
17356	Installed/Active	06/20/2013	G91200	RUUD	\$ 3,367.00	\$ 64.59
17357	Installed/Active	12/20/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17358	Installed/Active	12/31/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17359	Installed/Active	12/31/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17360	Installed/Active	12/31/2013	M440T6FBN	Bradford White	\$ 850.00	\$ 12.56
17361	Installed/Active	11/29/2013	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.43
17362	Installed/Active	12/02/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17363	Installed/Active	12/02/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17364	Installed/Active	12/30/2013	M45036FBN	BRADFORD-WHITE	\$ 880.00	\$ 12.56
17365	Installed/Active	11/05/2013	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17366	Installed/Active	12/11/2013	G91200	RUUD	\$ 3,350.00	\$ 65.53
17367	Installed/Active	01/08/2014	P230F	RUUD	\$ 850.00	\$ 6.19
17368	Installed/Active	01/04/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17369	Installed/Active	12/26/2013	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17370	Installed/Active	01/10/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17371	Installed/Active	01/07/2014	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17372	Installed/Active	01/06/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17373	Installed/Active	12/30/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17374	Installed/Active	01/07/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
17375	Installed/Active	01/02/2014	PH2DV50F	RUUD	\$ 979.00	\$ 6.19
17376	Installed/Active	12/09/2013	MI50L6FBN	BRADFORD-WHITE	\$ 744.00	\$ 12.56
17377	Installed/Active	05/28/2013	P230F	RUUD	\$ 850.00	\$ 12.75
17378	Installed/Active	12/13/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17379	Installed/Active	12/30/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17380	Installed/Active	12/27/2013	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17381	Installed/Active	12/28/2013	G82156	RUUD	\$ 3,360.00	\$ 56.35
17382	Installed/Active	01/07/2014	RF82156	RUUD	\$ 3,360.00	\$ 57.58
17383	Installed/Active	01/04/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17384	Installed/Active	01/02/2014	PH2DV50F	RUUD	\$ 979.00	\$ 11.22
17385	Installed/Active	12/30/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17386	Installed/Active	01/06/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17387	Installed/Active	12/06/2013	G82156	RUUD	\$ 3,350.00	\$ 56.35
17388	Installed/Active	01/10/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17389	Installed/Active	01/10/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17390	Installed/Active	01/15/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17391	Installed/Active	01/10/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17392	Installed/Active	01/06/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17393	Installed/Active	12/26/2013	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.06
17394	Installed/Active	12/13/2013	PH2DV50F	RUUD	\$ 979.00	\$ 17.81
17395	Installed/Active	01/14/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17396	Installed/Active	01/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17397	Installed/Active	01/26/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17398	Installed/Active	01/30/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17399	Installed/Active	01/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17400	Installed/Active	01/19/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17401	Installed/Active	01/22/2014	PH199119	PHOENIX	\$ 6,732.00	\$ 66.97
17402	Installed/Active	01/20/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17403	Installed/Active	01/21/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17404	Installed/Active	01/22/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17405	Installed/Active	01/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17406	Installed/Active	01/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17407	Installed/Active	01/16/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17408	Installed/Active	12/28/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.56
17409	Installed/Active	01/02/2014	G82156	RUUD	\$ 3,360.00	\$ 32.85
17410	Installed/Active	01/15/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17411	Installed/Active	01/11/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17412	Installed/Active	01/09/2014	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 17.81
17413	Installed/Active	01/06/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17414	Installed/Active	01/07/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17415	Installed/Active	01/09/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17416	Installed/Active	01/16/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17417	Installed/Active	01/28/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17418	Installed/Active	01/29/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17419	Installed/Active	12/27/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.56
17420	Installed/Active	01/23/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17421	Installed/Active	01/23/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17422	Installed/Active	01/27/2014	PGR50	AO SMITH	\$ 850.00	\$ 12.84
17423	Installed/Active	01/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17424	Installed/Active	02/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17425	Installed/Active	02/01/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
17426	Installed/Active	01/28/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17427	Installed/Active	02/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17428	Installed/Active	02/06/2014	PH2DV50F	RUUD	\$ 1,075.00	\$ 18.20
17429	Installed/Active	01/28/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17430	Installed/Active	01/29/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17431	Installed/Active	01/21/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17432	Installed/Active	01/22/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17433	Installed/Active	01/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17434	Installed/Active	01/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17435	Installed/Active	02/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17436	Installed/Active	02/11/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17437	Installed/Active	02/08/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17438	Installed/Active	02/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 17.81
17439	Installed/Active	01/31/2014	PH2DV50F	RUUD	\$ 979.00	\$ 11.22
17440	Installed/Active	01/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17441	Installed/Active	02/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17442	Installed/Active	02/07/2014	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.20
17443	Installed/Active	02/08/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17444	Installed/Active	02/06/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17445	Installed/Active	02/06/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17446	Installed/Active	02/03/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17447	Installed/Active	02/03/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17448	Installed/Active	02/04/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17449	Installed/Active	02/07/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17450	Installed/Active	02/07/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17451	Installed/Active	01/20/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17452	Installed/Active	01/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17453	Installed/Active	01/21/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17454	Installed/Active	01/21/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17455	Installed/Active	01/23/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17456	Installed/Active	01/23/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.82
17457	Installed/Active	01/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17458	Installed/Active	01/21/2014	PGR50	AO SMITH	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17459	Installed/Active	01/21/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.19
17460	Installed/Active	01/21/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17461	Installed/Active	02/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17462	Installed/Active	02/10/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 11.22
17463	Installed/Active	02/06/2014	MI75S6FBN	Bradford White	\$ 1,900.00	\$ 43.00
17464	Installed/Active	02/12/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17465	Installed/Active	12/24/2013	M45036FBN	Bradford White	\$ 850.00	\$ 7.65
17466	Installed/Active	02/14/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17467	Installed/Active	02/19/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17468	Installed/Active	02/19/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17469	Installed/Active	02/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17470	Installed/Active	01/31/2014	G82156	Ruud/Rheem	\$ 3,360.00	\$ 66.97
17471	Installed/Active	02/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17472	Installed/Active	01/27/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
17473	Installed/Active	02/06/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17474	Installed/Active	02/06/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17475	Installed/Active	12/17/2013	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.06
17476	Installed/Active	02/21/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17477	Installed/Active	02/20/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17478	Installed/Active	01/29/2014	G82156	RUUD	\$ 3,360.00	\$ 66.97
17479	Installed/Active	02/19/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17480	Installed/Active	02/14/2014	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17481	Installed/Active	01/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17482	Installed/Active	02/19/2014	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 18.20
17483	Installed/Active	02/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17484	Installed/Active	01/30/2014	G82156	RUUD	\$ 3,360.00	\$ 66.97
17485	Installed/Active	02/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17486	Installed/Active	02/12/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17487	Installed/Active	01/28/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17488	Installed/Active	01/25/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.82
17489	Installed/Active	01/28/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17490	Installed/Active	01/24/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17491	Installed/Active	01/28/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17492	Installed/Active	01/22/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17493	Installed/Active	02/11/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17494	Installed/Active	02/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17495	Installed/Active	02/05/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17496	Installed/Active	01/31/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17497	Installed/Active	01/19/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17498	Installed/Active	02/07/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
17499	Installed/Active	02/08/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17500	Installed/Active	02/10/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.82
17501	Installed/Active	02/07/2014	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17502	Installed/Active	02/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 17.81
17503	Installed/Active	02/17/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17504	Installed/Active	02/02/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17505	Installed/Active	02/17/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17506	Installed/Active	02/21/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17507	Installed/Active	02/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17508	Installed/Active	02/26/2014	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.20
17509	Installed/Active	02/11/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17510	Installed/Active	02/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17511	Installed/Active	02/18/2014	PH2DV50F	RUUD	\$ 979.00	\$ 43.00
17512	Installed/Active	02/11/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17513	Installed/Active	02/03/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17514	Installed/Active	01/31/2014	PH2DV50F	RUUD	\$ 979.00	\$ 12.84
17515	Installed/Active	02/14/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17516	Installed/Active	02/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17517	Installed/Active	01/30/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17518	Installed/Active	02/25/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17519	Installed/Active	01/22/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17520	Installed/Active	02/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17521	Installed/Active	02/24/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17522	Installed/Active	02/20/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17523	Installed/Active	02/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17524	Installed/Active	02/13/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17525	Installed/Active	02/21/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17526	Installed/Active	02/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17527	Installed/Active	02/28/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
17528	Installed/Active	02/28/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17529	Installed/Active	12/26/2013	G75125	RUUD	\$ 2,835.00	\$ 42.08
17530	Installed/Active	02/25/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17531	Installed/Active	02/20/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17532	Installed/Active	02/21/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17533	Installed/Active	02/26/2014	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.20
17534	Installed/Active	02/19/2014	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 12.84
17535	Installed/Active	02/18/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17536	Installed/Active	03/21/2013	M45036FBN	BRADFORD-WHITE	\$ 683.00	\$ 6.39
17537	Installed/Active	01/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17538	Installed/Active	02/13/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17539	Installed/Active	02/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17540	Installed/Active	02/13/2014	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 18.20
17541	Installed/Active	02/25/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 7.82
17542	Installed/Active	02/09/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
17543	Installed/Active	02/27/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
17544	Installed/Active	02/08/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17545	Installed/Active	01/26/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17546	Installed/Active	02/14/2014	PH2DV50F	RUUD	\$ 979.00	\$ 11.22
17547	Installed/Active	02/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17548	Installed/Active	02/26/2014	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17549	Installed/Active	02/17/2014	PH2DV50F	RUUD	\$ 1,075.00	\$ 18.20
17550	Installed/Active	02/20/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17551	Installed/Active	02/13/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17552	Installed/Active	02/15/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17553	Installed/Active	02/27/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17554	Installed/Active	02/06/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
17555	Installed/Active	02/27/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17556	Installed/Active	02/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17557	Installed/Active	02/09/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17558	Installed/Active	02/14/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17559	Installed/Active	02/18/2014	P230F	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17560	Installed/Active	02/13/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17561	Installed/Active	01/20/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17562	Installed/Active	02/28/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17563	Installed/Active	03/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17564	Installed/Active	02/19/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17565	Installed/Active	03/04/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17566	Installed/Active	03/04/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17567	Installed/Active	03/03/2014	PROG5038NRU58	Ruud	\$ 979.00	\$ 18.20
17568	Installed/Active	03/06/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
17569	Installed/Active	03/05/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17570	Installed/Active	03/11/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17571	Installed/Active	02/25/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17572	Installed/Active	03/12/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17573	Installed/Active	03/13/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17574	Installed/Active	02/15/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17575	Installed/Active	02/15/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17576	Installed/Active	03/12/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17577	Installed/Active	03/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 17.81
17578	Installed/Active	03/11/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17579	Installed/Active	03/08/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17580	Installed/Active	02/22/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 12.84
17581	Installed/Active	03/07/2014	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 18.20
17582	Installed/Active	03/17/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17583	Installed/Active	03/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17584	Installed/Active	03/16/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17585	Installed/Active	03/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17586	Installed/Active	03/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17587	Installed/Active	03/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17588	Installed/Active	03/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17589	Installed/Active	03/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17590	Installed/Active	03/01/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17591	Installed/Active	02/20/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17592	Installed/Active	03/07/2014	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.00
17593	Installed/Active	03/10/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17594	Installed/Active	03/10/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17595	Installed/Active	03/07/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17596	Installed/Active	03/03/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17597	Installed/Active	03/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17598	Installed/Active	03/12/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17599	Installed/Active	03/01/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
17600	Installed/Active	03/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17601	Installed/Active	02/28/2014	PH2DV50F	Ruud/Rheem	\$ 850.00	\$ 6.19
17602	Installed/Active	03/02/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17603	Installed/Active	02/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17604	Installed/Active	03/19/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17605	Installed/Active	03/10/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17606	Installed/Active	03/07/2014	M45036FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
17607	Installed/Active	03/07/2014	FSG40	AO SMITH	\$ 850.00	\$ 7.82
17608	Installed/Active	03/10/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17609	Installed/Active	02/21/2014	MI75S6FBN	Bradford White	\$ 950.00	\$ 43.00
17610	Installed/Active	03/07/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17611	Installed/Active	03/13/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17612	Installed/Active	03/13/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
17613	Installed/Active	03/20/2014	PH2DV50F	State	\$ 979.00	\$ 18.20
17614	Installed/Active	03/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17615	Installed/Active	02/21/2014	PGX50	AO SMITH	\$ 850.00	\$ 6.19
17616	Installed/Active	03/04/2014	DS140S6FBN	Bradford White	\$ 1,075.00	\$ 18.20
17617	Installed/Active	03/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17618	Installed/Active	03/09/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17619	Installed/Active	03/14/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17620	Installed/Active	03/12/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17621	Installed/Active	03/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17622	Installed/Active	02/23/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17623	Installed/Active	03/18/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17624	Installed/Active	03/20/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17625	Installed/Active	03/26/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17626	Installed/Active	03/28/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17627	Installed/Active	03/20/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17628	Installed/Active	03/20/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17629	Installed/Active	03/20/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17630	Installed/Active	03/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17631	Installed/Active	03/26/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17632	Installed/Active	03/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17633	Installed/Active	03/26/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17634	Installed/Active	03/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17635	Installed/Active	03/22/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
17636	Installed/Active	03/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17637	Installed/Active	03/31/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17638	Installed/Active	03/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17639	Installed/Active	03/31/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
17640	Installed/Active	02/25/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17641	Installed/Active	03/29/2014	PH2DV50F	RHEEM	\$ 979.00	\$ 18.20
17642	Installed/Active	03/31/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17643	Installed/Active	03/21/2014	G76200	Ruud/Rheem	\$ 3,380.00	\$ 66.97
17644	Installed/Active	03/31/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17645	Installed/Active	04/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17646	Installed/Active	04/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17647	Installed/Active	06/19/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17648	Installed/Active	03/31/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17649	Installed/Active	03/25/2014	G91200	Ruud/Rheem	\$ 3,367.00	\$ 66.97
17650	Installed/Active	03/21/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17651	Installed/Active	03/20/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17652	Installed/Active	04/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17653	Installed/Active	03/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
17654	Installed/Active	03/25/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 7.82
17655	Installed/Active	03/28/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.81
17656	Installed/Active	03/19/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 7.82
17657	Installed/Active	03/23/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
17658	Installed/Active	03/19/2014	G75125	Ruud/Rheem	\$ 2,835.00	\$ 43.00
17659	Installed/Active	03/22/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17660	Installed/Active	03/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17661	Installed/Active	03/04/2014	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 18.20
17662	Installed/Active	03/20/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17663	Installed/Active	03/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17664	Installed/Active	03/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17665	Installed/Active	03/25/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17666	Installed/Active	03/17/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17667	Installed/Active	04/14/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
17668	Installed/Active	04/04/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17669	Installed/Active	04/09/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17670	Installed/Active	04/08/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17671	Installed/Active	04/08/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17672	Installed/Active	04/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17673	Installed/Active	04/04/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17674	Installed/Active	03/08/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17675	Installed/Active	03/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17676	Installed/Active	03/25/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17677	Installed/Active	03/21/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17678	Installed/Active	03/19/2014	PH2DV50F	RUUD	\$ 1,075.00	\$ 18.20
17679	Installed/Active	03/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17680	Installed/Active	03/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17681	Installed/Active	03/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17682	Installed/Active	02/10/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17683	Installed/Active	03/25/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17684	Installed/Active	03/24/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17685	Installed/Active	03/31/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
17686	Installed/Active	03/31/2014	PGR40	AO SMITH	\$ 850.00	\$ 12.84
17687	Installed/Active	02/23/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17688	Installed/Active	03/31/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17689	Installed/Active	03/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17690	Installed/Active	04/01/2014	G91200	RUUD	\$ 3,350.00	\$ 66.97
17691	Installed/Active	03/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17692	Installed/Active	04/04/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17693	Installed/Active	03/16/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17694	Installed/Active	04/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17695	Installed/Active	03/24/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17696	Installed/Active	03/24/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17697	Installed/Active	04/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17698	Installed/Active	03/22/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
17699	Installed/Active	04/06/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17700	Installed/Active	04/08/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17701	Installed/Active	03/28/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17702	Installed/Active	04/08/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17703	Installed/Active	04/09/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17704	Installed/Active	04/09/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17705	Installed/Active	04/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17706	Installed/Active	04/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17707	Installed/Active	04/10/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17708	Installed/Active	04/09/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17709	Installed/Active	04/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17710	Installed/Active	04/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17711	Installed/Active	04/07/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17712	Installed/Active	04/12/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17713	Installed/Active	04/15/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17714	Installed/Active	03/22/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17715	Installed/Active	03/15/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17716	Installed/Active	03/26/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17717	Installed/Active	03/25/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17718	Installed/Active	03/20/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17719	Installed/Active	03/20/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17720	Installed/Active	03/24/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17721	Installed/Active	03/21/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17722	Installed/Active	03/22/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
17723	Installed/Active	04/04/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17724	Installed/Active	04/07/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17725	Installed/Active	04/02/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17726	Installed/Active	03/19/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17727	Installed/Active	11/04/2013	M175S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 42.08
17728	Installed/Active	03/25/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17729	Installed/Active	03/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.82
17730	Installed/Active	03/24/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17731	Installed/Active	03/20/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17732	Installed/Active	03/23/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17733	Installed/Active	03/06/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17734	Installed/Active	03/31/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17735	Installed/Active	03/24/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17736	Installed/Active	03/28/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17737	Installed/Active	03/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17738	Installed/Active	03/27/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17739	Installed/Active	03/28/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17740	Installed/Active	03/30/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
17741	Installed/Active	03/31/2014	PH2DV50F	RUUD	\$ 1,075.00	\$ 18.20
17742	Installed/Active	03/31/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17743	Installed/Active	03/23/2014	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 57.58
17744	Installed/Active	04/01/2014	M1404T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17745	Installed/Active	04/01/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17746	Installed/Active	04/01/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17747	Installed/Active	04/01/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
17748	Installed/Active	04/03/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17749	Installed/Active	03/18/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17750	Installed/Active	03/28/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17751	Installed/Active	04/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17752	Installed/Active	04/11/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17753	Installed/Active	04/11/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17754	Installed/Active	03/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 17.81
17755	Installed/Active	03/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17756	Installed/Active	04/14/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17757	Installed/Active	04/02/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17758	Installed/Active	04/09/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17759	Installed/Active	04/08/2014	PROG5038NRU58	Ruud/Rheem	\$ 979.00	\$ 18.20
17760	Installed/Active	04/08/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17761	Installed/Active	04/08/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.81
17762	Installed/Active	03/25/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17763	Installed/Active	03/30/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17764	Installed/Active	04/07/2014	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 18.20
17765	Installed/Active	04/10/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17766	Installed/Active	04/10/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17767	Installed/Active	04/14/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 66.97
17768	Installed/Active	04/13/2014	PH2DV50F	RUUD	\$ 979.00	\$ 11.22
17769	Installed/Active	04/12/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17770	Installed/Active	04/19/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17771	Installed/Active	04/20/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
17772	Installed/Active	04/21/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17773	Installed/Active	04/12/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17774	Installed/Active	04/23/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
17775	Installed/Active	04/22/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17776	Installed/Active	01/09/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17777	Installed/Active	04/18/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17778	Installed/Active	04/13/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17779	Installed/Active	04/22/2014	G76200	RUUD/RHEEM	\$ 3,380.00	\$ 66.97
17780	Installed/Active	04/26/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17781	Installed/Active	04/15/2014	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17782	Installed/Active	04/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17783	Installed/Active	04/20/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17784	Installed/Active	05/06/2014	PH199119	PHOENIX	\$ 6,732.00	\$ 66.97
17785	Installed/Active	05/09/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
17786	Installed/Active	05/09/2014	M15036FBN	Bradford White	\$ 850.00	\$ 6.19
17787	Installed/Active	05/06/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17788	Installed/Active	05/09/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17789	Installed/Active	04/18/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
17790	Installed/Active	04/16/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17791	Installed/Active	04/16/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17792	Installed/Active	04/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17793	Installed/Active	04/11/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17794	Installed/Active	04/21/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17795	Installed/Active	04/17/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17796	Installed/Active	04/17/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
17797	Installed/Active	04/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17798	Installed/Active	04/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17799	Installed/Active	04/23/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17800	Installed/Active	04/09/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17801	Installed/Active	11/16/2013	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.56
17802	Installed/Active	04/21/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17803	Installed/Active	04/22/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 15.81
17804	Installed/Active	04/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17805	Installed/Active	04/24/2014	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.19
17806	Installed/Active	04/17/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17807	Installed/Active	04/28/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17808	Installed/Active	04/27/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
17809	Installed/Active	04/11/2014	PH19980	PHOENIX	\$ 3,350.00	\$ 66.97
17810	Installed/Active	04/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17811	Installed/Active	04/14/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17812	Installed/Active	04/23/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
17813	Installed/Active	04/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17814	Installed/Active	04/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17815	Installed/Active	04/21/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17816	Installed/Active	04/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17817	Installed/Active	03/29/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17818	Installed/Active	05/05/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17819	Installed/Active	04/19/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
17820	Installed/Active	05/02/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
17821	Installed/Active	04/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17822	Installed/Active	04/30/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17823	Installed/Active	04/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17824	Installed/Active	05/06/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17825	Installed/Active	04/21/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17826	Installed/Active	05/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17827	Installed/Active	05/03/2014	PROG5038NRU58	RHEEM/RUUD	\$ 979.00	\$ 11.22
17828	Installed/Active	05/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17829	Installed/Active	05/21/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
17830	Installed/Active	05/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17831	Installed/Active	05/11/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17832	Installed/Active	05/04/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17833	Installed/Active	05/01/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17834	Installed/Active	04/12/2014	P230F	RUUD	\$ 865.00	\$ 6.19
17835	Installed/Active	05/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17836	Installed/Active	05/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17837	Installed/Active	04/30/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17838	Installed/Active	04/30/2014	P230F	RHEEM / RUUD	\$ 850.00	\$ 6.19
17839	Installed/Active	05/06/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17840	Installed/Active	05/08/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17841	Installed/Active	04/26/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17842	Installed/Active	05/09/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17843	Installed/Active	05/03/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17844	Installed/Active	05/08/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17845	Installed/Active	05/08/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17846	Installed/Active	05/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17847	Installed/Active	05/12/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17848	Installed/Active	05/10/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17849	Installed/Active	05/06/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17850	Installed/Active	05/13/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17851	Installed/Active	05/13/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17852	Installed/Active	05/04/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17853	Installed/Active	05/13/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17854	Installed/Active	05/14/2013	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.39
17855	Installed/Active	05/14/2014	G76200	RUUD/RHEEM	\$ 3,380.00	\$ 66.97
17856	Installed/Active	05/02/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17857	Installed/Active	05/08/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17858	Installed/Active	04/24/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.20
17859	Installed/Active	04/30/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
17860	Installed/Active	04/30/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17861	Installed/Active	04/23/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17862	Installed/Active	04/23/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
17863	Installed/Active	04/28/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
17864	Installed/Active	04/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17865	Installed/Active	03/12/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
17866	Installed/Active	04/07/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17867	Installed/Active	05/03/2014	G91200	Ruud/Rheem	\$ 3,367.00	\$ 66.97
17868	Installed/Active	04/20/2014	MI50L6FBN	Bradford White	\$ 850.00	\$ 12.84
17869	Installed/Active	05/03/2014	MI5036FBN	AO SMITH	\$ 850.00	\$ 12.84
17870	Installed/Active	05/01/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 12.84
17871	Installed/Active	05/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17872	Installed/Active	05/01/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17873	Installed/Active	05/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17874	Installed/Active	04/30/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17875	Installed/Active	05/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17876	Installed/Active	04/23/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17877	Installed/Active	05/08/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17878	Installed/Active	05/08/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17879	Installed/Active	05/12/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17880	Installed/Active	05/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17881	Installed/Active	05/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17882	Installed/Active	05/02/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17883	Installed/Active	05/08/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17884	Installed/Active	05/06/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17885	Installed/Active	05/08/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17886	Installed/Active	05/11/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17887	Installed/Active	05/12/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
17888	Installed/Active	05/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17889	Installed/Active	05/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17890	Installed/Active	05/15/2014	G82156	RUUD/RHEEM	\$ 3,367.00	\$ 57.58
17891	Installed/Active	05/14/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 18.20
17892	Installed/Active	05/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17893	Installed/Active	05/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17894	Installed/Active	04/22/2014	G82156	Rheem/Ruud	\$ 3,360.00	\$ 57.58
17895	Installed/Active	05/20/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
17896	Installed/Active	04/22/2014	G82156	RUUD	\$ 3,350.00	\$ 57.58
17897	Installed/Active	05/16/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17898	Installed/Active	05/21/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17899	Installed/Active	05/21/2014	MI75S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 43.00
17900	Installed/Active	05/20/2014	MI40S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17901	Installed/Active	05/20/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17902	Installed/Active	05/21/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 15.81
17903	Installed/Active	05/19/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17904	Installed/Active	05/21/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17905	Installed/Active	05/19/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17906	Installed/Active	05/16/2014	G91200	Rheem/Ruud	\$ 3,380.00	\$ 66.97
17907	Installed/Active	05/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17908	Installed/Active	05/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17909	Installed/Active	05/27/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
17910	Installed/Active	05/14/2014	G76200	Rheem/Ruud	\$ 3,380.00	\$ 66.97
17911	Installed/Active	05/20/2014	MI50L6FBN	Bradford White	\$ 850.00	\$ 6.19
17912	Installed/Active	05/28/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17913	Installed/Active	05/28/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
17914	Installed/Active	05/22/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17915	Installed/Active	05/24/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 7.82
17916	Installed/Active	05/23/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
17917	Installed/Active	05/28/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17918	Installed/Active	05/14/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17919	Installed/Active	05/22/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17920	Installed/Active	05/28/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17921	Installed/Active	05/11/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
17922	Installed/Active	06/03/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17923	Installed/Active	06/02/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17924	Installed/Active	06/05/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
17925	Installed/Active	06/02/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17926	Installed/Active	05/20/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
17927	Installed/Active	05/12/2014	PH2DV50F	Rheem/Ruud	\$ 979.00	\$ 18.20
17928	Installed/Active	05/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17929	Installed/Active	05/11/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17930	Installed/Active	05/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17931	Installed/Active	05/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17932	Installed/Active	05/15/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
17933	Installed/Active	05/15/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
17934	Installed/Active	06/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17935	Installed/Active	05/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17936	Installed/Active	05/02/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17937	Installed/Active	05/22/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
17938	Installed/Active	05/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17939	Installed/Active	05/08/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17940	Installed/Active	05/12/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17941	Installed/Active	05/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17942	Installed/Active	05/27/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17943	Installed/Active	05/11/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
17944	Installed/Active	05/28/2014	G100200	RUUD	\$ 3,419.00	\$ 66.97
17945	Installed/Active	05/29/2014	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 11.22
17946	Installed/Active	06/03/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17947	Installed/Active	06/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17948	Installed/Active	05/31/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17949	Installed/Active	05/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17950	Installed/Active	06/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17951	Installed/Active	06/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17952	Installed/Active	05/07/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17953	Installed/Active	06/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
17954	Installed/Active	06/03/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17955	Installed/Active	05/23/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17956	Installed/Active	05/22/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17957	Installed/Active	05/27/2014	DS140S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 18.20
17958	Installed/Active	05/19/2014	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17959	Installed/Active	06/02/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17960	Installed/Active	05/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17961	Installed/Active	05/22/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
17962	Installed/Active	06/02/2014	MI40S6FBN	Bradford White	\$ 850.00	\$ 12.84
17963	Installed/Active	06/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17964	Installed/Active	05/07/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
17965	Installed/Active	06/03/2014	G82156	Ruud/Rheem	\$ 3,360.00	\$ 57.58
17966	Installed/Active	05/19/2014	G91200	RUUD/RHEEM	\$ 3,380.00	\$ 66.97
17967	Installed/Active	05/31/2014	PH2DV50F	Ruud/Rheem	\$ 979.00	\$ 18.20
17968	Installed/Active	06/06/2014	G91200	RUUD/RHEEM	\$ 3,369.00	\$ 66.97
17969	Installed/Active	06/03/2014	MI40S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17970	Installed/Active	06/01/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
17971	Installed/Active	06/04/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
17972	Installed/Active	05/21/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17973	Installed/Active	06/05/2014	RF82156	Ruud/Rheem	\$ 3,360.00	\$ 57.58
17974	Installed/Active	06/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
17975	Installed/Active	06/04/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
17976	Installed/Active	06/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17977	Installed/Active	05/31/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
17978	Installed/Active	06/11/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17979	Installed/Active	06/06/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17980	Installed/Active	05/24/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
17981	Installed/Active	04/15/2014	G82156	RUUD/RHEEM	\$ 3,367.00	\$ 57.58
17982	Installed/Active	06/04/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17983	Installed/Active	06/08/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
17984	Installed/Active	05/28/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17985	Installed/Active	05/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17986	Installed/Active	06/03/2014	PROG5038NRU58	RUUD	\$ 850.00	\$ 6.19
17987	Installed/Active	06/02/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
17988	Installed/Active	06/10/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17989	Installed/Active	06/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
17990	Installed/Active	06/10/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
17991	Installed/Active	06/13/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
17992	Installed/Active	06/10/2014	PROG5038NRU58DV	Bradford White	\$ 1,075.00	\$ 18.20
17993	Installed/Active	06/12/2014	G100200	STATE	\$ 3,350.00	\$ 66.97
17994	Installed/Active	05/27/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.81
17995	Installed/Active	06/06/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.20
17996	Installed/Active	06/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17997	Installed/Active	06/12/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
17998	Installed/Active	06/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
17999	Installed/Active	06/02/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18000	Installed/Active	06/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18001	Installed/Active	06/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18002	Installed/Active	06/10/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18003	Installed/Active	06/13/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18004	Installed/Active	06/18/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18005	Installed/Active	06/16/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18006	Installed/Active	06/12/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18007	Installed/Active	06/16/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18008	Installed/Active	06/10/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18009	Installed/Active	06/19/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18010	Installed/Active	06/16/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18011	Installed/Active	06/18/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18012	Installed/Active	06/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18013	Installed/Active	06/18/2014	M175S8FBN	BRADFORD-WHITE	\$ 950.00	\$ 43.00
18014	Installed/Active	06/14/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18015	Installed/Active	06/17/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18016	Installed/Active	06/13/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18017	Installed/Active	06/16/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18018	Installed/Active	06/18/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18019	Installed/Active	06/13/2014	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18020	Installed/Active	06/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18021	Installed/Active	06/17/2014	G91200	Rheem/Ruud	\$ 3,367.00	\$ 66.97
18022	Installed/Active	06/16/2014	M15036FBN	Bradford White	\$ 850.00	\$ 6.19
18023	Installed/Active	06/13/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18024	Installed/Active	06/20/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18025	Installed/Active	06/02/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18026	Installed/Active	05/29/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18027	Installed/Active	06/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18028	Installed/Active	06/19/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18029	Installed/Active	06/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18030	Installed/Active	06/17/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18031	Installed/Active	06/18/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18032	Installed/Active	06/16/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18033	Installed/Active	06/12/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18034	Installed/Active	06/24/2014	PROG2932NRU62	RUUD	\$ 850.00	\$ 7.82
18035	Installed/Active	06/25/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18036	Installed/Active	06/10/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18037	Installed/Active	06/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18038	Installed/Active	06/21/2014	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.20
18039	Installed/Active	06/26/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18040	Installed/Active	06/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18041	Installed/Active	06/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18042	Installed/Active	06/25/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18043	Installed/Active	06/15/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18044	Installed/Active	06/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18045	Installed/Active	06/12/2014	PROG2932NRU62	RHEEM/RUUD	\$ 850.00	\$ 7.82
18046	Installed/Active	06/28/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18047	Installed/Active	06/27/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18048	Installed/Active	06/24/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18049	Installed/Active	06/23/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18050	Installed/Active	05/17/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
18051	Installed/Active	06/23/2014	PROG5038NRU58	RUUD / RHEEM	\$ 1,075.00	\$ 18.20
18052	Installed/Active	06/26/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18053	Installed/Active	06/26/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18054	Installed/Active	06/23/2014	G82156	Rheem/Ruud	\$ 3,360.00	\$ 57.58
18055	Installed/Active	06/24/2014	M15036FBN	Bradford White	\$ 850.00	\$ 7.82
18056	Installed/Active	06/26/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18057	Installed/Active	06/21/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18058	Installed/Active	06/24/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 18.20
18059	Installed/Active	06/26/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18060	Installed/Active	06/20/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18061	Installed/Active	06/22/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
18062	Installed/Active	06/21/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18063	Installed/Active	06/23/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18064	Installed/Active	06/30/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18065	Installed/Active	06/28/2014	P230F	RUUD	\$ 850.00	\$ 12.84
18066	Installed/Active	06/19/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18067	Installed/Active	06/24/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
18068	Installed/Active	06/24/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18069	Installed/Active	06/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18070	Installed/Active	06/21/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18071	Installed/Active	07/17/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18072	Installed/Active	07/08/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18073	Installed/Active	07/08/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18074	Installed/Active	07/07/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18075	Installed/Active	07/07/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18076	Installed/Active	07/22/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18077	Installed/Active	07/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18078	Installed/Active	07/08/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18079	Installed/Active	07/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18080	Installed/Active	07/03/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18081	Installed/Active	07/01/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18082	Installed/Active	07/01/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18083	Installed/Active	07/01/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18084	Installed/Active	07/07/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18085	Installed/Active	07/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18086	Installed/Active	07/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18087	Installed/Active	07/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18088	Installed/Active	07/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18089	Installed/Active	07/17/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18090	Installed/Active	07/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18091	Installed/Active	07/16/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18092	Installed/Active	07/17/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
18093	Installed/Active	07/19/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18094	Installed/Active	07/21/2014	PROG5038NRU58	Rheem/Ruud	\$ 1,075.00	\$ 18.20
18095	Installed/Active	07/17/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18096	Installed/Active	07/23/2014	M175S6FBN	BRADFORD-WHITE	\$ 950.00	\$ 43.00
18097	Installed/Active	07/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18098	Installed/Active	07/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18099	Installed/Active	07/23/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
18100	Installed/Active	07/24/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18101	Installed/Active	07/22/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18102	Installed/Active	07/23/2014	M45036FBN	Bradford White	\$ 350.00	\$ 15.81
18103	Installed/Active	07/27/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18104	Installed/Active	07/22/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18105	Installed/Active	07/28/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18106	Installed/Active	07/28/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 11.22
18107	Installed/Active	07/26/2014	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18108	Installed/Active	07/28/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18109	Installed/Active	07/14/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18110	Installed/Active	07/25/2014	FSGL40	AO SMITH	\$ 850.00	\$ 12.84
18111	Installed/Active	06/11/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18112	Installed/Active	07/30/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18113	Installed/Active	07/26/2014	DS140S6FBN	BRADFORD-WHITE	\$ 1,020.00	\$ 18.20
18114	Installed/Active	08/01/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18115	Installed/Active	08/14/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18116	Installed/Active	07/22/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18117	Installed/Active	07/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18118	Installed/Active	07/25/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18119	Installed/Active	07/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18120	Installed/Active	07/31/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18121	Installed/Active	07/18/2014	M175S6FBN	Bradford White	\$ 950.00	\$ 57.58
18122	Installed/Active	06/29/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18123	Installed/Active	07/01/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18124	Installed/Active	07/01/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 18.20
18125	Installed/Active	07/01/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 18.20
18126	Installed/Active	07/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18127	Installed/Active	07/09/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18128	Installed/Active	07/15/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
18129	Installed/Active	07/07/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18130	Installed/Active	07/15/2014	M2XR504T6FBN	RHEEM	\$ 1,150.00	\$ 17.81
18131	Installed/Active	07/08/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18132	Installed/Active	07/09/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18133	Installed/Active	06/24/2014	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18134	Installed/Active	07/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
18135	Installed/Active	07/11/2014	M15036FBN	Bradford White	\$ 850.00	\$ 7.82
18136	Installed/Active	07/15/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18137	Installed/Active	07/09/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18138	Installed/Active	07/10/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18139	Installed/Active	07/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18140	Installed/Active	07/15/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
18141	Installed/Active	07/01/2014	PH13080	PHOENIX	\$ 5,916.00	\$ 57.58
18142	Installed/Active	07/08/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18143	Installed/Active	07/08/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18144	Installed/Active	07/16/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 11.22
18145	Installed/Active	07/02/2014	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18146	Installed/Active	07/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18147	Installed/Active	06/14/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18148	Installed/Active	07/01/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18149	Installed/Active	07/03/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18150	Installed/Active	07/01/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
18151	Installed/Active	07/01/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18152	Installed/Active	06/14/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18153	Installed/Active	07/02/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18154	Installed/Active	07/05/2014	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 12.84
18155	Installed/Active	07/10/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18156	Installed/Active	07/15/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 20.81
18157	Installed/Active	07/14/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18158	Installed/Active	07/17/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
18159	Installed/Active	07/18/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18160	Installed/Active	07/15/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18161	Installed/Active	07/21/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18162	Installed/Active	07/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18163	Installed/Active	07/23/2014	M175S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.00
18164	Installed/Active	07/23/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18165	Installed/Active	07/17/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18166	Installed/Active	07/23/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18167	Installed/Active	07/20/2014	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.20
18168	Installed/Active	07/25/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18169	Installed/Active	07/09/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18170	Installed/Active	07/25/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18171	Installed/Active	07/28/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18172	Installed/Active	07/28/2014	DS140S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 18.20
18173	Installed/Active	07/09/2014	DS140S6FBN	BRADFORD-WHITE	\$ 1,020.00	\$ 18.20
18174	Installed/Active	07/05/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18175	Installed/Active	07/17/2014	G100200	RUUD	\$ 3,350.00	\$ 66.97
18176	Installed/Active	07/16/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18177	Installed/Active	07/18/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18178	Installed/Active	07/15/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18179	Installed/Active	07/21/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18180	Installed/Active	07/20/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18181	Installed/Active	07/21/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18182	Installed/Active	07/13/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18183	Installed/Active	07/24/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18184	Installed/Active	07/30/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18185	Installed/Active	07/23/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18186	Installed/Active	07/28/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18187	Installed/Active	07/28/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18188	Installed/Active	07/31/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18189	Installed/Active	07/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18190	Installed/Active	07/31/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18191	Installed/Active	08/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18192	Installed/Active	08/01/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18193	Installed/Active	08/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18194	Installed/Active	08/06/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18195	Installed/Active	08/06/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18196	Installed/Active	07/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18197	Installed/Active	08/05/2014	M5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18198	Installed/Active	07/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18199	Installed/Active	08/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18200	Installed/Active	08/01/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
18201	Installed/Active	07/29/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18202	Installed/Active	08/04/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18203	Installed/Active	08/04/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18204	Installed/Active	08/04/2014	DS140S6FBN	BRADFORD-WHITE	\$ 1,020.00	\$ 18.20
18205	Installed/Active	07/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18206	Installed/Active	07/30/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18207	Installed/Active	07/26/2014	M5036FBN	Bradford White	\$ 850.00	\$ 12.84
18208	Installed/Active	07/26/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18209	Installed/Active	05/29/2014	G82156	Ruud/Rheem	\$ 3,360.00	\$ 57.58
18210	Installed/Active	07/31/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18211	Installed/Active	07/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18212	Installed/Active	08/05/2014	FSG50	AO SMITH	\$ 850.00	\$ 12.84
18213	Installed/Active	08/07/2014	M5036FBN	Bradford White	\$ 850.00	\$ 12.84
18214	Installed/Active	08/04/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18215	Installed/Active	06/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18216	Installed/Active	08/01/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18217	Installed/Active	08/05/2014	M5036FBN	Bradford White	\$ 850.00	\$ 12.84
18218	Installed/Active	08/06/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18219	Installed/Active	07/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18220	Installed/Active	08/02/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18221	Installed/Active	08/04/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 7.82
18222	Installed/Active	08/08/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18223	Installed/Active	08/08/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18224	Installed/Active	08/11/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.20
18225	Installed/Active	08/09/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18226	Installed/Active	08/11/2014	M5036FBN	Bradford White	\$ 850.00	\$ 12.84
18227	Installed/Active	08/04/2014	M5036FBN	Bradford White	\$ 850.00	\$ 12.84
18228	Installed/Active	08/12/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18229	Installed/Active	07/24/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18230	Installed/Active	08/07/2014	M5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18231	Installed/Active	08/11/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18232	Installed/Active	08/05/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18233	Installed/Active	08/08/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18234	Installed/Active	07/08/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18235	Installed/Active	08/13/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18236	Installed/Active	07/31/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18237	Installed/Active	08/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18238	Installed/Active	08/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18239	Installed/Active	08/05/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18240	Installed/Active	09/03/2014	PROG5038NRU58DV	Rheem	\$ 979.00	\$ 11.22
18241	Installed/Active	08/12/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
18242	Installed/Active	08/12/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18243	Installed/Active	08/17/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18244	Installed/Active	08/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18245	Installed/Active	08/14/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 11.22
18246	Installed/Active	08/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18247	Installed/Active	08/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18248	Installed/Active	08/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18249	Installed/Active	08/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18250	Installed/Active	08/12/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18251	Installed/Active	08/10/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18252	Installed/Active	08/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18253	Installed/Active	08/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18254	Installed/Active	06/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18255	Installed/Active	08/19/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18256	Installed/Active	09/08/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18257	Installed/Active	08/15/2014	DS150S6FBN	BRADFORD-WHITE	\$ 1,078.00	\$ 18.20
18258	Installed/Active	09/23/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18259	Installed/Active	08/19/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18260	Installed/Active	08/27/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18261	Installed/Active	08/22/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18262	Installed/Active	08/12/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18263	Installed/Active	08/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18264	Installed/Active	08/05/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.81
18265	Installed/Active	08/18/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18266	Installed/Active	07/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18267	Installed/Active	08/09/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18268	Installed/Active	08/25/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 17.81
18269	Installed/Active	08/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18270	Installed/Active	08/19/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 11.22
18271	Installed/Active	08/14/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18272	Installed/Active	08/25/2014	PROG5038NRU58	Rheem/Ruud	\$ 979.00	\$ 18.20
18273	Installed/Active	08/22/2014	M175S6FBN	Bradford White	\$ 950.00	\$ 43.00
18274	Installed/Active	08/18/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18275	Installed/Active	08/08/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18276	Installed/Active	08/15/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18277	Installed/Active	08/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18278	Installed/Active	08/27/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18279	Installed/Active	08/28/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18280	Installed/Active	08/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18281	Installed/Active	08/20/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18282	Installed/Active	08/15/2014	G91200	RUUD	\$ 3,350.00	\$ 66.97
18283	Installed/Active	08/08/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18284	Installed/Active	08/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18285	Installed/Active	08/14/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18286	Installed/Active	09/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18287	Installed/Active	09/04/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18288	Installed/Active	09/04/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18289	Installed/Active	09/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18290	Installed/Active	08/12/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18291	Installed/Active	08/16/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 17.81
18292	Installed/Active	09/08/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18293	Installed/Active	08/16/2014	M140T6FBN	BRADFORD-WHITE	\$ 646.00	\$ 7.82
18294	Installed/Active	08/13/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18295	Installed/Active	09/09/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18296	Installed/Active	08/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18297	Installed/Active	09/03/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18298	Installed/Active	09/04/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18299	Installed/Active	09/09/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18300	Installed/Active	09/12/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18301	Installed/Active	09/12/2014	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.19
18302	Installed/Active	08/15/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18303	Installed/Active	09/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18304	Installed/Active	09/09/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18305	Installed/Active	08/13/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18306	Installed/Active	08/19/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18307	Installed/Active	08/19/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18308	Installed/Active	08/14/2014	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.20
18309	Installed/Active	08/12/2014	DS140S6FBN	BRADFORD-WHITE	\$ 1,020.00	\$ 18.20
18310	Installed/Active	08/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18311	Installed/Active	08/12/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18312	Installed/Active	08/05/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18313	Installed/Active	08/15/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18314	Installed/Active	08/18/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18315	Installed/Active	08/21/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18316	Installed/Active	08/05/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18317	Installed/Active	08/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18318	Installed/Active	08/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18319	Installed/Active	09/25/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18320	Installed/Active	08/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18321	Installed/Active	08/20/2014	G91200	Rheem/Ruud	\$ 3,367.00	\$ 66.97
18322	Installed/Active	07/14/2014	M175S6FBN	Bradford White	\$ 950.00	\$ 43.00
18323	Installed/Active	07/30/2014	M175S6FBN	Bradford White	\$ 950.00	\$ 20.81
18324	Installed/Active	08/25/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18325	Installed/Active	08/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18326	Installed/Active	08/26/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18327	Installed/Active	08/22/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18328	Installed/Active	08/18/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18329	Installed/Active	08/27/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18330	Installed/Active	08/28/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18331	Installed/Active	08/19/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18332	Installed/Active	08/25/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18333	Installed/Active	08/19/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18334	Installed/Active	08/08/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
18335	Installed/Active	09/02/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18336	Installed/Active	08/27/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18337	Installed/Active	08/27/2014	M150L6FBN	Bradford White	\$ 850.00	\$ 12.84
18338	Installed/Active	08/27/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18339	Installed/Active	08/13/2014	PROG5038NRU58DV	Bradford White	\$ 1,075.00	\$ 18.20
18340	Installed/Active	08/30/2014	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.97
18341	Installed/Active	08/27/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18342	Installed/Active	08/29/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18343	Installed/Active	08/29/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18344	Installed/Active	08/29/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18345	Installed/Active	08/26/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 66.97
18346	Installed/Active	09/04/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18347	Installed/Active	09/05/2014	G76200	RUUD/RHEEM	\$ 3,380.00	\$ 66.97
18348	Installed/Active	09/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18349	Installed/Active	09/06/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18350	Installed/Active	09/10/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18351	Installed/Active	09/02/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18352	Installed/Active	09/07/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18353	Installed/Active	08/21/2014	M175S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.00
18354	Installed/Active	09/01/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18355	Installed/Active	09/01/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18356	Installed/Active	08/28/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18357	Installed/Active	08/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18358	Installed/Active	08/29/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 11.22
18359	Installed/Active	08/29/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18360	Installed/Active	09/03/2014	PROG2932NRU62	Rheem/Ruud	\$ 850.00	\$ 6.19
18361	Installed/Active	09/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18362	Installed/Active	07/08/2014	G75125	RHEEM	\$ 2,835.00	\$ 43.00
18363	Installed/Active	09/11/2014	PROG5038NRU58DV	RUUD/RHEEM	\$ 979.00	\$ 18.20
18364	Installed/Active	09/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18365	Installed/Active	09/16/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18366	Installed/Active	09/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18367	Installed/Active	09/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18368	Installed/Active	09/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18369	Installed/Active	09/02/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18370	Installed/Active	09/10/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18371	Installed/Active	09/12/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18372	Installed/Active	09/13/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18373	Installed/Active	09/18/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18374	Installed/Active	09/13/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18375	Installed/Active	09/10/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18376	Installed/Active	09/02/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18377	Installed/Active	09/18/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18378	Installed/Active	09/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18379	Installed/Active	09/19/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18380	Installed/Active	09/22/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
18381	Installed/Active	09/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18382	Installed/Active	09/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18383	Installed/Active	09/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18384	Installed/Active	09/16/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18385	Installed/Active	09/06/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18386	Installed/Active	09/22/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18387	Installed/Active	08/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18388	Installed/Active	09/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18389	Installed/Active	09/10/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18390	Installed/Active	09/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18391	Installed/Active	09/16/2014	XVR50	A. O. SMITH	\$ 850.00	\$ 12.84
18392	Installed/Active	09/09/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18393	Installed/Active	09/11/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18394	Installed/Active	09/18/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18395	Installed/Active	03/23/2007	LTN050G	LOCHINVAR	\$ 850.00	\$ 16.35
18396	Installed/Active	10/07/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18397	Installed/Active	08/27/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 20.81
18398	Installed/Active	09/07/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18399	Installed/Active	09/17/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18400	Installed/Active	09/18/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18401	Installed/Active	09/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18402	Installed/Active	09/20/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18403	Installed/Active	09/22/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18404	Installed/Active	09/22/2014	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.00

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18405	Installed/Active	09/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18406	Installed/Active	08/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18407	Installed/Active	09/13/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18408	Installed/Active	09/08/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18409	Installed/Active	09/12/2014	P506	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18410	Installed/Active	09/16/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18411	Installed/Active	09/16/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18412	Installed/Active	09/25/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18413	Installed/Active	09/25/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18414	Installed/Active	09/03/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18415	Installed/Active	09/12/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18416	Installed/Active	09/10/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18417	Installed/Active	09/19/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18418	Installed/Active	09/22/2014	PROG5038NRU58DV	Rheem/Ruud	\$ 979.00	\$ 18.20
18419	Installed/Active	09/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18420	Installed/Active	09/23/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18421	Installed/Active	09/19/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
18422	Installed/Active	09/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18423	Installed/Active	09/28/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18424	Installed/Active	09/29/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18425	Installed/Active	09/27/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18426	Installed/Active	09/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18427	Installed/Active	09/26/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18428	Installed/Active	09/29/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
18429	Installed/Active	09/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18430	Installed/Active	09/30/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18431	Installed/Active	09/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18432	Installed/Active	09/30/2014	PROG5038NRU58DV	RUUD/RHEEM	\$ 979.00	\$ 18.20
18433	Installed/Active	10/03/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18434	Installed/Active	09/29/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18435	Installed/Active	09/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18436	Installed/Active	09/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18437	Installed/Active	09/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18438	Installed/Active	09/29/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18439	Installed/Active	09/30/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18440	Installed/Active	09/22/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18441	Installed/Active	09/09/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18442	Installed/Active	10/01/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18443	Installed/Active	09/18/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.81
18444	Installed/Active	10/03/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18445	Installed/Active	10/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18446	Installed/Active	09/30/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18447	Installed/Active	09/25/2014	G82156	Ruud/Rheem	\$ 3,350.00	\$ 57.58
18448	Installed/Active	09/29/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18449	Installed/Active	09/04/2014	MI75S6FBN	Bradford White	\$ 950.00	\$ 43.00
18450	Installed/Active	09/04/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18451	Installed/Active	09/04/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18452	Installed/Active	09/26/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18453	Installed/Active	09/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18454	Installed/Active	09/24/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.81
18455	Installed/Active	09/23/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18456	Installed/Active	10/06/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18457	Installed/Active	09/28/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18458	Installed/Active	10/09/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18459	Installed/Active	10/03/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18460	Installed/Active	09/30/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18461	Installed/Active	10/03/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18462	Installed/Active	10/02/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18463	Installed/Active	10/21/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18464	Installed/Active	10/01/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18465	Installed/Active	09/29/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18466	Installed/Active	10/07/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18467	Installed/Active	10/07/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.20
18468	Installed/Active	09/27/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18469	Installed/Active	10/06/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.19
18470	Installed/Active	10/01/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 7.82
18471	Installed/Active	09/27/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18472	Installed/Active	10/22/2014	MI403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18473	Installed/Active	09/26/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18474	Installed/Active	10/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18475	Installed/Active	10/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18476	Installed/Active	10/08/2014	PROG5038NRU58DV	RUUD/RHEEM	\$ 979.00	\$ 18.20
18477	Installed/Active	09/30/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18478	Installed/Active	09/13/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18479	Installed/Active	10/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18480	Installed/Active	10/08/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18481	Installed/Active	10/14/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18482	Installed/Active	10/13/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18483	Installed/Active	09/28/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18484	Installed/Active	10/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18485	Installed/Active	10/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18486	Installed/Active	10/09/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18487	Installed/Active	10/08/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18488	Installed/Active	10/15/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 17.81
18489	Installed/Active	10/15/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18490	Installed/Active	10/17/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18491	Installed/Active	10/14/2014	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18492	Installed/Active	10/15/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18493	Installed/Active	10/17/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18494	Installed/Active	10/08/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
18495	Installed/Active	10/16/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18496	Installed/Active	09/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18497	Installed/Active	10/11/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18498	Installed/Active	10/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18499	Installed/Active	10/01/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18500	Installed/Active	10/10/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18501	Installed/Active	09/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18502	Installed/Active	10/09/2014	PROG5038NRU58DV	RUUD RHEEM	\$ 979.00	\$ 18.20
18503	Installed/Active	10/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18504	Installed/Active	10/09/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18505	Installed/Active	10/13/2014	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 57.58
18506	Installed/Active	10/19/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18507	Installed/Active	10/16/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18508	Installed/Active	10/16/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
18509	Installed/Active	10/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18510	Installed/Active	10/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18511	Installed/Active	10/15/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 7.82
18512	Installed/Active	10/19/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 12.84
18513	Installed/Active	10/11/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18514	Installed/Active	10/10/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18515	Installed/Active	10/16/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18516	Installed/Active	10/13/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 20.81
18517	Installed/Active	10/07/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18518	Installed/Active	10/08/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18519	Installed/Active	10/12/2014	PROG2932NRU62	BRADFORD WHITE	\$ 850.00	\$ 6.19
18520	Installed/Active	10/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18521	Installed/Active	10/14/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18522	Installed/Active	10/13/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18523	Installed/Active	10/20/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18524	Installed/Active	10/13/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 17.81
18525	Installed/Active	10/10/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18526	Installed/Active	10/16/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18527	Installed/Active	10/16/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
18528	Installed/Active	10/11/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18529	Installed/Active	09/24/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18530	Installed/Active	10/02/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18531	Installed/Active	10/10/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 6.19
18532	Installed/Active	10/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18533	Installed/Active	10/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18534	Installed/Active	10/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18535	Installed/Active	10/15/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.81
18536	Installed/Active	10/14/2014	PROG5038NRU58DV	RHEEM / RUUD	\$ 979.00	\$ 18.20
18537	Installed/Active	10/18/2014	G91200	RUUD/RHEEM	\$ 2,361.55	\$ 66.97
18538	Installed/Active	10/14/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18539	Installed/Active	10/20/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18540	Installed/Active	10/24/2014	PH2DV50F	RUUD	\$ 979.00	\$ 18.20
18541	Installed/Active	10/27/2014	PROG2932NRU62	RHEEM RUUD	\$ 850.00	\$ 15.81
18542	Installed/Active	10/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18543	Installed/Active	09/30/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18544	Installed/Active	10/23/2014	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.19
18545	Installed/Active	10/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18546	Installed/Active	10/29/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.81
18547	Installed/Active	10/24/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84
18548	Installed/Active	10/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18549	Installed/Active	10/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18550	Installed/Active	10/25/2014	MI403S6FBN	Bradford White	\$ 350.00	\$ 15.81
18551	Installed/Active	10/21/2014	MI403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18552	Installed/Active	10/20/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18553	Installed/Active	10/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18554	Installed/Active	10/10/2014	PROG5038NRU58DV	BRADFORD WHITE	\$ 1,075.00	\$ 18.20
18555	Installed/Active	10/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18556	Installed/Active	10/24/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18557	Installed/Active	10/27/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18558	Installed/Active	10/23/2014	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18559	Installed/Active	10/29/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18560	Installed/Active	10/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18561	Installed/Active	10/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18562	Installed/Active	10/20/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18563	Installed/Active	10/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18564	Installed/Active	10/22/2014	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18565	Installed/Active	10/23/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18566	Installed/Active	10/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18567	Installed/Active	10/29/2014	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18568	Installed/Active	10/21/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18569	Installed/Active	10/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18570	Installed/Active	10/16/2014	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18571	Installed/Active	10/29/2014	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 17.81
18572	Installed/Active	10/28/2014	PROG5038NRU58DV	RUUD RHEEM	\$ 1,075.00	\$ 18.20
18573	Installed/Active	10/21/2014	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.00
18574	Installed/Active	10/14/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 6.19
18575	Installed/Active	11/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18576	Installed/Active	10/30/2014	MI5036FBN	Bradford White	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18577	Installed/Active	11/07/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18578	Installed/Active	11/09/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18579	Installed/Active	11/01/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18580	Installed/Active	10/27/2014	M15036FBN	Bradford White	\$ 850.00	\$ 6.19
18581	Installed/Active	10/30/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18582	Installed/Active	10/31/2014	G76200	RUUD/RHEEM	\$ 3,380.00	\$ 66.97
18583	Installed/Active	10/10/2014	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 66.97
18584	Installed/Active	10/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18585	Installed/Active	10/09/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18586	Installed/Active	10/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18587	Installed/Active	10/28/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18588	Installed/Active	10/27/2014	M150L6FBN	Bradford White	\$ 850.00	\$ 6.19
18589	Installed/Active	10/27/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18590	Installed/Active	10/31/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18591	Installed/Active	10/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18592	Installed/Active	10/24/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18593	Installed/Active	10/23/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18594	Installed/Active	11/03/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18595	Installed/Active	11/01/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18596	Installed/Active	11/04/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18597	Installed/Active	11/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18598	Installed/Active	11/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18599	Installed/Active	11/06/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18600	Installed/Active	11/10/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18601	Installed/Active	11/06/2014	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18602	Installed/Active	11/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18603	Installed/Active	11/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18604	Installed/Active	11/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18605	Installed/Active	10/02/2014	M15036FBN	Bradford White	\$ 1,150.00	\$ 17.81
18606	Installed/Active	10/08/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18607	Installed/Active	10/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18608	Installed/Active	11/13/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18609	Installed/Active	11/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18610	Installed/Active	11/23/2014	G76200	RUUD	\$ 3,380.00	\$ 66.97
18611	Installed/Active	11/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18612	Installed/Active	11/20/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18613	Installed/Active	11/21/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18614	Installed/Active	11/26/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18615	Installed/Active	11/25/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18616	Installed/Active	11/13/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18617	Installed/Active	11/30/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18618	Installed/Active	10/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18619	Installed/Active	10/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18620	Installed/Active	10/15/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18621	Installed/Active	10/28/2014	PROG5038NRU58DV	RUUD / RHEEM	\$ 979.00	\$ 18.20
18622	Installed/Active	10/21/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18623	Installed/Active	10/31/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18624	Installed/Active	12/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18625	Installed/Active	11/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18626	Installed/Active	10/30/2014	PROG5038NRU58	RUUD / RHEEM	\$ 979.00	\$ 12.84
18627	Installed/Active	10/31/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18628	Installed/Active	10/24/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.19
18629	Installed/Active	10/29/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18630	Installed/Active	10/28/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18631	Installed/Active	10/29/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18632	Installed/Active	10/30/2014	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18633	Installed/Active	11/03/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18634	Installed/Active	11/03/2014	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18635	Installed/Active	11/01/2014	PROG5038NRU60DV	RHEEM/RUUD	\$ 979.00	\$ 11.22
18636	Installed/Active	11/07/2014	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.82
18637	Installed/Active	10/20/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18638	Installed/Active	11/10/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18639	Installed/Active	11/11/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18640	Installed/Active	11/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18641	Installed/Active	11/20/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18642	Installed/Active	10/24/2014	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18643	Installed/Active	11/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18644	Installed/Active	11/04/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18645	Installed/Active	11/21/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18646	Installed/Active	11/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18647	Installed/Active	11/13/2014	P506	RUUD	\$ 1,150.00	\$ 17.81
18648	Installed/Active	11/11/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18649	Installed/Active	11/11/2014	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.00
18650	Installed/Active	11/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18651	Installed/Active	11/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18652	Installed/Active	11/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18653	Installed/Active	11/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18654	Installed/Active	11/18/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18655	Installed/Active	11/21/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18656	Installed/Active	11/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18657	Installed/Active	11/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18658	Installed/Active	11/21/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18659	Installed/Active	11/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18660	Installed/Active	11/26/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18661	Installed/Active	11/22/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18662	Installed/Active	11/18/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18663	Installed/Active	11/17/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18664	Installed/Active	11/25/2014	P230S30F	RUUD	\$ 850.00	\$ 7.82
18665	Installed/Active	12/02/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18666	Installed/Active	11/14/2014	DS140S6FBN	Bradford White	\$ 1,020.00	\$ 18.20
18667	Installed/Active	11/08/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18668	Installed/Active	11/08/2014	M45036FBN	AMERICAN	\$ 850.00	\$ 12.84
18669	Installed/Active	11/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18670	Installed/Active	11/13/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18671	Installed/Active	11/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
18672	Installed/Active	11/21/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18673	Installed/Active	11/16/2014	M15036FBN	Bradford White	\$ 850.00	\$ 6.19
18674	Installed/Active	11/17/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18675	Installed/Active	11/17/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18676	Installed/Active	11/08/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18677	Installed/Active	11/09/2014	21VR50	RHEEM	\$ 850.00	\$ 6.19
18678	Installed/Active	11/18/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18679	Installed/Active	11/20/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18680	Installed/Active	11/20/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18681	Installed/Active	11/19/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18682	Installed/Active	11/20/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18683	Installed/Active	11/12/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
18684	Installed/Active	11/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18685	Installed/Active	11/19/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18686	Installed/Active	11/04/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18687	Installed/Active	11/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18688	Installed/Active	11/15/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18689	Installed/Active	11/19/2014	PROG2932NRU62	RUUD	\$ 850.00	\$ 12.84
18690	Installed/Active	11/05/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18691	Installed/Active	11/05/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18692	Installed/Active	11/14/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18693	Installed/Active	11/21/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18694	Installed/Active	12/12/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18695	Installed/Active	11/12/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18696	Installed/Active	11/10/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18697	Installed/Active	11/04/2014	M45036FBN	Ruud/Rheem	\$ 850.00	\$ 6.19
18698	Installed/Active	11/28/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18699	Installed/Active	11/28/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18700	Installed/Active	11/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18701	Installed/Active	11/28/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18702	Installed/Active	11/25/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18703	Installed/Active	11/25/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18704	Installed/Active	11/26/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18705	Installed/Active	12/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18706	Installed/Active	12/01/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18707	Installed/Active	11/29/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18708	Installed/Active	12/04/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18709	Installed/Active	11/30/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18710	Installed/Active	12/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18711	Installed/Active	12/02/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18712	Installed/Active	12/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18713	Installed/Active	12/04/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18714	Installed/Active	12/03/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18715	Installed/Active	12/07/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18716	Installed/Active	12/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18717	Installed/Active	12/06/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18718	Installed/Active	12/03/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18719	Installed/Active	12/07/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18720	Installed/Active	12/05/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18721	Installed/Active	12/02/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18722	Installed/Active	11/25/2014	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 17.81
18723	Installed/Active	11/20/2014	M150L6FBN	Bradford White	\$ 850.00	\$ 12.84
18724	Installed/Active	11/30/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18725	Installed/Active	11/20/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18726	Installed/Active	11/20/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18727	Installed/Active	11/26/2014	G75125	Ruud/Rheem	\$ 2,835.00	\$ 43.00
18728	Installed/Active	12/04/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18729	Installed/Active	12/03/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18730	Installed/Active	12/09/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18731	Installed/Active	12/06/2014	PGR50	AO SMITH	\$ 850.00	\$ 12.84
18732	Installed/Active	12/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18733	Installed/Active	12/08/2014	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 18.20
18734	Installed/Active	12/09/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
18735	Installed/Active	12/13/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18736	Installed/Active	12/01/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18737	Installed/Active	12/10/2014	P230S30F	Bradford White	\$ 850.00	\$ 12.84
18738	Installed/Active	12/11/2014	PHR40	RUUD	\$ 850.00	\$ 6.19
18739	Installed/Active	12/16/2014	M15036FBN	Bradford White	\$ 850.00	\$ 20.81
18740	Installed/Active	12/16/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.19
18741	Installed/Active	11/22/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18742	Installed/Active	11/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18743	Installed/Active	12/04/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18744	Installed/Active	12/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18745	Installed/Active	12/03/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18746	Installed/Active	12/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18747	Installed/Active	12/04/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18748	Installed/Active	12/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18749	Installed/Active	11/05/2014	21DV50	RHEEM	\$ 1,075.00	\$ 18.20
18750	Installed/Active	12/05/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18751	Installed/Active	11/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 17.81
18752	Installed/Active	12/02/2014	PROG5038nru58DV	Ruud	\$ 979.00	\$ 18.20
18753	Installed/Active	12/01/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 6.19
18754	Installed/Active	12/02/2014	PROG5038NRU58DV	Ruud	\$ 850.00	\$ 12.84
18755	Installed/Active	11/25/2014	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 18.20
18756	Installed/Active	12/05/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18757	Installed/Active	12/07/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18758	Installed/Active	12/06/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18759	Installed/Active	12/12/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18760	Installed/Active	12/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18761	Installed/Active	11/26/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18762	Installed/Active	12/10/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18763	Installed/Active	12/12/2014	FSG50	AO SMITH	\$ 850.00	\$ 12.84
18764	Installed/Active	12/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18765	Installed/Active	12/15/2014	PROG5038NRU58DV	BRADFORD WHITE	\$ 979.00	\$ 18.20
18766	Installed/Active	12/11/2014	G82156	RUUD	\$ 3,360.00	\$ 57.58
18767	Installed/Active	12/08/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 12.84
18768	Installed/Active	12/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18769	Installed/Active	12/10/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18770	Installed/Active	12/16/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18771	Installed/Active	01/07/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18772	Installed/Active	01/07/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18773	Installed/Active	01/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18774	Installed/Active	01/05/2015	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 18.60
18775	Installed/Active	01/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18776	Installed/Active	01/07/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18777	Installed/Active	01/10/2015	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 58.84
18778	Installed/Active	01/07/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18779	Installed/Active	01/07/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18780	Installed/Active	11/18/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18781	Installed/Active	12/01/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18782	Installed/Active	12/18/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18783	Installed/Active	12/11/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18784	Installed/Active	12/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18785	Installed/Active	12/17/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18786	Installed/Active	12/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18787	Installed/Active	12/03/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18788	Installed/Active	12/02/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18789	Installed/Active	12/18/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18790	Installed/Active	12/17/2014	DS140S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 18.20
18791	Installed/Active	12/16/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18792	Installed/Active	12/29/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18793	Installed/Active	12/26/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18794	Installed/Active	12/30/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18795	Installed/Active	12/30/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18796	Installed/Active	12/26/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18797	Installed/Active	12/28/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18798	Installed/Active	01/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18799	Installed/Active	01/01/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
18800	Installed/Active	01/02/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18801	Installed/Active	01/04/2015	G75125	RUUD	\$ 2,835.00	\$ 43.94
18802	Installed/Active	01/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18803	Installed/Active	01/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18804	Installed/Active	01/02/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18805	Installed/Active	01/09/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18806	Installed/Active	12/15/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18807	Installed/Active	12/02/2014	PROG5038NRU58DV	Ruud	\$ 979.00	\$ 18.20
18808	Installed/Active	12/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18809	Installed/Active	12/07/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18810	Installed/Active	12/10/2014	LTN040GEF	LOCHINVAR	\$ 850.00	\$ 6.19
18811	Installed/Active	12/04/2014	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 18.20
18812	Installed/Active	12/06/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18813	Installed/Active	12/06/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18814	Installed/Active	12/10/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18815	Installed/Active	12/03/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18816	Installed/Active	12/15/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18817	Installed/Active	12/15/2014	M440T6FBN	Bradford White	\$ 850.00	\$ 12.84
18818	Installed/Active	12/14/2014	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 11.22
18819	Installed/Active	12/17/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18820	Installed/Active	12/10/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
18821	Installed/Active	12/08/2014	M150L6FBN	Bradford White	\$ 850.00	\$ 6.19
18822	Installed/Active	12/15/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18823	Installed/Active	12/14/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18824	Installed/Active	12/16/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18825	Installed/Active	12/23/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18826	Installed/Active	12/31/2014	M1403S6FBN	Bradford White	\$ 850.00	\$ 12.84
18827	Installed/Active	12/31/2014	M140T6FBN	Bradford White	\$ 850.00	\$ 12.84
18828	Installed/Active	12/30/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18829	Installed/Active	12/30/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18830	Installed/Active	12/30/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18831	Installed/Active	12/30/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18832	Installed/Active	12/29/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18833	Installed/Active	12/30/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20
18834	Installed/Active	12/30/2014	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.20

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18835	Installed/Active	12/23/2014	G75125	RUUD	\$ 2,835.00	\$ 43.00
18836	Installed/Active	12/26/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,125.00	\$ 20.81
18837	Installed/Active	12/31/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18838	Installed/Active	12/11/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18839	Installed/Active	12/12/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18840	Installed/Active	12/10/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18841	Installed/Active	12/09/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18842	Installed/Active	12/08/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18843	Installed/Active	12/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18844	Installed/Active	12/23/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18845	Installed/Active	12/28/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18846	Installed/Active	12/24/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18847	Installed/Active	12/26/2014	M45036FBN	Bradford White	\$ 850.00	\$ 12.84
18848	Installed/Active	12/31/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
18849	Installed/Active	12/12/2014	M45036FBN	Bradford White	\$ 850.00	\$ 7.82
18850	Installed/Active	12/29/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18851	Installed/Active	12/27/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18852	Installed/Active	12/17/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18853	Installed/Active	12/26/2014	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18854	Installed/Active	12/23/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18855	Installed/Active	12/31/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
18856	Installed/Active	12/22/2014	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.00
18857	Installed/Active	12/16/2014	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.84
18858	Installed/Active	12/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18859	Installed/Active	12/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.82
18860	Installed/Active	12/01/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18861	Installed/Active	12/16/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18862	Installed/Active	12/18/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
18863	Installed/Active	01/06/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18864	Installed/Active	01/09/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18865	Installed/Active	01/06/2015	G91200	Ruud	\$ 3,367.00	\$ 68.44
18866	Installed/Active	12/27/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18867	Installed/Active	01/10/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18868	Installed/Active	12/24/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18869	Installed/Active	01/07/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18870	Installed/Active	01/09/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
18871	Installed/Active	01/07/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18872	Installed/Active	01/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18873	Installed/Active	12/30/2014	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.20
18874	Installed/Active	12/19/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18875	Installed/Active	12/19/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18876	Installed/Active	01/08/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18877	Installed/Active	01/05/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18878	Installed/Active	01/09/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
18879	Installed/Active	01/07/2015	PROG5038NRU58DV	Ruud	\$ 979.00	\$ 18.60
18880	Installed/Active	01/07/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18881	Installed/Active	12/28/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18882	Installed/Active	01/13/2015	G76200	Ruud	\$ 3,380.00	\$ 68.44
18883	Installed/Active	01/03/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18884	Installed/Active	01/07/2015	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 18.60
18885	Installed/Active	01/06/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18886	Installed/Active	01/06/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
18887	Installed/Active	01/12/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18888	Installed/Active	01/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18889	Installed/Active	12/29/2014	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.20
18890	Installed/Active	01/02/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18891	Installed/Active	01/05/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
18892	Installed/Active	01/09/2015	DS150S6FBN	Bradford White	\$ 1,078.00	\$ 18.60
18893	Installed/Active	01/14/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
18894	Installed/Active	01/15/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18895	Installed/Active	01/05/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18896	Installed/Active	12/30/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
18897	Installed/Active	01/12/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 11.47
18898	Installed/Active	01/12/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18899	Installed/Active	01/15/2015	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 18.60
18900	Installed/Active	01/12/2015	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.94
18901	Installed/Active	01/16/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18902	Installed/Active	01/20/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18903	Installed/Active	01/23/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18904	Installed/Active	01/20/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18905	Installed/Active	01/23/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
18906	Installed/Active	01/24/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
18907	Installed/Active	01/26/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18908	Installed/Active	01/27/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18909	Installed/Active	01/27/2015	G76200	Ruud/Rheem	\$ 3,380.00	\$ 68.44
18910	Installed/Active	01/23/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
18911	Installed/Active	01/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18912	Installed/Active	01/26/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18913	Installed/Active	01/27/2015	M45036FBN	BRADFORD WH ITE	\$ 850.00	\$ 13.12
18914	Installed/Active	01/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18915	Installed/Active	01/21/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18916	Installed/Active	01/26/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18917	Installed/Active	01/24/2015	G82156	RUUD	\$ 3,350.00	\$ 68.44
18918	Installed/Active	01/13/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
18919	Installed/Active	01/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
18920	Installed/Active	01/08/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
18921	Installed/Active	01/27/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
18922	Installed/Active	01/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18923	Installed/Active	01/26/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 13.12
18924	Installed/Active	01/23/2015	P230S30F	RUUD	\$ 850.00	\$ 13.12
18925	Installed/Active	01/29/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
18926	Installed/Active	01/30/2015	P506	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
18927	Installed/Active	01/30/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18928	Installed/Active	01/31/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18929	Installed/Active	02/04/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18930	Installed/Active	01/30/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18931	Installed/Active	02/04/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18932	Installed/Active	01/15/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18933	Installed/Active	01/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18934	Installed/Active	02/11/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
18935	Installed/Active	02/09/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18936	Installed/Active	02/17/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18937	Installed/Active	02/17/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 13.12
18938	Installed/Active	01/28/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
18939	Installed/Active	02/09/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,125.00	\$ 21.27
18940	Installed/Active	02/18/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18941	Installed/Active	01/31/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18942	Installed/Active	02/17/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18943	Installed/Active	02/25/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18944	Installed/Active	02/23/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18945	Installed/Active	02/23/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18946	Installed/Active	02/26/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18947	Installed/Active	02/28/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18948	Installed/Active	02/25/2015	PROG5038NRU58DV	RUUD / RHEEM	\$ 979.00	\$ 18.60
18949	Installed/Active	02/26/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
18950	Installed/Active	02/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18951	Installed/Active	02/18/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
18952	Installed/Active	02/25/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18953	Installed/Active	03/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18954	Installed/Active	03/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18955	Installed/Active	01/05/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18956	Installed/Active	01/10/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18957	Installed/Active	01/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18958	Installed/Active	01/07/2015	M175S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.94
18959	Installed/Active	01/13/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18960	Installed/Active	01/13/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18961	Installed/Active	01/02/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18962	Installed/Active	12/30/2014	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
18963	Installed/Active	01/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18964	Installed/Active	01/03/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
18965	Installed/Active	01/02/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18966	Installed/Active	01/13/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18967	Installed/Active	01/14/2015	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.60
18968	Installed/Active	01/15/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18969	Installed/Active	12/31/2014	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.20
18970	Installed/Active	12/29/2014	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 20.81
18971	Installed/Active	01/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18972	Installed/Active	01/21/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
18973	Installed/Active	01/21/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18974	Installed/Active	01/10/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18975	Installed/Active	01/15/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
18976	Installed/Active	01/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18977	Installed/Active	01/29/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18978	Installed/Active	02/03/2015	M140T6FBN	AO SMITH	\$ 850.00	\$ 6.33
18979	Installed/Active	02/03/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18980	Installed/Active	02/04/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
18981	Installed/Active	02/16/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
18982	Installed/Active	02/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18983	Installed/Active	02/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18984	Installed/Active	02/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18985	Installed/Active	02/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18986	Installed/Active	02/18/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18987	Installed/Active	02/18/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
18988	Installed/Active	02/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18989	Installed/Active	02/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18990	Installed/Active	02/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
18991	Installed/Active	02/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
18992	Installed/Active	02/20/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
18993	Installed/Active	02/18/2015	M15036FBN	Bradford White	\$ 850.00	\$ 6.33
18994	Installed/Active	02/17/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18995	Installed/Active	12/22/2014	M15036FBN	Bradford White	\$ 1,150.00	\$ 17.81
18996	Installed/Active	12/22/2014	M45036FBN	Bradford White	\$ 850.00	\$ 6.19
18997	Installed/Active	01/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
18998	Installed/Active	01/17/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
18999	Installed/Active	01/14/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19000	Installed/Active	01/19/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19001	Installed/Active	01/16/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19002	Installed/Active	01/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19003	Installed/Active	01/17/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19004	Installed/Active	01/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19005	Installed/Active	12/17/2014	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.19
19006	Installed/Active	01/05/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19007	Installed/Active	01/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19008	Installed/Active	01/14/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19009	Installed/Active	01/20/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19010	Installed/Active	01/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19011	Installed/Active	01/15/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19012	Installed/Active	01/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19013	Installed/Active	01/25/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19014	Installed/Active	12/16/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
19015	Installed/Active	01/27/2015	DS150S6FBN	BRADFORD WHITE	\$ 1,078.00	\$ 18.60
19016	Installed/Active	01/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19017	Installed/Active	01/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19018	Installed/Active	01/23/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19019	Installed/Active	01/23/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19020	Installed/Active	01/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19021	Installed/Active	01/14/2015	G75125	RUUD	\$ 2,835.00	\$ 58.84
19022	Installed/Active	01/15/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19023	Installed/Active	01/22/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19024	Installed/Active	01/24/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19025	Installed/Active	01/31/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19026	Installed/Active	01/31/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19027	Installed/Active	01/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19028	Installed/Active	01/16/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 21.27
19029	Installed/Active	02/03/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19030	Installed/Active	02/02/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19031	Installed/Active	01/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19032	Installed/Active	01/01/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19033	Installed/Active	02/11/2015	M175S6FBN	Bradford White	\$ 950.00	\$ 68.44
19034	Installed/Active	02/16/2015	LTN050G	LOCHINVAR	\$ 850.00	\$ 13.12
19035	Installed/Active	02/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19036	Installed/Active	02/11/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19037	Installed/Active	02/13/2015	M140S6FBN	Bradford White	\$ 850.00	\$ 13.12
19038	Installed/Active	02/18/2015	PR650	STATE	\$ 1,075.00	\$ 18.60
19039	Installed/Active	01/27/2015	LSN041G	LOCHINVAR	\$ 850.00	\$ 13.12
19040	Installed/Active	02/17/2015	GVC50	A. O. SMITH	\$ 850.00	\$ 13.12
19041	Installed/Active	02/04/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19042	Installed/Active	01/29/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.20
19043	Installed/Active	01/26/2015	M140S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19044	Installed/Active	02/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19045	Installed/Active	02/05/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19046	Installed/Active	02/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19047	Installed/Active	01/29/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19048	Installed/Active	01/29/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19049	Installed/Active	02/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19050	Installed/Active	02/05/2015	G82156	RUUD	\$ 3,360.00	\$ 58.84
19051	Installed/Active	02/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19052	Installed/Active	02/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19053	Installed/Active	02/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19054	Installed/Active	02/12/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19055	Installed/Active	02/12/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19056	Installed/Active	02/13/2015	PROG5038NRU58DV	RHEEM RUUD	\$ 1,075.00	\$ 18.60
19057	Installed/Active	01/28/2015	PH199119	PHOENIX	\$ 6,732.00	\$ 68.44
19058	Installed/Active	01/23/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19059	Installed/Active	01/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19060	Installed/Active	01/29/2015	M140S6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19061	Installed/Active	01/31/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19062	Installed/Active	01/30/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19063	Installed/Active	01/31/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19064	Installed/Active	02/05/2015	G82156	Ruud/Rheem	\$ 3,360.00	\$ 58.84
19065	Installed/Active	01/26/2015	G91200	Ruud/Rheem	\$ 3,367.00	\$ 68.44
19066	Installed/Active	02/09/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19067	Installed/Active	02/09/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19068	Installed/Active	02/11/2015	M45036FBN	Bradford White	\$ 683.00	\$ 21.27
19069	Installed/Active	02/12/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19070	Installed/Active	02/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19071	Installed/Active	02/11/2015	M175S6FBN	BRADFORD WHITE	\$ 950.00	\$ 6.33
19072	Installed/Active	02/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19073	Installed/Active	02/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19074	Installed/Active	02/03/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19075	Installed/Active	02/08/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19076	Installed/Active	02/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19077	Installed/Active	02/12/2015	PH19980	Phoenix	\$ 6,391.00	\$ 68.44
19078	Installed/Active	02/09/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19079	Installed/Active	02/18/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19080	Installed/Active	02/10/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19081	Installed/Active	02/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19082	Installed/Active	02/18/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19083	Installed/Active	02/19/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19084	Installed/Active	02/17/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19085	Installed/Active	02/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19086	Installed/Active	02/18/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19087	Installed/Active	02/13/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19088	Installed/Active	02/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19089	Installed/Active	02/24/2015	M140S6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19090	Installed/Active	02/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19091	Installed/Active	02/18/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19092	Installed/Active	02/16/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19093	Installed/Active	02/06/2015	PROG5038NRU58DV	RUUD/RHEEM	\$ 979.00	\$ 18.60
19094	Installed/Active	02/14/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19095	Installed/Active	02/19/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19096	Installed/Active	02/07/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19097	Installed/Active	02/17/2015	PROG5038NRU58DV	RHEEM RUUD	\$ 979.00	\$ 18.60
19098	Installed/Active	02/08/2015	M175S6FBN	Bradford White	\$ 1,900.00	\$ 43.94
19099	Installed/Active	02/22/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19100	Installed/Active	02/24/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19101	Installed/Active	02/21/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19102	Installed/Active	02/23/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19103	Installed/Active	02/25/2015	M175S6FBN	Bradford White	\$ 1,900.00	\$ 43.94
19104	Installed/Active	02/22/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19105	Installed/Active	02/01/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19106	Installed/Active	02/23/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19107	Installed/Active	02/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19108	Installed/Active	02/27/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19109	Installed/Active	02/26/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19110	Installed/Active	02/20/2015	M175S6FBN	Bradford White	\$ 950.00	\$ 43.94
19111	Installed/Active	02/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19112	Installed/Active	02/23/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19113	Installed/Active	02/24/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19114	Installed/Active	02/27/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19115	Installed/Active	02/25/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19116	Installed/Active	02/24/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19117	Installed/Active	02/21/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19118	Installed/Active	02/28/2015	M45036FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
19119	Installed/Active	02/24/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19120	Installed/Active	02/11/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 21.27
19121	Installed/Active	02/25/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19122	Installed/Active	02/24/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19123	Installed/Active	02/24/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
19124	Installed/Active	02/02/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19125	Installed/Active	03/05/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19126	Installed/Active	02/09/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19127	Installed/Active	02/18/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19128	Installed/Active	02/23/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19129	Installed/Active	03/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19130	Installed/Active	03/03/2015	PROG5038NRU58DV	BRADFORD WHITE	\$ 1,078.00	\$ 18.60
19131	Installed/Active	03/06/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19132	Installed/Active	03/06/2015	M15036FBN	Bradford White	\$ 1,150.00	\$ 18.20
19133	Installed/Active	03/10/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19134	Installed/Active	03/04/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19135	Installed/Active	03/10/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19136	Installed/Active	03/09/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19137	Installed/Active	03/06/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19138	Installed/Active	03/02/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19139	Installed/Active	03/04/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19140	Installed/Active	03/03/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19141	Installed/Active	03/09/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19142	Installed/Active	03/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19143	Installed/Active	03/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19144	Installed/Active	03/03/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19145	Installed/Active	03/04/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19146	Installed/Active	03/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19147	Installed/Active	03/05/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19148	Installed/Active	03/13/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19149	Installed/Active	03/14/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19150	Installed/Active	03/12/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19151	Installed/Active	02/27/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19152	Installed/Active	03/17/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19153	Installed/Active	03/27/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19154	Installed/Active	03/22/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19155	Installed/Active	03/23/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.60
19156	Installed/Active	03/20/2015	PROG5038NRU58DV	BRADFORD WHITE	\$ 1,075.00	\$ 18.60
19157	Installed/Active	03/20/2015	G75125	RUUD	\$ 2,835.00	\$ 43.94
19158	Installed/Active	03/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.20
19159	Installed/Active	03/13/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19160	Installed/Active	03/06/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19161	Installed/Active	03/13/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19162	Installed/Active	03/11/2013	M45036FBN	Bradford White	\$ 850.00	\$ 12.75
19163	Installed/Active	03/07/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19164	Installed/Active	02/21/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19165	Installed/Active	03/04/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19166	Installed/Active	03/04/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19167	Installed/Active	03/06/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19168	Installed/Active	03/02/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19169	Installed/Active	03/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19170	Installed/Active	03/03/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19171	Installed/Active	03/03/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19172	Installed/Active	03/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19173	Installed/Active	03/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19174	Installed/Active	03/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19175	Installed/Active	02/26/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19176	Installed/Active	03/09/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19177	Installed/Active	03/03/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19178	Installed/Active	03/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19179	Installed/Active	03/09/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19180	Installed/Active	03/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19181	Installed/Active	03/10/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19182	Installed/Active	03/11/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19183	Installed/Active	03/11/2015	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.94
19184	Installed/Active	03/09/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19185	Installed/Active	03/13/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19186	Installed/Active	03/11/2015	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.94
19187	Installed/Active	03/12/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19188	Installed/Active	03/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19189	Installed/Active	03/14/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19190	Installed/Active	03/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19191	Installed/Active	03/13/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19192	Installed/Active	03/12/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19193	Installed/Active	03/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19194	Installed/Active	02/27/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19195	Installed/Active	03/13/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19196	Installed/Active	03/19/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19197	Installed/Active	03/19/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
19198	Installed/Active	03/10/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19199	Installed/Active	03/09/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19200	Installed/Active	03/18/2015	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19201	Installed/Active	03/16/2015	G82156	RUUD	\$ 3,360.00	\$ 58.84
19202	Installed/Active	03/16/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19203	Installed/Active	03/10/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19204	Installed/Active	03/18/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19205	Installed/Active	03/16/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19206	Installed/Active	03/17/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19207	Installed/Active	03/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19208	Installed/Active	03/24/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19209	Installed/Active	03/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19210	Installed/Active	03/24/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19211	Installed/Active	03/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19212	Installed/Active	03/18/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19213	Installed/Active	03/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19214	Installed/Active	03/18/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19215	Installed/Active	03/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19216	Installed/Active	03/13/2015	DS140S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19217	Installed/Active	03/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19218	Installed/Active	03/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19219	Installed/Active	03/19/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19220	Installed/Active	03/19/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19221	Installed/Active	03/27/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19222	Installed/Active	03/26/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19223	Installed/Active	03/26/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19224	Installed/Active	03/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19225	Installed/Active	03/23/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19226	Installed/Active	03/27/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19227	Installed/Active	03/25/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19228	Installed/Active	03/29/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19229	Installed/Active	03/16/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19230	Installed/Active	04/02/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19231	Installed/Active	04/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19232	Installed/Active	03/31/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19233	Installed/Active	03/27/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19234	Installed/Active	03/30/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19235	Installed/Active	03/30/2015	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.94
19236	Installed/Active	03/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19237	Installed/Active	03/28/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19238	Installed/Active	03/25/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.60
19239	Installed/Active	03/26/2015	G91200	Ruud/Rheem	\$ 3,350.00	\$ 68.44
19240	Installed/Active	03/17/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19241	Installed/Active	04/14/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.33
19242	Installed/Active	03/31/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19243	Installed/Active	03/31/2015	PROG5038RU58DV	RUUD	\$ 979.00	\$ 11.47
19244	Installed/Active	03/28/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19245	Installed/Active	03/30/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19246	Installed/Active	03/27/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19247	Installed/Active	03/20/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19248	Installed/Active	04/08/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19249	Installed/Active	04/02/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19250	Installed/Active	04/01/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19251	Installed/Active	04/07/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 7.99
19252	Installed/Active	04/03/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19253	Installed/Active	04/02/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19254	Installed/Active	04/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19255	Installed/Active	04/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19256	Installed/Active	04/02/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
19257	Installed/Active	04/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19258	Installed/Active	04/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19259	Installed/Active	04/07/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19260	Installed/Active	03/27/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19261	Installed/Active	03/27/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19262	Installed/Active	03/29/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19263	Installed/Active	03/28/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19264	Installed/Active	03/30/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19265	Installed/Active	03/30/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19266	Installed/Active	03/30/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19267	Installed/Active	03/31/2015	PROG5038NRU58DV	Ruud	\$ 1,075.00	\$ 18.60
19268	Installed/Active	03/18/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19269	Installed/Active	03/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19270	Installed/Active	03/19/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19271	Installed/Active	03/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19272	Installed/Active	03/20/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19273	Installed/Active	03/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19274	Installed/Active	03/18/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19275	Installed/Active	03/11/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19276	Installed/Active	03/24/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 11.47
19277	Installed/Active	03/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19278	Installed/Active	03/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19279	Installed/Active	03/23/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19280	Installed/Active	03/25/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19281	Installed/Active	03/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19282	Installed/Active	03/26/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19283	Installed/Active	03/17/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19284	Installed/Active	03/24/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19285	Installed/Active	03/26/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19286	Installed/Active	03/25/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19287	Installed/Active	03/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19288	Installed/Active	03/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19289	Installed/Active	04/06/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19290	Installed/Active	04/02/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19291	Installed/Active	03/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19292	Installed/Active	03/27/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19293	Installed/Active	03/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19294	Installed/Active	03/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19295	Installed/Active	03/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19296	Installed/Active	03/24/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19297	Installed/Active	03/25/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19298	Installed/Active	03/25/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19299	Installed/Active	03/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19300	Installed/Active	03/23/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19301	Installed/Active	04/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19302	Installed/Active	04/17/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19303	Installed/Active	04/03/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19304	Installed/Active	04/08/2015	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19305	Installed/Active	04/02/2015	PROG5038NRU58DV	Ruud	\$ 979.00	\$ 18.60
19306	Installed/Active	03/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19307	Installed/Active	04/01/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19308	Installed/Active	04/02/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19309	Installed/Active	04/08/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19310	Installed/Active	04/14/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19311	Installed/Active	04/14/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19312	Installed/Active	04/08/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19313	Installed/Active	04/09/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19314	Installed/Active	04/03/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19315	Installed/Active	04/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19316	Installed/Active	04/16/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19317	Installed/Active	04/16/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19318	Installed/Active	04/16/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19319	Installed/Active	04/15/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19320	Installed/Active	04/03/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19321	Installed/Active	04/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19322	Installed/Active	04/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19323	Installed/Active	04/15/2015	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.60
19324	Installed/Active	04/16/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19325	Installed/Active	04/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19326	Installed/Active	04/10/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19327	Installed/Active	04/09/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19328	Installed/Active	04/09/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19329	Installed/Active	04/20/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19330	Installed/Active	04/17/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19331	Installed/Active	04/16/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19332	Installed/Active	04/20/2015	PROG5038NRU58	RUUD	\$ 979.00	\$ 18.60
19333	Installed/Active	04/22/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19334	Installed/Active	04/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19335	Installed/Active	04/14/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19336	Installed/Active	04/15/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19337	Installed/Active	04/16/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19338	Installed/Active	04/04/2015	FSG50	AO SMITH	\$ 850.00	\$ 13.12
19339	Installed/Active	04/08/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19340	Installed/Active	04/08/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19341	Installed/Active	04/14/2015	PROG5038NRU60DV	RUUD	\$ 979.00	\$ 18.60
19342	Installed/Active	04/13/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19343	Installed/Active	03/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19344	Installed/Active	04/21/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19345	Installed/Active	04/17/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19346	Installed/Active	04/15/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19347	Installed/Active	05/18/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19348	Installed/Active	04/17/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19349	Installed/Active	04/17/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19350	Installed/Active	04/15/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19351	Installed/Active	04/20/2015	FSG40	AO SMITH	\$ 850.00	\$ 13.12
19352	Installed/Active	04/01/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19353	Installed/Active	04/03/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19354	Installed/Active	04/20/2015	PROG5038NRU60	RUUD	\$ 979.00	\$ 18.60
19355	Installed/Active	04/01/2015	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.94
19356	Installed/Active	04/28/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19357	Installed/Active	04/15/2015	DS140S6FBN	BRADFORD WHITE	\$ 1,020.00	\$ 18.60
19358	Installed/Active	04/23/2015	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.60
19359	Installed/Active	04/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19360	Installed/Active	04/21/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19361	Installed/Active	04/17/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19362	Installed/Active	05/04/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19363	Installed/Active	05/05/2015	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.94
19364	Installed/Active	05/10/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19365	Installed/Active	04/29/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19366	Installed/Active	04/24/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19367	Installed/Active	04/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19368	Installed/Active	04/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19369	Installed/Active	04/15/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19370	Installed/Active	04/10/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19371	Installed/Active	04/17/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19372	Installed/Active	03/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19373	Installed/Active	03/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19374	Installed/Active	04/15/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 7.99
19375	Installed/Active	04/09/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19376	Installed/Active	04/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19377	Installed/Active	04/16/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19378	Installed/Active	04/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19379	Installed/Active	04/10/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19380	Installed/Active	04/15/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19381	Installed/Active	04/13/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19382	Installed/Active	04/17/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19383	Installed/Active	04/19/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
19384	Installed/Active	04/15/2015	M1403S6FBN	BRADFORD WHITE	\$ 350.00	\$ 16.16
19385	Installed/Active	04/09/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19386	Installed/Active	04/10/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19387	Installed/Active	04/13/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19388	Installed/Active	04/08/2015	G75125	RUUD	\$ 2,835.00	\$ 68.44
19389	Installed/Active	04/23/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19390	Installed/Active	04/17/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19391	Installed/Active	05/01/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19392	Installed/Active	05/04/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19393	Installed/Active	04/29/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19394	Installed/Active	04/29/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19395	Installed/Active	04/25/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19396	Installed/Active	04/29/2015	PH199119	PHOENIX	\$ 6,732.00	\$ 68.44
19397	Installed/Active	04/29/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19398	Installed/Active	05/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.20
19399	Installed/Active	05/06/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19400	Installed/Active	05/07/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19401	Installed/Active	05/04/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19402	Installed/Active	05/04/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19403	Installed/Active	05/01/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19404	Installed/Active	05/05/2015	G82156	RUUD	\$ 3,360.00	\$ 58.84
19405	Installed/Active	05/05/2015	G82156	RUUD	\$ 3,360.00	\$ 58.84
19406	Installed/Active	05/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19407	Installed/Active	05/06/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19408	Installed/Active	05/11/2015	G76200	RUUD	\$ 3,380.00	\$ 68.44
19409	Installed/Active	04/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19410	Installed/Active	04/18/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19411	Installed/Active	03/28/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 33.57
19412	Installed/Active	04/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19413	Installed/Active	04/27/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19414	Installed/Active	04/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19415	Installed/Active	04/27/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19416	Installed/Active	04/20/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19417	Installed/Active	04/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19418	Installed/Active	04/22/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19419	Installed/Active	04/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19420	Installed/Active	04/25/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19421	Installed/Active	05/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19422	Installed/Active	05/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19423	Installed/Active	05/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19424	Installed/Active	05/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19425	Installed/Active	04/29/2015	PH13080	PHOENIX	\$ 5,916.00	\$ 68.44
19426	Installed/Active	04/29/2015	PH199119	PHOENIX	\$ 6,732.00	\$ 68.44
19427	Installed/Active	04/29/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19428	Installed/Active	05/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19429	Installed/Active	04/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19430	Installed/Active	04/09/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19431	Installed/Active	05/05/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19432	Installed/Active	05/04/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19433	Installed/Active	04/20/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19434	Installed/Active	04/26/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19435	Installed/Active	04/22/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 21.27
19436	Installed/Active	04/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19437	Installed/Active	05/18/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19438	Installed/Active	05/14/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19439	Installed/Active	05/16/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19440	Installed/Active	05/12/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19441	Installed/Active	05/19/2015	PROG5038NRU58DV	BRADFORD WHITE	\$ 1,078.00	\$ 18.60
19442	Installed/Active	05/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19443	Installed/Active	05/01/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19444	Installed/Active	05/06/2015	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19445	Installed/Active	05/19/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19446	Installed/Active	05/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19447	Installed/Active	06/02/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19448	Installed/Active	05/22/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19449	Installed/Active	05/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19450	Installed/Active	05/29/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19451	Installed/Active	05/22/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19452	Installed/Active	06/03/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19453	Installed/Active	06/02/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19454	Installed/Active	06/02/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19455	Installed/Active	06/02/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19456	Installed/Active	06/05/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19457	Installed/Active	06/04/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19458	Installed/Active	05/10/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19459	Installed/Active	06/04/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19460	Installed/Active	06/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19461	Installed/Active	05/30/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19462	Installed/Active	06/08/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19463	Installed/Active	05/30/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19464	Installed/Active	12/16/2013	MI75S6FBN	BRADFORD WHITE	\$ 1,750.00	\$ 32.15
19465	Installed/Active	05/02/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19466	Installed/Active	05/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.20
19467	Installed/Active	05/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19468	Installed/Active	04/20/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19469	Installed/Active	04/21/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19470	Installed/Active	04/23/2015	G91200	Ruud/Rheem	\$ 3,367.00	\$ 68.44
19471	Installed/Active	04/08/2015	G91200	Ruud/Rheem	\$ 3,367.00	\$ 68.44
19472	Installed/Active	04/20/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19473	Installed/Active	04/16/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19474	Installed/Active	04/24/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19475	Installed/Active	05/06/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19476	Installed/Active	05/06/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19477	Installed/Active	05/07/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19478	Installed/Active	05/12/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19479	Installed/Active	03/26/2015	PROG5038NRU58	Ruud/Rheem	\$ 979.00	\$ 16.16
19480	Installed/Active	05/02/2015	MI75S6FBN	Bradford White	\$ 950.00	\$ 43.94
19481	Installed/Active	04/27/2015	G75125	Ruud/Rheem	\$ 2,835.00	\$ 43.94
19482	Installed/Active	05/01/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19483	Installed/Active	05/01/2015	PROG5038nrU58DV	Ruud/Rheem	\$ 850.00	\$ 6.33
19484	Installed/Active	05/01/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19485	Installed/Active	04/28/2015	PR502T	RUUD	\$ 850.00	\$ 13.12
19486	Installed/Active	05/04/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19487	Installed/Active	05/04/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19488	Installed/Active	04/29/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19489	Installed/Active	04/30/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19490	Installed/Active	04/30/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19491	Installed/Active	05/11/2015	G91200	RHEEM	\$ 3,350.00	\$ 68.44
19492	Installed/Active	05/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19493	Installed/Active	05/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19494	Installed/Active	05/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19495	Installed/Active	05/21/2015	MI75S6FBN	BRADFORD WHITE	\$ 950.00	\$ 43.94
19496	Installed/Active	05/15/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19497	Installed/Active	05/13/2015	PROG2932NRU62	Ruud/Rheem	\$ 850.00	\$ 13.12
19498	Installed/Active	05/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19499	Installed/Active	05/09/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19500	Installed/Active	05/18/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19501	Installed/Active	05/12/2015	PROG2932NRU62	Ruud/Rheem	\$ 850.00	\$ 13.12
19502	Installed/Active	05/18/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 18.20
19503	Installed/Active	05/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19504	Installed/Active	05/14/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19505	Installed/Active	05/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19506	Installed/Active	05/21/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19507	Installed/Active	05/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19508	Installed/Active	05/19/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19509	Installed/Active	05/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19510	Installed/Active	05/16/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19511	Installed/Active	05/05/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19512	Installed/Active	05/08/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19513	Installed/Active	05/11/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19514	Installed/Active	05/05/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19515	Installed/Active	06/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19516	Installed/Active	05/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19517	Installed/Active	05/08/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19518	Installed/Active	05/15/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19519	Installed/Active	05/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19520	Installed/Active	05/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19521	Installed/Active	05/30/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19522	Installed/Active	05/28/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19523	Installed/Active	05/19/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19524	Installed/Active	05/28/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19525	Installed/Active	05/22/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19526	Installed/Active	05/24/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19527	Installed/Active	05/24/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19528	Installed/Active	05/27/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19529	Installed/Active	05/19/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19530	Installed/Active	05/29/2015	G91200	RUUD/RHEEM	\$ 3,367.00	\$ 68.44
19531	Installed/Active	05/29/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19532	Installed/Active	05/15/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
19533	Installed/Active	06/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19534	Installed/Active	06/02/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19535	Installed/Active	06/01/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19536	Installed/Active	06/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19537	Installed/Active	05/22/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19538	Installed/Active	06/03/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19539	Installed/Active	10/14/2014	G91200	RUUD	\$ 3,367.00	\$ 66.97
19540	Installed/Active	04/30/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19541	Installed/Active	05/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19542	Installed/Active	05/10/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19543	Installed/Active	05/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19544	Installed/Active	05/11/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19545	Installed/Active	05/15/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
19546	Installed/Active	05/15/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19547	Installed/Active	05/14/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19548	Installed/Active	05/18/2015	G76200	Ruud/Rheem	\$ 3,380.00	\$ 68.44
19549	Installed/Active	05/14/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19550	Installed/Active	05/21/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19551	Installed/Active	04/30/2015	M15036FBN	Bradford White	\$ 850.00	\$ 6.33
19552	Installed/Active	05/13/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19553	Installed/Active	05/27/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19554	Installed/Active	05/31/2015	G75125	RUUD/RHEEM	\$ 2,835.00	\$ 43.94
19555	Installed/Active	05/29/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19556	Installed/Active	06/08/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19557	Installed/Active	05/21/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19558	Installed/Active	05/29/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19559	Installed/Active	05/28/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19560	Installed/Active	05/21/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19561	Installed/Active	05/18/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19562	Installed/Active	05/29/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19563	Installed/Active	05/26/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19564	Installed/Active	06/04/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19565	Installed/Active	02/29/2008	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 51.80
19566	Installed/Active	05/28/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19567	Installed/Active	05/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19568	Installed/Active	05/13/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.60
19569	Installed/Active	05/28/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19570	Installed/Active	05/28/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 979.00	\$ 18.60
19571	Installed/Active	05/20/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
19572	Installed/Active	05/22/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 16.16
19573	Installed/Active	05/31/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19574	Installed/Active	06/01/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19575	Installed/Active	06/05/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19576	Installed/Active	06/05/2015	M15036FBN	Bradford White	\$ 850.00	\$ 6.33
19577	Installed/Active	06/02/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19578	Installed/Active	06/04/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19579	Installed/Active	04/14/2015	G82156	RUUD	\$ 3,360.00	\$ 58.84
19580	Installed/Active	06/02/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19581	Installed/Active	05/19/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19582	Installed/Active	06/03/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19583	Installed/Active	06/03/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19584	Installed/Active	06/10/2015	FSG40	AO SMITH	\$ 850.00	\$ 13.12
19585	Installed/Active	06/05/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19586	Installed/Active	06/12/2015	FSG40	AO SMITH	\$ 850.00	\$ 13.12
19587	Installed/Active	06/16/2015	FSGL40	AO SMITH	\$ 850.00	\$ 13.12
19588	Installed/Active	06/11/2015	LTN050GEF	LOCHINVAR	\$ 850.00	\$ 13.12
19589	Installed/Active	06/05/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19590	Installed/Active	06/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19591	Installed/Active	06/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19592	Installed/Active	06/12/2015	M15036FBN	Bradford White	\$ 850.00	\$ 7.99
19593	Installed/Active	06/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19594	Installed/Active	06/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19595	Installed/Active	06/15/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19596	Installed/Active	06/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19597	Installed/Active	06/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19598	Installed/Active	05/26/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19599	Installed/Active	05/27/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 18.60
19600	Installed/Active	05/27/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19601	Installed/Active	05/15/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19602	Installed/Active	05/27/2015	G91200	RUUD	\$ 3,367.00	\$ 68.44
19603	Installed/Active	06/03/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19604	Installed/Active	06/09/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19605	Installed/Active	05/29/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19606	Installed/Active	05/30/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19607	Installed/Active	06/02/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19608	Installed/Active	06/09/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19609	Installed/Active	06/03/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19610	Installed/Active	06/04/2015	MI40T6FBN	BRADFORD WHITE	\$ 350.00	\$ 16.16
19611	Installed/Active	06/04/2015	M45036FBN	BRADFORD WHITE	\$ 1,125.00	\$ 21.27
19612	Installed/Active	06/11/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 16.16
19613	Installed/Active	05/29/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19614	Installed/Active	06/26/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19615	Installed/Active	06/12/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19616	Installed/Active	06/04/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19617	Installed/Active	06/09/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19618	Installed/Active	06/11/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19619	Installed/Active	06/12/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.60
19620	Installed/Active	06/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19621	Installed/Active	06/10/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19622	Installed/Active	06/10/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19623	Installed/Active	06/10/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19624	Installed/Active	06/15/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19625	Installed/Active	06/17/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19626	Installed/Active	06/17/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19627	Installed/Active	06/18/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19628	Installed/Active	05/28/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19629	Installed/Active	06/22/2015	PROG2932NRU62	RUUD/RHEEM	\$ 850.00	\$ 6.33
19630	Installed/Active	06/07/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.33
19631	Installed/Active	06/29/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19632	Installed/Active	06/17/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19633	Installed/Active	06/16/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19634	Installed/Active	06/20/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19635	Installed/Active	06/18/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19636	Installed/Active	05/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19637	Installed/Active	06/08/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19638	Installed/Active	06/12/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 6.33
19639	Installed/Active	06/15/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19640	Installed/Active	06/15/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19641	Installed/Active	06/11/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19642	Installed/Active	06/12/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19643	Installed/Active	06/11/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19644	Installed/Active	06/15/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19645	Installed/Active	06/05/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19646	Installed/Active	05/22/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19647	Installed/Active	06/04/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19648	Installed/Active	06/06/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19649	Installed/Active	07/01/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19650	Installed/Active	07/01/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19651	Installed/Active	07/02/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19652	Installed/Active	07/02/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19653	Installed/Active	07/06/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19654	Installed/Active	06/16/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19655	Installed/Active	06/18/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19656	Installed/Active	06/18/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19657	Installed/Active	06/19/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19658	Installed/Active	06/19/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19659	Installed/Active	06/19/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19660	Installed/Active	06/23/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19661	Installed/Active	06/23/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19662	Installed/Active	06/23/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19663	Installed/Active	06/24/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19664	Installed/Active	06/25/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19665	Installed/Active	06/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19666	Installed/Active	06/25/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19667	Installed/Active	06/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19668	Installed/Active	06/16/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19669	Installed/Active	06/17/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19670	Installed/Active	06/19/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19671	Installed/Active	06/20/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19672	Installed/Active	06/21/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19673	Installed/Active	06/22/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19674	Installed/Active	06/23/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19675	Installed/Active	06/23/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19676	Installed/Active	06/24/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19677	Installed/Active	06/25/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19678	Installed/Active	06/25/2015	G91200	Ru	\$ 3,350.00	\$ 68.44
19679	Installed/Active	05/18/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19680	Installed/Active	06/16/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 6.33
19681	Installed/Active	06/22/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19682	Installed/Active	06/26/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19683	Installed/Active	06/26/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19684	Installed/Active	06/27/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19685	Installed/Active	06/29/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19686	Installed/Active	06/29/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19687	Installed/Active	06/26/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19688	Installed/Active	06/24/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19689	Installed/Active	06/25/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19690	Installed/Active	06/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19691	Installed/Active	06/26/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19692	Installed/Active	06/29/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19693	Installed/Active	06/30/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19694	Installed/Active	06/30/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19695	Installed/Active	06/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19696	Installed/Active	06/25/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19697	Installed/Active	07/01/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19698	Installed/Active	07/02/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19699	Installed/Active	07/02/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19700	Installed/Active	07/02/2015	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19701	Installed/Active	07/03/2015	M45036FBN	Bradford White	\$ 1,125.00	\$ 21.27
19702	Installed/Active	07/06/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19703	Installed/Active	07/06/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19704	Installed/Active	07/06/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19705	Installed/Active	07/06/2015	M45036FBN	Bradford White	\$ 1,150.00	\$ 18.20
19706	Installed/Active	07/06/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19707	Installed/Active	07/02/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19708	Installed/Active	07/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19709	Installed/Active	07/06/2015	PH13080	Phoenix	\$ 3,350.00	\$ 68.44
19710	Installed/Active	07/07/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19711	Installed/Active	06/12/2015	PROG5038NRU58	RUUD	\$ 979.00	\$ 11.47
19712	Installed/Active	06/03/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19713	Installed/Active	06/15/2015	M15036FBN	Bradford White	\$ 850.00	\$ 6.33
19714	Installed/Active	06/24/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 7.99
19715	Installed/Active	06/25/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19716	Installed/Active	06/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19717	Installed/Active	06/29/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19718	Installed/Active	06/29/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19719	Installed/Active	06/29/2015	PROG5038NRU58	RUUD/RHEEM	\$ 850.00	\$ 13.12
19720	Installed/Active	06/30/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19721	Installed/Active	06/30/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19722	Installed/Active	06/18/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19723	Installed/Active	07/15/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19724	Installed/Active	07/01/2015	PROG5038NRU58DV	RUUD	\$ 979.00	\$ 13.12
19725	Installed/Active	07/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19726	Installed/Active	07/08/2015	PROG5036NRU60DV	RUUD	\$ 979.00	\$ 18.60
19727	Installed/Active	07/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19728	Installed/Active	07/15/2015	PROG5038NRU58DV	Ruud/Rheem	\$ 1,075.00	\$ 18.60
19729	Installed/Active	07/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19730	Installed/Active	07/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19731	Installed/Active	07/10/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19732	Installed/Active	07/15/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19733	Installed/Active	07/14/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19734	Installed/Active	07/14/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19735	Installed/Active	07/01/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19736	Installed/Active	07/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19737	Installed/Active	07/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19738	Installed/Active	07/17/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
19739	Installed/Active	07/17/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19740	Installed/Active	07/20/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19741	Installed/Active	07/28/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19742	Installed/Active	07/28/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19743	Installed/Active	07/01/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19744	Installed/Active	07/01/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19745	Installed/Active	07/27/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19746	Installed/Active	08/03/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19747	Installed/Active	08/03/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19748	Installed/Active	07/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19749	Installed/Active	07/17/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19750	Installed/Active	07/22/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19751	Installed/Active	07/23/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19752	Installed/Active	07/10/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19753	Installed/Active	07/23/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19754	Installed/Active	07/09/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19755	Installed/Active	07/24/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19756	Installed/Active	06/05/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19757	Installed/Active	07/15/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19758	Installed/Active	06/26/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19759	Installed/Active	07/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19760	Installed/Active	07/07/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19761	Installed/Active	07/30/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19762	Installed/Active	07/30/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19763	Installed/Active	07/29/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19764	Installed/Active	07/29/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19765	Installed/Active	07/28/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19766	Installed/Active	07/25/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.33
19767	Installed/Active	07/21/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
19768	Installed/Active	07/22/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19769	Installed/Active	07/30/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19770	Installed/Active	07/24/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19771	Installed/Active	07/29/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19772	Installed/Active	07/16/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19773	Installed/Active	06/30/2015	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19774	Installed/Active	07/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19775	Installed/Active	07/19/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19776	Installed/Active	07/16/2015	M15036FBN	Bradford White	\$ 850.00	\$ 7.99
19777	Installed/Active	07/20/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19778	Installed/Active	07/29/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19779	Installed/Active	07/29/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19780	Installed/Active	07/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19781	Installed/Active	07/09/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19782	Installed/Active	07/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19783	Installed/Active	07/08/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19784	Installed/Active	07/14/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19785	Installed/Active	07/13/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19786	Installed/Active	07/08/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19787	Installed/Active	07/10/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19788	Installed/Active	07/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19789	Installed/Active	07/08/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19790	Installed/Active	07/10/2015	M45036FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
19791	Installed/Active	07/21/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19792	Installed/Active	07/20/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19793	Installed/Active	07/17/2015	PROG5036NRU60DV	RUUD	\$ 979.00	\$ 18.60
19794	Installed/Active	07/20/2015	PROG5038NRU58	RUUD	\$ 1,075.00	\$ 18.60
19795	Installed/Active	07/07/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19796	Installed/Active	07/15/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19797	Installed/Active	07/08/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19798	Installed/Active	07/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19799	Installed/Active	07/18/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19800	Installed/Active	07/18/2015	PROG5038NRU58	Ruud/Rheem	\$ 1,075.00	\$ 18.60
19801	Installed/Active	07/07/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19802	Installed/Active	07/15/2015	MI403S6FBN	Bradford White	\$ 850.00	\$ 13.12
19803	Installed/Active	07/21/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19804	Installed/Active	07/21/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19805	Installed/Active	07/21/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19806	Installed/Active	07/20/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19807	Installed/Active	07/10/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19808	Installed/Active	07/22/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19809	Installed/Active	07/23/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19810	Installed/Active	07/23/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19811	Installed/Active	07/09/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19812	Installed/Active	07/15/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19813	Installed/Active	07/24/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19814	Installed/Active	07/22/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19815	Installed/Active	06/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19816	Installed/Active	06/20/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19817	Installed/Active	06/20/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19818	Installed/Active	06/30/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19819	Installed/Active	07/27/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19820	Installed/Active	07/27/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19821	Installed/Active	07/29/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19822	Installed/Active	07/21/2015	MI50L6FBN	Bradford White	\$ 850.00	\$ 13.12
19823	Installed/Active	07/17/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19824	Installed/Active	07/16/2015	MI50L6FBN	Bradford White	\$ 850.00	\$ 13.12
19825	Installed/Active	07/22/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.33
19826	Installed/Active	07/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19827	Installed/Active	07/22/2015	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19828	Installed/Active	07/16/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19829	Installed/Active	07/16/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19830	Installed/Active	07/03/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19831	Installed/Active	07/28/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19832	Installed/Active	07/23/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19833	Installed/Active	07/08/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19834	Installed/Active	07/27/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19835	Installed/Active	07/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19836	Installed/Active	07/27/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19837	Installed/Active	07/21/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.33
19838	Installed/Active	07/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19839	Installed/Active	07/23/2015	M45036FBN	Bradford White	\$ 850.00	\$ 7.99
19840	Installed/Active	07/18/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19841	Installed/Active	03/12/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19842	Installed/Active	08/05/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19843	Installed/Active	08/04/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19844	Installed/Active	08/05/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19845	Installed/Active	08/03/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19846	Installed/Active	07/15/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19847	Installed/Active	08/07/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 13.12
19848	Installed/Active	08/06/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19849	Installed/Active	08/11/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19850	Installed/Active	08/07/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19851	Installed/Active	08/06/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19852	Installed/Active	08/03/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19853	Installed/Active	08/04/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19854	Installed/Active	08/03/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19855	Installed/Active	08/06/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19856	Installed/Active	07/21/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19857	Installed/Active	08/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19858	Installed/Active	08/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19859	Installed/Active	07/28/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19860	Installed/Active	07/31/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19861	Installed/Active	07/31/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19862	Installed/Active	08/06/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19863	Installed/Active	07/22/2015	MI40T6FBN	Bradford White	\$ 850.00	\$ 6.33
19864	Installed/Active	07/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 7.99
19865	Installed/Active	07/24/2015	MI5036FBN	Bradford White	\$ 850.00	\$ 13.12
19866	Installed/Active	08/04/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19867	Installed/Active	08/05/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19868	Installed/Active	08/15/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19869	Installed/Active	08/04/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19870	Installed/Active	08/05/2015	M175S6FBN	Bradford White	\$ 1,900.00	\$ 43.94
19871	Installed/Active	07/01/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19872	Installed/Active	08/20/2015	FGR40	Bradford White	\$ 850.00	\$ 13.12
19873	Installed/Active	08/24/2015	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 21.27
19874	Installed/Active	08/21/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19875	Installed/Active	08/21/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19876	Installed/Active	08/24/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19877	Installed/Active	07/19/2015	PROG2932NRU62	RUUD/RHEEM	\$ 850.00	\$ 13.12
19878	Installed/Active	08/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19879	Installed/Active	08/21/2015	DS140S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19880	Installed/Active	08/20/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19881	Installed/Active	08/18/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19882	Installed/Active	08/22/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19883	Installed/Active	08/18/2015	DS150S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19884	Installed/Active	08/24/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19885	Installed/Active	08/24/2015	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 11.47
19886	Installed/Active	08/19/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19887	Installed/Active	08/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19888	Installed/Active	08/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19889	Installed/Active	08/23/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19890	Installed/Active	08/25/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 7.99
19891	Installed/Active	08/25/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19892	Installed/Active	08/25/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19893	Installed/Active	08/26/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19894	Installed/Active	08/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19895	Installed/Active	08/28/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19896	Installed/Active	08/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19897	Installed/Active	08/19/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19898	Installed/Active	08/05/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19899	Installed/Active	08/14/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19900	Installed/Active	08/17/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19901	Installed/Active	08/18/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19902	Installed/Active	08/24/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19903	Installed/Active	08/24/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19904	Installed/Active	08/26/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19905	Installed/Active	08/27/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19906	Installed/Active	08/27/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19907	Installed/Active	08/19/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
19908	Installed/Active	08/17/2015	XTN050	LOCHINVAR	\$ 850.00	\$ 13.12
19909	Installed/Active	08/14/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19910	Installed/Active	08/14/2015	PROG5036NRU60	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19911	Installed/Active	08/03/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19912	Installed/Active	07/14/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19913	Installed/Active	08/08/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19914	Installed/Active	07/01/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19915	Installed/Active	08/05/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19916	Installed/Active	08/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19917	Installed/Active	08/06/2015	RG250T6N	Bradford White	\$ 1,125.00	\$ 21.27
19918	Installed/Active	08/11/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19919	Installed/Active	08/11/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
19920	Installed/Active	08/17/2015	RG250L6N	Bradford White	\$ 850.00	\$ 13.12
19921	Installed/Active	08/11/2015	M150L6FBN	Bradford White	\$ 850.00	\$ 13.12
19922	Installed/Active	08/14/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19923	Installed/Active	08/14/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19924	Installed/Active	08/06/2015	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 21.27
19925	Installed/Active	08/13/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 6.33
19926	Installed/Active	07/31/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19927	Installed/Active	08/12/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19928	Installed/Active	08/12/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
19929	Installed/Active	08/06/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19930	Installed/Active	07/30/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19931	Installed/Active	08/06/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19932	Installed/Active	08/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19933	Installed/Active	08/08/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19934	Installed/Active	08/08/2015	M45036FBN	Bradford White	\$ 850.00	\$ 6.33
19935	Installed/Active	08/07/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19936	Installed/Active	08/07/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19937	Installed/Active	08/04/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
19938	Installed/Active	08/04/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19939	Installed/Active	08/02/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19940	Installed/Active	08/02/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 7.99
19941	Installed/Active	08/19/2015	RG250L6N	Bradford White	\$ 850.00	\$ 13.12
19942	Installed/Active	08/18/2015	M15036FBN	Bradford White	\$ 850.00	\$ 13.12
19943	Installed/Active	07/31/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19944	Installed/Active	08/18/2015	M15036FBN	Bradford White	\$ 850.00	\$ 7.99
19945	Installed/Active	08/13/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19946	Installed/Active	08/19/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
19947	Installed/Active	08/20/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19948	Installed/Active	08/20/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 18.20
19949	Installed/Active	08/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19950	Installed/Active	08/19/2015	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19951	Installed/Active	08/17/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19952	Installed/Active	08/17/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
19953	Installed/Active	08/29/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19954	Installed/Active	08/27/2015	M15036FBN	Bradford White	\$ 850.00	\$ 7.99
19955	Installed/Active	08/31/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19956	Installed/Active	08/27/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19957	Installed/Active	08/27/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19958	Installed/Active	05/07/2015	PROG5038NRU58	RUUD/RHEEM	\$ 1,075.00	\$ 18.60
19959	Installed/Active	05/07/2015	M45036FBN	Bradford White	\$ 850.00	\$ 13.12
19960	Installed/Active	09/02/2015	DS140S6FBN	Bradford White	\$ 1,075.00	\$ 18.60
19961	Installed/Active	09/02/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19962	Installed/Active	09/02/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19963	Installed/Active	09/04/2015	RG250T6N	Bradford White	\$ 850.00	\$ 7.99
19964	Installed/Active	08/27/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19965	Installed/Active	08/31/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19966	Installed/Active	08/31/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
19967	Installed/Active	08/31/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19968	Installed/Active	08/24/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19969	Installed/Active	08/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19970	Installed/Active	09/01/2015	M140T6FBN	Bradford White	\$ 850.00	\$ 13.12
19971	Installed/Active	09/01/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
19972	Installed/Active	09/01/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19973	Installed/Active	09/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19974	Installed/Active	09/09/2015	DS140S6FBN	STATE	\$ 1,075.00	\$ 11.47
19975	Installed/Active	09/08/2015	M1403S6FBN	Bradford White	\$ 850.00	\$ 6.33
19976	Installed/Active	09/14/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
19977	Installed/Active	09/14/2015	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.94
19978	Installed/Active	09/08/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19979	Installed/Active	09/10/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
19980	Installed/Active	09/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19981	Installed/Active	09/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19982	Installed/Active	09/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19983	Installed/Active	09/12/2015	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19984	Installed/Active	09/09/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
19985	Installed/Active	09/02/2015	M150L6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 18.20
19986	Installed/Active	09/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19987	Installed/Active	09/08/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
19988	Installed/Active	09/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19989	Installed/Active	09/10/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19990	Installed/Active	09/04/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19991	Installed/Active	07/07/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
19992	Installed/Active	09/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
19993	Installed/Active	09/01/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19994	Installed/Active	09/22/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19995	Installed/Active	09/14/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
19996	Installed/Active	09/16/2015	DS140S6FBN	BRADFORD-WHITE	\$ 1,075.00	\$ 18.60
19997	Installed/Active	08/21/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
19998	Installed/Active	09/18/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
19999	Installed/Active	09/17/2015	LTN050	LOCHINVAR	\$ 850.00	\$ 13.12
20000	Installed/Active	09/22/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20001	Installed/Active	09/22/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20002	Installed/Active	09/18/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20003	Installed/Active	09/16/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.99
20004	Installed/Active	09/14/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20005	Installed/Active	09/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20006	Installed/Active	09/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20007	Installed/Active	09/01/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 7.99
20008	Installed/Active	08/24/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20009	Installed/Active	09/15/2015	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 18.20
20010	Installed/Active	09/16/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20011	Installed/Active	09/18/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 7.99
20012	Installed/Active	09/18/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20013	Installed/Active	09/08/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20014	Installed/Active	09/16/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20015	Installed/Active	09/18/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20016	Installed/Active	09/21/2015	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20017	Installed/Active	09/14/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20018	Installed/Active	09/17/2015	G76200	RUUD	\$ 3,350.00	\$ 68.44
20019	Installed/Active	09/08/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20020	Installed/Active	09/08/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20021	Installed/Active	09/14/2015	PROG5036NRU60DV	BRADFORD-WHITE	\$ 1,075.00	\$ 18.60
20022	Installed/Active	09/08/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20023	Installed/Active	09/14/2015	M2XR504T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20024	Installed/Active	09/14/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20025	Installed/Active	09/02/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20026	Installed/Active	09/11/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20027	Installed/Active	09/08/2015	M140T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20028	Installed/Active	09/21/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.33
20029	Installed/Active	09/29/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20030	Installed/Active	09/30/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20031	Installed/Active	09/30/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20032	Installed/Active	09/29/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20033	Installed/Active	09/30/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20034	Installed/Active	09/30/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
20035	Installed/Active	09/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20036	Installed/Active	09/28/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20037	Installed/Active	09/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20038	Installed/Active	09/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20039	Installed/Active	09/28/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20040	Installed/Active	09/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20041	Installed/Active	09/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20042	Installed/Active	09/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20043	Installed/Active	09/17/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20044	Installed/Active	09/16/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
20045	Installed/Active	09/02/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20046	Installed/Active	09/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20047	Installed/Active	09/18/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20048	Installed/Active	09/24/2015	PROG5038NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20049	Installed/Active	09/26/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20050	Installed/Active	09/25/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20051	Installed/Active	09/27/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20052	Installed/Active	09/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20053	Installed/Active	09/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20054	Installed/Active	09/22/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20055	Installed/Active	09/22/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20056	Installed/Active	09/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20057	Installed/Active	09/23/2015	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20058	Installed/Active	09/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20059	Installed/Active	09/26/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20060	Installed/Active	09/27/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20061	Installed/Active	09/29/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20062	Installed/Active	09/30/2015	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20063	Installed/Active	09/18/2015	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20064	Installed/Active	09/29/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20065	Installed/Active	09/25/2015	MI403S6FBN	BRADFORD WHITE	\$ 350.00	\$ 16.16
20066	Installed/Active	09/17/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20067	Installed/Active	09/24/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20068	Installed/Active	08/24/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20069	Installed/Active	09/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20070	Installed/Active	09/29/2015	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20071	Installed/Active	10/05/2015	MI5036FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20072	Installed/Active	10/05/2015	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20073	Installed/Active	10/07/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20074	Installed/Active	10/07/2015	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 13.12
20075	Installed/Active	10/08/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20076	Installed/Active	10/01/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20077	Installed/Active	10/01/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20078	Installed/Active	10/01/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20079	Installed/Active	10/01/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20080	Installed/Active	10/02/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20081	Installed/Active	10/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20082	Installed/Active	10/02/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20083	Installed/Active	10/05/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20084	Installed/Active	10/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20085	Installed/Active	10/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20086	Installed/Active	10/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20087	Installed/Active	10/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20088	Installed/Active	10/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20089	Installed/Active	10/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20090	Installed/Active	10/03/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20091	Installed/Active	10/08/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20092	Installed/Active	10/02/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20093	Installed/Active	09/24/2015	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20094	Installed/Active	10/12/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20095	Installed/Active	10/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20096	Installed/Active	10/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20097	Installed/Active	10/09/2015	MI40T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20098	Installed/Active	10/08/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20099	Installed/Active	10/07/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20100	Installed/Active	10/07/2015	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20101	Installed/Active	10/07/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20102	Installed/Active	10/06/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20103	Installed/Active	10/06/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20104	Installed/Active	10/04/2015	MI50L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20105	Installed/Active	10/09/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20106	Installed/Active	10/07/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20107	Installed/Active	10/15/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20108	Installed/Active	10/15/2015	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20109	Installed/Active	10/14/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20110	Installed/Active	10/13/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20111	Installed/Active	09/13/2015	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.94
20112	Installed/Active	09/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20113	Installed/Active	10/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20114	Installed/Active	10/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20115	Installed/Active	10/09/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.33
20116	Installed/Active	10/08/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20117	Installed/Active	10/08/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20118	Installed/Active	10/07/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20119	Installed/Active	10/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20120	Installed/Active	10/15/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20121	Installed/Active	10/15/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20122	Installed/Active	10/14/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20123	Installed/Active	10/14/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.20
20124	Installed/Active	10/14/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20125	Installed/Active	10/13/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20126	Installed/Active	10/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20127	Installed/Active	10/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20128	Installed/Active	10/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20129	Installed/Active	10/06/2015	RG240S6N	BRADFORD-WHITE	\$ 350.00	\$ 16.16
20130	Installed/Active	10/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20131	Installed/Active	10/19/2015	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 18.20
20132	Installed/Active	10/19/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20133	Installed/Active	10/19/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20134	Installed/Active	10/19/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 7.99
20135	Installed/Active	10/16/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20136	Installed/Active	10/15/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20137	Installed/Active	10/14/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 13.12
20138	Installed/Active	10/08/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20139	Installed/Active	10/01/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20140	Installed/Active	10/16/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20141	Installed/Active	10/17/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20142	Installed/Active	10/15/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20143	Installed/Active	10/20/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20144	Installed/Active	10/20/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20145	Installed/Active	10/20/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20146	Installed/Active	09/15/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20147	Installed/Active	10/12/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20148	Installed/Active	10/12/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20149	Installed/Active	10/16/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20150	Installed/Active	10/20/2015	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20151	Installed/Active	10/20/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20152	Installed/Active	10/15/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20153	Installed/Active	10/15/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20154	Installed/Active	10/17/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20155	Installed/Active	10/20/2015	M2XR504T6FBN	BRADFORD-WHITE	\$ 1,150.00	\$ 18.20
20156	Installed/Active	10/14/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20157	Installed/Active	10/26/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20158	Installed/Active	10/26/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20159	Installed/Active	10/30/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20160	Installed/Active	10/21/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20161	Installed/Active	10/26/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20162	Installed/Active	10/31/2015	G82156	RUUD	\$ 3,350.00	\$ 58.84
20163	Installed/Active	10/23/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20164	Installed/Active	10/17/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20165	Installed/Active	10/29/2015	PH199119	PHOENIX	\$ 3,350.00	\$ 68.44
20166	Installed/Active	10/28/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20167	Installed/Active	10/19/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20168	Installed/Active	10/19/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20169	Installed/Active	10/20/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20170	Installed/Active	10/23/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20171	Installed/Active	10/29/2015	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.33
20172	Installed/Active	10/29/2015	RG240S6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20173	Installed/Active	10/22/2015	RG240T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20174	Installed/Active	10/22/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20175	Installed/Active	10/21/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20176	Installed/Active	10/21/2015	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20177	Installed/Active	10/28/2015	RG240T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20178	Installed/Active	10/26/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20179	Installed/Active	10/28/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20180	Installed/Active	10/30/2015	M440T6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20181	Installed/Active	10/23/2015	RG240S6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20182	Installed/Active	10/23/2015	RG250L6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20183	Installed/Active	10/12/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20184	Installed/Active	10/13/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20185	Installed/Active	10/23/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20186	Installed/Active	11/03/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20187	Installed/Active	11/03/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20188	Installed/Active	11/03/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20189	Installed/Active	11/04/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20190	Installed/Active	11/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20191	Installed/Active	11/03/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20192	Installed/Active	11/03/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20193	Installed/Active	11/03/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20194	Installed/Active	11/02/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20195	Installed/Active	11/04/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20196	Installed/Active	11/02/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20197	Installed/Active	11/01/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20198	Installed/Active	10/31/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20199	Installed/Active	10/28/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20200	Installed/Active	10/28/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20201	Installed/Active	10/29/2015	M1403S6FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.12
20202	Installed/Active	11/05/2015	G82156	RUUD	\$ 3,350.00	\$ 58.84
20203	Installed/Active	11/04/2015	RG240T6N	BRADFORD-WHITE	\$ 350.00	\$ 16.16
20204	Installed/Active	11/04/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20205	Installed/Active	09/23/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20206	Installed/Active	11/15/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20207	Installed/Active	11/03/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20208	Installed/Active	10/29/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20209	Installed/Active	11/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20210	Installed/Active	11/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20211	Installed/Active	11/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20212	Installed/Active	11/04/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20213	Installed/Active	10/21/2015	RG250T6N	Bradford White	\$ 1,078.00	\$ 6.33
20214	Installed/Active	10/30/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 7.99
20215	Installed/Active	10/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20216	Installed/Active	11/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20217	Installed/Active	11/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20218	Installed/Active	11/06/2015	RG240T6N	BRADFORD WHITE	\$ 3,350.00	\$ 13.12
20219	Installed/Active	11/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20220	Installed/Active	11/08/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20221	Installed/Active	11/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20222	Installed/Active	11/10/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20223	Installed/Active	11/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20224	Installed/Active	11/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20225	Installed/Active	11/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20226	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20227	Installed/Active	11/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20228	Installed/Active	10/28/2015	G82156	RUUD	\$ 3,350.00	\$ 58.84
20229	Installed/Active	11/11/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20230	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20231	Installed/Active	11/12/2015	PROG5036NRU60DV	STATE	\$ 1,075.00	\$ 18.60
20232	Installed/Active	11/12/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20233	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20234	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20235	Installed/Active	11/10/2015	DS150S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 11.47
20236	Installed/Active	11/10/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20237	Installed/Active	11/07/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20238	Installed/Active	10/22/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20239	Installed/Active	11/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20240	Installed/Active	11/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20241	Installed/Active	11/11/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20242	Installed/Active	11/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20243	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20244	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20245	Installed/Active	11/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20246	Installed/Active	11/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20247	Installed/Active	11/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20248	Installed/Active	11/09/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20249	Installed/Active	11/12/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20250	Installed/Active	11/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20251	Installed/Active	11/13/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20252	Installed/Active	11/17/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20253	Installed/Active	11/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20254	Installed/Active	11/12/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20255	Installed/Active	10/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20256	Installed/Active	01/31/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20257	Installed/Active	11/09/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20258	Installed/Active	11/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20259	Installed/Active	11/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20260	Installed/Active	10/27/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20261	Installed/Active	11/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20262	Installed/Active	11/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20263	Installed/Active	11/17/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20264	Installed/Active	11/13/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20265	Installed/Active	11/24/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 500.00	\$ 21.27
20266	Installed/Active	11/19/2015	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 21.27
20267	Installed/Active	11/13/2015	G82156	RUUD	\$ 3,350.00	\$ 58.84
20268	Installed/Active	11/14/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20269	Installed/Active	11/21/2015	G76200	RUUD	\$ 3,350.00	\$ 68.44
20270	Installed/Active	11/04/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20271	Installed/Active	11/14/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20272	Installed/Active	10/01/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20273	Installed/Active	11/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20274	Installed/Active	11/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20275	Installed/Active	11/12/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20276	Installed/Active	11/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20277	Installed/Active	11/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20278	Installed/Active	11/18/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20279	Installed/Active	11/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20280	Installed/Active	11/18/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20281	Installed/Active	11/12/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
20282	Installed/Active	11/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20283	Installed/Active	11/06/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.33
20284	Installed/Active	11/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20285	Installed/Active	11/20/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20286	Installed/Active	11/20/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20287	Installed/Active	11/16/2015	GVC50	RUUD	\$ 850.00	\$ 13.12
20288	Installed/Active	11/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20289	Installed/Active	11/28/2015	DS150S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 18.60
20290	Installed/Active	11/09/2015	G76200	RUUD	\$ 3,350.00	\$ 68.44
20291	Installed/Active	10/26/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20292	Installed/Active	11/27/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20293	Installed/Active	11/13/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20294	Installed/Active	12/04/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20295	Installed/Active	12/14/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20296	Installed/Active	12/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20297	Installed/Active	12/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20298	Installed/Active	12/11/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20299	Installed/Active	12/09/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20300	Installed/Active	12/10/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20301	Installed/Active	12/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20302	Installed/Active	12/08/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20303	Installed/Active	12/08/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20304	Installed/Active	12/03/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20305	Installed/Active	08/25/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20306	Installed/Active	11/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20307	Installed/Active	11/16/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20308	Installed/Active	11/19/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20309	Installed/Active	10/30/2015	RG250T6N	Bradford White	\$ 1,150.00	\$ 18.20
20310	Installed/Active	11/25/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20311	Installed/Active	11/30/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20312	Installed/Active	11/30/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20313	Installed/Active	11/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20314	Installed/Active	11/24/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20315	Installed/Active	11/27/2015	FSG50	AO SMITH	\$ 850.00	\$ 13.12
20316	Installed/Active	11/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20317	Installed/Active	11/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20318	Installed/Active	11/17/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20319	Installed/Active	11/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20320	Installed/Active	11/25/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20321	Installed/Active	11/23/2015	PROG40S34NRU62	RUUD	\$ 850.00	\$ 13.12
20322	Installed/Active	11/28/2015	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.94
20323	Installed/Active	11/25/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.33
20324	Installed/Active	12/02/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20325	Installed/Active	12/01/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20326	Installed/Active	11/25/2015	RG250T6N	Bradford White	\$ 850.00	\$ 7.99
20327	Installed/Active	12/05/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20328	Installed/Active	12/02/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20329	Installed/Active	12/01/2015	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20330	Installed/Active	11/26/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20331	Installed/Active	12/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20332	Installed/Active	12/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20333	Installed/Active	12/11/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20334	Installed/Active	12/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20335	Installed/Active	11/17/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20336	Installed/Active	11/05/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20337	Installed/Active	11/30/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20338	Installed/Active	11/29/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20339	Installed/Active	10/05/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20340	Installed/Active	11/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20341	Installed/Active	11/20/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20342	Installed/Active	09/22/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20343	Installed/Active	11/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20344	Installed/Active	11/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20345	Installed/Active	11/21/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20346	Installed/Active	10/09/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20347	Installed/Active	11/25/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20348	Installed/Active	11/25/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20349	Installed/Active	11/18/2015	PROG30S30NRU63	RHEEM	\$ 850.00	\$ 6.33
20350	Installed/Active	11/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20351	Installed/Active	11/30/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20352	Installed/Active	11/30/2015	G75125	RUUD	\$ 1,900.00	\$ 43.94
20353	Installed/Active	11/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20354	Installed/Active	12/01/2015	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20355	Installed/Active	12/03/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20356	Installed/Active	12/06/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 7.99
20357	Installed/Active	12/07/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20358	Installed/Active	12/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20359	Installed/Active	12/09/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20360	Installed/Active	12/10/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20361	Installed/Active	12/04/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20362	Installed/Active	12/06/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20363	Installed/Active	11/23/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20364	Installed/Active	11/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20365	Installed/Active	11/30/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20366	Installed/Active	12/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20367	Installed/Active	12/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20368	Installed/Active	12/03/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20369	Installed/Active	12/10/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20370	Installed/Active	12/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20371	Installed/Active	11/28/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20372	Installed/Active	12/02/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20373	Installed/Active	12/03/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20374	Installed/Active	12/07/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20375	Installed/Active	11/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20376	Installed/Active	12/10/2015	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.20
20377	Installed/Active	12/10/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20378	Installed/Active	11/22/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20379	Installed/Active	11/26/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.47
20380	Installed/Active	12/07/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20381	Installed/Active	12/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20382	Installed/Active	12/07/2015	G91200	RHEEM / RUUD	\$ 3,350.00	\$ 68.44

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20383	Installed/Active	12/11/2015	G82156	RUUD	\$ 3,350.00	\$ 58.84
20384	Installed/Active	12/09/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20385	Installed/Active	12/03/2015	RG240T6N	Bradford White	\$ 850.00	\$ 6.33
20386	Installed/Active	12/13/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20387	Installed/Active	12/16/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20388	Installed/Active	12/16/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20389	Installed/Active	12/16/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20390	Installed/Active	12/15/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20391	Installed/Active	12/15/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
20392	Installed/Active	12/15/2015	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 68.44
20393	Installed/Active	12/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20394	Installed/Active	12/22/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20395	Installed/Active	12/22/2015	RG250T6N	Bradford White	\$ 850.00	\$ 7.99
20396	Installed/Active	12/14/2015	M175S6FBN	Bradford White	\$ 950.00	\$ 21.27
20397	Installed/Active	01/04/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20398	Installed/Active	01/11/2016	RG250T6N	Bradford White	\$ 1,125.00	\$ 21.74
20399	Installed/Active	01/06/2016	RG240T6N	Bradford White	\$ 850.00	\$ 8.17
20400	Installed/Active	01/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20401	Installed/Active	01/13/2016	DS140S6FBN	Bradford White	\$ 1,075.00	\$ 19.01
20402	Installed/Active	01/13/2016	RG2D40S6N	Bradford White	\$ 1,075.00	\$ 19.01
20403	Installed/Active	01/05/2016	RG250T6N	Bradford White	\$ 1,075.00	\$ 11.72
20404	Installed/Active	01/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20405	Installed/Active	01/12/2016	M440T6FBN	Bradford White	\$ 850.00	\$ 13.41
20406	Installed/Active	12/09/2015	RG240T6N	Bradford White	\$ 850.00	\$ 6.33
20407	Installed/Active	01/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20408	Installed/Active	01/14/2016	PROG5038NRU60	RUUD	\$ 850.00	\$ 13.41
20409	Installed/Active	01/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
20410	Installed/Active	01/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20411	Installed/Active	12/13/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20412	Installed/Active	01/27/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20413	Installed/Active	01/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20414	Installed/Active	01/29/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20415	Installed/Active	01/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20416	Installed/Active	01/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
20417	Installed/Active	01/26/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20418	Installed/Active	01/29/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
20419	Installed/Active	01/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20420	Installed/Active	12/31/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
20421	Installed/Active	01/14/2016	RG250T6N	Bradford White	\$ 1,150.00	\$ 18.60
20422	Installed/Active	01/19/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
20423	Installed/Active	12/11/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 6.33
20424	Installed/Active	12/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20425	Installed/Active	11/20/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20426	Installed/Active	12/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20427	Installed/Active	12/13/2015	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20428	Installed/Active	12/17/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20429	Installed/Active	12/03/2015	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.27
20430	Installed/Active	12/13/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20431	Installed/Active	12/14/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20432	Installed/Active	12/11/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20433	Installed/Active	12/03/2015	RG240T6N	Bradford White	\$ 850.00	\$ 6.33
20434	Installed/Active	12/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20435	Installed/Active	12/11/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20436	Installed/Active	12/14/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20437	Installed/Active	09/06/2015	M140T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
20438	Installed/Active	12/13/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20439	Installed/Active	12/18/2015	PROG5038NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20440	Installed/Active	12/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20441	Installed/Active	12/19/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20442	Installed/Active	12/19/2015	PROG5038NRU58DV	RUUD	\$ 1,075.00	\$ 18.60
20443	Installed/Active	12/18/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20444	Installed/Active	12/12/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20445	Installed/Active	12/16/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20446	Installed/Active	12/21/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20447	Installed/Active	12/21/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20448	Installed/Active	12/23/2015	G91200	RUUD	\$ 3,350.00	\$ 68.44
20449	Installed/Active	12/17/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20450	Installed/Active	12/17/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20451	Installed/Active	12/28/2015	PROG5036NRU60DV	Rheem	\$ 1,075.00	\$ 18.60
20452	Installed/Active	01/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20453	Installed/Active	01/11/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
20454	Installed/Active	01/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20455	Installed/Active	01/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20456	Installed/Active	01/09/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20457	Installed/Active	12/23/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20458	Installed/Active	12/26/2015	RG275H6N	Bradford White	\$ 1,750.00	\$ 33.57
20459	Installed/Active	12/26/2015	G76200	RUUD	\$ 3,350.00	\$ 68.44
20460	Installed/Active	01/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20461	Installed/Active	01/15/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20462	Installed/Active	02/02/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
20463	Installed/Active	02/01/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
20464	Installed/Active	12/30/2015	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.33
20465	Installed/Active	12/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20466	Installed/Active	12/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20467	Installed/Active	12/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20468	Installed/Active	12/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20469	Installed/Active	12/21/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20470	Installed/Active	12/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20471	Installed/Active	12/28/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20472	Installed/Active	12/31/2015	G75125	RUUD	\$ 1,900.00	\$ 43.94
20473	Installed/Active	12/28/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20474	Installed/Active	12/30/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20475	Installed/Active	12/11/2015	M440T6FBN	B	\$ 850.00	\$ 6.33
20476	Installed/Active	12/15/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20477	Installed/Active	12/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20478	Installed/Active	12/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20479	Installed/Active	12/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20480	Installed/Active	12/21/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20481	Installed/Active	12/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20482	Installed/Active	12/18/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20483	Installed/Active	12/08/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20484	Installed/Active	12/24/2015	RG250T6N	Bradford White	\$ 850.00	\$ 18.20
20485	Installed/Active	12/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20486	Installed/Active	12/22/2015	M2XR504T6FBN	Bradford White	\$ 1,150.00	\$ 18.20
20487	Installed/Active	12/22/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20488	Installed/Active	12/31/2015	M440T6FBN	Bradford White	\$ 850.00	\$ 13.12
20489	Installed/Active	12/17/2015	DS140S6FBN	Bradford White	\$ 1,075.00	\$ 11.47
20490	Installed/Active	12/23/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20491	Installed/Active	12/30/2015	RG240S6N	Bradford White	\$ 850.00	\$ 13.12
20492	Installed/Active	12/22/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20493	Installed/Active	12/23/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20494	Installed/Active	12/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20495	Installed/Active	12/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20496	Installed/Active	12/28/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20497	Installed/Active	12/29/2015	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 18.60
20498	Installed/Active	12/30/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20499	Installed/Active	12/22/2015	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.33
20500	Installed/Active	12/26/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20501	Installed/Active	12/29/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20502	Installed/Active	12/23/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20503	Installed/Active	12/30/2015	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20504	Installed/Active	01/03/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20505	Installed/Active	12/31/2015	RG275H6N	Bradford White	\$ 1,900.00	\$ 43.94
20506	Installed/Active	01/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20507	Installed/Active	12/16/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20508	Installed/Active	12/22/2015	RG240T6N	Bradford White	\$ 850.00	\$ 13.12
20509	Installed/Active	12/31/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20510	Installed/Active	01/05/2016	RG240T6N	Bradford White	\$ 850.00	\$ 8.17
20511	Installed/Active	01/04/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
20512	Installed/Active	01/07/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20513	Installed/Active	01/04/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
20514	Installed/Active	01/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20515	Installed/Active	12/14/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
20516	Installed/Active	01/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20517	Installed/Active	12/15/2015	M2XR504T6FBN	Bradford White	\$ 1,125.00	\$ 21.27
20518	Installed/Active	01/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20519	Installed/Active	01/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20520	Installed/Active	01/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20521	Installed/Active	01/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20522	Installed/Active	01/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20523	Installed/Active	01/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20524	Installed/Active	01/06/2019	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
20525	Installed/Active	12/21/2015	RG250T6N	Bradford White	\$ 850.00	\$ 6.33
20526	Installed/Active	01/07/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20527	Installed/Active	01/05/2016	M440T6FBN	Bradford White	\$ 850.00	\$ 8.17
20528	Installed/Active	12/17/2015	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20529	Installed/Active	12/31/2015	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20530	Installed/Active	12/31/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20531	Installed/Active	01/06/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20532	Installed/Active	01/12/2016	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20533	Installed/Active	01/08/2016	MI403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20534	Installed/Active	01/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20535	Installed/Active	01/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20536	Installed/Active	01/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20537	Installed/Active	01/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20538	Installed/Active	01/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20539	Installed/Active	01/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20540	Installed/Active	01/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20541	Installed/Active	01/17/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20542	Installed/Active	01/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20543	Installed/Active	01/14/2016	DS150S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
20544	Installed/Active	01/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20545	Installed/Active	01/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20546	Installed/Active	01/22/2016	RG240T6N	BRADFORD-WHITE	\$ 850.00	\$ 8.17
20547	Installed/Active	01/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20548	Installed/Active	01/21/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20549	Installed/Active	12/24/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20550	Installed/Active	12/30/2015	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
20551	Installed/Active	01/22/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 8.17
20552	Installed/Active	01/19/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
20553	Installed/Active	01/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20554	Installed/Active	01/04/2016	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20555	Installed/Active	01/11/2016	PGR50	AO SMITH	\$ 850.00	\$ 13.41
20556	Installed/Active	01/13/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
20557	Installed/Active	01/13/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20558	Installed/Active	01/15/2016	PROG5036NRU60DV	RUUD	\$ 1,150.00	\$ 18.60
20559	Installed/Active	12/18/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.33
20560	Installed/Active	01/22/2016	G76200	RUUD	\$ 3,350.00	\$ 69.94
20561	Installed/Active	01/20/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
20562	Installed/Active	01/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20563	Installed/Active	01/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20564	Installed/Active	01/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20565	Installed/Active	01/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20566	Installed/Active	01/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20567	Installed/Active	01/20/2016	M440T6FBN	Bradford White	\$ 850.00	\$ 13.41
20568	Installed/Active	01/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20569	Installed/Active	01/21/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20570	Installed/Active	01/25/2016	RG2D40S6N	Bradford White	\$ 850.00	\$ 13.41
20571	Installed/Active	01/25/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
20572	Installed/Active	01/24/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20573	Installed/Active	01/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20574	Installed/Active	01/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20575	Installed/Active	01/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20576	Installed/Active	01/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20577	Installed/Active	01/12/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20578	Installed/Active	01/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20579	Installed/Active	01/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20580	Installed/Active	01/19/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20581	Installed/Active	01/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20582	Installed/Active	01/20/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20583	Installed/Active	01/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20584	Installed/Active	01/25/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20585	Installed/Active	12/29/2015	MI40T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.12
20586	Installed/Active	01/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20587	Installed/Active	01/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20588	Installed/Active	01/25/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20589	Installed/Active	01/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20590	Installed/Active	01/26/2016	RG250H6N	BRADFORD WHITE	\$ 500.00	\$ 21.74
20591	Installed/Active	01/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20592	Installed/Active	01/27/2016	G76200	RHEEM	\$ 3,360.00	\$ 60.13
20593	Installed/Active	12/23/2015	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 58.84
20594	Installed/Active	12/28/2015	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 43.94
20595	Installed/Active	01/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20596	Installed/Active	01/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20597	Installed/Active	01/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20598	Installed/Active	01/27/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.47
20599	Installed/Active	01/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20600	Installed/Active	01/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20601	Installed/Active	01/26/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20602	Installed/Active	01/29/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
20603	Installed/Active	02/04/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20604	Installed/Active	01/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20605	Installed/Active	01/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20606	Installed/Active	01/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20607	Installed/Active	01/30/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20608	Installed/Active	02/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20609	Installed/Active	02/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20610	Installed/Active	02/03/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20611	Installed/Active	02/04/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20612	Installed/Active	02/03/2016	M430T6FBN	Bradford White	\$ 850.00	\$ 6.47
20613	Installed/Active	02/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20614	Installed/Active	02/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20615	Installed/Active	02/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20616	Installed/Active	02/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20617	Installed/Active	02/06/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20618	Installed/Active	02/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20619	Installed/Active	02/01/2016	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20620	Installed/Active	02/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20621	Installed/Active	02/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20622	Installed/Active	02/03/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20623	Installed/Active	02/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20624	Installed/Active	02/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20625	Installed/Active	02/06/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20626	Installed/Active	02/05/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20627	Installed/Active	02/09/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
20628	Installed/Active	02/06/2016	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20629	Installed/Active	02/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20630	Installed/Active	02/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20631	Installed/Active	02/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20632	Installed/Active	02/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20633	Installed/Active	02/02/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20634	Installed/Active	02/09/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20635	Installed/Active	01/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20636	Installed/Active	01/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20637	Installed/Active	01/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20638	Installed/Active	01/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20639	Installed/Active	02/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20640	Installed/Active	01/16/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20641	Installed/Active	01/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20642	Installed/Active	01/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20643	Installed/Active	01/26/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20644	Installed/Active	01/26/2016	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
20645	Installed/Active	01/28/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20646	Installed/Active	01/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20647	Installed/Active	01/31/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20648	Installed/Active	02/03/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20649	Installed/Active	02/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20650	Installed/Active	02/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20651	Installed/Active	01/28/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
20652	Installed/Active	02/08/2016	PH13080	PHOENIX	\$ 3,350.00	\$ 69.94
20653	Installed/Active	01/12/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
20654	Installed/Active	02/09/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
20655	Installed/Active	02/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20656	Installed/Active	02/11/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20657	Installed/Active	02/12/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20658	Installed/Active	02/17/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20659	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20660	Installed/Active	02/18/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20661	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20662	Installed/Active	02/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20663	Installed/Active	02/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20664	Installed/Active	02/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20665	Installed/Active	02/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20666	Installed/Active	02/16/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20667	Installed/Active	02/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20668	Installed/Active	02/17/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20669	Installed/Active	02/17/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20670	Installed/Active	02/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20671	Installed/Active	02/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20672	Installed/Active	02/17/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
20673	Installed/Active	02/18/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20674	Installed/Active	02/23/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20675	Installed/Active	02/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20676	Installed/Active	02/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20677	Installed/Active	02/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20678	Installed/Active	02/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20679	Installed/Active	02/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20680	Installed/Active	02/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20681	Installed/Active	02/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20682	Installed/Active	02/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20683	Installed/Active	02/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20684	Installed/Active	02/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20685	Installed/Active	01/08/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20686	Installed/Active	01/26/2016	M1403S6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20687	Installed/Active	02/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20688	Installed/Active	02/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20689	Installed/Active	02/10/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20690	Installed/Active	02/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20691	Installed/Active	02/10/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20692	Installed/Active	02/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20693	Installed/Active	02/11/2016	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20694	Installed/Active	02/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20695	Installed/Active	02/11/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20696	Installed/Active	02/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20697	Installed/Active	02/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20698	Installed/Active	02/12/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20699	Installed/Active	02/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20700	Installed/Active	02/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20701	Installed/Active	02/15/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20702	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20703	Installed/Active	02/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20704	Installed/Active	02/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20705	Installed/Active	02/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20706	Installed/Active	02/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20707	Installed/Active	02/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20708	Installed/Active	02/19/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20709	Installed/Active	02/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20710	Installed/Active	02/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20711	Installed/Active	03/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20712	Installed/Active	03/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20713	Installed/Active	03/03/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20714	Installed/Active	03/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20715	Installed/Active	03/06/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20716	Installed/Active	01/27/2016	M175S6FBN	BRADFORD WHITE	\$ 3,350.00	\$ 60.13
20717	Installed/Active	02/17/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20718	Installed/Active	02/19/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
20719	Installed/Active	02/19/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20720	Installed/Active	03/02/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20721	Installed/Active	03/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20722	Installed/Active	03/02/2016	RG2DV40S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
20723	Installed/Active	03/02/2016	RG2DV40S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
20724	Installed/Active	03/07/2016	PROG4038NRH62	RUUD	\$ 850.00	\$ 13.41
20725	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20726	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20727	Installed/Active	03/07/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20728	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20729	Installed/Active	02/23/2016	41XR40	RHEEM	\$ 850.00	\$ 13.41
20730	Installed/Active	02/25/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20731	Installed/Active	03/03/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20732	Installed/Active	02/11/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20733	Installed/Active	01/24/2016	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 8.17
20734	Installed/Active	01/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20735	Installed/Active	02/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20736	Installed/Active	02/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20737	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20738	Installed/Active	02/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20739	Installed/Active	02/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20740	Installed/Active	02/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20741	Installed/Active	02/12/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
20742	Installed/Active	02/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20743	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20744	Installed/Active	02/18/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20745	Installed/Active	02/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20746	Installed/Active	02/23/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20747	Installed/Active	02/23/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20748	Installed/Active	02/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20749	Installed/Active	02/25/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20750	Installed/Active	02/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20751	Installed/Active	02/23/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20752	Installed/Active	02/23/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20753	Installed/Active	02/24/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20754	Installed/Active	02/24/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20755	Installed/Active	03/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20756	Installed/Active	02/02/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20757	Installed/Active	03/01/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20758	Installed/Active	02/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20759	Installed/Active	02/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20760	Installed/Active	02/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20761	Installed/Active	02/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20762	Installed/Active	02/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20763	Installed/Active	02/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20764	Installed/Active	03/08/2016	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 8.17
20765	Installed/Active	03/08/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20766	Installed/Active	03/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20767	Installed/Active	03/14/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20768	Installed/Active	03/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20769	Installed/Active	03/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20770	Installed/Active	03/15/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20771	Installed/Active	03/15/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20772	Installed/Active	03/15/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20773	Installed/Active	03/15/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 13.41
20774	Installed/Active	03/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20775	Installed/Active	03/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20776	Installed/Active	03/04/2016	PH19980	PHOENIX	\$ 3,350.00	\$ 69.94
20777	Installed/Active	03/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20778	Installed/Active	03/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20779	Installed/Active	03/06/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20780	Installed/Active	03/08/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20781	Installed/Active	03/08/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20782	Installed/Active	03/09/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20783	Installed/Active	03/08/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20784	Installed/Active	03/08/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20785	Installed/Active	01/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20786	Installed/Active	03/01/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
20787	Installed/Active	03/04/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20788	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20789	Installed/Active	03/11/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20790	Installed/Active	03/11/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20791	Installed/Active	03/11/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20792	Installed/Active	04/01/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20793	Installed/Active	03/16/2016	M2XR504T6FBN	BRADFORD WHITE	\$ 1,125.00	\$ 21.74
20794	Installed/Active	03/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20795	Installed/Active	03/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20796	Installed/Active	03/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20797	Installed/Active	03/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20798	Installed/Active	03/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20799	Installed/Active	03/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20800	Installed/Active	03/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20801	Installed/Active	03/01/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
20802	Installed/Active	03/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20803	Installed/Active	03/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20804	Installed/Active	03/04/2016	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 44.90
20805	Installed/Active	03/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20806	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20807	Installed/Active	03/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20808	Installed/Active	03/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20809	Installed/Active	03/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20810	Installed/Active	03/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20811	Installed/Active	03/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20812	Installed/Active	03/23/2016	RG250T6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.74

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20813	Installed/Active	03/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 18.60
20814	Installed/Active	03/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20815	Installed/Active	03/25/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20816	Installed/Active	03/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20817	Installed/Active	03/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20818	Installed/Active	03/25/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20819	Installed/Active	03/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20820	Installed/Active	03/25/2016	FSG50	AO SMITH	\$ 850.00	\$ 13.41
20821	Installed/Active	03/28/2016	PROG5036NURU60DV	RUUD	\$ 1,075.00	\$ 19.01
20822	Installed/Active	03/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20823	Installed/Active	03/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20824	Installed/Active	03/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20825	Installed/Active	03/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20826	Installed/Active	03/30/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20827	Installed/Active	03/30/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20828	Installed/Active	03/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20829	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20830	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20831	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20832	Installed/Active	03/31/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20833	Installed/Active	03/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 18.60
20834	Installed/Active	03/10/2016	PROG5036NURU60DV	RUUD	\$ 1,075.00	\$ 19.01
20835	Installed/Active	03/10/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20836	Installed/Active	03/11/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20837	Installed/Active	03/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20838	Installed/Active	03/15/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20839	Installed/Active	03/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20840	Installed/Active	03/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20841	Installed/Active	03/19/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20842	Installed/Active	03/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20843	Installed/Active	03/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20844	Installed/Active	04/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20845	Installed/Active	04/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20846	Installed/Active	03/02/2016	FSG50	AO SMITH	\$ 850.00	\$ 13.41
20847	Installed/Active	03/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20848	Installed/Active	03/11/2016	PROG5036NURU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20849	Installed/Active	03/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20850	Installed/Active	03/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20851	Installed/Active	03/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20852	Installed/Active	03/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20853	Installed/Active	03/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20854	Installed/Active	03/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20855	Installed/Active	03/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20856	Installed/Active	03/22/2016	PROG30S30NRU63	RUUD/RHEEM	\$ 850.00	\$ 6.47
20857	Installed/Active	03/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20858	Installed/Active	03/18/2016	G91-200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20859	Installed/Active	03/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20860	Installed/Active	03/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20861	Installed/Active	03/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20862	Installed/Active	03/23/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20863	Installed/Active	04/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20864	Installed/Active	04/05/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20865	Installed/Active	04/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20866	Installed/Active	04/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20867	Installed/Active	04/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20868	Installed/Active	04/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20869	Installed/Active	04/08/2016	PROG5036NURU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20870	Installed/Active	04/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20871	Installed/Active	03/26/2016	PROG5036NURU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20872	Installed/Active	03/29/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20873	Installed/Active	03/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20874	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20875	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20876	Installed/Active	03/31/2016	PROG2932NRU63	RUUD/RHEEM	\$ 850.00	\$ 6.47
20877	Installed/Active	03/31/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20878	Installed/Active	04/01/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20879	Installed/Active	03/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20880	Installed/Active	02/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20881	Installed/Active	03/10/2016	M440T6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20882	Installed/Active	03/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20883	Installed/Active	03/13/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
20884	Installed/Active	03/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20885	Installed/Active	03/22/2016	PROG5036NURU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20886	Installed/Active	03/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20887	Installed/Active	03/24/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20888	Installed/Active	03/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20889	Installed/Active	03/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20890	Installed/Active	03/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20891	Installed/Active	04/01/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20892	Installed/Active	04/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20893	Installed/Active	04/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20894	Installed/Active	02/18/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20895	Installed/Active	04/08/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
20896	Installed/Active	04/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20897	Installed/Active	04/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
20898	Installed/Active	04/05/2015	RG240S6N	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20899	Installed/Active	04/07/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
20900	Installed/Active	03/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20901	Installed/Active	03/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20902	Installed/Active	03/30/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20903	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20904	Installed/Active	04/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20905	Installed/Active	04/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20906	Installed/Active	04/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20907	Installed/Active	04/05/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20908	Installed/Active	04/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20909	Installed/Active	04/08/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20910	Installed/Active	04/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20911	Installed/Active	04/06/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20912	Installed/Active	04/06/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
20913	Installed/Active	04/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20914	Installed/Active	04/12/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20915	Installed/Active	03/29/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20916	Installed/Active	04/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20917	Installed/Active	04/18/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20918	Installed/Active	04/19/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20919	Installed/Active	04/18/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20920	Installed/Active	04/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20921	Installed/Active	04/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20922	Installed/Active	04/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20923	Installed/Active	04/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20924	Installed/Active	04/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20925	Installed/Active	04/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20926	Installed/Active	04/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20927	Installed/Active	04/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20928	Installed/Active	04/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20929	Installed/Active	04/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20930	Installed/Active	04/12/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20931	Installed/Active	04/12/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20932	Installed/Active	04/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20933	Installed/Active	04/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20934	Installed/Active	04/08/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 11.72
20935	Installed/Active	03/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20936	Installed/Active	04/14/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20937	Installed/Active	04/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20938	Installed/Active	04/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20939	Installed/Active	04/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20940	Installed/Active	04/10/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
20941	Installed/Active	02/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20942	Installed/Active	04/19/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
20943	Installed/Active	04/21/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20944	Installed/Active	03/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20945	Installed/Active	04/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20946	Installed/Active	04/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20947	Installed/Active	03/19/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20948	Installed/Active	04/18/2016	G82156	RUUD/RHEEM	\$ 3,360.00	\$ 60.13
20949	Installed/Active	04/20/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20950	Installed/Active	04/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20951	Installed/Active	04/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20952	Installed/Active	04/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20953	Installed/Active	04/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20954	Installed/Active	04/19/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20955	Installed/Active	04/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20956	Installed/Active	04/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
20957	Installed/Active	03/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20958	Installed/Active	03/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20959	Installed/Active	04/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20960	Installed/Active	04/07/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20961	Installed/Active	04/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20962	Installed/Active	04/20/2016	PROG2932NRU63	RUUD/RHEEM	\$ 850.00	\$ 6.47
20963	Installed/Active	04/23/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20964	Installed/Active	04/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20965	Installed/Active	04/19/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20966	Installed/Active	04/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20967	Installed/Active	04/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20968	Installed/Active	04/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20969	Installed/Active	04/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20970	Installed/Active	04/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20971	Installed/Active	04/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20972	Installed/Active	04/27/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20973	Installed/Active	04/25/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20974	Installed/Active	04/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20975	Installed/Active	04/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20976	Installed/Active	04/10/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20977	Installed/Active	04/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20978	Installed/Active	04/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20979	Installed/Active	06/02/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
20980	Installed/Active	04/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20981	Installed/Active	04/29/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20982	Installed/Active	04/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20983	Installed/Active	04/30/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20984	Installed/Active	04/21/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
20985	Installed/Active	04/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20986	Installed/Active	04/20/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 11.72
20987	Installed/Active	04/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20988	Installed/Active	04/28/2016	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
20989	Installed/Active	04/28/2016	PROG5036NRU60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.01
20990	Installed/Active	04/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20991	Installed/Active	04/28/2016	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20992	Installed/Active	04/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20993	Installed/Active	04/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20994	Installed/Active	06/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
20995	Installed/Active	05/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20996	Installed/Active	04/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20997	Installed/Active	05/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20998	Installed/Active	04/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
20999	Installed/Active	04/05/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21000	Installed/Active	04/18/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21001	Installed/Active	04/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21002	Installed/Active	05/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21003	Installed/Active	04/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21004	Installed/Active	05/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21005	Installed/Active	04/18/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21006	Installed/Active	05/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21007	Installed/Active	06/16/2016	RG240T6N	Bradford White	\$ 850.00	\$ 8.17
21008	Installed/Active	05/17/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21009	Installed/Active	05/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21010	Installed/Active	05/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21011	Installed/Active	05/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21012	Installed/Active	04/27/2016	PROG4038NRH62	RUUD	\$ 850.00	\$ 13.41
21013	Installed/Active	07/09/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21014	Installed/Active	05/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21015	Installed/Active	05/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21016	Installed/Active	04/14/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21017	Installed/Active	04/30/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21018	Installed/Active	04/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21019	Installed/Active	04/20/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21020	Installed/Active	05/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21021	Installed/Active	05/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21022	Installed/Active	05/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21023	Installed/Active	04/28/2016	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21024	Installed/Active	05/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21025	Installed/Active	07/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21026	Installed/Active	04/23/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21027	Installed/Active	05/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21028	Installed/Active	05/04/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21029	Installed/Active	05/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21030	Installed/Active	05/12/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21031	Installed/Active	05/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21032	Installed/Active	05/26/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21033	Installed/Active	05/26/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21034	Installed/Active	05/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21035	Installed/Active	05/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21036	Installed/Active	05/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21037	Installed/Active	05/25/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21038	Installed/Active	05/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21039	Installed/Active	05/24/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21040	Installed/Active	05/16/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21041	Installed/Active	05/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21042	Installed/Active	02/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21043	Installed/Active	05/16/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21044	Installed/Active	05/26/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21045	Installed/Active	05/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21046	Installed/Active	05/31/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21047	Installed/Active	05/26/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21048	Installed/Active	05/31/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21049	Installed/Active	05/21/2016	RG2DV40S6N	BRADFORD WHITE	\$ 500.00	\$ 21.74
21050	Installed/Active	06/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21051	Installed/Active	05/31/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21052	Installed/Active	06/16/2015	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
21053	Installed/Active	05/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21054	Installed/Active	05/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21055	Installed/Active	05/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21056	Installed/Active	05/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21057	Installed/Active	05/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21058	Installed/Active	05/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21059	Installed/Active	05/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21060	Installed/Active	06/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21061	Installed/Active	06/01/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21062	Installed/Active	06/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21063	Installed/Active	06/04/2016	M2XR504T6FBN	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21064	Installed/Active	06/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21065	Installed/Active	06/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21066	Installed/Active	06/07/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21067	Installed/Active	05/28/2016	RG2DV40S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21068	Installed/Active	02/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21069	Installed/Active	05/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21070	Installed/Active	06/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21071	Installed/Active	05/12/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21072	Installed/Active	05/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21073	Installed/Active	05/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21074	Installed/Active	04/26/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21075	Installed/Active	05/11/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21076	Installed/Active	05/10/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21077	Installed/Active	07/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21078	Installed/Active	05/08/2016	PROG5036NRU60DV	Ruud	\$ 1,075.00	\$ 19.01
21079	Installed/Active	05/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21080	Installed/Active	05/09/2016	PROG5036NRU60DV	STATE	\$ 1,075.00	\$ 19.01
21081	Installed/Active	05/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21082	Installed/Active	05/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21083	Installed/Active	05/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21084	Installed/Active	08/01/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21085	Installed/Active	07/11/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21086	Installed/Active	04/14/2016	G76200	Ruud/Rheem	\$ 3,350.00	\$ 69.94
21087	Installed/Active	04/14/2016	G76200	Ruud/Rheem	\$ 3,350.00	\$ 69.94
21088	Installed/Active	06/08/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21089	Installed/Active	05/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21090	Installed/Active	05/12/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21091	Installed/Active	05/13/2016	PRX50	STATE	\$ 1,075.00	\$ 19.01
21092	Installed/Active	06/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21093	Installed/Active	06/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21094	Installed/Active	06/08/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21095	Installed/Active	06/14/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21096	Installed/Active	06/08/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21097	Installed/Active	06/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21098	Installed/Active	06/13/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21099	Installed/Active	06/02/2016	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21100	Installed/Active	06/16/2016	PROG5036NRU60DV	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21101	Installed/Active	06/14/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21102	Installed/Active	05/17/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21103	Installed/Active	05/10/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21104	Installed/Active	05/13/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21105	Installed/Active	05/17/2016	RG275H6N	Bradford White	\$ 1,900.00	\$ 44.90
21106	Installed/Active	05/06/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21107	Installed/Active	05/17/2016	RG250T6N	Bradford White	\$ 1,150.00	\$ 18.60
21108	Installed/Active	05/18/2016	PROG5036NRU60DV	Ruud	\$ 1,075.00	\$ 11.72
21109	Installed/Active	05/18/2016	PGR50	AO SMITH	\$ 850.00	\$ 13.41
21110	Installed/Active	06/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21111	Installed/Active	06/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21112	Installed/Active	06/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21113	Installed/Active	06/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21114	Installed/Active	06/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21115	Installed/Active	06/13/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21116	Installed/Active	06/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21117	Installed/Active	06/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21118	Installed/Active	06/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21119	Installed/Active	06/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21120	Installed/Active	06/17/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21121	Installed/Active	06/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21122	Installed/Active	06/17/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21123	Installed/Active	06/17/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21124	Installed/Active	06/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21125	Installed/Active	06/23/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21126	Installed/Active	07/01/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21127	Installed/Active	07/01/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21128	Installed/Active	07/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21129	Installed/Active	07/01/2016	PROG5036NRU60	RUUD RHEEM	\$ 1,075.00	\$ 19.01
21130	Installed/Active	07/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21131	Installed/Active	06/30/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21132	Installed/Active	06/30/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21133	Installed/Active	06/16/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21134	Installed/Active	06/30/2016	G75125	RUUD RHEEM	\$ 1,900.00	\$ 44.90
21135	Installed/Active	06/28/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21136	Installed/Active	06/28/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21137	Installed/Active	05/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21138	Installed/Active	05/13/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21139	Installed/Active	05/12/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21140	Installed/Active	05/16/2016	PGR50	AO SMITH	\$ 850.00	\$ 13.41
21141	Installed/Active	05/14/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21142	Installed/Active	05/16/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21143	Installed/Active	05/16/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21144	Installed/Active	05/17/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21145	Installed/Active	05/17/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21146	Installed/Active	05/17/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21147	Installed/Active	05/17/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21148	Installed/Active	05/09/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21149	Installed/Active	05/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21150	Installed/Active	05/16/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21151	Installed/Active	05/23/2016	G82156	Ruud/Rheem	\$ 3,350.00	\$ 60.13
21152	Installed/Active	05/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21153	Installed/Active	05/20/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21154	Installed/Active	05/20/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21155	Installed/Active	05/17/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21156	Installed/Active	05/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21157	Installed/Active	05/04/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21158	Installed/Active	04/04/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21159	Installed/Active	05/24/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21160	Installed/Active	06/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21161	Installed/Active	06/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21162	Installed/Active	06/16/2016	G91200	Ruud/Rheem	\$ 3,350.00	\$ 69.94
21163	Installed/Active	05/19/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21164	Installed/Active	05/20/2016	PROG5036NRU60	Ruud/Rheem	\$ 850.00	\$ 13.41
21165	Installed/Active	05/19/2016	RG250T6N	Bradford White	\$ 1,150.00	\$ 18.60
21166	Installed/Active	05/16/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21167	Installed/Active	05/22/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21168	Installed/Active	05/12/2016	G91200	Ruud/Rheem	\$ 3,350.00	\$ 69.94
21169	Installed/Active	05/23/2016	G82156	Ruud/Rheem	\$ 3,350.00	\$ 60.13
21170	Installed/Active	05/19/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21171	Installed/Active	05/20/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21172	Installed/Active	05/24/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21173	Installed/Active	05/24/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21174	Installed/Active	05/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21175	Installed/Active	05/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21176	Installed/Active	05/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21177	Installed/Active	06/29/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21178	Installed/Active	06/29/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21179	Installed/Active	06/29/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21180	Installed/Active	06/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21181	Installed/Active	06/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21182	Installed/Active	06/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21183	Installed/Active	06/03/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21184	Installed/Active	06/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21185	Installed/Active	06/20/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21186	Installed/Active	06/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21187	Installed/Active	06/09/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21188	Installed/Active	06/27/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21189	Installed/Active	06/30/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21190	Installed/Active	06/25/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21191	Installed/Active	06/25/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21192	Installed/Active	06/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21193	Installed/Active	06/25/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21194	Installed/Active	06/27/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21195	Installed/Active	06/22/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21196	Installed/Active	06/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21197	Installed/Active	06/21/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21198	Installed/Active	06/20/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21199	Installed/Active	06/30/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21200	Installed/Active	06/30/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21201	Installed/Active	07/01/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21202	Installed/Active	07/06/2016	RG240T6N	Bradford White	\$ 850.00	\$ 8.17
21203	Installed/Active	07/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21204	Installed/Active	03/11/2015	M45036FBN	RUUD	\$ 850.00	\$ 13.12
21205	Installed/Active	07/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21206	Installed/Active	07/05/2016	RG250L6N	Bradford White	\$ 850.00	\$ 13.41
21207	Installed/Active	07/01/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21208	Installed/Active	07/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21209	Installed/Active	06/27/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21210	Installed/Active	07/05/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 11.72
21211	Installed/Active	07/05/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21212	Installed/Active	07/05/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21213	Installed/Active	07/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21214	Installed/Active	07/02/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21215	Installed/Active	07/06/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21216	Installed/Active	07/07/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21217	Installed/Active	07/06/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21218	Installed/Active	05/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21219	Installed/Active	07/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21220	Installed/Active	07/03/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21221	Installed/Active	05/20/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21222	Installed/Active	05/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21223	Installed/Active	06/07/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21224	Installed/Active	06/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21225	Installed/Active	06/16/2016	RG240S6N	Bradford White	\$ 850.00	\$ 6.47
21226	Installed/Active	06/20/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21227	Installed/Active	06/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21228	Installed/Active	06/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21229	Installed/Active	06/15/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21230	Installed/Active	06/16/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21231	Installed/Active	06/07/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21232	Installed/Active	06/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21233	Installed/Active	05/28/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21234	Installed/Active	04/28/2016	PROG2932NRU62	Ruud/Rheem	\$ 850.00	\$ 8.17
21235	Installed/Active	05/21/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21236	Installed/Active	07/07/2016	RG240S6N	Bradford White	\$ 850.00	\$ 6.47
21237	Installed/Active	07/07/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21238	Installed/Active	08/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21239	Installed/Active	07/06/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21240	Installed/Active	07/26/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21241	Installed/Active	07/15/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21242	Installed/Active	10/21/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21243	Installed/Active	07/30/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21244	Installed/Active	07/30/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21245	Installed/Active	07/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21246	Installed/Active	07/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21247	Installed/Active	07/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21248	Installed/Active	08/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21249	Installed/Active	08/17/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21250	Installed/Active	08/16/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21251	Installed/Active	08/05/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 11.72
21252	Installed/Active	08/05/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21253	Installed/Active	08/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21254	Installed/Active	08/03/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21255	Installed/Active	08/03/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21256	Installed/Active	08/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21257	Installed/Active	12/12/2015	RG250T6N	Bradford White	\$ 850.00	\$ 13.12
21258	Installed/Active	06/14/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21259	Installed/Active	07/03/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21260	Installed/Active	03/21/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
21261	Installed/Active	03/21/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
21262	Installed/Active	07/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21263	Installed/Active	07/13/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21264	Installed/Active	07/13/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21265	Installed/Active	03/15/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21266	Installed/Active	05/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21267	Installed/Active	06/19/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21268	Installed/Active	07/11/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21269	Installed/Active	07/13/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21270	Installed/Active	07/14/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21271	Installed/Active	07/14/2016	FSG50	AO SMITH	\$ 850.00	\$ 13.41
21272	Installed/Active	07/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21273	Installed/Active	07/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21274	Installed/Active	07/15/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21275	Installed/Active	07/16/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21276	Installed/Active	07/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21277	Installed/Active	07/14/2016	RG275H6N	Bradford White	\$ 1,900.00	\$ 44.90
21278	Installed/Active	07/14/2016	RG275H6N	Bradford White	\$ 1,900.00	\$ 44.90
21279	Installed/Active	06/24/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21280	Installed/Active	07/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21281	Installed/Active	07/02/2016	RG240T6N	Bradford White	\$ 850.00	\$ 6.47
21282	Installed/Active	07/15/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21283	Installed/Active	07/15/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21284	Installed/Active	07/12/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21285	Installed/Active	07/12/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21286	Installed/Active	07/12/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21287	Installed/Active	07/11/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 13.41
21288	Installed/Active	07/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21289	Installed/Active	07/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21290	Installed/Active	07/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21291	Installed/Active	07/02/2016	RG240S6N	BRADFORD-WHITE	\$ 850.00	\$ 13.41
21292	Installed/Active	07/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21293	Installed/Active	07/11/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21294	Installed/Active	07/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21295	Installed/Active	07/09/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21296	Installed/Active	07/06/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21297	Installed/Active	07/07/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21298	Installed/Active	06/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21299	Installed/Active	06/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21300	Installed/Active	06/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21301	Installed/Active	06/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21302	Installed/Active	05/27/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.01
21303	Installed/Active	06/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21304	Installed/Active	06/17/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21305	Installed/Active	06/21/2016	RG275H6N	BRADFORD WHITE	\$ 3,350.00	\$ 69.94
21306	Installed/Active	07/29/2016	PROG5038NRU60	RUUD	\$ 850.00	\$ 13.41
21307	Installed/Active	07/23/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21308	Installed/Active	08/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21309	Installed/Active	07/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21310	Installed/Active	07/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21311	Installed/Active	07/18/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21312	Installed/Active	07/16/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21313	Installed/Active	07/16/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21314	Installed/Active	07/11/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21315	Installed/Active	07/18/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21316	Installed/Active	07/25/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21317	Installed/Active	07/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21318	Installed/Active	07/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21319	Installed/Active	07/27/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21320	Installed/Active	07/21/2016	PROG5036NRU60DV	RUUD RHEEM	\$ 1,075.00	\$ 11.72
21321	Installed/Active	07/25/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21322	Installed/Active	07/20/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21323	Installed/Active	07/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21324	Installed/Active	08/02/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21325	Installed/Active	08/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21326	Installed/Active	08/02/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21327	Installed/Active	08/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21328	Installed/Active	08/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21329	Installed/Active	08/02/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21330	Installed/Active	07/08/2016	G91200	RUUD RHEEM	\$ 3,350.00	\$ 69.94
21331	Installed/Active	07/08/2016	G91200	RUUD RHEEM	\$ 3,350.00	\$ 69.94
21332	Installed/Active	04/04/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
21333	Installed/Active	07/28/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21334	Installed/Active	07/26/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21335	Installed/Active	07/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21336	Installed/Active	07/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21337	Installed/Active	07/25/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21338	Installed/Active	07/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21339	Installed/Active	07/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21340	Installed/Active	07/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21341	Installed/Active	07/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21342	Installed/Active	07/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21343	Installed/Active	07/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21344	Installed/Active	07/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21345	Installed/Active	07/26/2016	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 13.41
21346	Installed/Active	07/26/2016	PROG5038NRU60	RUUD	\$ 1,075.00	\$ 19.01
21347	Installed/Active	07/26/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21348	Installed/Active	07/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21349	Installed/Active	07/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21350	Installed/Active	07/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21351	Installed/Active	07/14/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21352	Installed/Active	07/14/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21353	Installed/Active	08/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21354	Installed/Active	08/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21355	Installed/Active	08/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21356	Installed/Active	08/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21357	Installed/Active	08/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21358	Installed/Active	08/09/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 13.41
21359	Installed/Active	07/27/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.47
21360	Installed/Active	08/11/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21361	Installed/Active	08/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21362	Installed/Active	08/12/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21363	Installed/Active	07/29/2016	G76200	RUUD	\$ 3,350.00	\$ 69.94
21364	Installed/Active	07/28/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21365	Installed/Active	08/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21366	Installed/Active	08/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21367	Installed/Active	07/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21368	Installed/Active	07/28/2016	RG240S6N	Bradford White	\$ 850.00	\$ 13.41
21369	Installed/Active	08/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21370	Installed/Active	07/20/2016	21VR40	RHEEM	\$ 850.00	\$ 6.47
21371	Installed/Active	07/20/2016	PROG2932NRU62	Ruud/Rheem	\$ 850.00	\$ 6.47
21372	Installed/Active	07/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21373	Installed/Active	07/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21374	Installed/Active	07/28/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21375	Installed/Active	07/31/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21376	Installed/Active	07/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21377	Installed/Active	07/20/2016	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 13.41
21378	Installed/Active	07/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21379	Installed/Active	07/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21380	Installed/Active	08/04/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21381	Installed/Active	07/11/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21382	Installed/Active	07/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21383	Installed/Active	07/14/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 8.17
21384	Installed/Active	07/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21385	Installed/Active	07/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21386	Installed/Active	07/18/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21387	Installed/Active	08/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21388	Installed/Active	08/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21389	Installed/Active	08/06/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21390	Installed/Active	08/04/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21391	Installed/Active	07/27/2016	RG240S6N	Bradford White	\$ 350.00	\$ 16.51
21392	Installed/Active	07/21/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21393	Installed/Active	07/21/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21394	Installed/Active	07/22/2016	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.41
21395	Installed/Active	07/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21396	Installed/Active	07/24/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21397	Installed/Active	07/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21398	Installed/Active	07/22/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21399	Installed/Active	07/25/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21400	Installed/Active	07/22/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21401	Installed/Active	08/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21402	Installed/Active	08/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21403	Installed/Active	08/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21404	Installed/Active	08/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21405	Installed/Active	08/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21406	Installed/Active	08/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21407	Installed/Active	08/11/2016	PROG5038NRU60	RUUD	\$ 1,075.00	\$ 19.01
21408	Installed/Active	08/12/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21409	Installed/Active	08/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21410	Installed/Active	08/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21411	Installed/Active	08/15/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21412	Installed/Active	08/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21413	Installed/Active	08/02/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21414	Installed/Active	08/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21415	Installed/Active	08/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21416	Installed/Active	08/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21417	Installed/Active	08/16/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 13.41
21418	Installed/Active	08/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21419	Installed/Active	06/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21420	Installed/Active	08/12/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21421	Installed/Active	08/22/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21422	Installed/Active	08/12/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.47
21423	Installed/Active	08/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21424	Installed/Active	08/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21425	Installed/Active	08/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21426	Installed/Active	08/23/2016	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21427	Installed/Active	08/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21428	Installed/Active	08/08/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21429	Installed/Active	08/08/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21430	Installed/Active	08/15/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21431	Installed/Active	08/19/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21432	Installed/Active	08/16/2016	PROG5036NRU60DV	Ruud/Rheem	\$ 1,075.00	\$ 19.01
21433	Installed/Active	08/13/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21434	Installed/Active	08/17/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21435	Installed/Active	08/17/2016	RG250L6N	Bradford White	\$ 850.00	\$ 6.47
21436	Installed/Active	08/12/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21437	Installed/Active	07/28/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21438	Installed/Active	08/12/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21439	Installed/Active	08/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21440	Installed/Active	08/05/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21441	Installed/Active	08/16/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21442	Installed/Active	08/18/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21443	Installed/Active	08/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21444	Installed/Active	08/19/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21445	Installed/Active	08/15/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21446	Installed/Active	07/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21447	Installed/Active	08/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21448	Installed/Active	08/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21449	Installed/Active	08/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21450	Installed/Active	08/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21451	Installed/Active	08/23/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21452	Installed/Active	08/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21453	Installed/Active	08/22/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21454	Installed/Active	08/25/2016	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.47
21455	Installed/Active	07/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21456	Installed/Active	08/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21457	Installed/Active	08/31/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21458	Installed/Active	08/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21459	Installed/Active	08/31/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21460	Installed/Active	08/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21461	Installed/Active	08/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21462	Installed/Active	08/30/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21463	Installed/Active	08/25/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21464	Installed/Active	08/29/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21465	Installed/Active	08/29/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21466	Installed/Active	08/29/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21467	Installed/Active	08/29/2016	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21468	Installed/Active	08/26/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
21469	Installed/Active	08/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21470	Installed/Active	08/20/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21471	Installed/Active	08/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21472	Installed/Active	08/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21473	Installed/Active	08/26/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21474	Installed/Active	08/26/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21475	Installed/Active	08/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21476	Installed/Active	08/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21477	Installed/Active	08/23/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21478	Installed/Active	08/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21479	Installed/Active	08/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21480	Installed/Active	08/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21481	Installed/Active	08/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21482	Installed/Active	08/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21483	Installed/Active	08/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21484	Installed/Active	07/26/2016	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.74
21485	Installed/Active	08/14/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21486	Installed/Active	07/17/2016	PH199119	PHOENIX	\$ 6,732.00	\$ 69.94
21487	Installed/Active	08/25/2016	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 44.90
21488	Installed/Active	09/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21489	Installed/Active	09/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21490	Installed/Active	08/22/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 8.17
21491	Installed/Active	08/16/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21492	Installed/Active	09/01/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21493	Installed/Active	09/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21494	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21495	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21496	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21497	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21498	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21499	Installed/Active	09/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21500	Installed/Active	09/02/2016	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21501	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21502	Installed/Active	09/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21503	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21504	Installed/Active	09/02/2016	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 44.90
21505	Installed/Active	09/13/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21506	Installed/Active	09/09/2016	G76200	RUUD	\$ 3,350.00	\$ 69.94
21507	Installed/Active	09/03/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21508	Installed/Active	07/30/2016	G76200	RUUD	\$ 3,350.00	\$ 69.94
21509	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21510	Installed/Active	08/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21511	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21512	Installed/Active	09/07/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21513	Installed/Active	09/06/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21514	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21515	Installed/Active	09/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21516	Installed/Active	09/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21517	Installed/Active	09/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21518	Installed/Active	09/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21519	Installed/Active	09/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21520	Installed/Active	09/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21521	Installed/Active	09/12/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21522	Installed/Active	09/10/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21523	Installed/Active	09/05/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21524	Installed/Active	09/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21525	Installed/Active	09/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21526	Installed/Active	09/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21527	Installed/Active	09/13/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21528	Installed/Active	09/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21529	Installed/Active	09/09/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 13.41
21530	Installed/Active	09/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21531	Installed/Active	09/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21532	Installed/Active	09/13/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21533	Installed/Active	09/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21534	Installed/Active	09/07/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21535	Installed/Active	09/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21536	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21537	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21538	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21539	Installed/Active	09/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21540	Installed/Active	09/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21541	Installed/Active	09/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21542	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21543	Installed/Active	09/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21544	Installed/Active	09/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21545	Installed/Active	09/10/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21546	Installed/Active	09/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21547	Installed/Active	09/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21548	Installed/Active	09/22/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21549	Installed/Active	09/29/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21550	Installed/Active	11/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21551	Installed/Active	06/29/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21552	Installed/Active	06/29/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21553	Installed/Active	06/29/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21554	Installed/Active	09/12/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21555	Installed/Active	09/12/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21556	Installed/Active	09/16/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21557	Installed/Active	08/09/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 13.41
21558	Installed/Active	09/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21559	Installed/Active	09/07/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21560	Installed/Active	09/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21561	Installed/Active	09/09/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 8.17
21562	Installed/Active	09/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21563	Installed/Active	09/09/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21564	Installed/Active	09/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21565	Installed/Active	09/12/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21566	Installed/Active	09/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21567	Installed/Active	09/20/2016	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21568	Installed/Active	09/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21569	Installed/Active	09/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21570	Installed/Active	09/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21571	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21572	Installed/Active	09/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21573	Installed/Active	09/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21574	Installed/Active	09/21/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
21575	Installed/Active	09/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21576	Installed/Active	09/13/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21577	Installed/Active	09/02/2016	RG250T6N	BRAD	\$ 850.00	\$ 13.41
21578	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21579	Installed/Active	09/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21580	Installed/Active	09/22/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21581	Installed/Active	09/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21582	Installed/Active	09/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21583	Installed/Active	09/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21584	Installed/Active	09/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21585	Installed/Active	10/20/2016	RG250H6N	Bradford White	\$ 1,150.00	\$ 18.60
21586	Installed/Active	09/27/2016	RG240S6N	Bradford White	\$ 850.00	\$ 6.47

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21587	Installed/Active	09/28/2016	RG240S6N	Bradford White	\$ 850.00	\$ 6.47
21588	Installed/Active	09/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21589	Installed/Active	09/29/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21590	Installed/Active	09/29/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21591	Installed/Active	09/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21592	Installed/Active	09/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21593	Installed/Active	09/16/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21594	Installed/Active	09/29/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21595	Installed/Active	09/29/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21596	Installed/Active	09/17/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21597	Installed/Active	10/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21598	Installed/Active	10/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21599	Installed/Active	10/06/2016	PROG5036NRU60	RUUD	\$ 850.00	\$ 13.41
21600	Installed/Active	10/01/2016	PROG5036NRU60DV	RHEEM	\$ 1,075.00	\$ 19.01
21601	Installed/Active	10/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21602	Installed/Active	10/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21603	Installed/Active	09/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21604	Installed/Active	09/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21605	Installed/Active	10/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21606	Installed/Active	10/04/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21607	Installed/Active	10/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21608	Installed/Active	10/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21609	Installed/Active	10/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21610	Installed/Active	10/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21611	Installed/Active	10/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21612	Installed/Active	10/13/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21613	Installed/Active	10/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21614	Installed/Active	10/18/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21615	Installed/Active	10/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21616	Installed/Active	10/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21617	Installed/Active	10/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21618	Installed/Active	10/07/2016	DS140S6FBN	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21619	Installed/Active	10/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21620	Installed/Active	10/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21621	Installed/Active	10/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21622	Installed/Active	10/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21623	Installed/Active	10/11/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21624	Installed/Active	09/30/2016	G76200	Rheem	\$ 3,350.00	\$ 69.94
21625	Installed/Active	10/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21626	Installed/Active	10/11/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21627	Installed/Active	10/12/2016	RG240T6N	Bradford White	\$ 850.00	\$ 13.41
21628	Installed/Active	10/06/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21629	Installed/Active	09/28/2016	RG250T6N	Bradford White	\$ 850.00	\$ 6.47
21630	Installed/Active	10/01/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
21631	Installed/Active	10/02/2016	RG250T6N	Bradford White	\$ 850.00	\$ 8.17
21632	Installed/Active	09/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21633	Installed/Active	09/26/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21634	Installed/Active	09/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21635	Installed/Active	09/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21636	Installed/Active	10/05/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21637	Installed/Active	10/07/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21638	Installed/Active	10/08/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21639	Installed/Active	10/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21640	Installed/Active	10/12/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21641	Installed/Active	10/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21642	Installed/Active	10/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21643	Installed/Active	10/13/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21644	Installed/Active	10/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21645	Installed/Active	10/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21646	Installed/Active	10/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21647	Installed/Active	10/14/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21648	Installed/Active	10/09/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21649	Installed/Active	10/12/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21650	Installed/Active	10/17/2016	RG250H6N	BRADFORD WHITE	\$ 500.00	\$ 21.74
21651	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21652	Installed/Active	10/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21653	Installed/Active	09/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21654	Installed/Active	10/21/2016	PROG5036NRH60DV	RUUD	\$ 1,075.00	\$ 19.01
21655	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21656	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21657	Installed/Active	10/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21658	Installed/Active	10/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21659	Installed/Active	10/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21660	Installed/Active	10/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21661	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21662	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21663	Installed/Active	10/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21664	Installed/Active	10/23/2016	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.74
21665	Installed/Active	10/19/2016	G82156	RUUD	\$ 3,350.00	\$ 60.13
21666	Installed/Active	10/18/2016	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.74
21667	Installed/Active	10/19/2016	PROG5036NRU60DV	RHEEM	\$ 1,075.00	\$ 19.01
21668	Installed/Active	10/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21669	Installed/Active	10/11/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21670	Installed/Active	10/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21671	Installed/Active	10/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21672	Installed/Active	10/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21673	Installed/Active	10/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21674	Installed/Active	10/25/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21675	Installed/Active	10/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21676	Installed/Active	10/25/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21677	Installed/Active	10/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21678	Installed/Active	10/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21679	Installed/Active	10/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21680	Installed/Active	10/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21681	Installed/Active	10/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21682	Installed/Active	10/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21683	Installed/Active	10/27/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21684	Installed/Active	10/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21685	Installed/Active	10/26/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21686	Installed/Active	10/26/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21687	Installed/Active	09/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21688	Installed/Active	09/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21689	Installed/Active	09/30/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21690	Installed/Active	10/31/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21691	Installed/Active	10/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21692	Installed/Active	10/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21693	Installed/Active	10/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21694	Installed/Active	10/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21695	Installed/Active	10/13/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21696	Installed/Active	10/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21697	Installed/Active	10/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21698	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21699	Installed/Active	10/22/2016	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 13.41
21700	Installed/Active	10/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21701	Installed/Active	10/25/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21702	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21703	Installed/Active	10/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21704	Installed/Active	10/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21705	Installed/Active	10/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21706	Installed/Active	10/18/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21707	Installed/Active	10/26/2016	G91200	RUUD	\$ 3,350.00	\$ 69.94
21708	Installed/Active	10/25/2016	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 21.74
21709	Installed/Active	10/12/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
21710	Installed/Active	10/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21711	Installed/Active	10/15/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21712	Installed/Active	10/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21713	Installed/Active	10/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21714	Installed/Active	11/06/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 11.72
21715	Installed/Active	11/01/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21716	Installed/Active	11/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21717	Installed/Active	10/29/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21718	Installed/Active	10/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21719	Installed/Active	11/08/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21720	Installed/Active	11/08/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21721	Installed/Active	10/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21722	Installed/Active	11/01/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21723	Installed/Active	11/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21724	Installed/Active	11/07/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21725	Installed/Active	11/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21726	Installed/Active	11/08/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
21727	Installed/Active	11/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21728	Installed/Active	10/31/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21729	Installed/Active	11/10/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21730	Installed/Active	11/07/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21731	Installed/Active	11/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21732	Installed/Active	10/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21733	Installed/Active	10/26/2016	PH13080	PHOENIX	\$ 1,900.00	\$ 44.90
21734	Installed/Active	10/16/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21735	Installed/Active	11/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21736	Installed/Active	11/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21737	Installed/Active	11/02/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21738	Installed/Active	11/02/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21739	Installed/Active	11/07/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21740	Installed/Active	11/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21741	Installed/Active	11/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21742	Installed/Active	11/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21743	Installed/Active	11/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21744	Installed/Active	10/31/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21745	Installed/Active	11/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21746	Installed/Active	11/15/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21747	Installed/Active	11/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21748	Installed/Active	11/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21749	Installed/Active	10/04/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21750	Installed/Active	10/31/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21751	Installed/Active	11/01/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
21752	Installed/Active	10/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21753	Installed/Active	11/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21754	Installed/Active	11/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21755	Installed/Active	11/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21756	Installed/Active	11/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21757	Installed/Active	11/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21758	Installed/Active	11/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21759	Installed/Active	11/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21760	Installed/Active	11/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21761	Installed/Active	11/17/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21762	Installed/Active	11/17/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21763	Installed/Active	11/05/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21764	Installed/Active	11/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21765	Installed/Active	11/11/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21766	Installed/Active	11/15/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21767	Installed/Active	10/30/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21768	Installed/Active	10/30/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21769	Installed/Active	11/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21770	Installed/Active	11/15/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21771	Installed/Active	11/16/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21772	Installed/Active	11/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21773	Installed/Active	11/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21774	Installed/Active	09/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21775	Installed/Active	10/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21776	Installed/Active	10/31/2016	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21777	Installed/Active	11/01/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21778	Installed/Active	11/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21779	Installed/Active	11/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21780	Installed/Active	11/19/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21781	Installed/Active	11/29/2016	RG240S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.01
21782	Installed/Active	11/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21783	Installed/Active	11/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21784	Installed/Active	11/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21785	Installed/Active	11/30/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21786	Installed/Active	11/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21787	Installed/Active	11/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21788	Installed/Active	11/28/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21789	Installed/Active	11/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21790	Installed/Active	11/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21791	Installed/Active	11/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21792	Installed/Active	11/19/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21793	Installed/Active	11/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21794	Installed/Active	11/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21795	Installed/Active	11/23/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21796	Installed/Active	11/23/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21797	Installed/Active	11/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21798	Installed/Active	11/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21799	Installed/Active	11/28/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21800	Installed/Active	11/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21801	Installed/Active	11/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21802	Installed/Active	11/29/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21803	Installed/Active	11/25/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21804	Installed/Active	11/21/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21805	Installed/Active	11/22/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21806	Installed/Active	11/18/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21807	Installed/Active	11/16/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21808	Installed/Active	11/16/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21809	Installed/Active	11/14/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21810	Installed/Active	11/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21811	Installed/Active	11/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21812	Installed/Active	11/01/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21813	Installed/Active	11/22/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21814	Installed/Active	11/17/2016	PH199119	PHOENIX	\$ 3,350.00	\$ 69.94
21815	Installed/Active	11/25/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21816	Installed/Active	11/19/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21817	Installed/Active	11/18/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21818	Installed/Active	11/25/2016	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 60.13
21819	Installed/Active	12/01/2016	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 11.72
21820	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21821	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21822	Installed/Active	12/02/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21823	Installed/Active	12/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21824	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21825	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21826	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21827	Installed/Active	12/02/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21828	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21829	Installed/Active	12/03/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21830	Installed/Active	12/03/2016	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 44.90
21831	Installed/Active	12/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21832	Installed/Active	12/09/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21833	Installed/Active	12/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21834	Installed/Active	12/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21835	Installed/Active	12/08/2016	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21836	Installed/Active	12/07/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21837	Installed/Active	12/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21838	Installed/Active	12/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21839	Installed/Active	11/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21840	Installed/Active	12/03/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21841	Installed/Active	12/01/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21842	Installed/Active	12/01/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21843	Installed/Active	11/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21844	Installed/Active	11/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21845	Installed/Active	12/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21846	Installed/Active	12/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21847	Installed/Active	12/12/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21848	Installed/Active	12/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21849	Installed/Active	12/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21850	Installed/Active	12/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21851	Installed/Active	12/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21852	Installed/Active	11/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21853	Installed/Active	12/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21854	Installed/Active	12/21/2016	PROG2932NRU63	RUUD	\$ 850.00	\$ 8.17
21855	Installed/Active	12/12/2016	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21856	Installed/Active	12/06/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21857	Installed/Active	12/08/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 18.60
21858	Installed/Active	12/08/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21859	Installed/Active	12/08/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21860	Installed/Active	12/09/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21861	Installed/Active	12/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21862	Installed/Active	12/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21863	Installed/Active	12/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21864	Installed/Active	12/31/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21865	Installed/Active	12/28/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21866	Installed/Active	12/28/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21867	Installed/Active	12/28/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21868	Installed/Active	12/28/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21869	Installed/Active	12/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21870	Installed/Active	12/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21871	Installed/Active	12/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21872	Installed/Active	12/22/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21873	Installed/Active	12/22/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21874	Installed/Active	12/21/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21875	Installed/Active	12/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21876	Installed/Active	12/02/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21877	Installed/Active	12/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21878	Installed/Active	12/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21879	Installed/Active	12/13/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21880	Installed/Active	12/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21881	Installed/Active	12/21/2016	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21882	Installed/Active	12/23/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21883	Installed/Active	12/22/2016	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.41
21884	Installed/Active	12/22/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21885	Installed/Active	12/20/2016	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 13.41
21886	Installed/Active	12/05/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21887	Installed/Active	12/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21888	Installed/Active	12/13/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21889	Installed/Active	12/13/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21890	Installed/Active	12/30/2016	PROG2932NRU63	RUUD	\$ 350.00	\$ 16.51
21891	Installed/Active	12/01/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21892	Installed/Active	12/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21893	Installed/Active	12/08/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21894	Installed/Active	12/23/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21895	Installed/Active	12/24/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21896	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21897	Installed/Active	12/29/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21898	Installed/Active	12/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21899	Installed/Active	12/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21900	Installed/Active	12/27/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21901	Installed/Active	12/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21902	Installed/Active	12/27/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21903	Installed/Active	12/27/2016	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 19.01
21904	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21905	Installed/Active	12/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21906	Installed/Active	12/28/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.47
21907	Installed/Active	12/30/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21908	Installed/Active	12/24/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21909	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21910	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21911	Installed/Active	12/29/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21912	Installed/Active	12/23/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21913	Installed/Active	12/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21914	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21915	Installed/Active	12/21/2016	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.47
21916	Installed/Active	12/24/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21917	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21918	Installed/Active	12/23/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21919	Installed/Active	12/31/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21920	Installed/Active	12/27/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21921	Installed/Active	12/28/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21922	Installed/Active	12/13/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21923	Installed/Active	01/19/2017	MI50L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.70
21924	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
21925	Installed/Active	12/29/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21926	Installed/Active	01/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21927	Installed/Active	01/04/2017	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.61
21928	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21929	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21930	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
21931	Installed/Active	01/04/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21932	Installed/Active	01/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
21933	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21934	Installed/Active	01/08/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21935	Installed/Active	01/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21936	Installed/Active	01/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21937	Installed/Active	01/06/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21938	Installed/Active	01/06/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21939	Installed/Active	02/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
21940	Installed/Active	12/01/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21941	Installed/Active	02/20/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21942	Installed/Active	11/29/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21943	Installed/Active	12/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21944	Installed/Active	12/11/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21945	Installed/Active	12/10/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21946	Installed/Active	12/10/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21947	Installed/Active	12/10/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21948	Installed/Active	12/09/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21949	Installed/Active	12/10/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21950	Installed/Active	12/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21951	Installed/Active	12/19/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21952	Installed/Active	01/05/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
21953	Installed/Active	12/14/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21954	Installed/Active	12/10/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21955	Installed/Active	11/21/2016	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 44.90
21956	Installed/Active	12/19/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21957	Installed/Active	12/14/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21958	Installed/Active	12/14/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21959	Installed/Active	12/11/2016	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 60.13
21960	Installed/Active	12/19/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21961	Installed/Active	12/19/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.01
21962	Installed/Active	12/19/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.17
21963	Installed/Active	12/19/2016	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21964	Installed/Active	12/20/2016	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.47
21965	Installed/Active	12/20/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21966	Installed/Active	12/15/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21967	Installed/Active	12/15/2016	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 11.72
21968	Installed/Active	12/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21969	Installed/Active	12/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21970	Installed/Active	12/16/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21971	Installed/Active	12/20/2016	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
21972	Installed/Active	12/19/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
21973	Installed/Active	01/03/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21974	Installed/Active	01/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
21975	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21976	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21977	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21978	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
21979	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
21980	Installed/Active	01/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 19.01
21981	Installed/Active	01/13/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
21982	Installed/Active	03/04/2017	PROG5036NRU60DV	RHEEM	\$ 1,075.00	\$ 19.43
21983	Installed/Active	01/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21984	Installed/Active	01/17/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21985	Installed/Active	01/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21986	Installed/Active	01/12/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21987	Installed/Active	01/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21988	Installed/Active	01/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
21989	Installed/Active	01/11/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21990	Installed/Active	01/18/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
21991	Installed/Active	01/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21992	Installed/Active	01/13/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
21993	Installed/Active	01/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21994	Installed/Active	01/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21995	Installed/Active	01/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21996	Installed/Active	01/14/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21997	Installed/Active	01/14/2017	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.70
21998	Installed/Active	01/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
21999	Installed/Active	01/13/2017	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 6.61
22000	Installed/Active	01/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22001	Installed/Active	01/16/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22002	Installed/Active	01/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22003	Installed/Active	01/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22004	Installed/Active	01/09/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22005	Installed/Active	01/10/2017	G75125	RUUD	\$ 1,900.00	\$ 45.88
22006	Installed/Active	03/08/2017	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22007	Installed/Active	02/13/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 13.70
22008	Installed/Active	03/04/2013	M15036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.39
22009	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
22010	Installed/Active	12/30/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
22011	Installed/Active	12/29/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
22012	Installed/Active	01/31/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22013	Installed/Active	01/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22014	Installed/Active	01/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22015	Installed/Active	01/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22016	Installed/Active	01/31/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22017	Installed/Active	01/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22018	Installed/Active	01/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22019	Installed/Active	01/30/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22020	Installed/Active	01/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22021	Installed/Active	01/28/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22022	Installed/Active	01/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22023	Installed/Active	01/27/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22024	Installed/Active	01/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22025	Installed/Active	01/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22026	Installed/Active	01/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22027	Installed/Active	01/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22028	Installed/Active	01/26/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22029	Installed/Active	01/26/2017	PROG5036NRH60DV	RHEEM	\$ 1,075.00	\$ 19.43
22030	Installed/Active	01/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22031	Installed/Active	01/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22032	Installed/Active	01/25/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22033	Installed/Active	01/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22034	Installed/Active	01/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22035	Installed/Active	01/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22036	Installed/Active	01/24/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22037	Installed/Active	01/24/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22038	Installed/Active	01/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22039	Installed/Active	01/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22040	Installed/Active	01/23/2017	PGR40	AO SMITH	\$ 850.00	\$ 13.70
22041	Installed/Active	02/02/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22042	Installed/Active	02/02/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 11.98
22043	Installed/Active	02/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22044	Installed/Active	02/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22045	Installed/Active	02/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22046	Installed/Active	02/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22047	Installed/Active	02/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22048	Installed/Active	02/10/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22049	Installed/Active	02/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22050	Installed/Active	01/17/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22051	Installed/Active	12/04/2016	RG250T6N	Bradford White	\$ 850.00	\$ 13.41
22052	Installed/Active	01/06/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22053	Installed/Active	01/06/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22054	Installed/Active	01/05/2017	RG240S6N	Bradford White	\$ 850.00	\$ 13.70
22055	Installed/Active	01/03/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22056	Installed/Active	01/04/2017	RG240S6N	Bradford White	\$ 850.00	\$ 6.61
22057	Installed/Active	01/05/2017	PGX50	AO SMITH	\$ 850.00	\$ 8.35
22058	Installed/Active	01/18/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22059	Installed/Active	01/18/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22060	Installed/Active	01/10/2017	RG250T6N	Bradford White	\$ 1,150.00	\$ 19.01
22061	Installed/Active	01/10/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22062	Installed/Active	01/21/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22063	Installed/Active	01/22/2017	RG240T6N	Bradford White	\$ 850.00	\$ 6.61
22064	Installed/Active	01/20/2017	PROG5036NRU60	Ruud	\$ 850.00	\$ 13.70
22065	Installed/Active	01/20/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22066	Installed/Active	01/20/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22067	Installed/Active	01/20/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22068	Installed/Active	01/20/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22069	Installed/Active	01/19/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22070	Installed/Active	01/19/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22071	Installed/Active	01/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22072	Installed/Active	01/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22073	Installed/Active	01/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22074	Installed/Active	01/13/2017	PGR50	AO SMITH	\$ 850.00	\$ 13.70
22075	Installed/Active	01/18/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22076	Installed/Active	02/09/2017	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.43
22077	Installed/Active	02/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22078	Installed/Active	02/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22079	Installed/Active	02/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22080	Installed/Active	02/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22081	Installed/Active	01/30/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22082	Installed/Active	01/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22083	Installed/Active	01/21/2017	RG230T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22084	Installed/Active	01/19/2017	PROG2932NRU62	RUUD	\$ 850.00	\$ 6.61
22085	Installed/Active	01/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22086	Installed/Active	01/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22087	Installed/Active	01/28/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22088	Installed/Active	01/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22089	Installed/Active	01/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22090	Installed/Active	02/07/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22091	Installed/Active	02/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22092	Installed/Active	02/14/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22093	Installed/Active	02/15/2017	PROG4040NRU62	RUUD	\$ 850.00	\$ 8.35
22094	Installed/Active	02/15/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22095	Installed/Active	02/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22096	Installed/Active	02/14/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22097	Installed/Active	02/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22098	Installed/Active	02/14/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22099	Installed/Active	02/10/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22100	Installed/Active	02/10/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22101	Installed/Active	02/11/2017	RG250T6N	BRADFORD WHITE	\$ 683.00	\$ 6.61
22102	Installed/Active	02/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22103	Installed/Active	02/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22104	Installed/Active	02/21/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22105	Installed/Active	02/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22106	Installed/Active	02/21/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22107	Installed/Active	02/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22108	Installed/Active	02/21/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22109	Installed/Active	02/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22110	Installed/Active	02/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22111	Installed/Active	01/19/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22112	Installed/Active	01/19/2017	RG2DV50S6N	Bradford White	\$ 1,075.00	\$ 19.43
22113	Installed/Active	01/18/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22114	Installed/Active	01/10/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22115	Installed/Active	01/14/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22116	Installed/Active	01/17/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22117	Installed/Active	01/18/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22118	Installed/Active	01/05/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22119	Installed/Active	01/03/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22120	Installed/Active	07/25/2011	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.64
22121	Installed/Active	02/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22122	Installed/Active	02/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22123	Installed/Active	03/06/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22124	Installed/Active	02/06/2017	FG40	AO SMITH	\$ 850.00	\$ 13.70
22125	Installed/Active	02/07/2017	RG240T6N	Bradford White	\$ 850.00	\$ 13.70
22126	Installed/Active	02/11/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22127	Installed/Active	02/01/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22128	Installed/Active	02/02/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22129	Installed/Active	02/03/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22130	Installed/Active	02/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22131	Installed/Active	02/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22132	Installed/Active	02/13/2017	RG240T6N	Bradford White	\$ 850.00	\$ 13.70
22133	Installed/Active	02/09/2017	RG240T6N	Bradford White	\$ 850.00	\$ 13.70
22134	Installed/Active	02/02/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22135	Installed/Active	02/06/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22136	Installed/Active	02/07/2017	RG250T6N	Bradford White	\$ 850.00	\$ 8.35
22137	Installed/Active	02/07/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22138	Installed/Active	02/07/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 11.98
22139	Installed/Active	02/07/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22140	Installed/Active	01/26/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22141	Installed/Active	01/31/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22142	Installed/Active	01/11/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22143	Installed/Active	01/15/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22144	Installed/Active	01/26/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22145	Installed/Active	01/28/2017	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 13.70
22146	Installed/Active	01/31/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22147	Installed/Active	01/23/2017	RG240T6N	Bradford White	\$ 850.00	\$ 6.61
22148	Installed/Active	01/26/2017	PROG5036NRU60	Ruud	\$ 1,075.00	\$ 19.43
22149	Installed/Active	01/07/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22150	Installed/Active	01/23/2017	RG250T6N	Bradford White	\$ 850.00	\$ 8.35
22151	Installed/Active	02/13/2017	RG250T6N	Bradford White	\$ 850.00	\$ 6.61
22152	Installed/Active	02/14/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22153	Installed/Active	02/06/2017	PROG5036NRU60DV	Ruud	\$ 1,075.00	\$ 19.43
22154	Installed/Active	02/06/2017	RG240T6N	Bradford White	\$ 850.00	\$ 6.61
22155	Installed/Active	02/15/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22156	Installed/Active	02/15/2017	RG240S6N	Bradford White	\$ 850.00	\$ 13.70
22157	Installed/Active	02/09/2017	RG240T6N	Bradford White	\$ 850.00	\$ 8.35
22158	Installed/Active	02/21/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22159	Installed/Active	02/14/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22160	Installed/Active	02/11/2017	RG250T6N	Bradford White	\$ 850.00	\$ 8.35
22161	Installed/Active	02/20/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22162	Installed/Active	02/18/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22163	Installed/Active	02/06/2017	RG250H6N	Bradford White	\$ 500.00	\$ 22.22
22164	Installed/Active	02/09/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22165	Installed/Active	07/28/2003	FCV50	AO SMITH	\$ 850.00	
22166	Installed/Active	01/08/2017	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22167	Installed/Active	01/04/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22168	Installed/Active	01/04/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22169	Installed/Active	03/17/2017	RG250T6N	Bradford White	\$ 850.00	\$ 13.70
22170	Installed/Active	02/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22171	Installed/Active	02/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22172	Installed/Active	02/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22173	Installed/Active	02/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22174	Installed/Active	02/22/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22175	Installed/Active	02/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22176	Installed/Active	02/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22177	Installed/Active	02/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22178	Installed/Active	01/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22179	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22180	Installed/Active	02/21/2017	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.43
22181	Installed/Active	02/28/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22182	Installed/Active	02/16/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22183	Installed/Active	02/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22184	Installed/Active	02/10/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
22185	Installed/Active	02/15/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22186	Installed/Active	02/15/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22187	Installed/Active	02/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22188	Installed/Active	02/24/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22189	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22190	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22191	Installed/Active	02/28/2017	G76200	RUUD	\$ 3,350.00	\$ 71.47
22192	Installed/Active	03/02/2017	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.61
22193	Installed/Active	03/01/2017	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.61
22194	Installed/Active	03/02/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22195	Installed/Active	03/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22196	Installed/Active	03/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22197	Installed/Active	03/01/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22198	Installed/Active	03/03/2017	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 6.61
22199	Installed/Active	03/07/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22200	Installed/Active	03/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22201	Installed/Active	03/07/2017	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.43
22202	Installed/Active	03/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22203	Installed/Active	03/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22204	Installed/Active	03/08/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22205	Installed/Active	03/08/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22206	Installed/Active	03/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22207	Installed/Active	03/09/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22208	Installed/Active	03/10/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22209	Installed/Active	03/10/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22210	Installed/Active	03/07/2017	G75125	RUUD	\$ 1,900.00	\$ 45.88
22211	Installed/Active	03/09/2017	G75125	RUUD	\$ 1,900.00	\$ 45.88
22212	Installed/Active	03/10/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22213	Installed/Active	03/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22214	Installed/Active	03/13/2017	M150L6FBN	BRADFORD WHITE	\$ 850.00	\$ 13.70
22215	Installed/Active	03/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22216	Installed/Active	03/14/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22217	Installed/Active	03/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22218	Installed/Active	03/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22219	Installed/Active	03/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22220	Installed/Active	03/17/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22221	Installed/Active	03/17/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22222	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22223	Installed/Active	03/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22224	Installed/Active	03/10/2017	G75125	RUUD	\$ 1,900.00	\$ 45.88
22225	Installed/Active	03/13/2017	G76200	RUUD	\$ 3,350.00	\$ 71.47
22226	Installed/Active	03/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22227	Installed/Active	03/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22228	Installed/Active	03/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22229	Installed/Active	01/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22230	Installed/Active	02/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22231	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22232	Installed/Active	03/01/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22233	Installed/Active	03/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22234	Installed/Active	03/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22235	Installed/Active	03/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22236	Installed/Active	03/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22237	Installed/Active	03/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22238	Installed/Active	03/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22239	Installed/Active	03/09/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22240	Installed/Active	03/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22241	Installed/Active	03/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22242	Installed/Active	03/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22243	Installed/Active	03/13/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22244	Installed/Active	03/16/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22245	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22246	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22247	Installed/Active	03/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22248	Installed/Active	02/03/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22249	Installed/Active	03/02/2017	PROG2932NRU63	RUUD	\$ 850.00	\$ 6.61
22250	Installed/Active	03/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22251	Installed/Active	03/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22252	Installed/Active	03/22/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22253	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22254	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22255	Installed/Active	03/13/2017	PROG5038NRU60	RUUD	\$ 850.00	\$ 8.35
22256	Installed/Active	03/22/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22257	Installed/Active	03/22/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22258	Installed/Active	03/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22259	Installed/Active	03/22/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22260	Installed/Active	03/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22261	Installed/Active	03/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22262	Installed/Active	03/24/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22263	Installed/Active	02/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22264	Installed/Active	03/28/2017	PROG5036NRU60	RUUD	\$ 850.00	\$ 13.70
22265	Installed/Active	03/27/2017	PROG5036NRU60	RUUD	\$ 850.00	\$ 19.43
22266	Installed/Active	03/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22267	Installed/Active	03/27/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22268	Installed/Active	03/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22269	Installed/Active	03/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22270	Installed/Active	03/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22271	Installed/Active	03/21/2017	PROG40S34NRU62	RUUD	\$ 850.00	\$ 6.61
22272	Installed/Active	03/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22273	Installed/Active	03/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22274	Installed/Active	03/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22275	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22276	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22277	Installed/Active	03/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22278	Installed/Active	03/20/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22279	Installed/Active	03/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22280	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22281	Installed/Active	03/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22282	Installed/Active	03/29/2017	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22283	Installed/Active	03/30/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22284	Installed/Active	03/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22285	Installed/Active	03/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22286	Installed/Active	02/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22287	Installed/Active	02/15/2017	RG250H6N	BRADFORD WHITE	\$ 1,075.00	\$ 11.98
22288	Installed/Active	03/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22289	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22290	Installed/Active	03/16/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22291	Installed/Active	02/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22292	Installed/Active	03/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22293	Installed/Active	03/29/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22294	Installed/Active	02/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22295	Installed/Active	03/15/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22296	Installed/Active	03/21/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22297	Installed/Active	03/07/2017	RG230S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22298	Installed/Active	03/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22299	Installed/Active	03/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22300	Installed/Active	03/11/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22301	Installed/Active	03/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22302	Installed/Active	03/18/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22303	Installed/Active	03/17/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
22304	Installed/Active	03/22/2017	PH19980	Phoenix	\$ 6,391.00	\$ 71.47
22305	Installed/Active	03/31/2017	G91200	RUUD	\$ 3,350.00	\$ 71.47
22306	Installed/Active	03/31/2017	G91200	RUUD	\$ 3,350.00	\$ 71.47
22307	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22308	Installed/Active	03/28/2017	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22309	Installed/Active	03/26/2017	G82156	RUUD	\$ 3,350.00	\$ 71.47
22310	Installed/Active	03/15/2017	G82156	RUUD	\$ 1,900.00	\$ 45.88
22311	Installed/Active	03/23/2017	G75125	RUUD	\$ 1,900.00	\$ 45.88
22312	Installed/Active	03/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22313	Installed/Active	04/06/2017	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.70
22314	Installed/Active	04/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22315	Installed/Active	04/07/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22316	Installed/Active	04/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22317	Installed/Active	04/05/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22318	Installed/Active	04/10/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22319	Installed/Active	04/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22320	Installed/Active	04/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22321	Installed/Active	04/17/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22322	Installed/Active	04/17/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22323	Installed/Active	04/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22324	Installed/Active	04/19/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22325	Installed/Active	04/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22326	Installed/Active	04/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22327	Installed/Active	04/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22328	Installed/Active	04/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22329	Installed/Active	04/14/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22330	Installed/Active	04/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22331	Installed/Active	04/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22332	Installed/Active	04/26/2017	RG240T6N	Bradford White	\$ 850.00	\$ 6.61
22333	Installed/Active	04/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22334	Installed/Active	04/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22335	Installed/Active	04/01/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22336	Installed/Active	04/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22337	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22338	Installed/Active	04/05/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22339	Installed/Active	04/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22340	Installed/Active	04/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22341	Installed/Active	04/10/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22342	Installed/Active	04/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22343	Installed/Active	04/12/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22344	Installed/Active	04/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22345	Installed/Active	02/13/2017	PROG5036NRU60DV	RUUD	\$ 850.00	\$ 8.35
22346	Installed/Active	04/11/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22347	Installed/Active	04/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22348	Installed/Active	03/28/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
22349	Installed/Active	04/04/2017	G76200	RUUD	\$ 3,350.00	\$ 71.47
22350	Installed/Active	04/17/2017	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22351	Installed/Active	04/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22352	Installed/Active	03/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22353	Installed/Active	03/27/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22354	Installed/Active	02/28/2017	PH19980	PHOENIX	\$ 3,350.00	\$ 71.47
22355	Installed/Active	04/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22356	Installed/Active	04/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22357	Installed/Active	04/25/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22358	Installed/Active	04/25/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22359	Installed/Active	04/20/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22360	Installed/Active	04/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22361	Installed/Active	04/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22362	Installed/Active	04/20/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22363	Installed/Active	04/19/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22364	Installed/Active	04/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22365	Installed/Active	04/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22366	Installed/Active	04/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22367	Installed/Active	04/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22368	Installed/Active	04/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22369	Installed/Active	03/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22370	Installed/Active	04/06/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22371	Installed/Active	03/27/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22372	Installed/Active	03/23/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22373	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22374	Installed/Active	03/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22375	Installed/Active	03/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22376	Installed/Active	03/21/2017	RG250T6N	Bradford-White	\$ 660.00	\$ 13.70
22377	Installed/Active	04/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22378	Installed/Active	04/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22379	Installed/Active	04/17/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22380	Installed/Active	04/22/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22381	Installed/Active	04/28/2017	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22382	Installed/Active	04/27/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22383	Installed/Active	04/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22384	Installed/Active	04/13/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22385	Installed/Active	04/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22386	Installed/Active	04/14/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22387	Installed/Active	04/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22388	Installed/Active	04/10/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22389	Installed/Active	04/12/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22390	Installed/Active	03/07/2017	RG2DV50S6N	BRADFORD WHITE	\$ 1,075.00	\$ 19.43
22391	Installed/Active	04/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22392	Installed/Active	04/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22393	Installed/Active	04/23/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22394	Installed/Active	03/13/2017	RG250H6N	BRADFORD WHITE	\$ 350.00	\$ 16.87
22395	Installed/Active	05/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22396	Installed/Active	05/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22397	Installed/Active	05/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22398	Installed/Active	05/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22399	Installed/Active	05/01/2017	G75125	RHEEM / RUUD	\$ 2,917.34	\$ 45.88
22400	Installed/Active	05/03/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22401	Installed/Active	05/01/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22402	Installed/Active	05/04/2017	PH199119	Phoenix	\$ 3,350.00	\$ 71.47
22403	Installed/Active	05/16/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22404	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22405	Installed/Active	05/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22406	Installed/Active	05/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22407	Installed/Active	05/05/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22408	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22409	Installed/Active	05/05/2017	RG240T6N	BRADFORD-WHITE	\$ 850.00	\$ 8.35
22410	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22411	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22412	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22413	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22414	Installed/Active	05/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22415	Installed/Active	05/08/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22416	Installed/Active	05/16/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22417	Installed/Active	05/15/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22418	Installed/Active	05/14/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22419	Installed/Active	05/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22420	Installed/Active	04/29/2017	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22421	Installed/Active	04/24/2017	RG275H6N	BRADFORD WHITE	\$ 1,750.00	\$ 35.06
22422	Installed/Active	05/11/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22423	Installed/Active	05/11/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22424	Installed/Active	05/24/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22425	Installed/Active	04/29/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22426	Installed/Active	03/17/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22427	Installed/Active	04/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22428	Installed/Active	04/29/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22429	Installed/Active	04/30/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22430	Installed/Active	05/31/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22431	Installed/Active	05/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22432	Installed/Active	05/19/2017	G76200	RUUD	\$ 3,350.00	\$ 71.47
22433	Installed/Active	05/06/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22434	Installed/Active	05/13/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22435	Installed/Active	05/12/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22436	Installed/Active	05/11/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22437	Installed/Active	05/10/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22438	Installed/Active	05/10/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22439	Installed/Active	05/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22440	Installed/Active	05/03/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22441	Installed/Active	05/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22442	Installed/Active	05/04/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22443	Installed/Active	05/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22444	Installed/Active	05/03/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22445	Installed/Active	05/02/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22446	Installed/Active	05/02/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22447	Installed/Active	05/01/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22448	Installed/Active	05/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22449	Installed/Active	05/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22450	Installed/Active	01/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22451	Installed/Active	05/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22452	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22453	Installed/Active	05/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22454	Installed/Active	05/31/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22455	Installed/Active	05/31/2017	PROG5036NRH60	RUUD	\$ 1,075.00	\$ 19.43
22456	Installed/Active	05/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22457	Installed/Active	05/23/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22458	Installed/Active	05/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22459	Installed/Active	05/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22460	Installed/Active	05/26/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22461	Installed/Active	05/30/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22462	Installed/Active	05/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22463	Installed/Active	05/29/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22464	Installed/Active	05/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22465	Installed/Active	03/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22466	Installed/Active	05/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22467	Installed/Active	05/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22468	Installed/Active	05/15/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22469	Installed/Active	05/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22470	Installed/Active	06/09/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22471	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22472	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22473	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22474	Installed/Active	06/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22475	Installed/Active	06/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22476	Installed/Active	06/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22477	Installed/Active	06/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22478	Installed/Active	06/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22479	Installed/Active	06/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22480	Installed/Active	06/08/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22481	Installed/Active	06/08/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22482	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22483	Installed/Active	05/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22484	Installed/Active	05/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22485	Installed/Active	04/07/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22486	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22487	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22488	Installed/Active	06/12/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22489	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 19.01
22490	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22491	Installed/Active	06/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22492	Installed/Active	06/05/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22493	Installed/Active	06/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22494	Installed/Active	06/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22495	Installed/Active	06/13/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22496	Installed/Active	06/11/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22497	Installed/Active	03/31/2017	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22498	Installed/Active	05/17/2017	G91200	RUUD	\$ 3,350.00	\$ 71.47
22499	Installed/Active	05/18/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22500	Installed/Active	04/18/2017	PH199119	Phoenix	\$ 3,350.00	\$ 61.45
22501	Installed/Active	05/17/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22502	Installed/Active	06/28/2017	RG2DV50S6N	Bradford White	\$ 2,349.00	\$ 19.43
22503	Installed/Active	05/25/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22504	Installed/Active	04/15/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22505	Installed/Active	05/17/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22506	Installed/Active	05/17/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22507	Installed/Active	04/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22508	Installed/Active	04/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22509	Installed/Active	04/25/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22510	Installed/Active	04/24/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22511	Installed/Active	04/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22512	Installed/Active	04/19/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22513	Installed/Active	04/27/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22514	Installed/Active	04/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22515	Installed/Active	06/22/2017	RG250H6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22516	Installed/Active	06/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22517	Installed/Active	06/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22518	Installed/Active	06/21/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22519	Installed/Active	06/21/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22520	Installed/Active	06/21/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22521	Installed/Active	06/19/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
22522	Installed/Active	06/18/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22523	Installed/Active	06/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22524	Installed/Active	06/16/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22525	Installed/Active	06/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22526	Installed/Active	06/19/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22527	Installed/Active	06/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22528	Installed/Active	06/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22529	Installed/Active	06/19/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22530	Installed/Active	06/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22531	Installed/Active	06/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22532	Installed/Active	06/11/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22533	Installed/Active	02/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22534	Installed/Active	06/20/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22535	Installed/Active	02/27/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22536	Installed/Active	04/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22537	Installed/Active	04/05/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22538	Installed/Active	04/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22539	Installed/Active	04/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22540	Installed/Active	04/27/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22541	Installed/Active	04/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22542	Installed/Active	04/18/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22543	Installed/Active	04/28/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22544	Installed/Active	07/05/2017	G91200	RUUD/RHEEM	\$ 5,494.00	\$ 45.88
22545	Installed/Active	07/05/2017	G75125	RUUD/RHEEM	\$ 4,464.00	\$ 71.47
22546	Installed/Active	06/02/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22547	Installed/Active	06/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22548	Installed/Active	05/17/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22549	Installed/Active	06/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22550	Installed/Active	06/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22551	Installed/Active	06/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22552	Installed/Active	06/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22553	Installed/Active	05/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22554	Installed/Active	06/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22555	Installed/Active	06/25/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22556	Installed/Active	06/22/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22557	Installed/Active	06/23/2017	RG250L6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22558	Installed/Active	06/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22559	Installed/Active	06/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22560	Installed/Active	06/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22561	Installed/Active	06/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22562	Installed/Active	05/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22563	Installed/Active	05/09/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22564	Installed/Active	05/05/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22565	Installed/Active	05/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22566	Installed/Active	05/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22567	Installed/Active	05/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22568	Installed/Active	04/29/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22569	Installed/Active	05/01/2017	RG250T6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22570	Installed/Active	04/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22571	Installed/Active	05/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22572	Installed/Active	05/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22573	Installed/Active	05/19/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22574	Installed/Active	05/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22575	Installed/Active	06/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22576	Installed/Active	06/28/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22577	Installed/Active	05/06/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22578	Installed/Active	06/20/2017	PROG5036NRU60DV	RUUD	\$ 1,075.00	\$ 19.43
22579	Installed/Active	05/24/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22580	Installed/Active	06/01/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22581	Installed/Active	05/04/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22582	Installed/Active	05/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22583	Installed/Active	05/18/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22584	Installed/Active	05/08/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22585	Installed/Active	05/02/2017	PROG5036NRU60	RUUD	\$ 850.00	\$ 13.70
22586	Installed/Active	04/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22587	Installed/Active	05/27/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22588	Installed/Active	05/30/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22589	Installed/Active	05/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22590	Installed/Active	05/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22591	Installed/Active	05/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22592	Installed/Active	05/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22593	Installed/Active	05/23/2017	RG250T6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22594	Installed/Active	05/22/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22595	Installed/Active	05/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22596	Installed/Active	05/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22597	Installed/Active	05/15/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22598	Installed/Active	05/16/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22599	Installed/Active	05/30/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22600	Installed/Active	05/23/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22601	Installed/Active	06/06/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22602	Installed/Active	06/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22603	Installed/Active	06/06/2017	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 13.70
22604	Installed/Active	06/04/2017	RG250T6N	BRADFORD-WHITE	\$ 850.00	\$ 8.35
22605	Installed/Active	06/02/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22606	Installed/Active	05/31/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22607	Installed/Active	05/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22608	Installed/Active	05/25/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22609	Installed/Active	06/19/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22610	Installed/Active	06/19/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22611	Installed/Active	06/02/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22612	Installed/Active	05/15/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22613	Installed/Active	06/09/2017	RG250H6N	BRADFORD WHITE	\$ 1,150.00	\$ 19.01
22614	Installed/Active	06/08/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22615	Installed/Active	06/07/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22616	Installed/Active	05/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22617	Installed/Active	05/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22618	Installed/Active	06/06/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22619	Installed/Active	06/14/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22620	Installed/Active	06/14/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22621	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22622	Installed/Active	06/12/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22623	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22624	Installed/Active	06/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22625	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22626	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22627	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22628	Installed/Active	06/09/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22629	Installed/Active	06/09/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22630	Installed/Active	05/18/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22631	Installed/Active	05/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22632	Installed/Active	05/12/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22633	Installed/Active	05/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22634	Installed/Active	05/07/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 8.35
22635	Installed/Active	06/24/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22636	Installed/Active	06/19/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22637	Installed/Active	06/20/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22638	Installed/Active	06/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22639	Installed/Active	06/20/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22640	Installed/Active	06/23/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22641	Installed/Active	05/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22642	Installed/Active	06/26/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22643	Installed/Active	05/05/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22644	Installed/Active	04/20/2017	PH19980	PHOENIX	\$ 3,350.00	\$ 71.47
22645	Installed/Active	05/04/2017	G75125	RUUD/RHEEM	\$ 1,900.00	\$ 45.88
22646	Installed/Active	06/27/2017	G76200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22647	Installed/Active	05/05/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22648	Installed/Active	06/22/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22649	Installed/Active	06/22/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22650	Installed/Active	05/23/2017	RG275H6N	BRADFORD WHITE	\$ 1,900.00	\$ 45.88
22651	Installed/Active	05/23/2017	RG275H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22652	Installed/Active	05/23/2017	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22653	Installed/Active	06/19/2017	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 71.47
22654	Installed/Active	06/05/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22655	Installed/Active	07/02/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22656	Installed/Active	06/21/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22657	Installed/Active	05/30/2017	RG240T6N	BRADFORD-WHITE	\$ 850.00	\$ 8.35
22658	Installed/Active	06/06/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22659	Installed/Active	05/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22660	Installed/Active	06/01/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22661	Installed/Active	04/28/2017	RG240S6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22662	Installed/Active	09/25/2015	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.12
22663	Installed/Active	08/07/2014	M45036FBN	BRADFORD WHITE	\$ 1,150.00	\$ 17.81
22664	Installed/Active	09/15/2014	PROG5038NRU58	RUUD	\$ 850.00	\$ 12.84
22665	Installed/Active	07/14/2015	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 6.33
22666	Installed/Active	06/13/2017	PROG5036NRU60	RUUD	\$ 1,075.00	\$ 19.43
22667	Installed/Active	05/28/2017	G82156	RUUD/RHEEM	\$ 3,350.00	\$ 61.45
22668	Installed/Active	12/21/2016	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.41
22669	Installed/Active	12/22/2014	M45036FBN	BRADFORD WHITE	\$ 850.00	\$ 12.84
22670	Installed/Active	06/17/2017	RG230T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22671	Installed/Active	05/25/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22672	Installed/Active	05/31/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 13.70
22673	Installed/Active	04/30/2017	RG250T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22674	Installed/Active	02/14/2017	RG240T6N	BRADFORD WHITE	\$ 850.00	\$ 6.61
22675	Installed/Active	05/27/2017	RG250H6N	BRADFORD WHITE	\$ 1,750.00	\$ 35.06
22676	Installed/Active	06/23/2017	RG250H6N	BRADFORD WHITE	\$ 1,125.00	\$ 22.22
22677	Installed/Active	06/30/2017	PROG4038NRH62	RHEEM	\$ 1,133.50	\$ 8.35
22678	Installed/Active	07/02/2017	PROG5036NRH60DV	RHEEM	\$ 2,053.61	\$ 19.43
22679	Installed/Active	07/02/2017	PROG40S38NRH62	RHEEM	\$ 1,118.61	\$ 13.70
22680	Installed/Active	06/26/2017	PROG40S38NRH62	RHEEM	\$ 1,231.00	\$ 13.70
22681	Installed/Active	06/29/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 13.70
22682	Installed/Active	07/01/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 13.70
22683	Installed/Active	06/29/2017	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 13.70
22684	Installed/Active	06/30/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,254.21	\$ 19.43
22685	Installed/Active	06/30/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,133.50	\$ 13.70
22686	Installed/Active	06/27/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22687	Installed/Active	06/27/2017	G82156	RUUD/RHEEM	\$ 5,254.00	\$ 61.45
22688	Installed/Active	06/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22689	Installed/Active	07/01/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,109.00	\$ 6.61
22690	Installed/Active	06/30/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,019.00	\$ 13.70
22691	Installed/Active	06/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22692	Installed/Active	06/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 6.61
22693	Installed/Active	06/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,174.00	\$ 13.70
22694	Installed/Active	06/29/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 13.70
22695	Installed/Active	07/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,140.85	\$ 13.70
22696	Installed/Active	07/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,112.55	\$ 13.70
22697	Installed/Active	07/03/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22698	Installed/Active	06/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,172.15	\$ 6.61
22699	Installed/Active	07/03/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.50	\$ 13.70
22700	Installed/Active	07/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22701	Installed/Active	07/03/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22702	Installed/Active	07/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22703	Installed/Active	07/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22704	Installed/Active	07/03/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22705	Installed/Active	07/07/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,152.00	\$ 13.70
22706	Installed/Active	07/07/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,034.00	\$ 19.43
22707	Installed/Active	07/11/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,140.24	\$ 13.70
22708	Installed/Active	07/13/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 6.61
22709	Installed/Active	07/10/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22710	Installed/Active	07/12/2017	PROG2932NRH63	RUUD/RHEEM	\$ 1,399.00	\$ 13.70
22711	Installed/Active	07/12/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,075.00	\$ 19.43
22712	Installed/Active	07/06/2017	G91200	RUUD/RHEEM	\$ 5,354.00	\$ 71.47
22713	Installed/Active	07/01/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 13.70
22714	Installed/Active	07/02/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22715	Installed/Active	06/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22716	Installed/Active	06/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
22717	Installed/Active	06/27/2017	PROG4860NRH60	RUUD/RHEEM	\$ 1,219.00	\$ 19.01
22718	Installed/Active	08/07/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,120.24	\$ 13.70
22719	Installed/Active	07/02/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,039.00	\$ 19.43
22720	Installed/Active	06/30/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
22721	Installed/Active	06/12/2012	PROG5038NRH60	RUUD/RHEEM	\$ 850.00	\$ 12.75
22722	Installed/Active	07/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,189.00	\$ 13.70
22723	Installed/Active	07/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.00	\$ 13.70
22724	Installed/Active	07/06/2017	RG250S6N	BRADFORD WHITE	\$ 1,339.00	\$ 19.01
22725	Installed/Active	07/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22726	Installed/Active	06/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,140.24	\$ 13.70
22727	Installed/Active	07/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 6.61
22728	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 850.00	\$ 6.61
22729	Installed/Active	07/04/2017	G100200	RUUD/RHEEM	\$ 5,594.00	\$ 71.47
22730	Installed/Active	07/06/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,949.00	\$ 19.43
22731	Installed/Active	07/12/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22732	Installed/Active	07/13/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22733	Installed/Active	07/11/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,014.00	\$ 19.43
22734	Installed/Active	07/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22735	Installed/Active	07/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.00	\$ 13.70
22736	Installed/Active	07/11/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22737	Installed/Active	07/11/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22738	Installed/Active	07/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22739	Installed/Active	07/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22740	Installed/Active	07/12/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,100.05	\$ 13.70
22741	Installed/Active	07/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.00	\$ 6.61
22742	Installed/Active	07/22/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 8.35
22743	Installed/Active	07/19/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,034.00	\$ 19.43
22744	Installed/Active	07/21/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,169.00	\$ 13.70
22745	Installed/Active	07/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,112.55	\$ 13.70
22746	Installed/Active	07/21/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,074.00	\$ 19.43
22747	Installed/Active	07/18/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22748	Installed/Active	07/17/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,108.10	\$ 13.70
22749	Installed/Active	07/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22750	Installed/Active	07/18/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,120.85	\$ 13.70
22751	Installed/Active	07/10/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22752	Installed/Active	07/12/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22753	Installed/Active	07/22/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,949.00	\$ 19.43
22754	Installed/Active	07/14/2017	G76200	RUUD/RHEEM	\$ 5,294.00	\$ 71.47
22755	Installed/Active	07/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 6.61
22756	Installed/Active	07/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 6.61
22757	Installed/Active	07/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22758	Installed/Active	07/26/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,332.55	\$ 13.70
22759	Installed/Active	07/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 22.22
22760	Installed/Active	07/17/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,115.65	\$ 13.70
22761	Installed/Active	07/17/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
22762	Installed/Active	07/18/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,172.00	\$ 8.35
22763	Installed/Active	07/20/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,089.00	\$ 19.43
22764	Installed/Active	07/19/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,151.00	\$ 19.43
22765	Installed/Active	07/17/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,151.00	\$ 19.43
22766	Installed/Active	07/17/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,053.61	\$ 19.43
22767	Installed/Active	07/24/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 6.61
22768	Installed/Active	07/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22769	Installed/Active	07/26/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,304.21	\$ 6.61
22770	Installed/Active	07/27/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,231.00	\$ 6.61
22771	Installed/Active	07/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22772	Installed/Active	07/25/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22773	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22774	Installed/Active	07/25/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 6.61
22775	Installed/Active	07/24/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,121.00	\$ 13.70
22776	Installed/Active	07/28/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,079.00	\$ 8.35
22777	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,251.00	\$ 6.61
22778	Installed/Active	07/24/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 8.35
22779	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22780	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,140.24	\$ 13.70
22781	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22782	Installed/Active	07/25/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,139.00	\$ 13.70
22783	Installed/Active	07/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22784	Installed/Active	07/28/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,014.21	\$ 19.43
22785	Installed/Active	07/25/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22786	Installed/Active	07/24/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22787	Installed/Active	07/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.00	\$ 13.70
22788	Installed/Active	07/28/2017	G75125	RUUD/RHEEM	\$ 4,289.00	\$ 45.88
22789	Installed/Active	07/31/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,014.21	\$ 19.43
22790	Installed/Active	08/01/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,019.00	\$ 19.43

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22791	Installed/Active	07/31/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 6.61
22792	Installed/Active	07/31/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22793	Installed/Active	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22794	Installed/Active	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 6.61
22795	Installed/Active	08/03/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.39	\$ 13.70
22796	Installed/Active	07/31/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22797	Installed/Active	08/04/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22798	Installed/Active	08/04/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22799	Installed/Active	08/04/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,189.00	\$ 6.61
22800	Installed/Active	08/06/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 13.70
22801	Installed/Active	08/02/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22802	Installed/Active	08/05/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,039.00	\$ 19.43
22803	Installed/Active	08/02/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,309.00	\$ 13.70
22804	Installed/Active	07/31/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22805	Installed/Active	08/09/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.50	\$ 13.70
22806	Installed/Active	07/31/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,053.50	\$ 19.43
22807	Installed/Active	08/10/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22808	Installed/Active	08/06/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,079.00	\$ 13.70
22809	Installed/Active	08/04/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22810	Installed/Active	08/10/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22811	Installed/Active	09/16/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22812	Installed/Active	08/02/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22813	Installed/Active	07/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22814	Installed/Active	08/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22815	Installed/Active	08/08/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22816	Installed/Active	08/08/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22817	Installed/Active	08/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22818	Installed/Active	08/09/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 6.61
22819	Installed/Active	08/04/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22820	Installed/Active	08/10/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 8.35
22821	Installed/Active	08/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22822	Installed/Active	08/01/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,251.00	\$ 13.70
22823	Installed/Active	08/02/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 6.61
22824	Installed/Active	08/01/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.00	\$ 13.70
22825	Installed/Active	08/11/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,035.65	\$ 19.43
22826	Installed/Active	08/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,172.15	\$ 13.70
22827	Installed/Active	08/09/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 13.70
22828	Installed/Active	08/09/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 13.70
22829	Installed/Active	08/08/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,122.55	\$ 6.61
22830	Installed/Active	08/09/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 13.70
22831	Installed/Active	08/09/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22832	Installed/Active	08/06/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,056.96	\$ 19.43
22833	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22834	Installed/Active	08/16/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22835	Installed/Active	08/19/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22836	Installed/Active	08/17/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,134.00	\$ 13.70
22837	Installed/Active	08/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22838	Installed/Active	08/10/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,172.00	\$ 13.70
22839	Installed/Active	08/11/2017	PROG5038NRH60	RUUD/RHEEM	\$ 850.00	\$ 13.70
22840	Installed/Active	08/03/2017	G82156	RUUD/RHEEM	\$ 5,104.00	\$ 61.45
22841	Installed/Active	08/09/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,156.96	\$ 13.70
22842	Installed/Active	08/03/2017	G91200	RUUD/RHEEM	\$ 5,292.83	\$ 71.47
22843	Installed/Active	08/07/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
22844	Installed/Active	07/30/2017	G82156	RUUD/RHEEM	\$ 5,254.00	\$ 61.45
22845	Installed/Active	08/17/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22846	Installed/Active	08/18/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 8.35
22847	Installed/Active	08/18/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,097.00	\$ 13.70
22848	Installed/Active	08/16/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,164.00	\$ 13.70
22849	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,117.00	\$ 13.70
22850	Installed/Active	07/30/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22851	Installed/Active	08/03/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.50	\$ 8.35
22852	Installed/Active	07/25/2017	G75125	RUUD/RHEEM	\$ 4,464.00	\$ 71.47
22853	Installed/Active	08/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22854	Installed/Active	08/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,189.00	\$ 13.70
22855	Installed/Active	08/26/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,332.55	\$ 13.70
22856	Installed/Active	08/17/2017	G82156	RUUD/RHEEM	\$ 5,254.00	\$ 61.45
22857	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22858	Installed/Active	07/21/2017	G75125	RUUD/RHEEM	\$ 4,199.00	\$ 45.88
22859	Installed/Active	07/18/2017	G91200	RUUD/RHEEM	\$ 5,494.00	\$ 71.47
22860	Installed/Active	07/20/2017	PH199119	PHOENIX	\$ 3,350.00	\$ 71.47
22861	Installed/Active	03/31/2017	PROG40S34NRU62	RUUD/RHEEM	\$ 850.00	\$ 6.61
22862	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22863	Installed/Active	08/16/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22864	Installed/Active	08/18/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 8.35
22865	Installed/Active	08/14/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22866	Installed/Active	08/18/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,122.55	\$ 6.61
22867	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,193.00	\$ 13.70
22868	Installed/Active	08/15/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,343.61	\$ 13.70
22869	Installed/Active	08/15/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,231.00	\$ 6.61
22870	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.39	\$ 13.70
22871	Installed/Active	08/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22872	Installed/Active	08/25/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,949.00	\$ 19.43
22873	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22874	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 6.61
22875	Installed/Active	08/22/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,999.00	\$ 19.43
22876	Installed/Active	08/23/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22877	Installed/Active	08/07/2017	PH199119	PHOENIX	\$ 8,059.20	\$ 71.47
22878	Installed/Active	08/08/2017	PH199119	PHOENIX	\$ 8,059.20	\$ 71.47
22879	Installed/Active	08/22/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 13.70
22880	Installed/Active	08/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
22881	Installed/Active	08/24/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22882	Installed/Active	08/22/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 6.61
22883	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 13.70
22884	Installed/Active	08/23/2017	PROG2932NRH63	RUUD/RHEEM	\$ 1,418.59	\$ 8.35
22885	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,164.00	\$ 13.70
22886	Installed/Active	08/23/2017	G82156	RUUD	\$ 5,254.00	\$ 61.45
22887	Installed/Active	08/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22888	Installed/Active	08/27/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,090.00	\$ 13.70
22889	Installed/Active	08/25/2017	G75125	RUUD/RHEEM	\$ 4,264.21	\$ 45.88
22890	Installed/Active	08/23/2017	RG2DV40S6N	BRADFORD WHITE	\$ 2,312.15	\$ 11.98
22891	Installed/Active	08/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,117.00	\$ 13.70
22892	Installed/Active	08/22/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,251.00	\$ 13.70
22893	Installed/Active	08/22/2017	G76200	RUUD/RHEEM	\$ 5,294.00	\$ 71.47
22894	Installed/Active	08/23/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,008.10	\$ 19.43
22895	Installed/Active	08/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 6.61
22896	Installed/Active	08/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22897	Installed/Active	09/01/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,239.00	\$ 13.70
22898	Installed/Active	08/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,116.50	\$ 13.70
22899	Installed/Active	08/28/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,098.59	\$ 8.35
22900	Installed/Active	09/01/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,274.00	\$ 19.43
22901	Installed/Active	08/29/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,155.00	\$ 13.70
22902	Installed/Active	09/02/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,174.00	\$ 19.01
22903	Installed/Active	09/02/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,174.00	\$ 13.70
22904	Installed/Active	09/02/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22905	Installed/Active	09/02/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.00	\$ 13.70
22906	Installed/Active	08/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.35	\$ 13.70
22907	Installed/Active	08/30/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,120.24	\$ 8.35
22908	Installed/Active	09/01/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22909	Installed/Active	08/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,139.00	\$ 13.70
22910	Installed/Active	08/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22911	Installed/Active	08/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 13.70
22912	Installed/Active	08/31/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,079.00	\$ 6.61
22913	Installed/Active	08/29/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22914	Installed/Active	08/28/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,094.21	\$ 13.70
22915	Installed/Active	08/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22916	Installed/Active	08/28/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 6.61
22917	Installed/Active	08/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 6.61
22918	Installed/Active	09/01/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,121.00	\$ 13.70
22919	Installed/Active	08/31/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22920	Installed/Active	08/28/2017	G82156	RUUD/RHEEM	\$ 5,254.00	\$ 61.45
22921	Installed/Active	09/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22922	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,251.00	\$ 13.70
22923	Installed/Active	09/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 6.61
22924	Installed/Active	09/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22925	Installed/Active	09/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,134.00	\$ 8.35
22926	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.55	\$ 13.70
22927	Installed/Active	09/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 6.61
22928	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 6.61
22929	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,156.96	\$ 13.70
22930	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,118.59	\$ 8.35
22931	Installed/Active	09/05/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,114.00	\$ 13.70
22932	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,128.00	\$ 13.70
22933	Installed/Active	09/11/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,028.00	\$ 19.43
22934	Installed/Active	09/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
22935	Installed/Active	09/09/2017	PROG5038NRH60	RUUD	\$ 1,099.00	\$ 13.70
22936	Installed/Active	09/01/2017	G91200	RUUD/RHEEM	\$ 5,322.55	\$ 71.47
22937	Installed/Active	09/08/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,164.00	\$ 13.70
22938	Installed/Active	09/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,189.00	\$ 13.70
22939	Installed/Active	09/09/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22940	Installed/Active	09/07/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22941	Installed/Active	09/06/2017	PROG7576NRH	RUUD/RHEEM	\$ 1,884.00	\$ 22.22
22942	Installed/Active	09/11/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,134.00	\$ 13.70
22943	Installed/Active	09/13/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,092.83	\$ 8.35
22944	Installed/Active	09/17/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,090.00	\$ 6.61
22945	Installed/Active	09/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
22946	Installed/Active	09/15/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 19.43
22947	Installed/Active	09/12/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,090.00	\$ 13.70
22948	Installed/Active	09/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.39	\$ 6.61
22949	Installed/Active	09/11/2017	G76200	RUUD/RHEEM	\$ 5,119.00	\$ 61.45
22950	Installed/Active	09/14/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22951	Installed/Active	09/12/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,134.00	\$ 13.70
22952	Installed/Active	09/16/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,128.00	\$ 13.70
22953	Installed/Active	09/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 6.61
22954	Installed/Active	09/14/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,172.00	\$ 13.70
22955	Installed/Active	09/16/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22956	Installed/Active	09/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22957	Installed/Active	09/06/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22958	Installed/Active	09/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22959	Installed/Active	09/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,110.00	\$ 13.70
22960	Installed/Active	09/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,117.00	\$ 13.70
22961	Installed/Active	09/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22962	Installed/Active	09/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.39	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
22963	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22964	Installed/Active	09/18/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22965	Installed/Active	09/22/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 19.01
22966	Installed/Active	09/24/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 6.61
22967	Installed/Active	09/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22968	Installed/Active	09/23/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22969	Installed/Active	09/18/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,092.55	\$ 13.70
22970	Installed/Active	09/20/2017	G82156	RUUD/RHEEM	\$ 5,074.00	\$ 61.45
22971	Installed/Active	09/19/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
22972	Installed/Active	09/13/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
22973	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22974	Installed/Active	09/22/2017	G82156	RUUD/RHEEM	\$ 4,989.00	\$ 61.45
22975	Installed/Active	09/29/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,289.00	\$ 13.70
22976	Installed/Active	09/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,193.00	\$ 13.70
22977	Installed/Active	10/01/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22978	Installed/Active	09/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22979	Installed/Active	09/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,140.24	\$ 8.35
22980	Installed/Active	09/13/2017	G7575	RUUD/RHEEM	\$ 2,694.00	\$ 45.88
22981	Installed/Active	09/16/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,114.00	\$ 13.70
22982	Installed/Active	09/15/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,189.00	\$ 13.70
22983	Installed/Active	09/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,099.00	\$ 6.61
22984	Installed/Active	09/14/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 850.00	\$ 13.70
22985	Installed/Active	09/15/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,089.00	\$ 19.43
22986	Installed/Active	09/04/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
22987	Installed/Active	09/13/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,119.00	\$ 13.70
22988	Installed/Active	09/07/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,079.00	\$ 6.61
22989	Installed/Active	09/05/2017	PROG5038NRH60	RUUD/RHEEM	\$ 850.00	\$ 13.70
22990	Installed/Active	09/08/2017	RG130T6N	BRADFORD WHITE	\$ 1,417.00	\$ 8.35
22991	Installed/Active	09/19/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,035.65	\$ 19.43
22992	Installed/Active	09/20/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,159.00	\$ 8.35
22993	Installed/Active	09/20/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
22994	Installed/Active	09/20/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
22995	Installed/Active	09/24/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
22996	Installed/Active	09/18/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
22997	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22998	Installed/Active	09/20/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,142.55	\$ 13.70
22999	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,189.00	\$ 13.70
23000	Installed/Active	09/21/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,139.00	\$ 13.70
23001	Installed/Active	09/23/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,133.61	\$ 6.61
23002	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
23003	Installed/Active	09/22/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 8.35
23004	Installed/Active	09/19/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,114.21	\$ 13.70
23005	Installed/Active	09/23/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,156.96	\$ 13.70
23006	Installed/Active	09/22/2017	PROG50S40NRH61	RUUD/RHEEM	\$ 1,332.55	\$ 13.70
23007	Installed/Active	09/28/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,135.65	\$ 13.70
23008	Installed/Active	09/27/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,114.00	\$ 6.61
23009	Installed/Active	09/27/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 1,949.00	\$ 19.43
23010	Installed/Active	09/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,169.00	\$ 6.61
23011	Installed/Active	09/19/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
23012	Installed/Active	09/19/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
23013	Installed/Active	09/25/2017	G76200	RUUD/RHEEM	\$ 5,029.00	\$ 71.47
23014	Installed/Active	10/01/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,169.00	\$ 6.61
23015	Installed/Active	09/30/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
23016	Installed/Active	09/25/2017	G82156	RUUD/RHEEM	\$ 4,989.00	\$ 61.45
23017	Installed/Active	09/29/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,231.00	\$ 16.87
23018	Installed/Active	09/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
23019	Installed/Active	09/25/2017	PROG4038NRH62	RUUD/RHEEM	\$ 1,099.00	\$ 13.70
23020	Installed/Active	09/25/2017	PROG40S38NRH62	RUUD/RHEEM	\$ 1,029.00	\$ 13.70
23021	Installed/Active	11/09/2017	PROG4860NRH60	RUUD/RHEEM	\$ 1,342.15	\$ 19.01
23022	Installed/Active	09/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
23023	Installed/Active	09/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,153.61	\$ 13.70
23024	Installed/Active	09/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
23025	Installed/Active	09/27/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 13.70
23026	Installed/Active	09/29/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,174.00	\$ 13.70
23027	Installed/Active	09/26/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 6.61
23028	Installed/Active	09/30/2017	PROG5036NRH60DV	RUUD/RHEEM	\$ 2,053.61	\$ 19.43
23029	Installed/Active	10/15/2017	PROG5038NRU60	RHEEM	\$ 1,153.61	\$ 13.70
23030	Installed/Active	10/06/2017	PROG40S38NRH62	RHEEM	\$ 1,169.00	\$ 16.87
23031	Installed/Active	10/13/2017	PROG5038NRU60	RHEEM	\$ 1,172.15	\$ 13.70
23032	Installed/Active	10/13/2017	PROG4038NRH62	RHEEM	\$ 1,231.00	\$ 6.61
23033	Installed/Active	09/29/2017	PROG5036NRH60DV	RHEEM	\$ 2,019.00	\$ 11.98
23034	Installed/Active	10/01/2017	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 13.70
23035	Installed/Active	09/26/2017	PROG5036NRH60DV	RHEEM	\$ 2,042.55	\$ 19.43
23036	Installed/Active	09/28/2017	PROG5036NRH60DV	RHEEM	\$ 2,014.21	\$ 19.43
23037	Installed/Active	09/25/2017	G75125	RUUD/RHEEM	\$ 4,244.55	\$ 45.88
23038	Installed/Active	09/27/2017	G91200	RUUD/RHEEM	\$ 5,339.00	\$ 71.47
23039	Installed/Active	09/28/2017	G91200	RUUD/RHEEM	\$ 5,344.00	\$ 71.47
23040	Installed/Active	10/06/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 6.61
23041	Installed/Active	10/08/2017	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 13.70
23042	Installed/Active	10/03/2017	PROG40S38NRH62	RHEEM	\$ 1,108.00	\$ 13.70
23043	Installed/Active	10/03/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23044	Installed/Active	10/06/2017	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 13.70
23045	Installed/Active	10/07/2017	PROG5036NRH60DV	RHEEM	\$ 2,014.00	\$ 19.43
23046	Installed/Active	10/04/2017	PROG5036NRH60DV	RHEEM	\$ 2,089.00	\$ 19.43
23047	Installed/Active	10/03/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23048	Installed/Active	10/04/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23049	Installed/Active	10/02/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 13.70
23050	Installed/Active	10/07/2017	G82156	RUUD/RHEEM	\$ 5,159.50	\$ 61.45
23051	Installed/Active	10/06/2017	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 6.61
23052	Installed/Active	10/12/2017	PROG40S38NRH62	Rheem	\$ 1,029.00	\$ 13.70
23053	Installed/Active	10/12/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23054	Installed/Active	10/10/2017	PROG5038NRH60	Rheem	\$ 1,118.59	\$ 6.61
23055	Installed/Active	10/11/2017	PROG4038NRH62	Rheem	\$ 1,122.55	\$ 13.70
23056	Installed/Active	10/10/2017	G91200	Rheem	\$ 5,229.00	\$ 71.47
23057	Installed/Active	10/15/2017	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 13.70
23058	Installed/Active	10/14/2017	RG250H6N	RHEEM	\$ 1,150.00	\$ 19.01
23059	Installed/Active	10/13/2017	PROG50S40NRH61	Rheem	\$ 850.00	\$ 13.70
23060	Installed/Active	10/10/2017	PROG5038NRH60	Rheem	\$ 1,172.00	\$ 13.70
23061	Installed/Active	10/05/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23062	Installed/Active	10/06/2017	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 13.70
23063	Installed/Active	10/02/2017	G91200	RUUD/RHEEM	\$ 5,229.00	\$ 71.47
23064	Installed/Active	10/02/2017	PROG5036NRH60DV	RHEEM	\$ 2,042.55	\$ 13.70
23065	Installed/Active	10/04/2017	PROG40S38NRH62	RHEEM	\$ 1,129.00	\$ 8.35
23066	Installed/Active	10/04/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23067	Installed/Active	10/03/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 19.43
23068	Installed/Active	10/05/2017	PROG5038NRH60	RHEEM	\$ 1,185.50	\$ 19.01
23069	Installed/Active	10/08/2017	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 13.70
23070	Installed/Active	10/03/2017	PROG5038NRH60	RHEEM	\$ 1,193.00	\$ 6.61
23071	Installed/Active	10/07/2017	PROG5038NRH60	RHEEM	\$ 1,112.55	\$ 13.70
23072	Installed/Active	10/05/2017	PROG5036NRH60DV	RHEEM	\$ 2,008.10	\$ 19.43
23073	Installed/Active	10/02/2017	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 13.70
23074	Installed/Active	10/02/2017	PROG4038NRH62	RHEEM	\$ 1,094.21	\$ 8.35
23075	Installed/Active	10/02/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23076	Installed/Active	10/04/2017	PROG4038NRH62	RHEEM	\$ 1,120.24	\$ 13.70
23077	Installed/Active	10/06/2017	PROG5038NRH60	RHEEM	\$ 1,159.00	\$ 13.70
23078	Installed/Active	09/27/2017	RG2DV40S6N	BRADFORD WHITE	\$ 2,254.21	\$ 13.70
23079	Installed/Active	10/11/2017	PROG5036NRH60DV	Rheem	\$ 1,075.00	\$ 19.43
23080	Installed/Active	10/14/2017	PROG5038NRH60	Rheem	\$ 850.00	\$ 6.61
23081	Installed/Active	10/10/2017	PROG50S40NRH61	Rheem	\$ 850.00	\$ 13.70
23082	Installed/Active	10/14/2017	PROG5038NRH60	Rheem	\$ 1,118.59	\$ 8.35
23083	Installed/Active	10/10/2017	PROG5038NRH60	Rheem	\$ 1,140.24	\$ 13.70
23084	Installed/Active	10/11/2017	PROG5038NRH60	Rheem	\$ 1,228.00	\$ 13.70
23085	Installed/Active	10/12/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23086	Installed/Active	10/09/2017	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 6.61
23087	Installed/Active	10/14/2017	G91200	Rheem	\$ 5,294.21	\$ 71.47
23088	Installed/Active	10/13/2017	PROG4038NRH62	Rheem	\$ 1,144.00	\$ 13.70
23089	Installed/Active	10/13/2017	PROG5036NRH60	RHEEM	\$ 2,014.00	\$ 19.43
23090	Installed/Active	10/11/2017	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 13.70
23091	Installed/Active	10/12/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23092	Installed/Active	10/12/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23093	Installed/Active	10/14/2017	G75125	Rheem	\$ 4,199.00	\$ 45.88
23094	Installed/Active	10/14/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 6.61
23095	Installed/Active	10/22/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.61
23096	Installed/Active	10/17/2017	PROG4038NRH62	RHEEM	\$ 1,114.00	\$ 6.61
23097	Installed/Active	10/18/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 19.01
23098	Installed/Active	10/20/2017	PROG50S40NRH61	RHEEM	\$ 1,300.35	\$ 13.70
23099	Installed/Active	10/17/2017	PROG5036NRH60DV	RHEEM	\$ 2,075.00	\$ 19.43
23100	Installed/Active	10/11/2017	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 6.61
23101	Installed/Active	10/11/2017	PROG40S38NRH62	RHEEM	\$ 1,120.24	\$ 13.70
23102	Installed/Active	10/12/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 8.35
23103	Installed/Active	10/04/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 13.70
23104	Installed/Active	10/20/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 13.70
23105	Installed/Active	10/18/2017	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 6.61
23106	Installed/Active	10/18/2017	PROG5036NRH60	RHEEM	\$ 2,035.65	\$ 19.43
23107	Installed/Active	10/16/2017	PROG5038NRH60	Rheem	\$ 1,140.24	\$ 8.35
23108	Installed/Active	10/23/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 13.70
23109	Installed/Active	10/27/2017	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 13.70
23110	Installed/Active	10/24/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 13.70
23111	Installed/Active	10/19/2017	RG2DV40S6N	Bradford White	\$ 2,189.00	\$ 19.43
23112	Installed/Active	10/27/2017	RG2DV40S6N	Bradford White	\$ 2,189.00	\$ 19.43
23113	Installed/Active	10/20/2017	PROG40S38NRH62	Rheem	\$ 1,098.59	\$ 13.70
23114	Installed/Active	10/17/2017	PROG5038NRH60	RHEEM	\$ 1,110.00	\$ 13.70
23115	Installed/Active	10/16/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23116	Installed/Active	10/21/2017	PROG4038NRH62	RHEEM	\$ 1,152.00	\$ 13.70
23117	Installed/Active	10/17/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 13.70
23118	Installed/Active	10/20/2017	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 6.61
23119	Installed/Active	10/19/2017	PROG5038NRH60	RHEEM	\$ 1,110.00	\$ 13.70
23120	Installed/Active	10/30/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 6.61
23121	Installed/Active	11/05/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23122	Installed/Active	10/25/2017	G82156	RHEEM	\$ 4,989.00	\$ 61.45
23123	Installed/Active	10/25/2017	G82156	RHEEM	\$ 4,989.00	\$ 61.45
23124	Installed/Active	10/25/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23125	Installed/Active	10/25/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23126	Installed/Active	10/28/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23127	Installed/Active	10/26/2017	PROG40S38NRH62	RHEEM	\$ 1,098.59	\$ 6.61
23128	Installed/Active	10/28/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23129	Installed/Active	10/23/2017	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 13.70
23130	Installed/Active	10/26/2017	PROG4038NRH62	RHEEM	\$ 1,098.59	\$ 13.70
23131	Installed/Active	10/27/2017	PROG50S40NRH61	RHEEM	\$ 1,302.83	\$ 13.70
23132	Installed/Active	10/23/2017	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 13.70
23133	Installed/Active	10/28/2017	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 13.70
23134	Installed/Active	10/24/2017	PROG5038NRH60	RHEEM	\$ 1,149.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23135	Installed/Active	10/27/2017	PROG5036NRH60	RHEEM	\$ 2,042.55	\$ 19.43
23136	Installed/Active	10/28/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,282.55	\$ 19.43
23137	Installed/Active	10/23/2017	RG2DV40S6N	BRADFORD WHITE	\$ 2,274.00	\$ 19.43
23138	Installed/Active	10/19/2017	PROG4038NRH62	RHEEM	\$ 1,115.65	\$ 13.70
23139	Installed/Active	10/25/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 6.61
23140	Installed/Active	10/23/2017	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 13.70
23141	Installed/Active	10/27/2017	PROG4038NRH62	RHEEM	\$ 1,231.00	\$ 6.61
23142	Installed/Active	10/26/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23143	Installed/Active	11/05/2017	RG2DV50S6N	Bradford White	\$ 2,254.21	\$ 19.43
23144	Installed/Active	11/02/2017	PROG5038NRH60	Rheem	\$ 1,119.00	\$ 13.70
23145	Installed/Active	10/30/2017	PROG5038NRH60	Rheem	\$ 1,118.59	\$ 13.70
23146	Installed/Active	11/03/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23147	Installed/Active	11/05/2017	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 6.61
23148	Installed/Active	11/18/2017	PROG5038NRH60	Rheem	\$ 1,116.50	\$ 13.70
23149	Installed/Active	11/19/2017	PROG5038NRH60	Rheem	\$ 1,251.00	\$ 13.70
23150	Installed/Active	11/16/2017	PROG50S40NRH61	Rheem	\$ 1,239.00	\$ 13.70
23151	Installed/Active	11/16/2017	PROG5038NRH60	Rheem	\$ 850.00	\$ 6.61
23152	Installed/Active	11/16/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23153	Installed/Active	11/17/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23154	Installed/Active	11/19/2017	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 13.70
23155	Installed/Active	10/30/2017	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 13.70
23156	Installed/Active	11/01/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23157	Installed/Active	11/01/2017	PROG4038NRH62	RHEEM	\$ 1,099.39	\$ 13.70
23158	Installed/Active	10/31/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23159	Installed/Active	11/02/2017	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 13.70
23160	Installed/Active	10/30/2017	PROG4038NRH62	RHEEM	\$ 1,098.59	\$ 13.70
23161	Installed/Active	11/04/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.61
23162	Installed/Active	11/02/2017	G82156	RHEEM	\$ 4,989.00	\$ 61.45
23163	Installed/Active	11/02/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23164	Installed/Active	11/07/2017	PROG4038NRH62	RHEEM	\$ 1,153.61	\$ 6.61
23165	Installed/Active	11/12/2017	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 19.43
23166	Installed/Active	11/09/2017	PROG4038NRH62	RHEEM	\$ 1,092.83	\$ 6.61
23167	Installed/Active	11/09/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 6.61
23168	Installed/Active	11/09/2017	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 19.43
23169	Installed/Active	11/11/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,254.21	\$ 19.43
23170	Installed/Active	11/11/2017	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 13.70
23171	Installed/Active	11/14/2017	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 19.43
23172	Installed/Active	11/15/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23173	Installed/Active	11/19/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23174	Installed/Active	11/18/2017	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 8.35
23175	Installed/Active	11/15/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 13.70
23176	Installed/Active	11/15/2017	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 13.70
23177	Installed/Active	11/17/2017	PROG5036NRH60	RHEEM	\$ 2,014.00	\$ 13.70
23178	Installed/Active	11/17/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,258.59	\$ 19.43
23179	Installed/Active	11/14/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23180	Installed/Active	11/14/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23181	Installed/Active	11/13/2017	PROG4038NRH62	RHEEM	\$ 1,114.00	\$ 6.61
23182	Installed/Active	11/04/2017	PROG4038NRH62	Rheem	\$ 1,105.08	\$ 6.61
23183	Installed/Active	11/03/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23184	Installed/Active	10/31/2017	RG250H6N	Bradford White	\$ 1,763.61	\$ 13.70
23185	Installed/Active	10/31/2017	PROG5038NRH60	Rheem	\$ 1,119.00	\$ 13.70
23186	Installed/Active	10/30/2017	PROG40S38NRH62	Rheem	\$ 1,114.00	\$ 13.70
23187	Installed/Active	11/03/2017	PROG5038NRH60	Rheem	\$ 1,189.00	\$ 13.70
23188	Installed/Active	11/02/2017	PROG5038NRH60	Rheem	\$ 1,949.00	\$ 19.43
23189	Installed/Active	11/01/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23190	Installed/Active	11/06/2017	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 13.70
23191	Installed/Active	11/06/2017	PROG5038NRH60	RHEEM	\$ 1,112.83	\$ 13.70
23192	Installed/Active	11/12/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23193	Installed/Active	11/06/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23194	Installed/Active	11/11/2017	PROG5038NRH60	Rheem	\$ 1,148.00	\$ 13.70
23195	Installed/Active	11/08/2017	PROG40S38NRH62	Rheem	\$ 1,099.00	\$ 6.61
23196	Installed/Active	11/07/2017	PROG5038NRH60	Rheem	\$ 1,114.00	\$ 13.70
23197	Installed/Active	11/08/2017	PROG5038NRH60	Rheem	\$ 850.00	\$ 13.70
23198	Installed/Active	11/07/2017	PROG50S40NRH61	Rheem	\$ 850.00	\$ 6.61
23199	Installed/Active	11/12/2017	PROG5038NRH60	Rheem	\$ 1,099.50	\$ 13.70
23200	Installed/Active	11/08/2017	PROG5038NRH60	Rheem	\$ 850.00	\$ 13.70
23201	Installed/Active	11/12/2017	G75125	Rheem	\$ 4,264.21	\$ 45.88
23202	Installed/Active	11/06/2017	PROG5038NRH60	Rheem	\$ 2,008.10	\$ 19.43
23203	Installed/Active	11/11/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 13.70
23204	Installed/Active	11/10/2017	PROG40S38NRH62	Rheem	\$ 1,029.00	\$ 6.61
23205	Installed/Active	11/06/2017	FSG50	AO SMITH	\$ 850.00	\$ 6.61
23206	Installed/Active	11/09/2017	PROG5038NRH60	Rheem	\$ 1,135.65	\$ 6.61
23207	Installed/Active	11/09/2017	PROG5038NRH60	Rheem	\$ 1,110.35	\$ 13.70
23208	Installed/Active	11/10/2017	PROG5038NRH60	Rheem	\$ 1,172.00	\$ 13.70
23209	Installed/Active	11/08/2017	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 13.70
23210	Installed/Active	11/11/2017	RG2DV50S6N	Bradford White	\$ 2,254.21	\$ 19.43
23211	Installed/Active	10/31/2017	G76200	Rheem	\$ 5,029.00	\$ 71.47
23212	Installed/Active	11/06/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 6.61
23213	Installed/Active	11/14/2017	PROG5038NRH60	Rheem	\$ 1,098.15	\$ 13.70
23214	Installed/Active	11/13/2017	PROG5038NRH60	Rheem	\$ 1,118.59	\$ 13.70
23215	Installed/Active	11/15/2017	RG2DV50S6N	Bradford White	\$ 1,075.00	\$ 19.43
23216	Installed/Active	11/18/2017	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 13.70
23217	Installed/Active	11/16/2017	PROG5038NRH60	Rheem	\$ 1,119.00	\$ 13.70
23218	Installed/Active	11/14/2017	PROG5038NRH60	Rheem	\$ 1,114.21	\$ 13.70
23219	Installed/Active	11/16/2017	PROG5038NRH60	Rheem	\$ 2,014.21	\$ 19.43
23220	Installed/Active	11/19/2017	PROG50S40NRH61	Rheem	\$ 1,239.00	\$ 13.70

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23221	Installed/Active	11/13/2017	RG2DV50S6N	Bradford White	\$ 2,252.55	\$ 19.43
23222	Installed/Active	11/13/2017	PROG5036NRH60DV	Rheem	\$ 2,089.00	\$ 13.70
23223	Installed/Active	11/19/2017	PROG5038NRH60	Rheem	\$ 850.00	\$ 13.70
23224	Installed/Active	11/13/2017	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 13.70
23225	Installed/Active	11/14/2017	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 13.70
23226	Installed/Active	11/29/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23227	Installed/Active	12/02/2017	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 13.70
23228	Installed/Active	11/28/2017	PROG5038NRH60	RHEEM	\$ 1,175.00	\$ 13.70
23229	Installed/Active	12/02/2017	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 13.70
23230	Installed/Active	12/02/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,329.00	\$ 19.43
23231	Installed/Active	12/01/2017	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 13.70
23232	Installed/Active	11/27/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23233	Installed/Active	12/02/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23234	Installed/Active	11/29/2017	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23235	Installed/Active	11/29/2017	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 8.35
23236	Installed/Active	11/29/2017	PROG50S40NRH61	RHEEM	\$ 1,309.00	\$ 13.70
23237	Installed/Active	12/02/2017	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 13.70
23238	Installed/Active	12/03/2017	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 6.61
23239	Installed/Active	12/01/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23240	Installed/Active	11/17/2017	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 19.43
23241	Installed/Active	12/01/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23242	Installed/Active	12/03/2017	PROG4860NRH60	RHEEM	\$ 1,289.00	\$ 19.01
23243	Installed/Active	11/13/2017	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 6.61
23244	Installed/Active	11/17/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 13.70
23245	Installed/Active	11/18/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23246	Installed/Active	11/21/2017	PROG4860NRH60	RHEEM	\$ 1,219.00	\$ 19.01
23247	Installed/Active	11/26/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23248	Installed/Active	11/26/2017	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 13.70
23249	Installed/Active	11/24/2017	G82156	RHEEM	\$ 5,040.05	\$ 61.45
23250	Installed/Active	11/22/2017	RG140T6N	BRADFORD WHITE	\$ 1,198.00	\$ 13.70
23251	Installed/Active	11/21/2017	PH19980	PHOENIX	\$ 7,641.00	\$ 71.47
23252	Installed/Active	11/21/2017	PH19980	PHOENIX	\$ 7,641.00	\$ 71.47
23253	Installed/Active	11/24/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23254	Installed/Active	11/21/2017	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 13.70
23255	Installed/Active	11/26/2017	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 13.70
23256	Installed/Active	11/22/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 6.61
23257	Installed/Active	11/09/2017	PROG5036NRH60	RHEEM	\$ 2,089.00	\$ 19.43
23258	Installed/Active	11/20/2017	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 13.70
23259	Installed/Active	11/20/2017	RG250H6N	BRADFORD WHITE	\$ 1,795.50	\$ 19.01
23260	Installed/Active	11/20/2017	PROG5038NRH60	RHEEM	\$ 1,189.00	\$ 13.70
23261	Installed/Active	11/22/2017	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 13.70
23262	Installed/Active	11/25/2017	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 13.70
23263	Installed/Active	11/20/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23264	Installed/Active	11/22/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23265	Installed/Active	11/20/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23266	Installed/Active	11/20/2017	PROG40S38NRH62	RHEEM	\$ 1,120.24	\$ 13.70
23267	Installed/Active	11/21/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.61
23268	Installed/Active	11/27/2017	RG140T6N	BRADFORD WHITE	\$ 1,188.59	\$ 6.61
23269	Installed/Active	11/30/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,247.47	\$ 19.43
23270	Installed/Active	12/03/2017	PROG4038NRH62	RHEEM	\$ 1,154.00	\$ 13.70
23271	Installed/Active	12/01/2017	RG2DV40S6N	BRADFORD WHITE	\$ 2,275.65	\$ 19.43
23272	Installed/Active	11/29/2017	PROG5036NRH60	RHEEM	\$ 2,035.65	\$ 19.43
23273	Installed/Active	11/28/2017	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23274	Installed/Active	11/27/2017	PROG50S40NRH61	RHEEM	\$ 1,329.00	\$ 13.70
23275	Installed/Active	11/29/2017	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 13.70
23276	Installed/Active	12/01/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23277	Installed/Active	11/30/2017	PROG4038NRH62	RHEEM	\$ 1,099.39	\$ 13.70
23278	Installed/Active	11/30/2017	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 19.43
23279	Installed/Active	12/03/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 8.35
23280	Installed/Active	12/01/2017	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 13.70
23281	Installed/Active	12/07/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 6.61
23282	Installed/Active	12/07/2017	PROG5038NRH60	RHEEM	\$ 1,156.75	\$ 13.70
23283	Installed/Active	12/10/2017	PROG5036NRH60	RHEEM	\$ 2,072.15	\$ 19.43
23284	Installed/Active	12/08/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23285	Installed/Active	12/06/2017	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 13.70
23286	Installed/Active	12/06/2017	PROG4038NRH62	RHEEM	\$ 1,098.59	\$ 6.61
23287	Installed/Active	12/07/2017	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 13.70
23288	Installed/Active	12/04/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 19.43
23289	Installed/Active	12/08/2017	PROG4038NRH62	RHEEM	\$ 1,079.50	\$ 8.35
23290	Installed/Active	12/06/2017	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 13.70
23291	Installed/Active	12/05/2017	RG250H6N	BRADFORD WHITE	\$ 1,727.00	\$ 19.01
23292	Installed/Active	11/30/2017	PROG5038NRH60	RHEEM	\$ 1,189.00	\$ 13.70
23293	Installed/Active	12/10/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23294	Installed/Active	12/04/2017	PROG5038NRH60	RHEEM	\$ 1,110.35	\$ 6.61
23295	Installed/Active	12/08/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23296	Installed/Active	12/05/2017	PROG50S40NRH61	RHEEM	\$ 1,399.00	\$ 13.70
23297	Installed/Active	12/05/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 19.43
23298	Installed/Active	11/17/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23299	Installed/Active	11/22/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23300	Installed/Active	11/21/2017	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 13.70
23301	Installed/Active	11/22/2017	G91200	RHEEM	\$ 5,229.00	\$ 71.47
23302	Installed/Active	11/21/2017	PROG50S40NRH61	RHEEM	\$ 1,325.65	\$ 13.70
23303	Installed/Active	12/10/2017	G91200	RHEEM	\$ 5,322.55	\$ 71.47
23304	Installed/Active	12/09/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23305	Installed/Active	10/17/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 13.70
23306	Installed/Active	12/17/2017	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 6.61

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23307	Installed/Active	12/12/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23308	Installed/Active	12/13/2017	PROG5038NRH60	RHEEM	\$ 1,193.00	\$ 13.70
23309	Installed/Active	12/16/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 13.70
23310	Installed/Active	12/17/2017	PROG5038NRH60	RHEEM	\$ 1,100.05	\$ 6.61
23311	Installed/Active	12/17/2017	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 6.61
23312	Installed/Active	12/12/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 6.61
23313	Installed/Active	12/13/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 13.70
23314	Installed/Active	12/13/2017	PROG5038NRH60	RHEEM	\$ 1,172.15	\$ 13.70
23315	Installed/Active	12/14/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 13.70
23316	Installed/Active	12/15/2017	PROG40S38NRH62	RHEEM	\$ 1,231.00	\$ 13.70
23317	Installed/Active	12/15/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.61
23318	Installed/Active	12/15/2017	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 6.61
23319	Installed/Active	12/15/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 13.70
23320	Installed/Active	12/17/2017	G75125	RHEEM	\$ 4,199.00	\$ 45.88
23321	Installed/Active	12/09/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 13.70
23322	Installed/Active	12/12/2017	PROG4038NRH62	RHEEM	\$ 1,152.00	\$ 6.61
23323	Installed/Active	12/12/2017	RG2DV50S6N	BRADFORD WHITE	\$ 2,239.00	\$ 19.43
23324	Installed/Active	12/19/2017	PROG5038NRH60	RHEEM	\$ 1,172.00	\$ 12.76
23325	Installed/Active	12/13/2017	PROG5036NRH60	RHEEM	\$ 2,042.55	\$ 19.43
23326	Installed/Active	12/15/2017	G75125	RHEEM	\$ 4,199.00	\$ 45.88
23327	Installed/Active	12/12/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 6.61
23328	Installed/Active	12/12/2017	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 13.70
23329	Installed/Active	12/13/2017	PROG5036NRH60	RHEEM	\$ 2,000.05	\$ 19.43
23330	Installed/Active	12/14/2017	RG140T6N	Bradford White	\$ 1,119.00	\$ 13.70
23331	Installed/Active	12/21/2017	PROG5038NRH60	RHEEM	\$ 1,100.05	\$ 6.16
23332	Installed/Active	12/23/2017	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 12.76
23333	Installed/Active	12/31/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 6.16
23334	Installed/Active	12/27/2017	PROG5038NRH60	RHEEM	\$ 1,169.00	\$ 12.76
23335	Installed/Active	12/26/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 12.76
23336	Installed/Active	12/30/2017	PROG4038NRH62	RHEEM	\$ 1,133.61	\$ 7.77
23337	Installed/Active	12/31/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23338	Installed/Active	12/31/2017	PROG4038NRH62	RHEEM	\$ 1,079.50	\$ 12.76
23339	Installed/Active	12/28/2017	PROG4038NRH62	RHEEM	\$ 1,094.21	\$ 6.16
23340	Installed/Active	12/26/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 6.16
23341	Installed/Active	12/28/2017	G82156	RHEEM	\$ 4,989.00	\$ 57.23
23342	Installed/Active	12/28/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.16
23343	Installed/Active	12/29/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 12.76
23344	Installed/Active	12/30/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 12.76
23345	Installed/Active	12/20/2017	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 12.76
23346	Installed/Active	12/22/2017	PROG5038NRH60	RUUD/RHEEM	\$ 1,049.00	\$ 12.76
23347	Installed/Active	12/22/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23348	Installed/Active	12/23/2017	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 7.77
23349	Installed/Active	12/24/2017	PROG5038NRH60	RHEEM	\$ 850.00	\$ 12.76
23350	Installed/Active	12/18/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 13.70
23351	Installed/Active	12/22/2017	PROG5036NRH60DV	RHEEM	\$ 1,999.00	\$ 18.09
23352	Installed/Active	12/22/2017	PROG5038NRH60	RHEEM	\$ 1,999.00	\$ 12.76
23353	Installed/Active	12/22/2017	PROG5038NRH60	RHEEM	\$ 1,999.00	\$ 12.76
23354	Installed/Active	12/20/2017	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 6.16
23355	Installed/Active	12/21/2017	RG2DV50S6N	Bradford White	\$ 2,279.00	\$ 12.76
23356	Installed/Active	12/23/2017	PROG5036NRH60DV	RHEEM	\$ 2,042.55	\$ 18.09
23357	Installed/Active	12/19/2017	G75125	RHEEM	\$ 4,199.00	\$ 42.74
23358	Installed/Active	12/21/2017	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.76
23359	Installed/Active	12/23/2017	PROG5038NRH60	RHEEM	\$ 1,114.21	\$ 12.76
23360	Installed/Active	12/20/2017	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23361	Installed/Active	11/25/2017	G82156	RHEEM	\$ 5,074.00	\$ 61.45
23362	Installed/Active	12/29/2017	PROG50S40NRH61	RHEEM	\$ 1,309.00	\$ 12.76
23363	Installed/Active	12/28/2017	G82156	RHEEM	\$ 5,054.21	\$ 57.23
23364	Installed/Active	12/29/2017	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23365	Installed/Active	01/04/2018	PROG5038NRH60	RHEEM	\$ 1,112.83	\$ 6.16
23366	Installed/Active	01/04/2018	RG250H6N	Bradford White	\$ 1,659.00	\$ 17.71
23367	Installed/Active	01/03/2018	G75125	RHEEM	\$ 4,199.00	\$ 42.74
23368	Installed/Active	01/10/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23369	Installed/Active	01/12/2018	PROG4038NRH62	RHEEM	\$ 1,094.00	\$ 6.16
23370	Installed/Active	01/12/2018	PROG5038NRH60	RHEEM	\$ 1,159.00	\$ 12.76
23371	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.76
23372	Installed/Active	01/08/2018	PROG5038NRH60	RHEEM	\$ 1,156.96	\$ 12.76
23373	Installed/Active	01/12/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 18.09
23374	Installed/Active	01/10/2018	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 6.16
23375	Installed/Active	01/10/2018	PROG5036NRH60	RHEEM	\$ 2,035.65	\$ 18.09
23376	Installed/Active	01/09/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23377	Installed/Active	01/10/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23378	Installed/Active	01/12/2018	PROG5038NRH60	RHEEM	\$ 1,119.00	\$ 12.76
23379	Installed/Active	01/09/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 7.77
23380	Installed/Active	01/09/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23381	Installed/Active	01/08/2018	RG250H6N	Bradford White	\$ 1,750.24	\$ 17.71
23382	Installed/Active	12/27/2017	G75125	RHEEM	\$ 4,249.00	\$ 42.74
23383	Installed/Active	12/26/2017	PROG4038NRH62	RHEEM	\$ 1,084.00	\$ 6.16
23384	Installed/Active	01/03/2018	PROG5038NRH60	RHEEM	\$ 1,131.00	\$ 12.76
23385	Installed/Active	01/04/2018	PROG5038NRH60	RHEEM	\$ 1,251.00	\$ 12.76
23386	Installed/Active	01/02/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23387	Installed/Active	01/04/2018	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 12.76
23388	Installed/Active	01/03/2018	PROG4038NRH62	RHEEM	\$ 1,120.24	\$ 12.76
23389	Installed/Active	01/02/2018	G82156	RHEEM	\$ 4,989.00	\$ 57.23
23390	Installed/Active	01/05/2018	G91200	RHEEM	\$ 5,494.00	\$ 66.56
23391	Installed/Active	01/06/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.76
23392	Installed/Active	01/05/2018	PROG5038NRH60	RHEEM	\$ 1,118.59	\$ 12.76

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23393	Installed/Active	01/03/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.76
23394	Installed/Active	01/07/2018	PROG4038NRH62	RHEEM	\$ 1,096.74	\$ 12.76
23395	Installed/Active	01/06/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23396	Installed/Active	01/05/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 7.77
23397	Installed/Active	01/25/1993	FSG50	AO SMITH	\$ 850.00	
23398	Installed/Active	01/09/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.76
23399	Installed/Active	01/12/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23400	Installed/Active	01/12/2018	PROG5038NRH60	Rheem	\$ 1,114.00	\$ 6.16
23401	Installed/Active	01/13/2018	PROG40S38NRH62	Rheem	\$ 1,029.00	\$ 12.76
23402	Installed/Active	01/13/2018	RG2DV50S6N	Bradford White	\$ 2,274.00	\$ 18.09
23403	Installed/Active	01/13/2018	PROG5038NRH60	Rheem	\$ 1,135.65	\$ 12.76
23404	Installed/Active	08/30/2016	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 69.94
23405	Installed/Active	08/05/2017	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.61
23406	Installed/Active	10/12/2017	G91200	RHEEM	\$ 5,477.00	\$ 71.47
23407	Installed/Active	10/09/2017	PROG4038NRH62	RHEEM	\$ 1,099.00	\$ 13.70
23408	Installed/Active	10/24/2017	PROG5038NRH60	Rheem	\$ 1,119.00	\$ 13.70
23409	Installed/Active	01/03/2018	RG250H6N	Bradford White	\$ 1,729.00	\$ 17.71
23410	Installed/Active	01/03/2018	PROG5038NRH60	Rheem	\$ 1,135.65	\$ 12.76
23411	Installed/Active	01/08/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23412	Installed/Active	11/29/2017	PROG5036NRH60	RHEEM	\$ 2,034.00	\$ 19.01
23413	Installed/Active	01/13/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23414	Installed/Active	01/18/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23415	Installed/Active	01/16/2018	G75125	RHEEM	\$ 4,464.00	\$ 42.74
23416	Installed/Active	01/16/2018	PROG30S30NRH63	RHEEM	\$ 1,418.59	\$ 6.16
23417	Installed/Active	01/15/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 17.71
23418	Installed/Active	01/16/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,256.74	\$ 18.09
23419	Installed/Active	12/29/2017	PROG5038NRH60	Rheem	\$ 1,156.96	\$ 12.76
23420	Installed/Active	01/15/2018	RG2DV50S6N	Bradford White	\$ 2,329.00	\$ 18.09
23421	Installed/Active	01/18/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 18.09
23422	Installed/Active	01/17/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 12.76
23423	Installed/Active	01/17/2018	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 6.16
23424	Installed/Active	11/08/2017	PROG5036NRH60DV	Rheem	\$ 1,999.00	\$ 13.70
23425	Installed/Active	11/18/2017	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 13.70
23426	Installed/Active	11/15/2017	PROG4036NRH62DV	Rheem	\$ 2,081.00	\$ 19.43
23427	Installed/Active	11/29/2017	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 13.70
23428	Installed/Active	01/13/2018	PROG4038NRH62	RHEEM	\$ 1,122.55	\$ 7.77
23429	Installed/Active	01/09/2018	PROG4038NRH62	Rheem	\$ 850.00	\$ 12.76
23430	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,159.00	\$ 12.76
23431	Installed/Active	01/20/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 18.09
23432	Installed/Active	01/21/2018	PROG5038NRH60	RHEEM	\$ 1,136.91	\$ 12.76
23433	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23434	Installed/Active	01/16/2018	PROG50S40NRH61	RHEEM	\$ 1,364.65	\$ 12.76
23435	Installed/Active	01/16/2018	PROG5038NRH60	RHEEM	\$ 1,159.00	\$ 12.76
23436	Installed/Active	01/15/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,275.65	\$ 18.09
23437	Installed/Active	01/20/2018	PROG40S38NRH62	RHEEM	\$ 1,114.00	\$ 12.76
23438	Installed/Active	01/17/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23439	Installed/Active	01/17/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23440	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 12.76
23441	Installed/Active	01/10/2018	PROG4860NRH60	RHEEM	\$ 1,323.61	\$ 12.76
23442	Installed/Active	01/12/2018	GSN03035B	Lochinvar	\$ 1,519.00	\$ 7.77
23443	Installed/Active	01/25/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23444	Installed/Active	01/26/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 18.09
23445	Installed/Active	01/26/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23446	Installed/Active	01/26/2018	PROG5036NRH60DV	Rheem	\$ 2,039.00	\$ 18.09
23447	Installed/Active	10/10/2017	G91200	Rheem	\$ 5,229.00	\$ 71.47
23448	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.76
23449	Installed/Active	01/19/2018	PROG40S38NRH62	Rheem	\$ 1,152.00	\$ 12.76
23450	Installed/Active	01/18/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23451	Installed/Active	01/18/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23452	Installed/Active	01/17/2018	PROG4038NRH62	RHEEM	\$ 1,133.61	\$ 12.76
23453	Installed/Active	01/17/2018	RG2DV50S6N	Bradford White	\$ 2,274.00	\$ 18.09
23454	Installed/Active	12/21/2017	PROG5038NRH60	Rheem	\$ 1,117.00	\$ 12.76
23455	Installed/Active	01/24/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23456	Installed/Active	01/24/2018	PROG4038NRH62	RHEEM	\$ 1,119.00	\$ 6.16
23457	Installed/Active	01/22/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 18.09
23458	Installed/Active	01/24/2018	PROG4860NRH60	RHEEM	\$ 1,283.00	\$ 17.71
23459	Installed/Active	01/27/2018	PROG5038NRH60	RHEEM	\$ 1,136.91	\$ 6.16
23460	Installed/Active	01/22/2018	G76200	RUUD/RHEEM	\$ 5,131.45	\$ 66.56
23461	Installed/Active	01/31/2018	PROG50S40NRH61	Rheem	\$ 1,311.00	\$ 12.76
23462	Installed/Active	01/29/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 18.09
23463	Installed/Active	01/30/2018	PROG4038NRH62	Rheem	\$ 1,115.65	\$ 12.76
23464	Installed/Active	01/30/2018	PROG4038NRH62	Rheem	\$ 1,154.00	\$ 12.76
23465	Installed/Active	02/01/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 17.71
23466	Installed/Active	02/03/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23467	Installed/Active	01/27/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23468	Installed/Active	11/21/2017	PH19980	PHOENIX	\$ 7,641.00	\$ 71.47
23469	Installed/Active	12/23/2017	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23470	Installed/Active	02/05/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 7.77
23471	Installed/Active	01/29/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23472	Installed/Active	01/29/2018	PROG5038NRH60	RHEEM	\$ 1,109.00	\$ 12.76
23473	Installed/Active	01/30/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23474	Installed/Active	01/30/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 7.77
23475	Installed/Active	01/31/2018	PROG5038nrh60	RHEEM	\$ 1,134.00	\$ 12.76
23476	Installed/Active	02/01/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23477	Installed/Active	01/30/2018	PROG5038NRH60	RHEEM	\$ 1,175.00	\$ 12.76
23478	Installed/Active	01/31/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 6.16

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23479	Installed/Active	01/29/2018	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 12.76
23480	Installed/Active	01/31/2018	PROG5038NRH60	RHEEM	\$ 1,136.91	\$ 12.76
23481	Installed/Active	02/02/2018	PROG5038NRH60	RHEEM	\$ 1,127.00	\$ 6.16
23482	Installed/Active	02/04/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,259.39	\$ 18.09
23483	Installed/Active	02/04/2018	PROG5038NRH60	RHEEM	\$ 1,172.00	\$ 6.16
23484	Installed/Active	02/02/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23485	Installed/Active	02/01/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23486	Installed/Active	02/02/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 6.16
23487	Installed/Active	02/03/2018	G76200	RHEEM	\$ 5,139.00	\$ 66.56
23488	Installed/Active	02/02/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23489	Installed/Active	02/09/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23490	Installed/Active	01/25/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23491	Installed/Active	01/27/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.76
23492	Installed/Active	01/22/2018	PROG50S40NRH61	RHEEM	\$ 1,309.39	\$ 12.76
23493	Installed/Active	01/25/2018	PROG5038NRH60	RHEEM	\$ 1,156.75	\$ 12.76
23494	Installed/Active	01/26/2018	PROG5038NRH60	RHEEM	\$ 1,159.00	\$ 17.71
23495	Installed/Active	02/07/2018	PROG5036NRU60	RHEEM	\$ 2,036.91	\$ 18.09
23496	Installed/Active	02/07/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,293.61	\$ 18.09
23497	Installed/Active	02/07/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23498	Installed/Active	02/06/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23499	Installed/Active	02/09/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,242.00	\$ 18.09
23500	Installed/Active	02/04/2018	PROG50S40NRH61	RHEEM	\$ 1,332.55	\$ 7.77
23501	Installed/Active	02/08/2018	PROG4038NRH62	RHEEM	\$ 1,079.50	\$ 6.16
23502	Installed/Active	02/05/2018	PROG2932NRH63	RHEEM	\$ 1,399.00	\$ 6.16
23503	Installed/Active	02/05/2018	PROG5036NRH60	RHEEM	\$ 2,034.00	\$ 18.09
23504	Installed/Active	02/05/2018	PROG4860NRH60	RHEEM	\$ 1,269.00	\$ 20.68
23505	Installed/Active	02/07/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23506	Installed/Active	02/07/2018	PH199119	PHOENIX	\$ 8,283.60	\$ 66.56
23507	Installed/Active	02/07/2018	PROG7576NRU	RHEEM	\$ 1,939.00	\$ 42.74
23508	Installed/Active	02/06/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23509	Installed/Active	02/07/2018	PROG5036NRH60DV	RHEEM	\$ 2,034.00	\$ 18.09
23510	Installed/Active	02/06/2018	PROG5036NRH60DV	RHEEM	\$ 2,025.16	\$ 18.09
23511	Installed/Active	02/06/2018	PROG5038NRH60	RHEEM	\$ 1,156.96	\$ 12.76
23512	Installed/Active	02/08/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23513	Installed/Active	02/07/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23514	Installed/Active	02/06/2018	RG2DV50S6N	Bradford White	\$ 2,314.00	\$ 18.09
23515	Installed/Active	11/04/1982	PRV40	State	\$ 850.00	
23516	Installed/Active	02/14/2018	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 12.76
23517	Installed/Active	02/16/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23518	Installed/Active	02/16/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23519	Installed/Active	02/16/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 18.09
23520	Installed/Active	02/12/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 6.16
23521	Installed/Active	02/13/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23522	Installed/Active	02/17/2018	PROG5036NRH60	RHEEM	\$ 2,042.55	\$ 18.09
23523	Installed/Active	02/13/2018	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 6.16
23524	Installed/Active	02/13/2018	PROG40S38NRH62	RHEEM	\$ 1,152.00	\$ 12.76
23525	Installed/Active	02/13/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23526	Installed/Active	02/15/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23527	Installed/Active	02/17/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 6.16
23528	Installed/Active	02/13/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23529	Installed/Active	02/16/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23530	Installed/Active	02/14/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23531	Installed/Active	02/08/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23532	Installed/Active	02/07/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23533	Installed/Active	02/09/2018	PROG5036NRH60	RHEEM	\$ 2,076.50	\$ 18.09
23534	Installed/Active	02/08/2018	G91200	RHEEM	\$ 5,315.65	\$ 66.56
23535	Installed/Active	02/12/2018	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 12.76
23536	Installed/Active	02/14/2018	PROG40S38NRH62	RHEEM	\$ 1,237.00	\$ 12.76
23537	Installed/Active	02/13/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23538	Installed/Active	02/20/2018	G91200	RHEEM	\$ 5,554.00	\$ 66.56
23539	Installed/Active	02/17/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 6.16
23540	Installed/Active	02/12/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 18.09
23541	Installed/Active	02/12/2018	PH199119	PHOENIX	\$ 3,350.00	\$ 66.56
23542	Installed/Active	02/14/2018	G75125	RHEEM	\$ 4,199.00	\$ 42.74
23543	Installed/Active	02/07/2018	PROG5038NRH60	RHEEM	\$ 1,136.91	\$ 6.16
23544	Installed/Active	02/18/2018	PROG5038NRH60	RHEEM	\$ 1,112.55	\$ 12.76
23545	Installed/Active	02/16/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23546	Installed/Active	02/16/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.76
23547	Installed/Active	02/18/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23548	Installed/Active	02/17/2018	PROG30S30NRH63	RHEEM	\$ 1,349.00	\$ 12.76
23549	Installed/Active	02/25/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23550	Installed/Active	02/19/2018	PROG5038NRH60	RHEEM	\$ 1,209.46	\$ 12.76
23551	Installed/Active	02/23/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 7.77
23552	Installed/Active	02/21/2018	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 12.76
23553	Installed/Active	02/19/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23554	Installed/Active	02/23/2018	PROG5038NRH60	RHEEM	\$ 1,131.00	\$ 12.76
23555	Installed/Active	02/25/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.16
23556	Installed/Active	02/21/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.76
23557	Installed/Active	02/21/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.76
23558	Installed/Active	02/23/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23559	Installed/Active	02/24/2018	PROG5038NRH60	RHEEM	\$ 1,172.00	\$ 12.76
23560	Installed/Active	03/05/2018	G91200	RUUD/RHEEM	\$ 3,350.00	\$ 66.56
23561	Installed/Active	01/30/2018	PROG4038NRH62	RHEEM	\$ 1,154.00	\$ 12.76
23562	Installed/Active	01/31/2018	G75125	RUUD/RHEEM	\$ 4,199.00	\$ 42.74
23563	Installed/Active	02/02/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23564	Installed/Active	02/23/2018	PROG4038NRH62	RHEEM	\$ 1,125.16	\$ 6.16

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23565	Installed/Active	01/30/2018	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 12.76
23566	Installed/Active	03/02/2018	RG2DV50S6N	Bradford White	\$ 2,314.00	\$ 18.09
23567	Installed/Active	02/28/2018	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 12.76
23568	Installed/Active	03/01/2018	G7575	Rheem	\$ 2,609.00	\$ 42.74
23569	Installed/Active	03/02/2018	G75125	RUUD/RHEEM	\$ 4,289.00	\$ 42.74
23570	Installed/Active	02/26/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.76
23571	Installed/Active	03/02/2018	G91200	Rheem	\$ 5,229.00	\$ 66.56
23572	Installed/Active	03/03/2018	PROG40S38NRH62	Rheem	\$ 1,079.00	\$ 6.16
23573	Installed/Active	03/01/2018	PROG5038NRH60	Rheem	\$ 1,101.85	\$ 12.76
23574	Installed/Active	03/04/2018	PROG5036NRH60DV	Rheem	\$ 1,999.00	\$ 18.09
23575	Installed/Active	02/28/2018	G91200	Rheem	\$ 5,229.00	\$ 66.56
23576	Installed/Active	02/28/2018	G91200	Rheem	\$ 5,229.00	\$ 66.56
23577	Installed/Active	03/03/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23578	Installed/Active	02/27/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,282.55	\$ 18.09
23579	Installed/Active	02/28/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23580	Installed/Active	03/03/2018	PROG5036NRH60	RHEEM	\$ 2,128.00	\$ 11.15
23581	Installed/Active	03/01/2018	PROG4038NRH62	RHEEM	\$ 1,154.00	\$ 12.76
23582	Installed/Active	03/01/2018	PROG5038NRH60	RHEEM	\$ 1,149.00	\$ 6.16
23583	Installed/Active	03/03/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23584	Installed/Active	02/26/2018	RG140T6N	BRADFORD WHITE	\$ 1,172.00	\$ 12.76
23585	Installed/Active	03/02/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 12.76
23586	Installed/Active	03/04/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 18.09
23587	Installed/Active	03/04/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 6.16
23588	Installed/Active	03/04/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23589	Installed/Active	02/27/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,280.24	\$ 18.09
23590	Installed/Active	02/26/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 12.76
23591	Installed/Active	03/01/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23592	Installed/Active	02/19/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 6.16
23593	Installed/Active	02/22/2018	PROG5036NRH60DV	Rheem	\$ 2,035.65	\$ 18.09
23594	Installed/Active	02/26/2018	PROG5038NRH60	Rheem	\$ 1,172.15	\$ 12.76
23595	Installed/Active	02/26/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 18.09
23596	Installed/Active	02/21/2018	PROG5036NRH60	Rheem	\$ 1,153.61	\$ 12.76
23597	Installed/Active	02/28/2018	PROG5036NRH60	Rheem	\$ 1,135.65	\$ 12.76
23598	Installed/Active	02/27/2018	PROG50S40NRH61	Rheem	\$ 1,239.00	\$ 12.76
23599	Installed/Active	02/26/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23600	Installed/Active	03/09/2018	G76200	RHEEM	\$ 5,119.20	\$ 66.56
23601	Installed/Active	03/06/2018	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 12.76
23602	Installed/Active	03/06/2018	PROG5038NRH60	Rheem	\$ 1,101.85	\$ 12.76
23603	Installed/Active	03/01/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 18.09
23604	Installed/Active	03/05/2018	PROG5038NRH60	RHEEM	\$ 1,172.15	\$ 12.76
23605	Installed/Active	03/11/2018	PROG4038NRH62	RHEEM	\$ 1,179.96	\$ 6.16
23606	Installed/Active	03/09/2018	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 12.76
23607	Installed/Active	03/07/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.76
23608	Installed/Active	03/08/2018	PROG5038NRH60	Rheem	\$ 1,172.15	\$ 12.76
23609	Installed/Active	03/07/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23610	Installed/Active	03/07/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 17.71
23611	Installed/Active	03/06/2018	PROG5038NRH60	Rheem	\$ 1,117.00	\$ 12.76
23612	Installed/Active	03/05/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.76
23613	Installed/Active	03/10/2018	PROG5038NRH60	Rheem	\$ 1,114.00	\$ 12.76
23614	Installed/Active	03/05/2018	PROG40S38NRH62	Rheem	\$ 1,029.00	\$ 6.16
23615	Installed/Active	02/14/2018	PROG5036NRH60	Rheem	\$ 2,075.00	\$ 18.09
23616	Installed/Active	03/14/2018	PH19980	PHOENIX	\$ 7,524.00	\$ 66.56
23617	Installed/Active	03/13/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23618	Installed/Active	03/06/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 6.16
23619	Installed/Active	03/07/2018	PROG40S38NRH62	RHEEM	\$ 1,189.46	\$ 12.76
23620	Installed/Active	03/10/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23621	Installed/Active	03/10/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23622	Installed/Active	03/07/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23623	Installed/Active	03/07/2018	PROG40S38NRH62	Rheem	\$ 1,093.00	\$ 12.76
23624	Installed/Active	03/05/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.76
23625	Installed/Active	03/12/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 6.16
23626	Installed/Active	03/14/2018	PROG4038NRH62	RHEEM	\$ 1,142.55	\$ 12.76
23627	Installed/Active	03/13/2018	RG140T6N	BRADFORD WHITE	\$ 1,195.16	\$ 12.76
23628	Installed/Active	03/12/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 11.15
23629	Installed/Active	03/14/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23630	Installed/Active	03/17/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 6.16
23631	Installed/Active	03/17/2018	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 12.76
23632	Installed/Active	03/16/2018	PROG5036NRH60	RHEEM	\$ 2,075.00	\$ 18.09
23633	Installed/Active	03/13/2018	PROG40S38NRH62	RHEEM	\$ 1,101.00	\$ 12.76
23634	Installed/Active	03/16/2018	G91200	RHEEM	\$ 5,339.00	\$ 66.56
23635	Installed/Active	03/15/2018	PROG5038NRH60	Rheem	\$ 1,139.00	\$ 6.16
23636	Installed/Active	03/15/2018	PROG5038NRH60	Rheem	\$ 1,135.65	\$ 12.76
23637	Installed/Active	03/12/2018	RG2DV40S6N	Bradford White	\$ 2,248.51	\$ 11.15
23638	Installed/Active	03/12/2018	PROG5038NRH60	Rheem	\$ 1,949.00	\$ 18.09
23639	Installed/Active	03/15/2018	PROG5038NRH60	Rheem	\$ 1,140.24	\$ 12.76
23640	Installed/Active	03/14/2018	G82156	Rheem	\$ 4,989.00	\$ 57.23
23641	Installed/Active	03/14/2018	G91200	Rheem	\$ 5,437.00	\$ 66.56
23642	Installed/Active	03/12/2018	G100200	Rheem	\$ 5,329.00	\$ 66.56
23643	Installed/Active	03/20/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23644	Installed/Active	03/24/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.76
23645	Installed/Active	03/23/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.76
23646	Installed/Active	03/20/2018	PROG40S38NRH62	RHEEM	\$ 1,133.61	\$ 12.76
23647	Installed/Active	03/24/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 7.77
23648	Installed/Active	03/14/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23649	Installed/Active	03/19/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,242.00	\$ 18.09
23650	Installed/Active	03/22/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23651	Installed/Active	03/19/2018	G82156	RHEEM	\$ 4,989.00	\$ 57.23
23652	Installed/Active	03/21/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23653	Installed/Active	03/20/2018	G75125	RHEEM	\$ 4,199.00	\$ 42.74
23654	Installed/Active	03/25/2018	PROG5038NRH60	RHEEM	\$ 1,169.00	\$ 12.76
23655	Installed/Active	03/25/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23656	Installed/Active	03/06/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23657	Installed/Active	03/11/2018	PROG5038NRH60	RHEEM	\$ 1,172.00	\$ 12.76
23658	Installed/Active	03/08/2018	PROG4038NRH62	RHEEM	\$ 1,105.16	\$ 6.16
23659	Installed/Active	03/08/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23660	Installed/Active	03/20/2018	PROG4860NRH60	RHEEM	\$ 1,289.39	\$ 20.68
23661	Installed/Active	03/22/2018	PROG40S38NRH62	RHEEM	\$ 1,079.00	\$ 15.71
23662	Installed/Active	03/20/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23663	Installed/Active	03/21/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.76
23664	Installed/Active	03/22/2018	PROG2932NRH63	RHEEM	\$ 1,434.00	\$ 7.77
23665	Installed/Active	03/21/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23666	Installed/Active	03/22/2018	PROG40S38NRH62	RHEEM	\$ 1,088.51	\$ 12.76
23667	Installed/Active	03/20/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 11.15
23668	Installed/Active	03/19/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23669	Installed/Active	03/23/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.76
23670	Installed/Active	03/22/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.76
23671	Installed/Active	03/23/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23672	Installed/Active	03/24/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23673	Installed/Active	03/02/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 12.76
23674	Installed/Active	03/15/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23675	Installed/Active	03/30/2018	PROG4860NRH60	RHEEM	\$ 1,295.08	\$ 12.76
23676	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23677	Installed/Active	03/31/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23678	Installed/Active	03/29/2018	PROG40S38NRH62	RHEEM	\$ 1,122.55	\$ 15.71
23679	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,174.65	\$ 17.71
23680	Installed/Active	03/27/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.76
23681	Installed/Active	03/29/2018	PROG5038NRH60	RHEEM	\$ 1,099.50	\$ 12.76
23682	Installed/Active	03/27/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 7.77
23683	Installed/Active	03/26/2018	G100200	RHEEM	\$ 5,329.00	\$ 66.56
23684	Installed/Active	03/31/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23685	Installed/Active	03/29/2018	PROG5036NRH60	RHEEM	\$ 2,031.00	\$ 11.15
23686	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23687	Installed/Active	03/31/2018	PROG5038NRH60	RHEEM	\$ 1,127.00	\$ 6.16
23688	Installed/Active	03/29/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,315.00	\$ 18.09
23689	Installed/Active	03/26/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23690	Installed/Active	02/17/2018	PROG30S30NRH63	RHEEM	\$ 850.00	\$ 12.76
23691	Installed/Active	02/13/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23692	Installed/Active	02/16/2018	PROG5038NRH60	RHEEM	\$ 1,257.00	\$ 12.76
23693	Installed/Active	02/14/2018	PROG5038NRH60	RHEEM	\$ 2,008.51	\$ 12.76
23694	Installed/Active	03/31/2018	RG2DV40S6N	Bradford White	\$ 2,265.16	\$ 18.09
23695	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23696	Installed/Active	03/30/2018	PROG30S30NRH63	RHEEM	\$ 1,453.61	\$ 12.76
23697	Installed/Active	03/30/2018	PROG30S30NRH63	RHEEM	\$ 1,349.00	\$ 12.76
23698	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23699	Installed/Active	03/31/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 18.09
23700	Installed/Active	03/30/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.76
23701	Installed/Active	03/30/2018	G76200	RHEEM	\$ 5,029.00	\$ 66.56
23702	Installed/Active	03/07/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23703	Installed/Active	03/09/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23704	Installed/Active	03/07/2018	PROG5038NRH60	RHEEM	\$ 1,156.95	\$ 12.76
23705	Installed/Active	04/11/2018	RG2DV40S6N	RHEEM	\$ 2,274.00	\$ 18.09
23706	Installed/Active	04/09/2018	PROG50S40NRH61	Bradford White	\$ 1,239.00	\$ 12.76
23707	Installed/Active	04/09/2018	PH19980	Phoenix	\$ 7,439.00	\$ 66.56
23708	Installed/Active	04/14/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23709	Installed/Active	04/15/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23710	Installed/Active	04/10/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 18.09
23711	Installed/Active	04/10/2018	PROG5038NRH60	RHEEM	\$ 1,209.46	\$ 12.76
23712	Installed/Active	04/11/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23713	Installed/Active	04/11/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23714	Installed/Active	04/12/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23715	Installed/Active	04/09/2018	PROG5038NRH60	RHEEM	\$ 1,135.55	\$ 12.76
23716	Installed/Active	04/10/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.76
23717	Installed/Active	03/28/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23718	Installed/Active	04/06/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23719	Installed/Active	03/21/2018	PROG40S38NRH62	RHEEM	\$ 1,237.00	\$ 12.76
23720	Installed/Active	04/02/2018	PROG5036NRH60DV	RHEEM	\$ 2,040.24	\$ 18.09
23721	Installed/Active	03/24/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23722	Installed/Active	04/02/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23723	Installed/Active	04/03/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.76
23724	Installed/Active	04/02/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23725	Installed/Active	04/12/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23726	Installed/Active	04/10/2018	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 12.76
23727	Installed/Active	04/12/2018	PROG50S40NRH61	RHEEM	\$ 1,418.00	\$ 7.77
23728	Installed/Active	04/09/2018	PROG5038NRH60	RHEEM	\$ 1,125.08	\$ 12.76
23729	Installed/Active	04/12/2018	PROG4860NRH60	RHEEM	\$ 1,295.16	\$ 17.71
23730	Installed/Active	04/09/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,282.55	\$ 18.09
23731	Installed/Active	04/11/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 18.09
23732	Installed/Active	04/05/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23733	Installed/Active	04/12/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23734	Installed/Active	04/26/2017	RG250L6N	Bradford White	\$ 850.00	\$ 6.61
23735	Installed/Active	04/03/2018	PROG4038NRH62	RHEEM	\$ 1,088.51	\$ 6.16
23736	Installed/Active	04/03/2018	PROG5038NRH60	RHEEM	\$ 1,099.50	\$ 6.16

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23737	Installed/Active	04/05/2018	PROG5038NRH60	RHEEM	\$ 1,257.00	\$ 12.76
23738	Installed/Active	04/03/2018	PROG40S38NRH62	RHEEM	\$ 1,122.75	\$ 7.77
23739	Installed/Active	04/08/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 12.76
23740	Installed/Active	04/03/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23741	Installed/Active	04/04/2018	PROG5038NRH60	RHEEM	\$ 1,131.00	\$ 12.76
23742	Installed/Active	04/04/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 12.76
23743	Installed/Active	04/03/2018	G82156	RHEEM	\$ 4,989.00	\$ 57.23
23744	Installed/Active	04/03/2018	G82156	RHEEM	\$ 5,234.81	\$ 57.23
23745	Installed/Active	04/02/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.76
23746	Installed/Active	04/02/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 6.16
23747	Installed/Active	04/04/2018	PROG4038NRH62	Rheem	\$ 1,029.00	\$ 12.76
23748	Installed/Active	04/05/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23749	Installed/Active	04/05/2018	PROG4038NRH62	RHEEM	\$ 1,237.00	\$ 12.76
23750	Installed/Active	04/15/2018	PROG5038NRH60	RHEEM	\$ 1,108.10	\$ 12.76
23751	Installed/Active	04/10/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23752	Installed/Active	04/10/2018	G91200	RHEEM	\$ 5,392.75	\$ 66.56
23753	Installed/Active	04/12/2018	G75125	RHEEM	\$ 4,284.00	\$ 42.74
23754	Installed/Active	04/03/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23755	Installed/Active	04/06/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.76
23756	Installed/Active	04/02/2018	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 7.77
23757	Installed/Active	04/02/2018	PROG4038NRH62	RHEEM	\$ 1,093.00	\$ 12.76
23758	Installed/Active	04/04/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23759	Installed/Active	04/03/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.76
23760	Installed/Active	04/11/2018	G82156	RHEEM	\$ 4,989.00	\$ 57.23
23761	Installed/Active	03/21/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 18.09
23762	Installed/Active	04/06/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23763	Installed/Active	05/01/2018	G76200	Rheem	\$ 5,029.00	\$ 63.09
23764	Installed/Active	03/05/2018	PROG4038NRH62	Rheem	\$ 1,029.00	\$ 6.16
23765	Installed/Active	04/07/2018	G75125	RUUD/RHEEM	\$ 4,292.55	\$ 42.74
23766	Installed/Active	04/14/2018	GSN040	LOCHINVAR	\$ 1,443.00	\$ 12.76
23767	Installed/Active	04/19/2018	PROG4038NRH62	RHEEM	\$ 1,122.55	\$ 12.76
23768	Installed/Active	04/17/2018	PROG4860NRH60	RHEEM	\$ 1,323.61	\$ 17.71
23769	Installed/Active	04/22/2018	PROG5038NRH60	RHEEM	\$ 1,109.00	\$ 12.76
23770	Installed/Active	04/17/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,293.61	\$ 18.09
23771	Installed/Active	04/19/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 12.76
23772	Installed/Active	04/17/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 6.16
23773	Installed/Active	04/17/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.76
23774	Installed/Active	04/18/2018	PROG5038NRH60	Rheem	\$ 1,139.00	\$ 12.76
23775	Installed/Active	03/08/2018	PROG5036NRH60	RHEEM	\$ 2,157.00	\$ 18.09
23776	Installed/Active	03/11/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.76
23777	Installed/Active	04/16/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 6.16
23778	Installed/Active	04/18/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.76
23779	Installed/Active	04/19/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23780	Installed/Active	04/18/2018	PH199119	PHOENIX	\$ 8,073.61	\$ 66.56
23781	Installed/Active	04/17/2018	PROG30S30NRH63	Rheem	\$ 1,434.00	\$ 12.76
23782	Installed/Active	04/20/2018	G82156	Rheem	\$ 5,125.50	\$ 57.23
23783	Installed/Active	04/19/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.76
23784	Installed/Active	04/16/2018	G91200	Rheem	\$ 5,229.00	\$ 66.56
23785	Installed/Active	04/18/2018	PROG5038NRH60	Rheem	\$ 1,098.15	\$ 7.77
23786	Installed/Active	04/29/2018	PROG5038NRH60	RHEEM	\$ 1,099.50	\$ 6.16
23787	Installed/Active	04/29/2018	PROG5038NRH60	RHEEM	\$ 1,209.46	\$ 12.76
23788	Installed/Active	04/24/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.76
23789	Installed/Active	04/26/2018	G91200	RHEEM	\$ 5,229.00	\$ 66.56
23790	Installed/Active	04/27/2018	PROG4038NRH62	RHEEM	\$ 1,119.00	\$ 6.16
23791	Installed/Active	04/29/2018	G91200	Rheem	\$ 5,279.00	\$ 66.56
23792	Installed/Active	04/26/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 6.16
23793	Installed/Active	05/05/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 16.78
23794	Installed/Active	05/04/2018	PROG5038NRH60	Rheem	\$ 1,326.80	\$ 12.09
23795	Installed/Active	05/06/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 17.15
23796	Installed/Active	04/23/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 18.09
23797	Installed/Active	04/23/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 6.16
23798	Installed/Active	04/23/2018	PROG5038NRH60	RHEEM	\$ 1,142.55	\$ 12.76
23799	Installed/Active	04/29/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23800	Installed/Active	04/28/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.76
23801	Installed/Active	04/28/2018	PROG40S38NRH62	RHEEM	\$ 1,189.40	\$ 7.77
23802	Installed/Active	04/26/2018	PROG50S40NRH61	RHEEM	\$ 1,303.00	\$ 12.76
23803	Installed/Active	04/27/2018	PROG40S38NRH62	RHEEM	\$ 1,122.55	\$ 7.77
23804	Installed/Active	04/23/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 18.09
23805	Installed/Active	04/20/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.76
23806	Installed/Active	04/18/2018	PROG5036NRH60	RHEEM	\$ 2,053.61	\$ 18.09
23807	Installed/Active	04/17/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 12.76
23808	Installed/Active	04/18/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,283.33	\$ 11.15
23809	Installed/Active	04/18/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,283.33	\$ 11.15
23810	Installed/Active	05/06/2018	G91200	RHEEM	\$ 5,397.57	\$ 63.09
23811	Installed/Active	05/02/2018	PROG5036NRH60	RHEEM	\$ 2,109.00	\$ 12.09
23812	Installed/Active	05/01/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.09
23813	Installed/Active	04/30/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
23814	Installed/Active	04/30/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 6.16
23815	Installed/Active	05/01/2018	PROG5038NRH60	RHEEM	\$ 1,098.15	\$ 12.09
23816	Installed/Active	03/28/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 6.16
23817	Installed/Active	05/01/2018	PROG5036NRH60	RHEEM	\$ 1,998.15	\$ 12.09
23818	Installed/Active	04/30/2018	PROG40S38NRH62	RHEEM	\$ 1,139.00	\$ 12.76
23819	Installed/Active	03/01/2018	RG2DV40S6N	Rheem	\$ 617.00	\$ 11.15
23820	Installed/Active	04/26/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23821	Installed/Active	04/29/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.76
23822	Installed/Active	04/25/2018	PROG5038NRH60	Rheem	\$ 1,108.10	\$ 12.76

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23823	Installed/Active	04/23/2018	GSN040	Lochinvar	\$ 1,379.00	\$ 12.76
23824	Installed/Active	04/23/2018	PROG4038NRH62	Rheem	\$ 1,079.00	\$ 12.76
23825	Installed/Active	04/28/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 6.16
23826	Installed/Active	04/27/2018	PROG4860NRH60	Rheem	\$ 1,278.51	\$ 17.71
23827	Installed/Active	04/29/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.76
23828	Installed/Active	04/28/2018	PROG4038NRH62	Rheem	\$ 1,093.00	\$ 12.76
23829	Installed/Active	05/02/2018	G75125	RHEEM	\$ 4,199.00	\$ 40.51
23830	Installed/Active	05/01/2018	PH19980	PHOENIX	\$ 7,439.00	\$ 63.09
23831	Installed/Active	05/04/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.09
23832	Installed/Active	05/01/2018	PROG5038NRH60	Rheems	\$ 1,049.00	\$ 12.09
23833	Installed/Active	05/04/2018	PROG4038NRH62	Rheem	\$ 1,119.00	\$ 12.09
23834	Installed/Active	04/30/2018	PROG5038NRH60	Rheem	\$ 1,134.00	\$ 12.76
23835	Installed/Active	05/04/2018	PROG5038NRH60	Rheem	\$ 1,209.46	\$ 12.09
23836	Installed/Active	05/11/2018	RG2DV50S6N	Bradford White	\$ 1,075.00	\$ 17.15
23837	Installed/Active	05/12/2018	PROG40S38NRH62	Rheem	\$ 1,237.00	\$ 5.83
23838	Installed/Active	05/08/2018	PROG5036NRH60DV	Rheem	\$ 2,075.00	\$ 17.15
23839	Installed/Active	05/08/2018	PROG5038NRH60	Rheem	\$ 1,140.24	\$ 12.09
23840	Installed/Active	05/12/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 17.15
23841	Installed/Active	05/13/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 12.09
23842	Installed/Active	05/13/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.09
23843	Installed/Active	05/09/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23844	Installed/Active	05/09/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 5.83
23845	Installed/Active	05/07/2018	PROG5038NRH60	RHEEM	\$ 1,110.00	\$ 12.09
23846	Installed/Active	05/07/2018	PROG7576NRU	RHEEM	\$ 1,889.00	\$ 12.09
23847	Installed/Active	05/11/2018	PROG4038NRH62	RHEEM	\$ 1,094.00	\$ 7.37
23848	Installed/Active	05/13/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 12.09
23849	Installed/Active	05/08/2018	PROG5036NRH60DV	RHEEM	\$ 2,039.00	\$ 17.15
23850	Installed/Active	05/09/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
23851	Installed/Active	05/10/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
23852	Installed/Active	05/10/2018	PROG5036NRH60DV	Rheem	\$ 1,075.00	\$ 17.15
23853	Installed/Active	05/08/2018	RG2DV50H6N	Bradford White	\$ 2,314.00	\$ 17.15
23854	Installed/Active	05/12/2018	PROG5038NRH60	Rheem	\$ 1,209.46	\$ 12.09
23855	Installed/Active	05/12/2018	PROG5038NRH60	Rheem	\$ 1,102.00	\$ 12.09
23856	Installed/Active	05/10/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
23857	Installed/Active	05/18/2018	PROG50S40NRH61	RHEEM	\$ 1,332.55	\$ 12.09
23858	Installed/Active	05/16/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23859	Installed/Active	05/14/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
23860	Installed/Active	05/19/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.09
23861	Installed/Active	05/16/2018	PROG5038NRH60	RHEEM	\$ 1,164.00	\$ 12.09
23862	Installed/Active	05/20/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23863	Installed/Active	05/16/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 17.15
23864	Installed/Active	05/17/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
23865	Installed/Active	05/17/2018	PROG4038NRH62	RHEEM	\$ 1,088.51	\$ 5.83
23866	Installed/Active	05/18/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23867	Installed/Active	05/20/2018	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 12.09
23868	Installed/Active	05/16/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.09
23869	Installed/Active	05/19/2018	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 5.83
23870	Installed/Active	05/07/2018	PROG5038NRH60	Rheem	\$ 1,116.50	\$ 12.09
23871	Installed/Active	05/18/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
23872	Installed/Active	05/20/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
23873	Installed/Active	05/20/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 5.83
23874	Installed/Active	05/18/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
23875	Installed/Active	05/17/2018	PROG4860NRH60	Rheem	\$ 1,304.00	\$ 16.78
23876	Installed/Active	05/19/2018	G82156	Rheem	\$ 4,989.00	\$ 54.25
23877	Installed/Active	05/14/2018	G76200	Rheem	\$ 5,029.00	\$ 63.09
23878	Installed/Active	05/18/2018	RG2DV50S6N	Bradford White	\$ 2,248.51	\$ 17.15
23879	Installed/Active	05/15/2018	PROG40S38NRH62	Rheem	\$ 1,133.61	\$ 12.09
23880	Installed/Active	05/14/2018	PROG4038NRH62	Rheem	\$ 1,133.61	\$ 12.09
23881	Installed/Active	05/15/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 5.83
23882	Installed/Active	05/15/2018	PROG5038NRH60	Rheem	\$ 1,257.00	\$ 12.09
23883	Installed/Active	05/16/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
23884	Installed/Active	03/20/2018	PROG4038NRH62	RHEEM	\$ 1,114.00	\$ 12.76
23885	Installed/Active	05/13/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 17.15
23886	Installed/Active	05/12/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
23887	Installed/Active	05/17/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.09
23888	Installed/Active	05/26/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.09
23889	Installed/Active	05/24/2018	G76200	RHEEM	\$ 5,090.00	\$ 63.09
23890	Installed/Active	05/27/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23891	Installed/Active	05/23/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
23892	Installed/Active	05/21/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 5.83
23893	Installed/Active	05/25/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
23894	Installed/Active	05/24/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23895	Installed/Active	05/26/2018	PROG40S38NRH62	RHEEM	\$ 1,076.00	\$ 5.83
23896	Installed/Active	05/23/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23897	Installed/Active	05/22/2018	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 12.09
23898	Installed/Active	05/22/2018	PH199119	PHOENIX	\$ 8,020.00	\$ 63.09
23899	Installed/Active	05/22/2018	PH199119	PHOENIX	\$ 7,969.00	\$ 63.09
23900	Installed/Active	05/21/2018	PROG5038NRH60	Rheem	\$ 1,209.46	\$ 12.09
23901	Installed/Active	05/24/2018	PROG40S38NRH62	Rheem	\$ 1,097.00	\$ 7.37
23902	Installed/Active	05/25/2018	PROG40S38NRH62	Rheem	\$ 1,160.00	\$ 12.09
23903	Installed/Active	05/25/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.09
23904	Installed/Active	05/26/2018	PROG40S38NRH62	Rheem	\$ 1,155.00	\$ 12.09
23905	Installed/Active	05/24/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 5.83
23906	Installed/Active	05/25/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.09
23907	Installed/Active	05/27/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
23908	Installed/Active	05/23/2018	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23909	Installed/Active	05/26/2018	PROG4038NRH62	Rheem	\$ 1,115.65	\$ 5.83
23910	Installed/Active	05/21/2018	PROG4038NRH62	Rheem	\$ 1,088.51	\$ 12.09
23911	Installed/Active	05/30/2018	G82156	Rheem	\$ 4,989.00	\$ 54.25
23912	Installed/Active	05/29/2018	PROG5036NRH60DV	Rheem	\$ 2,008.51	\$ 17.15
23913	Installed/Active	06/02/2018	PROG7576NRH	Rheem	\$ 1,799.00	\$ 12.09
23914	Installed/Active	06/02/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 5.83
23915	Installed/Active	06/01/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 12.09
23916	Installed/Active	05/29/2018	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 5.83
23917	Installed/Active	05/29/2018	PROG5038NRH60	RHEEM	\$ 1,052.55	\$ 12.09
23918	Installed/Active	06/01/2018	PH19980	PHOENIX	\$ 7,499.00	\$ 63.09
23919	Installed/Active	05/29/2018	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 12.09
23920	Installed/Active	05/29/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23921	Installed/Active	05/31/2018	PROG4038NRH62	RHEEM	\$ 1,093.00	\$ 5.83
23922	Installed/Active	06/02/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.09
23923	Installed/Active	06/01/2018	PROG4038NRH62	RHEEM	\$ 1,148.75	\$ 5.83
23924	Installed/Active	06/02/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.09
23925	Installed/Active	06/03/2018	PROG4038NRH62	RHEEM	\$ 1,093.00	\$ 5.83
23926	Installed/Active	06/03/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,248.51	\$ 17.15
23927	Installed/Active	05/30/2018	G75125	RHEEM	\$ 4,199.00	\$ 16.78
23928	Installed/Active	06/05/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23929	Installed/Active	06/09/2018	PROG5036NRH60DV	RHEEM	\$ 2,053.61	\$ 17.15
23930	Installed/Active	06/04/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,397.00	\$ 17.15
23931	Installed/Active	06/08/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
23932	Installed/Active	06/08/2018	PROG5038NRH60	RHEEM	\$ 1,209.46	\$ 12.09
23933	Installed/Active	06/09/2018	PROG5038NRH60	RHEEM	\$ 1,112.83	\$ 12.09
23934	Installed/Active	06/09/2018	PROG40S38NRH62	RHEEM	\$ 1,090.00	\$ 12.09
23935	Installed/Active	06/06/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 16.78
23936	Installed/Active	06/05/2018	PH199119	PHOENIX	\$ 8,032.55	\$ 63.09
23937	Installed/Active	06/04/2018	PROG5038NRH60	Rheem	\$ 1,168.75	\$ 12.09
23938	Installed/Active	06/04/2018	PROG5038NRH60	Rheem	\$ 1,142.55	\$ 12.09
23939	Installed/Active	06/04/2018	PROG5038NRH60	Rheem	\$ 1,134.00	\$ 12.09
23940	Installed/Active	06/04/2018	PROG5038NRH60	Rheem	\$ 1,131.00	\$ 12.09
23941	Installed/Active	06/08/2018	PROG5038NRH60	RHEEM	\$ 1,098.15	\$ 12.09
23942	Installed/Active	06/08/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.09
23943	Installed/Active	06/06/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23944	Installed/Active	06/05/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 12.09
23945	Installed/Active	06/10/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.09
23946	Installed/Active	06/10/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,293.61	\$ 17.15
23947	Installed/Active	06/08/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23948	Installed/Active	06/08/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23949	Installed/Active	06/06/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
23950	Installed/Active	06/04/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23951	Installed/Active	06/04/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.09
23952	Installed/Active	06/08/2018	G75125	RHEEM	\$ 4,199.00	\$ 40.51
23953	Installed/Active	06/08/2018	G75125	RHEEM	\$ 4,199.00	\$ 40.51
23954	Installed/Active	06/06/2018	PROG5038NRH60	RHEEM	\$ 1,175.00	\$ 12.09
23955	Installed/Active	05/31/2018	PROG5038NRH60	RHEEM	\$ 1,169.00	\$ 5.83
23956	Installed/Active	06/15/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
23957	Installed/Active	06/11/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.09
23958	Installed/Active	06/13/2018	PROG5038NRH60	RHEEM	\$ 1,116.50	\$ 12.09
23959	Installed/Active	06/13/2018	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 12.09
23960	Installed/Active	06/11/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 5.83
23961	Installed/Active	06/12/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23962	Installed/Active	06/17/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.09
23963	Installed/Active	06/12/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
23964	Installed/Active	06/15/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
23965	Installed/Active	06/14/2018	PROG5036NRU60DV	Rheem	\$ 1,949.00	\$ 17.15
23966	Installed/Active	06/17/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
23967	Installed/Active	06/16/2018	G91200	Rheem	\$ 5,279.00	\$ 63.09
23968	Installed/Active	06/16/2018	G91200	Rheem	\$ 5,229.00	\$ 63.09
23969	Installed/Active	06/16/2018	PROG5038NRH60	Rheem	\$ 1,159.00	\$ 12.09
23970	Installed/Active	06/15/2018	PROG5038NRH60	Rheem	\$ 1,257.00	\$ 12.09
23971	Installed/Active	06/15/2018	RG2DV50S6N	Bradford White	\$ 2,293.61	\$ 17.15
23972	Installed/Active	06/15/2018	PROG5036NRU60DV	Rheem	\$ 1,949.00	\$ 17.15
23973	Installed/Active	06/12/2018	PROG7576NRH	RHEEM	\$ 1,944.00	\$ 19.60
23974	Installed/Active	06/12/2018	G76200	RUUD/RHEEM	\$ 5,029.00	\$ 63.09
23975	Installed/Active	06/12/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23976	Installed/Active	06/19/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,282.55	\$ 17.15
23977	Installed/Active	06/19/2018	PROG5036NRH60	RHEEM	\$ 1,949.00	\$ 17.15
23978	Installed/Active	06/21/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23979	Installed/Active	06/23/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,271.00	\$ 17.15
23980	Installed/Active	06/21/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23981	Installed/Active	06/20/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23982	Installed/Active	06/22/2018	PROG4038NRH62	RHEEM	\$ 1,114.00	\$ 5.83
23983	Installed/Active	06/23/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
23984	Installed/Active	06/24/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.09
23985	Installed/Active	06/23/2018	PROG7576NRH	RHEEM	\$ 1,799.00	\$ 40.51
23986	Installed/Active	06/21/2018	PROG5036NRH60	RHEEM	\$ 2,042.55	\$ 17.15
23987	Installed/Active	06/21/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.09
23988	Installed/Active	06/20/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.09
23989	Installed/Active	06/18/2018	PROG40S38NRH62	RHEEM	\$ 1,189.00	\$ 5.83
23990	Installed/Active	06/18/2018	PROG5038NRH60	RHEEM	\$ 1,139.00	\$ 12.09
23991	Installed/Active	06/18/2018	PROG5038NRH60	RHEEM	\$ 1,131.00	\$ 12.09
23992	Installed/Active	06/20/2018	PROG4038NRH62	RHEEM	\$ 1,133.61	\$ 5.83
23993	Installed/Active	06/20/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
23994	Installed/Active	06/22/2018	PROG5038NRH60	RHEEM	\$ 1,116.50	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
23995	Installed/Active	06/23/2018	PROG4860NRH60	RHEEM	\$ 1,219.00	\$ 16.78
23996	Installed/Active	06/24/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
23997	Installed/Active	06/18/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
23998	Installed/Active	06/18/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
23999	Installed/Active	06/18/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24000	Installed/Active	06/24/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 5.83
24001	Installed/Active	06/26/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,320.00	\$ 17.15
24002	Installed/Active	05/30/2018	PROG2932NRH63	RHEEM	\$ 1,435.65	\$ 12.09
24003	Installed/Active	06/27/2018	PROG5038NRH60	RHEEM	\$ 1,110.00	\$ 7.37
24004	Installed/Active	06/27/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24005	Installed/Active	06/27/2018	PROG5036NRH60	RHEEM	\$ 2,025.16	\$ 17.15
24006	Installed/Active	06/29/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.09
24007	Installed/Active	06/25/2018	PROG5036NRH60DV	RHEEM	\$ 2,125.45	\$ 17.15
24008	Installed/Active	06/28/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
24009	Installed/Active	06/26/2018	G82156	RHEEM	\$ 5,039.00	\$ 54.25
24010	Installed/Active	06/25/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 5.83
24011	Installed/Active	06/30/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 17.15
24012	Installed/Active	06/30/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.09
24013	Installed/Active	06/27/2018	PROG5036NRH60DV	RHEEM	\$ 2,012.83	\$ 17.15
24014	Installed/Active	06/28/2018	PROG5038NRH60	RHEEM	\$ 1,225.46	\$ 7.37
24015	Installed/Active	06/30/2018	PROG4038NRH62	RHEEM	\$ 1,097.00	\$ 12.09
24016	Installed/Active	07/01/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
24017	Installed/Active	06/29/2018	PROG40S38NRH62	RHEEM	\$ 1,120.24	\$ 12.09
24018	Installed/Active	06/30/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.00	\$ 17.15
24019	Installed/Active	07/01/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24020	Installed/Active	06/26/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
24021	Installed/Active	06/25/2018	PROG5038NRH60	RHEEM	\$ 1,140.24	\$ 12.09
24022	Installed/Active	06/26/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24023	Installed/Active	06/29/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 16.78
24024	Installed/Active	06/28/2018	PROG5038NRH60	RHEEM	\$ 1,174.65	\$ 12.09
24025	Installed/Active	06/29/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24026	Installed/Active	06/26/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 5.83
24027	Installed/Active	06/26/2018	PROG5038NRH60	RHEEM	\$ 1,110.35	\$ 12.09
24028	Installed/Active	06/26/2018	PROG4038NRH62	RHEEM	\$ 1,079.00	\$ 5.83
24029	Installed/Active	06/27/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24030	Installed/Active	06/26/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 5.83
24031	Installed/Active	06/25/2018	RG2DV50S6N	Bradford White	\$ 2,248.51	\$ 17.15
24032	Installed/Active	06/29/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 5.83
24033	Installed/Active	06/25/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.09
24034	Installed/Active	06/25/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24035	Installed/Active	06/28/2018	PROG40S38NRH62	RHEEM	\$ 1,120.24	\$ 12.09
24036	Installed/Active	07/01/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24037	Installed/Active	07/03/2018	RG2DV50S6N	Bradford White	\$ 2,349.46	\$ 17.15
24038	Installed/Active	06/27/2018	G100200	RHEEM	\$ 5,606.80	\$ 63.09
24039	Installed/Active	06/27/2018	G100200	RHEEM	\$ 5,618.00	\$ 63.09
24040	Installed/Active	07/06/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.09
24041	Installed/Active	07/06/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24042	Installed/Active	07/06/2018	PROG5038NRH60	RHEEM	\$ 1,119.39	\$ 12.09
24043	Installed/Active	07/07/2018	PROG4038NRH62	RHEEM	\$ 1,091.25	\$ 12.09
24044	Installed/Active	07/08/2018	PROG5036NRH60DV	RHEEM	\$ 2,040.24	\$ 17.15
24045	Installed/Active	07/03/2018	PROG5036NRH60DV	RHEEM	\$ 1,949.00	\$ 17.15
24046	Installed/Active	07/02/2018	PROG5038NRH60	RHEEM	\$ 1,117.00	\$ 12.09
24047	Installed/Active	07/02/2018	PROG5036NRH60DV	RHEEM	\$ 2,035.65	\$ 17.15
24048	Installed/Active	07/07/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
24049	Installed/Active	07/03/2018	RG2DV40S6N	Bradford White	\$ 2,248.51	\$ 17.15
24050	Installed/Active	07/05/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 17.15
24051	Installed/Active	07/06/2018	RG2DV50S6N	Bradford White	\$ 2,274.00	\$ 10.57
24052	Installed/Active	07/05/2018	PROG5036NRH60DV	RHEEM	\$ 1,999.00	\$ 5.83
24053	Installed/Active	07/05/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24054	Installed/Active	07/10/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 12.09
24055	Installed/Active	07/13/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
24056	Installed/Active	07/13/2018	PROG5036NRH60DV	RHEEM	\$ 2,012.83	\$ 17.15
24057	Installed/Active	07/13/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24058	Installed/Active	07/12/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,248.51	\$ 17.15
24059	Installed/Active	07/13/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24060	Installed/Active	07/12/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24061	Installed/Active	07/11/2018	PROG50S40NRH61	RHEEM	\$ 1,359.00	\$ 5.83
24062	Installed/Active	07/14/2018	PROG4860NRH60	RHEEM	\$ 1,319.00	\$ 16.78
24063	Installed/Active	07/12/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24064	Installed/Active	07/13/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24065	Installed/Active	07/14/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 16.78
24066	Installed/Active	06/18/2018	G75125	RHEEM	\$ 4,289.00	\$ 40.51
24067	Installed/Active	06/24/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.09
24068	Installed/Active	06/20/2018	PROG7576NRH	RHEEM	\$ 1,799.00	\$ 40.51
24069	Installed/Active	06/20/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24070	Installed/Active	06/20/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24071	Installed/Active	07/24/2018	PROG5036NRH60DV	RHEEM	\$ 2,053.61	\$ 17.15
24072	Installed/Active	07/25/2018	PROG4038NRH62	RHEEM	\$ 1,093.00	\$ 12.09
24073	Installed/Active	07/27/2018	PROG5038NRH60	RHEEM	\$ 1,153.61	\$ 12.09
24074	Installed/Active	07/28/2018	PROG5036NRH60DV	RHEEM	\$ 2,025.08	\$ 10.57
24075	Installed/Active	07/26/2018	PROG5038NRH60	RHEEM	\$ 1,149.00	\$ 16.78
24076	Installed/Active	07/28/2018	PROG5038NRH60	RHEEM	\$ 1,174.00	\$ 12.09
24077	Installed/Active	07/20/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24078	Installed/Active	07/28/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24079	Installed/Active	07/28/2018	G82156	RHEEM	\$ 5,157.30	\$ 54.25
24080	Installed/Active	07/26/2018	PROG5038NRH60	RHEEM	\$ 1,102.00	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24081	Installed/Active	07/30/2018	PROG4038NRH62	Rheem	\$ 1,122.75	\$ 12.09
24082	Installed/Active	07/25/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24083	Installed/Active	07/26/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24084	Installed/Active	07/26/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
24085	Installed/Active	07/27/2018	PROG4860NRH60	Rheem	\$ 1,219.00	\$ 19.60
24086	Installed/Active	07/26/2018	G91200	Rheem	\$ 5,229.00	\$ 63.09
24087	Installed/Active	07/25/2018	PROG40S38NRH62	Rheem	\$ 1,093.00	\$ 12.09
24088	Installed/Active	07/28/2018	PROG5038NRH60	Rheem	\$ 1,108.51	\$ 12.09
24089	Installed/Active	07/23/2018	PROG5038NRH60	Rheem	\$ 1,116.50	\$ 12.09
24090	Installed/Active	07/23/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
24091	Installed/Active	07/26/2018	PROG4860NRH60	Rheem	\$ 1,427.00	\$ 16.78
24092	Installed/Active	07/19/2018	PROG40S38NRH62	RHEEM	\$ 1,237.00	\$ 12.09
24093	Installed/Active	07/16/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
24094	Installed/Active	07/17/2018	PROG5038NRH60	RHEEM	\$ 1,134.00	\$ 12.09
24095	Installed/Active	07/18/2018	PROG5038NRH60	RHEEM	\$ 1,257.00	\$ 5.83
24096	Installed/Active	07/18/2018	PROG5038NRH60	RHEEM	\$ 1,099.00	\$ 12.09
24097	Installed/Active	07/20/2018	PROG5038NRH60	RHEEM	\$ 1,112.83	\$ 12.09
24098	Installed/Active	07/19/2018	PROG4038NRH62	RHEEM	\$ 1,160.00	\$ 5.83
24099	Installed/Active	07/19/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.09
24100	Installed/Active	07/21/2018	PROG4860NRH60	RHEEM	\$ 1,279.00	\$ 16.78
24101	Installed/Active	07/21/2018	PROG5038NRH60	RHEEM	\$ 1,114.00	\$ 12.09
24102	Installed/Active	07/22/2018	PROG50S40NRH61	RHEEM	\$ 1,239.00	\$ 12.09
24103	Installed/Active	07/20/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
24104	Installed/Active	07/21/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 17.15
24105	Installed/Active	07/21/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 12.09
24106	Installed/Active	07/21/2018	PROG40S38NRH62	Rheem	\$ 1,237.00	\$ 12.09
24107	Installed/Active	07/20/2018	PROG5038NRH60	Rheem	\$ 1,326.80	\$ 12.09
24108	Installed/Active	07/16/2018	PROG5036NRH60DV	Rheem	\$ 2,157.00	\$ 17.15
24109	Installed/Active	07/17/2018	RG2DV50S6N	Bradford White	\$ 2,239.00	\$ 17.15
24110	Installed/Active	07/18/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
24111	Installed/Active	07/18/2018	PROG5038NRH60	Rheem	\$ 1,225.46	\$ 5.83
24112	Installed/Active	08/01/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,189.00	\$ 17.15
24113	Installed/Active	07/31/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24114	Installed/Active	08/01/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 5.83
24115	Installed/Active	08/05/2018	GSN040	LOCHINVAR	\$ 1,379.00	\$ 12.09
24116	Installed/Active	08/04/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24117	Installed/Active	08/02/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24118	Installed/Active	08/02/2018	PROG5038NRH60	RHEEM	\$ 1,209.00	\$ 12.09
24119	Installed/Active	07/31/2018	PROG5038NRH60	RHEEM	\$ 1,110.35	\$ 5.83
24120	Installed/Active	08/01/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24121	Installed/Active	08/03/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 17.15
24122	Installed/Active	08/03/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24123	Installed/Active	08/04/2018	G75125	Rheem	\$ 4,199.00	\$ 40.51
24124	Installed/Active	07/31/2018	RG2DV50S6N	Bradford White	\$ 2,189.00	\$ 10.57
24125	Installed/Active	07/30/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24126	Installed/Active	08/04/2018	PROG40S38NRH62	Rheem	\$ 1,115.65	\$ 5.83
24127	Installed/Active	07/30/2018	PROG5038NRH60	Rheem	\$ 1,132.65	\$ 12.09
24128	Installed/Active	08/02/2018	PROG5038NRH60	Rheem	\$ 1,135.65	\$ 12.09
24129	Installed/Active	08/04/2018	PROG4038NRH62	Rheem	\$ 1,152.15	\$ 7.37
24130	Installed/Active	07/31/2018	PROG40S38NRH62	Rheem	\$ 1,111.00	\$ 12.09
24131	Installed/Active	08/04/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 17.15
24132	Installed/Active	07/30/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24133	Installed/Active	08/02/2018	PROG4038NRH62	Rheem	\$ 1,082.00	\$ 12.09
24134	Installed/Active	08/05/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24135	Installed/Active	07/31/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24136	Installed/Active	08/01/2018	PROG40S38NRH62	Rheem	\$ 1,029.00	\$ 5.83
24137	Installed/Active	07/30/2018	G91200	Rheem	\$ 5,229.00	\$ 63.09
24138	Installed/Active	08/03/2018	PROG5038NRH60	Rheem	\$ 1,209.45	\$ 12.09
24139	Installed/Active	08/04/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24140	Installed/Active	08/09/2018	PROG4038NRH62	RHEEM	\$ 1,122.75	\$ 5.83
24141	Installed/Active	08/07/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.09
24142	Installed/Active	08/10/2018	G82156	RHEEM	\$ 4,989.00	\$ 54.25
24143	Installed/Active	08/08/2018	PROG5036NRH60DV	RHEEM	\$ 1,949.00	\$ 17.15
24144	Installed/Active	08/08/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 5.83
24145	Installed/Active	08/09/2018	PROG5038NRH60	RHEEM	\$ 1,122.00	\$ 12.09
24146	Installed/Active	08/09/2018	PROG5038NRH60	RHEEM	\$ 1,142.75	\$ 12.09
24147	Installed/Active	08/06/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
24148	Installed/Active	08/12/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24149	Installed/Active	08/09/2018	M150L6FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.09
24150	Installed/Active	08/02/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24151	Installed/Active	08/07/2018	PROG4038NRH62	Rheem	\$ 1,139.00	\$ 12.09
24152	Installed/Active	08/10/2018	PROG5038NRH60	Rheem	\$ 1,114.00	\$ 12.09
24153	Installed/Active	08/07/2018	PROG5038NRH60	Rheem	\$ 1,125.16	\$ 12.09
24154	Installed/Active	08/10/2018	PROG5038NRH60	Rheem	\$ 1,104.24	\$ 12.09
24155	Installed/Active	08/08/2018	PH199119	PHOENIX	\$ 8,019.00	\$ 63.09
24156	Installed/Active	08/07/2018	PROG5038NRH60	Rheem	\$ 1,153.61	\$ 12.09
24157	Installed/Active	08/09/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24158	Installed/Active	08/07/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24159	Installed/Active	08/09/2018	PROG5036NRH60DV	Rheem	\$ 1,949.00	\$ 17.15
24160	Installed/Active	08/07/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09
24161	Installed/Active	08/07/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 16.78
24162	Installed/Active	08/06/2018	PROG5038NRH60	Rheem	\$ 1,109.00	\$ 12.09
24163	Installed/Active	08/09/2018	PROG40S38NRH62	Rheem	\$ 1,205.46	\$ 12.09
24164	Installed/Active	08/08/2018	PROG50S40NRH61	Rheem	\$ 1,418.46	\$ 12.09
24165	Installed/Active	08/08/2018	PROG4038NRH62	Rheem	\$ 1,088.51	\$ 12.09
24166	Installed/Active	08/10/2018	PROG5038NRH60	Rheem	\$ 1,049.00	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24167	Installed/Active	08/11/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24168	Installed/Active	08/11/2018	PROG5038NRH60	Rheem	\$ 1,113.00	\$ 12.09
24169	Installed/Active	08/09/2018	PROG7576NRH	Rheem	\$ 1,799.00	\$ 40.51
24170	Installed/Active	08/12/2018	PROG5038NRH60	Rheem	\$ 1,099.00	\$ 12.09
24171	Installed/Active	08/18/2018	PROG5038NRH60	RHEEM	\$ 1,116.50	\$ 12.09
24172	Installed/Active	08/13/2018	PROG5038NRH60	RHEEM	\$ 1,125.16	\$ 12.09
24173	Installed/Active	08/13/2018	PROG5038NRH60	RHEEM	\$ 1,135.65	\$ 12.09
24174	Installed/Active	08/16/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24175	Installed/Active	08/13/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.09
24176	Installed/Active	08/15/2018	PROG4038NRH62	RHEEM	\$ 1,154.00	\$ 12.09
24177	Installed/Active	08/19/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 16.78
24178	Installed/Active	08/13/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,397.00	\$ 17.15
24179	Installed/Active	08/18/2018	GSN040	LOCHINVAR	\$ 1,279.00	\$ 12.09
24180	Installed/Active	08/14/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24181	Installed/Active	08/16/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 5.83
24182	Installed/Active	08/15/2018	PROG40S38NRH62	RHEEM	\$ 1,088.51	\$ 7.37
24183	Installed/Active	08/17/2018	PROG40S38NRH62	RHEEM	\$ 1,029.00	\$ 12.09
24184	Installed/Active	08/21/2018	PROG5036NRH60DV	Rheem	\$ 2,103.32	\$ 17.15
24185	Installed/Active	08/21/2018	PROG4038NRH62	Rheem	\$ 1,147.96	\$ 5.83
24186	Installed/Active	08/26/2018	PROG50S40NRH61	Rheem	\$ 1,279.00	\$ 12.09
24187	Installed/Active	08/22/2018	PROG50S40NRH61	Rheem	\$ 1,279.00	\$ 12.09
24188	Installed/Active	08/26/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24189	Installed/Active	08/21/2018	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
24190	Installed/Active	08/23/2018	RG2DV50S6N	Bradford White	\$ 2,437.70	\$ 17.15
24191	Installed/Active	08/13/2018	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 12.09
24192	Installed/Active	08/20/2018	PROG5038NRH60	Rheem	\$ 1,159.78	\$ 12.09
24193	Installed/Active	08/24/2018	PROG5038NRH60	Rheem	\$ 1,148.62	\$ 12.09
24194	Installed/Active	08/18/2018	PROG40S38NRH62	RHEEM	\$ 1,152.15	\$ 5.83
24195	Installed/Active	08/14/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24196	Installed/Active	08/14/2018	G91200	RHEEM	\$ 5,494.00	\$ 63.09
24197	Installed/Active	08/14/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.09
24198	Installed/Active	08/13/2018	PROG5038NRH60	RHEEM	\$ 1,108.51	\$ 12.09
24199	Installed/Active	08/16/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 12.09
24200	Installed/Active	08/19/2018	PROG5038NRH60	RHEEM	\$ 1,049.00	\$ 7.37
24201	Installed/Active	08/16/2018	PROG4038NRH62	RHEEM	\$ 1,029.00	\$ 14.90
24202	Installed/Active	08/17/2018	PROG4038NRH62	RHEEM	\$ 1,111.00	\$ 5.83
24203	Installed/Active	08/16/2018	PROG40S38NRH62	RHEEM	\$ 1,093.00	\$ 12.09
24204	Installed/Active	08/16/2018	PROG5038NRH60	RHEEM	\$ 1,257.00	\$ 12.09
24205	Installed/Active	08/30/2018	PROG5038NRH60	Rheem	\$ 1,147.17	\$ 12.09
24206	Installed/Active	08/30/2018	PROG5038NRH60	Rheem	\$ 1,147.17	\$ 12.09
24207	Installed/Active	08/28/2018	PROG5038NRH60	Rheem	\$ 850.00	\$ 12.09
24208	Installed/Active	08/27/2018	RG2DV50S6N	Bradford White	\$ 2,386.24	\$ 17.15
24209	Installed/Active	08/30/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24210	Installed/Active	08/28/2018	PROG5038NRH60	Rheem	\$ 1,260.08	\$ 12.09
24211	Installed/Active	08/31/2018	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
24212	Installed/Active	08/30/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24213	Installed/Active	09/01/2018	G75125	RHEEM	\$ 4,602.57	\$ 40.51
24214	Installed/Active	08/24/2018	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24215	Installed/Active	08/22/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24216	Installed/Active	08/21/2018	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
24217	Installed/Active	08/24/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24218	Installed/Active	08/26/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24219	Installed/Active	08/25/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24220	Installed/Active	08/22/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24221	Installed/Active	08/24/2018	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
24222	Installed/Active	08/23/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 7.37
24223	Installed/Active	08/23/2018	PROG5038NRH60	RHEEM	\$ 1,147.17	\$ 12.09
24224	Installed/Active	08/23/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 7.37
24225	Installed/Active	08/21/2018	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 19.60
24226	Installed/Active	08/21/2018	PROG5038NRH60	RHEEM	\$ 1,361.42	\$ 5.83
24227	Installed/Active	08/08/2018	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24228	Installed/Active	08/24/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24229	Installed/Active	08/25/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24230	Installed/Active	08/24/2018	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24231	Installed/Active	08/24/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24232	Installed/Active	08/22/2018	PROG5038NRH60	Rheem	\$ 1,244.08	\$ 12.09
24233	Installed/Active	08/24/2018	RG2DV50S6N	Bradford White	\$ 2,387.24	\$ 16.78
24234	Installed/Active	08/23/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 5.83
24235	Installed/Active	08/21/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24236	Installed/Active	08/22/2018	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24237	Installed/Active	08/20/2018	G76200	RHEEM	\$ 5,194.96	\$ 63.09
24238	Installed/Active	08/22/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24239	Installed/Active	08/31/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24240	Installed/Active	08/27/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24241	Installed/Active	08/30/2018	PROG50S40NRH61	RHEEM	\$ 1,369.89	\$ 12.09
24242	Installed/Active	08/28/2018	PROG5036NRH60DV	RHEEM	\$ 2,221.32	\$ 17.15
24243	Installed/Active	08/28/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24244	Installed/Active	09/01/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24245	Installed/Active	09/04/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24246	Installed/Active	08/28/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24247	Installed/Active	08/30/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24248	Installed/Active	08/27/2018	PROG50S40NRH61	RHEEM	\$ 1,329.89	\$ 12.09
24249	Installed/Active	08/28/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24250	Installed/Active	08/29/2018	PROG5038NRH60	RHEEM	\$ 1,116.50	\$ 12.09
24251	Installed/Active	08/28/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,361.24	\$ 17.15
24252	Installed/Active	08/28/2018	PROG4860NRH60	RHEEM	\$ 1,363.84	\$ 16.78

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24253	Installed/Active	08/28/2018	PROG5038NRH60	Rheem	\$ 1,148.62	\$ 12.09
24254	Installed/Active	08/31/2018	PROG5036NRH60DV	Rheem	\$ 2,099.97	\$ 17.15
24255	Installed/Active	09/08/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24256	Installed/Active	09/06/2018	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
24257	Installed/Active	09/06/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24258	Installed/Active	09/05/2018	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 16.78
24259	Installed/Active	09/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24260	Installed/Active	09/06/2018	PROG5038NRH60	RHEEM	\$ 1,151.12	\$ 12.09
24261	Installed/Active	09/07/2018	PROG40S38NRH62	RHEEM	\$ 1,239.42	\$ 5.83
24262	Installed/Active	09/06/2018	PROG5038NRH60	RHEEM	\$ 1,244.08	\$ 12.09
24263	Installed/Active	09/04/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24264	Installed/Active	09/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24265	Installed/Active	09/08/2018	PROG40S38NRH62	RHEEM	\$ 1,167.57	\$ 7.37
24266	Installed/Active	09/05/2018	PROG5038NRH60	RHEEM	\$ 1,177.95	\$ 12.09
24267	Installed/Active	09/06/2018	PROG5036NRH60DV	Rheem	\$ 2,013.32	\$ 17.15
24268	Installed/Active	09/07/2018	PROG5038NRU60	Rheem	\$ 1,147.62	\$ 7.37
24269	Installed/Active	09/08/2018	PROG4038NRH62	Rheem	\$ 1,062.00	\$ 5.83
24270	Installed/Active	09/08/2018	PROG2932NRH63	Rheem	\$ 1,443.52	\$ 7.37
24271	Installed/Active	09/08/2018	PROG5036NRH60DV	RHEEM	\$ 2,098.32	\$ 17.15
24272	Installed/Active	09/07/2018	PROG5038NRH60	Rheem	\$ 1,209.62	\$ 12.09
24273	Installed/Active	09/05/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 14.90
24274	Installed/Active	08/25/2018	PROG4038NRH62	Rheem	\$ 1,112.96	\$ 12.09
24275	Installed/Active	09/05/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 5.83
24276	Installed/Active	09/04/2018	RG250H6N	Bradford White	\$ 1,818.36	\$ 16.78
24277	Installed/Active	09/06/2018	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 16.78
24278	Installed/Active	09/07/2018	PROG5036NRH60DV	Rheem	\$ 2,074.32	\$ 17.15
24279	Installed/Active	09/04/2018	PROG5038NRH60	Rheem	\$ 1,143.62	\$ 12.09
24280	Installed/Active	08/23/2018	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24281	Installed/Active	08/28/2018	RG150T6N	BRADFORD WHITE	\$ 1,390.55	\$ 12.09
24282	Installed/Active	08/20/2018	PROG50S40NRH61	RHEEM	\$ 1,384.50	\$ 12.09
24283	Installed/Active	09/10/2018	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24284	Installed/Active	09/14/2018	PROG5038NRH60	Rheem	\$ 1,291.62	\$ 12.09
24285	Installed/Active	09/16/2018	PROG40S38NRH62	Rheem	\$ 1,126.96	\$ 12.09
24286	Installed/Active	09/15/2018	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 12.09
24287	Installed/Active	09/10/2018	PROG4038NRH62	Rheem	\$ 1,112.96	\$ 5.83
24288	Installed/Active	09/10/2018	PROG5038NRH60	Rheem	\$ 1,144.97	\$ 12.09
24289	Installed/Active	09/16/2018	PROG5038NRH60	Rheem	\$ 1,147.17	\$ 7.37
24290	Installed/Active	09/15/2018	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 7.37
24291	Installed/Active	09/14/2018	PROG5038NRH60	Rheem	\$ 1,260.08	\$ 5.83
24292	Installed/Active	09/16/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,320.75	\$ 17.15
24293	Installed/Active	09/10/2018	PROG5036NRH60DV	RHEEM	\$ 2,078.32	\$ 17.15
24294	Installed/Active	09/15/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24295	Installed/Active	09/10/2018	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24296	Installed/Active	09/11/2018	PROG5038NRH60	RHEEM	\$ 1,177.37	\$ 12.09
24297	Installed/Active	09/15/2018	G76200	RHEEM	\$ 5,194.96	\$ 54.25
24298	Installed/Active	09/14/2018	PH19980	PHOENIX	\$ 7,734.49	\$ 63.09
24299	Installed/Active	09/12/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24300	Installed/Active	09/13/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24301	Installed/Active	09/15/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 7.37
24302	Installed/Active	09/10/2018	G91200	RHEEM	\$ 5,584.27	\$ 63.09
24303	Installed/Active	09/10/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24304	Installed/Active	09/12/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 17.15
24305	Installed/Active	09/16/2018	PROG5038NRH60	RHEEM	\$ 1,144.97	\$ 12.09
24306	Installed/Active	09/17/2018	PROG5038NRH60	RHEEM	\$ 1,147.17	\$ 12.09
24307	Installed/Active	09/20/2018	PROG5038NRH60	RHEEM	\$ 1,144.97	\$ 5.83
24308	Installed/Active	09/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24309	Installed/Active	09/21/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,365.85	\$ 17.15
24310	Installed/Active	09/21/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24311	Installed/Active	09/18/2018	PROG40S38NRH62	RHEEM	\$ 1,404.70	\$ 7.37
24312	Installed/Active	09/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24313	Installed/Active	09/22/2018	PROG5038NRH60	RHEEM	\$ 1,183.62	\$ 12.09
24314	Installed/Active	09/22/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24315	Installed/Active	09/18/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24316	Installed/Active	09/19/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24317	Installed/Active	09/17/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24318	Installed/Active	09/21/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24319	Installed/Active	09/04/2018	PROG5036NRH60DV	RHEEM	\$ 2,076.87	\$ 17.15
24320	Installed/Active	09/21/2018	RG2DV40S6N	Bradford White	\$ 2,539.04	\$ 17.15
24321	Installed/Active	09/17/2018	G7575	RHEEM	\$ 2,695.10	\$ 19.60
24322	Installed/Active	09/21/2018	G91200	Rheem	\$ 5,401.56	\$ 63.09
24323	Installed/Active	09/23/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24324	Installed/Active	09/19/2018	PROG5038NRH60	Rheem	\$ 1,151.12	\$ 12.09
24325	Installed/Active	09/19/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24326	Installed/Active	09/18/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24327	Installed/Active	09/17/2018	PROG50S40NRH61	Rheem	\$ 1,343.89	\$ 12.09
24328	Installed/Active	09/18/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24329	Installed/Active	09/17/2018	PROG5036NRH60DV	Rheem	\$ 2,139.32	\$ 17.15
24330	Installed/Active	09/22/2018	PROG5038NRH60	Rheem	\$ 1,140.13	\$ 12.09
24331	Installed/Active	10/07/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24332	Installed/Active	09/29/2018	PROG5038NRH60	Rheem	\$ 1,361.42	\$ 12.09
24333	Installed/Active	09/28/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24334	Installed/Active	10/01/2018	PROG50S40NRH61	Rheem	\$ 1,329.89	\$ 12.09
24335	Installed/Active	09/24/2018	PROG4860NRH60	RHEEM	\$ 1,344.23	\$ 16.78
24336	Installed/Active	09/29/2018	PROG5038NRH60	Rheem	\$ 1,243.62	\$ 12.09
24337	Installed/Active	09/26/2018	G82156	Rheem	\$ 5,258.25	\$ 54.25
24338	Installed/Active	09/25/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24339	Installed/Active	09/25/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24340	Installed/Active	09/28/2018	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 12.09
24341	Installed/Active	09/28/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 5.83
24342	Installed/Active	09/25/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24343	Installed/Active	09/27/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24344	Installed/Active	09/27/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24345	Installed/Active	09/30/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24346	Installed/Active	09/29/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24347	Installed/Active	09/28/2018	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24348	Installed/Active	09/26/2018	G82156	RHEEM	\$ 5,153.64	\$ 63.09
24349	Installed/Active	09/26/2018	G82156	RHEEM	\$ 5,153.64	\$ 63.09
24350	Installed/Active	09/27/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24351	Installed/Active	09/30/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 16.78
24352	Installed/Active	09/30/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24353	Installed/Active	09/29/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24354	Installed/Active	09/28/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24355	Installed/Active	09/28/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24356	Installed/Active	10/07/2018	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24357	Installed/Active	10/06/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24358	Installed/Active	10/03/2018	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24359	Installed/Active	09/24/2018	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
24360	Installed/Active	09/25/2018	PROG50S40NRH61	RHEEM	\$ 1,351.89	\$ 12.09
24361	Installed/Active	09/30/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24362	Installed/Active	09/25/2018	PROG5038NRH60	RHEEM	\$ 1,174.86	\$ 12.09
24363	Installed/Active	09/28/2018	PROG5038NRH60	RHEEM	\$ 1,148.42	\$ 12.09
24364	Installed/Active	09/30/2018	RG140T6N	BRADFORD WHITE	\$ 1,230.09	\$ 12.09
24365	Installed/Active	10/01/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24366	Installed/Active	10/01/2018	G75125	RHEEM	\$ 4,514.03	\$ 40.51
24367	Installed/Active	10/07/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24368	Installed/Active	10/05/2018	PROG5038NRH60	RHEEM	\$ 1,134.12	\$ 12.09
24369	Installed/Active	10/02/2018	PROG5038NRH60	RHEEM	\$ 1,251.62	\$ 12.09
24370	Installed/Active	10/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24371	Installed/Active	10/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24372	Installed/Active	10/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24373	Installed/Active	10/04/2018	PROG40S38NRH62	RHEEM	\$ 1,147.96	\$ 7.37
24374	Installed/Active	10/06/2018	PROG7576NRH	RHEEM	\$ 1,908.37	\$ 40.51
24375	Installed/Active	10/01/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24376	Installed/Active	10/05/2018	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24377	Installed/Active	10/05/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24378	Installed/Active	10/05/2018	PROG40S38NRH62	Rheem	\$ 1,130.46	\$ 12.09
24379	Installed/Active	10/02/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24380	Installed/Active	10/05/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24381	Installed/Active	10/02/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24382	Installed/Active	10/11/2018	PROG4038NRH62	RHEEM	\$ 1,193.96	\$ 12.09
24383	Installed/Active	10/08/2018	G91200	RHEEM	\$ 5,578.02	\$ 63.09
24384	Installed/Active	10/08/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24385	Installed/Active	10/08/2018	PROG50S40NRH61	RHEEM	\$ 1,456.35	\$ 12.09
24386	Installed/Active	10/13/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24387	Installed/Active	10/11/2018	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
24388	Installed/Active	10/09/2018	PROG5038NRH60	RHEEM	\$ 1,207.97	\$ 12.09
24389	Installed/Active	10/12/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24390	Installed/Active	10/08/2018	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24391	Installed/Active	10/13/2018	PROG5036NRH60DV	RHEEM	\$ 2,081.29	\$ 17.15
24392	Installed/Active	10/14/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24393	Installed/Active	10/11/2018	PROG5036NRH60DV	RHEEM	\$ 2,089.48	\$ 17.15
24394	Installed/Active	10/12/2018	PROG4038NRH62	RHEEM	\$ 1,239.42	\$ 12.09
24395	Installed/Active	10/08/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24396	Installed/Active	10/09/2018	PROG5038NRH60	Rheem	\$ 1,291.62	\$ 5.83
24397	Installed/Active	10/12/2018	PROG5038NRH60	Rheem	\$ 1,361.42	\$ 12.09
24398	Installed/Active	10/11/2018	PROG50S40NRH61	Rheem	\$ 1,343.89	\$ 12.09
24399	Installed/Active	10/08/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24400	Installed/Active	10/08/2018	PROG5038NRH60	Rheem	\$ 1,291.62	\$ 12.09
24401	Installed/Active	10/14/2018	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
24402	Installed/Active	10/12/2018	PROG5038NRH60	Rheem	\$ 1,174.86	\$ 12.09
24403	Installed/Active	10/08/2018	PH199119	Phoenix	\$ 8,231.98	\$ 63.09
24404	Installed/Active	09/22/2018	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24405	Installed/Active	09/22/2018	G82156	RHEEM	\$ 5,431.44	\$ 54.25
24406	Installed/Active	09/19/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24407	Installed/Active	09/21/2018	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24408	Installed/Active	10/17/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24409	Installed/Active	10/19/2018	PROG5038NRH60	RHEEM	\$ 1,361.42	\$ 12.09
24410	Installed/Active	10/19/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 19.60
24411	Installed/Active	10/18/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 5.83
24412	Installed/Active	10/19/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24413	Installed/Active	10/16/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15
24414	Installed/Active	10/20/2018	PROG5036NRH60DV	RHEEM	\$ 2,099.97	\$ 17.15
24415	Installed/Active	10/17/2018	PROG5038NRH60	RHEEM	\$ 1,207.97	\$ 12.09
24416	Installed/Active	10/19/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24417	Installed/Active	10/18/2018	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24418	Installed/Active	10/17/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24419	Installed/Active	10/20/2018	PH199119	PHOENIX	\$ 8,467.58	\$ 63.09
24420	Installed/Active	10/20/2018	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24421	Installed/Active	10/19/2018	PROG5036NRH60DV	RHEEM	\$ 2,221.32	\$ 17.15
24422	Installed/Active	10/16/2018	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24423	Installed/Active	10/19/2018	PROG4038NRH62	RHEEM	\$ 1,139.12	\$ 5.83
24424	Installed/Active	10/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24425	Installed/Active	10/21/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24426	Installed/Active	10/15/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24427	Installed/Active	10/17/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24428	Installed/Active	10/18/2018	RG2DV50S6N	BRADFORD-WHITE	\$ 2,365.85	\$ 17.15
24429	Installed/Active	10/15/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24430	Installed/Active	10/18/2018	PROG5038NRH60	Rheem	\$ 1,238.37	\$ 12.09
24431	Installed/Active	10/16/2018	PROG40S38NRH62	Rheem	\$ 1,167.57	\$ 7.37
24432	Installed/Active	10/20/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24433	Installed/Active	10/16/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24434	Installed/Active	10/26/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24435	Installed/Active	10/23/2018	PROG5036NRH60DV	RHEEM	\$ 2,104.56	\$ 10.57
24436	Installed/Active	10/23/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24437	Installed/Active	10/22/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24438	Installed/Active	10/22/2018	PROG2932NRH63	Rheem	\$ 1,569.98	\$ 5.83
24439	Installed/Active	10/24/2018	PROG5038NRH60	Rheem	\$ 1,177.37	\$ 12.09
24440	Installed/Active	10/27/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24441	Installed/Active	10/26/2018	MI5036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.09
24442	Installed/Active	10/28/2018	PROG5038NRH60	Rheem	\$ 1,174.84	\$ 12.09
24443	Installed/Active	10/22/2018	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 5.83
24444	Installed/Active	10/24/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24445	Installed/Active	11/03/2018	PROG5038NRH60	Rheem	\$ 850.00	\$ 12.09
24446	Installed/Active	10/29/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24447	Installed/Active	10/29/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24448	Installed/Active	10/29/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24449	Installed/Active	10/29/2018	PROG5038NRH60	Rheem	\$ 1,168.62	\$ 12.09
24450	Installed/Active	10/30/2018	RG2DV50S6N	Bradford White	\$ 2,347.89	\$ 17.15
24451	Installed/Active	11/03/2018	PROG5038NRH60	Rheem	\$ 1,168.62	\$ 12.09
24452	Installed/Active	11/03/2018	PROG5036NRH60DV	Rheem	\$ 2,117.93	\$ 17.15
24453	Installed/Active	10/29/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 12.09
24454	Installed/Active	10/24/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24455	Installed/Active	10/25/2018	RG2DV50S6N	Bradford White	\$ 2,354.99	\$ 17.15
24456	Installed/Active	10/23/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24457	Installed/Active	10/26/2018	PROG4038NRH62	Rheem	\$ 1,126.96	\$ 12.09
24458	Installed/Active	10/05/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24459	Installed/Active	11/03/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 7.37
24460	Installed/Active	11/03/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24461	Installed/Active	11/01/2018	PROG4038NRH62	RHEEM	\$ 1,083.62	\$ 12.09
24462	Installed/Active	10/31/2018	PROG40S38NRH62	RHEEM	\$ 1,152.96	\$ 12.09
24463	Installed/Active	10/30/2018	PROG5038NRH60	Rheem	\$ 1,168.62	\$ 12.09
24464	Installed/Active	10/31/2018	PROG5036NRH60DV	Rheem	\$ 2,063.32	\$ 17.15
24465	Installed/Active	11/04/2018	PROG4038NRH62	Rheem	\$ 1,112.96	\$ 12.09
24466	Installed/Active	11/04/2018	G91200	Rheem	\$ 5,587.06	\$ 63.09
24467	Installed/Active	10/30/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,329.24	\$ 17.15
24468	Installed/Active	11/02/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24469	Installed/Active	11/02/2018	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
24470	Installed/Active	11/02/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 5.83
24471	Installed/Active	10/31/2018	PROG5036NRH60DV	RHEEM	\$ 2,136.36	\$ 17.15
24472	Installed/Active	11/01/2018	PROG5038NRH60	Rheem	\$ 1,203.62	\$ 12.09
24473	Installed/Active	11/04/2018	PROG5038NRH60	Rheem	\$ 1,206.77	\$ 12.09
24474	Installed/Active	11/02/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24475	Installed/Active	11/02/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24476	Installed/Active	10/30/2018	PROG50S40NRH61	Rheem	\$ 1,329.89	\$ 12.09
24477	Installed/Active	11/09/2018	PROG50S40NRH61	RHEEM	\$ 1,389.89	\$ 12.09
24478	Installed/Active	11/09/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24479	Installed/Active	11/10/2018	PROG5038NRH60	RHEEM	\$ 1,159.78	\$ 12.09
24480	Installed/Active	11/11/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24481	Installed/Active	11/11/2018	PROG5038NRH60	RHEEM	\$ 1,183.62	\$ 12.09
24482	Installed/Active	11/10/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24483	Installed/Active	11/09/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24484	Installed/Active	11/08/2018	PROG5038NRH60	RHEEM	\$ 1,177.37	\$ 12.09
24485	Installed/Active	11/10/2018	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24486	Installed/Active	11/08/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24487	Installed/Active	11/09/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24488	Installed/Active	11/07/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24489	Installed/Active	11/05/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24490	Installed/Active	11/08/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24491	Installed/Active	11/07/2018	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 12.09
24492	Installed/Active	11/09/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24493	Installed/Active	11/09/2018	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24494	Installed/Active	11/09/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24495	Installed/Active	11/15/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24496	Installed/Active	11/12/2018	PROG4038NRH62	RHEEM	\$ 1,113.46	\$ 12.09
24497	Installed/Active	11/13/2018	G91200	RHEEM	\$ 5,578.02	\$ 63.09
24498	Installed/Active	11/14/2018	PROG5036NRH60DV	RHEEM	\$ 2,089.48	\$ 17.15
24499	Installed/Active	11/16/2018	PROG40S38NRH62	RHEEM	\$ 1,122.47	\$ 12.09
24500	Installed/Active	11/16/2018	PROG5038NRH60	Rheem	\$ 1,147.62	\$ 5.83
24501	Installed/Active	11/15/2018	PROG5038NRH60	Rheem	\$ 1,191.37	\$ 12.09
24502	Installed/Active	11/23/2018	PROG5038NRH60	RHEEM	\$ 1,174.86	\$ 12.09
24503	Installed/Active	11/21/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24504	Installed/Active	11/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24505	Installed/Active	11/21/2018	G76200	RHEEM	\$ 5,279.96	\$ 63.09
24506	Installed/Active	11/20/2018	PROG5038NRH60	RHEEM	\$ 1,251.92	\$ 5.83
24507	Installed/Active	11/19/2018	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 5.83
24508	Installed/Active	11/21/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 5.83
24509	Installed/Active	11/19/2018	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 5.83
24510	Installed/Active	11/17/2018	PROG5036NRH60DV	Rheem	\$ 2,119.78	\$ 17.15

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24511	Installed/Active	11/21/2018	PROG4038NRH62	RHEEM	\$ 1,223.42	\$ 12.09
24512	Installed/Active	11/16/2018	PROG5038NRH60	Rheem	\$ 1,144.62	\$ 12.09
24513	Installed/Active	11/16/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24514	Installed/Active	11/19/2018	PROG5038NRH60	Rheem	\$ 1,208.62	\$ 12.09
24515	Installed/Active	11/20/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24516	Installed/Active	11/24/2018	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24517	Installed/Active	11/20/2018	PROG5036NRH60DV	Rheem	\$ 2,072.83	\$ 17.15
24518	Installed/Active	11/23/2018	G91200	Rheem	\$ 5,401.56	\$ 63.09
24519	Installed/Active	11/19/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24520	Installed/Active	11/19/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24521	Installed/Active	11/20/2018	PH13055	PHOENIX	\$ 6,754.79	\$ 63.09
24522	Installed/Active	11/21/2018	G75125	Rheem	\$ 4,337.57	\$ 40.51
24523	Installed/Active	11/18/2018	PROG5038NRH60	Rheem	\$ 1,193.62	\$ 12.09
24524	Installed/Active	11/30/2018	PROG5038NRH60	Rheem	\$ 1,291.62	\$ 12.09
24525	Installed/Active	11/28/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24526	Installed/Active	12/02/2018	PROG50S40NRH61	Rheem	\$ 1,456.35	\$ 12.09
24527	Installed/Active	11/30/2018	PROG5036NRH60DV	Rheem	\$ 2,099.87	\$ 17.15
24528	Installed/Active	11/28/2018	PROG40S38NRH62	Rheem	\$ 1,139.12	\$ 12.09
24529	Installed/Active	12/03/2018	PROG5038NRH60	RHEEM	\$ 1,361.42	\$ 12.09
24530	Installed/Active	12/04/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24531	Installed/Active	12/08/2018	PROG40S38NRH62	RHEEM	\$ 1,127.76	\$ 12.09
24532	Installed/Active	12/04/2018	PROG5038NRH60	RHEEM	\$ 1,198.62	\$ 12.09
24533	Installed/Active	12/05/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24534	Installed/Active	11/28/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24535	Installed/Active	11/26/2018	PROG5036NRH60DV	Rheem	\$ 2,138.97	\$ 17.15
24536	Installed/Active	11/26/2018	PROG50S40NRH61	Rheem	\$ 1,339.40	\$ 5.83
24537	Installed/Active	11/26/2018	PROG5038NRH60	Rheem	\$ 1,361.42	\$ 12.09
24538	Installed/Active	11/28/2018	M15036FBN	BRADFORD-WHITE	\$ 850.00	\$ 12.09
24539	Installed/Active	12/04/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24540	Installed/Active	12/04/2018	G91200	RHEEM	\$ 5,451.56	\$ 63.09
24541	Installed/Active	12/09/2018	G91200	RHEEM	\$ 5,584.27	\$ 63.09
24542	Installed/Active	12/09/2018	PROG5038NRH60	RHEEM	\$ 1,165.62	\$ 12.09
24543	Installed/Active	12/07/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24544	Installed/Active	12/08/2018	PROG4038NRH62	RHEEM	\$ 1,122.47	\$ 5.83
24545	Installed/Active	12/08/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 7.37
24546	Installed/Active	12/09/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24547	Installed/Active	12/08/2018	PROG40S38NRH62	RHEEM	\$ 1,340.76	\$ 7.37
24548	Installed/Active	12/06/2018	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24549	Installed/Active	12/06/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,384.39	\$ 17.15
24550	Installed/Active	12/05/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24551	Installed/Active	12/06/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24552	Installed/Active	12/04/2018	G75125	RHEEM	\$ 1,900.00	\$ 40.51
24553	Installed/Active	12/01/2018	PROG5036NRH60DV	RHEEM	\$ 2,107.07	\$ 17.15
24554	Installed/Active	11/27/2018	PROG4038NRH62	RHEEM	\$ 1,112.96	\$ 12.09
24555	Installed/Active	12/03/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24556	Installed/Active	11/30/2018	RG140T6N	BRADFORD WHITE	\$ 1,205.93	\$ 12.09
24557	Installed/Active	11/26/2018	PROG2932NRH63	RHEEM	\$ 1,393.52	\$ 12.09
24558	Installed/Active	11/30/2018	PROG40S38NRH62	RHEEM	\$ 1,112.96	\$ 5.83
24559	Installed/Active	11/30/2018	PROG5038NRH60	RHEEM	\$ 1,277.37	\$ 16.78
24560	Installed/Active	11/28/2018	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
24561	Installed/Active	11/28/2018	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
24562	Installed/Active	12/02/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24563	Installed/Active	12/02/2018	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 12.09
24564	Installed/Active	11/09/2018	PROG5038NRH60	RHEEM	\$ 1,151.12	\$ 12.09
24565	Installed/Active	11/05/2018	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24566	Installed/Active	11/30/2018	PROG7576NRH	RHEEM	\$ 2,123.37	\$ 40.51
24567	Installed/Active	11/29/2018	G91200	RHEEM	\$ 5,551.56	\$ 63.09
24568	Installed/Active	11/28/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,365.85	\$ 17.15
24569	Installed/Active	11/26/2018	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24570	Installed/Active	12/01/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24571	Installed/Active	11/28/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24572	Installed/Active	11/30/2018	PROG4038NRH62	Rheem	\$ 1,167.57	\$ 12.09
24573	Installed/Active	12/01/2018	PROG5036NRH60DV	Rheem	\$ 2,013.32	\$ 17.15
24574	Installed/Active	12/04/2018	PROG5038NRH60TT	Rheem	\$ 1,083.62	\$ 12.09
24575	Installed/Active	12/07/2018	PROG5038NRH60TT	Rheem	\$ 1,083.62	\$ 12.09
24576	Installed/Active	12/07/2018	PROG7576N	Rheem	\$ 1,908.37	\$ 40.51
24577	Installed/Active	12/07/2018	PROG40S38NRH62	Rheem	\$ 1,149.61	\$ 5.83
24578	Installed/Active	12/08/2018	PROG5038NRH60TT	RHEEM	\$ 1,148.62	\$ 12.09
24579	Installed/Active	12/09/2018	PROG5038NRH60TT	Rheem	\$ 1,260.08	\$ 12.09
24580	Installed/Active	12/05/2018	PROG5038NRH60TT	Rheem	\$ 1,083.62	\$ 12.09
24581	Installed/Active	12/03/2018	PROG5038NRH60TT	Rheem	\$ 1,188.23	\$ 12.09
24582	Installed/Active	12/04/2018	PROG5038NRH60TT	Rheem	\$ 1,278.00	\$ 12.09
24583	Installed/Active	12/04/2018	PROG50S40NRH61	A. O. SMITH	\$ 1,373.64	\$ 12.09
24584	Installed/Active	12/03/2018	PROG4038NRH62TT	Rheem	\$ 1,126.96	\$ 5.83
24585	Installed/Active	12/05/2018	PROG5038NRH60TT	Rheem	\$ 1,173.62	\$ 12.09
24586	Installed/Active	12/08/2018	PROG4038NRH62TT	Rheem	\$ 1,183.96	\$ 5.83
24587	Installed/Active	12/06/2018	PROG4038NRH62TT	Rheem	\$ 1,113.46	\$ 7.37
24588	Installed/Active	12/08/2018	PROG5036NRH60DV	Rheem	\$ 2,098.32	\$ 12.09
24589	Installed/Active	12/09/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24590	Installed/Active	12/12/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24591	Installed/Active	12/12/2018	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24592	Installed/Active	12/13/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24593	Installed/Active	12/13/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24594	Installed/Active	12/11/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24595	Installed/Active	12/11/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24596	Installed/Active	12/11/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24597	Installed/Active	12/11/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24598	Installed/Active	12/12/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24599	Installed/Active	12/14/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24600	Installed/Active	12/14/2018	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 12.09
24601	Installed/Active	12/15/2018	PROG4038NRH62	RHEEM	\$ 1,126.96	\$ 12.09
24602	Installed/Active	12/15/2018	PROG5038NRH60	RHEEM	\$ 1,151.12	\$ 12.09
24603	Installed/Active	12/16/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24604	Installed/Active	12/16/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24605	Installed/Active	12/13/2018	PROG40S38NRH62	RHEEM	\$ 1,144.96	\$ 7.37
24606	Installed/Active	12/12/2018	PROG5038NRH60	RHEEM	\$ 1,227.62	\$ 12.09
24607	Installed/Active	12/10/2018	PROG5038NRH60	RHEEM	\$ 1,151.12	\$ 12.09
24608	Installed/Active	12/16/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24609	Installed/Active	12/08/2018	PROG4038NRH62	RHEEM	\$ 1,150.96	\$ 5.83
24610	Installed/Active	12/10/2018	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
24611	Installed/Active	12/14/2018	PROG5038NRH60	RHEEM	\$ 1,185.62	\$ 14.90
24612	Installed/Active	12/16/2018	PROG5038NRH60	RHEEM	\$ 1,144.62	\$ 12.09
24613	Installed/Active	12/16/2018	PROG40S38NRH62	RHEEM	\$ 1,239.42	\$ 12.09
24614	Installed/Active	12/14/2018	G82156	RHEEM	\$ 5,314.10	\$ 54.25
24615	Installed/Active	12/13/2018	RG2DV40S6N	BRADFORD WHITE	\$ 2,326.24	\$ 17.15
24616	Installed/Active	12/13/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24617	Installed/Active	12/13/2018	PROG40S38NRH62	RHEEM	\$ 1,239.42	\$ 7.37
24618	Installed/Active	12/10/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24619	Installed/Active	12/15/2018	PROG50S40NRH61	RHEEM	\$ 1,404.89	\$ 12.09
24620	Installed/Active	12/11/2018	PROG5038NRH60	RHEEM	\$ 1,208.62	\$ 12.09
24621	Installed/Active	12/12/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24622	Installed/Active	12/15/2018	BTH199	AO SMITH	\$ 8,914.00	\$ 63.09
24623	Installed/Active	12/20/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 5.83
24624	Installed/Active	12/19/2018	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24625	Installed/Active	12/22/2018	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 5.83
24626	Installed/Active	12/20/2018	PROG5038NRH60	RHEEM	\$ 1,251.92	\$ 12.09
24627	Installed/Active	12/21/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24628	Installed/Active	12/19/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24629	Installed/Active	12/20/2018	PROG5036NRH60DV	RHEEM	\$ 2,144.32	\$ 17.15
24630	Installed/Active	12/20/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24631	Installed/Active	12/17/2018	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24632	Installed/Active	12/22/2018	PROG5038NRH60	RHEEM	\$ 850.00	\$ 12.09
24633	Installed/Active	12/21/2018	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 5.83
24634	Installed/Active	12/22/2018	PROG40S38NRH62	RHEEM	\$ 1,122.47	\$ 5.83
24635	Installed/Active	12/22/2018	RG2DV50S6N	BRADFORD WHITE	\$ 2,328.74	\$ 17.15
24636	Installed/Active	12/23/2018	PROG5038NRH60	RHEEM	\$ 1,177.37	\$ 12.09
24637	Installed/Active	12/21/2018	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24638	Installed/Active	12/21/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24639	Installed/Active	12/21/2018	PROG40S38NRH62	RHEEM	\$ 1,130.96	\$ 5.83
24640	Installed/Active	12/21/2018	RG250H6N	BRADFORD WHITE	\$ 1,800.40	\$ 16.78
24641	Installed/Active	12/22/2018	PROG5038NRH60	RHEEM	\$ 1,144.62	\$ 12.09
24642	Installed/Active	12/18/2018	RG250H6N	BRADFORD WHITE	\$ 1,713.75	\$ 16.78
24643	Installed/Active	12/18/2018	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
24644	Installed/Active	12/19/2018	G82156	RHEEM	\$ 5,203.64	\$ 54.25
24645	Installed/Active	12/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24646	Installed/Active	12/20/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24647	Installed/Active	12/18/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24648	Installed/Active	12/20/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24649	Installed/Active	12/18/2018	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24650	Installed/Active	12/17/2018	G82156	RHEEM	\$ 5,243.64	\$ 54.25
24651	Installed/Active	12/29/2018	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24652	Installed/Active	12/28/2018	RG2DV50S6N	Bradford White	\$ 2,539.04	\$ 17.15
24653	Installed/Active	12/24/2018	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 5.83
24654	Installed/Active	12/30/2018	MI5036FBN	Bradford White	\$ 850.00	\$ 12.09
24655	Installed/Active	12/24/2018	PROG5038NRH60	RHEEM	\$ 1,147.62	\$ 12.09
24656	Installed/Active	12/28/2018	RG250H6N	Bradford White	\$ 1,758.75	\$ 16.78
24657	Installed/Active	12/31/2018	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24658	Installed/Active	12/28/2018	PROG5038NRH60	RHEEM	\$ 1,195.44	\$ 12.09
24659	Installed/Active	12/26/2018	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 16.78
24660	Installed/Active	12/28/2018	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 5.83
24661	Installed/Active	01/06/2019	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
24662	Installed/Active	01/05/2019	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24663	Installed/Active	12/31/2018	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24664	Installed/Active	01/05/2019	PROG5038NRH60	RHEEM	\$ 1,183.62	\$ 12.09
24665	Installed/Active	11/28/2018	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24666	Installed/Active	12/07/2018	G82156	RHEEM	\$ 5,418.64	\$ 54.25
24667	Installed/Active	01/19/2018	PROG5038NRH60	RHEEM	\$ 1,113.00	\$ 12.76
24668	Installed/Active	01/02/2019	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 12.09
24669	Installed/Active	01/02/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
24670	Installed/Active	01/03/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24671	Installed/Active	01/04/2019	PROG40S38NRH62	RHEEM	\$ 1,129.96	\$ 5.83
24672	Installed/Active	01/04/2019	PROG4038NRH62	RHEEM	\$ 1,122.47	\$ 12.09
24673	Installed/Active	01/05/2019	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24674	Installed/Active	01/06/2019	PROG5038NRH60	BRADFORD WHITE	\$ 1,291.62	\$ 16.78
24675	Installed/Active	01/05/2019	G76200	RHEEM	\$ 5,244.96	\$ 63.09
24676	Installed/Active	01/04/2019	PROG4038NRH62	RHEEM	\$ 1,129.96	\$ 5.83
24677	Installed/Active	01/02/2019	PH13055	PHOENIX	\$ 6,754.79	\$ 63.09
24678	Installed/Active	01/04/2019	PROG5038NRH60	RHEEM	\$ 1,144.62	\$ 12.09
24679	Installed/Active	01/03/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24680	Installed/Active	01/03/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24681	Installed/Active	01/02/2019	RG2DV40S6N	Bradford White	\$ 2,261.24	\$ 17.15
24682	Installed/Active	01/05/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24683	Installed/Active	01/05/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24684	Installed/Active	12/24/2018	PROG5038NRH60	Rheem	\$ 1,291.62	\$ 12.09
24685	Installed/Active	11/28/2018	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24686	Installed/Active	11/30/2018	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 7.37
24687	Installed/Active	11/27/2018	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24688	Installed/Active	12/04/2018	PH199119	PHOENIX	\$ 8,396.98	\$ 63.09
24689	Installed/Active	01/22/2019	21VR40	RHEEM	\$ 50.00	\$ 12.09
24690	Installed/Active	01/04/2019	PROG5038NRH60	RHEEM	\$ 1,136.62	\$ 12.09
24691	Installed/Active	01/10/2019	PROG5038NRH60	RHEEM	\$ 1,291.62	\$ 5.83
24692	Installed/Active	01/10/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24693	Installed/Active	01/11/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24694	Installed/Active	01/11/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24695	Installed/Active	01/07/2019	PROG4038NRH62	RHEEM	\$ 1,257.34	\$ 7.37
24696	Installed/Active	01/10/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 12.09
24697	Installed/Active	01/12/2019	PROG50S40NRH61	Rheem	\$ 1,440.35	\$ 12.09
24698	Installed/Active	01/14/2019	G75125	Rheem	\$ 4,456.57	\$ 40.51
24699	Installed/Active	01/09/2019	PROG5036NRH60DV	Rheem	\$ 2,013.32	\$ 17.15
24700	Installed/Active	01/12/2019	PROG5038NRH60	Rheem	\$ 1,174.86	\$ 12.09
24701	Installed/Active	01/11/2019	RG250H6N	Bradford White	\$ 1,798.75	\$ 16.78
24702	Installed/Active	01/13/2019	PROG5038NRH60	Rheem	\$ 1,243.62	\$ 12.09
24703	Installed/Active	01/10/2019	PROG5036NRH60DV	Rheem	\$ 2,104.56	\$ 17.15
24704	Installed/Active	01/09/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24705	Installed/Active	01/07/2019	PROG2932NRH63	Rheem	\$ 1,393.52	\$ 5.83
24706	Installed/Active	01/16/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 12.09
24707	Installed/Active	01/16/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24708	Installed/Active	01/18/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24709	Installed/Active	01/20/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24710	Installed/Active	01/19/2019	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24711	Installed/Active	01/17/2019	PROG4038NRH62	Rheem	\$ 1,123.96	\$ 5.83
24712	Installed/Active	01/19/2019	PROG5036NRH60DV	Rheem	\$ 2,104.56	\$ 17.15
24713	Installed/Active	01/19/2019	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24714	Installed/Active	01/18/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
24715	Installed/Active	01/14/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24716	Installed/Active	01/09/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24717	Installed/Active	01/21/2019	PROG40S38NRH62	Rheem	\$ 1,239.42	\$ 12.09
24718	Installed/Active	01/18/2019	PROG5038NRH60	Rheem	\$ 1,144.62	\$ 7.37
24719	Installed/Active	01/18/2019	PROG5038NRH60	Rheem	\$ 1,151.12	\$ 12.09
24720	Installed/Active	01/15/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24721	Installed/Active	01/15/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 12.09
24722	Installed/Active	01/14/2019	PROG4038NRH62	Rheem	\$ 1,167.57	\$ 12.09
24723	Installed/Active	01/15/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24724	Installed/Active	01/17/2019	PROG5038NRH60	Rheem	\$ 1,244.08	\$ 12.09
24725	Installed/Active	01/19/2019	PROG5038NRH60	Rheem	\$ 1,147.17	\$ 12.09
24726	Installed/Active	01/15/2019	PROG5038NRH60	Rheem	\$ 1,171.62	\$ 12.09
24727	Installed/Active	01/14/2019	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 12.09
24728	Installed/Active	01/14/2019	PROG5038NRH60	Rheem	\$ 1,151.12	\$ 12.09
24729	Installed/Active	01/15/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
24730	Installed/Active	01/23/2019	PROG5038NRH60	RHEEM	\$ 1,209.62	\$ 5.83
24731	Installed/Active	01/22/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24732	Installed/Active	01/23/2019	G76200	RHEEM	\$ 5,194.96	\$ 63.09
24733	Installed/Active	01/21/2019	PROG40S38NRH62	RHEEM	\$ 1,112.96	\$ 7.37
24734	Installed/Active	01/21/2019	G76200	RHEEM	\$ 5,194.96	\$ 63.09
24735	Installed/Active	01/23/2019	PROG4860NRH60	RHEEM	\$ 1,326.23	\$ 12.09
24736	Installed/Active	01/24/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24737	Installed/Active	01/24/2019	PH199119	PHOENIX	\$ 7,734.49	\$ 63.09
24738	Installed/Active	01/25/2019	PROG5038NRH60	RHEEM	\$ 1,144.97	\$ 5.83
24739	Installed/Active	01/24/2019	PROG2932NRH63	RHEEM	\$ 1,587.90	\$ 5.83
24740	Installed/Active	01/24/2019	PROG5038NRH60	RHEEM	\$ 1,174.86	\$ 12.09
24741	Installed/Active	01/23/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
24742	Installed/Active	01/24/2019	PROG4860NRH60	RHEEM	\$ 1,363.84	\$ 16.78
24743	Installed/Active	01/26/2019	PROG5038NRH60	RHEEM	\$ 1,138.62	\$ 12.09
24744	Installed/Active	01/25/2019	PROG5038NRH60	Rheem	\$ 1,152.62	\$ 5.83
24745	Installed/Active	01/22/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24746	Installed/Active	01/24/2019	PROG4860NRH60	RHEEM	\$ 1,312.23	\$ 19.60
24747	Installed/Active	01/25/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
24748	Installed/Active	01/27/2019	PROG5038NRH60	Rheem	\$ 1,138.62	\$ 12.09
24749	Installed/Active	02/02/2019	PROG40S38NRH62	RHEEM	\$ 1,122.47	\$ 12.09
24750	Installed/Active	01/31/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24751	Installed/Active	01/29/2019	PROG5038NRH60	RHEEM	\$ 1,208.62	\$ 12.09
24752	Installed/Active	01/29/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24753	Installed/Active	01/29/2019	G91200	RHEEM	\$ 5,931.56	\$ 63.09
24754	Installed/Active	01/31/2019	PROG2932NRH63	Rheem	\$ 1,393.52	\$ 12.09
24755	Installed/Active	01/29/2019	G76200	Rheem	\$ 5,194.96	\$ 63.09
24756	Installed/Active	01/29/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
24757	Installed/Active	01/28/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24758	Installed/Active	02/01/2019	PROG5038NRH60	Rheem	\$ 1,151.62	\$ 12.09
24759	Installed/Active	01/30/2019	PROG5038NRH60	Rheem	\$ 1,145.87	\$ 12.09
24760	Installed/Active	02/02/2019	RG2DV50S6N	Bradford White	\$ 2,328.24	\$ 17.15
24761	Installed/Active	02/01/2019	PROG5038NRH60	Rheem	\$ 1,206.77	\$ 12.09
24762	Installed/Active	01/31/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15
24763	Installed/Active	02/01/2019	PROG5038NRH60	RHEEM	\$ 1,212.62	\$ 12.09
24764	Installed/Active	02/01/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24765	Installed/Active	01/30/2019	PROG5038NRH60	RHEEM	\$ 1,212.62	\$ 12.09
24766	Installed/Active	01/30/2019	PROG5038NRH60	RHEEM	\$ 1,212.62	\$ 12.09
24767	Installed/Active	01/31/2019	PROG5038NRH60	RHEEM	\$ 1,209.62	\$ 12.09
24768	Installed/Active	02/08/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24769	Installed/Active	02/07/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 12.09
24770	Installed/Active	02/07/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 16.78
24771	Installed/Active	02/06/2019	PROG5038NRH60	Rheem	\$ 1,278.00	\$ 12.09
24772	Installed/Active	02/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 5.83
24773	Installed/Active	02/05/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24774	Installed/Active	02/05/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24775	Installed/Active	02/08/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
24776	Installed/Active	02/06/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24777	Installed/Active	02/05/2019	PROG4860NRH60	RHEEM	\$ 1,419.23	\$ 19.60
24778	Installed/Active	01/30/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24779	Installed/Active	01/18/2019	PROG5038NRH60	RHEEM	\$ 1,227.62	\$ 12.09
24780	Installed/Active	02/13/2019	RG2DV50S6N	Bradford White	\$ 2,365.85	\$ 17.15
24781	Installed/Active	02/14/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 7.37
24782	Installed/Active	02/17/2019	PROG50S40NRH61	RHEEM	\$ 1,456.35	\$ 12.09
24783	Installed/Active	02/16/2019	PROG5036NRH60DV	Rheem	\$ 2,081.32	\$ 17.15
24784	Installed/Active	02/15/2019	G91200	Rheem	\$ 5,486.56	\$ 63.09
24785	Installed/Active	02/17/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24786	Installed/Active	02/17/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
24787	Installed/Active	02/13/2019	PROG30S30NRH63	Rheem	\$ 1,443.52	\$ 5.83
24788	Installed/Active	02/14/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24789	Installed/Active	02/13/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,320.75	\$ 17.15
24790	Installed/Active	02/13/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24791	Installed/Active	02/15/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24792	Installed/Active	02/06/2019	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
24793	Installed/Active	02/12/2019	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24794	Installed/Active	02/15/2019	PROG5036NRH60DV	RHEEM	\$ 2,063.32	\$ 17.15
24795	Installed/Active	02/13/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 5.83
24796	Installed/Active	02/17/2019	PROG4860NRH60	RHEEM	\$ 1,326.23	\$ 16.78
24797	Installed/Active	02/20/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24798	Installed/Active	02/23/2019	G75125	RHEEM	\$ 4,531.95	\$ 40.51
24799	Installed/Active	02/20/2019	PROG5036NRH60DV	RHEEM	\$ 2,101.32	\$ 17.15
24800	Installed/Active	02/22/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24801	Installed/Active	02/20/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24802	Installed/Active	02/22/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
24803	Installed/Active	02/19/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24804	Installed/Active	02/20/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24805	Installed/Active	02/23/2019	PROG5038NRH60	RHEEM	\$ 1,152.62	\$ 12.09
24806	Installed/Active	02/23/2019	PROG4038NRH62	RHEEM	\$ 1,131.96	\$ 5.83
24807	Installed/Active	02/23/2019	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24808	Installed/Active	02/22/2019	PROG5038NRH60	RHEEM	\$ 1,244.08	\$ 12.09
24809	Installed/Active	02/20/2019	PROG5036NRH60DV	RHEEM	\$ 2,189.78	\$ 12.09
24810	Installed/Active	02/16/2019	RG2DV50S6N	Bradford White	\$ 2,325.24	\$ 17.15
24811	Installed/Active	02/20/2019	PROG5038NRH60	Rheem	\$ 1,174.86	\$ 12.09
24812	Installed/Active	02/13/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 5.83
24813	Installed/Active	02/15/2019	PROG2932NRH63	Rheem	\$ 1,393.52	\$ 5.83
24814	Installed/Active	02/19/2019	RG2DV50S6N	Bradford White	\$ 2,341.24	\$ 10.57
24815	Installed/Active	02/18/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 5.83
24816	Installed/Active	02/23/2019	PROG2932NRH63	Rheem	\$ 1,478.52	\$ 5.83
24817	Installed/Active	02/23/2019	PROG5038NRH60	RHEEM	\$ 1,174.86	\$ 12.09
24818	Installed/Active	02/20/2019	PROG4038NRH62	Rheem	\$ 1,239.42	\$ 5.83
24819	Installed/Active	02/20/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24820	Installed/Active	02/23/2019	PROG5038NRH60	Rheem	\$ 1,144.97	\$ 12.09
24821	Installed/Active	02/21/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
24822	Installed/Active	02/18/2019	RG2DV50S6N	Bradford White	\$ 2,384.39	\$ 17.15
24823	Installed/Active	02/18/2019	G82156	Rheem	\$ 5,240.29	\$ 54.25
24824	Installed/Active	02/18/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
24825	Installed/Active	02/27/2019	PROG5038NRH60	Rheem	\$ 1,297.62	\$ 12.09
24826	Installed/Active	02/25/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24827	Installed/Active	02/26/2019	RG2DV50S6N	Bradford White	\$ 2,347.89	\$ 17.15
24828	Installed/Active	03/01/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24829	Installed/Active	03/01/2019	PROG4860NRH60	RHEEM	\$ 1,344.23	\$ 16.78
24830	Installed/Active	03/01/2019	PROG40S38NRH62	Rheem	\$ 1,276.96	\$ 12.09
24831	Installed/Active	03/03/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 5.83
24832	Installed/Active	03/02/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24833	Installed/Active	02/28/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 12.09
24834	Installed/Active	02/26/2019	PROG40S38NRH62	Rheem	\$ 1,117.96	\$ 5.83
24835	Installed/Active	02/28/2019	PROG50S40NRH61	Rheem	\$ 1,391.71	\$ 12.09
24836	Installed/Active	02/28/2019	PROG40S38NRH62	Rheem	\$ 1,239.42	\$ 12.09
24837	Installed/Active	02/26/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24838	Installed/Active	02/26/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 7.37
24839	Installed/Active	02/26/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24840	Installed/Active	02/28/2019	PH19980	PHOENIX	\$ 7,860.95	\$ 63.09
24841	Installed/Active	02/24/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24842	Installed/Active	02/27/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
24843	Installed/Active	03/02/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24844	Installed/Active	03/01/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24845	Installed/Active	03/01/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
24846	Installed/Active	03/02/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24847	Installed/Active	03/01/2019	PROG5038NRH60	RHEEM	\$ 1,195.44	\$ 12.09
24848	Installed/Active	02/27/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24849	Installed/Active	02/27/2019	PROG5038NRH60	RHEEM	\$ 1,208.62	\$ 12.09
24850	Installed/Active	02/28/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
24851	Installed/Active	03/02/2019	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
24852	Installed/Active	03/01/2019	PROG5038NRH60	RHEEM	\$ 1,138.62	\$ 12.09
24853	Installed/Active	03/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 7.37
24854	Installed/Active	03/04/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24855	Installed/Active	03/05/2019	PROG5038NRH60	Rheem	\$ 1,171.62	\$ 16.78
24856	Installed/Active	03/05/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 19.60
24857	Installed/Active	03/04/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24858	Installed/Active	03/08/2019	PROG5038NRH60	Rheem	\$ 1,212.62	\$ 12.09
24859	Installed/Active	03/06/2019	PROG4860NRH60	RHEEM	\$ 1,326.23	\$ 16.78
24860	Installed/Active	03/05/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 5.83
24861	Installed/Active	03/04/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 7.37
24862	Installed/Active	03/04/2019	RG2DV50S6N	Bradford White	\$ 2,261.24	\$ 17.15
24863	Installed/Active	03/06/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24864	Installed/Active	03/08/2019	PROG40S38NRH62	Rheem	\$ 1,062.00	\$ 5.83
24865	Installed/Active	03/09/2019	PROG4038NRH62	Rheem	\$ 1,350.50	\$ 12.09
24866	Installed/Active	02/19/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24867	Installed/Active	03/08/2019	PROG5038NRH60	RHEEM	\$ 1,371.16	\$ 12.09
24868	Installed/Active	03/05/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24869	Installed/Active	03/10/2019	PROG5038NRH60	RHEEM	\$ 1,163.72	\$ 12.09
24870	Installed/Active	03/10/2019	PROG40S38NRH62	RHEEM	\$ 1,239.42	\$ 12.09
24871	Installed/Active	03/04/2019	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 16.78
24872	Installed/Active	03/07/2019	PROG5038NRH60	RHEEM	\$ 1,143.62	\$ 12.09
24873	Installed/Active	03/07/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24874	Installed/Active	03/10/2019	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
24875	Installed/Active	03/10/2019	PROG50S40NRH61	RHEEM	\$ 1,334.89	\$ 12.09
24876	Installed/Active	03/09/2019	PROG4038NRH62	RHEEM	\$ 1,143.06	\$ 7.37
24877	Installed/Active	03/09/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24878	Installed/Active	03/08/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24879	Installed/Active	03/13/2019	PROG50S40NRH61	RHEEM	\$ 1,379.89	\$ 12.09
24880	Installed/Active	03/14/2019	PROG5038NRH60	RHEEM	\$ 1,163.72	\$ 12.09
24881	Installed/Active	03/16/2019	PROG5038NRH60	RHEEM	\$ 1,208.62	\$ 12.09
24882	Installed/Active	03/12/2019	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24883	Installed/Active	03/15/2019	PROG5038NRH60	RHEEM	\$ 1,155.62	\$ 12.09
24884	Installed/Active	03/18/2019	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
24885	Installed/Active	03/17/2019	PROG5036NRH60DV	RHEEM	\$ 2,098.32	\$ 17.15
24886	Installed/Active	03/17/2019	PROG5038NRH60	RHEEM	\$ 1,144.62	\$ 12.09
24887	Installed/Active	03/14/2019	GSN040	LOCHINVAR	\$ 1,388.21	\$ 12.09
24888	Installed/Active	03/17/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24889	Installed/Active	03/16/2019	PH19955	Phoenix	\$ 6,629.00	\$ 54.25
24890	Installed/Active	03/14/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24891	Installed/Active	03/14/2019	PROG5038NRH60	Rheem	\$ 1,144.16	\$ 12.09
24892	Installed/Active	03/14/2019	GSN040	Lochinvar	\$ 1,380.72	\$ 12.09
24893	Installed/Active	03/14/2019	GSN040	LOCHINVAR	\$ 1,321.21	\$ 12.09
24894	Installed/Active	03/12/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 12.09
24895	Installed/Active	03/17/2019	PROG4038NRH62	Rheem	\$ 1,167.57	\$ 12.09
24896	Installed/Active	03/17/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 7.37
24897	Installed/Active	03/17/2019	PROG5038NRH60	Rheem	\$ 1,174.86	\$ 12.09
24898	Installed/Active	03/16/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24899	Installed/Active	03/15/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24900	Installed/Active	03/17/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
24901	Installed/Active	03/11/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24902	Installed/Active	03/15/2019	G91200	Rheem	\$ 5,666.56	\$ 63.09
24903	Installed/Active	03/17/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
24904	Installed/Active	03/22/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24905	Installed/Active	03/21/2019	PROG5038NRH60	RHEEM	\$ 1,195.44	\$ 12.09
24906	Installed/Active	03/18/2019	PROG5038NRH60	RHEEM	\$ 1,226.14	\$ 7.37
24907	Installed/Active	03/18/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24908	Installed/Active	03/19/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24909	Installed/Active	03/14/2019	G75125	RHEEM	\$ 4,502.57	\$ 40.51
24910	Installed/Active	03/18/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 10.57
24911	Installed/Active	03/21/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
24912	Installed/Active	03/22/2019	PROG5038NRH60	Rheem	\$ 2,117.93	\$ 10.57
24913	Installed/Active	03/24/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24914	Installed/Active	03/23/2019	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 5.83
24915	Installed/Active	03/18/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24916	Installed/Active	03/20/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 5.83
24917	Installed/Active	03/22/2019	G75125	Rheem	\$ 4,867.57	\$ 40.51
24918	Installed/Active	03/19/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 12.09
24919	Installed/Active	03/19/2019	RG2DV50S6N	Bradford White	\$ 2,365.85	\$ 17.15
24920	Installed/Active	03/23/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
24921	Installed/Active	03/18/2019	PROG30S30NRH63	RHEEM	\$ 1,443.52	\$ 12.09
24922	Installed/Active	03/21/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24923	Installed/Active	03/23/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24924	Installed/Active	03/21/2019	PH199119	PHOENIX	\$ 8,231.98	\$ 63.09
24925	Installed/Active	03/22/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24926	Installed/Active	03/18/2019	PROG40S38NRH62	RHEEM	\$ 1,112.96	\$ 12.09
24927	Installed/Active	03/19/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 5.83
24928	Installed/Active	03/23/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 12.09
24929	Installed/Active	03/22/2019	G75125	Rheem	\$ 4,514.03	\$ 40.51
24930	Installed/Active	03/19/2019	PROG5038NRH60	Rheem	\$ 1,260.08	\$ 12.09
24931	Installed/Active	04/05/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 12.09
24932	Installed/Active	04/04/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 12.09
24933	Installed/Active	04/08/2019	RG2DV50S6N	Bradford White	\$ 2,329.24	\$ 17.15
24934	Installed/Active	04/06/2019	PROG5038NRH60	Rheem	\$ 1,297.62	\$ 12.09
24935	Installed/Active	04/06/2019	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24936	Installed/Active	04/04/2019	LTN050G	LOCHINVAR	\$ 850.00	\$ 12.09
24937	Installed/Active	04/08/2019	PROG4038NRH62	Rheem	\$ 1,150.96	\$ 5.83
24938	Installed/Active	03/31/2019	PROG4038NRH62	RHEEM	\$ 1,174.78	\$ 5.83
24939	Installed/Active	04/01/2019	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 5.83
24940	Installed/Active	03/28/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
24941	Installed/Active	03/31/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24942	Installed/Active	03/30/2019	PROG5038NRH60	RHEEM	\$ 1,209.62	\$ 12.09
24943	Installed/Active	03/30/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24944	Installed/Active	03/31/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24945	Installed/Active	03/31/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 12.09
24946	Installed/Active	03/30/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24947	Installed/Active	03/30/2019	G76200	RHEEM	\$ 5,194.96	\$ 63.09
24948	Installed/Active	03/31/2019	G82156	RHEEM	\$ 5,289.97	\$ 54.25
24949	Installed/Active	03/26/2019	G82156	RHEEM	\$ 5,153.64	\$ 54.25
24950	Installed/Active	03/28/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 5.83
24951	Installed/Active	03/26/2019	PROG4038NRH62	RHEEM	\$ 1,143.06	\$ 12.09
24952	Installed/Active	03/29/2019	PROG4038NRH62	RHEEM	\$ 1,149.61	\$ 5.83
24953	Installed/Active	03/25/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,437.70	\$ 17.15
24954	Installed/Active	03/29/2019	G91200	RHEEM	\$ 5,229.00	\$ 63.09
24955	Installed/Active	03/13/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24956	Installed/Active	04/02/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24957	Installed/Active	04/04/2019	PROG5038NRH60	RHEEM	\$ 1,158.95	\$ 12.09
24958	Installed/Active	04/05/2019	PROG5036NRH60DV	RHEEM	\$ 2,093.42	\$ 17.15
24959	Installed/Active	04/05/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 7.37
24960	Installed/Active	04/05/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24961	Installed/Active	04/05/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
24962	Installed/Active	04/05/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
24963	Installed/Active	04/06/2019	PROG5038NRH60	RHEEM	\$ 1,151.59	\$ 12.09
24964	Installed/Active	04/04/2019	PROG4038NRH62	RHEEM	\$ 1,122.47	\$ 5.83
24965	Installed/Active	04/04/2019	PROG5036NRH60DV	RHEEM	\$ 2,081.32	\$ 17.15
24966	Installed/Active	04/01/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24967	Installed/Active	04/02/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
24968	Installed/Active	04/04/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24969	Installed/Active	04/02/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 12.09
24970	Installed/Active	04/02/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24971	Installed/Active	04/09/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 5.83
24972	Installed/Active	04/11/2019	PROG5038NRH60	RHEEM	\$ 1,191.37	\$ 12.09
24973	Installed/Active	04/13/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
24974	Installed/Active	04/10/2019	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
24975	Installed/Active	04/12/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24976	Installed/Active	04/11/2019	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 5.83
24977	Installed/Active	04/10/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
24978	Installed/Active	04/10/2019	PROG5038NRH60	RHEEM	\$ 1,180.52	\$ 12.09
24979	Installed/Active	04/09/2019	PROG50S40NRH61	RHEEM	\$ 1,493.89	\$ 12.09
24980	Installed/Active	04/11/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 5.83
24981	Installed/Active	04/15/2019	PROG5038NRH60	RHEEM	\$ 1,208.62	\$ 12.09
24982	Installed/Active	04/13/2019	PROG50S40NRH61	RHEEM	\$ 1,366.54	\$ 12.09
24983	Installed/Active	04/12/2019	PROG5038NRH60	RHEEM	\$ 1,219.59	\$ 12.09
24984	Installed/Active	04/11/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
24985	Installed/Active	04/14/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24986	Installed/Active	04/12/2019	RG2DV40S6NSLD	Bradford White	\$ 2,261.24	\$ 17.15
24987	Installed/Active	04/09/2019	PROG5038NRH60	RHEEM	\$ 1,244.08	\$ 12.09
24988	Installed/Active	04/10/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
24989	Installed/Active	04/10/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
24990	Installed/Active	04/16/2019	PROG5038NRH60	RHEEM	\$ 1,195.44	\$ 12.09
24991	Installed/Active	04/19/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
24992	Installed/Active	04/19/2019	PROG5038NRH60	RHEEM	\$ 1,170.27	\$ 12.09
24993	Installed/Active	04/18/2019	PROG5036NRH60DV	RHEEM	\$ 2,125.14	\$ 17.15
24994	Installed/Active	04/19/2019	PROG50S40NRH61	RHEEM	\$ 1,347.39	\$ 12.09
24995	Installed/Active	04/19/2019	PROG40S38NRH62	RHEEM	\$ 1,143.06	\$ 12.09
24996	Installed/Active	04/19/2019	PROG5038NRH60	RHEEM	\$ 1,173.62	\$ 12.09
24997	Installed/Active	04/20/2019	PROG4860NRH60	RHEEM	\$ 1,259.23	\$ 16.78
24998	Installed/Active	04/18/2019	PROG5038NRH60	RHEEM	\$ 1,198.62	\$ 12.09
24999	Installed/Active	04/16/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
25000	Installed/Active	04/21/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
25001	Installed/Active	04/15/2019	G91200	RHEEM	\$ 5,666.56	\$ 63.09
25002	Installed/Active	04/17/2019	RG2DV50S6N	Bradford White	\$ 2,403.76	\$ 17.15
25003	Installed/Active	04/21/2019	PROG5038NRH60	RHEEM	\$ 1,165.57	\$ 12.09
25004	Installed/Active	04/20/2019	PROG4038NRH62	RHEEM	\$ 1,122.47	\$ 5.83
25005	Installed/Active	04/21/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25006	Installed/Active	04/20/2019	RG2DV50S6N	Bradford White	\$ 2,528.78	\$ 17.15
25007	Installed/Active	04/20/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25008	Installed/Active	04/19/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
25009	Installed/Active	04/18/2019	PROG7576NRH	RHEEM	\$ 1,858.37	\$ 40.51
25010	Installed/Active	04/15/2019	PROG5038NRH60	RHEEM	\$ 1,180.52	\$ 12.09
25011	Installed/Active	04/24/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 5.83
25012	Installed/Active	04/26/2019	PROG5038NRH60	RHEEM	\$ 1,226.14	\$ 12.09
25013	Installed/Active	04/24/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
25014	Installed/Active	04/22/2019	PROG5038NRH60	RHEEM	\$ 1,147.17	\$ 12.09
25015	Installed/Active	04/26/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
25016	Installed/Active	04/23/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 7.37
25017	Installed/Active	04/22/2019	PROG40S38NRH62	RHEEM	\$ 1,129.96	\$ 12.09
25018	Installed/Active	04/23/2019	PROG5038NRH60	RHEEM	\$ 1,206.77	\$ 12.09
25019	Installed/Active	04/27/2019	PROG5036NRH60DV	RHEEM	\$ 2,072.83	\$ 17.15
25020	Installed/Active	04/23/2019	PROG4038NRH62	RHEEM	\$ 1,167.57	\$ 5.83
25021	Installed/Active	04/28/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25022	Installed/Active	04/23/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
25023	Installed/Active	04/24/2019	PROG5038NRH60	RHEEM	\$ 1,150.00	\$ 5.83
25024	Installed/Active	04/26/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25025	Installed/Active	04/28/2019	PROG40S38NRH62	RHEEM	\$ 1,112.96	\$ 5.83
25026	Installed/Active	04/25/2019	PROG5038NRH60	RHEEM	\$ 1,195.44	\$ 5.83

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
25027	Installed/Active	04/22/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25028	Installed/Active	04/22/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25029	Installed/Active	04/25/2019	PROG5038NRH60	Rheem	\$ 1,063.76	\$ 12.09
25030	Installed/Active	04/23/2019	PROG4038NRH62	Rheem	\$ 1,143.06	\$ 12.09
25031	Installed/Active	04/26/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09
25032	Installed/Active	04/25/2019	RG250T6N	Bradford White	\$ 1,256.26	\$ 12.09
25033	Installed/Active	05/19/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25034	Installed/Active	05/19/2019	PROG5038NRH60	RHEEM	\$ 1,203.60	\$ 16.78
25035	Installed/Active	05/15/2019	PROG2932NRH63	RHEEM	\$ 1,393.52	\$ 5.83
25036	Installed/Active	05/17/2019	PROG40S38NRH62	RHEEM	\$ 1,239.42	\$ 12.09
25037	Installed/Active	05/15/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
25038	Installed/Active	05/13/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
25039	Installed/Active	05/18/2019	PROG5038NRH60	RHEEM	\$ 1,170.62	\$ 5.83
25040	Installed/Active	05/16/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 12.09
25041	Installed/Active	04/30/2019	PROG5038NRH60	Rheem	\$ 1,171.62	\$ 12.09
25042	Installed/Active	05/03/2019	PROG4038NRH62	Rheem	\$ 1,117.96	\$ 5.83
25043	Installed/Active	05/03/2019	G76200	Rheem	\$ 5,194.96	\$ 63.09
25044	Installed/Active	05/03/2019	PROG40S38NRH62	Rheem	\$ 1,131.96	\$ 5.83
25045	Installed/Active	05/01/2019	PROG5038NRH60	Rheem	\$ 1,226.14	\$ 12.09
25046	Installed/Active	05/05/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25047	Installed/Active	05/05/2019	PROG5036NRU60DV	Rheem	\$ 2,095.27	\$ 17.15
25048	Installed/Active	04/30/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
25049	Installed/Active	04/15/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25050	Installed/Active	05/02/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 5.83
25051	Installed/Active	05/10/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 5.83
25052	Installed/Active	05/10/2019	PROG5038NRH60	Rheem	\$ 1,148.62	\$ 12.09
25053	Installed/Active	05/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25054	Installed/Active	05/09/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 7.37
25055	Installed/Active	05/09/2019	BTH199	AO Smith	\$ 8,789.00	\$ 63.09
25056	Installed/Active	05/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25057	Installed/Active	05/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25058	Installed/Active	05/08/2019	RG2DV50S6N	Bradford White	\$ 2,437.70	\$ 17.15
25059	Installed/Active	05/11/2019	PROG2932NRU62	Rheem	\$ 850.00	\$ 5.83
25060	Installed/Active	05/09/2019	PROG5038NRH60	Rheem	\$ 1,206.77	\$ 12.09
25061	Installed/Active	04/30/2019	PROG5038NRH60	Rheem	\$ 1,208.62	\$ 12.09
25062	Installed/Active	04/16/2019	PROG5038NRH60	RHEEM	\$ 1,211.92	\$ 12.09
25063	Installed/Active	05/02/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15
25064	Installed/Active	05/02/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15
25065	Installed/Active	05/03/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
25066	Installed/Active	05/05/2019	PROG40S38NRH62	RHEEM	\$ 1,062.96	\$ 7.37
25067	Installed/Active	05/03/2019	PROG4038NRH62	RHEEM	\$ 1,239.42	\$ 5.83
25068	Installed/Active	05/05/2019	PROG5038NRH60	RHEEM	\$ 1,148.62	\$ 12.09
25069	Installed/Active	05/02/2019	PROG4038NRH62	RHEEM	\$ 1,205.48	\$ 12.09
25070	Installed/Active	05/02/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25071	Installed/Active	05/03/2019	PROG5038NRH60	RHEEM	\$ 1,212.62	\$ 12.09
25072	Installed/Active	04/29/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
25073	Installed/Active	05/03/2019	PROG4038NRH62	RHEEM	\$ 1,211.96	\$ 5.83
25074	Installed/Active	05/05/2019	RG250H6N	RHEEM	\$ 1,763.75	\$ 19.60
25075	Installed/Active	05/01/2019	RG2DV50S6N	BRADFORD WHITE	\$ 2,261.24	\$ 17.15
25076	Installed/Active	04/30/2019	PROG40S38NRH62	RHEEM	\$ 1,167.57	\$ 5.83
25077	Installed/Active	05/01/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
25078	Installed/Active	05/12/2019	PROG5038NRH60	RHEEM	\$ 1,180.52	\$ 12.09
25079	Installed/Active	05/11/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 7.37
25080	Installed/Active	05/06/2019	G91200	RHEEM	\$ 5,559.62	\$ 54.25
25081	Installed/Active	05/09/2019	PROG40S38NRH62	RHEEM	\$ 1,167.57	\$ 5.83
25082	Installed/Active	05/08/2019	PROG4860NRH60	RHEEM	\$ 1,356.13	\$ 16.78
25083	Installed/Active	05/11/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25084	Installed/Active	05/06/2019	PROG4860NRH60	RHEEM	\$ 1,318.74	\$ 16.78
25085	Installed/Active	05/06/2019	PROG5038NRH60	RHEEM	\$ 1,226.14	\$ 12.09
25086	Installed/Active	05/10/2019	PROG5038NRH60	RHEEM	\$ 1,297.62	\$ 12.09
25087	Installed/Active	05/08/2019	PROG4038NRH62	RHEEM	\$ 1,129.96	\$ 5.83
25088	Installed/Active	05/08/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
25089	Installed/Active	05/07/2019	G76200	RHEEM	\$ 5,194.96	\$ 63.09
25090	Installed/Active	05/06/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 5.83
25091	Installed/Active	05/07/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25092	Installed/Active	05/10/2019	PROG5038NRH60	RHEEM	\$ 1,191.23	\$ 12.09
25093	Installed/Active	05/16/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
25094	Installed/Active	05/15/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25095	Installed/Active	05/16/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
25096	Installed/Active	05/18/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 17.15
25097	Installed/Active	05/13/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 12.09
25098	Installed/Active	05/15/2019	PROG5038NRH60	Rheem	\$ 1,180.52	\$ 12.09
25099	Installed/Active	05/14/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25100	Installed/Active	05/14/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25101	Installed/Active	05/19/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 5.83
25102	Installed/Active	05/18/2019	PROG5038NRH60	Rheem	\$ 1,244.08	\$ 12.09
25103	Installed/Active	05/17/2019	PROG40S38NRH62	Rheem	\$ 1,149.61	\$ 5.83
25104	Installed/Active	05/14/2019	PROG5036NRU60DV	Rheem	\$ 2,103.32	\$ 17.15
25105	Installed/Active	05/13/2019	PROG5038NRH60	Rheem	\$ 1,244.08	\$ 5.83
25106	Installed/Active	05/18/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25107	Installed/Active	05/13/2019	PROG5038NRH60	Rheem	\$ 1,297.62	\$ 12.09
25108	Installed/Active	05/16/2019	PROG5036NRU60DV	Rheem	\$ 2,072.83	\$ 17.15
25109	Installed/Active	05/17/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 7.37
25110	Installed/Active	05/17/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 12.09
25111	Installed/Active	05/21/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25112	Installed/Active	05/25/2019	PROG50S40NRH61	RHEEM	\$ 1,279.89	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
25113	Installed/Active	05/21/2019	PROG5038NRH60	RHEEM	\$ 1,371.16	\$ 12.09
25114	Installed/Active	05/20/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25115	Installed/Active	05/25/2019	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
25116	Installed/Active	05/20/2019	PROG5038NRH60	RHEEM	\$ 1,163.72	\$ 12.09
25117	Installed/Active	05/23/2019	PROG5038NRH60	RHEEM	\$ 1,371.16	\$ 12.09
25118	Installed/Active	05/21/2019	PROG5038NRH60	RHEEM	\$ 1,138.62	\$ 12.09
25119	Installed/Active	05/25/2019	PROG5038NRH60	RHEEM	\$ 1,278.00	\$ 12.09
25120	Installed/Active	05/20/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
25121	Installed/Active	05/21/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
25122	Installed/Active	05/21/2019	PROG5038NRH60	RHEEM	\$ 1,150.62	\$ 12.09
25123	Installed/Active	06/05/2019	PROG5038NRH60	Rheem	\$ 1,171.62	\$ 12.09
25124	Installed/Active	05/26/2019	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 12.09
25125	Installed/Active	05/24/2019	RG2DV50S6N	Bradford White	\$ 2,261.24	\$ 17.15
25126	Installed/Active	05/21/2019	PROG2932NRU63	Rheem	\$ 1,493.52	\$ 5.83
25127	Installed/Active	05/24/2019	PROG40S38NRH62	Rheem	\$ 1,169.42	\$ 12.09
25128	Installed/Active	05/21/2019	PROG5038NRH60	Rheem	\$ 850.00	\$ 12.09
25129	Installed/Active	05/21/2019	RG2DV50S6N	Bradford White	\$ 2,329.24	\$ 17.15
25130	Installed/Active	05/23/2019	PROG5038NRH60	Rheem	\$ 1,148.62	\$ 12.09
25131	Installed/Active	05/20/2019	G91200	Rheem	\$ 5,584.27	\$ 63.09
25132	Installed/Active	05/24/2019	G76200	Rheem	\$ 5,194.96	\$ 63.09
25133	Installed/Active	05/31/2019	PROG50S40NRH61	RHEEM	\$ 1,477.99	\$ 7.37
25134	Installed/Active	06/01/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25135	Installed/Active	05/28/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25136	Installed/Active	05/29/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
25137	Installed/Active	05/29/2019	G91200	RHEEM	\$ 5,401.56	\$ 63.09
25138	Installed/Active	05/31/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
25139	Installed/Active	06/02/2019	PROG5038NRH60	RHEEM	\$ 1,171.62	\$ 16.78
25140	Installed/Active	05/30/2019	PROG4038NRH62	Rheem	\$ 1,159.86	\$ 5.83
25141	Installed/Active	06/02/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25142	Installed/Active	05/29/2019	PROG50S40NRH61	Rheem	\$ 1,384.50	\$ 5.83
25143	Installed/Active	05/31/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
25144	Installed/Active	05/30/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
25145	Installed/Active	06/03/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
25146	Installed/Active	05/28/2019	PH199119	PHOENIX	\$ 8,039.49	\$ 63.09
25147	Installed/Active	06/01/2019	PROG5038NRH60	Rheem	\$ 1,194.62	\$ 12.09
25148	Installed/Active	06/01/2019	PROG5038NRH60	Rheem	\$ 1,194.62	\$ 7.37
25149	Installed/Active	05/31/2019	PROG50S40NRH61	Rheem	\$ 1,340.89	\$ 5.83
25150	Installed/Active	05/28/2019	PROG4038NRH62	Rheem	\$ 1,130.96	\$ 12.09
25151	Installed/Active	06/02/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
25152	Installed/Active	06/02/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 5.83
25153	Installed/Active	06/08/2019	G75125	RHEEM	\$ 4,387.57	\$ 40.51
25154	Installed/Active	06/09/2019	PROG40S38NRH62	RHEEM	\$ 1,350.50	\$ 7.37
25155	Installed/Active	06/06/2019	PROG40S38NRH62	RHEEM	\$ 1,129.96	\$ 12.09
25156	Installed/Active	06/07/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
25157	Installed/Active	06/08/2019	PROG40S38NRH62	RHEEM	\$ 1,122.47	\$ 12.09
25158	Installed/Active	06/08/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 16.78
25159	Installed/Active	06/07/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 19.60
25160	Installed/Active	06/04/2019	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 5.83
25161	Installed/Active	06/05/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25162	Installed/Active	06/04/2019	PROG40S38NRH62	Rheem	\$ 1,168.96	\$ 12.09
25163	Installed/Active	06/06/2019	PROG5038NRH60	Rheem	\$ 1,155.62	\$ 12.09
25164	Installed/Active	06/06/2019	PROG50S40NRH61	Rheem	\$ 1,404.89	\$ 12.09
25165	Installed/Active	06/05/2019	PROG4038NRH62	RHEEM	\$ 1,062.96	\$ 12.09
25166	Installed/Active	06/04/2019	PROG4038NRH62	Rheem	\$ 1,122.47	\$ 12.09
25167	Installed/Active	06/03/2019	GSN40	Lochinvar	\$ 1,321.21	\$ 12.09
25168	Installed/Active	06/03/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25169	Installed/Active	06/03/2019	PROG5038NRH60	Rheem	\$ 850.00	\$ 12.09
25170	Installed/Active	06/03/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25171	Installed/Active	06/04/2019	PROG5036NRU60DV	Rheem	\$ 2,117.93	\$ 17.15
25172	Installed/Active	06/07/2019	PROG40S38NRH62	Rheem	\$ 1,129.96	\$ 12.09
25173	Installed/Active	06/14/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
25174	Installed/Active	06/16/2019	PROG5038NRH60	RHEEM	\$ 1,143.13	\$ 12.09
25175	Installed/Active	06/10/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 5.83
25176	Installed/Active	06/13/2019	RG2DV40S6N	BRADFORD WHITE	\$ 2,311.24	\$ 17.15
25177	Installed/Active	06/13/2019	PROG5038NRH60	RHEEM	\$ 1,188.23	\$ 12.09
25178	Installed/Active	06/12/2019	PROG5038NRH60	RHEEM	\$ 1,133.62	\$ 5.83
25179	Installed/Active	06/10/2019	PROG5038NRH60	RHEEM	\$ 1,160.62	\$ 7.37
25180	Installed/Active	06/11/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
25181	Installed/Active	06/10/2019	PROG5038NRH60	RHEEM	\$ 1,194.62	\$ 12.09
25182	Installed/Active	06/14/2019	PROG40S38NRH62	RHEEM	\$ 1,123.96	\$ 7.37
25183	Installed/Active	06/10/2019	PROG4860NRH60	RHEEM	\$ 1,363.84	\$ 16.78
25184	Installed/Active	06/11/2019	PROG5038NRH60	RHEEM	\$ 1,151.62	\$ 12.09
25185	Installed/Active	06/12/2019	PROG5036NRH60DV	RHEEM	\$ 2,013.32	\$ 10.57
25186	Installed/Active	06/12/2019	PROG40S38NRH62	RHEEM	\$ 1,129.96	\$ 12.09
25187	Installed/Active	06/12/2019	PROG5036NRH60DV	RHEEM	\$ 2,117.93	\$ 17.15
25188	Installed/Active	06/13/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25189	Installed/Active	06/11/2019	PROG5036NRH60DV	RHEEM	\$ 2,085.32	\$ 17.15
25190	Installed/Active	06/11/2019	PROG5038NRH60	RHEEM	\$ 1,183.62	\$ 12.09
25191	Installed/Active	06/10/2019	G82156	RHEEM	\$ 5,153.64	\$ 54.25
25192	Installed/Active	06/10/2019	PROG40S38NRH62	RHEEM	\$ 1,134.96	\$ 7.37
25193	Installed/Active	06/14/2019	PROG5038NRH60	RHEEM	\$ 1,260.08	\$ 12.09
25194	Installed/Active	06/15/2019	PROG50S40NRH61	RHEEM	\$ 1,334.89	\$ 12.09
25195	Installed/Active	06/16/2019	PROG5038NRH60	RHEEM	\$ 1,083.62	\$ 12.09
25196	Installed/Active	06/19/2019	PROG5038NRH60	Rheem	\$ 1,212.62	\$ 12.09
25197	Installed/Active	06/18/2019	PROG5038NRH60	Rheem	\$ 1,206.77	\$ 12.09
25198	Installed/Active	06/20/2019	PROG40S38NRH62	Rheem	\$ 1,129.96	\$ 5.83

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
25199	Installed/Active	06/18/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
25200	Installed/Active	06/21/2019	PROG5038NRH60	Rheem	\$ 1,187.63	\$ 5.83
25201	Installed/Active	06/19/2019	PROG4038NRH62	Rheem	\$ 1,188.96	\$ 12.09
25202	Installed/Active	06/20/2019	PROG40S38NRH62	Rheem	\$ 1,122.47	\$ 5.83
25203	Installed/Active	06/17/2019	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 12.09
25204	Installed/Active	06/17/2019	PROG5038NRH60	Rheem	\$ 1,193.62	\$ 12.09
25205	Installed/Active	06/21/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
25206	Installed/Active	06/19/2019	PROG5036NRU60DV	Rheem	\$ 2,155.84	\$ 17.15
25207	Installed/Active	06/19/2019	G82156	Rheem	\$ 5,418.64	\$ 63.09
25208	Installed/Active	06/21/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
25209	Installed/Active	06/19/2019	PROG5038NRH60	Rheem	\$ 1,138.62	\$ 12.09
25210	Installed/Active	06/22/2019	PROG5038NRH60	Rheem	\$ 1,128.12	\$ 12.09
25211	Installed/Active	06/18/2019	PROG50S40NRH61	Rheem	\$ 1,346.89	\$ 12.09
25212	Installed/Active	06/21/2019	PROG40S38NRH62	Rheem	\$ 1,276.96	\$ 12.09
25213	Installed/Active	06/20/2019	PROG5038NRH60	RHEEM	\$ 1,206.77	\$ 12.09
25214	Installed/Active	06/20/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25215	Installed/Active	06/19/2019	PROG5038NRH60	Rheem	\$ 1,244.08	\$ 12.09
25216	Installed/Active	06/21/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25217	Installed/Active	06/19/2019	PROG40S38NRH62	Rheem	\$ 1,187.96	\$ 12.09
25218	Installed/Active	06/21/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 12.09
25219	Installed/Active	06/21/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
25220	Installed/Active	06/16/2019	PROG2932NRU63	Rheem	\$ 1,478.52	\$ 5.83
25221	Installed/Active	06/17/2019	PROG40S38NRH62	Rheem	\$ 1,117.96	\$ 12.09
25222	Installed/Active	06/18/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 12.09
25223	Installed/Active	06/18/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 5.83
25224	Installed/Active	06/19/2019	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 12.09
25225	Installed/Active	06/19/2019	PROG4038NRH62	Rheem	\$ 1,239.42	\$ 12.09
25226	Installed/Active	06/20/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25227	Installed/Active	06/21/2019	PROG5038NRH60	Rheem	\$ 1,190.08	\$ 5.83
25228	Installed/Active	06/24/2019	PROG5038NRH60	Rheem	\$ 1,212.62	\$ 12.09
25229	Installed/Active	06/24/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25230	Installed/Active	06/20/2019	PROG40S38NRH62	Rheem	\$ 1,117.96	\$ 12.09
25231	Installed/Active	06/19/2014	M15036FBN	Bradford White	\$ 850.00	\$ 12.84
25232	Installed/Active	06/25/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
25233	Installed/Active	06/25/2019	PROG5038NRH60	Rheem	\$ 1,143.13	\$ 12.09
25234	Installed/Active	06/25/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 5.83
25235	Installed/Active	06/29/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25236	Installed/Active	06/29/2019	G91200	Rheem	\$ 3,350.00	\$ 63.09
25237	Installed/Active	06/28/2019	RG250T6N	Bradford White	\$ 1,233.26	\$ 12.09
25238	Installed/Active	05/31/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25239	Installed/Active	07/01/2019	PROG40S38NRH62	Rheem	\$ 1,117.96	\$ 5.83
25240	Installed/Active	06/26/2019	RG2DV50S6N	Bradford White	\$ 2,347.79	\$ 17.15
25241	Installed/Active	06/26/2019	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 12.09
25242	Installed/Active	06/28/2019	PROG40S38NRH62	Rheem	\$ 1,143.06	\$ 12.09
25243	Installed/Active	06/25/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 12.09
25244	Installed/Active	06/29/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 16.78
25245	Installed/Active	06/02/2019	G75125	Rheem	\$ 4,337.57	\$ 40.51
25246	Installed/Active	07/07/2019	PROG4038NRH62	Rheem	\$ 1,257.34	\$ 5.83
25247	Installed/Active	07/01/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 12.09
25248	Installed/Active	07/05/2019	RG2DV40S6N	Bradford White	\$ 2,403.76	\$ 17.15
25249	Installed/Active	07/01/2019	PROG5038NRH60	Rheem	\$ 1,195.44	\$ 12.09
25250	Installed/Active	07/02/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25251	Installed/Active	07/02/2019	PROG5038NRH60	Rheem	\$ 1,973.72	\$ 5.83
25252	Installed/Active	06/27/2019	PROG5038NRH60	Rheem	\$ 1,260.08	\$ 12.09
25253	Installed/Active	06/29/2019	RG250H6N	Rheem	\$ 1,713.75	\$ 19.60
25254	Installed/Active	06/29/2019	PROG5038NRH60	Rheem	\$ 1,193.62	\$ 12.09
25255	Installed/Active	06/27/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25256	Installed/Active	06/24/2019	PROG4860NRH60	Rheem	\$ 1,259.23	\$ 16.78
25257	Installed/Active	06/24/2019	RG250H6N	Rheem	\$ 1,713.75	\$ 16.78
25258	Installed/Active	06/27/2019	PROG2932NRU63	Rheem	\$ 1,393.52	\$ 7.37
25259	Installed/Active	06/27/2019	PROG50S40NRH61	Rheem	\$ 1,279.89	\$ 12.09
25260	Installed/Active	06/27/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25261	Installed/Active	07/01/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25262	Installed/Active	07/08/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
25263	Installed/Active	07/06/2019	PROG4038NRH62	Rheem	\$ 1,123.96	\$ 7.37
25264	Installed/Active	07/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25265	Installed/Active	07/07/2019	PROG50S40NRH61	Rheem	\$ 1,339.40	\$ 12.09
25266	Installed/Active	07/05/2019	PROG5038NRH60	Rheem	\$ 1,371.16	\$ 12.09
25267	Installed/Active	07/02/2019	G91200	Rheem	\$ 5,451.56	\$ 63.09
25268	Installed/Active	07/03/2019	PROG5038NRH60	Rheem	\$ 1,205.82	\$ 12.09
25269	Installed/Active	07/03/2019	PROG5038NRH60	Rheem	\$ 1,205.82	\$ 12.09
25270	Installed/Active	07/03/2019	PROG5038NRH60	Rheem	\$ 2,155.84	\$ 17.15
25271	Installed/Active	07/05/2019	PROG4038NRH62	Rheem	\$ 1,276.96	\$ 12.09
25272	Installed/Active	07/07/2019	PROG5038NRH60	Rheem	\$ 1,133.62	\$ 5.83
25273	Installed/Active	07/06/2019	PROG40S38NRH62	Rheem	\$ 1,122.47	\$ 5.83
25274	Installed/Active	07/02/2019	RG2DV50S6N	Bradford White	\$ 2,365.85	\$ 17.15
25275	Installed/Active	07/02/2019	PROG2932NRU63	Rheem	\$ 1,512.52	\$ 12.09
25276	Installed/Active	07/04/2019	PROG5038NRH60	Rheem	\$ 1,148.62	\$ 12.09
25277	Installed/Active	07/05/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25278	Installed/Active	07/05/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25279	Installed/Active	07/07/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 5.83
25280	Installed/Active	07/06/2019	PROG5036NRH60DV	Rheem	\$ 2,078.32	\$ 17.15
25281	Installed/Active	07/14/2019	PROG5038NRH60	Rheem	\$ 1,297.62	\$ 12.09
25282	Installed/Active	07/08/2019	PROG50S40NRH61	Rheem	\$ 1,493.89	\$ 12.09
25283	Installed/Active	07/10/2019	RG2DV50S6N	Bradford White	\$ 2,328.24	\$ 17.15
25284	Installed/Active	07/10/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09

Customer No.	Status	Commencement date (a.)	Model number (e.)	Make/Manufacturer (e.)	Book Value at Initial Installation (f.)	Rate Charged at Commencement (d.)
25285	Installed/Active	07/11/2019	PROG5038NRH60	AO Smith	\$ 1,278.00	\$ 12.09
25286	Installed/Active	07/12/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25287	Installed/Active	07/11/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25288	Installed/Active	07/12/2019	G75125	Rheem	\$ 4,552.07	\$ 40.51
25289	Installed/Active	07/13/2019	PROG5038NRH60	Rheem	\$ 1,173.62	\$ 5.83
25290	Installed/Active	07/14/2019	PROG40S38NRH62	Rheem	\$ 1,062.96	\$ 5.83
25291	Installed/Active	07/08/2019	RG2DV50S6N	Bradford White	\$ 2,261.24	\$ 17.15
25292	Installed/Active	07/10/2019	G75125	Rheem	\$ 4,560.57	\$ 40.51
25293	Installed/Active	07/11/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
25294	Installed/Active	07/11/2019	G75125	RHEEM	\$ 4,337.57	\$ 40.51
25295	Installed/Active	07/11/2019	G75125	Rheem	\$ 4,337.57	\$ 40.51
25296	Installed/Active	07/13/2019	G91200	Rheem	\$ 5,401.56	\$ 63.09
25297	Installed/Active	07/08/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25298	Installed/Active	07/09/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25299	Installed/Active	07/09/2019	PROG5038NRH60	Rheem	\$ 1,180.52	\$ 12.09
25300	Installed/Active	07/09/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25301	Installed/Active	07/12/2019	G76200	Rheem	\$ 5,284.94	\$ 63.09
25302	Installed/Active	07/14/2019	PROG5038NRH60	Rheem	\$ 1,219.59	\$ 12.09
25303	Installed/Active	07/12/2019	PROG4038NRH62	Rheem	\$ 1,129.96	\$ 5.83
25304	Installed/Active	07/12/2019	RG2DV50S6N	Bradford White	\$ 2,320.75	\$ 17.15
25305	Installed/Active	07/10/2019	PROG4038NRH62	Rheem	\$ 1,062.96	\$ 5.83
25306	Installed/Active	07/10/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25307	Installed/Active	07/12/2019	PROG5038NRH60	Rheem	\$ 1,083.62	\$ 12.09
25308	Installed/Active	07/08/2019	PROG4038NRH62	Rheem	\$ 1,152.96	\$ 12.09
25309	Installed/Active	07/11/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
25310	Installed/Active	07/09/2019	RG2DV50S6N	BRADFORD WHITE	\$ 3,124.00	\$ 30.95
25311	Installed/Active	07/12/2019	PROG4038NRH62	Rheem	\$ 1,159.28	\$ 12.09
25312	Installed/Active	07/08/2019	PROG2932NRU63	Rheem	\$ 1,393.52	\$ 12.09
25313	Installed/Active	07/14/2019	PROG5038NRH60	Rheem	\$ 1,163.72	\$ 12.09
25314	Installed/Active	07/19/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25315	Installed/Active	07/20/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25316	Installed/Active	07/19/2019	PROG5038NRH60	Rheem	\$ 1,152.62	\$ 12.09
25317	Installed/Active	07/19/2019	PROG4038NRH62	Rheem	\$ 1,131.96	\$ 7.37
25318	Installed/Active	07/17/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 5.83
25319	Installed/Active	07/17/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25320	Installed/Active	07/18/2019	PROG5038NRH60	RHEEM	\$ 1,188.53	\$ 12.09
25321	Installed/Active	07/20/2019	PROG4038NRH62	Rheem	\$ 1,117.96	\$ 14.90
25322	Installed/Active	07/20/2019	PROG5038NRH60	Rheem	\$ 1,170.27	\$ 12.09
25323	Installed/Active	07/18/2019	PROG5038NRH60	Rheem	\$ 1,206.77	\$ 12.09
25324	Installed/Active	07/18/2019	PROG4038NRH62	Rheem	\$ 1,159.86	\$ 12.09
25325	Installed/Active	07/20/2019	G75125	Rheem	\$ 4,442.18	\$ 40.51
25326	Installed/Active	07/20/2019	PROG40S38NRH62	Rheem	\$ 1,167.57	\$ 5.83
25327	Installed/Active	07/20/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 12.09
25328	Installed/Active	07/17/2019	PROG5038NRH60	Rheem	\$ 1,191.37	\$ 12.09
25329	Installed/Active	07/15/2019	PROG5038NRH60	Rheem	\$ 1,188.23	\$ 12.09
25330	Installed/Active	07/16/2019	RG2DV40S6N	Bradford White	\$ 2,371.24	\$ 17.15
25331	Installed/Active	07/17/2019	PROG5036NRH60DV	Rheem	\$ 2,117.93	\$ 17.15
25332	Installed/Active	07/19/2019	G75125	Rheem	\$ 4,387.57	\$ 40.51
25333	Installed/Active	07/19/2019	PROG5038NRH60	Rheem	\$ 1,150.62	\$ 7.37
25334	Installed/Active	07/17/2019	PROG5038NRH60	Rheem	\$ 1,226.14	\$ 12.09
25335	Installed/Active	07/19/2019	PROG5036NRH60DV	Rheem	\$ 2,074.67	\$ 17.15
25336	Installed/Active	07/26/2019	PROG5038NRH60	Rheem	\$ 1,209.62	\$ 7.37
25337	Installed/Active	07/26/2019	PROG5038NRH60	Rheem	\$ 1,109.62	\$ 12.09
25338	Installed/Active	07/24/2019	PROG50S40NRH61	Rheem	\$ 1,377.60	\$ 12.09
25339	Installed/Active	07/26/2019	PROG5038NRH60	Rheem	\$ 1,214.23	\$ 12.09
25340	Installed/Active	07/24/2019	PROG5038NRH60	Rheem	\$ 1,109.62	\$ 12.09
25341	Installed/Active	07/22/2019	PROG5036NRH60DV	Rheem	\$ 2,134.64	\$ 17.15
25342	Installed/Active	07/22/2019	G65360	Rheem	\$ 12,039.00	\$ 54.25
25343	Installed/Active	07/26/2019	PROG5038NRH60	Rheem	\$ 1,176.62	\$ 12.09
25344	Installed/Active	07/26/2019	PROG5038NRH60	Rheem	\$ 1,109.62	\$ 12.09
25345	Installed/Active	07/24/2019	PROG5036NRH60DV	Rheem	\$ 2,210.64	\$ 17.15
25346	Installed/Active	07/24/2019	PROG4038NRH62	Rheem	\$ 1,138.47	\$ 12.09
25347	Installed/Active	07/22/2019	G91200	Rheem	\$ 5,531.19	\$ 63.09
25348	Installed/Active	07/24/2019	PROG5038NRH60	RHEEM	\$ 1,176.62	\$ 5.83
25349	Installed/Active	07/23/2019	G91200	Rheem	\$ 5,787.69	\$ 63.09
25350	Installed/Active	07/25/2019	PROG4038NRH62	Rheem	\$ 850.00	\$ 12.09
25351	Installed/Active	07/29/2019	G91200	Rheem	\$ 5,531.19	\$ 63.09
25352	Installed/Active	07/27/2019	PROG5038NRH60	Rheem	\$ 1,109.62	\$ 12.09
25353	Installed/Active	07/25/2019	G91200	Rheem	\$ 5,641.19	\$ 63.09
25354	Installed/Active	07/23/2019	PROG4860NRH60	Rheem	\$ 1,394.06	\$ 16.78
25355	Installed/Active	07/23/2019	PROG5042NRH67PV	Rheem	\$ 2,349.00	\$ 5.83
25356	Installed/Active	07/23/2019	PROG5038NRH60	Rheem	\$ 1,109.62	\$ 12.09
25357	Installed/Active	07/23/2019	PROG4038NRH62	Rheem	\$ 1,264.93	\$ 5.83

BEFORE THE WASHINGTON UTILITIES AND TRANSPORTATION COMMISSION**Dockets UE-190529 & UG-190530
Puget Sound Energy
2019 General Rate Case****PUBLIC COUNSEL DATA REQUEST NO. 178:**

Please refer to PSE's Response to Public Counsel Data Request No. 93.

Public Counsel requested the following in Data Request No. 93:

“Provide a list of the make, model, and the date of installation of all water heaters currently used by PSE customers participating in the water heater rental program. Please include any repairs and replacements to leased equipment.”

The Company did not provide any data regarding the replacement of a participant's water heater. Please explain why this information is missing. If the Company does not track this information, please provide an explanation as why the Company tracks repairs but not replacements. Also, please specify whether a repair and a replacement are different classifications in its tracking system.

Response:

In Puget Sound Energy's ("PSE") Response to Public Counsel Data Request No. 093, PSE provided updated information to PSE's Response to WUTC Staff Informal Data Request No. 001 from the Water Heater Rental Program Collaborative. As explained in PSE's Response to WUTC Staff Informal Data Request No. 001:

“When an old water heater is replaced by a new water heater, PSE updates their system with a new, unique equipment number. This would mean that any replacement water heater would fall under the same category as an installation date.”

The “Installation Date” in column B of Attachment A to PSE's Response to Public Counsel Data Request No. 093 reflects either when the water heater was initially installed or replaced.

In PSE's system, repairs are tracked separately from replacements.