

# **Rail Accident Inspection Form**

Docket No: <u>TR-111559</u>		Da	ate: 11/1/20	11		
Railroad Owning Track: BNSF		Ra	Railroad Operating on Track: <u>AMTRAK</u>			
FRA Investigation: Yes	No 🖂	Ins	spector: R J	<u>ohnston</u>		
I. Type of Accident						
Public Crossing	Private Crossing	Trestle	e 🗌	Pedestrian at Crossing		
Pedestrian Not at Crossing	Other (explain)			*		
II. Time and Location o	f Accident					
Date <u>8-26-2011</u>		Tir	ne <u>1713</u>			
USDOT Crossing No		W	UTC Crossi	ng No		
Railroad Milepost 24.2		GP	S Identifier	: Lat: <u>47.07333</u> Long: <u>-122.69324</u>		
Number of Tracks: 2		Cit	y:			
Road name, yard name, bridge	dentifier:	Co	unty: Pierce	2		
Company responsible for track	maintenance: BNSF					
Other railroad involved in train	accident/incident: AM	ΓRAK				
III. Conditions Surroun	ding the Acciden	t				
Weather: Clear to cloudy	Fog Rain	] Snow [		•		
Road Condition: Dry	Wet Snow	Ice	·			
Visibility Due to Weather: D	aylight 🛛 Darkness	s Unkn	own 🗌			
Adequate Sight Distance: Yes	□ No □ N/A ▷		Γ	Frain Speed: <u>40-45 MPH</u>		
Describe:				*		
Train Type: Freight Pass			s only	Tilt train		
Remote Control: Yes No	× N/A □	Ha	z-Mat on Ti	rain: Yes 🗌 No 🛛 N/A 🗍		
Type of Haz-Mat:	*					
IV. Pedestrian, Driver, o	r Passenger Fata	ilities [	oes this	section apply? Yes 🛛 No 🗌		
Number of people killed 1		If a vehicle	e accident, i	number of passengers		
Name: Ajia J. Luke						
Driver: Passenger Ped	estrian 🖂	Age <u>28</u>	Gend	ler: Male 🔲 Female 🔀		
Pedestrian trying to get on/off tr	ain? Yes 🗌 No 🛛	Suicide: Y	es 🛛 No	☐ Undetermined ☐		
Alcohol: Yes 🔲 No 🔲 Ur	ndetermined	nformation supp	lied by: WA	State Toxicology Labratory		
Drugs: Yes No Un	determined [ In	nformation supp	lied by: WA	State Toxicology Labratory		
Names of additional fatalities:	2	Redacted	per RCW 6	58.50.105 Medical Examiner Information		
* .						
		¥ 31		5 8		

Docket No: <u>TR-111559</u>	
V. Pedestrian, Driver, or Passenger Injuries	Does this section apply? Yes 🗌 No 🖂
Number of people injured Name:	If a vehicle accident, number of passengers
Driver: Passenger Pedestrian	Age Gender: Male Female
Pedestrian trying to get on/off train? Yes \( \square\) No \( \square\)	Drugs: Yes No Undetermined
Suicide: Yes  No  Undetermined	Alcohol: Yes  No Undetermined
Names of additional injured persons:	
VI. Pedestrian Access	Does this section apply? Yes 🗌 No 🗌
Obvious signs of consistent pedestrian trespass? Yes	No 🗌
If yes, describe:	
Pedestrian (not at a crossing) information: Accessing publi	c area? Yes No
If yes, describe:	
Deterrents at site, e.g. fence, signs, etc? Yes \( \square\) No \( \square\)	
If yes, describe:	
Previous collisions at or near site? Yes \( \square\) No \( \square\)	
If yes, describe:	
VII. Crossing History	Does this section apply? Yes $\square$ No $\boxtimes$
Prior accidents at this crossing? Yes \( \square\) No \( \square\)	How many?
Dates of prior accidents:	
Description of prior accidents (e.g., fatalities, injuries, prop	perty damage)
Last inspection date?	
Defects? Yes No	
If yes, describe:	
Required to attach most current inventory? Yes \( \square\) No [	
VIII. Attachments	
Railroad incident report? Yes 🛛 No 🗌	Local law enforcement report? Yes No
Coroner/medical examiner report? Yes 🖂 No 🗌	Pictures? Yes No No
Other (describe):	

Docket No: TR-111559

### **IX. Comments**

This incident occurred on BNSF Seattle Sub at MP 24.2, beneath the Nisqually Road SW overcrossing in Pierce County

The incident was between a northbound AMTRAK passenger train and the deceased.

The sole eye-witness was the engineer, who stated that he observed the decedent peeking out from behind a bridge column. As the train approached, the decedent ran to the tracks and lay down with her head on the rail.


The Sheriff Department report indicates that the train was camera equipped and that the video was accessed, which supported the engineers' statement.


The location is rural and readily assessable. There is a gate in the area that is effective at keeping vehicles from accessing the area beneath the bridge, but will not hinder individuals on foot. There is no fencing at this location, and none is being recommended.

The decedent had a history of psychiatric problems, and was bipolar with severe depression.

The decedent left messages interpreted as suicidal.

Considering that the decedent's intent was to commit suicide, it is doubtful that any fencing and/or signage at this location would have successfully prevented this incident.





# BNSF Fort Worth - Network Operations Center - INCIDENT REPORT

											D-Co	de:	18L53 0
Da te:	08/26,	/2011	Tim	e:	191	3 CT	MP:	24.2	to and		Div n:	Nor	thwest
Time	& Dat	te Last	Revi	ised:	:								
http TSS = "yello	Main Track disruption expected >8 hours? Has following link's report been accomplished? <a href="http://wfprd/approot/ncs">http://wfprd/approot/ncs</a> derail/load derail logon.htm  TSS = TJS Then A, symbol, PF9. Then select the next forward TJS station (next station not "yellowed").  Run STN and use the 3-3-3 station name.												
Subon:	<u>divisi</u>	Sea	ttle			*	Stat	e:	WA		Coun	ty:	Thurston
	Segm								52				
						ection from)		1	at Nisqu				
						nce/direction	n):		10 miles				
Wea	ther C	onditio	ons (	wind	l, pro	ecip, temp):			79°, sur	ny with	n wind f	from	N at 8 MPH
	-												
	uries alitie			Fata	l to t	trespasser	Emp	loyee?		No	a T		
Nam	ie:	Ajia J. Luke (Female) DOB: 06/29/83 7206 South Mullen Tacoma, WA 98405				Craf	t:			to .			
Sym	bol:	A 516	1 26				If Ya	,	is it Ren	note Co	ontrol	Oper	ration
Sym Lead Locos		A 516						,	is it Ren	note Co	ontrol L-E-T		14-0-312- 747
Lead Loco								,	is it Ren	note Co		FF:	14-0-312-
Lead Locos DP Lo	s: ocos:	AMTK	64	nave	Dito	ch Lites?	(RC	0)?	Were Ditc	2	L-E-T Direc n:	-F: ctio	14-0-312- 747 Northbound
Lead Locos DP Lo	s: ocos: Lead lo	AMTK  ocomol 36 MP	64 tive h			Maximum A	(RC	o)?	Were Dito	ch Lite'	L-E-T Direct n: s oper	-F: ctio	14-0-312- 747 Northbound
DP Lo	s: ocos: Lead Id ed: n Crew	AMTK	64 tive h			Maximum A	(RC	o)?	Were Ditc	ch Lite'	L-E-T Direct n: s oper	-F: ctio	14-0-312- 747 Northbound
DP Lo Did   Spec Train Conc or:	s: ocos: Lead Id ed: n Crew	AMTK  ocomol 36 MP	64 tive h H jin /			Maximum A	uthor	o)?	Were Dito	ch Lite'	L-E-T Direct n: s oper	rating	14-0-312- 747 Northbound
DP LO Did Spee	s: ocos: Lead Id ed: n Crew duct	AMTK  ocomot  36 MP	64 tive h H jin /			Maximum A	uthor	o)?	Were Dito	ch Lite'	L-E-T Direct n: 's oper	T-F: ctio	14-0-312- 747 Northbound
Lead Loco DP Lo Did I Spec Train Conc or: Pric Res	s: ocos: Lead lo ed: n Crew duct	AMTK  Ocomol 36 MP /'s Orig B Meri	64 tive h H jin /	Desi		Maximum Ation: Engineer: Prior Rest	uthor	o)?	Were Dito	ch Lite'	L-E-T Directors S oper 55 MF Other	T-F: ctio	14-0-312- 747 Northbound
Lead Loco DP Lo Did   Spee Train Concor: Pric Res On E Time Crev	s: Lead Idead Idead: In Crew duct Officit Outy Ed/Date	AMTK  Ocomol 36 MP /'s Orig B Meri	64 H Jin /	<b>Desi</b>	tinat 0 CT,	Maximum Ation: Engineer: Prior Rest	uthor	o)?	Were Dito eed: I, OR/Sea elon	ch Lite'	L-E-T Directors S oper 55 MF Other	rating	14-0-312- 747 Northbound
Lead Locol DP Lo Spee Train Concor: Pric Res On E Time Crev by:	s: Lead lo ed: n Crew duct  Of st Outy e/Date v Inter	AMTK  36 MP  7's Orig  B Meri	64  tive h H jin /	Desi	tinat 0 CT,	Maximum Ation: Engineer: Prior Rest	uthor	o)?  Vized Sp Portland DL Whee	Were Dito eed: I, OR/Seat elon y Locatio	ch Lite'	L-E-T Directors S oper 55 MF Other	rating	14-0-312- 747 Northbound

Locomotives video equipped?										
Lead Locos	Y/N		Y/N		Y/N		Y/N		Y/ N	Y
AMTK 64	У	AMTK 90250	N				_			

Crossi Name			Not at a	cros	rossing DOT Number:					
Equip	ped v	with:			Functioning?					
Vehicl	Vehicle Direction: Vehicle Description:									
Law E	Law Enforcement Agency:  Pierce County Sheriff Rpt# 11-238-0978  Citations?							?		
Haz M	late	rial 2		Pal	lease (Y/N):		# (	Cars, A	mount	
Comm				IXCI	icuse (1/14):		Tr.	curs/ A	TOGITC!	
COMM	Ouic	y -								
Derail	ed L	ocomo	tives / C	ars:	The state of the s				,e	
Init. Numb	er:	Lin	e:	Pos	sition (upright?):		Co	ntents:		Dispositio n:
								1		
Heavy	equ	<mark>iipmen</mark>	t ordere	d: <i>(l</i>	Blackberry Andrev	v Manthe	i)			
Equi		1			Facilities and				Equipm	
ETA	<b>\:</b>				Equipment Arrived:				ent Release	
					Allived.				d:	
Mai	n	mt-1			Estimated				Actual	22.42.07
Block		mt-2			Reopen:				Reopen:	2242 CT
		12	-				6			
Estim	ate	d Dam	ages an	d C	osts:					
	\$			Tra	nck			Track, Track Structures, and Roadbe		
	4				nosepono.			Damag	es.	
	\$				Signal  Adjacent buildings, other private				er private	
			*8	"01	ther"			propert	y, etc.	
	\$			Cai	r Damages			excludi	nage, incl. flat on ng their /containers and	
	\$			Loc	comotive Damage:	5				
	\$	0		FR	A Reportable Subt	otal		2011	RA Reportabl	e \$9,400
	\$			Coi	ntractor Expense	- A <sub>3</sub>		not incl		penses only. Do ntal cleanup, air
	\$			Est	imated Lading Re	covery Co	osts	Prevent	is usually Dama tion/LARS. This g charges and s s.	figure includes
	\$			Pre					ainer Conte	
				Tra	Trailer/Container Damages  Excludes contents. (Mktg-Equip Mtce Team – Evita Murdock)					n – Evita
	\$ 0 Not FRA Reportable Subtotal									
	\$	0			timated Grand T portable Subtotal)	otal (	FRA Repo	ortable S	ubtotal + Not	FRA
Cause Code:		M5			scription:	Investiga	ting			
				mot	ive, etc.?	8				
Brief I		ative o	of						٠	

MP 24.2, Nisqually Wa, 24 miles south of Tacoma Amtrak 516 traveling northbound on MT2 crossing over to MT1, struck and fatally injured trespasser that stepped in front of train at this location. This was not at a road crossing. BNSF records indicated AMTK locomotive A64 was not camera equipped. Will confirm camera status with Amtrak. 12 trains are projected to operate through this location by 2359. Call temporarily suspended pending civil authority investigation. Train delays not yet quantified.

Passenger desk confirmed locomotive is camera equipped and downloads will be secured on location by AMTK RFE Josh Thompson, ETA 1900 PT.

Update from AGST: Incident was a confirmed suicide. Track released by authorities at 2242 CT for a 3' 27" outage. Delaying 12 trains from 2-5 hours including 4 Amtrak and 2 UP trains. Will also result in 2 DOL's. Amtrak did confirm their locomotive was camera equipped and have secured downloads.

III 2 DOLS. Allitiak did Colli	in 2 DOL's. Afficial did confirm their locomotive was camera equipped and have secured downloads.							
	Post Accident Testing (FR							
Did this incident meet FRA P	ost Accident T	esting criteria?	no					
If the incident analysis indic								
Contact MEH Dept so they can			7					
the testing to insure proper pro-								
(817) 352-1648 during normal								
(817) 352-1613 After hours, we								
then page Martin Crespin or Chi	ris Kowalkowski	via Blackberry.						
Did the AGST agree with the	above analysi	s?	yes	]				
Was the Mgr. Dispatching Pr	actices and Ru	iles notified?						
Was the Shipping Box check								
Were the vials checked to in								
Was the train crew tested? Which BNSF Mgr too				for test?				
Was the Dispatcher tested? Which BNSF Mgr too			k Dispr	for test?	7			
COSCOI.								

Notification	ns:	0 1	
Time:	Entity:	Person Notified:	Reminders:
1914 CT 3	Service Interruption:	By dispatcher to SID - GAB	Include who notified SID.
1915 CT	Resource Operations:	Foster	
	Cust. Solutions: 593-4670 Outlook Mail: Desk, CNS Cust. Support: 593-4612 Outlook Mail: CSESDesk		Notify them of all derailments, collisions, or shipment damages.  Cust Support works 5pm-5am on weekdays and all shifts weekends.
locals	Trainmaster:	Prosser	Get ETA, check Cell number.
9.	Road Foreman Engines:		
1925 CT	Signal Desk: 593 - 5998	Jeff	Signal Logs, TWD Logs.
1926 CT	M/W Desk: 593-6823/1	Ken	Last track inspn, last B- 9 inspn.
1926 CT	Mechanical Desk:	Ronnie	234-7388 North 234- 2300 South 234- 6259 Cars
1947 CT	Corridor Supt:	Beck	
1916 CT	GST/AGST:	Hill	
locals	Divn Supt Operations:	Term Manager Tanner Wyatt	
1947 CT	Divn General Manager:	Johnson	
1947 CT	Divn GDT:	Stender .	A CONTRACTOR OF THE CONTRACTOR
yes	Severe Injury/Fatality:	Copy of report	Blackberry Page the following asap:  Ringelman,R yan  Wilde, Kevin  Safet

Î		Ī	Weber, Safe
			James K y
. at 17			Weber, Eric Safe
			У
	Manager Dispatching		Tape recordings,
	Practices & Rules:		including SID and ROC,
1947 CT	352-1312 Superintendent Operating	Hein	when appropriate.  California, L.A.   Coleman
1947 C1	Practices Practices	neili	Chicago Herbert
	(All have Blackberry)		Colorado Wazny, Gulf, Texas William
	,,	570 0	Kansas Kreger,
			Montana Larry P Nebraska Clevelan
ē.		20 E	Northwest d, Scott Powder River M
			Southwest Valencia
18.0		·	Springfield Randy J Twin Cities Mizelle,
		t v ty -	Nicholas
		8 8	O Harvey,
			Michael
			A. Hein,
			Gary L
		40	Erickson Tony A
Ē.,			McReyno ds, Kevi
-			C
			Rees, Lou
	The second second second		Lund,
	Podomon Day F		Blackberry in the event
	Bodeman, Dan E General Director	*	of:
	Rules and Field Support	a a a	(1) Major derailments incl
	The same of the sa		employee injury and/or HazMa evacuation.
		**	(2) HazMat if evacuation.
79		*	(3) Run-Away Equip if damages, derailment, fatality,
		i i	or possible rules violation.
			(4) Threat of Violence incl Bomb Threats
_			(5) Threat of Terrorist Attacks [vms, also]
			(6) Commuter Train-Report of
		2 "	Explosion or Discovery of Explosive Device [vms, also]
			(7) Employee injury.
yes	Schulze, Mark A	Copy of report	Blackberry in the event
* · · · · · · · · · · · · · · · · · · ·	VP Safety, Training and	4 T	Of: (1) Major derailments incl
	Operations Support		employee injury and/or HazMa
(95)			evacuation. (2) Roll outs, run-away
			equipment incidents. (3) Grade Crossing incident.
			(4) HazMat if equipment
			damage, derailment, fatality, or possible rules violation.
			(5) Catastrophic or Natural
		1°-	Disaster if results in equipment damage, derailment, fatality, of
	The second second second second		possible rules violation.
			(6) Threats of violence including bomb threats.
			(7) Alleged "False Proceed Signal Indications."
	Rogerson, David L		Major Derailments,
	Gen. Dir. Transp. Support		Major Hazardous
	(Blackberry)	a a	Incidents, Employee
	Siegele, Milton	3	Injuries & Employee
	AVP Labor Relations		Fatalities

	Conference Calls:		If Conf Call is being established:
i j			(1) Notify: NOC Mechanical Desk
			(2) Notify: NOC M/W Desk
· ·			(3) Notify: ROC
3 24			(4) If NW or MT Division derailment, Blackberry
	II.		to: Miller, Ryan J
	Hazardous Incidents:		ASAP, page the following:
	If California, notify CUPA.		Blackberry:
		* · · · · · · · · · · · · · · · · · · ·	Pat Brady, Howard Horn, Ed Chapman, David C
11/2			Clark, W Brock Lowman, Allen Stegman.
			Also, consider notifying
			Industrial Hygiene. If anything leaked or
			vented, notify Emer.
9			Nr. listed on Waybill
-			regardless if any product actually "hit
		V	the ground."
3	Assoc. of Amer. Railroads 202-639-2910		24-Hr. Railroad Alert Network.
	202-639-2910	·	Notify them of any
-3		, e ×	significant hazardous material event or any
	1 (4 to 1) (4 to 1)		suspicious potential Nat'l
9			Security event or threat to railroad property.
	ChemTrec (USA)	7	Call whenever Haz Matl
	800-424-9300		car involved in derailment or
	CanuTec (Canada)	¥ <sub>U1</sub> — — — — —	damaged; whether
	613-996-6666		leaking or not.
		5	Run TSS: WBCOPY & HAZ & EXCR
,	NRC: (#1) 800 - 424 - 8802		Obtain their Report Number and name of
	(Initial SID Analysis)		person who took the
	Reasons for notifying them now include for <i>significant</i> violence		report.
1950 CT	or threats of violence against	Post 987-385	This block is for the
	people or property (02-07-01).	3	Initial SID analysis. If initially "not
		8 N N	reportable" and later
			becomes "reportable," use next block.
	NRC: (#2)	J	
	800 - 424 - 8802		If initially "not
- 4	If initially "not reportable," and		reportable," and later becomes "reportable,"
	later becomes "reportable," record your notification here.		record your notification
	What changed?		here.
1950 CT	State:	Wa Emergency Operations - Earl Rpt #	11-2801
overstranschaft Street		Fax copy of report to WA Utilities and	
1	California - CUPA	David Pratt and Lori Halstead	
,	Foreign Railroad:		

4 1	"Go Team"  1. Alpha Page Mark Schulze.  2. Alpha Page team on duty.		Contact the "Team" that's on duty. If approp., also notify Mark Schulze. (To see Team on duty, go to n/SID/SIDBOTH/G OTEAM).
	Rules & Field Support:		Blackberry Page the following in event of
			any service interruption
		): · · · ·	that involves equipment
		1 *	damage, derailment, employee fatality, possible
		40	rules violation:
		#	Adams, Douglas R
			Portz, James L Ratledge,
		a 5	Aaron Aaron
			Repola, Robert E
			Wagner, Kevin L Weber, Eric
			Weber, James K
		9	Wilde, Kevin D.
1921 CT	Passenger Svcs: 234-7332	K Berry	If incident involves passenger train route, <b>Blackberry</b>
			to: Rich Wessler, Rick
1947 CT	Corporate Relations:	page to Melonas and Forsberg	Depler.  Notify of all significant
1947 61	corporate Relations.	page to ricionas and rorsserg	Incidents:
			Melonas: BC, ID, MT, OR,
			WA, WY Faust: AL, AR, LA, MS,
		985 G 9	NM, OK, TN, TX
1.0		. *	Kent: AZ, CA, NV, UT
			McBeth: IA, IL, KY, MB,
			MN, ND, SD, WI Williams: CO, KS, MO,
			NE
			Forsberg: ALL
2320 CT	Claims	Dennis Wright	
	8		

# Halstead, Lori (UTC)

From:

Pratt, David (UTC)

Sent:

Monday, August 29, 2011 7:14 AM

To: Subject: Halstead, Lori (UTC) FW: NRC#987462

**FYI** 

Dave Pratt

Assistant Director for Transportation Safety dpratt@utc.wa.gov 360.664,1100

----Original Message----From: Duty Officer (EMD)

Sent: Sunday, August 28, 2011 3:26 AM

To: Pratt, David (UTC)

Subject: FW: NRC#987462

Dave:

Karen called us earlier to report this.

Ted Henkle SEOO WA EMD

----Original Message----

From: HQS-PF-fldr-NRC@uscg.mil [mailto:HQS-PF-fldr-NRC@uscg.mil]

Sent: Sunday, August 28, 2011 3:26 AM

To: Duty Officer (EMD) Subject: NRC#987462

NATIONAL RESPONSE CENTER 1-800-424-8802

\*\*\*GOVERNMENT USE ONLY\*\*\*GOVERNMENT USE ONLY\*\*\*

Information released to a third party shall comply with any
applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 987462

#### INCIDENT DESCRIPTION

\*Report taken by: MST2 BRANDY HUGGINS at 06:19 on 28-AUG-11

Incident Type: RAILROAD NON-RELEASE

Incident Cause: TRESPASSER

Affected Area:

Incident was discovered on 28-AUG-11 at 04:58 local incident time.

Affected Medium: NON-RELEASE (N/A) NONE

# Halstead, Lori (UTC)

From:

Pratt, David (UTC)

Sent:

Monday, August 29, 2011 7:14 AM

To:

Halstead, Lori (UTC)

Subject:

FW: NRC#987385 (Train Vs Tresspasser - Nisqually)

**FYI** 

Dave Pratt

Assistant Director for Transportation Safety dpratt@utc.wa.gov 360.664.1100 -----Original Message-----

From: Duty Officer (EMD)

Sent: Friday, August 26, 2011 6:08 PM

To: Pratt, David (UTC)

Subject: FW: NRC#987385 (Train Vs Tresspasser - Nisqually)

Here is the NRC report on that incident.

State Emergency Operations Officer/ED

Washington State Emergency Operations Center Camp Murray, WA 98430

24-hr: 800-258-5990 Fax: 253-512-7203

www.emd.wa.gov

----Original Message----

From: HQS-PF-fldr-NRC@uscg.mil [mailto:HQS-PF-fldr-NRC@uscg.mil]

Sent: Friday, August 26, 2011 6:06 PM

To: Duty Officer (EMD) Subject: NRC#987385

NATIONAL RESPONSE CENTER 1-800-424-8802

\*\*\*GOVERNMENT USE ONLY\*\*\*GOVERNMENT USE ONLY\*\*\*

Information released to a third party shall comply with any applicable federal and/or state Freedom of Information and Privacy Laws

Incident Report # 987385

#### INCIDENT DESCRIPTION

\*Report taken by: E5 RUSSELL POST at 20:51 on 26-AUG-11

Incident Type: RAILROAD NON-RELEASE

Incident Cause: TRESPASSER

Affected Area:

Incident occurred on 26-AUG-11 at 17:13 local incident time.

Affected Medium: NON-RELEASE (N/A) TRESSPASSER FATALITY

Name:

GRETTA BAKER

Organization: BNSF RAILWAY

Address:

2600 LOU MENK DRIVE

FORT WORTH, TX 76161

PRIMARY Phone: (817)2346164

Type of Organization: PRIVATE ENTERPRISE

SUSPECTED RESPONSIBLE PARTY

Name:

**UNKNOWN** 

XX

#### INCIDENT LOCATION

County: THURSTON

City: NISQUALLY State: WA MILE POST- 24.2 SUB - SEATTLE

# RELEASED MATERIAL(S)

#### DESCRIPTION OF INCIDENT

CALLER STATED THAT AMTRAK 516 TRAVELING HEADING NORTH BOUND STRUCK A TRESPASSER THAT WALKED ONTO THE TRACKS AND LAID BETWEEN THE RAILS. THE CALLER STATED THAT THE TRESPASSER WAS DECLARED DECEASED ON SCENE.

#### SENSITIVE INFORMATION

# INCIDENT DETAILS

Grade Crossing: NO

Location Subdivision: SEATTLE

Railroad Milepost: 24.2 Type of Vehicle Involved: Crossing Device Type: Device Operational: YES DOTCrossing Number:

Date and Time Service was/will be Restored:

Brake Failure: NO

Federal Post-Accident 219.201 Sub Part C Testing Required: NO

Passenger Train Route: YES

Passenger Train Delay Expected: YES

Passenger Train Delay Handling: PASSENGERS WILL BE KEPT ON THE

TRAIN.

---RAILROAD INFORMATION--Railroad Involved: BNSF RAILWAY

Train Number: A-5161-26

Train Type: PASSENGER Train Direction: N

Train Speed: Track Speed: 55 Locomotives: 1 Cars: 10 Derailed: 0

Suspected DOT Regulation Non Compliance: NO

DERAILED CARS:

Pos. Carnumber Type Cargo

**IMPACT** 

Fire Involved: NO Fire Extinguished: UNKNOWN

INJURIES: NO Hospitalized: Empl/Crew: Passenger: FATALITIES: YES 1 Empl/Crew: Passenger: Occupant:

EVACUATIONS:NO Who Evacuated:

Radius/Area:

Damages: NO

Hours Direction of

Closure Type Description of Closure Closed Closure

N

Air:

N Major

Road: Artery:N

N

Waterway:

Y SEATTLE 1 N/S

Track:

Environmental Impact: UNKNOWN

Media Interest: NONE Community Impact due to Material:

REMEDIAL ACTIONS

INVESTIGATION IS UNDERWAY BY RAIL COMPANY AND LOCAL AUTHORITIES

Release Secured: UNKNOWN

Release Rate:

Estimated Release Duration:

WEATHER

Weather: UNKNOWN, °F

ADDITIONAL AGENCIES NOTIFIED

Federal: NONE

State/Local: WA-EMERG OPS, WA-UTILITY AND TRANSP.

State/Local On Scene: NONE State Agency Number: 11-2801

#### NOTIFICATIONS BY NRC

USCG ICC (ICC ONI)

26-AUG-11 21:05 (301)6693363

DOT CRISIS MANAGEMENT CENTER (MAIN OFFICE)

26-AUG-11 21:05 (202)3661863

FEDERAL RAILROAD ADMIN. (MAIN OFFICE)

26-AUG-11 21:05 (202)4936242

FEMA REGION 10 (MAIN OFFICE)

26-AUG-11 21:05 (425)4874704

NATIONAL INFRASTRUCTURE COORD CTR (MAIN OFFICE)

26-AUG-11 21:05 (202)2829201

NOAA RPTS FOR WA (MAIN OFFICE)

26-AUG-11 21:05 (206)5264911

NTSB RAIL (MAIN OFFICE)

26-AUG-11 21:05 (202)3146293

HOMELAND SEC COORDINATION CENTER (MAIN OFFICE)

26-AUG-11 21:05 (202)2828300

OREGON TITAN FUSION CENTER (COMMAND CENTER)

26-AUG-11 21:05 (877)6204702

WA STATE EMERGENCY MANAGEMENT (MAIN OFFICE)

26-AUG-11 21:05 (800)2585990

WASHINGTON STATE NATIONAL GUARD (COMMAND CENTER)

26-AUG-11 21:05 (253)5128159

#### ADDITIONAL INFORMATION

NONE PROVIDED

\*\*\* END INCIDENT REPORT #987385 \*\*\*
Report any problems by calling 1-800-424-8802
PLEASE VISIT OUR WEB SITE AT http://www.nrc.uscg.mil