WUCC Complaint Form

Requester Information

Your Name:		Your Company:				
Isaac Myhrum		Cascade Natural Gas Corporation				
Your Phone Number:		Your Email:				
5099758700		isaac.myhrur	m@mdu.com			
Your Address:						
8113 W Grandridge Blvd						
Your City:	Your State:		Your Zip:			
Kennewick	WA		99301			
Was a locate requested from the call	center? Yes) No				
Ticket Number:		Ticket Date:				
22382993		08/29/2022				
Violation Information Alleged Violation/Damage:						
 RCW 19.122.030 Must call for 	marking two (2) full	business days prid	or to digging.			
Other						
Section of Law Violated:		Alleged Violation Date:				
RCW 19.122.030 (2) and RCW	19.122.030 (5	08/31/2022				
Address of alleged violation:						
10023 OLD FRONTIER RD						
City of Alleged Violation:	State of Alleged Vi	iolation:	Zip of Alleged Violation:			
SILVERDALE	WA		98383			

Basic Description:

Cascade Natural Gas (Cascade or Company) hereby submits to the Washington State Dig Law Safety Committee (Committee) this formal complaint against excavator Evergreen Concrete Cutting (Evergreen), based in Pacific, Washington, for its repeated, and the Company believes, willful, violations of Washington State Dig Laws under RCW 19.122.

The Company cites an incident that occurred on August 31, 2022 under locate request 22382993. The Company has documentation to support the fact that Evergreen had commenced excavation activities prior to the valid locate ticket date (work to begin date) which would have been no earlier than September 1, 2022. Evergreen began such excavation activities prior to the Company marking all known gas utilities in the dig site identified on locate ticket number 22382993.

Allleged Violator	r			
Company Name:				
EVERGREEN CONCR	ETE CUTTING INC			
Company Phone Number:		Company Email:		
2538267644		MATTW@EVERGREENCONCRETECUTTING.O		
Company Address:				
Company City:	Company State:	Company Zip:		
PACI FI C	WA	98047		
Names of Employees on S	site:			

Other

Additional Information:

These violations were identified by the Company when its personnel responded to the locate ticket requested by Evergreen and discovered that excavation activities had already commenced prior to a one-number locator service being performed. The Company is in possession of photographs which show Evergreen engaged in excavation activities prior to a completed locate request. The Company believes that Evergreen, through its repeated and willful violations of RCW 19.122 and apparent unwillingness to change its practices demonstrates a clear disregard for the safety of Evergreen's own employees, public safety customers, and the Company's facilities.

By submitting this form I acknowledge that the statements that I alleged are true and accurate to the best of my knowledge.



In the Community to Serve®

8113 W. Grandridge Blvd Kennewick, WA 99336 888-522-1130 | www.cngc.com



Cascade Natural Gas (Cascade or Company) hereby submits to the Washington State Dig Law Safety Committee (Committee) this formal complaint against excavator Evergreen Concrete Cutting (Evergreen), based in Pacific, Washington, for its repeated, and the Company believes, willful, violations of Washington State Dig Laws under RCW 19.122.

The Company cites an incident that occurred on August 31, 2022 under locate request 22382993. The Company has documentation to support the fact that Evergreen had commenced excavation activities prior to the valid locate ticket date (work to begin date) which would have been no earlier than September 1, 2022. Evergreen began such excavation activities prior to the Company marking all known gas utilities in the dig site identified on locate ticket number 22382993. This is in violation of both RCW 19.122.030 (2) and RCW 19.122.030 (2) which state:

RCW 19.122.030 (2): "An excavator must provide the notice required by subsection (1) of this section to a one-number locator service not less than two business days and not more than ten business days before the scheduled date for commencement of excavation, unless otherwise agreed by the excavator and facility operators." (emphasis added)

RCW 19.122.03 (5): "An excavator must not excavate until all known facility operators have marked or provided information regarding underground facilities as provided in this section."

Additionally, the Company has documentation, provided in this complaint. In this instance along with multiple other occasions, Evergreen has failed to mark the boundary of Evergreen's proposed excavation area in white paint, which constitutes a violation of RCW 19.122.030 (2) which states:

RCW 19.122.030 (1), which requires excavators to "must mark the boundary of the excavation area with white paint applied on the ground of the worksite, then provide notice of the scheduled commencement of excavation to all facility operators through a one-number locator service."

These violations were noted by the Company when its personnel responded to locate tickets requested by Evergreen (or a related party) and excavation activities had already commenced prior to a one-number locator service being performed. The Company cites two incidents in this complaint which occurred on June 15, 2022 and June 22, 2022 under locate requests WA22263270 and WA22275992 respectively.

The Company's field personnel at the time of the violations communicated directly and in-person to Evergreen's personnel that its actions were in violation of the law. These communications have been documented by the Company. When reached directly by Cascade management regarding these alleged violations, representatives from Evergreen expressed no intention to change their practices. The Company has provided time-stamped photographs of Evergreen's alleged violations which show Evergreen engaged in excavation activities prior to a completed locate request.



In the Community to Serve®

8113 W. Grandridge Blvd Kennewick, WA 99336 888-522-1130 | www.cngc.com



The Company believes that Evergreen, through its repeated and willful violations of RCW 19.122 and apparent unwillingness to change its practices demonstrates a clear disregard for the safety of Evergreens own employees, customers, and the Company's facilities. The Company believes these actions by Evergreen warrant an investigation by the Committee.

These violations were identified by the Company when its personnel responded to the locate ticket requested by Evergreen and discovered that excavation activities had already commenced prior to a one-number locator service being performed. The Company is in possession of photographs which show Evergreen engaged in excavation activities prior to a completed locate request. The Company believes that Evergreen, through its repeated and willful violations of RCW 19.122 and apparent unwillingness to change its practices demonstrates a clear disregard for the safety of Evergreen's own employees, public safety customers, and the Company's facilities.

RCW 19.122.030 (2) and RCW 19.122.030 (5)

Hendrickson, Teresa

From: Bossard, Chris

Sent: Wednesday, August 31, 2022 4:40 PM

To: Myhrum, Isaac

Subject: FW: 10023 OLD FRONTIER RD

Isaac,

Bernie Jenkins submitted Form 23094 today for two Dig Law violations for Evergreen Concrete Cutting. The excavation area was not premarked with white paint and the excavation was competed prior to the work to begin date.

Locate: # WA22382993

PCAD Job Number: Mdug-20220829-21727

Please formally file two complaints against Evergreen Concrete Cutting with the WUTC.

Thanks,

Chris

From: Jenkins, Bernard < Bernard. Jenkins@cngc.com >

Sent: Wednesday, August 31, 2022 2:33 PM **To:** Bossard, Chris < Chris.Bossard@cngc.com>

Subject: 10023 OLD FRONTIER RD

Good Afternoon Chris.

Provided are the images that I've attached to the Form 23094 submitted this afternoon.









Bernie Jenkins Service Mechanic A



"In the Community to Serve"

A Subsidiary of MDU Resources Group Inc.

Cell: (360)633-5654

bernard.jenkins@cngc.com

"The meaning of life, is a life of meaning."
-Robert Byrne

Order Summary —							
PCAD Job ID MDU	G-20220829-21727	FA ID WA22382993	Service Code	NM-LOCAT			
Customer EVERGI	REEN CONCRETE CUT	TING					
Address 10023 OL	D FRONTIER RD, SILVE	RDALE, SILVERDALE			Attachments: 0		
Order Information							
FA Instructions ¹ ASPHALT CUTTING	3			Account ID	Appointment Code	FA Taken By	
				Requested By and Phone	Cal	Ahead Info	
Meter Information							1
Meter Number	ERT Number	Previous Read	Meter Location	Meter Location Details	2 B ₁	ypassable Meter Set	Maximo Directions
					//		
Meter Set Date	ERT Type	Previous Read Date	Meter Size	Number of Dials	Read Instructions ⁴		
Serial Number	Regulator 1	Regulator 2	Delivery Pressure	Billing Pressure	Meter Manufacturer	Meter On/Off Status	
Serial Number	Regulator 1	Regulator 2	Delivery Pressure	Billing Pressure	Meter Manufacturer	N/A	Maximo Work Log
Multiplier	Drive Rate	Press. Compensated	Temp. Compensated	L HPSS	Excess Flow Valve	Premise Warning	
·		<u> </u>					
Service Line #	Estimated Read Ind.	Previous Read 2	Meter Low Range	Meter High Range	External Relief Valve	Meter Rd Rte/Cycle ⁶	
Premise ID	Phase/Wire	Class	Amps	Form	SP Voltage	Meter Voltage	
							Maximo Location II
Premise Information		0		Unsafe/Unsatisfactory	Condition8	C. i. D.i.ID	
Aleit		Appliances ⁹		Offsale/Offsalistactory	Condition	Service Point ID	Maximo Location D
						Landlord Agreement	
Premise Time Zone	Premise Type	Disconnect Location	Life Support Sensitive ¹	Additional Address		Key ID	
USPACIFIC							
							Section ID
Order History							
Order Date 1	FA Type 1	Employee 1	Comments 1 ¹²				Owner Group
						//	
Order Date 2	FA Type 2	Employee 2	Comments 2 ¹³				
						1	
Order Date 3	FA Type 3	Employee 3	Comments 3 ¹⁴				
— Account Information)						
Account Status	Customer Class	Rate	Business Phone	Work Phone	Cellular Phone	_	
]	
Last Payment	Last Payment Date	Balance Due	Due Date	٦			

FA Instructions ¹	ASPHALT CUTTING
Meter Location Details ²	
Maximo Directions ³	
Read Instructions ⁴	
Maximo Work Log History ⁵	
Meter Rd Rte/Cycle ⁶	
Alert ⁷	

Unsafe/Unsatisfactory Condition ⁸	
Appliances ⁹	
Maximo Location Description ¹⁰	
Life Support Sensitive ¹¹	
Comments 1 ¹²	
Comments 2 ¹³	
Comments 3 ¹⁴	

Order Summary						
PCAD Job ID MDUG-20220829-21727						
Customer EVERGREEN CONCRETE CUTTING						
Address 10023 OLD FRONTIER RD, SILVERDALE, SILVERDALE Attachments: 0						
Locate Completion						
Completed Positive Response CGI Reason						
2						
Marking Method Grid Number Office Review? Reviewer						
PAINT	OR					
Comments ¹ Review Reason ²						
LOCATED AND MARKED 4" P.E. MAIN ON WEST SIDE OF OLD FRONTIER RD PARALLEL TO EXISTING SAW-CUT IN ASPHALT. NO WHITE PATHT TO TRENTTEY EXCAVATION AREA Facility Located? Choose All that Apply						
Gas Electric Fiber						
Select 1 Reason Below						
Near Miss? Facility Not Marked Due To: Facility Marked Inaccurately Due To:						
NO						
Excavator Notified Person Notified Notifier						
YES						
Locate Comments ³ Unusual Circumstances ⁴ Excavator Comments ⁵						
LOCATED AND MARKED 4" P.E. MAIN ON WEST SIDE OF OLD FRONTIER RD						

Unusual	Page 11
Locate Comments ³	LOCATED AND MARKED 4" P.E. MAIN ON WEST SIDE OF OLD FRONTIER RD PARALLEL TO EXISTING SAW-CUT IN ASPHALT. NO WHITE PAINT TO IDENTIFY EXCAVATION AREA. UTILIZED LOCATE TICKET INSTRUCTIONS ONLY. PHONED "SCOTT" WITH EVERGREEN CONCRETE (AS INSTRUCTED IN LO
Review Reason ²	LOCATED AND MARKED 4" P.E. MAIN ON WEST SIDE OF OLD FRONTIER RD PARALLEL TO EXISTING SAW-CUT IN ASPHALT. NO WHITE PAINT TO IDENTIFY EXCAVATION AREA. UTILIZED LOCATE TICKET INSTRUCTIONS ONLY. PHONED "SCOTT" WITH EVERGREEN CONCRETE (AS INSTRUCTED IN LO
Comments ¹	LOCATED AND MARKED 4" P.E. MAIN ON WEST SIDE OF OLD FRONTIER RD PARALLEL TO EXISTING SAW-CUT IN ASPHALT. NO WHITE PAINT TO IDENTIFY EXCAVATION AREA. UTILIZED LOCATE TICKET INSTRUCTIONS ONLY. PHONED "SCOTT" WITH EVERGREEN CONCRETE (AS INSTRUCTED IN LOCATE REQUEST TICKET), NO ANSWER, AND NO CALLBACK AFTER VOICEMAIL WITH CONTACT INFO. NOTIFIED MAX WAGNER WITH EVERGREEN CONCRETE CUTTING (INCLUDING CNG BREMERTON MANAGEMENT: S. O'NEILL, K. YOUNGBLOOD, AND C. BOSSARD) OF MONITOR REQUIREMENT.

Circumstances ⁴	
Excavator	
Comments ⁵	

Washington One Call

Ticket number 22382993 **Type/header** 2 FULL BUSINESS DAYS ITIC2.0

 Original call date
 08/29/22 11:24 am

 Work to begin date
 09/01/22 12:00 am

 Expiration date
 10/13/22 11:30 am

Excavator information

Company name EVERGREEN CONCRETE Type of CONTRACTOR

CUTTING excavator

Contact nameMATT WAGNERPhone253-826-7644Alt. contactJESSICA FERRISPhone253-826-7644

Address 767 VALENTINE AVE Fax phone

PACIFIC, WA 98047

Email address MATTW@EVERGREENCONCRETECUTTING.COM

Excavation information

Type of work ASPHALT CUTTING

Work being done for PIVETTA BROTHERS CONSTRUCTION

Directional drilling Maybe

Type(s) of excavation Unknown / Other

equipment

Location information

StateWACountyKITSAPPlaceSILVERDALEAddress10023

Street OLD FRONTIER RD

Intersecting street

Location of work DUPLICATE SAME MARKS AS TICKET# 22360952. CONTACT SCOTT 253-797-1031

FOR CUT LOCATIONS.

Remarks AREA MARKED IN WHITE PAINT

NW Lat 47.6545619 **Lon** -122.7077603 **SE Lat** 47.6537742 **Lon** -122.7061778

Members notified

District	Company name	Marking concerns	Customer service	Repair	Status
CNG06	CASCADE NATURAL GAS BREMERTON	360-373-1405	888-522-1130	888-522-1130	Marked, Complete
KITDPW01	KITSAP COUNTY PUBLIC WORKS	360-337-5777	360-337-5777	360-337-5777	Clear, No Utility Owned Facility in Excavation Area
KITDPW02	KITSAP COUNTY PUBLIC WORKS	360-337-5710	360-337-5777	360-337-5777	Does not report
KITDPW03	KITSAP COUNTY PUBLIC WORKS	360-337-5777	360-337-5777	360-337-5777	Does not report
PUGE04	PUGET SOUND ENERGY ELECTRIC	888-728-9343	888-225-5773	888-225-5773	Marked, Complete
QLNWA16	CTLQL-CENTURYLINK	800-778-9140	800-283-4237	800-573-1311	Ongoing Job
SILWTR01	SILVERDALE WATER DIST#16	360-447-3500	360-447-3500	360-447-3500	Does not report
WDOTOR02	WSDOT OLYMPIC REGION-AREA 2	360-874-3050	360-874-3050	360-874-3050	Does not report
XITPU02	KITSAP COUNTY PUD #1	800-778-9140	360-779-7656	360-779-7656	Due Date Extended

Мар

