

Marysville train speed petition

CAUSE: TR-940309

NO.	ID/ADM		WITNESS	DESCRIPTION
	1/19	1/19		
1	✓	✓	(WDOT) Mallery	part of Chapter 47.79 RCW
2	✓	✓	"	Resolution No. 445, passed by the Wash. State Transp. Comm.
3	✓	✓	"	map of Marysville track, showing speed limits existing and proposed.
4	✓	✓	"	FRA Track Safety Standards booklet
5	✓	✓	(BN) Henry	Table 25. Accidents Involving Hazardous Materials, by type 1993 - systemwide
6	✓	✓	"	Figure 1. Operational Data - systemwide
7	✓	✓	"	Figure 29 - map showing 1993 hazardous materials releases, by state
8	✓	✓	(Am Trac) Clabe	Table 16. Accidents 1993 @ crossings, by speed, circumstance & visibility - systemwide
9	✓	✓	(BN) Henry	Figure 5. Derailments - systemwide
10	✓	✓	"	Figure 9. Train accidents involving hazmat, 1975-1993 - systemwide
11	✓	✓	"	Table 28. Accidents involving haz materials, by state, 1993
12	✓	✓	"	Table 27. Accidents involving haz materials, by cause, 1993 - systemwide
13	✓	✓	"	Table 26. Train accidents involving haz. materials, 1988-1993 - systemwide
14	✓	✓	(WDOT) Mallery.	aerial photos
15	✓	✓	(city) Berg	map showing location & signals @ crossings
16	✓	✓	"	Berg summary statement regarding proposal, incl. traffic counts
17	1/20	1/20	(city) Ploeger	group of photos: 1-29, except #11, which was not included (taken 1/17/95)
18	✓	✓	(city) Nirashima	map of Comprehensive Plan
19	✓	✓	"	zoning map for city and county (taken 1992)
20	✓	✓	"	aerial photo showing urban growth areas

Monroeville train speed petition

CAUSE: TR-940309

NO.	ID/ADM	WITNESS	DESCRIPTION
21	1/20 1/20 ✓ ✓	(WUTC) Harder	map, with existing and proposed train speeds, and crossings
22	✓ ✓	"	photos taken by track inspector (22 pp)
23	✓ ✓	"	photos of grade crossings and roads @ crossing areas.
24	✓ ✓	"	materials from Operation Lifesaver
25	✓ ✓	(WUTC) Scott	accidents at all grade crossings reported 1972-current, Washington
26	✓ ✓	by agrmt of counsel	public letters (3) for illustrative purposes
7			
8			
9			
0			
1			
2			
3			
4			
5			
6			
7			
8			
9			
0			