

EXHIBIT LIST

Docket PL-140180

NUMBER	WITNESS	A/R	DATE	DESCRIPTION
AJ-1	Al Jones	A	5/28/14	Photo image of excavated trench and exposed pipe (1 page)
AJ-2	Al Jones	A	5/28/14	Photo image of excavated trench and exposed pipe (1 page)
AJ-3	Al Jones	A	5/28/14	Photo image of excavated trench and exposed pipe (1 page)
AJ-4	Al Jones	A	5/28/14	Photo image of excavated trench and exposed pipe (1 page)
AJ-5	Al Jones	A	5/28/14	Photo image of excavated trench running parallel to service road (1 page)
AJ-6	Al Jones	A	5/28/14	Photo image of excavated trench and markings (1 page)
AJ-7	Al Jones	A	5/28/14	Photo image of excavated trench and exposed pipe (1 page)
AJ-8	Al Jones	A	5/28/14	Photo image of excavated trench running parallel to service road (1 page)
AJ-9	Al Jones	A	5/28/14	Photo image of excavator and excavated trench in view on the right side of the image (1 page)
AJ-10	Al Jones	A	5/28/14	Photo image of excavated trench and markings (1 page)
AJ-11	Al Jones	A	5/28/14	Photo image of excavated trench, exposed water line, and orange marking (1 page)
AJ-12	Al Jones	A	5/28/14	Photo image of two markings and excavated trench in the background (1 page)
AJ-13	Al Jones	A	5/28/14	Aerial photo image of excavated trench and marking (1 page)
AJ-14	Al Jones	A	5/28/14	Penalty Assessment PL-140180, dated March 4, 2014, from Gregory J. Kopta to Mr. Randy Buchanan in the amount of \$5,000 for two violations of RCW 19.122.030 (4 pages)
AJ-15	Al Jones	A	5/28/14	Letter to Dave Lykken, Pipeline Safety Director, from Washington State Dig Law Safety Committee dated, January 29, 2014, and outlining the Committee's penalty recommendations (2 pages)
AJ-16	Al Jones	A	5/28/14	Complaint form from Tesoro Logistics Northwest Pipeline, LLC (1 page)
AJ-17	Al Jones	A	5/28/14	Letter from Washington State Dig Law Safety Committee to Tesoro Logistics Northwest Pipeline, LLC representative providing notice of scheduled review (1 page)

