



UTILITIES AND TRANSPORTATION
COMMISSION

Assignment Report Motor Carrier Safety

New Entrant? Yes No Was a CR conducted between 6-18 months after the permit was issued? Yes No

1. Investigator(s): Mathew Perkinson 2. Assignment No.: 116102
 3. Current Date: 6/16/2016 4. Date of Activity: 6/16/2016
 5. Carrier Name: Peninsula Trips LLC dba Peninsula Trips; Peninsulatrips.com
 6. Company ID: 17688 7. Industry Code: 232 8. USDOT #: 2898122
 9. Carrier is: Intrastate Yes No Intra and Interstate

10. Destination Check

11. Compliance Review

12. Part B Violations

13. Vehicle Inspection Data

| | Van 9-15 | Carrier Type | Carrier Type | Carrier Type | Carrier Type | Carrier Type | Carrier Type | Carrier Type |
|--------------------|----------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| Inspections | 1 | | | | | | | |
| Defective Vehicles | 1 | | | | | | | |
| OOS Vehicles | 0 | | | | | | | |
| Level | 7 | | | | | | | |

14. Vehicle Inspection Violations

| | VAN 9-15 | Vehicle Type | Vehicle Type | Vehicle Type | Vehicle Type | Vehicle Type |
|----------------|---------------------|--------------|--------------|--------------|--------------|--------------|
| Comments: | | | | | | |
| Other | Markings (no USDOT) | | | | | |
| Violation Type | | | | | | |
| Violation Type | | | | | | |

15. Driver Inspection Violations

| Medical Card | Medical Waiver | Hours of Service | Driver's License |
|--------------|----------------|------------------|------------------|
| | | | |
| Comment: | | | |

16. Relevant Carrier History:

Carrier is a new entrant planning to charge a fee to transport its customers throughout the Olympic National Forest on guided tours.

Assignment Report
Motor Carrier Safety

17. Findings:

One Level 7 inspection was performed on a 2007 Chevy. The vehicle did not have the carrier's name or USDOT number displayed as required. No CVSA decals were issued per level 7 guidelines. The inspections conformed to level 5 CVSA inspection standards. CFR Parts 382, 383, 387, 390, 391, 392, 393, 395, and 396 were discussed in detail. The new entrant verification of training form was completed with Mr. Farris. Mr. Farris was provided a paper and USB copy of the commission's safety guide. I informed him that the vehicle must have a periodic inspection prior to operating. I also informed him of medical certificate requirements specifically. Mr. Farris confirmed that he will complete all the items that are required prior to operating.

18. Recommended Safety Action: Yes No

19. Is this carrier considered a high risk carrier as a result of this activity? Yes No

20. Additional Comments:

Please close and issue authority.

Investigator's Signature: Mat Perkinson Date: 6/16/2016

OFFICE USE ONLY

Initial Review By: John Stuch Date: 6/17/16

Initial Reviewer's Recommendation: agree with recommendation
To forward to licensing. Close & file

Final Review By: DPratt Date: 6/17/16

Final Reviewer's Recommendation: close & file

-ok to issue permit

Internal Processing

Date Closed: 6/17/16 By: A. Elhardt

Company Name: Peninsula Trips LLC

Assignment Report
Motor Carrier Safety

| | | | |
|---------------|--------|-----------------|-----------|
| Assignment #: | 116102 | Staff Assigned: | Perkinson |
|---------------|--------|-----------------|-----------|