1 |

- 6. I believe I assisted with the replacement of bad crossing planks there although I cannot recall when that occurred.
- 7. I am also familiar with the BNSF crossing located at Massey Road in Whatcom County.
- 8. I recently assisted with repairs at the Massey Road crossing by tearing out the approaches and replacing it with gravel to level out the crossing.

DATED this 4 day of March, 2013, at Bulling to	M, Washington.

Chris Conover

Facsimile (206) 625-1807