



TransCanada Pipeline GTN; Milepost 231.5, Wallula District

Sinkhole Remediation at Babcock Road, Walla Walla County, Washington

View looking south (downstream) at six excavated trench breakers placed about 250 feet apart.

Photo taken 2/3/2011 by Al Jones, UTC

Photo 1/2



TransCanada Pipeline GTN; Milepost 231.5, Wallula District

Sinkhole Remediation at Babcock Road, Walla Walla County, Washington

View looking at excavated trench breakers of 26-inch and 42-inch transmission pipelines. Drain pipe will be place under the pipelines adjacent to sandbags to intercept water and transfer it to a tight line placed parallel to the pipeline near edge of right-of-way.

Photo taken 2/3/2011 by Al Jones, UTC

Photo 2/2