



March 1, 2010

Mr. David Lykken  
Director of Pipeline Safety  
Washington Utilities and Transportation Commission  
1300 S Evergreen Park Dr. SW  
PO Box 47250  
Olympia, WA. 98504-7250

**Re: Docket PG-090076, 2009 Natural Gas Standard Inspection – Pullman/Clarkston, Washington, AC Field Guide Submission**

Dear Mr. Lykken,

Enclosed please find a copy of Avista's updated Atmospheric Corrosion & Safety Inspection Handbook. This is the revision to the former "Scope of Work" document that was reviewed during the Pullman Standard Inspection. As per your December 23, 2009 correspondence related to this Inspection, it was agreed that this guide would be updated and improved by March 1, 2010 with a copy then submitted to the Commission.

Please contact me if there are any questions.

Thank you,

Kris Busko  
Pipeline Safety Engineer

cc: File

STATE OF WASHINGTON  
UTILITY AND TRANSPORTATION COMMISSION  
2010 MAR -3 AM 9:55  
RECEIVED  
MAR 3 2010