PATTIS Mobile Service (307) 2208 Sturgeon DIZ MARYSville, WA 98271 ANNUAL VEHICLE INSPECTION REPORT NUMBER PATTION REPORT NUMBER VEHICLE HISTORY RECORD FLEET UNIT NUMBER 58591716 #1 DATE 1-19-22 MOTOR CARRIER OPERATOR INSPECTOR'S NAME (PRINT OR TYPE) Americanu movers LLC

ADDRESS				QUALIFICATION	REQUIREMENTS IN SECTION 396.19.
520	Co S, 2nd AUE		YES		
CITY, STATE, ZIF	PCODE		VEHICLE IDENTIFICATION (AND COMPLETE)	LIC. PLATE NO. VIN OTHER
EUEK		203	5946-XR/	1GDEL	HIBXY3 901641
VEHICLE TYPE	TRACTOR TRAILER TRUCK	BUS	INCOPPORTION ACCINIONAL CONTI	TON (OPTIONAL)	
	(OTHER) 26' 130x		PAHTI'S MOD.	ile Se IV	ice El B-
		VELUCIE			
OK NEEDS REPAIRED	ITEM		COMPONENTS INSPECTED		EDITEM
DATE DATE	1. BRAKE SYSTEM	OK NEEDS REPAIRED DATE		OK NEEDS REPAIR DATE	10. TIRES
	a. Service Brakes		6. SAFE LOADING		
	b. Parking Brake System		a. Part(s) of vehicle or		a. Tires on any steering axle of a power unit.
	c. Brake Drums or Rotors		condition of loading such		b. All other tires.
1	d. Brake Hose		that the spare tire or any part of the load or dunnage	V	
	e. Brake Tubing		can fall onto the roadway.		c. Installation of speed- restricted tires unless
			b. Protection against shifting		specifically designated by
NK	f. Low Pressure Warning Device	1			motor carrier.
NR	g. Tractor Protection Valve		cargo.	N	11. WHEELS AND RIMS
NIR	h. Air Compressor		c. Container securement		a. Lock or Side Ring
No	i. Electric Brakes	NA	devices on intermodal		b. Wheels and Rims
	j. Hydraulic Brakes		equipment.		c. Fasteners
	k. Vacuum Systems		7. STEERING MECHANISM		d. Welds
	I. Antilock Brake System		a. Steering Wheel Free Play		12. WINDSHIELD GLAZING
	m. Automatic Brake Adjusters		b. Steering Column		Requirements and exceptions
	2. COUPLING DEVICES		c. Front Axle Beam and All		as stated pertaining to any
ALA	a. Fifth Wheels		Steering Components Other Then Steering	good	crack, discoloration or vision
	b. Pintle Hooks		Other Than Steering Column		reducing matter (reference
AU	c. Drawbar/Towbar Eye		d. Steering Gear Box		393.60 for exceptions).
A9 A	d Drawbar/Towbar Tonguo	V/	e. Pitman Arm		13. WINDSHIELD WIPERS
	e. Safety Devices				Any power unit that has an
	f. Saddle-Mounts	10	f. Power Steering		inoperative wiper, or missing
	3. EXHAUST SYSTEM		g. Ball and Socket Joints	9000	or damaged parts that render
	a. Exhaust system leaking		h. Tie Rods and Drag Links		it ineffective.
	forward of or directly below		i. Nuts		14. MOTORCOACH SEATS
10	the driver/sleeper		j. Steering System		Any passenger seat that is
	compartment.		8. SUSPENSION		not securely fastened to the
	b. Bus exhaust system		a. Any U-bolt(s), spring	N	vehicle structure.
AUA	leaking or discharging in violation of standard.		hanger(s), or other axle		15. OTHER
		1	positioning part(s) cracked,		List any other condition(s)
	burn, char, or damage the	9000	broken, loose or missing resulting in shifting of an	*	which may prevent safe
	electrical wiring, fuel supply,		axle from its normal position.		operation of this vehicle.
101	or any combustible part of		b. Spring Assembly		
	the motor vehicle.				No other
	4. FUEL SYSTEM		c. Torque, Radius or Tracking		
	a. Visible leak.		Components		Issues
	b. Fuel tank filler cap missing.		9. FRAME		
	c. Fuel tank securely attached.		a. Frame Members		
	5. LIGHTING DEVICES		b. Tire and Wheel Clearance		
	All lighting devices and		c. Adjustable Axle		
	reflectors required by Part 393 shall be operable.		Assemblies (Sliding		
INSTRUCTIONS	S: MARK COLUMN ENTRIES TO VERIFY IN	ISPECTION	Subframes)		
	ON: THIS VEHICLE HAS PAS		THE TOUTH AIN, INA	_ IF ITEMS DO	NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.