

# Inspection, Repair & Maintenance Record

## VEHICLE IDENTIFICATION

Make: <u>Isuzu FTR</u>	Serial Number: <u>4GTJ7C133XJ601223</u>
Year: <u>1999</u>	Tire Size: <u>11R 22.5</u>
Company number/other ID: <u>Flecks</u>	Owner, if leased: <u>N/A</u>

DATE	OPERATION PERFORMED, INSPECTION AND/OR REPAIR
<u>6/30/20</u>	<u>Trucks Feels Sluggish (Fuel Filters)</u>
<u>7/2/20</u>	<u>Oil Leak Detected</u>
<u>7/4/20</u>	<u>Oil Added</u>
<u>7/8/20</u>	<u>Oil Change And Fuel Filters Done</u>
<u>7/22/20</u>	<u>Belt Rubbing</u>
<u>7/28/20</u>	<u>Belts Changed / Alternator Changed / Valve Cover Replaced</u>