

wdsafetycommittee@gmail.com

From: sendmail@washington-ucc.org
Sent: Monday, August 17, 2020 12:56 PM
To: wdsafetycommittee@gmail.com
Subject: Complaint Form

Complaint Form Request

Requester Information

Name: Brian Hoback
Company: na
Company Phone: (541)510-2381
Company Email: brianhoback1@gmail.com
Company Address: 6305 Summerwod DR. E. , Puyallup, 98373
Ticket Requested: no

Violation Information

Violation RCW: RCW 19.122.030
Violation Section: Diging with no Locates
Violation Description: Digging with a trencher past a power vault with in 2ft and past a gas meter within 2ft
Violation Address: 13908 63rd Ave E Puyallup WA. 98373
Violation Date: 08/17/2020

Alleged Violator

Violator Name: Green Image Landscape Service
Violator Phone Number: (253)820-7696
Violator Email: KEVIN@GREENIMAGELS.COM
Violator Address: NA, NA, 11111-111
Violator Employess On Site: NA

Other Information

Other Information: I have Pictures of the open trench





