WUCC Complaint Form

Requester Information Your Name: Your Company: M&L Construction Inc and Underground Te Scot Wayne Hattenburg Your Phone Number: Your Email: scot@mlnorthwest.com 5099914129 Your Address: 4103 E Dalke 4103 e dalke ave Your City: Your State: Your Zip: WA Spokane 99217 Was a locate requested from the call center? Yes No Ticket Number: Ticket Date: 24198375 05/15/2024 **Violation Information** Alleged Violation/Damage: RCW 19.122.030 Must call for marking two (2) full business days prior to digging. Other 19.122.030 Section of Law Violated: Alleged Violation Date: 05/23/2024 failure to mark Address of alleged violation: 515 W Regina City of Alleged Violation: State of Alleged Violation: Zip of Alleged Violation:

99218

Wa

Spokane

Basic Description:

Power feed to a house across the street was marked coming from the west to the east and out of our bore path, but it actually was feeding from the east to the west and crossing directly in our bore path. We stopped the drill 30' short of our exit pit on the east side to pothole the existing utilities and found a power line that was heading west. after calling Avista, it was located correctly, and turned to cross directly in our bore path. We stopped less than a foot short of the power line directly in line with it by pure chance.

Allleged Violator				
Company Name:				
Avista Utilities				
Company Phone Number:		Company Email:		
5094890500		Proszek, Tyler		
Company Address:				
Company City:	Company State:		Company Zip:	
Spokane	Wa		99201	
Names of Employees on Site:				
Cody Hattenburg, Cardel Hov	well,			
Other				
Additional Information:				
we got lucky				

By submitting this form I acknowledge that the statements that I alleged are true and accurate to the best of my knowledge.